EquipmentName	Workshop	CodeAndSubCode	Description	Schedule	CompletionComments	DateDone	DistanceDone	Worktype	Workstate	EquipmentOwner	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
LOAD29	Wodonga - Workshop	Elect\TAIL LIGHT	clearance light not working r/rear			22/03/2024		Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Wodonga Workshop	LOADER
LOAD29	Wodonga - Workshop	DriCabRep\HOUSEKEEP	remove controllers			10/06/2021		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Wodonga Workshop	LOADER
LOAD29	Rosewood - Workshop	Body\DAMAGE	Tow Loader after Roll Over			04/05/2021	303197	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	DriCabRep\DAMAGE	back window broken		Sublet replace rear window by windscreen O'Brian Wagga	30/04/2021	303197	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	DriveLine\SHOCK ABS	cut out broken drive shock			28/04/2021	303197	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	DriCabRep\WINDSCREEN	Supply Rear Glass Window and Rubber seal		Obrien - replace windscreen	10/04/2021	303197	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	DrCabElect\ELECT P&W	Supply LED Lights, Markers and slack adjusted R/R clearance light replace			09/04/2021	303197	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	Elect\TAIL LIGHT	fit step			30/03/2021	300439	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	VehService\AS	A Service	VehService\AS		30/03/2021	300000	Service	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	Steering\TIE ROD	Supply Tie Rod Assembly			27/03/2021		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	Steering\WHEEL ALGN	called out to Forrest, severe toe-out of front tyres due to driver hitting stop or other non-moving object			26/03/2021	300227	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	Workshop\MOVE ASSET	checked was ok to travel back slowly to workshop and order parts			26/03/2021	300227	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	Steering	Supply Draglink			26/03/2021		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	Elect\TRL LIGHTS	RHS rear clearance light not working			12/03/2021	298556	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Tumut - Workshop	Elect\HEAD LIGHT	short in R/H headlight find fault rubbed wires bridge wires insulate and cable tie up			09/03/2021		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOAD29	Rosewood - Workshop	DriCabRep\WIPERS	change wiper blades x3			02/03/2021	296920	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Tumut - Workshop	Body\MOUNTS	adjust new step			27/02/2021	296723	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOAD29	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job A Service			27/02/2021	296723	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	VehService\AS	tighten RH drivine light	VehService\AS		27/02/2021	296723	Service	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Myrtleford - Workshop	Elect\TAIL LIGHT	reverse light broken call out to Maraylo load ute tyre jacks and tools travel Maraglo remove and refit wheel			27/02/2021	290811	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOAD29	Rosewood - Workshop	Tyres\DAMAGE	travel to Tumut			25/02/2021	296371	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	Tyres\TP9+10	replace 2 tyres			25/02/2021	296372	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Wodonga Workshop	LOADER
LOAD29	Myrtleford - Workshop	Elect\HEAD LIGHT	secured headlight with small nut and screw			19/02/2021	295240	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOAD29	Tumut - Workshop	Elect\HEAD LIGHT	blown headlight bulb			13/02/2021	294578	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOAD29	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			10/02/2021		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	VehService\AS	A Service	VehService\AS		10/02/2021		Service	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	DrCabElect\HEATER REP	replaced heater fan			10/02/2021	286537	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Tumut - Workshop	Body\PANELS	work on walkway			06/02/2021		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOAD29	Tumut - Workshop	Body\DAMAGE	travel to Rosewood with steel fab walkway			05/02/2021		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOAD29	Rosewood - Workshop	Elect\WORK LIGHT	replace work lights			04/02/2021	292900	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	Body\PANELS	help Toppo with walk way bent broken stops remove. Remove stops and brackets from L14 fit to 29 fit extra stop from walkway			04/02/2021	292900	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Tumut - Workshop	Body\DAMAGE	travel Tumut to ext steel walkway mesh			04/02/2021		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOAD29	Myrtleford - Workshop	Elect\WORK LIGHT	light under cab only work sometimes			30/01/2021	291551	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOAD29	Rosewood - Workshop	Elect\TAIL LIGHT	right rear clearance light not working			29/01/2021	292109	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	Elect\TAIL LIGHT	needs reversing light replaced			29/01/2021	292109	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	Elect\HEAD LIGHT	repair headlight wiring			28/01/2021	291730	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	Elect\TAIL LIGHT	reverse light broken			20/01/2021	290811	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	Elect\TAIL LIGHT	clearance light not working r/rear			20/01/2021	290811	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	Body\DAMAGE	left hand step needs fixing			20/01/2021	290811	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	DriveLine\CLUTCH	adjust clutch			19/01/2021	290633	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			19/01/2021	290633	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	VehService\BS	Service Due	VehService\BS	B Service	19/01/2021	290633	Service	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	Tyres\TP1+2	replaced 2 tyres			16/01/2021		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	Tyres\BREAKDOWN	call out steer tyre off the rim steps bent on left side		called out to loader in bush, steer tyre off the rim reolaced with soare from workshop	15/01/2021	290287	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	Body\DAMAGE	remove step straighten brackets refit step			10/01/2021	289528	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	Elect\ELECT P&W	repair LH parker light. New bulb			31/12/2020		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	DrCabElect\AIR CON	fit new evaporator			18/12/2020		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	DriCabRep\WIPERS	needs wiper blades			11/12/2020	287222	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	DrCabElect\HEATER REP	fan on heater and ac not working			11/12/2020	287222	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	Engine\BELTS/TENS	fan belts loose			11/12/2020	287222	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	Brakes\BRAKE ADJ	brake adjust		TCTC # R10331	08/12/2020	286036	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	Brakes\BRK O/HAUL	check brake operation			08/12/2020	286036	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	Elect\DRV LIGHT	repair driving lights not affixed properly and moving / falling out of adjustment rear axle needs s-cam bushes and reline asap			27/11/2020	284629	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Myrtleford - Workshop	Brakes\BRK RELINE	reline rear axle & fit s/cams & bushes & fit all new wheel bearies			27/11/2020	284171	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOAD29	Myrtleford - Workshop	DriCabRep\WIPERS	needs new wiper blades			24/11/2020	283898	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOAD29	Myrtleford - Workshop	DriCabRep\WIPERS	need new wiper blades			24/11/2020	283898	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOAD29	Rosewood - Workshop	DriCabRep\AIR LEAK	repair leaking airblow nozzle hose in cab			20/11/2020	283898	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	DriveLine\AIR LEAK	repair leaking splitter hose under cab			20/11/2020	283898	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	DriCabRep\WIPERS	replace wiper blades			20/11/2020	283898	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	DriCabRep\WIPERS	needs new wiper blades			18/11/2020	279695	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	DriCabRep\WIPERS	wiper blades badly needed			18/11/2020	279695	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	Elect\WORK LIGHT	light under cab only work sometimes			18/11/2020	279695	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	VehService\AS	Service 300km A	VehService\AS		18/11/2020	279695	Service	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			14/11/2020	283176	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	VehService\AS	A Service	VehService\AS		14/11/2020	283176	Service	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	Brakes\BRAKE ADJ	adjust brakes			13/11/2020	283006	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	Brakes\BRK RELINE	rear axle needs s-cam bushes and reline asap			13/11/2020	283006	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	DriCabRep\WIPERS	need new wiper blades			28/10/2020		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	Elect\DRV LIGHT	LHS driving light loose			28/10/2020		Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	DriCabRep\WIPERS	needs new wiper blades			16/10/2020	279695	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	VehService\AS	Service 300km	VehService\AS		16/10/2020	279695	Service	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			10/10/2020	279894	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	VehService\AS	A Service	VehService\AS		10/10/2020	279894	Service	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	Susp\AIR BAG	replace airbag on drive			08/10/2020	279623	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	DriveLine\OIL LEAK	tighten loose axle nuts			23/09/2020	278337	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Myrtleford - Workshop	Susp\HOUSEKEEP	LH shocker rubbers			10/09/2020	277260	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOAD29	Myrtleford - Workshop	Engine\HOUSEKEEP	engine number			10/09/2020	277260	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOAD29	Myrtleford - Workshop	Elect\DRV LIGHT	driving lights			10/09/2020	277260	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOAD29	Myrtleford - Workshop	Elect\ELECT P&W	weld chain links for d/light wiring			10/09/2020	277260	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOAD29	Myrtleford - Workshop	Susp\SHOCK ABS	replace steer shockers and rubbers			10/09/2020	277260	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOAD29	Myrtleford - Workshop	Body\PAINT/REST	wash truck			10/09/2020	277260	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOAD29	Myrtleford - Workshop	Body\AIR LEAK	air leak			10/09/2020	277260	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOAD29	Myrtleford - Workshop	Workshop\MOVE ASSET	take to Cummins			10/09/2020	277260	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOAD29	Myrtleford - Workshop	DriveLine\GEARBOX	replace g/stick bolt and bushes			05/09/2020	277259	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOAD29	Myrtleford - Workshop	DriveLine\CLUTCH	replace bell crank bearing lower			05/09/2020	277259	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOAD29	Myrtleford - Workshop	Body\PAINT/REST	wash truck adjust clutch free play			05/09/2020	277259	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOAD29	Myrtleford - Workshop	DriveLine\CLUTCH	clean soot mirror			05/09/2020	277259	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOAD29	Myrtleford - Workshop	Insp\INT INSP	fire extinguisher		fit fire ext	05/09/2020	277259	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOAD29	Myrtleford - Workshop	Body\PAINT/REST	wash truck			05/09/2020	277259	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOAD29	Myrtleford - Workshop	Elect\ELECT P&W	fit day time running lights (MAE)R9726			05/09/2020	277259	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOAD29	Myrtleford - Workshop	DriveLine\SUSPENSION	Replace all 4 front diff tie rod bushes			25/08/2020	277228	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOAD29	Myrtleford - Workshop	DriveLine\SUSPENSION	Replace all 4 rear diff tie rod bushes			25/08/2020	277228	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOAD29	Myrtleford - Workshop	DriveLine\SHOCK ABS	Replace 2 x rear drive shockers			25/08/2020	277228	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOAD29	Myrtleford - Workshop	DriveLine\TAIL SHAFT	Fit T-shaft centre bearing			25/08/2020	277228	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOAD29	Myrtleford - Workshop	Susp\HCV	Fit 2 x new rear suspension ride height valves R9553			25/08/2020	277228	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOAD29	Myrtleford - Workshop	Body\DAMAGE	repair RHS steps			22/08/2020	277228	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOAD29	Myrtleford - Workshop	DriCabRep\MOUNTS	replace cab ride height valve C Service			22/08/2020	277228	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOAD29	Myrtleford - Workshop	VehService\CS	210 000 C Service	VehService\CS		22/08/2020		Service	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOAD29	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		bonnet needs major repairs, fixed as best as possible replaced clutch rose joint, replaced bonnet guide roller tightened fan belts, replaced LHS bonnet blinker replaced leaking booster fitting RHD	22/08/2020	277228	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOAD29	Myrtleford - Workshop	VehService\BS	B Service As Per Attached Checklist	VehService\BS	replaced LHR booster	22/08/2020	277228	Service	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOAD29	Myrtleford - Workshop	Steering\DAMAGE	replace steering box and filter			20/08/2020	277157	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOAD29	Myrtleford - Workshop	Steering\DAMAGE	replace pitman arm			20/08/2020	277157	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOAD29	Myrtleford - Workshop	Susp\SWAYBAR	replace all rear sway bar bush			20/08/2020	277157	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOAD29	Myrtleford - Workshop	Steering\HOUSEKEEP	replace steering shaft			20/08/2020	277157	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOAD29	Myrtleford - Workshop	Steering\WHEEL ALGN	wheel align all 3 axles			20/08/2020	277157	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOAD29	Rosewood - Workshop	Tyres\CASE STOCK	Job Added From Invoice			24/07/2020	276502	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	Tyres\FITMENT	Job Added From Invoice			24/07/2020	276502	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	Tyres\CLEANSKIN	Job Added From Invoice			24/07/2020	276502	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	Body\HOUSEKEEP	unhold loader over pit and throw bonnet			18/07/2020	276535	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	DriveLine\CLUTCH	replace missing grease line to clutch bearing			18/07/2020	276635	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			18/07/2020	276635	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	VehService\AS	A Service	VehService\AS		18/07/2020	276635	Service	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	Susp\AIR BAG	replace RHF airbag			19/06/2020	273185	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	DrCabElect\INST/GAUGE	replace all dash globes, some were LED (green) some not working. All back to standard remove all piping associated with 2nd height valve, and valve itself (RHS) replace damaged piping and fitting plumb up LHS height valve to "single spec" so all bags are always running at the same pressures set height			19/06/2020	273185	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	DriveLine\SUSPENSION	re-strain all aixine			18/06/2020	273260	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	Susp\AIR BAG	replace RHF airbag			18/06/2020	273260	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	DriveLine\SUSPENSION	called out to Boomeroo, RH side airbags not inflating			17/06/2020	273210	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	DriveLine\SUSPENSION	repaired crossover pipe. Needs permanent fix			17/06/2020	273210	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	DriveLine\SUSPENSION	RHS airbags not pumping up			17/06/2020	273373	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	Body\HOUSEKEEP	basic check over			11/06/2020	273091	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	Body\CHN/RLR/MN	front grab bar need new hook for chain			04/06/2020	272331	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	Susp\HCV	height control valve right side		replace height control valves. These were full of oil and crude, tanks partially full of oil/water/soot	30/05/2020	272073	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	DriCabRep\AIR LEAK	yellow button leaking air			30/05/2020	272073	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	Susp\AIR BAG	replaced LHRF airbag. Damaged by driving before air built up			30/05/2020	272073	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Myrtleford - Workshop	DriCabRep\DOOR LOCK	driver side door catch not closing at times			20/05/2020	123405	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOAD29	Myrtleford - Workshop	DriCabRep\DOOR LOCK	door catch needs tightening			20/05/2020	123405	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOAD29	Rosewood - Workshop	DrCabElect\RADIO	UHF not working			16/05/2020	270488	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	DriCabRep\DOOR LOCK	short term fix on drivers door			16/05/2020	270488	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOAD29	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			16/05/2020	270488	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF

LOA029	Rosewood - Workshop	Tyres\DRV TYRES	pump up RHR outer tyre					01/05/2020	268691	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	DrivLine\SUSPENSION	adjust LH height control valve. May need replacement					01/05/2020	268691	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Tumut - Workshop	Elect\BATTERY	fit new battery					22/04/2020	6264	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
			pick up from Tumut															
LOA029	Tumut - Workshop	Elect\BREAKDOWN	take to Rosewood					22/04/2020	6264	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job					10/04/2020	265711	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	VehService\BS	B Service	VehService\BS				10/04/2020	265711	Service	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
					diagnose rear drive oil leak. Cleaned up													
					test drove found crack at rear top of diff housing													
					welded crack													
LOA029	Rosewood - Workshop	DrivLine\OIL LEAK	oil leak in drive line/diffs		topped up both diffs with oil			31/03/2020	263828	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Myrtleford - Workshop	DrCabElect\ELECT P&W	Supply Jumper Leads for loader					30/03/2020	264105	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOA029	Myrtleford - Workshop	DrCabReq\AIR LEAK	Supply air blow nozzle for cab					30/03/2020	264105	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOA029	Rosewood - Workshop	Engine\FAULT CODE	diagnose engine light coming on and missing at medium revs					10/03/2020	260949	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
			found codes 72,73& 74, all related to injector wiring															
			suspect bad wiring harness. Looked for obvious problems															
			cleaned connectors at rocker cover and ecm still no good															
LOA029	Rosewood - Workshop	Engine\FAULT CODE	oraanisine TCTC to attend with new harness					10/03/2020	260949	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Myrtleford - Workshop	Body\PAINT/REST	clean wheels and checker plate steps		test drove found crack at rear top of diff housing			19/02/2020	258397	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOA029	Myrtleford - Workshop	Body\REFLECTORS	fit tape to steps					19/02/2020	258397	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOA029	Myrtleford - Workshop	DrCabElect\INDICATORS	blinkers not working					18/02/2020	258359	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
			trace wiring fault															
LOA029	Myrtleford - Workshop	DrCabElect\INDICATORS	repair wirine and test - ok					18/02/2020	258359	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOA029	Myrtleford - Workshop	Body\MOUNTS	fix grill mesh					05/02/2020	258218	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOA029	Myrtleford - Workshop	Engine\HOUSEKEEP	move engine fan guard					05/02/2020	258218	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOA029	Myrtleford - Workshop	Elect\INDICATORS	RH bonnet indicator not working					05/02/2020	258218	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOA029	Rosewood - Workshop	Air Con\HEATER	raise PO for fan and servo					02/02/2020		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Wodonga Workshop	LOADER
LOA029	Myrtleford - Workshop	Air Con\AIR CON	Replace heater / air con control box in dash					29/01/2020	258254	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOA029	Myrtleford - Workshop	Body\DAMAGE	needs new bonnet					24/01/2020	258211	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOA029	Myrtleford - Workshop	DrCabReq\WIPERS	fit wiper blades					24/01/2020	258211	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOA029	Myrtleford - Workshop	DrCabReq\WINDOW REG	fit RH window winder		fit window handle			24/01/2020	258211	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOA029	Myrtleford - Workshop	Elect\ELECT P&W	repair lights		repair side light bracket			24/01/2020	258211	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOA029	Myrtleford - Workshop	Body\AIR FITTIN	make up drain cables		make up air tank drain cable			24/01/2020	258211	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOA029	Myrtleford - Workshop	Body\PAINT/REST	wash cab					24/01/2020	258211	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOA029	Myrtleford - Workshop	Workshop\MOVE ASSET	pick up loader					24/01/2020	258211	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOA029	Myrtleford - Workshop	Body\MOUNTS	fit grease gun holder					24/01/2020	258211	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOA029	Myrtleford - Workshop	Body\MOUNTS	weld thread for battery cover					24/01/2020	258211	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOA029	Myrtleford - Workshop	DrivLine\SUSPENSION	torque rod bushings					24/01/2020	258211	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOA029	Myrtleford - Workshop	Body\PAINT/REST	wash down under truck		truck wash			24/01/2020	258211	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOA029	Myrtleford - Workshop	Body\PAINT/REST	steam clean bonnet cabin					24/01/2020	258211	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOA029	Myrtleford - Workshop	Body\HOUSEKEEP	clean rear diff suspension					24/01/2020	258211	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOA029	Rosewood - Workshop	Brakes\AIR LEAK	repair air leak (rubbed pipe) under cab of truck					18/01/2020	257578	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Hydraulics\HOSES	have 2 hoses made		Travel to sight			18/01/2020		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Wodonga Workshop	LOADER
LOA029	Rosewood - Workshop	Air Con\HEATER	PO for fan assembly		TCTC			10/01/2020	257200	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Wodonga Workshop	LOADER
LOA029	Rosewood - Workshop	Elect\BATTERY	will working on A/C found battery needed replacing not holding charge					10/01/2020	257200	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Wodonga Workshop	LOADER
LOA029	Rosewood - Workshop	DrCabReq\DAMAGE	right hand mirror needs bolting on					17/12/2019	256145	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Hydraulics\RAM	repair/modify chain point grab housing					14/12/2019	255999	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job					14/12/2019	255999	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	VehService\AS	A Servicesupply 2 x new 10 stud rims	VehService\AS				14/12/2019	255999	Service	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Air Con\AIR CON	DIAGNOSE & REPAICE FAUTTLY CONDECER FAN					11/12/2019	255444	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Albury - Workshop	Air Con\AIR CON	REMOVED & REPLACED AIR CON HOSE					06/12/2019		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Myrtleford - Workshop	Workshop\MOVE ASSET	take across to Wodonga and then return					05/12/2019	254834	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOA029	Myrtleford - Workshop	DrCabElect\ELECT P&W	fit day time running lights					05/12/2019	254834	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOA029	Myrtleford - Workshop	Chassis\CHAS CRACK	weld up cracks in front bumper bar mount plates					05/12/2019	254834	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOA029	Myrtleford - Workshop	Brakes	5 cam tube/spider					05/12/2019	254834	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOA029	Myrtleford - Workshop	DrCabReq\WINDSCREEN	replace rear windeow and seal		check rear window ok			05/12/2019	254834	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOA029	Myrtleford - Workshop	Elect\TAIL LIGHT	LH REVERSE LIGHT BROKEN					05/12/2019	254834	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOA029	Myrtleford - Workshop	Elect\DRV LIGHT	need two driving lights					05/12/2019	254834	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOA029	Myrtleford - Workshop	DrivLine\SHOCK ABS	bottom shocker rubbers					05/12/2019	254834	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOA029	Myrtleford - Workshop	DrivLine\SUSPENSION	LHR bush		rear susp was done at TCTC			05/12/2019	254834	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOA029	Myrtleford - Workshop	Body\DAMAGE	deck cracked &(modify grag mount). deck cracked		RC done on another card			05/12/2019	254834	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOA029	Myrtleford - Workshop	Body\TOOLBOX	toolbox lid missing					05/12/2019	254834	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOA029	Myrtleford - Workshop	Air Con\AIR CON	aircondition not working					05/12/2019	254834	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOA029	Albury - Workshop	Workshop\MOVE ASSET	PICK FROM ALDONGA ENGINEERING					05/12/2019		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Albury - Workshop	Workshop\MOVE ASSET	DROP OF ALDONGA ENGINEERING					05/12/2019		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Albury - Workshop	Workshop\MOVE ASSET	PICK UP FROM ALDONGA					05/12/2019		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Myrtleford - Workshop	Susp\LTCH PACK	replaced airbag					04/12/2019	254834	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOA029	Myrtleford - Workshop	DrivLine\SUSPENSION	Replace front diff torque rod bush		replaced 6x torque rod bushes			29/11/2019	954819	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOA029	Myrtleford - Workshop	Body\ELECT P&W	Rewire gearbox pressure switch					29/11/2019	954819	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOA029	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					27/11/2019	254819	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
					replaced RHR booster													
					replaced RHR stack adjuster													
					shimmed s-cam repaired dash													
					am/fm radio repair UHF wiring roof lights wiring													
LOA029	Myrtleford - Workshop	VehService\AS	A Service As Per Attached Checklist	VehService\AS	reoaired too cab liahts			27/11/2019	254819	Service	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOA029	Myrtleford - Workshop	Steering\WHEEL ALIGN	wheel align all 3 axles					13/11/2019	254807	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOA029	Myrtleford - Workshop	DrivLine\SUSPENSION	Replace ride height rose joints		replaced ride height rods			13/11/2019	254807	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOA029	Myrtleford - Workshop	Elect\ELECT P&W	no brake lights					12/11/2019	254800	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOA029	Myrtleford - Workshop	Brakes\BOOSTER	RHF drive booster u/s					12/11/2019	254800	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOA029	Myrtleford - Workshop	DrivLine\SUSPENSION	LHF drive airbag leaking					12/11/2019	254800	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOA029	Myrtleford - Workshop	Elect\ELECT P&W	no reverse lights					12/11/2019	254800	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOA029	Myrtleford - Workshop	Body\AIR LEAK	leaking protection valve					12/11/2019	254800	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOA029	Myrtleford - Workshop	Brakes\AIR LEAK	replace steer brake hose					12/11/2019	254800	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
					fit kinggins to 2nd hand steer axle and fit 1 arm													
LOA029	Myrtleford - Workshop	DrCabElect\KING PIN	Fit 2nd hand 7.2 tonne steer axle		reline steer brakes			25/10/2019	254688	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOA029	Myrtleford - Workshop	Cooling\ENG FAN	Replace Horton,idler and alt pulleys and belts					25/10/2019	254688	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
			Remove engine and repair front timing chest oil leak		replace front intermediate plate													
LOA029	Myrtleford - Workshop	Engine\OIL LEAK	Repair rear main oil leak and remove head gasket		tune engine and change oil and filters			25/10/2019	254688	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOA029	Myrtleford - Workshop	Chassis\SUSPENSION	Repair Shock Mounts					19/10/2019	254688	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOA029	Myrtleford - Workshop	Insp\RWC COMP	repair items on nsw defect list					17/10/2019		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOA029	Rosewood - Workshop	Air Con\AIR CON	aircondition not working					04/10/2019	254173	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
					broken fitting in front of air tank remove broken fitting out of tank replace with pipe sealed													
					check for leaks													
LOA029	Tumut - Workshop	Chassis\AIR LEAK	fitting broken front of RHS air tank		travel to and from iob			01/10/2019	253901	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Workshop\MOVE ASSET	TRAVEL TO ROSEWOOD TO PICK UP FILTER & RETURNE					22/09/2019		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	VehService\BS	B SERVICE	VehService\BS				22/09/2019		Service	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Rosewood - Workshop	Body\DAMAGE	deck cracked					10/09/2019	252366	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Body\TOOLBOX	toolbox lid missing					10/09/2019	252366	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Body\HOUSEKEEP	no triangles in truck					10/09/2019	252366	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Tumut - Workshop	Engine\BELTS/TENS	engine belts slipping					04/09/2019	251569	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Steering\WHEEL ALIGN	pulls to the right and has a slight shake					04/09/2019	251569	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Body\TRL LEGS	legs pins and bushes need replacing					04/09/2019	251569	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	DrCabReq\WIPERS	driven side wiper blade marking window					04/09/2019	251569	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Engine\FAULT CODE	stop eng light on					04/09/2019	251569	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	DrCabReq\AIR LEAK	air leak between air tanks					04/09/2019	251569	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	DrCabReq\AIR LEAK	losing air somewhere					04/09/2019	251569	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Engine\FUEL TANK	transfer pump for diesel nozzel missing end					04/09/2019	251569	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Engine\ENG FAN	fan belts slipping					04/09/2019	251569	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	DrCabElect\UNIT/GAUGE	check engine light staying on					04/09/2019	251569	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Body\TOOLBOX	toolbox door is gone					04/09/2019	251569	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Steering\STEER UNI	steering has issues not working correctly					04/09/2019	251569	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Engine\FAULT CODE	check engine light is on					04/09/2019	251569	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Body\DAMAGE	tank steps need replacing/repair					04/09/2019	251569	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Elect\TAIL LIGHT	LHS tail light not working					04/09/2019	251569	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Air Con\AIR CON	a/c leaks water in cab					04/09/2019	251569	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Brakes\BRAKE ADJ	brake need adjusting					04/09/2019	251569	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Engine\FAULT CODE	check engine light keeps coming on					04/09/2019	251569	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Susp\SUSPENSION	truck suspension needs looking at. All over road					04/09/2019	251569	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Air Con\AIR CON	aircon leaks water all over floor					04/09/2019	251569	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Elect\DRV LIGHT	no driving lights					04/09/2019	251569	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Tyres\TYRES	no spare tyre					04/09/2019	251569	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Engine\BELTS/TENS	fan belt slipping a lot					04/09/2019	251569	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	DrCabElect\RADIO	Ipad charging port need replacing					04/09/2019	251569	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Elect\TAIL LIGHT	left rear tail lights not working					04/09/2019	251569	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Susp\Torque Rod	broken torque rod bolt right top front					04/09/2019	251569	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Elect\TAIL LIGHT	reverse light					04/09/2019	251569	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Body\TOOLBOX	door on toolbox					04/09/2019	251569	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Engine\BELTS/TENS	belts slipping on fan					04/09/2019	251569	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	DrCabElect\PHONE	needs new bracket for speaker for phone					04/09/2019	251569	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Elect\TAIL LIGHT	rear light bar hit by log bent					04/09/2019	251569	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Engine\FAULT CODE	engine stop light on					04/09/2019	251569	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Elect\DRV LIGHT	driving lights					04/09/2019	251569	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Elect\TAIL LIGHT	reverse lights					04/09/2019	251569	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Elect\DRV LIGHT	no driving lights holes in bonnet					04/09/2019	251569	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Steering\SUSPENSION	truck all over road interior light					04/09/2019	251569	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	DrCabElect\CONSUMABLE	half not working, steering wheel					04/09/2019	251569	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Steering\WHEEL ALIGN	off centre					04/09/2019	251569	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Chassis\AIR FITTIN	call out		remove and replace air drain valve			04/09/2019	251569	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
					call out to repair loose leg pin													
LOA029	Rosewood - Workshop	Hydraulics\RAM	pin on boom coming out		B7 in ute			13/08/2019	4918	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Workshop\MOVE ASSET	Move Assets					13/08/2019	4918	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Myrtleford - Workshop	Engine\ELECT P&W	repair eng harness and wiring		repower auto			12/08/2019	254688	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOA029	Myrtleford - Workshop	Air Con\AIR CON	repair a/con condensor		repower auto			12/08/2019	254688	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	C

LOA029	Rosewood - Workshop	DrivUnit\OIL SAMPLE	Checked both diffs for metal			30/06/2019		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
			Fit 2 new driving lights, wire up & check operation															
LOA029	Rosewood - Workshop	Elect\DRV LIGHT	Fabricate & weld on mounts to sost			22/06/2019	246430	Repair	Comoleted	Greenfreight Loaeine NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Elect\TAIL LIGHT	Fit 2 new reverse lights to P29, wire up & check operation			22/06/2019	246430	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Elect\WORK LIGHT	Fit work lights to boom undercarriage on P29			22/06/2019	246430	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Albury - Workshop	DrivCabRep\WIPERS	replaced L wiper arm			02/06/2019	244388	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Albury - Workshop	DrivUnit\SHOCK ABS	shockers pulled thru bottom mounts			02/06/2019	244388	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Albury - Workshop	DrivCabRep\MOUNTS	king pins worn			02/06/2019	244388	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Albury - Workshop	DrivUnit\SUSPENSION	tightened sway bar bolts			02/06/2019	244388	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Albury - Workshop	Elect\TAIL LIGHT	repaired tail light bar			02/06/2019	244388	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Albury - Workshop	Brakes\BRAKE ADJ	replaced brake hose			02/06/2019	244388	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Albury - Workshop	Engine\COMPRESSOR	replaced compressor inlet pipe			02/06/2019	244388	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Albury - Workshop	Engine\HOUSEKEEP	cleaned out intake pipes			02/06/2019	244388	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Albury - Workshop	Engine\AIR CLNR	requires air filter canister (housing)			02/06/2019	244388	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
			bottom front eng mount pates															
			rear of head exhaust mount cracked															
LOA029	Albury - Workshop	DrivCabRep\MOUNTS	power divider u/s rear ene mount lees u/s			02/06/2019	244388	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Albury - Workshop	Hydraulics\HOSES	RHR b/booster hose			02/06/2019	244388	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Albury - Workshop	DrivUnit\SHOCK ABS	bottom shocker rubbers			02/06/2019	244388	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Albury - Workshop	DrivUnit\SUSPENSION	LHR bush			02/06/2019	244388	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			02/06/2019	244388	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Albury - Workshop	VehService\BS	B Service	VehService\BS		02/06/2019	244388	Service	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Albury - Workshop	DrivCabRep\WIPERS	removed broken wiper arm, new arm ordered			30/05/2019	243118	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Albury - Workshop	DrivCabRep\SEAT	replaced drivers seat			09/05/2019	238893	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Albury - Workshop	Body\AIR LEAK	air leak rear end	leaking airbag		08/05/2019	238479	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Albury - Workshop	Body\AIR LEAK	replaced 3rd airbag on L side			08/05/2019	238479	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
			check over truck															
LOA029	Albury - Workshop	Insp\RWC COMP	found numerous defects			08/05/2019	238479	Repair	Comoleted	Greenfreight Loaeine NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
			repaired phone speaker bracket															
			5 liters engine oil															
LOA029	Albury - Workshop	DrivCabRep\RADIO	too us o/s fluid			08/05/2019	238479	Repair	Completed	Greenfreight Loaeine NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Albury - Workshop	Engine\FAULT CODE	engine stop light on			02/05/2019	237873	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Albury - Workshop	DrivCabRep\SEAT	seat stuffed			02/05/2019	237873	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Rosewood - Workshop	Elect\TAIL LIGHT	rear light bar hit by log bent			30/04/2019	237531	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
				check mic														
LOA029	Albury - Workshop	DrCabElect\PHONE	mic for phone	wirine has been butchered best ootion I recommend fittine a bluetooth hands free radio		17/04/2019	236484	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Albury - Workshop	DrCabElect\PHONE	bracket for phone speaker	check phone speaker u/s		17/04/2019	236484	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Rosewood - Workshop	Elect\TAIL LIGHT	reverse light			05/04/2019		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Body\TOOLBOX	door on toolbox			05/04/2019		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Engine\BELTS/TENS	belts slipping on fan			05/04/2019		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	DrCabElect\PHONE	needs new bracket for speaker for phone			05/04/2019		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Engine\HOUSEKEEP	check power steering oil level			05/04/2019		Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Brakes\BRAKE ADJ	brake adjust			05/04/2019		Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
			require new centre bearing															
LOA029	Rosewood - Workshop	Hydraulics\VALVES	advise Nich			04/04/2019	235110	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			04/04/2019	235110	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	VehService\AS	carry out A Service	VehService\AS		04/04/2019	235110	Service	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Steering\HOUSEKEEP	power steering needs oil			04/04/2019	235110	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	VehService\AS	A Service Due	VehService\AS		04/04/2019	235110	Service	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Albury - Workshop	DrivCabRep\WIPERS	left hand wiper broken			26/03/2019	233655	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
			adjusted alternator belts															
			and checked over															
LOA029	Albury - Workshop	Engine\ALT	tooped us hvd oil and checked for leaks			21/03/2019		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Albury - Workshop	Body\HOUSEKEEP	degreased and washed			20/03/2019		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
			cab shocker															
			cab dogbone															
			bumper rubber															
LOA029	Albury - Workshop	Susp\SHOCK ABS	cab shocker bolts were seized			19/03/2019	232902	Repair	Completed	Greenfreight Loaeine NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
			replaced torque rod bushes and set up with correct spacers															
			replaced front drive brake lines and secured all lines properly															
			compiled defect list															
LOA029	Albury - Workshop	Susp\Torque Rod	removed and plugged air filter informer			19/03/2019	232902	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Albury - Workshop	Susp\Torque Rod	removed covers and pressure washed inside chassis. Replaced broken torque rod mounts and torque rods			17/03/2019		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Rosewood - Workshop	Susp\Torque Rod	replace broken torque rod bolt and secure as best I could for travel to Albury workshop			16/03/2019		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Albury - Workshop	Susp\SUSPENSION	wash down for suspension repaires			16/03/2019		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Rosewood - Workshop	Elect\WORK LIGHT	clearance lights, replace/rewire 2 side markers			14/03/2019	232779	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Chassis\CROSS MBR	check and order broken cross member brace			14/03/2019	232779	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Elect\TAIL LIGHT	tail light, replace and check wiring			14/03/2019	232779	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Susp\Torque Rod	torque rod bolt broken	replace broken torque rod bush		07/03/2019	232231	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Elect\EJECT P&W	SIDE CLEARANCE LIGHTS NOT WORKING			27/02/2019 0		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Elect\TAIL LIGHT	LEFT REAR TAILIGHTNOT WORKING			27/02/2019 0		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Engine\BELTS/TENS	fit engine fan belt			26/02/2019		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Air Con\AIR CON	fit a/c fan belt			26/02/2019		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Steering\STEER UNI	Steer Shaft Uni	FIT UP STEERING ARM WITH TIE ROD END, FIT INTO TRUCK TEST DRIVE ADJUST TOE OUT		19/02/2019		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Albury - Workshop	Brakes\BRK RELINE	RELINE STEER BRAKES			15/02/2019		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Albury - Workshop	Steering\HOUSEKEEP	repaired damaged stub axles			13/02/2019		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Albury - Workshop	Steering\TIE ROD	removed troublesome tie-rod end			13/02/2019		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Albury - Workshop	Chassis\KING PIN	replaced kingpin bushes and reamed to fit pins			13/02/2019		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Albury - Workshop	DrivUnit\OIL LEAK	replaced seals			13/02/2019		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Albury - Workshop	Workshop\MOVE ASSET	packaged and loader for Rosewood workshop			13/02/2019		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Rosewood - Workshop	Susp\Torque Rod	torque rod bolts	broken bolts in torque rods		09/02/2019		Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
			called out to "long point", loader truck broken torque rod bolts on RH side, diff end															
			packed up trailer with supplier for repair and headed out															
			headed to breakdown and repaired bolts (housing very difficult to align)															
LOA029	Rosewood - Workshop	Susp\Torque Rod	uoon arrival driver informed us of hydraulic lieak. this reouired return to workshoo for oil. return and too uo			02/02/2019		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	VehService\DS	D Service			29/01/2019		Service	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Workshop\MOVE ASSET	travel to Tumut remove bolts from slew motor on L26 travel too Wvanele Rd fit bots tiehten the rest wait while loaded trucks slew motor loose aeain follow to Tumut vard lone oize			29/01/2019		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
			check into complaint of horrible steering															
			check rear suspension and chassis condition															
			check steering															
			test drive on way out to bush															
LOA029	Rosewood - Workshop	Steering\STEER UNI	-vehicle to return to workshop for fusther checks			23/01/2019		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
				check belts, a/c belts cracked, repticed														
LOA029	Rosewood - Workshop	Engine\BELTS/TENS	belts slipping	horton belts serviceable and tensioned ok		18/01/2019	227590	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Susp\AIR BAG	check left rear airbags look like they are bent up where air line goes in	replace all broken bolt's in rear diff arm bushs and push the diff axle across 2 inch's to remove airbag rubbing on rear tyre		11/01/2019	226990	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Steering\STEER UNI	replace steering uni-joints			04/01/2019	225918	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Elect\TAIL LIGHT	check and repair inoperative park light. Bad connection			04/01/2019	225918	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Susp\HCV	check ride height. Check seems ok			04/01/2019	225918	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Air Con\AIR CON	set up and pack up for subbie a/c repairs			04/01/2019	225918	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Body\MOUNTS	retighten body mounts on loader and reweld nuts back on			28/12/2018	236200	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Body\AIR LEAK	repaired air leak from air tank under truck			18/12/2018	225423	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Engine\FUEL TANK	Fuel Tank & System	remove tank take into tumba to get repaired and refit tested ok.		14/12/2018	220654	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Steering\SUSPENSION	remove outer boom row for eye bush repairs			12/12/2018		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
				pack ute for breakdown/ broken suspension bolts														
LOA029	Rosewood - Workshop	Susp\SUSPENSION	Suspension	drive to maraele and reolace bottom suspension bolts drive back to rosewood		06/12/2018		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Albury - Workshop	Elect	Job Added From Invoice			23/11/2018 0		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Albury - Workshop	Tyres\CASE STOCK	Job Added From Invoice			21/11/2018 219568		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice			21/11/2018 219568		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice			21/11/2018 219568		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Wodonga - Workshop	VehService\AS	A service due	VehService\AS		19/11/2018 0		Service	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Wodonga Workshop	LOADER
LOA029	Rosewood - Workshop	Susp\SUSPENSION	axel sitting out	found broken bolts on the rear diff arm RHS loose bottom sway bar and diff arms everythine reset where it should nothine bond . reolace bolts in diff arm bushes refit and		07/11/2018 20005		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Brakes\BOOSTER	Booster	air leak bolster fitting		06/11/2018 219720		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
				blown out tyres														
				replace 2x airbags R/H/R and R/H/M and replace shock absorber														
LOA029	Rosewood - Workshop	Susp\AIR BAG	2x airbags right rear and tyre shock	tested ok		02/11/2018 219568		Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Albury - Workshop	DrivUnit\DAMAGE	TYRE DAMAGE			02/11/2018		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Rosewood - Workshop	Elect\TAIL LIGHT	Tail Light	replace rear light combo		01/11/2018		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Engine\MOUNTS	replace R/H/F engine mount			20/10/2018 215033		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Brakes\BRAKE ADJ	adjusted brakes			20/10/2018 215033		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Albury - Workshop	Engine	Job Added From Invoice			20/10/2018 0		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Rosewood - Workshop	Engine\MOUNTS	replace engine mount (rear) bolt seized in the mount got bolt to move replace L/H/R			18/10/2018 217551		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Albury - Workshop	Brakes	Job Added From Invoice			17/10/2018 0		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Rosewood - Workshop	Susp\AIR BAG	airbag R/H/M	replace airbag R/H/M		13/10/2018 217087		Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	VehService\AS	Service	VehService\AS		26/09/2018 215453		Service	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Susp\SUSPENSION	tighten rear suspension bolts			26/09/2018 215453		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Body\HOSES	tighten R/H/R and L/H/F s-cam tubes			26/09/2018 215453		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Wash\WASH	wash down deck			26/09/2018 215453		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			26/09/2018 215453		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Albury - Workshop	DrivUnit\CLUTCH	REPLACE ROSE JOINTS AND BELL CRANK BEARINGS			15/09/2018		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
				REPAIR SHORT IN RH HEAD LIGHT														
				repair wiring to R headlight														
				replaced H4 plug														
LOA029	Rosewood - Workshop	Elect\HEAD LIGHT	RHS low beam flashes on sometimes	reolace 60/58 H4 elobe		15/09/2018 214469		Fault	Completed	Greenfreight Loaeine NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshoa	LOADER
LOA029	Rosewood - Workshop	Elect\HEAD LIGHT	short in R/H headlight			15/09/2018 214469		Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Elect\EJECT P&W	repair mark light			15/09/2018 214469		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Susp\SUSPENSION	push in bushs for diff arms x4			12/09/2018		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Brakes\BRK RELINE	RELINE DRIVE BRAKES	relines		05/09/2018 214254		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Susp\SUSPENSION	repalce torque rod bushes and sway bar bushes			05/09/2018 214254		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	DrivUnit\AIR LEAK	REPLACE SPLITTER HOSES			05/09/2018 214254		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Susp\SUSPENSION	Suspension	replace 4 diff arms		05/09/2018 214254		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Susp\SWAYBAR	Swaybar/Screwpin	replace 4 bottom sway bar bushes refit tested ok		05/09/2018 214254		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Susp\SHOCK ABS	Shock Absorber	replace 3x bottom shock rubbers		05/09/2018 214254		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	VehService\CS	VehService\CS	start C service (drain diff oils and replace with new oils)	VehService\CS	05/09/2018 214254		Service	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Brakes\BRAKE ADJ	Brake need adjusting.			01/09/2018		Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Tumut - Workshop	Brakes\BRAKE ADJ	BRAKE ADJ.			01/09/2018 214180		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Rosewood - Workshop	Tyres	Job Added From Invoice			24/07/2018 0		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Tyres\FITMENT	Job Added From Invoice			24/07/2018 0		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Tyres\RETREAD	Job Added From Invoice			24/07/2018 0		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Albury - Workshop	Brakes\BOOSTER	REPLACE RHF BRAKE BOOSTER			13/07/2018 212397		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Albury - Workshop	Brakes\BOOSTER	Front right brake booster broken	replace broken booster		13/07/2018 212397		Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Albury - Workshop	Hydraulics\HYD LEAKS	top up hydraulic oil			13/07/2018 212397		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Albury - Workshop	Workshop	Job Added From Invoice			11/07/2018 0		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Rosewood - Workshop	Elect\HEAD LIGHT	RHS low beam flashes on sometimes			09/07/2018 211984		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	VehService\BS	truck 2000 kms over service	VehService\BS		09/07/2018 211984		Service	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
				Replaced speed sensor														
LOA029	Rosewood - Workshop	DrCabElect\INST

					weld cracks deck																
					remove broken plate from under deck																
LOAD29	Rosewood - Workshop	Chassis\CHAS CRACK	cracks in the deck		reweld old piece		23/06/2018 210616	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Rosewood - Workshop	Elect\BATTERY	replaced batteries		refer to job#175508		20/06/2018 210315	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Rosewood - Workshop	Elect\BATTERY	batteries need replacing have to jump start		replaced batteries		20/06/2018 210315	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Rosewood - Workshop	Elect\HEAD LIGHT	RHS outer headlight loose jumping around				20/06/2018 210315	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Albury - Workshop	Elect\BATTERY	REPLACE BATTERIES, HOLD DOWN CLAMP AND TERMINALS				20/06/2018 210380	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER					
LOAD29	Rosewood - Workshop	Tyres\STEER TYRE	Job Added From Invoice				19/05/2018 206822	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Rosewood - Workshop	Tyres\FITMENT	Job Added From Invoice				19/05/2018 206822	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Rosewood - Workshop	Tyres\STEER TYRE	Job Added From Invoice				12/05/2018 206093	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Rosewood - Workshop	Tyres\FITMENT	Job Added From Invoice				12/05/2018 206093	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Rosewood - Workshop	Elect\INDICATORS	no blinkers		no indicators		08/05/2018 206186	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
			check fuses, flasher can																		
			eventually L started working, R not work																		
			unload prentice, throw bonnet and check wiring																		
			locate fault in L front indicator, bypass wiring																		
LOAD29	Rosewood - Workshop	Elect\EJECT P&W	resuires wirine to be resained				08/05/2018 206186	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Rosewood - Workshop	VehService\AS	A Service Due	VehService\AS			04/05/2018 205924	Service	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job				26/04/2018 204864	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Rosewood - Workshop	Body\AIR LEAK	repair air leak for the spitter line				26/04/2018 204864	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Rosewood - Workshop	Elect\WORK LIGHT	Replace work light				26/04/2018 204864	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Rosewood - Workshop	VehService\AS	A Service	VehService\AS			26/04/2018 204864	Service	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Rosewood - Workshop	VehService\CS	210 000 C Service	VehService\CS			26/04/2018 204864	Service	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Rosewood - Workshop	Brakes\BRAKE ADJ	Brakes need adjusting		Brake adjusted		25/04/2018 204750	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Rosewood - Workshop	Brakes\BOOSTER	Replaced L/F booster				25/04/2018 204750	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
			Tightened L rear sway bar.																		
LOAD29	Rosewood - Workshop	Susp\SWAYBAR	Reslaced bolts				25/04/2018 204750	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Rosewood - Workshop	Tyres	Job Added From Invoice				17/04/2018 0	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Rosewood - Workshop	Tyres\FITMENT	Job Added From Invoice				17/04/2018 0	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Rosewood - Workshop	Tyres\RETREAD	Job Added From Invoice				17/04/2018 0	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Rosewood - Workshop	Susp\AIR BAG	leaning to left in airbags		truck leaning to left		30/03/2018 201589	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Rosewood - Workshop	Susp\HCV	height control valve bracket was bent straighten bracket to the best I could get. Test ok				30/03/2018 201589	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
					broken booster fitting																
					replace broken fitting. Met truck at Motel. Replaced elbow																
LOAD29	Rosewood - Workshop	Brakes\BOOSTER	replace broken fitting of RF booster		tests OK		30/03/2018 201434	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Rosewood - Workshop	Steering\OIL LEAK	repair power steering leak				24/03/2018 200995	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Rosewood - Workshop	Body\MOUNTS	tightened R bonnet mount bolt				24/03/2018 200995	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Rosewood - Workshop	Susp\SUSPENSION	replaced bolt on L steer sping				24/03/2018 200995	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job				24/03/2018 200995	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Rosewood - Workshop	VehService\AS	A Service	VehService\AS			24/03/2018 200995	Service	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Rosewood - Workshop	Engine\FAULT CODE	check engine light keeps coming on				21/03/2018 200438	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Rosewood - Workshop	Tyres	Job Added From Invoice				20/03/2018 0	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Rosewood - Workshop	Tyres\FITMENT	Job Added From Invoice				20/03/2018 0	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Rosewood - Workshop	Tyres\RETREAD	Job Added From Invoice				20/03/2018 0	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Rosewood - Workshop	Elect\TAIL LIGHT	check reverse light not working				17/03/2018 200168	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Rosewood - Workshop	VehService\AS	A Service Due	VehService\AS			17/03/2018 200168	Service	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Rosewood - Workshop	Tyres\DRV TYRES	Change tyre				14/03/2018 199100	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Rosewood - Workshop	DrCabRep\RADIO	Phone not working, they can't hear you		Repair broken wires to phone mic		03/03/2018 198254	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Rosewood - Workshop	Brakes\BRAKE ADJ	Brake adjustment				03/03/2018 198254	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Rosewood - Workshop	Body\MOUNTS	Tighten R/F top shocker mount				03/03/2018 198254	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Rosewood - Workshop	Susp\SHOCK ABS	repair shock mount and replace bolts				03/03/2018 199017	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Rosewood - Workshop	DrCabRep\RADIO	repair phone mic				03/03/2018 199017	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Rosewood - Workshop	Brakes\BRAKE ADJ	brake adjustment				03/03/2018 199017	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Albury - Workshop	Elect\DRV LIGHT	need two driving lights				15/02/2018 196282	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER					
					remove broken reverse light																
LOAD29	Albury - Workshop	Elect\TAIL LIGHT	LH REVERSE LIGHT BROKEN		order new light		15/02/2018 196282	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER					
LOAD29	Rosewood - Workshop	Chassis\AIR TANKS	airline out of air tank under drivers side		replace broken fitting in air tank		09/02/2018 195514	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Rosewood - Workshop	Steering\STEER UNI	requires drag link				03/02/2018 194854	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Rosewood - Workshop	VehService\BS	B Service	VehService\BS			03/02/2018 194854	Service	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
					Replace drag link																
LOAD29	Rosewood - Workshop	Steering\STEER UNI	requires drag link		Old draw link hood alav in ball joint uo/down		03/02/2018 195672	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Rosewood - Workshop	Engine\FILTERS	filters				03/02/2018 195672	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Rosewood - Workshop	VehService\BS	B Service	VehService\BS			03/02/2018 195672	Service	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Albury - Workshop	VehService\BS	B Service Due	VehService\BS			03/02/2018 194854	Service	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER					
			check oil																		
LOAD29	Rosewood - Workshop	DrivLine\OIL LEAK	added 4 liters				30/01/2018 194094	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Albury - Workshop	Susp\SHOCK ABS	REPLACE RR SHOCKER				16/01/2018 192232	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER					
LOAD29	Albury - Workshop	Brakes\BACK PLATE	REPLACED 2X SET OF BACKING PLATES				16/01/2018 192232	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER					
LOAD29	Rosewood - Workshop	Tyres	Job Added From Invoice				13/01/2018 0	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Rosewood - Workshop	Tyres\FITMENT	Job Added From Invoice				13/01/2018 0	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Rosewood - Workshop	Tyres\RETREAD	Job Added From Invoice				13/01/2018 0	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
					refit R bonnet spring																
					adj. bonnet dick																
LOAD29	Albury - Workshop	VehService\AS	A SERVICE	VehService\AS	reslaced L/F shockers		23/12/2017 190322	Service	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER					
LOAD29	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				23/12/2017 190322	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER					
LOAD29	Rosewood - Workshop	Tyres	Job Added From Invoice				22/12/2017 0	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Rosewood - Workshop	Tyres\STEER TYRE	Job Added From Invoice				22/12/2017 0	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Rosewood - Workshop	Tyres\FITMENT	Job Added From Invoice				22/12/2017 0	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Rosewood - Workshop	Tyres\RETREAD	Job Added From Invoice				22/12/2017 0	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
					CALL OUT.																
LOAD29	Albury - Workshop	Body\AIR LEAK	AIR LEAK FROM AIR TANK NEEDS REPAIRING		REPLACED DAMAGED FITTING ON RH TANK.		22/12/2017 190277	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER					
LOAD29	Rosewood - Workshop	DrivLine\AIR LEAK	repair air leak on drive				20/12/2017 189781	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
					repaird rubbed brake hose, no hoses in stock. Fitted joiner																
					ordering hoses																
LOAD29	Rosewood - Workshop	Brakes\BRAKE ADJ	adjust drive brakes		brake adi		20/12/2017 189781	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Rosewood - Workshop	Tyres\STEER TYRE	Job Added From Invoice				16/12/2017 188625	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Rosewood - Workshop	Tyres\FITMENT	Job Added From Invoice				16/12/2017 188625	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
			P/S leak at pump																		
			pressure port on pump possibly stripped. Removed fitting change O'ring. Test still leaking																		
			removed again and fitted new O-ring - thread tape																		
LOAD29	Rosewood - Workshop	DrivLine\AIR LEAK	test oil. Will monitor				12/12/2017 88200	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Rosewood - Workshop	Engine\FAULT CODE	check engine light comes on sometimes		check for code & faults. No codes		02/12/2017 186877	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Rosewood - Workshop	Engine\FUEL TANK	transfer pump for diesel nozzel missing end		requires new transfer fuel nozzel		02/12/2017 186877	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Rosewood - Workshop	Body\TOOLBOX	toolbox door fell off		refit tool box door		02/12/2017 186877	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
					replace broken shock																
LOAD29	Albury - Workshop	Susp\AIR BAG	AIR BAG AND SHOCKER BROKEN		reolace air bae		28/11/2017 186058	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER					
LOAD29	Rosewood - Workshop	Body\CONSUMABLE	Radial Seal - Mirror Spotter				18/11/2017	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	TWIN CITY TRUCK CENTRE - 4 - OLD	LOADER					
LOAD29	Albury - Workshop	Elect\EJECT P&W	LHS parker not working		REPLAIR HEAD LIGHTS		18/11/2017 185398	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER					
LOAD29	Rosewood - Workshop	Elect\HEAD LIGHT	LHS hi beam not working				16/11/2017	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Rosewood - Workshop	DrCabRep\AIR LEAK	losing air somewhere				16/11/2017	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Rosewood - Workshop	Elect\HEAD LIGHT	hi beam light in dash don't work				16/11/2017	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Rosewood - Workshop	Body\LIGHTS	replace headlight globe/check wiring				16/11/2017	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job				12/11/2017 184825	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
					fix power steer leak																
LOAD29	Rosewood - Workshop	VehService\BS	Service Due	VehService\BS	trahten suspension		12/11/2017 184825	Service	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
					L high beam not working																
LOAD29	Rosewood - Workshop	Body\LIGHTS	LHS hi beam not working		reslaced alobe		10/11/2017 184752	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Rosewood - Workshop	Workshop\W/S MAINT	take to Tumbarumba to clear defects				04/11/2017	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Albury - Workshop	Brakes\BRK RELINE	RELINE DRIVE BRAKES				04/11/2017	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER					
LOAD29	Rosewood - Workshop	Brakes\BRK RELINE	reline				03/11/2017	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Rosewood - Workshop	Body\AIR BAG	replace 6 airbags				03/11/2017	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Tumut - Workshop	Body\AIR FITTIN	Spring Assembly - Airbags x 6				02/11/2017	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	TWIN CITY TRUCK CENTRE - 4 - OLD	LOADER					
			replace v-stay bushs																		
LOAD29	Rosewood - Workshop	Susp\SWAYBAR	reelace sway bar bushes				02/11/2017	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Albury - Workshop	Brakes\BRAKE ADJ	ADJUST DRIVE BRAKES				31/10/2017	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER					
					call out to Albury Depot																
					diagnose and replace alternator																
					jump start																
LOAD29	Albury - Workshop	Elect\ALT	REPLACE ALTERNATOR		test		26/10/2017 182719	Fault	Completed						Albury Workshop	LOADER					
			purchase s/hand bonnet due to been hit by cow																		
LOAD29	Rosewood - Workshop	Body\PANELS	use as parts to make one good bonnet		truck taken to Shepp Motors to be fixed bonnet badly damaged		12/10/2017 182540	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Wodonga Workshop	LOADER					
			Accident damage to RH Side bonnet																		
			Quote from Rovers $5500 for s/hand bonnet then repairs on top of this																		
LOAD29	Wodonga - Workshop	Body\PANELS	Bonnet found at UTW				06/10/2017	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Wodonwa Workshop	LOADER					
LOAD29	Rosewood - Workshop	Workshop\MOVE ASSET	pick up with Chris after it hit low				29/09/2017	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Rosewood - Workshop	Chassis\AIR LEAK	air leak air tank prime mover				20/09/2017		Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Rosewood - Workshop	Tyres\RUN OUT	Job Added From Invoice				14/09/2017 0	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Tumut - Workshop	Brakes\BRK RELINE	Brake reline		twin city - 484019		15/08/2017	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER					
LOAD29	Wodonga - Workshop	Brakes\BRK RELINE	Brake reline		Twin city - 484019		15/08/2017	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Wodonga Workshop	LOADER					
LOAD29	Rosewood - Workshop	Tyres\DRV TYRES	Adjusted drive brakes				11/08/2017 179360	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Rosewood - Workshop	DrivLine\WHEEL SEAL	found leaking hub seal RHR drive				11/08/2017 179360	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Rosewood - Workshop	Brakes\BRK RELINE	replaced RHR drive brakes, scam bushes x2 scam seals x2 and hub seal x1				11/08/2017 179360	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Tumut - Workshop	Engine\FILTERS	Work performed by Twinsity - 482471				01/08/2017	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER					
LOAD29	Rosewood - Workshop	VehService\BS	Loader due for service	VehService\BS	Strobe light broken - to be replaced		26/07/2017	Service	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Tumut - Workshop	Elect\EJECT P&W	sensor gp gr		Twin city 481104		22/07/2017	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER					
LOAD29	Tumut - Workshop	Elect\EJECT P&W	Hi low beam insert		twin city - 481532		20/07/2017	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER					
LOAD29	Tumut - Workshop	DrCabRep\WIPERS	arm wiper and blade assy		twin city - 481532		20/07/2017	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER					
LOAD29	Tumut - Workshop	Elect\EJECT P&W	lengthened and repaired wiring for pressure sensor		work performed by tumut auto elec - 00172527		19/07/2017	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER					
LOAD29	Tumut - Workshop	Elect\EJECT P&W	Work performed by Tumut electrics		00172520		18/07/2017	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER					
			sensor gp																		
LOAD29	Tumut - Workshop	Elect\EJECT P&W	seal - o rine				18/07/2017	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER					
LOAD29	Tumut - Workshop	Elect\EJECT P&W	sender pressure		order # 481108		15/07/2017	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER					
			travel to rosewood depot and inspect low oil pressure, connect mechanical gauge																		
			drain engine oil , remove oil pan, remove oil pump, disassemble and inspect, found wear internally in pump																		
			remove stiffner plate, remove 2 main and 2 ends for inspection, all ok. Refit and tension mains and big ends, clean parts, fit new oil pump and oil pressure sender. Refit stiffener																		
			plate, oil pan and refill with oil																		
			Fit new oil filter, start and run engine, all ok - check over for leaks																		
LOAD29	Rosewood - Workshop	Engine\OIL LEAK	pack up tooling and complete paperwork. Travel back to Tumut.		Express truck service		07/07/2017	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Tumut - Workshop	Elect\EJECT P&W	find fault with sensor		tumut electrics - 00172561		05/07/2017	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER					
LOAD29	Wodonga - Workshop	Chassis\AIR TANKS	front air tank not building up		truck had air issue where front tank wouldn't build up drained tanks as best as I could - a lot of metal and debri in tanks had to remove main supply to tank and clean out		04/07/2017 1756445	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Wodonga Workshop	LOADER					
LOAD29	Rosewood - Workshop	Engine\FAULT CODE	stop eng light on				04/07/2017 175708	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER					
LOAD29	Tumut - Workshop	Brakes\BRK RELINE	Relign steer brakes				24/06/2017	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER					
LOAD29	Tumut - Workshop	Tyres	Job Added From Invoice				17/06/2017 0	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	T

LOA029	Tumut - Workshop	Susp\SHOCK ABS	rear shock rubber and washer					25/05/2017	171167	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Elect\ELECT P&W	RHS low beam not working					24/05/2017	170989	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Elect\ELECT P&W	LHS parker not working					24/05/2017	170989	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Elect\ELECT P&W	LHS blinker c.p. interior light not working					24/05/2017	170989	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Tyres\RUN FLAT	Job Added From Invoice					08/05/2017	169740	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job					02/05/2017	169650	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	VehService\BS	Service	VehService\BS				02/05/2017	169650	Service	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Tumut - Workshop	Tyres\TP03	Job Added From Invoice					04/03/2017	164015	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Rosewood - Workshop	DrCabRep\WINDSCREEN	replace rear window and seal			rosewood w/shop		31/01/2017		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Tumut - Workshop	Tyres\TP01	Job Added From Invoice					26/01/2017	159876	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Tyres\TP02	Job Added From Invoice					26/01/2017	159876	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Rosewood - Workshop	Engine\COOL LEAKS	repair coolant leak					26/01/2017	160384	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Body\MOUNTS	tension engine mounts					26/01/2017	160384	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Body\SUSPENSION	tension suspension					26/01/2017	160384	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	VehService\AS	service	VehService\AS				26/01/2017	160384	Service	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Elect\ELECT P&W	repair wiring to work lights ,clean battery terminals and replace corroded onesw			Tumut auto electrics 21-12-16		12/01/2017		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	DrCabRep\WINDSCREEN	REPLACE WIND SCREEN			OBRIEANS GLASS WAGGA 30-12-16		11/01/2017		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Albury - Workshop	DrivLine\CLUTCH	Replace ball crank bearings and adjust clutch					04/01/2017	158396	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Albury - Workshop	Body\HOUSEKEEP	Tighten bolts between J brackets					04/01/2017	158396	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Albury - Workshop	Body\FUEL TANK	Replace bolt and remount fuel lines to bell housing					04/01/2017	158396	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Albury - Workshop	Body\PANELS	repair damaged tail light bar mount			welded mount back on & refit bar		04/01/2017	158396	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Albury - Workshop	DrCabRep\HOUSEKEEP	Replace AC cab filter					04/01/2017	158396	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
						replaced washer motor and required nozzels												
LOA029	Albury - Workshop	DrCabRep\WIPERS	Repair washers and wipers			tightened, bushed, and adjusted mechanism		04/01/2017	158396	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
						replaced quick release valve												
LOA029	Albury - Workshop	Brakes\AIR LEAK	Air leak in steer service brakes			repaired air line		04/01/2017	158396	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
			Replace LR booster															
LOA029	Albury - Workshop	Brakes\AIR LEAK	Reolace resuired brake hoses					04/01/2017	158396	Repair	Completed	Greenfreight Lowene NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
			Replace all rear drive torque rod bushes.															
			Tightened front sway bar bolts.															
			Replace RH HCV															
LOA029	Albury - Workshop	Susp\SUSPENSION	Reolace RR missine shocker					04/01/2017	158396	Repair	Completed	Greenfreight Lowene NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
						drain air tanks												
						fit drain lock to wet tank												
						replaced leaking pressure relief valve												
LOA029	Albury - Workshop	Brakes\AIR LEAK	Air leak under cab			tidy airlines away from tank		04/01/2017	158396	Fault	Completed	Greenfreight Lowene NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Albury - Workshop	Cooling\COOL LEAKS	Coolant leak			tightened up radiator hose and top up.		04/01/2017	158396	Repair	Completed	Greenfreight Lowene NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Albury - Workshop	Elect\HEAD LIGHT	RH driving light not working			repaired wiring		04/01/2017	158396	Repair	Completed	Greenfreight Lowene NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Rosewood - Workshop	Susp\SHOCK ABS	Replace shock absorbers			rosewood w/shop		30/12/2016		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Tumut - Workshop	Susp\SHOCK ABS	REPLACE SHOK ABSORBER MOUNT			ROSEWOOD W/SHOP		22/12/2016		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Tyres\TP05	Job Added From Invoice					15/12/2016	156831	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Tyres\TP09	Job Added From Invoice					15/12/2016	156831	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Rosewood - Workshop	Susp\AIR BAG	replace leaking air bags			Rosewood w/shop		14/12/2016		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	DrCabElect\RADIO	remove and replace old stero unit			Tumut auto electrics 25-11-16		08/12/2016		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Susp\SHOCK ABS	replace shoky mount and rubbers,fit new air filter			Rosewlk/shop		29/11/2016		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	VehService\BS	B service	VehService\BS				25/11/2016	154620	Service	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Elect\ELECT P&W	remove replace interior light			tumut auto electrics 21-10-16		23/11/2016		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Elect\WORK LIGHT	remove and replace work lights and repair stereo			Tumut auto electrics 21-10-16		23/11/2016		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Body\AIR BAG	remove & replace RHF & RHR airbags					15/11/2016		Repair	Completed	Greenfreight Lowene NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	DrivLine\SHOCK ABS	replace RH drive shock absorber					15/11/2016		Repair	Completed	Greenfreight Lowene NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Elect\ELECT P&W	boom lights go out and come back on in about 5 min but go out again					15/11/2016		Fault	Completed	Greenfreight Lowene NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Elect\CLAIMS	find low voltage fault ,replaced loom plugs			Tumut auto electrics this job has already been raised		08/11/2016		Repair	Completed	Greenfreight Lowene NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Tumut - Workshop	Tyres\TP06	Job Added From Invoice					04/11/2016	0	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Rosewood - Workshop	Elect\ELECT P&W	find and repar electrical fault			Tumut Auto electrical		26/10/2016		Repair	Completed	Greenfreight Lowene NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Elect\ELECT P&W	find fault and repair in alternator			Tumut Auto electrics 18-10-16		26/10/2016		Repair	Completed	Greenfreight Lowene NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	VehService\AS	A Service	VehService\AS				15/10/2016	150200	Service	Completed	Greenfreight Lowene NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Brakes	check and record brakes					15/10/2016	150200	Repair	Completed	Greenfreight Lowene NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Susp\SHOCK ABS	Replace drive shock absorbers			Rosewood W/ shop		15/10/2016		Repair	Completed	Greenfreight Lowene NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	VehService	service due					13/10/2016		Fault	Completed	Greenfreight Lowene NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Elect\HEAD LIGHT	RHS high beam light flashing on and off					13/10/2016		Fault	Completed	Greenfreight Lowene NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	DrCabElect\INST/GAUGE	lighter power socket not working					13/10/2016		Fault	Completed	Greenfreight Lowene NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
			front axle left and right shocks															
LOA029	Rosewood - Workshop	DrivLine	A Service					11/10/2016	149958	Fault	Completed	Greenfreight Lowene NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Albury - Workshop	Tyres\TP05	Job Added From Invoice					30/09/2016	148342	Repair	Completed	Greenfreight Lowene NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Rosewood - Workshop	Engine	repair coolant leak					30/09/2016	148929	Repair	Completed	Greenfreight Lowene NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Body	patched together in bush with clamp					30/09/2016	148929	Repair	Completed	Greenfreight Lowene NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Engine	got it to depot & replaced hose					30/09/2016	148929	Repair	Completed	Greenfreight Lowene NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Engine	repair alternator wiring					28/09/2016	148538	Repair	Completed	Greenfreight Lowene NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Albury - Workshop	Engine	truck wont start			old job		22/09/2016	148288	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Albury - Workshop	Engine\FAULT CODE	Check engine light comes on all the time					22/09/2016	148288	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
						valve set												
						jake overhaul												
LOA029	Albury - Workshop	Engine\ENG TUNE	Engine tune up. bikes soft and ticking noise in engine			as oer attached invoice		22/09/2016	148288	Fault	Completed	Greenfreight Lowene NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Albury - Workshop	Body\HOUSEKEEP	box for chain unsafe sitting on deck			fit extensions to chain retainer frame		22/09/2016	148276	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Albury - Workshop	Chassis\CHAS CRACK	Weld up cracks in "A" frame					22/09/2016	148276	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
						replaced covers over fuel tanks & fit new steps and mudflaps												
LOA029	Albury - Workshop	Body\HOUSEKEEP	RH cover over fuel tank needs replacing			L&R sides		22/09/2016	148276	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
			lower tail light bar so OVERSIZE signcan be fitted.															
LOA029	Albury - Workshop	Body\PANELS	Repaired lights.					22/09/2016	148276	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Albury - Workshop	Steering\WHEEL ALIGN	requires wheel alignment					22/09/2016	148288	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Albury - Workshop	DrCabRep\RADIO	UHF doesn't pick up very good only over short distances			check UHF operation		22/09/2016	148276	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Albury - Workshop	DrivLine\CLUTCH	Requires clutch adjustment			clutch adjuster removed and cleaned (siezed). Clean out excess grease on clutch brake		22/09/2016	148276	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Albury - Workshop	Body\TOOLBOX	tool box lid held on by a strap. toolbox lid held on by a strap			replaced tool box lock & latch		18/09/2016	148276	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Albury - Workshop	DrCabElect\PHONE	Phone not working			fitted new phone		18/09/2016	148276	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Albury - Workshop	Body\HOUSEKEEP	Drains on air tanks no wires			replaced drain cock		18/09/2016	148276	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
						remove cab sxs assy												
LOA029	Albury - Workshop	DrCabRep\MOUNTS	Replace Cab HCV and cab shocker. HCV for cab			overhaul & refit		17/09/2016		Fault	Completed	Greenfreight Lowene NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Albury - Workshop	Steering\STEER UNI	Replace lower steer shaft uni			as above		17/09/2016	148276	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
			replace bolts.															
LOA029	Albury - Workshop	Engine\BELTS/TENS	Tensioner bearine and damaeed boost hose			as above		16/09/2016	148276	Repair	Completed	Greenfreight Lowene NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
						remove bonnet												
						remove lal												
						remove front bumper												
						remove steering box												
						replace bonnet hinge/mounts												
						reassemble												
LOA029	Albury - Workshop	Body\MOUNTS	replace bonnet mount hinges.			nexar lights		15/09/2016	148276	Fault	Completed	Greenfreight Lowene NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Albury - Workshop	Susp\SUSPENSION	Torque rod bar bushes u/s.rear.					15/09/2016		Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
						remove front springs												
						replace bushes in hangers												
						replace springs with multi lube packs												
						replace shackes & pins												
LOA029	Albury - Workshop	Susp\SPRING PACK	steer springs keepers broken and packs out of alignment.			reassemble		15/09/2016	148276	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Albury Workshop	LOADER
LOA029	Wodonga - Workshop	DrCabElect\PHONE	New Ph required to replace Ballistic as not serviceable			ph ordered through Reconnect arived now		31/08/2016		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Wodonga Workshop	LOADER
LOA029	Rosewood - Workshop	Brakes	Check and record brakes					12/08/2016	144592	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	VehService\AS	A Service	VehService\AS				12/08/2016	144592	Service	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Brakes	brakes need adjustment					02/08/2016	144278	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Elect	LHS inner light not working					02/08/2016	144278	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Engine\START MOTR	replace starter motor			tumut auto Electrics		21/07/2016		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Tumut - Workshop	Tyres\TP07	Job Added From Invoice					21/07/2016	142944	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Rosewood - Workshop	DrCabElect\ELECT P&W	replace cab lights			completed by rosewood workshop		20/07/2016		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Tumut - Workshop	DrCabElect\RADIO	Fit new UHF aerial			completed by Tumut Auto Electricsan the 5th July		19/07/2016		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	DrCabElect\RADIO	travel to site fit new UHF aerial			completed by Tumut Auto Electrics on the 5th July		19/07/2016		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Tyres\TP09	Job Added From Invoice					14/07/2016	142134	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Tyres\TP09	Job Added From Invoice					14/07/2016	0	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Rosewood - Workshop	Brakes	no drain wire for air valve RHS					12/07/2016	141973	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Elect	LHS rear clearance light not working					12/07/2016	141973	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Elect	LHS inner light not working					12/07/2016	141973	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Tumut - Workshop	Tyres\TP02	Job Added From Invoice					05/07/2016	139800	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Tyres\TP02	Job Added From Invoice					05/07/2016	0	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job					24/06/2016	140743	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	VehService	service					24/06/2016	140743	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS				24/06/2016	140743	Service	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Tumut - Workshop	Tyres\TP02	Job Added From Invoice					31/05/2016	137565	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Tyres\TP02	Job Added From Invoice					31/05/2016	0	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Brakes\AIR LEAK	replace boot brake valve					17/05/2016		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Rosewood - Workshop	Brakes	R & R 3rd axel brake					10/05/2016	135848	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job					08/05/2016		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Brakes	S cam tube/spider					08/05/2016		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Elect	fix low beam					08/05/2016		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS				08/05/2016		Service	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	VehService\BS	B service	VehService\BS				05/05/2016		Service	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Wodonga - Workshop	Elect\START MOTR	call out replace stater			sub let to Tumut Auto Electrics		03/05/2016		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Wodonga Workshop	LOADER
LOA029	Rosewood - Workshop	Brakes\CONSUMABLE	replace foot brake valve					27/04/2016		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Tumut - Workshop	Tyres\TP07	Job Added From Invoice					16/04/2016	133426	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Rosewood - Workshop	Body\AIR FITTIN	replace drain cock					08/04/2016		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Susp\SWAYBAR	replace sway bar bushes x4					08/04/2016		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Brakes\AIR LEAK	drain fitting in air tank RHS broken					05/04/2016	132666	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Hydraulics\HYD LEAKS	slew motor seal leaking					05/04/2016	132620	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Elect\WORK LIGHT	broken bracket light outer boom					05/04/2016	132620	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Hydraulics\HYD LEAKS	oil leak rotator grab					05/04/2016	132620	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Susp\SWAYBAR	press out bushes					31/03/2016		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Susp\AIR BAG	replace drive air bag x2					30/03/2016		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job					18/03/2016	13119	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Susp\AIR BAG	replaced RHR front drive air bag					18/03/2016	13119	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS				18/03/2016	13119	Service	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Susp\SWAYBAR	replace worn torque rod bushesx8					09/03/2016		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Brakes\BRK RELINE	reline L/h/f R/h/f drive brakes and replace Scam and bearings					04/03/2016		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Tumut - Workshop	Tyres\TP08	Job Added From Invoice					01/03/2016	128662	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Rosewood - Workshop	Comp\ANN INSP	clear defects					01/03/2016		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Susp	replace all torque rod bushes					28/02/2016	129208	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Brakes\BRK RELINE	reline L/h/f R/h/f brakes					28/02/2016	129208	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT

LOA029	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job refit front steer springs				20/01/2016	124586	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Steering\SUSPENSION	replace all pins and replace u bolts				20/01/2016	124586	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Body	mount up new water tank as required				16/01/2016	124512	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Susp\SUSPENSION	pull out front springs				16/01/2016	124586	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Tumut - Workshop	Susp\SPRING PACK	Remove L/H and R/H spring packs and replace all pins				16/01/2016		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Body\TOOLBOX	Fit water tank to loader				16/01/2016		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Chassis	welding repairs carry out on the grab up right frame and work done by steel formation tumba - sublet				15/01/2016	124563	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Chassis	grab rest bar over bonnet cracked				13/01/2016		Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Elect\RADIO	uhf aerial				08/01/2016		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Tumut - Workshop	Tyres\TP51	Job Added From Invoice				01/01/2016	0	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Tyres\TP51	Job Added From Invoice				01/01/2016	0	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Tyres\TP51	Job Added From Invoice muffler				01/01/2016	0	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Engine\EXHAUST	tctc		comeleted		24/12/2015		Repair	Comeleted	Greenfreight Lowene NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Tyres\TP09	Job Added From Invoice				18/12/2015	121196	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Tyres\TP09	Job Added From Invoice				18/12/2015	0	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Tyres\TP09	Job Added From Invoice repair air con fan				18/12/2015	0	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Air Con\AIR CON	tae		comeleted		15/12/2015		Repair	Comeleted	Greenfreight Lowene NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Rosewood - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS			13/12/2015	120944	Service	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job				13/12/2015	120944	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	VehService	B service due filters				13/12/2015	120944	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Tumut - Workshop	Engine\FILTERS	tctc start fault		comeleted		12/12/2015		Repair	Completed	Greenfreight Lowene NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Engine\START MOTR	tumut auto elec		comeleted		09/12/2015		Repair	Comeleted	Greenfreight Lowene NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Tyres\TP07	Job Added From Invoice				04/12/2015	119166	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Tyres\TP07	Job Added From Invoice				04/12/2015	0	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Rosewood - Workshop	Air Con\AIR CON	airconditioner not working				02/12/2015		Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	DrCabElect\RADIO	uhf not picking up very good only short distances				02/12/2015		Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Body\TOOLBOX	toolbox lid still broken - held on with a strap				27/11/2015		Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Air Con	air con not working				27/11/2015	118619	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	DrCabElect\RADIO	UHF not picking up very good				27/11/2015	118619	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Tumut - Workshop	Tyres\DRV TYRES	Job Added From Invoice				21/11/2015	117324	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Tyres\DRV TYRES	Job Added From Invoice				21/11/2015	117324	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Tyres\DRV TYRES	Job Added From Invoice				21/11/2015	117324	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Rosewood - Workshop	Air Con\AIR CON	airconditioning not working. Thermostat?				20/11/2015	117766	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	DrCabRep\RADIO	UHF not picking up very good				20/11/2015	117766	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
			starter motor		completed												
LOA029	Tumut - Workshop	Elect\START MOTR	t a e			163935	17/11/2015		Repair	Comeleted	Greenfreight Lowene NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Tyres\STEER TYRE	Job Added From Invoice				06/11/2015	115521	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Tyres\STEER TYRE	Job Added From Invoice				06/11/2015	0	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Tyres\STEER TYRE	Job Added From Invoice				06/11/2015	115521	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Rosewood - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS			03/11/2015	115537	Service	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job				03/11/2015	115537	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Tumut - Workshop	Tyres\STEER TYRE	Job Added From Invoice				27/10/2015	113679	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Tyres\STEER TYRE	Job Added From Invoice				27/10/2015	0	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Rosewood - Workshop	Body\TOOLBOX	toolbox lid fell off				21/10/2015		Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Body\LIGHTS	LHS outer headlight falling out				21/10/2015		Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Myrtleford - Workshop	Engine\JAKE BRAKE	engine brake fault				16/10/2015		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOA029	Myrtleford - Workshop	Elect\BREAKDOWN	wiring fault - tae		completed		16/10/2015		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOA029	Myrtleford - Workshop	Engine\JAKE BRAKE	engine brakes not working on bank 2 - tctc		completed		14/10/2015		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Myrtleford Workshop	LOADER
LOA029	Rosewood - Workshop	Body\TOOLBOX	toolbox lid pulling off				13/10/2015	112214	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Tumut - Workshop	Insp\INT INSP	Roadworthy				01/10/2015		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Chassis\BWC COMP	Job Added From Invoice				01/10/2015	0	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Chassis\BWC COMP	Job Added From Invoice				01/10/2015	0	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Chassis\SUSPENSION	Job Added From Invoice				22/09/2015	0	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Body\WINDSCREEN	Job Added From Invoice				20/09/2015	0	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Rosewood - Workshop	Engine\HOUSEKEEP	Service Job Added From Invoice				16/09/2015	0	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Engine\HOUSEKEEP	Service Job Added From Invoice				16/09/2015	0	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Tumut - Workshop	Tyres\TP05	Job Added From Invoice				10/09/2015	0	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Tyres\TP06	Job Added From Invoice				10/09/2015	0	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Tyres\TP05	Job Added From Invoice				10/09/2015	110379	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Tumut - Workshop	Brakes\BRK O/HAUL	Service Job Added From Invoice				08/09/2015	0	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Tumut Workshop	LOADER
LOA029	Rosewood - Workshop	DrivLine	replace front diff torque rod bushes				03/09/2015		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	DrCabRep	replace front bonnet bushes				03/09/2015		Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS			02/09/2015	109825	Service	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	Brakes	check brakes				02/09/2015	109825	Repair	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER
LOA029	Rosewood - Workshop	DrivLine	repair faulty engine brake				02/09/2015	109825	Fault	Completed	Greenfreight Logging NSW	LOADKWorth	Rosewood	ALR	CF71JT	Rosewood Workshop	LOADER