EquipmentName	Workshop	CodeAndSubCode	Description	CompletionComments	DateDone	Workstate	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
P27	Myrtleford - Workshop	Elect\WORK LIGHT	REPLACE LIGHT BAR ON CAB REPAIR CRACKS IN GRAB & FIT NEW TIPS & WELD LOCK TABS ON PINS		05/09/2026	Completed	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Chassis\DAMAGE	(JASON WD RINLATECH)		05/09/2026	Completed	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Body\ELECT P&W	REPLACE RH OUTER BOOM LIGHT		04/09/2026	Completed	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	VehService\BS B Service	INSPECT OIL LEAK AT PILOT PUMP REILATECH REBUILT THE HYD SERVO PUMP	16/07/2026	Completed	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\PUMP	REMOVE HYD SERVO PUMP & SEND TO RINLATECH FOR A SEAL KIT & REFIT & TEST	TOP UP HYD OIL & ENGINE OIL DONE AT 9911 HRS	01/07/2026	Completed	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\RAM	REPLACE RH HYD LIFT CYLINDER	HRS AT TIME OF REPLACEMENT 9911	27/06/2026	Completed	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Body\HOUSEKEEP	REPLACE DOOR GAS STRUT		12/06/2026	Completed	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Body\LIGHTS	OUTER BOOM LIGHTS NOT WORKING CHECK OVER P27 (CHECK ALL FLUIDS)	REPAIR OUTER BOOM LIGHTS	12/06/2026	Completed	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Body\HOUSEKEEP	REPLACE RAIN CAP		12/06/2026	Completed	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\OIL LEAK	REPLACE BOOM AND GRAB CLY	HRS AT TIME OF REPLACEMENT 9846 REMOVED AND REPLACED CYL TESTED AND ALL GOOD	11/06/2026	Completed	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\RAM	FROM OPP SEAT LH HYD BOOM CYLINDER LEAKING	HRS AT TIME OF REPLACEMENT 9830	29/05/2026	Completed	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	VehService\BS B Service Repair Leaking Hydraulic Hose/s	completed by EC	14/05/2026	Completed	LOADPRENT	Myrtleford	MLR		Wodonga Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\HOSES	(Rapid Hydraulics P/O:		08/04/2026	Completed	LOADPRENT	Myrtleford	MLR		RAPID HYDRAULICS & PNEUMATICS -4	PRENTICE
P27	Myrtleford - Workshop	Engine\AIR CLNR	Replace Air Filter (P/N: P532503)	Removed Old Air Filter Wiped Out Air Filter Housing With Wet Cloth, Fitted New Air Filter. B/SERVICE & HYD SERVICE	21/03/2026	Completed	LOADPRENT	Myrtleford	MLR		Wodonga Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	VehService\BS B Service	HRS AT TIME OF SERVICE 9549 REMOVED AND FITTED NEW PIVOT LEG PIN	02/03/2026	Completed	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Chassis\STAB LEG	RH REAR BROKEN LEG PIVOT PIN	REFITTED REAR COVER AFTER ADJUSTING LATCH Repair grab tips 95.00 BWM-24 Dowtys 6 2.60 15.60	27/02/2026	Completed	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Chassis\Boom	REPAIR GRAB TIPS	S56-21 P27	24/02/2026	Completed	LOADPRENT	Myrtleford	MLR		RINLATECH ENGINEERING-3	PRENTICE
P27	Myrtleford - Workshop	Chassis\DAMAGE	REWELD GRAB TIP BACK ON	Repair grab tips	18/12/2025	Completed	LOADPRENT	Myrtleford	MLR		RINLATECH ENGINEERING-3	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	VehService\BS B Service REPAIR OIL LEAK IN NEW RECO HYD TRIPPLE PUMP	HRS AT TIME OF SERVICE 9340	11/12/2025	Completed	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\PUMP	(RINLATECH WARRANTY JOB)	REPLACED SLEW MOTOR AND TESTED ALL GOOD HRS AT TIME OF REPAIR 9235	25/11/2025	Completed	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\MOTOR	REPLACED FAILED SLEW MOTOR (BROKEN SHAFT)	HYD OIL REPLACED NOT FILTERS	13/11/2025	Completed	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\PUMP	REPLACE HYD TRIPPLE PUMP	HRS AT TIME OF REPLACEMENT 9209	06/11/2025	Completed	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\OIL/FILTER	DRAIN & REPLACE HYDRAULIC OIL & FILTERS	HRS AT TIME OF REPLACEMENT 9209 hrs at time of service 9119	06/11/2025	Completed	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	VehService\BS B Service	REPAIRED BOOM REST SLOP	11/10/2025	Completed	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Chassis\Boom	MOVEMENT IN MAIN BOOM PIN AND BUSHES GRAB TIP (SINGLE TIP) TO BE SHORTEN REPLACE BOTH GRAB TYNES & REPAIR GRAB CRACKS	INSPECTED AND STILL A BIT MORE SERVICE IN THEM P27 Prep and cutout and weld cracks, replace grab tynes and weld more cracks etc. 2,090.00 Materials 64.80	01/10/2025	Completed	LOADPRENT	Myrtleford	MLR		RINLATECH ENGINEERING-3	PRENTICE
P27	Myrtleford - Workshop	Body\HOUSEKEEP	G/F HAD NEW TYNES (WD)	Misc items and workshop consumables. remove and reseal and replace valve. 4 90.00 360.00 15 assorted orings RESEAL SLEW VALVE	01/10/2025	Completed	LOADPRENT	Myrtleford	MLR		RINLATECH ENGINEERING-3	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\OIL LEAK	HYD OIL LEAK AT SLEW CONTROL VALVE SHAFT REPAIR AIR CON SYSTEM REPLACE CONDENSOR FAN	DONE ON 29/8/25 CHECK A/C SYSTEM. CONNECT GAUGES. RUN SYSTEM AND CHECK. LITTLE COOLING. DIAGNOSE FAULTY CONDENSER FAN. REMOVE, SUPPLY AND FIT NEW FAN.	01/10/2025	Completed	LOADPRENT	Myrtleford	MLR		RINLATECH ENGINEERING-3	PRENTICE
P27	Myrtleford - Workshop	Air Con\AIR CON	L097085	TEST OK.	22/09/2025	Completed	LOADPRENT	Myrtleford	MLR		MYRTLEFORD AUTO ELECTRICS - 3	PRENTICE
P27	Myrtleford - Workshop	Insp\ANN INSP	Insp\ANN INSP		19/09/2025	Completed	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Body\HOUSEKEEP	CHECK OVER / GREASE AND INSPECT FLUID LEVELS		19/09/2025	Completed	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	VehService\BS B Service	HRS AT TIME OF SERVICE 8909	22/08/2025	Completed	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Body\FUEL TANK	RECRIMP FUEL HOSE		18/08/2025	Completed	LOADPRENT	Myrtleford	MLR		RINLATECH ENGINEERING-3	PRENTICE
P27	Myrtleford - Workshop	DriCabRep\WINDSCREEN	RUBBER SEAL LEAKING WATER ON FRONT WINDSCREEN	FITTED SEALANT AROUND TOP OF RUBBER	30/07/2025	Completed	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Chassis\DAMAGE	REPAIR GRAB TIPS ON GRAPPLE		28/07/2025	Completed	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Elect\ELECT P&W	ELE HORN NOT WORKING <

P27	Myrtleford - Workshop	Hydraulics\MOTOR	FIT SEAL KIT TO GRAB SLEW MOTOR		14/04/2025	Completed	LOADPRENT	Myrtleford	MLR	RINLATECH ENGINEERING-3	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	VehService\BS	HRS AT TIME OF SERVICE 8525	11/04/2025	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Chassis\Load Fram	FULLY GREASE LOADER & SLEW BEARING 9520 HRS		09/04/2025	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Body\WINDSCREEN	front windscreen to be replaced due to stone chips ALBURY AUTO SCREENS REPLACED FRONT W/SCREEN		01/04/2025	Completed	LOADPRENT	Myrtleford	MLR	AUTOTEK AUSTRALIA - 3	PRENTICE
P27	Myrtleford - Workshop	Elect\BATTERY	REPLACE BATTERY ON P27 (FAULTY)		26/03/2025	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Chassis\STAB LEG	replace broken leg pin RH rear		16/02/2025	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Body\ELECT P&W	replace broken strobe light		24/01/2025	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DrCabElect\ELECT P&W	repairs to pilot shut off switch		24/01/2025	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	VehService\BS Replace Batteries. (Batteries Supplied By Regional Batteries P/O: T091101) NOTE: I had to use Albury Workshop code due to one not being set up for Myrtleford Workshop	replaced fan belt	24/01/2025	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Albury - Workshop	Elect\BATTERY	with Regional Batteries.		31/12/2024	Completed	LOADPRENT	Myrtleford	MLR	REGIONAL BATTERY SUPPLY - 4	PRENTICE
P27	Myrtleford - Workshop	Chassis\Boom	REPAIR GRAB TIPS ON GRAPLE		06/12/2024	Completed	LOADPRENT	Myrtleford	MLR	RINLATECH ENGINEERING-3	PRENTICE
P27	Myrtleford - Workshop	DrCabElect\HOUSEKEEP	replace leg up/down switches and all globes in other switches replace hyd boom cly (rinlatech)	REBIULD 1 MAIN LIFT RAM OFF P27 6/2/25	03/12/2024	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\RAM	FIT 2 G/F SPARE MAIN LIFT RAMS TO P27	$1326.25 replaced air cleaner replaced hyd pipe clamp recheck rest of clamps replaced cab fresh air filter	29/11/2024	Unlocked	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	VehService\BS	replaced rain cap	28/11/2024	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	VehService\BS		20/09/2024	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\OIL LEAK	reseal LH/RH leaking pilot levers		16/09/2024	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Body\HOUSEKEEP	replace grab tips		03/09/2024	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Insp\ANN INSP	Insp\ANN INSP		29/08/2024	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	VehService\BS	grease loader	28/08/2024	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Body\HOUSEKEEP	Body\HOUSEKEEP	tighten all boom pin nuts	30/07/2024	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Wodonga - Workshop	Hydraulics\OIL LEAK	L/H SERVOS LEAKING OIL.		02/07/2024	Completed	LOADPRENT	Myrtleford	MLR	Wodonga Workshop	PRENTICE
P27	Wodonga - Workshop	Elect\WORK LIGHT	OUTER LIGHTS ON BOOM N/W.		02/07/2024	Completed	LOADPRENT	Myrtleford	MLR	Wodonga Workshop	PRENTICE
P27	Wodonga - Workshop	Hydraulics\RAM	OIL LEAKING HYDRAULIC RAM (SINGLE TYNE)		02/07/2024	Completed	LOADPRENT	Myrtleford	MLR	Wodonga Workshop	PRENTICE
P27	Wodonga - Workshop	Chassis\Boom	REPLACE BOLT IN GRAB MAIN PIN.		02/07/2024	Completed	LOADPRENT	Myrtleford	MLR	Wodonga Workshop	PRENTICE
P27	Wodonga - Workshop	Hydraulics\VALVES	OIL LEAKING UNDER CAB VALVE BANK.		02/07/2024	Completed	LOADPRENT	Myrtleford	MLR	Wodonga Workshop	PRENTICE
P27	Wodonga - Workshop	DrCabElect\RADIO	REPLACED AM/FM AERIEL		13/06/2024	Completed	LOADPRENT	Myrtleford	MLR	Wodonga Workshop	PRENTICE
P27	Wodonga - Workshop	Cooling\RADIATOR	LEAKING RESERVOIR TANK (COOLANT) Rebuild grab ram, machine new gland, hone barrel and reseamble with new seals. 637.50 160mm dia 1045 bar 0.075 550.60 41.30 seals 191.95	REPLACED TANK. TOPPED UP COOLANT.	13/06/2024	Completed	LOADPRENT	Myrtleford	MLR	Wodonga Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\RAM	7/16 x 1 1/2" unf b		13/06/2024	Completed	LOADPRENT	Myrtleford	MLR	RINLATECH ENGINEERING-3	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	VehService\BS	Hrs at last service 7549	12/06/2024	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Wodonga - Workshop	Cooling\RADIATOR	WASHED ENGINE. DRAINED COOLANT. REPLACED WATER PUMP AND BELTS. MODIFIED BOTTO		06/06/2024	Completed	LOADPRENT	Myrtleford	MLR	Wodonga Workshop	PRENTICE
P27	Wodonga - Workshop	DriCabRep\SEAT	FIT SEAT BELT.		02/05/2024	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DriCabRep\DOOR LOCK	DOOR LATCH NEEDS ADJUSTING.		23/04/2024	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Wodonga - Workshop	Unknown	GREASE LOADER.		05/04/2024	Completed	LOADPRENT	Myrtleford	MLR	Wodonga Workshop	PRENTICE
P27	Wodonga - Workshop	Hydraulics\HYD LEAKS	REPLACE GRAB RAM LEAKING.	REPLACED RAM.	05/04/2024	Completed	LOADPRENT	Myrtleford	MLR	Wodonga Workshop	PRENTICE
P27	Myrtleford - Workshop	Unknown	GREASE LOADER.		28/03/2024	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Body\OH&S	NO LOADER SIGNS.		28/03/2024	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	REPAIRED WIPER WASHERS. REPLACED RAIN CAP.	20/03/2024	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Wodonga - Workshop	Unknown	GREASED LOADER.		19/03/2024	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Wodonga - Workshop	Hydraulics\OIL/FILTER	TOPPED UP HYDRAULIC OIL.		19/03/2024	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Wodonga - Workshop	Body\PAINT/REST	PAINTED WALKWAYS.		19/03/2024	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Wodonga - Workshop	DrCabElect\RADIO	MOVED RADIO.		19/03/2024	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Wodonga - Workshop	Air Con\AIR CON	AIR CON VENTS R/H BEHIND SEAT NEED TO BE SEALED.		19/03/2024	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Wodonga - Workshop	Body\PANELS	LEAKING SUNROOF.		19/03/2024	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Wodonga - Workshop	DriCabRep\MOUNTS	REPLACE CAB MOUNTS WORN OUT.		19/03/2024	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Wodonga - Workshop	Body\PANELS	RE-SEAL SKY LIGHT. WATER LEAKING.		19/03/2024	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Wodonga - Workshop	Hydraulics\OIL LEAK	oil leaks under cab		08/03/2024	Completed	LOADPRENT	Myrtleford	MLR	Wodonga Workshop	PRENTICE
P27	Wodonga - Workshop	Elect\WORK LIGHT	outer boom lights N/W		08/03/2024	Completed	LOADPRENT	Myrtleford	MLR	Wodonga Workshop	PRENTICE
P27	Wodonga - Workshop	DrCabElect\RADIO	replace UHF arial		08/03/2024	Completed	LOADPRENT	Myrtleford	MLR	Wodonga Workshop	PRENTICE
P27	Wodonga - Workshop	Elect\ELECT P&W	light wiring need to be tucked away		08/03/2024	Completed	LOADPRENT	Myrtleford	MLR	Wodonga Workshop	PRENTICE
P27	Wodonga - Workshop	Hydraulics\RAM	replaced stick bearing rod end U/S		24/02/2024	Completed	LOADPRENT	Myrtleford	MLR	Wodonga Workshop	PRENTICE
P27	Wodonga - Workshop	Chassis\HOUSEKEEP	grease loader		24/02/2024	Completed	LOADPRENT	Myrtleford	MLR	Wodonga Workshop	PRENTICE
P27	Wodonga - Workshop	Elect\WORK LIGHT	replace work light		24/02/2024	Completed	LOADPRENT	Myrtleford	MLR	Wodonga Workshop	PRENTICE
P27	Myrtleford - Workshop	Unknown	GREASE SWING PEDAL UNDER CAB.		24/02/2024	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DriCabRep\HOUSEKEEP	GLUED ROOF LINING INTO PLACE.		23/01/2024	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Unknown	GREASE HOSE BEHIND BOOM NEEDS REARRANGING.	TIDIED UP GREASE LINES.(RINLATECH)	19/01/2024	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Body\FUEL TANK	FUEL LEAKING FROM FUEL CAP.	REPAIRED FUEL CAP NECK	19/01/2024	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\OIL LEAK	OIL HYD LEAK.	REPLACED OUTER BOOM HOSES. (RINLATECH)	19/01/2024	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Wodonga - Workshop	Hydraulics\OIL LEAK	leaking oil filter		16/01/2024	Completed	LOADPRENT	Myrtleford	MLR	Wodonga Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist Weld catching rod for grab		12/01/2024	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\RAM	Onsite and replace assorted hoses on loader.	Setup and start dismantling truck. Dismantle prentice loader and strip down all parts and prep for line boring job. Repairs to all hydraulic cylinders, replacing flogged eyes, bearings and bushes. Make up all profile plates and weld into place. Remove and machine and replace pins. Vee out and weld assorted cracks in main frame. Reassemble up loader and paint. Clean up.	05/01/2024	Completed	LOADPRENT	Myrtleford	MLR	RINLATECH ENGINEERING-3	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\RAM	lift rams leaking		30/12/2023	Completed	LOADPRENT	Myrtleford	MLR	Albury Workshop	PRENTICE
P27	Myrtleford - Workshop	Unknown	Grease loader		28/12/2023	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Wodonga - Workshop	Elect\WORK LIGHT	rewire front boom lights		22/12/2023	Completed	LOADPRENT	Myrtleford	MLR	Wodonga Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\MOTOR	replace slew bearing and pinion gear	Replace slew ring on loader.	19/12/2023	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\RAM	supply seal kit and Bushing		18/10/2023	Completed	LOADPRENT	Myrtleford	MLR	Albury Workshop	PRENTICE
P27	Wodonga - Workshop	Hydraulics\RAM	lift rams leaking	Lift arm cylinders need replacing	16/09/2023	Completed	LOADPRENT	Myrtleford	MLR	Wodonga Workshop	PRENTICE
P27	Wodonga - Workshop	DrCabElect\RADIO	am / fm radio Not working		16/09/2023	Completed	LOADPRENT	Myrtleford	MLR	Wodonga Workshop	PRENTICE
P27	Wodonga - Workshop	DrCabElect\RADIO	am / fm radio Not working		16/09/2023	Completed	LOADPRENT	Myrtleford	MLR	Wodonga Workshop	PRENTICE
P27	Wodonga - Workshop	Chassis\HOUSEKEEP	grease loader	CHECKED FUSES, RELAYS AND LOOMS.	16/09/2023	Completed	LOADPRENT	Myrtleford	MLR	Wodonga Workshop	PRENTICE
P27	Wodonga - Workshop	Elect\ELECT P&W	NOT STARTING.	REPAIRED WIRING AT ECM BY ARKON.	05/09/2023	Completed	LOADPRENT	Myrtleford	MLR	Wodonga Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\FUEL TANK	FUEL ISSUE.		02/09/2023	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist		01/09/2023	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist		01/07/2023	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Body\HOUSEKEEP	wash grab and windscreens Leg Cylinder Dismantle and clean leg ram. Polish up all sealing surfaces and repair crome rod. Remove and replace rod and barrel		28/06/2023	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\RAM	bushes, reasemble with new seals. Test and paint.		28/06/2023	Completed	LOADPRENT	Myrtleford	MLR	Albury Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\ENG REBLD	Rebuild staffa motor with broken shaft.	changed fuel filters - replaced pump control valve	27/06/2023	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
			fuel issues - engine dies down and picks up again	fuel rail pressure reline valve							
P27	Myrtleford - Workshop	Engine\BREAKDOWN	yellow warning light flashes when loader is started	tested all good	27/06/2023	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\RAM	Randalls supply parts		20/06/2023	Completed	LOADPRENT	Myrtleford	MLR	RANDALLS EQUIPMENT CO (VIC) - 3	PRENTICE

P27	Myrtleford - Workshop	Hydraulics\BREAKDOWN	breakdown in bush take P17 to change over loaders		16/06/2023	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\MOTOR	reco slew motor		16/06/2023	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Workshop\MOVE ASSET	take and pick up at Rinlatech		16/06/2023	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\OIL/FILTER	hyd oil		16/06/2023	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\MOTOR	slew motor		16/06/2023	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Wodonga - Workshop	Engine\FUEL TANK	Refit Fuel Rail Supply Tube To P29		14/06/2023	Completed	LOADPRENT	Myrtleford	MLR	Wodonga Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\BREAKDOWN	fuel leak (fuel supply line pump to rail)		06/06/2023	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DrCabElect\INST/GAUGE	replaced horn		06/06/2023	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Chassis\HOUSEKEEP	grease loader leg's		02/06/2023	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\RAM	Setup and test cylinder. Cut flogged rod eye off and remanufacture, reweld to rod and replace bearing. Polish cylinder rod.	Setup and test cylinder. Cut off both rod and barrel eyes, remanufacture eyes and weld back onto cylinder. Fit new spherical and paint.	02/06/2023	Completed	LOADPRENT	Myrtleford	MLR	Albury Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\FUEL TANK	Repair fuel line		02/06/2023	Completed	LOADPRENT	Myrtleford	MLR	Albury Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\RAM	Replace grab tips on grab. Repair crack in front grab support pole.		30/05/2023	Completed	LOADPRENT	Myrtleford	MLR	Albury Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\RAM	Setup and test lift cylinder. Dissmantle and clean all parts, linish crome rod and repair piston and hone barrel, reasemble with new seals.		26/05/2023	Completed	LOADPRENT	Myrtleford	MLR	Albury Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\OIL LEAK	slew motor leak	remove slew motor and replace shaft seal	25/05/2023	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\OIL LEAK	slew ring seal leaking	replace slew seal and wash down walkway	25/05/2023	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Body\HOUSEKEEP	REPLACE WORN LEG TO FEET PINS AND BUSHES	as above on all 4 legs Dissmantle all 4 leg assemblies from loader. Setup legs in mill and linebore foot mounts and rebush. Machine all new pins and cutout and rebush all feet. Fit new bushes and pins to all parts and reasemble. Remove and reseal Staffa slew motor, and refit.	25/05/2023	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
			Service As Per Attached Checklist								
			replace hyd filter	repaired lights							
P27	Myrtleford - Workshop	VehService\BS	***replace pilot filter***	coolant leaks	16/05/2023	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	load due for Service	service loader	10/05/2023	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Body\HOUSEKEEP	oil on check? (slew motor reseal Rinlatech)	wash oil from walk ways	10/05/2023	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Elect\WORK LIGHT	stick boom work lights not working		03/05/2023	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\HOUSEKEEP	check fluid's level's		03/05/2023	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\RAM	replace stick boom cly	replace hyd cly stick boom	03/05/2023	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\OIL LEAK	slew motor leak		03/05/2023	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Elect\WORK LIGHT	work light on boom R/H	boom lights not working	03/05/2023	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Body\HOUSEKEEP	grease loader		03/05/2023	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\FUEL TANK	Blockage on inlet fuel fitting to filter housing		20/04/2023	Completed	LOADPRENT	Myrtleford	MLR	Albury Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\HYD LEAKS	o-ring on hose on boom oil leak	repair oil leak on boom (on site)	01/04/2023	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Body\HOUSEKEEP	wash down truck, loader		30/03/2023	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Body\HOUSEKEEP	weld new bolt for pin		30/03/2023	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\OIL LEAK	repair oil leaks		30/03/2023	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\OIL LEAK	ram seal on grab (loose fitting)	tigthen fitting on grab	30/03/2023	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\HOSES	main boom hose leak	replace hyd hose, top up hyd oil level	30/03/2023	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\HOSES	hose on grab	hyd hose on grab	23/03/2023	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	B Service As Per Attached Checklist		23/02/2023	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\FUEL TANK	TCTC supply parts		17/02/2023	Completed	LOADPRENT	Myrtleford	MLR	Albury Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\DAMAGE	REPLACE ALL WORN LEG PINS & BUSHES. all leg pins flogged out		08/02/2023	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\DAMAGE	REPLACE ALL WORN BOOM BUSHES & BOSSES. main boom pin/boss flogged out		08/02/2023	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\DAMAGE	REBUILD GRAB TIPS. new roos on grab tips		08/02/2023	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\DAMAGE	all leg pins flogged out		03/02/2023	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\DAMAGE	main boom pin/boss flogged out		03/02/2023	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\DAMAGE	new roos on grab tips		03/02/2023	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\HYD LEAKS	hyd hose broken L/O/S top of boom	change hyd boom hose	03/02/2023	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DrCabElect\ELECT P&W	Repair Electric Fuel Pump - not working		18/01/2023	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DrCabElect\AIR CON	a/c not working		14/01/2023	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DriCabRep\AIR CON	repair aircon system		12/01/2023	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\RAM	seal in grab ram leaking	Machine new grab pin, cut off and use existing tag.	04/01/2023	Completed	LOADPRENT	Myrtleford	MLR	Albury Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\MOUNTS	Onsite and ours to manufacture new alternator bracket. Repair threads in housing.		04/01/2023	Completed	LOADPRENT	Myrtleford	MLR	Albury Workshop	PRENTICE
P27	Myrtleford - Workshop	Elect\WORK LIGHT	myrt auto - LED work light round		14/12/2022	Completed	LOADPRENT	Myrtleford	MLR	Albury Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\OIL LEAK	oil leak R/H front of engine	engine oil leak (oil cooler gaskets)	29/11/2022	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\RAM	seal in grab ram leaking		29/11/2022	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\OIL LEAK	slew ring seal leaking		29/11/2022	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\RAM	bearing collapse on centre hyd ram	replace stick c/y (failed bearing)	29/11/2022	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Body\HEATER REP	not taking grease boom/stick		29/11/2022	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	CHECK A/C SYSTEM. CONNECT GAUGES. NO REFRIGERANT PRESENT. PRESSURE TEST SYSTEM WITH NITROGEN. LOCATE LEAK IN A/C COMPRESSOR. REMOVE AND REPLACE COMPRESSOR. EVACUATE AND CHARGE SYSTEM.	05/11/2022	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DriCabRep\AIR CON	ac issues (Sublet Mae)	CHECK FOR LEAKS WITH ELECTRONIC DETECTOR.	29/10/2022	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DrCabElect\ELECT P&W	strobe light leaking water		29/10/2022	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\BELTS/TENS	replaced fan belt and check over		18/10/2022	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\EXHAUST	fit rain cap		13/10/2022	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DriCabRep\SEAT	fit seat base		13/10/2022	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Elect\WORK LIGHT	light RH on boom not working	fit RH work light to boom	13/10/2022	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Elect\ELECT P&W	light in switches need replacing	R&R bulbs in switches	13/10/2022	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\ALT2 DR	Arkon supply 2nd hand alternator		12/10/2022	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\RADIATOR	Bursons supply radiator hose		11/10/2022	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	changed work light LH lower corner	14/09/2022	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Body\HOUSEKEEP	REPLACE WORN LEG TO FEET PINS AND BUSHES		10/09/2022	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DriCabRep\SEAT	REPLACE SEAT BASE		10/09/2022	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\BELTS/TENS	REPLACE FAN BELT AND TENSIONER	remove radiator	10/09/2022	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\BELTS/TENS	checked belts pulley etc.		07/09/2022	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Body\MOUNTS	REPAIR HYD TANK MOUNTS	inspected all good hr 6588	11/08/2022	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\MOUNTS	REPLACE ENGINE MOUNTS AS NEEDED	inspected all good hr 6588	11/08/2022	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	replaced rain cap replaced coolant hose	09/08/2022	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\RAM	Assorted repairs to grab		02/08/2022	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DrCabElect\INST/GAUGE	supply switch and toggle		29/07/2022	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\BREAKDOWN	wont start		16/07/2022	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\EXHAUST	REPLACE RAIN CAP		08/07/2022	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\MOUNTS	REPLACE MOUNT BOLTS FOR RADIATOR AND INTERCOOLER		08/07/2022	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist		06/07/2022	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Body\HOUSEKEEP	grease loader	grease slew and grab	28/06/2022	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\HOUSEKEEP	fill coolant reservoir and fill 10 liter into drum		23/06/2022	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Body\MOUNTS	check for movement in boom pin	weld lift ram cracks and tighten both rams	10/06/2022	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\OIL LEAK	Randalls supply seal kit		26/05/2022	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist		17/05/2022	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE

P27	Myrtleford - Workshop	Hydraulics\RAM	grab not holding logs		03/05/2022	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DrCabElect\RADIO	UHF and radio lose/change channel by themselves		03/05/2022	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DriCabRep\RADIO	fit trunk phone aerial		03/05/2022	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\MOTOR	slew motor seal leaking		03/05/2022	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Body\HOUSEKEEP	Part dismantle to access welding, weeout and repair cracks in frame		02/05/2022	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Wodonga - Workshop	Chassis\CHAS CRACK	REPAIR RAM MOUNT CRACKS		04/03/2022	Completed	LOADPRENT	Myrtleford	MLR	Wodonga Workshop	PRENTICE
P27	Wodonga - Workshop	Chassis\CHAS CRACK	REPAIR MAIN BOOM		04/03/2022	Completed	LOADPRENT	Myrtleford	MLR	Wodonga Workshop	PRENTICE
P27	Wodonga - Workshop	Chassis\CHAS CRACK	REPAIR CRACKS IN LH AND RH MAIN BOOM BOSSES		04/03/2022	Completed	LOADPRENT	Myrtleford	MLR	Wodonga Workshop	PRENTICE
P27	Wodonga - Workshop	VehService\BS	Service As Per Attached Checklist		03/03/2022	Completed	LOADPRENT	Myrtleford	MLR	Wodonga Workshop	PRENTICE
P27	Myrtleford - Workshop	Body\HOUSEKEEP	weld rod's on grab tips		24/02/2022	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DrCabElect\ELECT P&W	interior light not working		08/02/2022	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\FUEL TANK	warning/caution light flashing when start no inside	check engine light on dirty fuel	08/02/2022	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
			REPAIR MOVEMENT BOTTOM PIN ON LIFT RAMS I LINE BORE BOTTOM MAIN LIFT HOUSING & FIT NEW BUSHES & MAKE NEW PIN & REPAIR	Repair prentice loader as required, ie: - remove lift cylinders - remove main pivot pin - setup and line bore main pivot - manufacture bushes - fit and weld to pivot - manufacture and fit main pivot pin - supply and fit new spherical bushes and locknuts						
P27	Myrtleford - Workshop	Body\MOUNTS	BOTH MAIN LIFT RAM EYES & REPLACE ALL 4 BUSHES	- re-assemble as required	15/01/2022	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\FILTERS	replace oil filter		11/01/2022	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist		08/01/2022	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\AS	check over	check oil and coolant	01/01/2022	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Wodonga - Workshop	Hydraulics\RAM	CHANGE OUT HYDRULIC BOOM LIFT CYLINDER	inspected all good	17/12/2021	Completed	LOADPRENT	Myrtleford	MLR	Wodonga Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\OIL/FILTER	check hyd filters		16/12/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\OIL/FILTER	check hyd pressures	checked hyd pressures and hyd service and tested	16/12/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Body\MOUNTS	FIT DROP LOCKS TO FRONT ENGINE COVER DOOR		25/11/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\BELTS/TENS	REPLACE FAN BELT AND FAN BELT TENSIONER AND FAN PULLEY		25/11/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Elect\WORK LIGHT	outer boom lights n/w		24/11/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist		24/11/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DrCabElect\AIR CON	repair aircon system		29/10/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist		22/10/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\BELTS/TENS	REPLACE A/C PULLEY		14/10/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\ELECT P&W	new fuse for fuel pump		13/10/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\HEATER TAP	put another heater tap can cause injury where they are		13/10/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\BELTS/TENS	a/c not working		13/10/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Chassis\HOUSEKEEP	put cable ties on hyd hose R/H bottom lift ram		05/10/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DrCabElect\AIR CON	CHECK AIR CONDITIONER SYSTEM		30/09/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DrCabElect\HEATER REP	REPLACE BOTH HEATER TAPS		30/09/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DrCabElect\AIR CON	a/c not working		28/09/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\BELTS/TENS	a/c tensioner		28/09/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\OIL/FILTER	wash/top up hyd fluid		24/09/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\HOUSEKEEP	replace thermostat		23/09/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Chassis\DAMAGE	bottom lift pins/bushes worn out		22/09/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DriCabRep\RADIO	fit FM/AM radio (bluetooth)	refit	22/09/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\OIL/FILTER	top up hydraulic oil		15/09/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Body\HOUSEKEEP	wash grab		15/09/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DriCabRep\RADIO	fit FM/AM radio (bluetooth)		15/09/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Body\HOUSEKEEP	replace broken grab hyd hose		15/09/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Elect\WORK LIGHT	out boom lights n/w (2 of)	boom lights	11/09/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Elect\WORK LIGHT	R/H outer boom light n/w		09/09/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\HOSES	REPLACE WORN HYDRULIC HOSE BETWEEN MAIN BOOM AND STICK BOOM	replace broken clamps on hydraulic cooler line	08/09/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	repair work light wiring	04/09/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Chassis\DAMAGE	replace broken grab tip		18/08/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist		04/08/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist		03/08/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Workshop\MOVE ASSET	change over loaders		03/08/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\HOUSEKEEP	extend breather tube		21/07/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\RADIATOR	inspected water pump		21/07/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DrCabElect\RADIO	UHF mic holder - change position	UHFmic needs moving	21/07/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DrCabElect\INST/GAUGE	guages all over the place	guages all over place	21/07/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Elect\WORK LIGHT	replace L/H outer boom light	LH outer boom light	21/07/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\HYD LEAKS	L/H servos leaking oil /RHS	replaced servo seals LH/RH	21/07/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DriCabRep\RADIO	fit mount for UHF mic	replaced UHF mic holder	10/07/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DriCabRep\SEAT	replace seat arm rests		09/07/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DrCabElect\HEATER REP	flush heater core and blow out filters		09/07/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
			Service As Per Attached Checklist L11958	replaced rubbed grab hose. Please get one made staffa motor has a leak from bottom seal. (just started)							
P27	Myrtleford - Workshop	VehService\BS	CHANGE HYDRAULIC FILTERS	refitted staffa gear after it fell off	29/06/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Chassis\DAMAGE	crack on solid grab near bottom	weld grab	20/06/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Chassis\HOUSEKEEP	new grease nipple centre hyd ram		05/06/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Chassis\DAMAGE	REPAIR CRACKS IN BOOM		26/05/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\BOOST HOSE	REPLACE 90deg BOOST HOSE	wrong hose	26/05/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	VehService\BS		25/05/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Elect\WORK LIGHT	fit work light to boom		13/05/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DriCabRep\SEAT	REPLACE RH SEAT BELT BUCKEL		06/05/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\HOSES	Replace small lift ram hose		29/04/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Body\PAINT/REST	Hot Wash prentice loader		29/04/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\RAM	REPLACE LEAKING RHS MAIN LIFT RAMS	Top up hydraulic oil Replace hydraulic tank breather	28/04/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	B Service As Per Attached Checklist		20/04/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DriCabRep\HOUSEKEEP	Replace Joy Stick Handles	replaced LH arm rest gas strut	16/04/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\BELTS/TENS	tighten a/con belt	tighten a/c belt	08/04/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DrCabElect\AIR CON	aircon not working in loader		08/04/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\HOSES	elbow on grab ram and hydraulic hose please	grab hose hyd oil	01/04/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\PUMP	REMOVE AND REPLACE LEAKING TRIPLE PUMP		27/03/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Body\HOUSEKEEP	put an extension on the grease nipple at the end of the main boom pin please	grease line for boom to dipper arm pin	26/03/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist		13/03/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DrCabElect\INST/GAUGE	replaced decals on switch's		11/03/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DriCabRep\RADIO	replace missing screw to hold am/fm radio	am/fm radio screws missing	11/03/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\EXHAUST	replace broken rain cap exhaust	replaced exhaust rain cap	11/03/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\OIL/FILTER	top up hyd oil	topped up hyd oil	25/02/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\HYD LEAKS	hyd steel pipe under cab pinhole		25/02/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Chassis\HYDRAULICS	replace grab pin		18/02/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Chassis\HOUSEKEEP	welding - RHF legs pin		18/02/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist L11037		26/01/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\EXHAUST	no rain cap on exhaust	fit rain cap on exhaust	16/01/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Chassis\HYDRAULICS	cable tie hyd hoses R/H lift pin base	cable tie rubbing hoses	16/01/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\BELTS/TENS	a/c belt squaling at high revs	tighten a/c belt	16/01/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Chassis\DAMAGE	weld extra on tips of grab		09/01/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\RAM	weld 2 tag pins on grab (hyd pins)		09/01/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE

P27	Myrtleford - Workshop	Chassis\DAMAGE	repair grab stand support		09/01/2021	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	B SERVICE & HYDRAULIC SERVICE		10/12/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Brakes	Check Brake %		10/12/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\MOTOR	Replace Slew Motor Seal	fit bottom seal and crack test shaft	08/12/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\HYD LEAKS	replace leaking LH servo seals		01/12/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
				pulled off slew cover check gear etc cleaned up							
P27	Myrtleford - Workshop	Hydraulics\MOTOR	Replace Slew Motor Seal	fit bottom seal and crack test shaft	28/11/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Elect\WORK LIGHT	outer boom light flicking on/off	replaced boom light plug	27/11/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\OIL/FILTER	replace tank breather filter		06/11/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\HYD LEAKS	oil leaking R/H joystick		06/11/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\HOUSEKEEP	Check for noise in engine at flywheel housing area		22/10/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	replaced exhaust rain cap	21/10/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Elect\WORK LIGHT	lights outer boom n/w		10/10/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Unknown - Unknown	Chassis\DAMAGE	Check and replace all worn boom and ram bushes and pins	replace 5x boom, bushes and pins and top and bottom main lift pin	02/10/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Chassis\DAMAGE	bottom lift pins/bushes worn out		01/10/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Elect\WORK LIGHT	outer boom lights shorting out		01/10/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\FUEL TANK	fit replacement fuel lines and fittings to engine		15/09/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\FUEL TANK	fuel line between engine and fuel filter replace		12/09/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist L9847		11/09/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DrCabElect\RADIO	Fit new UHF		08/09/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DrCabElect\INST/GAUGE	dashlights n/w	dash lights	05/09/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Chassis\HYDRAULICS	botton lift pin/bushes need replacing	boom pins	05/09/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DriCabRep\SEAT	replace RH arm rest cushion	replace arm rest	05/09/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	B Service As Per Attached Checklist		07/08/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\HYD LEAKS	Fit bottom slew motor seal	fit seal kit and crack test shaft	29/07/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\HYD LEAKS	Repair Hydraulic leak at bottom of stick boom pipe fitting		29/07/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DriCabRep\WIPERS	change wiper blade		28/07/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\OIL LEAK	tighten hyd nut on middle hyd ram	tightened hyd hose as best as could and washer down and can you ask Paul to keep a close eye on it?	19/07/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\COOL LEAKS	pressure test radiator - leaking bottom hose	tightened coolant hose clamps and pressure test and all good	19/07/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\FUEL TANK	engine warning light flashing when starting ladder	drain loader fuel tank	10/07/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\FUEL TANK	fuel leaking from drain plug on fuel tank		08/07/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist		08/07/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\FUEL TANK	Replace fuel cap	check cap and adjust	27/06/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\FILTERS	replace fuel filter		26/06/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\FUEL TANK	diagnose power issue - clear fuel restrictions		20/06/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\FUEL TANK	drain fuel tank of any foreign matter		19/06/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\FILTERS	replace 2x fuel filters		19/06/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Body\CHN/RLR/MN	need pin for grab chain		18/06/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DrCabElect\ELECT P&W	a/c electrical line fan short		18/06/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Chassis\HOUSEKEEP	replace 2 grease nipples L/R/rear legs		18/06/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\FILTERS	warning light flashing (water in fuel filler)		18/06/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Elect\WORK LIGHT	worklights outer boom n/w		18/06/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Elect\WORK LIGHT	work light n/w near steps		18/06/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\OIL/FILTER	Replace hydraulic tank filter		05/06/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
			B Service As Per Attached Checklist PLUS								
P27	Myrtleford - Workshop	VehService\BS	Hydraulic Service (L8967)	repaired boom lights	04/06/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DrCabElect\ELECT P&W	electric fuel pump not working		02/06/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Chassis\HYDRAULICS	replace main boom pivot bushes & FIT STICK BOOM BUSHED ALSO		26/05/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Chassis\DAMAGE	repair crack in main boom at first pivot		26/05/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Body\DAMAGE	straight RH drive guards		20/05/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\MOUNTS	check engine mounts/cab mount vibrations		20/05/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Chassis\HOUSEKEEP	grease loader/not grab		20/05/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Chassis\CHAS CRACK	repair cracks in main and outer booms		25/04/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist		24/04/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\OIL LEAK	top up hyd oil		09/04/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Chassis\CHAS CRACK	weld cracks in lift boom		09/04/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\HOUSEKEEP	check oil and coolant		09/04/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Chassis\HOUSEKEEP	grease loader and grab		09/04/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist		21/03/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DrCabElect\ELECT P&W	stroke light on roof u/s		06/03/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Chassis\HOUSEKEEP	grease slew ring		28/02/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Body\PANELS	remove rear engine cover to be copied for P-26		27/02/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Workshop\MOVE ASSET	take to Rinlatech and pick up and return		20/02/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Body\HOUSEKEEP	wash off loader deck		20/02/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\RAM	L/H lift ram seal leaking (fit seal kit)		20/02/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Air Con\AIR CON	aircon duct		18/02/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Body\PAINT/REST	pressure clean boom		18/02/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Chassis\HOUSEKEEP	grease loader		18/02/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Chassis\DAMAGE	weld pin/tags on grab		18/02/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\BELTS/TENS	adjust ac belt		06/02/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\HOUSEKEEP	extend engine breather pipe		06/02/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DriCabRep\AIR CON	relocate a/c vent from behind shoulder to in front		06/02/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist		06/02/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\HYD LEAKS	fit seal kit to grab hose swivel		30/01/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\HYD LEAKS	check grab rotator seal leaking hyd oil	remove and refit rotator for reseal	30/01/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\EXHAUST	missing exhaust rain cap	check rain cap (ok)	01/01/2020	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Chassis\HOUSEKEEP	grease bottom lift rams		11/12/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DriCabRep\WIPERS	replace wiper		11/12/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\DAMAGE	replace broken bolt on grab - tag bolt - hyd		11/12/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\MOTOR	Replace slew motor seal	fit c/over reo slew motor	06/12/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Chassis\DAMAGE	replace top main boom pin		04/12/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
				replaced hydraulic return filter							
				replaced servo filter							
P27	Myrtleford - Workshop	VehService\BS	B Service As Per Attached Checklist	replace cab filter	04/12/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\VALVES	Replace slew pedal linkage yoke & pin	remove bell crank under floor, build up holes and redrill them, refit and adjust linkages	03/12/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Chassis\HYDRAULICS	grease bottom lift ram pins		26/11/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\VALVES	take slack out of slew pedals		26/11/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\OIL LEAK	oil leaking - end of boom steel pipe joint hose	replace hyd fitting on end of boom	26/11/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\OIL LEAK	replace boom hose fitting		26/11/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\FILTERS	drain fuel filter		13/11/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Body\PANELS	Repair Walkway deck cracks		09/11/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\OIL/FILTER	filled hydraulic oil tank		08/11/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Chassis\HYDRAULICS	rewelded hose bracket and replaced bolts		08/11/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Body\HOUSEKEEP	washed down machine		08/11/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\HOSES	hose blown under loader	replaced hoses	08/11/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	B Service As Per Attached Checklist		08/11/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\CONSUMABLE	grease loader and grab		31/10/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Workshop\MOVE ASSET	pick up from Rinlatech		16/10/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
				repair LH main lift ram eye							
P27	Myrtleford - Workshop	Hydraulics\RAM	broken lift ram/spear	(reweld to spear on ram)	16/10/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\RAM	Remove & repair main lift cylinder		04/10/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Chassis\HYDRAULICS	grease bottom lift ram pins and slew ring	greased pins and slew ring	04/10/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	B Service As Per Attached Checklist		01/10/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\FILTERS	drain fuel filter		18/09/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\OIL/FILTER	check and add hydraulic oil		18/09/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE

P27	Myrtleford - Workshop	Hydraulics\OIL LEAK	Replace slew motor bottom seal	remove slew motor of P16 and Rinlatech have put bottom seal in motor and fitted to P27	18/09/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\OIL/FILTER	check/add hyd oil	added hydraulic oil	17/09/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\RAM	grease main lift pin		30/08/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\RAM	grease bottom lift hyd pins		21/08/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	B Service As Per Attached Checklist		20/08/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\RAM	grease bottom lift pins		10/08/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\FILTERS	check/drain fuel filter/water		10/08/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\EXHAUST	Replace Rain Cap		20/07/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\HOSES	Tighten Hydraulic Hose - Enfd Of Boom		20/07/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
				pressure wash leg swivel							
				Part No. S00153							
				SN235							
P27	Myrtleford - Workshop	Hydraulics\HYD LEAKS	Fit Seal Kit To Leg Swivel Under Cab	10049018	20/07/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\RAM	Grease Bottom Lift Rams		20/07/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\EXHAUST	missing exhaust rain cap		19/07/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	B Service As Per Attached Checklist		19/07/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\HOSES	check/replace hyd hose above boom		10/07/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\HOSES	need 2 new hyd hoses		10/07/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\DAMAGE	reweld grapple tips		16/06/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
				washers n/w							
				reattached grapple tip							
P27	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	change hyd and servo filters	15/06/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\DAMAGE	Weld Grab Tip Back On		14/06/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Body\ELECT P&W	Replaced LHS Work Light Plug		14/06/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Body\MOUNTS	Re - Attach Work Light Cover RHS		14/06/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\EXHAUST	repair exhaust leak		04/06/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Chassis\HYDRAULICS	Repair Grack Cracks & Build Up Tips		04/06/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\HYD LEAKS	tightened weeping hose on grabble		02/06/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	B Service As Per Attached Checklist		15/05/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DriCabRep\RADIO	replace UHF microphone		11/05/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Chassis\DAMAGE	Replace LHR Lower Leg Pin		09/05/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Chassis\DAMAGE	check/tighten LHR main leg pin		08/05/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DrCabElect\INST/GAUGE	hr meter n/w		08/05/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Cooling\RADIATOR	Repair Leaking Radiator(L6002)(L6018)(6019)		13/04/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\COOL LEAKS	check hose/clamp bottom of radiator		15/03/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Chassis\HYDRAULICS	tighten nut grab head to link		15/03/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\BELTS/TENS	fit new a/con belt		13/03/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Chassis\CHAS CRACK	repair crack in LH/RH bottom ram mount on chassis		13/03/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\TOOLBOX	inspect steel hyd pipe end of boom leaking oil		13/03/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Chassis\HYDRAULICS	weld tips on grab		13/03/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\PUMP	check hyd pressure/adjust		13/03/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Cooling\RADIATOR	check radiator/pressure, using coolant		13/03/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	B Service As Per Attached Checklist	replace exhaust rain cap	09/03/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	B Service As Per Attached Checklist	check coolant leak and top up	02/02/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\BELTS/TENS	check a/c belt tension		16/01/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\FAULT CODE	waving light flashing fuel filter (water)		05/01/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\HOUSEKEEP	fill reservoir coolant		05/01/2019	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
			replace aircon compressor								
			replace drier								
P27	Myrtleford - Workshop	Air Con\AIR CON	repair and regas aircon system		25/12/2018	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist		15/12/2018	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Workshop\MOVE ASSET	take P27 to and from Rinlatech		27/11/2018	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\RAM	replace grab ram seals and fit new spare to ram		27/11/2018	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Elect\WORK LIGHT	fit new led light bar to cabin		25/10/2018	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\RAM	check other boom pins and ram bushes (ok)		20/10/2018	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\DAMAGE	Replace 3 bottom boom bushes and make new pin		20/10/2018	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\OIL/FILTER	change servo filter		05/10/2018	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\OIL/FILTER	change hydraulic filter		05/10/2018	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\BELTS/TENS	Replace engine fan pulley		27/09/2018	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
				tighten engine mount bracket bolts							
P27	Myrtleford - Workshop	VehService\BS	B Service As Per Attached Checklist	tight fan bolts	26/09/2018	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DrCabElect\HEATER REP	cabin heater knob missing - make up knob		08/09/2018	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\FILTERS	drain fuel filter/seperator		08/09/2018	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\FAULT CODE	replace fuel pump		26/08/2018	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	B Service As Per Attached Checklist		21/08/2018	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\FAULT CODE	water in fuel filter		09/08/2018	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DriCabRep\HOUSEKEEP	fitted screws to guage cluster panel		21/07/2018	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DriCabRep\RADIO	fitted screws to radio panel		21/07/2018	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\FAULT CODE	warning light flashing. warningi light flashing		21/07/2018	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DriCabRep\HOUSEKEEP	water leaking through roof/bolts above fan (2) of		21/07/2018	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DriCabRep\DOOR LOCK	adjust door latch hard to open door		21/07/2018	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	B Service As Per Attached Checklist		13/07/2018	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DriCabRep\DOOR LOCK	adjust door latch - hard to open		30/06/2018	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Body\CHN/RLR/MN	missing bolt in grab chain		29/06/2018	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\OIL LEAK	Replace engine breather pipe & o'rings		28/06/2018	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	B Service As Per Attached Checklist	slastic roof top (leaking)	09/06/2018	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Cooling\RADIATOR	Check cooling system for leaks & cold water leaks		01/06/2018	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DriCabRep\SEAT	Replace R/H arm rest cushion		31/05/2018	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Cooling\RADIATOR	radiator leaking water		31/05/2018	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DriCabRep\SEAT	Replace strut for arm rest L/H		31/05/2018	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
				Washed down motor & loader							
P27	Myrtleford - Workshop	Hydraulics\MOTOR	Fit seals to slew motor	fit reco slew motor	26/05/2018	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Chassis\DAMAGE	Repair grab tips		26/05/2018	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\HOUSEKEEP	fill coolant reservoir and check engine oil		25/05/2018	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DrCabElect\ELECT P&W	electric fuel pump n/working		25/05/2018	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\HOSES	Replace both slew motor hoses & wash down	check hyd oil	04/05/2018	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Body\HOUSEKEEP	grease loader		03/05/2018	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	B Service As Per Attached Checklist		03/05/2018	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\RAM	Repair grab pin bolt - keeps coming loose		13/04/2018	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DrCabElect\INST/GAUGE	dash lights not working		05/04/2018	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DrCabElect\ELECT P&W	Interior light not working		05/04/2018	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\OIL LEAK	replace grab rotor fittings and o'rings		23/03/2018	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
			drain hyd oil								
			replace hyd filter								
P27	Myrtleford - Workshop	Hydraulics\OIL/FILTER	replace servo filter		20/03/2018	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Chassis\CHAS CRACK	Repair crack in LHS of main boom		10/03/2018	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Chassis\HOUSEKEEP	Repair LH deck cracks		10/03/2018	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
			L/H hand control/servo's worn out								
P27	Myrtleford - Workshop	Hydraulics\VALVES	-joystick comes out		09/03/2018	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	B Service As Per Attached Checklist		09/03/2018	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
			Check & Repair hydraulic servo pump								
			- engine oil getting into hydraulic system								
P27	Myrtleford - Workshop	Hydraulics\PUMP	Get servo pump inspected/rebuilt	fit seal kit to hyd servo pump	08/03/2018	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\HOUSEKEEP	Top up engine oil		07/03/2018	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE

P27	Myrtleford - Workshop	Engine\HOUSEKEEP	Inspect engine oil getting into hydraulic oil		07/03/2018	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Body\HOUSEKEEP	Wash hydraulic tank		07/03/2018	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\OIL/FILTER	Drain overull hydraulic tank		07/03/2018	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\HOUSEKEEP	top up coolant		06/03/2018	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
			slew not holding position - creeping L&R								
P27	Myrtleford - Workshop	Hydraulics\VALVES	L/H servo's sticking		06/03/2018	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Elect\BATTERY	jumpstart battery on loader (call out)		23/02/2018	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Elect\BATTERY	Fit new battery		23/02/2018	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Elect\ELECT P&W	Check starting & charging system		23/02/2018	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\HOUSEKEEP	fill up coolant drum		22/02/2018	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\HOUSEKEEP	check and top up engine oil & coolant		22/02/2018	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
			check + top up engine oil								
			check coolant								
P27	Myrtleford - Workshop	Engine\HOUSEKEEP	top up windscreen washer bottle		17/02/2018	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Chassis\DAMAGE	weld new tip on grab		08/02/2018	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DrCabElect\RADIO	tighten aerial for radio (loose)		03/02/2018	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	B Service As Per Attached Checklist		31/01/2018	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Body\HOUSEKEEP	Fill engine oil container & wash loader		20/01/2018	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\OIL/FILTER	Check hydraulic filter & oil change tank filter		20/01/2018	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\HOUSEKEEP	check oil and coolant		16/01/2018	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Chassis\HOUSEKEEP	weld crack in cab (Rinlatech)		16/01/2018	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\HOSES	Repair or replace hydraulic boom pipes		21/12/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\RAM	put grease in bottom lift rams		20/12/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	B Service As Per Attached Checklist		19/12/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\HOSES	make up 2x spare boom to grab hoses		14/12/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DrCabElect\INST/GAUGE	flashing light on roof - not working		05/12/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
			de-grease and wash grab, booms and rams								
			remove fly boom ram								
			pins siezed and severely worn on bearing carrier area and required heating, cutting, hitting and								
			weld on frame to remove								
			clean up and weld cracked boom and loader frame								
			replaced worn linkage pins for slew pedal								
			repaired bushes and barrel end of ram								
P27	Albury - Workshop	Body\PANELS	fitted ram		05/12/2017	Completed	LOADPRENT	Myrtleford	MLR	Albury Workshop	PRENTICE
			add engine oil to container								
			add coolant to container								
P27	Myrtleford - Workshop	Engine\HOUSEKEEP	check & top up engine oil		30/11/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\EXHAUST	Replace Rain Cap		15/11/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
				inner air filter changed at 6108 hrs							
P27	Myrtleford - Workshop	VehService\BS	B SERVICE per the attached Check list	rain cap broken	14/11/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\CONSUMABLE	test loader		07/11/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\OIL/FILTER	check hydraulic oil		07/11/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Body\HOUSEKEEP	wash loader		07/11/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\HYD LEAKS	repair hard line		07/11/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\HOSES	replace hyd hose from hyd pump to servo valve		07/11/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\HOUSEKEEP	add engine oil		31/10/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\HOSES	tidy up hydraulic hose and refit clamps on main boom		05/10/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
			fit 2x new light force								
P27	Myrtleford - Workshop	Elect\WORK LIGHT	work lights to main boom		04/10/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DrCabElect\RADIO	Send UHF for repairs & refit		29/09/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DrCabElect\RADIO	UHF light - not working		28/09/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Body\HOUSEKEEP	supply 1 box of grease		28/09/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\HOUSEKEEP	check and add engine oil		28/09/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\OIL/FILTER	check and add hydraulic oil		28/09/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\HOSES	make up 2x boom - hydraulic hoses		28/09/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\FUEL TANK	Make new fuel cap gasket		20/09/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
				fuel tank cap cork gasket u/s							
P27	Myrtleford - Workshop	VehService\BS	B Service As Per Attached Checklist	grease loader replace warn grease nipples	19/09/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
			9L - engine oil								
P27	Myrtleford - Workshop	Engine\HOUSEKEEP	3L - coolant		01/09/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\HOUSEKEEP	check engine oil/coolant		01/09/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\OIL/FILTER	Change Hyd Servo Fiter		18/08/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\OIL/FILTER	Change Hydraulic Oil		18/08/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\VALVES	Check & Adj Hyd. Pressure		18/08/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	B Service As Per Attached Checklist		12/08/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\BELTS/TENS	tighten fan belts - squealing heater/aircon on		08/08/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\OIL/FILTER	check hyd oil level		29/07/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Body\HOUSEKEEP	wash downb loader and engine		29/07/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\FAULT CODE	check eng settings		28/07/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\ENG TUNE	tune engine		28/07/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Chassis\HOUSEKEEP	weld extra on grab tip		19/07/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
			Replace fan belt tensioner								
			Replace fan pulley								
P27	Myrtleford - Workshop	Engine\BELTS/TENS	Replace fan belt		29/06/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	B Service As Per Attached Checklist		27/06/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DrCabElect\INST/GAUGE	Repair hour meter - not working	Complete	26/06/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DrCabElect\INST/GAUGE	Check no dash/switch lights	Complete	23/06/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
				Tighten air con belt							
P27	Myrtleford - Workshop	Engine\BELTS/TENS	Check idle pulley - squealing when air con heater on or high revs	Complete	23/06/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\FUEL TANK	drain water out of tank and fuel filter		09/06/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Elect\WORK LIGHT	lights on outer boom short in wire		09/06/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\FAULT CODE	warning light flashing when engine started (10 sec)		08/06/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Body\DAMAGE	repair LHS - check log damage		02/06/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DrCabElect\RADIO	UHF antenna broken		02/06/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DrCabElect\INST/GAUGE	repair dash light power problem		02/06/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\HOSES	replace grab hyd hose		02/06/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\HOUSEKEEP	check/add engine oil		01/06/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Body\HOUSEKEEP	clean down hydraulic leak		23/05/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\OIL/FILTER	check hydraulic oil		23/05/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\HYD LEAKS	check hydraulic leak and tighten bolts on filter cap		23/05/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\FAULT CODE	Check for engine codes	code 418 clean and check fuel filter plug also drain fuel filter	23/05/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Chassis\HOUSEKEEP	Repair LHR leg pin tag		23/05/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\FAULT CODE	Check warning light flashing when starting up	Complete	19/05/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\MOUNTS	reposition a/c compressor mount		16/05/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\HOUSEKEEP	modify safety cover		16/05/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\BELTS/TENS	fit new fan and a/c belts		16/05/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Cooling\COOL LEAKS	replace radiator overflow pipe		13/05/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist		09/05/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
				Tighten a/c belt							
P27	Myrtleford - Workshop	Engine\BELTS/TENS	Fan belts squealing when a/c heater operating	Complete	08/05/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\HOUSEKEEP	oil filler cap keeps coming off		29/04/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\COOL LEAKS	loader loosing coolant		29/04/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\HOUSEKEEP	check and top up oil		22/04/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Cooling\HOUSEKEEP	add coolant to reservoir		22/04/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE

				repair LH joystick ball and fin							
P27	Myrtleford - Workshop	Hydraulics\VALVES	Replace LH servo lever ball & socket & pin	new pin	24/03/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\BOOST HOSE	Replace 90deg bend boost hose	check boost hose - ok at this stage. We have new hose in stock ready to replace	24/03/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\OIL LEAK	Replace sump plug dowdy washer		24/03/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist		23/03/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\VALVES	Remove servo handle & inspect defect parts	Complete	22/03/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\HOUSEKEEP	check engine oil		22/03/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Body\PAINT/REST	paint grab bar/cradle		10/03/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Body\PAINT/REST	paint grab		10/03/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\HOSES	replace leaking hydraulic hoses at pump	Complete	07/03/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DriCabRep\RADIO	Fit new am/fm aerial	Complete	07/03/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
			replace bottom seal in slew motor								
P27	Myrtleford - Workshop	Hydraulics\HYD LEAKS	-Rinlatech eng.		03/03/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\HOUSEKEEP	top up coolant		01/03/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\HOUSEKEEP	top up engine oil		01/03/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\FILTERS	replace inner air filter		25/02/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\HOUSEKEEP	top up engine oil 7 lts		25/02/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\BOOST HOSE	tighten cooling hose clamps		25/02/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\AIR CLNR	check over engine intake for dust contamination		25/02/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Chassis\HOUSEKEEP	weld tip on grab		19/02/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Chassis\HOUSEKEEP	Replace broken slew ring mount bolt. Relace broken slew ring mount bolt	checked slew ring bolt - ok for now	08/02/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\RAM	Tighten bolt/tag on grab ram (top)	Complete	07/02/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist		07/02/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\HOUSEKEEP	check/add engine oil		26/01/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\CONSUMABLE	1x hyd fitting for grab hose/ram		20/01/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\HOUSEKEEP	oil gauge moving around - operating revs		20/01/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
				Tighten belt							
P27	Myrtleford - Workshop	Engine\BELTS/TENS	Check air con belt, fan belts & pulleys - starting to squeal	Complete	03/01/2017	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DriCabRep\WIPERS	windscreen blocked (bottle)		23/12/2016	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\VALVES	check hydraulic problems		21/12/2016	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\PUMP	no hydraulics		21/12/2016	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist		20/12/2016	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\HOSES	fit lay flat to hyd hose		13/12/2016	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Body\HOUSEKEEP	wash & degrease loader		13/12/2016	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\HOSES	replace hyd hose (short) bottom RH lift ram blown		13/12/2016	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\HYD LEAKS	Wash out containers for hydraulic oil		12/12/2016	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Chassis\HOUSEKEEP	replace grease nipple. L/H bottom lift ram (steps)		18/11/2016	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Cooling\RADIATOR	radiator losing water		18/11/2016	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\MOTOR	Replace slew motor drive gear		15/11/2016	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
				Remove broken slew motor, fit re-conditioned slew motor							
				test & wash down. Fit new gear locking screw. Check & top up hydraulic oil							
P27	Myrtleford - Workshop	Hydraulics\MOTOR	Replace broken slew shaft	Complete	12/11/2016	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
			Hydraulic pressure Test	pressure test hyd system							
P27	Myrtleford - Workshop	Hydraulics\VALVES	Lift boom + grab	weld tips on grab	12/11/2016	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	fit bolt & tighten washer bottle bracket	08/11/2016	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Body\HOUSEKEEP	fit bolt to stereo console		20/10/2016	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Body\HOUSEKEEP	weld extra on tips of grab		20/10/2016	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\RAM	Replace broken bolt to hold pin (grapple) on hyd spear	Complete	17/10/2016	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Body\HOUSEKEEP	replace broken nipple LH rear leg		30/09/2016	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist		28/09/2016	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Body\TP05	weld crack in rear panel		10/09/2016	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Body\TP05	rear panel latch/pins need adjusting		10/09/2016	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DrCabElect\RADIO	replace UHF microphone & bracket		01/09/2016	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist		26/08/2016	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DriCabRep\DOOR LOCK	Replace door gas strut		25/08/2016	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\HOSES	Replace broken bolt for triple pump hydraulic hose clamp	Complete	23/08/2016	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\FAULT CODE	Check warning light flashing	Complete	23/08/2016	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DriCabRep\AIR CON	Unblock air con water outlet	Complete	23/08/2016	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\OIL LEAK	hose down grapple and truck		12/08/2016	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\HOSES	replace 2 hyd hoses from end boom to grapple		12/08/2016	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\RAM	put grease in bottom lift rams		20/07/2016	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Chassis\HOUSEKEEP	replace "d" shackle on grab bar		20/07/2016	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	retro fit another sump plug until new one arrives	20/07/2016	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DrCabElect\ELECT P&W	Replace Horn		05/07/2016	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DriCabRep\WIPERS	Replace wiper blade	Complete	01/07/2016	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Body\TOOLBOX	Drill 2 holes in tool box A frame to drain water	Complete	01/07/2016	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist		02/06/2016	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\VALVES	Lube parts under joysticks LH & RH	Complete	27/05/2016	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Body\HOUSEKEEP	lock for fuel pump wont lock		21/05/2016	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\HOSES	make up spare hyd hyd hoses & supply fittings		14/05/2016	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist		29/04/2016	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Chassis\HOUSEKEEP	grease loader		28/04/2016	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
			Grease boom nipples								
P27	Myrtleford - Workshop	Chassis\HOUSEKEEP	Grease all leg grese nipples	Complete	15/04/2016	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Body\HOUSEKEEP	replace lock for fuel pump		15/04/2016	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Brakes\PAINT/REST	paint body		09/04/2016	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Chassis\HOUSEKEEP	Fit grease lines to main boom bushes	Complete	04/04/2016	Completed	LOADPRENT	Myrtleford	MLR	Unknown	PRENTICE
			Replace all 4 Bushes on both main Lift Rams								
P27	Myrtleford - Workshop	Hydraulics\RAM	Replace bottom & top main lift pins	Complete	04/04/2016	Completed	LOADPRENT	Myrtleford	MLR	Unknown	PRENTICE
			replace main boom bass pin & bushesx3								
			replace bottom & top main lift ram pins								
P27	Myrtleford - Workshop	Body\MOUNTS	replace all 4 main lift ram end bushes	Complete	04/04/2016	Completed	LOADPRENT	Myrtleford	MLR	Unknown	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\PUMP	Inspect Slew Gear	complete	10/03/2016	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Elect\HOUSEKEEP	Wash Loader	Complete	10/03/2016	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
			Check air con system								
P27	Myrtleford - Workshop	Air Con\AIR CON	Regas & replace dryer	Completed - Myrtleford Auto Electrics	10/03/2016	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
				Driver to monitor							
P27	Myrtleford - Workshop	DrCabElect\INST/GAUGE	check horn - only works occasionally	Completed	19/02/2016	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\HOSES	grease hoses coming off end of boom	Completed	19/02/2016	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Body\WIPERS	wiper water jets blocked	Completed	19/02/2016	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
				Tighten heater hoses and blow out air con drains							
P27	Myrtleford - Workshop	Air Con\AIR CON	1/2" hose for air con cracked under floor	Completed	19/02/2016	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
				Completed B Service							
P27	Myrtleford - Workshop	VehService\BS	oil & fuel filters	Replaced Oil & Fuel Filters	18/02/2016	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
				Some movement found in main boom bushes							
				Driver to monitor							
P27	Myrtleford - Workshop	Body\MOUNTS	Check pins & bushes on main boom to main frame	Completed	12/02/2016	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\HOSES	Grease line undone at end of main boom	Completed	12/02/2016	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DriCabRep\HOUSEKEEP	repair leak in bolts on sunroof	completed	22/01/2016	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\FILTERS	oil fuel & air filters	completed	12/01/2016	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	completed	11/01/2016	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
				replace worn pin & bushes at end of boom							
P27	Myrtleford - Workshop	Hydraulics\RAM	pin/bushes end of boom all flogged out near cab	completed	11/01/2016	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\HOSES	replace grease hose on end of boom near cab	completed	11/01/2016	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\BELTS/TENS	1 x fan belt 1 x air con belt	completed	06/01/2016	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE

P27	Myrtleford - Workshop	Chassis\HOUSEKEEP	grease hose has come undone at end of boom	completed	29/12/2015	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\RAM	repair tag bolt on grab	completed	29/12/2015	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\RAM	repair leg rams uhf mics+filters	completed	05/12/2015	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\FILTERS	tctc repair short in worklights check all boom light wiring	completed	21/11/2015	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Elect\ELECT P&W	make up longer boom light harness between main + stick booms	completed	21/11/2015	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist repair wiring loom for outer book work lights drain water from fuel/water seperator filter fit 2 new rear leg lock valves	completed	21/11/2015	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Elect\ELECT P&W	top uo hyd oil	completed	18/11/2015	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\RAM	2 leg lock valves fit seal kit to rhr leg	completed	13/11/2015	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Body\TRL LEGS	change front leg hold valves to rear legs	completed	12/11/2015	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	DrCabElect\RADIO	replace uhf microphone repairs to leg ram	completed	10/11/2015	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\RAM	rinl	completed	06/11/2015	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Hydraulics\RAM	reseal front + rear leg relief valves + check pressure	completed	03/11/2015	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	completed	16/10/2015	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	VehService\BS	oil+fuel+air filters	completed	16/10/2015	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Chassis\HYDRAULICS	fit seals to lift ram + hyd pump + susp parts check + clean air con filters	completed	10/10/2015	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Air Con\AIR CON	fit seal kit to lhr leg ram	completed	09/10/2015	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Chassis\HYDRAULICS	Job Added From Invoice repair hydraulics + rear leg pressure fit bearing + seals to hyd pump adjust servo pressure+replace servo filter		09/10/2015	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Engine\DAMAGE	Replace hyd oil + filter	completed	24/09/2015	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Steering\WHEEL SEAL	Service Job Added From Invoice fit outer boom seal kit weld boom pin lock tab		24/09/2015	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Body	top up hyd oil repair leaking hyd ram for dipper arm	completed	10/09/2015	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P27	Myrtleford - Workshop	Elect	repair uhf back light	completed	05/09/2015	Completed	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE