EquipmentName	Workshop	CodeAndSubCode	Description	Schedule	CompletionComments	DateDone	DistanceDone	Worktype	Workstate	EquipmentOwner	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
LOAD27	Myrtleford - Workshop	Engine\AIR LEAK	REPLACE LEAKING AIR DRYER & FILTER ASM		CHANGE AIR DRYER FILTER & TEST ALL OK	13/10/2026	763500	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	VehService\AS	VehService\AS A Service	VehService\AS	B SERVICE AT 766398 KMS	13/10/2026	763500	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	VehService\BS	VehService\BS B Service	VehService\BS	B SERVICE AT 766398 KMS	13/10/2026	763500	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Insp\ANN INSP	Insp\ANN INSP annual inspection as per check list	Insp\ANN INSP		24/08/2026	763500	PreventativeMaintenance	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	VehService\AS	VehService\AS A Service	VehService\AS		13/08/2026	761800	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\WIPERS	CHECK AND REPAIR WIPER WASHERS NOT WORKING		REMOVE WASHER JETS CLEANED OUT AND RETESTED ALL GOOD REFILLED BOTTLE	31/07/2026	759038	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\MIRRORS	REPLACE LH & RH TOP MIRROR GLASSES			29/07/2026	761800	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
					Check operation of electric windows. located relays and check output from swiches, missing common return for down function, check wiring in door. Found broken wires, repair and test, windows now working. Check mirror heat function, found broken wires in mirror, repair and test, bottom mirrors heating up but top mirrors are not, check											
LOAD27	Myrtleford - Workshop	DrCabRep\ELECT P&W	ELE ISSUE WITH PASS SIDE WINDOW UP /DOWN		resistance, diagnose faulty mirrors. reassemble.	29/07/2026	755147	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Susp\SWAYBAR	REPLACE REAR SWAY BAR & BUSHES			29/07/2026	761800	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\AKE BRAKE	REPLACE EXHAUST BRAKE HOUSING AT TURBO			29/07/2026	761800	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
					KLM AT TIME OF REPLACEMENT 755147 (CALL OUT)											
LOAD27	Myrtleford - Workshop	Susp\AIR BAG	FRONT DRIVE RH SECOND AIR BAG BLOWN		PART NUMBER 3092216 (FRONT DRIVE AIR BAG)	07/07/2026	755147	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
					KLM AT TIME OF SERVICE 754320											
LOAD27	Myrtleford - Workshop	VehService\AS	VehService\AS A Service	VehService\AS	TIGHTEN FRONT DIFF INPUT SHARFT NUT	02/07/2026	754330	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
					KLM AT TIME OF REPLACEMENT 754330											
LOAD27	Myrtleford - Workshop	Steering\PWR STEER	STEERING BOX SECTOR SHAFT TO MUCH MOVEMENT BOX NEEDS REPLACING		SERVICED P/STEERING SYSTEM NEW OIL AND FILTER	30/06/2026	754330	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Steering\KING PIN	KINGS NEED ADJUSTING TO MUCH UP AND DOWN MOVEMENT		READJUSTED LH /RH KING UP AND DOWN BYE REMOVING SHIMS UNDER TOP BEARING (WASHED AND REPACKED BEARING) KLM AT TIME OF ADJUSTMENT 754330	30/06/2026	754330	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
					Test reverse lights. Not working. Test relay.											
					Not switching earth to relay. Check wiring.											
					Bulk head connector faulty. Bypass connector.											
LOAD27	Myrtleford - Workshop	Body\ELECT P&W	REV LIGHTS AND BUZZER NOT WORKING & BRAKE LIGHTS (ELE ISSUE)		Retested ok. Reverse liahts now work.	25/06/2026	750079	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	ARKON AUTO ELECTRICAL - 3	LOADER
					Remove rocker cover. Test engine brakes.											
					Engine brakes working. Road tested to confirm											
					all ok.											
					Tested exhaust brake system.											
			ENGINE BRAKE NOT WORKING ON STAGE 1 OR 2 (ELE ISSUE)		Exhaust brake solenoid working. Remove											
			* 2 Repair engine brakes [engine under rocker cover]		pneumatic valve for exhaust brakes.											
					Broken in half. Will need to replace whole											
LOAD27	Myrtleford - Workshop	Engine\ELECT P&W	* 3 Exhaust brake doesn't come on with oark brake.		accuator.	25/06/2026	750079	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	ARKON AUTO ELECTRICAL - 3	LOADER
LOAD27	Myrtleford - Workshop	DrCabRep\ELECT P&W	BLOWER FAN NOT WORKING AFTER ATTENDING ARKON		INSPECTED ALL COMPONENTS AND SWITCHES FOUND PLUG WAS UNPLUGGED AT BLOWER FAN BEHIND DASH PASSENGER SIDE	10/06/2026	750079	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabRep\SEAT	FIT NEW ISRI DRIVERS SEAT TO SUIT VOLVO			10/06/2026	750079	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Elect\BRK LIGHT	BRAKE LIGHTS NOT WORKING		INSPECTED FOUND LIGHTS WORK ONLY WHEN PARK BRAKE IS RELEASED NOT ENGAGED STILL NOT RIGHT ARKON TO INSPECT MORE	04/06/2026	750079	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Tyres\TP11	Tyres\TP11		P/R NWR	29/05/2026	750079	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	BORDER BANDAG PTY LTD -3	LOADER
					KLM AT TIME OF SERVICE 750079											
					CARRY OUT SERVICE PLUS R&R WORK LIST											
LOAD27	Myrtleford - Workshop	VehService\AS	VehService\AS A Service	VehService\AS	REPLACED FLAT TIRE RH REAR INNER	28/05/2026	750079	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
					Check the operation of the speedo and jakes, the speedo was dropping											
					in and out when driving down the road. Plugged scan tool into the vehicle											
					and found the engine computer was not connecting to the rest of the truck.											
					Lift crane off of the support to lift the bonnet. Inspect speed sensor wiring,											
					could not find any breaks or rubs in the speed sensor wiring. Inspect the											
					wiring harness from the ecm to the firewall for rubs, brakes or shorts.											
					Found multiple rubbed wires, found the can wiring was rubbed and there											
					was a melted wire from the alternator back to the firewall, need to remove the											
					dash to inspect the wiring inside the cab. Cut and repair all of the wiring											
					correctly, tape and tube the wiring harness. Secure. Check the operation of											
					the can and found the circuit was still open, did an end to end test across											
					the firewall plug and found the can wiring was not connecting inside the plug,											
					cut and bypass the plug. Connect wiring into a new plug and test. The engine											
					computer is now working correctly. Test drove and found the speedo still											
					dropped out but the jakes are now working correctly. Ran new wiring from the											
					dash to the speed sensor and secure correctly, test. The speedo is now											
LOAD27	Myrtleford - Workshop	Elect\ELECT P&W	Road speed sensor has a short in the wiring, it goes good then it goes into limp mode.		workine correctly. Put the truck back toeether	08/05/2026	744167	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	ARKON AUTO ELECTRICAL - 3	LOADER
LOAD27	Myrtleford - Workshop	VehService\BS	VehService\BS B Service	VehService\BS	KLM AT TIME OF SERVICE 744167	27/03/2026	744167	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Brakes\BRK O/HAUL	REPLACE RHF DRIVE HUB SEAL		KLM AT TIME OF REPAIR 744167	26/03/2026	744167	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Susp\SWAYBAR	REPLACE UPPER & LOWER REAR SWAY BAR CLAMP RUBBERS ON RHR SIDE			26/03/2026	744167	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Chassis\SUSPENSION	Bush missing, Stable Arm on torsion arm			24/03/2026	744167	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	RINLATECH ENGINEERING-3	LOADER
LOAD27	Myrtleford - Workshop	Body\FUEL TANK	TANK STRAP CRACKED DRIVERS SIDE		RE WELDED TANK STRAP WERE DRIVERS STEP MOUNTS TO	06/03/2026	742897	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
			REPLACE REAR DIFF VEE STAY (KOETONG)		KLM AT TIME OF REPAIR 741897											
LOAD27	Myrtleford - Workshop	DrivLine\SUSPENSION			REPLACED REAR SERVICE LINE Q/R VALVE DAMAGED BY VEE STAY	04/03/2026	741897	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Tyres\Punct	Tyres\Punct POS 8			26/02/2026	742897	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	BORDER BANDAG PTY LTD -3	LOADER
LOAD27	Myrtleford - Workshop	Tyres\TP1+2	Tyres\TP1+2			19/02/2026	731732	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	BORDER BANDAG PTY LTD -3	LOADER
LOAD27	Myrtleford - Workshop	VehService\AS	VehService\AS A Service	VehService\AS	SERVICED AT 739160 KMS	12/02/2026	731732	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
					CHECK G/BOX LINKAGE & FOR AIR LEAKS (ALL OK)											
LOAD27	Myrtleford - Workshop	DrivLine\CLUTCH	INSPECT FIRST AND FORTH GEAR HARD TO SELECT WHILE MOVING		CHECKED AT 739160KMS	11/02/2026	731732	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Tyres\TP11+12	Tyres\TP11+12		LOW	24/01/2026	731732	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	BORDER BANDAG PTY LTD -3	LOADER
LOAD27	Myrtleford - Workshop	Tyres\TP9+10	Tyres\TP9+10		LOW	24/01/2026	731732	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	BORDER BANDAG PTY LTD -3	LOADER
LOAD27	Myrtleford - Workshop	Tyres\RUN OUT	Tyres\RUN OUT FITTED TO SPARE			15/01/2026	731732	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	BORDER BANDAG PTY LTD -3	LOADER
					REPAIRED A/C WIRING											
LOAD27	Myrtleford - Workshop	VehService\AS	VehService\AS A Service	VehService\AS	TIGHTEN MIRROR BRACKET	08/01/2026	731732	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Tyres\Punct	REPLACE LH REAR INNER DRIVE TYRE (FLAT)			04/12/2025	731732	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	VehService\BS	VehService\BS B Service	VehService\BS	KLM AT TIME OF SERVICE 730137	15/11/2025	730137	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
					REPLACED LH REAR AIR BAG											
LOAD27	Myrtleford - Workshop	VehService\AS	VehService\AS A Service	VehService\AS	TIGHTEN ALT BELT	19/09/2025	725981	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Elect\HEAD LIGHT	REPAIR H/LIGHTS & D/LIGHTS FLICKERING		REPLACED LH FRONT HEAD LED GLOBE	17/09/2025	725981	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	MYRTLEFORD AUTO ELECTRICS - 3	LOADER
LOAD27	Myrtleford - Workshop	Body\WHL HUB	REPLACE BROKEN WHEEL STUD LH STEER			16/09/2025	725981	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Insp\ANN INSP	Insp\ANN INSP			09/08/2025	725981	PreventativeMaintenance	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
				Insp\ANN INSP	FOUND BROKEN WIRING AT BACK OF LIGHT REPAIRED AND TESTED											
LOAD27	Myrtleford - Workshop	Elect\INDICATORS	LH FRONT INDICATOR NOT WORKING		ALL GOOD	10/07/2025	717091	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Elect\DRV LIGHT	driving light LH side flicking on and off		replaced wire to driving light and tested all good	01/07/2025	717091	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	VehService\BS	VehService\BS	VehService\BS		14/06/2025	714854	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
					FITTED 2 NEW SWAY BAR BUSHES ON 11/2/26											
LOAD27	Myrtleford - Workshop	Susp\SWAYBAR	REPLACE FRONT STEER AXLE SWAY BAR BUSHES		AT 739160 KMS	14/06/2025	731732	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrivLine\SUSPENSION	REPLACE REAR DIFF SWAY BAR BUSH			14/06/2025	731732	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\CH&S	replace walk way grip tape rear of cabin			14/06/2025	731732	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\WATER PUMP	FIT NEW WATER PUMP & GASKETS & O RINGS			14/06/2025	731732	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrivLine\SUSPENSION	FIT REAR DIFF VEE STAY BUSH KIT			14/06/2025	731732	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrivLine\OIL LEAK	REPLACE GEAR SELECTOR SHAFT SEAL & BOOT			14/06/2025	731732	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrivLine\OIL LEAK	REPLACE REAR DIFF INPUT SEAL			14/06/2025	731732	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\MOUNTS	REPAIR INTERCOOLER PIPE MOUNT & FOT NEW O RINGS		Repair intercooler pipe mounts.	14/06/2025	731732	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrivLine\SUSPENSION	REPAIR REAR AXLE SUPPORT CHAINS			14/06/2025	731732	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Tyres\TP1+2	Tyres\TP1+2			11/06/2025	711919	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	BORDER BANDAG PTY LTD -3	LOADER
LOAD27	Myrtleford - Workshop	Elect\DAY LIGHTS	lh drl not working			17/05/2025	711919	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
					KLM at time of service 710810											
					repaired wiring for rh side lights											
LOAD27	Myrtleford - Workshop	VehService\AS	VehService\AS	VehService\AS		06/05/2025	710200	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Susp\AIR BAG	replace LH front drive first air bag		KLM at time of repair 710810	06/05/2025	710200	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
			LH mirror top bracket broken													
LOAD27	Myrtleford - Workshop	Body\MIRRORS	TIGHTEN MIRROR MOUNT BOLTS			08/04/2025	708184	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
			FIT CHAIN TO FUEL CAP													
LOAD27	Myrtleford - Workshop	Body\FUEL TANK	R/R 128926			08/04/2025	708184	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Susp\AIR BAG	replace RHF air bag on rear drive axle			08/04/2025	708184	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
			REPAIR DASH LIGHTS													
LOAD27	Myrtleford - Workshop	DrCabElect\INST/GAUGE	R/R 128926			08/04/2025	708184	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
			REPLACE ACCESSORY DRIVE ASSEMBLY FAN & ALT BELTS													
			(BEARING HAS FAILED) & WASH ENGINE & SURROUNDS													
LOAD27	Myrtleford - Workshop	Engine\OIL LEAK	done at 708235kms			27/02/2025	706944	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	CMV TRUCK AND BUS PTY LTD - 3	LOADER
			TUNE ENGINE & CHECK JAKES													
LOAD27	Myrtleford - Workshop	Engine\ENG TUNE	done at 708235kms			27/02/2025	706944	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	CMV TRUCK AND BUS PTY LTD - 3	LOADER
LOAD27	Myrtleford - Workshop	Body\ELECT P&W	LH front indicator not working			22/02/2025	708184	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Susp\SWAYBAR	replace broken LH rear swaybar link mount on chassis			15/02/2025	706944	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabElect\INST/GAUGE	REPLACE INSTRUMENTS COVER IN DASH			15/02/2025	700340	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
					Check, diagnose, remove & replace faulty starter motor.											
					Remove old starter. Pull extra length through for the battery negative.											
LOAD27	Myrtleford - Workshop	Elect\START MOTR	SUPPLY & FIT & WIRE UP VOLVO STARTOR MOTOR		Fit new starter. Reconnect the battery and test starting.	31/01/2025	701712	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	ARKON AUTO ELECTRICAL - 3	LOADER
LOAD27	Myrtleford - Workshop	Tyres\TP1+2	Tyres\TP1+2			30/01/2025	701712	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	BEAUREPAIRES - 3	LOADER
					repaired broken bracket on eng for coolant pipe (made a new bracket)											
					repaired starter leads											
LOAD27	Myrtleford - Workshop	VehService\AS	VehService\AS	VehService\AS	tidy uo a/c hoses	24/01/2025	704840	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\HOUSEKEEP	LH side bottom step loos			24/01/2025	701712	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Brakes\BRAKE ADJ	check and adjust brakes			24/01/2025	701712	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
			RH rear shackle pin not taking grease													
LOAD27	Myrtleford - Workshop	Susp\SUSPENSION	Insolace enease nisole and re-erease all ok!			24/01/2025	701712	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabElect\ELECT P&W	Job Created from Purchase Order #: 105486			13/01/2025	701712	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	MYRTLEFORD AUTO ELECTRICS - 3	LOADER
LOAD27	Myrtleford - Workshop	Tyres\TP3+4	Tyres\TP3+4			17/12/2024	701712	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	BEAUREPAIRES - 3	LOADER
LOAD27	Myrtleford - Workshop	Tyres\TP5+6	Tyres\TP5+6			17/12/2024	701712	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	BEAUREPAIRES - 3	LOADER
LOAD27	Myrtleford - Workshop	Brakes\AIR FITTIN	broken air fitting RH front brake booster drive			13/12/2024	701712	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
					sublet Myrt auto ele carried out repair											
					AIR CONDITIONING SERVICE											
					CHECK A/C SYSTEM.											
					CONNECT GAUGES.											
					RECOVER REFRIGERANT.											
					CHECK FOR LEAK WITH TRACER GAS.											
					LOCATE LEAKING VALVE.											
					REMOVE, SUPPLY AND FIT NEW VALVE.											
					EVACUATE AND CHARGE SYSTEM.											
LOAD27	Myrtleford - Workshop	Air Con\AIR CON	A/C not getting cold		CHECK FOR LEAKS WITH ELECTRONIC DETECTOR.	04/12/2024	700340	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	MYRTLEFORD AUTO ELECTRICS - 3	LOADER
LOAD27	Myrtleford - Workshop	Tyres\TP9+10	Tyres\TP9+10			03/12/2024	700340	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	BEAUREPAIRES - 3	LOADER
LOAD27	Myrtleford - Workshop	Tyres\TP7+8	Tyres\TP7+8			03/12/2024	700340	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	BEAUREPAIRES - 3	LOADER
LOAD27	Myrtleford - Workshop	DrivLine\DIFF OIL	replace front and rear diff oils			01/12/2024	700340	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Brakes\BOOSTER	REPLACE RHF VOLVO DRIVE BRAKE BOOSTER			30/11/2024	700340	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	VehService\AS	VehService\AS	VehService\AS	KLM at time of service 700340	28/11/2024	700340	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\EXHAUST	EXH clamps under cab loose and need replace			28/11/2024	700340	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Steering\WHEEL STUD	replace broken LH front wheel stud			23/11/2024	700340	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Elect\ELECT P&W	replace rear number plate light missing			23/11/2024	700340	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Tyres\TP05	replace flat tyre LH rear outer (KLM at of change 699217)			19/11/2024	699217	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Tyres\RUN OUT	Fit Run Out Tyre On Position 9. (Wodonga Tyre & Auto P/O: L090165)			16/11/2024	681833	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	BEAUREPAIRES - 3	LOADER
LOAD27	Myrtleford - Workshop	Tyres\TP9+10	Tyres\TP9+10			04/10/2024	681833	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	BEAUREPAIRES - 3	LOADER

LOAD27	Myrtleford - Workshop	Hydraulics\RAM	Rebuild grab cylinder.			21/09/2024	681833	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	RINLATECH ENGINEERING-3	LOADER
LOAD27	Myrtleford - Workshop	VehService\BS	B Service	VehService\BS		03/09/2024	681833	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Tyres\TP1+2	Tyres\TP1+2			02/08/2024	681833	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	BEAUREPAIRES - 3	LOADER
LOAD27	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection	Insp\ANN INSP		30/07/2024	681833	PreventativeMaintenance	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
					tighten ac belt											
LOAD27	Myrtleford - Workshop	VehService\AS	VehService\AS	VehService\AS	v-stav bushes need reolace soon	30/07/2024	681833	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
			Inspect batteries. Load test both batteries. Ok.													
			Inspect battery isolator operation. Battery isolator													
			seems to be working ok. Inspect battery drain. Battery drain													
			was drawing 0. 02 of an amp. Inspect battery drain and found													
			some wiring on the wrong side of the isolator which was not													
			getting isolated. Relocate wiring to the correct side of the isolator.													
			Remove dash panels and inspect heater fan operation.													
			Heater fan had a blown fuse and only had speed 4.													
			Inspect heater fan resistors. Fan resistors had gotten hot and failed.													
			Fan resistor had failed due to blower fan drawing to much current.													
			Remove blower fan and fan resistor. Replace blower fan and resistor,													
LOAD27	Myrtleford - Workshop	Engine\BATTERY	refit all dash panels and test ok. Carry out final tests and checks ok.			24/07/2024	680230	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	ARKON AUTO ELECTRICAL - 3	LOADER
LOAD27	Myrtleford - Workshop	Tyres\TP9+10	Tyres\TP9+10			24/07/2024	680230	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	BEAUREPAIRES - 3	LOADER
LOAD27	Myrtleford - Workshop	Body\ELECT P&W	jump start truck			23/07/2024	680230	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Tyres\TP05	replace flat Tyre LHS rear drive inside		replaced both inside and outside tyres	04/07/2024	676965	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Wodonga - Workshop	Tyres\FITMENT	REPLACED RH INNER FLAT TYRE.			02/07/2024	674523	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Wodonga Workshop	LOADER
LOAD27	Wodonga - Workshop	Engine\BELTS/TENS	FAN BELT SQUEALING.			02/07/2024	674550	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Wodonga Workshop	LOADER
LOAD27	Myrtleford - Workshop	VehService\AS	A Service	VehService\AS		19/06/2024	674916	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Wodonga - Workshop	Air Con\HEATER	CHECKED SEAT BELT LATCH. TURNED HEATER TAPS ON.			13/06/2024	671387	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Wodonga Workshop	LOADER
LOAD27	Wodonga - Workshop	DrCabRep\HOUSEKEEP	MADE FRAMEANDSECURED WORK BOX. CLEANED CABIN.			13/06/2024	671898	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Wodonga Workshop	LOADER
					Supply, fit & wire up handbrake off door open or seatbelt undone alarm. Connect											
					door switch & seatbelt switch as necessary. Wire in to switch relay to activate											
					horn. Assemble and test.											
					Removed trims and panels on driver side, around the instrument											
					cluster and off the centre console. Mounted door switch and seatbelt switch.											
					Ran cable from switches to the centre of the dash.											
			*Handbrake off door open alarm		Cut air line from the brake switch and added a pressure switch.											
			*Handbrake off seatbelt undone alarm		Mounted relay, horn and hand brake alarm, using nuts and blots,											
			New Unit: 464007741		close to the fuse box. Secured cables. Removed the old mtdata unit on the same											
			Old Unit 412010503		time and upgraded it with a 4g unit, added t-bar antrenna.											
			Pin 7970		Tested hand brake alarm.											
			SIM 8000 4358 1590 9 SO		Tested mtdata. Called mtdata and finish the setup using companion.											
LOAD27	Myrtleford - Workshop	DrCabElect\ELECT P&W	Phone 0475450555		Put everything backtogether, used new bolts and screws when necessary.	01/05/2024	670564	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Albury Workshop	LOADER
LOAD27	Myrtleford - Workshop	Elect\ELECT P&W	BATTERY LIGHT FLICKERS ON AND OFF.		REPLACED BELT AND BROKEN BOLT ON ALTERNATOR BRACKET.	23/04/2024	670564	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\MIRRORS	MIRROR BRACKET RATTLES R/H DOOR.			23/04/2024	670564	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Susp\SHOCK ABS	CHECK FRONT SHOCKERS.			23/04/2024	670564	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Tyres\TP09	Tyre Position 9			06/04/2024	670564	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Albury Workshop	LOADER
LOAD27	Myrtleford - Workshop	Tyres\TP11	FLAT DRIVE TYRE RHR INSIDE.			28/03/2024		Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Chassis\AIR LEAK	REPAIRED AIR LEAKS.			28/03/2024		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrivLine	REPLACED MISSING BOLTS.			28/03/2024		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
					* Found thrust bearing to have failed and pulled out of pressure plate											
					* Removed tailshaft & crossovers											
					* Drained coolant											
					* Ballast vehicle											
					* Lifted bonnet & removed side panels & inner guards for access											
					* Disconnected & removed lines to gearbox											
					* Removed gearstick & gantry											
					* Unbolted & removed gearbox											
					* Removed clutch & spigot bearing											
					* Inspected flywheel - All ok											
					* Installed replacement spigot bearing & clutch											
					* Refit gearbox											
					* Aligned & tensioned all as required											
					* Refit gearstick & gantry											
					* Refit all lines											
					* Found air supply line damaged and required replacement											
					* Replaced damaged section as required											
					* Refit tailshaft & crossovers											
					* Refilled coolant											
					* Refit all removed components											
					* Tensioned all to specifications											
LOAD27	Myrtleford - Workshop	DrivLine\CLUTCH	REPORTS TRUCK HAS FAILED THRUST BEARING		* Test operations - All ok. fault no lonwer present	14/03/2024		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Albury Workshop	LOADER
			REPLACE UNI'S ON JACKSHAFT .													
			* Unbolted & removed jackshaft													
			* Pressed out old uni's													
			* Cleaned down all surfaces													
			* Pressed in replacement uni's													
			* Refit jackshaft													
			* Aligned & tensioned all as required													
LOAD27	Myrtleford - Workshop	Steering\UNI JOINTS	* Test operations - All ok			14/03/2024		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Albury Workshop	LOADER
					* Sourced replacement parts											
					* Unbolted & removed tie rod											
					* Pressed out tie rod ends											
					* Cleaned down surfaces											
					* Pressed in replacement tie rod ends											
					* Installed tie rod											
					* Aligned & tensioned as required											
					* Greased all components											
LOAD27	Myrtleford - Workshop	Steering\TIE ROD	WHILST CARRYING OUT CLUTCH REPLACEMENT, FOUND RH TIE ROD WORN & UNSERIVICEABLE		* Test operations - All ok, fault no longer present	14/03/2024		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Albury Workshop	LOADER
LOAD27	Wodonga - Workshop	DrivLine\CLUTCH	clutch issues			06/03/2024	669729	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Wodonga Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body	TOW FROM WHERE ROSEWHITE TO TCTC			05/03/2024	674916	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	COMPLETE BODY CRAFT - 3	LOADER
LOAD27	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			24/02/2024	669280	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS	replaced RHR drive shocker mount	24/02/2024	669280	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabElect\ELECT P&W	LUBE WIPER STALK.		REMOVED DASH. LUBED STALK AND PEDAL SHAFT.	15/02/2024	668869	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabRep\SEAT	REPLACED SEAT CUSHION.			15/02/2024	668869	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Wodonga - Workshop	DrCabRep\SEAT	INSPECTED SEAT BASE.			08/02/2024	668498	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Wodonga Workshop	LOADER
LOAD27	Wodonga - Workshop	DrCabRep\HOUSEKEEP	FITTED AED.			08/02/2024	668498	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Wodonga Workshop	LOADER
LOAD27	Myrtleford - Workshop	Air Con\AIR CON	A/C N/WORKING.			02/02/2024	667664	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\EXHAUST	HOLE IN MUFFLER.		REPLACED MUFFLER.	02/02/2024	667664	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabRep\MOUNTS	CHECK FRONT CAB MOUNTS.			02/02/2024	667664	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Susp\SHOCK ABS	CHECKED AND REPLACED STEER SHOCKS.			02/02/2024	667664	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Unknown	GREASED TRUCK.			02/02/2024	667664	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabRep\SEAT	Seat & Seat Belt			29/01/2024	674916	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Albury Workshop	LOADER
LOAD27	Myrtleford - Workshop	Susp\SHOCK ABS	Shock Absorber			29/01/2024	674916	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Albury Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\FILTERS	Filters			29/01/2024	674916	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Albury Workshop	LOADER
LOAD27	Myrtleford - Workshop	Susp\AIR BAG	REPLACED LH 3RD AIRBAG.			23/01/2024	667304	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Wodonga - Workshop	DrCabElect\ELECT P&W	No power to phone / tablet - not charging			13/01/2024	666500	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Wodonga Workshop	LOADER
LOAD27	Wodonga - Workshop	Body\PANELS	R/H Mirror bracket rattles			13/01/2024	666500	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Wodonga Workshop	LOADER
LOAD27	Wodonga - Workshop	Elect\BATTERY	battery light comes on - can hear relay clicking			13/01/2024	666500	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Wodonga Workshop	LOADER
LOAD27	Wodonga - Workshop	Susp\SWAYBAR	sway bar bush's			13/01/2024	666500	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Wodonga Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabElect\ELECT P&W	repair lead and fit CIG plug for Acc in cab			06/01/2024	666440	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Tyres\Punct	8			21/12/2023		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Albury Workshop	LOADER
LOAD27	Myrtleford - Workshop	Susp\Torque Rod	CMV SUPPLY BUSHES			22/12/2023	674916	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Albury Workshop	LOADER
LOAD27	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			22/12/2023	665850	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS		22/12/2023	665850	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
					.											
					* Checked over all brake components											
					* Found all brake levers & yokes severly worn, steer brake boosters at full stroke, brakes released & LH booster leaking											
					* Removed & replaced all parts supplied											
					* Removed & replaced brake levers, yokes, brake booster											
					* Aligned & tensioned all as required											
					* Timed all brakes as required											
					* Test steer brake operations as required											
LOAD27	Myrtleford - Workshop	Brake\BRK O/HAUL	CHECK OVER Z-CAMS & ALL BRAKE COMPONENTS		* All ok, fault no longer present	15/12/2023		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Albury Workshop	LOADER
					* Unbolted & removed drive shock absorbers											
					* Replaced with supplied											
					* Aligned & tensioned all as required											
LOAD27	Myrtleford - Workshop	Susp\SHOCK ABS	REPLACE LEAKING SHOCK ABSORBERS		* Test operations - All ok	15/12/2023		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Albury Workshop	LOADER
					* Ballast rear drive axle & removed wheel end equipment											
					* Removed drums, hubs & unservicable brake shoes											
					* Fit new brake shoes											
					* Timed as required											
					* Refit all other components with new brake drums											
					* Aligned & tensioned all as required											
					* Ballast front drive axle											
					* Removed wheel end equipment											
					* Upon inspection, found uneven wear present on brake shoes											
					* Removed & replaced brake shoes											
					* Timed as required											
					* Unable to replace brake drums as parts not supplied within time restrains											
					* Refit all other components											
					* Aligned & tensioned to specifications											
LOAD27	Myrtleford - Workshop	Brake\BRK RELINE	RETIME FRONT DRIVE BRAKES & RELINE REAR DRIVE BRAKES		* Test all operations - All ok. fault no lonwer present	15/12/2023		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Albury Workshop	LOADER
LOAD27	Wodonga - Workshop	DrCabElect\GPS	Fit supplied MT Data 412 unit			30/11/2023	665726	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Wodonga Workshop	LOADER
LOAD27	Wodonga - Workshop	Body\HOUSEKEEP	wash down loader for repaires			19/10/2023	665367	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Wodonga Workshop	LOADER
LOAD27	Wodonga - Workshop	Engine\ELECT P&W	ENGINE REVS UP AND DOWN.			16/09/2023	6933	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Wodonga Workshop	LOADER
LOAD27	Wodonga - Workshop	Engine\HOUSEKEEP	check engine oil / water coolant			16/09/2023	6933	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Wodonga Workshop	LOADER
LOAD27	Wodonga - Workshop	DrCabElect\INDICATORS	repair L/H indicator			16/09/2023	6933	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Wodonga Workshop	LOADER
			*Prentice Loader													
			*Lossing power													
			Check the operation of the loader. Found the dash lights don't turn on with													
			the key. Checked all the fuses. Found no blown fuses.													
			Checked for power and earth to the computer on the loader. Had power and													
			earth. Went to plug the 4-pin plug back into the ECU and noticed it wouldn't													
			plug in correctly. Cleaned the plug up and sprayed rubber care into the plug.													
			The plug now locks in as it should. Test the loader, the loader now works													
LOAD27	Myrtleford - Workshop	DrCabElect\ELECT P&W	correctly.			05/09/2023		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Albury Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabElect\INST/GAUGE	DASH LIGHTS.			02/09/2023		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Elect\INDICATORS	LH INDICATOR.			02/09/2023		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER

LOAD27	Myrtleford - Workshop	DrCabElect\UNST/GAUGE	REPAIR/ REPLACE SPEEDO. METER HAS MISSING NUMBERS.(remove soeedo head and send for repairs and refit soeedo head and test all ol				26/08/2023	684844	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	ARKON AUTO ELECTRICAL - 3	LOADER
LOAD27	Myrtleford - Workshop	Engine\ELECT P&W	ENGINE REVS UP AND DOWN.(clean fuel pick up stainer in L/ft fuel tank) WO. ENGINE REVS UP AND DOWN.				26/08/2023	684844	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	ARKON AUTO ELECTRICAL - 3	LOADER
					Inspect operation of Speedo and odometer, digits missing on display and													
					Speedo not moving, inspect wiring from sensor to cluster, wiring tests good,													
					check for pulse out of sensor, no pulse, replace sensor and fit new													
					sensor and plug.													
					Secure wiring and test drive. Speedo operational.													
					Send Speedo away for repair.													
LOAD27	Myrtleford - Workshop	DrCabElect\UNST/GAUGE	DIGITAL SPEEDO READ OUT MISSING NUMBERS.		Fit repaired Speedo into truck, test drive, Speedo operational & odometer working.		16/08/2023		Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Albury Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\MIRRORS	CMV supply Mirror glass				25/07/2023	674916	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Albury Workshop	LOADER
LOAD27	Myrtleford - Workshop	Elect\BATTERY	REPLACED BATTERIES.				25/07/2023	65092	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Elect\HEAD LIGHT	REPLACED LH HEADLIGHT GLOBE.				25/07/2023	65092	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS			21/07/2023	674916	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				21/07/2023	674916	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabElect\RADIO	PHONE NOT WORKING.				19/07/2023	659624	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Air Con\HEATER	TURN HEATER/ COOL TAP- ONLY HEATER ON.				19/07/2023	659624	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\FUEL TANK	L/H BOTTOM TANK BRACKET LOOSE. (STEP)				19/07/2023	659624	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\MIRRORS	REPLACE R/H MIRROR.				19/07/2023	659624	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\FUEL TANK	REMOVED AND CLEANED FUEL PICKUP. ADDED FUEL TREATMENT.				19/07/2023	659624	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabElect\UNST/GAUGE	REPAIR/ REPLACE SPEEDO. METER HAS MISSING NUMBERS.				19/07/2023	659624	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Susp\AIR BAG	replaced right hand rear drive front airbag				01/07/2023	658250	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\HOUSEKEEP	repaired fuel leak at filter head				01/07/2023	658250	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\HOUSEKEEP	wash truck w/screen				28/06/2023		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabElect\PHONE	phone not working		check phone		27/06/2023		Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabRep\HOUSEKEEP	repair mast park brake handle		repair park brake handle		27/06/2023		Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Insp\ANN INSP	annual inspection as per check list	Insp\ANN INSP			06/06/2023	656987	PreventativeMaintenance	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				06/06/2023	656987	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
					tighten front diff rear output pinion nut													
					LH mirror light													
LOAD27	Myrtleford - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS	wiper washer's repaired		06/06/2023	656987	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Air Con\HEATER	Heater				31/05/2023	674916	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Albury Workshop	LOADER
LOAD27	Myrtleford - Workshop	Elect\DRV LIGHT	R/H driving light out		LH driving lights		30/05/2023	696512	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\CHN/RLR/MN	straighten R/H chain holder		straighten chain hook		30/05/2023	696512	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabRep\RADIO	no volume am/fm radio		no volume on radio		30/05/2023	696512	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabElect\HEATER REP	turn tap on for heater		turn heater tap on		30/05/2023	696512	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabElect\HEATER REP	repair heater and vent controls		heater controls cables		30/05/2023	696512	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabElect\UNST/GAUGE	repair diff lock switches and warning lights		repair diff lock switches		30/05/2023	696512	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
			Removed the dash cluster from the vehicle and checked the operation of the															
			dash on the test bench. Found the dash to be working correctly. Checked the															
			truck's power, ignition, and earth to the dash. Found the earth to the dash was															
			missing. Checked a diagram to locate where the earth comes from. Moved the															
			log crane on the truck to get the bonnet over. Removed the air filter box to get															
			to the plugs on the firewall. Found the plug with the earth wire going into it was															
			full of corrosion. Removed the pins from the plug and replaced them. Cleaned															
			the pins on the firewall side of the plug as best as possible. Plugged the plug															
			back together and checked over the wiring behind the dash. Plugged the cluster															
			back into the truck and tested the operation of the cluster. All is working correctly.															
			The UHF also started working after the repairs on the firewall plug. Put the dash															
			and the air box back into the truck correctly. Put the bonnet down and the crane															
LOAD27	Myrtleford - Workshop	DrCabRep\ELECT P&W	back to its transport location.				22/04/2023		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Albury Workshop	LOADER
LOAD27	Myrtleford - Workshop	Elect\BATTERY	jump start at Rinlatach				19/04/2023		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Brakes\BOOSTER	Booster				20/02/2023	674916	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Albury Workshop	LOADER
LOAD27	Myrtleford - Workshop	Steering\WHEEL STUD	front right steer broken wheel stud				20/02/2023	674916	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Albury Workshop	LOADER
			CHECK FOR FAULT WITH AIR CONDITIONING.															
			AIR CONDITIONING SERVICE															
			CHECK A/C SYSTEM.															
			CONNECT GAUGES.															
			RECOVER REFRIGERANT.															
			NO LEAK FOUND.															
			EVACUATE AND CHARGE SYSTEM.															
LOAD27	Myrtleford - Workshop	Air Con\AIR CON	CHECK FOR LEAKS WITH ELECTRONIC DETECTOR.				20/01/2023		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Albury Workshop	LOADER
LOAD27	Myrtleford - Workshop	Elect\INDICATORS	R/H rear blinker n/w		RH t/light blinker		14/01/2023		Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\MOUNTS	fit bracket to RH fuel tank step		tank step bracket		14/01/2023		Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Workshop\MOVE ASSET	pick up Mae				12/01/2023		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				10/01/2023	649681	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS			10/01/2023	649681	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrivLine\UNI JOINTS	replace jack shaft uni's				08/12/2022		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\BELTS/TENS	fan belt tensioner falling off				07/12/2022	648391	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\RADIATOR	remove radiator				07/12/2022	648391	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\RADIATOR	clean radiator and intercooler				07/12/2022	648391	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\BELTS/TENS	remove broken bolt				07/12/2022	648391	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\HOUSEKEEP	wash down motor				07/12/2022	648391	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\RADIATOR	refit radiator and road test				07/12/2022	648391	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabRep\SEAT	replaced drivers seat base		replace seat base, repair air switches		29/11/2022	648163	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\HOUSEKEEP	check over truck				25/11/2022	646406	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabRep\HOUSEKEEP	glue dash together				29/10/2022	645600	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabRep\RADIO	replace am/fm radio and aerial				13/10/2022	645285	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabRep\DOOR LOCK	L/H wont unlock (door)		LH door		13/10/2022	645285	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\HOUSEKEEP	straighten L/H chain hook				13/10/2022	645285	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\WIPERS	replace wipers				13/10/2022	645285	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrivLine\AIR LEAK	air leak when diff lock on				13/10/2022	645285	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabRep\WINDOW REG	L/H R/H window not going up or down				13/10/2022	645285	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabElect\PHONE	phone reception very poor				13/10/2022	645285	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				07/10/2022	645116	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS			07/10/2022	645116	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrivLine\TAIL SHAFT	CMVT supply centre bearing				20/09/2022	674916	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrivLine\TAIL SHAFT	inspect drive line issue				20/09/2022	644446	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrivLine\TAIL SHAFT	remove and replace center bearing on site				20/09/2022	644446	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Elect\INDICATORS	Replace indicator				13/09/2022	643961	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\HOUSEKEEP	Fix diesel pump handle				13/09/2022	643961	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Susp\SHOCK ABS	CMV supply Shock Absorbers				12/09/2022	674916	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabElect\INDICATORS	Indicators				09/09/2022	674916	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Elect\DRV LIGHT	check electrical plugs and wiring etc.				07/09/2022	643691	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrivLine\AIR LEAK	air leak when diff locks engaged				30/08/2022	643153	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\AIR FITTN	REMOVE AND REPLACE AIR TANK DRAIN FITTING				21/07/2022	656451	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrivLine\AIR LEAK	replaced broken air line				19/07/2022	640292	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Brakes\SLACK ADJ	REPLACE RHF DIRVE BRAKE ADJUSTER		adjust timing on all 4 drive axles		13/07/2022	665744	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrivLine\OIL LEAK	FRONT DIFF OUTPUT SEAL LEAKING				13/07/2022	665744	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\RADIATOR	DEBUG RADIATOR		inspected all good		13/07/2022	665744	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\EXHAUST	REPLACE EXHAUST MANIFOLD GASKET		inspected all good		13/07/2022	665744	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				06/07/2022	639553	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS			06/07/2022	639553	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				06/07/2022	639553	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS			06/07/2022	639553	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Elect\DRV LIGHT	driving light R/H not working		driving light not working (broken wire)		28/06/2022	638980	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Elect\ELECT P&W	repair wiring issue				25/06/2022	638920	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Tyres\TP5+6	supply and fit 2tyres				25/06/2022		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Tyres\TP3+4	supply and fit 2tyres				25/06/2022		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Tyres\TP9+10	Tyre Position 9 + 10				25/06/2022		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Tyres\TP7+8	Tyre Position 7 + 8				25/06/2022		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Elect\DRV LIGHT	driving lights not working				23/06/2022	638797	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabRep\WINDSCREEN	remove and replace window regulator motor				17/06/2022	638797	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabRep\MOUNTS	fix R/H mirror bracket		bolt mirror bracket		10/06/2022	638318	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Brakes\AIR LEAK	no foot brakes broken air line		no service brakes (air leak)		01/06/2022	637809	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Chassis\FUEL TANK	cable tie fuel line cross flow between tanks		nozp tie fuel cross over line		01/06/2022	637809	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\HOUSEKEEP	cut of handle and fix broken dash				17/05/2022	637408	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\HOUSEKEEP	walkway and paint				03/05/2022	636592	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\HOUSEKEEP	weld grab cradle cracks				03/05/2022	636592	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
					Check codes, found codes for speed signals not matching.													
					Check wires from speed sensor to cluster, no damages.													
					Check speed signal at sensor and at vecu. Speed signals do not match.													
					Remove cluster and inspect/ clean.													
					Boost signal with pulse generator from plug at gearbox.													
					Speedo working diagnose faulty speed sensor. Remove and replace.													
			Speedo & Derated															
LOAD27	Myrtleford - Workshop	Engine\FAULT CODE	Has had new sensor 12 months ago		Test. Clear codes.		31/03/2022	636036	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Susp\SWAYBAR	REPLACE FRONT AND REAR DRIVE SWAY BAR BUSHES		inspected all good		17/03/2022	656451	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\HOUSEKEEP	check coolant				16/03/2022	635310	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\Cool	CMVT SUPPLY HOSE OIL COOLER GEARBOX				10/03/2022	674916	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Steering\WHEEL BRGS	Wheel Bearings				09/03/2022	674916	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	MULTISPARES LTD - 3	LOADER
LOAD27	Myrtleford - Workshop	Insp\ANN INSP	annual inspection as per check list	Insp\ANN INSP			04/03/2022	634573	PreventativeMaintenance	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				04/03/2022	634573	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
					replaced 2x gearbox coolant hoses													
LOAD27	Myrtleford - Workshop	VehService\CS	Service As Per Attached Checklist	VehService\CS	reolaced coolant		04/03/2022	634573	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Tyres\TP5B	puncture repair				23/02/2022		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\FUEL TANK	water/fuel filter display comes on		water in fuel light on		08/02/2022	631342	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\DAMAGE	REPAIR LH DRIVE MUD GAUARD		inspected all good		15/01/2022	631464	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\HOUSEKEEP	fit signs to frame				01/01/2022	630717	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	VehService\AS	check over	VehService\AS			01/01/2022	630717	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\WIPERS	window washer n/w				16/12/2021	630273	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				11/12/2021	629991	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Wodonga	MLR	TQI660	Wodonga Workshop	LOADER
LOAD27	Wodonga - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS	replaced shocker bolt		11/12/2021	629991	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Wodonga	MLR	TQI660	Wodonga Workshop	LOADER
LOAD27	Myrtleford - Workshop	Tyres\TP1+2	supply and fit 2 tyres				08/12/2021	629794	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\DAMAGE	REPAIR LH DRIVE MUD GUARDS				25/11/2021	631464	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Brakes\BRAKE ADJ	adjust front R/H brakes (steer) pulling to the right				24/11/2021	628950	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabElect\RADIO	new mic for UHF				24/11/2021	628950	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabRep\HOUSEKEEP	glue dash panel				24/11/2021	628950	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Insp\UNT INSP	fit fire extinguisher				24/11/2021	628950	Repair	Completed

LOAD27	Myrtleford - Workshop	Engine\EXHAUST	replace exhaust engine pipe				22/09/2021	626539	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Dr\Cab\Rep\WIPERS	wiper blades				22/09/2021	626539	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\AIR LEAK	check for air leak near axle airbag - air line				16/09/2021		Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\AIR LEAK	check for air leak - rear of cab				16/09/2021		Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Susp\AIR LEAK	broken air line for airbag RH front				15/09/2021	626403	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\MIRRORS	mirror brackets vibrating R/H				09/09/2021	626500	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\MIRRORS	mirror wont adjust - lengthened adjustment pin				28/08/2021	625619	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\MUDGUARDS	REPLACE LH AND RH STEER MUD GUARD				21/08/2021	625619	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Elect\DRV LIGHT	driving lights n/w				18/08/2021	625044	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\MIRRORS	straighten R/H mirror bracket				18/08/2021	625044	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\DAMAGE	straighten R/H drive guards				18/08/2021	625044	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Steering\DAMAGE	replace steering box and filter		(526539 kms)		06/08/2021	631476	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Brakes\SLACK ADJ	FIT LH & RH STEER Z CAM ADJUSTERS		fit LH & RH steer z cam adjusters		06/08/2021	631476	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				05/08/2021	503915	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS			05/08/2021	503915	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Elect\TAIL LIGHT	number plate light not working		repair number plate light		21/07/2021	622939	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\FAULT CODE	cab controller comes on dash				21/07/2021	622939	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Elect\TAIL LIGHT	weld bracket				21/07/2021	622939	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\RWC COMP	Replace rear number plate		ok for now		14/07/2021		Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Brakes\BRAKE ADJ	adjust steer bakes - pulling to the right		adjust brakes		13/07/2021	622312	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
					replaced wheel stud												
LOAD27	Myrtleford - Workshop	Steering\WHEEL STUD	R/H wheel stud broken (steer)		robe		10/07/2021		Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\FAULT CODE	REPAIR CODE 255		repair range change wiring		08/07/2021	636036	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Dr\Cab\Elect\UNST/GAUGE	dash lights n/w speedo/revs		repair dash lights		25/06/2021	621123	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Dr\Cab\Elect\UNST/GAUGE	poor lighting on R/S of dash				25/06/2021	621123	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
					rewire clearance lights order 2x light assembles												
LOAD27	Myrtleford - Workshop	Elect\TRL LIGHTS	Replace LH & RHR tail lights		rewield mountine brackets		22/06/2021	621123	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Elect\DRV LIGHT	adjust driving lights				17/06/2021	620296	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Susp\AIR BAG	removved and RHS back drive front airbag				17/06/2021	620296	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Dr\Cab\Elect\INDICATORS	REPLACE LH BONNET INDRCATOR				09/06/2021	620119	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Elect\DRV LIGHT	REPLACE BOTH DRIVING LIGHTS				09/06/2021	620119	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Elect\HEAD LIGHT	FIT LED HEADLIGHTS GLOBES				09/06/2021	620119	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrivLine\SUSPENSION	PEPLACE LHR DRIVE U BOLT		inspected all good		09/06/2021	620119	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				08/06/2021	619923	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS	welded cracks on booster mounts		08/06/2021	619923	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
					4x drive airbags												
					replace LHF&HR&RHR on front drive axle												
LOAD27	Myrtleford - Workshop	Susp\AIR BAG	REPLACE ALL 4 CREASED DRIVE AIR BAGS		replace LHR & RHF of rear drive axle		08/06/2021	620119	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Dr\Cab\Elect\UNST/GAUGE	fuel water temp, oil pressure warning lights not working				05/06/2021	619679	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrivLine\DRV LN SER	power divider/diff locks not working				05/06/2021	619679	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Susp\AIR BAG	airbags keep popping when leg lifted off grand				05/06/2021	619679	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				25/05/2021		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
			Service As Per Attached Checklist														
LOAD27	Myrtleford - Workshop	VehService\BS	MINI B SERVICE	VehService\BS			25/05/2021		Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Elect\WORK LIGHT	fit work lights to rear of cabin				13/05/2021	617078	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\FAULT CODE	REPAIR SPEED SENSOR AND GEARBOX DATA FULTS		replace cab control ecm and program new ecm		12/05/2021	617078	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
			transmission faults														
			-range inhibitor electrical fault (mid 144/PPID 075/FMI 4														
LOAD27	Myrtleford - Workshop	Engine\FAULT CODE	-road speed data error (mid 144/PPID 084/FMI 2				11/05/2021	617078	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\FAULT CODE	elec issue with speedo or cab wiring				05/05/2021	616438	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\FAULT CODE	replaced speed sensor - test drive - all good				05/05/2021	616438	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Dr\Cab\Elect\ELECT P&W	The fuel trainder pump shorting out and blows a fuse as soon as you turn it on.				22/04/2021	615499	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Tynes\BREAKDOWN	Fit second hand RHR tyre (flat). Fit secondhand RHR tyre (flat)		Rebuild fuel transfer pump and test		22/04/2021	615499	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Elect\TAIL LIGHT	Repair number plate that was bent fitted new light				22/04/2021	615499	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\AIR FITTIN	replace air line and fittings on rear air tank				15/04/2021	614733	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Tynes\DRV TYRES	REPLACE LHF TYRE				14/04/2021		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Steering\STEER UNI	REPLACE STEERING SHAFT				14/04/2021	617076	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Steering\HOSES	REPLACE POWER STEERING HOSE				14/04/2021	617076	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Chassis\CHAS CRACK	REPAIR CHASSIS CRACK				14/04/2021	617076	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Dr\Cab\Rep\DOOR LOCK	replace outer RH door handle				13/04/2021	614456	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Dr\Cab\Rep\DOOR LOCK	drivers side door wont open from outside		RH door handle not opening		10/04/2021	614382	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				10/04/2021	614456	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS			10/04/2021	614456	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\BREAKDOWN	air line broken off air tank for brakes		drive to punhu and back to shop		09/04/2021	614309	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\AIR FITTIN	blown air line on air tank				09/04/2021	614309	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\FAULT CODE	check engine light is on				09/04/2021	160340	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Workshop\MOVE ASSET	deliver truck				01/04/2021		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Brakes\BOOSTER	replaced RH steer booster				31/03/2021	613377	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
			REPLACE RHF BRAKE BOOSTER														
LOAD27	Myrtleford - Workshop	Brakes\BOOSTER	MULTISPARES SUPPLY BRAKE CHAMBER				26/03/2021		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Susp\SUSPENSION	please check front left steer tyre rod ends? Something not right		steer axle suspension check		26/03/2021	613186	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Steering\PWR STEER	POWER STEERING HOSE LEAKING				23/03/2021	612886	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Elect\HEAD LIGHT	RHS headlight globe please		RHS headlight u/s		20/03/2021	612886	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Steering\PWR STEER	power steering hose leaking at steering box		power steering hose leaking		20/03/2021	612886	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Elect\BATTERY	replace 2x batteries				12/03/2021	611968	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\BELTS/TENS	retension alternator pulley				12/03/2021	611968	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\CHN/RLR/MN	relocate chain for grab bar				12/03/2021	611968	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
			check alternator/battery light on														
LOAD27	Myrtleford - Workshop	Elect\ALT	replace alternator		truck wont start alternator issue		11/03/2021	611918	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\ELECT P&W	fit alternator and 7.5 amp inline fuse				11/03/2021	611918	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrivLine\SUSPENSION	adjust ride height				26/02/2021	610770	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Dr\Cab\Rep\DOOR LOCK	REPLACE RH DOOR CATCH AND STRIKER		610770klms		26/02/2021	612066	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrivLine\GEARBOX	REPAIR POWER DIRRVDER NOT WORKING				26/02/2021	612066	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Brakes\DRK RELINE	RELINE STEER BRAKES AND FIT DRUMS				19/02/2021	610242	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Steering\WHEEL BRGS	REPLACE STEER BEARINGS LH/RH SIDES				19/02/2021	610242	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Susp\SPRING PACK	REPLACE LH AND RH STEER SPRINGS AND UBOLTS WITH 9 TON SPRINGS L10845 L10853 L10884				19/02/2021	610242	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Chassis\DAMAGE	welding - front craddle support				18/02/2021	610242	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Chassis\DAMAGE	welding - top craddle support				18/02/2021	610242	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Steering\WHEEL SEAL	REPLACE LH STEER HUB SEAL				11/02/2021	610242	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Susp\SWAYBAR	REPACE STEER SWAY BAR BUSHES				11/02/2021	610242	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrivLine\SUSPENSION	REPLACE REAR DIFF 'V' STAY				11/02/2021	610242	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				10/02/2021	610017	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS			10/02/2021	610017	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Dr\Cab\Rep\DOOR LOCK	replace upper and lower door hinges				20/01/2021	608247	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Dr\Cab\Rep\DOOR LOCK	inspact RHS door latch				19/01/2021	608130	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Dr\Cab\Elect\UNST/GAUGE	middle dash air vents n/w		air vents directions		16/01/2021	608027	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
					RH door catch												
LOAD27	Myrtleford - Workshop	Dr\Cab\Rep\DOOR LOCK	driver side door latch need adjusting/lube/replace		clean ensase from door latch and soray lube onto door catch		16/01/2021	608027	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Elect\TAIL LIGHT	fit number plate light		fit number plate light		16/01/2021	608027	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\REFLECTORS	fit rear sign		fit sign		16/01/2021	608027	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Tynes\DRV TYRES	change tyre/drive rock damage				09/01/2021	606965	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Tynes\TP03	replace tyre				08/01/2021	606965	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
			REPAIR GRAB BAR														
LOAD27	Myrtleford - Workshop	Chassis\HOUSEKEEP	STOP CRACKS				17/12/2020	608247	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Brakes\BRK O/HAUL	LH STEER Z CAM TUBES LEAKING GREASE		grease is coming out tell tail hole so you don't over grease s/cams		17/12/2020	610242	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
			CHECK AND REPAIR LH & RH STEER & FRONT DRIVE AXLE		check adjusters ok at this stage												
LOAD27	Myrtleford - Workshop	Brakes\BRK O/HAUL	2 CAM BRAKE ADJUSTERS		will rechack next service		17/12/2020	610242	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				15/12/2020		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	VehService\CS	Service As Per Attached Checklist	VehService\CS			15/12/2020		Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Chassis\DAMAGE	weld crack in grab rest				11/12/2020	604789	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\DAMAGE	straighten light bar mounts (tail lights)				10/12/2020	604527	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Tynes\TP7+8	replace 2 tynes				05/12/2020	604274	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Wodonga Workshop	LOADER
LOAD27	Myrtleford - Workshop	Tynes\TP9+10	replace 2 tynes				05/12/2020	604274	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Wodonga Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\BELTS/TENS	travel to breakdown - replace fan belt				01/12/2020	603691	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Dr\Cab\Elect\UNST/GAUGE	fit cross lock switch				28/11/2020	603568	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrivLine\AIR LEAK	Replace power divider diaphragm and cover		replace switch in dash also		28/11/2020	603568	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\BELTS/TENS	Replace fan belt and tensioner and air/ con belt		check pulleys fan belts etc - ordered new belts and pulley		28/11/2020	603568	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Dr\Cab\Elect\ELECT P&W	R&R ignition switch - tested all good				15/11/2020	602528	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Chassis\FIRE EXTIN	fit fire extinguisher				15/11/2020	602528	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\HOUSEKEEP	replace anti-slip strips behind cab walk way		walk way tape		10/10/2020	599666	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
			windows cig light, radio doesnt work sometime														
LOAD27	Myrtleford - Workshop	Dr\Cab\Elect\ELECT P&W	check ianition		check ianition switch L10127		10/10/2020	599666	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\AIR LEAK	air leak behind cabin		air leaks		10/10/2020	599666	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				10/10/2020	599666	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS			10/10/2020	599666	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
			n/w radio														
			LH/RH windows n/w														
			cigarette lighter n/w														
LOAD27	Myrtleford - Workshop	Dr\Cab\Elect\UNST/GAUGE	light back of cab n/w				15/09/2020	597252	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Elect\BREAKDOWN	jump start truck				15/09/2020	597181	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
			UHF left on over weekend														
LOAD27	Myrtleford - Workshop	Dr\Cab\Elect\UNST/GAUGE	draining batteries				15/09/2020	597181	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Dr\Cab\Rep\DOOR LOCK	lube/test RH door adjust hard to open				12/09/2020	597180	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrivLine\DRV LN SER	power divider and cross lock's light not working on dash				11/09/2020	596800	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop

LOAD27	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			03/07/2020	589954	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS		03/07/2020	589954	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Susp\AIR BAG	check RHF airbag			02/07/2020	589855	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabRep\DOOR LOCK	driver side door latch needs adjusting			02/07/2020	589855	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabRep\SEAT	Replace drivers seat cover			27/06/2020	596508	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabRep\ELECT P&W	replace floor mat			26/06/2020		Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabElect\HEATER REP	Repair air direction in dash vent		re-mounted after market cable, tested and labeled	19/06/2020	589735	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabElect\ELECT P&W	RH electric window			19/06/2020	589735	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabRep\HOUSEKEEP	new gear knob vibrating making noise, rattles			18/06/2020	588205	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Elect\DRV LIGHT	driving lights flickering then stops working			18/06/2020	588205	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabRep\AIR LEAK	Replace gear stick knob assembly			02/06/2020	586960	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Workshop\MOVE ASSET	take loader to Rinlatech			26/05/2020	586391	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Chassis\HOUSEKEEP	unfold/hold up			20/05/2020	586070	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Susp\AIR BAG	replace RHF rear airbag		LHF & LHR airbags	20/05/2020	586070	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Elect\WORK LIGHT	work lights rear of cab not working			20/05/2020	586070	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\HOUSEKEEP	check over/grease			20/05/2020	586070	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Brakes\BRAKE ADJ	Brake adjust all wheels			16/05/2020	586070	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
					replace number 4 injector (CMV)											
LOAD27	Myrtleford - Workshop	Engine\BREAKDOWN	Replace all 6 injector tubes		replace 2x fuel wires and clean all connections	16/05/2020	586070	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\ENG TUNE	Tune engine and lakes			16/05/2020	586070	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\FAULT CODE	engine has a misfire			14/05/2020	586042	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\FILTERS	replace fuel filters x2			14/05/2020	586042	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\FUEL TANK	remove fuel pick up clean and reassemble			14/05/2020	586042	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\ELECT P&W	remove rocker cover inspect wiring			14/05/2020	586042	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\FILTERS	replace air filter			14/05/2020	586042	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\FUEL TANK	inspect fuel lines			14/05/2020	586042	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\HOUSEKEEP	replace fuel pump and primer pump			14/05/2020	586042	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Workshop\MOVE ASSET	drop off and pick up loader at Rinlatech			25/04/2020	584989	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			24/04/2020	584989	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS	repair LH mirror light	24/04/2020	584989	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Susp\AIR BAG	replace LHF rear airbag L8540 supply spare volvo air bag. replace LHF rear airbag			09/04/2020	583742	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrivLine\SUSPENSION	support chain LHR diff broken			09/04/2020	583742	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Elect\DRV LIGHT	driving light adjust			13/03/2020	580534	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrivLine\SUSPENSION	sway bar link change out x2			13/03/2020	580534	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabRep\HOUSEKEEP	replace screw in steering column		replaced screws in steering column cover	11/03/2020	580000	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabElect\ELECT P&W	no hazard lights		cleaned hazard switch working again	11/03/2020	580000	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			11/03/2020	580000	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS	replace 2x driving light	11/03/2020	580000	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Air Con\AIR CON	a/c n/w check belts			06/03/2020	579439	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Elect\ALT	alternator not charging - fit new one			28/02/2020	578376	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Elect\BATTERY	charged up batteries			28/02/2020	578376	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Elect\TAIL LIGHT	fit new side light and number plate light			28/02/2020	578376	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Workshop\MOVE ASSET	change over L-18 with L-27			28/02/2020	578376	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\DAMAGE	L/H bottom tank step bracket loose			28/02/2020	578300	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
			inspect airbag scrunching #													
LOAD27	Myrtleford - Workshop	Susp\SUSPENSION	comment- only one airbag scrunching, on front axle left hand side at the rear of axle, may need replacing			27/02/2020	578041	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrivLine\SUSPENSION	take photos of axle chains and mounts			27/02/2020	578041	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Susp\AIR BAG	Replace LHR air bag on front drive axle		check LH airbag	19/02/2020	576793	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabRep\WIPERS	wipers linkage loose			18/02/2020	576722	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\HOUSEKEEP	check all engine fluids and belts			18/02/2020	576722	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrivLine\OIL LEAK	fit hose to diff breather			18/02/2020	576722	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\MOUNTS	retighten gearbox mounts			18/02/2020	576722	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Susp\HCV	replaced gromets on the end of ride height valves on rear susp			12/02/2020	576451	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabElect\UNST/GAUGE	no highbeam indicator on dash			06/02/2020	576190	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrivLine\SUSPENSION	ride height issue low on left side			06/02/2020	576190	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\AIR LEAK	broken hose/fitting on to air dryer		check out air leak	30/01/2020	575990	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\HOUSEKEEP	check all fluids under bonnet			30/01/2020	575990	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabRep\WIPERS	clean out wiper washer nozzles and test			30/01/2020	575990	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabRep\SEAT	seat belt missing		tighten up seat mount bolts that were loose	03/01/2020	574630	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Elect\HEAD LIGHT	RH headlight out		replaced and tested RH globe	03/01/2020	574630	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrivLine\CTCH PACK	fit new clutch pack			28/12/2019	574550	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrivLine\GEARBOX	fit g/box supplied by CMV Volvo and fitted by TCTC			28/12/2019	574550	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Steering\HOUSEKEEP	steering wheel has chunck missing in it		this job has been done	28/12/2019	574528	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabRep\DOOR LOCK	new R/H inside door skin/door panel (cracked/broken)		this job has been done	28/12/2019	574528	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\JAKE BRAKE	second stage engine brake sticks on		road test and check jakes all stages are working	28/12/2019	574528	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabRep\HOUSEKEEP	new floor mat driver side		new floor mats have been fitted	28/12/2019	574528	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrivLine\GEARBOX	Repair or replace gear box		gearbox issue	14/12/2019	574550	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrivLine\CLUTCH	Inspect clutch assembly			14/12/2019	574550	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrivLine\TAIL SHAFT	remove jack shaft and front tail shaft		remove front and rear tail shafts	13/12/2019	574435	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Brakes\BRAKE ADJ	back off drive brakes		back off brakes for vehicle to be towed to TCTC	13/12/2019	574435	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabRep\WIPERS	replace wipers			11/12/2019	574325	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			11/12/2019	574326	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS		11/12/2019	574326	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
			replace diaphram in spring brake booster													
LOAD27	Myrtleford - Workshop	Brakes\AIR LEAK	leakine air			06/12/2019	574091	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\MOUNTS	make new rear tow pin		make up new tow pin	26/11/2019	573587	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Elect\HEAD LIGHT	R/H headlight out			26/11/2019	573587	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Chassis\HOUSEKEEP	male up new tow pin			26/11/2019	573147	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\MIRRORS	Repair or replace RH mirror support bracket			14/11/2019	572400	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabElect\UNST/GAUGE	no dash lights			13/11/2019	572085	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Elect\TAIL LIGHT	no tail lights			13/11/2019	572085	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Elect\TAIL LIGHT	no side light			13/11/2019	572085	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
					replace RHR leg pivot pin											
LOAD27	Myrtleford - Workshop	Chassis\DAMAGE	RHR leg pin broken		repair diamare to pin supports	12/11/2019		Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
			noise at lower speed. Brake dradding													
LOAD27	Myrtleford - Workshop	DrivLine\TAIL SHAFT	check drive line			31/10/2019		Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
			call out													
			truck wont start													
			check batteries and starting system													
			fit starter motor													
LOAD27	Myrtleford - Workshop	Elect\START MOTR	replace terminal on exciter wire			22/10/2019	570780	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrivLine\SUSPENSION	Replace LHR suspension support chain			19/09/2019	564806	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrivLine\SUSPENSION	Repair RHF air bag bell mount			19/09/2019	564806	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
					power sway bar bushes 24/9/19											
					fit bushes to sway bar link											
LOAD27	Myrtleford - Workshop	DrivLine\SUSPENSION	Replace lower rear sway bar bushes		rear droo link swav bar bushes x4 u/s	19/09/2019	564806	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Steering\KING PIN	Repair movement in steer king pins		will keep monitoring	19/09/2019	564806	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			18/09/2019	564472	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS		18/09/2019	564472	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\HOUSEKEEP	check oil and coolant			12/09/2019	568898	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Elect\ELECT P&W	repair side marker wiring			30/08/2019	568098	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrivLine\GEARBOX	Re-check gearbox oil, leak and air leak		re-route gearbox breather and check oil	29/08/2019	568098	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrivLine\GEARBOX	replace gearbox oil filter and inspect for metal - ok			28/08/2019	567500	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrivLine\GEARBOX	check gearbox noise			28/08/2019	567500	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrivLine\GEARBOX	change gearbox oil			28/08/2019	567500	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
			inspect oil leak from gearbox													
			re-rate breather hose													
			top up gearbox oil													
			check PTO air supply isnt pressurising box													
			hi/low range selector has a small air leak													
LOAD27	Myrtleford - Workshop	DrivLine\GEARBOX	ineed to re-check oil after a dav's use			28/08/2019	567887	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\HOUSEKEEP	truck has a whining noise - engine		check engine	20/08/2019	567290	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrivLine\DRV LN SER	drive line		drive line for noise under load	20/08/2019	567290	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrivLine\DRIVES	checked diffs ok			20/08/2019	567290	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrivLine\GEARBOX	gearbox output pinion bearing has movement			20/08/2019	567290	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\TURBO	checked turbo ok			20/08/2019	567290	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\BELTS/TENS	checked a/c, alternator, idler pullies ok			20/08/2019	567290	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			25/06/2019	564409	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS		25/06/2019	564409	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Insp\ANN INSP	annual inspection as per check list	Insp\ANN INSP		25/06/2019	564409	PreventativeMaintenance	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			25/06/2019	564409	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS		25/06/2019	564409	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Elect\BATTERY	Test Battery & Starting System		fit 2x new batteries	18/06/2019	564409	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Elect\ELECT P&W	jump start truck			17/06/2019	564092	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Elect\ELECT P&W	put battery on charge			17/06/2019	564092	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Susp\AIR BAG	Replace RHF Driver Air Bag			14/06/2019	564806	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrivLine\AIR LEAK	Power Divider Plate Gasket Leaking			14/06/2019	564806	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrivLine\SUSPENSION	adjusted ride height			02/06/2019	563564	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabElect\HEATER REP	Replace Heater Fan & Resistor			30/05/2019	563565	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Susp\HCV	Replace Ride Height Valve Ball Joints			30/05/2019	563565	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Susp\AIR BAG	Replace LHF Drive Air Bag		repair airbag bottom mount	29/05/2019	563565	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Elect\DRV LIGHT	turn RH driving light outwards			29/05/2019	563257	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabElect\ELECT P&W	R/h clearance light n/working			29/05/2019	563257	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabRep\DOOR LOCK	driver door latch needs adjusting			29/05/2019	563257	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Steering\WHEEL STUD	RH steer stud broken			16/05/2019	562431	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Tyres\Rims	LH Steer Rim Cracked		fit 2x new steer rims	16/05/2019	562600	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabElect\RADIO	replace UHF mic			15/05/2019	562324	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Elect\TAIL LIGHT	replace LH tail light assembly			11/05/2019	562136	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	L

LOAD27	Myrtleford - Workshop	Elect\ELECT P&W	replace no. plate light			17/11/2018	553717	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrivLine\SHOCK ABS	Replace All 4 Drive Shockers			24/10/2018	553709	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Brakes\BRK RELINE	Reline front drive axle			18/10/2018	553709	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			13/10/2018	553702	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	VehService\BS	B Service As Per Attached Checklist	VehService\BS		13/10/2018	553702	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\OIL LEAK	Replace Engine Sump & Gasket(LS049)			11/10/2018	553709	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Susp\DAMAGE	Replace 1x Damaged Top Driver Shock Mounts			11/10/2018	553709	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Susp\SUSPENSION	Replace Front & Rear Diff Vee Stay Bushes			11/10/2018	553709	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabElec\UNST/GAUGE	dash guages n/w			08/09/2018	551863	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Steering\TIE ROD	Replace steering drag link			30/08/2018	551253	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Steering\TIE ROD	replace LH tie rod ball joint			25/08/2018	550824	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Brakes\BOOSTER	Replace RHR drive booster			22/08/2018	550824	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
			Repair loose LH5 headlight & assembly													
LOAD27	Myrtleford - Workshop	DrCabRep\MOUNTS	Check wiring		Terry repair	22/08/2018	551000	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabElec\UNST/GAUGE	dash guages not working			21/08/2018	550266	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			21/08/2018	550267	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	VehService\AS	A Service As Per Attached Checklist	VehService\AS		21/08/2018	550267	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\OIL LEAK	Replace engine oil filler cap			14/08/2018	550267	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\OIL LEAK	wash degrease engine/bonnet			11/08/2018	549453	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\CONSUMABLE	top up engine oil			11/08/2018	549453	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\HOUSEKEEP	check oil and coolant			10/08/2018	549371	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabRep\DOOR LOCK	adjust R/H door latch			09/08/2018	549328	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Steering\HOUSEKEEP	adjust steering wheel - centre offset			09/08/2018	549328	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabRep\HOUSEKEEP	new floor mat driver side			09/08/2018	549328	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Brakes\BOOSTER	check brake boosters for leaks			09/08/2018	549328	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabRep\DAMAGE	R&R steering wheel			04/08/2018	549157	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabRep\DAMAGE	R&R RH door trim			04/08/2018	549157	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabRep\HOUSEKEEP	water leaking from roof (above phone)			21/07/2018	548582	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Susp\HCV	check left rear airbags (down)			21/07/2018	548582	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Steering\HOUSEKEEP	steering wheel has chunck missing in it			21/07/2018	548582	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabRep\DOOR LOCK	new R/H inside door skin/door panel (cracked/broken)			21/07/2018	548582	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\JAKE BRAKE	second stage engine brake sticks on			21/07/2018	548582	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Steering\WHEEL STUD	L/H R/H wheel studs broken (front)			30/06/2018	547648	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\BREAKDOWN	replace D shackle for chain in grab bar			15/06/2018	546710	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\MUDGUARDS	L/H rear mudflap needs replacing			15/06/2018	546710	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Steering\WHEEL STUD	L/H steer wheel stud broken			31/05/2018		Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabRep\WIPERS	windscreen wiper washers not working			31/05/2018		Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\HOUSEKEEP	check cold coolant			31/05/2018		Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabRep\ELECT P&W	Replace LH window switch			26/05/2018	549157	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
					LH tie rod ball joint											
					steer sway bar bushes											
					suspension buses worn											
LOAD27	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection as per check list	Insp\ANN INSP	draw link ball joint	25/05/2018	545161	PreventativeMaintenance	Completed	Greenfreight Loxeine Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			25/05/2018	545161	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	VehService\AS	A Service As Per Attached Checklist	VehService\AS	tighten RHR sway bar top bracket bolts	25/05/2018	545161	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabRep\ELECT P&W	left window not working			25/05/2018	545160	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabRep\WIPERS	change wiper blades			25/05/2018	545160	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Tyres\STEER TYRE	Job Added From Invoice			15/05/2018	0	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice			15/05/2018	0	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\FUEL TANK	clean fuel pick up in LH fuel tank			12/05/2018	544202	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\FILTERS	drain primary fuel filter			12/05/2018	544202	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\FUEL TANK	put fuel set in both fuel tanks			12/05/2018	544202	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Tyres	Job Added From Invoice			12/05/2018	543565	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice			12/05/2018	543565	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Steering\WHEEL STUD	replaced 3x wheel stud's on RHS steer one wheel stud is too long as there are no correct one's left			10/05/2018	543906	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Tyres\TPI1	fitted spare wheel back on carrier			10/05/2018	543906	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Susp\SWAYBAR	fit rear sway bar bush			09/05/2018	543565	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabRep\HOUSEKEEP	Fit new door switch surround on RHS			13/04/2018	541396	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Brakes\DAMAGE	Replace LH steer 2 cam tube mount bolts			13/04/2018	541396	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Brakes\SLACK ADJ	Replace LH steer auto brake adjuster			13/04/2018	541396	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Steering\WHEEL STUD	LH steer wheel stud broken			11/04/2018	541396	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabRep\MOUNTS	put screw in steering cloumn cover			05/04/2018	540983	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabElec\UNST/GAUGE	guages not working in dash			05/04/2018	540983	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabElec\ELECT P&W	right window not working			05/04/2018	540983	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\MUDGUARDS	replace LHR mudflap			05/04/2018	540983	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Brakes\AIR LEAK	Replace 4 way brake valve at RHF air tank			07/03/2018	540516	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Brakes\AIR LEAK	check air leak behind cab			06/03/2018	540250	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			02/03/2018	539937	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	VehService\BS	B Service As Per Attached Checklist	VehService\BS		02/03/2018	539937	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\TOOLBOX	repair toolbox lid hinge			22/02/2018	538904	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Brakes\AIR LEAK	Replace trailer brake valve			20/02/2018	538904	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrivLine\CTCH PACK	fit clutch kit			09/02/2018		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrivLine\CTCH PACK	fit clutch servo			09/02/2018		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
			replace rear main seal													
			replace both rear engine mounts													
LOAD27	Myrtleford - Workshop	Engine\OIL LEAK	replace rear main seal			09/02/2018		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\HOUSEKEEP	machine flywheel			09/02/2018		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabRep\HOUSEKEEP	glue gear knob together			03/02/2018	538013	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabElec\WHEEL STUD	Replace broken RH front wheel stud			24/01/2018	537106	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Brakes\AIR LEAK	Replace bromz button			23/01/2018	538415	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\CONSUMABLE	Check engine oil & coolant			20/01/2018	536673	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\HOUSEKEEP	Top up washer bottle			20/01/2018	536673	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Tyres	Job Added From Invoice			12/01/2018	0	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice			12/01/2018	0	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice			12/01/2018	0	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Susp\SWAYBAR	Replace LHR sway bar mount bracket			06/01/2018		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Susp\SWAYBAR	Replace all worn sway bar bushes		replace all rear susp t/rod bushes x8	06/01/2018	553702	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			05/01/2018	535157	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS		05/01/2018	535157	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Tyres\TPI7	LHR tyre puncture fit red space			27/12/2017	534046	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\MOUNTS	tighten drivers side step bracket			20/12/2017	533877	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabElec\INDICATORS	Replace RHF indicator globe holder			19/12/2017	536673	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabElec\INDICATORS	R/H front indicator not working			16/12/2017		Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabElec\FUEL TANK	R/H bottom step fuel tank step loose			16/12/2017		Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\HOUSEKEEP	check/add engine oil			16/12/2017		Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\HOUSEKEEP	check/all coolant			16/12/2017		Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\JAKE BRAKE	Repair engine brakes			01/12/2017	555497	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\JAKE BRAKE	check stage 1/2 engine brake n/w			30/11/2017	531482	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabRep\RADIO	replace broken speaker brackets top RHS			25/11/2017	530994	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabRep\WIPERS	water jets for windscreen blocked			25/11/2017	530994	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabElec\ELECT P&W	no power to cigarette socket			02/11/2017	529785	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\MIRRORS	Rh mirror bracket bent - straighten			02/11/2017	529785	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\JAKE BRAKE	engine brake sticking on - switch			02/11/2017	529785	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Steering\WHEEL STUD	broken R/H steer wheel stud			31/10/2017	529658	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrivLine\CLUTCH	check/adjust clutch			25/10/2017	529420	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabElec\ELECT P&W	repair RHS mirror light			25/10/2017	529420	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			25/10/2017	529420	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	VehService\AS	A Service As Per Attached Checklist	VehService\AS		25/10/2017	529420	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrivLine\R DIFF OIL	change rear diff oil			07/10/2017	528306	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrivLine\SUSPENSION	weld "R" clip pipe to LHR airbag			07/10/2017	528306	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrivLine\DRIVES	check wheel tension			07/10/2017	528306	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Steering\HOUSEKEEP	check and top up front hub oil			07/10/2017	528306	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Air Con\AIR CON	Replace air con compressor & regas system			06/10/2017	528306	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Brakes\BRK RELINE	reline steer brakes			05/10/2017	528306	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Brakes\AIR LEAK	replace LH & RH steer booster hoses			05/10/2017	528306	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
			Replace wheel bearings & seals & nuts On lhr drive		replace RHR wheel bearings											
LOAD27	Myrtleford - Workshop	DrCabRep\WHEEL BRGS	fit new hub asm & seals & nuts		fit new hub ASM on LHR drive	03/10/2017	528306	Repair	Completed	Greenfreight Loxeine Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Brakes\BRK RELINE	Reline rear axle drive brakes			03/10/2017	528306	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabRep\WHEEL BRGS	Check Wheel Bearings		Complete	03/10/2017	528306	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Elect\HEAD LIGHT	high beam light on dash - not working			28/09/2017	528020	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabRep\WIPERS	clean out windscreen wiper jets and pump			21/09/2017	526910	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Wodonga - Workshop	Body\HOUSEKEEP	put stickers on trailer, front, rear, inside			21/09/2017		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Wodonga Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\FILTERS	fit new air cleaner			19/09/2017	526567	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			06/09/2017	525116	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
			B Service As Per Attached Checklist		volvo 1665898											
LOAD27	Myrtleford - Workshop	VehService\BS	L3174 CMV L3224	VehService\BS	(66HD) (0702)	06/09/2017	525116	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Steering\WHEEL STUD	L/H steer broken wheel stud			17/08/2017	523818	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Tyres\PRES CHECK	Job Added From Invoice			16/08/2017	0	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\MUDGUARDS	replace RHR mudflap		R/Hand rear m/flap missing	12/08/2017	523601	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabElec\RADIO	interference in UHF when driving lights on			08/08/2017	523327	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrivLine\CLUTCH	clutch slipping 2nd high box direct/overdrive			08/08/2017	523327	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\BELTS/TENS	replace fan belt and tensioner and bolts			29/07/2017	522208	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\OIL LEAK	replace axillary pully o-ring			29/07/2017	522208	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27

LOAD27	Myrtleford - Workshop	DrCabElect\INST/GAUGE	speedo/tacho still playing up			02/06/2017	518109	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Chassis\HOUSEKEEP	wash windscreen & bonnet - hyd oil leaks			02/06/2017	518109	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabElect\INST/GAUGE	speedo/tacho drops out			01/06/2017	518087	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabElect\INST/GAUGE	high battery voltage reading			01/06/2017	518087	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Susp\SWAYBAR	LHR broken sway bar mount			01/06/2017	518087	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Elect\HEAD LIGHT	RH headlight out			01/06/2017	518087	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\AIR LEAK	air leak at rear of truck			01/06/2017	518087	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Tyres\PRES CHECK	Job Added From Invoice			30/05/2017	516468	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Tyres\RUN OUT	Job Added From Invoice			30/05/2017	516468	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\OIL LEAK	Replace turbo drain gaskets		check turbo drain all ok at this stage	24/05/2017	528306	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Steering\KING PIN	Replace LH & RH king pins			24/05/2017	528306	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabRep\AIR LEAK	Replace park brake valve in dash			23/05/2017	522208	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Insp\ANN INSP	annual inspection as per check list	Insp\ANN INSP		23/05/2017	516468	PreventativeMaintenance	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabRep\AIR LEAK	Check park brake valve leaking air		Complete	19/05/2017	516440	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Elect\HEAD LIGHT	Replace LH headlight assembly (LS188). Replace LH headlight assembly			10/05/2017	553717	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
					remove bonnet for repair, wash engine bay											
			Repair kangaroo damage to bonnet		SHEP panels repaired and painted bonnet (LS314)											
LOAD27	Myrtleford - Workshop	Body\DAMAGE	MAKE UP SMALL HOSE. Repair kanearoo damaee to bonnet		unload of trailer	10/05/2017	553717	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Tyres\RUN OUT	Job Added From Invoice			10/05/2017	514510	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
					Check dash circuit board & plugs - replace blown dash globes											
LOAD27	Myrtleford - Workshop	DrCabElect\INST/GAUGE	Dashlights dull - RHS not working		Comolete	08/05/2017	515163	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
					Temporarily secure headlight assembly											
LOAD27	Myrtleford - Workshop	Elect\HEAD LIGHT	LH headlight not working		Comolete	08/05/2017	515163	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\MOUNTS	Replace RHF axle support chain eye bolt			02/05/2017	514684	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Tyres	Job Added From Invoice			29/04/2017	514229	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			29/04/2017	514509	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS	RHF axle support chain eye bolt needs replacing	29/04/2017	514509	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Elect\HEAD LIGHT	L/H headlight/ Hi beam not working			22/04/2017	514108	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\BELTS/TENS	fan belts squealing when engine started			22/04/2017	514108	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\HOUSEKEEP	Repair or replace engine oil dipstick		dipstick measured 690mm overall length	11/04/2017	514509	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\HOUSEKEEP	check engine oil			22/03/2017	512552	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Tyres\TP01	Job Added From Invoice			16/03/2017	512058	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Tyres\TP05	Job Added From Invoice			16/03/2017	512058	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Tyres\TP07	Job Added From Invoice			16/03/2017	512058	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\PAINT/REST	paint toolboxes			10/03/2017	512058	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\PAINT/REST	acid wash rims			10/03/2017	512058	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\PAINT/REST	paint mudguard sides			10/03/2017	512058	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\PAINT/REST	paint front bar			10/03/2017	512058	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabRep\WINDSCREEN	Replace cracked windscreen			09/03/2017	512058	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabRep\AIR LEAK	Check air leaks in dash maxi brake & lever		Complete	07/03/2017		Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\MOUNTS	Repair loose RH bottom step bracket		Complete	07/03/2017		Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\COOL LEAKS	fit new hose clamp			01/03/2017		Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\HOUSEKEEP	top up coolant			01/03/2017		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Tyres\TP09	Job Added From Invoice			01/03/2017	509513	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Tyres\TP02	Job Added From Invoice			01/03/2017	511203	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\ENG FAN	Replace viscus engine fan			28/02/2017		Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Cooling\RADIATOR	refit radiator & intercooler & test			28/02/2017		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			08/02/2017	509842	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS	change air dryer filter	08/02/2017	509842	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabRep\HOUSEKEEP	glue top of gearstick (shift pattern)			26/01/2017	509264	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Steering\WHEEL STUD	replace R/H steer wheel stud			24/01/2017	509144	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
					Check operation of viscus fan											
LOAD27	Myrtleford - Workshop	Engine\ENG FAN	Truck running hot - water temp light coming on		Comolete	22/01/2017		Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Cooling\RADIATOR	De-bug radiator		Complete	22/01/2017		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\BELTS/TENS	Replace fan belt		Complete	22/01/2017		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
			exhaust elbow sitting on fuel tank													
LOAD27	Myrtleford - Workshop	Body\EXHAUST	-loose bottom of muffler			20/01/2017	509020	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Chassis\HOUSEKEEP	replace missing tow pin			20/01/2017	509020	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabElect\ELECT P&W	Repair Engine Brakes			14/01/2017	508885	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabElect\ELECT P&W	Repair indicator & park light		repair wiring behind seat	14/01/2017	508885	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Steering\WHEEL STUD	replace broken LH steer wheel stud			06/01/2017	508346	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
					selector housing problem maybe de-dent spring - need volvo housing schematic											
LOAD27	Myrtleford - Workshop	DrivLine\GEARBOX	Check gearbox & linkage for wear & damage		rebuild selector housing	05/01/2017	508358	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Tyres\TP08	Job Added From Invoice			31/12/2016	507540	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\MUDGUARDS	refit L/H mudflap			23/12/2016	507200	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\MUDGUARDS	replace LH rear mudflap			16/12/2016	507215	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\MOUNTS	RHS bottom step bracket loose			16/12/2016	507215	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Elect\TAIL LIGHT	RHF clearance light not working on drive			13/12/2016		Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\AIR LEAK	broken cable for air tank LHS behind fuel tank. broken cable for air tank LHS behond fuel tank			13/12/2016		Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Steering\WHEEL STUD	replace broken LH steer wheel stud			19/11/2016	505067	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Steering\WHEEL SEAL	replace LH hub seal			19/11/2016	505067	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS		18/11/2016	504952	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			18/11/2016	504952	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\ALT	Replace alternator			12/11/2016	504361	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\BELTS/TENS	Check fan belt squeal when starting engine		Complete	10/11/2016	504335	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\EXHAUST	Lift exhaust off RHS fuel tank		Complete	10/11/2016	504335	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Susp\HCV	lift suspension level (higher)			20/10/2016		Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Susp\HCV	water leaking in cab above fuse console			20/10/2016		Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabElect\INST/GAUGE	Repair power fault in dash guages		fit 2 new batteries (as below)	19/10/2016	502027	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabElect\BATTERY	Load test batteries		fit 2x new batteries	19/10/2016	502027	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Tyres\TP08	Job Added From Invoice			14/10/2016	499839	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Tyres\TP09	Job Added From Invoice			14/10/2016	499839	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabRep\HOUSEKEEP	water leaking from roof			30/09/2016	500113	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Brakes\BACK PLATE	Tighten RH steer brake backing plate		remove and repair backing plate	29/09/2016	528306	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Susp\SUSPENSION	Replace rear diff sway bar bushes		(500113 km) 29-9-16	29/09/2016	528306	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			28/09/2016	499839	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS		28/09/2016	499839	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabElect\INST/GAUGE	gauges on dash not working			17/09/2016	499192	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabElect\RADIO	replace UHF microphone & bracket. replace UHF microphoner & bracket			01/09/2016	498352	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\DAMAGE	Remove, Repair & Paint LHF quarter guard			31/08/2016	502038	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Steering\WHEEL STUD	Replace broken LH wheel stud & nut. Repair broken LH wheel stud		Complete	29/08/2016	498131	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Elect\HEAD LIGHT	Replace LH headlight rear cover & clips			25/08/2016	498131	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
					Fit H4 24v globe to RH headlight											
LOAD27	Myrtleford - Workshop	Elect\HEAD LIGHT	Repair RH headlight Short		Comolete	23/08/2016	497653	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabElect\PHONE	Check phone & settings		Complete	23/08/2016	497653	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\HOUSEKEEP	Replace air filter housing & fit filter		Complete	23/08/2016	497653	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\BOOST HOSE	repair boost leaks			09/08/2016	495872	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Susp\HCV	adjust ride height			09/08/2016	495872	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\FAULT CODE	clear engine codes			09/08/2016	495872	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabRep\WIPERS	Replace RH wiper & blade			02/08/2016	512060	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Susp\AIR BAG	Replace LHR drive airbag			02/08/2016	512060	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Elect\TAIL LIGHT	Make up box for between seats			02/08/2016	512060	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			29/07/2016	495059	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS		29/07/2016	495059	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Elect\WORK LIGHT	Repair RHR reverse light		Complete	28/07/2016	495059	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Susp\HCV	Check ride height		Complete	28/07/2016	495059	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Elect\TAIL LIGHT	Replace RHR clearance light		Complete	28/07/2016	495059	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\BOOST HOSE	Replace turbo boost pipe o'rings			16/07/2016	494135	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Susp\SWAYBAR	LH bracket/mount broken for swaybar			08/07/2016	491961	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\AIR LEAK	air leaking rear air tank			08/07/2016	491961	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\Cool	remove leaking intercooler & replace			08/07/2016	491961	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\MOUNTS	replace radiator mount rubbers			08/07/2016	491961	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Steering\WHEEL STUD	replace broken wheel stud			08/07/2016	491961	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\AIR LEAK	fit air tank			07/07/2016	491817	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\TURBO	inspect turbo and intercooler for leaks			06/07/2016	491598	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\FAULT CODE	pressure test intercooler			06/07/2016	491598	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Elect\WORK LIGHT	repair truck work lights			06/07/2016	491598	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Elect\TAIL LIGHT	Replace RHS Mirror Light			05/07/2016	491598	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\JAKE BRAKE	Repair engine brake - sticking on		road test touch & test engine brakes + micro switch all (ok)	05/07/2016	491598	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
			Check RH Mirror light out													
LOAD27	Myrtleford - Workshop	Elect\TAIL LIGHT	Repair Rear tail liehts & side liehts not workine			01/07/2016	491558	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
			Check air leaking from engine brake													
LOAD27	Myrtleford - Workshop	Engine\JAKE BRAKE	Check enaine brake comina on when chaneine gears		Comolete	01/07/2016	491558	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Susp\HCV	Adjust ride height - LHS		Complete	01/07/2016	491558	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabRep\WIPERS	Replace wiper blades		Complete	01/07/2016	491558	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\MUDGUARDS	Replace mudflap LHR		Complete	01/07/2016	491558	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS		11/06/2016	489852	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			11/06/2016	489852	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
					Replace LH hi beam globe											
LOAD27	Myrtleford - Workshop	Elect\TAIL LIGHT	Repair LH Hi beam		Complete	27/05/2016	488890	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
					Check over for boost/exhaust leak											
LOAD27	Myrtleford - Workshop	Engine\EXHAUST	Repair air leak in exhaust system		Complete	27/05/2016	488890	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Tyres\STEER TYRE	Job Added From Invoice			27/05/2016	488476	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Tyres\STEER TYRE	Job Added From Invoice			27/05/2016	0	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Insp\ANN INSP	annual inspection as per check list	Insp\ANN INSP		27/05/2016	488890	PreventativeMaintenance	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOA

			Fit new fan & alternator belts															
LOAD27	Myrtleford - Workshop	Engine\BELTS/TENS	Fit new idler pulley bearing		Comolete	18/03/2016	484380	Fault	Completed	Greenfreight Loxeine Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Cooling\RADIATOR	Fill radiator with new coolant		Complete	18/03/2016	484380	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
			Fit new air dryer filter															
			wash down engine & remmove bonnet for repairs															
LOAD27	Myrtleford - Workshop	Engine\HOUSEKEEP	Road tes		Complete	18/01/2016	484380	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Chassis\HOUSEKEEP	Cut down 3"side bumper bar plates on front of truck		Complete	18/03/2016	484380	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Elect\HOUSEKEEP	wash truck		complete	10/03/2016	483728	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabRep\DOOR LOCK	Adjust RH Door vibration		complete	10/03/2016	483728	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabRep\AIR CON	Unblock inner air vent on RH dash - passenger side		complete	10/03/2016	483728	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
					checked for coolant leak - ok													
					checked operation of thermo fan - ok													
LOAD27	Myrtleford - Workshop	Cooling\RADIATOR	Water temp alarm went off then went down		de-bue radiator and after cooler as best as oossible	03/03/2016	483541	Fault	Completed	Greenfreight Loxeine Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Susp\HCV	replace lh & rh ride height soleniods		completed	26/02/2016	482930	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
					Re-set ride height / suspension													
					checked suspension system for leaks - unable to fault													
					Driver to monitor													
LOAD27	Myrtleford - Workshop	Susp\HCV	Repair Truck Lean		Completed	23/02/2016	482454	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Susp\HCV	Fit LH & RH rear ride height valves		Completed	19/02/2016	481714	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabRep\DAMAGE	Repair damage to LHR corner of cab		inspect damage to cab all ok at this stage	19/02/2016	553717	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabElect\DOOR LOCK	Adjust & Lube RH door lock		(483734)	19/02/2016	553717	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Tyres\TP10	Job Added From Invoice			16/02/2016	480942	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
			Repair LH headlight															
LOAD27	Myrtleford - Workshop	DrCabElect\ELECT P&W	Repair number plate light		Completed	13/02/2016	481297	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabRep\WIPERS	Replace wiper blades		Completed	13/02/2016	481297	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Susp\HCV	adjust air ride height		Completed	09/02/2016	480942	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
					fit new headlight globe													
LOAD27	Myrtleford - Workshop	Elect\ELECT P&W	LH High beam not working		comoleted	05/02/2016		Fault	Completed	Greenfreight Loxeine Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
					adjust ride height valves													
LOAD27	Myrtleford - Workshop	Susp\HCV	check ride height wavle - leaning to the right		comoleted	05/02/2016		Fault	Completed	Greenfreight Loxeine Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		completed	01/02/2016	480014	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\FILTERS	supply b ser filters		completed	01/02/2016	480014	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS	480014 km reading	01/02/2016	480014	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\MOUNTS	weld crack in drivers side top step mount		completed	29/01/2016		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Susp\SHOCK ABS	replace RHR shocker		completed	27/01/2016		Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\MOUNTS	replace RHR upper shocker mount		completed	27/01/2016		Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
					replace LH indicator globe													
LOAD27	Myrtleford - Workshop	DrCabElect\INDICATORS	front LH indicator not working		comoleted	22/01/2016		Fault	Completed	Greenfreight Loxeine Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\MOUNTS	replace broken RR axle pin		completed	22/01/2016		Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\JAKE BRAKE	replace no 5 valve bridge pozit+tune engine		completed	11/12/2015		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Chassis\CROSS MBR	repair chassis crack		completed	08/12/2015		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
			rh steer shocker mount															
LOAD27	Myrtleford - Workshop	Body\MOUNTS	cmv		COMPLETED	03/12/2015		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
			repair lh bottom chassis flange crack behind lhf leg															
LOAD27	Myrtleford - Workshop	Chassis\AXLE CT	replace rh bottom steer shocker mount		completed	03/12/2015		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
			Rear suspension air bags won't come up															
LOAD27	Myrtleford - Workshop	Susp\AIR BAG	Replace air bag,regulator valve & clean dump valves		completed	02/12/2015		Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
			repair engine jakes															
LOAD27	Myrtleford - Workshop	Engine\JAKE BRAKE	clear engine codes		completed	02/12/2015		Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS	completed	02/12/2015		Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		completed	02/12/2015		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Chassis\SUSPENSION	replace lhr sway bar support		completed	01/12/2015		Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\ENG TUNE	replace no 5 injector + tune engine		completed	24/11/2015		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
			replace no 5 injector + tune															
LOAD27	Myrtleford - Workshop	Engine\FAULT CODE	cmv		comoleted	24/11/2015		Reapir	Completed	Greenfreight Loxeine Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Elect\ELECT P&W	repair wiring to lh indicator plug		completed	10/11/2015		Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
			2 steer shocks															
LOAD27	Myrtleford - Workshop	Susp\SHOCK ABS	multisoares		comoleted	06/11/2015		Reapir	Completed	Greenfreight Loxeine Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Susp\SHOCK ABS	replace steer shockers		completed	03/11/2015		Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\COOL LEAKS	repair coolant leak from header tank by cutting off split section of hose + add coolant		completed	03/11/2015		Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
			replace rear mudflaps															
LOAD27	Myrtleford - Workshop	Chassis\MUDGUARDS	tighten lh too stes bolts		comoleted	03/11/2015		Fault	Completed	Greenfreight Loxeine Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	DrCabRep\DOOR LOCK	adjust rh door lock striker plate		completed	09/10/2015		Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS	completed	01/10/2015		Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Brakes\BRK O/HAUL	brakes		completed	01/10/2015		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
			adjust front brakes															
LOAD27	Myrtleford - Workshop	Brakes\BRK O/HAUL	fit new lh front steer wheel stud + wheel nut		completed	30/09/2015		Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
			repair rh rear clearance light															
LOAD27	Myrtleford - Workshop	DrCabElect\ELECT P&W	repair dash guages		completed	24/09/2015		Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Engine\FUEL TANK	Service Job Added From Invoice			22/09/2015	0	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
			replace 6 injector tubes															
			tune engine + jakes															
			replace fuel check valve in head															
			replace copper washers on fuel fittings															
LOAD27	Myrtleford - Workshop	Engine	clear codes		comoleted	18/09/2015		Reapir	Completed	Greenfreight Loxeine Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Body\MOUNTS	Job Added From Invoice			17/09/2015	0	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
			replace rhr sway bar mount															
			repair guage on dash															
LOAD27	Myrtleford - Workshop	Chassis	replace fuel filter glass		completed	16/09/2015		Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
			adjust driving lights															
			check fuel issues won't start															
			replace check valves in filter heads															
			replace check valve at fuel pump															
LOAD27	Myrtleford - Workshop	Engine	check over fuel lines		completed	04/09/2015	468555	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER
LOAD27	Myrtleford - Workshop	Elect\ELECT P&W	Service Job Added From Invoice			02/09/2015	0	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	TQI660	Myrtleford Workshop	LOADER