EquipmentName	Workshop	CodeAndSubCode	Description	Schedule	CompletionComments	DateDone	HourDone	Worktype	Workstate	EquipmentOwner	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
					P26											
					Repairs to grab. 237.50											
P26	Albury - Workshop	Chassis\Boom	REPLACE LUGS ON GRAB TO MAKE GRAB FOLD UP		1 3/4" 4140	24/11/2025	181	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		RINLATECH ENGINEERING - 4	PRENTICE
					Rebuild Tripple pump. 455.00											
					P350 1 1/2" housing 477.00											
					P350 2" housing 531.00											
					6306-2rs 31.75 outrigger bearing 92.00											
			REBUILD HYD TRIPPLE PUMP		SKF350-3 seal kit. 182.90											
P26	Albury - Workshop	Hydraulics\PUMP	T097331		freight on parts	10/10/2025	181	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Albury Workshop	PRENTICE
					Travel to Shelley											
					Remove blown hose											
					Make and fit new hose											
					Fill up oil											
P26	Albury - Workshop	Hydraulics\HOSES	MAKE REPLACEMENT GRAB HOSES		Test - OK	08/08/2025	181	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		RAPID HYDRAULICS & PNEUMATICS -4	PRENTICE
					REPLACED GRAB CYLINDER											
					REPAIRED LH REAR LEG PIN NOT TAKING GREASE											
					WELDING REPAIRS											
P26	Albury - Workshop	VehService\BS	VehService\BS B Service	VehService\BS	LIGHT REPAIRS (SOME NOT WORKING)	23/07/2025	181	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Albury Workshop	PRENTICE
P26	Albury - Workshop	Hydraulics\HOSES	MAKE REPLACEMENT HYDRAULIC HOSE			19/07/2025	181	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		RAPID HYDRAULICS & PNEUMATICS -4	PRENTICE
P26	Albury - Workshop	Hydraulics\HOSES	MAKE UP SPARE HYD GRAB HOSE			27/05/2025	125	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		RINLATECH ENGINEERING - 4	PRENTICE
			inspect and repair movement (stop) in slew pedal		found clevis pins to be worn out replaced and improved movement but still a slight amount in it											
P26	Albury - Workshop	Hydraulics\VALVES	(hrs at time of repair 9826)		check and too us hyd oil level	20/05/2025	125	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Albury Workshop	PRENTICE
P26	Albury - Workshop	Hydraulics\VALVES	reseal pilot levers due to leaking oil			20/05/2025	125	Fault	Unlocked	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Albury Workshop	PRENTICE
			REPLACE ALTERNATOR													
			REPLACE FAN PULLEY BEARING													
			REPLACE FAN & A/CON BELTS													
P26	Albury - Workshop	Elect\ALT	FIT HOSE CLAMP TO OIL FILLER NECK			20/05/2025	100	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Albury Workshop	PRENTICE
P26	Albury - Workshop	Body\DH&S	REPLACE WALK WAY GRIP TAPE			20/05/2025	100	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Albury Workshop	PRENTICE
P26	Albury - Workshop	VehService\BS	VehService\BS	VehService\BS		19/05/2025	50	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Albury Workshop	PRENTICE
P26	Albury - Workshop	Hydraulics\HYD LEAKS	wash down to inspect for oil leaks			16/05/2025	125	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Albury Workshop	PRENTICE
P26	Albury - Workshop	Chassis\Boom	REPAIR MAIN BOOM CRACKS ON BOTH SIDE OF BOOM		sublet rinlatech	16/05/2025	125	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Albury Workshop	PRENTICE
P26	Albury - Workshop	Hydraulics\RAM	REPLACE RH MAIN LIFT RAM BOTTOM EYE & BUSHES		sublet rinlatech	16/05/2025	125	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Albury Workshop	PRENTICE
P26	Albury - Workshop	Engine\OIL LEAK	REPLACE DIP STICK & TUBE REPLACE OIL FILLER TUBE REPLACE LEAKING HEATER TAP (WASH ENGINE & TEST FOR OIL LEAKS)		done at 9686 hrs	03/04/2025	35	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		CUMMINS SOUTH PACIFIC P/L - 4	PRENTICE
			TEST ENGINE BLOW BY													
P26	Albury - Workshop	Engine\FAULT CODE	(BLOW BY IS AT MAXIMUM SPEC LEVEL)		done at 9686 hrs	03/04/2025	35	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		CUMMINS SOUTH PACIFIC P/L - 4	PRENTICE
			REBUILD 2 X GRAB RAMS													
P26	Albury - Workshop	Hydraulics\RAM	SUPPLT 2 X GRAB HOSES			12/02/2025	35	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		RINLATECH ENGINEERING - 4	PRENTICE
P26	Myrtleford - Workshop	DriCabElect\HOUSEKEEP	radio cradle / over head console loose		HRS at time of repair 9606	04/02/2025	35	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics\MOTOR	LOADER SLEW GEAR CLUNKING.		REFIT BOLT THAT HOLDS SLEW GEAR ONTO SLEW MOTOR (THE MOUNT BOLT HAD FALLEN OUT)	04/02/2025	9606	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Elect\WORK LIGHT	LIGHT ON LOADER CAB LOOSE.			04/02/2025	9606	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics\HYD LEAKS	GRAB LEAKING HYDRAULIC OIL.		replaced both hyd grab cly (HRS 9606)	31/01/2025	9606	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	VServLab	LOADER 150 HOURS OVERDUE FOR SERVICE.		job completed on job number 193635 (B-service)	31/01/2025	9606	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	DriCabElect\RADIO	LOADER UHF RADIO INTERMITTENTLY NOT WORKING.		HRS at time of repair 9606	31/01/2025	9606	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Chassis\STAB LEG	LHS REAR LEG PIN BROKEN.		HRS at time of repair 9606	31/01/2025	9606	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Chassis\STAB LEG	VARIOUS GREASE NIPPLES MISSING FROM GRAB & LEGS.		hrs at time of repair 9606	31/01/2025	9606	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Insp\ANN INSP	Insp\ANN INSP	Insp\ANN INSP		31/01/2025	9606	PreventativeMaintenance	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Myrtleford Workshop	PRENTICE
			VehService\BS													
P26	Myrtleford - Workshop	VehService\BS	REPLACE HYD & SERVO FILTERS	VehService\BS		30/01/2025	9606	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Myrtleford Workshop	PRENTICE
P26	Wodonga - Workshop	Hydraulics\DAMAGE	Replace Hydraulic Cylinder Due To Damaged Rod.			04/12/2024	5	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Wodonga Workshop	PRENTICE
			Setup jig and remove seized lift pin. Machine new bushes and													
			both top and bottom pins and reinstall. Reamble up and													
			change out lift cylinders. Repair leaks and replace hyd hoses.													
			Replace hyd pump and replace servo seals in hand controls.													
P26	Myrtleford - Workshop	Hydraulics\RAM	Setup and test sensures etc.			09/08/2024	5	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		RINLATECH ENGINEERING-3	PRENTICE
P26	Myrtleford - Workshop	Elect\WORK LIGHT	repair work lights			26/07/2024	5	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Myrtleford Workshop	PRENTICE
					HRS at time of service 8776											
					/air cleaners inner and outer replaced											
					rain cap replaced											
P26	Myrtleford - Workshop	VehService\BS	B Service	VehService\BS	outer boom liaht repaired RHS	26/07/2024	3	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Myrtleford Workshop	PRENTICE
P26	Wodonga - Workshop	Hydraulics\RAM	Replaced Grab ram			18/06/2024	1	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Wodonga Workshop	PRENTICE
P26	Wodonga - Workshop	Engine\BREAKDOWN	LOADER RAN OUT OF FUEL.		PACKED TOOLS. FUELLED UP POD ON UTE. TRAVELLED TO SHELLY. FILLED FILTERS. PRIMED WITH HAND PUMP UNSUCCESSFULLY. TRAVELLED TO RETRIEVE WORKSITE FOR COMPRESSOR- NO ONE	27/04/2024	8502	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Wodonga Workshop	PRENTICE
P26	Wodonga - Workshop	Engine\FUEL TANK	REPLACE HAND LIFT PUMP.			27/04/2024	8502	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Wodonga Workshop	PRENTICE
P26	Wodonga - Workshop	Hydraulics\HYD LEAKS	REPLACE HYD GRAB HOSE.		UNFOLDED AND DIAGNOSED HOSE LEAK. RAPID REPLACED. TESTED. FOLDED AND WASHED.	11/04/2024	8434	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Wodonga Workshop	PRENTICE
P26	Wodonga - Workshop	Unknown	SERVICE DUE ON LOADER.			11/04/2024	8434	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Wodonga Workshop	PRENTICE
P26	Wodonga - Workshop	Hydraulics\PUMP	HYDRAULIC PUMP DRIVE SHAFT SEAL LEAKING.			11/04/2024	8434	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Wodonga Workshop	PRENTICE
P26	Wodonga - Workshop	VehService\CS	Service As Per Attached Checklist	VehService\CS	RELOCATED RUBBING FUEL LINES. REPLACED HYDRAULIC RETURN FILTER. TIGHTENED LEAKING HYDRAULIC FITTINGS AT VALVE BLOCK.	11/04/2024	8434	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Wodonga Workshop	PRENTICE
P26	Wodonga - Workshop	DriCabRep\SEAT	RE-PIN SEAT- ROCKING BACK/ FORTH.		INSPECTED. REPLACED RAILS.	31/03/2024		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Wodonga Workshop	PRENTICE
P26	Wodonga - Workshop	Chassis\Boom	REPLACED LIFT BOOM.			31/03/2024		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Wodonga Workshop	PRENTICE
P26	Wodonga - Workshop	Engine	CHECK/ADD ENGINE OIL			26/03/2024		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Wodonga Workshop	PRENTICE
P26	Wodonga - Workshop	Unknown	GREASE LOADER.			26/03/2024		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Wodonga Workshop	PRENTICE
P26	Wodonga - Workshop	Chassis\STAB LEG	REPLACED RR LEG RAM PIN. GREASED LEGS.			01/03/2024	8163	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics\HYD LEAKS	LEAKING RH SERVO.		REBUILT WITH NEW SEAL KIT.	23/02/2024	8130	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Body	CHECKED OIL, COOLANT AND LIGHTS. REPAIRED PLATE.			23/02/2024	8130	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Myrtleford Workshop	PRENTICE
P26	Wodonga - Workshop	Hydraulics\OIL LEAK	CHECK HYD LIFT RAM OIL LEAK.		REPLACED O-RINGS AT HOSE FITTINGS. WASHED DECK.	25/01/2024		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Wodonga Workshop	PRENTICE
P26	Wodonga - Workshop	DriCabElect\ELECT P&W	INTERIOR LIGHT NOT WORKING.			25/01/2024		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Wodonga Workshop	PRENTICE
P26	Wodonga - Workshop	DriCabRep	RESEALED LH JOYSTICK.			25/01/2024		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Wodonga Workshop	PRENTICE
P26	Wodonga - Workshop	Hydraulics\HOSES	CROSS OVER HYD HOSE & FITTING.		REMOVED, SHORTENED AND FITTED CROSSOVER HOSE FOR LIFT RAMS.	25/01/2024		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Wodonga Workshop	PRENTICE
P26	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS		20/12/2023	8094	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Myrtleford Workshop	PRENTICE
P26	Wodonga - Workshop	Body\MOUNTS	replace missing bolt for light bar			06/12/2023		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Wodonga Workshop	PRENTICE
P26	Myrtleford - Workshop	Chassis\STAB LEG	REPLACED BROKEN LEG PIN.			05/12/2023	8010	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics\RAM	REPLACED GRAB RAM.			05/12/2023	8010	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Chassis\Boom	REPAIRED CRACKS IN GRAB.			05/12/2023	8010	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Myrtleford Workshop	PRENTICE
			Dismantle spare lift cylinder, had lots of difficulty removing													
			stuck piston. Cut off rod eye and setup and skim out, rotary													
			weld up eye and machine new bearing journal. Reweld to rod.													
			Severly hone out shrunk part of barrel, resemble up cylinder													
P26	Myrtleford - Workshop	Hydraulics\RAM	and test.			02/12/2023		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Albury Workshop	PRENTICE
P26	Wodonga - Workshop	Hydraulics\RAM	BROKEN BUSH HYD CENTRE SPEAR RAM.		REPLACED RAM DUE TO FAILED BEARING.	14/11/2023	7922	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Wodonga Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics\OIL/FILTER	CHANGE ALL HYD FILTERS AND CHANGE HYD OIL		WELDED & REPAIRED CRACKED BRACKET ON BOOM.	31/10/2023	7853	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS	FITTED BREATHER HOSE AND CLAMP TO HYDRAULIC HOSE. REPAIRED 2 WORK LIGHTS. TIGHTENED BOOM HOSE BRACKETS. PAINT PATCH ON BOOM.	31/10/2023	7853	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics\DAMAGE	REPLACE BROCKEN TOP MAIN LIFT PIN (rinlatech removed old mian lift pin and made and fitted new top main lift pin)			26/10/2023	7830	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		RINLATECH ENGINEERING-3	PRENTICE
P26	Myrtleford - Workshop	Engine\FUEL TANK	Fuel Tank & System			21/10/2023		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Albury Workshop	PRENTICE
P26	Wodonga - Workshop	Engine\FUEL TANK	BREAKDOWN IN BUSH. FUEL ISSUES.		RAN FUEL CHECKS WITH CUMMINS.SHOWED LOW FUEL.	21/10/2023	7824	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Wodonga Workshop	PRENTICE
P26	Wodonga - Workshop	Chassis\HOUSEKEEP	REPLACE 3 GREASE PINS ON GRAB			20/10/2023	7814	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Wodonga Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics\PUMP	PILOT PUMP LEAKING		WASHED MOTOR. REMOVED PUMP. OVERHAULED AT RINLATECH. FITTED PUMP. WASHED OIL. CHECKED OIL AND COOLANT. TESTED.	14/09/2023	7770	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Myrtleford Workshop	PRENTICE
					Repair Leg Ram											
			Setup and test cylinder. Cut off rod eye and buildup and		Dismantle and clean leg ram. Polish up all sealing surfaces											
			machine. Refit eye. Repairs to damaged cylinder rod. Reseal		and repair crome rod. Remove and replace rod and barrel											
P26	Myrtleford - Workshop	Hydraulics\RAM	and retest.		bushes. reasemble with new seals. Test and paint.	23/06/2023		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Albury Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics\VALVES	reseal RH/Ut pivot lever's			22/06/2023	7664	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Myrtleford Workshop	PRENTICE
P26	Albury - Workshop	Hydraulics\RAM	Randall supply parts			20/06/2023		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		RANDALLS EQUIPMENT CO (VIC) - 3	PRENTICE
P26	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS		15/06/2023	7652	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	DriCabRep\SEAT	NE MOTOR TRIM REPAIR ARM RESTS X 2			09/06/2023		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Albury Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics\HYD LEAKS	fit seal kit to grab hose swivel			08/06/2023	7642	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics\HOSES	replace grab hose and fitting o-rings			08/06/2023	7642	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Workshop\MOVE ASSET	take P26 to Rinlatech			08/06/2023	7642	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Workshop\MOVE ASSET	pick up P26 at Rinlatech			08/06/2023	7642	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Myrtleford Workshop	PRENTICE
			Setup and test grab cylinder, dismantle and repair crome rod.													
			Repair and polish all parts and reasemble with new seals and													
P26	Myrtleford - Workshop	Hydraulics\RAM	test. Paint.			26/05/2023		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Albury Workshop	PRENTICE
P26	Myrtleford - Workshop	Body\HOUSEKEEP	wash down grab from hyd leak			02/05/2023	7520	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics\RAM	replace grab cly and test			02/05/2023	7520	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Engine\FILTERS	engine not starting			22/04/2023	7484	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics\MOTOR	change over slew motor		replace slew motor	13/04/2023	7460	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics\MOTOR	top up hyd oil			13/04/2023	7460	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	DriCabElect\RADIO	radio wont keep its memory		tune radio	13/04/2023	7454	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	DriCabRep\HOUSEKEEP	replace broken servo grips		fit covers to handles	13/04/2023	7454	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS		13/04/2023	7454	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	DriCabRep\AIR CON	a/c not working in loader		replace ac compressure	02/04/2023	7432	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	DriCabRep\AIR CON	replace ac dryer			02/04/2023	7432	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	DriCabRep\AIR CON	remove ac hoses			02/04/2023	7432	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Body\HOUSEKEEP	repair crack's in grab (welding)			07/03/2023	1380	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Body\HOUSEKEEP	check over			21/02/2023	7377	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics\RAM	replace stick cly (bearing failed)			21/02/2023	7377	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Chassis\HOUSEKEEP	weld boss back in place for stick cly			21/02/2023	7377	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Myrtleford Workshop	PRENTICE
			RHF leg ram leaking													
			Repairs to grab cylinder, repair damaged crome and resemble		replace RHF leg ram											
P26	Myrtleford - Workshop	Hydraulics\RAM	with new seals and test.. RHF lee ram leakine		Reoair too mountine pin chanee out lee cylinder.	12/01/2023	7338	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics\DAMAGE	top LH leg pin tab		repair LHR top leg pin mount	12/01/2023	7338	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics\VALVES	adjust servo handle		adjust servo controls	12/01/2023	7338	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Myrtleford Workshop	PRENTICE
			check and repair aircon system													
			CHECK A/C SYSTEM.													
			CONNECT GAUGES.													
			RECOVER REFRIGERANT.													
			PRESSURE TEST SYSTEM WITH NITROGEN.													
			NO LEAK FOUND.													
			EVACUATE AND CHARGE SYSTEM.													
P26	Myrtleford - Workshop	DriCabRep\AIR CON	CHECK FOR LEAKS WITH ELECTRONIC DETECTOR.. check and reoair aircon system		check and repair aircon system	12/01/2023	7338	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Myrtleford Workshop	PRENTICE
P26	Wodonga - Workshop	Hydraulics\RAM	REPLACE RHF LEG CYLINDER LEARING OIL		fit c/over leg ram	14/12/2022	7421	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Wodonga Workshop	PRENTICE
P26	Wodonga - Workshop	Engine\OIL LEAK	REPAIR OIL/COOLANT LEAK AT FILTER HOUSING			14/12/2022	7421	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Wodonga Workshop	PRENTICE
					top up coolant											
P26	Wodonga - Workshop	VehService\BS	VehService\BS	VehService\BS	too us too up hyd oil	14/12/2022	7300	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Wodonew Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics\VALVES	check out grab keeps opening up and dropping logs		check pressure in grab circuit	26/10/2022	1719	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics\HYD LEAKS	Hyd fitting leaking rod end main lift cly		Replaced leaking fitting hyd	12/10/2022	7179	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Myrtleford Workshop	PRENTICE
			Setup and carry out tests on grab, set grab up in diffrent													
			positions and retest. Test both sides of cylinders, test swivell.													
			Check and test valve function. Could not fault holding in any													
P26	Myrtleford - Workshop	Hydraulics\RAM	way. Suspect operator error.			06/10/2022		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Albury Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics\HOSES	Replace blown pilot hose from pump to filter (on site)			04/10/2022	7155	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics\OIL LEAK	hose leak on grab		hyd hoses	29/09/2022		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Body\HOUSEKEEP	grease loader			26/08/2022	7077	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	VehService\BS	B Service As Per Attached Checklist	VehService\BS	repair a/c tensioner	17/08/2022	7050	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics\HOSES	blown hyd hose on site			13/08/2022	7044	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics\OIL LEAK	top up hyd oil			02/08/2022	7002	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Chassis\HOUSEKEEP	inspect slew ring			02/08/2022	7002	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics\RAM	Rebuild grab cylinder, new rod seals etc.			02/08/2022		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics\RAM	replace grab cylinder			27/07/2022	6994	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Body\HOUSEKEEP	grease loader/legs/grab			16/07/2022	6968	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics\OIL LEAK	oil leak at grab			16/07/2022	6968	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Body\HOUSEKEEP	fit grab to loader			09/07/2022	6952	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR		Myrtleford Workshop	P

P26	Myrtleford - Workshop	Hydraulics\BREAKDOWN	change grab				08/07/2022		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics\MOTOR	dismantle , repair and reseal Staffa Slew motor				05/07/2022		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Body\HOUSEKEEP	replace broken grease nipple RHR foot				04/06/2022	6850	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics\RAM	replace leaking grab ram			grab ram	03/06/2022	6846	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS			03/06/2022	6851	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics\OIL LEAK	hydraulic leak				26/05/2022	6806	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics\OIL LEAK	grab leaking oil				25/05/2022	8600	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics\OIL LEAK	oil leak top of grab			oil leak at grab	19/05/2022	6776	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Body\HOUSEKEEP	check grease nipple RH main ram lower - doesn't seem to take grease			grease nipple's	19/05/2022	6776	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics\MOTOR	wash grab R&R top swivel motor				12/05/2022	6744	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics\RAM	change grab c/y				12/05/2022	6744	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Body\HOUSEKEEP	flop up grab				04/05/2022	6728	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Elect\WORK LIGHT	work lights cutting out			check wiring	28/04/2022	6703	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics\OIL LEAK	ram on grab leaking			replace ram and 2x hard lines	28/04/2022	6703	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	DrCabRep\HOUSEKEEP	tighten RH lever			tighten joystick	28/04/2022	6703	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Elect\WORK LIGHT	RH outer boom light n/w				27/04/2022	6697	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	DrCabRep\HOUSEKEEP	supply floor mat				27/04/2022	6697	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics\OIL LEAK	RH plungers leaking				27/04/2022	6697	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics\HOSES	FIT UP NEW HYDRAULIC STEEL LINES TO OUTER BOOM				20/04/2022	6708	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics\HOSES	fit 2nd hand stick boom steel line				15/04/2022	6663	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Elect\WORK LIGHT	fit LED light bar				15/04/2022	6663	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Body\HOSES	CHARGE AIR HOSE U/S				14/04/2022	1	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Elect\WORK LIGHT	light up top on cage/windscreen keeps flicking				14/04/2022	6646	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Chassis\HOUSEKEEP	box grease				14/04/2022	6646	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Chassis\HOUSEKEEP	rags				14/04/2022	6646	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Body\HOUSEKEEP	top hose on dipper arm broken clamp bolt				14/04/2022	6646	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS			14/04/2022	6654	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Chassis\HOUSEKEEP	grease loader grab and legs				01/04/2022	6617	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Albury - Workshop	Body	REMOVE ALL LEGS AND CLEAN UP ALL PLATES AND REMOVE O/D PLATES AND WELD NEW ONES. Removed and reolaced bushes. machine all new oins. Reaser				30/03/2022		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Myrtleford - Workshop	Body\HOUSEKEEP	grease loader				24/03/2022		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
			check oil leak from grab													
			RHR grab ram													
P26	Myrtleford - Workshop	Hydraulics\RAM	too up hyd oil			hyd leak at arab	22/03/2022	6579	Fault	Completed	Greenfreight Loxeine NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics\HOSES	RHR leg operating opposite to others (ref brenton)				17/03/2022	6564	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Body\HOUSEKEEP	fit new no entry signs				05/03/2022		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Engine\EXHAUST	fit rain cap				20/02/2022	6508	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics\HOSES	Rinlatech supply hose & fittings				14/02/2022	1	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Chassis\HOUSEKEEP	grease loader				01/02/2022	6432	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Body\MOUNTS	weld boom pipe brackets				01/02/2022	6432	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS			22/01/2022	6448	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	DrCabElect\SCALES	remove old scale link display				19/01/2022	6431	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	DrCabRep\HOUSEKEEP	replaced joystick grips				19/01/2022	6431	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics\RAM	LH ram leaking			change hyd lift ram	18/01/2022	6426	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	DrCabRep\HOUSEKEEP	replace broken servo grips				18/01/2022	6426	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Body\HOUSEKEEP	grease loader and grab				12/01/2022	6400	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Engine\RADIATOR	lower radiator hose bracket				12/01/2022	6400	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics\VALVES	tighten slop in slew pedal				12/01/2022	6400	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Chassis\HOUSEKEEP	check over				07/01/2022	6395	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Elect\ELECT P&W	rewire boom lights and replaced brackets				07/01/2022	6395	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Body\HOUSEKEEP	cracks in grab				07/01/2022	6395	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Body\HOUSEKEEP	cracks in front cradle frame				07/01/2022	6395	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics\RAM	LHR leg ram bolt				07/01/2022	6395	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Body\HOUSEKEEP	Machine up 2 allum hand controls				05/01/2022		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	RINLATECH ENGINEERING-3	PRENTICE
P26	Myrtleford - Workshop	Workshop\MOVE ASSET	take L17 to Wandi swap with L26				22/12/2021	6387	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics\RAM	remove RHD lift ram				22/12/2021	6387	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Body\HOUSEKEEP	build up loose as were worn, will need re doing sooner rather than later				22/12/2021	6387	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics\OIL LEAK	top up oil and test and wash				22/12/2021	6387	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Engine\HOUSEKEEP	top up engine oil loader			grease and top up engine oil	17/12/2021	6368	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Body\HOUSEKEEP	grease loader				17/12/2021	6368	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics\HYD LEAKS	RHR leg hydraulic leak			hyd oil leak RHR leg	17/12/2021	6368	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Air Con\AIR CON	ac condensor foam had moved				08/12/2021	6211	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Body\HOUSEKEEP	LHR loader leg pin			LHR leg pivot pin broken	08/12/2021	6211	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics\OIL LEAK	oil leak RH ram main boom			replaced "o" ring on hyd hose - tested - topped up fluid	26/11/2021	6271	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Chassis\HOUSEKEEP	box of grease				26/11/2021	6271	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
						steam clean motor										
P26	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS		servo ourno	20/11/2021	6249	Service	Completed	Greenfreight Loxeine NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Chassis\DAMAGE	RHR under leg pin broken				17/11/2021	6233	Fault	Completed	Greenfreight Loxeine NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	DrCabRep\HOUSEKEEP	replace servo hand grips			replace joy stick handles	12/11/2021	6218	Fault	Completed	Greenfreight Loxeine NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Engine\HOUSEKEEP	top up engine oil				09/11/2021	6204	Fault	Completed	Greenfreight Loxeine NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	DrCabRep\DOOR LOCK	refit door strut				09/11/2021	6204	Fault	Completed	Greenfreight Loxeine NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Chassis\DAMAGE	grease loader grab and legs				04/11/2021	6178	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
			fit cooling fan in cabin													
P26	Myrtleford - Workshop	DrCabElect\ELECT P&W	fit grease nicole block to boom				23/10/2021	6150	Repair	Completed	Greenfreight Loxeine NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Chassis\HOUSEKEEP	fit remote grease lines to main boom				23/10/2021	6150	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics\RAM	grab ram leaking oil			replaced grab ram	05/10/2021	6083	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics\PUMP	fit seal kit to hyd servo pump				01/10/2021	6077	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Chassis\DAMAGE	repair damage grab tips				01/10/2021	6077	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS		weld cracks	28/09/2021	4064	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Engine\HOUSEKEEP	check fluids				24/09/2021	6057	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Engine\BREAKDOWN	top up engine oil on site 11 liters				23/09/2021	6046	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics\RAM	RH RAM bearing U/S			fit boom lift RAM	22/09/2021	8040	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Body\CHN/RUN/MN	Chain on grab cradle broken			weld chain on frame	22/09/2021	8040	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Chassis\HOUSEKEEP	replace missing grab RAM grease nipple				21/09/2021	6038	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	DrCabElect\RADIO	rewire radio and fit microphone				17/09/2021	6031	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Air Con\AIR CON	check a/c operation				14/09/2021	6014	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	DrCabElect\RADIO	radio wont keep its memory				14/09/2021	6014	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	DrCabRep\RADIO	Replace am/fm stereo				10/09/2021	6007	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Elect\WORK LIGHT	Fit light bar to cab				10/09/2021	6007	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	DrCabRep\DOOR LOCK	Fit gas strut to door				10/09/2021	6007	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Chassis\HOUSEKEEP	grease loader, grab and legs				09/09/2021	5996	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	DrCabRep\HOUSEKEEP	s/f floor mat				09/09/2021	5996	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	DrCabElect\HEATER REP	heater control doesn't work				09/09/2021	5996	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics\MOTOR	remove and refit grapple slew motor				03/09/2021	5974	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	DrCabRep\SEAT	remove and replaced seat base				03/09/2021	5974	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics\HYD LEAKS	Rinlatech fit seal kit to grab slew motor				03/09/2021	5974	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Engine\RADIATOR	remove radiator, debug and pressure test				03/09/2021	5974	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Engine\MOUNTS	replace all 4 eng mount rubbers and all bolts				03/09/2021	5974	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Engine\ENG TUNE	TUNE ENGINE				03/09/2021	5974	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Chassis\HYDRAULICS	Grab double side jaw, missing grease nipple on bottom of ram			replaced grease nipples	31/08/2021	5960	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Engine\BELTS/TENS	REPLACE CRANK AND FAN AND ALT PULLES AND FIT TENSIONER AND FAN BELT				27/08/2021	5974	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Chassis\HOUSEKEEP	x3 grease nipples onto of loader blocked				26/08/2021	5950	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Chassis\HOUSEKEEP	main ram top boom front grease nipple			replace 4x grease nipples	19/08/2021	5929	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Chassis\HOUSEKEEP	LJH ram grease nipple				19/08/2021	5929	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	DrCabElect\RADIO	load UHF straps channels and hard to hear			check over U.H.F replaced unit with second hand one	19/08/2021	5929	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics\HOSES	leaking grab hose			check hose	17/08/2021	5922	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics\OIL/FILTER	top up oil test wash down truck and loader				17/08/2021	5922	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Elect\WORK LIGHT	rewire boom lights from relay to lights				12/08/2021	5905	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Body\CHN/RUN/MN	weld chain to tow pin				12/08/2021	5905	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Elect\WORK LIGHT	top boom worklights not working and move brackets			boom lights not working (updated lights) moved brackets	11/08/2021	5900	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics\HYD LEAKS	grab leaking oil			oil leak at grapple/heel	10/08/2021	5894	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics\VALVES	hyd noise grooning			grapple motor issue when rotating	10/08/2021	5894	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics\HOSES	both hydraulic hoses down RHS of crane			readjust grapple hoses rewrap	10/08/2021	5894	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Engine\HOUSEKEEP	wash engine bay				07/08/2021	5894	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Engine\RADIATOR	fit new hose to overflow reservoir				07/08/2021	5894	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Body\HOUSEKEEP	wash cab				07/08/2021	5894	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Chassis\HOUSEKEEP	degrease and wash grab				07/08/2021	5894	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Chassis\HOUSEKEEP	grease prentice				06/08/2021	5882	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Chassis\HOUSEKEEP	cracks LH main boom cylinder at front pivot				06/08/2021	5882	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Engine\COOL LEAKS	coolant bottle cap				04/08/2021	5868	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Engine\COOL LEAKS	check coolant leak				04/08/2021	5868	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Engine\HOUSEKEEP	clean motor				04/08/2021	5868	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Chassis\HOUSEKEEP	repair grab tips				04/08/2021	5868	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics\HYD LEAKS	fit seal kit to grab hose swivel				04/08/2021	5868	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Workshop\MOVE ASSET	take to Rinlatech for repairs				04/08/2021	5868	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Chassis\DAMAGE	repair grab rest				04/08/2021	5868	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics\VALVES	check slew pressure				04/08/2021	5868	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Workshop\MOVE ASSET	swap P26 with P27				03/08/2021	5868	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Engine\BELTS/TENS	replace fan belt				03/08/2021	5868	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Engine\HOUSEKEEP	inspet coolant leak. Looked over full				03/08/2021	5868	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics\OIL/FILTER	Change hyd oil & sight glass & clean out tank				24/07/2021	5864	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics\HOSES	Repair hyd leak at spool bank & feed hose				24/07/2021	5864	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Body\DAMAGE	Repair hyd tank cracks				24/07/2021	5864	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	DrCabRep\MOUNTS	Replace cab mounts				24/07/2021	5864	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	DrCabRep\WINDSCREEN	Replace windscreen				24/07/2021	5864	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Engine\RADIATOR	Repair LHS of fan shroud				24/07/2021	5864	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics\PUMP	broken bolt triple pumps				24/07/2021	5864	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics\OIL/FILTER	change hyd oil and filters				24/07/2021	5864	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Body\PAINT/REST	wash loader				24/07/2021	5864	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics\VALVES	tighten up slew pedal movement				24/07/2021	5864	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics\HOSES	make up

P26	Rosewood - Workshop	Hydraulics|HYD LEAKS	hyd oil leak under loader - main hoses				09/04/2021	5513	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Hydraulics|HYD LEAKS	hyd oil leak in grab - rotator				09/04/2021	5513	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Chassis|HOUSEKEEP	grease nipple missing on bottom of grab				09/04/2021	5513	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	DrCabElect|HOUSEKEEP	sunvisor needs brakes R/H side				09/04/2021		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Drivcirwl|SUSPENSION	chains front axle not attached				09/04/2021		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Rosewood Workshop	PRENTICE
P26	Albury - Workshop	Elect|WORK LIGHT	Supply LED Lamp				09/04/2021		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Albury Workshop	PRENTICE
P26	Rosewood - Workshop	VehService|AS	check over				08/04/2021	5501	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Rosewood Workshop	PRENTICE
					oil leak on dipper arm											
					hose leaking											
					remove hose fit new hose											
					top up with oil											
P26	Rosewood - Workshop	Hydraulics|HYD LEAKS	loader has hydraulic oil leak		clean off		01/04/2021	5490	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Body|FUEL TANK	fuel tank falling out call out		prep and weld fuel tankl brackets		01/04/2021	5410	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Elect|WORK LIGHT	fit new lights to outer boom				30/03/2021	5472	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Rosewood Workshop	PRENTICE
			called out to bush, fuel tank brackets broken and tank hanging down													
P26	Rosewood - Workshop	Body|DAMAGE	strapped up temporarily to allow finish off shift				30/03/2021	5468	Repair	Completed	Greenfreight Loxeine NSW	LOADPRENT	Albury	AUR	Rosewood Workshop	PRENTICE
			replace leaking hose on boom pivot													
P26	Rosewood - Workshop	Hydraulics|HYD LEAKS	next dav repair leak at boom hose				30/03/2021	5468	Repair	Completed	Greenfreight Loxeine NSW	LOADPRENT	Albury	AUR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Body|ELECT P&W	repair boom lights. Outter still not working				26/03/2021	5454	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	DrCabRep|ELECT P&W	replace lower cab light				26/03/2021	5454	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Hydraulics|OIL LEAK	check grab hoses. Looks like rotator leaking				26/03/2021	5454	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	DrCabElect|AIR CON	repair aircon system and regas				21/03/2021	5248	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Rosewood Workshop	PRENTICE
P26	Wodonga - Workshop	Workshop|MOVE ASSET	drive to cummins for parts				22/12/2020		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Wodonga Workshop	PRENTICE
					cummins Powx060690											
P26	Wodonga - Workshop	Engine|CONSUMABLE	engine fan bearing worn out		comoleted		22/12/2020		Repair	Completed	Greenfreight Loxeine NSW	LOADPRENT	Albury	AUR	Wodonwe Workshop	PRENTICE
					rapid for new hose Powx059427											
P26	Wodonga - Workshop	Hydraulics|HOSES	hydraulic hose leaking on claw		remove and replace damaged hydraulic hose and wet a soare hose		07/11/2020		Repair	Completed	Greenfreight Loxeine NSW	LOADPRENT	Albury	AUR	Wodonwe Workshop	PRENTICE
					cummins Powx058965											
					replaced water pump											
					replaced tensioner bearings											
					wash down motor											
					checked for leaks											
P26	Wodonga - Workshop	Engine|WATER PUMP	water pump needs replacing		clean uo		21/10/2020		Repair	Completed	Greenfreight Loxeine NSW	LOADPRENT	Albury	AUR	Wodonwe Workshop	PRENTICE
P26	Wodonga - Workshop	Elect|ELECT P&W	inspect starting issue - starter cables loose				21/10/2020		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Wodonga Workshop	PRENTICE
P26	Albury - Workshop	Hydraulics|RAM	fit LH lift cylinder				08/10/2020		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Workshop|CLEAN	clean up after job completion				08/10/2020		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Hydraulics|RAM	fit LH lift cylinder				08/10/2020		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Workshop|CLEAN	clean up after job completion				08/10/2020		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Albury Workshop	PRENTICE
P26	Rosewood - Workshop	DrCabElect|AIR CON	check aircon system				02/09/2020	5248	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	VehService|BS	B Service	VehService|BS	remove and reolace damaged hydraulic hose and wet a soare hose		27/08/2020	5228	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Hydraulics|DAMAGE	replace LHR leg ram top pin				26/08/2020	5205	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	DrCabRep|WIPERS	replace wiper blade/assembly with repaired original				25/08/2020	5195	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Chassis|DAMAGE	top leg pin broken		replace broken upper leg ram pin LHR		18/08/2020	5131	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Hydraulics|VALVES	joy stick in loader fell apart L/H side				14/08/2020	5060	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Engine|HOUSEKEEP	basic check over				14/08/2020	7122	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Rosewood Workshop	PRENTICE
P26	Albury - Workshop	Workshop|MOVE ASSET	meet Rosewood along Hume deliver parts				07/08/2020		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Albury Workshop	PRENTICE
					B Service											
P26	Rosewood - Workshop	VehService|BS	loader due Service	VehService|BS	replace both inner and outer air filters		30/07/2020	4973	Service	Completed	Greenfreight Loxeine NSW	LOADPRENT	Albury	AUR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Hydraulics|RAM	main lift ram bearing has 3/4 play rubbing end of ram on pin housing		LH lower boom bearing needs replacing		24/07/2020		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Hydraulics|OIL LEAK	oil leak in grab		replace hose and cross threaded filling with from hydraulink		24/07/2020		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Hydraulics|HOSES	replace all 4 hoses over handle boom pivot with Rowan from hydraulink making them on side				29/06/2020	4692	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Hydraulics|HOSES	check oil leak at handle boom, found some hoses perished				26/06/2020	4658	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Chassis|HYDRAULICS	attempted to fit missing pipe clamp, captive nut missing, will repair properly when time permits				26/06/2020	4658	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Engine|HOUSEKEEP	added 4 liters oil (by driver) to bring back to full				23/06/2020	4632	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Engine|COOL LEAKS	coolant leak		check levels and coolant leak. Found it coming out of top of overflow bottle, may have been over filled at recent service or is pressurising system. Drivers monitoring		18/06/2020	4598	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Body|MOUNTS	boom pipes bracket missing		ordered boom pipe clamps (arrived 19/6/20)		18/06/2020	4598	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Cooling|RADIATOR	Temp Running High		driver to monitor		18/06/2020	4598	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Rosewood Workshop	PRENTICE
P26	Albury - Workshop	Hydraulics|HOSES	removed hydraulic pipe clamps from de-commisioned machine and package for Rosewood				18/06/2020		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Albury Workshop	PRENTICE
P26	Rosewood - Workshop	Elect|WORK LIGHT	change light bar from top of cab to under cab				16/06/2020	4576	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Elect|WORK LIGHT	change top right light				16/06/2020	4576	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	VehService|BS	B Service	VehService|BS			16/06/2020	4576	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Rosewood Workshop	PRENTICE
			call out to bush on my way back to Rosewood													
P26	Rosewood - Workshop	Hydraulics|OIL LEAK	tghten leaking lag ram fitting to monitor				11/06/2020	4548	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Elect|WORK LIGHT	wire broken middle of boom - twitched together at moment		rewire/repair wiring at extension boom for work lights		10/06/2020	4543	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Rosewood Workshop	PRENTICE
			change hydraulic filter													
P26	Tumut - Workshop	Hydraulics|OIL/FILTER	too us with oil				20/05/2020	4419	Repair	Completed	Greenfreight Loxeine NSW	LOADPRENT	Albury	AUR	Tumut Workshoo	PRENTICE
P26	Tumut - Workshop	Body|HOUSEKEEP	wash down degrease				20/05/2020	4419	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Tumut Workshop	PRENTICE
P26	Rosewood - Workshop	Engine|HOUSEKEEP	check over loader				19/05/2020		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Hydraulics|OIL/FILTER	check hydraulics slow. Filter wouuldnt budge, will replace ASAP loader has to go to work				19/05/2020		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Hydraulics|VALVES	check hydraulic pressures seem ok				16/05/2020	4399	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Hydraulics|OIL/FILTER	replace pilot filter				16/05/2020	4399	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	DrCabElect|HEATER REP	heater switch not working		check heater operation. Turn on taps		03/05/2020	4338	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	DrCabRep|HOUSEKEEP	roof leaking		seal up "sun roof"		03/05/2020	4338	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	DrCabRep|AIR CON	aircon belt need checking		check a/c belt for slipping seems ok		03/05/2020	4338	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Body|HOUSEKEEP	check over				03/05/2020	4338	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Hydraulics|HYD LEAKS	hyd leak main boom		called out to Rippling from Tumut. Hyd oil leak. Incorrect fitting let go		29/04/2020	4319	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Rosewood Workshop	PRENTICE
					replaced incorrect fitting with proper one and test. All good											
P26	Rosewood - Workshop	Hydraulics|HYD LEAKS	dieck need cleaning oil all over		check oil level, all good		29/04/2020	4319	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	DrCabElect|RADIO	UHF not working		repair UHF wiring		29/04/2020	4319	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Body|HOUSEKEEP	clean down oil spill from yesterday				29/04/2020	4319	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Rosewood Workshop	PRENTICE
					loader presented with oil leaking from RH side main lift ram fitting											
					found blown o-ring, replaced. Fitting loaded "bent"											
					still leaked, several attemptslater I found the incorrect tappedl "fitting was used with an o-ring and it was leaking											
P26	Rosewood - Workshop	Hydraulics|OIL LEAK	hyd leak on main ram		I did not have the correct fittinw sore fitted with new o-rine until reolacement arrived		28/04/2020		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Rosewood Workshop	PRENTICE
P26	Myrtleford - Workshop	Body|PAINT/REST	wash cab and roof				24/04/2020	4302	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Engine|FUEL TANK	fuel line issue at tank				24/04/2020	4302	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Chassis|HYDRAULICS	check over hyd sys replace clamp on boom				24/04/2020	4302	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	DrCabRep|SEAT	fit seat cover				24/04/2020	4302	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Elect|BATTERY	charge truck battery				24/04/2020	4302	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics|DAMAGE	replace outer boom pipes				17/04/2020	4302	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics|HOSES	replace outer boom hoses				17/04/2020	4302	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Chassis|DAMAGE	make up and fit new boom to grab link				17/04/2020	4302	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	DrCabElect|AIR CON	repair aircon system				10/04/2020	4302	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Elect|BATTERY	replace battery				10/04/2020	4302	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Chassis|CHAS CRACK	repair grab cracks				10/04/2020	4302	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics|RAM	fit grab ram				10/04/2020	4302	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Body|PAINT/REST	paint engine cover				10/04/2020	4302	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	DrCabRep|WIPERS	repair wirings and washers				10/04/2020	4302	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	DrCabElect|ELECT P&W	fit air horn				10/04/2020	4302	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	DrCabElect|ELECT P&W	repair strobe light				10/04/2020	4302	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Elect|WORK LIGHT	fit LED light bar				10/04/2020	4302	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Elect|BATTERY	fit new battery				10/04/2020	4302	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	DrCabRep|DAMAGE	repair window guard and fit straps				10/04/2020	4302	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics|RAM	replace both main lift ram seal kits R8439				20/03/2020	4301	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics|HOSES	check and replace any worn hyd hoses				20/03/2020	4301	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics|RAM	replace RHF leg ram seals & repair all 4 leg feet make up new pins & bushes				20/03/2020	4301	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics|OIL/FILTER	replace hyd oil filter and servo filter & change hyd oil & clean out tank				19/03/2020	4301	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Body|PANELS	Make up new rear engine cover		Aldonga Engineering made cover mount new cover and paint		03/03/2020	4301	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Hydraulics|RAM	Fit seal kit to outer boom ram				03/03/2020	4301	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Chassis|HYDRAULICS	Check outer boom bushes				03/03/2020	4301	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Engine|EXHAUST	replace exhaust rain cap				29/02/2020	4301	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Myrtleford Workshop	PRENTICE
P26	Myrtleford - Workshop	Body|DAMAGE	repair walkway and reweld brackets etc.				26/02/2020	4301	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Myrtleford Workshop	PRENTICE
P26	Albury - Workshop	Workshop|MOVE ASSET	TRAVEL O & FROM WODONGA LOG YARD				22/11/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Engine|FUEL TANK	BLEED ENGINE & JUMP START				22/11/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Engine|HEATER TAP	TURNED HEATHER OFF				22/11/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Engine|HOUSEKEEP	CHECKED OVER LEVELS & OPERATION				22/11/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Workshop|MOVE ASSET	PICK UP LIGHT & ELECTICAL PARTS				22/11/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Elect|WORK LIGHT	FIT OUTER BOOM LIGHTS & RE - WIRED				22/11/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Cooling|RADIATOR	3 LITERS COOLANT				21/09/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Engine|AIR CLNR	REPLACED AIR FILTER				21/09/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Hydraulics|HYD LEAKS	REPAIRED HYD LEAK AT LIFT RAM				21/09/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Elect|ELECT P&W	REPAIRED STROBE LIGHT WIRING				21/09/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Albury Workshop	PRENTICE
P26	Albury - Workshop	VehService|BS	B SERVES	VehService|BS			21/09/2019		Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Workshop|MOVE ASSET	DEGREAED & WASHED LOADER				20/09/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Elect|WORK LIGHT	Fitted work lights		Repaired wiring		18/09/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Body|CRN/RUN/MN	grab ripping logs				17/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Body	engine door keeps falling off				17/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Hydraulics|OIL LEAK	grab rotator motor leaks				17/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Body	engine door falling open				17/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Hydraulics|OIL LEAK	rotar motor leaking				17/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Hydraulics|OIL LEAK	HYD OIL LEAK AT VALVE BANK				17/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Albury Workshop	PRENTICE
P26	Albury - Workshop	DrCabElect|RADIO	CD radio needs looking at has no service				17/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Hydraulics|RAM	outer boom ram end eye worn out. Slew is weak				17/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Body|ELECT P&W	need new hand controls				17/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Chassis|Boom	tips on grab				17/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Albury Workshop	PRENTICE
P26	Albury - Workshop	DrCabRep|DOOR LOCK	top hinge on door				17/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Hydraulics|HOSES	boom hose needs clamp				17/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Engine|FAULT CODE	Stop engine light comes on				17/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Hydraulics|HYD LEAKS	Low hydraulics pressure				17/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Hydraulics|RAM	Won't slew left or right				17/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Hydraulics|PWR STEER	Pressure very low				17/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Hydraulics|RAM	Has trouble lifting				17/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Hydraulics|HYD LEAKS	Leak in RHS main ram				17/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Engine|OIL LEAK	Using oil				17/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Engine|OIL LEAK	Oil Leak under cam				17/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Hydraulics|OIL LEAK	Main lift ram RHS leaking (hoses)				17/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Body|DAMAGE	tips on grab				17/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Elect|ELECT P&W	cab light				17/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Elect|ELECT P&W	load rack - tips on grab				17/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Albury Workshop	PRENTICE
P26	Albury - Workshop	DrCabRep|ELECT P&W	new cab lights needs				17/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Hydraulics|OIL LEAK	oil leak in boom o-ring				17/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Body|DAMAGE	tips on grab				17/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Albury Workshop	PRENTICE
P26	Albury - Workshop	DrCabElect|INST/GAUGE	temp gauge not reading right				17/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Albury Workshop	PRENTICE
P26	Albury - Workshop	DrCabElect|RADIO	needs new phone bracket for dash				17/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	AUR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Prod Howl|DOOR LOCK	need

P26	Albury - Workshop	Elect\ELECT P&W	RHS work light on main boom has loose/exposed wire keeps flicking on and off			17/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Cooling\RADIATOR	loader engine temp guage is showing very hot - just under 250 mark			17/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Elect\WORK LIGHT	LHS dipper boom light not working			17/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Elect\WORK LIGHT	RHS main boom light has loose wire and only works sometimes			17/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Body\FUEL TANK	fuel cap is leaking			17/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Hydraulics\PUMP	foot pedal for slew drive needs adusting very slow			17/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	DrCabRep\DAMAGE	front window safety screen latches are missing and only 1 left which is about to break. Fix asap held on by rope at present			17/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Body\DAMAGE	cover plate for grab rotator motor missing			17/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Engine\MOUNTS	check engine mount bolt missing of front gauge front window no grease gun			17/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Body\DAMAGE	show Rosewood and Tumut loader driver how to arease loader			17/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Cooling\RADIATOR	loader engine temp guage is showing very hot - just under 250 mark			17/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Elect\WORK LIGHT	LHS dipper boom light not working			17/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Elect\WORK LIGHT	RHS main boom light has loose wire and only works sometimes			17/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	VehService\DS	D Service Due			17/09/2019		Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Body\FUEL TANK	fuel cap is leaking			17/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Hydraulics\PUMP	foot pedal for slew drive needs adjusting/very slow			17/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	DrCabRep\DAMAGE	front window safety screen latches are missing and only 1 left which is about to break. Fix asap. Held on by rope at present			17/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Body\CHAS	cover plate for gear rotator motor missing			17/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Engine\ENG FAN	engine fan always on			17/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Hydraulics\VALVES	slew very slow			17/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Elect\WORK LIGHT	REPLACED OUTER BOOM LIGHT MOUNTS			17/09/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	VehService\BS	B Service Due	VehService\BS		17/09/2019		Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Elect\WORK LIGHT	removed and replaced load lights and replaced wiring for load lights			05/07/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Wodonga - Workshop	Workshop\MOVE ASSET	Inspected and operated slew system			28/06/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Wodonga Workshop	PRENTICE
P26	Rosewood - Workshop	Workshop\MOVE ASSET	Call out to thyne mill		Swapped with loader P25 & returned to Rosewood	27/06/2019	4227	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Hydraulics\PUMP	Slew VERY slow to right, slow to left. Would not slew to right under load.		Found bolt missing from slew pedal pivot. Replaced, adjusted & tested. *New rose joints needed*	27/06/2019	4227	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Albury - Workshop	Steering\WHEEL ALIGN	sterring doesn't feel right wonders			22/06/2019	438124	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	DrCabElect\HEATER REP	heater in truck not working			22/06/2019	438124	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Engine\ENG FAN	engine fan always on			22/06/2019	438124	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Body\TRL LEGS	passenger side front loader leg			22/06/2019	438124	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	DrCabRep\DOOR LOCK	not working door			22/06/2019	438124	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Body\HOUSEKEEP	grease loader			22/06/2019	438124	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Hydraulics	replace loader with tiger cut			22/06/2019	438124	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Hydraulics\VALVES	slew very slow			22/06/2019	438124	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	DrCabRep\WIPERS	fill windscreen wiper bottle up			22/06/2019	438124	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Rosewood - Workshop	Workshop\MOVE ASSET	called out to bush (Nixon's) major hydraulic leak			20/06/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Hydraulics\HOSES	found main centre pressure hose to ruptured			20/06/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Workshop\MOVE ASSET	could not organise one in a timely manner, returned to yard and removed serviceable hose fro P-14			20/06/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Hydraulics\HOSES	returned to bush fitted. Topped up oil. Tested, good returned to depot and cleaned oil spillage			20/06/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Workshop\CLEAN	checked over. all good			20/06/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Albury - Workshop	Engine\FUEL TANK	removed and replaced fuel primer housing			14/05/2019	4070	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Cooling\COOL LEAKS	repaire d coolant leak and replaced heater tap			14/05/2019	4070	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Engine\HOUSEKEEP	degreased and washed engine			14/05/2019	4070	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Cooling\RADIATOR	checked and topped up coolant travel to Shelly for breakdown fuel loader and replaced fuel filters ran and tested loader			14/05/2019	4070	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Engine\FUEL TANK	travel back to Albury			11/05/2019	4071	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Engine\FUEL TANK	out of fuel - bleed fule system and start weld up crack in engine cover			10/05/2019	4052	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	DrCabRep\ENG COVER	oaint eneine cover			03/05/2019	4031	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Engine\HOUSEKEEP	wash engine			03/05/2019	4031	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	VehService\BS	Service	VehService\BS		03/05/2019	4031	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Chassis\Boom	REPAIRS TO BOOM.			29/03/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Hydraulics\RAM	broken top RHS leg pin		replaced RHR top leg ram pin	14/03/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Workshop\CLEAN	unload and check over replaced radiator hose fill up with coolant wash engine			06/03/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Cooling\RADIATOR	check over			28/02/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Engine\HOUSEKEEP	degrease and washed loader and engine bay			08/02/2019	3860	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Engine\BELTS/TENS	replaced fan belt			08/02/2019	3860	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Engine\BELTS/TENS	refit and tension a/c belt			08/02/2019	3860	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	DrCabRep\DOOR LOCK	fit s/hand door strut			08/02/2019	3860	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Cooling\RADIATOR	removed and ordered radiator hoses			08/02/2019	3860	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Body\DAMAGE	complied list for major repairs			08/02/2019	3860	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Elect\START MOTR	REPLACE STARTER MOTOR			17/01/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Hydraulics\OIL LEAK	SWIVEL VALVE LEAKING FOR LEGS. bad oil leak under swel running down diff on truck			12/01/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Rosewood - Workshop	Engine\START MOTR	starter motor wont kick in sometimes			20/12/2018	3827	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Elect\WORK LIGHT	LHS light on outer boom flashes			20/12/2018	3827	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
					check over + through grease										
					investigate, clean and diagnose hydraulic leak										
					top up hyd fluid										
					loader needs repaires @ scan logging										
					rich organising repaires, main slew rotator										
P26	Rosewood - Workshop	Hydraulics\BELTS/TENS	Belts & Tensioners		leakine badly. loader not to be used	11/12/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Albury - Workshop	Air Con	Job Added From Invoice			07/12/2018	0	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Rosewood - Workshop	VehService\BS	B Service	VehService\BS		05/12/2018	3800	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
					drive to Rosewood pick up parts and pack ute ready for Tumut										
P26	Rosewood - Workshop	Body\TRL LEGS	replace R/H/R leg pin with nut		found broken R/H/R leg pin broken pull off tyres and hit out old pin replace with new pin and grease new pin before it went out do up out on the back off the pin put tyres back on tested ok	01/12/2018	2750	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Albury - Workshop	Engine	Job Added From Invoice			01/12/2018	0	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	DrivLine\GEARBOX	LHS joystick sticking			28/11/2018		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Body\DAMAGE	replaced left hand side step			15/11/2018	430375	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Tyres\DRV TYRES	front drives right			10/11/2018	430084	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Body\AIR BAG	airbags 2			10/11/2018	430084	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Body\TRL DOORS	front door right			10/11/2018	430084	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	VehService\DS	Service Due			10/11/2018	430084	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	DrCabRep\DOOR LOCK	right hand door need fixing			02/11/2018		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	DrCabElect	Job Added From Invoice broken light remove old light fit new light. Wire in			28/10/2018	0	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Rosewood - Workshop	Elect\ELECT P&W	test ok			24/10/2018	3516	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Albury - Workshop	DrCabElect\INST/GAUGE	REPLACE BROKEN STROBE LIGHT			24/10/2018	3516	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Tumut - Workshop	VehService\BS	B SERVICE	VehService\BS		18/10/2018	3479	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P26	Albury - Workshop	Elect\TRL LIGHTS	need new light on toip of cab (orange)			18/10/2018		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	DrCabRep\DOOR LOCK	need new latches to front cage of cab (window)			18/10/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Air Con\AIR CON	REPAIR AC.		REPLACED CONDENSOR FAN	16/10/2018	3455	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	VehService\BS	Service due in 60 hrs	VehService\BS		11/10/2018	3439	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Air Con\AIR CON	aircon needs gasing not real cold			09/10/2018	3414	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	DrCabRep\SEAT	needs RHS arm rest			06/10/2018	3398	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Elect\WORK LIGHT	out a boom lights flickering			06/10/2018	3398	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Rosewood - Workshop	VehService\BS	B SERVICE	VehService\BS		04/09/2018	3296	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Hydraulics\MOTOR	put gear back on rotor motor measure motor where it sit's to make sure the bolt doesn't hit refit tested ok replace leaking valve fit new second valve tested ok			28/08/2018	3253	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Hydraulics\VALVES	fit seal kit to arab hos swivel			28/08/2018	3253	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Wash\WASH	wash down grab rotator motor drive pinion brake bolt remove motor. Found bolt broken			28/08/2018	3253	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Hydraulics\MOTOR	wear requires machinine and rewelidne (wear arab motor & fit seal kit) rinlatech			25/08/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Albury - Workshop	Body\FUEL TANK	REPLACE MISSING FUEL CAP		order header tank and fuel tank cap	22/08/2018	3197	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Albury - Workshop	Cooling\COOL LEAKS	REPLACE CRACKED COOLANT RECOVERY BOTTLE.		top up coolant	22/08/2018	3197	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Hydraulics\HOSES	blown hose in between main lift boom had to wait for hose to be picked up from Tumut		refer to job#184441	17/08/2018	3200	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Hydraulics\HOSES	blown hydraulic hose		blown hose in between main lift boom had to wait for hose to be picked up from Tumut	17/08/2018	3200	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Albury - Workshop	Hydraulics\HOSES	REPLACE LEAKING HYDRAULIC HOSE @ MAIN BOOM Rotator in head not working			17/08/2018	2180J	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Rosewood - Workshop	Hydraulics\DAMAGE	as oer Job no 82624			08/08/2018	423584	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Albury - Workshop	DrCabRep\MOUNTS	needs another RHS arm rest			05/08/2018		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	DrCabRep\DAMAGE	Needs another RHS arm rest			05/08/2018		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Workshop\MOVE ASSET	pick up arm rest's from ultimate upholstery			05/08/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Rosewood - Workshop	Hydraulics\MOTOR	replace rotor motor in grab and new bottom gear that come up from Albury and check grab teeth inside to make sure nothing was broken or worn away			03/08/2018	3121	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Albury - Workshop	Hydraulics\HYD LEAKS	REPAIR HYDRAULIC LEAK @ RR LEG CYLINDER		REPLACE O'RINGS ON TOP FITTING	02/08/2018	3112	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Hydraulics\MOTOR	PINION GEAR OFF ROTATOR MOTOR BOLT BROKE.		FIT 2ND HAND PINION	02/08/2018	3112	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	VehService\BS	B SERVICE	VehService\BS	top up hyd oil 40liters repair interior light	02/08/2018	3112	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Rosewood - Workshop	DrCabElect\ELECT P&W	cab light not working		reolaced light aesv	01/08/2018	3102	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	VehService\DS	Service Due			31/07/2018	3094	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	DrCabElect\INST/GAUGE	temp gauge not reading right			31/07/2018	3094	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
					FIT RECO CYLINDER remove cylinder fit reco cylinder off shelf										
P26	Albury - Workshop	Hydraulics\HYD LEAKS	RHR LEG CYLINDER LEAKING travel Tumut fit rotator motor to P26 which was removed to keep P22 goind whilst L26 was broken down		test clean up	26/07/2018	3023	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Tumut - Workshop	Hydraulics\MOTOR	exchanged motor of P24 put radiator in loader put all covers back on and run loader for 15mins			26/07/2018	3023	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P26	Rosewood - Workshop	Cooling\RADIATOR	test ok			03/07/2018	2936	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Albury - Workshop	Cooling\RADIATOR	REMOVE RADIATOR FOR REPAIR		PICK UP RADIATOR FROM NATRAD	29/06/2018	2936	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Rosewood - Workshop	Engine\CUMTUNEUP	carry out engine tune by Cummins removed radiator to send to Natrad			29/06/2018	2936	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Cooling\RADIATOR	oreanised Tumut fraht to sick us at 4am to deliver to Wodonga			27/06/2018	2936	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Cooling\RADIATOR	make up lifting lugs to lift up radiator			27/06/2018	2936	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Cooling\RADIATOR	start radiator (weld lugs on top engine cover)			22/06/2018	2936	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Tumut - Workshop	VehService\BS	Service	VehService\BS		17/06/2018	2921	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P26	Tumut - Workshop	VehService\DS	Due for Service			14/06/2018	2921	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P26	Tumut - Workshop	DrCabRep\ELECT P&W	new cab lights needs			14/06/2018	2921	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P26	Tumut - Workshop	Hydraulics\OIL LEAK	oil leak in motor			14/06/2018	2921	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P26	Tumut - Workshop	Hydraulics\OIL LEAK	oil leak in boom o-ring			14/06/2018	2921	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P26	Tumut - Workshop	Elect\HEAD LIGHT	RHS headlight not working			13/06/2018	420557	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P26	Rosewood - Workshop	Body\DAMAGE	repair hand railing bolts were loose and three were stripped replaced with new bolts			07/06/2018	2810	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Engine\HOUSEKEEP	check oil and coolant			07/06/2018	2810	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Tumut - Workshop	Hydraulics\OIL/FILTER	top up hyd oil		top up hyd oil	30/05/2018		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P26	Tumut - Workshop	Body\DAMAGE	tips on grab			30/05/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P26	Rosewood - Workshop	Engine\OIL LEAK	bad oil leak under swel running down diff on truck			20/05/2018	2710	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Tumut - Workshop	DrivLine\TOOLBOX	bad oil leak under swel running down diff on truck			20/05/2018	2710	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P26	Tumut - Workshop	VehService\BS	Service	VehService\BS		08/05/2018	2260	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE

P26	Rosewood - Workshop	Elect\ELECT P&W	Lights on over boom loose				02/05/2018	2671	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE			
P26	Rosewood - Workshop	Engine\FAULT CODE	Stop engine light comes on				02/05/2018	2671	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE			
P26	Rosewood - Workshop	Hydraulics\HYD LEAKS	Low hydraulics pressure				02/05/2018	2671	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE			
P26	Rosewood - Workshop	Cooling\COOL LEAKS	replaced leaking coolant level sensor				02/05/2018	2671	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE			
P26	Rosewood - Workshop	Workshop\MOVE ASSET	travel back to Tumba				02/05/2018	2671	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE			
P26	Albury - Workshop	Hydraulics\HOSES	main lift ram RHS leaking (hoses)				06/04/2018	2474	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE			
P26	Albury - Workshop	Steering\STEER UNI	wont slew left or right pressure very low has trouble lifting				06/04/2018	2474	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE			
P26	Albury - Workshop	Hydraulics\HYD LEAKS	leak in RHS main ram				06/04/2018	2474	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE			
P26	Albury - Workshop	Hydraulics\HYD LEAKS	main lifting rams leaking bad				06/04/2018	2474	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE			
P26	Albury - Workshop	Hydraulics\HYD LEAKS	grab ram leaking <

P26	Albury - Workshop	Engine\BELTS/TENS	REPLACE FAN AND AC BELTS				02/06/2017	913	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Cooling\HOUSEKEEP	REPLACED OVER FLOW HOSE, RADIATOR CAP AND CLEANED OUT OVER FLOW BOTTLE.				02/06/2017	913	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Tumut - Workshop	Hydraulics\RAM	oil "hydraulic" black needs replacing				17/03/2017		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P26	Tumut - Workshop	Hydraulics\VALVES	left hand control broken				17/03/2017		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P26	Tumut - Workshop	VehService\BS	service should be due	VehService\BS			17/03/2017		Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P26	Rosewood - Workshop	DrCabRep\WINDOW REG	left hand window not going up				15/03/2017	382657	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Engine\OIL LEAK	manifold gasket leaking				15/03/2017	382657	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Tumut - Workshop	Elect\HEAD LIGHT	both headlights not working				04/03/2017	381240	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P26	Rosewood - Workshop	Elect\EJECT P&W	Left hand blinker broken/light head connection in left hand front on main lifting ram				25/02/2017	380310	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Elect\EJECT P&W	leakine belt on room not working				23/02/2017		Fault	Completed	Greenfreight Loxeine NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Tumut - Workshop	Hydraulics\HOSES	replace hydrulic hoses on boom		Tumut w/shop		15/02/2017		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P26	Tumut - Workshop	Engine\FILTERS	replace engine filters		rosewood w/shop		07/02/2017		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P26	Tumut - Workshop	Hydraulics\PUMP	check hydrulic pressures in all systems ,modify grab travel cradel		Scandinavian forestry & engineering Tumut		04/02/2017		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P26	Tumut - Workshop	Elect\HEAD LIGHT	repair head light fault		Tumut auto electric13-1-17		24/01/2017		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P26	Tumut - Workshop	Body\FUEL TANK	repair loose fuel tank		Scan forestry and engineering tumut		18/01/2017		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P26	Rosewood - Workshop	Elect\EJECT P&W	low beam left hand not working				12/01/2017	375723	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Albury - Workshop	Body\FUEL TANK	replace AUX. fuel pump		set up fuel pump to send to Rosewood		23/12/2016	373	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Hydraulics\HOSES	brackets on hydraulic pipes near door on boom. brackets on hydric pipes near door on boom				14/12/2016	373	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Hydraulics\HOSES	brackets for oil lines on boom				14/12/2016	373	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Body\EJECT P&W	cover on fuse box				14/12/2016	373	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Chassis\HOUSEKEEP	right hand leg hip pin		ordered leg pin & tag		14/12/2016	373	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Cooling\COOL LEAKS	heater (page 88655)				14/12/2016	373	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Cooling\COOL LEAKS	heat losing coolant on deck				14/12/2016	373	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
					as per attached invoice											
P26	Albury - Workshop	Chassis\CHAS CRACK	Repairs to cracked main boom.		reoaired bv wec		02/11/2016	10372	Repair	Completed	Greenfreight Loxeine NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Hydraulics\RAM	LR lag cylinder leaking				14/10/2016	372	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Tumut - Workshop	Chassis\HYDRAULICS	replace leg pin on hydrulic ram		Roddys engerneering 10-8-16		03/09/2016		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P26	Tumut - Workshop	DrCabRep\WINDSCREEN	replace windscreen glass and refit window rubber on RHS		completed by obrians glass wagga on the 16th August		18/08/2016		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P26	Tumut - Workshop	DrivLine	outer boom hydric fitting leaking				16/08/2016	195	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P26	Tumut - Workshop	DrCabElect	high & low beam switch not working				09/08/2016	369997	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P26	Tumut - Workshop	Steering	steering needs looked at stiff to the left				09/08/2016	369997	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P26	Tumut - Workshop	VehService\BS	B Service Prentice loader	VehService\BS	completed by snowy truckson the 22nd july		27/07/2016		Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P26	Tumut - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS			23/07/2016		Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P26	Rosewood - Workshop	Body	grab ripping locs				22/07/2016	19	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Body	boom rest cracked				22/07/2016	19	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Body	broken binker lens back				19/07/2016	367299	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	DrCabRep	left window not working				19/07/2016	367299	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	VehService	service near due 26 hours to go				19/07/2016	367299	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Hydraulics	hydraulic oil filter - controls slow				17/07/2016	9981	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Engine	brackets for oil lines on boom				17/07/2016	9981	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Tumut - Workshop	VehService	A Service near due in 900km				16/07/2016	367261	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P26	Tumut - Workshop	Engine\COOL LEAKS	coolant leak is worse				16/07/2016	367261	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P26	Tumut - Workshop	VehService	service due at 9833 hours				23/06/2016	9833	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P26	Tumut - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS			23/06/2016	9833	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P26	Rosewood - Workshop	Body	bracket on front boom missing				01/06/2016	362662	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Albury - Workshop	Hydraulics\VALVES	leaking grab swivel valve.		swivel valve was sent to Albury. Then taken to Myrtleford to Rinlatech to rebuild. Sent back to Rosewood to refit.		20/05/2016		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Tumut - Workshop	Hydraulics\HOSES	replace boom hoses				05/05/2016		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P26	Rosewood - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS			24/04/2016	9420	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Tumut - Workshop	Hydraulics\CONS/MABLE	replace joy stick handles				06/04/2016		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Tumut - Workshop	Elect\EJECT P&W	repair lights				30/03/2016		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Body\CHN/RUR/MN	back bracket broken				17/03/2016		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Body\SUSPENSION	back bracket towbaybay broken				17/03/2016		Fault	Completed	Greenfreight Logging NSW	RENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Tumut - Workshop	Engine\FILTERS	oil filter				17/03/2016		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Hydraulics\HOSES	replace blown hydraulic hose to slew pump				02/03/2016		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Chassis\SUSPENSION	air bag				26/02/2016	353430	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Elect\TRL LIGHTS	R/H back side light				26/02/2016	353430	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS			26/02/2016	9205	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	DrCabRep\WINDSCREEN	front window need looking at				25/02/2016	353335	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Air Con\HEATER	heater leaking coolant in cab				19/02/2016		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Body\CHN/RUR/MN	grab ripping logs				19/02/2016		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Hydraulics\HOSES	hose fitting leaking on slew				19/02/2016		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	DrCabRep\WINDSCREEN	window screen bolt				19/02/2016		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Tumut - Workshop	Hydraulics\HOSES	replace damaged hyd fitting in grab ram				19/02/2016		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Elect\EJECT P&W	front boom lights not working				17/02/2016		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Body\EJECT P&W	cover on fuse box				13/02/2016		Repair	Completed	Greenfreight Logging NSW	RENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Air Con\AIR CON	repair faulty A/C				11/02/2016		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	DrCabElect\PHONE	phone aerial				10/02/2016		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	DrCabElect\RADIO	hand pieces broken off				10/02/2016		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Elect\EJECT P&W	outer boom light has a short				10/02/2016		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Hydraulics\RAM	elbow fitting on ram leaking				10/02/2016		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Hydraulics\RAM	slew not holding in place				10/02/2016		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Air Con\AIR CON	aircon not working				09/02/2016		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Wodonga - Workshop	DrCabRep	joystick lh side coming off				02/02/2016		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Wodonga Workshop	PRENTICE
P26	Albury - Workshop	Elect\CLAIMS	work lights		completed		19/01/2016		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Elect\CLAIMS	strobe light				19/01/2016		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Chassis\CROSS MBR	weld boom support/boom		as above		13/01/2016		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Rosewood - Workshop	Engine\EXHAUST	exhaust cap		completed		24/12/2015		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Albury - Workshop	Engine\EXHAUST	replaced exhaust pipe cap				22/12/2015	9062	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
			sump plug													
P26	Rosewood - Workshop	Engine\OIL LEAK	tstc		comolated		19/12/2015		Repair	Completed	Greenfreight Loxeine NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
			filters													
P26	Rosewood - Workshop	Engine\FILTERS	tstc		comolated		16/12/2015		Repair	Completed	Greenfreight Loxeine NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
			header tank cap													
P26	Rosewood - Workshop	Cooling\RADIATOR	randalls				15/12/2015		Repair	Completed	Greenfreight Loxeine NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
			battery													
P26	Rosewood - Workshop	Elect\BATTERY	arkon		comolated		15/12/2015		Repair	Completed	Greenfreight Loxeine NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Albury - Workshop	Body	safety lever		replaced lever and fit new micro switch		12/12/2015		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Elect	strobe light		replace light		12/12/2015		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS			12/12/2015	9023	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Elect	strobe light				12/12/2015	9023	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Body	safety lever				12/12/2015	9023	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Engine	wash engine bay and hydraulic valve banks				12/12/2015	9023	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Wodonga - Workshop	DrCabRep\DOOR LOCK	door strut missing				11/12/2015		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Wodonga Workshop	PRENTICE
P26	Wodonga - Workshop	Engine	cover on motor needs replacing				11/12/2015		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Wodonga Workshop	PRENTICE
P26	Wodonga - Workshop	Hydraulics	servos sticking when operating		checked operation of levers - working ok		11/12/2015		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Wodonga Workshop	PRENTICE
P26	Albury - Workshop	Elect\BATTERY	loader had flat battery in bush. loader had flat battery		tested battery, replaced with 2nd hand from P25		08/12/2015	8882	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Rosewood - Workshop	Body\MOUNTS	z bracket		completed		25/11/2015		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
			arm rest strut													
P26	Rosewood - Workshop	DrCabRep\SEAT	randalls		co.l.eted		20/11/2015		Repair	Completed	Greenfreight Loxeine NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
			filters													
P26	Rosewood - Workshop	Engine\FILTERS	tstc		comolated		12/11/2015		Repair	Completed	Greenfreight Loxeine NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Albury - Workshop	Chassis	boom not sitting on rack properly when grab unchained		rotated grab mount 180o		11/11/2015		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS			07/11/2015	8801	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Engine\AIR CLNR	changed inner and outer				07/11/2015	8801	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	Body\LIGHTS	no revolving light				07/11/2015	8801	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	DrCabElect\HEATER REP	radio needs fixing				07/11/2015	8801	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	DrCabRep	joystick strut broken, window keeps falling out				07/11/2015	8801	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
			grab hose													
P26	Rosewood - Workshop	Hydraulics\HOSES	erved		comolated		03/11/2015		Repair	Completed	Greenfreight Loxeine NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
			boom hoses													
P26	Rosewood - Workshop	Hydraulics\HOSES	tumut hvd		comolated		31/10/2015		Repair	Completed	Greenfreight Loxeine NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Albury - Workshop	Elect\EJECT P&W	fix boom lights				27/10/2015		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	DrCabRep	rh window falling out				27/10/2015		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	DrCabElect\RADIO	radio not working in loader				27/10/2015		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Rosewood - Workshop	DrCabRep	loader window needs fixing - falling out, grease gun needs new end				23/10/2015		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Rosewood - Workshop	Elect\EJECT P&W	boom lights need fixing				23/10/2015		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
			weld boom													
P26	Rosewood - Workshop	Chassis\SUSPENSION	aldonea ene		comolated		22/10/2015		Repair	Completed	Greenfreight Loxeine NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Albury - Workshop	Chassis\HYDRAULICS	brackets broken that hold down hydraulic hoses on top of boom				20/10/2015		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	DrCabElect\RADIO	radio aerial broken behind unit				20/10/2015		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	DrCabRep\SEAT	seat can not move back or forward		seat is ok		13/10/2015		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	DrCabRep\RADIO	no bracket for UHF mic		fitted mic holder		13/10/2015		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	DrCabRep	joystick lh side coming off				13/10/2015		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	DrCabElect\RADIO	UHF not working				13/10/2015	8655	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Albury - Workshop	DrCabElect\AIR CON	a/c not working				13/10/2015	8655	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P26	Rosewood - Workshop	Engine\DAMAGE	Job Added From Invoice				09/10/2015	0	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Engine	replace sump plug and o-ring				04/10/2015	8611	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS			04/10/2015	8611	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	VehService\BS	Job Added From Invoice	VehService\BS			03/10/2015	0	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	VehService\BS	Job Added From Invoice	VehService\BS			02/10/2015	0	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Tumut - Workshop	VehService\BS	Job Added From Invoice	VehService\BS			18/09/2015	0	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P26	Rosewood - Workshop	Engine\HOUSEKEEP	Service Job Added from Invoice				16/09/2015	0	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Rosewood - Workshop	Chassis\HYDRAULICS	replace slew motor, replace hydraulic oil + filter + replace pinion gear				09/09/2015	8441	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P26	Unknown - Unknown	Engine\ENG TUNE	Service Job Added From Invoice				08/09/2015	0	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE