EquipmentName	Workshop	CodeAndSubCode	Description	Schedule	CompletionComments	DateDone	DistanceDone	Worktype	Workstate	EquipmentOwner	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
			Truck Derating (Check Gear-box Speed Sensor)													
LOAD26	Albury - Workshop	DriveLine|GEARBOX				17/04/2026	504429	Repair	Completed	Greenfreight Loxeine NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonwa Workshop	LOADER
LOAD26	Albury - Workshop	VehService|BS	VehService|BS B Service	VehService|BS		15/10/2025	504429	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
					REMOVED ALTERNATOR PULLEY. FITTED SPACER TO ALIGN PULLEY.											
LOAD26	Albury - Workshop	Elect|ALT2 DR	Align Alternator & Accessories Pullies So They Run Thru.		REPLACED BELT. CHARGED BATTERIES.	23/08/2025	504429	Repair	Completed	Greenfreight Loxeine NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonwa Workshop	LOADER
LOAD26	Albury - Workshop	Susp|AIR BAG	Replace Damaged Air Bags		REPLACED LF AIRBAG ON REAR AXLE.	23/08/2025	504429	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
LOAD26	Albury - Workshop	Engine|MOUNTS	Check Engine Mounts Repair As Required		REMOVED BROKEN PART FROM GEARBOX.	23/08/2025	504429	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
LOAD26	Albury - Workshop	Susp|BREAKDOWN	Susp|BREAKDOWN AAA TOW FROM MURRAY VALLEY HIGHWAY (SHELLY) TO WODONGA YARD Tow Asset From Koetong To Wodonga Yard.		Load 26 was missing a couple of air bags and batteries weren't charging and it was unsafe to bring down from Shelly,	23/08/2025	504429	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
LOAD26	Albury - Workshop	Susp|DAMAGE	(AAA Towne P/O:			15/08/2025	504429	Repair	Completed	Greenfreight Loxeine NSW	LOADVOLVO	Albury	ALR	PUC996	AAA TOWING SERVICE - 4	LOADER
LOAD26	Albury - Workshop	Elect|ALT	Replace alternator. Alternator Not Charging.		-on site repairs at shelly logging site, snapped alternator belt replaced, compressore will need to be replaced, pulley is warped and damaged -on site check of truck starting issue 05/08/25 alternator belt torn to pieces causing charge and start fault, new belt supplied was incorrect, returned to shop and waiting on correct equipment.	09/08/2025	504429	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER
			(Alternator Supplied By Arkon Auto Electrical P/O: T0961104) (Alternator Belt Supplied By CMV Wodonga P/O: T0961107)		-06/08/25 correct belt installed on site, vehicle had to be jumped and charged, batteries in ok condition, voltage, amp and charge test conducted, alternator working as intended											
LOAD26	Albury - Workshop	Elect|ALT2 DR	(Belt Supplied Be Tilons		-driver will need to ensure isolator is switched off when vehicle is not in use	06/08/2025	504429	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
LOAD26	Myrtleford - Workshop	Susp|AIR BAG	REPLACE LH FRONT DRIVE 2ND AIR BAG		KLM AT TIME OF REPAIR 504429	23/07/2025	504429	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Susp|AIR BAG	REPLACE RH REAR DRIVE 2ND AIR BAG		KLM AT TIME OF REPAIR 504429	23/07/2025	504429	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	VehService|AS	VehService|AS A Service	VehService|AS	KLM AT TIME OF SERVICE 504429	22/07/2025	504429	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
					REPLACED AIRBAG.											
LOAD26	Albury - Workshop	Susp|AIR BAG	TRAVEL TO AS RD SHELLEY. REPLACE RF AIRBAG.		S.McCABE.	17/07/2025	504429	Repair	Completed	Greenfreight Loxeine NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER
					repaired air leaks all around truck											
			VehService|AS		replaced front drive RH lower shocker rubbers											
			replace work light on rear of cab		repainted rear light bar											
			replace dash light globes		repaired dash lights not working											
LOAD26	Albury - Workshop	VehService|AS	replace walk way base	VehService|AS	(KLM at time of service 502696 \	20/05/2025	503858	Service	Completed	Greenfreight Loxeine NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Albury - Workshop	Workshop|MOVE ASSET	PICKED UP FROM YACKANDANDAH . DROVE TO WODONGA DEPOT. FUELLED UP.			20/05/2025	503857	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER
LOAD26	Albury - Workshop	DriveLine|UNI JOINTS	REPLACE JACK SHAFT UNI			16/05/2025	503857	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Albury - Workshop	Workshop|MOVE ASSET	pick up truck from wodonga W/S deliver back to myrtleford W/S			13/05/2025	503857	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER
LOAD26	Myrtleford - Workshop	Tyres|TP1+2	Tyres|TP1+2			17/04/2025	501057	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	BEAURDPAIRES - 3	LOADER
LOAD26	Myrtleford - Workshop	Tyres|Punct	Tyres|PUNCTURE FITTED POS 4 DRIVE			27/03/2025	501057	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	BEAUREPAIRES - 3	LOADER
					SLACK ADJUSTER											
					CUSTOMER REPORTS ON FRONT DRIVE AXLE, 2 CAM ADJUSTERS ARE NOT ADJUSTING BRAKES $4,492.52											
					* inspected front drive brakes											
					* Found LH brakes backed right off & adjuster seized, and RH brakes out of timing & adjuster not adjusting due to being stripped											
					* Lowered stabiliser legs & ballast front drive axle											
					* Unbolted & removed wheel end equipment											
					* Removed axle shafts & removed hubs											
					* Removed brake shoes											
					* Removed cover on Z Cam brak housing											
					* Found top & bottom shoe adjusters to be seized on both sides & top shoe adjusters unservicable due to stripped teeth on main adjuster											
					* Removed brake levers											
					* Unbolted & removed Z Cam tubes											
					* Unbolted & removed backing plate											
					* Removed & replaced main adjusters											
					* Refit backing plates & Z Cam tubes											
					* Installed replacement shoe adjusters in housing											
					* Installed replacement brake shoes & timed											
					* Replaced seals & refit hubs											
					* Adjusted bearings & brakes as required											
			SHAKING IN FRONT END WHEN BRAKING.		* Refit wheel end equipment											
			ALSO FRONT DRIVE AXLE Z/CAM BRAKES OUT OF TIMMING		* Aligned, adjusted & tensioned all components											
LOAD26	Myrtleford - Workshop	Brakes|BRK O/HAUL	RELINE FRONT DRIVE AXLE & REPLACE WARN Z/ CAM ADJUSTER PARTS		* Test operations - All ok. fault no lonser oresent	20/03/2025	501057	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
					BRAKES-STEER											
					WHILST CARRYING OUT REPAIRS, FOUND LH STEER BRAKE DRUM CRACKED $1,078.19											
					* Ballast axle											
					* Drained hub oil											
					* Removed oil caps & found LH cap threads unserviceable											
					* Unbolted & removed wheel end equipment											
					* Removed drums & hub assemblies											
					* Inspected brake shoes & found to be worn uneven											
					* Inspected further & found brake shoes installed incorrectly & timing incorrect											
					* Removed brake shoes											
					* Cleaned down all components & installed replacement brake shoes & timed as required											
					* Installed replacement brake drums											
					* Fit bearings & seals & refit hubs											
					* Aligned, adjusted & tensioned all components											
			RELINE LH & RH STEER BRAKES & REPLACE BOTH BRAKE DRUMS		* Refit wheel end equipment											
					* Installed replacement hub cap & refilled hub oil to specifications											
			done at 38375 kms		* Test operations - All ok, fault no longer present											
LOAD26	Myrtleford - Workshop	Brakes|BRK RELINE				20/03/2025	501057	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	PACCAR PARTS FLEET SERVICES - 3	LOADER
					AIR BAG											
					WHILST CARRYING OUT REPAIRS, FOUND LHR FRONT AIRBAG MISSING A CHUNK $179.70											
					* Disconnected all lines to airbag											
					* Unbolted & removed airbag											
					* Installed replacement airbag supplied by customer											
					* Refit all lines & components											
					* Test operations - All ok, fault no longer present											
			REPLACE FRONT AIR BAG ON REAR DRIVE AXLE		CHAIN											
LOAD26	Myrtleford - Workshop	Susp|AIR BAG	REFIT AXLE CHAIN		WHILST CARRYING OUT REPAIRS. FOUND AXLE RESTRAINING CHAIN MISSING ON LH REAR AXLE	20/03/2025	501057	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	PACCAR PARTS FLEET SERVICES - 3	LOADER
LOAD26	Myrtleford - Workshop	Tyres|FITMENT	Tyres|FITMENT - RUNOUT 3-10			19/03/2025	501057	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	BEAURDPAIRES - 3	LOADER
			CHECK ENGINE FOR MISS FIRE													
			REPLACE NUMBER 5 INJECTOR													
			TUNE ENGINE													
LOAD26	Myrtleford - Workshop	Engine|FAULT CODE	KMS 473111			23/02/2025	501057	Repair	Completed	Greenfreight Loxeine NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
			REPLACE FRONT DIFF LOWER T/ROD & BOLTS													
LOAD26	Myrtleford - Workshop	Susp|DAMAGE	KMS 473111			23/02/2025	501057	Repair	Completed	Greenfreight Loxeine NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Susp|HCV	REPLACE LH & RH DRIVE RIDE HEIGHT VALVES & ADJUST RIDE HEIGHT			17/02/2025	501057	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Steering|TIE ROD	REPLACE DRAG LINK THEADED END TIE ROD JOINT			17/02/2025	501057	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
			REPLACE FRONT DIFF VEE STAY ASM													
LOAD26	Myrtleford - Workshop	DriveLine|SUSPENSION	REPLACE REAR DIFF SWAY BAR END BUSHES			14/02/2025	501057	Repair	Completed	Greenfreight Loxeine NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Susp|AIR BAG	air bags not pumping up		found pressure protection valve above jack shaft leaking and stuck closed pulled apart to lube witch help but still leaked air replaced valve and tested all good	05/02/2025	501057	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
			REVERSE LIGHTS INSUFFICIENT.													
LOAD26	Myrtleford - Workshop	Elect|ELECT P&W	NO REV BUZZER			04/02/2025	501057	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Susp|SWAYBAR	REPLACE REAR DIFF SWAY BAR BUSHES		remove and replace rear sway bar bushes and pins	04/02/2025	501057	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Engine|EXHAUST	Engine|EXHAUST		repair exhaust leak from turbo to muffler	04/02/2025	501057	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
					REPLACE LHR UPPER & LOWER SPRING EYE BUSHES & PINS											
LOAD26	Myrtleford - Workshop	Susp|SPRING PACK	CLUNKING FROM FRONT END.		CLEAN OUT LH FUEL TANK & PICK UP	04/02/2025	501057	Fault	Completed	Greenfreight Loxeine NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	DriCabRep|WIPERS	WIPER BLADES NEED REPLACING.			04/02/2025	501057	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Elect|ELECT P&W	REGO PLATE LIGHT MISSING.			04/02/2025	501057	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Insp|ANN INSP	Insp|ANN INSP	Insp|ANN INSP	KLM at time of inspection 501057	03/02/2025	501057	PreventativeMaintenance	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	VehService|AS	VehService|AS	VehService|AS	KLM at time of service 501057	03/02/2025	501057	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
					replaced broken grab stick											
LOAD26	Myrtleford - Workshop	VehService|AS	A Service	VehService|AS	replaced cab filter	28/01/2025	488500	Service	Completed	Greenfreight Loxeine NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
			CALL OUT AFTER HOURS													
			10.30PM													
			TRAVEL TO GREENFEIGHTS YARD													
			check loader found circuit breaker is faulty. replace breake with fuse test fuse pop instatly.													
			check over wiring in fuse box ok check all exterior light													
			check light bar found rub wiring for light bar . repair wiring a. replace fuse test ok. repair wiring													
LOAD26	Albury - Workshop	Elect|ELECT P&W	for 2 boom arm lights. test all lights all ok. travel back to shoo			23/01/2025	501057	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	HAGANS AUTO ELECTRICAL - 4	LOADER
LOAD26	Albury - Workshop	Tyres|TP5+6	Tyres|TP5+6			23/01/2025	488500	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	BEAURDPAIRES - 4	LOADER
LOAD26	Albury - Workshop	Tyres|TP3+4	Tyres|TP3+4			23/01/2025	488500	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	BEAURDPAIRES - 4	LOADER
LOAD26	Albury - Workshop	Tyres|TP7+8	Tyres|TP7+8			22/01/2025	488500	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	BEAURDPAIRES - 4	LOADER
LOAD26	Albury - Workshop	Tyres|TP9+10	Tyres|TP9+10			22/01/2025	488500	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	BEAURDPAIRES - 4	LOADER
LOAD26	Wodonga - Workshop	Chassis|FIRE EXTIN	Replace Damaged Fire Fighting Pump. (Wodonga Pumps Supplied Pump P/O: T090622) Check Over & Test Fire Fighting Pump.		Replaced Fire Pump On Loader, Tested All Good	04/12/2024	488500	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
LOAD26	Wodonga - Workshop	Chassis|FIRE EXTIN	(Carburetor Supplied By Elite Mowers & Chainsaws P/O: T090091)		Travel to Shelly, checked over pump, found carburetor had been broken off, checked all other fire extinguisher's, travelled back to yard.	12/11/2024	488500	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
			Transmission Won't Select Low Range.													
LOAD26	Albury - Workshop	DriveLine|GEARBOX	(Parts Suscebd By CMV Wodonwa P/O: L0885721		Reslaced Gear-box Shuttle Valve. Test Drove All Good.	07/09/2024	488500	Repair	Completed	Greenfreight Loxeine NSW	LOADVOLVO	Albury	ALR	PUC996	CMV TRUCK & BUS - WODONGA	LOADER
					removed and replaced blown air bag recheck and retested all good											
LOAD26	Myrtleford - Workshop	Susp|AIR BAG	replace rear drive front RHS air bag		KLM at time of reaar 494340	26/07/2024	488500	Fault	Completed	Greenfreight Loxeine NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
			*RH headlight N/W													
			Fault find right side headlight not working. Check fuses.													
			Flip bonnet. Found headlight plug was not getting a good													
			connection and wires in wrong spot. Re wire with new hlk plug and test.													
LOAD26	Albury - Workshop	Elect|HEAD LIGHT	Check fhs is ok.			24/07/2024	488407	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	ARKON AUTO ELECTRICAL - 4	LOADER
LOAD26	Wodonga - Workshop	Elect|ELECT P&W	Speedo N/W, Engine Won't Rev Over 1500 rpm (Hagan's Auto Electrical P/O: WW087226)			06/07/2024	488407	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	HAGANS AUTO ELECTRICAL SERVICE	LOADER
			CLUTCH ISSUES:													
LOAD26	Wodonga - Workshop	DriveLine|CLUTCH	LIFTED BONNET TO INSPECT CLUTCH RESERVOUR. OK. BONNET LOCK JAMMED. REMOVED BASE TO RELEASE. LIFTED BAR INTO PLACE. Clutch Pedal Keeps Going Hard Every Now & Then (CMV Wodonga P/O: T087184)			04/07/2024	488407	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
LOAD26	Albury - Workshop	DriveLine|CLUTCH			Removed & cleaned clutch actuator. refitted & tested. clutch better than it was but still hard at times. ordered new clutch actuator. reolaced clutch actuator. test drove. all eood. sent back to work.	02/07/2024	488500	Repair	Completed	Greenfreight Loxeine NSW	LOADVOLVO	Albury	ALR	PUC996	CMV TRUCK & BUS - 4	LOADER
			Test Batteries (Myrtleford Auto Electrical P/O: T087158)													
LOAD26	Myrtleford - Workshop	Elect|BATTERY				29/06/2024	488407	Repair	Completed	Greenfreight Loxeine NSW	LOADVOLVO	Albury	ALR	PUC996	MYRTLEFORD AUTO ELECTRICS - 4	LOADER
			Rewire Speed Sensor & MT Data Upgrade (Arkon Auto Electrical P/O: T087155)													
LOAD26	Albury - Workshop	Elect|ELECT P&W				29/06/2024	488407	Repair	Completed	Greenfreight Loxeine NSW	LOADVOLVO	Albury	ALR	PUC996	ARKON AUTO ELECTRICAL	LOADER
					Hagans rewired and still not working											
			speedo not working		CMV inspected unable to repair on weekend											
LOAD26	Albury - Workshop	DrCabElect|VNST/GAUGE	fit seat belt alarm		Arkon received and fit seat belt alarm	18/06/2024	488407	Repair	Completed	Greenfreight Loxeine NSW	LOADVOLVO	Albury	ALR	PUC996	CMV TRUCK & BUS - 4	LOADER
LOAD26	Albury - Workshop	Engine|FUEL TANK	Customer advised that truck had stopped running		- * Customer contacted dealership breakdown technician to report breakdown * Customer advised that truck had stopped runnine * Technician sourced additional tooline * Technician travelled to breakdown site near Rosewood. NSW * Inspect to diamonse *\	18/06/2024	488407	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	CMV TRUCK & BUS - 4	LOADER
LOAD26	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			10/04/2024	488407	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
LOAD26	Wodonga - Workshop	Elect|HEAD LIGHT	NO LOW BEAM HEADLIGHTS.			10/04/2024	488407	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
LOAD26	Wodonga - Workshop	DriCabRep|WIPERS	WINDSCREEN WASHER NOT WORKING.			10/04/2024	488407	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
LOAD26	Wodonga - Workshop	VehService|CS	Service As Per Attached Checklist	VehService|CS		10/04/2024	488407	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
LOAD26	Wodonga - Workshop	Unknown	SERVICE DUE.			10/04/2024	488407	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
LOAD26	Wodonga - Workshop	DrCabElect|HOUSEKEEP	sunvisor needs brakes R/H side			22/03/2024		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
LOAD26	Wodonga - Workshop	DrCabElect|ELECT P&W	DRIVER INTERIOR LIGHT NEED SCREWING BACK ROOF.			22/03/2024		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
LOAD26	Wodonga - Workshop	Body|EXHAUST	EXH AUST VIBRATING BAD WHIEN TRAVELLING.			22/03/2024		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
LOAD26	Wodonga - Workshop	Elect|ELECT P&W	R/H REAR REVERSE LIGHT LOOSE.			21/03/2024		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
LOAD26	Albury - Workshop	Tyres|TP07	Tyre Position 7			16/03/2024		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER
LOAD26	Wodonga - Workshop	Body|HOUSEKEEP	RAKEHOE MOUNT STUFFED.7 RAKE HOE HANDLE.			23/02/2024		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
LOAD26	Wodonga - Workshop	Body|PANELS	REAR PLATE ABOVE TOW PIN NEED PUSHED IN.			23/02/2024		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
LOAD26	Wodonga - Workshop	Elect|ELECT P&W	R/H PARK LIGHT OUT.			23/02/2024		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
LOAD26	Wodonga - Workshop	DrCabRep|SEAT	REPLACE DRIVER SEAT CUSHION.			23/02/2024		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
					Speedo N/W & derating											
LOAD26	Albury - Workshop	Engine|ELECT P&W	WON'T REV OVER 1200RPM.		*Suzuiv sseed sensor	02/02/2024	488407	Fault	Completed	Greenfreight Loxeine NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER
LOAD26	Myrtleford - Workshop	Susp|AIR BAG	TCTC supply			31/01/2024	488407	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER
LOAD26	Wodonga - Workshop	DrCabElect|VNST/GAUGE	SPEEDO N/W.		REPLACED SENSOR.	30/01/2024	488407	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
LOAD26	Wodonga - Workshop	Susp|AIR BAG	REPLACED RR AIRBAG.			30/01/2024	488407	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
LOAD26	Wodonga - Workshop	Chassis	CHASSIS SPACER.		MADE CHASSIS STOPPER AND FITTED.	25/01/2024	488407	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
LOAD26	Wodonga - Workshop	Body|PANELS	Screw in loose screws on patches on bonnet			10/01/2024	485559	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
LOAD26	Myrtleford - Workshop	Chassis|EXHAUST	REPLACED MUFFLER.			05/12/2023	485494	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Tyres|TP06	REPLACE TYRE			05/12/2023		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	BEAURDPAIRES - 3	LOADER
LOAD26	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			28/11/2023	484899	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	VehService|AS	Service As Per Attached Checklist	VehService|AS		28/11/2023	484899	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER

LOAD26	Wodonga - Workshop	DrivLine/AIR LEAK	AIR LEAK WHEN DIFF LOCK ON.				25/11/2023		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
LOAD26	Wodonga - Workshop	DrCabElect\INST/GAUGE	AIR FILTER WARNING LIGHT ON DASH.		REPLACED AIR FILTER.		25/11/2023		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
LOAD26	Wodonga - Workshop	Body\PANELS	STRAIGHTEN R/H BOTTOM TANK STEP.				25/11/2023		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
LOAD26	Wodonga - Workshop	DrivLine/CLUTCH	CLUTCH SQUEAKS AND LEAKS AIR WHEN APPLIED.				25/11/2023		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
LOAD26	Albury - Workshop	DrCabElect\GPS	fit GPS & tablet				16/11/2023		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	ARKON AUTO ELECTRICAL - 4	LOADER
LOAD26	Myrtleford - Workshop	DrCabRep\SEAT	cmv supply				02/11/2023	488407	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER
LOAD26	Myrtleford - Workshop	Engine\FILTERS	Filters				02/11/2023	488407	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER
LOAD26	Wodonga - Workshop	DrCabRep\SEAT	SEAT BELT BUCKLE NEED ADJUSTMENT.		REPLACED SEAT BELT		31/10/2023	483220	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
LOAD26	Wodonga - Workshop	DrCabRep\SEAT	SEAT PUMPED UP. CANT LOWER.				31/10/2023	483220	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
LOAD26	Wodonga - Workshop	DrCabRep\SEAT	SEAT BELT LATCH NEED TO REPLACE.				31/10/2023	483220	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
LOAD26	Wodonga - Workshop	Air Con\AIR CON	A/C N/W. (TURNED HEATER TAPS OFF)				31/10/2023	483220	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
LOAD26	Wodonga - Workshop	Body\HOUSEKEEP	REPAIRED AIR HORN. CHECKED ALL FLUID LEVELS.				31/10/2023	483220	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
LOAD26	Myrtleford - Workshop	Engine\FUEL TANK	BROKEN FUEL LINE/ FUEL LEAK ON MOTOR.				05/09/2023	481514	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Tyres\TP1+2	Tyre Position 1 + 2				30/08/2023		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER
			TOP END RESET INCLUDING INJECTOR PRELOAD														
			Carry out valve adjustment as per impact procedure														
			NOTE extra time taken remove and install crane to acces under bonnet														
LOAD26	Myrtleford - Workshop	Engine	area				24/08/2023		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER
					Inspect wiring from sensor to cluster, wiring ok.												
					Check pulse up to cluster. Signal present but not very strong.												
					Switch cluster out and test. Speedo still not operational.												
					Fit VDO speedo to both speed signals & speedo worked.												
					Re-assemble vehicle and send it to CMV truck. CMV returned the												
					vehicle and let Trevor know the speed sensor was faulty, remove												
					and replace the speed sensor, test drive vehicle, ok. Speedo now												
LOAD26	Myrtleford - Workshop	DrCabElect\INST/GAUGE	CMV supply Speed sensor		workine as normal and the vehicle is no lonwer derating.		05/08/2023		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER
					CHECKED WIRING, DASH PLUGS AND FUSES. REPLACED SPEED SENSOR.												
LOAD26	Wodonga - Workshop	DrCabElect\INST/GAUGE	SPEEDO NOT WORKING.		REPAIRED AT ARKON.		04/08/2023	480173	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
LOAD26	Wodonga - Workshop	Engine\ENG TUNE	REPAIRED DEBATING ENGINE. TUNED ENGINE. (CMV)				04/08/2023	480173	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
LOAD26	Myrtleford - Workshop	Susp\Torque Rod	CMV supply parts				28/07/2023	488407	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER
LOAD26	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				22/07/2023	480048	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
			* Jacked up front axle														
			* Removed wheels														
			* Removed axle shaft and hub														
			* Checked adjuster and found top shoe adjusting as required and bottom shoe not adjusting'														
			* Removed cover and found link rod damaged and unservicable														
			* Removed and replaced link rod with supplied parts														
			* Test adjusting operations - All ok, fault no longer present														
			* Timed brake shoes														
			* Re-fit hub and adjusted bearings														
			* Re-fit axle shaft														
			* Adjusted brakes														
			* Re-fit wheels and tensioned as required														
LOAD26	Myrtleford - Workshop	Susp\AXLES	* Test all coserations - All ok. fault no lonwer onesent		RHF DRIVE S-CAM ADJUSTER FAULTY - WON'T ADJUST		22/07/2023	480048	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
			Service As Per Attached Checklist														
LOAD26	Myrtleford - Workshop	VehService\BS	TCTC FOR LO70713	VehService\BS			22/07/2023	480048	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
					* Whilst carrying out service, found steering shaft uni's worn and requiring replacement												
					* Removed covers off steering column												
					* Removed steering shaft and boot												
					* Removed and replaced uni's												
					* Re-fit shaft												
					* Secured boot and re-fit covers'												
LOAD26	Myrtleford - Workshop	Steering\UNI JOINTS	STEERING SHAFT UNI'S FOUND TO REQUIRE REPLACEMENT				22/07/2023	480048	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
					* Test operations - All ok.												
					* Supported sway bar												
					* Unbolted link bar												
					* Removed and replaced rubbers with supplied parts												
					* Re-fit link bar												
					* Fit new mounting bolts as found to be broken												
					* Tensioned as required												
LOAD26	Myrtleford - Workshop	Susp\SWAYBAR	SWAY BAR LINK BAR BROKEN				22/07/2023	480048	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
					* Whilst carrying out service, found LHR drive bottom shock mount unservicable												
					* Removed wheels off LHF drive												
					* Removed shock												
					* Repaired shock mount												
					* Re-fit mount and shock												
					* Re-fit wheels												
					* Tensioned as required												
LOAD26	Myrtleford - Workshop	Susp\SHOCK ABS	LHF DRIVE BOTTOM SHOCK MOUNT BROKEN				22/07/2023	480048	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
					* Test operation - All ok. fault no lonwer onesent												
LOAD26	Myrtleford - Workshop	Brakes\BRK CL/HAUL	CMV SUPPLY PARTS				22/06/2023	488407	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER
LOAD26	Myrtleford - Workshop	DrCabRep\DOOR LOCK	adjust RH door				20/06/2023	479318	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
			D Service As Per Attached Checklist														
LOAD26	Wodonga - Workshop	VehService\DS	Barry Maney FOR WWS79307				16/06/2023	488407	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
LOAD26	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				16/06/2023	488407	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
LOAD26	Myrtleford - Workshop	Steering\WHEEL HUB	CMV supply parts				30/05/2023		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	CMV TRUCK AND BUS PTY LTD - 3	LOADER
LOAD26	Myrtleford - Workshop	DrivLine/SHOCK ABS	replace LHR & RHR top shocker mounts and fit 2x new shockers				25/05/2023	478759	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	DrivLine/R.DIFF OIL	fit new yoke, nut and pinion seal rear diff				25/05/2023	478759	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Susp\AIR LEAK	repair air leak at airbag				25/05/2023	478759	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	DrCabRep\DOOR LOCK	inspect driver door droping				25/05/2023	478759	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Susp\SHOCK ABS	CMV supply shocker bracket				18/05/2023	488407	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER
LOAD26	Myrtleford - Workshop	Brakes\BRAKE ADJ	adjust brakes				05/05/2023	477804	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER
LOAD26	Myrtleford - Workshop	Susp\AIR BAG	RH front 2nd airbag				19/04/2023		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	DrivLine/DIFF REPMN	CMV supply parts				18/04/2023	488407	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER
LOAD26	Myrtleford - Workshop	Tyres\DRV TYRES	R/H front rear tyre need changing				12/04/2023	476805	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Tyres\DRV TYRES	RHF outer flat tyre		change flat tyre RHF outer		12/04/2023	476805	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	DrivLine/TAIL SHAFT	jack shaft falling off (loose pinion nut)				12/04/2023	476805	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Tyres\TP06	Tyre Position 6				12/04/2023		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER
LOAD26	Myrtleford - Workshop	Tyres\TP9+10	Tyre Position 9 + 10				12/04/2023		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER
LOAD26	Myrtleford - Workshop	Susp\AIR BAG	rear airbag R/H		replace RHF airbag		02/04/2023	476415	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Susp\AIR BAG	repair LHF axle chain				02/04/2023	476415	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Susp\AIR BAG	CMV SUPPLY AIRBAGS		REPLACE RHF & RHFM AIRBAG		31/03/2023	488407	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER
LOAD26	Myrtleford - Workshop	Body\HOUSEKEEP	wash down loader				23/03/2023	475860	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Susp\SHOCK ABS	repair LHR sway bar mount				23/03/2023	475860	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Elect\INDICATORS	replace LHF indicator				23/03/2023	475860	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Body\MUDGUARDS	replace RHF mudguard bracket				23/03/2023	475860	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Elect\INDICATORS	CMV Supply Parts				21/03/2023	488407	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER
LOAD26	Myrtleford - Workshop	Susp\SWAYBAR	Sway bar/Screwpin				21/03/2023	488407	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER
LOAD26	Myrtleford - Workshop	Susp\SWAYBAR	LH rear sway bar link mount broken		replace LH rear sway bar link arm bracket		16/03/2023	475486	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Albury - Workshop	DrCabElect\SELECT P&W	Int led light not working				06/03/2023	488407	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER
LOAD26	Myrtleford - Workshop	Body\HOUSEKEEP	check over				21/02/2023	474911	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Susp\AIR LEAK	airbag leak		refit airbag fitting		12/01/2023	472511	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Workshop\MOVE ASSET	drop off and pick up L-26 from Rinlatech		drop off and pick up at Rinlatech		12/01/2023	474305	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	DrCabRep\DOOR LOCK	repair door latch RH side				16/12/2022	646200	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Hydraulics\RAM	replace grab cly				13/12/2022		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Body\HOUSEKEEP	weld grab tip on				13/12/2022		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Body\HOUSEKEEP	wash down cab on truck and loader due to oil leak				13/12/2022		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Tyres\TP7+8	Tyre Position 7 + 8				09/12/2022		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER
LOAD26	Myrtleford - Workshop	Engine\BELTS/TENS	CMV supply Alternator Belt, Fan Belt and parts				08/12/2022	488407	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER
LOAD26	Myrtleford - Workshop	DrivLine/UNI JOINTS	replace jackshaft uni's				08/12/2022		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	DrivLine/UNI JOINTS	Supply Unijoint Circlip Jackshaft x 2				07/12/2022	488407	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER
LOAD26	Myrtleford - Workshop	DrivLine/TAIL SHAFT	travel to loader to remove jack shaft due to yoke falling off				03/12/2022	478494	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Tyres\DRV TYRES	change LHRD flat tyre				03/12/2022	478494	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Tyres\TP02	Tyre Position 2				16/11/2022		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER
LOAD26	Myrtleford - Workshop	Tyres\BREAKDOWN	change front RH tyre				12/11/2022	472843	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Susp\HCV	ride height valves				20/10/2022	472511	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Elect\SELECT P&W	light switch				20/10/2022	472511	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	DrCabRep\RADIO	Supply Radio				17/10/2022		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Susp\HCV	Multi Spares supply parts				06/10/2022	488407	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Brakes\BRAKE ADJ	Adjust drive brakes				01/10/2022	471853	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	DrivLine/TAIL SHAFT	replace center bearing				27/09/2022	471580	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Albury - Workshop	DrCabElect\INST/GAUGE	CMV supply Speedo Sensor				26/09/2022	488407	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER
LOAD26	Myrtleford - Workshop	Susp\SHOCK ABS	REMOVE AND REPLACE CAB SHOCKERS		inspected all good		10/09/2022	479318	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Susp\SHOCK ABS	Shock Absorber				10/09/2022		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	DrCabRep\AIR BAG	replaced RHS cab airbag				08/09/2022	471330	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	DrCabRep\AIR BAG	SUPPLY AIR TANK DRAINS & CAB AIR BAG				07/09/2022		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER
			check for fault with electric windows														
			Trace wiring and check current draw of each window														
			Diagnose faulty relay as problem														
			Remove, supply and fit 4 genuine bosch relays														
LOAD26	Myrtleford - Workshop	DrCabRep\WINDOW REG	Test ok				28/07/2022		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Tyres\TP09	puncture repair				23/07/2022		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				23/07/2022	470065	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
					repair rear diff lock												
					repaired wiring rear diff lock												
LOAD26	Myrtleford - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS	replaced bottom shocker rubbers front axle		23/07/2022	470065	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	DrCabRep\DOOR LOCK	driver door won't shut		adjust drivers door		16/07/2022	469742	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
					interior light												
LOAD26	Myrtleford - Workshop	DrCabElect\ELECT P&W	Int led light not working		fit switch to led light		16/07/2022	469742	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
					CHECK FOR FAULT WITH ELECTRIC WINDOWS.												
					CHECK FUSE AND RELAYS OK.												
					LOCATE FAULTY CONNECTION AT SWITCH PANEL.												
					REMOVE, CLEAN AND RETENSION PINS IN PLUG TO SWITCH .												
LOAD26	Myrtleford - Workshop	DrCabRep\WINDOW REG	both windows not working		#EFIT AND TEST. OK.		16/07/2022	469742	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	DrCabRep\WINDOW REG	driver side window wont go up		window issues		13/07/2022	469635	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	DrCabRep\CONSUMABLE	new R&R book				13/07/2022	469635	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Engine\BATTERY	Jump start truck				09/07/2022		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	DrCabRep\DOOR LOCK	door cable				15/06/2022	488407	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	DrCabRep\DOOR LOCK	Fit Window Switch				15/06/2022	488407	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	DrCabElect\INST/GAUGE	Ignition Switch				15/06/2022	488407	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Body\MIRRORS	fix RH mirror/LH mirror		repair mirror brackets		04/06/2022	468417	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Engine\HEATER TAP	turn heater taps on				24/05/2022	467725	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Engine\TURBO	check engine seems to have lost power				24/05/2022	467725	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	DrCabBed\RADIO	MAE supply AXIS MECHLESS BLUETOOTH MULTIMEDIA				10/05/2022	488407	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER
LOAD26	Myrtleford - Workshop	Engine\RADIATOR	Block off leaking tube, External clean and test.Intercooler,Repair damaged leaking tubes,External clean and test				07/05/2022		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Susp\AIR BAG	CMV supply airbag				04/05/2022	488407	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER
LOAD26	Myrtleford - Workshop	Engine\BELTS/TENS	Supply Fan Belt & Alternator Belt				04/05/2022	488407	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Engine\RADIATOR	leaking radiator				04/05/2022	466827	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	DrCabRep\RADIO	replace radio and truck phone				04/05/2022	466827	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Tyres\TP09	puncture repair				04/05/2022		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Body\HOUSEKEEP	MAKE AND FIT SAFTY RAILS TO TRUCK LHS				28/04/2022	466519	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Body\HOUSEKEEP	move spare tyre and signs				27/04/2022	466361	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Tyres\DRV TYRES	RHR inside drive tyre flat		replace flat tyre RHR inner drive		23/04/2022	466319	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Body\HOUSEKEEP	make up 2x new step extensions				06/04/2022	465671	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Body\PAINT/REST	paint all grab/hand rails				06/04/2022	465671	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Body\HOUSEKEEP	make up new hand rails				06/04/2022	465671	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Brakes\SLACK ADJ	REPLACE LHS BRAKE ADJUSTER		km(479318 21-6-23)		25/03/2022	479318	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Susp\SHOCK ABS	REPAIR FRONT DRIVE AXLE SHOCKER MOUNTS		inspected all good		25/03/2022	479318	Repair	Completed	Greenfreight Logging NSW	LOAD

LOAD26	Myrtleford - Workshop	Body\PANELS	bonnet damaged repair				05/03/2022 464705	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Tyres\TP1+2	supply and fit 6 tyres				02/03/2022 464500	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Tyres\TP3+4	Tyre Position 3 + 4				02/03/2022 464500	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Tyres\TP5+6	Tyre Position 5 + 6				02/03/2022 464500	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Steering\PWR STEER	replace power steering box mount bolts				23/02/2022 464205	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
						New springs and front right hanger after accident. Found steering sloppy when driving. Investigate to find steering box loose on chassis bracket . Advise Wowne										
LOAD26	Myrtleford - Workshop	Steering\WHEEL ALGN	Perform laser wheel alignment on Volvo				22/02/2022 464128	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Body\HOUSEKEEP	CMVT supplied parts Anti Roll Bar				10/02/2022 488407	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Engine	CMVT supply sump				10/02/2022 488407	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Body\WINDSCREEN	CARTWRIGHT SUPPLY PERSPEX FOR WINDOW				10/02/2022 488407	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Susp\DAMAGE	Front end damage				10/02/2022 464046	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Susp\SPRING HANG	replace RHF spring hanger				10/02/2022 464046	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Susp\SPRING PACK	inspect spring pack's for damage				10/02/2022 464046	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Engine\DAMAGE	remove and inspect sump for damage				10/02/2022 464046	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Engine\DAMAGE	replace sump				10/02/2022 464046	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Susp\SWAYBAR	replace front sway bar and bushes				10/02/2022 464046	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Engine\EXHAUST	replace exhaust flex				10/02/2022 464046	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Steering\WHEEL ALGN	send to Wodonga for wheel alignment Towed From: BRUARONG LOG SANDING Towed To: GREENFREIGTH DEPOT MYRTLEFORD				10/02/2022 464046	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Wodonga - Workshop	Engine\BREAKDOWN	AUTHORIZED BY WAYNE DELARU				10/02/2022	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
LOAD26	Myrtleford - Workshop	DrCabRep\DOOR LOCK	cable on RH door				01/02/2022 463667	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	DrCabRep\WIPERS	washers				01/02/2022 463667	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Elec\ELECT R&W	lights				12/01/2022 462230	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Hydraulics\VALVES	supply ball valve				07/01/2022	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	RINLATECH ENGINEERING-3	LOADER
LOAD26	Myrtleford - Workshop	Engine\OIL LEAK	tighten sump bolts				07/01/2022 462140	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Chassis\HOUSEKEEP	check over				07/01/2022 462140	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Chassis\PANC CONP	rear tail light bar zebra signs				07/01/2022 462140	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Chassis\EXHAUST	restrengthen exhaust stack bracket with more bolts, remove battery and tank				05/01/2022 460140	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Body\HOUSEKEEP	need grip tap on standing area behind cab			fit grip tap	17/12/2021 461759	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Engine\FUEL TANK	fuel issue not running right and not starting				07/12/2021 461040	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Engine\FUEL TANK	replace fuel pick up and return fuel lines				07/12/2021 461040	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Tyres\TP1+2	SUPPLY AND FIT 2 TYRES				02/12/2021 460897	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	DrCabElec\INST/GAUGE	odo not working			check speedo	18/11/2021 460198	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	DrivLine\AIR LEAK	check diff locks n/w			check diff locks after repairs	18/11/2021 460198	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	DrivLine\AIR LEAK	REPLACE REAR DIFF LOCK DIAPHRAM RUBBER			all ok and working	18/11/2021 460198	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Tyres\TP06	puncture repair				18/11/2021 460198	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	DrivLine\AIR LEAK	check diff locks n/w				17/11/2021	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	DrCabBeq\HEATER REP	TURN HEATER TAPS OFF			fitted new heater taps	13/11/2021 462140	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Tyres\TP09	PUNCTURE REPAIR			change RHR inner tyre	13/11/2021 459924	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Tyres\DRV TYRES	puncture RHR inner			bar	12/11/2021 459838	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Engine\BOOST HOSE	REPLACE BOTTOM BOOST HOSE AND O RING				11/11/2021 459838	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				09/11/2021 459894	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
						repaired RHR booster										
LOAD26	Myrtleford - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS		fitted LED headlamb	09/11/2021 459694	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS			08/11/2021 488407	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				08/11/2021 488407	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Elec\HEAD LIGHT	REPLACE FAULTY LED HEADLIGHT GLOBE				05/11/2021 459894	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	DrCabElec\RADIO	replace UHF handpiece (sticking)				04/11/2021 459398	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Engine\BREAKDOWN	call out and start truck				04/11/2021 459233	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	DrCabRep\ELECT R&W	wire up cap fan				26/10/2021 6150	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
						make new mount bracket										
LOAD26	Myrtleford - Workshop	Body\MIRRORS	REPLACE LH TOP MIRROR			wire in mirror light	06/10/2021 459924	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	DrCabRep\WIPERS	replace wiper inserts			replace wipers and wash truck	01/10/2021 457826	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Body\AIR LEAK	repair air leaks				30/09/2021 457762	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Workshop\ABOVE ASSET	deliver and pick up truck				30/09/2021 457762	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Workshop\ABOVE ASSET	pick up Rinlatech				30/09/2021 457762	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Engine\HOUSEKEEP	check fluids check a/c operation				24/09/2021 457530	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Air Con\AIR CON	L12339				14/09/2021 457091	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	DrCabRep\HOUSEKEEP	s/f floor mat				09/09/2021 456966	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	DrCabRep\AIR LEAK	air blower nuve n/w				09/09/2021 456966	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Engine\HOUSEKEEP	check over fluids				03/09/2021 456782	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	DrCabRep\MOUNTS	repair and adjustment to bonnet and guards				03/09/2021 456782	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	DrCabElec\INDICATORS	Replaced LH indicator base plate			replaced light backing plate	31/08/2021 456671	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Elec\WORK LIGHT	fit rear cab work light and wires up				26/08/2021 456569	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	DrCabRep\WIPERS	wiper washer need refilling				19/08/2021 456251	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Body\EXHAUST	redo bottom exhaust muffle bottom mount				14/08/2021 456068	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Body\DAMAGE	repair bonnet and LHS indicator			bonnet and LH headlight/indicator repair	11/08/2021 455880	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Body\HOUSEKEEP	degrease and wash bonnet				07/08/2021 455839	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Body\PAINT/REST	paint front bar				07/08/2021 455839	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Chassis\BULLBAR	fit upright bars to bumper bar				07/08/2021 455839	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Brakes\BRK RELINE	Reline rear drive axle				27/07/2021 455200	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Brakes\JACK PLATE	Replace LHR & RHR brake backing plates				27/07/2021 455200	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	DrivLine\SUSPENSION	rear susy bar bushes				24/07/2021 455220	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	DrivLine\SHOCK ABS	shocker rubbers				24/07/2021 455220	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Susp\DAMAGE	RH-LH front drive airbag chain's broken				24/07/2021 455220	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Engine\HOUSEKEEP	check over - check fluids				24/07/2021 455220	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	DrCabElec\INDICATORS	replace LHS cab indicator				24/07/2021 455220	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	DrCabRep\WIPERS	replace wiper blades				24/07/2021 455220	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	DrivLine\SHOCK ABS	RHR drive shocker broken				24/07/2021 455220	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	DrivLine\SUSPENSION	rear drive sway bar bushes u/s				24/07/2021 455220	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Susp\AIR BAG	replace RHF drive airbag				24/07/2021 455220	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Engine\BELTS/TENS	tighten alt belt				24/07/2021 455220	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Engine\EXHAUST	exh muffler u/s				24/07/2021 455220	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	DrCabRep\DAMAGE	holes in engine bonnet R11999				24/07/2021 455220	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Body\PAINT/REST	wash truck				24/07/2021 455220	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	DrCabRep\HOUSEKEEP	clutch rubber				24/07/2021 455220	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Body\DAMAGE	straighten rear light bar mount				24/07/2021 455220	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Insp\INT INSP	Fit Rake Hoe			make up new holder	24/07/2021 455558	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Workshop\ABOVE ASSET	pick up from Wodongs yard deliver to Myrtleford Start truck and prentice. Got steer tyre pressures checked Low PSI 85 PSI.				23/07/2021 455220	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Wodonga - Workshop	Tyres\PRES CHECK	Parked up needs for sick us.				23/07/2021 455220	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
LOAD26	Wodonga - Workshop	Body\WIPERS	Replace wiper blades.			Remove and replace wiper blades.	02/07/2021 806854	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
LOAD26	Wodonga - Workshop	Susp\AXLES	Axles				24/06/2021 455221	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
LOAD26	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				24/06/2021 455221	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
LOAD26	Wodonga - Workshop	VehService\BS	B Service As Per Attached Checklist	VehService\BS			24/06/2021 455221	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
			Inspect wiring going to plug on VGS and ensure correct connections. Remove sensor & using scan tool inspect operation. No signal being found. Inspect signal PT BCM. Found incorrect readings from from sensor clear codes & check again. Diagnose faulty													
LOAD26	Albury - Workshop	DrCabElec\INST/GAUGE	sensor. Replace & test.				04/06/2021 452846	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER
LOAD26	Rosewood - Workshop	Brakes\BRAKE ADJ	brake adjustment				23/04/2021 453100	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Rosewood - Workshop	Engine\BELTS/TENS	squealing belts - lubed belts - all ok				23/04/2021 453100	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
						TRUCK HAS A BELT SQUEAL, REPAIR AS REQUIRED $66.70										
						* Inspected & diagnosed belt squeal * Found no belts available to replace * Lubricated belts										
LOAD26	Rosewood - Workshop	Engine\BELTS/TENS	belts squealing on motor			* Repair complete	14/04/2021	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
						ADJUST BRAKES - * Inspect brake components * Adjust brakes to specification * Test braking operation * Brakes within specification * Return vehicle to service BRAKE RESULTS - LH Front: 30% LHF Mid: 30% LHR Rear: 30% RH Front: 30% RHF Mid: 30% RHR Rear: 30%										
LOAD26	Rosewood - Workshop	Brakes\BRAKE ADJ	needs brake adjust				14/04/2021	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Rosewood - Workshop	Engine\FUEL TANK	diagnose and repair fuel leak under bonnet from fuel return hose				08/04/2021 452846	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Rosewood - Workshop	DrCabElec\INST/GAUGE	odo not working				08/04/2021 452846	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
			LOWPOWER CUSTOMER REPORTS THE TRUCK WON'T REV OVER 1300RPM AND POSSIBLY HAS A SPEEDO FAULT, DIAGNOSE And REPAIR AS REQUIRED. * Inspected for derating issue. * Unable to fix, will require electrician. * Codes. * Cab controller road speed out of calibration. * Engine road speed communication error. * Engine road speed unknown fault.													
LOAD26	Albury - Workshop	DrCabElec\INST/GAUGE	* Enetne air filter pressure droo electrical fault. Carried out A service and Suspension check on (31/3/21) as per service sheets required. * Carried out A service. * Inspected for derating issue. * Unable to fix, will require electrician. * Codes. * Cab controller road speed out of calibration. * Engine road speed communication error. * Engine road speed unknown fault.				01/04/2021 452846	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER
LOAD26	Albury - Workshop	VehService\AS	* Enetne air filter pressure droo electrical fault.	VehService\AS			01/04/2021 452846	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER
LOAD26	Wodonga - Workshop	Chassis\CHAS CRACK	inspect and repair chass crack				20/03/2021	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
LOAD26	Wodonga - Workshop	Hydraulics\OIL LEAK	leaking hydraulic line on loader head, tightened line and tested all ok				15/12/2020 5370	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
LOAD26	Wodonga - Workshop	Chassis\HOUSEKEEP	take a look at the grab pin as it was falling out ended up getting it back in and put 2 roll pins in				26/11/2020	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
LOAD26	Wodonga - Workshop	Hydraulics\RAM	remove and replace LH boom lift ram			includes washing loader and cleaning w/shop	06/11/2020	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
LOAD26	Wodonga - Workshop	Hydraulics\RAM	trawel to Myrtleford to collect ram			includes fuelling up ute on way to Myrtleford	06/11/2020	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
LOAD26	Wodonga - Workshop	Susp\SWAYBAR	needs sway bar rubbers				22/10/2020	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
LOAD26	Wodonga - Workshop	Chassis\CHAS CRACK	cracked chassis LHS rear front leg of loader				22/10/2020	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
LOAD26	Wodonga - Workshop	Engine\OIL LEAK	engine sump leaking oil				22/10/2020	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
LOAD26	Wodonga - Workshop	DrivLine\SUSPENSION	rear sway bar bushes have movement				22/10/2020	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
LOAD26	Wodonga - Workshop	Body\MOUNTS	had to adjust damaged bonnet to get over				22/10/2020	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
LOAD26	Wodonga - Workshop	Susp\AIR BAG	RHR airbag has rub marks on it suggest replacing next service				22/10/2020	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
LOAD26	Wodonga - Workshop	DrCabElec\HEATER REP	Heater controls not working properly				22/10/2020	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
LOAD26	Wodonga - Workshop	DrCabElec\PHONE	Phone not working (Sim Card problem)				22/10/2020	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
LOAD26	Wodonga - Workshop	Engine\HOUSEKEEP	Engine not pulling properly on hills				22/10/2020	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
LOAD26	Wodonga - Workshop	Chassis\CHAS CRACK	chassis cracked				22/10/2020	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
LOAD26	Wodonga - Workshop	DrCabElec\PHONE	phone not working (sim card proplem)				22/10/2020	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
LOAD26	Wodonga - Workshop	Engine\HOUSEKEEP	engine not pulling properly in hills				22/10/2020	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER

LOAD26	Wodonga - Workshop	Brakes\BRK O/HAUL	brakes not good for emergency stops				22/10/2020		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
LOAD26	Wodonga - Workshop	Body\DAMAGE	air intake exposed to all elements				22/10/2020		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
LOAD26	Wodonga - Workshop	Body\DAMAGE	hole in bonnet - log rolled from stack				22/10/2020		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
LOAD26	Wodonga - Workshop	DrivLine\GEARBOX	hard to get reverse sometimes				22/10/2020		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
LOAD26	Wodonga - Workshop	Cooling\RADIATOR	replace water pump				22/10/2020		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
LOAD26	Wodonga - Workshop	Susp\AIR BAG	replaced blown airbag on the front drive axle		inspected under loader for damage		30/09/2020	452727	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
LOAD26	Wodonga - Workshop	Susp\AIR BAG	RHR airbag has rub marks on it suggest replacing next service				30/09/2020	452727	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
LOAD26	Albury - Workshop	Susp\SUSPENSION	PO FOR AIR SPRING				30/09/2020		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER
			replace speed sensor on gearbox															
LOAD26	Rosewood - Workshop	Engine\FAULT CODE	test drive. all exsed				02/09/2020	452575	Reair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
					call out to Laurell hill, truck derating no engine brakes													
					found speed sensor fault. Checked plugs and cleaned out c cleaner. No improvement													
					escort loader back to yard													
LOAD26	Rosewood - Workshop	Engine\FAULT CODE	truck derating - no speedo. No jake brake wont rev over 1500 rpms		no visual cromblems evident on oil		28/08/2020	452575	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
			replace speed sensor															
LOAD26	Rosewood - Workshop	Engine\ELECT P&W	road test. All exsed				28/08/2020	452575	Reair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Rosewood - Workshop	DrivCabRep\RADIO	re-fit and secure UHF headset				21/08/2020	451897	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
					TCTC check radiator after a shaft and tighten a hose clamp/cold leak													
LOAD26	Myrtleford - Workshop	Cooling\RADIATOR	Replace Radiator and hoses		replaced radiator and hoses		22/08/2020	451341	Reair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Engine\HOUSEKEEP	still cannot get loader stood down to replace radiator. This is going to lead to a failure				22/08/2020	451341	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	DrivLine\SUSPENSION	replaced airbag				22/08/2020	451341	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Engine\HOUSEKEEP	topped up oil in P26 3L				20/08/2020	450622	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Elect\HEAD LIGHT	Adjust headlights				20/08/2020	450622	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
			A Service, repaired wiring for RH															
			front indicator and parker. Adjusted headlights															
LOAD26	Myrtleford - Workshop	VehService\AS	tightened loose nut for rear shift bolt	VehService\AS			20/08/2020	450622	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Rosewood - Workshop	Susp\AIR BAG	airbag gone on front drive L/H side		didn't have a bag, removed and blocked off supply		15/08/2020	451005	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
			blown airbag, caused by raising legs and airbags not having air in them, bag bottoms out and deforms bag seat and it let go. Has done several now															
LOAD26	Rosewood - Workshop	Susp\BREAKDOWN	airbae rear suspension is not a good choice on loader trucks				15/08/2020	451005	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Rosewood - Workshop	Engine\HOUSEKEEP	unfold loader and top up coolant				14/08/2020	450740	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
			A Service, repaired wiring for RH															
			front indicator and parker. Adjusted headlights															
LOAD26	Rosewood - Workshop	VehService\AS	tightened loose nut for rear shift bolt	VehService\AS			13/08/2020	450668	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Rosewood - Workshop	Susp\DAMAGE	torsion bar broken off right rear side suspension				06/08/2020	450022	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Rosewood - Workshop	VehService\AS	A Service Due	VehService\AS			06/08/2020	450022	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
			unfold loader as needed and access coolant reservoir															
LOAD26	Rosewood - Workshop	Engine\HOUSEKEEP	too un coolant				25/07/2020		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Rosewood - Workshop	Body\DAMAGE	air intake exposed to all elements				24/07/2020	448544	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Rosewood - Workshop	Body\DAMAGE	hole in bonnet - log rolled from stack				24/07/2020	448544	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
			check damage to bonnet from loader															
LOAD26	Rosewood - Workshop	Body\DAMAGE	driver loe strike				24/07/2020	448800	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
			unfold loader and throw bonnet open															
LOAD26	Rosewood - Workshop	Engine\HOUSEKEEP	too un coolant. 5 liters				21/07/2020	448090	Reair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Rosewood - Workshop	Engine\HOUSEKEEP	still cannot get loader stood down to replace radiator. This is going to lead to a failure				21/07/2020	448090	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Rosewood - Workshop	DrivLine\GEARBOX	hard to get reverse sometimes				16/07/2020	447644	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Tumut - Workshop	Engine\HOUSEKEEP	check fluids on engines				16/07/2020	447644	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop	LOADER
			fabricate new safety handle															
			cut off old handle															
LOAD26	Tumut - Workshop	Body\HOUSEKEEP	weld on new once and paint				16/07/2020	447644	Reair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop	LOADER
LOAD26	Rosewood - Workshop	Cooling\RADIATOR	check and top up coolant. Need spare loader so we can replace radiator ASAP				14/07/2020		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
					replace engine brake switch													
LOAD26	Myrtleford - Workshop	Engine\JAKE BRAKE	engine brake sometimes won't work, other times cuts in and out when using going down hill		test drive - ok		14/07/2020	446966	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Rosewood - Workshop	Cooling\RADIATOR	Replace Radiator and hoses				09/07/2020		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
			unpack loader, bonnet and inspect radiator again since cleaning last week															
LOAD26	Rosewood - Workshop	Engine\COOL LEAKS	coolant accesrs to be comine out of ion between core and too tank of radiator				07/07/2020	446353	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Rosewood - Workshop	Engine\COOL LEAKS	check radiator for leaks. To monitor				29/06/2020	495557	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Rosewood - Workshop	Body\AIR LEAK	repair air leak LHS under cab				29/06/2020	495557	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Rosewood - Workshop	Susp\SWAYBAR	needs sway bar rubbers				29/06/2020	495557	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Rosewood - Workshop	Chassis\CHAS CRACK	cracked chassis LH1 rear front lag of loader				29/06/2020	495557	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job				29/06/2020	495557	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Rosewood - Workshop	VehService\AS	A Service	VehService\AS			29/06/2020	495557	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Rosewood - Workshop	Engine\FAULT CODE	engine working light coming on		check fluids. All good (Took 3 liters coolant)		18/06/2020	444447	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Myrtleford - Workshop	Engine\BELTS/TENS	Replace Fan and Alternator belts				05/06/2020	443118	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Engine\HOUSEKEEP	Replace Thermostat and Gasket				05/06/2020	443118	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Engine\COOL LEAKS	Replace water hoses as needed				05/06/2020	443118	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Engine\HOUSEKEEP	DIff locks not working		replace rear diff lock actuator diaphram		05/06/2020	443118	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Rosewood - Workshop	DrCabElec\ELEVATER REP	heater controls not working properly				04/06/2020	443118	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Rosewood - Workshop	DrCabElec\PHONE	phone not working (sim card problem)				04/06/2020	443118	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Rosewood - Workshop	Engine\HOUSEKEEP	engine not pulling properly in hills				04/06/2020	443118	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Rosewood - Workshop	Engine\JAKE BRAKE	engine brake sometimes won't work, other times cuts in and out when using going down hill				04/06/2020	443118	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Rosewood - Workshop	Body\WH L HUB	no triangle breakown reflectors				04/06/2020	443118	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Rosewood - Workshop	Brakes\BRK O/HAUL	brakes not good for emergency stops				04/06/2020	443118	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Rosewood - Workshop	DrCabElec\ELECT P&W	left widow not working				04/06/2020	443118	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Rosewood - Workshop	DrivLine\GEARBOX	check all gear shift linkages				04/06/2020	443118	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Rosewood - Workshop	Workshop\MOVE ASSET	test drive				04/06/2020	443118	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Rosewood - Workshop	Brakes\BRAKE ADJ	brake adjustment		adjust brakes		27/05/2020	442503	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Rosewood - Workshop	Chassis\CHAS CRACK	chassis cracked		crack in chassis noticed		27/05/2020	442503	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
			chain for rear and support broken eye bolt															
LOAD26	Rosewood - Workshop	Body\DAMAGE	removed old bolt measured. New one ordered				27/05/2020	442503	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
			diagnose faulty cross locks/diff lock switch															
LOAD26	Rosewood - Workshop	DrivLine\AIR LEAK	non repairable				24/05/2020	442321	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
			installed 2 toggle switches and wired them up to work as intended, ie power divider must be in for cross locks															
LOAD26	Rosewood - Workshop	DrivCabRep\ELECT P&W	now the electrics are workine the rear diff is aressurine. New diashrem ordered				24/05/2020	442321	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Tumut - Workshop	Hydraulic\OIL/FILTER	Change hydraulic filter- top up with oil				20/05/2020	4419	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop	LOADER
LOAD26	Tumut - Workshop	Body\HOUSEKEEP	Wash down degreaser				20/05/2020	4419	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop	LOADER
LOAD26	Rosewood - Workshop	Body\FUEL TANK	tighten fuel tank straps				12/05/2020	440994	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Rosewood - Workshop	Brakes\BRAKE ADJ	adjust brakes				01/05/2020	440410	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Rosewood - Workshop	Steering\HOUSEKEEP	George front end				01/05/2020	440410	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Rosewood - Workshop	Body\MOUNTS	Repair Loose Top Step On Driver Side				25/04/2020		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Myrtleford - Workshop	DrCabElec\AIR CON	service and repair aircon system				10/04/2020	439780	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Body\PAINT/REST	wash truck and clean cab		wash truck and loader		10/04/2020	439780	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Body\TOOLBOX	clean out toolbox and check tools				10/04/2020	439780	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Body\AIR LEAK	repair air leaks				10/04/2020	439780	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Brakes\BRAKE ADJ	adjust brakes				10/04/2020	439780	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Elect\DRV LIGHT	fit driving lights				10/04/2020	439780	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Brakes\AIR LEAK	replace bromes brake valve in dash				19/03/2020	439762	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Engine\ENG FAN	Replace Engine Fan Assembly R8083				05/03/2020	439736	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Engine\BELTS/TENS	Replace belt tensioner				05/03/2020	439736	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Engine\BELTS/TENS	Replace Fan and Alternator belts				05/03/2020	439736	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Engine\HOUSEKEEP	Replace Thermostat and Gasket (R8042)				05/03/2020	439736	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Engine\COOL LEAKS	Replace water hoses as needed				05/03/2020	439736	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Engine\COOL LEAKS	Replace Compressor water hose#8071				05/03/2020	439736	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Engine\BOOST HOSE	Replace Top and Bottom Boost Hoses				05/03/2020	439736	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Engine\HOUSEKEEP	Replace Fan Cowling and Rubber R8003				05/03/2020	439736	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Body\MOUNTS	Replace Radiator Mounts				05/03/2020	439736	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Engine\BELTS/TENS	replace fan pulley bearing				05/03/2020	439736	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Cooling\RADIATOR	debug radiator and inter cooler				05/03/2020	439736	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Cooling\RADIATOR	test inter cooler (R8027)				05/03/2020	439736	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Engine\HOUSEKEEP	check turbo				05/03/2020	439736	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Body\DIA&S	Wash down truck and inspect front and rear suspension				26/02/2020	439736	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Susp\SWAYBAR	Replace sway bar link arms (to long) and fit bushes and pins				22/02/2020	439736	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	DrivLine\SUSPENSION	Replace all front and rear diff T/Rod bushes				22/02/2020	439736	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	DrivLine\SUSPENSION	Fit chains to support front and rear drive axles?UT990				22/02/2020	439736	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Body\AIR LEAK	Repair air leaks				22/02/2020	439736	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Elect\AIR FITTIN	Repair lights				22/02/2020	439736	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Body\DAMAGE	Repair all body damage R8023				22/02/2020	439736	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Body\HOUSEKEEP	Fit tape to walk ways				22/02/2020	439736	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Chassis\CHAS CRACK	Requested to inspect slew system on loader. Noticed suspension not performing correctly whilst moving machine.				22/02/2020	439762	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Susp\SWAYBAR	Sway bar bushes destroyed				22/02/2020	439762	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	Body\DIA&S	wash down truck inspect front and rear suspension				21/02/2020	439728	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Myrtleford - Workshop	DrivLine\SUSPENSION	measure L27 and L26 swaybar link arms				20/02/2020	439728	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
			L27 measured at 285mm															
LOAD26	Myrtleford - Workshop	DrivLine\SUSPENSION	measured at 340mm				20/02/2020	439728	Reair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Albury - Workshop	Insp\RWC COMP	checked fluid levels. Checked for roadworthiness				19/02/2020		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER
			travel to Myrtleford															
LOAD26	Albury - Workshop	Workshop\MOVE ASSET	re-fueled				19/02/2020		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER
					REPLACED FUEL LINES FITTERS & LINES													
					REPLACED FUEL FILTERS													
					REMOVED TANK PICK-UP CHECKED FOR CRACKS & CLEANED SCREEN													
					BLED & TOOK BACK TO WORKSHOP													
					ORDERED PICK UP & REPLACED FUEL HAND LEFT PUMP													
					TESTED													
LOAD26	Albury - Workshop	Elect\FUEL TANK	WON,T START				25/11/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER
LOAD26	Albury - Workshop	Engine\BELTS/TENS	TIGHTENED BELTS				25/11/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER
LOAD26	Albury - Workshop	Air Con\AIR CON	aircon				20/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER
LOAD26	Albury - Workshop	Engine\JAKE BRAKE	engine brake leaks				20/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER
			drivers door not closing right															
LOAD26	Albury - Workshop	DrivCabRep\DOOR LOCK	hinge is bent. Door was swining in the wind at Bondo Camp				20/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER
LOAD26	Albury - Workshop	Engine\RADIATOR	truck heating up as well				20/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER
LOAD26	Albury - Workshop	Cooling\RADIATOR	truck engine is overheating - stop engine light comes on and temp guage is in the red				20/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER
			swether in cab for controls															
LOAD26	Albury - Workshop	DrCabElec\CONSUMABLE	belt not warkine				20/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER
LOAD26	Albury - Workshop	Chassis\MUDGUARDS	FIT OUTER MUDGAURDS		HOUNT MUDLAPS TO STEERS		20/09/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER
LOAD26	Albury - Workshop	Workshop\MOVE ASSET	DEGREASED & WASH TRUCK & FILL UP TRUCK				20/09/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER
LOAD26	Albury - Workshop	Engine\HEATER TAP	please turn heater taps on at Service Due in 300km				18/09/2019	419000	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER
LOAD26	Albury - Workshop	Brakes	Brake test results attached				18/09/2019	419000	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER
LOAD26	Albury - Workshop	DrCabRep\WIPERS	Replaced wiper heads & wiper washers				18/09/2019	419000	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER
LOAD26	Albury - Workshop	Elect\HEAD LIGHT	Repaired wiring to inserts to both park lights in headlight bases				18/09/2019	419000	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER
LOAD26	Albury - Workshop	Body\AIR LEAK	Repaired air leaks				18/09/2019	419000	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER
LOAD26	Albury - Workshop	Elect\INDICATORS	Repaired indicators, repaired wiring				18/09/2019	419000	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER
LOAD26	Albury - Workshop	Chassis\FIRE EXTIN	Fitted fire extinguisher bracket & extinguisher				18/09/2019	419000	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER
LOAD26	Albury - Workshop	Elect\ELECT P&W

LOAD26	Albury - Workshop	Elect|HEAD LIGHT	short in headlight (go out)						18/09/2019	419000	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	DrCabElect|ELECT P&W	cab light need refixing to roof						18/09/2019	419000	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Body|DIH&S	fire extinguisher bracket broken						18/09/2019	419000	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Steering|WHEEL ALGN	wobble in the steering						18/09/2019	419000	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	DrCabElect|RADIO	need aerial for phone						18/09/2019	419000	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
			drivers door not closing right																	
LOAD26	Albury - Workshop	DrCabReg|DOOR LOCK	hinge is bent. Door was swinine in the wind at Bondo Camp						18/09/2019	419000	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER	
LOAD26	Albury - Workshop	Body|DIH&S	LHS step on tank loose						18/09/2019	419000	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Elect|TAIL LIGHT	right hand side parker not working						18/09/2019	419000	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
			rear left hand light lens needs replacing																	
LOAD26	Albury - Workshop	Elect|DRV LIGHT	need two drivine lahts						18/09/2019	419000	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER	
LOAD26	Albury - Workshop	Elect|TAIL LIGHT	reversing light left side not working						18/09/2019	419000	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Elect|ELECT P&W	right hand rear clearance light need fixing "on tray"						18/09/2019	419000	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Engine|RADIATOR	truck heating up as well						18/09/2019	419000	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Elect|TAIL LIGHT	reversing light left side not working						18/09/2019	419000	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Elect|TAIL LIGHT	right hand rear clearance light need fixing "on tray"						18/09/2019	419000	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Cooling|RADIATOR	truck heating up as well						18/09/2019	419000	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Cooling|RADIATOR	truck heating up as well						18/09/2019	419000	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Engine|FAULT CODE	overheats and derates						18/09/2019	419000	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Elect|HEAD LIGHT	headlights need lowering to high can't see						18/09/2019	419000	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	DrCabElect|RADIO	phone is broken in cab						18/09/2019	419000	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	DrCabElect|RADIO	phone has no aerial - no reception						18/09/2019	419000	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	DrCabElect|RADIO	UHF not working in loader						18/09/2019	419000	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Elect|HEAD LIGHT	both park light bulbs blown in headlights						18/09/2019	419000	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	DrCabReg|DOOR LOCK	RHS side door seal is coming off						18/09/2019	419000	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Cooling|RADIATOR	truck engine is overheating - stop engine light comes on and temp guage is in the red						18/09/2019	419000	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Cooling|RADIATOR	motor getting hot. Buzzer came on						18/09/2019	419000	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Engine|HEATER TAP	please turn heater taps on at service due in 300km						18/09/2019	419000	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	DrCabReg|DOOR LOCK	drivers door not shutting properly						18/09/2019	419000	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	DrCabReg|DOOR LOCK	door latch needs looking at top of door						18/09/2019	419000	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Elect|DRV LIGHT	needs driving lights						18/09/2019	419000	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Body|FUEL TANK	LHS fuel tank leaking						18/09/2019	419000	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Body|FUEL TANK	steps need replacing						18/09/2019	419000	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Steering|PWR STEER	need to check steering box all over road						18/09/2019	419000	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Elect|DAMAGE	LHS headlight all broken out needs fixing						18/09/2019	419000	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Air Con|HEATER	heather not working in truck						18/09/2019	419000	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
			swether in cab for controls																	
LOAD26	Albury - Workshop	DrCabElect|CONSUMABLE	befrt not worktine						18/09/2019	419000	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER	
LOAD26	Albury - Workshop	Elect|WORK LIGHT	no night lights on deck for night time work						18/09/2019	419000	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Body|DAMAGE	door on back of motor needs replacing						18/09/2019	419000	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Body|DAMAGE	door on back of motor needs replacing						18/09/2019	419000	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Elect|WORK LIGHT	some light on loader need replacing						18/09/2019	419000	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Elect|WORK LIGHT	some light on loader need replacing						18/09/2019	419000	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Cooling|RADIATOR	truck engine is overheating - stop engine light comes on and temp guage is in the red						18/09/2019	419000	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Cooling|RADIATOR	motor getting hot. Buzzer came on						18/09/2019	419000	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	VehService|CS	C Service	VehService|CS					18/09/2019	419000	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
					Manufactured plates & modified "J" brackets to fit, modified fuel lines to suit															
LOAD26	Albury - Workshop	Body|FUEL TANK	Fitted second hand tank		Modified Lit tank steps				10/09/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER	
LOAD26	Albury - Workshop	Steering|STEER UNI	Fit steering shaft & modify boots						10/09/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER	
LOAD26	Albury - Workshop	Elect|BATTERY	Replaced batteries						10/09/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER	
LOAD26	Albury - Workshop	Susp|SHOCK ABS	Replaced all drive shocks						10/09/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER	
LOAD26	Albury - Workshop	Engine|AIR CLNR	Repaired air filter/inlet system, replaced filters						10/09/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER	
LOAD26	Albury - Workshop	Steering|HOUSEKEEP	Repaired steering column covers						10/09/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER	
LOAD26	Albury - Workshop	Workshop|MOVE ASSET	went to Hare suspension to see what s/hand tank 'j' brackets he had - none suitable						10/08/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER	
LOAD26	Albury - Workshop	Body|FUEL TANK	do fit up and measure up for mount plates to suit						10/08/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER	
LOAD26	Wodonga - Workshop	Body|FUEL TANK	Fuel tank						25/07/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER	
LOAD26	Wodonga - Workshop	Body|FUEL TANK	Fuel tank repairs		Drain tank, removed, washed up & taken to Aldonga for repairs				11/07/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER	
LOAD26	Wodonga - Workshop	Chassis|KING PIN	Kingpins						11/07/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER	
					Set up workshop for repairs.															
					Dismantled hubs, kingpins etc															
					Ordered parts															
					Assembled Front end, replaced king pins, brake lines wheel bearings & grease nipples.															
					Replaced 2 cam seals.															
					Repaired ABS sensor mounts.															
					Replaced LHR, LHF air bags, modified bottom anchors															
					Modified & fitted mud guards to steers															
LOAD26	Albury - Workshop	Body|HOUSEKEEP	check over and write up a list		Reslaced shocks. resained mounts				05/07/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER	
LOAD26	Albury - Workshop	Engine|FILTERS	replaced air filters						05/07/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER	
LOAD26	Albury - Workshop	Engine|HOUSEKEEP	tightened loose bolts						05/07/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER	
LOAD26	Albury - Workshop	Engine|COOL LEAKS	diagnosed coolant leaks, ordered parts						05/07/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER	
LOAD26	Wodonga - Workshop	Chassis|CHAS CRACK	Requested to inspect slew system on loader. Noticed suspension not performing correctly whilst moving machine.		Inspected & found cracked chassis-loose bolts in chassis stiffeners				28/06/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER	
LOAD26	Wodonga - Workshop	Susp|SHOCK ABS	missing shocks						28/06/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER	
LOAD26	Wodonga - Workshop	Susp|SWAYBAR	Sway bar bushes destroyed						28/06/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER	
LOAD26	Wodonga - Workshop	Susp|AIR BAG	Air Bags leaking						28/06/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER	
LOAD26	Wodonga - Workshop	Susp|VCV	Ride height uneven						28/06/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER	
LOAD26	Wodonga - Workshop	Body|FUEL TANK	Leaking fuel tank						29/06/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER	
LOAD26	Wodonga - Workshop	Air Con|HEATER	Inspected heater, not working		Found cabin tap not connected to controls, modified controls and tested				22/06/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER	
LOAD26	Wodonga - Workshop	Steering|HOSES	Inspected steering complaints, power steering hose blown		replaced by exced				22/06/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER	
LOAD26	Wodonga - Workshop	Steering|TIE ROD	Found L/h tie rod U/S		Tie rod replaced				22/06/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER	
LOAD26	Wodonga - Workshop	Steering|KING PIN	R/H King pin has excessive movement						22/06/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER	
LOAD26	Wodonga - Workshop	DrivLine|UNI JOINTS	Bolt missing front drive shaft yoke		Picked up parts, Replaced yoke bolts				22/06/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER	
LOAD26	Wodonga - Workshop	DrCabReg|DOOR LOCK	Inspected R/H door not closing		Repaired damaged cabin at hinges, made & fitted door stopper, repaired door skin				22/06/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER	
LOAD26	Wodonga - Workshop	Steering|UNI JOINTS	Found tight steer shaft universal joint		Lubricated for temporary use				22/06/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER	
LOAD26	Wodonga - Workshop	Susp|SWAYBAR	Replaced missing front sway bar bolt						22/06/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER	
LOAD26	Albury - Workshop	Body|MUDGUARDS	fit and modify steer guards						04/05/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER	
LOAD26	Albury - Workshop	DrCabReg|RADIO	fit phone aerial						03/05/2019	436280	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER	
LOAD26	Albury - Workshop	Body|HOUSEKEEP	wash steps and bonnet						03/05/2019	436280	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER	
LOAD26	Rosewood - Workshop	Engine|BELTS/TENS	replace drive belts						16/04/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER	
LOAD26	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job						16/04/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER	
LOAD26	Rosewood - Workshop	VehService|AS	A Service	VehService|AS					16/04/2019		Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER	
LOAD26	Albury - Workshop	Chassis|CHAS CRACK	RETURNED TO IVEKONS TO REPAIR CHASSIS CRACK						29/03/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER	
			REPLACE DNOT SIGNS		repaired side markers															
LOAD26	Albury - Workshop	Body|DAMAGE	REPLACE SIDE MARKERS		warnine plates dnot sians				01/03/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER	
LOAD26	Rosewood - Workshop	Body|MOUNTS	refit slew bolts that where keep L29 going						09/02/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER	
LOAD26	Albury - Workshop	Susp|AIR BAG	fitted airbags with heavy duty holders						25/01/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER	
LOAD26	Albury - Workshop	Engine|ENG FAN	ENGINE OVER HEATING						17/01/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER	
			travel to Batlow																	
LOAD26	Rosewood - Workshop	Susp|AIR BAG	reolace RHF axle. rear airbae						10/01/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER	
			Batlow to remove tail shaft return back to Rosewood																	
LOAD26	Rosewood - Workshop	DrivLine|TAIL SHAFT	remove seized bearine from tail shaft measure centre bearine ordered new centre bearine from Nixon's						09/01/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER	
LOAD26	Rosewood - Workshop	Engine|FAULT CODE	overheats and derates						20/12/2018	432842	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER	
LOAD26	Rosewood - Workshop	Air Con|AIR CON	a/c not working						20/12/2018	432842	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER	
LOAD26	Rosewood - Workshop	Elect|HEAD LIGHT	headlights need lowering to high can't see						20/12/2018	432842	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER	
LOAD26	Rosewood - Workshop	DrCabElect|RADIO	phone is broken in cab						20/12/2018	432842	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER	
LOAD26	Rosewood - Workshop	DrCabElect|RADIO	phone has no aerial - no reception						20/12/2018	432842	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER	
LOAD26	Albury - Workshop	DrivLine|BREADOWN	REPLACE CENTRE BEARING						16/12/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER	
LOAD26	Rosewood - Workshop	VehService|DS	D Service		D service completed				11/12/2018		Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER	
LOAD26	Rosewood - Workshop	Workshop|MOVE ASSET	Move Assets		bring vehicle to w/shop and check over				11/12/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER	
					park ready for Tumut															
					airbag bracket bent and airbag hitting the tyre															
					try to straighten bracket on the shassis with the hydraulic enapac didn't work pull pff bracket and straighten with sledge hammer refit bracket and fit airbag tested ok															
LOAD26	Rosewood - Workshop	Susp|AIR BAG	replace air bag L/H/F/M. repair bracket		return back ro Rosewood				28/11/2018		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER	
LOAD26	Albury - Workshop	DrCabReg|DOOR LOCK	drivers side door wont close						28/11/2018	431811	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER	
LOAD26	Albury - Workshop	Tyres|RETREAD	Job Added From Invoice						21/11/2018	426207	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER	
			organise airbag																	
			meet CM at Tarrevila																	
LOAD26	Tumut - Workshop	Cooling|AIR BAG	airbaes needed at Tumut for shift						16/11/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop	LOADER	
LOAD26	Rosewood - Workshop	Susp|BELTS/TENS	Belts & Tensioners		pack ute for tumut and broken sway bar bracket. Replace sway bar bracket and replace L/H/F/R air bag and tighten up loose tank step cause by tree stub and return to rosewood				16/11/2018	430500	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER	
LOAD26	Rosewood - Workshop	VehService|DS	D Service		D service completed				16/11/2018	430500	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER	
LOAD26	Albury - Workshop	VehService|AS	A SERV	VehService|AS					11/11/2018	430336	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop	LOADER	
LOAD26	Albury - Workshop	Susp|AIR BAG	REPLACE LEAKING AIR BAGS						11/11/2018	430336	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop	LOADER	
LOAD26	Albury - Workshop	DrCabReg|DOOR LOCK	REPAIR DOOR HINGES						11/11/2018	430336	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop	LOADER	
LOAD26	Albury - Workshop	Brakes	Record Check Results As Attached To This Job						11/11/2018	430336	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop	LOADER	
LOAD26	Albury - Workshop	Susp|AIR BAG	weld extension rod's to airbag's						06/11/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER	
LOAD26	Tumut - Workshop	Susp|AIR BAG	REPLACE AIR BAG						02/11/2018	429862	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop	LOADER	
LOAD26	Albury - Workshop	Frid Serv	Job Added From Invoice						26/10/2018	0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER	
			broken brake light assy																	
			source light assy (Tumut Auto elect)																	
			soldier in new assy. Test. No lights																	
			locate fuses and check. All good. Call Auto elect																	
			locate relay, brake light switch faulty switch																	
			refit panels etc																	
LOAD26	Rosewood - Workshop	Elect|BRK LIGHT	order switch						24/10/2018	428506	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER	
LOAD26	Albury - Workshop	Elect|BRK LIGHT	REPLACE BROKEN STOP/TAIL LIGHT ASSY.		NO BRAKE LIGHTS. ORDERED SWITCH				24/10/2018	428506	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER	
LOAD26	Albury - Workshop	DrCabReg|DOOR LOCK	REPLACE DOOR HINGES						24/10/2018	428506	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER	
LOAD26	Albury - Workshop	Elect|TAIL LIGHT	right hand side parker not working						18/10/2018	427388	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER	
			rear left hand light lens needs replacing																	
LOAD26	Albury - Workshop	Elect|DRV LIGHT	need two drivine lahts						18/10/2018	427388	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER	
LOAD26	Albury - Workshop	Susp|AIR BAG	LHS airbag blown						06/10/2018	426310	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER	
LOAD26	Albury - Workshop	Steering|WHEEL ALGN	wobble in the steering						06/10/2018	426310	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER	
LOAD26	Albury - Workshop	DrCabElect|RADIO	need aerial for phone						06/10/2018	426310	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER	
LOAD26	Albury - Workshop	Brakes|AIR LEAK	LEAKING RELAY VALVE						25/09/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER	
					check for air leak															
LOAD26	Albury - Workshop	Brakes|AIR LEAK	REPLACE LEAKING PRESSURE VALVE		try and get description of relay leaking				12/09/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER	
LOAD26	Rosewood - Workshop	Body|AIR LEAK	Air Leak/s		repair air leak under				11/09/2018	426801	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER	
LOAD26	Rosewood - Workshop	DrCabElect|ELECT P&W	Electrical Parts & Wiring		repair cab light				11/09/2018	426801	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER	
LOAD26	Rosewood - Workshop	Susp|SUSPENSION	Suspension		welded U bolt on A frame fortow chasin				11/09/2018	426801	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER	
LOAD26	Rosewood - Workshop	Body|DAMAGE	Damaged Equipment		check tank steps				11/09/2018	426801	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER	
LOAD26	Rosewood - Workshop	Cooling|COOL LEAKS	coolant leak						04/09/2018	425312	Repair	Completed	Greenfreight Logging NSW	LOADVOL

LOAD26	Rosewood - Workshop	Tyres\DRV TYRES	change drive tyres soun on rim					09/08/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
					REPLACE ALT, BATTERIES AND BELTS.														
					Flat batteries														
					not charging replace belts/fan and alt														
			FLAT BATTERIES		remove and fit alt. replace batteries														
LOAD26	Albury - Workshop	Elect\BATTERY	NOT CHARGING		repair broken wires and alt and batterv			08/08/2018	423817	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
					repair interior light														
LOAD26	Rosewood - Workshop	DrCabElect\ELECT P&W	cab light not working		reolaced assv			01/08/2018	423450	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
					REPLACED SWAY BAR														
					pack and travel Tumut														
					remove broken sway bar														
					fit supplied bar														
					pack up														
LOAD26	Albury - Workshop	Susp\SUSPENSION	REPLACE BROKEN FRONT SWAY BAR AND LINK ARMS		return to Rosewood			20/07/2018	422753	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Susp\AIR BAG	REPLACE LHF AIR BAG		move vehicle into workshop, support chassis using prentice, remove airbag, fit new airbag LHF, reconnect air line, run up and check over all ok, pack up tooling and complete paperwork			11/07/2018	422248	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Elect\HEAD LIGHT	NO LOW BEAM					08/07/2018	421716	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
			Carry Out Repair Request																
			inspect unoperational headlights, found mud building up on wiring loom																
LOAD26	Tumut - Workshop	Elect\ELECT P&W	clean and reconnect alue and cable tie wirine loom up					08/07/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop		LOADER
LOAD26	Albury - Workshop	Engine\EXHAUST	REFIT ELBOW BACK INTO MUFFLER					07/07/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Tumut - Workshop	Engine\EXHAUST	move vehicle into workshoo. refit exhaust elbow into muffler. re-secure clamo. run ue and check over all ok. Droo vehicle back at deoot eack ua tooline					07/07/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop		LOADER
LOAD26	Rosewood - Workshop	DrCabElect\ELECT P&W	light in cab not working					04/07/2018	421376	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Rosewood - Workshop	DrCabRep\AIR LEAK	air leak under cab					04/07/2018	421376	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Rosewood - Workshop	DrCabRep\ELECT P&W	lights in cab					04/07/2018	421376	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Rosewood - Workshop	Elect\HEAD LIGHT	L/H headlight blinker looses		secure L headlight assy			04/07/2018	421376	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Rosewood - Workshop	Elect\ELECT P&W	2 lights in cab					04/07/2018	421376	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
			air leak - diff leaks on																
LOAD26	Rosewood - Workshop	Air Con\OIL LEAK	air leak under cab					04/07/2018	421376	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Rosewood - Workshop	Elect\ELECT P&W	L/H headlight loose		secure L headlight assy			04/07/2018	421376	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Rosewood - Workshop	DrCabRep\AIR LEAK	air leak under cab					04/07/2018	421376	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Rosewood - Workshop	Engine\EXHAUST	clamp on slack leaking					04/07/2018	421376	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Rosewood - Workshop	Brakes\BOOSTER	repair air leak at RR booster					04/07/2018	421376	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Rosewood - Workshop	Hydraulic\VALVES	replaced power divider cylinder rubber					04/07/2018	421376	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Rosewood - Workshop	Steering\PWR STEER	replace power steering hose					04/07/2018	421376	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Rosewood - Workshop	Engine\EXHAUST	rise the muffler box higher to clear the water tank					26/06/2018	421376	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Rosewood - Workshop	Engine\EXHAUST	replace broken exhaust muffler					28/06/2018	421376	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Rosewood - Workshop	Tyres	Job Added From Invoice					27/06/2018	0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Rosewood - Workshop	Susp\AIR FITTIN	replace leaking valve near air tank test ok					20/06/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job					17/06/2018	421021	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop		LOADER
LOAD26	Tumut - Workshop	VehService\AS	Service	VehService\AS				17/06/2018	421021	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop		LOADER
LOAD26	Tumut - Workshop	Elect\ELECT P&W	left hand light not working					14/06/2018	420706	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop		LOADER
LOAD26	Tumut - Workshop	DrCabRep\AIR LEAK	air leak under cab					14/06/2018	420706	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop		LOADER
LOAD26	Tumut - Workshop	DrCabElect\RADIO	phone aerial need fixing (been long time)					14/06/2018	420706	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop		LOADER
LOAD26	Tumut - Workshop	Engine\JAKE BRAKE	engine brake leaks					14/06/2018	420706	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop		LOADER
LOAD26	Tumut - Workshop	Engine\EXHAUST	clamp on slack leaking					14/06/2018	420706	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop		LOADER
LOAD26	Tumut - Workshop	VehService\AS	Due for Service	VehService\AS				14/06/2018	420706	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop		LOADER
LOAD26	Rosewood - Workshop	Susp\SUSPENSION	replace R/H/S suspension bracket					08/06/2018	420438	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Rosewood - Workshop	Susp\SUSPENSION	replace L/H/S suspension bracket					07/06/2018	420426	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Rosewood - Workshop	Body\DR&S	repair fire extinguisher bracket					07/06/2018	420426	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Rosewood - Workshop	Body\AIR LEAK	diff lock air leak					07/06/2018	420426	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Rosewood - Workshop	Body\AIR LEAK	repair air leak near air tank					07/06/2018	420426	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
			broken suspension mount																
LOAD26	Rosewood - Workshop	Susp\SUSPENSION	no parts. Oreantoe truck/loader to be left at Bondo. Receive photo's of broken components					06/06/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Wodonga - Workshop	Body\DR&S	fire extinguisher bracket broken					05/06/2018	419854	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop		LOADER
			air leak - diff leaks on																
LOAD26	Wodonga - Workshop	Air Con\OIL LEAK	air leak under cab					05/06/2018	419854	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop		LOADER
LOAD26	Wodonga - Workshop	Brakes\BRAKE ADJ	brakes					05/06/2018	419854	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop		LOADER
LOAD26	Wodonga - Workshop	Steering\ELECT P&W	L/H headlight loose					05/06/2018	419854	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop		LOADER
LOAD26	Wodonga - Workshop	Hydraulic\F DIFF OIL	sway bar					05/06/2018	419854	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop		LOADER
LOAD26	Tumut - Workshop	Tyres	Job Added From Invoice					04/06/2018	0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop		LOADER
LOAD26	Tumut - Workshop	Tyres\FITMENT	Job Added From Invoice					04/06/2018	0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop		LOADER
LOAD26	Tumut - Workshop	Tyres\RETREAD	Job Added From Invoice					04/06/2018	0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop		LOADER
LOAD26	Tumut - Workshop	Elect\HEAD LIGHT	replace R headlight assy					30/05/2018	418891	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop		LOADER
LOAD26	Tumut - Workshop	Elect\HEAD LIGHT	replace L headlight globe					30/05/2018	418891	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop		LOADER
LOAD26	Tumut - Workshop	Body\AIR LEAK	repair air leak		repair air leak at hot line hose			30/05/2018	418891	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop		LOADER
LOAD26	Tumut - Workshop	Elect\HEAD LIGHT	short in headlight (go out)					30/05/2018	418891	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop		LOADER
LOAD26	Tumut - Workshop	Elect\HEAD LIGHT	R/H headlights full of dust					30/05/2018	418891	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop		LOADER
LOAD26	Tumut - Workshop	Workshop\MOVE ASSET	pack and travel to Tumut					30/05/2018	418891	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop		LOADER
LOAD26	Tumut - Workshop	Body\DAMAGE	replace rivets in dnot sign					30/05/2018	418891	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop		LOADER
LOAD26	Rosewood - Workshop	Elect\ELECT P&W	2 lights in cab					20/05/2018	418051	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Tumut - Workshop	DrCabElect\ELECT P&W	2 lights in cab					20/05/2018	418051	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop		LOADER
LOAD26	Tumut - Workshop	Elect\HEAD LIGHT	short in headlight (go out)					18/05/2018	417738	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop		LOADER
LOAD26	Tumut - Workshop	Elect\HEAD LIGHT	R/H headlights full of dust					18/05/2018	417738	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop		LOADER
LOAD26	Rosewood - Workshop	Susp\SWAYBAR	Broken sway bar					16/05/2018	417416	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Rosewood - Workshop	Workshop\MOVE ASSET	Travel to Tumut - replave broken sway bar					16/05/2018	417416	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
			Pick up parts at TAE for coolent sensor (plug)																
LOAD26	Rosewood - Workshop	Workshop\MOVE ASSET	Tumut hydraulics fittines for T324					16/05/2018	417416	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Rosewood - Workshop	Susp\AIR BAG	left hand drive airbag					14/05/2018	2436	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Rosewood - Workshop	Elect\ELECT P&W	thermostat					14/05/2018	2436	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Rosewood - Workshop	Air Con\AIR CON	aircon					14/05/2018	2436	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Rosewood - Workshop	VehService\AS	Service	VehService\AS				14/05/2018	2436	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Rosewood - Workshop	Workshop\MOVE ASSET	Travel to Tumut					10/05/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Rosewood - Workshop	Susp\SWAYBAR	broken sway bar					10/05/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Rosewood - Workshop	Susp\SUSPENSION	check over rear suspension of L26 and seen what parts we require to repair					10/05/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Rosewood - Workshop	Workshop\MOVE ASSET	get parts from Tumut hydraulics and Tumut forest centre					10/05/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Rosewood - Workshop	Elect\DRV LIGHT	RHS driving light - wire got chopped					02/05/2018	416991	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Rosewood - Workshop	Body\AIR LEAK	Air leak under RHS fuel tank					02/05/2018	416991	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
			Right door not shutting																
LOAD26	Rosewood - Workshop	DrCabRep\DOOR LOCK	Adiust stricker and erease.					19/04/2018	415922	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
			Eng derating																
			Locate broken wiring, open sensor																
LOAD26	Rosewood - Workshop	Engine\FAULT CODE	Remove loom for repair					17/04/2018	415922	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
			fuel tank leaking																
			bring truck into workshop																
			drain fuel tank. Remove hoses and remove tank straps																
			remove tank and degrease. Wash down																
			sent to Roddey's eng for repair																
LOAD26	Rosewood - Workshop	Engine\FUEL TANK	refit tank and transfer fuel test ok					17/04/2018	415922	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
			engine derating																
			locate broken wiring at speed sensor																
LOAD26	Rosewood - Workshop	Engine\FAULT CODE	remove loom for repair					17/04/2018	415922	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Rosewood - Workshop	Susp\SWAYBAR	REPLACE BROKEN RH TOP SWAY BAR MOUNT		replace RR broken sway bar mount			23/03/2018	415330	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Tumut - Workshop	Tyres\STEER TYRE	Job Added From Invoice					20/03/2018	414958	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop		LOADER
LOAD26	Tumut - Workshop	Tyres\FITMENT	Job Added From Invoice					20/03/2018	414958	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop		LOADER
LOAD26	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job					18/03/2018	414955	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop		LOADER
LOAD26	Tumut - Workshop	VehService\AS	A Service	VehService\AS				18/03/2018	414955	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop		LOADER
LOAD26	Albury - Workshop	Workshop	Job Added From Invoice					17/03/2018	0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Rosewood - Workshop	Susp\SUSPENSION	Replace link arm for suspension					15/03/2018	414543	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Rosewood - Workshop	Body\MOUNTS	Repair step		refer to job#160086			15/03/2018	414543	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Rosewood - Workshop	Body\MOUNTS	Fix Step		repair step			15/03/2018	414543	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
			Wheel Stud.																
LOAD26	Rosewood - Workshop	Tyres\DAMAGE	Travel to Tumut and rolace wheel stud					13/03/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Rosewood - Workshop	Susp\SWAYBAR	travel to S ways. Replaced missing sway bar rubber					07/03/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Albury - Workshop	Engine\FAULT CODE	ENGINE DERATING					01/03/2018	412662	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Hydraulic\HOSES	tie-down hyd hose to get truck into w/shop					01/03/2018	412662	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Engine\FAULT CODE	fit new diagnose/wiper stalk to access codes					01/03/2018	412662	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
			find code for vss active. Trace wiring and find broken wire at vss plug. Repair wiring																
LOAD26	Albury - Workshop	Engine\ELECT P&W	have driver test drive. All ok					01/03/2018	412662	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Susp\SUSPENSION	LOOSE 'U' BOLTS/ TIGHTEN ALL 'U' BOLTS ON STEER.					01/03/2018		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Body\WS\SKEEP	TIGHTEN TANK STEP					01/03/2018	412662	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Susp\SHOCK ABS	REFIT SHOCKER AND RUBBERS.					01/03/2018	412662	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
			REPLACE BROKEN SUSPENSION BRACKET.																
LOAD26	Albury - Workshop	Susp\SUSPENSION	REPLACED AIR BAG					28/02/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
			failed air bag																
			airbag x1																
			airbag top bracket x1																
LOAD26	Tumut - Workshop	Susp\AIR BAG	B&B160389					26/02/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop		LOADER
LOAD26	Rosewood - Workshop	Susp\AIR BAG	RHS rear airbag (big hose)					24/02/2018	412526	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Rosewood - Workshop	Elect\HEAD LIGHT	L/H headlight blinker looses					24/02/2018	412526	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Albury - Workshop	Engine\AIR CLNR	A/ HOUSING U/S. ORDER NEW HOUSING TO BE FITTED.					22/02/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Susp\SWAYBAR	REAR SWAYBAR BOLTS BROKEN U/S		replace bottom suspension bolt in sway bar broken bolts			21/02/2018	411902	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Body\MUDGUARDS	reattach R/H mudflap					21/02/2018	411902	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Susp\AIR BAG	RR AXLE FRONT AIR BAG BLOWN		REPLACED AIR BAG			20/02/2018	411809	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Susp\AIR BAG	RR AXLE FRONT AIR BAG BLOWN		REPLACED AIR BAG			20/02/2018	411809	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Chassis\CHAS CRACK	SENT TRUCK TO NIXONS WAGGA TO HAVE CHASSIS REPAIRED					15/02/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
					Travel to Tumut - Pick up hub. Return to Tumba. Wash up hub. Knock out bearrings. Remove hole studs. Wrong bearings supplied by CMU. They delivered correct ones. Press in bearings using old press frame. Nich's Enerpac unit. Re fit studs. Pack and														
					Travel to Tumut. Replaced brings, fit hub. Return to Tumba.														
					Drop into Tumut Depot - Catch up with Phil.														
			LEAKING HUB SEAL																
LOAD26	Albury - Workshop	DrvLine\OIL LEAK	FAILED WHEEL BEARING		Resolaced bearinas in hub.			07/02/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Body\MIRRORS	REPLACED RH MIRROR ASSY.		ENTRW 71012			04/02/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	VehService\AS	A SERVICE	VehService\AS	INCLUDE WORKS DONE ON #71320			04/02/2018		Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Brakes	Record Check Results As Attached To This Job					04/02/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Rosewood - Workshop	Susp\SHOCK ABS	front drive shock rubbers					03/02/2018	412244	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Tumut - Workshop	Tyres	Job Added From Invoice					03/02/2018	0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop		LOADER
LOAD26	Tumut - Workshop	Tyres\FITMENT	Job Added From Invoice					03/02/2018	0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop		LOADER
LOAD26	Tumut - Workshop	Tyres\RETREAD	Job Added From Invoice					03/02/2018	0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop		LOADER
LOAD26	Albury - Workshop	DrvLine\OIL LEAK	inner drive seal leaking					02/02/2018	410809	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Body\MIRRORS	driver side mirror					02/02/2018	410809	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	DrCabElect\ELECT P&W	light in cab not working					02/02/2018	410809	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Body\MIRRORS	REPLACE BROKEN MIRRORS					30/01/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Rosewood - Workshop	Brakes\BOOSTER	Brake adjustment		Tightened RF booster			26/01/2018	193765	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
			brake adjust																
LOAD26	Rosewood - Workshop	Brakes\BOOSTER	tighten RF booster					26/01/2018	193765	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Albury - Workshop	Cooling\RADIATOR	check radiator heating up					24/01/2018	409365	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	VehService\AS	A Service Due at 410000	VehService\AS				24/01/2018	409365	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		L

LOAD26	Albury - Workshop	DrCabElect/BWC COMP	no horn						24/12/2017	405098	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Chassi/FIRE EXTIN	pass ok no date tag						24/12/2017	405098	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	DriveLine/TAIL SHAFT	center bracing rubber worn						24/12/2017	405098	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Chassi/SUSPENSION	RHF steer shock leaking, RHD drive shock lower						24/12/2017	405098	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Brakes	Record Check Results As Attached To This Job						24/12/2017	405098	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Engine/COMPRESSOR	AIR COMPRESSOR FAILED						20/12/2017	405140	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
			head gasket on air compressor leaking																			
LOAD26	Albury - Workshop	VehService	travel to Lower Bare Rd. Daewoo compressor. Removed and returned to Rosewood. Order parts						20/12/2017	405140	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Workshop/AIR BAG	sick uo parts. Travel to truck. Fit compressor and drier. Test. Get ese. To oo. tems all ok. Pack us truck and loader sack us tool trawel back to Rosewood						20/12/2017	405140	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Rosewood - Workshop	DrCabElect/AIR CON	aircon not working						12/12/2017	404061	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Rosewood - Workshop	Elect/HEAD LIGHT	clearance lights bolster rear						12/12/2017	404061	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Tumut - Workshop	Tyres/STEER TYRE	Job Added From Invoice						12/12/2017	403984	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop		LOADER
LOAD26	Tumut - Workshop	Tyres/FITMENT	Job Added From Invoice						12/12/2017	403984	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop		LOADER
LOAD26	Albury - Workshop	Engine/OIL LEAK	dipstick broken the end off					DONE BY ETS	10/12/2017		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Brakes/BOOSTER	CLEVIS AND BRAKE ROD ARMS.					DONE BY ETS	10/12/2017		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Tumut - Workshop	Tyres/STEER TYRE	Job Added From Invoice						09/12/2017	403574	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop		LOADER
LOAD26	Tumut - Workshop	Tyres/FITMENT	Job Added From Invoice						09/12/2017	403574	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop		LOADER
LOAD26	Albury - Workshop	Elect/WORK LIGHT	WORK LIGHT BROKEN					replaced back up light	09/12/2017	403820	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	DrCabRep'd/OUSDEEP	REFIT DOOR RUBBER						09/12/2017	403820	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	DrCabRep'd/WIPERS	REPLACE WIPER RUBBERS					replaced wipers	09/12/2017	403820	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
								loose 'u' bolts														
								travel to Bago crk rd.														
								Tighten loose Ubolts. One nut missing														
								8-12														
								send out Alex to Bago crk. Rd with nut and tools														
								replace nut and check tension of all others														
LOAD26	Rosewood - Workshop	DriveLine/UNI JOINTS	repair loose u-bolts/re tighten Ubolts					will order ubolts	08/12/2017	403937	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Albury - Workshop	Susp/SWAYBAR	replace sway bar top mounting bracket/CLAMP BRACKET						07/12/2017	400155	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
								REPLACE CONDENSOR.														
LOAD26	Albury - Workshop	Air Con/AIR CON	REPAIR AJC					DONE @ TAE. 11/12/2017	07/12/2017	400155	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Elect/TAIL LIGHT	REPAIR SIDE MARKERS					DONE @ TAE, 11/12/2017	07/12/2017	400155	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Workshop/MOVE ASSET	pick up parts from CMV						07/12/2017	400155	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Wodonga - Workshop	Hydraulic/HYD LEAKS	Find hydraulic leak on boom remove steel pipe & replace . Reassemble & test for leak OK . Returned Loader to Greenfreight .					Snowy trucks .	05/12/2017		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop		LOADER
LOAD26	Albury - Workshop	Susp/SHOCK ABS	REPLACE DRIVE SHOCKERS						15/11/2017		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Elect/DRV LIGHT	REPLACE DRIVING LIGHT						15/11/2017		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
								JOB GETTING DONE @ EXPRESS TRUCK SERVICE														
LOAD26	Albury - Workshop	Engine/OIL LEAK	DIPSTICK TUBE BROKEN					Replace broken dip stick assy	14/11/2017		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Brakes/BOOSTER	CLEVIS AND BRAKE ROD ARMS.						14/11/2017		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Susp/AIR BAG	SUPPLY 2X AIR BAGS TO TUMUT.						08/11/2017		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Engine/OIL LEAK	Engine problems leaking oil						04/11/2017	400271	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Susp/SHOCK ABS	No shocks on rear drives						04/11/2017	400271	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Engine/OIL LEAK	Dipstick broken the end off						04/11/2017	400271	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	VehService/JBS	B Service due		VehService/JBS				04/11/2017	400271	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Engine/JOHAUST	EXH AUST LEAKS . Inspected by Snowy Trucks & found all manifold & turbooxsketereouire reolacine . Advised Phill he would swap out vehicle for reoaire					replace turbo mount gaskets/manifold gaskets	04/11/2017	400272	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
								done at express truck service														
								tightened steering wheel														
LOAD26	Albury - Workshop	VehService/JBS	B SERVICE		VehService/JBS			tighten L mirror	04/11/2017	400272	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Brakes	Record Check Results As Attached To This Job						04/11/2017	400272	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Rosewood - Workshop	Engine/RADIATOR	blown radiator hose						28/10/2017	399305	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Rosewood - Workshop	Engine/BOOST HOSE	blown boost hose						28/10/2017	399305	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Rosewood - Workshop	Workshop/MOVE ASSET	travel to bondo						28/10/2017	399305	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Albury - Workshop	Workshop/MOVE ASSET	pickup parts from CMV						27/10/2017		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
								TRAVEL TO BREAKDOWN.														
			BREAKDOWN @ PHEASANT RD BONDO.					REFIT RADIATOR HOSE WITH NEW CLAMP.														
			BLOWN BOTTOM RADIATOR HOSE.					BOOST HOSE CRIMP FITTING BROKEN. REQUIRES NEW BOOST HOSE. ORDERED NEW HOSE AND CLAMP.														
LOAD26	Albury - Workshop	Engine/BREAKDOWN	BLOWN LOWER BOOST HOSE.					PARTS PICKED UP @ TUMBA @ 9.30PM. ORGANISED TO FIT 27/10/2017	27/10/2017	399305	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Rosewood - Workshop	Engine/RADIATOR	blown radiator hose						27/10/2017	399305	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Rosewood - Workshop	Workshop/MOVE ASSET	travel to Bondo						27/10/2017	399305	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Albury - Workshop	Elect/ELECT P&W	Lights flickering						25/10/2017	399125	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Engine/FAULT CODE	Belt screaming on start up everytime						25/10/2017	399125	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	VehService/JBS	B Service		VehService/JBS				25/10/2017	399125	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Hydraulic/LIMOTOR	Has a miss in the motor						19/10/2017	398157	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Engine/1P15	Lacking power						19/10/2017	398157	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	DrCabRep'd/GARAGE	Steering wheel loose						19/10/2017	398157	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Body/MIRRORS	Tighten LHS mirror						19/10/2017	398157	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Tumut - Workshop	Brakes/BRAKE ADJ	adjust drive brakes						18/10/2017	397400	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop		LOADER
			SUPPLY PARTS FOR SNOWY TRUCK REPAIRS TO REUNE DRIVE . Removed all drive wheels & hubs , Fit new																			
LOAD26	Albury - Workshop	Brakes/BRK RELINE	brake shoes sucelled . re fit hubs & wheels . Tension nuts to spec . adiust brakes & test drive .						15/10/2017	397550	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Rosewood - Workshop	Tyres	Job Added From Invoice						14/10/2017	0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Rosewood - Workshop	Tyres/FITMENT	Job Added From Invoice						14/10/2017	0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Rosewood - Workshop	Tyres/RETREAD	Job Added From Invoice						14/10/2017	0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Rosewood - Workshop	DriveLine/OIL LEAK	Tarhten Front Diff & Clawn . Monitior Diff Leak . Tighten Hydrolic Fittine to Rams . Repair RH fuel tank step . Tighten Bolts that hold Prentice to chassis . ne					Snowy Trucks	12/10/2017	397492	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Rosewood - Workshop	Body/AIR LEAK	air leak underneath back of cab						10/10/2017	396715	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Rosewood - Workshop	Tyres	Job Added From Invoice						07/10/2017	396183	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Rosewood - Workshop	Hydraulic/BAM	right hand main ram 2 leaks						29/09/2017		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job						23/09/2017	394811	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop		LOADER
LOAD26	Tumut - Workshop	VehService/AS	A Service		VehService/AS				23/09/2017	394811	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop		LOADER
								Work performed on 22/9/17 as per GF sheet														
LOAD26	Rosewood - Workshop	VehService/AS	A service		VehService/AS		Snowy trucks - 00038467		23/09/2017		Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Rosewood - Workshop	Elect/ELECT P&W	Remove & replace housing in clearence light , remove & replace no plate light . Check indicator on Front , replace blown globe .					Tumut Auto Elects	22/09/2017	394560	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Albury - Workshop	DrCabElect/INDICATORS	LHS front blinker not working						21/09/2017	394444	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Engine/JOHAUST	exhaust brake stops working						21/09/2017	394444	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Body/LIGHTS	number plate light						21/09/2017	394444	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	VehService/AS	due for A Service 500kms		VehService/AS				21/09/2017	394444	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	DrCabRep'd/DOOR LOCK	Right hand door needs fixing						19/09/2017		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Tumut - Workshop	Body/SHN/RLN/NN	Pin repairs						12/09/2017		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop		LOADER
LOAD26	Rosewood - Workshop	VehService/AS	1200 km to 3 A Service		VehService/AS				02/09/2017	393722	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Albury - Workshop	Tyres	Job Added From Invoice						22/08/2017	0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Tyres/FITMENT	Job Added From Invoice						22/08/2017	0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Tyres/RETREAD	Job Added From Invoice						22/08/2017	0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Susp/SUSPENSION	REPLACE REAR SWAY BAR ANCHORS						16/08/2017		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	DriveLine/CLUTCH	CLUTCH SMELLS LIKE ITS BURNING WHEN DRIVING.					we were told that loader had only just pulled out bogged B double when smell appeared	12/08/2017	391923	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Engine/FUEL TANK	FUEL LEAK UNDER TRUCK (VERY BAD)					Replaced damaged fuel filter	12/08/2017	391923	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	DrCabRep'd/SEAT	SEAT NEEDS REPLACING					Check seat, take photos and id seat	12/08/2017	391923	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Rosewood - Workshop	Tyres	Job Added From Invoice						08/08/2017	390646	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Albury - Workshop	Tyres/RUN OUT	Job Added From Invoice						08/08/2017	390241	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Brakes/AIR LEAK	AIR LEAK NEAR BRAKE BOOSTERS					modify airbags to suit	02/08/2017	391020	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Susp/AIR BAG	RH REAR AIR BAGS NEED REPLACING					travel to kootong to replace rhrr airbag	02/08/2017	391020	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	DrCabRep'd/DOOR LOCK	DOOR STOPPER SEIZED						30/07/2017	390646	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	VehService/AS	A SERVICE		VehService/AS				30/07/2017	390646	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	DrCabElect/PHONE	fix phone back to dash					refit phone	24/07/2017	389600	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Body/MIRRORS	left hand mirror					replaced LH mirror	24/07/2017	389600	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	DrCabRep'd/WIPERS	refit wiper washer hoses and wiper blades						24/07/2017	389600	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Body/MOUNTS	replace front bar bolts						24/07/2017	389600	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Body/MIRRORS	REPLACE LH MIRROR						23/07/2017		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Brakes/BREAKDOWN	LOG DAMAGE TO AIR DISTRIBUTION VALVE						20/07/2017	389230	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Rosewood - Workshop	Body/AIR LEAK	air leak under cab					could not find air leak at back of cab, seat is lifting and lowering ok	06/07/2017	387551	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Rosewood - Workshop	Body/PANELS	carry out work to repair roll over damage						22/06/2017		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop		LOADER
								PICK UP BATTERIES.														
								MODIFY BATTERY HOLDER AND CLAMPS.														
								FIT BATTERIES.														
LOAD26	Albury - Workshop	Elect/BATTERY	FLAT BATTERIES					DIAGNOSE AND REPAIR VOLTAGE DROP. CHANGE LEADS AT MASTER SWITCH.	22/06/2017	387297	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
			LHF DRIVE BOOSTER LEAKING.					REPLACED BOOSTERS.														
LOAD26	Albury - Workshop	Brakes/BOOSTER	RH INCORRECT BOOSTER FITTED					REPLACED AIR LINE AND FITTINGS TO BOOSTERS	07/06/2017	387297	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
								Picked up oil from valvoline														
LOAD26	Albury - Workshop	DriveLine/OIL LEAK	CHECK OIL LEVELS IN DIFFS AND GEARBOX					replaced sight glass and filled with oil	02/06/2017		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Elect/HEAD LIGHT	REPAIR HEAD LIGHT WIRING.						02/06/2017	387297	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Body/HOUSEKEEP	CHECK OVER AFTER RETURNING FROM SMP.						02/06/2017	387297	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Rosewood - Workshop	Tyres/RUN OUT	Job Added From Invoice						29/04/2017	386926	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Rosewood - Workshop	Workshop/WS MAINT	drive to Tumut 126						19/04/2017		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Rosewood - Workshop	Susp/SWAYBAR	sway bar repairs and shift change						19/04/2017		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Rosewood - Workshop	Susp/SWAYBAR	sway bar bushes						19/04/2017		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Albury - Workshop	Susp/SWAYBAR	SUPPLY BUSHES FOR SWAY BAR					HAD TO OPEN NEW ENTRY AS I COULD NOT ISSUE AN ORDER NUMBER TO EXISTING ENTRY NUMBER	06/04/2017		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Rosewood - Workshop	Tyres/LTP02	Job Added From Invoice						29/03/2017	374097	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Rosewood - Workshop	Tyres/LTP01	Job Added From Invoice						29/03/2017	379344	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Wodonga - Workshop	Susp/SWAYBAR	Sway bar top mounting broken temp repair been done & replacement parts ordered						24/03/2017	383686	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop		LOADER
LOAD26	Tumut - Workshop	VehService/JBS	Service		VehService/JBS				21/03/2017	383450	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop		LOADER
LOAD26	Tumut - Workshop	Susp/SWAYBAR	Sway bar top mounting broken temp repair been done & replacement parts ordered						21/03/2017		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop		LOADER
LOAD26	Tumut - Workshop	VehService/JBS	Service		VehService/JBS				21/03/2017		Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop		LOADER
LOAD26	Tumut - Workshop	Chassi/FIRE EXTIN	fire extinguisher bracket broken						17/03/2017	383048	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop		LOADER
LOAD26	Tumut - Workshop	Body/AIR LEAK	air leak under cab						17/03/2017	383048	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop		LOADER
LOAD26	Rosewood - Workshop	Susp/AIR BAG	R/H back airbag						25/02/2017	380368	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop		LOADER
LOAD26	Tumut - Workshop	Susp/SWAYBAR	remove and refit new sway bar bracket					Snowy truck service 24-1-17	01/02/2017		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop		LOADER
LOAD26	Tumut - Workshop	Susp/SWAYBAR	repLace top sway bar mounting bracket						18/01/2017		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop		LOADER
LOAD26	Albury - Workshop	Brakes/BOOSTER	turn R/H b/booster						16/12/2016	374160	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Brakes/BOOSTER	cut & remove kink in airline into R/R B/booster						16/12/2016	374160	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	Brakes/AIR LEAK	park brake need looking at asap					checked park brake operation. All Ok.	16/12/2016	374160	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
			Replace sway bar link brackets.																			
LOAD26	Albury - Workshop	Susp/SWAYBAR	shorter brackets					stck uo part frm CMV Wodonas and fit LHR bottom bush	15/12/2016	374160	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop		LOADER
LOAD26	Albury - Workshop	El

LOAD26	Tumut - Workshop	Engine\BREAKDOWN	travel to Batlow inspect turbo function found to be blown return to tumut		Snowy truck service 6-9-16		09/09/2016		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop	LOADER
LOAD26	Tumut - Workshop	Susp\SWAYBAR	Swayber/Screwpin				09/09/2016		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop	LOADER
LOAD26	Rosewood - Workshop	Tyres\TP01	Job Added From Invoice				08/09/2016	372874	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Tumut - Workshop	Susp\SWAYBAR	replace sway bar bracket RHS worn away by draging on drive way				07/09/2016		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop	LOADER
LOAD26	Rosewood - Workshop	Body	R/H back broken leg pin				03/09/2016	326	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Rosewood - Workshop	Elect	R/H headlight not working				03/09/2016	326	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Tumut - Workshop	DrCabRep\WINDOW REG	replace faulty window regulator		Tumut auto electrics 30-8-16		03/09/2016		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop	LOADER
LOAD26	Tumut - Workshop	Susp\SWAYBAR	replace broken sway bar bracket		snowy truck service 31-8-16		01/09/2016		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop	LOADER
LOAD26	Tumut - Workshop	Body\MIRRORS	replace mirror				26/08/2016		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop	LOADER
LOAD26	Tumut - Workshop	DrCabRep\WINDOW REG	Replace window regulator and door switch LHS				26/08/2016		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop	LOADER
LOAD26	Tumut - Workshop	Elect\ELECT P&W	Find fault in window and order part through w shop		Tumut auto electrics 24-816		26/08/2016		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop	LOADER
LOAD26	Tumut - Workshop	Steering\STEER UNI	Check uni joints in steering Shaft (stiffness in steering)				24/08/2016		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop	LOADER
LOAD26	Tumut - Workshop	Body\LIGHTS	repair short curcuit in lights replace bulbs		completed by tumut Auto electrics on the 17th August		20/08/2016		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop	LOADER
LOAD26	Tumut - Workshop	Body\LIGHTS	replace indecator lens LHS				17/08/2016		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop	LOADER
LOAD26	Tumut - Workshop	DrCabRep	broken front window				16/08/2016	195	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop	LOADER
LOAD26	Tumut - Workshop	Body\LIGHTS	replace indecator lens				16/08/2016		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop	LOADER
LOAD26	Tumut - Workshop	Elect\ELECT P&W	repair fault in headlights		completed by tumut Auto Electrics on the 8th August		13/08/2016		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop	LOADER
LOAD26	Tumut - Workshop	DrCabElect\INDICATORS	broken L/F binker lenses				11/08/2016	154	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop	LOADER
LOAD26	Tumut - Workshop	Body	L/H back leg pin broken				11/08/2016	154	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop	LOADER
LOAD26	Tumut - Workshop	Steering\PWR STEER	Power Steering				10/08/2016		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop	LOADER
LOAD26	Rosewood - Workshop	Body	R/H mirror glass				30/07/2016		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Tumut - Workshop	Insp\WAC COMP	rego brown slip completed		completed by snowy truck service on the 22nd july		27/07/2016		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop	LOADER
LOAD26	Tumut - Workshop	VehService\AS	Volvo truck a service	VehService\AS	completed by snowy truck service on the 22 july		27/07/2016		Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop	LOADER
LOAD26	Tumut - Workshop	Engine\COOL LEAKS	remove replace thermostate housing re fit new gaskets and o rings		completed by Snowy truck service on the 22nd july		27/07/2016		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop	LOADER
LOAD26	Tumut - Workshop	DrCabElect\RADIO	remove replace phone aerial		completed by tumut auto electrics		27/07/2016		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop	LOADER
LOAD26	Tumut - Workshop	DrCabElect\PHONE	remove replace phone kit		completed by Tumut Auto electrics		27/07/2016		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop	LOADER
LOAD26	Rosewood - Workshop	Engine\FAULT CODE	low oil pressure light coming on when loader is idling				27/07/2016	38	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Tumut - Workshop	Elect\TAIL LIGHT	Replace RHS rear Tail light combernation		completed by Tumut Auto eletrical on the18th july		26/07/2016		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop	LOADER
LOAD26	Tumut - Workshop	Brakes	check and record brakes				23/07/2016	367999	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop	LOADER
LOAD26	Tumut - Workshop	VehService\AS	A Service	VehService\AS			23/07/2016	367999	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop	LOADER
LOAD26	Rosewood - Workshop	Body	foot on brake - air leak				22/07/2016	367960	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Rosewood - Workshop	DriveLine	cross locks - diff lock working				22/07/2016	367960	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Rosewood - Workshop	Elect	short R/H headlight				22/07/2016	367960	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Rosewood - Workshop	Body	L/H fuel tank leaking				22/07/2016	367960	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Rosewood - Workshop	Body	heater mirrors				22/07/2016	367960	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Rosewood - Workshop	Brakes	adjust brakes				22/07/2016	367960	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Rosewood - Workshop	Elect	R/H back tail light				17/07/2016	367205	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Rosewood - Workshop	Body	air leak in truck				17/07/2016	367205	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Rosewood - Workshop	DrCabElect	lights in dash h/c beam-oil-temp				17/07/2016	367205	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Tumut - Workshop	Body	replace drain valve on air tank				16/07/2016	365177	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop	LOADER
LOAD26	Tumut - Workshop	Body\PHONE	Job Added From Invoice				15/07/2016	0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop	LOADER
LOAD26	Rosewood - Workshop	Body	R/H boroism step bent				07/07/2016	365733	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Rosewood - Workshop	Body	R/H front mudguard				06/07/2016		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Rosewood - Workshop	Elect	height and low beam -will not change				06/07/2016		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Rosewood - Workshop	Body	R/H door - hard to open -closes				06/07/2016		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Rosewood - Workshop	Elect	headlight out				06/07/2016		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Tumut - Workshop	Cooling\COOL LEAKS	pressure test cooling system on prentice loader		completed by snow trucks on the 1st July		05/07/2016		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop	LOADER
LOAD26	Tumut - Workshop	DrCabElect\HEATER REP	Remove and replace Heater core in prentice loader		completed by T.A.E. on the 29th june		02/07/2016		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop	LOADER
LOAD26	Tumut - Workshop	Air Con\HEATER	Check heater for operating temps 53 and climbing test ok		completed by TAE on the 8th june		22/06/2016		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop	LOADER
LOAD26	Tumut - Workshop	VehService\BS	Volvo Truck service (loader L 26)	VehService\BS	Completed by snowy trucks on the 9th june		21/06/2016		Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop	LOADER
LOAD26	Tumut - Workshop	Brakes	check and record brakes				10/06/2016	363345	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop	LOADER
LOAD26	Tumut - Workshop	VehService\BS	B Service	VehService\BS			10/06/2016	363345	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop	LOADER
LOAD26	Tumut - Workshop	VehService\BS	B service	VehService\BS			09/06/2016		Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop	LOADER
LOAD26	Tumut - Workshop	Cooling\AS	replace mud flaps				24/05/2016		Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop	LOADER
LOAD26	Rosewood - Workshop	Tyres\TP02	Job Added From Invoice				14/05/2016	359872	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Rosewood - Workshop	Tyres\TP02	Job Added From Invoice				14/05/2016	0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Tumut - Workshop	Elect\ELECT P&W	fix wiring				05/05/2016		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop	LOADER
LOAD26	Tumut - Workshop	Steering\WHEEL ALGN	fix steering arm				05/05/2016		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop	LOADER
LOAD26	Tumut - Workshop	Cooling\COOL LEAKS	replace thermo stat				05/05/2016		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop	LOADER
LOAD26	Tumut - Workshop	Steering\WHEEL STUD	replace wheel stud				05/05/2016		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop	LOADER
LOAD26	Tumut - Workshop	Steering\WHEEL STUD	replace wheel studs				05/05/2016		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Rosewood - Workshop	Engine\EXHAUST	secured exhaust bracket temp fix				20/04/2016		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
					temporary hose hose fitted.												
			Busted fuel hose.		Requires correct type of fuel hose fitted.												
LOAD26	Albury - Workshop	Engine\FUEL TANK	Bad fuel leak		Fuel hose from rear of head to left oumo		13/04/2016	356902	Fault	Completed							
			air leaks under cab														
LOAD26	Albury - Workshop	DriveLine\AIR LEAK	Ranee chanee leakine air . air leaks under cab		rebuilt ranee shift actuator		09/04/2016	356845	Fault	Completed	Greenfreight Loseine NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshoo	LOADER
LOAD26	Wodonga - Workshop	Tyres\DRV TYRES	Need drive tyres RRhand drive				05/04/2016	356684	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Tumut - Workshop	Elect\DRV LIGHT	repair headlights				31/03/2016		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Tumut - Workshop	Chassis\BULLBAR	straighten front bar				31/03/2016		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Rosewood - Workshop	Brakes\BRAKE ADJ	brake need adjustment				30/03/2016		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Rosewood - Workshop	DrCabRep\AIR LEAK	air leak under cab				30/03/2016		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Tumut - Workshop	Susp\SUSPENSION	replace broken sway bar plates				17/03/2016		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Tumut - Workshop	Chassis\FUEL TANK	remove damaged fuel tank				16/03/2016		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Rosewood - Workshop	Chassis\FUEL TANK	remove fuel tank and get poured at refit to truck		remove and repair tank		15/03/2016	355255	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Rosewood - Workshop	Tyres\TP09	Job Added From Invoice				08/03/2016	354119	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Tumut - Workshop	Susp\AIR BAG	replace l/h/m air bag				05/03/2016		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Tumut - Workshop	DrCabRep\WINDSCREEN	replace windscreen				04/03/2016		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job				02/03/2016		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Rosewood - Workshop	DrCabRep\WINDSCREEN	windscreen crack				02/03/2016		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Rosewood - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS			02/03/2016		Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Rosewood - Workshop	Engine\EXHAUST	replace cracked muffler				18/02/2016	352235	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Tumut - Workshop	Engine\EXHAUST	replace broken muffler				18/02/2016		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Rosewood - Workshop	DrCabRep\SEAT	seatbelt lock broken				17/02/2016		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Rosewood - Workshop	Chassis\EXHAUST	crack in muffler				13/02/2016	351709	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Rosewood - Workshop	DrCabRep\AIR LEAK	air leak under cab				13/02/2016	351709	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Rosewood - Workshop	DriveLine\GEARBOX	jumps out off reverse				13/02/2016	351709	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Rosewood - Workshop	Tyres\TP51	Job Added From Invoice				13/02/2016	0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Rosewood - Workshop	Tyres\TP51	Job Added From Invoice				13/02/2016	0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Rosewood - Workshop	Elect\HEAD LIGHT	short in R/H head light -low beam				10/02/2016		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Rosewood - Workshop	DrCabRep\SEAT	seat cannot adjust to height				10/02/2016		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Wodonga - Workshop	DriveLine\GEARBOX	have to hold in reverse				02/02/2016		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Wodonga Workshop	LOADER
			replaced turbo drain seals														
LOAD26	Albury - Workshop	Engine\OIL LEAK	tightened sump				29/01/2016	350496	Repair	Completed	Greenfreight Loseine NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshoo	LOADER
LOAD26	Albury - Workshop	DrCabElect\ELECT P&W	Replace dash globes that are not working		Replaced globes		27/01/2016		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER
					Enzed made up hoses.												
LOAD26	Albury - Workshop	Air Con\AIR CON	A/C not working. Requires hoses replacing		Pinners reweed unit		23/01/2016	350469	Repair	Completed	Greenfreight Loseine NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshoo	LOADER
LOAD26	Albury - Workshop	Air Con\HEATER	Heater tap leaking		replace heater tap and modify operating cable mount		23/01/2016	350469	Repair	Completed	Greenfreight Loseine NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshoo	LOADER
LOAD26	Albury - Workshop	DrCabRep\MOUNTS	Cab HCV leaking air		replace HCV		23/01/2016	350469	Repair	Completed	Greenfreight Loseine NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshoo	LOADER
LOAD26	Albury - Workshop	Air Con\AIR CON	Evaporator leaking		remove evaporator and have it repaired at Natrad. RS84		23/01/2016	350469	Repair	Completed	Greenfreight Loseine NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshoo	LOADER
LOAD26	Albury - Workshop	Chassis\SPAREWHEEL	weld up cracked spare tyre carrier and exhaust stay		Aldonga		21/01/2016	350470	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER
			repair electrical faults.														
			Engine and exhaust brake.														
			Mirror heat.														
			Electric windows.														
LOAD26	Albury - Workshop	Elect\DAMAGE	Electric horn.		Arkon diamosed a fault with the soleniod. Required reolace.		20/01/2016		Repair	Completed	Greenfreight Loseine NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshoo	LOADER
LOAD26	Albury - Workshop	DriveLine\WHEEL BRGS	hub cap spanner		required to complete the job		19/01/2016		Repair	Completed	Greenfreight Loseine NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshoo	LOADER
LOAD26	Albury - Workshop	Elect\CLAIMS	engine brake not working		arkon diagnosed faulty wiring loom and exhaust soleniod.		15/01/2016		Repair	Completed	Greenfreight Loseine NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshoo	LOADER
LOAD26	Albury - Workshop	Air Con\AIR CON	air compressor		completed		15/01/2016		Repair	Completed	Greenfreight Loseine NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshoo	LOADER
LOAD26	Myrtleford - Workshop	Body\HOUSEKEEP	bonnet catch broken		Replaced catch.		14/01/2016		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER
LOAD26	Albury - Workshop	Body\HOUSEKEEP	bonnet hold down		completed		13/01/2016		Repair	Completed	Greenfreight Loseine NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshoo	LOADER
LOAD26	Albury - Workshop	Susp\SUSPENSION	bolts		completed		12/01/2016		Repair	Completed	Greenfreight Loseine NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshoo	LOADER
LOAD26	Albury - Workshop	Susp\AIR BAG	air bags		completed		12/01/2016		Repair	Completed	Greenfreight Loseine NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshoo	LOADER
LOAD26	Albury - Workshop	DrCabRep\DAMAGE	mirror assembly		completed		12/01/2016		Repair	Completed	Greenfreight Loseine NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshoo	LOADER
LOAD26	Albury - Workshop	Engine\OIL LEAK	engine parts		completed		12/01/2016		Repair	Completed	Greenfreight Loseine NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshoo	LOADER
LOAD26	Albury - Workshop	Chassis\FUEL TANK	tank strap rubber		completed		08/01/2016		Repair	Completed	Greenfreight Loseine NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshoo	LOADER
LOAD26	Albury - Workshop	Engine\BOOST HOSE	boost clamp		completed		07/01/2016		Repair	Completed	Greenfreight Loseine NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshoo	LOADER
LOAD26	Albury - Workshop	Susp\SUSPENSION	push in bushes				07/01/2016		Repair	Completed	Greenfreight Loseine NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshoo	LOADER
LOAD26	Albury - Workshop	Susp\SUSPENSION	nuts		completed		06/01/2016		Repair	Completed	Greenfreight Loseine NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshoo	LOADER
			king pin														
LOAD26	Rosewood - Workshop	Steering\KING PIN	cmv		completed		24/12/2015		Repair	Completed	Greenfreight Loseine NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshoo	LOADER
			fit + ream king pins														
LOAD26	Rosewood - Workshop	Steering\KING PIN	wado one ctr		completed		24/12/2015		Repair	Completed	Greenfreight Loseine NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshoo	LOADER
			weld fuel tank														
LOAD26	Rosewood - Workshop	Body\FUEL TANK	aldonea one		complete		24/12/2015		Repair	Completed	Greenfreight Loseine NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshoo	LOADER
			king pin kits														
LOAD26	Rosewood - Workshop	Steering\KING PIN	cmv		complete		23/12/2015		Repair	Completed	Greenfreight Loseine NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshoo	LOADER
			suspension parts														
LOAD26	Rosewood - Workshop	Susp\SUSPENSION	albu t & t		completed		23/12/2015		Repair	Completed	Greenfreight Loseine NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshoo	LOADER
LOAD26	Albury - Workshop	Tyres\STEER TYRE	Job Added From Invoice				19/12/2015	349420	Repair	Completed	Greenfreight Loseine NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshoo	LOADER
LOAD26	Rosewood - Workshop	Tyres\STEER TYRE	Job Added From Invoice				15/12/2015	0	Repair	Completed	Greenfreight Loseine NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshoo	LOADER
LOAD26	Rosewood - Workshop	Tyres\STEER TYRE	Job Added From Invoice				15/12/2015	0	Repair	Completed	Greenfreight Loseine NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshoo	LOADER
LOAD26	Albury - Workshop	Engine\RADIATOR	coolant leak		repaired heater hose (split) and topped up with coolant, wash engine		09/12/2015	348559	Fault	Completed	Greenfreight Loseine NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshoo	LOADER
LOAD26	Albury - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS			02/12/2015	346997	Service	Completed	Greenfreight Loseine NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshoo	LOADER
LOAD26	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				02/12/2015	346997	Repair	Completed	Greenfreight Loseine NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshoo	LOADER
LOAD26	Albury - Workshop	Body	job created to register R&R				02/12/2015	346997	Fault	Completed	Greenfreight Loseine NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshoo	LOADER
			wheel studs														
LOAD26	Rosewood - Workshop	Steering\STEER TYRE	alb t & t		98795 COMPLETED		02/12/2015		Repair	Completed	Greenfreight Loseine NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshoo	LOADER
LOAD26	Rosewood - Workshop	Tyres\TP09	Job Added From Invoice				01/12/2015	346220	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER
LOAD26	Albury - Workshop	Tyres\DRV TYRES	Job Added From Invoice				28/11/2015	343645	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury

			diagnose engine fault															
LOAD26	Rosewood - Workshop	Engine\FAULT CODE	arkon		completed		29/10/2015		Repair	Completed	Greenfreight Loxeine NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER	
LOAD26	Albury - Workshop	DrCabElect	rh headlight not working				27/10/2015	340140	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER	
			air temp sensor															
LOAD26	Rosewood - Workshop	Engine\FAULT CODE	cmv		completed		27/10/2015		Repair	Completed	Greenfreight Loxeine NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER	
LOAD26	Rosewood - Workshop	Body	truck needs rake how				23/10/2015	339472	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER	
LOAD26	Rosewood - Workshop	Elect	replace air flow sensor				23/10/2015	339472	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER	
LOAD26	Rosewood - Workshop	Brakes	adjust brakes				23/10/2015	339472	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER	
LOAD26	Albury - Workshop	DrCabRep\SEAT	air leak under seat				20/10/2015	338724	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER	
LOAD26	Albury - Workshop	Brakes\AIR LEAK	park brake air leak				20/10/2015	338724	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER	
LOAD26	Albury - Workshop	Brakes\BRAKE ADJ	adjust brakes				20/10/2015	338724	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER	
			repairs to fuel tank															
LOAD26	Myrtleford - Workshop	Body\FUEL TANK	rodds enviroweise				19/10/2015	488407	Repair	Completed	Greenfreight Loxeine NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER	
LOAD26	Myrtleford - Workshop	Body\FUEL TANK	repair fuel tank		completed		15/10/2015		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER	
			filters															
LOAD26	Myrtleford - Workshop	VehService\BS	maxiparts 2114261	VehService\BS	completed		14/10/2015		Service	Completed	Greenfreight Loxeine NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER	
LOAD26	Rosewood - Workshop	Tyres\DRY TYRES	wheel spacer - maxiparts r513		completed		14/10/2015		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER	
LOAD26	Albury - Workshop	DrCabRep	seat air not working				13/10/2015	337508	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER	
LOAD26	Albury - Workshop	Body\MIRRORS	lh and rh mirrors				13/10/2015	337508	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER	
LOAD26	Albury - Workshop	DrCabRep	no fire extinguisher				13/10/2015	337508	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER	
LOAD26	Albury - Workshop	Steering	front king pins need replacing		replace king pins/wheel bearings		13/10/2015		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER	
LOAD26	Albury - Workshop	Susp	lhr and rhr shockers, rear suspension bushes		replace shockers		13/10/2015		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER	
LOAD26	Albury - Workshop	Engine\JAKE BRAKE	fault with engine brake		arkon replace engine loom sensor and exhaust brake solenoid		13/10/2015		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER	
LOAD26	Albury - Workshop	DrivLine\GEARBOX	have to hold in reverse				13/10/2015		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER	
LOAD26	Albury - Workshop	DrCabRep	steering wheel not on straight		reposition steering wheel		13/10/2015		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER	
LOAD26	Albury - Workshop	Body\MIRRORS	lh and rh mirrors		replace mirrors - arkon found mfaulty switch for morror heat		13/10/2015		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Albury Workshop	LOADER	
LOAD26	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job				13/10/2015	337508	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER	
LOAD26	Rosewood - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS			13/10/2015	337508	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER	
LOAD26	Myrtleford - Workshop	Engine\OIL LEAK	replace sump plug & oring - tstc		completed		13/10/2015		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Myrtleford Workshop	LOADER	
LOAD26	Rosewood - Workshop	Susp	replace rhr air bag				02/10/2015	336815	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER	
LOAD26	Rosewood - Workshop	DrCabRep\SEAT	Job Added From Invoice				11/09/2015	0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER	
LOAD26	Rosewood - Workshop	Engine\FUEL TANK	replace lh i bracket for fuel tanks, replace 4x fuel tank straps				09/09/2015	334344	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER	
LOAD26	Rosewood - Workshop	Body\DAMAGE	replace lh bottom step				09/09/2015	334344	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER	
LOAD26	Rosewood - Workshop	DrivLine\GEARBOX	replace gearbox bush				09/09/2015	334344	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Rosewood Workshop	LOADER	
LOAD26	Tumut - Workshop	Body\HOUSEKEEP	Service Job Added From Invoice				08/09/2015	0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	PUC996	Tumut Workshop	LOADER	