EquipmentName	Workshop	CodeAndSubCode	Description	Schedule	CompletionComments	DateDone	HourDone	Worktype	Workstate	EquipmentOwner	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
					-batteries swapped over with originals put on charge for further testing											
					-no current draw present											
P25	Albury - Workshop	Elect\BATTERY	Replace batterys and test alternator.		-chaninne as intended	03/07/2025	7550	Fault	Completed	Greenfreight Loeeine NSW	LOADPRENT	Albury	ALR		Albury Workshop	PRENTICE
P25	Wodonga - Workshop	VehService\AS	A Service			09/12/2024	7550	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Wodonga Workshop	PRENTICE
P25	Wodonga - Workshop	Insp\ANN INSP	Insp\ANN INSP	Insp\ANN INSP		09/12/2024	7550	PreventativeMaintenance	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Wodonga Workshop	PRENTICE
P25	Wodonga - Workshop	VehService\CS	C Service	VehService\CS		09/12/2024	7550	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Wodonga Workshop	PRENTICE
P25	Wodonga - Workshop	VehService\BS	VehService\BS	VehService\BS		09/12/2024	7550	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Wodonga Workshop	PRENTICE
P25	Myrtleford - Workshop	Hydraulics\HYD LEAKS	repair hyd oil leak at control valve under cab		replaced o-ring at pipe tested all good	25/09/2024	7550	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Myrtleford Workshop	PRENTICE
P25	Myrtleford - Workshop	Hydraulics\PUMP	remove servo pump to be resealed (rinlatech) and then refit and test (due to hyd oil leaking into eng)			10/09/2024	1	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Myrtleford Workshop	PRENTICE
					inspected and found oil level way over full mark drained to correct level											
P25	Myrtleford - Workshop	Engine\OIL LEAK	inspect excessive blow bye		found hyd oil to be down top up problem poss could be in pilot pump leaking hyd oil into eng need to reseal pilot pump	06/08/2024	1	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Myrtleford Workshop	PRENTICE
P25	Wodonga - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS		15/03/2023	6031	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Wodonga Workshop	PRENTICE
P25	Wodonga - Workshop	Hydraulics\HOSES	Replace Damage Hydraulic Hose		Rapid #POWW077196	11/03/2023	6031	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Wodonga Workshop	PRENTICE
P25	Wodonga - Workshop	Prewent\CONSUMABLE	Grease Loader		REPLACED GRAB PIN KEEPER BOLTS.	11/03/2023	6031	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Wodonga Workshop	PRENTICE
			Make Up New Lift Cylinder Hose (Rapid Hydraulics)													
P25	Wodonga - Workshop	Hydraulics\HYD LEAKS	Purchase Order Number: WW076925			23/02/2023	1	Reapir	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Wodonasa Workshop	PRENTICE
P25	Wodonga - Workshop	Hydraulics\HOSES	TRAVELLED TO AND FROM SHELLEY. REPLACED HYDRAULIC HOSE.			23/02/2023		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Wodonga Workshop	PRENTICE
P25	Wodonga - Workshop	Engine\OIL LEAK	Rear main seal weeping.			02/02/2023	1	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Wodonga Workshop	PRENTICE
			Two bad air leaks one around the horton.													
P25	Wodonga - Workshop	Chassis\AIR LEAK	The other is under the cab droos air straieht awav.			02/02/2023	1	Fault	Completed	Greenfreight Loeeine NSW	LOADPRENT	Albury	ALR		Wodonasa Workshop	PRENTICE
P25	Wodonga - Workshop	Air Con\AIR CON	AIR CONDITIONER NOT WORKING FAN.			02/02/2023	1	Fault	Completed	Greenfreight Loeeine NSW	LOADPRENT	Albury	ALR		Wodonasa Workshop	PRENTICE
			FLY BOOM LIGHTS NOT WORKING.													
P25	Wodonga - Workshop	Elect\ELECT P&W	WORK LIGHT ON CAB WINDSCREEN NOT WORKING.		DIAGNOSED AND REPAIRED WIRING.	02/02/2023	1	Fault	Completed	Greenfreight Loeeine NSW	LOADPRENT	Albury	ALR		Wodonasa Workshop	PRENTICE
P25	Wodonga - Workshop	Engine\BATTERY	Change Batteries			10/01/2023		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Wodonga Workshop	PRENTICE
					Setup and test spare grab ram, dissmantle and replace gland											
P25	Albury - Workshop	Hydraulics\RAM	Rebuild grab ram. Machine new rod eye etc.		backup and orine and reassemble and test.	05/11/2022		Reapir	Completed	Greenfreight Loeeine NSW	LOADPRENT	Albury	ALR		Albury Workshop	PRENTICE
P25	Wodonga - Workshop	Hydraulics\VALVES	Replace servo o rings and seals.		REPLACED 8 O-RINGS AND SEALS. ADJUSTED SERVO HANDLES. CLEANED OUT CAB.	15/10/2022	6752	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Wodonga Workshop	PRENTICE
P25	Wodonga - Workshop	Air Con\AIR CON	AIR CONDITIONER NOT WORKING FAN.			13/10/2022	5799	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Wodonga Workshop	PRENTICE
P25	Wodonga - Workshop	Engine\OIL LEAK	Rear main seal weeping.			13/10/2022	5799	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Wodonga Workshop	PRENTICE
			Two bad air leaks one around the horton.													
P25	Wodonga - Workshop	Chassis\AIR LEAK	The other is under the cab droos air straight away.			13/10/2022	5799	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Wodonga Workshop	PRENTICE
P25	Wodonga - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS		13/10/2022	5799	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Wodonga Workshop	PRENTICE
P25	Wodonga - Workshop	Hydraulics\RAM	Replace Grab Ram		REPLACED RAM. CLEANED UP. TESTED.	22/09/2022	5798	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Wodonga Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\HOSES	Make hose as per sample			23/07/2022		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Albury Workshop	PRENTICE
P25	Rosewood - Workshop	Chassis\Boom	BROKEN GRAB FORK.		FABRICATE NEW TIP AND WELD IN PLACE. TEST.	25/06/2022	5671	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Rosewood Workshop	PRENTICE
P25	Wodonga - Workshop	Chassis\Boom	CALLED OUT TO SHELLEY FIRST THING. REPLACED BROKEN GRAB RAM PIN ON RHR.			22/06/2022		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Wodonga Workshop	PRENTICE
P25	Wodonga - Workshop	Hydraulics\RAM	REPLACED LR LOWER LEG RAM PIN.			19/05/2022	5588	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Wodonga Workshop	PRENTICE
P25	Wodonga - Workshop	Hydraulics\HYD LEAKS	DIAGNOSED, CLEANED AND REPAIRED 2 LEAKS AT GRAB HOSES. TESTED.			10/03/2022	5486	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Wodonga Workshop	PRENTICE
P25	Wodonga - Workshop	Chassis\Load Fram	GREASE AND CHECK OVER LOADER.			22/02/2022	5436	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Wodonga Workshop	PRENTICE
					Reconnect rear sway bar link.											
P25	Wodonga - Workshop	Susp\SWAYBAR	Sway bar at rear of truck.		Attemot to wash hydraulic oil off truck.	27/07/2021	808447	Fault	Completed	Greenfreight Loeeine NSW	LOADPRENT	Albury	ALR		Wodonasa Workshop	PRENTICE
P25	Wodonga - Workshop	Body				27/07/2021	808447	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Wodonga Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\HOSES	Make hoses as per sample			21/07/2021		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Albury Workshop	PRENTICE
					Grab not holding.											
					Lift cylinders creeping down.											
					Tested main lift circuit for piston bypass - Failed.											
					Tested grab circuit for pison bypass - Failed.											
					Made support frame to remove cylinders safely.											
					Cleaned cylinders down.											
					Stripped cylinders in workshop.											
					Found cylinders to be in poor condtion.											
					Barrels scored & one cylinder had a dent. One rod had chrome flacking off surface.											
					Contacted customer with quote and to work out a solution.											
					Customer decided they wanted us to remove cylinder from the truck, in the yard and inspect.											
					Salvaged a rod from one of the cylinders and assembled cylinders.											
					Honed barrels and linished rods.											
P25	Albury - Workshop	Hydraulics\RAM	Wont hold hydraulic pressure			21/07/2021		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Albury Workshop	PRENTICE
P25	Albury - Workshop	VehService\AS	need service and hydraulic service			21/07/2021		Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Albury Workshop	PRENTICE
P25	Wodonga - Workshop	Hydraulics\VALVES	REPLACED LH JOY STICK.			10/07/2021		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Wodonga Workshop	PRENTICE
P25	Myrtleford - Workshop	Hydraulics\CONSUMABLE	Two small hoses need replacing above grab rotator also leaking.			04/06/2021		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Myrtleford Workshop	PRENTICE
P25	Myrtleford - Workshop	Hydraulics\HOSES	replace leaking grab hose and clean up			04/06/2021		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Myrtleford Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\HYD LEAKS	Hydraulic Leaks			30/05/2021		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Wodonga Workshop	PRENTICE
P25	Tumut - Workshop	VehService\BS	carry out B service as per check list	VehService\BS		16/05/2021	5164	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Tumut Workshop	PRENTICE
P25	Tumut - Workshop	Engine\OIL LEAK	Rear main seal weeping.			16/05/2021	5164	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Tumut Workshop	PRENTICE
P25	Tumut - Workshop	Engine\OIL LEAK	Engine oil filler neck weeping.		Cleaned and tightened.	16/05/2021	5164	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Tumut Workshop	PRENTICE
P25	Wodonga - Workshop	Hydraulics\PUMP	new drive adaptor needed. Ordered and waiting for parts		completed	12/05/2021	4999	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Wodonga Workshop	PRENTICE
					check over											
P25	Wodonga - Workshop	Engine\FAULT CODE	something in engine bad when loader is running		comoleted	12/05/2021	4999	Fault	Completed	Greenfreight Loeeine NSW	LOADPRENT	Albury	ALR		Wodonasa Workshop	PRENTICE
P25	Wodonga - Workshop	Engine\COOL LEAKS	coolant bottle leaking at bottom		completed	12/05/2021	4999	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Wodonga Workshop	PRENTICE
P25	Wodonga - Workshop	Chassis\DAMAGE	main boom cracked at anchor pins		completed	12/05/2021	4999	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Wodonga Workshop	PRENTICE
P25	Wodonga - Workshop	Hydraulics\HYD LEAKS	L/H joystick leaking oil		completed	12/05/2021	4999	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Wodonga Workshop	PRENTICE
P25	Wodonga - Workshop	Chassis\BOLSTER	RHS rear leg pin locking pin broken			08/05/2021		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Wodonga Workshop	PRENTICE
			left hand side main lift ram leaking													
P25	Wodonga - Workshop	Hydraulics\HYD LEAKS	main ram from main boom and fly boom is leaking and hydraulic hoses on main boom leaking			08/05/2021		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Wodonga Workshop	PRENTICE
			check and diagnose leak at joysticks													
P25	Rosewood - Workshop	Hydraulics\OIL LEAK	ordered kits to reseal from Wayne			04/05/2021	4952	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Rosewood Workshop	PRENTICE
P25	Rosewood - Workshop	Chassis\HOUSEKEEP	replace grab pin lock bolt			23/04/2021	4909	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Rosewood Workshop	PRENTICE
P25	Albury - Workshop	Chassis\Load Fram	loader grab pin broken		replaced broken grab pin	13/04/2021	4883	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Albury Workshop	PRENTICE
P25	Tumut - Workshop	Engine\FILTERS	Supply Filters			09/04/2021		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Tumut Workshop	PRENTICE
			prepare cracks													
			pre heat													
			weld													
			clean off													
P25	Tumut - Workshop	Chassis\TP06	paint			27/03/2021	4809	Reapir	Completed	Greenfreight Loeeine NSW	LOADPRENT	Albury	ALR		Tumut Workshop	PRENTICE
P25	Rosewood - Workshop	Hydraulics\DAMAGE	L/H joystick handle cracking			25/03/2021	4803	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Rosewood Workshop	PRENTICE
P25	Rosewood - Workshop	VehService\BS	loader B Service due	VehService\BS		25/03/2021	4803	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Rosewood Workshop	PRENTICE
P25	Albury - Workshop	Elect\WORK LIGHT	Supply LED Work Lamp and clamp			24/03/2021		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Albury Workshop	PRENTICE
P25	Rosewood - Workshop	Chassis\DAMAGE	main boom cracked at anchor pins			23/03/2021	4780	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Rosewood Workshop	PRENTICE
P25	Rosewood - Workshop	Chassis\HOUSEKEEP	replace LHR lower leg pin			10/03/2021	4683	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Rosewood Workshop	PRENTICE
P25	Rosewood - Workshop	Engine\FILTERS	blow out air filter and check fluid levels			10/03/2021	4683	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Rosewood Workshop	PRENTICE
			R/H upper leg pin broken		R/H upper leg pin broken											
			grease nipple stuffed top of R/H		remove leg pin replace with new one											
P25	Rosewood - Workshop	Chassis\DAMAGE	rear lee		weld tae on lower pin	03/03/2021	4643	Fault	Completed	Greenfreight Loeeine NSW	LOADPRENT	Albury	ALR		Rosewood Workshop	PRENTICE
P25	Rosewood - Workshop	VehService\BS	B Service	VehService\BS		02/03/2021	4631	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Rosewood Workshop	PRENTICE
			reg pin keeper broken off pin													
P25	Rosewood - Workshop	Chassis\DAMAGE	oreoare and weld			26/02/2021	8604	Reapir	Completed	Greenfreight Loeeine NSW	LOADPRENT	Albury	ALR		Rosewood Workshop	PRENTICE
P25	Rosewood - Workshop	Chassis\DAMAGE	weld leg pin up			26/02/2021	4608	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Rosewood Workshop	PRENTICE
			grease													
P25	Tumut - Workshop	Hydraulics\DAMAGE	weld upper lee pin retainer			26/02/2021	4622	Reapir	Completed	Greenfreight Loeeine NSW	LOADPRENT	Albury	ALR		Tumut Workshop	PRENTICE
			broken lower leg ram pin													
P25	Rosewood - Workshop	Chassis\DAMAGE	remove old sion			25/02/2021	8591	Repair	Completed	Greenfreight Loeeine NSW	LOADPRENT	Albury	ALR		Rosewood Workshop	PRENTICE
			fit new pin (short pin)													
			weld in place nut and keeper													
P25	Rosewood - Workshop	Chassis\DAMAGE	refit tyre tension nuts			25/02/2021	8591	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Rosewood Workshop	PRENTICE
			replace grab ram on 2 prong side of grab													
			clean up oil stains and test													
P25	Rosewood - Workshop	Hydraulics\RAM	check fluid level			24/02/2021	4589	Repair	Completed	Greenfreight Loeeine NSW	LOADPRENT	Albury	ALR		Rosewood Workshop	PRENTICE
P25	Rosewood - Workshop	Engine\HOUSEKEEP	check over REPAIR FUEL LEAKS			10/02/2021	4434	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Rosewood Workshop	PRENTICE
P25	Rosewood - Workshop	Engine\FILTERS	blow out outer air filter			10/02/2021	4434	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Rosewood Workshop	PRENTICE
P25	Rosewood - Workshop	Engine\HOUSEKEEP	check over			20/01/2021	4379	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Rosewood Workshop	PRENTICE
P25	Rosewood - Workshop	Hydraulics\DAMAGE	broken foot pin		transport to job remove bolt in pin	20/01/2021	4374	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Rosewood Workshop	PRENTICE
					bend foot to release pin remove pin remove broken feet											
					fit new feet and pin bolt in pin grease											
					check operation pack up tools											
					transport back to diepot											
P25	Rosewood - Workshop	Hydraulics\DAMAGE	bent pin			20/01/2021	4374	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Rosewood Workshop	PRENTICE
P25	Rosewood - Workshop	Hydraulics\DAMAGE	missing collar			20/01/2021	4374	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Rosewood Workshop	PRENTICE
P25	Rosewood - Workshop	Chassis\BREAKDOWN	call out MT Garlan R&R 122792			20/01/2021	4374	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Rosewood Workshop	PRENTICE
P25	Rosewood - Workshop	Elect\ALT	alternator failed remove alternator order new one. Fit replacement alternator non standard run different wire etc to get alternator working. Fit new alternator found crack in bolt			19/01/2021	4368	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Rosewood Workshop	PRENTICE
P25	Albury - Workshop	Steering\WHEEL BRGS	Supply Spherical Bearings			16/01/2021		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Albury Workshop	PRENTICE
			hydraulics very slow on main boom and lags. Confirmed													
			remove inspect and change main filter													
			check in tank for foreign objects													
			remove inspect and change pilot filter													
P25	Rosewood - Workshop	Hydraulics\OIL/FILTER	top up with oil test ok			08/01/2021	4229	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Rosewood Workshop	PRENTICE
P25	Myrtleford - Workshop	Hydraulics\OIL LEAK	R/H joystick leaking oil			05/01/2021	4339	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Myrtleford Workshop	PRENTICE
P25	Myrtleford - Workshop	Elect\ELECT P&W	safety light on loader deck not working			05/01/2021	4339	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Myrtleford Workshop	PRENTICE
P25	Myrtleford - Workshop	Elect\ELECT P&W	safety light located on loader wall not working			05/01/2021	4339	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Myrtleford Workshop	PRENTICE
P25	Rosewood - Workshop	Hydraulics\RAM	replace LHR leg ram			01/01/2021	4340	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Rosewood Workshop	PRENTICE
			R&R 122776													
			joystick leaking oil													
P25	Rosewood - Workshop	Hydraulics\HYD LEAKS	remove reolace			01/01/2021	4339	Reapir	Completed	Greenfreight Loeeine NSW	LOADPRENT	Albury	ALR		Rosewood Workshop	PRENTICE
			refit test ok													
P25	Rosewood - Workshop	Elect\WORK LIGHT	fix safety latht for dismount			01/01/2021	4339	Reapir	Completed	Greenfreight Loeeine NSW	LOADPRENT	Albury	ALR		Rosewood Workshop	PRENTICE
P25	Rosewood - Workshop	Chassis\DAMAGE	fab prep and weld grapple			23/12/2020	4319	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Rosewood Workshop	PRENTICE
P25	Rosewood - Workshop	Hydraulics\DAMAGE	top of grab jaw needs welding			22/12/2020		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Rosewood Workshop	PRENTICE
P25	Rosewood - Workshop	Chassis\DAMAGE	prepare and weld cracks in grapple			22/12/2020	4310	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Rosewood Workshop	PRENTICE
P25	Rosewood - Workshop	Elect\WORK LIGHT	boom light not working			12/12/2020		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Rosewood Workshop	PRENTICE
P25	Rosewood - Workshop	Hydraulics\DAMAGE	replace left hand joystick handle			12/12/2020	4803	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Rosewood Workshop	PRENTICE
P25	Rosewood - Workshop	VehService\BS	B Service	VehService\BS		12/12/2020	4803	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Rosewood Workshop	PRENTICE
P25	Tumut - Workshop	Elect\ELECT P&W	lights on dipper arm not working			11/12/2020		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Tumut Workshop	PRENTICE

P25	Rosewood - Workshop	VehService\JBS	Service	VehService\JBS		02/12/2020	4207	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P25	Rosewood - Workshop	Engine\BELTS/TENS	sublet repair by Cummins, replace belt drive pulley I removed the fan hub bearing and greased it and reassembled			01/12/2020		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P25	Rosewood - Workshop	Engine\BELTS/TENS	new bearing on order			01/12/2020		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P25	Myrtleford - Workshop	Engine\BELTS/TENS	fit fan pulleys and belts			01/12/2020	4193	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P25	Myrtleford - Workshop	Engine\BELTS/TENS	repack fan pulley bearing			01/12/2020	4193	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P25	Myrtleford - Workshop	Engine\FAULT CODE	check engine rpm sat to high called out to Hyne Mill, loader overheating			01/12/2020	4193	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P25	Rosewood - Workshop	Engine\HOUSEKEEP	I sat on loader with ozerator and lowered revs to 1.700rom. This worked well and did not run hot			21/11/2020	4158	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P25	Rosewood - Workshop	Engine\BELTS/TENS	needs new pulleys to stop from slipping			21/11/2020	4158	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P25	Rosewood - Workshop	Engine\HOUSEKEEP	loader is over heating		diagnose over heating and organise sublet repairs	20/11/2020	4152	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P25	Myrtleford - Workshop	Cooling\BREAKDOWN	call out			20/11/2020	4185	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P25	Myrtleford - Workshop	Engine\WATER PUMP	replace water pump			20/11/2020	4185	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P25	Myrtleford - Workshop	Engine\HOUSEKEEP	replace thermostat			20/11/2020	4185	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P25	Myrtleford - Workshop	Engine\RADIATOR	test engine for running warm called out to loader at Rosewood, found main drive belt missing. Driver handed me the belt that was broken, I later found a second piece			20/11/2020	4185	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P25	Rosewood - Workshop	Engine\BELTS/TENS	broken fan belt		twisted all accessories. No problem evident replaced belt and tested. All good eave broken belt to TCTC (Hayden) as it was 5 days old	19/11/2020	4141	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P25	Rosewood - Workshop	Hydraulics\OIL/FILTER	hyd oil light flickers on/off		checked wiring to hydraulic oil sensor. No obvious problems. Will monitor	18/11/2020	4125	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P25	Rosewood - Workshop	Hydraulics\RAM	bolt missing out of grab ram called out to bush, leg pin coming out		replace broken ram pin bolt in grab	18/11/2020	4125	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P25	Rosewood - Workshop	Chassis\HOUSEKEEP	refitted. areased and fited lockine bolt and nut			07/11/2020		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P25	Rosewood - Workshop	Engine\HOUSEKEEP	check levels			04/11/2020	4033	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P25	Rosewood - Workshop	DrCabElec\RADIO	fit UHF mic hanger properly fit rebuilt triple pump and test			04/11/2020	4033	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P25	Rosewood - Workshop	Hydraulics\PUMP	fit main lift ram diagnose hydraulic propblem, faulty triple pump			31/10/2020	3961	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P25	Rosewood - Workshop	Hydraulics\PUMP	remove triple pump clean hydraulic tank out, flush with diesel remove filter housing and disassemble, clean and inspect R10114 R10146			27/10/2020	3961	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P25	Rosewood - Workshop	Hydraulics\OIL/FILTER	reassemble filter asembly and ready for new oumo			27/10/2020	3961	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P25	Rosewood - Workshop	Hydraulics\PUMP	new drive adaptor needed. Ordered and waiting for parts R10007			27/10/2020	3961	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P25	Rosewood - Workshop	Hydraulics\PUMP	loader main ram wont lift/sometimes slow lift check slow boom lift found metal in pilot filter			27/10/2020		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P25	Rosewood - Workshop	Hydraulics\OIL/FILTER	cleaned housine and reolace filter hydraulic oil was low, topped it up			24/10/2020	4004	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P25	Rosewood - Workshop	Hydraulics\OIL/FILTER	test oaerated. better. not sure its 100% but will monitor			24/10/2020	4004	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P25	Rosewood - Workshop	Engine\MOUNTS	compressor mount broken and belt slipping			24/10/2020	4004	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P25	Rosewood - Workshop	Engine\OIL LEAK	sump plug works doesn't look like the correct one			24/10/2020	4004	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P25	Rosewood - Workshop	VehService\JBS	B Service and check over	VehService\JBS		24/10/2020	4004	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P25	Rosewood - Workshop	Hydraulics\OIL LEAK	R/H joystick leaking oil T10064			21/10/2020	3955	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P25	Rosewood - Workshop	Chassis\HOUSEKEEP	grease nipple on knuckle boom missing		modify and adapt temporary grease nipple set up infly boom pivot. Parts ordered	21/10/2020	3955	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P25	Rosewood - Workshop	Elect\ELECT P&W	safety light on loader deck not working PO FOR SERVICE (PARTS)-AWAITING W/O			21/10/2020	3955	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P25	Tumut - Workshop	VehService\JBS	make up hyd hoses 7 supply fittings 1	VehService\JBS		20/10/2020		Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P25	Rosewood - Workshop	Chassis\HOUSEKEEP	2 grease nipples missing on boom safety light located on loader wall not working		check over and grease replace several enease nipples	16/10/2020	3913	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P25	Rosewood - Workshop	Elect\ELECT P&W				16/10/2020	3913	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P25	Rosewood - Workshop	Engine\COOL LEAKS	coolant bottle leaking at bottom			16/10/2020	3913	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P25	Albury - Workshop	Chassis\HOUSEKEEP	excessive movement in main boom pin		inspected movement in main boom pin - requires line boring and new pin made to suit (asap)	11/10/2020	3879	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	VehService\JBS	loader service overdue	VehService\JBS		11/10/2020	3879	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Engine\START MOTR	SUPPLY AND FIT STARTER AS REQUESTED			06/10/2020	3815	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Engine\FAULT CODE	something in engine bad when loader is running		engine rattle - exhaust flap broken/ damage, will order new piece	03/10/2020	3820	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Elect\ELECT P&W	L/H side fly boom flicking		fly boom light flickering - could not get it to faulter	03/10/2020	3820	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\OIL LEAK	reseal hydraulic leaks		REPLACE O/RINGS AND HYDRAULIC HOSE-ENZED	23/09/2020		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Chassis\HOUSEKEEP	degrease wash deck			23/09/2020		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\OIL LEAK	loader hydraulic oil leak main lines into system motor		repair hydraulic leak main control valve enease loader renair boom light	22/09/2020		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Myrtleford - Workshop	DrCabElect\INST/GAUGE	Engine gauges not working and no dash lights		fit new gauge clutster and fit new hyd temp gauge	12/09/2020	3746	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	ARKON AUTO ELECTRICAL	PRENTICE
P25	Myrtleford - Workshop	DrCabElect\INST/GAUGE	dash (gauges) lights not working			09/09/2020	3746	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P25	Myrtleford - Workshop	Chassis\DAMAGE	weld tips on grab			06/09/2020	3746	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P25	Myrtleford - Workshop	Chassis\DAMAGE	weld cracks in grab			06/09/2020	3746	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P25	Myrtleford - Workshop	Hydraulics\OIL/FILTER	top up hyd oil & cummins fitted a new fan belt & checked the tensoiner			06/09/2020	3746	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P25	Myrtleford - Workshop	Engine\EXHAUST	exh system repair			25/08/2020	3746	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P25	Myrtleford - Workshop	Body\PANELS	make new rear engine cover make latchs, droplocks etc			25/08/2020	3747	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P25	Myrtleford - Workshop	DrCabRep\WIPERS	replace front windscreen			21/08/2020	3746	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P25	Myrtleford - Workshop	Body\HOUSEKEEP	wash down loader and valve area			20/08/2020	3746	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P25	Myrtleford - Workshop	Body\MOUNTS	weld cracks in hyd tank			20/08/2020	3746	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P25	Myrtleford - Workshop	Body\MOUNTS	replace hydraulic tank mount bolts			20/08/2020	3746	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P25	Myrtleford - Workshop	Body\PANELS	fit engine cover and redo wiring etc T9570			20/08/2020	3746	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P25	Myrtleford - Workshop	Insp\UNT INSP	check over and sign off pending job list replace rose joints			20/08/2020	3746	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P25	Myrtleford - Workshop	Body\HOUSEKEEP	remove slop from linkages rerease			15/08/2020	3746	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P25	Myrtleford - Workshop	Chassis\DAMAGE	remove boom top pin to have a new one made			15/08/2020	3746	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P25	Myrtleford - Workshop	Chassis\DAMAGE	weld cracks in boom and pipe brackets			15/08/2020	3746	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P25	Myrtleford - Workshop	DrCabRep\DAMAGE	remove/refit front window			15/08/2020	3746	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P25	Myrtleford - Workshop	Body\DAMAGE	straighten front grill			15/08/2020	3746	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P25	Myrtleford - Workshop	Chassis\HYDRAULICS	weld cracks in grab			15/08/2020	3746	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P25	Myrtleford - Workshop	Hydraulics\VALVES	Remove and fit lag ram swivel kit T9351			15/08/2020	3746	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P25	Myrtleford - Workshop	Engine\PAINT/REST	Wash Engine and Clean Cab		wash engine	15/08/2020	3746	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P25	Myrtleford - Workshop	Engine\ENG TUNE	Tune Engine			15/08/2020	3746	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P25	Myrtleford - Workshop	Chassis\HYDRAULICS	Check boom Pins and Bushes and cracksT9526			15/08/2020	3746	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P25	Myrtleford - Workshop	Hydraulics\RAM	Check all Boom RamsT9713T9788			15/08/2020	3746	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P25	Myrtleford - Workshop	Hydraulics\VALVES	Check all Hydraulic Pressures		check all hyd pressures ok T9786	15/08/2020	3746	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P25	Myrtleford - Workshop	Body\HOUSEKEEP	Check / replace walk way Tape			15/08/2020	3746	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P25	Myrtleford - Workshop	Body\REFLECTORS	Fit Reflective tape		fit tape to walk ways	15/08/2020	3746	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P25	Myrtleford - Workshop	Elect\WORK LIGHT	Check all work lights T9582			15/08/2020	3746	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P25	Myrtleford - Workshop	DrCabElect\AIR CON	Check Air con and Heaters		replaced heater check aircon system lokl	15/08/2020	3746	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P25	Myrtleford - Workshop	Hydraulics\VALVES	remove and fit lag ram swivel kit			12/08/2020	3746	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P25	Myrtleford - Workshop	Body\FUEL TANK	remove fuel tank and weld cracks			12/08/2020	3746	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P25	Myrtleford - Workshop	Elect\ELECT P&W	Fuel transfer pump not working			11/08/2020		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P25	Myrtleford - Workshop	Engine\BELTS/TENS	belt idler bearig gone - making bad noise			11/08/2020		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P25	Myrtleford - Workshop	Elect\ELECT P&W	transfer pump not working Engine Protection Screen has come off			11/08/2020		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P25	Myrtleford - Workshop	Body\PANELS	to be straightened and refit			11/08/2020		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P25	Myrtleford - Workshop	Hydraulics\VALVES	Rubber boots around controls need replacing getting too hot.			11/08/2020		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P25	Myrtleford - Workshop	Hydraulics\SWIVEL LEAKS	rotary coupling in turret leaking			11/08/2020		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P25	Myrtleford - Workshop	Chassis\Boom	Grab lower ram pin bolt broken			11/08/2020		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P25	Myrtleford - Workshop	Elect\ELECT P&W	Fuel transfer pump not working T9614			11/08/2020		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P25	Myrtleford - Workshop	Engine\BELTS/TENS	belt idler bearig gone - making bad noise			11/08/2020		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P25	Myrtleford - Workshop	Elect\ELECT P&W	transfer pump not working Engine Protection Screen has come off			11/08/2020		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P25	Myrtleford - Workshop	Body\PANELS	to be straightened and refit			11/08/2020		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P25	Wodonga - Workshop	DrCabRep\HOUSEKEEP	JOY STICKS NEED RUBBER BOOTS		RR's pre Jan 20 (system clean out) 05/08/20	06/08/2020	3746	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Wodonga Workshop	PRENTICE
P25	Wodonga - Workshop	DrCabRep\HOUSEKEEP	SERVO'S NEED RUBBER BOOTS		refer job 298784 double	06/08/2020	3746	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Wodonga Workshop	PRENTICE
P25	Wodonga - Workshop	DrCabRep\HOUSEKEEP	RUBBER BOOTS MISSING OFF SERVOS.		refer job 298784	06/08/2020	3746	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Wodonga Workshop	PRENTICE
P25	Wodonga - Workshop	DrCabRep\HOUSEKEEP	RAIN LEAKING ON TO FLOOR OF CAB		new ram fitted	06/08/2020	3746	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Wodonga Workshop	PRENTICE
P25	Wodonga - Workshop	Body\FUEL TANK	REQUIRES LITE WITH AUX. FUEL TANK BEFORE CHRISTMAS.			06/08/2020	3746	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Wodonga Workshop	PRENTICE
P25	Wodonga - Workshop	DrCabRep\HOUSEKEEP	NEEDS RUBBER BOOTS ON HAND CONTROLS		refer 128018	06/08/2020	3746	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Wodonga Workshop	PRENTICE
P25	Wodonga - Workshop	Hydraulics\OIL LEAK	LH HAND PIECE LEAKING OIL AT HOSE		replace LH and RH servo seals tighten all fittings and hoses	06/08/2020	3746	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Wodonga Workshop	PRENTICE
P25	Wodonga - Workshop	Hydraulics\OIL LEAK	CHECK HOSES ON GRAB LEAKING, SOME NEED NEW FITTINGS		rechecked all eood	06/08/2020	3746	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Wodonwa Workshop	PRENTICE
P25	Wodonga - Workshop	Hydraulics\VALVES	LHS JOY STICK STICKING AT TIMES JOY STICK STICKING.		refer 298790	06/08/2020	3746	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Wodonga Workshop	PRENTICE
P25	Wodonga - Workshop	Hydraulics\VALVES	REQUIRE RUBBER BOOTS PUT ON JOY STICKS		replace iovstick ball ioint	06/08/2020	3746	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Wodonwa Workshop	PRENTICE
P25	Wodonga - Workshop	Elect\TRL LIGHTS	need better reverse lights		inspected all good 4 fitted to back	06/08/2020	3746	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Wodonga Workshop	PRENTICE
P25	Wodonga - Workshop	DrCabElect\INST/GAUGE	speedo not working		road test and check spread on gps on phone all ok boosters and brake hoses have been replace and LHR 2 cam adjuster also	06/08/2020	3746	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Wodonga Workshop	PRENTICE
P25	Wodonga - Workshop	Brakes\BRAKE ADJ	brakes not good, need looking at		road test + check brakes + readiust + recheck all ok	06/08/2020	3746	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Wodonwa Workshop	PRENTICE
P25	Wodonga - Workshop	Elect\ELECT P&W	side light needs replacing		inspected all good	06/08/2020	3746	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Wodonga Workshop	PRENTICE
P25	Wodonga - Workshop	Elect\TAIL LIGHT	tail lights not working and side lights		inspected all good new window and rubber fitted	06/08/2020	3746	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Wodonga Workshop	PRENTICE
P25	Wodonga - Workshop	DrCabRep\WINDSCREEN	water leaking thru front window, all over the floor		refer 129055	06/08/2020	3746	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Wodonwa Workshop	PRENTICE
P25	Wodonga - Workshop	DrCabRep\SEAT	seat in loader needs looking at			06/08/2020	3746	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Wodonga Workshop	PRENTICE
P25	Wodonga - Workshop	Hydraulics\RAM	replace grab ram fitting got yellow rag around it log strit		inspected all good	06/08/2020	3746	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Wodonga Workshop	PRENTICE
P25	Wodonga - Workshop	Body\DAMAGE	point missing off grab		inspected all good	06/08/2020	3746	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Wodonga Workshop	PRENTICE
P25	Wodonga - Workshop	Elect\ELECT P&W	sender light not working		check dash lights all ok	06/08/2020	3746	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Wodonga Workshop	PRENTICE
P25	Wodonga - Workshop	DrCabRep\SEAT	truck need new seat		check seat ok at this stage	06/08/2020	3746	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Wodonga Workshop	PRENTICE
P25	Wodonga - Workshop	Body\TRL LEGS	possible broken leg pin		inspected all good	06/08/2020	3746	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Wodonga Workshop	PRENTICE
P25	Wodonga - Workshop	DrCabRep\HOUSEKEEP	LHS console strut broken		ok	06/08/2020	3746	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Wodonga Workshop	PRENTICE
P25	Wodonga - Workshop	Body\DAMAGE	tip of log grab has broken off		inspected all good	06/08/2020	3746	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Wodonga Workshop	PRENTICE
P25	Wodonga - Workshop	Cooling\COOL LEAKS	heater hoses leaking coolant			06/08/2020	3746	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Wodonga Workshop	PRENTICE
P25	Wodonga - Workshop	DrCabRep\CONSUMABLE	no bottom door seal		ok	06/08/2020	3746	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Wodonga Workshop	PRENTICE
P25	Wodonga - Workshop	DrCabRep\CONSUMABLE	arm rests in loader need replacing		replace arm rest	06/08/2020	3746	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Wodonga Workshop	PRENTICE
P25	Wodonga - Workshop	DrCabRep\DOOR LOCK	loader door latch is loose		ok	06/08/2020	3746	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Wodonga Workshop	PRENTICE
P25	Wodonga - Workshop	Engine\DAMAGE	engine oil fill pipe needs replacing - over expanded at top			06/08/2020	3746	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Wodonga Workshop	PRENTICE
P25	Wodonga - Workshop	Body\DAMAGE	hand rail on loader has broken bolt at rear		ok	06/08/2020	3746	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Wodonga Workshop	PRENTICE
P25	Wodonga - Workshop	Hydraulics\HYD LEAKS	LHS lift ram seal ox leaking oil onto walking deck			06/08/2020	3746	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Wodonga Workshop	PRENTICE
P25	Wodonga - Workshop	Engine\FUEL TANK	loader motor is running rough - injcter, fuel issue		replaced inner and outer air fitters	06/08/2020	3746	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Wodonga Workshop	PRENTICE
P25	Wodonga - Workshop	DrCabRep\ELECT P&W	upgrade interior light T9457. upgrade interior light		fitted LED light	06/08/2020	3746	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Wodonga Workshop	PRENTICE
P25	Wodonga - Workshop	DrCabRep\ELECT P&W	no lights working in switch panel, below key			06/08/2020	3746	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Wodonga Workshop	PRENTICE
P25	Wodonga - Workshop	DrCabRep\ELECT P&W	upgrade interior light		double	06/08/2020	3746	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Wodonga Workshop	PRENTICE
P25	Wodonga - Workshop	VehService\AS	Service Due in 15 hours		refer 126350	06/08/2020	3746	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Wodonga Workshop	PRENTICE
P25	Myrtleford - Workshop	Hydraulics\OIL LEAK	slew leaking hyd oil all over deck		iob 294284 refer 126350	31/07/2020	3693	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P25	Myrtleford - Workshop	Hydraulics\HYD LEAKS	slew leaving oil on platform		iob 294284	31/07/2020	3693	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE

						refer 126350											
P25	Myrtleford - Workshop	Engine\OIL LEAK	bad oil leak on deck			iob 294284	31/07/2020	3693	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE	
						refer 126350											
P25	Myrtleford - Workshop	Hydraulics\HYD LEAKS	slew motor leaking oil over platform			iob 294284	31/07/2020	3693	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE	
						refer 126350											
P25	Myrtleford - Workshop	Hydraulics\HYD LEAKS	slew leaking hyd oil over deck			iob 294284	31/07/2020	3693	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE	
						refer 126350											
P25	Myrtleford - Workshop	Hydraulics\HYD LEAKS	slew drive pressure weak and leaking oil			iob 294284	31/07/2020	3693	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE	
						refer 126350											
P25	Myrtleford - Workshop	Hydraulics\HYD LEAKS	slew motor leaking			iob 294284	31/07/2020	3693	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE	
			excessive oil leak from slew motor														
P25	Myrtleford - Workshop	Hydraulics\HYD LEAKS	needs 20 liters hydraulic oil			refer126350	31/07/2020	3693	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE	
P25	Albury - Workshop	Workshop\MOVE ASSET	load up ute with tools and slew motor				03/07/2020	3693	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Workshop\MOVE ASSET	travel to Wodonga yard and fit				03/07/2020	3693	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
			repaired several other leaks at valve banks														
P25	Albury - Workshop	Hydraulics\OIL LEAK	replaced slew and test for leaks				03/07/2020	3693	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Workshop\MOVE ASSET	returned to Albury depot, degreased used slew motor, ute and washed				03/07/2020	3693	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Hydraulics\OIL/FILTER	replaced o-ring at slew valve. Tightened hoses and fittings				11/06/2020		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Workshop\CLEAN	cleaned up and tested				11/06/2020		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Hydraulics\OIL/FILTER	topped up hydraulic tank				11/06/2020		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Workshop\MOVE ASSET	load required parts/tubes and drive over to Wodonga				04/06/2020	23632	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	VehService\BS	yard and service	VehService\BS			04/06/2020	23632	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Hydraulics\HYD LEAKS	replace elbow fitting in grab cylinder				04/06/2020		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Tumut - Workshop	Hydraulics\HOSES	Enzed to manufacture and replace hyd hoses				20/05/2020		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Wodonga Workshop	PRENTICE	
P25	Albury - Workshop	Hydraulics\HYD LEAKS	boom ram below cab leaking replace hose				16/05/2020	3585	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Workshop\TRL WALL	checked over machine				24/04/2020		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Engine\CONSUMABLE	topped up fluids				24/04/2020		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Hydraulics\HOUSEKEEP	tightened hydraulic fittings				24/04/2020		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Chassis\HOUSEKEEP	replaced grease nipples				24/04/2020		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
			get hoses made														
			travel to Laurel Hill hoses have wrong fitting														
			travel to Tumut														
			get hoses fixed														
P25	Tumut - Workshop	Hydraulics\BREAKDOWN	fit to prentice grab at change over				09/04/2020	2614	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE	
P25	Tumut - Workshop	Hydraulics\HOSES	replace hydraulic fittings and hoses				28/03/2020	3530	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE	
P25	Rosewood - Workshop	Chassis\DAMAGE	further attempt to fix thread on upper mount for main ram				27/03/2020	3525	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE	
P25	Rosewood - Workshop	Chassis\DAMAGE	fit and plumb main boom ram and send to print (scan)				27/03/2020	3525	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE	
			call out to Monterey Rd area, top (outter) pin on RH side main boom ran eye sheared off. (at base of ram)														
P25	Rosewood - Workshop	Hydraulics\BREAKDOWN	recover loader from stock and get back to Rosewood workshop				24/03/2020	3535	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE	
P25	Rosewood - Workshop	Hydraulics\RAM	remove good ram from P-14, but P-22 upper mount nut was unable to be removed due to damage to end of thread (most likely from installation). Worked on it for hours and go				24/03/2020	3535	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE	
P25	Myrtleford - Workshop	Air Con\AIR CON	Air con not working				13/03/2020	1148	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE	
P25	Tumut - Workshop	Chassis\DAMAGE	replace short leg pin with one from scan logging & MAKE UP HYD HOSE				08/03/2020	3401	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE	
P25	Tumut - Workshop	Hydraulics\OIL/FILTER	hydraulic filters small and large grease				08/03/2020	3401	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE	
P25	Tumut - Workshop	Engine\HOUSEKEEP	check coolant add 2liters				08/03/2020	3401	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE	
P25	Tumut - Workshop	VehService\BS	B Service/TUB073 TUB050	VehService\BS			08/03/2020	3401	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE	
P25	Tumut - Workshop	VehService\BS	Service Due	VehService\BS		service loader & remove grab ram for repairs	07/03/2020	3396	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE	
						leg pin replaced											
P25	Tumut - Workshop	Chassis\HYDRAULICS	2 leg pins need replacing			lonaer bottom pin reolaced oin machined bv scan	07/03/2020	3396	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE	
P25	Tumut - Workshop	Hydraulics\HOSES	lift hose need replacing			change blown lift hose	07/03/2020	3396	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE	
P25	Tumut - Workshop	Engine\OIL LEAK	change sump plug and washer				07/03/2020	3396	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE	
			Call Out To Montaray Road, Broken Leg Pin.														
			Remove Correct Pin From P14 & Take Some New Stud.														
P25	Rosewood - Workshop	Chassis\DAMAGE	Travel To Site & Replace Pin, Loader Has Been Modified & standard Pin Wont Fit Properly. Discussed With R. Toppin What Needs To Be Done In Tumut To Repair 100%				06/03/2020		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE	
P25	Tumut - Workshop	Elect\WORK LIGHT	broken light wire on dipper boom cable is too short or too many cable ties used around hydraulic hoses so it can't move and breaks - has blown fuse. 3x lights out			broken wires on dipper boom	05/03/2020		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE	
P25	Tumut - Workshop	Elect\WORK LIGHT	broken light wire on dipper boom			broken wires on lights on dipper boom	04/03/2020	3320	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE	
P25	Tumut - Workshop	DrCabReq\DOOR LOCK	weld door latch				01/03/2020		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE	
P25	Tumut - Workshop	Engine\HOUSEKEEP	check fluids etc				01/03/2020		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE	
P25	Tumut - Workshop	Engine\HOUSEKEEP	check fluids engine oil, coolant, hydraulic oil levels				01/03/2020	3337	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE	
P25	Tumut - Workshop	DrCabReq\DOOR LOCK	weld up door latch				01/03/2020	3337	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE	
			low fuel														
P25	Tumut - Workshop	Engine\FUEL TANK	refuel in bush				29/02/2020		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE	
P25	Rosewood - Workshop	Hydraulics\HOSES	replace metal oil line on dipper boom			call out to Rosewood, holed steel pipe on fly boom again	28/02/2020	3331	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE	
			replace metal oil line on dipper boom			call out to Rosewood, steel hydraulic pipe to dipper ram holed, leaking badly											
P25	Rosewood - Workshop	Hydraulics\OIL LEAK	leakine due to rusture			removed pipe from P14 and cleaned and fitted to P25	21/02/2020	3268	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE	
P25	Tumut - Workshop	Hydraulics\TP06	1x long hose from boom to grab is leaking oil onto truck and windscreen			replace hose on dipper boom	20/02/2020	3260	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE	
P25	Tumut - Workshop	DrCabReq\DOOR LOCK	door latch on frame of cab is broken			door latch	16/02/2020	3220	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE	
P25	Tumut - Workshop	Elect\WORK LIGHT	dipper boom work lights just the same on/off/on/off, blink, blink flash,flash LHS not on at all, RHS as above			lights on boom replace (one)	09/02/2020	3170	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE	
P25	Tumut - Workshop	Chassis\Boom	lift pin on lower boom mount moving lit back in tighten up grab screw				09/02/2020	3170	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE	
P25	Tumut - Workshop	Hydraulics\OIL LEAK	log grab has oil leak I can't tell if it a ram hose or is coming from rotator			tighten all hoses on boom and grapple and rotator replace	02/02/2020	3095	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE	
P25	Tumut - Workshop	Body\CHN/RLR/MN	please replace D shackle on grab chain			D shackle tightened loose bolts on lights	02/02/2020	3095	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE	
			Tighten All Hoses On Boom & Grapple & Rotator														
P25	Tumut - Workshop	Hydraulics\HYD LEAKS	MAKE UP HYD HOSES				02/02/2020	3095	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE	
P25	Tumut - Workshop	Body\CHN/RLR/MN	Replace D Shackle				02/02/2020	3095	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE	
P25	Tumut - Workshop	Elect\WORK LIGHT	Tighten Loose Bolts On Lights				02/02/2020	3095	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE	
						R&R 117393											
P25	Myrtleford - Workshop	Elect\ELECT P&W	Fuel transfer pump not working			transfer pump not working. Power to the switch on pump, needs new pump or switch end of pump	29/01/2020	3746	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE	
P25	Tumut - Workshop	Elect\ELECT P&W	transfer pump not working				24/01/2020	3025	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE	
P25	Tumut - Workshop	Hydraulics\RAM	Grab Ram Leaking Remove & Replace With Stock				24/01/2020		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE	
						ram flange missing bolts and leaking											
P25	Tumut - Workshop	Hydraulics\RAM	leak in seal on grab			fit new bolts tighten no leak detected	23/01/2020	3020	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE	
			ram flange missing bolts and leaking														
P25	Tumut - Workshop	Hydraulics\RAM	fit new bolts tighten no leak detected				23/01/2020	3020	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE	
			B Service														
P25	Rosewood - Workshop	VehService\BS	1000 hrs service needs to be comoleted	VehService\BS			18/01/2020	2990	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE	
P25	Rosewood - Workshop	Body\HOUSEKEEP	grease and check over loader				17/01/2020	2980	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE	
						Straighten & weld back into shape.											
P25	Tumut - Workshop	Body\DAMAGE	Walking deck damaged by log			Rewire clearance liehts behind damaaed section	14/01/2020		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE	
P25	Tumut - Workshop	Engine\BELTS/TENS	Belt tensioner seized			Removed & replaced tensioner and belt. Adjust A/C belt tension	20/12/2019	2924	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE	
P25	Tumut - Workshop	Hydraulics\RAM	Re-shape, cut, grind & weld grapple				20/12/2019	2924	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE	
P25	Tumut - Workshop	Chassis\DAMAGE	log grab tips too sharp				19/12/2019	2924	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE	
P25	Tumut - Workshop	Chassis\HYDRAULICS	back LHS leg ram pin has broken keeper bolt				19/12/2019	2924	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE	
P25	Tumut - Workshop	Hydraulics\OIL/FILTER	hydraulic oil cooler not working - oil and hoses are very very hot and also both control console in cab				19/12/2019	2924	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE	
P25	Tumut - Workshop	Engine\BELTS/TENS	belt idler bearig gone - making bad noise				19/12/2019	2924	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE	
P25	Tumut - Workshop	VehService\BS	B SERVICE	VehService\BS			07/12/2019	2800	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE	
P25	Tumut - Workshop	VehService\AS	Service Due in 15 hours				29/11/2019	2785	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE	
P25	Tumut - Workshop	Hydraulics\RAM	pin replaced front left leg				29/11/2019	2785	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE	
P25	Rosewood - Workshop	Hydraulics\HYD LEAKS	slew motor leaking bad getting unsafe to walk on deck (FIT NEW RECO SLEW MOTOR) SCAN LOG TUMUT. slew motor leaking bad getting unsafe to walk on deck				29/11/2019	2785	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE	
P25	Rosewood - Workshop	Workshop\MOVE ASSET	CALL OUT TO BUSH				26/11/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE	
						REPLACED BELT, COULD NOT GET A/C BELT BACK ON OVER FAN											
						BACK TO WORKSHOP ! REMOVED ENGINE FAN ASSAMBLY & FITTED BELT BEHU-IND											
P25	Rosewood - Workshop	Air Con\AIR CON	THROWN MEAN BELT			RE ASSEMBLED & FITTED A/C BELT	26/11/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE	
			rear right leg pin replaced														
P25	Albury - Workshop	Hydraulics\RAM	rod end ram				23/11/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Rosewood - Workshop	DrivLine\SHOCK ABS	RHS back shock needs replacing				14/11/2019	2625	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE	
P25	Rosewood - Workshop	Engine\BELTS/TENS	belts swelling on aircon again				14/11/2019	2625	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE	
P25	Rosewood - Workshop	Hydraulics\RAM	oil leak left hand ram main boom				14/11/2019	2625	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE	
P25	Rosewood - Workshop	VehService\BS	B SERVICE	VehService\BS			14/11/2019	2625	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE	
P25	Tumut - Workshop	Hydraulics\HYD LEAKS	leg ram leaking remove drop at scan get o-rings for fittings refit leg ram leaking badly from bolted flange organise another ram from Rosewood				20/10/2019	2436	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE	
P25	Tumut - Workshop	Hydraulics\HOUSEKEEP	Service grease grab screw loose in lift				20/10/2019	2436	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE	
P25	Tumut - Workshop	DrCabElect\ELECT P&W	ram pin tighten light in cab				20/10/2019	2436	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE	
P25	Tumut - Workshop	VehService\BS	B Service	VehService\BS			20/10/2019	2436	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE	
P25	Tumut - Workshop	Hydraulics\RAM	right back ram leaking in leg				16/10/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE	
P25	Tumut - Workshop	Hydraulics\MOTOR	slew motor needs looking at				16/10/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE	
P25	Tumut - Workshop	Hydraulics\RAM	lift ram pin moving sideways in boom housing				10/10/2019	2364	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE	
P25	Albury - Workshop	Body\TRL LEGS	back leg pin needs replace LHS rear				08/10/2019	2311	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Tumut - Workshop	Hydraulics\HYD LEAKS	slew motor leaking				14/09/2019	2160	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE	
P25	Tumut - Workshop	VehService\AS	due for Service in 40hours				14/09/2019	2160	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE	
P25	Tumut - Workshop	Hydraulics\RAM	pin in grab needs replacing& fit c/o grab ram. pin in grab needs replacing				10/09/2019	2108	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE	
P25	Rosewood - Workshop	Chassis\Boom	Grab lower ram pin bolt broken			remove bolt and replace check operation	04/09/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Wodonga Workshop	PRENTICE	
P25	Myrtleford - Workshop	Hydraulics\MOTOR	fit seal kit to slew motor				24/08/2019	2012	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE	
P25	Myrtleford - Workshop	Chassis\HYDRAULICS	repair light ram boss cracks top and bottom				24/08/2019	2012	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE	
P25	Myrtleford - Workshop	Chassis\HYDRAULICS	repair main boom pipe mounts cracked				24/08/2019	2012	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE	
P25	Myrtleford - Workshop	Chassis\HYDRAULICS	repair main boom cracks/gussets to outer boom ram				24/08/2019	2012	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE	
P25	Myrtleford - Workshop	Chassis\HYDRAULICS	repair hyd tank mounts cracks and bolts				24/08/2019	2012	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE	
P25	Myrtleford - Workshop	Chassis\CHAS CRACK	repair a frame cracks behind L-25 cab				24/08/2019	2012	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE	
P25	Myrtleford - Workshop	Body\MOUNTS	repair cab screen guard cracks and mounts				24/08/2019	2012	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE	
P25	Myrtleford - Workshop	Chassis\HOUSEKEEP	repair grab cracks				24/08/2019	2012	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE	
P25	Myrtleford - Workshop	Body\MOUNTS	repair outer boom light cracks				24/08/2019	2012	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE	
P25	Myrtleford - Workshop	Hydraulics\RAM	repair all 4 leg ram boss				24/08/2019	2012	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE	
P25	Myrtleford - Workshop	Elect\BATTERY	jump start P25 (MAE)(T7015)				24/08/2019	2012	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE	
						Removed hydraulic test guages from cabin x3											
P25	Wodonga - Workshop	Body\HOUSEKEEP	Checkover			Removed test ports from hydraulic valves	17/08/2019	22001	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Wodonga Workshop	PRENTICE	
P25	Tumut - Workshop	VehService\AS	Service Due soon				01/08/2019	1961	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE	
P25	Rosewood - Workshop	Body\DAMAGE	front left side leg pivot pin broken				31/07/2019	743700	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE	
P25	Rosewood - Workshop	Body\DAMAGE	cut up and remove				31/07/2019	743700	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE	
P25	Rosewood - Workshop	Body\DAMAGE	replace leg pin and grease throughly				31/07/2019	743700	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE	
P25	Wodonga - Workshop	Hydraulics\RAM	Prepare and weld grab				23/06/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Wodonga Workshop	PRENTICE	
P25	Wodonga - Workshop	DrCabElect\ELECT P&W	Fit interior strip lighting in cab				23/06/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Wodonga Workshop	PRENTICE	
P25	Albury - Workshop	DrCabReq\ELECT P&W	upgrade interior light				21/06/2019	1653	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Hydraulics\RAM	repair broken tip on log grab/or cut off T-piece				21/06/2019	1653	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	DrCabReq\ELECT P&W	no lights working in switch panel, below key				21/06/2019	1653	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Rosewood - Workshop	Hydraulics\RAM	weld boom				16/06/2019	2409	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE	
P25	Rosewood - Workshop	DrCabElect\HOUSEKEEP	electric light in cab				16/06/2019	2409	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE	
P25	Rosewood - Workshop	Chassis\HOUSEKEEP	grease				16/06/2019	2409	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE	
P25	Rosewood - Workshop	Workshop\CLEAN	clean up workshop				16/06/2019	2409	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE	
P25	Rosewood - Workshop	VehService\BS	B Service	VehService\BS			16/06/2019	2409	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE	
P25	Albury - Workshop	VehService\QS	Service Due at 1600				15/06/2019	1607	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Hydraulics\RAM	reweld pipe brackets on boom				15/06/2019	1607	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Hydraulics\RAM	cut off T shape tip on log grab				15/06/2019	1607	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	DrCabReq\ELECT P&W	upgrade interior light				15/06/2019	1607	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
			pressures need checking slow														
P25	Albury - Workshop	Hydraulics\RAM	wav too slow				07/06/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	DrivLine\WHEEL BRGS	bearing needs replacing in eye of dipper boom ram				07/06/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	

					replace (have one mode) 1 inch main (middle hose)												
P25	Rosewood - Workshop	Hydraulics\HOSES	middle tripple pump hose leaking		hvdraulic line under loader	25/05/2019	1467	Fault	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE		
P25	Rosewood - Workshop	DrCabRep\SEAT	replace arm rests			25/05/2019	1467	Fault	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE		
P25	Rosewood - Workshop	DrCabRep\HOUSEKEEP	LHS console strut broken			25/05/2019	1467	Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE		
P25	Rosewood - Workshop	DrCabRep\DOOR LOCK	door latch is very loose			25/05/2019	1467	Fault	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE		
P25	Rosewood - Workshop	Hydraulics\HYD LEAKS	slew motor leaking oil on deck			25/05/2019	1467	Fault	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE		
P25	Rosewood - Workshop	Elect\ELECT P&W	rewire up "hard switch" for loader platform illumination to work with times switch so either can be used			25/05/2019	1467	Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE		
P25	Rosewood - Workshop	VehService\BS	B Service	VehService\BS		25/05/2019	1467	Service	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE		
P25	Rosewood - Workshop	Elect\ELECT P&W	rewire up "hard switch" for loader platform illumination to work with times switch so either can be used			25/05/2019	1467	Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE		
P25	Rosewood - Workshop	Hydraulics\HOSES	replace (have one mode) 1 inch main (middle hose) hydraulic line under loader			25/05/2019	1467	Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE		
P25	Rosewood - Workshop	DrCabElect\HEATER REP	replaced heater hoses			25/05/2019	1467	Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE		
P25	Rosewood - Workshop	VehService\BS	B Service	VehService\BS		25/05/2019	1467	Service	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE		
P25	Albury - Workshop	VehService\AS	A Service			24/05/2019		Service	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Rosewood - Workshop	Elect\BATTERY	change flat battery			12/04/2019		Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE		
P25	Rosewood - Workshop	VehService\BS	Carry out B service (completed)	VehService\BS		12/04/2019		Service	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE		
P25	Albury - Workshop	Hydraulics\PUMP	NO MAIN / GRAPPLE HYDRAULIC FUNCTION.		REBUILD HYD PUMP.	11/04/2019		Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	DrivLine\WHEEL BRGS	bearing needs replacing in eye of dipper boom ram			10/04/2019	1272	Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
			remove staff motor out of work ute														
			get paperwork out of ute														
P25	Albury - Workshop	Workshop\CLEAN	Simon was unable to do for some reason			07/04/2019		Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
			travel fold up loader blank slew line														
P25	Rosewood - Workshop	Hydraulics\OIL LEAK	return to vard remove replace slew motor and hydraulic return filter run & test			06/04/2019		Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE		
P25	Rosewood - Workshop	Engine\FUEL TANK	repair fuel tank backets			16/03/2019	1145	Fault	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE		
			weld up fuel tank mounts														
			make up new bolt with "cathcas" on need to stop spinning in inaccessible area and fit														
P25	Rosewood - Workshop	Engine\FUEL TANK	#this vehicle must have tank removed and repaired thoroughly			16/03/2019	1145	Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE		
P25	Albury - Workshop	Workshop\MOVE ASSET	Fold-up machine for transport			06/03/2019		Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Elect\DRV LIGHT	fix driving light			26/02/2019	767484	Fault	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	DrCabRep\SEAT	truck need new seat			26/02/2019	767484	Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
			replaced hyd. Slew motor with rebuilt unit														
			replaced o-rings, degreased and washed down deck and slew motor(TS246)														
			checked hyd, functions for leaks														
			checked hyd oil level - ok														
P25	Albury - Workshop	Hydraulics\MOTOR	cleaned up after job completion			22/02/2019	1044	Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
			oil sample														
			hyd filter														
P25	Albury - Workshop	Engine\OIL SAMPLE	topped up hyd oil			17/02/2019	21003	Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
			Service														
P25	Albury - Workshop	VehService\BS	fit neco grab swivel	VehService\BS		17/02/2019	21003	Service	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Body\DAMAGE	Welded new tip on crab tynes			14/02/2019	970	Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Body\HYD LEAKS	oil leak on deck getting very bad. Point on grab damaging timber			13/02/2019	970	Fault	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Body\TRL LEGS	replaced RHR bottom leg pin (broken)			13/02/2019	20970	Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Hydraulics\HYD LEAKS	slew motor leaking oil over platform			09/02/2019	937	Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Body\TRL LEGS	RH leg pin bottom broken			09/02/2019	937	Fault	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Body\DAMAGE	paint missing off grab			09/02/2019	937	Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Hydraulics\HYD LEAKS	slew leaking hyd oil over deck			08/02/2019	921	Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Body\DAMAGE	tyne broken of grab again			08/02/2019	921	Fault	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Elect\ELECT P&W	sander light not working			08/02/2019	921	Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Body\TRL LEGS	replace R/R leg pin bolt			31/01/2019	874	Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Cooling\RADIATOR	top up coolant 4 lts			30/01/2019	864	Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
			Service														
P25	Albury - Workshop	VehService\BS	measure radiator hose for reolacement order	VehService\BS		30/01/2019	864	Service	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
					replaced damaged boom pipe												
P25	Albury - Workshop	Hydraulics\DAMAGE	check boom steer pipes been hit		drop trailer off 1008 to access P20. shift trailer hook back up	27/01/2019	851	Fault	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
					broken shaft on slew motor												
					remove motor. No spare slew motor												
					remove slew motor from P20. wash												
					fit motor off P20 to P25. test ok												
					replace slew pinion												
P25	Albury - Workshop	Hydraulics\MOTOR	replace slew motor		wash down	27/01/2019	851	Fault	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Body\TRL LEGS	missing bolt LH lug leg pin		replaced broken lag pin keeper bolt	18/01/2019	775	Fault	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Elect\ELECT P&W	broken side lights		repaired marker lights	18/01/2019	775	Fault	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Body\DOOR LOCK	RH servo adjust lock u/s		replaced RH arm rest adjustment knob from parts in decommisioned machine	18/01/2019	775	Fault	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Elect\ELECT P&W	replaced operator safety lights control timer			18/01/2019	775	Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Hydraulics\RAM	Ram		washed LHR hyd ram + hoses. Replaced o-ring at ram fitting, washed + tested, no leaks to be found	13/01/2019	22723	Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
					slew requires replacing as seal is leaking												
P25	Albury - Workshop	Hydraulics\HYD LEAKS	slew leaving oil on platform		ewar for oinion has been ordered to replace as well	11/01/2019	22716	Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Air Con\AIR CON	aircon not working (hot air)			09/01/2019	687	Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	DrCabRep\SEAT	R/H side arm chair adjuster broken			09/01/2019	687	Fault	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Body\TRL LEGS	LHS back top leg pin bolt missing			28/12/2018		Fault	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
			REPLACE AIR FILTERS.														
P25	Albury - Workshop	Engine\AIR CLNR	REPLACE COVER FOR AIR FILTERS			22/12/2018	22618	Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	VehService\BS	Service	VehService\BS		21/12/2018	22614	Service	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Hydraulics\HOSES	SUPPLY HOSE AS PER SAMPLE			21/12/2018		Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Hydraulics\HYD LEAKS	hyd oil leak in grab ram		washed and degreased to check hyd leak	20/12/2018	20609	Fault	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Hydraulics\VALVES	tightened hyd fittings			20/12/2018	20609	Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Body\TRL LEGS	replaced broken leg pin bolt LHR			20/12/2018	20609	Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
			excessive movement in slew														
			removed cover and checked pinion gear - u/s														
			replaced with gear from P12														
			ordered replacement gear														
P25	Albury - Workshop	Hydraulics\PUMP	washed up and reolaced cover			13/12/2018		Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
			STAFFA MOTOR LEAKING														
P25	Albury - Workshop	Hydraulics\MOTOR	WORN SLEW PINION			13/12/2018		Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Hydraulics\RAM	repairs to grab ram fit seals & new shaft (rinlatech)		replaced damaged grab ram fitting	12/12/2018		Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
					slow slow,												
P25	Albury - Workshop	Hydraulics\MOTOR	Motor		reolaced rose ioints on slew/bedal	06/12/2018		Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Hydraulics\MOTOR	rotor on grab not working properly		replaced grapple rotator motor with rebuilt original unit	27/11/2018	20440	Fault	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Body\MOUNTS	tapped and cleaned out all mount holes			27/11/2018	20440	Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Body\DAMAGE	degreased and washed grapple			27/11/2018	20440	Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Hydraulics\HYD LEAKS	test and checked for leaks			27/11/2018	20440	Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Engine	Job Added From Invoice			23/11/2018	0	Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Wash\WASH	Truck or Trailer wash		dgreased and washed the machine	21/11/2018	20405	Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Engine\FUEL TANK	Fuel Tank & System		filled fire fighting unit with new fuel	21/11/2018	20405	Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Hydraulics\OIL LEAK	Oil Leaks		repaired oil leaks at valve bank	21/11/2018	20405	Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Hydraulics\OIL/FILTER	Oil/Filter		tested and topped up hydraulic oil 40lts approx	21/11/2018	20405	Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Body\TRL DOORS	Trailer Rear Doors			16/11/2018		Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	VehService\QS	due for a service			16/11/2018		Service	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
					replaced broken end on grab												
P25	Albury - Workshop	Body\DAMAGE	tighten - broken off		repairs to spare grab ram (rinlatech)	15/11/2018	20374	Fault	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Myrtleford - Workshop	Hydraulics\MOTOR	drop off hyd motor to Rinlatech			13/11/2018		Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE		
			replaced grab rotator motor														
			degreased and washed														
			tested for leaks - ok														
P25	Albury - Workshop	Hydraulics\MOTOR	tozoed uo hyd oil (40 liters aporox.)			09/11/2018	20347	Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Hydraulics\STCH GUARD	Stretch Guard		removed S/hand rotator from P20, wahsed and replaced P25 rotator on grapple- test functions (ok) degreased and wahsed.	07/11/2018	20330	Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
					checked for hydraulic oil leak in grapple												
					wahed and degreased												
P25	Albury - Workshop	Hydraulics\HYD LEAKS	Hydraulic Leaks		neco spare grab hose swivel (rinlatech)	07/11/2018	20336	Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	DrCabRep\DOOR LOCK	Door Lock, Latch etc		fit temporary door latch	07/11/2018	20325	Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Hydraulics\MOTOR	rotator in grab sometime not working			06/11/2018	329	Fault	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
					ORDERED DOOR LATCH AND STRIKER PIN												
P25	Albury - Workshop	DrCabRep\DOOR LOCK	DOOR LATCH ON LOADER NEEDS LOOKING AT. SOMETIMES COMES OPEN.		Reolaced door latch + striker	06/11/2018	20388	Fault	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	DrCabElect\RADIO	replaced CHF handpiece		completed	03/11/2018	309	Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	DrCabElect\RADIO	UHF needs looking at not working real good		replaced UHF handpiece	01/11/2018	303	Fault	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Hydraulics\HYD LEAKS	repaired hydraulic leak at grab open pressure pipe to valve bank			01/11/2018	303	Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	DrCabElect\RADIO	replaced UHF handpiece		A SECOND MIC HAD TO BE FITTED AS SOMEONE HAD SWAPPED THE NEW ONE WITH AN OLD.	01/11/2018	303	Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	DrCabRep\DOOR LOCK	door on loader not shutting properly		straightened door striker and test	30/10/2018		Fault	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
					washed and degreased grapple - found grapple cylinder leaking												
P25	Albury - Workshop	Hydraulics\HYD LEAKS	repair oil leak in grapple		reolaced	30/10/2018		Fault	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Hydraulics\VALVES	replaced hyd. Coupling up inside grapple			27/10/2018	20279	Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Hydraulics\HOSES	replaced one hyd. Hose			27/10/2018	20279	Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Hydraulics\AIR FITTIN	replaced o-rings on fittings			27/10/2018	20279	Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Hydraulics\OIL LEAK	washed and trsted for oil leaks			27/10/2018	20279	Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Workshop\CLEAN	cleaned up after job completion			27/10/2018	20279	Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Tynes\DRV TYRES	LHS back drive tynes need replacing.			24/10/2018		Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	BEAUREPAIRES - 4	PRENTICE		
P25	Albury - Workshop	Hydraulics\HYD LEAKS	repaired hyd leak			19/10/2018	20219	Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Hydraulics\HOSES	welded broken bracket for hyd hoses			19/10/2018	20219	Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Hydraulics\HOSES	degreased and washed			19/10/2018	20219	Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Hydraulics\VALVES	tightened hyd clamps			19/10/2018	20219	Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Body\DAMAGE	tightened RH leg pin out			19/10/2018	20219	Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Hydraulics\MOUNTS	secured hydraulic pipe mounts			19/10/2018		Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Hydraulics\HYD LEAKS	hyd oil leak in top of boom (pipe) fitting			19/10/2018	20216	Fault	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Hydraulics\HYD LEAKS	hyd oil leak in grab somewhere			19/10/2018	20216	Fault	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Engine	Job Added From Invoice			18/10/2018	0	Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Engine\OIL SAMPLE	oil sample taken			17/10/2018	20201	Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	VehService\BS	Service	VehService\BS		17/10/2018	20201	Service	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Body\DAMAGE	RHS back leg pin bolt broken top pin		turned pin and replaced broken bolt	16/10/2018	189	Fault	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Brakes	Job Added From Invoice			14/10/2018	0	Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Body\REFLECTORS	oversize sign			12/10/2018		Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	DrCabElect\INST/GAUGE	dash lights			12/10/2018		Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Body\DAMAGE	weld crack in grab			10/10/2018	167	Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Body\DAMAGE	weld - replace tips on grab			10/10/2018	167	Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Hydraulics\HOSES	replace spade hydraulic hose			10/10/2018	167	Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Hydraulics\OIL/FILTER	top up hyd oil			10/10/2018	167	Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Air Con\AIR CON	REPLACE AC THERMO FAN.			09/10/2018	155	Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Engine\BELTS/TENS	replaced fan belt and test run			06/10/2018	20146	Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Engine\BELTS/TENS	refit fan guard			06/10/2018	20146	Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Workshop\MOVE ASSET	pick up parts			06/10/2018		Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Hydraulics\HOSES	supply hose as per sample			05/10/2018		Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Engine	Job Added From Invoice			25/09/2018	0	Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Engine\BELTS/TENS	belts broken			23/09/2018	32	Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	DrivLine\WHEEL BRGS	removed fan hub, check bearings etc.			23/09/2018	32	Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Engine\WATER PUMP	replaced water pump, heater tap and belts			23/09/2018	32	Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P25	Albury - Workshop	Wash\WASH	washed engine			23/09/2018	32	Repair	Completed	Greenfreight Loggina NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		

P25	Albury - Workshop	Engine\RADIATOR	ordered condensor fan			23/09/2018	32	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Engine\BELTS/TENS	belts broken			22/09/2018	32	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Workshop	Job Added From Invoice			22/09/2018	0	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\HYD LEAKS	hyd oil leak on top of main boom all wet on top			19/09/2018	19994	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Engine\AIR CLNR	replaced both air cleaners			19/09/2018	19994	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	VehService\85	B Service Due 10,000	VehService\85		19/09/2018	19994	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
			Assisted replaced hyd hoses												
P25	Albury - Workshop	Hydraulics\HOSES	Deeneased and washed			15/09/2018	19976	Reoair	Completed	Greenfreiaht Loneinne NSW	LOADPRENT	Albury	ALR	Albury Workshoo	PRENTICE
			LHS back leg pin broken		replaced broken LHR leg rod end pin										
P25	Albury - Workshop	Body\DAMAGE	repair soare arab ram. LHS back lee oin broken		ordered reolacements	13/09/2018	19960	Fault	Completed	Greenfreiaht Loneinne NSW	LOADPRENT	Albury	ALR	Albury Workshoo	PRENTICE
P25	Albury - Workshop	Hydraulics\PUMP	Degreased & washed pump from loader			12/09/2018	9952	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\PUMP	replaced hyd pump			11/09/2018	9952	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\VALVES	replaced flex drive and adaptor (seized)			11/09/2018	9952	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\OIL/FILTER	drained and replace hyd oil (120 lts approx.)			11/09/2018	9952	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\OIL/FILTER	replaced hyd return filter			11/09/2018	9952	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\OIL/FILTER	replaced pilot pressure filter			11/09/2018	9952	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\PUMP	replaced all o-rings to pump			11/09/2018	9952	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Wash\WASH	washed down after job completion			11/09/2018	9952	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\MOTOR	starter and tested hyd			11/09/2018	9952	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Workshop\CLEAN	cleaned after job completion			11/09/2018	9952	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\HOSES	REPLACE WORN HOSES			11/09/2018	9952	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Elect\WORK LIGHT	fly boom lights not working			04/09/2018	9910	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Elect\WORK LIGHT	one on R/H side ram not working			04/09/2018	9910	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\PUMP	HYDRAULIC PUMP LEAKING @ FRONT SEAL.			04/09/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\PUMP	REPLACE PUMP DRIVE PLATE AND SHAFT			04/09/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\RAM	Replaced grapple ram			04/09/2018	9941	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
			Heated & straightened grab plate behind ram												
P25	Albury - Workshop	Body\DAMAGE	(bend new ram would fit)			04/09/2018	9941	Reoair	Completed	Greenfreight Loneinne NSW	LOADPRENT	Albury	ALR	Albury Workshoo	PRENTICE
P25	Albury - Workshop	Hydraulics\HOSES	Adjusted hose fittings at rotary coupling			04/09/2018	9941	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Elect\ELECT P&W	Replaced damaged lights wiring			04/09/2018	9910	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
					repaired fly boom work lights wiring										
					replaced fuse										
P25	Albury - Workshop	Elect\WORK LIGHT	fly boom lights not working		instructed operator	30/08/2018	9855	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\OIL/FILTER	Checked & topped up hyd. oil (20 lts approx.)			26/08/2018	9846	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	VehService\85	B Service	VehService\85		26/08/2018	9846	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	VehService\85	B SERVICE	VehService\85		26/08/2018		Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Myrtleford - Workshop	Hydraulics\OIL LEAK	TRIPPLE PUMP LEAKING			25/08/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
			HYD. OIL ON DECK. AROUND SLEW RING.												
P25	Myrtleford - Workshop	Hydraulics\OIL LEAK	FIT CHANGEOVER SLEW MOTOR			25/08/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\AIR FITTIN	tightened hyd. Fittings on boom and test (ok)		refer to job#185464	24/08/2018	9829	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\AIR FITTIN	check and repair oil leak on boom		tightened hyd. Fittings on boom and test (ok)	24/08/2018	9829	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	DrCabRep\HEATER REP	REPLACE HEATER TAP.			11/08/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
					removed and replaced outer boom ram										
P25	Albury - Workshop	Hydraulics\RAM	lift ram leaking		reolaced outer oin (manufactured at WEC)	08/08/2018	9697	Fault	Completed	Greenfreight Loneinne NSW	LOADPRENT	Albury	ALR	Albury Workshoo	PRENTICE
P25	Albury - Workshop	DrCabRep\DOOR LOCK	door still not shutting properly		repaired door latch striker and adjusted	08/08/2018	9697	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
			inspected heater not working												
			checked taps and lines from engine												
			removed rubbish, rags and equipment blocking heater - a/c system												
			dismantled heater core/evaporator box												
			found faulty cable and leaking tap - ordered												
			modified to temporarily run heater												
			purchased and made new cabin filter and assembled												
			topped up coolant and tested												
P25	Albury - Workshop	Air Con\HEATER	oreanised with Nich Martin reolacement hydraulic triole oumo and couolines			02/08/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Air Con\HEATER	heater not working. Heater taps are on		checked heater - heater control seems to be seized	31/07/2018	9634	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	DrCabRep\DOOR LOCK	door on loader not shutting properly		fit washers in hinges and adjusted door latch striker	31/07/2018	9634	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	VehService\85	B SERVICE	VehService\85		29/07/2018		Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\HYD LEAKS	rotary coupling in turret leaking			29/07/2018	9620	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	VehService\85	B Service due (9600 hrs)	VehService\85		29/07/2018	9620	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Engine\ENG COVER	repaired engine door lock			26/07/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Engine\BELTS/TENS	tightened loose a/c belt and check idler/tensioners			26/07/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\HOSES	replaced hyd hose to fly boom ram			26/07/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\OIL/FILTER	topped up hyd oil			26/07/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\HOUSEKEEP	degreased and washed engine and deck			26/07/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\HOSES	blown hose on boom - went Shelley with Enzed to replace/repair hose could not remove hose as of position on boom layout. Repaired hose to load crane up to get home to repla			25/07/2018	9358	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Workshop	Job Added From Invoice			25/07/2018	0	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Engine\ENG COVER	door on engine keep coming open			25/07/2018	9586	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Insp	Job Added From Invoice			04/07/2018	0	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\HYD LEAKS	hyd leak under right hand side			04/07/2018	9423	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\VALVES	replaced o-rings and seals in LH handpiece			04/07/2018	9423	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\VALVES	adjusted LH handpiece			04/07/2018	9423	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Body\MOUNTS	repaired broken "A" frame mount			01/07/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Workshop\CLEAN	Degreased and wash engine			01/07/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	VehService\85	B Service	VehService\85		01/07/2018		Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Chassis\Boom	REPLACE BROKEN BOOM PIN			28/06/2018	9343	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\HOSES	SUPPLY HOSE			27/06/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\HOSES	plumb up lift cylinder hoses, wash and topped up hyd oil			26/06/2018	9344	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Workshop\BREAKDOWN	prepare and pack for breakdown			20/06/2018	9343	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Workshop\MOVE ASSET	travel to Shelley-Walwa Rd job site			20/06/2018	9343	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\HOSES	plug rams and hoses			20/06/2018	9343	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\RAM	tie up RH main lift ram			20/06/2018	9343	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Workshop\MOVE ASSET	fold up machine onto truck			20/06/2018	9343	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Workshop\MOVE ASSET	take truck to parking area on Shelley - Walwa Rd			20/06/2018	9343	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Workshop\CLEAN	clean up oil spill at landing			20/06/2018	9343	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Workshop\MOVE ASSET	pick up Chris Mac from Wodonga engineering			20/06/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\RAM	replaced hyd fitting on grapple ram (tested - ok)			19/06/2018	9338	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\MOUNTS	repair hydarulics pipe clamp mount			16/06/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Workshop\MOVE ASSET	Travelled to a E Road at Shelley			15/06/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
			Removed pilot piston for main boom lift												
			Fried up piston and rotated. Tested.												
P25	Albury - Workshop	Hydraulics\RAM	Assisted in returning loaders and drivers to Shelley depot			15/06/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\DAMAGE	cap on hyd tank missing needs replacing			13/06/2018		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\HYD LEAKS	hyd oil all around cortivals under boots leaking			13/06/2018		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Body\TRL LEGS	repaired leg pin			10/06/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	DrCabRep\WINDSCREEN	water leaking thru front window, all over the floor			03/06/2018	9229	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	DrCabRep\SEAT	seat in loader needs looking at			03/06/2018	9229	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	DrCabElect\ELECT P&W	dash light need replacing		replaced dash lights	03/06/2018	9229	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Cooling\COOL LEAKS	repaired coolant leak			03/06/2018	9229	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Engine\HOUSEKEEP	degreased and washed engine bay			03/06/2018	9229	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	VehService\85	B Service	VehService\85		03/06/2018	9229	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\RAM	clean up grab ram			30/05/2018	9184	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Workshop\MOVE ASSET	ring Wayne De la Rue and organize ram to be picked up for Myrtleford			30/05/2018	9184	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\RAM	Replace grab RAM		Replaced damaged grab RAM	29/05/2018	9184	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\HYD LEAKS	look for hyd oil leak in grab			27/05/2018	9173	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\HYD LEAKS	hyd oil leak in (grab)			26/05/2018	9173	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\MOTOR	replaced slew motor			24/05/2018	9160	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Wash\WASH	washed and degreased loader and deck			24/05/2018	9160	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\OIL/FILTER	topped up hyd oil (40 liters approx.)			24/05/2018	9160	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\MOTOR	grease slew gear			24/05/2018	9160	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\MOTOR	degreased and washed old slew motor			24/05/2018	9160	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Chassis\CHAS CRACK	welded boom and base cracks.			24/05/2018	9160	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Workshop\CLEAN	cleaned up w/shop after job completion			24/05/2018	9160	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Workshop\CLEAN	ordered new pinion gear (old worn)			24/05/2018	9160	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Workshop\MOVE ASSET	pick up my trailer from M'ford and bring cylinders back to Albury			13/05/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Engine\FAULT CODE	dropping rev's when under load			09/05/2018	9026	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\OIL LEAK	slew leaking hyd oil all over deck			09/05/2018	9026	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
					stop engine light on										
					checked codes										
					modified pipe and replaced coolant level sensor with Kenworth sensor										
					replaced plug										
P25	Albury - Workshop	Engine\FAULT CODE	stop engine light staying on		tested	09/05/2018	9026	Fault	Completed	Greenfreight Loneinne NSW	LOADPRENT	Albury	ALR	Albury Workshoo	PRENTICE
P25	Albury - Workshop	Hydraulics\RAM	removed RH lift cylinder			06/05/2018	9006	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\RAM	fittef faulty cylinder and then removed and fitted cylinder from P20			06/05/2018	9006	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\HOUSEKEEP	washed and degreased			06/05/2018	9006	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\RAM	packaged 3 lift cylinders for repairs			06/05/2018	9006	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Engine\HOUSEKEEP	degrease and wash loader engine bay			04/05/2018	8992	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Engine\HOUSEKEEP	topped up hyd oil (40 lts approx)			04/05/2018	8992	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
			replaced fresh air filter												
P25	Albury - Workshop	Engine\FILTERS	replaced filter housing seal			04/05/2018	8992	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\OIL/FILTER	replaced hyd, return filter			04/05/2018	8992	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\PUMP	cleaned fine pump			04/05/2018	8992	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Engine\MOUNTS	tightened engine mount brackets			04/05/2018	8992	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\OIL LEAK	drained bell housing (hyd pump leak)			04/05/2018	8992	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	VehService\85	Service	VehService\85		04/05/2018	8992	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Body\DAMAGE	Strut on door come of haapened at coming ha R&R 109382. RHS lift RHM seal leaking all over deck		Replaced door strut	27/04/2018	8940	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Elect\ALT2 DR	diagnosed and replaced alternator			21/04/2018	8886	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Elect\BATTERY	chaged battery			21/04/2018	8886	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\HOSES	Hose on crob needs replacement on the two front side		Replaced grappled hose and cylinder fitting	18/04/2018	8869	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Body\HOUSEKEEP	topped up hyd oil			13/04/2018	8846	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Body\MOUNTS	tightened engine mount carriers			13/04/2018	8846	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Engine\OIL LEAK	drained bell housing			13/04/2018	8846	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	VehService\85	B Service	VehService\85		13/04/2018	8846	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\VALVES	replaced ball joints for slew control pedal with parts removed from de-commissioned machine			07/04/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	DrCabElect\UNST/GAUGE	speedo not working			05/04/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Elect\DRV LIGHT	need new driving lights			05/04/2018		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Engine\FAULT CODE	truck has a miss			05/04/2018		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Brakes\BRAKE ADJ	brakes not good, need looking at			05/04/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Elect\ELECT P&W	side light needs replacing			28/03/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Elect\TAIL LIGHT	tail lights not working and side lights			28/03/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Chassis\UNST/GAUGE	light around speedo not working			28/03/2018		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Chassis\KING PIN	replaced broken leg pin RHR ram rod end			21/03/2018	8576	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Workshop	Job Added From Invoice			17/03/2018	0	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Elect\ELECT P&W	L/H joy shock need looking at a lot of movement		adjusted joy stick and tested functions	16/03/2018		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE

			travel to and from worksite at Tintaldba													
			main lift not working													
			removed and checked operation of pilot system													
			removed and checked main lift spool													
P25	Albury - Workshop	Hydraulics\MOTOR	assembled and tested			15/03/2018	8640	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
			P25 broke down - no hyd functionsfor boom													
P25	Albury - Workshop	Hydraulics\MOTOR	rang Nich to let him kkno, in turn spoke to Ceasor. Started L-22/P22 in case it has to go to work. Trucks had been diverted to Shelly (P18). L22 to go out in morning			15/03/2018	8640	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
			travel to Hill top. Remove blown hose													
			took hoses on shelf in workshop. They were too short. Return to depot. Sent Butch to Tumut to make hose. Butch returned to depot. Travel back to Hill top. Fit hose													
			fill with hyd oil. Return to depot													
P25	Rosewood - Workshop	Body\HOSES	call out 3am. Oraanise and sent out soare loader on dav shift			15/03/2018	1262	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE	
			pulls and belts fall of radiator													
			collant leaking everywhere													
			major problem													
			check coolant, pulls and blets fall of radiator													
			collant leaking everywhere													
			major problem													
P25	Albury - Workshop	Cooling\COOL LEAKS	check coolant			09/03/2018	8609	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Engine\BELTS/TENS	replaced failed fan belt tensioner			09/03/2018	8609	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Engine\BELTS/TENS	fitted belts			09/03/2018	8609	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Engine\HOUSEKEEP	filled up coolant			09/03/2018	8609	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Engine\FAULT CODE	ran engine - opened thermostat			09/03/2018	8609	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Engine\HOUSEKEEP	checked and topped up coolant			09/03/2018	8609	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
			tested under load													
P25	Albury - Workshop	Workshop\MOVE ASSET	casked up loader			09/03/2018	8609	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Workshop	Job Added From Invoice			08/03/2018	0	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Hydraulics\RAM	Washdown grab ram			06/03/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Hydraulics\HYD LEAKS	oil leak in grab		hydraulic pump front seal leaking - drained bell housing	04/03/2018	8884	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
					checked starter motor - only 6 months old - can't fault											
P25	Albury - Workshop	Engine\START MOTR	starter motor playing up needs replacing		repaired grab tynes	04/03/2018	8884	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Chassis\Boom	tightens broken of grab needs replacing			04/03/2018	8884	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Body\MOUNTS	LHS back bottom leg pin broken			04/03/2018	8884	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Hydraulics\RAM	repaired grab oil leaks - replaced ram			04/03/2018	8884	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Engine\MOUNTS	tightened engine mount brackets			04/03/2018	8884	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Body\HOUSEKEEP	washed and tested grab			04/03/2018	8884	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	VehService/JBS	B Service Due (8600 hrs)	VehService/JBS		04/03/2018	8884	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
					joystick sticking - removed top knuckle from control lever											
P25	Albury - Workshop	DrCabRep\ELECT P&W	L/H side joy stick sticking		found ball in knuckle worn. Removed s/hand unit from P20 and fitted to P25. adjusted and tested	01/03/2018	8566	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Hydraulics\OIL LEAK	hyd oil leak in grab			01/03/2018	8566	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Hydraulics\RAM	grab needs piece putting back on of end of grab		checked and tighened hoses, washed grab	01/03/2018	8566	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	DrCabRep\ELECT P&W	dismantle LH joystick and rekit plungers			28/02/2018	8555	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Body\HOUSEKEEP	cleaned up all excess oil			28/02/2018	8555	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	DrCabRep\ELECT P&W	adjusted hand piece			28/02/2018	8555	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Hydraulics\HOSES	replaced hyd hoses to slew motor			28/02/2018	8555	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Hydraulics\OIL/FILTER	topped up hyd oil 30lts approx.			28/02/2018	8555	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Body\HOUSEKEEP	wash valve bank			28/02/2018	8555	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
			replaced LHR bottom leg pin													
			weld new tag onto new pin													
P25	Albury - Workshop	Body\MOUNTS	tightened nut and greased bushes		cleaned up after job	23/02/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Hydraulics\PUMP	Adjusted servo controls			18/02/2018	8473	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Hydraulics\CONSUMABLE	Fitted new lever covers to controls			18/02/2018	8473	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Engine\FAULT CODE	truck has a miss needs looking at			16/02/2018	641613	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
			NOT STARTING ALL THE TIME.		worked in workshop, fuel filters changed at service may assist											
P25	Albury - Workshop	Engine\FAULT CODE	TAKES A BIT TO WIND OVER		not starting all the time taking a bit to wind over	11/02/2018	8421	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
					replaced o-rings in fittings											
					degreased and washed											
P25	Albury - Workshop	Hydraulics\OIL LEAK	OIL ON DECK AROUND SLEW MOTOR.		oil on deck around slowie motor needs lookine at	11/02/2018	8421	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
					replaced leg pin keeper bolts											
P25	Albury - Workshop	VehService/JBS	B SERVICE	VehService/JBS	tightened bell housine bolts	11/02/2018	8421	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Elect\ELECT P&W	fit 3x led lights			03/02/2018	8351	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
			LHS lift ram leaking													
P25	Albury - Workshop	Hydraulics\RAM	REPAIR GRAM RAM HOSE SWIVEL. LHS lift ram leakine		removed lift cvlinder from P10 and replaced LH lift cvlinder on P25	01/02/2018	8337	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Hydraulics\HYD LEAKS	washed down loader platform of hyd oil			01/02/2018	8337	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Workshop\CLEAN	clean up after job completion			01/02/2018	8337	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Hydraulics\RAM	replaced lift cylinder bearings x2			01/02/2018	8337	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Workshop\W/S MAINT	pack up tools and parts from job			01/02/2018	8337	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Hydraulics\RAM	Degrease, wash and load hydraulics rams for repair		oil on deck around slowie motor needs lookine at	24/01/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Hydraulics\RAM	LH MAIN BOOM RAM LEAKING OIL & REPAIR OUTER BOOM RAM ALSO. LH MAIN BOOM RAM LEAKING OIL			21/01/2018		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Body\HOUSEKEEP	REQUIRES SPANNER SET.		ordered 17/01/2018	18/01/2018		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Elect\WORK LIGHT	LOADER CAB NEEDS NEW LIGHTS			18/01/2018		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
					Removed and replaced boom hose from valve bank											
			REPLACE HYD. HOSE NEAR MAIN RAM.		Degreased and washed loader & truck											
P25	Albury - Workshop	Hydraulics\HOSES	CHECK HYD. OIL		Tooved uo hvdraulic oil 50Lts	16/01/2018	8218	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	VehService/JBS	B SERVICE	VehService/JBS		14/01/2018	8202	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Air Con\CONSUMABLE	replaced a/c filters			14/01/2018	8202	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Elect\ELECT P&W	repaired wiring to cab worklight			14/01/2018	8202	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Hydraulics\CONSUMABLE	tigtened hydraulic fittings			14/01/2018	8202	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Body\HOUSEKEEP	TIGHTEN BOOM LIGHTS		tightened lights on boom	22/12/2017		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
					CALLOUT.											
P25	Albury - Workshop	Body\HOUSEKEEP	MISSING BOLT OUT OF PIN ON GRAB. HAD TO GET ONE FROM ROSEWOOD.		SUPPLY BOLT.	22/12/2017		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Hydraulics\RAM	REPLACE GRAB RAM			20/12/2017	8109	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
					CHANGED HYD OIL.											
P25	Albury - Workshop	Hydraulics\OIL/FILTER	HYD. OIL IS VERY DARK		Drained and replaced hyd. Oil	15/12/2017	8069	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Engine\MOUNTS	TIGHTENED ENG MOUNT BOLTS		tightened engine mount bolts	15/12/2017	8069	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Engine\BELTS/TENS	REPLACED ALTERNATOR PULLEY AND BELT		replaced alternator pulley and fan belt	15/12/2017	8069	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
			TIDY UP RUBBED WIRING LOOM.													
P25	Albury - Workshop	Engine\HOUSEKEEP	TOPPED UP COOLANT		tidy up rubbed wiring looms	15/12/2017	8069	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Hydraulics\OIL LEAK	HYDRAULIC OIL LEAK IN GRAB		topped up hyd oil	12/12/2017	8052	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Hydraulics\HYD LEAKS	check grab hoses for has leaks			12/12/2017	8052	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Hydraulics\HOSES	tightened hoses and washed grab			12/12/2017	8052	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Susp\AIR BAG	LHS airbags all flat			30/11/2017	631812	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Susp\SHOCK ABS	RHS back shock needs replacing pulling off broken out		removed broken shockers RHR - LHF	30/11/2017	631812	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Hydraulics\OIL LEAK	HYDRAULIC OIL LEAK IN GRAB		replaced hydraulic and air filters	25/11/2017	7983	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
					tightened a/c belt. Cleaned fan belt. Ordered new belt											
P25	Albury - Workshop	Engine\BELTS/TENS	AC BELT SQUEALLING		tightened grab hoses	25/11/2017	7983	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Hydraulics\RAM	RH BACK LEG PIN HAS BOLT MISSING		replaced RR lag ram keeper bolt	25/11/2017	7983	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
			1000HR B SERVICE.													
P25	Albury - Workshop	VehService/JBS	HYD FILTER	VehService/JBS		25/11/2017	7983	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Hydraulics\VALVES	LHS JOY STICK STICKING AT TIMES			23/11/2017		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Body\HOUSEKEEP	grease and check over			22/11/2017		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
			HYD HOSE NEEDS REPLACING BETWEEN BOOMS.													
P25	Albury - Workshop	Hydraulics\HOSES	OTHERS PERISHED		REPLACED ALL HOSES BETWEEN BOOM	19/11/2017	7927	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Body\CONSUMABLE	LHS back leg pin bolt missing		removed broken pin bolt and fitted new bolt	14/11/2017		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Chassis\HOUSEKEEP	LHR LOWER LEG PIN BROKEN		REPLACED LEG PIN	07/11/2017	7818	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Hydraulics\RAM	LHS MAIN LIFT RAM LEAKING		monitor	04/11/2017	17807	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
					wash down eng. Bay											
P25	Albury - Workshop	VehService/JBS	B SERVICE	VehService/JBS	tightened leaking hose on top of thermostat	04/11/2017	17807	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	DrCabElect\RADIO	replace radio aerial			29/10/2017		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	DrCabElect\RADIO	checked radio aerial and loom. Fully inserted plug. Tested ok in workshop			27/10/2017	7748	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	DrCabRep\RADIO	radio aerial needs replacing			27/10/2017	7748	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
					WELD UP BROKEN PIPE. ORDERED 2 NEW PIPES FROM ENZED.											
					Fitted new pipes											
					-Removed and repaired grab open fly boom pipe. Assembled and tested. Tightened rotator motor fittings.											
P25	Albury - Workshop	Hydraulics\OIL LEAK	HYD PIPE ON OUTER BOOM NEEDS REPLACING.		Reauires new sizes	25/10/2017	7710	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Body\HOUSEKEEP	GREASE MACHINE			24/10/2017	7703	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Body\CHN/RLR/MN	bolt missing pin on grab		replaced bolt out of grab cylinder	21/10/2017	7699	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Hydraulics\OIL LEAK	HYD. OIL ON DECK. AROUND SLEW RING.		RINLATECH HAS REBUILT A SLEW MOTOR TO SWAP OUT.	11/10/2017		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Body\MUDGUARDS	checked guards and shrouds			08/10/2017	7589	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Chassis\EXHAUST	tightened loose exhaust mounts			08/10/2017	7589	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Engine\START MOTR	removed and checked starter motor and flywheel			08/10/2017	7589	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
					fitted new round tips											
			NEED TIPS PUT ON GRAB TO STOP PINCHING OF LOGS.		repaired cracked grab ram pin locator											
P25	Albury - Workshop	Body\HOUSEKEEP	TOO HARD ON THE LOGS		repaired cracked leg ram pin locator	08/10/2017	7589	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
			TINES NEED RODS REWELDED ON TO TIPS OF GRABS.													
P25	Albury - Workshop	Chassis\HOUSEKEEP	TO HARD ON THE LOGS		#130563	08/10/2017	7589	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	DrCabElect\UNST/GAUGE	SWITCH TO PUT LEGS DOWN, BACK ONES. SOMETIMES DOES NOT WORK.		replaced switch with part from P8	08/10/2017	7589	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Body\HOUSEKEEP	KNOBS ON GRAB NEEDS REPLACING.		#130563	08/10/2017	7589	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	DrCabElect\UNST/GAUGE	SWITCH TO PUT BACK LEGS DOWN PLAYING UP.		#130565	08/10/2017	7589	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Hydraulics\OIL LEAK	LH HAND PIECE LEAKING OIL AT HOSE			08/10/2017	7589	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	DrCabElect\UNST/GAUGE	SWITCH FOR REAR LEGS NEEDS REPLACING		#130565	08/10/2017	7589	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	VehService/JBS	B SERVICE	VehService/JBS		08/10/2017	7589	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Body\HOSES	tightened loose hose fittings under LH			08/10/2017	7589	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Body\HOUSEKEEP	control lever & cleaned			08/10/2017	7589	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Hydraulics\VALVES	tightened hoses on valvebank			08/10/2017	7589	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Engine\HOUSEKEEP	wash engine bay and valvebank			08/10/2017	7589	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Body\HOUSEKEEP	parts of grab need putting back on			07/10/2017	7589	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Body\TRL LEGS	switch for back lag's need replacing			07/10/2017	7589	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	VehService/JBS	Service Due 7600 hrs	VehService/JBS		07/10/2017	7589	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Wodonga - Workshop	Body\TRL LEGS	switch to put back legs down playing up. Needs replacing			06/10/2017	619434	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Wodonga Workshop	PRENTICE	
P25	Albury - Workshop	Engine\BELTS/TENS	WHEN STARTING LOADER, MAKING A WINDING NOISE IN ENGINE BAY.		REPLACED STARTER MOTOR	30/09/2017	7558	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Elect\WORK LIGHT	TIMER LIGHT ONLY STAYS ON FOR 10 SECONDS		Replaced timer switch	28/09/2017		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Elect\WORK LIGHT	TIMER FOR THE DECK LIGHTS NOT SWITCHING OFF.			28/09/2017		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Elect\WORK LIGHT	PRENTICE NEEDS BETTER LIGHTS, ONES ON IT ARE VERY POOR AT NIGHT.		Replaced boom lights and repaired wiring on boom	28/09/2017	7558	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Elect\WORK LIGHT	LOADER NEEDS BETTER LIGHTS FOR NIGHT TIME WORK.			28/09/2017	7558	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Chassis\HOUSEKEEP	RH SIDE BACK LEG FOOT GETTING STUCK.		replaced damaged RHR stabilizer foot	14/09/2017	7018	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	VehService/JBS	B SERVICE DUE @ 7400HRS	VehService/JBS	fire pump engine air inlet/filter housing u/s. removed for ID and replacement. Blocked carby etc from dirt entry	13/09/2017	7406	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
			SUPPLY REFUELLING STORAGE TANK.													
P25	Albury - Workshop	Body\HOUSEKEEP	FIT TO UTE.			05/09/2017		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	DrCabElect\RADIO	REPLACE UHF MIC			29/08/2017	7303	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Hydraulics\OIL LEAK	SUPPLY O'RINGS TO TOP UP KIT			29/08/2017		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Hydraulics\OIL LEAK	HYD. OIL ON DECK. AROUND SLEW RING		LEAKING FROM SLEW MOTOR SHAFT SEAL	27/08/2017		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	Chassis\HOUSEKEEP	TIP PUT ON GRAB BROKEN OFF.		REQUIRES TIP WELDING BACK ONTO GRAB	27/08/2017		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	
P25	Albury - Workshop	DrCabElect\UNST/GAUGE	check feet control panel sometimes when putting feet down nothing happens check switch		check leg operation	20/08/2017		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE	

P25	Albury - Workshop	Elect\ELECT P&W	reset timer for operator safety lights			18/08/2017		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	VehService\BS	B SERVICE	VehService\BS		14/08/2017	7194	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Elect\WORK LIGHT	OUTER BOOM LIGHTS NOT WORKING			11/08/2017		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
					WELD CRACK ION GRAB.										
P25	Albury - Workshop	Chassis\HOUSEKEEP	LUGS PUT ON END OF THE GRAB TO PREVENT BREAKING IN HALF. NEED TIPS PUT ON GRAB TO STOP PINCHING OF LOGS.		WELD TIPS TO GRAB POINTS	09/08/2017		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Body\HOUSEKEEP	TOO HARD ON THE LOGS			09/08/2017		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
					DELIVERED TRUCK TO WEC.										
					7/08/2017										
					PICK UP LOADER. FOUND WEC HAD LEFT ISOLATOR ON. JUMP START AND TAKE LOADER TO ALODONGA FOR FURTHER REPAIRS										
P25	Albury - Workshop	Chassis\Boom	MAIN BOOM CRACKED NEAR MAIN PIN		16/08/2017 P25 WENT BACK TO WEC TO HAVE SPACERS FITTED BETWEEN BOOM AND FRAME.	01/08/2017		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\OIL LEAK	ROTORY COUPLING LEAKING. REQUIRES FITTING C/O UNIT.			29/07/2017		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
					replaced hyd. Return hose to tank and replaced hyd supply hose to lift valve bank - both hoses 1"										
P25	Albury - Workshop	Hydraulics\HYD LEAKS	REPLACE LEAKING HYD. HOSE		topped up hyd oil (20lts approx.)	27/07/2017	7141	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Chassis\HOUSEKEEP	REPLACE LEG PIN ROD END.		replaced r/r lower leg pin on cylinder	21/07/2017	7121	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
					CHANGED HYD. FILTER										
P25	Albury - Workshop	VehService\BS	B SERVICE	VehService\BS	washed enzine bay	04/07/2017	7009	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Chassis\Boom	MAIN BOOM CRACKED NEAR MAIN PIN LEG ROTORY COUPLING LEAKING.		AS PER JOB #58870 AS PER JOB #58869	04/07/2017	7009	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\OIL LEAK	TRIPPLE PUMP LEAKING		FIT C/O ROTORARY COUPLING	04/07/2017	7009	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\OIL/FILTER	HYD FILTER DUE		changed filter	04/07/2017	7009	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\HOSES	REPLACE LEAKING HYD. HOSE			29/06/2017	6971	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	DrCabRep\WINDSCREEN	water leaking down front window, around seal and back window.		RESEALED WINDOWS	21/06/2017		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	DrCabRep\WINDSCREEN	WINDOW LEAKING AROUND FRONT WINDOW SEAL		AS PER #22400	21/06/2017		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	DrCabRep\WINDSCREEN	WINDSCREEN LEAKING		AS PER #22400	21/06/2017		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	DrCabRep\WINDSCREEN	WINDSCREEN LEAKING		AS PER #22400	21/06/2017		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	DrCabRep\WINDSCREEN	WINDSCREEN LEAKING		AS PER #22400	21/06/2017		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	VehService\BS	B SERVICE	VehService\BS		09/06/2017	6860	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Body\HOUSEKEEP	RR lag pin needs replacing		Replaced grab pin	02/06/2017		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Body\MOUNTS	repaired boom hose mounts			02/06/2017		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Body\MOUNTS	tightened engine hood bolts			02/06/2017		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Air Con\AIR CON	Replaced fan and A/C belts			02/06/2017		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Engine\RADIATOR	Replaced overflow hose, radiator cap and cleaned out bottle			02/06/2017		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	DrCabRep\WINDSCREEN	WINDSCREEN LEAKING			02/06/2017		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	DrCabRep\HOUSEKEEP	SERVO'S NEED RUBBER BOOTS			02/06/2017		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	DrCabRep\WINDSCREEN	WINDSCREEN LEAKING			02/06/2017		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	DrCabRep\HOUSEKEEP	SERVO'S NEED RUBBER BOOTS			02/06/2017		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Chassis\CHAS CRACK	MAIN BOOM STARTING TO CRACK IN FRONT OF MAIN PIN		Picked up boom ram	27/05/2017		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	DrCabElect\INST/GAUGE	INTERIOR LIGHT NOT WORKING IN LOADER		REPLACED GLOBE	24/05/2017	6722	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
					WASHED DOWN GRAB AND CHECK FOR LEAKS.										
P25	Albury - Workshop	Hydraulics\OIL LEAK	GRAB LEAKING HYDRAULIC OIL. ROTATOR		CHECKED HYDRAULIC OIL LEVEL	24/05/2017	6722	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Body\HOUSEKEEP	LHR FOOT PIN NEEDS LOOKING AT		FITTED FOOT AND PIN OFF P10.	13/05/2017	6639	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	VehService\BS	B SERVICE DUE	VehService\BS	REPAIRED STARTER CORD ON FIRE FIGHTING UNIT	13/05/2017	6639	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\OIL LEAK	ROTORY COUPLING LEAKING			13/05/2017	6639	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Elect\ELECT P&W	Dash lights not working			09/05/2017		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
					Replaced all dash and guage globes										
					FITTED LIGHT TO SHINE OVER DECK OF LOADER										
					Fitted new LED on deck										
P25	Albury - Workshop	Elect\HOUSEKEEP	NEEDS A LIGHT ON PLATFORM OF PRENTICE FOR SAFETY		wire in timer switch for deck light & work lights set for 2 mins	07/05/2017	6575	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Elect\HOUSEKEEP	REQUIRES LIGHT ON DECK FOR VISION AT NIGHT.			07/05/2017	6575	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	DrCabRep\WINDSCREEN	WINDSCREEN CRACKED		REPLACED WINSCREEN	07/05/2017	6575	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	DrCabRep\WINDSCREEN	WINDOW NEEDS REPLACING		AS ABOVE	07/05/2017	6575	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
			swapped out hyd cylinder for fly boom with old unit offp-10												
P25	Albury - Workshop	Hydraulics\RAM	washed ram and took to Wodonga Engineering for rebuild			25/04/2017	6487	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\OIL LEAK	hyd oil leak in grab		hyd. Oil leak - grapple swivel leaking. Requires kit (new style)	20/04/2017	6437	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Engine\OIL LEAK	coolant leaking out back of loader		coolant leak - overflow hose (coolant leaking down onto bell housing etc.)	20/04/2017	6437	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Susp\SUSPENSION	check pin and bush between main and fly boom replaced outer boom cylinder bearing new pin made (aldonga)			20/04/2017	6437	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Chassis\Load Fram	refit cylinder			20/04/2017	6437	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Elect\WORK LIGHT	RH LIFT RAM WORKLIGHT SHORTING OUT.		push pins inside plugs and resecured	13/04/2017	6413	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
					AS PER ATTACHED										
					Travel to and from worksite off yench's road, Lankey creek										
P25	Albury - Workshop	Hydraulics\RAM	REPLACE LEAKING GRAB RAM.		replace leaking grab ram. Top up hydraulic oil. Test. Wash ram for repair	13/04/2017	6413	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\OIL LEAK	LH SERVO LEAKING		REPLACED SERVO SEALS AND ORINGS FOR EAST / WEST FUNCTIONS.	12/04/2017	6407	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Cooling\COOL LEAKS	HEATER TAP LEAKING		REPLACED TAP	12/04/2017	6407	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\OIL LEAK	HYDRAULIC OIL LEAK IN GRAB.		REPLACED HOSE	12/04/2017	6407	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	DrCabElect\RADIO	RADIO PLAYING UP WITH WORK LIGHTS ON		REPLACED RADIO. ALL OTHER CHECKS HAD BEEN DONE	11/04/2017	6394	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	VehService\BS	B SERVICE	VehService\BS		09/04/2017	6383	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
					replaced grease nipple										
P25	Albury - Workshop	Body\HOUSEKEEP	LHS REAR FOOT GREASE NIPPLE NEEDS REPLACING		greased leak/feet	08/04/2017	6383	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	DrCabRep\DOOR LOCK	DOOR LATCH NOT SHUTTING PROPERLY ALL THE TIME.		DOOR JUST REQUIRE MORE EFFORT TO SHUT. DOOR HAD BEEN ADJUSTED	02/04/2017	6309	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Elect\WORK LIGHT	BOOM LIGHT BROKEN		REPLACED LIGHT	02/04/2017	6309	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Body\MOUNTS	REPLACE 'D' SHACKLE FOR GRAB SUPPORT		REPAIRED "D" SHACKLE	02/04/2017	6309	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	DrCabRep\HOUSEKEEP	FAN IN PRENTICE NEEDS LOOKING AT. NEEDS TIGHTENING. FAN IN LOADER NEEDS LOOKING AT. NEEDS TIGHTENING		replaced fan	01/04/2017	4383	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Body\HOUSEKEEP	REPLACE BROKEN GREASE GUN		SUPPLY GREASE GUN TO PRENTICE	28/03/2017		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
					replaced RHR leg pin bolt										
					greased all leg pins										
P25	Albury - Workshop	VehService\BS	B SERVICE	VehService\BS	fit washers to door hinges (spacers)	19/03/2017	6205	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
					OPERATOR FITTED HOSE.										
P25	Albury - Workshop	Hydraulics\HOSES	HYD HOSE ON OUTER BOOM TO GRAB		FITTED SPIRAL WRAP TO HOSE.	18/03/2017	6199	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Elect\WORK LIGHT	WORK LIGHT NEAR STEP IS NOT WORKING		replaced fuse. Repaired wiring and common earth at distribution box	10/03/2017	6149	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
					replaced holder with unused holder on LHS of cabin										
P25	Albury - Workshop	DrCabRep\RADIO	UHF MIC HOLDER NEEDS REPLACING		removed sharp screws from cabin. Modified holder to fit handpiece	10/03/2017	6149	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	DrCabElect\RADIO	RADIO NOT WORKING WHEN LIGHTS ARE ON. cracked mounts on "A" frame		replaced aerial	10/03/2017	6149	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Body\MOUNTS	remove broken mounts oreo & reweld			09/03/2017	6140	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\HOSES	MAIN LIFT HYD HOSE REQUIRES REPLACMENT		AS ABOVE	09/03/2017	6140	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	VehService	GREASE PRENTICE AND CHECK OVER			08/03/2017	6130	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
					replaced plunger kit in servo for main lift										
P25	Albury - Workshop	Hydraulics\PUMP	HYDRAULICS NEED LOOKING AT, NOT LIFTING PROPERLY. SEAL KITS ORDERED FOR HAND PIECES.		adjusted servo pressures	08/03/2017	6130	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	DrCabElect\RADIO	RADIO WORKS FINE UNTIL YOU TURN ON LOADER LIGHTS, THEN IT PLAYS UP		tested. Problem on distant stations. Checked aerial and wiring. Checked work lights for faults	08/03/2017	6130	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\PUMP	GETTING SLOW IN HYD. MAIN LIFT		as per 54320	08/03/2017	6130	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Engine\FAULT CODE	DROPPING REV'S UNDER LOAD AND CUT OUT TWICE		replaced fuel filter at tank. Checked fuel lines and connectors. Washed/degreased pressure pump to identify leaks/air suction	08/03/2017	6130	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	DrCabRep\RADIO	RADIO NOT WORKING WHEN WORK LIGHTS ARE ON.		removed all associated wiring and checked. Inspected switches. Replaced cabin worklight. Removed unused lights wiring. Insulated looms	08/03/2017	6130	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Engine\BELTS/TENS	excessive belt noise. Checked belts and bearings. Washed belt. Drive area. Ok in workshop			05/03/2017	6130	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
					CHECKED HYD. PRESSURES 2300PSI. TESTED GOOD										
P25	Albury - Workshop	Hydraulics\PUMP	HYDRAULICS NEED LOOKING AT, NOT LIFTING PROPERLY		YES LIFT IS SLOW. POSSIBLY IN HAND PIECE OR CYLINDERS	05/03/2017	6119	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Chassis\HOUSEKEEP	RH REAR LEG PIN, BOLT MISSING		REPLACED BOLT AND GREASED ALL LEGS.	05/03/2017	6119	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\PUMP	GETTING SLOW IN HYD. MAIN LIFT		AS PER JOB #93680	05/03/2017	6119	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
					FITTED NEW CARBY AND FILTER HOUSING AND ASSY.										
					RAN PUMP AND TEST OPERATION. TEST OK.										
P25	Albury - Workshop	Chassis\FIRE EXTIN	FIRE FIGHTING PUMP NOT STARTING. PARTS ORDERED 21/02/2017		MODIFY ORIGINAL CANVAS COVER AND FIT OVER ENGINE	25/02/2017	6035	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Air Con\AIR CON	AC NOT WORKING		REPAIRED BROKEN WIRE	22/02/2017	6024	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
					REMOVE FUEL TANK AND CLEAN OUT.										
					REMOVE CARBY AND INSPECT. FOUND CARBY TO BE FULL OUT WATER AND SEIZED.										
					GOVERNOR JAMMED UP WITH ROCKS AND DEBRIS.										
P25	Albury - Workshop	Chassis\FIRE EXTIN	FIRE FIGHTING PUMP NOT STARTING		ORDERED CARBY ASSY. AND FILTER ASSY. 21/02/2017	19/02/2017	6004	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\OIL/FILTER	HYDRAULIC FILTER DUE.		replaced hyd filter	19/02/2017	6004	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
					removed pins. Grease pins. Reassemble.										
P25	Albury - Workshop	Chassis\HOUSEKEEP	RH AND LH BACK LEG PINS MISSING		Check & grease others	19/02/2017	6004	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\PUMP	HYDRAULICS NEED LOOKING AT, NOT LIFTING PROPERLEY		not done	19/02/2017	6004	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	VehService\BS	B SERVICE	VehService\BS	wash down	19/02/2017	6004	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Chassis\HOUSEKEEP	BOTH REAR LEG PINS MISSING BOLTS		REPLACED BOLTS	15/02/2017	5967	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	DrCabElect\RADIO	RADIO NOT WORKING		replaced blown fuse, repaired rubbed wires	07/02/2017	5687	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	DrCabRep\SEAT	Seat in loader is like a rocking chair. Parts order off Randalls 12/01/2017			05/02/2017	5880	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	DrCabRep\DOOR LOCK	door rubber at bottom needs looking at. Hanging off		pressed rubber together against door	05/02/2017	5880	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\HOSES	Hose leaking on outer boom. 2nd from right		replaced both RHS outer boom pipes	25/01/2017	5791	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	VehService\BS	B service	VehService\BS		25/01/2017	5791	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\RAM	RR cylinder to leg pin broken			25/01/2017	5791	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Cooling\HOUSEKEEP	coolant needs topping up.		Checked for leaks, topped up	24/01/2017		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Body\HOUSEKEEP	Replace missing bolt in LHR lower leg pin			15/01/2017	5703	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Elect\WORK LIGHT	fly boom lights not working		Repaired wiring	13/01/2017	5691	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Chassis\HOUSEKEEP	needs a grease.			13/01/2017	5691	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	DrCabRep\SEAT	Seat in loader is like a rocking chair		Seat rocking too much	13/01/2017		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Air Con\AIR CON	Replace AC compressor		replace broken ac compressor	12/01/2017	5679	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\HOSES	Hyd hose needs restrapping on main boom rubbing thru			12/01/2017	5679	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	VehService\BS	B service	VehService\BS		12/01/2017	5679	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Engine\BELTS/TENS	Replace fan belt to shorter belt			12/01/2017	5679	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
					moved overflow hose to rear of cabin										
					cleaned out radiator										
					washed and tested belts and pulleys										
P25	Albury - Workshop	Engine\BELTS/TENS	belts still getting coolant on them from over flow bottle. Coolant leak @ heater box.		tightened loose engine cover bolts	30/12/2016	5560	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Air Con\HEATER	Ordered heater tap		Replaced tap, hoses and clamps	29/12/2016	5556	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
					Relocated radiator header tank to outside eng bay away from belts.										
P25	Albury - Workshop	Engine\BELTS/TENS	Belts squealling		Reelaced bleed hose.	23/12/2016	5556	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Chassis\CHAS CRACK	Weld crack in boom		WEC welded boom	23/12/2016	5556	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
					removed cylinder for repair.										
					Return to Rinkatech										
					fitted cylinder										
P25	Albury - Workshop	Hydraulics\RAM	Broken weld on grab ram.		washed hydraulic oil from grab and truck	22/12/2016	5556	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Air Con\HEATER	Coolant leak @ heater box		parts ordered	21/12/2016	5551	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Cooling\COOL LEAKS	coolant needs topping up.		topped up coolant	21/12/2016	5551	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\RAM	Oil leak @ grab ram. Single prong		replaced cylinder	21/12/2016	5551	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
					Ordered crank pulley.										
P25	Albury - Workshop	Engine\BELTS/TENS	Belts squealling		As per attached	13/12/2016	5552	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\OIL LEAK	oil leak on grab		as attached	13/12/2016	5509	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Engine\COOL LEAKS	coolant overflow bottle pressurizing. Coolant leaking onto alternator. Fitted overflow hose to bottle. Washed engine check coolant leaks at overflow bottle			02/12/2016	5426	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Engine\COOL LEAKS	washed engine. Modified overflow bottle for bigger breather. Cleaned pulleys. Tested			30/11/2016	5408	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Body\MOUNTS	LHR leg pin bolt			29/11/2016	5400	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Body\MOUNTS	removed and checked pin condition. Replaced holding bolt			29/11/2016	5400	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Engine\DAMAGE	found crack in engine mount bracket. Washed engine. Removed and repaired bracket. Fitted			29/11/2016	5400	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	VehService\BS	B service	VehService\BS		29/11/2016	5400	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Body\HOUSEKEEP	replace missing grease nipple on outer boom			29/11/2016	5400	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE

P25	Albury - Workshop	Body\HOUSEKEEP	replace grease nipple inside grab prong. Can not reach?			29/11/2016	5400	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	DrCabRep\HOUSEKEEP	Hood lining falling off Rubber boots around controls need replacing getting too hot. Parts ordered. 15.2 mm		set roof lining back in	17/11/2016	5324	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\VALVES	91.87 mm			15/11/2016		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\HOSES	Hyd. Hose needs replacing on main boom at bottom.			13/11/2016	5297	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	DrCabElect\UNST/GAUGE	Interior light not working		working	13/11/2016	5297	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Engine\WATER PUMP	coolant leak in engine bay		replaced water pump	13/11/2016	5297	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	DrCabRep\DOOR LOCK	Door latch not shutting properley		tightened door latch	13/11/2016	5297	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Elect\WORK LIGHT	fly boom light flickering on/off		repaired wiring	13/11/2016	5297	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Elect\ELECT P&W	Strobe light on roof needs replacing		replaced light	13/11/2016	5297	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Chassis\HOUSEKEEP	replace missing leg pin retaining bolt.			13/11/2016	5297	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\RAM	Grab cylinder leaking		replaced grab cylinder cracked barrel	11/11/2016	5277	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Engine\BELTS/TENS	Belts squealling @ 1800RPM.		replaced radiator cap overflow hose wash out radiator & pullet & alternator test	04/11/2016	5227	Fault	Completed	Greenfreight Loreinne NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	VehService\BS	B service	VehService\BS	replaced broken p-clamp on hyd return hose wash engine bay	02/11/2016	5206	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Engine\FUEL TANK	Loader still cutting out		filters been changed	20/10/2016	5128	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	DrCabElect\UNST/GAUGE	Interior light not working		working on acc. And ignition replaced ram	20/10/2016	5128	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\RAM	Ram on grab leaking		heated & straightened frame cleaned pulleys replaced belt	20/10/2016	5128	Fault	Completed	Greenfreight Loreinne NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Engine\BELTS/TENS	Fan belts squealling		checked bearinas removed & fitted c/over slew motor wash down	19/10/2016	5120	Fault	Completed	Greenfreight Loreinne NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\MOTOR	Hyd. Oil leak out of slew motor		topped up hyd oil (60lts approx)	18/10/2016	5115	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\MOTOR	Slew motor leaking bad		as per #34148 As per attached invoice send to wec for repairs 11/10 travel to wec undo main pin nut	18/10/2016	5115	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\RAM	RH ram bearing no good. Unsafe to use		14/10 stick uc truck	13/10/2016	5092	Fault	Completed	Greenfreight Loreinne NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Body\HOUSEKEEP	RH back leg ram pin, bolt missing		replaced bolt in leg pin	07/10/2016	5092	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\OIL/FILTER	Hyd filter due for change @ 5000HRS		replaced inner & outer air filters	24/09/2016	5022	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	VehService\BS	B service	VehService\BS	tightened engine cover bolts	24/09/2016	5022	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Body\HOUSEKEEP	Bolt missing in pin on grab			22/09/2016	5004	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Body\HOUSEKEEP	Bolt missing that hold pin in for ram.		repaired wiring for outer boom lights	20/09/2016	4986	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Elect\WORK LIGHT	Fly boom light going on/off		repaired broken wires for outer boom Changed out cylinder. Has a split in the weld on the rod end. Send to Rinlatech for repairs.	14/09/2016	4943	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\RAM	Grab ram		Check hyd oil level replaced by-passing cylinder. Check operation of spool if returning ect. Adjusted LH handpiece	31/08/2016	4830	Fault	Completed	Greenfreight Loreinne NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\RAM	grab loosing pressure. Single prong opening		washed valve banks	28/08/2016	4821	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Body\MOUNTS	Check movement in slew bearing Cap broken on over flow bottle which is leaking coolant on to alternator and down side of engine.			28/08/2016		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Cooling\COOL LEAKS	Parts ordered		replaced over flow bottle	27/08/2016	4821	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	DrCabElect\UNST/GAUGE	No dash lights. Only 3 working			27/08/2016	4821	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	VehService\BS	B service	VehService\BS	replaed fuel supply and return hoses. Enzed	27/08/2016	4821	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\RAM	Replace LHR leg pin rod end.			27/08/2016	4802	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\OIL LEAK	Check hoses on grab for leaks			27/08/2016	4802	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Body\HOUSEKEEP	replace missing grease nipples			27/08/2016	4802	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Body\HOUSEKEEP	LHS back leg pin bolt missing holds		replaced bolt	09/08/2016	4644	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	VehService\BS	B service	VehService\BS		31/07/2016	4602	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	VehService	B Service Due 4600 hrs			31/07/2016	4602	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Chassis\HOUSEKEEP	needs a grease have not had time with wet weather			24/07/2016	4538	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Cooling\COOL LEAKS	Cap broken on over flow bottle which is leaking coolant on to alternator and down side of engine.		ordered bottle.	13/07/2016		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	DrCabElect\RADIO	Radio not working when work lights are on.		checked radio and could not fault. Replaced missing bolts surrounding engine coolant leak remove broken bolt and replace.	13/07/2016	4472	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Body\HOUSEKEEP	bolt broken for ram pin on grab		Welded broken pin tag reelaced oivot pin bolt	05/07/2016	4430	Fault	Completed	Greenfreight Loreinne NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	VehService\BS	B service due @ 4400 hrs.	VehService\BS		30/06/2016	4400	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Chassis\CHAS CRACK	weld cracks in main boom and grab support		weld crack fit 8mm namelock to erab bar chain	29/06/2016		Repair	Completed	Greenfreight Loreinne NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	DrCabElect\RADIO	UHF not working properley		fit c/o unit tightened hoses. Wash and inspect for leaks topped up hydraulic tank	28/06/2016	4382	Fault	Completed	Greenfreight Loreinne NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\HYD LEAKS	Hydraulic oil leak in grab		replaced windscreen wiper blade replace hose from spool valve to slew motor. Replaced hyd, hose from slew motor to valve bank	28/06/2016	4382	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\HYD LEAKS	hydraulic oil leak at valve bank.		washed & inspected (ok)	28/06/2016	4382	Fault	Completed	Greenfreight Loreinne NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	VehService	Grease machine		as above Put replacement hose in truck.	28/06/2016	4382	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\HOSES	Operator had replaced hose. Requires a replacement.		Too us hydraulic oil.	17/06/2016		Repair	Completed	Greenfreight Loreinne NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Body\DAMAGE	cracks in grab Hydraulic oil leak in grab.		weld cracks in grab Replaced hose and fitting.	16/06/2016	4313	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\RAM	Ram on sinale tine at bottom.		Replaced missine erease nipples on erab.	15/06/2016	4313	Fault	Completed	Greenfreight Loreinne NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	VehService\BS	B service	VehService\BS	as above	31/05/2016	4202	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	DrCabRep\WINDSCREEN	Roof and windscreen leaking. (very bad)		checked securing bolts are tight. Applied sealant to the heads of then bolts.	18/05/2016	4104	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	DrCabRep\WINDSCREEN	Roof leaking water through securing bolts.		sealed bolts	18/05/2016	4104	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\CONSUMABLE	replace broken 15° shifter		as above	14/05/2016	4097	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Body\DAMAGE	Tines on grab need replacing. Not gripping logs properly.		cut off tine tip - replace	14/05/2016	4097	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\VALVES	Tines on grab need replacing not gripping logs properly			14/05/2016	4097	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\RAM	grab needs looking at prongs to short			14/05/2016	4097	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Air Con\HEATER	turn heater taps on		as above plugged in wire plug	10/05/2016	4051	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Elect\WORK LIGHT	work light RH sidetop of ram shorting out.		replaced LH work light	05/05/2016	4014	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	VehService\BS	B service	VehService\BS		28/04/2016	3983	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\OIL LEAK	Hydraulic oil leak in grab. Can not locate		tightened fitting on grab ram.	15/04/2016	3878	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\VALVES	Tines on grab need replacing not gripping logs properly		as per #22196	02/04/2016		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	VehService\BS	B service	VehService\BS	as above	01/04/2016	3793	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Body\DAMAGE	replace missing bolts on pin on grab		replaced both bolts in both lower pins.	31/03/2016		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\OIL LEAK	Hydraulic oil leak under loader		Removed blown hose. Enzed made new hose and refitted hose.	30/03/2016		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\OIL/FILTER	check hyd oil		topped up hydraulic oil. 60ltrs	30/03/2016		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Elect\WORK LIGHT	RH fly boom light not working		repaired wiring at connector	16/03/2016	3692	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Elect\WORK LIGHT	Fly boom RH side light needs replacing. Belts on loader squealling. A/C not on. Refer job entry # 15754			11/03/2016	3664	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Engine\BELTS/TENS	Job # 27789		tightened belts. recaired coolant leak. Waished enaine. alternator and condensor. Tested alternator Travel to Shelley.	11/03/2016	3664	Fault	Completed	Greenfreight Loreinne NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\RAM	Replace grapple ram. Split at weld Air con cutting on and off. Belt slipping @ 1800RPM.		Replaced grab cylinder	09/03/2016	3649	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Air Con\AIR CON	Works fine for 10 mins and then belt squeals.		replaced pulley for aircon belt ait on main fan and replaced fan belt and a/c belt	08/03/2016	4455	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	VehService\BS	B service	VehService\BS		04/03/2016	3610	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\VALVES	LHS joy stick sticking		replaced knuckle at base of joy stick	27/02/2016	3564	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Engine\FUEL TANK	engine cutting in and out. 3 times		changed primary filter	27/02/2016	3564	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	DrCabElect\HEATER REP	Loader needs fan put back in.		fitted cab fan fitted c/o slew motor. Found bearing starting to fail.	27/02/2016	3560	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\OIL LEAK	Oil leak around big ring gear. Slew seal leakina.		Replaced leaking hydraulic hose. Reelace worn slew oimion aear.	23/02/2016	3610	Fault	Completed	Greenfreight Loreinne NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\RAM	Tynes on grab are worn and need replacing.		as per job # 22196	23/02/2016	3610	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\VALVES	LHS joy stick jamming.. LHS joy stick jambing.		adjusted lever contol, checked for broken or weak springs - ok found bottom wire loom iammine under lever	20/02/2016	3524	Fault	Completed	Greenfreight Loreinne NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Engine\FAULT CODE	Engine cutting out		tested fuel flow in system. Replaced tank fuel filter	16/02/2016	13498	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	DrCabElect\UNST/GAUGE	prentice requires fan fitted cab.		now A/C is working. Fan should not be required cleaned out evapourator,condensor, cab and A/C filters. Parts on order to fit. Cab filter and A/C filter	11/02/2016		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Air Con\AIR CON	A/C not working real good		-ordered filters for cab & A/C Done	11/02/2016		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Engine\FILTERS	B service. engine still missing under load.			04/02/2016	3406	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Engine\FUEL TANK	Found more contamination in fuel system. Have ordered a fuel seoarator filter. Will fit it when it arrives.		Cummins	28/01/2016		Repair	Completed	Greenfreight Loreinne NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Wodonga - Workshop	Engine	loader still cutting under load		Cummins	28/01/2016	3346	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Wodonga Workshop	PRENTICE
P25	Albury - Workshop	Engine	loader cutting out at times		Cummins. Found contamination in the fuel system. Monitor.	23/01/2016	13346	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Body	grab tynes need looking at			23/01/2016	13346	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Elect\ELECT P&W	strobe light			19/01/2016		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Engine	loader cutting out when under load at 1800 revs - not all the time		Cummins: checked fuel pressure and found lift pump faulty. Stripped and cleaned, refitted, sent to work.	17/01/2016	3299	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Engine\FUEL TANK	replace damaged/leaking fuel lines		Enzed. Replaced fuel lines	16/01/2016		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Engine\FILTERS	filters		completed	12/01/2016		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Engine	loader cutting out at times		replaced fuel filters	09/01/2016		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Engine\FILTERS	filter		completed	30/12/2015		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Engine	wash engine bay			25/12/2015	3204	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	VehService\BS	B Service	VehService\BS		25/12/2015	3204	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Engine	belts rear bad need replacing		belts ok	24/12/2015		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Air Con	air con needs looking at - not real cold		a/c is working	24/12/2015		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Engine	belts need tightening canvas seat cover			22/12/2015		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	DrCabRep\SEAT	tctc header tank cap		completed	18/12/2015		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Cooling\RADIATOR	randalls 205 hydraulic oil			15/12/2015		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\OIL/FILTER	valvoline		COMPLETED	15/12/2015		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Elect\BATTERY	fit new battery			11/12/2015	3171	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\OIL/FILTER	replace 150lts hydraulic oil supply hose			11/12/2015	3171	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Hydraulics\HOSES	enzed		completed	08/12/2015		Repair	Completed	Greenfreight Loreinne NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE

P25	Albury - Workshop	Body\DAMAGE	weld boom crack aldonea ene		ourchase order onCOMPLETED	28/11/2015		Reoair	Comoleted	Greenfreiaht Loaeine NSW	LOADPRENT	Alburv	ALR	Alburv Workshoo	PRENTICE
P25	Albury - Workshop	Hydraulics\HOSES	shorten hyd hose ensed o rings		comoleted	17/11/2015		Reoair	Comoleted	Greenfreiaht Loaeine NSW	LOADPRENT	Alburv	ALR	Alburv Workshoo	PRENTICE
P25	Albury - Workshop	Hydraulics\HOSES	ensed o rings		comoleted	03/11/2015		Reoair	Comoleted	Greenfreiaht Loaeine NSW	LOADPRENT	Alburv	ALR	Alburv Workshoo	PRENTICE
P25	Albury - Workshop	Body\DAMAGE	ensed replace boom pin			31/10/2015		Reoair	Comoleted	Greenfreiaht Loaeine NSW	LOADPRENT	Alburv	ALR	Alburv Workshoo	PRENTICE
P25	Albury - Workshop	Body\DAMAGE	aldonea eneineerine		comoleted	23/10/2015		Reoair	Comoleted	Greenfreiaht Loaeine NSW	LOADPRENT	Alburv	ALR	Alburv Workshoo	PRENTICE
P25	Rosewood - Workshop	Hydraulics	hydraulic oil leak out valve bank at back of loader, check hydraulic oil		replace leaking pipe from valve bank to turret hoses	13/10/2015	3135	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	DrCabRep\HOUSEKEEP	roof lining falling down		re-glued roof lining	08/10/2015		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Chassis\SUSPENSION	Job Added From Invoice			07/10/2015	0	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	DrCabRep\SEAT	needs new strut in Rr arm rest			29/09/2015	3068	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Susp\SUSPENSION	Job Added From Invoice			23/09/2015	0	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Chassis	repair cracked outer boom ram pin			19/09/2015	3009	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	VehService\85	B Service	VehService\85		19/09/2015	3009	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Engine\HOUSEKEEP	Service Job Added From Invoice			16/09/2015	0	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	DrCabElect\INST/GAUGE	no dash lights		replaced globes	09/09/2015		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	DrCabRep\SEAT	needs a seat cover		fitted new seat cover	09/09/2015		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Body\HOSES	Service Job Added From Invoice			08/09/2015	0	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	Body	replace wiper blade			04/09/2015		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P25	Albury - Workshop	DrivLine	hoses above grab		replace 2x grab ram hoses and replace link between outer boom and grapple	04/09/2015		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE