EquipmentName	Workshop	CodeAndSubCode	Description	CompletionComments	DateDone	DistanceDone	Worktype	Workstate	EquipmentOwner	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
LOAD25	Albury - Workshop	Tyres\PRES CHECK	Tyres\PRES CHECK FULL PRESSURE CHECK		22/10/2025	818952	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	BORDER BANDAG PTY LTD - 4	LOADER
LOAD25	Albury - Workshop	Elect\BATTERY	Flat batteries jump start	-loader jump started, vehicle still tagged out	17/10/2025	818952	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Albury - Workshop	Tyres\PRES CHECK	Tyres\PRES CHECK 1-2 STEER 3-10 DRIVE		28/04/2025	818952	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	BEAUREPAIRES - 4	LOADER
LOAD25	Albury - Workshop	Susp\AIR BAG	Replace Blown Air Bags, Front Drive Axle Rear Air Bag & Rear Drive Axle Front Air Bag. (Parts Supplied By CMV Wodonga P/O: T093723)		25/04/2025	818952	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	CMV TRUCK & BUS - 4	LOADER
LOAD25	Albury - Workshop	Elect\ELECT P&W	JUMP START TRUCK- BATTERY ISOLATOR SWITCH LEFT ON.		22/03/2025	818952	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Myrtleford - Workshop	Engine\HOUSEKEEP	check over oils and fluid levels before use	check over all fluids and oil levels all good	15/10/2024	818952	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Myrtleford Workshop	LOADER
LOAD25	Myrtleford - Workshop	Body\HOUSEKEEP	wash down loader walk way of oil to prevent slip hazard		09/08/2024	818952	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Myrtleford Workshop	LOADER
LOAD25	Myrtleford - Workshop	Body\HOUSEKEEP	jump start truck check and top fluids blocked off RHFD rear air bag		06/08/2024	818952	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Myrtleford Workshop	LOADER
LOAD25	Myrtleford - Workshop	Elect\BATTERY	jump start truck		05/08/2024	818952	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Myrtleford Workshop	LOADER
LOAD25	Wodonga - Workshop	Engine\FAULT CODE	ENGINE POSITION SENSOR CODE ACTIVE.		22/03/2024		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Engine\OIL LEAK	Middle head sweating.		22/03/2024		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Elect\HEAD LIGHT	LOW BEAM HEADLIGHTS VERY DULL.		22/03/2024		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Elect\WORK LIGHT	WORK LIGHT FRONT OF WINDSCREEN TOP NOT WORKING.		22/03/2024		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Engine\FUEL TANK	Truck Out Of Fuel	Put fuel in tank and bled fuel system.	24/06/2023		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Albury - Workshop	Steering\SUSPENSION	CHECK ALL STEER AND DRIVE SUSPENSION COMPONENTS AND REPORT - Carry out test drive and confirm wandering fault. - Inspect suspension components. - Found all torque-rod bushes excessively worn. - Found all track rod bushes excessively worn also. - Found 4x perished airbags. - Quote all for repair/replace.		22/03/2023	818952	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Elect\HEAD LIGHT	CHECK AND REPAIR ANY N/W LIGHTS - Inspect and found LH top marker light n/w - Repair damaged wirine to light. all ok		22/03/2023	818952	Repair	Completed	Greenfreight Loxwine NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Wodonga - Workshop	Tyres\TP10	TRAVELLED TO SHELLEY. REPLACED LR OUTER TYRE. CHECKED OVER. DROVE TRUCK BACK TO WODONGA DEPOT.		18/03/2023	818952	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Albury - Workshop	Tyres\TP3+4	runouts		18/03/2023	818952	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Tyres\TP07	runout		18/03/2023	818952	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Wodonga - Workshop	Susp\SWAYBAR	BOLTED RH SWAY BAR BRACKET ON. UNFOLDED LOADER FOR WINDSCREEN FITMENT.		16/03/2023	818952	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		11/03/2023	817978	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	DrCabElect\INST/GAUGE	LED Screen burnt out/broken - odometer.		11/03/2023	817978	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Engine\OIL LEAK	Middle head sweating.		11/03/2023	817978	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Steering\OIL LEAK	steering box oil leak	Previously completed.	11/03/2023	817978	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Engine\OIL LEAK	Air compressor gasket leaking.	Previously Completed.	11/03/2023	817978	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Susp\AIR BAG	REPLACE FRONT DRIVE RHR AIR BAG.		11/03/2023	817978	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Engine\FAULT CODE	ENGINE POSITION SENSOR CODE ACTIVE.		11/03/2023	817978	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	DrCabElect\INST/GAUGE	Dash Globes. TRUCK NEEDS NEW WINDSCREEN. REPLACED BY AUTOTEX		11/03/2023	817978	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	DrCabRep\WINDSCREEN	POH WW077251		11/03/2023	817978	Repair	Completed	Greenfreight Loxwine NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonwa Workshop	LOADER
LOAD25	Wodonga - Workshop	Elect\HEAD LIGHT	LOW BEAM HEADLIGHTS VERY DULL. Headbiths Faded.		11/03/2023	817978	Repair	Completed	Greenfreight Loxwine NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonwa Workshop	LOADER
LOAD25	Wodonga - Workshop	Elect\WORK LIGHT	WORK LIGHT FRONT OF WINDSCREEN TOP NOT WORKING.		11/03/2023	817978	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	DrCabRep\WINDSCREEN	REQUIRES NEW WINDSCREEN.	REFER JOB # 405180	11/03/2023	817978	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Chassis\Load Fram	Loader A Frame Cracked		11/03/2023	817978	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Hydraulics\HOSES	Replace Damaged Hose	Previously Completed	11/03/2023	817978	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Elect\HEAD LIGHT	Head Lights Dull Replace Rear Sway Bar Brackets (CMV)	Refer Job # 405181	11/03/2023	817978	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Susp\SWAYBAR	Purchase Order Number: WW077201		11/03/2023	817978	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Elect\INDICATORS	Replaced LHF Indicator globe.		11/03/2023	817978	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	VehService\AS	Service As Per Attached Checklist		11/03/2023	817978	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Brakes\YEL VALVE	BLACK BUTTON- AIR LEAK. Rapid To Do.. BLACK BUTTON- AIR LEAK. REPLACE BROMS VALVE.	Rapid #WW076959 - Remove dash panels for access. - Carry out multiple tests and locate faulty park brake valve. Order new valve. - Remove and replace valve and carry out checks, all ok.	28/02/2023		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Albury - Workshop	Brakes\VALVES	CUSTOMER REPORTS PARK BAKE CANNOT BE RELEASED WITHOUT PURGING AIR FROM BROMM VALVE. REPAIR AS required	- Refit dash panels	24/02/2023		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Wodonga - Workshop	Workshop\MOVE ASSET	DROP OFF CUMMINS.		07/02/2023		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	DrCabElect\INST/GAUGE	LED Screen burnt out/broken - odometer.		01/02/2023		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Engine\OIL LEAK	Middle head sweating.		01/02/2023		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Steering\OIL LEAK	steering box oil leak		01/02/2023		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Steering\PWR STEER	Power steering hoses leaking.	LEAK IS FROM COMPRESSOR.	01/02/2023		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Engine\OIL LEAK	Air compressor gasket leaking.		01/02/2023		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Susp\AIR BAG	REPLACE FRONT DRIVE RHR AIR BAG.		01/02/2023		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Engine\FAULT CODE	ENGINE POSITION SENSOR CODE ACTIVE.		01/02/2023		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	DrCabElect\INST/GAUGE	Dash Globes.		01/02/2023		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Body\PANELS	Right Hand Bonnet Strap broken.	NO FAULT.	01/02/2023		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Engine\ENG FAN	Bad air leak around Horton fan.		01/02/2023		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	DrCabRep\WINDOW REG	Fix drivers side window.	NO FAULT.	01/02/2023		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Elect\HEAD LIGHT	LOW BEAM HEADLIGHTS VERY DULL.		01/02/2023		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	DrCabRep\WINDSCREEN	TRUCK NEEDS NEW WINDSCREEN.		01/02/2023		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Brakes\VALVES	REPLACE BROMS VALVE.		01/02/2023		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		13/10/2022		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Engine\OIL LEAK	Middle head sweating.		13/10/2022		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Steering\OIL LEAK	steering box oil leak		13/10/2022		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Steering\PWR STEER	Power steering hoses leaking.		13/10/2022		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Engine\OIL LEAK	Air compressor gasket leaking.		13/10/2022		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Body\REFLECTORS	LHR Marker sign not secured. Fix drivers side window. Mirrors and Left hand window functions not working.		13/10/2022		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	DrCabRep\WINDOW REG	New Mirror/Window switch ordord.		13/10/2022		Repair	Completed	Greenfreight Loxwine NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonwa Workshoa	LOADER
LOAD25	Wodonga - Workshop	Susp\AIR BAG	REPLACE FRONT DRIVE RHR AIR BAG.		13/10/2022		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Susp\SWAYBAR	REPLACE SWAY BAR BUSHES.		13/10/2022		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	DrCabRep\WINDOW REG	RH WINDOW STUCK DOWN.		13/10/2022		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Engine\FAULT CODE	ENGINE POSITION SENSOR CODE ACTIVE.		13/10/2022		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Engine\ENG FAN	Bad air leak around Horton fan.		13/10/2022		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Engine\FAULT CODE	Check engine light going on and off Hydraulics still wont hold pressure, main boom drops by itself and grabs open by them selves, unless you hold pressure on it.		13/10/2022		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Hydraulics\MOTOR	Left hand side main lift ram still leakine and exttine worse.		13/10/2022		Fault	Completed	Greenfreight Loxwine NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonwa Workshoa	LOADER
LOAD25	Wodonga - Workshop	Hydraulics\OIL LEAK	2 x Hydraulic hoses right hand side.		13/10/2022		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Unknown	B Service due.		13/10/2022		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	DrCabElect\INST/GAUGE	Dash Globes.		13/10/2022		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Body\PANELS	Right Hand Bonnet Strap broken.		13/10/2022		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Engine\EXHAUST	Remove and Retighten Exhaust Flanges x 2 Leaking exhaust.		13/10/2022		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Workshop\CLEAN	Clean Workshop after service.		13/10/2022		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	VehService\CS	Service As Per Attached Checklist REMOVE AND REPLACE BLOWN COMPRESSOR LINE , RE-SEAL AND TIGHTEN		13/10/2022		Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Albury - Workshop	Engine\HOT PIPE	LOOSE FITTINGS ON COMPRESSOR LINE / RUN AND TEST		27/07/2022	814918	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Hydraulics\HOSES	Make new hose to sample		18/05/2022		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Wodonga - Workshop	DrCabRep\WINDOW REG	RH WINDOW STUCK DOWN. DIAGNOSED ENGINE LIGHT ON WITH CUMMINS.	DIAGNOSED AND ORDERED SEIZED MOTOR. MANUALLY LIFTED WINDOW UP AND RE-FIT MOTOR TO HOLD UP.	26/03/2022	811669	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Engine\FAULT CODE	ENGINE POSITION SENSOR CODE ON.	(COMPLETED JOB, OPENED NEW JOB)	11/03/2022	812321	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Engine\FAULT CODE	ENGINE POSITION SENSOR CODE ACTIVE.		11/03/2022	812321	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Albury - Workshop	Body\WINDSCREEN	Windscreen Replacement		02/03/2022	818952	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Susp\Torque Rod	Torque Rodd aArm & Bushes		02/03/2022	818952	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Wodonga - Workshop	Susp\AIR BAG	CHANGED OVER LFF AND RRR AIRBAGS. SET UPWITH LONGER BAGS IN REAR AXLE AND SHORTER AT FRONT. TEST DROVE.		22/02/2022	811422	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	DrivLine\OIL LEAK	CHECKED OIL LEAKS WHEN IDLING. DIAGNOSED AND REPAIRED LEAKING GEARBOX UPPER COOLER HOSE. CLEANED AREA. TESTED. TOPPED UP.		09/02/2022	810488	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Rosewood - Workshop	Susp\AIR BAG	COLLECTED FROM HYNE MILL. LIMPED TO ROSEWOOD WITH LIMITED RIDE HEIGHT RHS. REPLACED LEAKING FRONT DRIVE RHF AIR BAG.		08/02/2022	810470	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Rosewood Workshop	LOADER
LOAD25	Rosewood - Workshop	Susp\AIR BAG	REPLACE FRONT DRIVE RHR AIR BAG.		08/02/2022	810470	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Rosewood Workshop	LOADER
LOAD25	Rosewood - Workshop	Susp\SWAYBAR	REPLACE SWAY BAR BUSHES.		08/02/2022	810470	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Rosewood Workshop	LOADER
LOAD25	Albury - Workshop	Engine\BATTERY	TCTC supply Batteries RADIO SHELF		20/01/2022	818952	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabElect\RADIO	R12831 Put batteries on charge.		24/12/2021		Repair	Completed	Greenfreight Loxwine NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshoo	LOADER
LOAD25	Wodonga - Workshop	Elect\BATTERY	Refit battery box.		21/09/2021	818051	Repair	Completed	Greenfreight Loxwine NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonwa Workshoa	LOADER
LOAD25	Wodonga - Workshop	Elect\ELECT P&W	Repair right hand window switch. Remove battery cover under support cradle. Jump start and bring over workshop.		21/09/2021	818051	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Elect\BATTERY	Jump start	Took more time due to logs being stacked too close to machine.	21/09/2021	812051	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Workshop\MOVE ASSET	Drop off to Rapid.		04/08/2021		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Susp\SWAYBAR	reconnect rear swaybar link Inspected for air leaks, found drain cock that has previously had silicone jammed inside. Don't have a drain cock to suit.	Refer Entry # 148755 P25	27/07/2021	808447	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Brakes\AIR TANKS	Replace drain plug on air tank.	Ended up cluxeine tank - Includes smoko.	23/07/2021	808099	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	DrivLine\OIL LEAK	REPAIRED TRANSMISSION COOLER LINE LEAKS.		10/07/2021		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Steering\OIL LEAK	steering box oil leak LH rear shackle top nipple unaccessable COMPLETED. steering box input shaft seal leaking		08/07/2021		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Susp\HOUSEKEEP	REFER JOB # 345350		08/07/2021		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Steering\PWR STEER	Power steering hoses leaking.		08/07/2021		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Engine\OIL LEAK	Air compressor gasket leaking.		08/07/2021		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Elect\TAIL LIGHT	LHR tail light assembly damaged.	Replaced and completed	08/07/2021		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Body\REFLECTORS	LHR Marker sign not secured.		08/07/2021		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Steering\OIL LEAK	steering box leaking oil	Refer Job# 345350	08/07/2021		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	DrCabRep\DOOR LOCK	drivers side door flies open	Cant fault.	08/07/2021		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	DrCabRep\WIPERS	needs wiper blades	Washer bottle out of water and oil on window.	08/07/2021		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Engine\MOUNTS	possible broken engine mount	Previously completed.	08/07/2021		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Engine\ENG FAN	Bad air leak around Horton fan.		08/07/2021		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Hydraulics\HOSES	Need two grab hoses replaced leaking bad.		08/07/2021		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Hydraulics\HYD LEAKS	joy sticks leaking oil on floor		08/07/2021		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Hydraulics\HYD LEAKS	Joy sticks leaking oil all over the floor	Refer Job# 345362	08/07/2021		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Elect\TAIL LIGHT	LHS Back tail lights hanging off.	Refer Job# 345354 Inspect drivers door issue with window. Cant Fault. Mirrors and Left hand window functions not working.	08/07/2021		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	DrCabRep\WINDOW REG	Fix drivers side window.	New Mirror/Window switch ordord.	08/07/2021		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Body	Body		08/07/2021		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Susp\SWAYBAR	Rear sway bar bushes need replacing.	TCTC	17/06/2021		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER

				Vehicle isolated unable to obtain download												
				R&R rear main seal												
				Seal carrier gasket not replaced												
				Not leaking at time of replacement												
				Install new flywheel housing												
				Dial in housing												
				Tension housing to specification												
				Drill and fit new dowel pins												
LOAD25	Wodonga - Workshop	Engine\OIL LEAK	Rear structure cracked TRUCK TAGGED OUT.	Customer to re install awar box	17/06/2021		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER	
			Bell housing replacement (Rear Structure Crack)													
LOAD25	Wodonga - Workshop	DrivLine\DAMAGE	CMV Wodonna PO# WWO64737		03/06/2021	8585	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER	
LOAD25	Wodonga - Workshop	DrivLine\SUSPENSION	needs front swaybar (on drive) bushes replacing	CMV Powwo64719	03/06/2021		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER	
LOAD25	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		19/05/2021	801911	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER	
LOAD25	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		19/05/2021	801911	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER	
LOAD25	Wodonga - Workshop	Steering\OIL LEAK	steering box leaking oil		19/05/2021	801911	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER	
LOAD25	Wodonga - Workshop	Susp\SWAYBAR	Rear sway bar bushes need replacing.		19/05/2021	801911	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER	
LOAD25	Wodonga - Workshop	DrCabElect\INST/GAUGE	LED Screen burnt out/broken - odometer.		19/05/2021	801911	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER	
LOAD25	Wodonga - Workshop	Steering\PWR STEER	Power steering hoses leaking.		19/05/2021	801911	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER	
LOAD25	Wodonga - Workshop	Engine\OIL LEAK	Air compressor gasket leaking.		19/05/2021	801911	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER	
LOAD25	Wodonga - Workshop	Engine\OIL LEAK	Middle head sweating.		19/05/2021	801911	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER	
LOAD25	Wodonga - Workshop	Engine\OIL LEAK	Rear structure cracked TRUCK TAGGED OUT.		19/05/2021	801911	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER	
LOAD25	Wodonga - Workshop	Elect\TAIL LIGHT	LHR tail light assembly damaged.		19/05/2021	801911	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER	
LOAD25	Wodonga - Workshop	Body\REFLECTORS	LHR Marker sign not secured.		19/05/2021	801911	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER	
LOAD25	Wodonga - Workshop	VehService\CS	Service As Per Attached Checklist		19/05/2021	801911	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER	
LOAD25	Wodonga - Workshop	VehService\CS	Service As Per Attached Checklist		19/05/2021	801911	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER	
LOAD25	Wodonga - Workshop	DrCabRep\WIPERS	needs wiper blades		08/05/2021		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER	
LOAD25	Wodonga - Workshop	Engine\MOUNTS	possible broken engine mount		08/05/2021		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER	
LOAD25	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		10/04/2021	797466	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER	
LOAD25	Albury - Workshop	Steering\OIL LEAK	steering box oil leak		10/04/2021	797466	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER	
			LH rear shackle top nipple unaccessable													
LOAD25	Albury - Workshop	Susp\HOUSEKEEP	steering box input shaft seal leaking		10/04/2021	797466	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER	
LOAD25	Albury - Workshop	DrivLine\SUSPENSION	needs front swaybar (on drive) bushes replacing		10/04/2021	797466	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER	
				CHECK DRIVERS ELECTRIC WINDOW NOT WORKING.												
				CHECK WIRING, LOCATE BROKEN WIRING IN DOOR												
				JAM HARNESS.												
LOAD25	Albury - Workshop	DrCabElect\ELECT P&W	L/H window wont go up/down	REPAIR AS NEEDED. TEST - OKAY	10/04/2021	797466	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER	
LOAD25	Albury - Workshop	VehService\CS	Service As Per Attached Checklist		10/04/2021	797466	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER	
				Mount driving light to existing bracket on LH side of Bar.												
				Rhys 1400 - 1445												
				Rhys 1630 - 2000												
LOAD25	Albury - Workshop	Elect\HEAD LIGHT	TCTC - Supply Driving Light	Rhys 2030 - 0000	10/04/2021	797466	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER	
LOAD25	Wodonga - Workshop	Workshop\MOVE ASSET	Pick Up loader from Albury Depot		09/04/2021		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER	
				remove crane from cradle												
				pop bonnet												
				check oil												
				top up oil												
				close bonnett												
				refit crane to cradle												
LOAD25	Rosewood - Workshop	Engine\HOUSEKEEP	needs engine oil		01/04/2021	796226	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Rosewood Workshop	LOADER	
LOAD25	Tumut - Workshop	Body\REFLECTORS	fit safety signs to rear		26/03/2021	795787	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Tumut Workshop	LOADER	
LOAD25	Rosewood - Workshop	Body\REFLECTORS	warning sign rear of truck needs fixing back on		25/03/2021		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Rosewood Workshop	LOADER	
LOAD25	Tumut - Workshop	Tyres\TP04	Supply 1 retread tyre, 1 Runout, Bolted on by driver		25/03/2021		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Tumut Workshop	LOADER	
LOAD25	Tumut - Workshop	Tyres\TP08	Tyre Position 8		25/03/2021		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Tumut Workshop	LOADER	
LOAD25	Albury - Workshop	Engine\Cool	Supply Hump Hose		24/03/2021		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER	
LOAD25	Rosewood - Workshop	Steering\OIL LEAK	steering box leaking oil		23/03/2021	794936	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Rosewood Workshop	LOADER	
LOAD25	Rosewood - Workshop	VehService\AS	A Service Due		23/03/2021	794936	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Rosewood Workshop	LOADER	
			BOOST LEAK													
			DURING SERVICE FOUND BOOST HOSES AT TURBO HAS HOLE IN IT.													
			Undo pipe off turbo and removed clamp.													
			Removed boost hose and found similar part in stock.													
			Cut hose shorter and remove x1 metal ring to get pipe on enough.													
			Fitted new hose													
LOAD25	Tumut - Workshop	Brakes\BOOSTER	Tensioned clamps and refitted to turbo as reauired		23/03/2021	795018	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Tumut Workshop	LOADER	
				1GREENLOG-A												
				Carried out A service and Suspension check on 22/03/2021 as per service sheets required. $124.45												
				-												
				DURING SERVICE:												
				* Steering box seal failed												
				* Steering pump leaking												
				* Oil pump leaking at LH front of engine												
				* Gearbox oil leak												
				* Boost hose at turbo has hole present - repaired.												
				* All brakes at 50%, LH rear at 10% and LH rear adjuster u/s.												
				* Sway bar bushes on both drives cracked												
				* Diff plugs u/s - unable to check levels.												
LOAD25	Tumut - Workshop	VehService\AS	Carried out A-Service		23/03/2021	795018	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Tumut Workshop	LOADER	
LOAD25	Rosewood - Workshop	Tyres\TP1+2	Supply and Fit 2 tyres		19/03/2021		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Rosewood Workshop	LOADER	
LOAD25	Rosewood - Workshop	Body\CHN/RLR/MN	Supply Connector -Hammerlock		17/03/2021		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Rosewood Workshop	LOADER	
LOAD25	Albury - Workshop	Body\AIR BAG	Supply Air bags		17/03/2021		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER	
LOAD25	Rosewood - Workshop	Tyres\TP7+8	Supply and Fit 2 tyres		13/03/2021		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Rosewood Workshop	LOADER	
LOAD25	Tumut - Workshop	Susp\AIR BAG	airbag replaced	airbag replacement	13/03/2021		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Tumut Workshop	LOADER	
LOAD25	Tumut - Workshop	Tyres	2 new tyres	change 2 tyres	13/03/2021		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Tumut Workshop	LOADER	
			remove door lining - check power to window winder motors and switches													
LOAD25	Rosewood - Workshop	DrCabElect\ELECT P&W	check relays and solenoids		02/03/2021	791784	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Rosewood Workshop	LOADER	
LOAD25	Rosewood - Workshop	Tyres\TP9+10	Supply and Fit 2 tyres		27/02/2021		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER	
LOAD25	Rosewood - Workshop	DrivLine\SUSPENSION	needs front swaybar (on drive) bushes replacing		26/02/2021	791424	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Rosewood Workshop	LOADER	
LOAD25	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		26/02/2021	791424	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Rosewood Workshop	LOADER	
LOAD25	Rosewood - Workshop	VehService\AS	A Service		26/02/2021	791424	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Rosewood Workshop	LOADER	
LOAD25	Rosewood - Workshop	Engine\ENG FAN	check hortin fan operation and for obvious problems		13/02/2021	787669	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Rosewood Workshop	LOADER	
LOAD25	Rosewood - Workshop	Engine\ELECT P&W	organised Ian Grey to attend Rosewood for repairs		13/02/2021	787669	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Rosewood Workshop	LOADER	
			get vehicle into workshop to replace sway bar mount. Blow flys swarming and putrid stench													
			took to wash bay and cleaned throughly to remove roadkill													
LOAD25	Rosewood - Workshop	DrivLine\SUSPENSION	loader operator turned up before we cold do job		10/02/2021	787669	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Rosewood Workshop	LOADER	
LOAD25	Rosewood - Workshop	Elect\DRV LIGHT	remove broken driving light and order replacement		04/02/2021	786700	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Rosewood Workshop	LOADER	
				flat tyre cause by shock mount broken off												
				stabbing tyre												
				removed wheels and removed shock and mount												
				refitted wheels												
LOAD25	Rosewood - Workshop	Tyres\DRV TYRES	R/H front inner tyre needs repair	oarts on order	23/01/2021	786734	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Rosewood Workshop	LOADER	
			LH rear shackle top nipple unaccessable R10718													
LOAD25	Rosewood - Workshop	Susp\HOUSEKEEP	steerine box inout shaft seal leaking		20/01/2021	786060	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Rosewood Workshop	LOADER	
LOAD25	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		20/01/2021	786060	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Rosewood Workshop	LOADER	
LOAD25	Rosewood - Workshop	VehService\AS	A Service Due		20/01/2021	786060	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Rosewood Workshop	LOADER	
LOAD25	Rosewood - Workshop	DrCabElect\INST/GAUGE	no dash lights	diagnose no dash lights. Smoke has been released needs an instrument tech	19/01/2021	785885	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Rosewood Workshop	LOADER	
LOAD25	Rosewood - Workshop	DrivLine\CLUTCH	needs clutch adjust	adjusted clutch	19/01/2021	785885	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Rosewood Workshop	LOADER	
LOAD25	Myrtleford - Workshop	DrivLine\OIL LEAK	gearbox oil leak		15/01/2021	785525	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Myrtleford Workshop	LOADER	
LOAD25	Myrtleford - Workshop	DrCabRep\WIPERS	wiper blades		15/01/2021	785525	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Myrtleford Workshop	LOADER	
LOAD25	Myrtleford - Workshop	DrivLine\GEARBOX	noisy gearbox/vibration at higher speeds		15/01/2021	785525	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Myrtleford Workshop	LOADER	
			reco rear section of g/box													
LOAD25	Rosewood - Workshop	DrivLine\GEARBOX	fit bearing and seals and gears		14/01/2021	785525	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Rosewood Workshop	LOADER	
LOAD25	Rosewood - Workshop	DrivLine\GEARBOX	fit 2nd hang rear housing		14/01/2021	785525	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Rosewood Workshop	LOADER	
LOAD25	Rosewood - Workshop	DrCabElect\INST/GAUGE	repair speedo		14/01/2021	785525	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Rosewood Workshop	LOADER	
LOAD25	Myrtleford - Workshop	DrCabElect\INST/GAUGE	no high beam dash light		05/01/2021		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Myrtleford Workshop	LOADER	
			R&R at Rosewood Depot													
LOAD25	Tumut - Workshop	DrCabElect\ELECT P&W	electrical window L/side not working		11/12/2020		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Tumut Workshop	LOADER	
LOAD25	Tumut - Workshop	Engine\OIL LEAK	turn off heater taps		11/12/2020		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Tumut Workshop	LOADER	
LOAD25	Rosewood - Workshop	Elect\HEAD LIGHT	R/H headlight not working	replace blown headlight globe	08/12/2020	782542	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Rosewood Workshop	LOADER	
			vehicle slow to start, winding over but no fine													
			replaced fuel filter, suspect faulty seal on recal fit													
			bleed air from filter system extensively													
LOAD25	Rosewood - Workshop	Engine\FILTERS	seems ok will monitor		04/12/2020	781330	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Rosewood Workshop	LOADER	
LOAD25	Rosewood - Workshop	Engine\OIL LEAK	oil leaking from motor badly	called out to Rosewood depot. Bad oil leak from engine	03/12/2020	782027	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Rosewood Workshop	LOADER	
LOAD25	Rosewood - Workshop	DrivLine\GEARBOX	noisy gearbox/vibration at higher speeds		03/12/2020	782027	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Rosewood Workshop	LOADER	
LOAD25	Rosewood - Workshop	Steering\OIL LEAK	steering box oil leak		03/12/2020	782027	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Rosewood Workshop	LOADER	
LOAD25	Rosewood - Workshop	DrivLine\OIL LEAK	gearbox oil leak		03/12/2020	782027	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Rosewood Workshop	LOADER	
LOAD25	Rosewood - Workshop	VehService\BS	B Service Due	oil filter was leaking. I deacided to perform a "B" Service and replaced all filters	03/12/2020	782027	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Rosewood Workshop	LOADER	
LOAD25	Rosewood - Workshop	Brakes\BRAKE ADJ	adjust front brakes		10/11/2020		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Rosewood Workshop	LOADER	
LOAD25	Rosewood - Workshop	Elect\TAIL LIGHT	repaired rear marker light		10/11/2020	778300	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Rosewood Workshop	LOADER	
LOAD25	Rosewood - Workshop	Chassis\HYDRAULICS	greased loader		10/11/2020	778300	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Rosewood Workshop	LOADER	
LOAD25	Rosewood - Workshop	DrivLine\SUSPENSION	repaired rear chains for axle		10/11/2020	778300	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Rosewood Workshop	LOADER	
LOAD25	Rosewood - Workshop	VehService\AS	Carried out A Service		10/11/2020	778300	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Rosewood Workshop	LOADER	
				called out to bush squealing noise in RHF												
LOAD25	Rosewood - Workshop	Brakes\BRK O/HAUL	noise front right steer wheel	found bolt (from backing plate) trapped inside brake cavity	07/11/2020		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Rosewood Workshop	LOADER	
LOAD25	Rosewood - Workshop	DrivLine\DRV LN SER	check tailshaft alignment and possible ride height problem	remove bolt. Will need to check and adiust at workshoo	07/11/2020	777892	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Rosewood Workshop	LOADER	
			set height slightly higher to achieve better jack shaft uni alignment													
LOAD25	Rosewood - Workshop	Susp\HCV	vibration is better		07/11/2020	777892	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Rosewood Workshop	LOADER	
			check into engine light coming on													
			all levels under bonnet good													
LOAD25	Rosewood - Workshop	Engine\FAULT CODE	suspect coolant level sensor have ordered a replacement		04/11/2020	777249	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Rosewood Workshop	LOADER	
LOAD25	Rosewood - Workshop	DrivLine\CLUTCH	adjusted clutch		04/11/2020	777249	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Rosewood Workshop	LOADER	
LOAD25	Rosewood - Workshop	DrivLine\SUSPENSION	rear R/H torsion bar hanger broken		23/10/2020		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Rosewood Workshop	LOADER	
				replace bracket and airbag												
LOAD25	Rosewood - Workshop	Susp\AIR BAG	airbag split	called back 5km out of Rosewood then not needed due to electrical issue with horn staying on	23/10/2020		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Rosewood Workshop	LOADER	
LOAD25	Rosewood - Workshop	Susp\DAMAGE	called out to Rosewood, RHR sway bar bracket broken. Airbag holed		23/10/2020		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Rosewood Workshop	LOADER	
LOAD25	Rosewood - Workshop	DrCabRep\WIPERS	wiper blades		16/10/2020	715927	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Rosewood Workshop	LOADER	
LOAD25	Rosewood - Workshop	DrCabElect\ELECT P&W	L/H window wont go up/down		16/10/2020	715927	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Rosewood Workshop	LOADER	
LOAD25	Rosewood - Workshop	DrCabElect\INST/GAUGE	no high beam dash light		16/10/2020	715927	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Rosewood Workshop	LOADER	
LOAD25	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		16/10/2020	715927	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Rosewood Workshop	LOADER	
LOAD25	Rosewood - Workshop	VehService\AS	A Service	A Service completed by TCTC	16/10/2020	715927	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Rosewood Workshop	LOADER	
LOAD25	Tumut - Workshop	Elect\ELECT P&W	CHECK HIGH BEAM/DRIVING LIGHTS STAYING ON CHECK AND FOUND FAULTY COMBINATION SWITCH. ADVISE WORKSHOP TO ORDER REPALCEMENT FROM CMV TRUCKS		06/10/2020		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Tumut Workshop	LOADER	
LOAD25	Albury - Workshop	Elect\HEAD LIGHT	parker light in driving light keep flickering when fan come on and off	checked day running lights - ok	03/10/2020	773379	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER	
LOAD25	Albury - Workshop	Elect\RADIO	uhf very poor service. uhf very poor service 265	cleaned earth mounts to aerial	03/10/2020	773379	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER	
LOAD25	Albury - Workshop	VehService\AS	A Service Due 775000		03/10/2020	773379	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER	
LOAD25	Albury - Workshop	Body\MIRRORS	repaired broken RH mirror mount and fitted mirror. Repaired wiring		02/10/2020		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER	
LOAD25	Albury - Workshop	DrivLine\HOUSEKEEP	checked driveline for vibration cause		02/10/2020		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER	
LOAD25	Albury - Workshop	Workshop\MOVE ASSET	pick up from cummins		24/09/2020	770883	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER	

LOAD25	Albury - Workshop	Workshop\MOVE ASSET	drop off at Cummins R/H drive light needs braket modified				23/09/2020		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Albury Workshop		LOADER
LOAD25	Albury - Workshop	Body\DRV LIGHT	light ointtine down - no more adiust uz	reshaae and refit drivine liaht 2 mount			22/09/2020		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Albury Workshop		LOADER
LOAD25	Albury - Workshop	Engine\CONSUMABLE	engine oil low temp light came on twice	top up engine oil inspect motor after refit			22/09/2020		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Albury Workshop		LOADER
LOAD25	Albury - Workshop	Engine\FAULT CODE	checked coolant at start and mid shift was ok				22/09/2020		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Albury Workshop		LOADER
LOAD25	Myrtleford - Workshop	DrCabElect\INST/GAUGE	Fit temp gauges				12/09/2020		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 ARKON AUTO ELECTRICAL		LOADER
LOAD25	Myrtleford - Workshop	DrCabElect\INST/GAUGE	Fit Oil Pressure Gauge				12/09/2020		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 ARKON AUTO ELECTRICAL		LOADER
LOAD25	Myrtleford - Workshop	DrCabElect\INST/GAUGE	Fit Volt gauge				12/09/2020		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 ARKON AUTO ELECTRICAL		LOADER
LOAD25	Myrtleford - Workshop	DrCabElect\INST/GAUGE	No Top Speedo light				12/09/2020		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 ARKON AUTO ELECTRICAL		LOADER
LOAD25	Myrtleford - Workshop	Elect\DRV LIGHT	Fit day lights with day time running lights that stay on.				12/09/2020		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 ARKON AUTO ELECTRICAL		LOADER
LOAD25	Myrtleford - Workshop	Elect\HEAD LIGHT	clean headlights				09/09/2020	770320	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
LOAD25	Myrtleford - Workshop	Body\HOUSEKEEP	zip tie up airlines and electric leads under truck				09/09/2020	770320	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
LOAD25	Myrtleford - Workshop	DrivLine\DRV LN SER	cross locks not working				09/09/2020	770320	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
LOAD25	Myrtleford - Workshop	Brakes\AIR LEAK	brake booster clamp				09/09/2020	770320	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
LOAD25	Myrtleford - Workshop	Engine\BOOST HOSE	replace bottom boost hose and fit mount				09/09/2020	770320	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
LOAD25	Myrtleford - Workshop	Body\PAINT/REST	polish cab				09/09/2020	770320	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
LOAD25	Myrtleford - Workshop	Body\PAINT/REST	clean cab inside				09/09/2020	770320	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
LOAD25	Myrtleford - Workshop	Engine\FUEL TANK	fuel truck with diesel				09/09/2020	770320	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
LOAD25	Myrtleford - Workshop	DrCabElect\AIR CON	fit dash vents				06/09/2020	770320	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
LOAD25	Myrtleford - Workshop	Chassis\DAMAGE	Replace Front and Rear Diff V stay mount and bolts LHR and RHR sides.				03/09/2020	770278	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
LOAD25	Myrtleford - Workshop	DrivLine\SUSPENSION	wash and remove rear axle to replace v-stay mounts				25/08/2020	770278	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
LOAD25	Myrtleford - Workshop	Susp\DAMAGE	refit front guard after brake booster replaced and test				25/08/2020	770278	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
LOAD25	Myrtleford - Workshop	Body\AIR FITTIN	air hoses replace due to joiners everywhere				25/08/2020	770278	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
LOAD25	Myrtleford - Workshop	Elect\ELECT P&W	fit new reverse beeper				25/08/2020	770278	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
LOAD25	Myrtleford - Workshop	DrivLine\SUSPENSION	weld crack airbag mount				25/08/2020	770278	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
LOAD25	Myrtleford - Workshop	Brakes\SLACK ADJ	inspect and replace LHR 2 cam adjuster				25/08/2020	770278	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
LOAD25	Myrtleford - Workshop	Brakes\BACK PLATE	fit backing plates to rear drive				25/08/2020	770278	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
LOAD25	Myrtleford - Workshop	Body\DAMAGE	repair LH/RH steps				25/08/2020	770278	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
LOAD25	Myrtleford - Workshop	DrivLine\SUSPENSION	make new airbag releasers on bottom				25/08/2020	770278	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
LOAD25	Myrtleford - Workshop	Body\MOUNTS	weld bracket for 5 liters bottle holder				25/08/2020	770278	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
LOAD25	Myrtleford - Workshop	Brakes\ABS	RHF drive abs sensor				25/08/2020	770278	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
LOAD25	Myrtleford - Workshop	Body\AIR FITTIN	fit air dryer kit				25/08/2020	770278	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
LOAD25	Myrtleford - Workshop	Engine\HOUSEKEEP	remove air dryer fit kit and aeassemble				25/08/2020	770278	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
LOAD25	Myrtleford - Workshop	DrivLine\SUSPENSION	refit v-stay				20/08/2020	770278	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
LOAD25	Myrtleford - Workshop	DrivLine\SUSPENSION	refit front diff sway bay				20/08/2020	770278	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
LOAD25	Myrtleford - Workshop	DrivLine\SUSPENSION	fix strip bolt holes in v stay mount on truck side T9528				20/08/2020	770278	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
LOAD25	Myrtleford - Workshop	DrivLine\DRV LN SER	p/devider not engaging				20/08/2020	770278	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
LOAD25	Myrtleford - Workshop	DrivLine\DRV LN SER	front diff lock adjust				20/08/2020	770278	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
LOAD25	Myrtleford - Workshop	Body\MOUNTS	make bolt drum holder				20/08/2020	770278	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
LOAD25	Myrtleford - Workshop	Body\MOUNTS	make up grab handles and paint				20/08/2020	770278	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
LOAD25	Myrtleford - Workshop	Brakes\BOOSTER	fit LH ster brake booster T9555				20/08/2020	770278	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
LOAD25	Myrtleford - Workshop	Chassis\DAMAGE	v-stay strip bolts				20/08/2020	770278	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
LOAD25	Myrtleford - Workshop	Body\MOUNTS	make up battery clamp				15/08/2020	770278	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
				refit and set up cleaned up rechecked work													
LOAD25	Myrtleford - Workshop	Steering\KING PIN	Fit RH Steer King Pin Kit T9365	all good			15/08/2020	770278	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
LOAD25	Myrtleford - Workshop	Steering\HOUSEKEEP	Fit 4 New Steer U Bolts	fit "u" bolts and straighten LH spring			15/08/2020	770278	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
LOAD25	Myrtleford - Workshop	Steering\SUSPENSION	Fit Steer Sway Bar Bushes	fit bushes			15/08/2020	770278	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
LOAD25	Myrtleford - Workshop	Body\FUEL TANK	Fit Fuel Tank Rubbers T9379	fit tank rubbers			15/08/2020	770278	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
LOAD25	Myrtleford - Workshop	Body\HOUSEKEEP	Fit Walkway Tape				15/08/2020	770278	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
LOAD25	Myrtleford - Workshop	Body\REFLECTORS	Fit Reflective Tape				15/08/2020	770278	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
LOAD25	Myrtleford - Workshop	Elect\RWC COMP	Make up New Tail Light Bar and Fit Lights and Oversize Sign T9370 T9407				15/08/2020	770278	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
LOAD25	Myrtleford - Workshop	Body\PAINT/REST	Wash Truck and Clean Cab & fit 3 new dash vents				15/08/2020	770278	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
LOAD25	Myrtleford - Workshop	DrivLine\GEARBOX	inspect and remove sloppy gear shift				12/08/2020	770278	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
LOAD25	Myrtleford - Workshop	Elect\RWC COMP	make new tail light bar and fit lights and fit new sign				12/08/2020	770278	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
LOAD25	Myrtleford - Workshop	Steering\KING PIN	remove and rebush RHS kingpin				12/08/2020	770278	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
LOAD25	Myrtleford - Workshop	Body\DAMAGE	straighten brackets				11/08/2020	770278	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
LOAD25	Myrtleford - Workshop	Body\DAMAGE	drivers side steps broken				11/08/2020	770278	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
LOAD25	Myrtleford - Workshop	Body\MOUNTS	make new bracket				11/08/2020	770278	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
				this is a P25 job not a L25 job													
LOAD25	Myrtleford - Workshop	Chassis\TRL LEGS	Back RHS Leg Is Creeping Down In Transit	remove RHR lee and fit seal kit to ram			11/08/2020	3746	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
LOAD25	Myrtleford - Workshop	DrCabRep\WIPERS	fix wiper washers and replaced blades				07/08/2020	770278	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
LOAD25	Myrtleford - Workshop	Body\AIR FITTIN	fit/fix all new drain valve's on air tanks				07/08/2020	770278	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
LOAD25	Myrtleford - Workshop	Susp\HOUSEKEEP	inspect all suspension for replacement fit kit to rear diff vee stay				07/08/2020	770278	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
LOAD25	Myrtleford - Workshop	DrivLine\SUSPENSION	fit v stay front bushes				07/08/2020	770278	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
LOAD25	Myrtleford - Workshop	Susp\SWAYBAR	fit front drive sway bar bushes				07/08/2020	770278	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
LOAD25	Myrtleford - Workshop	Body\HOUSEKEEP	wash down rear susp				07/08/2020	770278	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
LOAD25	Myrtleford - Workshop	Engine\BOOST HOSE	fit new button boost hose				07/08/2020	770278	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
LOAD25	Myrtleford - Workshop	DrivLine\OIL LEAK	FRONT DIFF RESEAL DOOR RUBBERS NEED GLUING BOTH SIDES.	inspected all good			07/08/2020	770278	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
LOAD25	Myrtleford - Workshop	DrCabRep\DOOR LOCK	RUBBER BEHIND SEAT	inspected all good inspected no leaks nut is tight			07/08/2020	770278	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
			g/box yoke seal														
LOAD25	Myrtleford - Workshop	DrivLine\GEARBOX	parts ordered	outout bearing is in of replacement aux section needs to be removed			07/08/2020	770278	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
LOAD25	Myrtleford - Workshop	Susp\SUSPENSION	shackle pins and bushes - parts ordered (T9328)				07/08/2020	770278	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
				inspected all good													
LOAD25	Myrtleford - Workshop	Elect\INDICATORS	removed LHF indicator. Wrong part delivered - re- ordered	fit blinker liaht TCTC			07/08/2020	770278	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
LOAD25	Myrtleford - Workshop	Body\HOSES	turbo oil supply hose	inspected all good			07/08/2020	770278	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
LOAD25	Myrtleford - Workshop	Susp\SWAYBAR	sway bar rubbers (all) rear	inspected only front need doing			07/08/2020	770278	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
LOAD25	Myrtleford - Workshop	Body\HOUSEKEEP	Rattle In Drivers Door				07/08/2020	770278	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
LOAD25	Myrtleford - Workshop	DrCabRep\HOUSEKEEP	gear shift boot under cab needs repair/replace(T9331). gear shift boot under cab needs repair/replace	remove old boot and g-shift			07/08/2020	770278	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
LOAD25	Myrtleford - Workshop	Susp\AIR BAG	replace RHF drive airbag on front drive axle				06/08/2020	770279	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
LOAD25	Wodonga - Workshop	DrCabRep\SEAT	DRIVER SEAT REQUIRES A SEAT COVER.	RR's pre Jan 20 (system clean out) 05/08/20			06/08/2020	770278	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Wodonga Workshop		LOADER
LOAD25	Wodonga - Workshop	DrCabRep\SEAT	TRUCK NEEDS SEAT COVER	as above			06/08/2020	770278	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Wodonga Workshop		LOADER
LOAD25	Wodonga - Workshop	DrCabRep\HOUSEKEEP	DOOR TRIM NEEDS REPLACING (T9305). DOOR TRIM NEEDS REPLACING	as per entry no.128168 (LH 6/8/20)			06/08/2020	770278	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Wodonga Workshop		LOADER
LOAD25	Wodonga - Workshop	Body	please inquire on heater parts and T9429 T9433. please inquire on heater parts and	check heater controls			06/08/2020	770278	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Wodonga Workshop		LOADER
LOAD25	Wodonga - Workshop	DrCabRep\ELECT P&W	upgrade interior light				06/08/2020	770278	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Wodonga Workshop		LOADER
LOAD25	Wodonga - Workshop	DrCabRep\ELECT P&W	upgrade interior light bulb T9456. upgrade interior light bulb				06/08/2020	770278	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Wodonga Workshop		LOADER
LOAD25	Wodonga - Workshop	Body\EXHAUST	top of stack is gone?				06/08/2020	770278	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Wodonga Workshop		LOADER
LOAD25	Wodonga - Workshop	Air Con\AIR CON	Air Conditioning				06/08/2020	770278	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Wodonga Workshop		LOADER
LOAD25	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				06/08/2020	770279	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
				fixed wiper washers replaced blades													
				fixed all drains on air tanks													
LOAD25	Myrtleford - Workshop	VehService\BS	B Service As Per Attached Checklist	insoected suoxemsion to see what oarts to order			06/08/2020	770278	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
LOAD25	Myrtleford - Workshop	DrivLine\CLUTCH	clutch is about gone	TCTC fitted new clutch when the engine wash changed			06/08/2020	770279	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop		LOADER
				fit new turbo supplied by UTW													
				warranty job													
LOAD25	Albury - Workshop	Engine\ENG REBLD	Fit Reco 2nd hand engine from UTW change parts from Old engine to New engine to suit volvo truck	fit new thermostates			25/07/2020	770279	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 TWIN CITY TRUCK CENTRE - 4 - OLD		LOADER
LOAD25	Albury - Workshop	DrivLine\CTCH PACK	Fit new clutch kit				25/07/2020	770279	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 TWIN CITY TRUCK CENTRE - 4 - OLD		LOADER
LOAD25	Albury - Workshop	Engine\MOUNTS	Fit front engine mounts				25/07/2020	770279	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 TWIN CITY TRUCK CENTRE - 4 - OLD		LOADER
LOAD25	Albury - Workshop	Engine\BELTS/TENS	Fit new belts and tensioners				25/07/2020	770279	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 TWIN CITY TRUCK CENTRE - 4 - OLD		LOADER
LOAD25	Albury - Workshop	Engine\HOUSEKEEP	Replace engine fan rubber				25/07/2020	770279	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 TWIN CITY TRUCK CENTRE - 4 - OLD		LOADER
LOAD25	Albury - Workshop	Cooling\RADIATOR	Debug radiator and intercooler				25/07/2020	770279	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 TWIN CITY TRUCK CENTRE - 4 - OLD		LOADER
				repair aircon and regas													
				replace heater core orings													
LOAD25	Albury - Workshop	Engine\ELECT P&W	Repair engine bay and head light wiring & repair a/con & regas & repair heater leak (T9285)	repair horton wiring			25/07/2020	770279	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 TWIN CITY TRUCK CENTRE - 4 - OLD		LOADER
LOAD25	Wodonga - Workshop	Elect\ELECT P&W	pulled off micro switch from loader to see if we could get a new one				10/07/2020		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Wodonga Workshop		LOADER
LOAD25	Wodonga - Workshop	Workshop\MOVE ASSET	went to arkon and picked up microswitch anf fitted				09/07/2020		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Wodonga Workshop		LOADER
LOAD25	Wodonga - Workshop	Chassis\HYDRAULICS	repair hydraulic leak at slew motor	Rapid Hydrulics to supply parts WW056161			09/07/2020		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Wodonga Workshop		LOADER
LOAD25	Wodonga - Workshop	Hydraulics\OIL LEAK	inspect loader for hydraulic leak	replaced O rings in slew motor fittings			08/07/2020		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Wodonga Workshop		LOADER
LOAD25	Wodonga - Workshop	Elect\BATTERY	jump start	using decommisioned scania still have no 24 volt jump starting capable equipment for w/shopas addressed in toolbox meeting 23/1/1			11/05/2020	770124	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Wodonga Workshop		LOADER
LOAD25	Albury - Workshop	Engine\COOL LEAKS	repaired coolant leak				24/04/2020	770051	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Albury Workshop		LOADER
			removed LH step and removed blank plug from rear cylinder head														
LOAD25	Albury - Workshop	Body\HOUSEKEEP	replaced o-ring on plug, reassembled, added coolant, ran and tested				24/04/2020	770051	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Albury Workshop		LOADER
LOAD25	Tumut - Workshop	Engine\COOL LEAKS	fit clamp to rear of engine pipe cover with sealant fill with coolant and top up oil				01/04/2020	976710	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Tumut Workshop		LOADER
			drive to Adelong all good Billy Mae take truck over called to little billabong top up coolant and oil engine light on														
LOAD25	Tumut - Workshop	Workshop\MOVE ASSET	I drive into cummins				01/04/2020	976710	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Tumut Workshop		LOADER
			check major coolant leak from rear of head														
			drain coolant and clean and dry blocking plate at rear of head (unable to remove) and seal with good sealant														
			leave overnight to set														
			#vehicle to be driven to Cummins for repair tomorrow														
LOAD25	Rosewood - Workshop	Engine\COOL LEAKS	return home				31/03/2020	769289	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Rosewood Workshop		LOADER
			Drop Bonnet,														
LOAD25	Rosewood - Workshop	Body\HOUSEKEEP	Load Crane				31/03/2020	769289	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Rosewood Workshop		LOADER
LOAD25	Tumut - Workshop	Chassis\HYDRAULICS	back LHS leg ram pin has broken keeper bolt	fit new pin and bolt			31/03/2020		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Tumut Workshop		LOADER
LOAD25	Rosewood - Workshop	Chassis\DAMAGE	Rear LHS leg ram pin has broken keeper bolt	Fit new pin & bolt			30/03/2020	769550	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Rosewood Workshop		LOADER
LOAD25	Tumut - Workshop	Engine\EXHAUST	exhaust leaking change flexi pipe	replace flexi pipe on motor			13/03/2020	768509	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Tumut Workshop		LOADER
LOAD25	Tumut - Workshop	Engine\EXHAUST	exhaust fumes in cab of truck Rear LHS Shocker Gone				13/03/2020	768509	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Tumut Workshop		LOADER
LOAD25	Tumut - Workshop	DrivLine\SHOCK ABS	Replaced Rob Toppin				08/03/2020	765900	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Tumut Workshop		LOADER
LOAD25	Tumut - Workshop	Elect\HEAD LIGHT	RHS headlight needs bulb	RHS headlight bulb not plugged in			07/03/2020	767857	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Tumut Workshop		LOADER
LOAD25	Tumut - Workshop	Engine\OIL LEAK	fit new dipstick				01/03/2020	767085	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Tumut Workshop		LOADER
LOAD25	Tumut - Workshop	VehService\BS	B Service				01/03/2020	767085	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Tumut Workshop		LOADER
				truck will not keep running													
				check coolant levels and sensors clean top up													
LOAD25	Tumut - Workshop	Engine\HOUSEKEEP	truck won't keep running 2:15am	check eneine oil			27/02/2020	766756	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Tumut Workshop		LOADER
LOAD25	Tumut - Workshop	DrCabRep\WIPERS	replace wiper blades				16/02/2020	765036	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Tumut Workshop		LOADER
LOAD25	Tumut - Workshop	Engine\HOUSEKEEP	check oil top up 5liters engine				16/02/2020	765036	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Tumut Workshop		LOADER
			when out on call out for for another vehicle I observed a flat steer tyre, we left vehicle at location. No spare.														
			I returned to Tumut to get a spare and driver, no spare due to Beaurepairs not retuning it after repairs														
			Call Beaurepairs hotline and organised fitter to attend														
LOAD25	Rosewood - Workshop	Tyres\BREAKDOWN	return home				14/02/2020		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Rosewood Workshop		LOADER
				replace rear airbag LH rear and front bay													
				cut off stripped nut													
LOAD25	Rosewood - Workshop	DrivLine\SUSPENSION	replace rear airbag	revair damaaed air line			11/02/2020	764297	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Rosewood Workshop		LOADER
			lift off crane throw bonnet check oil														
LOAD25	Tumut - Workshop	Engine\HOUSEKEEP	add 10liters drain air tanks				09/02/2020	764220	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Tumut Workshop		LOADER
LOAD25	Tumut - Workshop	Engine\HOUSE

LOAD25	Tumut - Workshop	Workshop\MOVE ASSET	seems ok after road test		06/02/2020	763640	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Tumut Workshop	LOADER
LOAD25	Tumut - Workshop	Elect\ELECT P&W	deck light not working - probably fuse?	replace fuse on deck light	04/02/2020	763400	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Tumut Workshop	LOADER
LOAD25	Tumut - Workshop	Engine\BOOST HOSE	intercooler hoses came off and bracket needs fixing	intercooler hose off fixing bracket broken	01/02/2020	763087	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Tumut Workshop	LOADER
				air tank bracket on front left side broken off remove tank and bracket prepare and weld gussett crack fit new air fittings and bolts										
LOAD25	Tumut - Workshop	Body\MOUNTS	bracket stapped on air tank at front left	P/O T U7711	25/01/2020	762075	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Tumut Workshop	LOADER
LOAD25	Tumut - Workshop	Tyres\BREAKDOWN	front right tyre (2am)	flat steer tyre bondo called out change take flat to Beaurepairs	25/01/2020	762075	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Tumut Workshop	LOADER
LOAD25	Tumut - Workshop	Chassis\CALIPER	RHS Front Leg Plate Is Cracked		24/01/2020	3027	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Tumut Workshop	LOADER
				throw bonnet check over engine fluids										
LOAD25	Tumut - Workshop	Steering\HOUSEKEEP	power steering fluid may be low, please check	2liters ATF topped up	22/01/2020	761360	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Tumut Workshop	LOADER
LOAD25	Tumut - Workshop	DrCabElect\ELECT P&W	driving lights switch is faulty or has loose wire	driving light switch playing up removed cleaned up terminals on switch and plug ok	22/01/2020	761360	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Tumut Workshop	LOADER
				called out to shortout rd. lower boost hose on drivers side torn and completely blown off										
				correct part not in stock, have photgraped and got Wayne onto it. Have doctored one up temporarily										
				#enaine has been dusted										
LOAD25	Tumut - Workshop	Engine\BOOST HOSE	blown air intake hoses to engine		17/01/2020	760906	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Tumut Workshop	LOADER
LOAD25	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job		09/01/2020		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Tumut Workshop	LOADER
			B Service As Per Attached Checklist											
LOAD25	Tumut - Workshop	VehService\BS	Paxerwork to come Rob Toozin & Gordon Mackinlav did service		09/01/2020		Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Tumut Workshop	LOADER
LOAD25	Tumut - Workshop	Engine\EXHAUST	replace exhaust stack		14/12/2019	759175	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Tumut Workshop	LOADER
LOAD25	Tumut - Workshop	Insp\RWC COMP	AS PER DEFECT NOTICE OFF TO SCAN PICKUP VARIOUS PHONE CALLS WINDSCREEN PARTS ETC. TIE ROD ENDS REMOVED AND REPLACED. SIDE MARKER LAMPS REPLACED REAR COMBO LIGHTS REPLACED BRING CLIMM CLEARANCE NOTICE; DEFECT HAS BEEN CLEARED: INSPECTION NO. CA1726054		13/12/2019	759000	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Tumut Workshop	LOADER
LOAD25	Myrtleford - Workshop	Insp\RWC COMP	clear all defect items		06/12/2019	758500	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop	LOADER
LOAD25	Rosewood - Workshop	DrCabRep\SEAT	DRIVER SEAT REQUIRES A SEAT COVER.		14/11/2019	755400	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Rosewood Workshop	LOADER
LOAD25	Rosewood - Workshop	DrCabRep\DOOR LOCK	RHS DOOR HANDLE GETTING HARD TO OPEN		14/11/2019	755400	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Rosewood Workshop	LOADER
LOAD25	Rosewood - Workshop	DrCabRep\SEAT	DRIVERS SEAT NEEDS A COVER		14/11/2019	755400	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Rosewood Workshop	LOADER
LOAD25	Rosewood - Workshop	DrCabRep\SEAT	SEAT STILL NEEDS A SEAT COVER		14/11/2019	755400	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Rosewood Workshop	LOADER
LOAD25	Rosewood - Workshop	Body\HOUSEKEEP	NEED AXE BOUGHT FOR LOADER		14/11/2019	755400	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Rosewood Workshop	LOADER
			DOOR RUBBERS NEED GLUING BOTH SIDES.											
LOAD25	Rosewood - Workshop	DrCabRep\DOOR LOCK	RUBBER BEHIND SEAT		14/11/2019	755400	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Rosewood Workshop	LOADER
LOAD25	Rosewood - Workshop	DrCabRep\SEAT	SEAT NEEDS LOOKING AT GOING FLAT		14/11/2019	755400	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Rosewood Workshop	LOADER
			PHONE IN TRUCK NEEDS LOOKING AT, SOMETIMES DOES NOT WORK.											
LOAD25	Rosewood - Workshop	DrCabElect\PHONE	MAKES A FUNNY SOUND LIKE A FAX. WHEN NOT EVEN USING, NEEDS REPLACING.		14/11/2019	755400	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Rosewood Workshop	LOADER
LOAD25	Rosewood - Workshop	DrCabRep\SEAT	SEAT HAS NO SEAT COVER		14/11/2019	755400	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Rosewood Workshop	LOADER
LOAD25	Rosewood - Workshop	DrCabRep\SEAT	TRUCK NEEDS SEAT COVER		14/11/2019	755400	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Rosewood Workshop	LOADER
LOAD25	Rosewood - Workshop	DrCabRep\HOUSEKEEP	DOOR RUBBER RHS NEEDS GLUING.		14/11/2019	755400	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Rosewood Workshop	LOADER
LOAD25	Rosewood - Workshop	DrCabElect\INST/GAUGE	TEMP GAUGE SITTING ON HOT ALL THE TIME.		14/11/2019	755400	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Rosewood Workshop	LOADER
LOAD25	Rosewood - Workshop	Air Con\AIR CON	AIR CON STILL NOT WORKING PROPERLY.		14/11/2019	755400	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Rosewood Workshop	LOADER
LOAD25	Rosewood - Workshop	DrCabRep\HOUSEKEEP	DOOR TRIM NEEDS REPLACING		14/11/2019	755400	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Rosewood Workshop	LOADER
LOAD25	Rosewood - Workshop	DrCabElect\INST/GAUGE	tacho needs replacing		14/11/2019	755400	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Rosewood Workshop	LOADER
LOAD25	Rosewood - Workshop	Elect\DRV LIGHT	driving light not working		14/11/2019	755400	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Rosewood Workshop	LOADER
LOAD25	Rosewood - Workshop	DrCabElect\INST/GAUGE	tacho not working		14/11/2019	755400	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Rosewood Workshop	LOADER
LOAD25	Rosewood - Workshop	DrCabElect\INST/GAUGE	dash light not working L/H side		14/11/2019	755400	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Rosewood Workshop	LOADER
LOAD25	Rosewood - Workshop	Body\AIR LEAK	air leak under cab		14/11/2019	755400	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Rosewood Workshop	LOADER
LOAD25	Rosewood - Workshop	Body\AIR LEAK	air leak still under seat		14/11/2019	755400	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Rosewood Workshop	LOADER
LOAD25	Rosewood - Workshop	Susp\SHOCK ABS	LHS back shock top rubber mount needs replacing		14/11/2019	755400	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Rosewood Workshop	LOADER
LOAD25	Rosewood - Workshop	Elect\DRV LIGHT	LHS driving light needs fixing. Hit with grab		14/11/2019	755400	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Rosewood Workshop	LOADER
LOAD25	Rosewood - Workshop	DrCabElect\RADIO	truck phone u/s		14/11/2019	755400	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Rosewood Workshop	LOADER
LOAD25	Rosewood - Workshop	DrivLine\CLUTCH	clutch brake adjustment		14/11/2019	755400	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Rosewood Workshop	LOADER
LOAD25	Rosewood - Workshop	Steering\STEER UNI	steering shaking bad at 100ks		14/11/2019	755400	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Rosewood Workshop	LOADER
LOAD25	Rosewood - Workshop	DrCabElect\INST/GAUGE	temp gauge reading hot all the time temp gauge on and off all the time		14/11/2019	755400	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Rosewood Workshop	LOADER
LOAD25	Rosewood - Workshop	DrivLine\CLUTCH	next to no clutch		14/11/2019	755400	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Rosewood Workshop	LOADER
LOAD25	Rosewood - Workshop	Steering\CONSUMABLE	vibration around 85km to 95km in steering		14/11/2019	755400	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Rosewood Workshop	LOADER
LOAD25	Rosewood - Workshop	Body\DAMAGE	anti slip tape on RHS tank is dangerous/replace		14/11/2019	755400	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Rosewood Workshop	LOADER
LOAD25	Rosewood - Workshop	DrCabRep\WINDOW REG	LHS window not working		14/11/2019	755400	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Rosewood Workshop	LOADER
LOAD25	Rosewood - Workshop	Engine\FUEL TANK	LHS tank step is loose		14/11/2019	755400	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Rosewood Workshop	LOADER
LOAD25	Rosewood - Workshop	Elect\HEAD LIGHT	replace both headlight unit, dull and lenses are perished		14/11/2019	755400	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Rosewood Workshop	LOADER
LOAD25	Rosewood - Workshop	Elect\HEAD LIGHT	low beam needs replaced		14/11/2019	755400	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Rosewood Workshop	LOADER
LOAD25	Rosewood - Workshop	Hydraulics\RAM	needs tips welded on the ends of the grab		14/11/2019	755400	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Rosewood Workshop	LOADER
LOAD25	Rosewood - Workshop	Brakes			14/11/2019	755400	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Rosewood Workshop	LOADER
LOAD25	Rosewood - Workshop	VehService\AS	Due for A Service		14/11/2019	755400	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Rosewood Workshop	LOADER
LOAD25	Rosewood - Workshop	VehService\AS	Service Due in 440km		14/11/2019	755400	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Rosewood Workshop	LOADER
LOAD25	Rosewood - Workshop	VehService\AS	Service Due at 740,000		14/11/2019	755400	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Rosewood Workshop	LOADER
LOAD25	Rosewood - Workshop	VehService\AS	Service Due in 600km		14/11/2019	755400	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Rosewood Workshop	LOADER
LOAD25	Rosewood - Workshop	VehService\AS	A SERVICE		14/11/2019	755400	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Rosewood Workshop	LOADER
LOAD25	Albury - Workshop	Elect\ELECT P&W	LHS work light on main boom has broken wire or bad connection at plug or just above		13/11/2019	2610	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Albury Workshop	LOADER
LOAD25	Albury - Workshop	Elect\DRV LIGHT	LED driving lights have failed and should be under warranty		07/11/2019	955055	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Albury Workshop	LOADER
			check for fire audit											
			fire fighting pump seized											
			fitted new rake hoe											
LOAD25	Tumut - Workshop	DrCabRep\HOUSEKEEP	checked fire extinguishers		18/10/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Tumut Workshop	LOADER
LOAD25	Tumut - Workshop	Body\EXHAUST	top of stack is gone?		10/09/2019	746263	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Tumut Workshop	LOADER
LOAD25	Myrtleford - Workshop	Chassis\BULLBAR	weld front bar cracks		24/08/2019	744932	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Myrtleford Workshop	LOADER
LOAD25	Albury - Workshop	Engine\BELTS/TENS	diagnosed and replaced alternator, a/c and fan belts		17/08/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Albury Workshop	LOADER
LOAD25	Albury - Workshop	Engine\COOL LEAKS	repaired coolant leaks and topped up system		17/08/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Albury Workshop	LOADER
LOAD25	Albury - Workshop	Body\DAMAGE	refitted missing RH cabin cover		17/08/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Albury Workshop	LOADER
LOAD25	Albury - Workshop	Body\DAMAGE	replaced broken "p" clamps		17/08/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabElect\ELECT P&W	repaired tacho wiring		17/08/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Albury Workshop	LOADER
LOAD25	Wodonga - Workshop	Steering\OIL LEAK	Repaired power steering leaks & topped up oil	Degreased & washed engine	16/08/2019	744816	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Body\DAMAGE	Repaired RHS tank steps		16/08/2019	744816	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Body\MUDGUARDS	Tightened RHS steer outrigger & repaired guard		16/08/2019	744816	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Steering\DAMAGE	Removed, rebuilt & refitted steering shaft		16/08/2019	744816	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Workshop\MOVE ASSET	Picked up from TCTC		16/08/2019	744802	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Workshop\MOVE ASSET	Pick up from TCTC		16/08/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Body\EXHAUST	Repaired & replaced exhaust		09/08/2019	744780	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Wodonga Workshop	LOADER
LOAD25	Wodonga - Workshop	Workshop\MOVE ASSET	Drop off at TCTC		09/08/2019	744780	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Wodonga Workshop	LOADER
				Attended vehicle roadside & removed broken studs.										
LOAD25	Rosewood - Workshop	DrivLine\DAMAGE	Broken studs on diff housing	Reolaced 3x studs (1x to be removed in workshop) & reassembled torque rod mounts	06/08/2019	174555	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Rosewood Workshop	LOADER
LOAD25	Rosewood - Workshop	Body\HOUSEKEEP	Took to tumut & thouroughly pressure washed		06/08/2019	174555	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Rosewood Workshop	LOADER
LOAD25	Rosewood - Workshop	Workshop\MOVE ASSET	Brought loader back to Rosewood		06/08/2019	174555	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Rosewood Workshop	LOADER
			REPAIRS CARRIED OUT BY TCTC.											
LOAD25	Rosewood - Workshop	Brakes\BRK RELINE	RELINED REAR AXLE		06/08/2019	174535	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Rosewood Workshop	LOADER
LOAD25	Tumut - Workshop	VehService\AS	needs service done asap 5000km over		03/08/2019	745803	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Tumut Workshop	LOADER
LOAD25	Tumut - Workshop	Elect\HEAD LIGHT	low beam needs replaced		01/08/2019	1744252	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Tumut Workshop	LOADER
LOAD25	Tumut - Workshop	VehService\AS	Service Due		01/08/2019	1744252	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Tumut Workshop	LOADER
LOAD25	Tumut - Workshop	Body\DAMAGE	front LHS leg pin looks broken		27/07/2019	743700	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Tumut Workshop	LOADER
				UHF left on all weekend & isolator NOT turned off										
LOAD25	Rosewood - Workshop	Elect\BREAKDOWN	Called out at 2:30am to Tumut. Flat battery, no start	Drivers tried to start but had jumper leads crossed and reversed the polarity of the batteries	16/07/2019	748872	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Rosewood Workshop	LOADER
				Both batteries replaced, checked charge rate = 27.2v all good										
LOAD25	Rosewood - Workshop	Elect\BATTERY	Battery replacement	returned to Rosewood	16/07/2019	748872	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Rosewood Workshop	LOADER
LOAD25	Albury - Workshop	Air Con\HEATER	FAILED HEATER CORE		19/06/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Albury Workshop	LOADER
LOAD25	Rosewood - Workshop	Body\HOUSEKEEP	apply safety tape on tanks steps etc.		16/06/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Rosewood Workshop	LOADER
LOAD25	Rosewood - Workshop	Elect\HOUSEKEEP	check lights		16/06/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Rosewood Workshop	LOADER
LOAD25	Rosewood - Workshop	Chassis\HOUSEKEEP	grease		16/06/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Rosewood Workshop	LOADER
LOAD25	Rosewood - Workshop	Brakes\BRAKE ADJ	need to get to Rosewood for brake adjust input		16/06/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Rosewood Workshop	LOADER
LOAD25	Albury - Workshop	Body\DH&S	replace grip tape on RHS tank		15/06/2019	739056	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabRep\ELECT P&W	upgrade interior light bulb		15/06/2019	739056	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Albury Workshop	LOADER
LOAD25	Albury - Workshop	VehService\AS	Service Due at 740,000		15/06/2019	739056	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Albury Workshop	LOADER
LOAD25	Albury - Workshop	Engine\COMPRESSOR	compressor hot line blown		24/05/2019	737192	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Albury Workshop	LOADER
LOAD25	Rosewood - Workshop	DrCabRep\AIR LEAK	diagnose air leak, severe in Tumut yard. Found blown "hotline"		24/05/2019	737171	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Rosewood Workshop	LOADER
LOAD25	Rosewood - Workshop	Hydraulics\HOSES	removed, had new one made and fitted, tested. All good		24/05/2019	737171	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Rosewood Workshop	LOADER
LOAD25	Rosewood - Workshop	Elect\WORK LIGHT	1x manual switch for deck lights - over ride timer switch or remove		24/05/2019	737171	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Rosewood Workshop	LOADER
LOAD25	Albury - Workshop	Engine\AIR LEAK	air leak under cab		22/05/2019	736881	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Albury Workshop	LOADER
LOAD25	Albury - Workshop	Elect\HEAD LIGHT	REPLACE HEAD LIGHT INSERTS.		19/04/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Albury Workshop	LOADER
LOAD25	Rosewood - Workshop	Engine\COOL LEAKS	repair coolant leaks from bottom		12/04/2019	734673	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Rosewood Workshop	LOADER
LOAD25	Rosewood - Workshop	VehService\AS	A service completed		12/04/2019	734673	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Rosewood Workshop	LOADER
LOAD25	Albury - Workshop	Susp\SHOCK ABS	RHF SHOCKER NEEDS REPLACING		09/04/2019		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabElect\INST/GAUGE	no power at switches to activate deck lights. Very dark and dangerous		02/04/2019	733664	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Albury Workshop	LOADER
LOAD25	Rosewood - Workshop	Engine\AIR LEAK	slow motor leaking grapple very slow		28/03/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Rosewood Workshop	LOADER
			lift boom rams not working ring Nich											
LOAD25	Rosewood - Workshop	Hydraulics\RAM	go through it with him take to scan eng		28/03/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Rosewood Workshop	LOADER
LOAD25	Rosewood - Workshop	Body\DAMAGE	remove and refit leg pin on prentice		26/03/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Rosewood Workshop	LOADER
			REPLACE BROKEN BOLTS											
LOAD25	Albury - Workshop	Susp\Torque Rod	AS PER INVOICE		22/03/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Tumut Workshop	LOADER
LOAD25	Albury - Workshop	Cooling\RADIATOR	removed and replaced lower radiator bushes		26/02/2019	731441	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Albury Workshop	LOADER
LOAD25	Albury - Workshop	Brakes\BRAKE ADJ	replaced front steer brakes		26/02/2019	731441	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Albury Workshop	LOADER
			removed and repaired interior light											
LOAD25	Albury - Workshop	DrCabElect\RADIO	replaced phone with unit removed from decommissioned truck		20/02/2019	730111	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Albury Workshop	LOADER
LOAD25	Albury - Workshop	Elect\HEAD LIGHT	replaced RH hi/low beam globe		17/02/2019	729812	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Albury Workshop	LOADER
LOAD25	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		17/02/2019	729812	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Albury Workshop	LOADER
LOAD25	Albury - Workshop	VehService\AS	A Service		17/02/2019	729812	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Albury Workshop	LOADER
			diagnosed and replaced batteries. Tested.											
			pick up batteries from Marshalls (Repower Ace)											
			remove spare tyre hyd oil/coolant drums											
			remove battery box lid to access batteries											
			test batteries didn't seem to bad											
			had reports that operator leaving park lights on all night											
LOAD25	Albury - Workshop	Elect\BATTERY	replaced batteries, refit all other parts		14/02/2019	729111	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabElect\RADIO	truck phone u/s		14/02/2019	729219	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Albury Workshop	LOADER
LOAD25	Albury - Workshop	Elect\HEAD LIGHT	RHS headlight out		14/02/2019	729219	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Albury Workshop	LOADER
LOAD25	Albury - Workshop	VehService\AS	Due for A Service		14/02/2019	729219	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Albury Workshop	LOADER
			high/low range change grinding											
LOAD25	Albury - Workshop	DrivLine\GEARBOX	intera light truck needs upgrading		13/02/2019		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Albury Workshop	LOADER
LOAD25	Albury - Workshop	Elect\BATTERY	needs new batteries		13/02/2019		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabElect\RADIO	truck phone is u/s		09/02/2019	728258	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrivLine\CLUTCH	clutch brake adjustment		09/02/2019	728258	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Albury Workshop	LOADER
LOAD25	Albury - Workshop	Steering\STEER UNI	steering shaking bad at 100ks		09/02/2019	728258	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabElect\RADIO	phone no good keeps shutting down turn off turn on by itself		08/02/2019	727898	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Albury Workshop	LOADER
LOAD25	Albury - Workshop	Body\MUDGUARDS	replace damaged mudflap. Tyre damage		01/02/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Albury Workshop	LOADER
LOAD25	Albury - Workshop	Engine\BOOST HOSE	LF drive booster mount bracket cracked		31/01/2019	726042	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Albury Workshop	LOADER
LOAD25	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		31/01/2019	726042	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Albury Workshop	LOADER
LOAD25	Albury - Workshop	VehService\AS	Service		31/01/2019	726042	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Albury Workshop	LOADER
LOAD25	Albury - Workshop	Elect\ELECT P&W	replaced damaged side marker RHR		30/01/2019	723753	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrivLine\WHEEL BRGS	replaced steer bearings and seals		13/01/2019	271917	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897 Albury Workshop	LOADER
LOAD25	Albury - Workshop	Brakes\BOOSTER	replaced RH

LOAD2S	Albury - Workshop	DrivLine|CLUTCH	adjust clutch brake		11/01/2019	712595	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		11/01/2019	712595	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	VehService|BS	B Service		11/01/2019	712595	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	VehService|BS	B Service almost due		11/01/2019	712595	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	DrCabElect|INST/GAUGE	temp gauge reading hot all the time temp gauge on and off all the time		09/01/2019	720588	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Body|TOOLBOX	toolbox needs moving		09/01/2019	720588	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
				repaired damaged RH step											
LOAD2S	Albury - Workshop	Body|DAMAGE	R/H side fuel tank step needs looking at think step mount broken (Saturday day shift)	made new bracket (front) for steo	20/12/2018	717832	Fault	Comolated	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
			end play in steer wheel bearings												
			removed hub cover for adjustment												
			unadjustable pressed in style bearings												
			order wheel bearings												
LOAD2S	Albury - Workshop	DrivLine|WHEEL BRGS	re-filled with oil	COMPLETED 12/01/2019	13/12/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Brakes|BRK RELINE	PARTS ORDERED TO RELINE STEER.		13/12/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Tyres|DRV TYRES	Drive Tyres	removed front drive axle wheels + replaced brake drums	13/12/2018	715818	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Engine|CAC	Charge Air Cooler	removed and replaced intercooler, washed out radiator, re-placed O-rings, hosesand lamps, re mounted radiator top tank correctly	12/12/2018	71588	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Engine|FILTERS	Filters	replaced air filters	12/12/2018	71588	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Tyres|DRV TYRES	Drive Tyres	tensioned front drives	12/12/2018	71588	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Tyres|STEER TYRE	Steer Tyres	replaced LHS steer wheel stud	12/12/2018	71588	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Engine|TURBO	Turbo Change	assisted cummins with turbo replacement	12/12/2018	71588	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	DrivLine|BRK RELINE	reline front drive axle		11/12/2018	715561	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
			access intercooler and inspect leak												
LOAD2S	Albury - Workshop	Cooling|COOL LEAKS	measure for replacement with border radiators		11/12/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Engine|TURBO	turbo requires replacement, oil seals failure		09/12/2018	71500	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Engine|RADIATOR	intercooler leaking		09/12/2018	71500	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Engine|FILTERS	air filter required AF25239		09/12/2018	71500	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Steering|WHEEL BRGS	steer bearings need adjust		09/12/2018	71500	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Susp|SUSPENSION	tightened loose steer u-bolts		09/12/2018	71500	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	DrivLine|GEARBOX	gearbox output loose/leaking		09/12/2018	71500	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Brakes|BRK O/HAUL	LF drive brakes worn out		09/12/2018	71500	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Engine|OIL/FILTER	added 4L engine oil		09/12/2018	71500	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Engine|FUEL TANK	tightened tank stays		09/12/2018	71500	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Body|DAMAGE	unblocked LHS washers		09/12/2018	71500	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Body|HOSES	tightened inlet pipes		09/12/2018	71500	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		09/12/2018	71500	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	VehService|AS	A Service		09/12/2018	71500	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Susp|SHOCK ABS	LHS back shock top rubber mount needs replacing		07/12/2018	715013	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
			truck needs new phone												
LOAD2S	Albury - Workshop	DrCabElect|RADIO	not clear when talking to people		07/12/2018	715013	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	VehService|AS	A Service Due		07/12/2018	715013	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	DrCabRep|SEAT	replaced drivers seat		06/12/2018	714538	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Elect|DRV LIGHT	LHS driveng light needs fixing. Hit with grab		04/12/2018	713434	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
				inspected seat to be replaced											
LOAD2S	Albury - Workshop	DrCabRep|SEAT	something has broken in seat when air in very bad	neaired bent seat belt mount	01/12/2018	712916	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	DrCabRep|WIPERS	Wiper Blade/Washer Nozzle	replaced wipers	23/11/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	DrCabRep|SEAT	repaired airline in seat		22/11/2018	709892	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Body|AIR LEAK	Air Leak/s	repaired air leak at LHF airtank	21/11/2018	709718	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Steering|PWR STEER	Power Steering	topped up power steering fluid	21/11/2018	709718	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	DrivLine|OH&S	tightened the front diff mount bolts (completed)		21/11/2018	709718	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	VehService|AS	VehService|AS	a service completed- see attached	21/11/2018	709718	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Tyres|CASE STOCK	Job Added From Invoice		21/11/2018	426207	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Tyres|FITMENT	Job Added From Invoice		21/11/2018	426207	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Brakes|BRAKE ADJ	Brake Adjustment	adjusted all brakes and filled up washer bottle	16/11/2018	708818	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Elect|HEAD LIGHT	RHS headlight out	replaced RH hi/low globe and test - ok	15/11/2018	708711	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		01/11/2018	705593	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Susp|SUSPENSION	tighten loose LH u-bolts		01/11/2018	705593	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	VehService|AS	A Service overdue		01/11/2018	705593	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Tyres|FITMENT	Job Added From Invoice		31/10/2018	764378	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Tyres|RETREAD	Job Added From Invoice		31/10/2018	764378	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Tyres|FITMENT	Job Added From Invoice		31/10/2018	764738	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Tyres|RETREAD	Job Added From Invoice		31/10/2018	764738	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
			horton fan not working												
LOAD2S	Albury - Workshop	Cooling|ENG FAN	truck 300k off A Service	repaired horton electrical fault	30/10/2018	704756	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
			travel to crk road												
			horton fan not working												
			electric fault												
			plumb up fan to run contiuously												
LOAD2S	Rosewood - Workshop	Cooling|ENG FAN	return to rosewood		30/10/2018		Repair	Comolated	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Rosewood Workshop	LOADER
LOAD2S	Albury - Workshop	Engine|FUEL TANK	tightened RH tank brackets and steps		27/10/2018	704378	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Body|REFLECTORS	repaired oversize sign mounts		27/10/2018	704378	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Engine|START MOTR	load not starting properly check starter motor		24/10/2018	0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	DrCabElect|INST/GAUGE	replaced/repaired dash lights		19/10/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
			repaired air line in seat												
LOAD2S	Albury - Workshop	DrCabRep|SEAT	ordered new joiners		16/10/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Tyres|RUN OUT	Job Added From Invoice		16/10/2018	759569	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
				repaired airline in seat											
LOAD2S	Wodonga - Workshop	DrCabRep|SEAT	not air in seat blown hose	ordered new joiners	16/10/2018		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
			needs clutch adjustment												
LOAD2S	Wodonga - Workshop	DrivLine|CLUTCH	no clutch brake		16/10/2018		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Wodonga - Workshop	DrCabElect|INST/GAUGE	no dash lights		16/10/2018		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
			removed damaged air fitting												
			travel Enzed. Organise fitting												
			replaced fitting												
			fit stoppers to seat to prevent fitting from getting damaged												
LOAD2S	Wodonga - Workshop	Susp|AIR FITTIN	test ok		16/10/2018		Repair	Comolated	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Body|DAMAGE	LHS top step needs fixing bent down	replaced step brackets (LH) and straightened step (top)	16/10/2018	701248	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Body|AIR LEAK	air leak still under seat		16/10/2018	701248	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	DrivLine|CLUTCH	adjusted clutch - brake cleaned clutch brake		16/10/2018	701248	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Engine	Job Added From Invoice		10/10/2018	0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	DrCabElect|INST/GAUGE	speedo not working. Display. Repairs on going	REPLACED SPEEDO, MOUNTED IN ROOF CONSOLE	10/10/2018	700000	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Body|HOUSEKEEP	REPLACE OVERSIZE SIGN		10/10/2018	700000	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Workshop|ABOVE ASSET	drop off parts		09/10/2018	700000	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Elect|ELECT P&W	repaired wiring to RH side marker lights		06/10/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	VehService|BS	B Service Due	completed B Service 8/10/18	06/10/2018		Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	VehService|AS	A Service		06/10/2018		Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Body|HOUSEKEEP	REPLACE OVER SIZE SIGN	order, modify and fit oversize sign	16/09/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
			repaired coolant leak at header tank												
			washed down engine												
LOAD2S	Albury - Workshop	Cooling|COOL LEAKS	tooowd uo coolant		10/09/2018		Repair	Comolated	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Susp|HCV	Replaced cab suspension HCV.		07/09/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Susp|AIR FITTIN	Replaced fitting at regulator		07/09/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	DrivLine|GEARBOX	Tightened fitting at gearbox		07/09/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Susp|SWAYBAR	Replaced sway bar bushes and bolts.		07/09/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Engine|BOOST HOSE	Replaced turbo pressure line.		07/09/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Wash|WASH	Washed & degreased engine.		07/09/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Body|AIR LEAK	air leak under cab		05/09/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Hydraulics|HYD LEAKS	repaired leaking line to gearbox splitter		05/09/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Susp|HCV	diagnosed and ordered leaking cab HCV		05/09/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Susp|SWAYBAR	measured sway bar and mount for CMV		05/09/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	DrCabRep|MOUNTS	CAB HCV		04/09/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	DrivLine|DIFF REPMN	diff locks not working		04/09/2018		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Engine|OIL LEAK	REPLACE TURBO FEED HOSE.		04/09/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Susp|SUSPENSION	ORDER PARTS FOR REAR SWAY BAR BUSH REPLACEMENT.		02/09/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Body|HOSES	turbo oil supply hose		02/09/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Engine|HOSES	tightened radiator hose clamps		02/09/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Steering|PWR STEER	tightened fitting at p/steering pump		02/09/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Susp|SWAYBAR	sway bar rubbers (all)		02/09/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		02/09/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	VehService|AS	A Service		02/09/2018		Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	DrCabRep|WIPERS	Replaced wiper assembly		19/08/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Air Con|BELTS/TENS	Adjust A/C belt		19/08/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Engine|HOUSEKEEP	Checked fluids		19/08/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Susp|SHOCK ABS	Tightened shock - replaced rubber		19/08/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
			dismantled firewall												
			removed and refitted wiper assembly (wrong parts delivered)												
LOAD2S	Albury - Workshop	Body|DAMAGE	assembled truck		12/08/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Body|CHN/RLR/MN	replaced grab holder chain		10/08/2018	688181	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
				LHS wiper not working											
				diagnosed and ordered broken wiper drive pivot assembly											
LOAD2S	Albury - Workshop	DrCabRep|WIPERS	L/S windscreen wiper not working	temporarily repaired assembly	10/08/2018	688181	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	DrCabRep|WIPERS	wiper blades need replacing	replaced wiper heads	10/08/2018	688181	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Body|DAMAGE	secured firewall panels		10/08/2018	688181	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	DrivLine|DAMAGE	repaired and remounted RHF drive backing plate		29/07/2018	686029	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		29/07/2018	686029	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	VehService|AS	Service Due (30.7.18)		29/07/2018	686029	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Body|DAMAGE	REPLACE BROKEN WATER TANK.		29/07/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Elect|ELECT P&W	diagnosed start problem with re-power, ordered ignition switch. Temporarily repaired wiring		26/07/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Elect|INDICATORS	removed LHF indicator. Wrong part delivered - re- ordered		26/07/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Body|DAMAGE	replaced bolts in grab support structure		26/07/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Elect|START MOTR	REPLACED STARTER MOTOR.		26/07/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Elect|BATTERY	truck wont start - checked electrical wiring at starter/batteries and isolation switch. Rang Chris Jones and got auto elect up to find issue, no power to starter solenoid, made up dummy starter button to get home		25/07/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Elect|INDICATORS	REPLACE SIDE INDICATOR		22/07/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Engine|ALT	Diagnosed and repaired wiring to alternator		18/07/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Elect|ELECT P&W	remounted isolation control box		15/07/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Tyres|FITMENT	Job Added From Invoice		12/07/2018	0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Tyres|RETREAD	Job Added From Invoice		12/07/2018	0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	DrivLine|DIFF REPMN	checked diff locks working		04/07/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
			working lights on. Checked levels and codes												
			codes for accelerator pedal malfunction												
LOAD2S	Albury - Workshop	Engine|FAULT CODE	checked connections and calibrated		04/07/2018		Repair	Comolated	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		01/07/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Steering|PWR STEER	Topped up power steering fluid		01/07/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Engine|FUEL TANK	Tightened LH fuel tank straps		01/07/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Engine|OIL/FILTER	Topped up engine oil (3ltrs)		01/07/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	VehService|AS	A Service		01/07/2018		Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER

LOAD25	Albury - Workshop	DrCabRep\WIPERS	replaced LH wiper arm assembly		28/06/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabRep\DOOR LOCK	reseal LH door seal		28/06/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Workshop\MOVE ASSET	pick up L25 from wec		26/06/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
			removed both rear sway bars to new												
			bushes fitted refit sway bars, new bokts & nuts												
			replaced all 4 anchor chains to diffs												
LOAD25	Albury - Workshop	Susp\SUSPENSION	reset HCV's		09/06/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Susp\SUSPENSION	took sway bars to Wodonga engine to have bushes dressed in		09/06/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Elect\INDICATORS	LHS front blinker broken needs looking at	refer job#172355	31/05/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Elect\ELECT P&W	R/H back side clear light needs replacing	refer to job#172356	31/05/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Elect\INDICATORS	LHS front blinker broken needs looking at	checked LHF indicator (order new unit)	31/05/2018		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Elect\ELECT P&W	R/H back side clean light needs replacing	replaced wiring and clearance light RHR	31/05/2018		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	VehService\8S	B Service Due		24/05/2018	612333	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Elect\DRV LIGHT	driving light not working		24/05/2018	612333	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabElect\UNST/GAUGE	tacho not working		24/05/2018	612333	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabElect\UNST/GAUGE	dash light not working L/H side		24/05/2018	612333	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		24/05/2018	612333	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Brakes\BOOSTER	repaired air leak at RHF drive b/booster		24/05/2018	612333	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Cooling\COOL LEAKS	tightened hose clamps (coolant leak)		24/05/2018	612333	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Engine\EXHAUST	tightened loose exhaust bolts		24/05/2018	612333	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Body\DAMAGE	repaired LH bottom step		24/05/2018	612333	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
			g/box yoke seal												
LOAD25	Albury - Workshop	DrivLine\GEARBOX	parts ordered		24/05/2018	612333	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Susp\SUSPENSION	shackle pins and bushes - parts ordered		24/05/2018	612333	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabElect\UNST/GAUGE	speedo not working. Display. Repairs on going		24/05/2018	612333	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Tyres	Job Added From Invoice		22/05/2018	0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice		22/05/2018	0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice		22/05/2018	0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrivLine\DIFF REPAIN	diff lock not working	replaced diaphram in power lock	22/05/2018		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Susp\SHOCK ABS	replaced LHR top shocker mount and shocker		18/05/2018	670688	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Body\AIR LEAK	replaced LHF drive airbag		18/05/2018	670688	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Engine\OIL LEAK	diagnoses and ordered leaking power divider lock diaphram		18/05/2018	670688	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Susp\AIR BAG	ordered airbags and shock		18/05/2018	670688	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Elect\TAIL LIGHT	replaced broken LH tail light mounting ass		18/05/2018	670688	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Elect\TAIL LIGHT	fitted extra reverse lights		18/05/2018	670688	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Elect\HEAD LIGHT	dismantled, cleaned and assembled headlights		18/05/2018	670688	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Tyres	Job Added From Invoice		17/05/2018	0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice		17/05/2018	0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice		17/05/2018	0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Susp\AIR BAG	L/H back air bag blower	replaced LHR airbag	15/05/2018	668721	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Elect\DRV LIGHT	driving light still flashing on and off		15/05/2018	668721	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Susp\SHOCK ABS	replace shock mount and shock L/H back	removed broken shock mount and shocker	15/05/2018	668721	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabRep\WIPERS	washer bottle need looking think leaking	topped up washer bottle and checked for leaks	15/05/2018	668721	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabElect\UNST/GAUGE	tacho needs replacing		15/05/2018	668721	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Body\AIR LEAK	tested suspension for other leaks (ok)		15/05/2018	668721	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Susp\SHOCK ABS	ordered new shock mount x2		15/05/2018	668721	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Susp\SUSPENSION	ordered new sway bar bushes x4		15/05/2018	668721	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Elect\ELECT P&W	repaired wiring to lights at bonnets hinges		15/05/2018	668721	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Engine\FAULT CODE	WHEN TRUCK IS ON CRUISE THE ENGINE HAS A MISS.	REPAIRED BY CUMMINS 24/04/18	12/05/2018	1068548	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabElect\UNST/GAUGE	check truck for Service km	SPEED REPAIRED BY REPOWER AUTO ELECT	12/05/2018	1068548	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Elect\DRV LIGHT	driving lights stopped working		11/05/2018		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
				trace driving light fault											
			L/H side back light falling out	replaced circuit breaker											
LOAD25	Albury - Workshop	Elect\ELECT P&W	shorting out driving lights	tested	11/05/2018		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Body\DAMAGE	R/H side fuel tank steps need replacing	removed and repaired RH steps	09/05/2018	668723	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Susp\SUSPENSION	removed and refitted new sway bar		09/05/2018	668723	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
			Belts slipping real bad. When heater on coolant all over deck and around motor	Diagnosed and removed broken coolant leak sensor.											
			Check radiator hoses.. Blets slipping real bad. When heater on coolant all over deck and around motor	Plugged leak. Shorted sensor. Filled with coolant.											
LOAD25	Albury - Workshop	Cooling\COOL LEAKS	Check radiator hoses.	Tested.	08/05/2018	9013	Fault	Comsleted	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabRep\WIPERS	replaced wiper blades		06/05/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Workshop\CLEAN	ordered parts		04/05/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
			fitted taps to by-passed heater hoses. Tested												
LOAD25	Albury - Workshop	Body\HOSES	checked fluids		01/05/2018		Repair	Comsleted	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
			door strut need repair												
LOAD25	Albury - Workshop	Body\DAMAGE	hanging of door		26/04/2018		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Body\MOUNTS	RHS middle and botton step needs fixing	Straightened RH step. Reqiores parts	24/04/2018		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Tyres	Job Added From Invoice		24/04/2018	632162	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Tyres\STEER TYRE	Job Added From Invoice		24/04/2018	632162	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice		24/04/2018	632162	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Tyres	Job Added From Invoice		18/04/2018	0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Tyres\RUN OUT	Job Added From Invoice		18/04/2018	0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Brakes\BRK RELINE	replaced leaking brake lines to left steer		15/04/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Elect\DRV LIGHT	replaced driving lights from #957		15/04/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Brakes\BOOSTER	repaired leaking and clogged rear boosters		15/04/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Brakes\AIR LEAK	air leaking when put foot on brakes		14/04/2018		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabRep\WIPERS	replaced L/H side windscreen wiper		14/04/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Elect\DRV LIGHT	driving light not working needs replacing		14/04/2018		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Brakes\BRK RELINE	reline RHR axle		07/04/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Workshop\CLEAN	cleaned up after job completion		07/04/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Engine\AIR CLNR	removed air cleaner housing		28/03/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrivLine\CLUTCH	clutch fluid tank etc for access		28/03/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
			replaced treadle valve												
LOAD25	Albury - Workshop	Brakes\VALVES	assembled		28/03/2018		Repair	Comsleted	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		25/03/2018	356372	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	VehService\AS	A Service		25/03/2018	356372	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabRep\RADIO	fitted UHF mic holder		24/03/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
			check engine light on												
			checked codes - coded for accelerator potentiometre												
			pedal ass ordered												
LOAD25	Albury - Workshop	Engine\FAULT CODE	checked levels		21/03/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Body\MOUNTS	RHS back leg top leg pin broken		20/03/2018		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Engine	Job Added From Invoice		18/03/2018	0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
			checked brakes												
			removed and checked treadle valve push rod												
LOAD25	Albury - Workshop	Brakes\DAMAGE	checked pedal lever and bearinas		17/03/2018		Repair	Comsleted	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
			adjusted brakes												
LOAD25	Albury - Workshop	Brakes\BRAKE ADJ	ordered valve		17/03/2018		Repair	Comsleted	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
			checked brakes												
			removed and checked treadle valve push rod												
			checked pedal lever and bearings												
			adjusted brakes												
LOAD25	Albury - Workshop	Brakes\BRAKE ADJ	ordered valve		17/03/2018		Repair	Comsleted	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrivLine\GEARBOX	truck still got a miss when going through gears		14/03/2018		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabElect\TP17	tacho not working		14/03/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Elect\DRV LIGHT	L/H side drive light not working needs replacing		14/03/2018		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Elect\ELECT P&W	L/H side back clear light bracket broken		14/03/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
			Removed RH door skin.												
			Had repaired at border plastic welding.												
LOAD25	Albury - Workshop	Body\PANELS	Fitted.		09/03/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabElect\UNST/GAUGE	speedo not working	refer to job#159141	07/03/2018	651840	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
			truck has a miss down on power												
			check engine light on												
LOAD25	Albury - Workshop	Engine\FAULT CODE	diff locks not workine oroperlv	refer to iob #159142	07/03/2018	651840	Repair	Comsleted	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabElect\UNST/GAUGE	speedo not working	speedo is working - number hard to read	07/03/2018	651840	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
			truck has a miss down on power												
			check engine light on												
LOAD25	Albury - Workshop	Engine\FAULT CODE	diff locks not working properly	checked for codes - inactive code for speed sensor had Cummins here checking for engine miss. Replaced fuel filter, tightened fuel fitti	07/03/2018	651840	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabRep\SEAT	Pick up seat from Wodonga upholsterers		06/03/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrivLine\WHL HUB	Reline LHR axle (hub seal)		06/03/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Body\CHN/RLR/MN	Replaced & tightened LHR track bar bolts		06/03/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabRep\SEAT	Assemble and refit seat		06/03/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Workshop\CLEAN	Cleaned up after jobs		06/03/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Workshop	Job Added From Invoice		06/03/2018	0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrivLine\DRV LN SER	tightened drive shaft bolts at front diff		28/02/2018	650322	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Steering\SWAYBAR	tightened sway bay bolts		28/02/2018	650322	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Elect\ELECT P&W	repaired wiring to rear lights		28/02/2018	650322	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Body\MOUNTS	tightened guard bolts		28/02/2018	650322	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Body\MOUNTS	tightened LH step		28/02/2018	650322	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Engine\FAULT CODE	checked for codes - ok		28/02/2018	650322	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Elect\ELECT P&W	checked all looms		28/02/2018	650322	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Air Con\AIR CON	replaced a/c belt		28/02/2018	650322	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Engine\BELTS/TENS	replaced idler and tensioner bearings		28/02/2018	650322	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Engine\WATER PUMP	water pump tensioner bearings and belt		28/02/2018	650322	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		28/02/2018	650322	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	VehService\AS	A Service		28/02/2018	650322	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Brakes\BRK RELINE	relined LHR drive axle		28/02/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrivLine\WHEEL SEAL	replaced inner seal		28/02/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Elect\ELECT P&W	loader sometimes starts fumy check starter motor		16/02/2018		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
				Replaced damaged expansion tank											
				Replaced hose clamps											
LOAD25	Albury - Workshop	Cooling\COOL LEAKS	REPLACE LEAKING HEADER TANK	Topped up coolant tank	14/02/2018	641325	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Brakes\BRK RELINE	RELINE REAR DRIVE		11/02/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
				repaired wiring to LH side marker lights											
LOAD25	Albury - Workshop	VehService\AS	A SERVICE	degrease and wash engine (ccolant leak)	10/02/2018	645844	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		10/02/2018	645844	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Elect\TRL LIGHTS	repaired LHR side marker		02/02/2018	643518	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	VehService\8S	B SERVICE		21/01/2018		Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Elect\HEAD LIGHT	L/H side head light goes out when light beam on		11/01/2018	637858	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Engine\HEATER TAP	Heater taps need turning off		11/01/2018	637858	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabRep\WIPERS	Replace L/H side wipper blade		11/01/2018	637858	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabElect\UNST/GAUGE	Temp guage sitting on hot all the time		11/01/2018	637858	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	VehService\AS	A Service		11/01/2018	637858	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Elect\DRV LIGHT	LH DRIVING LIGHT GOING ON/OFF		11/01/2018	637858	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Elect\HEAD LIGHT	LH HEAD LIGHT GOES OUT WHEN ON HI BEAM	unload boom and tilt bonnet to replace LH hi/lo beam globe and repair wiring	11/01/2018	637858	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Air Con\HEATER	HEATER TAPS NEED TURNING OFF	inspected heater lines - no steering taps. Removed dash panels and manually turned off tap	11/01/2018	637858	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER

LOAD25	Albury - Workshop	DrCabRep\WIPERS	REPLACE LH WIPER BLADE		11/01/2018	637858	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Elect\TAIL LIGHT	LEFT SIDE LIGHT NOT WORKING	replaced wiring on LHS for side marker lights	22/12/2017	635467	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	VehService\AS	A SERVICE	replaced hot line hose	22/12/2017	635467	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		22/12/2017	635467	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Elect\TAIL LIGHT	RH REAR CLEARANCE LIGHT NEEDS REPLACING	replaced RHR side marker light	20/12/2017	635105	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Elect\TAIL LIGHT	REPAIR CLEARANCE LIGHTS		20/12/2017	635105	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
				REPAIRS BEING CARRIED OUT BY TCTC											
LOAD25	Albury - Workshop	Susp\SUSPENSION	REPLACE WORN SUSPENSION BUSHES ON REAR AND FRONT SUSPENSION.	Pickup from TCTC	08/12/2017	632380	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Tyres	Job Added From Invoice		05/12/2017	0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice		05/12/2017	0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice		05/12/2017	0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Workshop\MOVE ASSET	drop off to TCTC for suspension repairs		02/12/2017	632364	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
			had call from LZS												
			suspension laying down on L side												
			organised Kevin in Albury to trawel to Yenches and check sus/airbags												
			call received at 4:26 am												
			organised Kev at 6:15												
LOAD25	Rosewood - Workshop	Susp\BREAKDOWN	call received from Chris M. refer use of 1003 for load to Wawea		30/11/2017		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Rosewood Workshop	LOADER
LOAD25	Albury - Workshop	Susp\AIR BAG	travelled to log coup in Yenchi's Road, Lankeys creek. Replaced airbag		30/11/2017		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrivLine\AXLE REPLC	rear axle LF, including standby time whilst loading		30/11/2017		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Tyres	Job Added From Invoice		29/11/2017	0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice		29/11/2017	0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice		29/11/2017	0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	VehService\AS	A SERVICE		25/11/2017	630971	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		25/11/2017	630971	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Elect\TAIL LIGHT	RHF SIDE MARKER NOT WORKING		14/11/2017	628127	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
			seat switch was in incorrect position												
LOAD25	Albury - Workshop	DrCabRep\SEAT	tested seat - working properly		14/11/2017	628127	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabRep\SEAT	dry lubed seatbelt clip and tested		14/11/2017	628127	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Tyres\RUN OUT	Job Added From Invoice		10/11/2017	626300	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Body\CHN/RLN/MN	replaced hammer and chain eyelet		09/11/2017	637226	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Susp\AIR BAG	RHR AIR BAG NEEDS REPLACING. BAD AIR LEAK.	REPLACED AIR BAG	08/11/2017	626846	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabRep\WIPERS	RH WIPER BLADE NEEDS PUTTING BACK ON.	replaced complete wiper insert	07/11/2017	626546	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Susp\AIR BAG	RH SIDE #3 AIR BAG LEAKING AT TOP.	replaced airbag	07/11/2017	626546	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
				unload crane and lift bonnet											
LOAD25	Albury - Workshop	DrCabElect\INST/GAUGE	TEMP GAUGE NEEDS LOOKING AT, SITTING ON HOT ALL THE TIME.	checked sensors for rubbed wiring - ok	07/11/2017	626546	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabRep\WIPERS	REPLACE WIPER BLADES	replaced both wiper blades	05/11/2017	626328	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Tyres\STEER TYRE	Job Added From Invoice		02/11/2017	624724	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice		02/11/2017	624724	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Tyres\BALANCE	Job Added From Invoice		02/11/2017	624724	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
				Replaced LHF drive shocker											
				replaced RHR top shocker bolt											
				replaced RH park light globe											
LOAD25	Albury - Workshop	VehService\AS	A SERVICE	reoaired wirine to RH side marker liahts	01/11/2017	625523	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		01/11/2017	625523	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Tyres\RUN OUT	Job Added From Invoice		31/10/2017	623459	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
				replaced washer motor grommet											
				replaced washed motor											
LOAD25	Albury - Workshop	DrCabRep\WIPERS	REPLACE WASHER BOTTLE	cleaned out lines and nozzles	29/10/2017	624724	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Susp\SUSPENSION	REPLACE WORN SUSPENSION BUSHES ON REAR AND FRONT SUSPENSION.		29/10/2017	624724	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Body\AIR LEAK	REPAIRED AIR LEAKS.	REPLACED DRAIN COCK.	24/10/2017	623459	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Engine\BOOST HOSE	REPLACE BROKEN BOOST HOSE STRAP		24/10/2017	623459	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrivLine\CLUTCH	FIND FAULT WITH CLUTCH BRAKE.	clutch brake not working. Diagnose with Warren from TCTC. Remove and repair clutch lever. Replace bolts. Test	24/10/2017	623459	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Engine\CAC	replaced lower boost clamp		24/10/2017	623459	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Engine\FILTERS	replaced air filters		21/10/2017	623259	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Tyres\RUN OUT	Job Added From Invoice		21/10/2017	621345	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Brakes\AIR LEAK	AIR LEAK BEHIND CAB LEAKING BAD.	replaced drain cock valve on upper airtank beind cab	15/10/2017	621345	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	VehService	B SERVICE DUE IN 1500KM.		15/10/2017	621345	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrivLine\CLUTCH	CLUTCH BRAKE NOT WORKING	cleaned excess grease at clutch brake and adjusted	15/10/2017	621345	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	VehService\BS	B SEVICE DUE @ 620000KM	as per #131688	15/10/2017	621345	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		15/10/2017	621345	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabRep\HOUSEKEEP	WINDOW RUBBER NEEDS LOOKING AT RH SIDE	fitted bottom window rubber	08/10/2017	619552	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
			RH WIPER NEEDS REPLACING.												
LOAD25	Albury - Workshop	DrCabRep\WIPERS	FILL WASHER BOTTLE.	replaced wiper blade filled washer bottle	08/10/2017	619552	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Elect\TAIL LIGHT	LH REAR MARKER NEEDS REPLACING	replaced light and mount	08/10/2017	619552	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabRep\WIPERS	window rubber needs looking at R/H side		07/10/2017	619553	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabRep\WIPERS	R/H side wiper blade needs replacing		07/10/2017	619553	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Body\LIGHTS	L/H back clearance light needs replacing		07/10/2017	619553	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Body\WIPERS	fill washer bottom		07/10/2017	619553	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Wodonga - Workshop	Hydraulics\HOSES	LHS - hyd hose on bottom of control leaking needs looking at		06/10/2017		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Wodonga Workshop	LOADER
LOAD25	Albury - Workshop	Elect\TAIL LIGHT	RHS MARKER LIGHT NOT WORKING.	Weld mount back on, replaced led ot bracket	30/09/2017	618564	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
				ORDER PARTS FROM FLOWER AND MACKLAN.											
				PAID BY C JONES CREDIT CARD.											
LOAD25	Albury - Workshop	Body\DAMAGE	REPAIR DAMAGED FIRE FIGHTING PUMP.	Reolaced air filter housine. Reolaced air filter and ore-filter. Reolaced damaged fuel tas with external inline tao. Modified cover to suit	29/09/2017	623459	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	VehService	TRUCK HAS NO SERVICE STICKER	FITTED SERVICE STICKER	28/09/2017	617911	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Body\FUEL TANK	RH FUEL TANK NEEDS WATER DRAINED OUT AND PUT DIESEL BACK IN.	THIS CAN NOT BE DONE. THE OPERATOR KNOWS BETTER THAN THIS. THIS IS A TANK FOR THE FIRE FIGHTING PUMP.	28/09/2017	617911	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrivLine\CLUTCH	CLUTCH ADJ.	cleaned grease from clutch brake and adjusted - tested	23/09/2017	617118	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabRep\WIPERS	RH WIPER GETTING STUCK.	repaired wiper arm	14/09/2017	615653	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Engine\AIR LEAK	AIR LEAK UNDER BONNET		10/09/2017	615305	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	VehService\AS	A SERVICE DUE @ 615000KM		10/09/2017	615305	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabRep\WINDSCREEN	WIND SCREEN HAS A CRACK RUNNING THRU IT.	DONE @ TCTC BY O'BRIEN GLASS	10/09/2017	675579	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
			BOOM SUPPORT BENT AND CRACKED.												
LOAD25	Albury - Workshop	Chassis\DAMAGE	REQUIRES REMOVING AND PRESSING BACK SQUARE.	REPAIRS CARRIED OUT BY TCTC AND ALDONGA ENG.	10/09/2017		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Chassis\Boom	CRACK IN CRADDLE.		10/09/2017		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
				Replaced 2nd airbag on LHF axle											
LOAD25	Albury - Workshop	Susp\AIR BAG	LH FRONT AIR BAG NEEDS REPLACING	checked all airbags for leaks - ok	06/09/2017	614939	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabElect\RADIO	UHF MIC FAULTY	SUPPLIED DRIVER WITH A NEW HAND PIECE	03/09/2017	614150	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Engine\AIR LEAK	TRUCK DROPPING AIR. AIR LEAK UNDER BONNET		27/08/2017	612628	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Susp\AIR BAG	REPLACED FRONT AXLE REAR AIR BAG AND SHOCKER	AS PER COVER SHEET	27/08/2017	612628	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Tyres	Job Added From Invoice		22/08/2017	609726	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
				air leak											
LOAD25	Albury - Workshop	Brakes\AIR LEAK	when releasing the brake its clamping the air only does - it every second move forward when loading	could not find obvious fault	20/08/2017	610173	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		18/08/2017	610059	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
				Repaired washers and replaced blades											
				tightened door signs											
				replaced missing axle chain belt											
				requires repairs to grab rest cracks											
				requires battery isolation switch box repair											
LOAD25	Albury - Workshop	VehService\AS	A SERVICE	requires LHR booster	18/08/2017	610059	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
				AS PER JOB #59977											
				replaced rod from diff housig to HCV											
				part #1079310											
LOAD25	Albury - Workshop	Susp\HCV	LHS HCV ROD LINKAGE BROKEN	reset tide heiaht	17/08/2017	609725	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabRep\RADIO	SPEAKER BRACKET BROKEN	replaced speaker bracket	17/08/2017	609725	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabElect\PHONE	PHONE TURNS OFF WHEN TRUCK IGNITION TURNS OFF	modified wiring for phone. Replaced speaker for radio. Secured radio	17/08/2017	609725	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
			DOOR RUBBERS NEED GILLING BOTH SIDES.												
LOAD25	Albury - Workshop	DrCabRep\DOOR LOCK	RUBBER BEHIND SEAT		17/08/2017	609725	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
				REPLACED AIR BAG. REPLACED ALL OTHER LYNCH PINS AND WASHERS FOR OTHER AIR BAGS											
LOAD25	Albury - Workshop	Susp\AIR BAG	REPLACED LHR AIR BAG.	reolaced LHR axle front bae	17/08/2017	609725	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
				Travel to and from Dartmouth											
				Diagnose LHS suspension problem											
				Temporary repair to HCV to axle linkage											
LOAD25	Albury - Workshop	Susp\HCV	SUSPENSION FAULT	Order parts	16/08/2017	609630	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Susp\SPRING HANG	REPLACE LHR SWAY BAR HANGER		15/08/2017		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Susp\SWAYBAR	replaced LHR sway bar mount		13/08/2017	609184	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Workshop\W/S MAINT	travel to CMV pick up parts		13/08/2017	609184	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabElect\RADIO	AM/FM RADIO HAS NO VOLUME	replaced radio unit. Requires speakers	12/08/2017		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Body\FUEL TANK	FUEL TANK STEP BOTTOM BRACKET MISSING RH SIDE		09/08/2017		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Tyres\RUN OUT	Job Added From Invoice		27/07/2017	602970	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Susp\AIR BAG	RH SIDE BACK AIR BAGS NEED REPLACING	replaced 2 blown air bags	21/07/2017	606143	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Brakes\AIR LEAK	AIR LEAK UNDER CAB	REPLACED DRAIN COCK	20/07/2017	605833	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		16/07/2017	604885	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
				REPLACED WIPER BLADES.											
				REPAIRED AIR LEAK REAR FRONT DIFF.											
LOAD25	Albury - Workshop	VehService\AS	A SERVICE DUE @ 605000	REPLACED LHR DRIVE SHOCKER RUBBERS	16/07/2017	604885	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabRep\DOOR LOCK	RH DOOR RUBBER KEEPS COMING OFF WHEN WINDOW GOES UP		04/07/2017	602573	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Susp\HCV	CHECK RIDE HEIGHT		21/06/2017	599435	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrivLine\CLUTCH	CLUTCH NEEDS ADJUSTMENT.		21/06/2017	599435	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	VehService\BS	B SERVICE DUE @ 600000KMS.		21/06/2017	599435	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	VehService\BS	B SERV DUE IN 800KM.		21/06/2017	599435	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Engine\FILTERS	TRUCK HAVING TROUBLE STARTING		21/06/2017	599518	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrivLine\CLUTCH	CHECK CLUTCH ADJUSTMENT		09/06/2017	597071	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabRep\WIPERS	WINDSCREEN WASHERS NOT WORKING. WINDSCREEVN WASHERS NOT WORKING	unblocked. Working ook	31/05/2017	595180	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
				repaired R/H hi beam wiring											
				replaced R/H hi beam globe											
LOAD25	Albury - Workshop	VehService\AS	A SERVICE	reolaced R/H side marker	31/05/2017	595180	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		31/05/2017	595180	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabRep\WIPERS	TRUCK NEEDS NEW WIPER BLADES		24/05/2017	592672	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
				SUBLET. ALDONGA ENG.											
				WELDED CRACKS IN BOOM SUPPORT BAR AND BULLBAR FRAME.											
LOAD25	Albury - Workshop	Chassis\DAMAGE	BOOM SUPPORT BENT AND CRACKED.	SUPPORT NEEDS TOBE REMOVED AND PRESSED BACK TO SQUARE.	23/05/2017		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabElect\INST/GAUGE	SPEEDO NOT WORKING. ONLY SOMETIMES KM DIGITAL		21/05/2017	5292561	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
				SUPPLY TCTC WITH BUSHES AND HCV.											
LOAD25	Albury - Workshop	Susp\SWAYBAR	REPLACED REAR SWAY BAR BUSHES AND LH HCV	AS PER ATTACHED INVOICE	17/05/2017	594300	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Body\AIR LEAK	AIR LEAK BEHIND CAB.	COULD NOT FIND	11/05/2017	590984	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
				REPAIRED LHR SHOCKER MOUNT.											
LOAD25	Albury - Workshop	VehService\AS	A SERVICE DUE	REPLACED SHOCKER	11/05/2017	590984	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrivLine\OIL LEAK	FRONT DIFF RESEAL		11/05/2017	590984	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
				REPLACED AIR BAG											
				Travel to Yenches rd.											
LOAD25	Albury - Workshop	Susp\AIR BAG	REPLACE AIR BAG REAR OF FRONT DRIVE ON RHS.. REPLACE AIR BAG REAR OF FRONT DRIVEON RHS.	Replaced airbag	02/05/2017	587663	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Tyres	Job Added From Invoice		28/04/2017	0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice		28/04/2017	0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice		28/04/2017	0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER

LOAD25	Albury - Workshop	Comp\ELECT P&W	repaired broken wiring LH sidemarker lights		20/04/2017	585153	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Susp\SWAYBAR	rear sway bar bushes		20/04/2017	585153	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		20/04/2017	585153	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	VehService\AS	Service		20/04/2017	585153	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabRep\WINDSCREEN	WINDOW HAS A CRACK THRU IT.	O'BRIEN'S REPLACED WINDSCREEN	14/04/2017		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Body\EXHAUST	EXHAUST PIPE NEEDS PUTTING BACK ON		13/04/2017	584049	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabRep\WIPERS	RHS WIPER NEEDS FIXING	refitted wiper head	12/04/2017	583692	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Chassis\AIR LEAK	AIR LEAK UNDER CAB	REPLACED LEAKING REGULATOR VALVE LEAKING IN CHASSIS RAIL FOR CLUTCH ACTUATOR	11/04/2017	583503	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
				travel to and from Lankeys creek											
				replace broken HCV											
				check over in w/shop											
				adjusted ride heights in w/shop											
LOAD25	Albury - Workshop	Susp\HCV	HCV BROKEN	straightened bottom tag on 2nd airbag RHS	08/04/2017	583177	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Susp\HCV	RH HCV BROKEN	AS PER ENTRY # 50840	08/04/2017	583177	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Susp\SWAYBAR	RHS SWAYBAR CLAMP BRACKET BROKEN		01/04/2017		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Engine\AIR LEAK	AIR LEAK UNDER CAB. NOT HOLDING AIR.	COULD NOT LOCATE ANY AIR LEAK.	01/04/2017	581307	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
				REPAIRED D SHACKLE.											
LOAD25	Albury - Workshop	Body\HOUSEKEEP	"D" SHACKLE THAT HOLDS UP GRAB SUPPORT NEEDS REPLACING	As per ioSHR3958 on o25	01/04/2017	581307	Fault	Comoleted	Greenfreight Loxeine NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
				TESTED OPERATION OF SEAT. OK											
LOAD25	Albury - Workshop	DrCabRep\SEAT	DRIVERS SEAT NOT PUMPING UP.	seat workine	01/04/2017	581307	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	VehService\BS	B SERVICE		29/03/2017	580276	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Body\FUEL TANK	BOTTOM STEP MISSING BOLT AND HOLD DOWN CLAMP.	MAKE UP NEW CLAMP AND REPLACE BOLT	25/03/2017	579743	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabRep\HOUSEKEEP	RH DOOR MISSING DOOR TRIM BOLT/SCREW.	REPLACED SCREW	25/03/2017	579743	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabRep\WIPERS	REATTACH WIPER ARM. FIT BIRD AND DISLODGED ARM.	REFIT WIPER ARM	14/03/2017	577024	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Tyres\TP09	Job Added From Invoice		11/03/2017	0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabElect\UNST/GAUGE	ODOMETER STILL NOT WORKING.PARTS ORDERED ARKON, 6/03/2017	SEND DASH TO ARKON FOR REPAIR.	08/03/2017		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
				REMOVE DASH AND TAKE TO ARKON TO REPAIR.											
LOAD25	Albury - Workshop	DrCabElect\UNST/GAUGE	ODOMETER STILL NOT WORKING	COULD NOT REPAIR. LOCKING FOR PARTS FOR REPLACEMENT.	05/03/2017	575212	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Elect\TAIL LIGHT	LH CLEARANCE LIGHT NEEDS STRAIGHTENING	REPAIRED SIDE MARKER	05/03/2017	575212	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Susp\SHOCK ABS	REPAIR LOWER SHOCKER MOUNTS RHS DRIVE	WELD UP MOUNTS AND FIT NEW SHOCKERS	26/02/2017	573468	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
			A SERVICE												
			ODOMETER HAS NOT BEEN WORKING FOR 2 OR 3 WEEKS.												
LOAD25	Albury - Workshop	VehService\AS	SERVICED TRUCK TO BRING IT IN LINE.		25/02/2017	574468	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
			ODOMETER NOT WORKING.												
LOAD25	Albury - Workshop	DrCabElect\UNST/GAUGE	REQUIRES REMOVING FOR REPAIR. 21/02/2017		25/02/2017		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Air Con\AIR CON	AC BLOWING HOT AIR.	AC IS GETTING COOL	22/02/2017		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
				straightened RH tail light mount											
LOAD25	Albury - Workshop	Elect\DAMAGE	REVERSED INTO STACK. BROKE BOTH TAIL LIGHT AND INDICATOR	fit & wire new tail liaht assemblv	21/02/2017		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabRep\WIPERS	replaced wiper blades		19/02/2017	572477	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Elect\HEAD LIGHT	repair RHR marker light		19/02/2017	572477	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
			AC not working. Fan not blowing air.												
LOAD25	Albury - Workshop	Air Con\AIR CON	Ordered parts 23/01/2017	fit partition wall to a/c/heater box repaired vents. Removed broken vent parts in ducts	19/02/2017	572477	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabElect\UNST/GAUGE	ODOMETER NOT WORKING	remove dash check and cleaned circuit board and terminals. Test. Ok. Worked temporarily still has problem in LCD screen	19/02/2017	572477	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabElect\UNST/GAUGE	ODOMETER NOT WORKING		19/02/2017	572477	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Air Con\AIR CON	THE FAN IS ON HIGH BUT STILL CANT FEEL COLD AIR COMING OUT THE VENTS. ITS HOT	AS PER ENTRY #43482	11/02/2017		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	VehService\AS	A SERVICE DUE AT 570000 KM		08/02/2017	569708	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabRep\SEAT	NO AIR IN DRIVERS SEAT. PUT TAPE ON IT TO STOP LEAK	re-assembled hoses & fittings	07/02/2017	569322	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Susp\SHOCK ABS	REPLACE LHF DRIVE SHOCKER		05/02/2017	569042	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Air Con\AIR CON	Air con still not working	As per Entry #43482	01/02/2017	567975	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
			low air light coming on when touching brakes.												
LOAD25	Albury - Workshop	DrCabElect\UNST/GAUGE	Parts on order	Replaced No 2 air tank guage	28/01/2017		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
				FAULTY NO. 2 AIR GAUGE.											
LOAD25	Albury - Workshop	DrCabElect\UNST/GAUGE	low air light coming on when touching brakes	Parts on order	26/01/2017	566202	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
				Replace clutch fluid, Clean out system											
LOAD25	Albury - Workshop	DriveLine\CLUTCH	clutch needs adjusting very spongy. clutch needs adjusting very spoongie	pick up pressure bleeder at TCTC. Bleed system	25/01/2017	566431	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
				as per job #46031											
				dismantle a/c box clean evaporator/heater core											
				diagnose problem with Arkon											
LOAD25	Albury - Workshop	Air Con\AIR CON	AC not working. Fan not blowing air	order parts	24/01/2017	566202	Fault	Comoleted	Greenfreight Loxeine NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabRep\DOOR LOCK	Door trim needs att. RH top	repair door	24/01/2017	566202	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Air Con\AIR CON	AC not working	reset circuit breaker working	24/01/2017	565967	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabRep\WINDOW REG	RH drivers door window not working	reset circuit breaker	24/01/2017	565967	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabRep\HOUSEKEEP	RH door trim needs looking at.		24/01/2017	565967	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Elect\HEAD LIGHT	LH mirror light out	reset circuit breaker	24/01/2017	565967	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Elect\TAIL LIGHT	Clearance lights not working	Replaced LHR side marker light and reset fuse	21/01/2017	565967	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	VehService\AS	A service		21/01/2017	565967	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Body\MOUNTS	Repair Grab bar retainer		21/01/2017	565967	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabElect\RADIO	Replace UHF mic		17/01/2017		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Tyres\TP04	Job Added From Invoice		13/01/2017	562885	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Engine\EXHAUST	Tip of exhaust needs replacing. Struck by prentice.	removed and repaired exhaust pipe	13/01/2017	563914	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Body\MOUNTS	Fit new D shackle to grab support	Pick up equipment at Border Lifting equipment	13/01/2017		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
				fitted 2x new straps											
LOAD25	Albury - Workshop	Chassis\AIR TANKS	Air tank strap broken. Ordered 2x new tank straps. CMV 5/01/2017	pick up parts	10/01/2017		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Elect\DRV LIGHT	Needs new driving lights		10/01/2017	562769	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabRep\WIPERS	needs new wiper blade LH		10/01/2017	562769	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Body\MIRRORS	RH mirror needs tightening		10/01/2017	562769	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Body\HOUSEKEEP	Air tank strap broken		05/01/2017	561756	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Brakes\AIR LEAK	Air leak @ front drive		05/01/2017	561756	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Body\HOUSEKEEP	Fix drivers side bottom step		05/01/2017	561756	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Body\HOUSEKEEP	New D shackle on front		05/01/2017	561756	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Chassis\AIR TANKS	air tank strap broken		05/01/2017	561756	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Brakes\AIR LEAK	Dropping air to quick when legs are down	No abnormal leaks, designed to dump when ride height too high	24/12/2016	560667	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Steering\HOUSEKEEP	Bad rattle in steering when driving along	Couldn't fault steering - test drove	24/12/2016	560667	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Engine\HOUSEKEEP	replace broken dipstick		22/12/2016	560663	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	VehService\BS	B service	repair washers	16/12/2016	559542	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Engine\FILTERS	Supply oil filter		16/12/2016		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
				Removed sway bar and pressed new bushes at Aldonga Engineering - Fitted bar with new hangar bushes											
LOAD25	Albury - Workshop	Susp\SWAYBAR	Requires rear sway bar bushes	Pick up bushes at CMV	14/12/2016		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabElect\PHONE	Phone not working	Replaced phone mic	13/12/2016	559059	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Susp\SWAYBAR	Requires rear sway bar bushes	ordered bushes	01/12/2016		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Body\HOUSEKEEP	New D shackle on front bar to hold cradle up.		27/11/2016	555936	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	VehService\AS	A service		25/11/2016	555673	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
				replaced stalk											
				secured loose ignition barrel											
				Arkon											
				fitted unit out of L26											
				tested ok											
LOAD25	Albury - Workshop	Elect\INDICATORS	Requires indicator stalk.	fitted new unit into L26. left one out of L26 in L25	19/11/2016	554404	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
				only replaced R shocker											
LOAD25	Albury - Workshop	Susp\SHOCK ABS	Replace front drive shockers	used 2nd hand bushes to fix	18/11/2016		Repair	Comoleted	Greenfreight Loxeine NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabRep\DOOR LOCK	Tighten 1/4 guard bolts		17/11/2016	554182	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabRep\WIPERS	LH washer not working.	cleaned washers/adj	17/11/2016	554182	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DriveLine\AIR LEAK	Air leak when diff locks are engaged	repaired air line	17/11/2016	554182	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Elect\INDICATORS	Indicators not working all the time.	indicator may require stalk	17/11/2016	554182	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
				loose panels											
				salastlied panels											
LOAD25	Albury - Workshop	DrCabElect\RADIO	Rattle in UHF	driver to monitor	17/11/2016	554182	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Steering\HOUSEKEEP	Steering wheel not straight		13/11/2016	553523	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabRep\WIPERS	washer bottle needs filling up		13/11/2016	553523	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Tyres\TP07	Job Added From Invoice		09/11/2016	0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Brakes\AIR LEAK	Air leak at front drive		08/11/2016	551938	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Tyres\TP09	Job Added From Invoice		05/11/2016	550623	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
				deliver truck to cummins											
				take driver over to pick up truck											
				replaced centre section manifold											
LOAD25	Albury - Workshop	Engine\JAKE BRAKE	Jake brake making different noise	replaced #6 injector	04/11/2016	515414	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Engine\JAKE BRAKE	jake making different noise		04/11/2016	515414	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Engine\FAULT CODE	Truck missing going thru gears	replaced # 6 injector	04/11/2016	515414	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Steering\HOUSEKEEP	Steering wheel not on straight		02/11/2016	550924	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabElect\UNST/GAUGE	No dash lights		02/11/2016	550924	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Tyres\BREAKDOWN	Travel to Shelley and fit two drive tyres	refit spare on rack	27/10/2016		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Tyres\TP07	Job Added From Invoice		26/10/2016	549041	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Elect\HEAD LIGHT	Replace RH head light globe		25/10/2016	549897	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Susp\SHOCK ABS	Replace Rh shocker and hammer lock for axle chain		22/10/2016	549660	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
			Requires 2 cams LHR and RHR.												
LOAD25	Albury - Workshop	Brakes\BRK O/HAUL	Reline rear axle as per reline sheet.	clean up after iob	22/10/2016	549660	Repair	Comoleted	Greenfreight Loxeine NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
				checked engine codes											
				tested throttle potentiometre											
				repaired washers											
				checked suspension											
				replaced throttle potentiometer											
LOAD25	Albury - Workshop	Engine\FAULT CODE	Engine missed thru gear changes. Red light come on and buzzer. Turned off truck and did not play up again	test drive to check - ok	21/10/2016	549757	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	VehService\AS	A service		20/10/2016	549757	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
				Removed spring pack from L26 RH side and fitted to RH side.											
LOAD25	Albury - Workshop	Susp\SPRING PACK	Broken spring pack RH steer	Spring pack in L26 LH side is broken. (off road)	20/10/2016	549757	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Brakes\BRK O/HAUL	Requires 2 cams LHR and RHR		20/10/2016	549757	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Steering\HOUSEKEEP	Steering wheel not straight	straightened steering wheel	19/10/2016	549040	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
				modified steel pipe on lower boost hose											
LOAD25	Albury - Workshop	Engine\BOOST HOSE	Replaced lower boost hose	re-routed bottom radiator hose	18/10/2016		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
				modify boot to suit											
				replaced steer shaft											
			Power steering needs looking at. Not right.												
LOAD25	Albury - Workshop	Steering\PWR STEER	Resuires new steerine shaft	old shaft had seized unit	11/10/2016	548706	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Body\MUDGUARDS	LH back mudflap needs replacing	replaced mudflap	08/10/2016	548676	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Susp\SUSPENSION	sway bar bushes	replaced bushes	27/09/2016	544838	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
				s'cam											
				410											
LOAD25	Albury - Workshop	VehService\AS	A service	anti clockwise	27/09/2016	544838	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Brakes	check and record brakes		27/09/2016	544838	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
				couldn't fault all leak											
LOAD25	Albury - Workshop	Body\AIR LEAK	Air leak under cab.	all ok	23/09/2016	543952	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Susp\SUSPENSION	HCV needs looking at.sitting down in rear end.	check sys	23/09/2016	543952	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
				found blown fuse											
LOAD25	Albury - Workshop	DrCabElect\HEATER REP	heater stopped working in truck, no fan.	reolaced fuse test ok	18/09/2016	541948	Fault	Comoleted	Greenfreight Loxeine NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER

LOAD25	Albury - Workshop	VehService\BS	B service	replaced RR stop/tail light	10/09/2016 539789	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Brakes	check and record brakes		10/09/2016 539789	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabRep\WIPERS	Truck needs new wiper blades	replaced wipers	28/08/2016 535699	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabElect\UNST/GAUGE	dash light out in tremp gauge. dash light out in tremp gauge	replaced dash globe	28/08/2016 535699	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
				service was done 534897km										
				job # 10324										
LOAD25	Albury - Workshop	VehService	A serv due at 535000km	Check over	27/08/2016 535699	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Engine\ENG FAN	Horton stuck on.	as per attached invoice	20/08/2016 534897	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	VehService\AS	A service	repaired windscreen washers	20/08/2016 534897	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Steering\PWR STEER	Power steering needs looking at. Not right		11/08/2016	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Engine\BOOST HOSE	Replaced lower boost hose	ordere boost hose	11/08/2016	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Elect\TAIL LIGHT	RH back clearance light missing	Repalced missing marker light.	09/08/2016 532264	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
				fluids good										
				went for test drive was heavy										
LOAD25	Albury - Workshop	Steering\PWR STEER	power steering needs looking at, very hard sometimes		31/07/2016 530109	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Brakes	check and record brakes		31/07/2016 530109	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	VehService	A Service Due 530,000		31/07/2016 530109	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Steering	power steering needs looking at very hard some times		31/07/2016 530109	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Brakes	jake making different noise		31/07/2016 530109	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
				requires lower boost hose										
				part#3122237 12x52 38764										
LOAD25	Albury - Workshop	VehService\AS	A service	leakinz exhaust manifold	31/07/2016 530109	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabRep\WIPERS	RH wiper blade	straightened wiper arm & replaced wiper blade	24/07/2016 528740	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Body\MIRRORS	LH mirror glass loose	tightened	24/07/2016 528740	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabRep\WIPERS	fill up washer bottle		24/07/2016 528740	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
				ordered new jack shaft. Had to get truck going. Will have old shaft repaired for spare as there are other trucks in the fleet with this										
				shaft.										
LOAD25	Albury - Workshop	Driveline\TAIL SHAFT	Found tail shaft yoke failed	Fitted shaft	21/07/2016 528179	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
				replaced light.										
				Repaired isolation switch bracket										
				replaced LH arriving light										
LOAD25	Albury - Workshop	Elect\HOUSEKEEP	Needs a brighter light on cradle for lighting deck.	tightened CIB shock bolts	13/07/2016 526504	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabRep\WIPERS	replace LH wiper blade	replaced wiper blade	13/07/2016 526504	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabRep\DOOR LOCK	LH dooor hard to open from outside	lubed door.	13/07/2016 526504	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Engine\BOOST HOSE	Boost hose has rub marks.	replaced boost hose	05/07/2016 525108	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Engine\AIR CLNR	Air filters due for replacement.	As above	05/07/2016 525108	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Tyres\TP03	Job Added From Invoice		05/07/2016 525022	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Tyres\TP03	Job Added From Invoice		05/07/2016 0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Tyres\TP03	Job Added From Invoice		05/07/2016 0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Engine\MOUNTS	requires rear engine mounts		01/07/2016	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Brakes\BRAKE ADJ	Needs a brake adjustment	at service above	28/06/2016 524230	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Brakes	check and record brakes		28/06/2016 524230	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
				rear engine mounts req										
				boost hose at turbo req										
LOAD25	Albury - Workshop	VehService\AS	A service	tightened loose chassis bolts	28/06/2016 524230	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabRep\WIPERS	Truck needs new wiper blades.	replaced wiper heads	23/06/2016 523497	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
				repaired speaker wiring										
LOAD25	Albury - Workshop	DrCabElect\RADIO	Radio in truck not working	replaced dash elobes & holders	07/06/2016 520421	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabElect\RADIO	something wrong with speakers	as above # 43502	07/06/2016 520421	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
				repair mounts										
LOAD25	Albury - Workshop	Body\PANELS	LHS tank step has come loose	straighten supports	07/06/2016 520421	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabRep\WINDOW REG	RH window hard to go up	lubed runner	02/06/2016 519503	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabRep\WIPERS	windscreen washer not working	cleaned out washer nozzels	02/06/2016 519503	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Brakes	check and record brakes		02/06/2016 519503	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
				as above										
LOAD25	Albury - Workshop	VehService\BS	B service	replaced RHF drive shocker	02/06/2016 519503	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Tyres\TP07	Job Added From Invoice		01/06/2016 0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Susp\AIR LEAK	air leak under front drive	only air leak found was HCV exhausting	31/05/2016 518863	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Susp\AIR BAG	back air bags not going all the way up.	replaced 3rd air bag RH side	31/05/2016 518863	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Elect\BATTERY	hard to start.	replaced batteries	31/05/2016 518967	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Tyres\TP05	Job Added From Invoice		27/05/2016 517959	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabElect\RADIO	radio not working	removed radio and inspected that the aerial was plugged in. plugged in aerial.	18/05/2016 516053	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabElect\UNST/GAUGE	not all dash lights are working	replaced dash globes that were not working	18/05/2016 516053	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Tyres\STEER TYRE	Job Added From Invoice		14/05/2016 514964	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
				replaced heater fan.										
LOAD25	Albury - Workshop	DrCabElect\HEATER REP	Heater/air conditioning fan not working. Heater/air conditioning not working	Arkon resained wirinz.	10/05/2016 515924	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabRep\WIPERS	LH window wiper needs fixing	repaired wiper	10/05/2016 514964	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	VehService\AS	A service	above	10/05/2016 514964	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Brakes	check and record brakes		10/05/2016 514964	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabRep\SEAT	Seat has movement in it. No good	fitted new seat	10/05/2016 514964	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabRep\SEAT	Seat needs replacing		10/05/2016 514964	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabElect\ELECT P&W	Circuit breaker needs looking at making noise	heater fan ordered	05/05/2016 513881	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Body\MUDGUARDS	needs skirt over steer tyres.	fit new gaurds on steers, straightened outriggers & cut guards to suit under bonnet	05/05/2016 513881	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Susp\SHOCK ABS	replaced front drive shockers x 2	eailer job raised rubber mount failed	29/04/2016	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Chassis	replaced broken sway bar mount & bush		28/04/2016 512540	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Body\FUEL TANK	repaired LH steps		28/04/2016 512540	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Susp\SHOCK ABS	LH front drive shocker needs replacing. LH front drive shocker needs reolacing	Replaced shocker	20/04/2016 511271	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabRep\DOOR LOCK	Door trim coming away from door RH side	tightened screws	15/04/2016 510206	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Brakes	check and record brakes		15/04/2016 510206	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	VehService\AS	A service		15/04/2016 510206	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Engine\COMPRESSOR	hot line hose blown out.	replaced hose	15/04/2016 510206	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Tyres\TP05	Job Added From Invoice		12/04/2016 508056	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Tyres\TP09	Job Added From Invoice		12/04/2016 508056	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Tyres\TP09	Job Added From Invoice		12/04/2016 0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Tyres\TP09	Job Added From Invoice		12/04/2016 0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Rosewood - Workshop	Tyres\TP09	Job Added From Invoice		09/04/2016 0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Rosewood Workshop	LOADER
LOAD25	Rosewood - Workshop	Tyres\TP09	Job Added From Invoice		09/04/2016 0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Rosewood Workshop	LOADER
LOAD25	Rosewood - Workshop	Tyres\TP09	Job Added From Invoice		09/04/2016 0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Rosewood Workshop	LOADER
				cleaned out mic. Rang out and tested ok.										
LOAD25	Albury - Workshop	DrCabElect\PHONE	truck phone is not working properly, people can't hear you when speaking.	Checked oluas & wirrnz	03/04/2016 508056	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Elect\ELECT P&W	Auxiliary fuel pump not working.	replace relay and repair wiring	03/04/2016 508056	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabElect\PHONE	truck phone not working probably people cant here you when speaking		02/04/2016 507804	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Body\FUEL TANK	fuel pump not working		02/04/2016 507804	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Tyres\TP02	Job Added From Invoice		25/03/2016 502279	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
			Transfer pumpnot working.											
LOAD25	Albury - Workshop	Body\ELECT P&W	Hose needs outtine back on. (in toolbox)	reolaced fuse in battery box	23/03/2016 505775	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Tyres\TP02	Job Added From Invoice		22/03/2016 501544	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	VehService\AS	A Service		16/03/2016 504819	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Brakes	check and record brakes		16/03/2016 504819	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
			Truck belts squealling.											
LOAD25	Albury - Workshop	Engine\BELTS/TENS	Air con not on.		11/03/2016 503861	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
				Checked voltage @ alternator 27.4 volts.										
				Checked voltage @ batteries 27.38 volts.										
				Tested batteries individually. Both ok.										
LOAD25	Albury - Workshop	Elect\BATTERY	Had to roll start in bush	Checked connections terminals and fluid level ok.	08/03/2016 503213	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Brakes\BRAKE ADJ	Brake adj.	as above	03/03/2016 502299	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Tyres\TP09	Job Added From Invoice		01/03/2016 501129	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Elect\TAIL LIGHT	indicators not working	replaced indicator insert RHF. Cleaned hazard switch	27/02/2016 501449	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Elect\TAIL LIGHT	L/H mirror light not working	replaced mirror lights with LED	27/02/2016 501449	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Brakes\BRK RELINE	Reline rear axle	relined rear axle	25/02/2016 501449	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	VehService\BS	B service		20/02/2016 499666	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Brakes	Check and records brakes		20/02/2016 499666	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Susp\AIR BAG	RHS front air bag needs replacing	replaced RHS air bag	13/02/2016 498052	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Body\DAMAGE	left side tank step bent	straightened l/h step.	11/02/2016 496292	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
				Call out. Truck was left at Rose River. Driver had left the isolator switch on at end of shift Saturday.										
				Travel to Rose River. Jump start truck.										
LOAD25	Albury - Workshop	Elect\BREAKDOWN	flat batteries	Left battery cover off. Truck returned to Albury depot at end of shift. Cleaned aqnd inspected batteries. Refit cover.	09/02/2016 496400	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Brakes\AIR LEAK	Air leak in behind dash. Trailer brake control valve leaking	replaced trailer control valve	28/01/2016 494523	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabElect\UNST/GAUGE	Odometer is not working	Arkon tested wiring. Could not fault it. Reassambled and now is working. Will monitor.	28/01/2016 494523	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Tyres\TP07	Job Added From Invoice		23/01/2016 494518	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabElect\WARRANTY	tacho not working	repair broken wire at alternator	16/01/2016	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	VehService\AS	Service As Per Attached Checklist		16/01/2016 494508	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		16/01/2016 494508	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Elect	lh side parker not working		16/01/2016 494508	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabRep	dash needs bolts in it		16/01/2016 494508	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Myrtleford - Workshop	Engine\ENG FAN	repair horton	completed	14/01/2016	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Myrtleford Workshop	LOADER
LOAD25	Albury - Workshop	Engine\BELTS/TENS	replaced fan belts	as above	14/01/2016	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Susp\AIR BAG	air bags	completed	12/01/2016	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Susp\AIR BAG	rhr air bag leaking	replaced air bag	09/01/2016	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Elect	UHF hand piece cuts radio out	tested UHF - all working good	09/01/2016	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Susp\AIR BAG	replace two rh air bags, replace lhr air bag	replace air bag	08/01/2016 493337	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	DrCabRep\SEAT	rh seat won't pump up	check seat operation	08/01/2016 493337	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Body	rh fuel tank step needs fixing	repair tank step	08/01/2016 493337	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Engine\ENG FAN	horton	completed	06/01/2016	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Engine	horton failed - required overhaul. horton failed	removed radiator to access horton, kit horton, replaced belts and idler bearings, refit radiator	24/12/2015	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
			strengthen sign											
LOAD25	Albury - Workshop	Body\WC COMP	alb canvas	completed	19/12/2015	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
			oversize sign											
LOAD25	Albury - Workshop	Body\WC COMP	alby t & t	completed	19/12/2015	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Body	fit oversize sign, repair light bar		18/12/2015 490378	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
			lights											
LOAD25	Albury - Workshop	Elect\ELECT P&W	adva auto	completed	16/12/2015	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
			bolts											
LOAD25	Albury - Workshop	Chassis\CROSS MBR	aldonga eng	completed	15/12/2015	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
			engine oil leaks											
LOAD25	Myrtleford - Workshop	Engine\OIL LEAK	cummins	completed	11/12/2015	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Myrtleford Workshop	LOADER
			filters"clamp											
LOAD25	Myrtleford - Workshop	Engine\FILTERS	tctc	completed	11/12/2015	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Myrtleford Workshop	LOADER
LOAD25	Albury - Workshop	Chassis\RWC COMP	Repair counterweight	completed	04/12/2015	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Brakes	replaced boost hose		01/12/2015 489698	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	Engine\FILTERS	replace oil filter	had to replace oil filter as it was damaged from boost hose clamp when it came off	01/12/2015 489698	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
			weld bumper											
LOAD25	Albury - Workshop	Body\MOUNTS	ald enz	ourchase order on comoleted	01/12/2015	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
			switch											
LOAD25	Albury - Workshop	Elect\ELECT P&W	cmv	completed	28/11/2015	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD25	Albury - Workshop	VehService\AS	Service As Per Attached Checklist		26/11/2015 488628	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER

LOAD2S	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		26/11/2015	489628	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	DrCabElect\PHONE	phone won't shut off		26/11/2015	489628	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Chassis\SUSPENSION	counter weight randalls	comoleted	10/11/2015		Repair	Comoleted	Greenfreight Loggine NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshoo	LOADER
LOAD2S	Albury - Workshop	Tyres\STEER TYRE	Job Added From Invoice		27/10/2015	0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Tyres\STEER TYRE	Job Added From Invoice		27/10/2015	0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Tyres\STEER TYRE	Job Added From Invoice do not overtake sign		27/10/2015	0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Body\DAMAGE	tctc wheel studs	comoleted	27/10/2015		Reapir	Comoleted	Greenfreight Loggine NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshoo	LOADER
LOAD2S	Albury - Workshop	Steering\STEER TYRE	cmv number plate lamps	comoleted	27/10/2015		Reapir	Comoleted	Greenfreight Loggine NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshoo	LOADER
LOAD2S	Albury - Workshop	Elect\ELECT P&W	tctc	completed	27/10/2015		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Tyres\TP01	Job Added From Invoice		23/10/2015	0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	DrivLine\FUEL TANK	Job Added From Invoice		14/10/2015	0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Rosewood - Workshop	Body	clearance lights on roof not working	repair roof marker light wiring at accelerator pedal	13/10/2015	488560	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	VehService\BS	Job Added From Invoice		09/10/2015	0	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Engine\FUEL TANK	truck not starting properly		08/10/2015	487779	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	DrCabRep\WIPERS	replace rh wiper blade		29/09/2015		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Tyres\TP04	Job Added From Invoice		23/09/2015	555555	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Susp\SHOCK ABS	Service Job Added From Invoice		16/09/2015	0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		16/09/2015	485263	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	VehService\AS	Service As Per Attached Checklist		16/09/2015	485263	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Elect	light on roof not working, mirror light not working		09/09/2015	482473	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	DrCabRep	door trim needs fixing		09/09/2015	482473	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Elect\START MOTR	Service Job Added From Invoice		08/09/2015	0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Engine\HOUSEKEEP	Service Job Added From Invoice		08/09/2015	0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Body	replace wiper blades		04/09/2015	487600	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Insp\ANN INSP	Roadworthy Inspection		03/09/2015	481398	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		03/09/2015	481398	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	DrCabRep\HOUSEKEEP	replace lh mirror light globe		03/09/2015	481398	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	DrivLine\DIFF OIL	replace front diff oil		03/09/2015	481398	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Engine\EXHAUST	replace exhaust flex clamp under cab + tighten bracket		03/09/2015	481398	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Body\LIGHTS	replace driving lights		03/09/2015	481398	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	DrCabRep\HOUSEKEEP	repair + brace lh bottom tank step		03/09/2015	481398	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	VehService\BS	Service As Per Attached Checklist		03/09/2015	481398	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Engine	replace starter motor		02/09/2015	0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER
LOAD2S	Albury - Workshop	Susp	replace lhr shocker		02/09/2015	0	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Albury	ALR	XTG897	Albury Workshop	LOADER