EquipmentName	Workshop	CodeAndSubCode	Description	Schedule	CompletionComments	DateDone	HourDone	Worktype	Workstate	EquipmentOwner	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
P18	Myrtleford - Workshop	VehService\BS	VehService\BS	VehService\BS		22/10/2024	9490	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Wodonga - Workshop	Hydraulics\HOSES	Hoses			22/03/2024		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Wodonga Workshop	PRENTICE
P18	Wodonga - Workshop	DrCabElect\AIR CON	thermostat control don't work			22/03/2024		Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Wodonga Workshop	PRENTICE
P18	Myrtleford - Workshop	Body\MOUNTS	swap P18 onto L17			29/10/2023		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		RINLATECH ENGINEERING - 4	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\BREAKDOWN	HYDRAULICS NOT WORKING.			14/09/2023	9490	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Body\HOUSEKEEP	wash oil from walkway			29/04/2021	9489	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\FUEL TANK	Bleed and jumpstart prentice			27/04/2021	9489	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
					Checked compressor/clutch - ok turned heater taps off made no difference may have lost gas deliver truck											
P18	Myrtleford - Workshop	Air Con\AIR CON	AIR CONDITIONER NOT WORKING		pick up truck	18/03/2021	479018	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\FILTERS	check over prentice			16/03/2021	9457	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\FILTERS	bleed fuel system			16/03/2021	9457	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\FILTERS	run for half hour and recheck ok			16/03/2021	9457	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\HOUSEKEEP	check hard staring when cold			27/02/2021	9456	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\BREAKDOWN	REPLACE FUEL PUMP DRAIN BACK CHECK VALVE			26/02/2021	9457	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\BREAKDOWN	inspected hard starting			25/02/2021	9456	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\HOSES	fitted pipe clamp to hyd lines			25/02/2021	9456	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\BREAKDOWN	wont start			18/02/2021	9441	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\DAMAGE	REPLACE MAIN GRAB TIP			10/02/2021	9440	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\DAMAGE	the main grab pin locking bolt has broken will need to be replaced. the main grab pin locking bokt has broken will need to be replaced			09/02/2021	9440	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\HOSES	Hoses			06/02/2021	9440	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
					repair wash light wiring replace tank mount bolts and washers grease loader											
P18	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS	tighten grab pin retainer bolts	06/02/2021	9440	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\HYD LEAKS	Fit seals to LH Joy Stick Plungers. RHS joystick sticking			02/02/2021	9424	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\HOUSEKEEP	grease loader			29/01/2021	9419	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\HOUSEKEEP	check oil and coolant			29/01/2021	9419	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	DrCabElect\RADIO	replace UHF aerial and base L11181. replace UHF aerial and base			16/01/2021	9391	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\HOUSEKEEP	grease loader			16/12/2020	9323	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\MOTOR	staffa motor shaft seal leaking (replaced)			16/12/2020	9323	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	DrCabRep\WINDSCREEN	replace front windscreen (cracked)			16/12/2020	9323	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\HOUSEKEEP	grease loader grab and legs			16/12/2020	9323	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\MOTOR	staffa motor shaft seal leaking			16/12/2020	9323	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	DrCabRep\WINDOW REG	front windscreen cracked			16/12/2020	9323	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\HYDRAULICS	check all lower leg pivot pins			09/12/2020	9304	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\HOUSEKEEP	replace engine side cover gasket and seals			01/12/2020		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\OIL LEAK	engine oil leak rear off motor wash and check			28/11/2020	9285	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\HOUSEKEEP	check over top up engine oil			28/11/2020	9285	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Workshop\MOVE ASSET	take to Rinlatech to fix LHS bottom lift cylinder bearing and repair to grab			25/11/2020	9270	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\RAM	replace LHS lift bearings			25/11/2020	9270	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\BREAKDOWN	repair grab tips			25/11/2020	9270	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\FAULT CODE	fuel leaking at fitting rear of injector pump		fuel leak at rear of motor no3 fuel line at fault	14/11/2020	9252	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\HOUSEKEEP	grease loader and grab and legs			14/11/2020	9252	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\EXHAUST	replace each pipe 90° bend outlet of muffler			14/11/2020	9252	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	DrCabElect\ELECT P&W	Replace warning horn			14/11/2020	9271	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	DrCabElect\ELECT P&W	Fit New Leg switch and decals			14/11/2020	9271	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\VALVES	rear legs don't go down sometimes cleaned ele plugs undercab checked, cleaned and tested switch for front and back			13/11/2020	473730	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	DrCabElect\ELECT P&W	ordered new switch			13/11/2020	473730	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
					steam clean motor											
P18	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS	fit extinguisher	13/11/2020	9252	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\HOUSEKEEP	grease			10/11/2020	3235	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\EXHAUST	fit exhaust clamp			10/11/2020	3235	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\HOUSEKEEP	check oil and water			10/11/2020	3235	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\BELTS/TENS	adjust belt			10/11/2020	3235	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Body\MOUNTS	bolts missing and loose bottom of radiator mount			23/10/2020	9172	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\HOUSEKEEP	recheck all fluids and grease loader			23/10/2020	9172	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Elect\WORK LIGHT	RHS beam light not working			23/10/2020	9172	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	DrCabElect\ELECT P&W	tidy up wiring under cab			23/10/2020	9172	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	DrCabRep\HOUSEKEEP	sloopy foot controls (slew)			13/10/2020	9171	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\HOUSEKEEP	extend enp breather			13/10/2020	9171	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Workshop\MOVE ASSET	take down to Rinlatech			13/10/2020	9171	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	DrCabRep\MOUNTS	loose pilot shut off lever			13/10/2020	9171	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Unknown - Unknown	Air Con\MOUNTS	Repair Cracks in Boom and Grab Rests			07/10/2020	9171	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Unknown - Unknown	Chassis\DAMAGE	Remove Main Boom and Repair Cracks and Fit Pins and Bushes. Remove Main Boo and Repair Cracks and Fit Pins and Bushes		repair crack in main frame	07/10/2020	9171	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Unknown - Unknown	Hydraulics\DAMAGE	Replace Worn Grab Pins and Bushes		Rinlatech checked all leg and eye pins only RHR is ok	07/10/2020	9171	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Unknown - Unknown	Chassis\DAMAGE	Replace Worn Leg Pins and Bushes		all other's need doing	07/10/2020	9171	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\HOUSEKEEP	Tighten RHF Prentice mount bolt			22/09/2020	9171	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\HOUSEKEEP	check over			19/09/2020	9119	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\DAMAGE	ram pin broken on grab		replaced broken grab pin	08/09/2020	9092	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\HOUSEKEEP	grease grab and loader		greased loader	08/09/2020	9092	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	DrCabElect\INST/GAUGE	replace all dash light globes in loeader			08/09/2020	9092	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\HOUSEKEEP	fix RHR leg pin not taking grease			08/09/2020	9092	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\DAMAGE	replace leg pivot pin			04/09/2020	9082	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS	Rinlatech	03/09/2020	9068	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\RAM	RHR leg ram leaking			29/08/2020	9042	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\RAM	RHR leg ram upper pin broken		replace RHR leg cylinder and pins	29/08/2020	9042	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\HOUSEKEEP	grease loader and grab		grease and check fluid levels	29/08/2020	9042	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\DAMAGE	weld main boom crack		weld cracks on boom	29/08/2020	9042	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\HOSES	leaking hose above rotator		replace hyd hose	06/08/2020	8964	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\OIL/FILTER	top up hyd oil			06/08/2020	8964	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS	drain fuel tank check water content pressure wash motor	10/07/2020	8885	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\EXHAUST	repair exhaust			24/06/2020	8816	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\HOUSEKEEP	grease loader legs			18/06/2020	8793	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\HOUSEKEEP	check loader coolant			18/06/2020	8793	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\HOUSEKEEP	clean motor			18/06/2020	8793	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Body\PANELS	engine covers			18/06/2020	8793	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Cooling\RADIATOR	Re-core leaking radiator & refit & test			16/06/2020	8793	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\ENG TUNE	Tune Engine			16/06/2020	8793	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\HOUSEKEEP	grease loader and grab		weld leg pin tab	06/06/2020	8793	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\FUEL TANK	engine misfire (ref WD)		clean out fuel tank and fit new fuel lines	06/06/2020	8793	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	DrCabElect\RADIO	check stereo wirin - radio cuts out (have to wiggle the orange wire)			06/06/2020	8793	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\DAMAGE	replace grab tips		fit new tips on grab. Rinlatech	06/06/2020	8793	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Body\PANELS	repair engine covers			06/06/2020	8793	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\PUMP	remove hyd servo pump and fit seal kit and gasket			06/06/2020	8793	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\BELTS/TENS	replaced fan and a/c belts			30/05/2020		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\HOUSEKEEP	check fluids			30/05/2020		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\HOUSEKEEP	grease machine			30/05/2020		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\DAMAGE	repair LH & RH main lift eyes and fit new bushes			26/05/2020	8776	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\DAMAGE	replace bottom main lift pin			26/05/2020	8776	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\DAMAGE	line bore bottom main lift pin boss and fit bushes			26/05/2020	8776	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	VehService\BS	B Service As Per Attached Checklist	VehService\BS		09/05/2020	8684	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\HOUSEKEEP	grease loader and check all fluids			02/05/2020		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	DrCabRep\HOUSEKEEP	replace headlinings		roof liner	21/03/2020	8639	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\HYDRAULICS	move fly boom grease nipple (ref W.D)		remote grease line	21/03/2020	8639	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\HYDRAULICS	replace broken nipple on grab ram		grease nipples	21/03/2020	8639	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\HYDRAULICS	replace nipples on top main boom rams			21/03/2020	8639	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\HOUSEKEEP	check if grease gun can pump lo grease			21/03/2020	8639	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\HOUSEKEEP	mod grab to delete chain (ref W.D)			21/03/2020	8639	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\FILTERS	replaced air filter			21/03/2020	8639	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\HOUSEKEEP	repair crocks on boom hard line mounts		hardline mounts	21/03/2020	8639	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\HOSES	fix hydraulic hoses			21/03/2020	8639	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Body\HOUSEKEEP	water leaking through roof			07/03/2020	8594	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	DrCabRep\HOUSEKEEP	roof lining wet and sagging			07/03/2020	8594	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\HOUSEKEEP	check and top up oil and coolant			07/03/2020	8594	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Workshop\MOVE ASSET	pick uploader			04/03/2020	8576	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Body\HOUSEKEEP	wash grab and top up			04/03/2020	8576	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\OIL/FILTER	hyd oil			04/03/2020	8576	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE

P18	Myrtleford - Workshop	Hydraulics\HYD LEAKS	fit seal kit to grab swivel			03/03/2020	8575	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\RAM	replace leaking grab ram			25/02/2020	8570	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\HOUSEKEEP	weld cracks up in grapple			25/02/2020	8570	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	DriCabRep\WINDSCREEN	front window not fitting correctly			25/02/2020	8570	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	DriCabRep\WINDSCREEN	Replace front windscreen L7998			18/02/2020	8569	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	DriCabRep\DAMAGE	Fit seal kit to LH joystick			18/02/2020	8569	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\HOUSEKEEP	grease loader and grab		greased loader and grab	16/02/2020	8540	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	DriCabRep\DAMAGE	replace joystick handles (ref w.d)		replaced joystick grips	16/02/2020	8540	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\HOSES	replace leaking hose on top of boom		replaced x4 hose's at boom knackle	16/02/2020	8540	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Elect\WORK LIGHT	replace light bar		replaced light bar top of cab	16/02/2020	8540	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\MOTOR	check noise in slew motor		inspect noise - slew gear/motor	07/02/2020	6501	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\HYDRAULICS	checked drive gear - all tight checked for movement - all good - need to monitor or investigate more			07/02/2020	6501	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\BREAKDOWN	oil leak at filter head		call out. Inspect and fix hyd oil leak at filter head	03/02/2020	6479	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\OIL LEAK	drove up to loader fitted hyd return filter cap and o-ring missing from cap starter ands tested all good			03/02/2020	6479	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Body\PAINT/REST	wash down due to hyd leak			03/02/2020	6479	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\EXHAUST	replace exhaust clamp at muffler			03/02/2020	6479	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	VehService\BS	B Service As Per Attached Checklist	VehService\BS	carry out hydraulic service	01/02/2020	8474	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\HOUSEKEEP	check over top up fluids			25/01/2020	8438	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\HOUSEKEEP	grease			25/01/2020	8438	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\HOUSEKEEP	grease main boom ram ends			15/01/2020	8404	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\HYDRAULICS	repair cracked grapple pin retainer			15/01/2020	8404	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Albury - Workshop	DriCabRep\HOUSEKEEP	wash and assemble grab parts			09/01/2020		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Albury Workshop	PRENTICE
P18	Myrtleford - Workshop	DrCabElect\PHONE	check and repair trunk phone			09/01/2020	8375	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Air Con\AIR CON	replace aircon and repair aircon system and regas			28/12/2019	8359	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\HOUSEKEEP	grease loader and check lights			20/12/2019	8358	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	DrCabElect\RADIO	UHF extension speaker not working		fit RHN cap to exhaust	20/12/2019	8359	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Air Con\AIR CON	fan unit is on all the time, UHF is not hard wired and key needs to be on to power UHF which makes fan run			20/12/2019	8359	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	DrCabElect\INST/GAUGE	no guage lights or panel lights			20/12/2019	8359	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Rosewood - Workshop	Hydraulics\HYD LEAKS	grab oil leak			14/12/2019	8300	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Rosewood Workshop	PRENTICE
P18	Rosewood - Workshop	VehService\BS	B Service	VehService\BS		14/12/2019	8300	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Rosewood Workshop	PRENTICE
P18	Rosewood - Workshop	Body\HOUSEKEEP	check over			12/12/2019		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Rosewood Workshop	PRENTICE
P18	Rosewood - Workshop	Hydraulics\HOSES	supply 4 hyd hoses as per sample			12/12/2019		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Wodonga Workshop	PRENTICE
P18	Tumut - Workshop	Hydraulics\HOSES	hose fitting on RHS lift ram leaking			06/12/2019	8313	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Tumut Workshop	PRENTICE
P18	Tumut - Workshop	DrCabElect\RADIO	UHF extension speaker not working			06/12/2019	8313	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Tumut Workshop	PRENTICE
P18	Tumut - Workshop	Air Con\AIR CON	fan unit is on all the time, UHF is not hard wired and key needs to be on to power UHF which makes fan run			06/12/2019	8313	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Tumut Workshop	PRENTICE
P18	Tumut - Workshop	DrCabElect\INST/GAUGE	no guage lights or panel lights			06/12/2019	8313	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Tumut Workshop	PRENTICE
P18	Rosewood - Workshop	Hydraulics\HOSES	REPLACE ALL 4 HOSES TO GRAPLE HEAD FROM FLY BOOM			28/11/2019	8302	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Rosewood Workshop	PRENTICE
P18	Rosewood - Workshop	Brakes\HOUSEKEEP	CHECK & GREASE (WHAT)			26/11/2019	8296	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Rosewood Workshop	PRENTICE
P18	Rosewood - Workshop	DriCabRep\RADIO	TIGHTENED UHF ANTENNA & CHECK CABLE		FIT UHF RADIO HAND PIECEHOLDER	20/11/2019	8255	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Rosewood Workshop	PRENTICE
					TOP UP HYD OIL										
P18	Rosewood - Workshop	Engine\HOUSEKEEP	GRASE LOADER		CHECK OVER	20/11/2019	8255	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Rosewood Workshop	PRENTICE
P18	Rosewood - Workshop	Hydraulics\RAM	WELD GRAB PIN PLATE IN PLACE			13/11/2019		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Rosewood Workshop	PRENTICE
P18	Rosewood - Workshop	Hydraulics\RAM	REPLACE MAIN BOOM PIN LOCK BOLT (REPLACE MAIN BOOM PIN & LINEBORE HOUSING)			12/11/2019	8186	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Rosewood Workshop	PRENTICE
P18	Rosewood - Workshop	Workshop\MOVE ASSET	CALL OUT TO BENDENERE			11/11/2019	8188	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Rosewood Workshop	PRENTICE
P18	Rosewood - Workshop	Air Con\AIR CON	DIAGNOSE FAULTY RELAY ON A/C FAN, BYPASSED TEMP AND FIX			11/11/2019	8188	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Rosewood Workshop	PRENTICE
			REMOVE BLOCKED PILOT FILTER,CHECK HYD												
P18	Rosewood - Workshop	Hydraulics\OIL/FILTER	ALL GOOD			11/11/2019	8188	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Rosewood Workshop	PRENTICE
					SUPPED OLD PILOT FILTER FOR ONE OFF P14										
P18	Rosewood - Workshop	Hydraulics\HYD LEAKS	CALL TO MARAGLE TO REPAIRE SLOW HYDRAULIC		TESTED ALL GOOD	08/11/2019	8164	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Rosewood Workshop	PRENTICE
P18	Rosewood - Workshop	Body\AIR LEAK	TEMP REPAIRE TO AIR LEAK UNDER FUEL TANK AREA			08/11/2019	457953	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Rosewood Workshop	PRENTICE
P18	Rosewood - Workshop	Chassis\MOUNTS	REPAIRED & WELD CRAKS ON ENGINE MOUNTS			01/11/2019	8100	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Rosewood Workshop	PRENTICE
P18	Rosewood - Workshop	VehService\BS	B SERVICE	VehService\BS		01/11/2019	8100	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Rosewood Workshop	PRENTICE
			due for service at 7950 hrs												
P18	Albury - Workshop	VehService\BS	non at 7967 hrs	VehService\BS		22/10/2019		Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Albury Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\HOUSEKEEP	grease loader			11/10/2019	7904	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\HOUSEKEEP	check and top up fluids and check coolant leak			11/10/2019	7904	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Cooling\RADIATOR	add stop leak to radiator - small leak in core			11/10/2019	7904	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Body\HOUSEKEEP	wash loader			11/10/2019	7904	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\CROSS MBR	repair cracks in grab (Rinlatech) - Sublet			11/10/2019	7904	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
					moved hose										
					put spiral wrap on hose										
P18	Myrtleford - Workshop	Hydraulics\HOSES	replace hose on grab - you'll see which one		got extra hoses made	24/09/2019	7847	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Body\HOUSEKEEP	hot washed grab			24/09/2019	7847	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\HYD LEAKS	oil leak at grab again			20/09/2019		Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	DrCabElect\RADIO	replace UHF handpiece - button sticking			20/09/2019		Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\OIL/FILTER	test and check hyd. oil			20/09/2019		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	DrCabElect\RADIO	UHF			19/09/2019	7835	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Body\HOUSEKEEP	grease loader and grab			18/09/2019	7828	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\HOSES	replace leaking hoses on grab			18/09/2019	7828	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	DrCabElect\RADIO	check uhf/aerial - very poor range			18/09/2019	7828	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Body\HOUSEKEEP	wash truck bonnet			18/09/2019	7828	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\HOUSEKEEP	grease loader & grab			11/09/2019	7803	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	DriCabRep\DOOR LOCK	Replace door striker		top up hydraulic oil	24/08/2019	7798	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\OIL LEAK	Replace fuel lift pump			24/08/2019	7798	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS		23/08/2019	7740	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	DrCabElect\AIR CON	repair aircon system			01/08/2019	7678	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\OIL/FILTER	top up hyd oil			06/07/2019	7543	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	VehService	grease loader and grab			02/07/2019	7542	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\HOSES	oil leak at hose on top of boom			02/07/2019	7542	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\HOUSEKEEP	check engine breathing very heavy and using oil			02/07/2019	7542	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\DAMAGE	RHR leg pin nut loose			02/07/2019	7542	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	DrCabElect\INST/GAUGE	gauge lights n/w		fit bulbs to loader gauge	02/07/2019	7542	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	DriCabRep\RADIO	supply new UHF aerial			02/07/2019	7542	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\OIL LEAK	fit seals to LH servo - control			02/07/2019	7542	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	VehService	fit grease nipples to loader rams			02/07/2019	7542	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	DrCabElect\ELECT P&W	fit strobe light to leader cabin			02/07/2019	7542	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\HOUSEKEEP	weld cracks in boom			02/07/2019	7542	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\HOUSEKEEP	steam clean log grab			02/07/2019	7542	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\HOUSEKEEP	clean loader motor			02/07/2019	7542	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\HOUSEKEEP	carry out engine blow by test			02/07/2019	7542	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS	change hyd filters	02/07/2019	7542	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Albury - Workshop	Workshop\MOVE ASSET	travelled to and from Wodonga depot			14/06/2019		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Albury Workshop	PRENTICE
P18	Albury - Workshop	Hydraulics\HYD LEAKS	diagnosed hydraulic leaks			14/06/2019		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Albury Workshop	PRENTICE
P18	Albury - Workshop	Hydraulics\HOSES	removed hydraulic pipe and clamps for outer boom lift			14/06/2019		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Albury Workshop	PRENTICE
P18	Albury - Workshop	Hydraulics\HOSES	replaced pipe, hose, clamps and o-rings			14/06/2019		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Albury Workshop	PRENTICE
P18	Albury - Workshop	Hydraulics\HOSES	re-routed hoses to added rubbing			14/06/2019		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Albury Workshop	PRENTICE
P18	Albury - Workshop	Hydraulics\HYD LEAKS	tested, found other leaks and replaced required o-rings			14/06/2019		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Albury Workshop	PRENTICE
P18	Albury - Workshop	Workshop\CLEAN	degreased and washed			14/06/2019		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Albury Workshop	PRENTICE
P18	Albury - Workshop	Hydraulics\RAM	tightened grab ram fitting			14/06/2019		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Albury Workshop	PRENTICE
P18	Myrtleford - Workshop	Body\MOUNTS	Fit Guides To A Frame Where Boom Sits			28/05/2019	7780	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\HOUSEKEEP	grease loader and grab			25/05/2019	7312	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\DAMAGE	fit missing grease nipple to boom			25/05/2019	7312	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	DrCabElect\ELECT P&W	interior light not working			25/05/2019	7312	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Elect\WORK LIGHT	fit new LH out boom work light			25/05/2019	7312	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS	topped up 30liter hyd oil	25/05/2019	7312	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Albury - Workshop	Chassis\Boom	REPLACE BROKEN LOWER BOOM PIN.			18/05/2019	7275	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Albury Workshop	PRENTICE
P18	Albury - Workshop	Workshop\MOVE ASSET	pick up from wec			17/05/2019	7275	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Albury Workshop	PRENTICE
P18	Albury - Workshop	Body\AIR LEAK	replaced leaking grab ram			17/05/2019	7275	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Albury Workshop	PRENTICE
P18	Albury - Workshop	Body\AIR LEAK	removed broken grap pin bolt			17/05/2019	7275	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Albury Workshop	PRENTICE
P18	Albury - Workshop	Engine\HOUSEKEEP	degreased and washed			17/05/2019	7275	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Albury Workshop	PRENTICE
P18	Albury - Workshop	Workshop\MOVE ASSET	drop off to Wodonga Engineering for repairs			01/05/2019		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Albury Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\HOUSEKEEP	grease loader and grab			27/04/2019	7266	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\HOSES	replace blown hyd hose			12/04/2019	7211	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\OIL/FILTER	check hyd oil			12/04/2019	7211	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\HOUSEKEEP	check engine oil and coolant			12/04/2019	7211	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Body\HOUSEKEEP	wash oil off			12/04/2019	7211	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\HYDRAULICS	replace RHR top leg pin			06/04/2019	7190	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\HOSES	reposition 2x pressure line on pump			06/04/2019	7190	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\PUMP	repair thread pump suction hose			06/04/2019	7190	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\OIL/FILTER	top up/check hyd oil			06/04/2019	7190	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\DAMAGE	weld retainer lug on RHR			06/04/2019	7190	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\HOUSEKEEP	fit retainer bolt to bottom RHR leg pin			06/04/2019	7190	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
			remove tripple pump off P16 and fit to P18												
P18	Myrtleford - Workshop	Hydraulics\PUMP	reco tripple pump off p 18 & make up new drive adapator			06/04/2019	7190	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE

P18	Myrtleford - Workshop	Hydraulics\PUMP	remove tripple pump off P18				06/04/2019	7190	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\PUMP	fit hyd pump and drive adaptor off P16 to P18				06/04/2019	7190	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\BREAKDOWN	travel to breakdown				06/04/2019	7190	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	DriCabRep\WINDSCREEN	Replace RH sliding window				23/03/2019	7151	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	VehService\BS	B Service As Per Attached Checklist	VehService\BS			16/03/2019	7096	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	VehService\BS	B Service As Per Attached Checklist	VehService\BS			24/01/2019	6904	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\RAM	stick body ram broken				18/01/2019	6883	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\CHAS CRACK	repair crack in boom				18/01/2019	6883	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Body\HOUSEKEEP	grease loader please				18/01/2019	6883	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\HOSES	Replace hyd return hose				21/12/2018	6792	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Body\MOUNTS	Fit bolts to boom support				21/12/2018	6792	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\RAM	weld pin cap on grab ram				15/12/2018	6782	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\HOUSEKEEP	grease loader and grab				24/11/2018	6699	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	DrCabElect\RADIO	stereo keeps cutting out				24/11/2018	6699	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\MOTOR	check slew gear and pinion gear				24/11/2018	6699	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS			24/11/2018	6699	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\HOUSEKEEP	check engine breathing heavily				10/11/2018	6642	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\OIL LEAK	oil leak at grab				10/11/2018	6642	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	DriCabRep\SEAT	replace both arm rests				02/10/2018	6504	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\OIL/FILTER	hydraulic service				21/09/2018	6522	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\RAM	Replace LH bottom main lift ram bush		replace bottom eye on ram replace bottom eye on ram		21/09/2018	6503	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\RAM	Replace outer boom ram bushes		top up 30lts hyd oil		21/09/2018	6503	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	DrCabElect\AIR CON	Reift air con filler box				21/09/2018	6503	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	VehService\BS	B Service As Per Attached Checklist aircon not cold	VehService\BS			19/09/2018	6522	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	DrCabElect\AIR CON	fit a/con compressor & tx valve hoses & dryer & pressure switch. aircon not cold				18/09/2018	6503	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	DrCabElect\RADIO	check prentice UHF aerial base (aerials keep falling off can't tighten)				18/09/2018	6503	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\HYDRAULICS	pin retaining bolt broken				28/08/2018	6392	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Body\HOUSEKEEP	grease legs and boom				28/08/2018	6392	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\HOUSEKEEP	2L coolant				28/08/2018	6392	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\HOUSEKEEP	5L engine oil				28/08/2018	6392	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
					replaced inner and outer P611856											
P18	Myrtleford - Workshop	Engine\AIR CLNR	Replace air filter		P611857		09/08/2018	6503	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\CONSUMABLE	Replace RHS servo handle				09/08/2018	6503	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\PUMP	Rebuild servo pump				09/08/2018	6503	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\HYD LEAKS	RH level plunger leaking oil				08/08/2018	3607	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Body\CONSUMABLE	grease loader and grab				08/08/2018	3607	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	VehService\BS	B Service As Per Attached Checklist	VehService\BS			08/08/2018	6307	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\HYD LEAKS	Remove servo pump to be re-sealed and refit. Remove servo pump to be re-sealed				03/08/2018	6503	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\CONSUMABLE	Grease Loader				01/08/2018	6279	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Body\HOUSEKEEP	grease loader and grab				19/06/2018	6106	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Body\EXHAUST	exhaust mount broken				19/06/2018	6106	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Body\MOUNTS	tighten loose A frame plate bolts				19/06/2018	6106	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	VehService\BS	B Service As Per Attached Checklist	VehService\BS			19/06/2018	6106	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Body\REFLECTORS	fit 2 new L&R zebra signs to back of loader				05/06/2018	430982	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\RAM	Replace out boom ram bush (spear end)				22/05/2018		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\BREAKDOWN	remove broken bottom main lift pin make up and fit new bottom main lift pin & REPLACE BOOM HOSES				17/05/2018	6035	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Frid Serv\BREAKDOWN	(L4468)				17/05/2018	6035	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\RAM	grease both light rams				17/05/2018	6035	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Workshop\MOVE ASSET	take to Rinlatech and pick up				17/05/2018	6035	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\HOUSEKEEP	grease loader and grab				15/05/2018	6033	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	DriCabRep\SEAT	fit 2x new seat runners				12/05/2018	6027	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\OIL/FILTER	top up hyd oil				12/05/2018	6027	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\HOUSEKEEP	check engine fluids				12/05/2018	6027	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\HOUSEKEEP	Remove Scale Link & Fit Solid Link		remove grab from P12 and remove link for P18		28/04/2018	5981	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Body\EXHAUST	repair exhaust bracket				24/04/2018	5981	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	DriCabRep\DOOR LOCK	repair door latch				24/04/2018	5981	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\VALVES	check and adjust servo pressure				24/04/2018	5981	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Body\PANELS	refit cover, weld lugs to cover and fit new turbo intake clamps				24/04/2018	5981	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Cooling\RADIATOR	Remove & repair & refit Radiator				20/04/2018	5981	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\HOUSEKEEP	Repair or replace RHF pin lock tab Repair or replace grab pin lock tab				20/04/2018	5981	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\HOUSEKEEP	(L4331). Repair or replace grab pin lock tab				20/04/2018	5981	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\VALVES	Check all hydraulic pressures				20/04/2018	5981	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\VALVES	Check servo pressure		adjust RHS servo joystick		20/04/2018	5981	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	DriCabRep\DOOR LOCK	Repair cab door not sealing on cab				20/04/2018	5981	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\HOSES	Replace weeping boom hoses				20/04/2018	5981	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	DrCabElect\RADIO	Check AM/FM Radio reception		checked radio reception is fine		20/04/2018	5981	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\DAMAGE	Repair tips on grab				20/04/2018	5981	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Cooling\RADIATOR	Check & Test Radiator				17/04/2018		Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\HOUSEKEEP	Replace leg pin & tab				17/04/2018		Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\FILTERS	Replace air filter cover clips				28/03/2018	5981	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\HOUSEKEEP	grease loader		replace leg grease nipples		27/03/2018	5894	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	VehService\BS	B Service As Per Attached Checklist	VehService\BS	fit new hyd tank air filter		27/03/2018	5894	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Elect\WORK LIGHT	fit 2nd LH boom work light				02/03/2018	5781	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	DriCabRep\HOUSEKEEP	roof lining falling down				02/03/2018	5781	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	DrCabElect\AIR CON	aircon not working				02/03/2018	5781	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\HOUSEKEEP	wash grab				09/02/2018	5862	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\OIL/FILTER	top up hydraulic oil				09/02/2018	5862	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\OIL LEAK	Fit seal kit to grab hose swivel				09/02/2018	5862	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	DriCabRep\DOOR LOCK	Adjust cab door & replace door rubber if needed		5781 hrs		09/02/2018	5862	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\HOUSEKEEP	Grease Loader				09/02/2018	5862	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	VehService\BS	B Service As Per Attached Checklist	VehService\BS			07/02/2018	5685	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\HOUSEKEEP	Housekeeping - Weld Main boom crack at base if boom				06/01/2018	5563	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\BELTS/TENS	Replace Air con pulley & belt Replace Fan belt pulley's & belts		Replace crank shaft pulley & seal & reseal front cover plate		05/01/2018	5562	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\BELTS/TENS	Check Tensioners		wash engine & test		05/01/2018	5562	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\EXHAUST	exhaust muffler adrift again				03/01/2018		Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	DriCabRep\HOUSEKEEP	fit seal to bottom of loader door				03/01/2018		Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\HYD LEAKS	LH control plungers leaking				03/01/2018		Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\BELTS/TENS	high pitched noise when aircon on				03/01/2018		Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\HOUSEKEEP	grease loader				03/01/2018		Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\HOUSEKEEP	grease loader				16/12/2017	5484	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\RAM	replace missing bolt on pin in ram on grab		Replaced hydraulic filter no air cleaner to replace existing one no fuel filters P550115 weld leg pin retain and tighten all retainer bolts		16/12/2017	5484	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	VehService\BS	B Service As Per Attached Checklist	VehService\BS	replaced exhaust mount, and exhanged servo filter		16/12/2017	5485	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\HOUSEKEEP	grease loader				02/12/2017	5397	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\MOTOR	refit gear to grab slew motor (Rinlatech)				02/12/2017	5397	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\HYD LEAKS	oil leaks at fitting on grab rams				04/11/2017	5272	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Elect\WORK LIGHT	LH work light on outer boom flickers				04/11/2017	5272	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	VehService\BS	B Service per attached Checklist	VehService\BS	tighten a/c belt		04/11/2017	5272	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	DriCabRep\HOUSEKEEP	Fit seal along the bottom of cab door				25/10/2017	5981	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	DriCabRep\DOOR LOCK	Repair or replace door strut				25/10/2017	5981	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\MOTOR	grab keeps on rotating		fit new grab rotator motor		24/10/2017	5222	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\HOUSEKEEP	grease loader				24/10/2017	5222	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\HOUSEKEEP	R/rear leg pin broken		replace RHR lower leg pin		07/10/2017	5160	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Workshop\MOVE ASSET	take loader to Rinlatech and pick up and return to Depot				07/10/2017	5160	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\HOSES	replace leaking hose on body				27/09/2017	5106	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\OIL/FILTER	check hyd oil level				27/09/2017	5106	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Cooling\HOUSEKEEP	check coolant level				27/09/2017	5106	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\MOUNTS	Replace broken RHF engine mount bolt & fit all new bolts		fit disc lock washers to all bolts adjusted A/C belt top up hyd oil 30 LT		14/09/2017	415835	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS	broken RHF engine mount bolt		12/09/2017	5047	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\RAM	Fit seal kit to LH main lift ram				05/09/2017	5047	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\RAM	Fit seal kit to stick boom ram				05/09/2017	5047	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE

					replace a/con compressor L3294										
					fit new dryer asm.										
P18	Myrtleford - Workshop	Air Con\AIR CON	Check and repair air con		Regas and test aircon system	05/09/2017	5047	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Elect\WORK LIGHT	fit light bar			02/09/2017	5016	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\HOUSEKEEP	grease loader please			19/07/2017	4867	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
			Replace RHR welsh plug in cylinder head												
P18	Myrtleford - Workshop	Engine\COOL LEAKS	(cummins fitted 5 new welsh plugs in engine block)			18/07/2017	4926	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Body\HOUSEKEEP	wash loader			16/07/2017		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\HYD LEAKS	oil lost out of scale head			15/07/2017	4689	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
					RHR welsh plug leaking coolant										
P18	Myrtleford - Workshop	VehService\BS	B Service As Per Attached Checklist	VehService\BS	seal around welsh plug at rear of eng. And RHS rear	14/07/2017	4850	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\HOUSEKEEP	replace injector pump			13/07/2017	4832	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\HOUSEKEEP	check fuel lift pump			13/07/2017	4832	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\FAULT CODE	check codes			13/07/2017	4832	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\HOUSEKEEP	Start Engine & check over		fit new battery and check engine codes	07/07/2017	4832	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
			drive out to breakdown												
P18	Myrtleford - Workshop	Engine\BREAKDOWN	motor cranks but wont start			06/07/2017		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\RADIATOR	engine using coolant			06/07/2017		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
			check battery voltage												
P18	Myrtleford - Workshop	Elect\BATTERY	replace battery (mae)			06/07/2017		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
			check injector line for fuel - ok. Need to check pressure												
			check fuel cut off solenoid and harness												
P18	Myrtleford - Workshop	Engine\HOUSEKEEP	check engine oil condition and level			06/07/2017		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\HOUSEKEEP	replace grease nipple on main boom (lower one)		grease main boom	21/06/2017	411102	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	DrCabElect\RADIO	fit new UHF handpiece		fit new UHF handpiece	21/06/2017	411102	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\HOUSEKEEP	weld cracks in main boom			13/06/2017	4766	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\OIL/FILTER	top up hydraulic oil & fit new air filter to hyd tank			13/06/2017	4766	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\HOUSEKEEP	grease loader			13/06/2017	4766	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\RAM	replace outer boom ram bushes and eyes			13/06/2017	4766	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\HYDRAULICS	replace outer boom bushes and pivot pin			13/06/2017	4766	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
			fitting on scale head loose												
P18	Myrtleford - Workshop	Hydraulics\OIL LEAK	lost oil			30/05/2017	4713	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\HOSES	hose on top of boom leaking			13/05/2017	4671	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	VehService\BS	B Service As Per Attached Checklist	VehService\BS		12/05/2017	4654	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\HOUSEKEEP	nut where grab joins boom loose			06/05/2017	4632	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\HOUSEKEEP	grease loader			06/05/2017	4632	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\RAM	repair RH hyd ram leak (crack in weld on barrel)			07/04/2017	4530	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\RAM	refit RHS main lift ram			07/04/2017	4530	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\OIL/FILTER	top up hyd oil and test			07/04/2017	4530	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Body\HOUSEKEEP	wash down loader & rams			07/04/2017	4530	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Elect\WORK LIGHT	repair lift boom wiring for work lights			07/04/2017	4530	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
					remove hyd pump and send for repairs										
P18	Myrtleford - Workshop	Hydraulics\PUMP	Replace leaking seal & hydraulic triple pump		clean out fly wheel housing	30/03/2017	4536	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
					Fit new scale link fitting & bleed scale link										
P18	Myrtleford - Workshop	Hydraulics\HYD LEAKS	Hose on scale link ripped off		Complete	28/03/2017	4497	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
					change hyd. Filter										
P18	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS	change servo filter	15/03/2017	4439	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\PUMP	remove and reseal servo pump & refit & check pressures			15/03/2017	4439	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\EXHAUST	remove and make up new exhaust bracket			15/03/2017	4439	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\EXHAUST	fit new 3 1/2 inch exhaust clamp			15/03/2017	4439	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\EXHAUST	fit new 3 1/8" exhaust clamp to turbo			15/03/2017	4439	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\OIL LEAK	fit new rivets at oil filler cap cover lock			15/03/2017	4439	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\HYD LEAKS	check oil leak at grab			08/03/2017	4417	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
					clean down fuel pump, run engine at high revs										
P18	Myrtleford - Workshop	Engine\HOUSEKEEP	Check fuel pump for fuel leaks		tightened leaking fuel line, rinsed engine down	03/03/2017	4398	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\HOUSEKEEP	fuel leak at diesel pump			02/03/2017	4392	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	DrCabElect\RADIO	supply new uhf aerial			02/03/2017	4392	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Body\HOUSEKEEP	grease loader			25/02/2017	4366	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
					Myrtleford Auto Electrics										
P18	Myrtleford - Workshop	Air Con\AIR CON	Repair air con system		Complete	22/02/2017	4353	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
			remove hydraulic ram												
			replace seals and clean spear												
			replace ram eye bearings												
			make 2x ram mount pins												
			cut off damaged pin boss make new one and weld back on												
P18	Myrtleford - Workshop	Hydraulics\RAM	refit ram & test			08/02/2017	4300	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\OIL/FILTER	top up hydraulic oil and grease			08/02/2017	4300	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
			Fit rod to all grab tips		fit rod to grab tips										
P18	Myrtleford - Workshop	Hydraulics\CONSUMABLE	Fit plates to grab tines & repair tips. Fit rod to all grab tips		(didn't need plates)	24/01/2017	5981	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
					pick up wire from R/lech and pick up truck										
P18	Myrtleford - Workshop	Hydraulics\RAM	Check & Replace leg ram bushes & pins		check pins ok at this stage	24/01/2017	5981	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\OIL LEAK	oil leak at grab - fitting loose on ram			21/01/2017	4241	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS		21/01/2017	4241	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\VALVES	Fit seal kit to slew valve under cab			06/01/2017	4178	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
					Replace broken scale link bulk head fitting & bleed										
P18	Myrtleford - Workshop	Hydraulics\HOSES	Scale head leaking oil		Complete	04/01/2017	4170	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Body\MOUNTS	Fit hydraulic pipe brackets & weld frame		Complete	04/01/2017	4170	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Elect\WORK LIGHT	work lights not working			29/12/2016	4158	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\HOUSEKEEP	grease loader			29/12/2016	4158	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	DrCabRep\DOOR LOCK	fit door hinge bolts			29/12/2016	4158	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Body\HOUSEKEEP	wash loader			21/12/2016	4141	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\OIL/FILTER	fill hyd oil tank & fit new filter + strainer			21/12/2016	4141	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\MOTOR	fit new slew motor shaft + reline valves			21/12/2016	4141	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\OIL LEAK	Replace slew motor seal			15/12/2016	4138	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	DrCabElect\AIR CON	Repair air con & fan speed		replace fan resister	15/12/2016	4138	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Body\HOUSEKEEP	Grease loader		Complete	13/12/2016	4123	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	DrCabElect\RADIO	Check trunk phone handpiece - not working at times		Complete	13/12/2016	4123	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS		23/11/2016	4047	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\EXHAUST	repair exhaust clamp bracket			15/11/2016	4004	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\BELTS/TENS	Replace fan belt			15/11/2016	4004	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
					Tighten loose air con belt										
					check tensioner, water pump, pulleys & idler bearing										
P18	Myrtleford - Workshop	Engine\BELTS/TENS	Check air con operation - noisey		complete	11/11/2016	3998	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Body\HOUSEKEEP	Grease loader		Complete	03/11/2016	3964	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\HOUSEKEEP	Check oil & coolant		Complete	17/10/2016	3924	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	DrCabElect\INST/GAUGE	Repair engine RPM wiring system			27/09/2016	3944	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS		24/09/2016	3830	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\EXHAUST	Repair exhaust bracket		Complete	23/09/2016	3830	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
			Replace broken grease nipple LHR leg												
P18	Myrtleford - Workshop	Chassis\HOUSEKEEP	Grease loader		Complete	23/09/2016	3830	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\HOSES	fitting on scale head loose - lost oil			23/08/2016	3715	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\OIL LEAK	hydraulic oil leak raising & lowering legs			18/08/2016	3692	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\OIL/FILTER	top up hyd oil			18/08/2016	3692	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\EXHAUST	exhaust falling off- flange u/s			13/08/2016	3677	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Unknown	PRENTICE
P18	Myrtleford - Workshop	DrCabElect\ELECT P&W	replace strobe light			13/08/2016	3677	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Unknown	PRENTICE
P18	Myrtleford - Workshop	DrCabRep\DOOR LOCK	door gettting hard to open			13/08/2016	3677	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Unknown	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\HOSES	check hoses on boom			13/08/2016	3677	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Unknown	PRENTICE
P18	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS		03/08/2016	3629	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\EXHAUST	refit exhaust to turbo			21/07/2016	3595	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\EXHAUST	repair broken exhaust mount. exhaust mount broken			21/07/2016	3595	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\HOUSEKEEP	top up 5 LT engine oil			21/07/2016	3595	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	DrCabRep\WINDSCREEN	Replace front windscreen			19/07/2016	3612	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	DrCabElect\ELECT P&W	Repair fan on roof - not working		Check fan - remove & replace	15/07/2016	3573	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\HOSES	repair damaged hard lines			30/06/2016	3507	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Elect\WORK LIGHT	repair damaged work light wiring			30/06/2016	3507	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\OIL/FILTER	replace hyd filter			08/06/2016	3453	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\OIL/FILTER	replace servo filter			08/06/2016	3453	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\OIL/FILTER	replace hyd oil			08/06/2016	3453	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\OIL/FILTER	clean out hyd tank			08/06/2016	3453	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\OIL/FILTER	replace hyd breather filter			08/06/2016	3453	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
					fit 2nd hand ram barrel + make up new piston & fit seal kit										
P18	Myrtleford - Workshop	Hydraulics\RAM	Replace LH & RH Bottom ram bushes		replace top + bottom main lift ram pins	27/05/2016	3453	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE

			Replace main crane base pin & bosses														
P18	Myrtleford - Workshop	Chassis\HOUSEKEEP	Replace main boom bushes & grease lines														
P18	Myrtleford - Workshop	DrCabElect\SCALES	Check oil loss out of scale head		complete	25/05/2016	3652	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\PUMP	Repair cracked grab ram retaining plate		complete	25/05/2016	3652	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Elect\WORK LIGHT	Repair wiring & resecure on top of ram		complete	25/05/2016	3652	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\HOUSEKEEP	General check over		complete	25/05/2016	3652	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
					repaired outer boom light										
P18	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS	replace dash light globes	09/05/2016	3410	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\VALVES	fit new half set hand piece to LH servo controls			14/04/2016	3305	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	DrCabRep\WIPERS	Replace wiper insert		Complete	12/04/2016	3304	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	DrCabElect\RADIO	Fit new am/fm radio		Complete	18/03/2016	3213	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\EXHAUST	Refit Muffler		Complete	17/03/2016	3212	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS		15/03/2016	3205	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Body\HOUSEKEEP	Wash Loader		Complete	15/03/2016		Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\HOSES	Replace hydraulic hose on scales		Completed - RINLATECH	20/02/2016	2126	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
					Found broken transducer & bled scales										
P18	Myrtleford - Workshop	Hydraulics\HYD LEAKS	Check for oil leak at scale head		Completed	18/02/2016	3118	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\RAM	Grease main rams & boom		Completed	18/02/2016	3118	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Body\PANELS	wash cab & boom - hose blown		Completed	10/02/2016	3077	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\OIL/FILTER	check hydraulic oil level		Completed	10/02/2016	3077	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\HOSES	make up spare hydraulic hose		completed by Rinlatech	10/02/2016	3077	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
					Remove exhaust & panel beat flanges,straighten mount bracket										
					Fit new rubber mount & straighten rain cap										
P18	Myrtleford - Workshop	Engine\EXHAUST	exhaust mount broken		Completed	09/02/2016	3069	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Body\HOUSEKEEP	wash loader, steps & cabin		completed	02/02/2016	3036	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\OIL/FILTER	top up hydraulic oil		completed	02/02/2016	3036	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
			repair scales												
P18	Myrtleford - Workshop	Body	calibrate scales		completed	29/01/2016	3026	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
					replace turbo hose										
P18	Myrtleford - Workshop	Engine\BOOST HOSE	SUPPLY BOOST HOSE		completed	29/01/2016	3025	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Cooling\RADIATOR	repair radiator cowling		completed	29/01/2016	3025	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\EXHAUST	repair exhaust bracket		completed	29/01/2016	3025	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Body\PANELS	panel beat top cover		completed	29/01/2016	3025	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\ENG TUNE	tune up engine		completed	29/01/2016	3025	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
			test and calibrate scales												
P18	Myrtleford - Workshop	DrCabElect\SCALES	fit 2nd hand scale tranducer		completed	29/01/2016		Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
					replace exhaust bracket										
P18	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS	completed	25/01/2016	3015	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
					replaced hydraulic filter & servo pump filter										
P18	Myrtleford - Workshop	Hydraulics\OIL/FILTER	SUPPLY HYD FILTERS		completed	25/01/2016	3015	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\FILTERS	oil fuel & air filters		completed	25/01/2016	3015	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Cooling\RADIATOR	repair leaking radiator		completed	25/01/2016		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Cooling\RADIATOR	repair radiator leaks		completed	25/01/2016		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	DrCabRep\RADIO	2 X UHF MICS		completed	13/01/2016		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Body\MOUNTS	fit new bases to loader feet		completed	06/01/2016		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Body\DAMAGE	replace broken tip on grab		completed	19/12/2015	2900	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Body\MOUNTS	replace tips on other 2 tines		completed	19/12/2015	2900	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
			weld new tips on grab												
P18	Myrtleford - Workshop	Body\DAMAGE	rinatech		completed	19/12/2015		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	DrCabElect\INST/GAUGE	replace idler switch		completed	15/12/2015	2871	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
			throttle switch												
P18	Myrtleford - Workshop	DrCabElect\INST/GAUGE	rqandalls		COMPLETED	11/12/2015		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
			clean throttle pulse switch												
			clean plug at back of fuel pump												
			check coolant + oil levels												
P18	Myrtleford - Workshop	Engine\ELECT P&W	check alt voltage		completed	10/12/2015	2855	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
			supply fittings												
P18	Myrtleford - Workshop	Hydraulics\HOSES	rinlatech		completed	08/12/2015		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS	completed	05/12/2015	2843	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine\FUEL TANK	make lockable box for diesel pump		completed	05/12/2015		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
			filters												
P18	Myrtleford - Workshop	Engine\FILTERS	tctc		1339374 completed	03/12/2015		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
			fit new hydraulic hose to grab												
			wash down + test												
			make spare hyd hose												
P18	Myrtleford - Workshop	Hydraulics\HOSES	check hyd oil level		completed	03/12/2015	2822	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
			wire up 24 volt elec pump												
P18	Myrtleford - Workshop	Elect\ELECT P&W	mae		completed	02/12/2015		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Hydraulics\PUMP	replace 4 servo plunger seals on rhs servo		completed	12/11/2015	2718	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
			supply hoses + fittings												
P18	Myrtleford - Workshop	Hydraulics\HOSES	rinl		completed	06/11/2015		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
			oil + fuel + air filters												
P18	Myrtleford - Workshop	Engine\FILTERS	tctc		completed	27/10/2015		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS	completed	22/10/2015	2638	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
			fit new seat cover												
P18	Myrtleford - Workshop	Body\SEAT	replace scales transducer		completed	20/10/2015	2606	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Body\SEAT	seat cover		completed	17/10/2015		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Body\MOUNTS	tighten lhf loader mount bolt		completed	13/10/2015	2606	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Chassis\HYDRAULICS	make hoses		completed	10/10/2015		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Body\WINDSCREEN	refit rh window		completed	01/10/2015	2537	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Body\WINDSCREEN	refit rh window		completed	01/10/2015	2537	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
			tighten pin for ram on grab												
P18	Myrtleford - Workshop	Body	turn grab hose fitting		completed	18/09/2015	2484	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Body	replace hyd hose at grab because of oil leak		completed	16/09/2015	2471	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P18	Myrtleford - Workshop	Engine	b service		completed	08/09/2015	2434	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE