EquipmentName	Workshop	CodeAndSubCode	Description	Schedule	CompletionComments	DateDone	HourDone	Worktype	Workstate	EquipmentOwner	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
LOAD16	Wodonga - Workshop	Elect\ELECT P&W	wiring from front of truck to rear tail light bar may still have fault			26/03/2024		Repair	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Wodonga Workshop	LOADER
LOAD16	Myrtleford - Workshop	Elect\ELECT P&W	replace reverse light and repair buzzer wiring		check way reverse light and buzzer not working	20/11/2018	482288	Fault	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Engine\HOUSEKEEP	check coolant and oil			20/09/2018	480579	Fault	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Engine\HOUSEKEEP	start L-16, check oil and water			05/09/2018	48054	Repair	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Tyres\PRES CHECK	Job Added From Invoice			26/08/2018	0	Repair	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			08/06/2018		Repair	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	VehService\BS	B Service As Per Attached Checklist	VehService\BS		08/06/2018		Service	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Brakes\BRAKE ADJ	adjust brakes drive only			07/06/2018	479921	Fault	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Elect\HEAD LIGHT	LH headlight not working			07/06/2018	479921	Fault	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	DrivLine\OIL LEAK	topped up diff oil			07/06/2018	479921	Fault	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Engine\COOL LEAKS	fill with stop leak and run truck motor			24/05/2018	478971	Repair	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Tyres\RUN OUT	Job Added From Invoice			12/05/2018	0	Repair	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Brakes\BRAKE ADJ	adjust brakes drive only			11/05/2018	478833	Fault	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Elect\BREAKDOWN	Call Out			28/04/2018	478180	Repair	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Elect\BATTERY	Jump Start Truck & add radiator stop leak			28/04/2018	478180	Repair	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Elect\ELECT P&W	Test Starting System		Myrteford Auto Electrics	28/04/2018	478180	Repair	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Elect\BATTERY	Fit 2 x New Batteries		Myrtleford Auto Electrics	28/04/2018	478180	Repair	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Elect\TAIL LIGHT	check wiring to brake/reverse lights repair wires at tail light bar plug			25/04/2018	478150	Repair	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Elect\TAIL LIGHT	test circuit ok			25/04/2018	478150	Repair	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Elect\ELECT P&W	wiring from front of truck to rear tail light bar may still have fault			25/04/2018	478150	Repair	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Elect\BATTERY	put batteries on charge			25/04/2018	478150	Repair	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Brakes\BRAKE ADJ	adjust brakes on drive only			13/04/2018	477747	Fault	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Engine\HOUSEKEEP	check engine oil and coolant			13/04/2018	477747	Fault	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	DrivLine\DRV LN SER	check drive line and grease			13/04/2018	477747	Fault	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	DrivLine\DRV LN SER	check diff oil			13/04/2018	477747	Fault	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Elect\BATTERY	jump start at Jack Road			28/03/2018	427398	Repair	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Elect\BREAKDOWN	travel to and from site for Load16 breakdown			28/03/2018	427398	Repair	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Engine\ENG FAN	lock engine fan			23/03/2018	477278	Repair	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Engine\ENG FAN	remove fan and fit 2nd hand fan			23/03/2018	477278	Repair	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Engine\COOL LEAKS	check leaking coolant			10/03/2018		Fault	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Body\HOUSEKEEP	wash off hyd oil		ok for now	10/03/2018		Fault	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Engine\EXHAUST	Check exhaust leak		Driver to monitor	12/02/2018	476837	Fault	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Elect\BATTERY	truck won't start			10/02/2018	476781	Fault	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Brakes\BRAKE ADJ	adjust brakes			26/01/2018		Fault	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Engine\HOUSEKEEP	check oil and water check belt and retension			26/01/2018		Fault	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Engine\BELTS/TENS	JUMP START AT RINLATECH. check belt and retension			16/01/2018	476418	Fault	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Engine\HOUSEKEEP	check engine oil and coolant			23/12/2017	475941	Fault	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Body\HOUSEKEEP	check over			23/12/2017	475941	Fault	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Air Con\BRAKE ADJ	adjust brakes			01/12/2017	475593	Repair	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Engine\HOUSEKEEP	check fluids check oil and coolant			28/11/2017	475488	Repair	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Engine\HOUSEKEEP	start and check over			13/09/2017	475125	Repair	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Cooling\COOL LEAKS	fill radiator with stop leak			31/08/2017	474941	Fault	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Cooling\RADIATOR	fill radiator - overheating - unable to fill this morning as hoses frozen			31/08/2017	474941	Fault	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Elect\BATTERY	charge batteries			31/08/2017	474941	Fault	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Elect\HEAD LIGHT	LH headlight n/w			31/08/2017	474941	Fault	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Body\MOUNTS	L/hand air tank bolt missing			31/08/2017	474941	Fault	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Tyres\PRES CHECK	Job Added From Invoice			16/08/2017	0	Repair	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Engine\HOUSEKEEP	check engine oil/coolant			02/08/2017	474443	Fault	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			29/07/2017	474309	Repair	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS		29/07/2017	474309	Service	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Tyres\PRES CHECK	Job Added From Invoice			06/07/2017	0	Repair	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Tyres	Job Added From Invoice			07/06/2017	0	Repair	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Tyres	Job Added From Invoice			30/05/2017	0	Repair	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Tyres\PRES CHECK	Job Added From Invoice			30/05/2017	0	Repair	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice			30/05/2017	0	Repair	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice			30/05/2017	0	Repair	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Engine\FUEL TANK	drain fuel tank top up with Alpine mix			16/05/2017	473305	Repair	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Body\MOUNTS	repair RH fuel tank step			16/05/2017	473305	Repair	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Engine\HOUSEKEEP	check and top up engine oil and coolant			16/05/2017	473305	Repair	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Engine\FUEL TANK	clean fuel bowl strainer and bleed engine			09/05/2017	473295	Repair	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Elect\BATTERY	call out to jum start - flat batteries (MAE) tested batteries they were (ok) replace faulty master switck			09/05/2017	473295	Repair	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Engine\FUEL TANK	check fuel problem			09/05/2017	473295	Repair	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Tyres	Job Added From Invoice			29/04/2017	0	Repair	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Engine\HOUSEKEEP	check engine oil & coolant			28/04/2017	473241	Fault	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			05/04/2017	473246	Repair	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS	put stop leak in cooling system	05/04/2017	473246	Service	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Tyres\TP03	Job Added From Invoice			29/03/2017	0	Repair	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Engine\HOUSEKEEP	start up and check			25/03/2017	473052	Repair	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	DriCabRep\SEAT	air leak under drivers seat			17/02/2017	472374	Fault	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Cooling\RADIATOR	top up coolant			17/02/2017	472374	Fault	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	DriCabRep\AIR LEAK	air leak under driver's seat			11/02/2017	472169	Fault	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Engine\HOUSEKEEP	check oil & coolant			11/02/2017	472169	Fault	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Hydraulics\HOSES	fit hydraulic hose to cabin lift cylinder			01/02/2017	472168	Repair	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	DriCabRep\SEAT	fit air line hose to air valve in drivers seat			01/02/2017	472168	Repair	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Engine\HOUSEKEEP	start + run		Top up coolant	06/01/2017	47208	Repair	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Cooling\COOL LEAKS	Check for coolant leak		Complete	05/12/2016		Fault	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Tyres\TP10	Job Added From Invoice			30/11/2016	0	Repair	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Engine\COOL LEAKS	check coolant level			24/11/2016	472678	Repair	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection			29/10/2016	469723	Repair	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS		29/10/2016	469724	Service	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			29/10/2016	469724	Repair	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Engine\FUEL TANK	bleed & start engine			05/10/2016	46828	Repair	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Chassis\HOUSEKEEP	take truck back to stanley		reline steer brakes	05/10/2016	46828	Repair	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Brakes\BRK O/HAUL	replace lh & rh steer brake drums & seals also fit new brake linnings		road test	20/07/2016	467924	Repair	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Body\HOUSEKEEP	wash hyd oil off cab			15/07/2016	467918	Fault	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Engine\BELTS/TENS	Replace alternator belt		alt belt W/O 26642 pending to replace belt	15/07/2016	473246	Fault	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Engine\BELTS/TENS	Adjust alternator belt		Complete	13/07/2016	467000	Fault	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Cooling\RADIATOR	Top up Coolant		Complete	13/07/2016	467000	Fault	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Brakes\BRAKE ADJ	adjust rear brakes			28/06/2016	467705	Fault	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Cooling\RADIATOR	top up coolant			28/06/2016	467705	Fault	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Elect\ELECT P&W	fix broken wire at alternator for tacho. fix broken wire at alternator for tacko			28/06/2016	467705	Fault	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Engine\HOUSEKEEP	check oil + coolant			23/06/2016	467682	Repair	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Elect\HOUSEKEEP	check lights			23/06/2016	467682	Repair	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Brakes\BRAKE ADJ	adjust brakes			23/06/2016	467682	Repair	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Brakes\BRAKE ADJ	Adjust brakes		Complete Add radiator stop leak to cooling system	30/05/2016	466719	Fault	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Engine\COOL LEAKS	Top up coolant		Complete	30/05/2016	466719	Fault	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Engine\HOUSEKEEP	check over loader			14/05/2016	46621	Repair	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Elect\WORK LIGHT	replaced worklight bracket & remounted & repaired wiring			31/03/2016	466207	Fault	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Engine\FUEL TANK	prime fuel system			21/03/2016	466130	Fault	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER

LOAD16	Myrtleford - Workshop	Engine\HOUSEKEEP	check oil and coolant			21/03/2016	466130	Fault	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Elect\BATTERY	charge batteries check both fuel pick up lines braze pick up tubes			21/03/2016	466130	Fault	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Engine\FUEL TANK	top up fuel		Completed	12/02/2016	465690	Fault	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	DrCabElect\ELECT P&W	install new 24v horn		completed	29/01/2016	465688	Fault	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Engine\FILTERS	fit new air dryer filter element		completed	29/01/2016	465688	Fault	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	DrCabElect\INDICATORS	change blown dash globes		completed	29/01/2016	465688	Fault	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Engine\FUEL TANK	fit new fuel return line hoses & copper washers to banjo fittings		completed	29/01/2016	465688	Fault	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	DriCabRep\WIPERS	fit 2 x new wiper blades		completed	29/01/2016	465688	Fault	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Body\MOUNTS	repair LH air tank bracket repair crack in cross member bracket on LHS		completed	29/01/2016	465688	Fault	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Chassis\CROSS MBR	fit new bolts to cross member on LHS		completed	29/01/2016	465688	Fault	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Chassis\EXHAUST	repair holes in exhaust		completed	29/01/2016	465688	Fault	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Brakes\SLACK ADJ	Replace RHR slack adjuster			28/01/2016	467754	Repair	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Steering\TIE ROD	Replace cracked RH tie rod ball joint rubber boot		replaced drag link tie rod ball joint	28/01/2016	467754	Repair	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Susp\SHOCK ABS	Replace steer shockers			28/01/2016	467754	Repair	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Susp\SWAYBAR	Replace worn bushes on link stabiliser bar			28/01/2016	467754	Repair	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Engine\FILTERS	supply oil fuil & air drier filters			28/01/2016		Repair	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	DrCabElect\INST/GAUGE	repair speedo - not showing distance travelled			27/01/2016	465689	Fault	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS		27/01/2016	465688	Service	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			27/01/2016	465688	Repair	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	DrCabElect\INST/GAUGE	remove & repair speedo			27/01/2016	465689	Repair	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Engine\FILTERS	check fuel filters & fittings			25/01/2016	465688	Fault	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Elect\BATTERY	charge batteries check furel filter lines & fittings			25/01/2016	465688	Fault	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Engine\FUEL TANK	fit check valve to injection pump		completed	22/01/2016		Fault	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	DriCabRep\MOUNTS	cab mounts		completed	15/01/2016		Repair	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Engine\HOUSEKEEP	fit new fuel lift pump		completed	14/01/2016	465686	Fault	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Engine\FUEL TANK	replace fuel bleed off hoses		completed	14/01/2016	465686	Fault	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Engine\FILTERS	1x lift pump			14/01/2016		Repair	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Chassis\CROSS MBR	replace front crossmember bolts		completed	13/01/2016	465688	Fault	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Elect\RADIO	remove trunk phone		completed	13/01/2016	465688	Fault	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Body\HOUSEKEEP	inspect fuel hose		completed	13/01/2016	465688	Fault	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Engine\FUEL TANK	tctc clean glass bowl + fuel filter on lift pump cut off split return fuel line + reattach + prime		completed	14/11/2015		Repair	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Engine\FUEL TANK	road test		completed	28/10/2015	465688	Fault	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER
LOAD16	Myrtleford - Workshop	Brakes\BRK O/HAUL	replace rhr drive brake booster		completed	26/09/2015	465688	Fault	Completed	Greenfreight Logging Vic	LOADM/Benz	Myrtleford	MLR	ERP578	Myrtleford Workshop	LOADER