EquipmentName	Workshop	CodeAndSubCode	Description	Schedule	CompletionComments	DateDone	HourDone	Worktype	Workstate	EquipmentOwner	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
P15	Wodonga - Workshop	DrCabElect\ELECT P&W	no light in cab "still!"			22/03/2024		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Wodonga Workshop	PRENTICE
P15	Albury - Workshop	Engine\BATTERY	REPLACED BATTERY. MADE NEW LEADS.			05/04/2023		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Albury Workshop	PRENTICE
P15	Wodonga - Workshop	Body\CONSUMABLE	Checkover. Check Oils & Fuel. Inspect Hoses			08/11/2022		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Wodonga Workshop	PRENTICE
			Dissmantle grapple cylinder, machine new rod, machine new													
			rod eye, machine barrel and reweld up. Assemble all together.													
P15	Myrtleford - Workshop	Hydraulics\RAM	85/40 chb			02/09/2022		Repair	Completed							
P15	Albury - Workshop	Hydraulics\HOSES	supply haydraulic fittings for prentice			08/06/2022	21381	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Albury Workshop	PRENTICE
P15	Wodonga - Workshop	Engine\OIL LEAK	DIAGNOSED OIL LEAK AT LOOSE FUEL PUMP. REPLACED MISSING BOLT AND TIGHTENED ALL.DE-GREASED AND WASHED. TESTED.			08/02/2022	26868	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Wodonga Workshop	PRENTICE
			full grease and fluid check on loader													
			replace/broken grease nipple													
P15	Rosewood - Workshop	Chassis\HOUSEKEEP	remove main grab swing pin and unblock grease galley. Refit and grease thoroughly			12/11/2021	27622	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Rosewood Workshop	PRENTICE
			fit reconditioned grab swivel													
			re-route hoses to fit more ergonomically													
P15	Rosewood - Workshop	Hydraulics\HYD LEAKS	test run and check for leaks. All good			02/11/2021	26649	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Rosewood Workshop	PRENTICE
			PRENTICE LOADER PLANT # 15													
			Service call to Rosewood w/shop													
			Supply2 hoses as per samples													
P15	Rosewood - Workshop	Hydraulics\HOSES	Wrap in spiral guard			19/09/2021		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Rosewood Workshop	PRENTICE
			check over													
P15	Rosewood - Workshop	DrCabElect\VNST/GAUGE	reolace aauge illumination alobes			14/09/2021	26615	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Rosewood Workshop	PRENTICE
P15	Rosewood - Workshop	DrCabElect\ELECT P&W	repair poor power supply to interior light. Could do with proper repair new radio to be fitted asap			14/09/2021	26615	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Rosewood Workshop	PRENTICE
			called out to Shalley Victoria, blown hose at main boom pivot. Packed ute and some hoses.													
			Removed old blown hose, has been modified during recent repairs (elsewhere) and no longer used a shrouded hose.													
			Removed hose and had one made up (200mm longer as that was why it failed) and took home with oil to fit Wed.													
P15	Rosewood - Workshop	Hydraulics\BREAKDOWN	Returned to loader Wednesday and fitted. Topped up oil and checked. All good			31/08/2021	26521	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Rosewood Workshop	PRENTICE
P15	Rosewood - Workshop	Engine\HOUSEKEEP	check over prior to shift			31/08/2021	26574	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Rosewood Workshop	PRENTICE
					fit new interior light											
P15	Rosewood - Workshop	DrCabElect\ELECT P&W	no light in cab		plug cab for back in and test, all good	24/08/2021	26550	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Rosewood Workshop	PRENTICE
P15	Rosewood - Workshop	VehService\BS	B Service	VehService\BS		11/08/2021	25499	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Rosewood Workshop	PRENTICE
P15	Rosewood - Workshop	Engine\HOUSEKEEP	check over for use			06/08/2021	26480	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Rosewood Workshop	PRENTICE
P15	Rosewood - Workshop	Hydraulics\DAMAGE	reolace grab oivot oin bolts			27/07/2021	26462	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Rosewood Workshop	PRENTICE
P15	Rosewood - Workshop	Engine\HOUSEKEEP	check over			23/07/2021	26462	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Rosewood Workshop	PRENTICE
			diagnose and disassemble grab rotary union													
			drive to Tumut for parts left by Jonesy (were wrong parts)													
			reassemble, replace hoses													
P15	Rosewood - Workshop	Hydraulics\HYD LEAKS	thorough clean and test. All good			07/07/2021	26473	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Rosewood Workshop	PRENTICE
P15	Rosewood - Workshop	Elect\WORK LIGHT	replace work light top RHS of windscreen guard		replace broken work light above windscreen of loader. Modify mount to suit	25/06/2021	26386	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Rosewood Workshop	PRENTICE
P15	Rosewood - Workshop	VehService\BS	service loader as per schedule	VehService\BS		18/06/2021	26334	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Rosewood Workshop	PRENTICE
P15	Myrtleford - Workshop	Hydraulics\BREAKDOWN	call out to Carabost		called out to Carrabost. sort out erab hoses with Rowan from Hantrite(sublet reoair) and check cle	17/06/2021	26315	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Myrtleford Workshop	PRENTICE
P15	Myrtleford - Workshop	Hydraulics\HOSES	reolace hvd hoses and suooly soare hvd hose			17/06/2021	26315	Reoair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Myrtleford Workshop	PRENTICE
P15	Rosewood - Workshop	Chassis\DAMAGE	fabricate and weld on new grab tip, old one broken off			16/06/2021	26301	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Rosewood Workshop	PRENTICE
P15	Rosewood - Workshop	Hydraulics\HOSES	replaced 2 damaged grab hoses, hoses have been mis-aligned and made too long, will need sorting out properly ASAP			12/06/2021	26302	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Rosewood Workshop	PRENTICE
			diagnose oil leak, found fuel pump missing a bolt and 2 nuts loose													
P15	Rosewood - Workshop	Engine\COMPRESSOR	reolace bolt			08/06/2021	26247	Reoair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Rosewood Workshop	PRENTICE
			manufacture special tool to get to rear most nut													
P15	Rosewood - Workshop	Engine\HOUSEKEEP	tighten			08/06/2021	26247	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Rosewood Workshop	PRENTICE
			clean area and test run. All good													
P15	Rosewood - Workshop	Engine\HOUSEKEEP	check all fluid levels			08/06/2021	26247	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Rosewood Workshop	PRENTICE
P15	Rosewood - Workshop	Hydraulics\RAM	replace outer grab ram only put on 2 days ago			04/06/2021	26247	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Rosewood Workshop	PRENTICE
P15	Myrtleford - Workshop	Hydraulics\HOSES	sublet hose replacement to be done		refer to 145211	04/06/2021	26185	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Myrtleford Workshop	PRENTICE
			diagnose grab leak, coming from flange on cylinder													
P15	Rosewood - Workshop	Hydraulics\RAM	fitted yesterday			03/06/2021	26218	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Rosewood Workshop	PRENTICE
P15	Rosewood - Workshop	Hydraulics\RAM	organised new parts from Tumut store, will fit asap			03/06/2021	26218	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Rosewood Workshop	PRENTICE
			called out to Bendemere, broken grab ram, leaked hydraulic oil. Unable to fold up.													
			Made temporary repairs to get back to workshop													
			replaced ram at workshop and topped up fluid													
P15	Rosewood - Workshop	Hydraulics\HYD LEAKS	cleaned up and tested. All good			02/06/2021	26215	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Rosewood Workshop	PRENTICE
P15	Rosewood - Workshop	Hydraulics\HOSES	diagnose and repair leak at grab			29/05/2021	26185	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Rosewood Workshop	PRENTICE
P15	Rosewood - Workshop	Hydraulics\HOSES	sublet hose replacement to be done			29/05/2021	26185	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Rosewood Workshop	PRENTICE
			replace faulty LH outer boom light and wire up													
P15	Rosewood - Workshop	Elect\WORK LIGHT	test and adjust. All good			28/05/2021		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Rosewood Workshop	PRENTICE
			replace UHF mic													
P15	Rosewood - Workshop	DrCabElect\RADIO	mount UHF hanger and tidy up wiring			25/05/2021	26128	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Rosewood Workshop	PRENTICE
P15	Rosewood - Workshop	DrCabElect\VNST/GAUGE	fit missing grab bar rub			25/05/2021	26128	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Rosewood Workshop	PRENTICE
P15	Wodonga - Workshop	Engine\OIL LEAK	oil leak near fuel leak			15/05/2021		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Wodonga Workshop	PRENTICE
P15	Wodonga - Workshop	Engine\OIL LEAK	oil leak near fuel leak			15/05/2021		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Wodonga Workshop	PRENTICE
					remove tripple pump from P29											
P15	Wodonga - Workshop	Hydraulics\HYD LEAKS	failed tripple pump and hydraulic leaks		Rapid replaced hoses	15/05/2021		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Wodonga Workshop	PRENTICE
P15	Myrtleford - Workshop	DrCabElect\VNST/GAUGE	needs interior light			14/05/2021		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Myrtleford Workshop	PRENTICE
P15	Rosewood - Workshop	Chassis\DAMAGE	called out to loader, RH main beam bottom pin broken			12/05/2021	26090	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Rosewood Workshop	PRENTICE
			plumb hoses to disable broken side and strap ram to boom. Pack up and get to Rosewood													
P15	Rosewood - Workshop	Hydraulics\HOSES	clean up oil on loader for repair			12/05/2021	26090	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Rosewood Workshop	PRENTICE
			call scan logging and book loader in for repair													
			Toppo took to scan logging Tumut													
P15	Rosewood - Workshop	Chassis\DAMAGE	make up and fit new bottom main lift pin			12/05/2021	26090	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Rosewood Workshop	PRENTICE
P15	Rosewood - Workshop	Hydraulics\HYD LEAKS	diagnose and repair leak from steel pipe at hydraulic servo block (broken o-ring)			11/05/2021	26087	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Rosewood Workshop	PRENTICE
			top up oil													
P15	Rosewood - Workshop	Hydraulics\OIL/FILTER	clean up spilt oil and test. All good			11/05/2021	26087	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Rosewood Workshop	PRENTICE
P15	Rosewood - Workshop	Hydraulics\HOSES	change leaking grab hose		replace short grab hose to rotator	07/05/2021	26064	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Rosewood Workshop	PRENTICE
P15	Rosewood - Workshop	DrCabElect\VNST/GAUGE	needs interior light			07/05/2021	26064	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Rosewood Workshop	PRENTICE
P15	Rosewood - Workshop	Hydraulics\VALVES	slew not yawing to the right properly		replace worn slew pedal pin and set to even speed. Test	07/05/2021	26064	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Rosewood Workshop	PRENTICE
			Inspect oil leak from Bell housing inspection hole.													
			Suspected failed seal on hydraulic 3 way pump.													
P15	Wodonga - Workshop	DrivLine\OIL LEAK	Taken to rapid for repair.			27/04/2021	260659	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Wodonga Workshop	PRENTICE
P15	Wodonga - Workshop	Elect\START MOTR	hard to start		Change Battery.	12/04/2021	25968.1	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Wodonga Workshop	PRENTICE
					Load vehicle and travel to Twin City Truck Centre.											
					Remove and replace the fuel pump (supplied by customer)											
					Found equipment batteries to be flat.											
					Jump start engine and test run, OK.											
					Inspect engine, OK.											
					Return Unit to service.											
P15	Rosewood - Workshop	Engine\FUEL TANK	fuel leak is bad it "unsafe: on deck page 122889		Return oriainal oump to customer.	09/04/2021		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Rosewood Workshop	PRENTICE
P15	Rosewood - Workshop	Engine\FUEL TANK	fuel leak under engine			09/04/2021		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Rosewood Workshop	PRENTICE
P15	Rosewood - Workshop	Engine\HOUSEKEEP	check over pre-shift			11/03/2021	25911	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Rosewood Workshop	PRENTICE
					call out to bush											
P15	Rosewood - Workshop	Chassis\HOUSEKEEP	bolt missing on grab		fit new bolt to arab oin	09/03/2021	25904	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Rosewood Workshop	PRENTICE
P15	Rosewood - Workshop	Engine\EXHAUST	fuel leak under engine			06/03/2021		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Rosewood Workshop	PRENTICE
P15	Rosewood - Workshop	Engine\OIL LEAK	oil leak near fuel leak			06/03/2021		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Rosewood Workshop	PRENTICE
P15	Rosewood - Workshop	DriCabRep\HOUSEKEEP	arm rest needs fixing			06/03/2021		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Rosewood Workshop	PRENTICE
P15	Rosewood - Workshop	DriCabRep\WINDOW REG	window needs fixing			06/03/2021		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Rosewood Workshop	PRENTICE
P15	Rosewood - Workshop	DrCabElect\VNST/GAUGE	hour meter not working			06/03/2021		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Rosewood Workshop	PRENTICE
					STARTING ISSUES											
					DRIVER REPORTS PRENTICE IS HARD TO START.											
					02/03/2021											
					Performed quick inspection and monitored starting issue											
					Blew excessively but wouldn't crank over for 5-10 secs then would run fine.											
					Inspected and found fuel leak under engine											
					Moved to shed – utilised ladder and removed engine cover as required											
					Monitored fuel pump, found it leaking from body. Found all fuel pump bolts are tight											
					Obtained photo – Refit cover as required											
P15	Tumut - Workshop	Engine\FUEL TANK	fuel leak under		Sent photo to Customer (Gordon) and advised.	06/03/2021		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Tumut Workshop	PRENTICE
P15	Tumut - Workshop	Engine\OIL LEAK	oil leak near fuel leak			06/03/2021		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Tumut Workshop	PRENTICE
P15	Tumut - Workshop	DriCabRep\SEAT	arm rest needs fixing		arm rest air clip missing fit new one	06/03/2021		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Tumut Workshop	PRENTICE
P15	Tumut - Workshop	DriCabReo\DOOR LOCK	window needs fixinz		window slidine oaen out screw in to stoo	06/03/2021		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Tumut Workshop	PRENTICE
P15	Tumut - Workshop	DrCabElect\VNST/GAUGE	hour meter not workine		rina TAE book in to aet hour meter looked at Monday 1om	06/03/2021		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Tumut Workshop	PRENTICE
P15	Rosewood - Workshop	Engine\HOUSEKEEP	check over			24/02/2021	25904	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Rosewood Workshop	PRENTICE
			called out to Tumut 3am													
P15	Rosewood - Workshop	Elect\BREAKDOWN	make uo soare erab ram hoses			20/02/2021	25904	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Rosewood Workshop	PRENTICE
			loader would not start. Winding over but not firing													
			12.6 volt at battery, 12.1 at fuel shut off solenoid													
			hooked up jump leads, wound over, "shocked" fuel solenoid and it started													
			alternator not changing													
			cleaned up around fuel pump/pilot pump areas													
P15	Rosewood - Workshop	DrivLine\ALT2 DR	sent back to TAE			20/02/2021	25904	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Rosewood Workshop	PRENTICE
P15	Tumut - Workshop	Workshop\MOVE ASSET	return to Tumut			17/02/2021	28857	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Tumut Workshop	PRENTICE
P15	Tumut - Workshop	Workshop\MOVE ASSET	take to Cummins Wodonga pump injection swap			17/02/2021	28857	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		Tumut Workshop	PRENTICE
P15	Albury - Workshop	Workshop\MOVE ASSET	picked up driver from cummins			17/02/2021		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		CUMMINS SOUTH PACIFIC P/L - 4	PRENTICE
P15	Albury - Workshop	Workshop\MOVE ASSET	dropped of driver at Cummins			17/02/2021		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR		CUMMINS SOUTH PACIFIC P/L - 4	PRENTICE

						Cummins													
						Mechanical engine No ECM													
						Inspect engine for source of fuel leak													
						Find fuel pump leaking from hydraulic advance inner													
						cover plate													
						Remove pilot hydraulic pump for access													
						Hose cracked during removal due to age (Hard/Brittle)													
						Find oil supply hose to accessory adaptor Hard Brittle													
						Remove fuel pump													
						As per customer request													
						Fit used unit supplied by customer													
						Inform customer of damage to hoses													
						Customer organized hose fitter to repair hoses													
						Assist hose fitter													
						Bleed fuel system run engine													
						Steam clean													
						Run engine check for leaks													
						All ok													
P15	Albury - Workshop	Hydraulics\HYD LEAKS	assisted enzed replacing pilot hydraulic lines			Return machine to service	17/02/2021		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	CUMMINS SOUTH PACIFIC P/L - 4	PRENTICE			
P15	Myrtleford - Workshop	Engine\BREAKDOWN	fit injector pump supplied by Greenfreight				16/02/2021	25904	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE			
P15	Myrtleford - Workshop	Hydraulics\HOSES	replace hyd hoses				16/02/2021	25904	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE			
P15	Myrtleford - Workshop	Engine\BREAKDOWN	remove fuel pump from spare engine to be fitted to P15 by Cummins Wodonga				16/02/2021	25904	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE			
			diagnose fuel leak, needs new fuel pump																
P15	Rosewood - Workshop	Engine\BREAKDOWN	replaced by Cummins				16/02/2021	25904	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
P15	Rosewood - Workshop	Elect\BREAKDOWN	remove (seized on) pulley from an old alternator to use on an alternator in stock, different size so not usable				13/02/2021	25899	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
			fuel pump leaking																
			get o-rings from Tumut hydraulics																
P15	Tumut - Workshop	Engine\BREAKDOWN	fit orings				10/02/2021		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Tumut Workshop	PRENTICE			
			call out to bush fuel pump leaking																
			clean up find leak																
			photo's to Gordon M																
P15	Tumut - Workshop	Engine\BREAKDOWN	travel to Rosewood				09/02/2021	25583	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Tumut Workshop	PRENTICE			
P15	Rosewood - Workshop	Engine\HOUSEKEEP	check over				06/02/2021	25849	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
P15	Rosewood - Workshop	Engine\HOUSEKEEP	check over				29/01/2021		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
P15	Rosewood - Workshop	DrCabElect\ELECT P&W	check and order new interior light			TUMUT AUTO ELECTRICS 2-2-21	29/01/2021		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
P15	Rosewood - Workshop	Chassis\HOUSEKEEP	grease loader in workshop				29/01/2021	25841	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
			assist Toppo with alternator replacement and wiring slightly different alternator																
P15	Rosewood - Workshop	Elect\ALT2 DR	fit new alt				28/01/2021	25825	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
P15	Rosewood - Workshop	VehService\BS	B Service	VehService\BS			28/01/2021	4411	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
						found alternator not charging													
						fitted 2nd hand alternator from Albury as a stop- gap until proper one arrives													
P15	Rosewood - Workshop	Elect\ALT2 DR	no power to lights/uhf			alternators different, modify wiring to get it to charge	14/01/2021	25781	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
P15	Rosewood - Workshop	DrCabElect\VNST/GAUGE	diagnose in radio UHF, lights stopped, then engine not start after shutting down				14/01/2021	25781	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
			tried to source alternator																
P15	Albury - Workshop	Elect\ALT2 DR	removed alternator from P10 and sent with operator to Rosewood				14/01/2021		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE			
P15	Rosewood - Workshop	DrCabElect\ELECT P&W	no power to lights/uhf				14/01/2021	25802	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
P15	Rosewood - Workshop	Hydraulics\OIL/FILTER	check and top up hydraulic fluid				12/01/2021	25781	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
P15	Rosewood - Workshop	Engine\HOUSEKEEP	check oil and coolant				12/01/2021	25781	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
P15	Rosewood - Workshop	Engine\FILTERS	clean out air filter pre-cleaner				12/01/2021	25781	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
P15	Rosewood - Workshop	Hydraulics\OIL/FILTER	need hydraulic oil				05/01/2021	25798	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
P15	Rosewood - Workshop	DrivLine\ALT	found alternator recently fitted with loose mount bolts, pulley nut loose and slipping on alternator shaft, need new alternator				12/12/2020	25904	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
P15	Rosewood - Workshop	Engine\OIL LEAK	bad oil leak at front of engine				12/12/2020	25904	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
P15	Rosewood - Workshop	VehService\BS	B Service	VehService\BS			12/12/2020	25904	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
			dry seat out as best I could with compressed air																
P15	Rosewood - Workshop	DriCabRep\HOUSEKEEP	cut a piece off broom handle to keep window closed				24/11/2020	25689	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
P15	Rosewood - Workshop	Elect\BATTERY	Jumo start flat battery			called out to Greenhills battery flat. Jumo started	24/11/2020	25689	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
			replace crack in chassis of loader																
P15	Tumut - Workshop	Chassis\CHAS CRACK	crack on deck getting bigger becoming unsafe				21/11/2020		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Tumut Workshop	PRENTICE			
P15	Tumut - Workshop	Chassis\DAMAGE	back leg left + right broken where pin is frame on				21/11/2020		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Tumut Workshop	PRENTICE			
P15	Tumut - Workshop	Hydraulics\RAM	repair rear lee ram				21/11/2020		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Tumut Workshop	PRENTICE			
P15	Rosewood - Workshop	VehService\BS	B Service TU10390	VehService\BS			21/11/2020	25082	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
P15	Rosewood - Workshop	Hydraulics\DAMAGE	atttempted replacement of grab ram. Was welded in unable to move even after cutting welds out.				17/11/2020	25627	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
P15	Rosewood - Workshop	Hydraulics\RAM	sent to s-cam logging for sublet repairs				17/11/2020	25627	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
P15	Rosewood - Workshop	Hydraulics\RAM	log grab ram leaking oil				14/11/2020		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
P15	Rosewood - Workshop	Chassis\DAMAGE	pin in boom needs bolt in it				10/11/2020	25587	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
P15	Rosewood - Workshop	Chassis\HYDRAULICS	refit grab pin and fit locking plate bolt after extracting broken bolt				07/11/2020	25577	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
P15	Rosewood - Workshop	Elect\WORK LIGHT	meet driver at Black boots and replace both left boom lights				05/11/2020		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
P15	Rosewood - Workshop	Elect\WORK LIGHT	light fixed x2				05/11/2020		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
P15	Wodonga - Workshop	Chassis\HOUSEKEEP	loader claw kinpin half fell out. Re-align back in and bolt back together				22/10/2020		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Wodonga Workshop	PRENTICE			
P15	Wodonga - Workshop	Workshop\MOVE ASSET	test operation and clean workshop				22/10/2020		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Wodonga Workshop	PRENTICE			
P15	Albury - Workshop	Body\HOSES	MAKE HOSES AS PER SAMPLES				01/10/2020		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE			
P15	Albury - Workshop	Hydraulics\HOSES	reolaced blown hydraulic hoses flv boom to araaole				30/09/2020		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE			
P15	Albury - Workshop	Workshop\MOVE ASSET	travelled to and from Wodonga depot				30/09/2020		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE			
P15	Albury - Workshop	Workshop\MOVE ASSET	travel over to wodonga yard				01/09/2020	25308	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE			
P15	Albury - Workshop	Hydraulics\HOUSEKEEP	checked loader controls - adjusted handpieces				01/09/2020	25308	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE			
P15	Wodonga - Workshop	Engine\BELTS/TENS	Replace Dampener			Couldn't fault	19/08/2020	25220	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Wodonga Workshop	PRENTICE			
P15	Wodonga - Workshop	Air Con\HEATER	Heater fan noisy				19/08/2020	25220	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Wodonga Workshop	PRENTICE			
P15	Wodonga - Workshop	Engine\MOUNTS	Engine mounts worn out			inspected - ok	19/08/2020	25220	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Wodonga Workshop	PRENTICE			
P15	Wodonga - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS			19/08/2020	25220	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Wodonga Workshop	PRENTICE			
P15	Albury - Workshop	Workshop\MOVE ASSET	travel to and from Wodonga Depot				14/08/2020		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE			
			inspect fan issue																
			replaced burnt wiring in switch panel																
P15	Albury - Workshop	Elect\DAMAGE	organised fan replacement				14/08/2020		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE			
P15	Wodonga - Workshop	DriCabRep\AIR LEAK	air leak under cab				06/08/2020		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Wodonga Workshop	PRENTICE			
P15	Wodonga - Workshop	Hydraulics\DAMAGE	RHS joy stick broken handle				06/08/2020		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Wodonga Workshop	PRENTICE			
P15	Wodonga - Workshop	DriCabRep\HYD LEAKS	RHS joystick leaking oil on hands and clothes cancer hazard				06/08/2020		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Wodonga Workshop	PRENTICE			
P15	Wodonga - Workshop	Air Con\AIR CON	Air Conditioning				06/08/2020		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Wodonga Workshop	PRENTICE			
P15	Wodonga - Workshop	Air Con\AIR CON	Air Conditioning				06/08/2020		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Wodonga Workshop	PRENTICE			
P15	Wodonga - Workshop	Elect\BATTERY	removed and reolaced batterv				05/08/2020		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Wodonga Workshop	PRENTICE			
P15	Wodonga - Workshop	DriCabReo\DOOR LOCK	Reoair loader door				30/07/2020		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Wodonga Workshop	PRENTICE			
P15	Wodonga - Workshop	DriCabRep\DOOR LOCK	door latch needs repairing				30/07/2020		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Wodonga Workshop	PRENTICE			
P15	Albury - Workshop	Hydraulics\RAM	drive to shelley camp to repair hydrolic leak on grappling ram				23/05/2020		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE			
P15	Myrtleford - Workshop	Engine\HOUSEKEEP	start and run truck and prentice				01/05/2020	25022	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE			
P15	Myrtleford - Workshop	Body\REFLECTORS	fit reflecting tape to steps				22/02/2020		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE			
P15	Myrtleford - Workshop	Chassis\GEARBOX	grease loader				20/02/2020	25022	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE			
P15	Myrtleford - Workshop	Body\PANELS	fit vent to rear engine bay door and paint				06/02/2020	25021	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE			
			B Service As Per Attached Checklist																
P15	Myrtleford - Workshop	VehService\BS	& Hydraulic Service	VehService\BS			05/02/2020	25021	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE			
P15	Myrtleford - Workshop	DriCabRep\SEAT	Repair & recoil drivers seat & arm rests			refit hold down strap	05/02/2020	25022	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE			
						need's aerial													
						repaired wiring													
P15	Myrtleford - Workshop	DrCabElect\PHONE	Repair trunk phone			(tested) truck phone is faulty	05/02/2020	25022	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE			
P15	Myrtleford - Workshop	DrCabElect\RADIO	UHF speaker needs mounting properly				23/01/2020	25021	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE			
P15	Myrtleford - Workshop	DrCabElect\PHONE	satelite trunk phone (test) - needs aerial				23/01/2020	25021	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE			
P15	Myrtleford - Workshop	DrCabElect\RADIO	UHF aerial wiring and mount need replacing				23/01/2020	25021	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE			
P15	Myrtleford - Workshop	Body\HOUSEKEEP	inspect loader				23/01/2020	25021	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE			
P15	Myrtleford - Workshop	Hydraulics\RAM	RHF leg creeping down/by passing				23/01/2020	25021	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE			
P15	Wodonga - Workshop	Elect\TAIL LIGHT	No new lights				21/01/2020	25022	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE			
P15	Wodonga - Workshop	DrCabElect\RADIO	UHF hand piece needs holder. UHF needs speaker hard to hear when loading			made brackets to mount handpiece	21/01/2020	25022	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE			
						heater fan in prentice u/s needs replacing													
P15	Wodonga - Workshop	Elect\ELECT P&W	Demister pseed control not working			replace heater fan	21/01/2020	25022	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE			
P15	Wodonga - Workshop	Steering\HUBCAP	bad vibration in steering wheel 80/9016			steer tyres replaced	21/01/2020	25022	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE			
P15	Wodonga - Workshop	DriCabReo\AIR LEAK	air leak under cab				21/01/2020	25022	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE			
P15	Wodonga - Workshop	Body\MIRRORS	RHS mirrors broken				21/01/2020	25022	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE			
						wipers working fit 2nd hand washer jets													
P15	Wodonga - Workshop	DriCabRep\WIPERS	No window wipers. No window wipes			fit washer bottle to bracket	21/01/2020	25022	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE			
P15	Wodonga - Workshop	DrivLine\GEARBOX	Hard to get into gear			tested ok	21/01/2020	25022	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE			
						cleaned cab out													
P15	Wodonga - Workshop	Body\DAMAGE	Cab need clearing out, stuff			cleaned windows	21/01/2020	25022	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE			
P15	Wodonga - Workshop	DrCabElect\AP	Everywhere, MTData not working			not fitted	21/01/2020	25022	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE			
P15	Wodonga - Workshop	Engine\FUEL TANK	needs fuel cap				21/01/2020	25022	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE			
			Heater blowing cold air																
P15	Wodonga - Workshop	Air Con\HEATER	needs new UHF hand piece and removed somewhere				21/01/2020	25022	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE			
P15	Wodonga - Workshop	DrivLine\AIR LEAK	Bed air leak when putting clutch in				21/01/2020	25022	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE			
P15	Wodonga - Workshop	Body\MIRRORS	Broken RHS mirrors				21/01/2020	25022	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE			
						fit 2nd hand washers jets													
P15	Wodonga - Workshop	DriCabRep\WIPERS	No wipers			wipers working	21/01/2020	25022	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE			
P15	Wodonga - Workshop	DrCabElect\HEATER	No heater			heater in L15	21/01/2020	25022	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE			
P15	Wodonga - Workshop	Steering\STEER UNI	Steering needs checking				21/01/2020	25022	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE			
P15	Wodonga - Workshop	DrivLine\GEARBOX	Gear box needs look & hard to get into gear				21/01/2020	25022	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE			
P15	Wodonga - Workshop	Tyres\DRV TYRES	LHS drive tyre half				21/01/2020	25022	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE			
P15	Wodonga - Workshop	Hydraulics\OIL LEAK	massive oil leak RH servo				21/01/2020	25022	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE			
P15	Wodonga - Workshop	Hydraulics\VALVES	hydraulic very slow when hot			checked all pressures all correct	21/01/2020	25022	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE			
P15	Wodonga - Workshop	Cooling\RADIATOR	radiator replace				21/01/2020	25022	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE			
P15	Wodonga - Workshop	DrivLine\HEAD LIGHT	side light out				21/01/2020	25022	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE			
P15	Wodonga - Workshop	DriCabRep\WINDSCREEN	front windscreen				21/01/2020	25022	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE			
P15	Wodonga - Workshop	DriCabRep\HOUSEKEEP	roof lining held up by sticks			removed old liner and cleaned	21/01/2020	25022	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE			
P15	Wodonga - Workshop	DriCabRep\ELECT P&W	cd player needs fixing			works fine	21/01/2020	25022	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE			

						replaced door seal											
						adjusted door latch and striker											
P15	Wodonga - Workshop	DriCabRep\DOOR LOCK	door needs adjusting			welded crack in door	21/01/2020	25022	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
			remove old scale unit - wiring													
P15	Wodonga - Workshop	Elect\ELECT P&W	boom lights			boom lights	21/01/2020	25022	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P15	Wodonga - Workshop	Body\AIR LEAK	leaking rear main seal			checked ok	21/01/2020	25022	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P15	Wodonga - Workshop	Body\MOUNTS	needs grease gun mount for winder			done	21/01/2020	25022	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P15	Wodonga - Workshop	Air Con\AIR CON	cab fan			ok	21/01/2020	25022	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P15	Wodonga - Workshop	Body\DAMAGE	outer boom creeping down				21/01/2020	25022	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P15	Wodonga - Workshop	DriCabReo\RADIO	needs new UHF and extension speaker			done	21/01/2020	25022	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
			RHS joystick leaking bad													
P15	Wodonga - Workshop	DrivLine\CLUTCH	LHS lovstick sticking				21/01/2020	25022	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P15	Wodonga - Workshop	DriCabReo\WINDSCREEN	cracked windscreen				21/01/2020	25022	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P15	Wodonga - Workshop	DriCabReo\WINDSCREEN	front windscreen crack			ok	21/01/2020	25022	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P15	Wodonga - Workshop	DrCabElect\RADIO	needs new base for UHF			replaced wiring and aerial mount	21/01/2020	25022	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P15	Wodonga - Workshop	Engine\OIL LEAK	RH servo oil leak				21/01/2020	25022	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P15	Wodonga - Workshop	Engine\FAULT CODE	eng sometimes will not turn off with key				21/01/2020	25022	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P15	Wodonga - Workshop	Engine\HOUSEKEEP	no grease gun			made grease gun holder	21/01/2020	25022	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P15	Wodonga - Workshop	Engine\FAULT CODE	loader very slow slew up hill			checked slewer pressure - set at 2300psi	21/01/2020	25022	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P15	Wodonga - Workshop	Hydraulics\DAMAGE	RHS joy stick broken handle				21/01/2020	25022	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P15	Wodonga - Workshop	DriCabRep\WYD LEAKS	RHS joystick leaking oil on hands and clothes cancer hazard			tested no leaks waiting on rubber boots	21/01/2020	25022	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P15	Wodonga - Workshop	Hydraulics\RAM	no pressure in grab			set pressure to 2200psi	21/01/2020	25022	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
						tested pressure at 2300psi										
P15	Wodonga - Workshop	Hydraulics\MOTOR	slew very weak			tried to adjust to 2400psi but wouldn't	21/01/2020	25022	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P15	Wodonga - Workshop	Hydraulics\HYD LEAKS	right hand joy stick leaking				21/01/2020	25022	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P15	Wodonga - Workshop	DriCabRep\WINDSCREEN	needs new top window and front windscreen R7861. needs new top window and front windscreen			removed perspec window to be made	21/01/2020	25022	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P15	Wodonga - Workshop	Engine\OIL LEAK	RH servo oil leak			not leaking ok	21/01/2020	25022	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P15	Wodonga - Workshop	Engine\FAULT CODE	engine sometimes will not turn off with key			double	21/01/2020	25022	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P15	Wodonga - Workshop	Body\DAMAGE	no aresse aun			double up	21/01/2020	25022	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P15	Wodonga - Workshop	DriCabReo\DAMAGE	fix roof linine IT7828\ fix roof linine				21/01/2020	25022	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P15	Wodonga - Workshop	Air Con\AIR CON	new cab fan missing blade			replaced cab fan, made new (ordered) bracket for fan and wired in	21/01/2020	25022	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P15	Wodonga - Workshop	Body\DAMAGE	repair as per RR116859				21/01/2020	25022	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P15	Wodonga - Workshop	Cooling\COOL LEAKS	coolant leak			coolant in L1S	21/01/2020	25022	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P15	Wodonga - Workshop	DrCabElect\RADIO	no range with am/fm radio				21/01/2020	25022	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P15	Wodonga - Workshop	DrCabElect\RADIO	needs new hand mic for UHF				21/01/2020	25022	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P15	Wodonga - Workshop	Air Con\HEATER	heater/aircon fan noise			double up	21/01/2020	25022	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P15	Wodonga - Workshop	Elect\WORK LIGHT	LH work light inder crairne not working				21/01/2020	25022	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P15	Wodonga - Workshop	Elect\TRL LIGHTS	reverse light not working				21/01/2020	25022	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P15	Wodonga - Workshop	Body\TRL LEGS	grease nipple frm leg broken replaced				21/01/2020	25022	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P15	Wodonga - Workshop	Hydraulics\RAM	outer boom creeping down			fit outer boom ram seals	21/01/2020	25022	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P15	Wodonga - Workshop	Air Con\AIR CON	a/c/heater fan verv noisv			fan needs reolacine	21/01/2020	25022	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P15	Wodonaa - Workshop	Air Con\AIR CON	ac not workine			a/c workine aoal	21/01/2020	25022	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P15	Myrtleford - Workshop	Hydraulics\RAM	reolace outer boom ram seals				07/01/2020	25021	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P15	Myrtleford - Workshop	Chassis\DAMAGE	repair grab tips and cracks				28/12/2019	25020	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P15	Myrtleford - Workshop	Hydraulics\OIL LEAK	repair grab hose leaks				28/12/2019	25020	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P15	Myrtleford - Workshop	Body\DAMAGE	broken tip on grab				28/12/2019	25020	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	RINLATECH ENGINEERING-3	PRENTICE
P15	Myrtleford - Workshop	Body\TRL LEGS	right back leg seals				28/12/2019	25020	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	RINLATECH ENGINEERING-3	PRENTICE
P15	Myrtleford - Workshop	Hydraulics\RAM	Grab tyne wear plates required				28/12/2019	25020	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P15	Myrtleford - Workshop	Body\DAMAGE	grab needs new points				28/12/2019	25020	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P15	Myrtleford - Workshop	DrivLine\OIL LEAK	oil leaking in grab				28/12/2019	25020	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P15	Myrtleford - Workshop	Hydraulics\RAM	RH lift ram leaking				28/12/2019	25020	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
			massive oil leak in grab													
P15	Myrtleford - Workshop	Hydraulics\HYD LEAKS	fix roof linning				28/12/2019	25020	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P15	Myrtleford - Workshop	Hydraulics\HYD LEAKS	massive oil leak in grab				28/12/2019	25020	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P15	Myrtleford - Workshop	Hydraulics\RAM	graple tyre end broken				28/12/2019	25020	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P15	Myrtleford - Workshop	Hydraulics\HYD LEAKS	legs creeping down while operating				28/12/2019	25020	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P15	Myrtleford - Workshop	Chassis\HYDRAULICS	Replace outer boom bushes			repair crack also	13/12/2019	25020	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P15	Myrtleford - Workshop	Hydraulics\RAM	Fit seals to leaking leg ramsx 4 IT 7565\				13/12/2019	25020	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
						repair hyd hose mounts										
P15	Myrtleford - Workshop	Chassis\DAMAGE	Repair major crack in main boom at pivot pin			weld other boom cracks	30/11/2019	25020	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	RINLATECH ENGINEERING - 4	PRENTICE
P15	Myrtleford - Workshop	Chassis\HYDRAULICS	Fit 3 x boom bushes			fit new boom pin and fit shims	30/11/2019	25020	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	RINLATECH ENGINEERING - 4	PRENTICE
P15	Myrtleford - Workshop	Chassis\HYDRAULICS	fold loader leas				29/11/2019	25019	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P15	Myrtleford - Workshop	Engine\HOUSEKEEP	start and check				29/11/2019	25019	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P15	Albury - Workshop	Hydraulics\RAM	REPLACED RF TOP LEG RAM PIN				10/11/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE
P15	Albury - Workshop	Chassis\CHAS CRACK	FOUND CRACKS IN CHASSIS				10/11/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE
P15	Albury - Workshop	Workshop\MOVE ASSET	TRAVELLED TO & FROM WODONGA DEPOT				10/11/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE
P15	Albury - Workshop	Engine\FUEL TANK	Repaired leaking fuel return line				02/11/2019	24761	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE
P15	Albury - Workshop	Engine\HEATER TAP	Turned heater taps off				02/11/2019	24761	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE
P15	Albury - Workshop	Air Con\HOSES	Inspected A/C hoses				02/11/2019	24761	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE
P15	Albury - Workshop	Engine\AIR CLNR	Replaced Air filter				02/11/2019	24761	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE
P15	Albury - Workshop	Hydraulics\RAM	Grab tyne wear plates required				02/11/2019	24761	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE
P15	Albury - Workshop	Air Con\HEATER	Heater fan noisy				02/11/2019	24761	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE
P15	Albury - Workshop	Engine\MOUNTS	Engine mounts worn out				02/11/2019	24761	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE
P15	Albury - Workshop	VehService\BS	B Service	VehService\BS		Travelled to & from Wodonga yard	02/11/2019	24761	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE
P15	Rosewood - Workshop	Hydraulics\HYD LEAKS	leas creeoine down while operating				31/10/2019	24950	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE
P15	Rosewood - Workshop	VehService\DS	needs service				31/10/2019	24950	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE
P15	Rosewood - Workshop	Hydraulics\RAM	outer boom creeping down				31/10/2019	24950	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE
P15	Rosewood - Workshop	Air Con\AIR CON	a/c/heater fan very noisy				31/10/2019	24950	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE
P15	Rosewood - Workshop	Air Con\AIR CON	ac not working				31/10/2019	24950	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE
P15	Albury - Workshop	Workshop\MOVE ASSET	fill up 2x 20lts drums of hyd oil take to Wodonga and top up hyd oil				03/09/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE
P15	Albury - Workshop	Hydraulics\RAM	RH rear leg pin eyelet broken				10/08/2019	27447	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE
P15	Albury - Workshop	Workshop\MOVE ASSET	drive to Wodonga yard to inspect leg pin on loader - took to Aldonga Engineering for repairs				10/08/2019	27447	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE
P15	Wodonga - Workshop	Hydraulics\RAM	Drive to Wodonga yard to inspect P15			Broken lift ram pin on boom	18/07/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Wodonga Workshop	PRENTICE
			Drive truck to Wodonga Engineering for repairs													
P15	Wodonga - Workshop	Workshop\MOVE ASSET	Bring loader operator back to Albury yard				18/07/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Wodonga Workshop	PRENTICE
P15	Myrtleford - Workshop	Elect\WORK LIGHT	Fit new LED light bar to Prentice T6692				26/06/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P15	Myrtleford - Workshop	Engine\FUEL TANK	Starting problem - bleed fuel lines & fill tank with Alpine Mix				26/06/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P15	Myrtleford - Workshop	DriCabRep\WIPERS	Fit 2nd hand wiper arm & new wiper insert				26/06/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P15	Myrtleford - Workshop	Body\PANELS	Adjust windscreen cage & weld spacers				26/06/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P15	Myrtleford - Workshop	Chassis\HOUSEKEEP	Grease Loader/Prentice				26/06/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P15	Myrtleford - Workshop	Body\PAINT/REST	Wash Loader/Prentice				26/06/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P15	Myrtleford - Workshop	Chassis\HYDRAULICS	arease slew rine				21/06/2019	24578	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P15	Myrtleford - Workshop	Engine\HOUSEKEEP	checked engine fluids				20/06/2019	24578	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P15	Myrtleford - Workshop	Hydraulics\OIL/FILTER	topped up hyd oil				20/06/2019	24578	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P15	Myrtleford - Workshop	Body\HOUSEKEEP	greased whole machine and slew bearing				20/06/2019	24578	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
						replace seals and hoses in leg swing in well										
						repair boom hoses and pipes										
P15	Myrtleford - Workshop	Hydraulics\DAMAGE	Replace Slew Bearings & Pinion Gear			replace oil tank suction hose	06/06/2019	24578	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	RINLATECH ENGINEERING-3	PRENTICE
P15	Myrtleford - Workshop	DriCabRep\WINDSCREEN	replace front w/screen				30/05/2019	24578	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P15	Albury - Workshop	Workshop\MOVE ASSET	travel to and from Wodonga depot				07/05/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE
P15	Albury - Workshop	DrivLine\WHEEL BRGS	diagnosed failed centre/slew bearing				07/05/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE
P15	Albury - Workshop	DrivLine\WHEEL BRGS	organised replacement loader				07/05/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE
			pick up driver from Wodonga depot													
			take him toYack to pick up L17													
P15	Albury - Workshop	Workshop\MOVE ASSET	take other driver back to Myrtleford				07/05/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE
P15	Albury - Workshop	Elect\WORK LIGHT	repaired R outer boom light				05/05/2019	24571	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE
P15	Albury - Workshop	DriCabRep\WIPERS	requires wiper blade				05/05/2019	24571	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE
P15	Albury - Workshop	Hydraulics\HOSES	requires fuel lines at filter head changing and pilot pump hoses changing				05/05/2019	24571	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE
P15	Albury - Workshop	VehService\BS	B Service	VehService\BS			05/05/2019	24571	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE
P15	Albury - Workshop	Workshop\MOVE ASSET	travel to and from Wodonga depot				28/04/2019	24533	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE
P15	Albury - Workshop	Engine\FUEL TANK	replaced fuel oumo return hose				28/04/2019	24533	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE
P15	Albury - Workshop	Elect\ELECT P&W	reoaired outer boom liehts wirine				28/04/2019	24533	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE
P15	Albury - Workshop	Elect\ELECT P&W	reoair outer boom RH liaht mount				28/04/2019	24533	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE
P15	Albury - Workshop	DrCabElect\RADIO	fitted new UHF mic and holder				28/04/2019	24533	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE
			repair engine cover													
P15	Albury - Workshop	DriCabRep\ENG COVER	areased outer boom bearinas				28/04/2019	24533	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE
P15	Albury - Workshop	Workshop\MOVE ASSET	travel to and from Wodonea depot				17/04/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE
P15	Albury - Workshop	DriCabRep\RADIO	repaired aerial lead and mount and replace aerial shaft for UHF				17/04/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE
P15	Albury - Workshop	Hydraulics\RAM	check and tighten grab hoses				17/04/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE
			replaced crack pulley													
			replaced fan belt													
			replaced both hand piece plunger kits (all)													
			repaired hyd oil leaks													
			removed pilot pressure pump and replaced o-rings													
			replaced suction hose to slew valve pump													
P15	Albury - Workshop	Engine\BELTS/TENS	degreased and washed				09/04/2019	24457	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE
P15	Albury - Workshop	Hydraulics\SWAYBAR	replaced arab laws				03/04/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE
P15	Albury - Workshop	Hydraulics\SWAYBAR	repaired laws and re-tioned				03/04/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE
P15	Albury - Workshop	Hydraulics\HYD LEAKS	replaced leakine swivel (eraopole)				03/04/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE
P15	Albury - Workshop	Hydraulics\HYD LEAKS	removed, degreased and washed grab cylinders				03/04/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE
P15	Albury - Workshop	Hydraulics\SWAYBAR	reassembled grab				03/04/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE
P15	Albury - Workshop	Workshop\CLEAN	cleaned up after job completion				03/04/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE
P15	Albury - Workshop	Engine\BELTS/TENS	Replace Dampener				09/03/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE

						diagnosed and removed failed radiator and hoses													
						rebuilt by Natrad													
						fitted Radiator													
						replaced radiator frame bolts and repaired frame													
						replaced a/c compressor													
						replaced radiator hoses and clamps													
						degreased and washed down engine bay													
P15	Albury - Workshop	Cooling\RADIATOR	LEAKING RADIATOR			charged flat batteries	09/03/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE			
P15	Albury - Workshop	Hydraulics\RAM	removed and replaced grab ram				06/03/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE			
			repaired damaged grab skin - replacement required																
P15	Albury - Workshop	Cooling\RADIATOR	found raptured radiator				06/03/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE			
P15	Rosewood - Workshop	Engine				RNR 116867	26/02/2019	24435	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
P15	Albury - Workshop	Hydraulics\RAM	fitting in grab ram loose				16/02/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE			
P15	Albury - Workshop	Hydraulics\SWAYBAR	rotator leaking				16/02/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE			
P15	Albury - Workshop	Hydraulics\HYD LEAKS	radiator leaking bottom right corner				16/02/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE			
P15	Albury - Workshop	Hydraulics\HYD LEAKS	right hand joy stick leaking				16/02/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE			
P15	Albury - Workshop	DriCabRep\WINDSCREEN	needs new top window and front windscreen				16/02/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE			
P15	Rosewood - Workshop	DriCabRep\WINDSCREEN	needs new top window and front windscreen				16/02/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
P15	Rosewood - Workshop	DrivLine\BOLSTER	radiator leaking bottom right corner, right hand joy stick leaking, needs new top window and front windscreen.				16/02/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
P15	Albury - Workshop	Hydraulics\RAM	fitting in grab ram loose				16/02/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE			
P15	Albury - Workshop	Hydraulics\SWAYBAR	rotator leaking				16/02/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE			
P15	Albury - Workshop	Hydraulics\HYD LEAKS	radiator leaking bottom right corner				16/02/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE			
P15	Albury - Workshop	Hydraulics\HYD LEAKS	right hand joy stick leaking				16/02/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE			
P15	Albury - Workshop	DriCabRep\WINDSCREEN	needs new top window and front windscreen				16/02/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE			
P15	Rosewood - Workshop	Engine\RADIATOR	radiator leaking				16/02/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
P15	Rosewood - Workshop	Hydraulics\RAM	fitting in grab ram loose				16/02/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
P15	Albury - Workshop	Hydraulics\HOSES	supply hoses				07/02/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE			
			jump start loader and run for a while																
			test change rate ok																
			top u coolant (5 LITERS)																
P15	Rosewood - Workshop	Elect\BATTERY	slow dropped legs away				22/01/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
			loader not starting. Batteries flat or starter																
			jump started, all good																
			coolant level very low. Topped up																
P15	Rosewood - Workshop	Elect\BATTERY	secured landing legs and ran for a while to charge				22/01/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
			fabricate and weld on new grab tips (on double tipside)																
P15	Rosewood - Workshop	Cooling\RADIATOR	noticed coolant dripping on workshop floor either coming from radiator itself or a coolant hose, tightened hose and cleaned radiator area on wash bay. Ran loader to recheck				03/01/2019	24252	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
			noticed fuel leaking on fuel pump																
P15	Rosewood - Workshop	Engine\FUEL TANK	replaced copper washers, all good now				03/01/2019	24252	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
						fuel leaking from fuel pump supply fitting													
						had to modify pump housing and fittings/hoses to get an air tight suction line to pump													
						bleed fuel system													
						test motor preformance and restarting. All good,													
P15	Rosewood - Workshop	Engine\FUEL TANK	main fuel line at fuel pump leaking at fitting on injector			wash and degrease when fuel has leaked	21/12/2018	24237	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
P15	Rosewood - Workshop	Hydraulics\ELECT P&W	broken servo handle left			replace L/H/S joystick	24/10/2018	23989	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
P15	Albury - Workshop	Engine	Job Added From Invoice				18/10/2018	0	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE			
P15	Rosewood - Workshop	VehService\BS	Service Due	VehService\BS			16/10/2018	2498	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
			Jump start																
P15	Rosewood - Workshop	Elect\BATTERY	UHF left on				15/09/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
						left hand joy stick leaking replace the leaking plunger													
P15	Rosewood - Workshop	Hydraulics\HYD LEAKS	right and left joy stick leaking			refit tested ok	29/08/2018	23905	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
P15	Rosewood - Workshop	Engine\FUEL TANK	needs fuel cap				29/08/2018	23905	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
P15	Rosewood - Workshop	Elect\WORK LIGHT	tighten loose work light near step				29/08/2018	23905	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
P15	Rosewood - Workshop	Hydraulics\HYD LEAKS	check over right hand joy stick to see if leaking				29/08/2018	23905	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
P15	Rosewood - Workshop	Hydraulics\HOUSEKEEP	grease loader due to grease gun wasn't working				29/08/2018	23905	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
P15	Rosewood - Workshop	Cooling\COOL LEAKS	repair coolant leaking bottom radiator hose leaking				29/08/2018	23905	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
P15	Rosewood - Workshop	Elect\BATTERY	flat battery			replace battery second hand P14	16/08/2018	23838	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
			breakdown at pound creek loader wont start put the battery tester on the loader battery tested faulty. Jump start the loader tested the alternator it was charging return back to																
			Rosewood. Pull out second hand battery off P14 put it on the charger																
P15	Rosewood - Workshop	Elect\BREAKDOWN	ready to fit				16/08/2018	23838	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
P15	Myrtleford - Workshop	DrCabElect\INST/GAUGE	repair volt gauge not working				10/07/2018	23751	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE			
P15	Myrtleford - Workshop	Engine\BELTS/TENS	replace fan belt and a/c belt and chrck bearings				10/07/2018	23751	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE			
P15	Myrtleford - Workshop	Elect\ALT	check alternator				10/07/2018	23751	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE			
P15	Myrtleford - Workshop	Body\HOUSEKEEP	wash loader				10/07/2018	23751	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE			
P15	Myrtleford - Workshop	DriCabReo\HOUSEKEEP	roof liniing fallinz in needs fixinz				30/06/2018		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE			
P15	Myrtleford - Workshop	DrCabElect\RADIO	radio in loader not working				30/06/2018		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE			
P15	Myrtleford - Workshop	DrCabElect\RADIO	UHF hand piece needs holder. UHF needs speaker hard to hear when loading				30/06/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE			
P15	Myrtleford - Workshop	Body\TANK RAIL	hand rail needs stretching			Rinlatech	30/06/2018		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE			
						Fit new UHF mic & check UHF & Speaker													
P15	Myrtleford - Workshop	DrCabElect\RADIO	needs speaker for UHF. needs spoiler for UHF			all ok	30/06/2018		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE			
P15	Myrtleford - Workshop	Body\CHN/RLR/MN	grab chain shackle need replacing				30/06/2018		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE			
P15	Myrtleford - Workshop	Body\HOUSEKEEP	joy stick vibrating all the time			reco LH & RH servo's	30/06/2018		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE			
						checked heater control - reset to cold													
P15	Myrtleford - Workshop	Air Con\AIR CON	Air con not working			clean air passage fro a/c box ok	30/06/2018		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE			
P15	Myrtleford - Workshop	Elect\ELECT P&W	Demister speed control not working				30/06/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE			
P15	Myrtleford - Workshop	Steering\WLBCAP	bad vibration in steering wheel 80/9016				30/06/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE			
P15	Myrtleford - Workshop	DriCabRep\AIR LEAK	air leak under cab				30/06/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE			
						Repair Grab tips													
P15	Myrtleford - Workshop	Body\MOUNTS	tips 2 sharp ripping logs			inlatech Engineering	30/06/2018		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE			
P15	Myrtleford - Workshop	Elect\ELECT P&W	no walkway light			Switch is in Cab	30/06/2018		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE			
P15	Myrtleford - Workshop	Elect\TAIL LIGHT	no back up lights			Switch is in Cab	30/06/2018		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE			
P15	Myrtleford - Workshop	Body\MIRRORS	RHS mirrors broken				30/06/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE			
P15	Myrtleford - Workshop	DriCabRep\WIPERS	No window wipers				30/06/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE			
P15	Myrtleford - Workshop	DrivLine\GEARBOX	Hard to get into gear				30/06/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE			
P15	Myrtleford - Workshop	Body\DAMAGE	Cab need clearing out, stuff				30/06/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE			
P15	Myrtleford - Workshop	DrCabElect\AP	Everywhere, MTData not working				30/06/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE			
P15	Myrtleford - Workshop	VehService\BS	B Service As Per Attached Checklist	VehService\BS			30/06/2018	23749	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE			
			talk on phone to drivers about loader UHF																
			send UHF and extension speaker with driver to job site																
			advise how to start loader with flat battery																
			travel to Koetong																
P15	Albury - Workshop	DrCabElect\RADIO	replaced ignition switch and uhf				27/06/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE			
P15	Albury - Workshop	Hydraulics\HOSES	SUPPLY HOSES				27/06/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE			
			replaced door with door from de-commissioned machine																
P15	Albury - Workshop	DriCabRep\DOOR LOCK	adjusted/modified striker				21/06/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE			
P15	Albury - Workshop	Elect\BATTERY	battery flat				15/06/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE			
P15	Albury - Workshop	Engine\START MOTR	inspected connection and tightened lug at starter				15/06/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE			
P15	Albury - Workshop	Elect\BATTERY	repaired broken jump leads				15/06/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE			
P15	Albury - Workshop	Elect\BATTERY	jump started and checked charge				15/06/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE			
P15	Albury - Workshop	Body\HOUSEKEEP	joy stick vibrating all the time				06/04/2018	2366	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
						hyd fault													
						remove caps off spool. No issues													
P15	Albury - Workshop	Hydraulics\OIL LEAK	oil leaking R/H hand control			aood oil flow from servo's	06/04/2018	2366	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
P15	Albury - Workshop	Hydraulics\BREAKDOWN	OUTER BOOM NOT GOING DOWN. FUNCTION IS VERY SLOW			hyd function fault	06/04/2018	2366	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
			check cylinder for bypass found it had no pressure at cylinder																
			found that flow valve into DCV was partially block																
P15	Albury - Workshop	Hydraulics\VALVES	fitted second hand flow valve test ok				06/04/2018	2366	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
P15	Albury - Workshop	Hydraulics\VALVES	replaced seal and o-rine on down servo spool				06/04/2018	2366	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
P15	Albury - Workshop	Hydraulics\VALVES	remove hand piece free up spools				06/04/2018	2366	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
P15	Albury - Workshop	Chassis\CHAS CRACK	LEG ASSY. BROKEN OUT OF CHASSIS				01/04/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE			
			pack and travel to Greenhills Forest Way																
			check complaint of fumey smell in cab																
P15	Rosewood - Workshop	DriCabRep\AIR LEAK	nothing noticed				29/03/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
P15	Rosewood - Workshop	Workshop\MOVE ASSET	travel back to Rosewod				29/03/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
			replace leaking water pump drained coolant																
P15	Rosewood - Workshop	Engine\COOL LEAKS	reolace with new coolant test ok				27/03/2018	23630	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
P15	Rosewood - Workshop	Hydraulics\HOSES	repair hydraulic pipe clamp tighten up and cable tie up tight so it wont move. Test ok				27/03/2018	23630	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
P15	Rosewood - Workshop	Hydraulics\BREAKDOWN	call out. Hyd others				27/03/2018	23636	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
P15	Rosewood - Workshop	Hydraulics\OIL/FILTER	travel to workshop. Fil 2x 20 liters hyd oil				27/03/2018	23636	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
P15	Rosewood - Workshop	Workshop\MOVE ASSET	travel to Gerrar's (hilltop)				27/03/2018	23636	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
			check hyd oil level. Remove cap assy & top up hyd oil																
			refit cap assy																
P15	Rosewood - Workshop	Hydraulics\HOUSEKEEP	tests ok				27/03/2018	23636	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
P15	Rosewood - Workshop	Workshop\MOVE ASSET	return to Depot, unload ute. Return to Tumba				27/03/2018	23636	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
P15	Rosewood - Workshop	Hydraulics\R DIFF OIL	replace grab cylinder				23/03/2018	2465	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
P15	Rosewood - Workshop	Workshop\CLEAN	remove from P14. wash up				23/03/2018	2465	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
P15	Rosewood - Workshop	Workshop\MOVE ASSET	travel to Tumut fit grab cylinder and drop off parts scan loggin				23/03/2018	2465	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
P15	Albury - Workshop	Workshop	Job Added From Invoice				23/03/2018	0	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE			
P15	Rosewood - Workshop	Chassis\BOLSTER	Replace broken leggin				14/03/2018	23478	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
P15	Rosewood - Workshop	DriCabRep\DOOR LOCK	Put new door latch				14/03/2018	23478	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
			check oil and water and check over																
P15	Rosewood - Workshop	Engine\HOUSEKEEP	add 10lts				10/03/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshop	PRENTICE			
			BOSSES HAVE BROKEN OUT OUT FRAME OF LOADER																
P15	Albury - Workshop	Chassis\CHAS CRACK	AS PER INVOICE				07/02/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE			
P15	Albury - Workshop	DrCabElect\AIR CON	NO AC.				06/02/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE			
P15	Albury - Workshop	DriCabRep\ELECT P&W	No power in cab for ignition				15/12/2017	74225	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE			
P15	Albury - Workshop	Elect\ELECT P&W	Left hand front light not working				29/11/2017	741112	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Albury Workshop	PRENTICE			

P15	Alburv - Workshoo	Elect\ELECT P&W	Left hand rear light not working			29/11/2017	741112	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Alburv Workshoo	PRENTICE	
P15	Alburv - Workshoo	Air Con\AIR CON	Air con not working			29/11/2017	741112	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Alburv Workshoo	PRENTICE	
P15	Alburv - Workshoo	Elect\ELECT P&W	Demister speed control not working			29/11/2017	741112	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Alburv Workshop	PRENTICE	
P15	Alburv - Workshop	Elect\ELECT P&W	Temp control not working			29/11/2017	741112	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Alburv Workshop	PRENTICE	
P15	Alburv - Workshop	Elect\ELECT P&W	Left hand back clearant light not working			29/11/2017	741112	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Alburv Workshop	PRENTICE	
					REMOVED OLD LEG PIN. COULD NOT REMOVE BROKEN PART OUT OF EYE OF CYLINDER. PIN WOULD NOT LINE UP. REAR FRAME BENT BAD ENOUGH THAT THE PIN WAS 3/8" OUT OF ALIGNMENT.									
P15	Alburv - Workshop	Chassis\HOUSEKEEP	BROKEN LHR LEG PIN. REMOVED TRIPPLE PUMP OFF P1D		MACHINE SENT TO SCAN LOG.	28/10/2017		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Alburv Workshop	PRENTICE	
P15	Alburv - Workshop	Hydraulics\PUMP	SENT TO SCAN LOG TO REPLACE ORIGINAL ON P15		IT WAS REMOVED AS IT WAS LOOKING EXTERNAL.	21/10/2017		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Alburv Workshop	PRENTICE	
P15	Rosewood - Workshoo	DrivLine\OIL LEAK	oil leakine runnine out of hole in bottom of bell housine		as oer entry #64710	19/10/2017	23187	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Rosewood Workshoo	PRENTICE	
P15	Alburv - Workshoo	Chassis\HOUSEKEEP	REPLACE BROKEN LHR LEG PIN.			12/10/2017	23113	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Alburv Workshoo	PRENTICE	
P15	Alburv - Workshop	VehService\BS	B SERVICE	VehService\BS		12/10/2017	23113	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Alburv Workshoo	PRENTICE	
P15	Alburv - Workshop	Elect\WORK LIGHT	SOME WORK LIGHTS NOT WORKING		repaired/replaced work lights and wiring	10/09/2017	22971	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Alburv Workshop	PRENTICE	
P15	Myrtleford - Workshop	Hydraulics\HYD LEAKS	repair oil leak at grab			03/08/2017	22915	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Hydraulics\PUMP	controls sloppy and not responsive			01/08/2017	22902	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Hydraulics\VALVES	grab opens by itself			01/08/2017	22902	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Hydraulics\RAM	outer boom drops during operation check over			01/08/2017	22902	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Body\HOUSEKEEP	wash truck and loader			16/07/2017	22888	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	VehService\BS	B Service As Per Attached Checklist	VehService\BS		22/06/2017	22888	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Chassis\DAMAGE	weld up cracked grab			14/06/2017	22874	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Hydraulics\DAMAGE	replace grab pin bush			23/05/2017	22820	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Chassis\HOUSEKEEP	replace LHR top leg pin			20/05/2017	22815	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Elect\WORK LIGHT	repair outer boom lights			20/05/2017	22815	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Engine\OIL LEAK	remove and repair and refit dip stick tube			10/05/2017	22797	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Cooling\RADIATOR	Repair leaking radiator			27/04/2017	22790	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Cooling\HOUSEKEEP	Reolace radiator mount rubbers			27/04/2017	22790	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Eneinel\COOL LEAKS	Reolace eneine head easket			27/04/2017	22790	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Engine\HOUSEKEEP	Replace thermostat & gasket			27/04/2017	22790	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Engine\ENG TUNE	Tune Engine			27/04/2017	22790	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Cooling\HOUSEKEEP	Change engine coolant			27/04/2017	22790	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Engine\BELTS/TENS	Replace fan belt & engine fan pulley			27/04/2017	22790	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Engine\BELTS/TENS	Replace air con belt pulley			27/04/2017	22790	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Hydraulics\VALVES	Test servo pressure and adjust to low		Complete	26/04/2017	22788	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Cooling\HOUSEKEEP	Debug hyd cooler		Complete	26/04/2017	22788	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Elect\WORK LIGHT	Re-wire worklight, relay's, boom & cab lights		Comlete	26/04/2017	22788	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Hydraulics\HOSES	reposition hydraulic hose clamp on boom			20/04/2017	22772	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Chassis\HOUSEKEEP	wash boom and grab			20/04/2017	22772	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Hydraulics\HOSES	weld hydraulic hose clamp bracket			20/04/2017	22772	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Eneinel\COOL LEAKS	add stop leak to cooline system to stop head easket leak & test run			13/04/2017	22771	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Hydraulics\OIL LEAK	oil leak from centre of arab			08/04/2017	22770	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Hydraulics\VALVES	Rh lever in cabin leaking			08/04/2017	22770	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	DrCabElect\RADIO	fit new am/fm antenna			08/04/2017	22770	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Hydraulics\VALVES	fit new R/H servo seals			08/04/2017	22770	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	DriCabRep\HOUSEKEEP	clean cabin			08/04/2017	22770	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Hydraulics\HOSES	boom hose & clamps tidy up fit 2nd hand clamp			08/04/2017	22770	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Hydraulics\HOSES	fit new hydraulic stick boom hose			08/04/2017	22770	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Chassis\HOUSEKEEP	weld new stud for grab cover plate			08/04/2017	22770	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Body\HOUSEKEEP	wash down & test			08/04/2017	22770	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Chassis\HOUSEKEEP	grease prentice loader			08/04/2017	22770	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Engine\HOUSEKEEP	run + check hose needs replacing			17/01/2017	22718	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Hydraulics\HOSES	main lift R/H side			30/12/2016	731488	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	DriCabRep\DOOR LOCK	cabin door latch needs replacing			30/12/2016	731488	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Body\HOUSEKEEP	wash loader			30/12/2016	731488	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS		30/12/2016	22702	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Elect\START MOTR	check startine			29/12/2016	22701	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Elect\ALT	check charging system & test alternator output			29/12/2016	22701	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Elect\ELECT P&W	check starter motor & cables			29/12/2016	22701	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Elect\BATTERY	check battery & terminals			29/12/2016	22701	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Air Con\AIR CON	tighten a/c belt			13/12/2016	22656	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Engine\RADIATOR	top up coolant			13/12/2016	22656	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Hydraulics\MOTOR	Replace grab hydraulic motor		flush out system	13/12/2016	22656	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Hydraulics\OIL/FILTER	Change hydraulic filter		change servo filter also	13/12/2016	22656	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Hydraulics\OIL LEAK	Replace RHS joystick plunger seals			13/12/2016	22656	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Workshop\MOVE ASSET	Swap loader over Diagnose grapple swivel motor		Complete	09/12/2016	22656	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Hydraulics\MOTOR	Remove motor for repair		Complete	09/12/2016	22656	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	DriCabRep\MOUNTS	broken leg pin - top RHS			08/12/2016	222652	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Engine\HOUSEKEEP	check oil + coolant			03/12/2016	22630	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Hydraulics\RAM	Replace u/s knuckle ram, spear eye, bearings & pin			03/11/2016	22525	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Hydraulics\HYD LEAKS	Rotator leaks where arab hoses ao under		Comolete	31/10/2016	22508	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Body\HOUSEKEEP	Wash loader. Wah loader		Comolete	31/10/2016	22508	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Hydraulics\VALVES	Reolace 2 x check valve cartridges in grapple swivel block		weld crack in loader frame	29/10/2016	22610	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS		28/10/2016	22497	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Hydraulics\HYD LEAKS	Replace grapple grab swivel for hydraulic hoses replace check valve Orings for grapple slet motor			28/10/2016	22497	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Hydraulics\VALVES	remove arapple slet motor. extract broken aear retainer bolt. fit new bolt			28/10/2016	22497	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Hydraulics\MOTOR	refit motor & test R&R bolts on muffler mount + adjust clamp fit new bolts			28/10/2016	22497	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Body\MOUNTS	R&R rain cap			28/10/2016	22497	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Body\MOUNTS	fit new LH top leg pin			26/10/2016		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Body\PANELS	weld cracks at rear leg support bar			26/10/2016		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Elect\WORK LIGHT	Repair loose RH boom light bracket		Complete	04/10/2016	22411	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	DrCabElect\RADIO	R&R uhf radio & test			29/09/2016	22387	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Engine\HOUSEKEEP	top up radiator coolant			29/09/2016	22387	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Engine\COOL LEAKS	Replace cylinder head gasket		repair fuel leal at injector pump main fuel line	09/09/2016	222790	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS		08/09/2016	22297	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Hydraulics\HOSES	replace leaking servo hydraulic hose			02/09/2016	22205	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Body\HOUSEKEEP	wash down loader			02/09/2016	22205	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Hydraulics\RAM	broken leg pin RHF top			27/08/2016	22247	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Chassis\HOUSEKEEP	weld cracks on loader			27/08/2016	22247	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Hydraulics\RAM	reolace bolt on arab ram oin			26/07/2016		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS	replace hyd filter replace servo filter	22/07/2016	22100	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Hydraulics\HOSES	2 hyd lines on truck behind cab need reolacine			20/07/2016	22062	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Hydraulics\MOTOR	Reolace Slew motor pinion aear			23/06/2016	22206	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Hydraulics\PUMP	Fit seal kit to hydraulic servo pump		check servo pressure	22/06/2016	21901	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS		21/06/2016	21876	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Chassis\HOUSEKEEP	replace all slew bearings, bolts + nuts			16/06/2016	21876	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Chassis\HOUSEKEEP	turn slew bearing 9 deg			16/06/2016	21876	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Chassis\HOUSEKEEP	grease loader			16/06/2016	21876	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Engine\HOUSEKEEP	check lights + fluids			16/06/2016	21876	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Body\HOUSEKEEP	wash loader			16/06/2016	21876	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Chassis\HOUSEKEEP	steam clean the rotator pinion gear			10/06/2016	21875	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Body\HOUSEKEEP	wash truck + clean cabin			25/05/2016	21815	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Chassis\HOUSEKEEP	grease louder			17/05/2016	21813	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Chassis\HOUSEKEEP	Reolace LHR Top Lee Pin			07/04/2016	21727	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS		06/04/2016	21700	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Chassis\HOUSEKEEP	Check boom oins & bushes. Reolace main boom bushes & oin fit arease lines & reolace too & bottom main lift ram oins & fit new bushes to both ends of lift rams.. Check boom oins & bu			30/03/2016	21782	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Body\MOUNTS	Repair tag on pin for grab		Complete	29/03/2016	21655	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Engine\OIL LEAK	Wash engine & inspect front cover oil leak Replace all worn grapple pins & bushes			26/02/2016	21815	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Hydraulics\RAM	Fit Seal kit to RHS main lift ram			26/02/2016	21815	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS		24/02/2016	21502	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Elect\RADIO	fit change over UHF & fit new hand piece		Completed	09/02/2016	21413	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Hydraulics\VALVES	R & R change over grab swivel			03/02/2016	21387	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Hydraulics\OIL/FILTER	Top up hydraulic oil			03/02/2016	21387	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Engine\BELTS/TENS	adjust a/c belt			03/02/2016	21387	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	DriCabRep\SEAT	replace seat. replace drivers seat replace grab hose swivel		fit seat out of p-16 into p-15 top up hyd oil	03/02/2016	21781	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Hydraulics\HYD LEAKS	wash down grab		tighten a/c belt Rinlatech	03/02/2016	21781	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Hydraulics\HOSES	MAKE UP HYD HOSE		Completed refit roof lining	02/02/2016	21381	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	DrCabElect\HOUSEKEEP	roof liner keeps falling		completed	02/02/2016	21381	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	DriCabRep\SEAT	replace RHS arm rest cover		completed	02/02/2016	21381	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Chassis\HOUSEKEEP	gease all points on loader		completed	13/01/2016	21316	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Elect\HOUSEKEEP	check lights		completed	13/01/2016	21316	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Engine\HOUSEKEEP	inspect engine		completed	13/01/2016	21316	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	Air Con\AIR CON	clean cab filter repair arm rest pads		completed	13/01/2016	21316	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	DriCabRep\SEAT	n e motor trim		completed	23/12/2015		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	DriCabRep\SEAT	replace joy stick covers		completed	19/12/2015	21295	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	DriCabRep\DAMAGE	replace work signs		completed	19/12/2015	21295	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	
P15	Myrtleford - Workshop	DriCabRep\RADIO	trunk phone needs new speaker		completed	19/12/2015	21296	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE	

P1S	Myrtleford - Workshop	Hydraulics\HOSES	reolace hoses on knuckle		completed	19/12/2015	21296	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P1S	Myrtleford - Workshop	Engine\BELTS/TENS	check fan. air conditioner & alternator belts		completed	19/12/2015	21296	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P1S	Myrtleford - Workshop	Hydraulics\OIL/FILTER	top up hydraulic oil tank		completed	19/12/2015	21296	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P1S	Myrtleford - Workshop	Body\MOUNTS	main pin in grap is flogged out 2 air con belts		completed	19/12/2015	21296	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P1S	Myrtleford - Workshop	Air Con\AIR CON	tctc		completed	15/12/2015		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P1S	Myrtleford - Workshop	Engine\OIL LEAK	wash engine + inspect oil leaks filters		completed	12/12/2015	21295	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P1S	Myrtleford - Workshop	Engine\FILTERS	tctc		completed	12/12/2015		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P1S	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist work lights	VehService\BS	completed	11/12/2015	21295	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P1S	Myrtleford - Workshop	DrCabElect\ELECT P&W	mvrt auto elec make up hoses + supply wrap		completed	11/12/2015		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P1S	Myrtleford - Workshop	Hydraulics\HOSES	rinlatech check new trunk aerial not working fit new work light + re-position work light make bracket for top worklight above windscreen replace ugh mic		completed	11/12/2015		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P1S	Myrtleford - Workshop	DriCabRep\DAMAGE	check seat in loader - driver to moniter repair air con system		completed	04/12/2015	21261	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P1S	Myrtleford - Workshop	DriCabRep\AIR CON	mae regas air con replace condensor fan replace dryer + repair aircon system		completed	02/12/2015		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P1S	Myrtleford - Workshop	Air Con\AIR CON	reolace damaged aircon hose		completed	12/11/2015	21222	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P1S	Myrtleford - Workshop	Body\DAMAGE	replace rhr top leg pin		completed	20/10/2015	21192	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P1S	Myrtleford - Workshop	Chassis\HYDRAULICS	hoses + supply parts		completed	10/10/2015		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE
P1S	Myrtleford - Workshop	Air Con\AIR CON	fit air con belt back on water pump + air con compressor pulleys + test		completed	06/10/2015	21179	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Rosewood	ALR	Myrtleford Workshop	PRENTICE