EquipmentName	Workshop	CodeAndSubCode	Description	Schedule	CompletionComments	DateDone	DistanceDone	Worktype	Workstate	EquipmentOwner	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
LOAD15	Wodonga - Workshop	Elect\BATTERY	Jump start and check batteries.		Test charged and Replaced batteries	16/08/2024		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER
LOAD15	Wodonga - Workshop	DriCabRep\MOUNTS	RH bonnet locator missing			22/03/2024		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER
LOAD15	Wodonga - Workshop	DrCabElect\INST/GAUGE	services schedules monthly not km based as odometer not working			22/03/2024		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER
LOAD15	Wodonga - Workshop	DrCabElect\ELECT P&W	does need some work, possible an earth on wiper motor/circuit			22/03/2024		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER
LOAD15	Wodonga - Workshop	DriCabRep\MOUNTS	need RH bonnet strap			22/03/2024		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER
LOAD15	Wodonga - Workshop	DrCabElect\INST/GAUGE	odometer not working			22/03/2024		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER
LOAD15	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			22/03/2024		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER
LOAD15	Wodonga - Workshop	Susp\SPRNG PACK	FRONT SPRING SHACKLES WORN.			22/03/2024		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER
LOAD15	Wodonga - Workshop	Steering\SUSPENSION	replace front RHS spring pack keeper			22/03/2024		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER
LOAD15	Wodonga - Workshop	Steering\OIL LEAK	oil leak near steeing box			22/03/2024		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER
LOAD15	Wodonga - Workshop	DrCabElect\INST/GAUGE	speedo not working			22/03/2024		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER
LOAD15	Wodonga - Workshop	Elect\INDICATORS	cracked left rear blinker			22/03/2024		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER
LOAD15	Wodonga - Workshop	DriCabRep\AIR LEAK	air leak and no splitters in gear shift			22/03/2024		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER
LOAD15	Wodonga - Workshop	Steering\OIL LEAK	oil leak near steering box			22/03/2024		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER
LOAD15	Wodonga - Workshop	DrCabElect\INST/GAUGE	speedo not working			22/03/2024		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER
LOAD15	Wodonga - Workshop	DrCabElect\ELECT P&W	WIPERS NOT WORKING.			22/03/2024		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER
LOAD15	Wodonga - Workshop	Air Con\HEATER	HEATER.			22/03/2024		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER
LOAD15	Wodonga - Workshop	Elect\ELECT P&W	CLEARANCE LIGHT.			22/03/2024		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER
LOAD15	Wodonga - Workshop	Elect\TAIL LIGHT	TAIL LEFT REAR LIGHT.			22/03/2024		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER
LOAD15	Wodonga - Workshop	Air Con\AIR CON	AC NOT.			22/03/2024		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER
LOAD15	Wodonga - Workshop	Air Con\AIR CON	DEMISTER.			22/03/2024		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER
LOAD15	Wodonga - Workshop	Elect\INDICATORS	CRACKED LEFT REAR BLINKER.			22/03/2024		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER
LOAD15	Wodonga - Workshop	Susp\SWAYBAR	BUSHES IN REAR SWAY BAR.			22/03/2024		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER
LOAD15	Wodonga - Workshop	DriCabRep\WIPERS	WIPERS NOT WORKING.			22/03/2024		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER
LOAD15	Wodonga - Workshop	Air Con\HEATER	HEATER.			22/03/2024		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER
LOAD15	Wodonga - Workshop	Elect\ELECT P&W	CLEARANCE LIGHT			22/03/2024		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER
LOAD15	Wodonga - Workshop	Elect\TAIL LIGHT	TAIL LEFT REAR LIGHT.			22/03/2024		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER
LOAD15	Wodonga - Workshop	Air Con\AIR CON	AC NOT.			22/03/2024		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER
LOAD15	Wodonga - Workshop	Air Con\AIR CON	DEMISTER.			22/03/2024		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER
LOAD15	Wodonga - Workshop	Elect\INDICATORS	CRACKED LEFT REAR BLINKER.			22/03/2024		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER
LOAD15	Wodonga - Workshop	Susp\SWAYBAR	BUSHES IN SWAY BAR.			22/03/2024		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER
LOAD15	Albury - Workshop	Tyres\RETREAD	supply and fit 1tyre POS not given			09/03/2022		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Albury Workshop	LOADER
LOAD15	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			01/03/2022		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER
LOAD15	Wodonga - Workshop	Susp\SPRNG PACK	FRONT SPRING SHACKLES WORN.			01/03/2022		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER
LOAD15	Wodonga - Workshop	Steering\TIE ROD	REPLACE LH TIE-ROD END.			01/03/2022		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER
LOAD15	Wodonga - Workshop	Steering\KING PIN	REPLACE KING PINS. UNROADWORTHY.			01/03/2022		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER
					REMOVED JACK SHAFT AND IDENTIFIED. ORDERED NEW JOINT.											
LOAD15	Wodonga - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS	TIGHTENED DRIVING LIGHTS.	01/03/2022		Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER
			DIAGNOSED UNSERVICABLE UNI JOINT IN JACK SHAFT.													
LOAD15	Wodonga - Workshop	DrivLine\TAIL SHAFT	GROUNDED VEHICLE AWAITING REPAIR.		REPLACED REAR UNI-JOINT. CAPS SEIZED AND REQUIRED CUTTING OUT WITH OXY.	09/02/2022		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER
			HARTRITES													
			Service call to Rosewood w/shop													
LOAD15	Albury - Workshop	Hydraulics\HOSES	Supply 1 hose as per sample			11/01/2022		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Albury Workshop	LOADER
LOAD15	Rosewood - Workshop	Elect\BATTERY	supply battery cable			19/11/2021		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
LOAD15	Albury - Workshop	Engine\BATTERY	REPLACED BY-PASSED BATTERY ISOLATOR.			29/10/2021		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Albury Workshop	LOADER
			Service call to Rosewod w/shop													
			Wait for mechanic to arrive													
			Supply 2 hoses as per sample													
LOAD15	Albury - Workshop	Hydraulics\HOSES	Supply a third hose 200mm longer than sample			01/09/2021		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Albury Workshop	LOADER
LOAD15	Rosewood - Workshop	Engine\HOUSEKEEP	check over prior to shift			31/08/2021		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
LOAD15	Rosewood - Workshop	Engine\COOL LEAKS	tightened loose coolant loose clamp at heater tank			31/08/2021		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
					replace/repair/weld up mirror brackets from vehicle and 2nd hand set sent from Myrtleford to											
					repair brackets to a roadworthy standard											
					replace both main mirror heads with good 2nd hand											
LOAD15	Rosewood - Workshop	Body\MIRRORS	LHS & RHS mirrors		replace both spotter mirrors with good 2nd hand ones	24/08/2021		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
LOAD15	Myrtleford - Workshop	Body\DAMAGE	remove RH mirror arm and mirror from wreak fitted new glass to two mirrors send to Tumba			20/08/2021		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Rosewood - Workshop	Body\DAMAGE	travel to Rosewood via Shelley to inspect mirror and bracket damage and organise parts for replacement on Monday 23/08/21			20/08/2021		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
			rewire wiper switch installed by Tumut Auto Elec so wipers will operate when headlight are switched on													
LOAD15	Rosewood - Workshop	DrCabElect\ELECT P&W	gord			06/08/2021		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
			loosen repairing mount bolts in front bar													
			straighten bar and replace bolts (5 missing)													
			weld up several cracks in mounts													
LOAD15	Rosewood - Workshop	Brakes\DAMAGE	load up grab and check. All good			28/07/2021		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
LOAD15	Rosewood - Workshop	Engine\HOUSEKEEP	check over			23/07/2021		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
LOAD15	Rosewood - Workshop	Body\CHN/RLR/MN	weld on catch for grab rest bar on front			06/07/2021		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
LOAD15	Albury - Workshop	DriCabRep\WIPERS	Repair wiper blades			02/07/2021		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Albury Workshop	LOADER
LOAD15	Rosewood - Workshop	DriCabRep\MOUNTS	need RH bonnet strap			19/06/2021		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
LOAD15	Rosewood - Workshop	DrCabElect\INST/GAUGE	odometer not working			19/06/2021		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
LOAD15	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			19/06/2021		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
LOAD15	Rosewood - Workshop	VehService\AS	A Service	VehService\AS		19/06/2021		Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
LOAD15	Rosewood - Workshop	DriCabRep\WIPERS	replace wiper blades			03/06/2021		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
LOAD15	Rosewood - Workshop	Body\PAINT/REST	clean oil residue off cab/windscreen			03/06/2021		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
LOAD15	Rosewood - Workshop	DrCabElect\RADIO	mount UHF mic clip and tidy wiring			25/05/2021		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
LOAD15	Rosewood - Workshop	DriCabRep\WINDOW REG	modify L14 window winder and fit to left door			25/05/2021		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
LOAD15	Rosewood - Workshop	DriCabRep\WINDOW REG	fit to left door window winder to drivers door			25/05/2021		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
LOAD15	Rosewood - Workshop	DriCabRep\WINDOW REG	reinstall LH door seal (was removed and on the floor)			25/05/2021		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
LOAD15	Rosewood - Workshop	DriCabRep\WIPERS	windscreen wipers		check wiper operation	07/05/2021		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
LOAD15	Rosewood - Workshop	DrCabElect\INST/GAUGE	switches were set wrong			07/05/2021		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
LOAD15	Rosewood - Workshop	DrCabElect\ELECT P&W	does need some work, possible an earth on wiper motor/circuit			07/05/2021		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
LOAD15	Wodonga - Workshop	Workshop\MOVE ASSET	Pick Up from TCTC			10/04/2021		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER
			BRAKE RELINE													
			CUSTOMER REPORTS THERE ARE SOME BRAKE RELINES REQUIRED ON THE TRUCK, DIAGNOSE AND REPORT TO													
			SERVICE WHICH ONES BEFORE REPAIRING.													
			$1,067.20													
			19/03/2021.													
			Jacked up front end and supported													
			Removed oil caps – found to have trouble with LH cap – eventually removed as required													
			Removed hub and stripped brakes													
			Found RH drum cracked													
			Inspected and found Wheel bearings u/s.													
			Replaced wheel bearings													
			Unbolt brake drums and mount up and secured new drums as required													
			Removed old linings from shoes and cleaned													
			Fitted new linings (required to rivet new linings on)													
			Travelled to Corowa Truck and trailer and rivet linings on.													
			Returned to TCTC. Fitted brakes on													
			Fitted hub seals to hubs and fitted hub and tensioned wheel bearings as required													
			Refit caps and filled with oil													
			Adjusted brakes and washed and road tested													
			Re-inspected oil levels, all ok.													
LOAD15	Albury - Workshop	Brakes\BRK RELINE	Re-checked wheel bearings adjustment, all ok.			20/03/2021		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Albury Workshop	LOADER
LOAD15	Rosewood - Workshop	Engine\COOL LEAKS	coolant leak			06/03/2021		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
LOAD15	Rosewood - Workshop	DriCabRep\AIR LEAK	air leak and no splitters in gear shift			06/03/2021		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
LOAD15	Rosewood - Workshop	Steering\OIL LEAK	oil leak near steering box			06/03/2021		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
LOAD15	Rosewood - Workshop	DrCabElect\INST/GAUGE	speedo not working			06/03/2021		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
LOAD15	Tumut - Workshop	Engine\COOL LEAKS	coolant leak		check coolant leak has stopped checked radiator full	06/03/2021		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Tumut Workshop	LOADER
LOAD15	Tumut - Workshop	DrivLine\GEARBOX	air leak no spliters in gear shift			06/03/2021		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Tumut Workshop	LOADER
LOAD15	Tumut - Workshop	Steering\OIL LEAK	oil leak near steeing box			06/03/2021		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Tumut Workshop	LOADER
LOAD15	Tumut - Workshop	DrCabElect\INST/GAUGE	speedo not working			06/03/2021		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Tumut Workshop	LOADER
LOAD15	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			06/03/2021		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
LOAD15	Rosewood - Workshop	VehService\AS	A Service	VehService\AS	tctc Carried out A service and Suspension check on 05/03/2021 as per service sheets required.	06/03/2021		Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
			c/over at shift change													
			top up coolant													
LOAD15	Myrtleford - Workshop	Engine\HOUSEKEEP	tighten clamps			04/03/2021		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Steering\HOUSEKEEP	top up power steering oil			04/03/2021		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
			fit new front right shock mount steer bottom													
			remove ubolt nuts tap up ubolts and fit new mount													
LOAD15	Rosewood - Workshop	Steering\SUSPENSION	tighten up ubolts check ok			24/02/2021		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
LOAD15	Rosewood - Workshop	Engine\ELECT P&W	check and test voltage output,27volts			24/02/2021		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
LOAD15	Rosewood - Workshop	Engine\HOUSEKEEP	check fluid levels			24/02/2021		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
			phone calls to Kevin at Lavington													
			about knob on gearshift													
			get hoses correct													
LOAD15	Tumut - Workshop	DrivLine\GEARBOX	still leaking in splitter			21/02/2021		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Tumut Workshop	LOADER

			prepare and weld gearshift shaft remove hoses from range change knob fit gearshift knob															
LOAD15	Tumut - Workshop	DrivLine\GEARBOX	fit hoses by photo wrong sequence				20/02/2021	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Tumut Workshop	LOADER
LOAD15	Albury - Workshop	Hydraulics\HOSES	Make new Hoses as per sample for Load15 as per request take L15 to Cummins Wodonga				18/02/2021	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Albury Workshop	LOADER
LOAD15	Tumut - Workshop	Workshop\MOVE ASSET	bring L15 back to Tumut take loader to Tumut				17/02/2021	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Tumut Workshop	LOADER
LOAD15	Tumut - Workshop	Elect\BATTERY	put on battery charger				13/02/2021	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Tumut Workshop	LOADER
LOAD15	Rosewood - Workshop	Engine\FILTERS	blew air fitter out				13/02/2021	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
LOAD15	Rosewood - Workshop	Elect\ELECT P&W	repaired rubber wires rear bonnet mount and secured				13/02/2021	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
LOAD15	Rosewood - Workshop	DrCabRep\MOUNTS	RH bonnet locator missing				13/02/2021	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
LOAD15	Rosewood - Workshop	DrCabElect\INST/GAUGE	services schedules monthly not km based as odometer not working				13/02/2021	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
LOAD15	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job				13/02/2021	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
LOAD15	Rosewood - Workshop	VehService\BS	B Service attempt to wire up new alternator, spoke with TAE and we could not get it to work	VehService\BS			13/02/2021	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
LOAD15	Rosewood - Workshop	Elect\ELECT P&W	booked in for TAE Monday loader milked clean out drums fill with fuel travel to machine fill with fuel bleed system travel back				13/02/2021	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
LOAD15	Tumut - Workshop	Engine\BREAKDOWN	head home clean up		truck was milked of fuel clean out 20liters drums fill with diesel 100liters travel to bush fall truck with diesel blood system of air		11/02/2021	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Tumut Workshop	LOADER
LOAD15	Tumut - Workshop	Engine\FUEL TANK	truck milked of fuel		travel to Tumut shower new clothes		11/02/2021	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Tumut Workshop	LOADER
LOAD15	Tumut - Workshop	Steering\SUSPENSION	broken front right shocker mount remove				10/02/2021	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Tumut Workshop	LOADER
LOAD15	Rosewood - Workshop	DrCabElect\RADIO	UHF not working		called to bush, driver was not wanting to drive it without a functioning UHF found bad connection to power supply of UHF. Repaired as needed		05/02/2021	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
LOAD15	Tumut - Workshop	Tyres\TP1+2	replace 2 tyres				05/02/2021	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER
LOAD15	Rosewood - Workshop	Tyres\BREAKDOWN	called to Tumut, steer tyre split and dangerous (tyre fitter didn't look at loader as it was at TAE) no spare at Tumut				03/02/2021	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
LOAD15	Rosewood - Workshop	Tyres\STEER TYRE	travel home				03/02/2021	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
LOAD15	Tumut - Workshop	Elect\ALT	drop at TAE alternator replacement & wiring				03/02/2021	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Tumut Workshop	LOADER
					checked headlights as per repair request 122880, light performance is as expected for the lighting											
LOAD15	Myrtleford - Workshop	Elect\HEAD LIGHT	low beam needs to be brighter		fitted to the vehicle. Note, vehicle lighting appears to be standard		03/02/2021	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Engine\JAKE BRAKE	no engine brake		engine brake (exhaust brake) is working and is as for as I can tell as good as can be expected		03/02/2021	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	DrCabElect\AIR CON	no a/c fitted, a/c cannot be repaired as it is decommisioned checked braking performance on test drive, very poor checked brake temps, front was 70°c average, fdrive 22° average adjusted drive brakes, were very far out of spec retest droved, brake performance very good				03/02/2021	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Brakes\BRAKE ADJ	check brake temps on drive a 2nd time tachometer does not work odometed does not tick over noticed on test drive				03/02/2021	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	DrCabElect\INST/GAUGE	80.5° average temp. brakes now working				03/02/2021	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	DrCabElect\RADIO	UHF mic replaced 20/01/21 by C. Matthews jump start and check change ride. not charging found broken exciter wire, repaired. Still no charge				03/02/2021	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Rosewood - Workshop	Elect\ELECT P&W	TAE to supply and fit new alternator after it tested bad				02/02/2021	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
LOAD15	Rosewood - Workshop	Body\AIR LEAK	repair air leak at gearbox area				02/02/2021	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
LOAD15	Rosewood - Workshop	Elect\HEAD LIGHT	removed headlight covers and cleaned lenses				02/02/2021	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
LOAD15	Rosewood - Workshop	Elect\BATTERY	put on battery charger				02/02/2021	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
LOAD15	Rosewood - Workshop	Engine\HOUSEKEEP	check over before going to Tumut		test drive and check brake performance, very poor check brake temps, very cold checked adjustment, all drive brakes out of adjustment adjusted to requirement and re-terst drove, stopping very well		30/01/2021	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
LOAD15	Rosewood - Workshop	Brakes\BRAKE ADJ	Brakes still not adjusted		re-checked brake temps, all hot/warm indicating they were working		29/01/2021	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
LOAD15	Rosewood - Workshop	DrCabElect\RADIO	uhf not transmitting clearly		remove brake hose get part number photo send to Wayne for ordering		29/01/2021	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
LOAD15	Rosewood - Workshop	Brakes\AIR LEAK	repair brake air hose		put truck on pitt inspect with TCTC leaking hose on signal push joiner replaced		21/01/2021	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
LOAD15	Rosewood - Workshop	Brakes\BRAKE ADJ	needs brake adjust				14/01/2021	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
LOAD15	Rosewood - Workshop	Tyres\TP3+4	replaced 2 tyres				13/01/2021	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
LOAD15	Rosewood - Workshop	Tyres\TP5+6	replaced 2 tyres				13/01/2021	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
LOAD15	Rosewood - Workshop	Tyres\DRV TYRES	needs drive tyres				05/01/2021	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
LOAD15	Rosewood - Workshop	Engine\HOUSEKEEP	check over				03/12/2020	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
LOAD15	Rosewood - Workshop	DrCabRep\WIPERS	(tighten wiper arm) need new pivot + arms				03/12/2020	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
LOAD15	Tumut - Workshop	Elect\HEAD LIGHT	low beam needs to be brighter				21/11/2020	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Tumut Workshop	LOADER
LOAD15	Tumut - Workshop	Air Con\AIR CON	no "ac"				21/11/2020	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Tumut Workshop	LOADER
LOAD15	Tumut - Workshop	Engine\JAKE BRAKE	no engine brake				21/11/2020	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Tumut Workshop	LOADER
LOAD15	Rosewood - Workshop	Steering\SUSPENSION	replace front RHS spring pack keeper		removed hotline and arranged sublet repaired to collect from Rosewood in morning		17/11/2020	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
LOAD15	Rosewood - Workshop	Engine\AIR LEAK	remove and replace air hose		returned next day and fitted hose. Tested, all good		13/11/2020	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
LOAD15	Rosewood - Workshop	Engine\BREAKDOWN	called out to Adelong Creek Rd. major air leak foubd ruptured 'hotline'				13/11/2020	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
LOAD15	Rosewood - Workshop	VehService\BS	Service Due	VehService\BS			05/11/2020	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
LOAD15	Rosewood - Workshop	Engine\HOUSEKEEP	accelerator stuck on high revs				31/10/2020	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
LOAD15	Wodonga - Workshop	DrCabRep\DOOR LOCK	replace loader door latch - involved some panel beating				13/10/2020	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER
LOAD15	Wodonga - Workshop	Chassis\HOUSEKEEP	grease loader boom and leg pins				13/10/2020	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER
LOAD15	Wodonga - Workshop	Workshop\MOVE ASSET	park truck				13/10/2020	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER
LOAD15	Wodonga - Workshop	Elect\BATTERY	Job Added From Invoice				19/09/2020 0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER
LOAD15	Wodonga - Workshop	Elect\BATTERY	jump start vehicle, found batteries and terminals required replacement, replaced both batteries and 2 terminals which correct				15/09/2020	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER
LOAD15	Wodonga - Workshop	Elect\BATTERY	Job Added From Invoice				12/08/2020 0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER
LOAD15	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				11/08/2020	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER
LOAD15	Wodonga - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS			11/08/2020	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER
LOAD15	Wodonga - Workshop	DrivLine\OIL LEAK	leaking service brake		RR's Pre Jan 2020 (system clean up) 05/08/20		06/08/2020	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER
LOAD15	Wodonga - Workshop	Elect\BATTERY	loader wont start dead battery		got battery from loader in albury need to order new one		04/08/2020	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER
LOAD15	Albury - Workshop	DrCabElect\RADIO	PO FOR MICROPHONE				31/07/2020	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Albury Workshop	LOADER
LOAD15	Wodonga - Workshop	Elect\BRK LIGHT	brake lights stuck on				31/07/2020	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER
LOAD15	Wodonga - Workshop	Elect\BRK LIGHT	Brake Light				30/07/2020	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER
LOAD15	Myrtleford - Workshop	Engine\HOUSEKEEP	start and run truck and prentice				01/05/2020	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Body\PAINT/REST	wash truck and paint wheels				22/02/2020	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Body\REFLECTORS	fit reflecting tape on steps		see job no. 118058 - P15		22/02/2020	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Body\MUDGUARDS	R&R mudflaps straighten m/flap bracket straighten t/light bar				21/02/2020	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Body\DAMAGE	clean and paint				21/02/2020	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Body\PAINT/REST	weld plat to t/light mount and fit m/flaps				21/02/2020	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Body\PAINT/REST	fit t/light bar degrease wheels and hubs				21/02/2020	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	DrivLine\DRV LN SER	tightened loose drive shaft yoke bolts				20/02/2020	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Chassis\HOUSEKEEP	jack up front end, check kingpins and grease				20/02/2020	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Engine\BELTS/TENS	repair seized fan belt tensioner				12/02/2020	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	DrivLine\DRV LN SER	retension all front yoke caps				11/02/2020	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Body\MOUNTS	replace j-bracket and fit new step				11/02/2020	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Body\DAMAGE	Repair & re-mount grill				11/02/2020	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Steering\SUSPENSION	Replace steer shocker rubbers				11/02/2020	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Body\FUEL TANK	replace broken j-bracket on LHS fuel tank				08/02/2020	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Body\MOUNTS	drivers side step modify and straighten				08/02/2020	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Engine\EXHAUST	replace exhaust muffler				06/02/2020	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Body\DAMAGE	straighten tank j-bracket and remount bent step				06/02/2020	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	DrCabElect\DOOR LOCK	weld cracks and repair drivers door				06/02/2020	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Body\MUDGUARDS	Repair RHF steer mudguard mount				05/02/2020	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	DrivLine\SUSPENSION	replaced rear diff v-stay				31/01/2020	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Brakes\BOOSTER	LH steer booster maxi 24/24 booster u/s				23/01/2020	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	DrCabRep\DOOR LOCK	driver side window glides need attention				23/01/2020	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	DrCabRep\AIR LEAK	accelerator pedal leaking air				23/01/2020	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	DrCabElect\ELECT P&W	12x supply to uhf and am/fm stereo				23/01/2020	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Body\HOUSEKEEP	inspect truck				23/01/2020	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	DrCabElect\INST/GAUGE	oil pressure guage leaking oil				23/01/2020	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Body\FUEL TANK	fit tank rubber				23/01/2020	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Steering\WHEEL SEAL	reseal RHF steer hub cap				23/01/2020	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Steering\COOL FILTR	front hub cap				23/01/2020	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
					pressure clean motor											
LOAD15	Wodonga - Workshop	DrivLine\GEARBOX	gearbox needs looking at hard to get into gear		pressure clean bonnet and frame		21/01/2020	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER

					road test - ok														
LOAD15	Wodonga - Workshop	Steering\WHEEL ALGN	A bad wobble in steering		replace steer tyres		21/01/2020	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER			
LOAD15	Wodonga - Workshop	DrCabElect\RADIO	UHF need speaker hard to hear				21/01/2020	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER			
LOAD15	Wodonga - Workshop	DriCabRep\SEAT	seat needs looking				21/01/2020	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER			
LOAD15	Wodonga - Workshop	Body\HOUSEKEEP	walking platform not safe slippery		L1S and P1S		21/01/2020	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER			
LOAD15	Wodonga - Workshop	Elect\ELECT P&W	no reverse light not back up lights				21/01/2020	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER			
LOAD15	Wodonga - Workshop	Steering\WHEEL ALGN	truck all over road steering not good		rear vee- stay u/s		21/01/2020	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER			
LOAD15	Wodonga - Workshop	DrivLine\GEARBOX	very hard to get in and out of gear				21/01/2020	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER			
LOAD15	Wodonga - Workshop	DriCabRep\HOUSEKEEP	seat not getting air				21/01/2020	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER			
LOAD15	Wodonga - Workshop	Elect\INDICATORS	blinkers not working				21/01/2020	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER			
LOAD15	Wodonga - Workshop	Body\TRL DOORS	door not shutting				21/01/2020	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER			
LOAD15	Wodonga - Workshop	Body\MOUNTS	Broken main lift pin Hydraulic oil all over floor grab ground in hydraulic oil.				21/01/2020	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER			
LOAD15	Wodonga - Workshop	Hydraulics\OIL LEAK	Door not shutting probably roof line falling in		door		21/01/2020	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER			
LOAD15	Wodonga - Workshop	Elect\DRV LIGHT	Driving light out L/H side				21/01/2020	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER			
LOAD15	Wodonga - Workshop	Elect\TAIL LIGHT	Reverse light not working		double		21/01/2020	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER			
LOAD15	Wodonga - Workshop	DrivLine\AIR LEAK	Cluch leaking air when inguge Right hand serve needs fixing had oil all over floor door need fixing				21/01/2020	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER			
LOAD15	Wodonga - Workshop	DrCabElect\DOOR LOCK	need light put on back of cab for night work		door		21/01/2020	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER			
LOAD15	Wodonga - Workshop	Elect\DRV LIGHT	Drives light on truck not working fuel pump on back need update		lights		21/01/2020	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER			
LOAD15	Wodonga - Workshop	Hydraulics\HYD LEAKS	RH servo leaking		double		21/01/2020	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER			
LOAD15	Wodonga - Workshop	Engine\EXHAUST	exhaust switch on floor				21/01/2020	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER			
LOAD15	Wodonga - Workshop	Hydraulics\HYD LEAKS	outer boom seal creeping		outer boom ram seals fitted		21/01/2020	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER			
LOAD15	Wodonga - Workshop	Elect\ELECT P&W	check wires exhaust switch				21/01/2020	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER			
LOAD15	Wodonga - Workshop	Body\DAMAGE	racho rubbing back window				21/01/2020	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER			
LOAD15	Wodonga - Workshop	Elect\DRV LIGHT	left driving light		double		21/01/2020	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER			
LOAD15	Wodonga - Workshop	Engine\EXHAUST	exhaust pipe and clamp loader				21/01/2020	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER			
LOAD15	Wodonga - Workshop	Hydraulics\HYD LEAKS	rotator leaking				21/01/2020	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER			
LOAD15	Wodonga - Workshop	DriCabRep\HOUSEKEEP	glove box cover broken				21/01/2020	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER			
LOAD15	Wodonga - Workshop	Brakes\AIR LEAK	air leak under braking				21/01/2020	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER			
LOAD15	Wodonga - Workshop	DriCabRep\WINDOW REG	needs new wiper blades		replaced LHS wiper assembly		21/01/2020	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER			
LOAD15	Wodonga - Workshop	Body	straighten RH top tank step				21/01/2020	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER			
LOAD15	Wodonga - Workshop	Tyres\STEER TYRE	steer tyres need replacing				21/01/2020	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER			
LOAD15	Wodonga - Workshop	Steering\PWR STEER	check steering no fire ext				21/01/2020	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER			
LOAD15	Wodonga - Workshop	Body\HOUSEKEEP	no racko				21/01/2020	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER			
LOAD15	Wodonga - Workshop	Brakes\AIR LEAK	air leaks when park brake applied				21/01/2020	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER			
LOAD15	Wodonga - Workshop	DriCabRep\WIPERS	windscreen wiper blades				21/01/2020	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER			
LOAD15	Wodonga - Workshop	Engine\JAKE BRAKE	exhaust brake				21/01/2020	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER			
LOAD15	Wodonga - Workshop	Body\AIR LEAK	air leak near park brake				21/01/2020	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER			
LOAD15	Wodonga - Workshop	Air Con\AIR CON	no airconditioner		cab has cab fan fitted		21/01/2020	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER			
LOAD15	Wodonga - Workshop	Elect\DRV LIGHT	LHS driving light not working				21/01/2020	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER			
LOAD15	Wodonga - Workshop	Steering\STEER UNI	check steering fair bit of movement clunking sound				21/01/2020	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER			
LOAD15	Wodonga - Workshop	Engine\JAKE BRAKE	exhaust brake				21/01/2020	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER			
LOAD15	Wodonga - Workshop	Tyres\STEER TYRE	needs RH steer tyre				21/01/2020	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER			
LOAD15	Wodonga - Workshop	Tyres\DRV TYRES	needs RHF drive outer tyre				21/01/2020	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER			
LOAD15	Wodonga - Workshop	Body\DAMAGE	repair as per RR116858				21/01/2020	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER			
LOAD15	Wodonga - Workshop	Cooling\RADIATOR	truck getting hot				21/01/2020	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER			
LOAD15	Wodonga - Workshop	DrivLine\OIL LEAK	leaking service brake				21/01/2020	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER			
LOAD15	Wodonga - Workshop	VehService\BS	B Service Due	VehService\BS			21/01/2020	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER			
LOAD15	Myrtleford - Workshop	DrCabElect\LELECT P&W	replace start button				24/12/2019	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER			
LOAD15	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice		Removed & fit new starter Fit new push button for starter		29/09/2019	754411	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Albury Workshop	LOADER		
LOAD15	Albury - Workshop	Elect\START MOTR	Starter locked in mesh from faulty ignition switch		*P/O #T047817		14/09/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Albury Workshop	LOADER		
LOAD15	Wodonga - Workshop	Elect\BATTERY	Jump start truck		Replaced batteries		30/07/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER		
LOAD15	Wodonga - Workshop	Workshop\MOVE ASSET	Pick up from Wodonga Engineering & drop off at wodonga yard				25/07/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER		
LOAD15	Myrtleford - Workshop	DriCabRep\HOUSEKEEP	Refit interior lining. Flat roof lining falling in Adjust RH wiper arm and repair wiper jets				28/06/2019		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER		
LOAD15	Myrtleford - Workshop	DriCabRep\WIPERS	LH wiper arm missing and spline shaft worn. windscreen wiper blades				28/06/2019		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER		
LOAD15	Myrtleford - Workshop	Engine\FUEL TANK	Remov L & R fuel from tank & fill with Alpine Mix				28/06/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER		
LOAD15	Myrtleford - Workshop	Engine\HOUSEKEEP	Fit new hand throttle cable(T6492)				28/06/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER		
LOAD15	Myrtleford - Workshop	Engine\EXHAUST	Repair holes in exhaust(T6564)				28/06/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER		
LOAD15	Myrtleford - Workshop	Engine\MOUNTS	Modify hand throttle bracket				28/06/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER		
LOAD15	Myrtleford - Workshop	Brakes\AIR LEAK	Re kit valve(T6528)				28/06/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER		
LOAD15	Myrtleford - Workshop	Body\PAINT/REST	Wash Truck				28/06/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER		
LOAD15	Myrtleford - Workshop	DriCabRep\MOUNTS	replace RH bottom bonnet dick				21/06/2019		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER		
LOAD15	Myrtleford - Workshop	DriCabRep\HOUSEKEEP	repair globe box lid				21/06/2019		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER		
LOAD15	Myrtleford - Workshop	Engine\AIR LEAK	replace exhaust solenoid pressure regulator valve				21/06/2019		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER		
LOAD15	Myrtleford - Workshop	Engine\FUEL TANK	repair fuel leak at fuel filter supply line				21/06/2019		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER		
LOAD15	Myrtleford - Workshop	Steering\HOUSEKEEP	top up p/s fluid				21/06/2019		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER		
LOAD15	Myrtleford - Workshop	DrivLine\DRV LN SER	grease and check drive line				21/06/2019		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER		
LOAD15	Myrtleford - Workshop	DrCabElect\LELECT P&W	repair LH mirror, LHR park and LHF park light				21/06/2019		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER		
LOAD15	Myrtleford - Workshop	Body\DAMAGE	repair R/H tank step				21/06/2019		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER		
LOAD15	Myrtleford - Workshop	Elect\ELECT P&W	replaced truck clearance light				20/06/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER		
LOAD15	Myrtleford - Workshop	Engine\HOUSEKEEP	checked truck fluids ran out of fuel take 20 lts to Wodonga. Try - prime system would not prime get Wodonga w/shoo ute with compressor. Pressure tank. Prime system				20/06/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER		
LOAD15	Albury - Workshop	Engine\FUEL TANK	run test - ok replaced universal joint in jack shaft and fitted				07/05/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Albury Workshop	LOADER		
LOAD15	Albury - Workshop	Brakes\BRAKE ADJ	replaced RHS service brake hose on steer				10/04/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Albury Workshop	LOADER		
LOAD15	Albury - Workshop	DrivLine\DRV LN SER	tightened loose drive shaft flanges				10/04/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Albury Workshop	LOADER		
LOAD15	Albury - Workshop	Elect\TAIL LIGHT	repaired/replaced lights				10/04/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Albury Workshop	LOADER		
LOAD15	Albury - Workshop	Engine\HOUSEKEEP	degreased and washed				10/04/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Albury Workshop	LOADER		
LOAD15	Albury - Workshop	DrivLine\DRV LN SER	tightened through shaft				10/04/2019		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Albury Workshop	LOADER		
LOAD15	Rosewood - Workshop	Steering\STEER UNI	Steer Shaft Uni				16/02/2019	0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER		
LOAD15	Rosewood - Workshop	DrivLine\TAIL SHAFT	Tailshaft		tighten up loose tailshaft bolts		16/11/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER		
LOAD15	Rosewood - Workshop	VehService\BELTS/TENS	Belts & Tensioners		0 service completed		16/11/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER		
LOAD15	Rosewood - Workshop	Workshop\MOVE ASSET	travel to Greenhills across Rd. - replace elephants foot R/H/R. Travel to Tumut				04/10/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER		
LOAD15	Rosewood - Workshop	DrCabElect\CLUTCH	Fit new clutch servo & bleed		air leak air leaking around clutch cylinder servo replace servo bleed the system wasn't bleeding found that the master cylinder was faulty 28/11/18 replace master cylinder bleed the system tested ok		08/09/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER		
LOAD15	Rosewood - Workshop	DrCabElect\RADIO	phone not held in holder screws missing		repair phine holder and put phone back on holder		29/08/2018		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER		
LOAD15	Rosewood - Workshop	DrivLine\TAIL SHAFT	tighten loose tail shaft bolts				29/08/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER		
LOAD15	Rosewood - Workshop	Hydraulics\VALVES	replace pressure ref valve				29/08/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER		
LOAD15	Myrtleford - Workshop	Tyres\PRES CHECK	Job Added From Invoice				03/07/2018	0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER		
LOAD15	Myrtleford - Workshop	DrCabElect\HEATER REP	Repair heater fan		make new knot for heater fan speed		03/07/2018		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER		
LOAD15	Myrtleford - Workshop	DrCabElect\LELECT P&W	Repair wipers		fit 2 new wiper blades		03/07/2018		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER		
LOAD15	Myrtleford - Workshop	DrCabElect\UNIT/GAUGE	Repair dash & guage wiring T4534. Repair dash & guage wiring brakes would not release travel to Greenhill Forest Way find valve exhausting. remove valve and plug off. Tests ok.		repair 12v acc socket power supply		03/07/2018		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER		
LOAD15	Rosewood - Workshop	Brakes\BRAKE ADJ	Return to Rosewood				29/03/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER		
LOAD15	Rosewood - Workshop	Engine\BELTS/TENS	replace fan belts				21/03/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER		
LOAD15	Rosewood - Workshop	DrivLine\TAIL SHAFT	tighten tail shaft bolts				21/03/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER		
LOAD15	Rosewood - Workshop	Brakes\BRAKE ADJ	adjust brakes				21/03/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER		
LOAD15	Rosewood - Workshop	Engine\GOV VALVE	replace governor valve				21/03/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER		
LOAD15	Rosewood - Workshop	Tyres\DRV TYRES	Change flat tyre Travel to Mannos				14/03/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER		
LOAD15	Rosewood - Workshop	Body\HOUSEKEEP	Ran out of fuel. Transfere fuel to main tank from secondary.				14/03/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER		
LOAD15	Rosewood - Workshop	Chassis\KING PIN	check front end and check kingpins test ok				13/03/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER		
LOAD15	Rosewood - Workshop	Tyres\STEER TYRE	check steer tyres to see if they were true				13/03/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER		
LOAD15	Myrtleford - Workshop	Elect\INDICATORS	No indicators working		repair Tumut Auto Electrics		08/03/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER		
LOAD15	Albury - Workshop	VehService\BS	B SERVICE	VehService\BS	DONE BY ETS		02/03/2018		Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Albury Workshop	LOADER		
LOAD15	Tumut - Workshop	Body\HOUSEKEEP	30L engine oil out of store				02/03/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Tumut Workshop	LOADER		
LOAD15	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job				02/03/2018		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Tumut Workshop	LOADER		
LOAD15	Tumut - Workshop	VehService\BS	B Service on L-15 volvo	VehService\BS			02/03/2018		Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Tumut Workshop	LOADER		
LOAD15	Rosewood - Workshop	DrivLine\CLUTCH	truck hard to get into gear, truck turns off to get a gear				13/02/2018		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER		
LOAD15	Rosewood - Workshop	Engine\GOV VALVE	making too much air				13/02/2018		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER		
LOAD15	Tumut - Workshop	Air Con\AIR CON	aircon not working				01/02/2018		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Tumut Workshop	LOADER		
LOAD15	Tumut - Workshop	Elect\ELECT P&W	outer boom lights not working				01/02/2018		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Tumut Workshop	LOADER		
LOAD15	Albury - Workshop	Elect\BREAKDOWN	TRUCK WOULD NOT START IN THE TUMUT YARD.				15/12/2017		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Albury Workshop	LOADER		

LOAD15	Myrtleford - Workshop	Tyres	Job Added From Invoice			13/12/2017	742086	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Wodonga - Workshop	Body\PANELS	Pin joining dipper boom moved out broken keeper bolt		replace grab support shackle	09/12/2017		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
LOAD15	Rosewood - Workshop	Body\MOUNTS	shackle for cab		tighten inner door handle	21/11/2017		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
LOAD15	Albury - Workshop	Tyres\WIPERS	remove wipers from de-commissioned truck. Replace blades. Package for Rosewood			17/11/2017		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Albury Workshop	LOADER
LOAD15	Albury - Workshop	Engine\FAULT CODE	battery light on no power to guages or radio or blinkers lights			16/11/2017		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Albury Workshop	LOADER
LOAD15	Albury - Workshop	DrCabRep\DOOR LOCK	driver door handle need screws in it test batteries			16/11/2017		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Albury Workshop	LOADER
LOAD15	Myrtleford - Workshop	Elect\BATTERY	fit 2x new batteries			09/11/2017		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Rosewood - Workshop	Body\CHN/RLR/MN	replace rubber block on rear left diff housing to leaf spring at big horn			04/11/2017		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
LOAD15	Rosewood - Workshop	DrCabRep\DOOR LOCK	repair door handle			02/11/2017		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
LOAD15	Rosewood - Workshop	Body\MOUNTS	needs a step putting on drivers side to big of a step			19/10/2017		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Wodonga Workshop	LOADER
LOAD15	Rosewood - Workshop	Body\FUEL TANK	refit fuel tank			17/10/2017		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
LOAD15	Rosewood - Workshop	Elect\ELECT P&W	reset indicator c/b and test			17/10/2017		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
LOAD15	Rosewood - Workshop	Engine\JAKE BRAKE	check exhaust brake n/w correctly			17/10/2017		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
LOAD15	Rosewood - Workshop	Brakes\BRAKE ADJ	adjust brakes			04/10/2017		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
LOAD15	Rosewood - Workshop	Engine\JAKE BRAKE	check exhaust brake operation. Found circuit breaker popped reset. Test ok			04/10/2017		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
LOAD15	Rosewood - Workshop	Steering\TIE ROD	check tie rod end ect for wobble in steering			04/10/2017		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
LOAD15	Rosewood - Workshop	DrCabRep\DOOR LOCK	L/H door held closed by strap pulled out the lock/handle cleaned with brake clean and inoxs tested all good			22/09/2017		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Rosewood Workshop	LOADER
LOAD15	Albury - Workshop	DrCabRep\DOOR LOCK	LH DOOR NOT LOCKING. STRAP HOLDING DOOR SHUT		repaired LH door mechanism REPLACED INDICATOR SUPPLIED BY MYRTLEFORD.	10/09/2017		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Albury Workshop	LOADER
LOAD15	Albury - Workshop	Elect\INDICATORS	RHF INDICATOR MISSING OFF BONNET fit clip to acc pedal pin		Repalced broken RH par/indicator light assembly, replaced globes	05/09/2017		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Albury Workshop	LOADER
LOAD15	Myrtleford - Workshop	DrCabRep\MOUNTS	wash cab			03/08/2017		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	DrivLine\AIR LEAK	1/2 splitter not working check over			01/08/2017		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Body\HOUSEKEEP	wash truck and loader			16/07/2017		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Tyres\PRES CHECK	Job Added From Invoice			06/07/2017	0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Tyres	Job Added From Invoice			29/06/2017	0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice			29/06/2017	0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice			29/06/2017	0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			17/06/2017		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS		17/06/2017		Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	DrCabRep\HOUSEKEEP	Repair & refit sunvisor			10/06/2017		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	DrCabRep\HOUSEKEEP	remove sunvisor for repairs			09/06/2017		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Tyres	Job Added From Invoice			07/06/2017	0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Engine\COMPRESSOR	fit unloader spring return in compressor			30/05/2017		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Tyres\PRES CHECK	Job Added From Invoice			30/05/2017	732857	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Elect\TAIL LIGHT	no lights r/hand rear			16/05/2017		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Body\MOUNTS	repair grab stand			19/04/2017		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Body\KWC COMP	fit L/H do not overtake sign			08/04/2017		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Engine\FUEL TANK	RH fuel tank about to fall out			08/04/2017		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Elect\TAIL LIGHT	LHR clearance light missing			08/04/2017		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Tyres\TP01	Job Added From Invoice			07/04/2017	0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			06/04/2017		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS		06/04/2017		Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Engine\FILTERS	change fuel filters			17/02/2017	731966	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Engine\HOUSEKEEP	check engine oil and coolant			17/02/2017	731966	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Engine\HOUSEKEEP	run + check			17/01/2017	731554	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Chassis\HOUSEKEEP	fit new tow point to rear of truck			07/01/2017	731481	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Engine\BELTS/TENS	refit alternator belt			29/12/2016	731451	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Insp\ANN INSP	fit fire equipment			03/12/2016	73055	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Elect\HOUSEKEEP	check lights			03/12/2016	73055	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Brakes\BRK RELINE	Reline rear drive axle			30/11/2016	730831	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS		29/11/2016	730428	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			29/11/2016	730428	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Tyres\TP07	Job Added From Invoice			26/11/2016	429297	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Tyres\TP03	Job Added From Invoice			26/11/2016	729623	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Engine\HOUSEKEEP	Air throttle assist valve sticking			03/11/2016	730360	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Body\MUDGUARDS	Repair RH steer mudflap		Adjuste idle rod replace worn rose joint fit new return spring	03/11/2016	730360	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Engine\HOUSEKEEP	truck idling to high. truck idling to high.		Complete	31/10/2016	729091	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Body\HOUSEKEEP	Wash truck - oil leak		Complete	31/10/2016	729091	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Steering\PWR STEER	bleed pls box top up fluid			26/10/2016	728032	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Body\DAMAGE	make new front bumper brackets & new power steer pipe & fittings & refit grab			26/10/2016	728032	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Steering\PWR STEER	bleed power steering system			25/10/2016		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Body\DAMAGE	Refit & modify front bumper & grab stand mount			21/10/2016	728032	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Susp\SPRNG HANG	Remove LHS broken spring hanger & fit 2nd hand spring hanger		Complete Travel to Shelley. Remove grab and dismantle boom support so truck could be returned to workshop. Drop off at Arkon	19/10/2016		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Albury - Workshop	Chassis\BULLBAR	Front bumper/boom support broken off truck.		Repair works to be completed at Myrtleford work shop. travel to Koetong, fuel & bleed engine replaced fuel filters replaced fuel return spring repaired broken horn wiring repaired wiper adjusted hand idle cable	15/10/2016		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Albury Workshop	LOADER
LOAD15	Albury - Workshop	Engine\FUEL TANK	Ran out of fuel @ Koetong.		checked steering kingpins	13/10/2016		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Albury Workshop	LOADER
LOAD15	Myrtleford - Workshop	Tyres\STEER TYRE	Job Added From Invoice			12/10/2016	726570	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Albury - Workshop	DrCabRep\SEAT	Had to move drivers seat. No adjustment		relocate seat	11/10/2016	727730	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Albury Workshop	LOADER
LOAD15	Myrtleford - Workshop	DrCabElect\INST/GAUGE	Repair temperature guage			06/10/2016	728025	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	DrCabRep\WIPERS	Repair broken drivers side wiper		Complete	04/10/2016	726261	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	DrCabElect\INST/GAUGE	Repair fuel guage		Complete Driver to monitor	04/10/2016	726261	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Engine\FUEL TANK	Fuel tank movement		Complete	04/10/2016	726261	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Steering\HOUSEKEEP	Check front end shake when driving		Complete	04/10/2016	726261	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Engine\HOUSEKEEP	Check hand throttle - not working		Complete	04/10/2016	726261	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	DrCabElect\PHONE	Phone not working & loose bracket		Complete	04/10/2016	726261	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Insp\ANN INSP	annual inspection as per check list	Insp\ANN INSP		27/09/2016	724860	PreventativeMaintenance	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			27/09/2016	724860	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS		27/09/2016	724860	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Engine\FUEL TANK	fit new fuel lift pump			13/09/2016	723767	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Engine\OIL LEAK	repair turbo oil feed hardline			13/09/2016	723767	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Engine\HOUSEKEEP	wash engine			13/09/2016	723767	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Chassis\AIR LEAK	air leak between chassis			01/09/2016	727831	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Engine\FUEL TANK	remove & clean out fuel tank & clean fuels from tank to engine			30/08/2016	722368	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Engine\FILTERS	fit 2x new fuel filters			30/08/2016	722368	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Engine\FUEL TANK	fit 2nd lift pump			30/08/2016	722368	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Engine\HOUSEKEEP	steam clean motor			30/08/2016	722368	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Susp\SHOCK ABS	Replace front diff vee stay assembly			06/08/2016	722365	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			04/08/2016	719750	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS	wash down truck	04/08/2016	719750	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	DrCabRep\HOUSEKEEP	refit screw to gearstick knob			28/07/2016	718648	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Elect\TAIL LIGHT	short in wiring to tail lights and side lights			20/07/2016	718305	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	DrCabElect\PHONE	phone still doesn't work			20/07/2016	718305	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	DrCabElect\PHONE	Remove Phone & send for repairs		refit repaired phone Reset phone, remove sim card and replace with spare phone. Send original phone for repairs	22/06/2016	718305	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	DrCabElect\PHONE	Phone will not read sim card		Complete	20/06/2016	716556	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Comp	Fit Truckafe Label		Complete	20/06/2016	716556	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			17/06/2016	716555	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS		17/06/2016	716555	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Body\HOUSEKEEP	wash truck			16/06/2016	716555	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	DrCabRep\WIPERS	replace wiper blades			16/06/2016	716555	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Engine\OIL LEAK	wash down engine			24/05/2016	715538	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Body\HOUSEKEEP	wash truck + clean cabin fit new compressor governor valve			24/05/2016	715538	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Engine\COMPRESSOR	check unloading system			07/05/2016	715267	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	DrCabRep\HOUSEKEEP	repair glove box catch			07/05/2016	715267	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Elect\DRV LIGHT	remove + refit driving light			07/05/2016	71526	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Elect\WORK LIGHT	wire up new rear tail light bar work light			06/05/2016	715261	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Engine\GOV VALVE	fit new governor valve for air compressor			06/05/2016	715261	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	DrCabElect\INDICATORS	Replace RHF bonnet indicator			04/05/2016	715260	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Brakes\BRK RELINE	Reline front drive axle			04/05/2016	715260	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER

LOAD15	Myrtleford - Workshop	VehService\BS	VehService\BS	VehService\BS		19/04/2016	715125	Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Brakes	check and record brakes			19/04/2016	715125	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	DrCabElect\PHONE	Repair Phone screen		fit phone out of fleet 856 into L-15	31/03/2016		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Engine\HOUSEKEEP	Check exelerator - sticking		replace both fuel filters	31/03/2016		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Tyres\STEER TYRE	Check steering - vibration		Complete	29/03/2016		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Tyres\DRV TYRES	Job Added From Invoice			16/02/2016	0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS		11/02/2016		Service	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			11/02/2016		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	DriCabRep\HOUSEKEEP	Re-fit gauge panel. Re-fit guage panel		Completed	11/02/2016		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	DrCabElect\INST/GAUGE	Check gauge lights. Check guage lights		Completed	11/02/2016		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	DriCabRep\HOUSEKEEP	Steam clean truck cabin & bonnet		completed	03/02/2016		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	DrCabElect\PHONE	phone screen goes blank and can't use		re-set phone (using red off button) completed	02/02/2016		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Tyres\STEER TYRE	steering shakes badly between 80-90km/hour		check steering - true up both steer wheels fit new wheel stud clamp completed	02/02/2016		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Body\HOUSEKEEP	grease & inspect truck undercarriage		completed	13/01/2016		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Elect\HOUSEKEEP	check lights		completed	13/01/2016		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	DriCabRep\WIPERS	repair wiper washers no reception on truck phone		completed	13/01/2016		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	DriCabRep\RADIO	replace & fit phone aerial cord through pipe in door		completed	19/12/2015		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	DriCabRep\WIPERS	replace wiper blades		completed	19/12/2015		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	DrivLine\GEARBOX	check gearbox oil replace RHR side marker bracket		completed	19/12/2015		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	DriCabRep\ELECT P&W	remount LED interior light - loose adjust transmission splitter lever replace bolt in lh radio speaker repair light switch on dash not working repair rev counter not working		completed completed	19/12/2015		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	DriCabRep\DAMAGE	repair altenator wiring loom + rubbed wires on fuel guage repair indicators not working repair horn not working replace rh zebra sign		driver to moniter	04/12/2015		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Elect\ELECT P&W	repair rhr side marker not working		compelted	20/11/2015		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Chassis\AIR LEAK	repair diff lock air fitting		completed	12/11/2015		Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Susp\SUSPENSION	Job Added From Invoice			24/09/2015	0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Susp\SWAYBAR	Job Added From Invoice replace t/shaft c/bearing			19/09/2015	0	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Chassis	replace lhf sway bar bush		completed	08/09/2015		Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER
LOAD15	Myrtleford - Workshop	Insp\ANN INSP	annual inspection as per check list	Insp\ANN INSP	completed	02/09/2015	706755	PreventativeMaintenance	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR	DPX230	Myrtleford Workshop	LOADER