EquipmentName	Workshop	CodeAndSubCode	Description	Schedule	CompletionComments	DateDone	HourDone	Worktype	Workstate	EquipmentOwner	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
P17	Myrtleford - Workshop	Body\HOUSEKEEP	CHECK OVER FLUID LEVELS AND GREASE LOADER CHECK ENGINE NOISE		HRS AT TIME OF CHECK OVER 2216 COLD START ENGINE & CHECK FOR NOISE & MISS ALL OK AT THIS STAGE	23/06/2026	2216	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Engine\BELTS/TENS	REPLACE FAN & A/CON BELTS REMOVE HYD PUMP AND REPLACE WITH ONE FROM P18 REPLACE HYD FILTER AND PILOT FILTER		CHECK ALL FLUID LEVELS ALSO	10/04/2026	2176	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\PUMP	HRS AT TIME OF REPLACEMENT 2176			16/01/2026	2176	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Engine\HOUSEKEEP	CHECK FLUIDS AND ALL LEVELS			10/10/2025	2150	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Chassis\Boom	SUPPLY & FIT GRAB LOCKING SYSTEM TO OUTER BOOM REPAIR LEAKING MAIN LIFT RAMS		Dismantle qty of lift cylinders, run test hone to determine good barrels. Clean up all parts and hone barrels, repair scuffs and dings in rods, reassemble cylinders with seals supplied, replace sphericals and paint. Including work already performed. 618.75 1 set of hone stones 28.75 GEZ208 2 184.75 369.50	04/07/2025	2095	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		RINLATECH ENGINEERING-3	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\RAM			misc items including honeing fluid, abrasives and coatings	04/07/2025	2095	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR		RINLATECH ENGINEERING-3	PRENTICE
P17	Myrtleford - Workshop	Elect\WORK LIGHT	REPAIR LEFT HAND SIDE BOOM LIGHTS <

			check oil and coolant															
P17	Myrtleford - Workshop	Engine\HOUSEKEEP	check lights			11/12/2021	1379	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Engine\FUEL TANK	loader run out of fuel could not prime to shoot back up. Call out		prime and bleed fuel system	07/12/2021	1378	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Engine\BREAKDOWN	travel to Wandi and back			07/12/2021	1378	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Engine\HOUSEKEEP	check oil and coolant			24/11/2021	1372	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Chassis\HOUSEKEEP	grease loader and grab			24/11/2021	1372	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Engine\HOUSEKEEP	check oil and coolant			21/10/2021	1364	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Chassis\DAMAGE	L/H rear leg pin broken grease loader			23/09/2021	1359	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Body\HOUSEKEEP	weld cracked walking deck			23/09/2021	1359	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Hydraulics\HYD LEAKS	replace hyd pipe outer boom			17/08/2021	1313	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Engine\OIL LEAK	remove pilot pump to be resealed			17/08/2021	1313	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Engine\OIL LEAK	refit pilot pump and test			17/08/2021	1313	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Body\PAINT/REST	paint loader guards			17/08/2021	1313	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	DriCabRep\HOUSEKEEP	Seal around front windscreen. windscreen needs reseal			20/07/2021	1313	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Hydraulics\VALVES	check slew & pressure		ok from now only spare loader	20/07/2021	1313	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Engine\ELECT P&W	check and repair starting problems			20/07/2021	1300	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Elect\ELECT P&W	repair loose wiring on starter motor			20/07/2021	1300	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Chassis\HOUSEKEEP	loader needs a grease			16/07/2021	1294	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Chassis\HOUSEKEEP	2-3 grease nipple on legs need replacing, 2-3 grease nipple onlegs need replacing			16/07/2021	1294	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Engine\BATTERY	jump start prentice and charge batteries			16/07/2021	1294	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Hydraulics\VALVES	check slew operation. Replace pin at slew valve may need to be pressure checked			14/07/2021	1273	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Engine\BELTS/TENS	replace fan belt			24/06/2021	1249	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Hydraulics\VALVES	remove joystick swivel plate clean up readjust x2			19/06/2021	1248	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Hydraulics\DAMAGE	fitted new grip LHS and arm rest bushes and shut			19/06/2021	1248	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Chassis\HOUSEKEEP	REPAIR BOOM STAND CRACKS			17/06/2021		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Chassis\DAMAGE	REPAIR CRACKS IN GRAB			17/06/2021		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Hydraulics\HYD LEAKS	REPLACE HYDRAULIC TANK SIGHT GLASS			17/06/2021		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Elect\WORK LIGHT	REPLACE CAB STROBE LIGHT			17/06/2021		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Hydraulics\PUMP	REPLACE LEAKING TRIPPLE PUMP FRONT SEAL			17/06/2021	1248	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS	replace bolts in tank mounts	16/06/2021	1236	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	DriCabRep\HOUSEKEEP	RESEAL FRONT WINDSCREEN IN LOADER			10/06/2021	1214	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Hydraulics\HOSES	REPLACE WORN BOOM TO GRAB HOSE			10/06/2021	1214	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Engine\HOUSEKEEP	check oil			04/06/2021	1128	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Engine\HOUSEKEEP	check coolant			04/06/2021	1128	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Elect\WORK LIGHT	check boom lights			04/06/2021	1128	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	DrCabElect\RADIO	loader UHF handpiece holder missing screw			29/05/2021	1175	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	DrCabElect\AIR CON	a/c in loader not working			29/05/2021	1175	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Engine\HOUSEKEEP	check water in truck			29/05/2021	1175	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Hydraulics\HYD LEAKS	REPAIR HYDRAULIC LEAK AT TRIPPLE PUMP AND CHECK HOSES AND ORINGS		wash down pump, need to recheck	26/05/2021	1236	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Hydraulics\RAM	grab screw missing ram pin in grab			25/05/2021	1139	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Chassis\HYDRAULICS	main grab pin bushes coming out			25/05/2021	1139	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Body\DAMAGE	bend walkway back and reweld crack			21/05/2021	1125	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
					test hydraulic pressures													
					-slew pressure at 1000psi should be at 2400psi													
					-main lift at 1600psi should be at 2200psi													
					-dipper pressure ok at 2300psi													
P17	Myrtleford - Workshop	Hydraulics\VALVES	HYDRAULICS ARE SLOW		-servo pressure ok at 440psi	19/05/2021	1119	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Body\HOUSEKEEP	CRACK IN HYDRAULIC TANK		mounting bolts loose	19/05/2021	1119	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Hydraulics\OIL LEAK	hyd leak top of tank			18/05/2021	1118	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Workshop\MOVE ASSET	swap loaders			18/05/2021	1118	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Hydraulics\OIL/FILTER	R&R hyd filter			18/05/2021	1117	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Hydraulics\OIL/FILTER	top up hyd oil			18/05/2021	1117	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Hydraulics\PUMP	clean and deliver hyd pump			18/05/2021	1117	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	DrCabElect\AIR CON	A/C NOT WORKING		make up new hose and regas system	18/05/2021	1129	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	DrCabElect\HEATER REP	FIT KNOB TO HEATER CONTROLLER		has manual heat taps fitted on engine heater holes	18/05/2021	1129	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Hydraulics\HOSES	blown hyd hose under boom/cab			13/05/2021	11044	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	VehService\BS	B Service As Per Attached Checklist	VehService\BS		04/05/2021	1038	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Chassis\DAMAGE	Broken leg ram pin LHR			01/05/2021	1027	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Chassis\HOUSEKEEP	grease loader			27/04/2021	1005	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Hydraulics\HOSES	tighten/check fitting on grab rotator/open shut			21/04/2021	9884	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	DriCabRep\DOOR LOCK	Fit door dampner strut			20/04/2021	1358	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	DrCabElect\RADIO	UHF aerial missing		UHF antenna	17/04/2021		Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Chassis\HOUSEKEEP	hard to get grease in LHR leg main pins		LHR leg pin not taking grease	17/04/2021		Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Chassis\HOUSEKEEP	hard to get grease top main lift pin		top main lift pin not taking grease	17/04/2021		Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Hydraulics\HOSES	blown rotao hose		hyd hose at blower	17/04/2021		Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Chassis\HOUSEKEEP	grease loader			17/04/2021		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Wodonga - Workshop	Hydraulics\VALVES	fit new pluggers and seals to RH servo handle			14/04/2021	964	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Wodonga Workshop	PRENTICE			
P17	Myrtleford - Workshop	Chassis\DAMAGE	L17 crack around main lift pin RHS + crack near grab pin bottom		weld piuns main lift	02/04/2021	924.6	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	DrCabElect\RADIO	complaints of UHF hard to understand trouble starting loader "like flat batteries"		fit UHF radio and test check terminals and load	02/04/2021	924.6	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Elect\ELECT P&W	just clicking (only once)		test battery	02/04/2021	924.6	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Chassis\DAMAGE	cracks in boom cradle		welding grapple pin	02/04/2021	924.6	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Chassis\HOUSEKEEP	one box of grease		grease nipples in grab	02/04/2021	924.6	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Engine\BREAKDOWN	replace fuel lift pump			02/04/2021	924.6	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Elect\WORK LIGHT	fit work light to boom		fit narva work lamp	02/04/2021	924.6	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Body\MOUNTS	fit bolts to front cowl/radiator mount			02/04/2021	924.6	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Hydraulics\VALVES	RH servo (2nd hand one) sticking and leaking oil		replace servo with second hand one	27/03/2021	909	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Air Con\AIR CON	aircon drain maybe blocked		aircon drain	27/03/2021	909	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Hydraulics\VALVES	sticky servo RHS. sticker servo RHS			25/03/2021	895	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Air Con\AIR CON	aircon stopped working			25/03/2021	895	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Body\WINDSCREEN	windscreen needs reseal			25/03/2021	895	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Body\HOUSEKEEP	slew peddels so much movement and replace rose joint		slew pedal play	20/03/2021	873	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Hydraulics\HYD LEAKS	RH servo sticking		servo seals	20/03/2021	873	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Hydraulics\HOSES	hyd hose			18/03/2021	86401	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Body\HOUSEKEEP	grease nipple			18/03/2021	86401	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Hydraulics\HYD LEAKS	grab swivel			16/03/2021	860	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Body\CHN/RLR/MN	fit D shackle to grab chain			16/03/2021	860	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Body\HOUSEKEEP	wash grab recheck hyd oil			16/03/2021	860	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Hydraulics\HYD LEAKS	REPAIR HYD LEAK BETWEEN ENGINE AND TIPPER PUMP			11/03/2021	1117	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	DriCabRep\MOUNTS	weld up log guard for window			06/03/2021	833	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Wodonga - Workshop	Engine\OIL LEAK	WASH DOWN ENGINE AND HYDRAULIC PUMP AND INSPECT OIL LEAK		engine leak nothing there	06/03/2021	833	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Wodonga - Workshop	DriCabRep\WIPERS	MAKE UP WASHER BOTTLE MOUNT BRACKET			06/03/2021	833	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Unknown - Unknown	VehService\BS	Service As Per Attached Checklist	VehService\BS	replaced boom light bracket	05/03/2021	825	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Body\MOUNTS	weld grab pin bush back in			03/03/2021	813	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Hydraulics\HOSES	replace hyd hose			03/03/2021	813	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Engine\FUEL TANK	replace fuel drain back valve			26/02/2021	797	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Hydraulics\OIL/FILTER	top up hyd oil			25/02/2021	792	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Hydraulics\VALVES	Fit seal kit to grab hose swivel			25/02/2021	964	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Hydraulics\RAM	leaking RH main lift ram		fit re-cored RH main lift ram	24/02/2021	497298	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Chassis\HOUSEKEEP	grease			18/02/2021		Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Engine\HOUSEKEEP	check fluids			18/02/2021		Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	DrCabElect\UNST/GAUGE	R&R horn			23/12/2020	735	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	DrCabElect\UNST/GAUGE	R&R decals on switches and globes			23/12/2020	735	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	DriCabRep\WIPERS	windscreen wipers not working			23/12/2020	735	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Hydraulics\OIL/FILTER	top up hydraulic oil			23/12/2020	735	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Hydraulics\RAM	outer boom ram broken			19/12/2020	735	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	DrCabElect\AIR CON	replace a/con compressor and dryer and regas system			17/12/2020	725	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Hydraulics\MOTOR	replace slew motor seal			16/12/2020	719	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Hydraulics\HYD LEAKS	repair hyd spool bank oil leak			16/12/2020	719	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Chassis\DAMAGE	replace slew ring broken bols			16/12/2020	719	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Engine\HOUSEKEEP	check fluids			16/12/2020	719	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Chassis\DAMAGE	RHR leg pin replaced			16/12/2020	719	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Chassis\HOUSEKEEP	greased			16/12/2020	719	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Engine\OIL LEAK	Replace Fuel Lift pump		wash engine and test	16/10/2020	661	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
					light faulty, needs replacing													
P17	Myrtleford - Workshop	Elect\WORK LIGHT	Check cab light bar and wiring		replaced light bar	16/10/2020	661	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS		15/10/2020	634	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Chassis\HOUSEKEEP	grease prentice			14/10/2020	620	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Hydraulics\BREAKDOWN	blown hose			13/10/2020	607	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Chassis\DAMAGE	replace broken leg pin RHR			13/10/2020	607	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	DriCabRep\WINDSCREEN	Replace Windscreen			10/10/2020	719	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	DriCabRep\SEAT	Replace Arm Rest Struts			10/10/2020	719	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Chassis\HOUSEKEEP	grease loader			09/10/2020	590	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	DrCabElect\UNST/GAUGE	fix all none working dash light			09/10/2020	590	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Engine\FILTERS	replace precleaner bowl			09/10/2020	590	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	Elect\ELECT P&W	tighten battery terminals			09/10/2020	590	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			
P17	Myrtleford - Workshop	DrCabElect\ELECT P&W	tidy up wiring in roof			09/10/2020	590	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE			

P17	Myrtleford - Workshop	Engine\FILTERS	clean air filter pre cleaner and clean air filter			06/10/2020	535	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Chassis\CHAS CRACK	repair major crack in crane bass			03/10/2020	535	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Chassis\DAMAGE	replace main boom pin and bushes			03/10/2020	535	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Chassis\DAMAGE	replace bottom and top main lift pins in bass and boom			03/10/2020	535	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Chassis\DAMAGE	replace stick boom bushes and pins			03/10/2020	535	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Chassis\DAMAGE	replace any worn ram bushes			03/10/2020	535	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Engine\HOUSEKEEP	check fluid			03/10/2020	565	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Elect\WORK LIGHT	check lights			03/10/2020	565	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Elect\WORK LIGHT	re-wire light bar			03/10/2020	565	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Body\MOUNTS	a/c compressor main pivot bolt loose/stripped		replace adjusting brackets off P-12	17/09/2020	535	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
					check, photograph and report to Wayne re-cracked boom										
P17	Rosewood - Workshop	Chassis\DAMAGE	Remove Main Boom and Repair Cracks		fit new main pin and 5 bushes	16/09/2020	535	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
			diagnose and repair hydraulic leak at valve												
			(was a broken o-ring)												
			check oil												
P17	Rosewood - Workshop	Hydraulics\HYD LEAKS	clean up			09/09/2020	530	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Rosewood Workshop	PRENTICE
P17	Rosewood - Workshop	Chassis\DAMAGE	broken top left leg pin		TCTC replaced top left leg pin with me	05/09/2020	506	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Rosewood Workshop	PRENTICE
			-call out to Gerards, coolant leak below cab. Driver said heater taps were off												
			-upon inspection fround 1 tap still on. Turned off												
			-leak seems to be from heater area												
P17	Rosewood - Workshop	Engine\COOL LEAKS	-observed loader for 2 bays of loading and rechecked. All good			29/08/2020	428	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Rosewood Workshop	PRENTICE
P17	Rosewood - Workshop	DrCabElect\HEATER REP	heater leak needs furthers diagnosis			29/08/2020	428	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Rosewood Workshop	PRENTICE
P17	Rosewood - Workshop	VehService\BS	Service Due 6hrs	VehService\BS	B Service	28/08/2020	428	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Rosewood Workshop	PRENTICE
P17	Rosewood - Workshop	Chassis\DAMAGE	TCTC replace leg pin			19/08/2020	342	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Rosewood Workshop	PRENTICE
P17	Rosewood - Workshop	Hydraulics\RAM	replace grab ram with TCTC			19/08/2020	342	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Rosewood Workshop	PRENTICE
P17	Rosewood - Workshop	Hydraulics\RAM	grapple ram leaking bad oil all over windscreen			18/08/2020	333	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Rosewood Workshop	PRENTICE
P17	Rosewood - Workshop	Chassis\DAMAGE	rear LHS leg pin broken			18/08/2020	333	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Rosewood Workshop	PRENTICE
P17	Rosewood - Workshop	Hydraulics\RAM	double side prong ram leaking on grab			18/08/2020	333	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Rosewood Workshop	PRENTICE
P17	Rosewood - Workshop	Engine\EXHAUST	broken muffler		remove muffler assembly from P14 and fit to P17	14/08/2020	303	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Rosewood Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\HOSES	make up hyd hoses			14/08/2020	194	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Wodonga - Workshop	Hydraulics\RAM	main boom and outer boom pins have excessive movement		RR's pre Jan 20 (system clean out) 05/08/20	06/08/2020		Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Wodonga Workshop	PRENTICE
P17	Wodonga - Workshop	Hydraulics	hydraulic very slow and not good pressure in grab			06/08/2020		Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Wodonga Workshop	PRENTICE
P17	Rosewood - Workshop	Engine\ELECT P&W	loader hard to start			01/08/2020	190	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Rosewood Workshop	PRENTICE
P17	Rosewood - Workshop	Body\CHN/RLR/MN	lost bolt out of "D" holding grab up			01/08/2020	190	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Rosewood Workshop	PRENTICE
P17	Rosewood - Workshop	Body\MOUNTS	a/c compressor main pivot bolt loose/stripped			01/08/2020	190	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Rosewood Workshop	PRENTICE
P17	Rosewood - Workshop	VehService\BS	Service Due	VehService\BS	B Service	01/08/2020	190	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Rosewood Workshop	PRENTICE
P17	Rosewood - Workshop	DrCabRep\RADIO	repair, refabricate UHF mic hanger			25/07/2020	118	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Rosewood Workshop	PRENTICE
P17	Albury - Workshop	Chassis\HYDRAULICS	blown hydraulic line at Gadd Rd. measured lines on like machine in yard			25/06/2020		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Albury Workshop	PRENTICE
P17	Albury - Workshop	Workshop\MOVE ASSET	travelled to and from Gadd Rd.			25/06/2020		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Albury Workshop	PRENTICE
P17	Albury - Workshop	Chassis\HYDRAULICS	made temporary repairs to line to get machine in position. Replaced entire line			25/06/2020		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Albury Workshop	PRENTICE
			travelled to P23 on Edmonson's Rd. to retrieve more oil												
P17	Albury - Workshop	Workshop\MOVE ASSET	topped up and tested			25/06/2020		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Albury Workshop	PRENTICE
P17	Albury - Workshop	Chassis\HYDRAULICS	replaced oil for P23			25/06/2020		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Albury Workshop	PRENTICE
P17	Albury - Workshop	Chassis\HYDRAULICS	supplied oil for P17			25/06/2020		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Albury Workshop	PRENTICE
P17	Myrtleford - Workshop	DrCabElect\RADIO	replace UHF turning knob channel - goes any which way (channels) - need aerial		fit c/over UHF and antenna	03/06/2020	9976	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	DrCabElect\RADIO	fit UHF aerial			03/06/2020	9976	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Body\HOUSEKEEP	c/over			03/06/2020	9976	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Chassis\DAMAGE	RH rear leg pin broken		replace u/s RHR leg ram pin	03/06/2020	9976	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Chassis\HOUSEKEEP	grease prentice			03/06/2020	9976	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
					replace exhaust mount										
					repair window washer										
P17	Myrtleford - Workshop	VehService\BS	B Service As Per Attached Checklist	VehService\BS	replace hyd filter	02/06/2020	9976	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Elect\WORK LIGHT	bar light on cab needs moving		fit new boom light	12/05/2020	9908	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\HYD LEAKS	bad oil leak in grab			12/05/2020	9908	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Elect\WORK LIGHT	L.boom light needs replacing			12/05/2020	9908	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Chassis\HOUSEKEEP	grease loader			12/05/2020	9908	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Engine\EXHAUST	fitted rain cap to exh			12/05/2020	9908	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\OIL LEAK	fit seal to gram hose swivel			30/04/2020	9908	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Rosewood - Workshop	Chassis\HOUSEKEEP	grease loader and check over			15/04/2020	9884	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Rosewood Workshop	PRENTICE
P17	Albury - Workshop	VehService	ORDER FILTERS			01/04/2020		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Wodonga Workshop	PRENTICE
P17	Albury - Workshop	Hydraulics\HOSES	have Enzed make up hyd hose raise PO			01/04/2020		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Wodonga Workshop	PRENTICE
P17	Albury - Workshop	Hydraulics\VALVES	right hand servo sticking (slow)			24/03/2020	9796	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Albury Workshop	PRENTICE
P17	Albury - Workshop	Elect\WORK LIGHT	refit light bar (behind driver seat)		reattach light bar above cabin and test - ok	24/03/2020	9796	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Albury Workshop	PRENTICE
P17	Albury - Workshop	Brakes\BRK O/HAUL	dismantled RH handpiece, replaced plunger o-rings, cleaned, assemble and adjust			24/03/2020	9796	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Albury Workshop	PRENTICE
					check engine - stop engine on can't plug in										
					manually extracted code										
					checked wiring and crank sensor										
					found crank sensor failed										
			engine fault code 284		ordered sensor - delivered with Cummins mechanic										
P17	Albury - Workshop	Engine\FAULT CODE	engine crank postion censor short		assisted Cummins checked and repaired old faults	07/03/2020	9713	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Albury Workshop	PRENTICE
P17	Myrtleford - Workshop	Chassis\HOUSEKEEP	weld crack up in grapple			04/03/2020		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
			check and fill engine oil												
P17	Myrtleford - Workshop	Engine\HOUSEKEEP	check coolant			19/02/2020	9660	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\RAM	grab pin bush is rooted		grab has been repaired and changed	29/01/2020	9660	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	DrCabRep\RADIO	UHF gets bad range			29/01/2020	9660	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Chassis\HYDRAULICS	change over and test grapple			24/01/2020	9642	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\RAM	RHF support leg remove c/y to be resealed L7956			24/01/2020	9642	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Engine\ENG TUNE	engine miss five djust valves (tune up)(L7771)			24/01/2020	9642	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\HYD LEAKS	Replace slew motor seal		removed old slew motor clean up area fitted new resealed motor washed down started and tested all good	17/12/2019	9642	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Chassis\HOUSEKEEP	grab scissor pin fogged out			14/12/2019	9565	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Elect\BATTERY	check batteries - very slow cranking		replaced battery and test charging system	14/12/2019	9565	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	DrCabElect\RADIO	fit bluetooth stereo		replaced radio and aerial with new bluetooth unit	14/12/2019	9565	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Elect\WORK LIGHT	fit light bar			14/12/2019	9565	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\HOSES	Replace hose and pipe clamps at battery box		removed clamp from other loader got template made to make new one's fitted clamp removed from P16 to P17	06/12/2019	9642	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
					carry out B Service as per sheet #114061										
P17	Myrtleford - Workshop	VehService\BS	B Service As Per Attached Checklist	VehService\BS	grapple head need's bushing at a later date (WD)	05/12/2019	9542	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Elect\BATTERY	start and test battery			04/12/2019	9537	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Elect\HOUSEKEEP	put battery on charge			04/12/2019	9537	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Engine\HOUSEKEEP	check oil and water			04/12/2019	9537	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Elect\WORK LIGHT	check lights			04/12/2019	9537	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Albury - Workshop	Hydraulics\RAM	REPLACED GRAB RE ROUTED HOSE		TESTED & GREASED	29/11/2019		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Albury Workshop	PRENTICE
					REPAIRED CRACKS IN GRAB										
P17	Albury - Workshop	Hydraulics\RAM	DEGREASED WASHED & INSPECTED CHANGE OVER GRAB ASSEMBLY		REPAIRED PIN KEEPER	16/11/2019		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Albury Workshop	PRENTICE
P17	Rosewood - Workshop	Engine\HOUSEKEEP	CHECK HYD OIL LEVEL			12/11/2019		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Rosewood Workshop	PRENTICE
P17	Rosewood - Workshop	Hydraulics\MOTOR	TEST RAM & LISTEN FOR NOISE SLEW GEAR,SLEW MOTOR LEAKING & STARTING TO GET NOISY			12/11/2019		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Rosewood Workshop	PRENTICE
P17	Rosewood - Workshop	Body\TRL LEGS	REPLACE BROCKEN LEG PIN			11/11/2019		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Rosewood Workshop	PRENTICE
			BUSH WORN IN GRAB PIVOT,INSPECTED & GREASED												
P17	Rosewood - Workshop	Hydraulics\RAM	NO NEW PARTS IN STOCK		ATTEMPTED TO GRT OLD SERVICEABLE BUSH FROM P14 OUT THE BACK BUT UNABLE DESPITE MULTIPLE EFFARTS (	06/11/2019	8117	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Rosewood Workshop	PRENTICE
P17	Myrtleford - Workshop	DrCabElect\LELECT P&W	fit new strob light			17/10/2019	9406	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Elect\WORK LIGHT	replace top work lights globes blown			15/10/2019	9398	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	DrCabRep\WIPERS	broken wiper washer nozzle			03/10/2019	9406	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Chassis\HOUSEKEEP	LHR leg pin cracked & bolt broken			03/10/2019	9406	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\RAM	leaking leg ram RH rear			03/10/2019	9406	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\HYD LEAKS	grapple leaking oil			03/10/2019	9406	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\HYD LEAKS	L/H servo plunges leaking oil		fit seals to LH & RH servo's	03/10/2019	9406	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Body\OH&S	straighten R/H deck plate			03/10/2019	9406	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\OIL LEAK	slew motor leaking oil onto deck		check slew seal (ok) fit new bolt on slew gear	03/10/2019	9406	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	DrCabRep\HOUSEKEEP	replace L/H joy stick grip		fit new hand grip to LH joy stick	03/10/2019	9406	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
					fit new pin and bosses to cab frame										
P17	Myrtleford - Workshop	Hydraulics\RAM	excessive movement in main boom pin (T7172). excessive movement in main boom pin		also fit 3x boom bushes	03/10/2019	9406	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	DrivLine\OIL LEAK	servo's leaking oil badly, plungers stick down		fit seals to LH & RH servo's	03/10/2019	9406	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	DrCabElect\RADIO	UHF in loader RS, having trouble getting channels			03/10/2019	9406	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Engine\HOUSEKEEP	checked oil/coolant			19/09/2019	9350	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Chassis\HOUSEKEEP	greased			19/09/2019	9350	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Elect\WORK LIGHT	checked lights			19/09/2019	9350	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Elect\BATTERY	swapped out battery out of P16			19/09/2019	9350	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Rosewood - Workshop	Hydraulics\RAM	excessive movement in main boom pin		check and video excessive main boom pivot. Excessive movement evident	27/08/2019	9319	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Rosewood Workshop	PRENTICE
P17	Rosewood - Workshop	Susp\SUSPENSION	check leaf spring for cracks noticed in drivers daily inspection. Photographed			27/08/2019	9319	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Rosewood Workshop	PRENTICE
P17	Rosewood - Workshop	Workshop\CLEAN	sent video and pics to C. Jones and W. Dela Rue			27/08/2019	9319	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Rosewood Workshop	PRENTICE
P17	Rosewood - Workshop	Workshop\MOVE ASSET	travel to Mundaroo and back			27/08/2019	9319	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Rosewood Workshop	PRENTICE
P17	Albury - Workshop	Elect\BATTERY	SUPPLY BATTERY AND STARTER TO ROSEWOOD			24/08/2019		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Albury Workshop	PRENTICE
P17	Rosewood - Workshop	Body\HOUSEKEEP	degrease and wash down loader from oil spill			14/08/2019	9245	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Rosewood Workshop	PRENTICE
P17	Rosewood - Workshop	Body\DAMAGE	remove broken leg foot and weld up collect refit and test			14/08/2019	9245	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Rosewood Workshop	PRENTICE
P17	Rosewood - Workshop	Hydraulics\HOSES	replace blown main boom hydraulic hose			14/08/2019	9245	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Rosewood Workshop	PRENTICE
P17	Rosewood - Workshop	Body\HOUSEKEEP	grease loader throughly			14/08/2019	9245	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Rosewood Workshop	PRENTICE
P17	Rosewood - Workshop	VehService\BS	Service	VehService\BS		14/08/2019	9245	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Rosewood Workshop	PRENTICE
P17	Rosewood - Workshop	Hydraulics\RAM	reweld boss back on L/H/R foot pin			13/08/2019	9233	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Rosewood Workshop	PRENTICE

P17	Wodonga - Workshop	Hydraulics\RAM	Tightened main boom pin			20/07/2019	9090	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Wodonga Workshop	PRENTICE
P17	Rosewood - Workshop	Hydraulics\HYD LEAKS	L/H servo plunges leaking oil			18/07/2019	9067	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Rosewood Workshop	PRENTICE
P17	Rosewood - Workshop	Body\OH&S	straighten R/H deck plate			18/07/2019	9067	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Rosewood Workshop	PRENTICE
P17	Rosewood - Workshop	Hydraulics\OIL LEAK	slew motor leaking oil onto deck			18/07/2019	9067	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Rosewood Workshop	PRENTICE
P17	Rosewood - Workshop	Body\TRL LEGS	broken or loose R/H leg pin rear lower			18/07/2019	9067	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Rosewood Workshop	PRENTICE
P17	Rosewood - Workshop	Hydraulics\HYD LEAKS	fill hydraulic oil up			18/07/2019	9067	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Rosewood Workshop	PRENTICE
P17	Rosewood - Workshop	DriCabRep\HOUSEKEEP	replace L/H joy stick grip			18/07/2019	9067	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Rosewood Workshop	PRENTICE
P17	Myrtleford - Workshop	Engine\HOUSEKEEP	start and check			03/07/2019	9010	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\HYD LEAKS	repair grab swivel leak (fit seal kit)			01/06/2019	8984	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Body\HOUSEKEEP	wash grab			01/06/2019	8984	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\OIL LEAK	wash grab			03/05/2019	8920	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	DriCabRep\WINDSCREEN	Replace front windscreen			03/05/2019	8920	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Chassis\CHAS CRACK	Replace Main Boom Pin Boss Crack(LS228)			03/05/2019	8920	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\MOTOR	Repair Slew Problems		adj slew x over reline valves to 2600psi and test	03/05/2019	8920	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\RAM	repair leg pin thread and fit new nut and washer			02/05/2019	8920	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\OIL/FILTER	replace hydraulic oil			01/05/2019	8920	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\CONSUMABLE	replace hydraulic sight guage			01/05/2019	8920	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	DriCabRep\SEAT	replace 2x seat arm rests L6122			01/05/2019	8920	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	DriCabRep\WIPERS	repair wiper washers			01/05/2019	8920	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	VehService\BS	B Service As Per Attached Checklist	VehService\BS		01/05/2019	8920	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Albury - Workshop	Chassis\CHAS CRACK	weld LH deck			25/04/2019	8914	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Albury Workshop	PRENTICE
P17	Albury - Workshop	DriCabRep\SEAT	lubricate, un-jam and set up seat			24/04/2019		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Albury Workshop	PRENTICE
			inspect slew not stopping complaint												
			change relief cross-over valves												
P17	Albury - Workshop	Hydraulics\VALVES	inspect slew drive			24/04/2019		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Albury Workshop	PRENTICE
			found motor leaking/poor performance, pinion worn out and loose												
			tightened pinion												
			identifies parts required												
P17	Albury - Workshop	Engine\OIL LEAK	assembled			24/04/2019		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Albury Workshop	PRENTICE
P17	Albury - Workshop	Hydraulics\RAM	degreased and washed leaking grab. Diagnosed hydraulic oil leaks. Assisted Enzed. Assembled			16/04/2019		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Albury Workshop	PRENTICE
P17	Albury - Workshop	Hydraulics\HOSES	top right and bottom right hoses leaking on rotator hydraulic		replaced hosoes	13/04/2019		Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Albury Workshop	PRENTICE
P17	Albury - Workshop	DriCabRep\MOUNTS	tightened fittings on grab			13/04/2019		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Albury Workshop	PRENTICE
					removed both grab cylinders and replaced fittings										
					tightened hoses to top of rotary coupling										
					degreased and washed										
					tested for leaks										
					topped up hyd oil (40 liters approx.)										
			elbow in grab ram needs		replaced grab cylinder (leaking at seam), tested and washed										
P17	Albury - Workshop	Hydraulics\RAM	replacing also oil leak above rotator		washed damaged cylinder for repairs	10/04/2019	8876	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Albury Workshop	PRENTICE
			inspected, tightened and tested leaking hydraulic hoses and fittings in cab												
			greased grab												
P17	Albury - Workshop	Hydraulics\HYD LEAKS	replaced grab d-shackle			03/04/2019		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Albury Workshop	PRENTICE
P17	Rosewood - Workshop	Hydraulics\HYD LEAKS	grapple leaking oil			22/03/2019	8774	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Rosewood Workshop	PRENTICE
P17	Rosewood - Workshop	Body\DAMAGE	RH joystick, sticking in forward position			22/03/2019	8774	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Rosewood Workshop	PRENTICE
					grease loader free up RH servo										
P17	Rosewood - Workshop	Hydraulics\HOUSEKEEP	grease whole machine booms squeaking		check operation	22/03/2019	8774	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Rosewood Workshop	PRENTICE
P17	Myrtleford - Workshop	Engine\HOUSEKEEP	check engine oil, coolant and hydraulic oil			21/03/2019	8770	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Wodonga - Workshop	Hydraulics\OIL/FILTER	check hyd oil			15/03/2019	8760	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Wodonga - Workshop	Chassis\HOUSEKEEP	refit plates on grab with new bolts and washers			15/03/2019	8760	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Wodonga - Workshop	Hydraulics\HYD LEAKS	repair hyd leak at grab hose swivel			15/03/2019	8760	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Body\HOUSEKEEP	wash prentice			19/02/2019	8759	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\HYD LEAKS	repair hoses on top of boom damaged by trees			14/02/2019	8759	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Chassis\CHAS CRACK	Repair Boom stand cracks		pick up at Rinatech	07/02/2019	8722	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Chassis\CHAS CRACK	Repair cracks in lift ram bosses			07/02/2019	8722	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Chassis\CHAS CRACK	check over boom/handle for cracks			06/02/2019		Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Body\PANELS	cut main grab tips down			31/01/2019	8701	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\OIL/FILTER	top up hyd oil			11/01/2019	8676	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\RAM	grease RH rear leg ram			11/01/2019	8676	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	DriCabRep\ELECT P&W	fit strop glass to light			11/01/2019	8676	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\RAM	repair crack in RHR leg ram barrel			11/01/2019	8676	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\RAM	fit seal kit to RHR leg ram			11/01/2019	8676	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Elect\BATTERY	check batteries very slow to crank			04/01/2019	8667	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS		20/12/2018	8628	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\OIL/FILTER	top up hydraulic oil			19/12/2018	8622	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\HYD LEAKS	replace hyd cooler return hose			12/12/2018	6766	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\OIL/FILTER	top up hyd oil - ok			12/12/2018	6766	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Workshop\MOVE ASSET	pick up Rinatech			12/12/2018	6766	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\RAM	broken leg pin (end of ram to leg) (RH rear)			05/12/2018	8547	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\RAM	leaking leg ram RH rear			05/12/2018	8547	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Chassis\HOUSEKEEP	repair leg pin retainer RHR top			05/12/2018	8547	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Body\OH&S	Replace Grip Tape on Main Platform			08/11/2018	8759	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS		06/11/2018	8427	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
			Replace air con compressor & hoses & regas system												
P17	Myrtleford - Workshop	DrCabElect\AIR CON	repair a/con compressore mount & supply bolts (rinlatech). Replace air con compressor & hoses & regas system			26/10/2018		Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\OIL LEAK	Fit seals to LH servo in cab		checked all ok	26/10/2018	8759	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Chassis\HOUSEKEEP	replace broken leg pin L/H side rear			03/10/2018		Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Chassis\HYDRAULICS	fit bush to grab and grease grab and fold up			27/09/2018	8267	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
					Replaced rubber exhaust mount										
					Repaired boom light wiring										
P17	Myrtleford - Workshop	VehService\BS	B Service As Per Attached Checklist	VehService\BS	unblocked wiper washers	18/09/2018	8220	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Body\HOUSEKEEP	wash down grab			05/09/2018	8147	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\VALVES	grab swivel leaking			05/09/2018	8147	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\OIL/FILTER	check hyd oil and top up 15 liters			05/09/2018	8147	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\HYD LEAKS	grab leaking oil			04/09/2018	8136	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Engine\OIL LEAK	replace oil filter housing gaskets (warranty)			27/07/2018	8023	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Body\MOUNTS	repair RHR top leg pin lock tab			27/07/2018	8023	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
					repair worklight wiring x2										
P17	Myrtleford - Workshop	VehService\BS	B Service As Per Attached Checklist	VehService\BS	change hyd filter and servo filter	24/07/2018	8008	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Albury - Workshop	Hydraulics\HOUSEKEEP	Grease check over			30/06/2018		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Albury Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\OIL/FILTER	check hydraulic oil			28/06/2018	7961	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Chassis\DAMAGE	Replace bottom main lift pin in boom		Rinlatech	28/06/2018	7961	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\RAM	Replace main lift ram eye & bushes		Rinlatech	28/06/2018	7961	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Engine\HOUSEKEEP	top up engine oil			19/06/2018	7935	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\HOSES	replace spare hoses from boom to grab			05/06/2018	7906	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	VehService\BS	B Service As Per Attached Checklist	VehService\BS		09/05/2018	7777	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Workshop\MOVE ASSET	Take P17 to Cummins for repairs & return			08/05/2018	7777	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Engine\ENG REBLD	Fit new engine			08/05/2018	7777	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Engine\ENG REBLD	Fit 6 x Injectors			08/05/2018	7777	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Engine\MOUNTS	Fit new Engine Mounts			08/05/2018	7777	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Engine\TURBO	fit new turbo			01/05/2018	7759	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Air Con\HEATER	turn heater taps on			21/04/2018	7748	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Engine\HOUSEKEEP	check coolant and top up engine oil			21/04/2018	7748	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Elect\WORK LIGHT	prentice work lights (top of cab) not working			18/04/2018	7722	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
			replace leg pin R/H rear												
P17	Myrtleford - Workshop	Chassis\HYDRAULICS	weld foot ring (LHR)			17/04/2018	7713	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\OIL/FILTER	top up hyd oil			13/04/2018	7707	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\RAM	grease LH leg ram			13/04/2018	7707	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Body\PANELS	Repair deck cracks			13/04/2018	7707	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\DAMAGE	Repair grab tips			13/04/2018	7707	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\OIL LEAK	Fit seal kit to grab swivel & replace hoses			13/04/2018	7707	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\RAM	Fit seal kit to LHF leg ram			13/04/2018	7707	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\DAMAGE	Repair cracks in grab			13/04/2018	7707	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Chassis\HYDRAULICS	Replace LHR lower leg pivot pin			07/03/2018	7634	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Chassis\HYDRAULICS	Weld top leg ram pin tag			07/03/2018	7634	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	VehService\BS	B Service As Per Attached Checklist	VehService\BS	weld cracks on prentice deck	02/03/2018	7607	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
			Bolts missing and loose												
P17	Myrtleford - Workshop	Hydraulics\PUMP	Tripple pump mount			28/02/2018	7593	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\RAM	replace LHR leg ram seals			18/02/2018	7547	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\OIL/FILTER	top up hyd oil			18/02/2018	7547	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Workshop\MOVE ASSET	pick up at Rinlatech			18/02/2018	7547	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Engine\OIL LEAK	Replace engine side cover gaskets		(hrs 7520)	09/02/2018	7707	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\RAM	Replace stick boom ram seals(L4192). Replace stick boom ram seals			09/02/2018	7707	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
					triple pump seal not leaking										
					the oil leak most have been the rear main seal on the old eng. since the new eng has been fitted there is no oil										
P17	Myrtleford - Workshop	Hydraulics\PUMP	Replace seals & bearing in hydraulic triple pump		leak from pump area	09/02/2018	7832	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\VALVES	oil leak L/H sevo's			06/02/2018	7478	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE

P17	Myrtleford - Workshop	Elect\WORK LIGHT	top cab guard lights n/w			06/02/2018	7478	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Elect\WORK LIGHT	LH step w/light n/w			06/02/2018	7478	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	DrCabElect\INST/GAUGE	Repair dash lights			20/01/2018	7492	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	DrCabElect\INST/GAUGE	Check gauge lights on loader		Checked dash light wiring	19/01/2018	7403	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\OIL/FILTER	check hydraulic oil			16/01/2018	7393	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\INST/GAUGE	repair oil leak at spool bank			16/01/2018	7393	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Body\HOUSEKEEP	wash platform			16/01/2018	7393	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
					weld leg pin retainer										
P17	Myrtleford - Workshop	VehService\BS	B Service As Per Attached Checklist	VehService\BS	repair wiring to strobe light	13/01/2018	7401	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Cooling\RADIATOR	loader motor running hot			19/12/2017	7293	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\OIL LEAK	repair hyd leaks			14/12/2017		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\HOSES	make up 4x spare boom to grab hoses			14/12/2017		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Elect\START MOTR	fit new starter motor (warranty)			05/12/2017	7230	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Engine\FAULT CODE	repair engine fault codes (engine wont start)			05/12/2017	7230	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Engine\ELECT P&W	rewire from ignition key to fuel pump			05/12/2017	7230	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Engine\FAULT CODE	fir new ecm			05/12/2017	7230	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Workshop\MOVE ASSET	Drop off & pick up from Cummins Wodonga			05/12/2017	7230	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
			Rewire from ignition switch to ECM & ECM to electric fuel pump												
P17	Myrtleford - Workshop	Engine\FAULT CODE	Clear all codes			02/12/2017	7220	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Elect\START MOTR	Replace starter motor			02/12/2017	7220	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
					Checked filters for blockages, cleaned fuel pick up lines, bled fuel system.										
					Engine Code 373 is showing										
P17	Myrtleford - Workshop	Engine\FAULT CODE	Motor shut down - water in filter & light on		Checked wiring & cleaned - Still showing fault.	02/12/2017	7220	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
			replace crank shaft pulley												
			replace fan pulley												
			check belt tensioner												
P17	Myrtleford - Workshop	Engine\BELTS/TENS	fit new fan belt			23/11/2017		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Engine\OIL LEAK	replace front crank shaft pulley seal			23/11/2017		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Engine\OIL LEAK	reseal front cover plate			23/11/2017		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Engine\OIL LEAK	replace sump gasket			23/11/2017		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
					fit new gasket										
P17	Myrtleford - Workshop	Hydraulics\PUMP	Remove servo pump for repair		wash eng and surrounds	17/11/2017	7211	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
			Pressure check air con												
P17	Myrtleford - Workshop	DrCabElect\AIR CON	Check air con operation		check tensioner, and main pullies on main belt	16/11/2017	7211	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
					belts and water pump pully - ok										
					check a/c clutch and pressure check										
P17	Myrtleford - Workshop	DrCabElect\AIR CON	Check air con belt and pullies for wear		re adjust belt	15/11/2017	7181	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	VehService\BS	B SERVICE as per attached check list	VehService\BS		15/11/2017	7181	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	DrCabElect\AIR CON	check aircon bolts slipping		a/c belt pulley need replacing	14/11/2017	7174	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Chassis\DAMAGE	Repair Tip on Grab			02/11/2017	7140	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Engine\BELTS/TENS	Check all belts pulley's & tensioners		replace fan belt pulleys (ok)	28/10/2017	7116	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Air Con\AIR CON	Check air con compressor operation & settings			28/10/2017	7116	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Air Con\AIR CON	replace air compressor fitting and hose and regas system			26/10/2017	7099	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Chassis\HOUSEKEEP	Weld cracks in grab			12/10/2017	7070	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\RAM	Fit seal kit to RH main lift ram		refit ram wash & test & top up hyd oil	12/10/2017	7070	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Elect\WORK LIGHT	fit 4 new light force work lights to boom			10/10/2017	7070	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Air Con\AIR CON	Repair Air Con system		replace aircon dryer and replace hose and regas and test system	05/10/2017	7070	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Elect\WORK LIGHT	replace work light main boom			04/10/2017	7042	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Engine\HOUSEKEEP	top up 5 lt engine oil			04/10/2017	7042	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Chassis\HOUSEKEEP	Replace LHR lower leg pin			21/09/2017	6980	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	VehService\BS	B Service As Per Attached Checklist	VehService\BS	replaced hyd and servo filters	21/09/2017	6980	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Body\MOUNTS	R/H rear foot pin loose (needs rewelding)			15/09/2017	6945	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Chassis\HOUSEKEEP	replace leg pin R/H rear			12/09/2017	6920	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\OIL LEAK	oil leak in grab			23/08/2017	6813	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Engine\FILTERS	water in fuel			23/08/2017	6813	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	VehService\BS	B Service As Per Attached Checklist	VehService\BS		12/08/2017	6759	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
					fit new rain cap										
P17	Myrtleford - Workshop	Cooling\RADIATOR	Repair leak in radiator		top up engine oil	18/07/2017	6651	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Chassis\HOUSEKEEP	broken leg pin L/H front			13/07/2017	436058	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
					pressure test radiator - small leak (hole)										
					found in bottom radiator tank										
P17	Myrtleford - Workshop	Cooling\RADIATOR	coolant leak		-remove radiator for repairs	13/07/2017	436058	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	DrCabRep\DOOR LOCK	door catch needs welding back on			16/06/2017	8536	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Elect\WORK LIGHT	Re-Wire all 4 boom lights			06/06/2017	6486	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	VehService\BS	B Service As Per Attached Checklist	VehService\BS		03/06/2017	6510	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Chassis\HOUSEKEEP	grease loader			02/06/2017	6510	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Engine\HOUSEKEEP	Top up engine oil		Complete	30/05/2017	6486	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Cooling\HOUSEKEEP	Top up coolant		Complete	30/05/2017	6486	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Elect\HOUSEKEEP	Check alternator & battery		Complete	30/05/2017	6486	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\OIL LEAK	remove & fit seal kit to grab hose swivel			25/05/2017	6485	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\DAMAGE	main boom on loader cracked			28/04/2017	428021	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\RAM	leak at the back of stick boom ram			28/04/2017	428021	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\RAM	replace RHR ram leg pin			28/04/2017	428021	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\OIL/FILTER	top up hyd oil			28/04/2017	428021	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	DrCabRep\SEAT	Replace LH servo gas strut			14/04/2017	6359	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Wodonga - Workshop	Hydraulics\OIL/FILTER	top up hyd oil			13/04/2017	6334	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Wodonga - Workshop	Hydraulics\HOSES	replace hyd hose triple pump. replace hyd hose tripple pump			13/04/2017	6334	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Wodonga - Workshop	Hydraulics\VALVES	L/H servo leaking			13/04/2017	6334	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Wodonga - Workshop	DrCabRep\DOOR LOCK	fit gas strut to cabin door			13/04/2017	6334	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS		11/04/2017	6322	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\RAM	grab ram leaking			25/03/2017	6264	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
					replace fan belt										
					replace a/con belt										
					replace eng fan hub bearing										
P17	Myrtleford - Workshop	Engine\BELTS/TENS	serpentine belt sill slipping		replace eng fan pulley	25/03/2017	6264	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Elect\WORK LIGHT	repair work light wiring			25/03/2017	6264	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\OIL/FILTER	top up hyraulic oil			25/03/2017	6264	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Body\HOUSEKEEP	check over			25/03/2017	6264	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\DAMAGE	replace LHR bottom leg pin			16/03/2017	6204	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Engine\BELTS/TENS	replace fan belt tensioner			07/03/2017	6170	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	DrCabElect\AIR CON	check and repair aircon system			07/03/2017	6170	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Elect\WORK LIGHT	Refit boom light			06/03/2017	6135	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
			alternator & fan belts noisy												
P17	Myrtleford - Workshop	Engine\BELTS/TENS	-fitted 2 new belts			25/02/2017	6139	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Engine\MOUNTS	repair crack in RHF enigne mount leg to chassis mount			19/02/2017	6109	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Chassis\CHAS CRACK	repair crack I cab chassis WELD UP GRAB TIPS			19/02/2017	6109	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS		11/02/2017	6109	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\HYD LEAKS	Replace seals in grab hose swivel			09/02/2017		Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\PUMP	Replace seals in hydraulic servo pump			09/02/2017		Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Engine\ALT2 DR	Replace alternator			09/02/2017		Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Engine\BELTS/TENS	Replace fan belt			09/02/2017		Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Body\HOUSEKEEP	Wash engine & grab			09/02/2017		Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Cooling\RADIATOR	Debug oil cooler			09/02/2017		Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Engine\ENG TUNE	Tune Engine			09/02/2017		Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Engine\EXHAUST	Repair exhaust system			09/02/2017		Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
					recor radiator										
P17	Myrtleford - Workshop	Cooling\RADIATOR	Remove & repair leaking radiator		change coolant	08/02/2017	6109	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\OIL LEAK	Repair steel pipe		Complete	06/02/2017	6091	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	DrCabElect\AIR CON	Repair air con system & replace battery & check starting system. Repair air con system			25/01/2017	6070	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\HOSES	Replace Grab hoses & wash			25/01/2017	6070	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
			Re-bush slew linkage												
P17	Myrtleford - Workshop	Hydraulics\VALVES	Cean slew valve			25/01/2017	6070	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\CONSUMABLE	Fit plates to grab tines & repair tips			25/01/2017	6070	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Elect\BATTERY	Replace Battery		fit new battery	19/01/2017	6052	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Chassis\HOUSEKEEP	Replace Leg Pin RHS		Complete - Rinlatech Engineering	17/01/2017	6038	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Body\MOUNTS	Replace bolt in grab pin		Complete - Rinlatech Engineering	17/01/2017	6038	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Chassis\HOUSEKEEP	weld in bush on grab			13/01/2017	22718	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	DrCabElect\ELECT P&W	check engine starting problems			13/01/2017	22718	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
			change hydraulic filter												
			change hydraulic servo filter												
P17	Myrtleford - Workshop	Hydraulics\OIL/FILTER	chech hydraulic level			30/12/2016	5951	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Body\HOUSEKEEP	wash down loader			30/12/2016	5951	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\RAM	Remove & Replace bottom main lift ram pin		Complete	28/12/2016	5951	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
			Replace damaged ram hoses												
P17	Myrtleford - Workshop	Hydraulics\HOSES	Replace damaged outer boom to grab hoses		Complete	28/12/2016	5951	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Chassis\MUDGUARDS	Repair damaged mudguards		Complete	28/12/2016	5951	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Chassis\HOUSEKEEP	Fit 4 x Pins & weld on bushes to all stabilizer feet		Complete	28/12/2016	5951	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE

P17	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS		20/12/2016	5947	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\OIL LEAK	Fit Seals to slew valve under cab			17/12/2016	5951	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Engine\BELTS/TENS	Repair air con belts - slipping		Complete	15/12/2016	5910	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
					refit door latch spring (temp repair)										
P17	Myrtleford - Workshop	DrCabRep\DOOR LOCK	Replace inner door catch & door striker		fit 2 new door hinge bolts	13/12/2016	5970	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	DrCabRep\DOOR LOCK	Make up temporary door lock		Complete	09/12/2016	5879	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Elect\WORK LIGHT	Repair outer boom work light			26/11/2016	5798	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Engine\EXHAUST	Extract broken manifold bolts & replace			21/10/2016	3763	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS		20/10/2016	57223	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
					repaired muffler mount										
P17	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS	unblock w/screen wiper	09/09/2016	5532	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Elect\WORK LIGHT	stick boom lights not working			01/09/2016	8482	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\RAM	Replace outer boom ram pin & bearing			27/08/2016	5452	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Chassis\HOUSEKEEP	Repair outer boom ram mount & fit new boss to boom			27/08/2016	5452	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\HOSES	replace blown hydraulic hose on boom knuckle			17/08/2016	5414	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Body\HOUSEKEEP	wash prentice			17/08/2016	5414	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\RAM	replace LHR top leg mount pin			09/08/2016		Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\OIL LEAK	LHR ram leaking			09/08/2016		Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\RAM	fit seal kit to LHR leg ram			09/08/2016		Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\OIL/FILTER	check hydraulic oil			09/08/2016		Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS		28/07/2016	5311	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\OIL/FILTER	top up 20Lt hydraulic oil			23/07/2016	5292	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Elect\WORK LIGHT	Repair Light bracket on cab guard. Repair bracket on cab guard		Complete	05/07/2016		Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Chassis\HOUSEKEEP	Repair crack in LHF A frame		Complete	05/07/2016		Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\OIL/FILTER	check hyd oil level			16/06/2016	5178	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
					Repair rocker cover no1 leak										
P17	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS	Repair exhaust bracket	31/05/2016	5118	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\RAM	Repair LH top leg pin mount bolt		Complete	31/05/2016	5118	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
					Remove engine valve cover & tighten loose fitting, re-fit cover with a new gasket										
P17	Myrtleford - Workshop	Engine\OIL LEAK	Repair oil leak at engine valve cover		Complete	31/05/2016	5118	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
			Fit new fan belt												
P17	Myrtleford - Workshop	Engine\BELTS/TENS	Fit new a/c belt		Complete	31/05/2016	5118	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
					Remove & Repair exhaust mount										
P17	Myrtleford - Workshop	Engine\EXHAUST	Repair broken exhaust mount		Complete	31/05/2016	5118	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\HOSES	make up spare hyd hoses			14/05/2016		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
			Check heater not working												
P17	Myrtleford - Workshop	DrCabElect\HEATER REP	Replace heater tap		Complete	02/05/2016	5004	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Chassis\HOUSEKEEP	Replace broken leg pin LHS		Complete	29/04/2016	4987	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\OIL/FILTER	top up hydraulic oil			08/04/2016	4912	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Body\MOUNTS	tighten bolts on walking platforms			08/04/2016	4912	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	DrCabElect\ELECT P&W	tidy up wiring			08/04/2016	4912	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	DrCabRep\WIPERS	Replace windscreen washer nozzle			07/04/2016	4912	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Chassis\HOUSEKEEP	Repair LHR Leg Pin mount bolt & plate		fit ne rhr bottom leg pin also	07/04/2016	4912	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS		02/04/2016	4902	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	DrCabRep\WIPERS	broken wiper washer nozzle			02/04/2016	4902	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Chassis\HOUSEKEEP	LHR leg pin cracked & bolt broken			02/04/2016	4902	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
					repaired wiring & plug										
P17	Myrtleford - Workshop	Elect\WORK LIGHT	R/H side stick boom light not working		complete	23/03/2016	4863	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Chassis\HOUSEKEEP	Repair cracked main boom pin housing		completed - Rinlatech Engineering	05/03/2016	4795	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Body\MOUNTS	Fit spacers to boom rest		Completed - Garner	05/03/2016	4795	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\RAM	remove top main lift pin from boom (broken)		Completed - Sublet Repair	23/02/2016	4760	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
			Grease main lift pins												
P17	Myrtleford - Workshop	Hydraulics\OIL/FILTER	Check hydraulic oil		Completed	23/02/2016	4760	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\OIL/FILTER	Replace Top main lift pin		Completed - RINLATECH	23/02/2016	4760	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\RAM	Replace LH lift ram eye & bush		Completed - RINLATECH	23/02/2016	4760	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\HOSES	Replace damaged hydraulic hose		Completed - RINLATECH	23/02/2016	4760	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
					Weld up lock tab on main lift pin on boom to stop pin turning										
P17	Myrtleford - Workshop	Chassis\HOUSEKEEP	Main boom pin repair - cabin end		Completed by RINLATECH	19/02/2016	4760	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	DrCabRep\WINDSCREEN	Supply & fit new rear window		Completed by NEWS	10/02/2016	4720	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	DrCabElect\UNST/GAUGE	Replace cab strobe light		completed	08/02/2016	4711	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS		05/02/2016	4700	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
					Myrtleford Auto Electrics										
P17	Myrtleford - Workshop	Elect\BATTERY	test batteries		completed	01/02/2016	4678	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Elect\HOUSEKEEP	place batteries on charge		completed	01/02/2016	4678	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	DrCabElect\ELECT P&W	replace starter cables		completed	19/01/2016	4637	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	DrCabElect\UNST/GAUGE	refit dash panels		completed	19/01/2016	4637	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Elect\RADIO	fit 606 trunk phone to loader		completed	13/01/2016	4613	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Engine\BELTS/TENS	fan belt		completed	13/01/2016		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
			replace fan belt												
P17	Myrtleford - Workshop	Engine\BELTS/TENS	check all pulley's & idlers		completed	11/01/2016	4598	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Body\HOUSEKEEP	fit reflective tape to legs & cab		completed	11/01/2016	4598	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
			make up leg pins												
P17	Myrtleford - Workshop	Hydraulics\RAM	rinlatech		completed	19/12/2015		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
			filters												
P17	Myrtleford - Workshop	Engine\FILTERS	tctc		completed	12/12/2015		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS	completed	11/12/2015	4485	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
			hyd guage												
P17	Myrtleford - Workshop	Chassis\HYDRAULICS	rinlatech		COMPLETED	09/12/2015		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\HYD LEAKS	site glass on hydraulic tank leaking		completed	08/12/2015	4447	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Chassis\SUSPENSION	repair cracks in base of frame near chasis rail both sides		completed	08/12/2015	4447	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Body\DAMAGE	repair grab + swivel		completed	05/12/2015		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
			weld main boom cracks												
P17	Myrtleford - Workshop	Body\DAMAGE	weld tips on grab		completed	17/11/2015	43372	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
			1 grab hose+swivel kit+leg seal												
P17	Myrtleford - Workshop	Hydraulics\RAM	randalls		completed	10/11/2015		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
			filters												
P17	Myrtleford - Workshop	Engine\FILTERS	tctc		completed	06/11/2015		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Hydraulics\HOSES	fit grab hose swivel kit		completed	03/11/2015	4371	Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS	completed	16/10/2015	4280	Service	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Chassis\HYDRAULICS	make hoses + supply parts		completed	10/10/2015		Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Body\LIGHTS	Job Added From Invoice			15/09/2015	0	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
P17	Myrtleford - Workshop	Engine\FUEL TANK	Service Job Added From Invoice			05/09/2015	0	Repair	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
			oil leak front of loader motor												
			replace servo plunger seals												
			replace windscreen wiper blade												
			fit 2 new led outer book lights												
P17	Myrtleford - Workshop	Engine	repair cab led lights		repaired	02/09/2015		Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Myrtleford Workshop	PRENTICE
			repair leaking servos lh side handle												
			replace top cab work light												
			remove radio +panel for repairs												
P17	Wodonga - Workshop	Elect	repair radio panel+refit radio		completed	29/08/2015		Fault	Completed	Greenfreight Logging Vic	LOADPRENT	Myrtleford	MLR	Wodonga Workshop	PRENTICE