EquipmentName	Workshop	CodeAndSubCode	Description	Schedule	CompletionComments	DateDone	HourDone	Worktype	Workstate	EquipmentOwner	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
					Leaking side cover, Oil pan, Front cover, Oil cooler/ Leaking Cylinder head gasket Inspect engine for Oil/ Coolant leaks Leaking side cover, Oil pan, Front cover, Oil cooler/ Leaking Cylinder head gasket Remove all leaking components Clean remove gaskets and inspect for re use All ok to reuse Some fretting to cylinder head Fretting found on top of cylinder block At customer request inspect engine bearings Find #6 big end bearing Galled Find #6 big end journal galled Leave engine dismantled										
			Bad Engine oil leak Investigate & Diagnose Oil & Coolant													
P22	Albury - Workshop	Engine\OIL LEAK	Leaks.		Report findings to customer	08/02/2023		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Albury Workshop	PRENTICE
P22	Albury - Workshop	Hydraulics\PUMP	Lap and reseal Servp Pump			04/01/2023		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Albury Workshop	PRENTICE
P22	Wodonga - Workshop	Engine\OIL LEAK	REPACED TURBO DRANI, DIPSTICK Y PIECE.			05/10/2022		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Wodonga Workshop	PRENTICE
P22	Wodonga - Workshop	Elect\BATTERY	TURNED OFF LIGHTS LEFT ON. CHECKED STARTING.			28/05/2022	27921	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Wodonga Workshop	PRENTICE
P22	Wodonga - Workshop	Elect\HEAD LIGHT	Low beam very dull Hydraulic pump very slow moving.			28/04/2022	27906	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Wodonga Workshop	PRENTICE
P22	Wodonga - Workshop	Hydraulics\PUMP	Shudder through Hydarulics.		CHECKED HYDRAULIC OIL LEVEL.	28/04/2022	27906	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Wodonga Workshop	PRENTICE
P22	Wodonga - Workshop	Engine\OIL LEAK	Bad Engine oil leak LOADER IS LEAKING HEAVILY) OUT OIL. NO HYDRAULIC PRESSURE.			28/04/2022	27906	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Wodonga Workshop	PRENTICE
P22	Wodonga - Workshop	Hydraulics\OIL LEAK	CAN'T LIFT.		NO LEAKS FOUND.	28/04/2022	27906	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Wodonga Workshop	PRENTICE
P22	Wodonga - Workshop	Hydraulics	PLEASE CHECK HYDRAULIC OIL- ENGINE OIL.			28/04/2022	27906	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Wodonga Workshop	PRENTICE
P22	Wodonga - Workshop	Prevent	POSSIBLY GREASE LOADER		OPERATOR JOB.	28/04/2022	27906	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Wodonga Workshop	PRENTICE
P22	Wodonga - Workshop	Engine\BELTS/TENS	ADJUST FAN BELT.			28/04/2022	27906	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Wodonga Workshop	PRENTICE
P22	Wodonga - Workshop	Body\OH&S	STEPS VERY SLIPPERY. REQUIRES NON-SLIP TAPE.			28/04/2022	27906	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Wodonga Workshop	PRENTICE
P22	Wodonga - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS	ADJUSTED A/C BELT TENSION. REPLACED RH MAIN BOOM LIGHT. ADDED 5L COOLANT.	28/04/2022	27906	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Wodonga Workshop	PRENTICE
P22	Wodonga - Workshop	Elect\ELECT P&W	REPAIRED BROKEN SAFETY SWITCH IN CAB.			23/03/2022		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Wodonga Workshop	PRENTICE
P22	Wodonga - Workshop	Chassis\Load Fram	WELDED TAG ONTO CORRECT LENGTH PIN. REPLACED TEMPORARY PIN FITTED TO RR LEG.			24/02/2022	27869	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Wodonga Workshop	PRENTICE
P22	Wodonga - Workshoo	Elect\WORK LIGHT	NO BOOM LIGHTS			23/02/2022		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Wodonga Workshoo	PRENTICE
P22	Wodonga - Workshop	Hydraulics\RAM	Replace RHS rear lower leg pin		TEMPORARY REPAIR- LEG PIN USED INCORRECT LENGTH.	23/02/2022		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Wodonga Workshop	PRENTICE
P22	Wodonga - Workshop	Engine\OIL LEAK	CHECKED P29 TO SEE IF TURBO OIL RETURN AND DIPSTICK WILL SUIT P22. NOT COMPATIBLE. INSPECTED OIL LEAKS AND TOPPED UP. PARKED. ORDERED PARTS.			11/02/2022	27843	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Wodonga Workshop	PRENTICE
P22	Wodonga - Workshop	Engine\OIL LEAK	INSPECTED OIL LEAKS. FOUND LEAKS AT INSPECTION PLATE, TURBO OIL RETURN AND DIPSTICK TUBE. REPLACED O-RINGS AND SEALED TUBE WITH RTV. DE-GREASED AND WASHED.			04/02/2022	27826	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Wodonga Workshop	PRENTICE
P22	Wodonga - Workshop	Elect\BATTERY	JUMP STARTED LOADER			07/12/2021	27776	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Wodonga Workshop	PRENTICE
P22	Rosewood - Workshoo	Steering\BATTERY	replace batterv			20/11/2021	27761	Reapir	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Rosewood Workshoo	PRENTICE
P22	Rosewood - Workshop	Elect\BATTERY	called out to Hyne to jumpstart both truck and loader tested alternator and batteries, organised replacements grease loader check over			17/11/2021	27621	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Body\HOUSEKEEP	add 2 liters oil			08/10/2021	27742	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Chassis\DAMAGE	make new grab chain up, unload and fold loader and fit			23/09/2021	27725	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Elect\BATTERY	test battery and change rate. All good (REPLACE BATTERY)			23/09/2021	27725	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Body\HOUSEKEEP	check over prior to use			14/09/2021	27622	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Rosewood Workshop	PRENTICE
P22	Wodonga - Workshop	Engine\BELTS/TENS	Has thrown aircon belt off, and fogs up all the time.		Belt has been replaced Belt # 1730 Lunch Included.	05/08/2021		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Wodonga Workshoo	PRENTICE
P22	Wodonga - Workshop	Chassis\STAB LEG	Replaced RHF leg pin.			03/08/2021	27666	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Wodonga Workshop	PRENTICE
P22	Wodonga - Workshop	Elect\HEAD LIGHT	Low beam very dull B Service			03/08/2021	27666	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Wodonga Workshop	PRENTICE
P22	Rosewood - Workshop	VehService\BS	repair boom light bad connection replace grease nipple on fly lift boom ram	VehService\BS		24/07/2021	27636	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Chassis\HYDRAULICS	remount pilot pump safety lever base			07/07/2021	27597	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Engine\HOUSEKEEP	check over before shift take 2 hubs into Tumbarumba for pressing wrong bearing supplied. Used best one wrong pulley supplied so drilled holes to suit			26/06/2021	27555	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Engine\BELTS/TENS	wrong belt supplied so found are to suit re-assemble and test run (batteries flat after driver left radio on) jump started			09/06/2021	27482	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Engine\ELECT P&W	all good disassemble failed fan and pulley assembly			09/06/2021	27482	Reapir	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Rosewood Workshoo	PRENTICE
P22	Rosewood - Workshop	Engine\BELTS/TENS	inspect parts and arrange missing hub (damaged)			08/06/2021	27482	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Hydraulics\HOSES	oil leak under slew rotator		sublet repairs on leaking hose	02/06/2021	27482	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Engine\BELTS/TENS	started to remove broken fan hub pulley R11617			02/06/2021	27482	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Rosewood Workshop	PRENTICE
P22	Myrtleford - Workshop	Elect\WORK LIGHT	work light top RH corner out windscreen guard has broken wirew or faulty connection diagnose and repair heater not working			29/05/2021	27500	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Myrtleford Workshop	PRENTICE
P22	Rosewood - Workshop	DrCabElect\HEATER REP	I pulled interior apart and found cable had come off the dial appears to be backward that is "hot" was actually cold and vice-versa			22/05/2021	27482	Reapir	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Rosewood Workshoo	PRENTICE
P22	Rosewood - Workshop	DrCabElect\HEATER REP	I re-attached the top and advised the operator of how it works			22/05/2021	27482	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Engine\RADIATOR	chanae thermostat			21/05/2021	27479	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	VehService\BS	B Service	VehService\BS		21/05/2021	27479	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Chassis\DAMAGE	broken bolt in knee pin			19/05/2021	27468	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Tumut Workshop	PRENTICE
P22	Rosewood - Workshop	DrCabElect\HEATER REP	coolant leak hoses under it (had to fill before start)		check coolant leak. Needs new heater core	07/05/2021		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Chassis\DAMAGE	back driverside leg pin needs bolt put in it		replace rear leg pin bolt (FIT CHANGE OVER LEG RAM)	07/05/2021		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Rosewood Workshop	PRENTICE
P22	Rosewood - Workshoo	Elect\WORK LIGHT	move liaht above windscreen (swap with other side)			07/05/2021		Reapir	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Rosewood Workshoo	PRENTICE
P22	Rosewood - Workshop	Hydraulics\MOTOR	replace slew motor			04/05/2021	27357	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Body\HOUSEKEEP	clean up and test. All good			04/05/2021	27357	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Rosewood Workshop	PRENTICE
					R&R120622 heater hoses leaking tighten up clamps tap op with coolant run engine until operating temp											
P22	Tumut - Workshop	Engine\COOL LEAKS	coolant leak out off hoses underneath Service call to Rosewood w/shop Travel from Hume hwy back to Rosewood Assist Greenfreight mechanic (Gordon) in diagnosis & pressure testing slew motor Motor is leaking oil externally from drive shaft after recent rebuild Locate pressure test point & fit gauge Test pressure while slewing & stalled out Check case drain Report outcomes to Gordon Supply ORFS caps & plugs		check again ok	20/04/2021	27309	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Tumut Workshop	PRENTICE
P22	Rosewood - Workshop	Engine\OIL LEAK	Return to Wagga			18/03/2021		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Engine\FILTERS	Supply Oil Filter Cartridge			17/03/2021		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Hydraulics\MOTOR	replace slew motor with refurbished unit ex Myrtleford. Sent old one back			16/03/2021	27210	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Hydraulics\OIL/FILTER	replace hydraulic filter			16/03/2021	27210	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Hydraulics\OIL/FILTER	top up hydraulic oil			16/03/2021	27210	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Hydraulics\HOUSEKEEP	test run. All good			16/03/2021	27210	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Body\HOUSEKEEP	degrease and hose down			16/03/2021	27210	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Rosewood Workshop	PRENTICE
P22	Myrtleford - Workshop	Elect\WORK LIGHT	LH work light		fit work light LH side boom	13/03/2021	7200	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Body\MOUNTS	fuel tank bolt		fit counter sunk bolt to fuel tank support	13/03/2021	7200	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshoo	Body\HOUSEKEEP	wash oil from loader			13/03/2021	7200	Reapir	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Myrtleford Workshoo	PRENTICE
P22	Myrtleford - Workshop	Hydraulics\HYD LEAKS	hyd oil leak at fitting wash and test			12/03/2021	22197	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Engine\HOUSEKEEP	re-route throttle cable			12/03/2021	22197	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Hydraulics\HYD LEAKS	Remove Centre hose swivel and replace all 28 O Rings and Test and Refit		remove swivel due to leaking	12/03/2021	22197	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	DrCabElect\INST/GAUGE	replace decal's on all switch's			10/03/2021	22197	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Hydraulics\VALVES	adjust slew pedals			10/03/2021	22197	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Chassis\HOUSEKEEP	grease check over			10/03/2021	22197	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Body\PAINT/REST	rear bar paint			10/03/2021	22197	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Body\REFLECTORS	reflective tape			05/03/2021	27196	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Body\PAINT/REST	wash loader			05/03/2021	27196	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Body\PAINT/REST	paint rams			05/03/2021	27196	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	DrCabRep\SEAT	fit gas strut to arm rest RHS			05/03/2021	27196	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Body\REFLECTORS	keep clear signs			05/03/2021	27196	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Body\PAINT/REST	wash loader/truck			05/03/2021	27196	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Engine\FUEL TANK	refuel bleed and stat loader			25/02/2021	27196	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshoo	DrCabReo\WINDSCREEN	supply and fit new front w/screen and rubber			25/02/2021	27196	Reapir	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Myrtleford Workshoo	PRENTICE
P22	Myrtleford - Workshop	Hydraulics\OIL/FILTER	top up hyd oil level			25/02/2021	27196	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Body\WORK LIGHT	boom lights not working			25/02/2021	27196	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	DrCabElect\AIR CON	cab fan not working			25/02/2021	27196	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	DrCabElect\SEAT	needs new seat in loader/causing back pain		rebuild seat susp and fit 2x new shockers	20/02/2021	27196	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshoo	Body\HOUSEKEEP	Remove cab from P22 and reolace mount bushes and repair and refit cab			10/02/2021	27196	Reapir	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Myrtleford Workshoo	PRENTICE
P22	Myrtleford - Workshop	DrCabRep\SEAT	Repair Loader Seat			10/02/2021	27196	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	DrCabRep\HOUSEKEEP	Tidy Up Cam and Wiring			10/02/2021	27196	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR		Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Chassis\CHAS CRACK	Repair cracks in main boom and fit 5 new bushes and pins R11243			10/02/2021	27196	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	RINLATECH ENGINEERING	PRENTICE
P22	Myrtleford - Workshop	Hydraulics\RAM	Repair boom rams R10904 R12150		fit seal kits t both main rams	10/02/2021	27196	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	RINLATECH ENGINEERING	PRENTICE
P22	Myrtleford - Workshoo	Chassis\CHAS CRACK	Repair Cracks in Boom Mounts on sub Frame			10/02/2021	27196	Reapir	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	RINLATECH ENGINEERING	PRENTICE
P22	Myrtleford - Workshop	Engine\BELTS/TENS	pit temp fan belt tensioner			05/02/2021	27196	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Body\DAMAGE	remove cab from loader to repair cracks and refit			05/02/2021	27196	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Workshop\MOVE ASSET	take to Rinlatech for boom repair			05/02/2021	27196	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Rosewood - Workshop	Body\PAINT/REST	clean up before sending to Myrtleford			30/01/2021	27195	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Tumut - Workshoo	DrCabElect\ELECT P&W	will not turn off with kev			29/01/2021	27193	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshoo	PRENTICE
P22	Tumut - Workshop	VehService\BS	service near due	VehService\BS	service not due	29/01/2021	27193	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P22	Rosewood - Workshop	Engine\HOUSEKEEP	check over			29/01/2021	2719	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Body\HOUSEKEEP	prepare and weld gussets on brackets			22/01/2021		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Hydraulics\HOSES	make up spare hyd hoses			21/01/2021		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Tumut - Workshoo	Body\HOUSEKEEP	middle oost on handrail on orentice broken			20/01/2021	27196	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshoo	PRENTICE
P22	Rosewood - Workshop	Hydraulics\VALVES	need new hand control		replace left joystick handle	12/01/2021	27075	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Hydraulics\HOSES	fix hoses		replace short rotator hose in grab	12/01/2021	27075	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE

P22	Rosewood - Workshop	Engine\HOUSKEEEP	check oil and coolant			12/01/2021	27075	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Engine\FILTERS	clean air filter pre-cleaner			12/01/2021	27075	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Engine\HOUSEKEEP	check over check valve port leaking remove one from P14 remove from P22			09/01/2021	27051	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Hydraulics\VALVES	fit new one			30/12/2020	26996	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Hydraulics\OIL/FILTER	remove hydraulic and pilot filter housings and clean thorougly and replace oil			30/12/2020	26996	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	VehService\BS	1000 hourly serviceR10569	VehService\BS		30/12/2020	26996	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
					called out Greenhills, grab pivot pin retaining bolt broke and fell out										
P22	Tumut - Workshop	Chassis\DAMAGE	replace keeper bolt on grab pin		made bolt from threaded rod and fitted	24/12/2020	26990	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P22	Myrtleford - Workshop	Eneine\OIL LEAK	needs new dip stick (leak oil) check engine fluids and check over			24/12/2020		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Rosewood - Workshop	Engine\HOUSKEEEP	#added 2 liters oil			23/12/2020	26974	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Tumut - Workshop	Hydraulics\HOSES	supply and reolace loe grab hose investigate oil leak at leg ram swivel		called out to Greenhills via Rosewood to aet the "correct" arab hose	22/12/2020	26968	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P22	Rosewood - Workshop	Hydraulics\HYD LEAKS	replace o-rings on fitting on swivel checked oil level and topped up as needed diagnose and repair oil leak from fitting at leg rotator was a damage o-ring			18/12/2020		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Hydraulics\HYD LEAKS	clean up and check ok			17/12/2020	26931	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	DrCabElect\SEAT	needs new seat in loader/causing back pain			15/12/2020	26907	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Myrtleford - Workshop	Hydraulics\HYD LEAKS	removed swivel from loader in yard			10/12/2020	26901	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Hydraulics\HYD LEAKS	fit resealed leg swivel diagnose major oil leak night shift driver noticed on his walk around			10/12/2020	26901	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Rosewood - Workshop	Hydraulics\OIL LEAK	found to be leg rotator, sent to Wayne via Albury depot			09/12/2020	26901	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Engine\OIL LEAK	needs new dip stick (leak oil)			08/12/2020		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Myrtleford - Workshop	Hydraulics\VALVES	inspect hyd issue with slew			17/11/2020	26862	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Hydraulics\VALVES	repair slew main reline valve and check slew pressures left & right			17/11/2020	26862	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Hydraulics\HYD LEAKS	repair spool bank hyd oil leaks			17/11/2020	26862	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Elect\WORK LIGHT	repair worklight			30/10/2020	26855	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Body\MOUNTS	weld cracks in hyd tank			30/10/2020	26855	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Chassis\CHAS CRACK	weld cracks in boom			30/10/2020	26855	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Hydraulics\HOSES	replace hydraulic hose clamps			30/10/2020	26855	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Body\MOUNTS	replace hydraulic tank mount bolts			30/10/2020	26855	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Body\PANELS	fix eneine door latch and hooks			30/10/2020	26855	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Body\EXHAUST	exhaust/muffler rubbers			30/10/2020	26855	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Body\EXHAUST	exhaust clamps			30/10/2020	26855	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Elect\ELECT P&W	tidy up start clamps			30/10/2020	26855	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Hydraulics\HYD LEAKS	remove and reseal and refit leg swivel			27/10/2020	26855	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Body\HOUSEKEEP	wash and test loader for leaks			27/10/2020	26855	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Body\PAINT/REST	fit cover to grapple slew motor and point			27/10/2020	26855	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Hydraulics\HYD LEAKS	hydraulic oil leak at grapple			27/10/2020	26855	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Hydraulics\HOSES	shorten all grab hoses (too long) Rinlatech			27/10/2020	26855	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Chassis\HOUSEKEEP	Repair cracks in boom & crane base R9961 R10041 T10055 Replace bottom main lift pin			20/10/2020	26855	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Hydraulics\DAMAGE	Remove main lift ram to have 4 x new ram end bearings fitted T10058 R10067			20/10/2020	26855	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Hydraulics\DAMAGE	Remove outer boom ram to have ram end bearings fitted			20/10/2020	26855	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Chassis\DAMAGE	Repair or replace crane top housing that connects to outer boom & fit pins			20/10/2020	26855	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Chassis\HOUSEKEEP	Repair boom stand & cracks			20/10/2020	26855	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Hydraulics\DAMAGE	Fit new slew motor pinion gear			20/10/2020	26855	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	DrCabRep\HOUSEKEEP	Repair hand rail R10084			20/10/2020	26855	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Hydraulics\RAM	dipper boom ram bearing r/s			16/10/2020	26855	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Hydraulics\RAM	dipper boom ram bearing i/s			16/10/2020	26855	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Body\PAINT/REST	wash truck and loader			15/10/2020	26855	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Hydraulics\OIL LEAK	remove swivel to be strip and inspected			15/10/2020	26855	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Rosewood - Workshop	Hydraulics\OIL LEAK	staffa motor leakine lots of oil (fit reco staffa motor bv rinlatech). staffa motor leakine lots of oil		fit reco staffa motor	13/10/2020	26798	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Rosewood - Workshop	Chassis\DAMAGE	broken leg pin			13/10/2020	26798	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Rosewood - Workshop	Hydraulics\MOTOR	staffa motor leaking lots of oil		replace staffa motor	13/10/2020	26798	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Rosewood - Workshop	Hydraulics\RAM	dipper boom ram bearing i/s		started to replace ram (hydraulic lift) but was not coming off. Aborted after talking to Wayne	13/10/2020	26798	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Rosewood - Workshop	Body\EXHAUST	broken exhaust mount rubbers			09/10/2020	21851	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Eneine\FUEL TANK	fuel leak all fuel lines			09/10/2020	21851	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Engine\BELTS/TENS	belt tensioner to be replaced			09/10/2020	21851	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	VehService\BS	B Service	VehService\BS		09/10/2020	21851	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
					called out to Rosewood, broken RHR lower leg pin										
P22	Rosewood - Workshop	Chassis\DAMAGE	broken leg pin		replaced pin travelled home	02/10/2020	26798	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Hydraulics\OIL LEAK	staffa motor leaking lots of oil			02/10/2020	26798	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Hydraulics\RAM	dipper boom ram bearing r/s			02/10/2020	26798	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	VehService\BS	B Service	VehService\BS		23/09/2020	26701	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	DrCabElect\HEATER REP	clean up under engine and around heater hose area thorough test run under load with heater taps in various configurations. Suspect heater core leak check hydraulics operation replace bolt in slew pedal pivot check and adjust slew pedals			05/09/2020	26553	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Hydraulics\VALVES	operators to monitor			05/09/2020	26553	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Engine\COOL LEAKS	repair suspect heater hose end and replace clamp			04/09/2020	26553	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Engine\HOUSEKEEP	check coolant and oil remove grab stand foot plate and spin around as it was fitted incorrectly and not holding boom			04/09/2020	26553	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Chassis\HOUSEKEEP	test fit all good		boom stand on wrone	02/09/2020	26525	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Engine\COOL LEAKS	check for coolant leak. Intermittent and not present			02/09/2020	26525	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Body\HOUSEKEEP	grease loader and check over			19/08/2020	6741	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Chassis\DAMAGE	replace lower leg pin			19/08/2020	6741	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Body\BREAKDOWN	called out to loader, steve not working			14/08/2020	26456	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Body\MOUNTS	"robbed" bolt from L22 to reolace missine bolt in oedal pivot			14/08/2020	26456	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Albury - Workshop	Elect\BATTERY	re-mount battery cover			11/08/2020		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Myrtleford - Workshop	Hydraulics\VALVES	replace joy stick ball joint on RHS			07/08/2020	26424	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	DrCabRep\HOUSEKEEP	replace hood lining			07/08/2020	26424	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Body\HOUSEKEEP	wash loader test run recheck for leaks and check over			07/08/2020	26424	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Chassis\HOUSEKEEP	grease loader			07/08/2020	26424	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Insp\INT INSP	recheck work and paperwork			07/08/2020	26424	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	DrCabElect\UNST/GAUGE	fit strobe light to cab			31/07/2020	26400	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Hydraulics\RAM	R&R RHF leg R9624			31/07/2020	26400	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Engine\OIL LEAK	replace oil filter tube			31/07/2020	26400	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Hydraulics\OIL/FILTER	top up hyd oi lbolts)			31/07/2020	26400	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	DrCabElect\UNST/GAUGE	oil pressure gauge			31/07/2020	26400	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	DrCabElect\ELECT P&W	wiper motor not working		remove dash fit bulbs	31/07/2020	26400	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	DrCabElect\UNST/GAUGE	lights in gauges not working		check wiper switch and motor	31/07/2020	26400	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	DrCabRep\MOUNTS	repair stop in foot pedals			31/07/2020	26400	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Hydraulics\DAMAGE	remove LHF lea and work oin			31/07/2020	26400	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Hydraulics\DAMAGE	replace LHF leg mount on chassis			31/07/2020	26400	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	DrCabRep\WIPERS	fit new windscreen washer bottle			31/07/2020	26400	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	DrCabElect\UNST/GAUGE	fit new volt gauge			31/07/2020	26400	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Hydraulics\DAMAGE	inspect all leg ram pins/bushes, all need repair		all resealed and rebushed	30/07/2020	26423	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Hydraulics\DAMAGE	lee ram oivot oins and bushes u/s x4		all done	30/07/2020	26423	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Hydraulics\RAM	secondary ram on boom needs attention			30/07/2020	26423	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Chassis\HYDRAULICS	boom pivots need closer inspection		need's rebushing and possible pin	30/07/2020	26423	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Hydraulics\HYD LEAKS	replace RHS plunger seals and o-rings			28/07/2020	26400	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Chassis\HOUSEKEEP	weld craddle cracks			28/07/2020	26400	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Elect\ELECT P&W	iumo start loader due to flat batterv			28/07/2020	26400	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Hydraulics\PUMP	fit seal kit to hyd pilot pump			28/07/2020	26400	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Hydraulics\RAM	replace LHR leg ram and pins			25/07/2020	26400	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Hydraulics\DAMAGE	inspect all leg ram pins/bushes, all need repair			25/07/2020	26400	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Hydraulics\DAMAGE	leg ram pivot pins and bushes u/s x4			25/07/2020	26400	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Hydraulics\RAM	secondary ram on boom needs attention			25/07/2020	26400	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Chassis\HYDRAULICS	boom pivots need closer inspection			25/07/2020	26400	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Engine\ENG TUNE	carry out valve adjustment			24/07/2020	26400	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Engine\OIL LEAK	replace rocker cover gaskets			24/07/2020	26400	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Hydraulics\OIL LEAK	Rekit Leaking Leg Swivel			24/07/2020	26400	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	RINLATECH ENGINEERING	PRENTICE
P22	Myrtleford - Workshop	Chassis\DAMAGE	Weld Tios on Grab		repair arab cracks	24/07/2020	26400	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	RINLATECH ENGINEERING	PRENTICE
P22	Myrtleford - Workshop	Elect\WORK LIGHT	repair work lights			17/07/2020	26400	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Body\DAMAGE	light brackets			17/07/2020	26400	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Body\MOUNTS	hose brackets			17/07/2020	26400	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Body\PANELS	engine cover missing remove top of engine cover			17/07/2020	26400	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Body\PANELS	refit engine cover			17/07/2020	26400	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Hydraulics\PUMP	replace piolt pump on loader		resealed servo pump	15/07/2020	26400	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Chassis\HOUSEKEEP	LHF lea oivot not takina erease		need removine and inspected	15/07/2020	26400	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Chassis\HOUSEKEEP	LHF leg top pin grease nipple not taking grease			15/07/2020	26400	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Engine\HEATER TAP	fan belt making sounds		inspected all good	15/07/2020	26400	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Chassis\TRL LEGS	check front LHS leg pin, replace grease nipples on front L&R side RHS has broken nipple as pen last request		all four cylinders replaced and new pins fitted	15/07/2020	26400	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Engine\OIL LEAK	motor leaking engine oil over deck		front cover leaking but pilot pump resealed	15/07/2020	26400	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Hydraulics\HYD LEAKS	main slew motor leakine oil also		tested and rechecked all eood	15/07/2020	26400	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	DrCabRep\HOUSEKEEP	needs bracket to sit folder in above UHF			15/07/2020	26400	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Hydraulics\RAM	all 3 tips on grab need replacing damaging log			15/07/2020	26400	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Hydraulics\OIL LEAK	oil leaking on deck slip hazard		inspected all good pilot pump resealed and pressure set by Rinlatech	15/07/2020	26400	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Hydraulics	all controls very slow		check and adjust hyd pressures	15/07/2020	26400	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Elect\BATTERY	cover missine form batterys trio hazard			15/07/2020	26400	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Hydraulics\HOUSEKEEP	LHS joystick sticking		need's new ball joint in handle	15/07/2020	26400	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Air Con\HEATER	thermostat control not working		inspected all good	15/07/2020	26400	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Body\HOUSEKEEP	replace grease nipple as page 117823		all are good	15/07/2020	26400	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	DrCabRep\DAMAGE	hand rail on loader deck broken			15/07/2020	26400	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Hydraulics\RAM	grab ram leakine oil		inspected all eood	15/07/2020	26400	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE

P22	Myrtleford - Workshop	Hydraulics\RAM	L/hand rear leg ram has oil leak			15/07/2020	26400	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Hydraulics\VALVES	grab pressure down		pressure's tested by Rinlatech	15/07/2020	26400	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Hydraulics\HYD LEAKS	fluid leaks getting worse		a lot have been fixed and tested	15/07/2020	26400	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Chassis\DAMAGE	Repair Grab Cracks			15/07/2020	26400	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Chassis\HYDRAULICS	front LHS pee pin cracked and unable to grease		Rinlatech	15/07/2020	26400	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Hydraulics\HYD LEAKS	grab ram has leaking seal		inpected all good	15/07/2020	26400	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Engine\COOL LEAKS	coolant leak			15/07/2020	26400	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Engine\OIL LEAK	fuel/oil leak on motor (injector)		pilot pump leaking resealed	15/07/2020	26400	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Hydraulics\VALVES	grab pressure down		pressure tested by Rinlatech	15/07/2020	26400	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Albury - Workshop	Chassis\HYDRAULICS	arab ram broken. Reolaced ram and fittinas. Reoaired bent arab webbine. Tooped uo hydraulic oil			26/06/2020		Repair	Completed	Greenfreight Loaeine NSW	LOADPRENT	Albury	ALR	Albury Workshoe	PRENTICE
P22	Rosewood - Workshop	VehService\BS	B Service	VehService\BS		23/06/2020	26385	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Myrtleford - Workshop	DrCabRep\WIPERS	new wiper blade		wiper insert ok	23/06/2020	25824	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	DrCabRep\WIPERS	new wiper blade			23/06/2020		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Rosewood - Workshop	Engine\COOL LEAKS	coolant leak? Needs checking			17/06/2020	26364	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
					check LHR leg ram oil leak. Can do with a good pressure wash (we don't have one) to monitor properly										
					leak is very minimal at this stage, driver to monitor										
P22	Rosewood - Workshop	Hydraulics\OIL LEAK	grab ram leaking oil		grab ram no leaking badly, has been on workshop floor all afternoon with no trace left on floor. Will monitor	17/06/2020	26364	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Hydraulics\RAM	L/hand rear leg ram has oil leak			17/06/2020	26364	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Hydraulics\VALVES	grab pressure down		grab pressure to be checked when loader returns to Myrtleford	17/06/2020	26364	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Chassis\HOUSEKEEP	grease loader and check over			05/06/2020	26304	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Tumut - Workshop	Chassis\DAMAGE	fit 2 new too lee ram pins			21/05/2020	26250	Repair	Completed	Greenfreight Loaeine NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P22	Rosewood - Workshop	Chassis\HYDRAULICS	front LHS peg pin cracked and unable to grease		went to replace broken leg ram, none in stock in Tumut	21/05/2020	26281	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Hydraulics\HYD LEAKS	grab ram has leaking seal			21/05/2020	26281	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	DrCabRep\WIPERS	new wiper blade			21/05/2020	26281	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Engine\COOL LEAKS	coolant leak			21/05/2020	26281	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Eneine\OIL LEAK	fuel/oil leak on motor (iniector)			21/05/2020	26281	Repair	Completed	Greenfreight Loaeine NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Hydraulics\OIL LEAK	hydraulic oil leak under cab leaking onto deck		replace blown hydraulic steel pipe with flexible hose (sublet, hydraulink) and top y hydraulic tank (60 liters)	21/05/2020	26281	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
			bring loader to Tumut guage cracks												
			prepare to weld												
P22	Tumut - Workshop	Chassis\DAMAGE	preheat and weld all cracks			15/05/2020	26256	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P22	Rosewood - Workshop	Hydraulics\HYD LEAKS	fluid leaks getting worse			12/05/2020	26238	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Eneine\HOUSEKEEP	check over and arease			12/05/2020	26238	Repair	Completed	Greenfreight Loaeine NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Engine\COOL LEAKS	tighten radiator hoses			12/05/2020	26238	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Chassis\HOUSEKEEP	LHF leg pivot not taking grease			12/05/2020	26238	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Chassis\HOUSEKEEP	LHF leg top pin grease nipple not taking grease			12/05/2020	26238	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Hydraulics\HYD LEAKS	oil leaking from steeel pipe on valve bank			09/05/2020	26238	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Eneine\COOL LEAKS	coolant leak at too hose			09/05/2020	26238	Fault	Completed	Greenfreight Loaeine NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Tumut - Workshop	Body\DAMAGE	RHS deck about to fall off		weld brackets that hold deck on	07/05/2020	26209	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P22	Tumut - Workshop	Hydraulics\HYD LEAKS	Fit seals to leg spool			07/05/2020	26209	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
					Fluid leaks getting worse										
P22	Tumut - Workshop	Engine\HOUSEKEEP	check fluid levels		fluid leak coming out of slew valve bank plunger	07/05/2020	26209	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P22	Rosewood - Workshop	VehService\BS	Service Due B Service	VehService\BS	B Service loader	29/04/2020	26148	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Tumut - Workshop	Engine\COOL LEAKS	coolant leak		tighten heater hoses where they go into cab (loose clamps)	29/04/2020	26145	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P22	Tumut - Workshop	VehService\BS	B Service	VehService\BS		29/04/2020	26145	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P22	Tumut - Workshop	Eneine\HOUSEKEEP	oil leak over motor and smoke comine off it			25/04/2020	26123	Fault	Completed	Greenfreight Loaeine NSW	LOADPRENT	Albury	ALR	Tumut Workshoo	PRENTICE
P22	Tumut - Workshop	Engine\BREAKDOWN	travel to machina			25/04/2020	26123	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P22	Tumut - Workshop	Engine\OIL LEAK	check oil leak			25/04/2020	26123	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
			check idlers												
			check pulleys												
P22	Tumut - Workshop	Engine\BELTS/TENS	check fan belts			25/04/2020	26123	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P22	Tumut - Workshoo	Eneine\COOL LEAKS	check hoses			25/04/2020	26123	Repair	Completed	Greenfreight Loaeine NSW	LOADPRENT	Albury	ALR	Tumut Workshoo	PRENTICE
P22	Rosewood - Workshop	Engine\COOL LEAKS	coolant leak? Needs checking			19/04/2020	2609	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Hydraulics\RAM	grab ram leaking oil			19/04/2020	2609	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Hydraulics\RAM	L/hand rear leg ram has oil leak			19/04/2020	2609	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Hydraulics\VALVES	grab pressure down			19/04/2020	2609	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Chassis\HOUSEKEEP	check over and arease			19/04/2020	2609	Repair	Completed	Greenfreight Loaeine NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Chassis\HOUSEKEEP	replaced 3 broken grease nipples			19/04/2020	2609	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Myrtleford - Workshop	DrCabRep\DOOR LOCK	door lock loose in need of repair		refer 116930	10/04/2020	2614	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	Engine\HOUSEKEEP	trottle very hard to pull up and down not getting full reverse		refer 119619	10/04/2020	2614	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Myrtleford - Workshop	DrCabRep\DOOR LOCK	door latch on cab frame is about to break		refer 116930	10/04/2020	2614	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
			get hoses made												
			travel to Laurel Hill hoses have wrong fitting												
P22	Tumut - Workshop	Hydraulics\BREAKDOWN	travel to Tumut			09/04/2020	2614	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
			get hoses fixed												
P22	Tumut - Workshop	Hydraulics\HOSES	fit to prentice grab at change over			09/04/2020	2614	Repair	Completed	Greenfreight Loaeine NSW	LOADPRENT	Albury	ALR	Tumut Workshoo	PRENTICE
P22	Tumut - Workshop	Hydraulics\BREAKDOWN	call out to bush			08/04/2020	2604	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
			pick up grab ram hose to get new one made												
P22	Tumut - Workshop	Hydraulics\HOSES	fit hose too long but make do until new ones are made			08/04/2020	2604	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
			B Service												
P22	Rosewood - Workshop	VehService\BS	thorough grease	VehService\BS		21/03/2020		Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	DrCabElect\RADIO	UHF need replacing			18/03/2020	25891	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Engine\HOUSEKEEP	replace throttle cable		refer to job#277391	07/03/2020	25827	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
			throttle cable needs replacing												
P22	Rosewood - Workshop	Engine\HOUSEKEEP	repairs done to try to keep going		replace throttle cable	07/03/2020	25827	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Eneine\COOL LEAKS	replace leakine heater taps on eneine			06/03/2020	25827	Repair	Completed	Greenfreight Loaeine NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Chassis\DAMAGE	Broken Leg Pin, RHR Lower			06/03/2020	25827	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Engine\WATER PUMP	water leak R8061. water leak		sublet repairs at Holbrook (Caltex replace water pump)	13/02/2020	25715	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	VehService\BS	Service Due	VehService\BS		13/02/2020	25715	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Engine\HOUSEKEEP	check coolant leak, looks like water pup, cleared and rechecked, going to run for a shift and recheck			13/02/2020	25705	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshoo	Chassis\HYDRAULICS	left front lee pin & make uo hvd hoses. left front lee pin		check lee pin. still intact but will require new bushinas	08/02/2020	25663	Fault	Completed	Greenfreight Loaeine NSW	LOADPRENT	Albury	ALR	Rosewood Workshoo	PRENTICE
P22	Myrtleford - Workshop	DrCabRep\DOOR LOCK	Tighten Loose Door Latch			06/02/2020	2614	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
			called out to Maragle after hours												
			replace hose from valve bal to main ram with one off P-14. will have new one made and replace												
			check operation, all good												
P22	Rosewood - Workshop	Hydraulics\BREAKDOWN	return home			04/02/2020	25612	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
					locate repair oil leak in grab										
P22	Rosewood - Workshop	Hydraulics\OIL LEAK	oil leak on top of grab near rotator		degrease check operator	29/01/2020	25548	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshoo	Eneine\FUEL TANK	lub throttle cable temo repair		straighten light and rewire	25/01/2020		Repair	Completed	Greenfreight Loaeine NSW	LOADPRENT	Albury	ALR	Rosewood Workshoo	PRENTICE
			oil leak up in grab R&R no. 117813 supply leg ram seal kit & servo filters												
P22	Tumut - Workshop	Hydraulics\OIL LEAK	1. oil leak up in grab R&R no. 117813			24/01/2020		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Wodonga Workshop	PRENTICE
P22	Tumut - Workshop	Hydraulics\RAM	grab no pressure to hold log keep falling out			24/01/2020		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Wodonga Workshop	PRENTICE
P22	Albury - Workshop	Engine\ENG TUNE	carry out major service			17/01/2020	2250572	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	Hydraulics\OIL/FILTER	replace hydraulic filter degrease grab			17/01/2020	2250572	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshoo	Workshoo\MOVE ASSET	oick uo oarts from Aldonza Enaineerinz			15/01/2020		Repair	Completed	Greenfreight Loaeine NSW	LOADPRENT	Albury	ALR	Albury Workshoo	PRENTICE
P22	Albury - Workshop	Chassis\HYDRAULICS	replaced damaged outer boom ram			14/01/2020		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	Chassis\HYDRAULICS	replaced both pins			14/01/2020		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Tumut - Workshop	Body\HOUSEKEEP	replace grease nipple as page 117823			11/12/2019	967672	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
					call out red strip rd cannot grease dipper boom book grease nipple broken off front bearing destroyed cannot remove old grease nipple										
			cracks in grab very bad		will need drilling out when cearing changed										
P22	Tumut - Workshop	Hydraulics\RAM	grease nipple broken off in outerboom ram		grapple very bad cracks gauge out prepare to weld, weld up take photos sent does need a rebuild badly more time	05/12/2019	25392	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P22	Tumut - Workshop	DrCabRep\DAMAGE	hand rail on loader deck broken			05/12/2019	25392	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
			main lift very slow and intermitent lift												
P22	Tumut - Workshop	Hydraulics\RAM	others functions seem ok		FIT HYD PUMP OFF P18 TO P22	03/12/2019	25377	Fault	Completed	Greenfreight Loaeine NSW	LOADPRENT	Albury	ALR	Tumut Workshoo	PRENTICE
P22	Rosewood - Workshop	Workshop\MOVE ASSET	CALL OUT TO BENDEMER TO SECURE LEG PIN			28/11/2019	25345	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Body\TANK LID	LATER @ WORK SHOP CUT OUT OLD PIN & REPLACE		REMOVE TYRES TO ACCESS	28/11/2019	25345	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Hydraulics\RAM	REPLACED GRAB PIN			21/11/2019	25290	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Tumut - Workshop	Hydraulics\HOUSEKEEP	LHS joystick sticking			18/10/2019	25153	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P22	Tumut - Workshoo	Air Con\HEATER	thermostat control not working			18/10/2019	25153	Repair	Completed	Greenfreight Loaeine NSW	LOADPRENT	Albury	ALR	Tumut Workshoo	PRENTICE
P22	Rosewood - Workshop	DrCabElect\THROTTLE	LUB & FREE UP STICKEY THROTTLE			02/10/2019	25015	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Air Con\AIR CON	re-round and restrain a/c hoses, were rubbing on fuel lift pump			22/09/2019	24975	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Engine\ELECT P&W	tidy and restrain wiring in engine bay			22/09/2019	24975	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	DrCabElect\ELECT P&W	adjust door clutch			22/09/2019	24975	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Hydraulics\HOSES	fit correct hose under main boom oivot. used a lonaer one on breakdown earlier in week until a new one are available			22/09/2019	24975	Repair	Completed	Greenfreight Loaeine NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Hydraulics\HOSES	straighten steel hyd pipe that was causing hose to rub			22/09/2019	24975	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	VehService\BS	Service	VehService\BS		22/09/2019	24975	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
			replace hydraulic hose												
P22	Tumut - Workshop	Hydraulics\HOSES	main boom to fly boom			20/09/2019	24969	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P22	Rosewood - Workshop	Hydraulics\RAM	replace outer top main boom/flyboom connecting			20/09/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Hydraulics\RAM	degrease and wash off boom and deck			20/09/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Chassis\HOUSEKEEP	replace multiple broken grease nipples			11/09/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshoo	Body\HOUSEKEEP	thoroughly grease loader			11/09/2019		Repair	Completed	Greenfreight Loaeine NSW	LOADPRENT	Albury	ALR	Rosewood Workshoo	PRENTICE
P22	Albury - Workshop	DrCabRep\DOOR LOCK	Door not shutting properley			10/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	Engine\OIL LEAK	Oil leak out of engine. Not sure where from			10/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	Body\PANELS	Needs new engine cover. Missing			10/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	DrCabRep\WINDSCREEN	windscreen cracked			10/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshoo	DrivLine\SHOCK ABS	back left shock broken			10/09/2019		Fault	Completed	Greenfreight Loaeine NSW	LOADPRENT	Albury	ALR	Albury Workshoo	PRENTICE
P22	Albury - Workshop	Prod Hose\SHOCK ABS	front left shock loss			10/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	Body\MOUNTS	grill needs fixing			10/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	Prod Hose\WIPERS	wiper blades			10/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	DrCabRep\DOOR LOCK	right hand door getting hard to open			10/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshoo	Body\MOUNTS	right hand step			10/09/2019		Fault	Completed	Greenfreight Loaeine NSW	LOADPRENT	Albury	ALR	Albury Workshoo	PRENTICE
P22	Albury - Workshop	DrCabRep\WINDSCREEN	window leak right hand side			10/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	Susp\SHOCK ABS	right hand back shock			10/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	DrivLine\OIL LEAK	pinned seal			10/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	Body\AIR LEAK	air leak up cab			10/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	Eneine\OIL LEAK	leak in motor			10/09/2019		Fault	Completed	Greenfreight Loaeine NSW	LOADPRENT	Albury	ALR	Albury Workshoo	PRENTICE
P22	Albury - Workshop	Body\HOUSEKEEP	NO GREASE GUN. NO ONE GREASES IT!			10/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	Engine\ELECT P&W	throttle very tight			10/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	Body\MOUNTS	Windscreen guard loose			10/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	Engine\HEATER TAP	heater hose leaking at tap			10/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	Body\DAMAGE	ties need doine on arab			10/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	Elect\ELECT P&W	Handles at the controls need fixing			10/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	DrCabRep\DAMAGE	water coming in on floor			10/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE

P22	Albury - Workshop	Air Con\AIR CON	a/c air vents need fixing no front ones work."too hot"			10/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	Hydraulics\HYD LEAKS	log grab has multi oil leaks			10/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	Hydraulics\DAMAGE	log grab has large crack in frame			10/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	Hydraulics\RAM	single lift ram has leaking seal			10/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshoo	DrCabRep\WIPERS	windscreen wioers have fault. work only sometimes			10/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshoo	PRENTICE
P22	Albury - Workshop	Hydraulics\MOTOR	rotator motor leaking			10/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	Air Con\AIR CON	ac not working properly			10/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	Engine\DAMAGE	throttle cable very hard			10/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	Hydraulics\RAM	grab ram seals are leaking bad, replace as per request 25/2/19 doc.no.117604			10/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	Driv\rw\DAMAGE	excessive movement in slew drive/circle			10/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	Body\TRL\ LEGS	back RHS leg plate is cracked			10/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	VehService\DS	Service near due			10/09/2019		Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	Air Con\AIR CON	clean/replace a/c filters			10/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	Hydraulics\BREAKDOWN	grab drops go of log's			10/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshoo	Eneine\CONSUMABLE	needs new throttle cable			10/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshoo	PRENTICE
P22	Albury - Workshop	Hydraulics\PUMP	hydraulic pressure is very weak			10/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	Hydraulics\RAM	broken lift ram shaft			10/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	Engine\CONSUMABLE	throttle cable is sticking - needs replacing			10/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	Hydraulics\PUMP	hydraulic pressure is very weak			10/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	Hydraulics\RAM	broken lift ram shaft			10/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	Engine\HOUSEKEEP	throttle cable is sticking needs replacing			10/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	Hydraulics\HYD LEAKS	rotator motor leaking in gab and landing on windscreen of truck			10/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	DrCabElect\INST/GAUGE	no gauge lights			10/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	Elect\ELECT P&W	no switch lights			10/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshoo	DrCabRep\HOUSEKEEP	LHS console strut is broken			10/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshoo	PRENTICE
P22	Albury - Workshop	DrCabRep\DOOR LOCK	door latch on loader frame is loose			10/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	Hydraulics	foot slew control is sticking on - I have greased and lubed			10/09/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	Hydraulics\RAM	WASH,plug and package hyd ram and motor for transport and repair			10/09/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Rosewood - Workshop	Engine\OIL LEAK	motor leaking engine oil over deck			06/09/2019	24895	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshoo	Hydraulics\HYD LEAKS	main slew motor leakine oil also			06/09/2019	24895	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshoo	PRENTICE
P22	Rosewood - Workshop	DrCabRep\HOUSEKEEP	needs bracket to sit folder in above UHF			06/09/2019	24895	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	DrCabRep\DOOR LOCK	door lock loose in need of repair			06/09/2019	24895	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Tumut - Workshop	Engine\HEATER TAP	coolant leaking out of heater tap		broken hose on heater at clamp back	29/08/2019	24810	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P22	Tumut - Workshop	Engine\HEATER TAP	fan belt making sounds			29/08/2019	24810	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P22	Rosewood - Workshoo	Body\DAMAGE	reolace broken RHR lee oin			27/08/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshoo	PRENTICE
P22	Tumut - Workshop	Body\HOUSEKEEP	replace grease nipples			16/08/2019	24684	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P22	Tumut - Workshop	Hydraulics\RAM	LHS front L&R top stabilizer pin, RHS front L top stabilizer pin			16/08/2019	24684	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P22	Tumut - Workshop	DrCabRep\HOUSEKEEP	LHS console strut broken			16/08/2019	24684	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P22	Wodonga - Workshop	Hydraulics\HYD LEAKS	Repaired hydraulic oil leaks at valve bank		Tested, degreased & washed Clean up oil mess Top up Hydraulic oil	27/07/2019	24485	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Wodonga Workshop	PRENTICE
P22	Rosewood - Workshop	Hydraulics\PUMP	Replace rotator with reconditioned unit		Test operation - All good	20/07/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Wodonga - Workshop	Hydraulics\OIL/FILTER	Inspect hydraulics not working		Replaced blocked filter, Checked electrical pilot bypass, refitted pilot filter correctly, tetsed machine including when hot	04/07/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Wodonga Workshop	PRENTICE
P22	Wodonga - Workshop	Body\HOUSEKEEP	Wash		Washed hydraulic hoses, pipes & oil cooler/radiator	04/07/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Wodonga Workshop	PRENTICE
P22	Tumut - Workshop	VehService\AS	Service Due 50 hours			07/06/2019	24350	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P22	Rosewood - Workshoo	Workshoo\MOVE ASSET	check over for use after sittine for a while			31/05/2019	22336	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshoo	PRENTICE
P22	Rosewood - Workshop	Body\HOUSEKEEP	grease loader			31/05/2019	22336	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Albury - Workshop	Chassis\Boom	replace broken main lift pin and rebuild cylinders Service remove broken long grease nipple on leg pivot, didn't have one, sent pic to Nich to order several greased loader			11/05/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Rosewood - Workshop	VehService\BS	degreased and pressure washed loader, driver and Toppo to monitor for oil leaks	VehService\BS		07/05/2019		Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Tumut - Workshop	Hydraulics\PUMP	hydraulics are slow			30/04/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P22	Tumut - Workshop	Engine\CONSUMABLE	needs new throttle cable			30/04/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P22	Rosewood - Workshop	Hydraulics\RAM	replaced leaking grab ram & repair leaking leg ram			20/03/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Albury - Workshop	Elect\WORK LIGHT	REPAIR WORK LIGHTS			08/03/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Rosewood - Workshoo	Bodv\DAMAGE	needs new bolt in back oin on lee finish off service express trucks			27/02/2019		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshoo	PRENTICE
P22	Rosewood - Workshop	Engine\FILTERS	fit engine air filter at long point			26/02/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshoo	VehService\BS	B Service	VehService\BS		26/02/2019		Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshoo	PRENTICE
P22	Tumut - Workshop	VehService\BS	B SERVICE	VehService\BS		24/02/2019	23501	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P22	Tumut - Workshop	VehService\BS	B SERVICE	VehService\BS		24/01/2019	23724	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P22	Rosewood - Workshop	Air Con\AIR CON	a/c air vents need fixing no front ones work."too hot" AC AIR VENTS NEED FIXING NO FRONT WORK (TO HOT)			16/01/2019	944513	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Wodonga - Workshop	Air Con\AIR CON	COMPLETED ON 28/1/19 clean parts			16/01/2019		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Wodonga Workshop	PRENTICE
P22	Albury - Workshop	Workshop\CLEAN	pack away tools			18/12/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	Hydraulics\RAM	REPLACE LOWER MAIN BOOM PIN. CUT OUT OLD BOSS AND REPLACE			16/12/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Tumut - Workshoo	VehService\BS	B SERVICE	VehService\BS	travel to Tumut T6116 take truck over to ETS to use their fork lift remove tripple pump and fit c/o pump top up hyd oil warm up system. Operate machine test pressures main/grab 2100psi outer/rotator 2100psi	14/12/2018	23501	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshoo	PRENTICE
P22	Albury - Workshop	Hydraulics\PUMP	EVERY FUNCTION IS VERY SLOW. NO PRESSURE IN GRAB. DROPPING LOGS		slow 2600psi fitted bearings into c/o cylinder remove main lift cylinder c/o fittings and fit c/o ram	14/12/2018	23497	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	Hydraulics\RAM	lift ram leaking		pack up tools and return truck to Tumut depot	14/12/2018	23497	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	Hydraulics\OIL LEAK	RHS ram leaking still on main boom			12/12/2018	23491	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	VehService\BS	Due for B Service call at 11pm. Broken ram fitting (hyd/ram) organise to repair Saturday	VehService\BS		12/12/2018	23491	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Tumut - Workshop	Hydraulics\RAM	remove damaged cylinder and fitting repaired one boom lights shorting replaced R outer boom light			09/12/2018	23475	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P22	Tumut - Workshop	Elect\WORK LIGHT	rewire from main boom lights to outer boom grab pin			09/12/2018	23475	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P22	Tumut - Workshop	Body\DAMAGE	replaced broken grab pin			09/12/2018	23475	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P22	Albury - Workshop	Chassis\BREAKDOWN	BROKEN GRAB PIN			07/12/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	Bodv\TRL\ LEGS	LHS pin broken on back leg (paddle)			05/12/2018		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	Elect\WORK LIGHT	out a boom lights keeo blowine			05/12/2018		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	DrCabElect\RADIO	repaired CP.H.F Holder			31/10/2018	23358	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	DrCabElect\RADIO	repaired isolation hand pulse			31/10/2018	23358	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	Elect\WORK LIGHT	repaired boom lights			31/10/2018	23358	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	DrCabRep\SEAT	replaced seat runners			23/10/2018	23345	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	DrCabRep\SEAT	reoaired LH arm rest for strut			23/10/2018	23345	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	Body\DAMAGE	straightened/repaired outer boom pipes repaired cracked main boom checked main lift rams bottom pin - machining required tightened engine mount brackets			23/10/2018	23345	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	Hydraulics\RAM	degreased and washed			23/10/2018	23345	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	Air Con\AIR CON	a/c needs doing			10/10/2018	23348	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	DrCabElect\ELECT P&W	hand controls need new one thanks			10/10/2018	23348	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Rosewood - Workshoo	Workshoo\MOVE ASSET	travel to Tumut grind out cracks in grab			26/09/2018	23302	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshoo	PRENTICE
P22	Rosewood - Workshop	Body\DAMAGE	weld			26/09/2018	23302	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Workshop\CLEAN	clean up workshop			26/09/2018	23302	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Workshop\MOVE ASSET	return to Rosewood. Unload ute			26/09/2018	23302	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	VehService\BS	B SERVICE	VehService\BS	B service at Tumut	22/09/2018	23277	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshoo	Workshoo\MOVE ASSET	Travel to Tumut. Return to Tumba			22/09/2018	23277	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshoo	PRENTICE
P22	Albury - Workshop	Hydraulics\RAM	main lifting ram leaking			21/09/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	Hydraulics\HOUSEKEEP	grease nipples some need replacing			21/09/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	VehService\BS	Service in 37 hrs	VehService\BS		21/09/2018		Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	DrCabRep\WIPERS	needs new wiper blade			07/09/2018	23134	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	DrCabRep\DAMAGE	water comina in on floor			07/09/2018	23134	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	DrCabRep\DAMAGE	LHS walkway bent and slippery		leaking grab cylinder ram fitting thread damaged in cylinder swap out with c/o ram	07/09/2018	23134	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Tumut - Workshop	Hydraulics\RAM	FIT C/O CYLINDER		sent to scan log for repair	05/09/2018	23108	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P22	Tumut - Workshop	Workshop\MOVE ASSET	travel to - from Rosewood - Tumut			05/09/2018	23108	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P22	Albury - Workshop	Hydraulics\DAMAGE	REPLACE BROKEN HAND GRIPS			04/09/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Rosewood - Workshop	Hydraulics\BREAKDOWN	REPLACE BLOWN HOSE		breakdown travel to Lyrebird Crk Rd. Bago Ck	31/08/2018	23072	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Engine\HOSES	replaced blown hose. Top up			31/08/2018	23072	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Workshop\MOVE ASSET	return to Tumba			31/08/2018	23072	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Albury - Workshop	Engine\EXHAUST	FIT ELBOW TO EXHAUST			30/08/2018	23085	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Rosewood - Workshop	VehService\BS	B SERVICE	VehService\BS		30/08/2018	23085	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Bodv\DAMAGE	reolace broken arab craddle with second hand one of P14 blown hyd hose. Lyrebird Rd. Bago Crk, replaced hose top up hyd oil 20lts.			30/08/2018	23085	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Hydraulics\HOSES	Test ok			29/08/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Albury - Workshop	Brakes\BRAKE ADJ	Brake adjustment			29/08/2018	936151	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	VehService\BS	Service due in 30 hrs	VehService\BS		28/08/2018		Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Tumut - Workshop	Bodv\DAMAGE	reolace R/R lee oin			24/08/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P22	Tumut - Workshop	DrCabRep\DOOR LOCK	fit door and striker off P14			24/08/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P22	Tumut - Workshop	Workshop\MOVE ASSET	travel to Tumut			24/08/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P22	Albury - Workshop	Engine\ELECT P&W	REPLACE STOPPER SOLENIOD.			18/08/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE

			stopper solenoid															
			organise solenoid from Cummins															
			organise fit up by ETS for Friday															
P22	Tumut - Workshop	Workshop\CLEAN	return to Tumba															
P22	Rosewood - Workshop	VehService\BS	B Service	VehService\BS			10/08/2018	22913	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE		
			Travel to Tumut.															
P22	Rosewood - Workshop	Workshop\MOVE ASSET	Pack up ready for Tumut for B service.				10/08/2018	22913	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE		
P22	Albury - Workshop	Body\DAMAGE	need 2 rubber latches for steel door on windscreen				10/08/2018		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P22	Albury - Workshop	DrCabRep\DOOR LOCK	Need 2 rubber latches for steel door on windscreen.				10/08/2018		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P22	Rosewood - Workshop	DrCabRep\DOOR LOCK	latch on loader door - worn out				09/08/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE		
P22	Rosewood - Workshop	VehService\BS	Due for Service 48hours	VehService\BS			09/08/2018		Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE		
P22	Albury - Workshop	VehService\BS	B SERVICE	VehService\BS			09/08/2018		Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P22	Albury - Workshop	Hydraulics\MOTOR	removed rotator motor, valve and pinion from de-commisioned machine and packed for courier to Rosewood				03/08/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
					remove rotator motor from P26 (off rd.)													
P22	Tumut - Workshop	Hydraulics\MOTOR	grapple rotator broke		remove rotator motor from P22. refit c/o unit		18/07/2018	12721	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE		
P22	Tumut - Workshop	Workshop\MOVE ASSET	travel to Tumba				18/07/2018	12721	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE		
			replace broken pin															
			weld keeper bolt															
P22	Rosewood - Workshop	Body\DAMAGE	tighten fitting on grab which had been leaking				11/07/2018	22699	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE		
P22	Albury - Workshop	Hydraulics\RAM	seals R/H tower lift ram leaking				10/07/2018		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
			went to remove main lift cylinder, no jocket to undo nut															
			move truck to access cylinder. Remove hoses and plug															
P22	Rosewood - Workshop	Hydraulics\VALVES	shift truck out of way				06/07/2018	22699	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE		
					travel to Tumut													
					fit exchange arm rests													
					B Service													
P22	Albury - Workshop	VehService\BS	B SERVICE	VehService\BS	tidy up. Return to Rosewood		06/07/2018	22699	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
			check parts for P22 muffler															
P22	Rosewood - Workshop	Engine\EXHAUST	check cylinder leaking on main lift				26/06/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE		
					exhaust leak													
					found that the u-clamp was crack and broken replace with new u-clamp and nuts fitted up test ok													
			MOUNTS THAT HOLD MUFFLER BROKEN.		replace muffler mount rubbers													
P22	Albury - Workshop	Engine\EXHAUST	REPLACE EXHAUST ELBOW AND RAIN CAP.		replace exhaust elbow and rain cap		21/06/2018	22655	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE		
P22	Rosewood - Workshop	Hydraulics\PUMP	swap out lift pump from old motor				13/06/2018	2258	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE		
P22	Rosewood - Workshop	VehService\BS	Service	VehService\BS			13/06/2018	2258	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE		
P22	Rosewood - Workshop	Hydraulics\MOTOR	finish off engine and re-tieing lumes up start and run for 15mins. Test ok				13/06/2018	2258	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE		
P22	Rosewood - Workshop	Engine\PUMP	finished off engine put on hydraulic pump				12/06/2018	2258	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE		
P22	Albury - Workshop	Hydraulics\HYD LEAKS	Remove and refit swap out engine				10/06/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P22	Rosewood - Workshop	Hydraulics\MOTOR	swap out engine				09/06/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE		
P22	Rosewood - Workshop	Wash\WASH	wash down loader engine				09/06/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE		
P22	Rosewood - Workshop	Workshop\MOVE ASSET	load into ute				09/06/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE		
P22	Rosewood - Workshop	Workshop\MOVE ASSET	delivered to Cummins				09/06/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE		
P22	Rosewood - Workshop	Hydraulics\MOTOR	remove engine				07/06/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE		
P22	Rosewood - Workshop	Hydraulics\MOTOR	remove enaine from P14				06/06/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE		
P22	Rosewood - Workshop	Hydraulics\PUMP	put truck in w/shop. Remove hyd pump				05/06/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE		
P22	Rosewood - Workshop	Hydraulics\MOTOR	start to remove engine				05/06/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE		
P22	Rosewood - Workshop	Hydraulics\RAM	broke fitting on grab ram		replace 90° hydraulic fitting in the grab ram		26/05/2018	22560	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE		
P22	Rosewood - Workshop	Hydraulics\BREAKDOWN	breakdown mill rd greads leaking o'ring tested ok				26/05/2018	22560	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE		
P22	Albury - Workshop	Hydraulics\RAM	lift ram leaking				20/05/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P22	Albury - Workshop	Engine\EXHAUST	muffler rubber broken				20/05/2018		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P22	Tumut - Workshop	Elect\ELECT P&W	stop solenoid not working				01/05/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE		
			starting fault															
			engine wil only run for 2 seconds before stopping															
P22	Rosewood - Workshop	Engine\FAULT CODE	diagnose faulty stop solenoid. Order parts and supply to ETS to fit				01/05/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE		
P22	Albury - Workshop	DrCabRep\SEAT	strut missine of arm rest				06/04/2018	22246	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P22	Albury - Workshop	DrCabRep\SEAT	seat in loader needs looking at				06/04/2018	22246	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
			Call out 12:00am-3:00am															
			fan hitting shrould. Remove top cover															
P22	Rosewood - Workshop	Cooling\BREAKDOWN	diagnose cause welded plates on radiator had let go				05/04/2018	22246	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE		
P22	Rosewood - Workshop	Cooling\RADIATOR	removed radiator out of P14 to fit into P22 to get in going for pm shift				05/04/2018	22246	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE		
P22	Albury - Workshop	Workshop\CLEAN	ordered replacement parts				24/03/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P22	Albury - Workshop	DrCabRep\ENG COVER	roof lining needs replacing		installed stay for roof lining		22/03/2018	22206	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P22	Albury - Workshop	Eneine\ELECT P&W	throttle very tight				22/03/2018	22206	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P22	Albury - Workshop	DrCabRep\SEAT	strut missing of arm rest		checked seat and strut - parts required		22/03/2018	22206	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P22	Albury - Workshop	DrCabRep\SEAT	seat in loader needs looking at				22/03/2018	22206	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P22	Albury - Workshop	Body\HOUSEKEEP	topped up hydraulic oil (30 lts approx)				09/03/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
			remove grab rotator motor out of grab off P23															
P22	Myrtleford - Workshop	Hydraulics\MOTOR	FIT SEAL KIT TO GRAB MOTOR OFF P22				24/02/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE		
P22	Albury - Workshop	Hydraulics\RAM	Deerease. wash and load hydraulics rams for reoair				24/01/2018		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
			Paint welds															
			Fold up for service															
P22	Albury - Workshop	Body\PAINT/REST	Washed windscreen & windows				29/12/2017		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P22	Albury - Workshop	Workshop\CLEAN	cleaned deck from ram job, degrease and washed loader				14/12/2017	22190	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P22	Albury - Workshop	Hydraulics\RAM	fit outer : boom ram				13/12/2017	22190	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P22	Albury - Workshop	Chassis\CHAS CRACK	cleaned out bosses for oins. welded up cracked bosses				13/12/2017	22190	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P22	Albury - Workshop	Workshop\CLEAN	cleaned up mess from job				13/12/2017	22190	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P22	Albury - Workshop	Body\ELECT P&W	replaced leg position switch. Replaced globes				08/12/2017		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P22	Albury - Workshop	Body\HOUSEKEEP	repaired console				08/12/2017		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P22	Albury - Workshop	Chassis\BULLBAR	remove fly boom ram				06/12/2017		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
			hydraulics slow "cantation" noise															
			checked and replaced hydraulic filter															
			checked pilot system filter. Replaced assembly with original style from donor machine. By-passed after market filter															
P22	Albury - Workshop	Hydraulics\HYD LEAKS	replaced leaking hoses				02/12/2017		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P22	Albury - Workshop	Engine\FAULT CODE	Engine warning light coming on				01/12/2017	925643	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P22	Albury - Workshop	Engine\FAULT CODE	Motor has a miss				01/12/2017	925643	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P22	Albury - Workshop	Elect\ELECT P&W	RHS side light flickering				01/12/2017	925643	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P22	Albury - Workshop	DrCabRep\AIR LEAK	Bad air leak behind cab				01/12/2017	925643	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
			Key barrel hard to tuen															
P22	Albury - Workshop	DrCabRep\ELECT P&W	Key hole thing loose				01/12/2017	925643	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
					RECO A/C UNIT													
P22	Albury - Workshop	Air Con\AIR CON	NO AC. NO COMPRESSOR.		removed unit for overhaul as per invoice		23/11/2017	22183	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
			check pilot pressure setting															
P22	Albury - Workshop	DrCabElect\INST/GAUGE	set at 300psi, adjusted to 450psi as required				14/11/2017	22182	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P22	Rosewood - Workshop	Hydraulics\PUMP	every function is very slow				20/10/2017		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE		
P22	Rosewood - Workshop	Hydraulics\PUMP	no pressure in grab logs keep falling out				20/10/2017		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE		
P22	Rosewood - Workshop	Air Con\AIR CON	no aircondition - no compressor on it				20/10/2017		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE		
P22	Rosewood - Workshop	Body\HOUSEKEEP	no grease gun - no one grease it				20/10/2017		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE		
P22	Rosewood - Workshop	Hydraulics\RAM	main LHS lift ram rear eve worn out				20/10/2017		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE		
P22	Albury - Workshop	VehService\AS	Due for A2 Service				12/08/2017	919811	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P22	Albury - Workshop	Brakes\BRAKE ADJ	check back drive brakes				12/08/2017	919811	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P22	Albury - Workshop	Body\MOUNTS	right hand top step				12/08/2017	919811	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P22	Albury - Workshop	Susp\SHOCK ABS	right hand back shock loses				12/08/2017	919811	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P22	Albury - Workshop	Eneine\FAULT CODE	ene warnine lisht keeps comine on and off				12/08/2017	919811	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P22	Albury - Workshop	VehService\BS	snowy trucks - 00037907	VehService\BS	200 hour service - B		28/07/2017	21709	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P22	Albury - Workshop	Hydraulics\OIL LEAK	Work performed by snowy trucks - 37882		check and top up hydraulic oil		26/07/2017		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P22	Albury - Workshop	Body\TRL LEGS	fit new pin to rear leg on loader		snowy trucks - 00037834		22/07/2017	917214	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P22	Rosewood - Workshop	Body\TRL LEGS	lag pin		RHR lag pin top of ram broken repaired		05/07/2017		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE		
P22	Rosewood - Workshop	Hydraulics\HOSES	Email from Chris Matthews requestina order number				30/06/2017		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE		
P22	Albury - Workshop	VehService\BS	Completed B service	VehService\BS			29/06/2017	22142	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P22	Albury - Workshop	VehService\AS	service due loader				29/06/2017	21432	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P22	Rosewood - Workshop	Hydraulics\OIL LEAK	Oil leak in grab				21/06/2017		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE		
P22	Albury - Workshop	Air Con\AIR CON	Air con not working - seized compressor, degas air con system, remove air con system		As per invoice - 00171917		02/06/2017		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P22	Tumut - Workshop	VehService\BS	Service	VehService\BS			01/06/2017		Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE		
P22	Tumut - Workshop	VehService\DS	Service Due				30/05/2017		Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE		
P22	Tumut - Workshop	VehService\DS	please grease				30/05/2017		Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE		
P22	Albury - Workshop	Hydraulics\OIL LEAK	leak in outer boom getting bad throttle control - hard to use				26/05/2017		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P22	Tumut - Workshop	VehService\BS	B service due	VehService\BS			23/05/2017	910122	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE		
P22	Tumut - Workshop	DrCabElect\THROTTLE	throttle cable tight				20/05/2017	910030	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE		
P22	Tumut - Workshop	VehService\BS	200 hrs service	VehService\BS			20/05/2017	910030	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE		
P22	Tumut - Workshop	DrCabElect\HEATER REP	heater not working				18/05/2017	909694	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE		
P22	Tumut - Workshop	VehService\BS	Service	VehService\BS			09/05/2017	21035	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE		
P22	Tumut - Workshop	VehService\DS	service near due 26 hours				04/05/2017	908177	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE		
P22	Albury - Workshop	Hydraulics\OIL LEAK	LEAKING SWIVEL VALVE.		OVER HAUL SWIVEL VALVE (RINLATECH)		28/04/2017		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P22	Rosewood - Workshop	Body\CHN/RLR/MN	chain guild				13/04/2017		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE		
P22	Rosewood - Workshop	Hydraulics\HOSES	replace fitting/hose in grab				18/03/2017	20875	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE		
P22	Rosewood - Workshop	VehService\BS	Service	VehService\BS			18/03/2017	20875	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE		
P22	Albury - Workshop	Engine\FILTERS	REPLACE ENGINE FILTERS		TUMUT WORK SHOP		04/02/2017		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P22	Albury - Workshop	Hydraulics\PUMP	REPLACE PILOT PUMP		SCANDINAVIAN ENGINEERING TUMUT		04/02/2017		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P22	Albury - Workshop	Hydraulics\HOSES	replace leaking hydraulic hoses		Tumut w/shop		03/02/2017		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P22	Albury - Workshop	Hydraulics\PUMP	replace piolt pump on loader		Scandinavian forestry and engineering		02/02/2017		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P22	Albury - Workshop	VehService\BS	B service prentice loader	VehService\BS	Snowy truck service 30-1-17		01/02/2017		Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P22	Albury - Workshop	Elect\ELECT P&W	front right light not working "outer arm"				01/02/2017		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P22	Albury - Workshop	Hydraulics\PUMP	hydraulic pump leaking				01/02/2017		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P22	Tumut - Workshop	VehService\BS	B Service Due	VehService\BS			26/01/2017		Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE		
P22	Albury - Workshop	Chassis\CONSUMABLE	replace grab saftey chain		rosewood w/shop		12/01/2017		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P22	Albury - Workshop	Elect\WORK LIGHT	REPLACE BROKEN WORK LIGHT		TUMUT AUTO ELECTRICS		29/12/2016		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P22	Albury - Workshop	Cooling\COOL LEAKS	FIND AND REPAIR COOLANT LEAK REPAIR HYDRULIC LEAK		SNOWY TRUCK SERVICE 13-12-16		23/12/2016		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P22	Albury - Workshop	Hydraulics\HOSES	reolace blown erab hoses		tumut w/shoo		16/12/2016		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshoo	PRENTICE		
P22	Albury - Workshop	Chassis\HOUSEKEEP	weld rod onto worn grab tips		Roddys engineering 9-12-16		16/12/2016		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE		
P22	Tumut - Workshop	Engine\FILTERS	supply filters for service				14/12/2016		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE		
P22	Tumut - Workshop	Engine\RADIATOR	leak bottom of radiator				14/12/2016		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE		
P22	Tumut - Workshop	Engine\RADIATOR	leak hoses bottom of right hand control				14/12/2016		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE		
P22	Tumut - Workshop	Hydraulics\CONSUMABLE	grease aun to grease oins on loader		tumut W/shoo		26/11/2016		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE		
P22	Tumut - Workshop	Hydraulics\RAM	Check main lift ram bearing and pin for wear		Scandinavian forestry and enginering 31-10-16		16/11/2016		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE		

P22	Rosewood - Workshop	DrivLine	l/front diff axle brush rubber			01/11/2016	892141	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Tumut - Workshop	Engine\START MOTR	remove replace starter motor		Tumut Auto electrics 19-10-16	26/10/2016		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P22	Tumut - Workshop	Susp\SHOCK ABS	refit shock absorbers repair grab pin broken		Snowy truck service 19-10-16	26/10/2016		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P22	Rosewood - Workshop	Engine\DAMAGE	muffler bracket rubber			18/10/2016	890236	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Tumut - Workshop	Bodv\FUEL TANK	fuel cap fall off			17/09/2016	886168	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P22	Tumut - Workshop	DrivLine\CLUTCH	clutch too hard			17/09/2016	886168	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P22	Tumut - Workshop	DrivCabRep\WIPERS	wiper washer - new wiper blades			17/09/2016	886168	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P22	Tumut - Workshop	Brakes\BRAKE ADJ	engine brake all noise			17/09/2016	886168	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P22	Tumut - Workshop	Steering\WHEEL ALGN	steering all off the road			17/09/2016	886168	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P22	Tumut - Workshop	DrCabElect\ELECT P&W	cab light			17/09/2016	886168	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P22	Tumut - Workshop	DrCabRep\WINDSCREEN	windscreen cracked			17/09/2016	886168	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Tumut Workshop	PRENTICE
P22	Albury - Workshop	Body\HOUSEKEEP	LH rear leg pin needs replacing		replaced top cylinder leg pin	25/08/2016		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	Body\HOUSEKEEP	requires 2x 'D' shackles for drag chain			18/08/2016		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	Chassis\HOUSEKEEP	needs a grease		Operators responsibility	18/08/2016		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	Body\HOUSEKEEP	Loader leakine water into cabin.			10/08/2016	19725	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	Air Con\HEATER	heater not working blowing hot air		turned on heater taps and adjusted heater controller.	10/08/2016	19725	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
					fitted lever										
P22	Albury - Workshop	Hydraulics\VALVES	No safety cut out lever		repaired wiring, adjusted switch & mount	10/08/2016	19725	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	Hydraulics\OIL LEAK	HYD oil needs draining. Coming out over flow		drained 1l to lower level	07/08/2016	19714	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	Hydraulics\RAM	oil leak in grapple			07/08/2016	19714	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
					degreased & washed machine										
P22	Albury - Workshop	VehService\BS	B service	VehService\BS	replaced return hydraulic oring	07/08/2016	19714	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
					added 50 liters oil										
P22	Albury - Workshop	Hydraulics\HOSES	Check Hyd oil. Replaced hyd hose on night shift.		put hose into tool box of truck	05/08/2016	19705	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	Bodv\HOUSEKEEP	Loader leakine water into cabin.		as above	05/08/2016	19705	Reapir	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	DrCabRep\WINDOW REG	Loader window needs fixing will not shut			05/08/2016	19705	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	Hydraulics\MOTOR	Rebuild slew motor		as per attached invoice	28/07/2016		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	Hydraulics\OIL LEAK	hydraulic oil leak in grab		replaced o'ring on grab ram fitting.	08/07/2016	19613	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	Hydraulics\OIL LEAK	oil leak on pilot pump		replaced o'ring. Still leaking at casting drilling. Monitor	07/07/2016	19598	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	Engine\OIL LEAK	eneine oil leak		reolaced easket / seal at access cover	07/07/2016	19598	Reapir	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
					Travel to Shelley to swap out Loader with L25.										
					Return to Albury. Found slew pinion gear to have fallen off.										
P22	Albury - Workshop	Hydraulics\MOTOR	no slew		Refit pinion. Lockitte bolt. Grease and test. Ok	06/07/2016	19598	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
					replaced rubber boots off P10										
					adjusted joysticks										
P22	Albury - Workshop	Hydraulics\VALVES	joy stick rubber boots need replacing		repaired joystick handles	28/06/2016	19560	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	DrCabRep\SEAT	seast needs looking at won't slide back and forward.		lubed runners	28/06/2016	19560	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
					removed leg ram and replaced one off P10.										
P22	Albury - Workshop	Hydraulics\RAM	Leaking RR leg ram.		Replaced top leg pin.	24/06/2016	19554	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
					replace blown hydraulic hose and top up oil.										
P22	Albury - Workshop	Hydraulics\HOSES	oil leak in grab		Washed down grapple& cabin	21/06/2016	19530	Reapir	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	Engine\FUEL TANK	fuel cap		has been replaced	18/06/2016	19523	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	DrCabRep\WIPERS	window wipers not working		wipers are working.	18/06/2016	19523	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	VehService\BS	B service due @ 19510hrs.	VehService\BS	replaced muffler mounts & strailtened muffler	18/06/2016	19523	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	Body\DAMAGE	RHF leg pin tab broken		replaced leg pin	05/06/2016	19486	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	Air Con\HEATER	heater taps need turning on		turned heater taps on.	28/05/2016	19453	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
					straightened step										
P22	Albury - Workshop	Bodv\HOUSEKEEP	step on loader needs pulling out		removed and straightened	28/05/2016	19453	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
					straightened hand rail										
P22	Albury - Workshop	Body\HOUSEKEEP	hand rail needs fixing		removed rail to straightened	28/05/2016	19453	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	DrCabRep\WIPERS	requires new wiper blade		replaced wiper blade	28/05/2016	19453	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	Hydraulics\VALVES	joy sticks need looking. A bit sticky		removed spool. Fitted new seals and polished spool. Test ok.	25/05/2016	19444	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
					Temporary repair by Cummins now not working.										
					Injetor pump has been removed for repair.12/04/2016 sent to wagga diesels for repair.										
P22	Albury - Workshop	Engine\FAULT CODE	engine will not shut off		6/05/2016 Cummins refitted injector pump.	16/04/2016	19400	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Rosewood - Workshop	Hydraulics\HYD LEAKS	remove leaking slew pump		fitted rebuilt slew motor. Rebuilt by Rinlatech.	09/04/2016	19391	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Albury - Workshop	Hydraulics\OIL LEAK	remove leaking slew			08/04/2016	19386	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Rosewood - Workshop	Bodv\DAMAGE	orones on arab to sharo damaeine loss			07/04/2016	6651	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshoo	PRENTICE
P22	Rosewood - Workshop	Hydraulics\OIL LEAK	grease line slew bearing not greasing hole in pipe			07/04/2016	6651	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Albury - Workshop	Engine\FILTERS	b service			01/04/2016		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Albury - Workshop	Engine\ELECT P&W	electrical fault fuel pump			31/03/2016		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	DrivLine\SHOCK ABS	back left shock bent			22/03/2016	866859	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshoo	DrivLine\AIR LEAK	leak in slew			22/03/2016	19262	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshoo	PRENTICE
P22	Rosewood - Workshop	Hydraulics\OIL LEAK	grapple has bad oil leak			04/02/2016		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Hydraulics\OIL LEAK	grapple has bad oil leak			04/02/2016	19200	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Hydraulics\HOSES	replace boom hose			22/01/2016	16501	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Hydraulics\HOSES	boom hoses			22/01/2016		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS		20/01/2016	19105	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Hydraulics\RAM	replace boom hose, loader got sent to scan logging to remove ram to get boom hose out -sublet			14/01/2016	19082	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
			fire pump hose												
P22	Albury - Workshop	Hydraulics\HOSES	tymyt hyd		completed	24/12/2015		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
			repair radiator												
P22	Myrtleford - Workshop	Engine\RADIATOR	barclay rad		completed	22/12/2015		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Myrtleford Workshop	PRENTICE
P22	Albury - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS		09/12/2015	18923	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Albury - Workshop	Hydraulics\MOTOR	Rebuild orentice slewing motor		Comoleted	05/12/2015		Reapir	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshoo	PRENTICE
P22	Rosewood - Workshop	Hydraulics\OIL LEAK	oil leak rotator			04/12/2015		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
			seal kit		completed										
P22	Albury - Workshop	Hydraulics\RAM	randalls		22250	20/11/2015		Reapir	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshoo	PRENTICE
P22	Rosewood - Workshop	Hydraulics\RAM	ram housing rubbing			11/11/2015	18778	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Hydraulics\RAM	slew making noise			11/11/2015	18778	Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
			leg pin shaft												
P22	Albury - Workshop	Hydraulics\RAM	aldonga eng		completed	03/11/2015		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
			caps/plug												
P22	Albury - Workshop	Hydraulics\RAM	enzed		completed	03/11/2015		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Rosewood - Workshop	Hydraulics\OIL LEAK	swivel valve leaking hydraulic oil. slew leaking hydraulic oil			03/11/2015		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Albury - Workshop	Chassis\SUSPENSION	Job Added From Invoice			30/10/2015	0	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
			filters												
P22	Albury - Workshop	Engine\FILTERS	tctc		comoleted	30/10/2015		Reapir	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshoo	PRENTICE
			replace leg ram												
P22	Albury - Workshop	Chassis\HYDRAULICS	scan logging		completed	30/10/2015		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Rosewood - Workshop	Hydraulics\RAM	requires lhr leg ram re-seal		repaired by Scan Logging (Tumut)	23/10/2015		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS		23/10/2015	18700	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Chassis\TRL LEGS	back left hand leg leaking ram seal			23/10/2015		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS		22/10/2015	1	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	DrCabRep	require servo controller rubber boots and new plastic hand part of ? tip for muffler			10/10/2015		Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS		10/10/2015	18624	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Albury - Workshop	Chassis\HYDRAULICS	Job Added From Invoice			01/10/2015	0	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Albury - Workshop	VehService\BS	Job Added From Invoice	VehService\BS		18/09/2015	0	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Albury Workshop	PRENTICE
P22	Rosewood - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS		13/09/2015	18431	Service	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Chassis\HYDRAULICS	all servo pistons and boot to be replaced			28/08/2015	18345	Repair	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE
P22	Rosewood - Workshop	Hydraulics	grab working too slow			20/08/2015		Fault	Completed	Greenfreight Logging NSW	LOADPRENT	Albury	ALR	Rosewood Workshop	PRENTICE