EquipmentName	Workshop	CodeAndSubCode	Description	Schedule	CompletionComments	DateDone	DistanceDone	WorkType	WorkState	EquipmentOwner	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
			Tyres\PRES CHECK													
LOAD22	Albury - Workshop	Tyres\PRES CHECK	FULL PRESSURE CHECK		LOW	######## 10731		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	BORDER BANDAG PTY LTD - 4	LOADER
LOAD22	Wodonga - Workshop	Elect\LLECT P&W	lots of untidy wiring needs tidying up/repair			########		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Wodonga Workshop	LOADER
			rear diff needs track rod bushes replacing													
LOAD22	Wodonga - Workshop	DrivLine\SUSPENSION	Still required to be done.			########		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Wodonga Workshop	LOADER
			front springs flattening out, shackle laid back and starting to twist in packs													
LOAD22	Wodonga - Workshop	Steering\SUSPENSION	Also right hand front ewlett worn. shackles bottomed out.			########		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Wodonga Workshop	LOADER
LOAD22	Wodonga - Workshop	Body\WIPERS	Washers U/S			########		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Wodonga Workshop	LOADER
LOAD22	Wodonga - Workshop	Elect\ELECT P&W	Air horn U/S			########		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Wodonga Workshop	LOADER
LOAD22	Wodonga - Workshop	Body\DAMAGE	Right hand rear of cab pushed in.			########		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Wodonga Workshop	LOADER
LOAD22	Wodonga - Workshop	Engine\OIL LEAK	Engine multiple oil leaks.			########		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Wodonga Workshop	LOADER
LOAD22	Wodonga - Workshop	Susp\Torque Rod	Rear track rod bushes.			########		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Wodonga Workshop	LOADER
LOAD22	Wodonga - Workshop	Engine\OIL LEAK	oil leak at compressor			########		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Wodonga Workshop	LOADER
LOAD22	Wodonga - Workshop	Elect\DOOR LOCK	headlights not roadworthy. Need replacement ASAP			########		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Wodonga Workshop	LOADER
LOAD22	Wodonga - Workshop	Susp\SPRING PACK	front springs bottomed out on rear shackles			########		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Wodonga Workshop	LOADER
LOAD22	Wodonga - Workshop	DrivLine\CONSUMABLE	left cross shaft (bell housing) grease niggle missing and stripped			########		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Wodonga Workshop	LOADER
LOAD22	Wodonga - Workshop	Engine\FUEL TANK	diesel leak below fuel pump area			########		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Wodonga Workshop	LOADER
LOAD22	Wodonga - Workshop	Hydraulics\HYD LEAKS	Loader has major Hydraulic leak.			########		Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Wodonga Workshop	LOADER
LOAD22	Wodonga - Workshop	DrCabElect\HEATER REP	heater not working a demister was work last Thursday "unsafe"			########		Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Wodonga Workshop	LOADER
LOAD22	Wodonga - Workshop	DrCabElect\HEATER REP	heater not working			########		Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Wodonga Workshop	LOADER
LOAD22	Wodonga - Workshop	Elect\HEAD LIGHT	Head Lights very dull uncafe.			########		Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Wodonga Workshop	LOADER
			Tune Engine (Cummins)													
LOAD22	Wodonga - Workshop	Engine\ENG TUNE	Purchase Order Number: WW0760246			######## 10731		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Wodonga Workshop	LOADER
LOAD22	Wodonga - Workshop	Elect\BATTERY	FOUND BATTERIES FLAT PICKING UP FOR SERVICE. ACCESSORIES LEFT ON.		TESTED BATTERIES. REPLACED BATTERIES AND TWO CORRODED TERMINALS. SERVICED OTHER TERMINALS. STARTED AND TESTED.	########		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Wodonga Workshop	LOADER
LOAD22	Albury - Workshop	Engine\BATTERY	Battery			######## 10731		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Albury Workshop	LOADER
LOAD22	Rosewood - Workshop	Elect\BATTERY	replace batteries			######## 10723		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Rosewood Workshop	LOADER
			called out to niyne to jumpstart both truck and loader													
LOAD22	Rosewood - Workshop	Elect\BATTERY	tested alternator and batteries. oranavsed replacements			######## 7239		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Rosewood Workshop	LOADER
LOAD22	Rosewood - Workshop	Engine\OIL LEAK	oil leak at compressor			######## 10165		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Rosewood Workshop	LOADER
LOAD22	Rosewood - Workshop	Elect\HEAD LIGHT	headlights not roadworthy. Need replacement ASAP			######## 10165		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Rosewood Workshop	LOADER
LOAD22	Rosewood - Workshop	Susp\SPRING PACK	front springs bottomed out on rear shackles			######## 10165		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Rosewood Workshop	LOADER
LOAD22	Rosewood - Workshop	DrivLine\CONSUMABLE	left cross shaft (bell housing) grease niggle missing and stripped			######## 10165		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Rosewood Workshop	LOADER
LOAD22	Rosewood - Workshop	Engine\FUEL TANK	diesel leak below fuel pump area			######## 10165		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Rosewood Workshop	LOADER
LOAD22	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			######## 10165		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Rosewood Workshop	LOADER
LOAD22	Rosewood - Workshop	VehService\AS	A Service	VehService\AS		######## 10165		Service	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Rosewood Workshop	LOADER
					jump start, batteries flat due UHF and phone being left on											
			headlight hardly see very uncafe		drive vehicle to change and check steering/handling I cannot fault the way the vehicle steers on handles											
LOAD22	Rosewood - Workshop	Elect\HEAD LIGHT	all over the road not very safe		headlights have been modified and need to be replaced	######## 10129		Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Rosewood Workshop	LOADER
LOAD22	Rosewood - Workshop	Body\HOUSEKEEP	check batteries/starting/charging			######## 9500		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Rosewood Workshop	LOADER
LOAD22	Wodonga - Workshop	Engine\BATTERY	Jump Start.			######## 9486		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Wodonga Workshop	LOADER
			Blown Right hand side headlight, still very dull.													
LOAD22	Wodonga - Workshop	Elect\HEAD LIGHT	in the wet very dangerous as can only see iust in front of truck.		Replaced light Assembly.	######## 9154		Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Wodonga Workshop	LOADER
LOAD22	Wodonga - Workshop	Elect\HEAD LIGHT	low beam not working very well		Refer Job # 168768	######## 9154		Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Wodonga Workshop	LOADER
LOAD22	Wodonga - Workshop	Elect\HEAD LIGHT	Blown headlight also very dull.			######## 8807		Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Wodonga Workshop	LOADER
LOAD22	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			######## 8980		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Wodonga Workshop	LOADER
LOAD22	Wodonga - Workshop	Elect\ELECT P&W	lots of untidy wiring needs tidying up/repair		Above rear diff.	######## 8980		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Wodonga Workshop	LOADER
			rear diff needs track rod bushes replacing													
LOAD22	Wodonga - Workshop	DrivLine\SUSPENSION	Still required to be done.			######## 8980		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Wodonga Workshop	LOADER
			front springs flattening out, shackle laid back and starting to twist in packs													
LOAD22	Wodonga - Workshop	Steering\SUSPENSION	Also right hand front ewlett worn. shackles bottomed out.			######## 8980		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Wodonga Workshop	LOADER
			low beam not working very well													
			inspect headlights for being dull													
			Found LED's fitted have been modified to suit headlight.													
LOAD22	Wodonga - Workshop	Elect\HEAD LIGHT	Will need to look into correct globes to suit		Right hand head light blown	######## 8980		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Wodonga Workshop	LOADER
LOAD22	Wodonga - Workshop	Brakes\AIR LEAK	back air leak in left side brake			######## 8980		Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Wodonga Workshop	LOADER
LOAD22	Wodonga - Workshop	Elect\INDICATORS	blinker not working		Working when tested.	######## 8980		Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Wodonga Workshop	LOADER
			loader has major Hydraulic leak.													
LOAD22	Wodonga - Workshop	Hydraulics\HYD LEAKS	3 wie sumo drive seal weeping.			######## 8980		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Wodonga Workshop	LOADER
LOAD22	Wodonga - Workshop	Body\WIPERS	Washers U/S			######## 8980		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Wodonga Workshop	LOADER
LOAD22	Wodonga - Workshop	Elect\ELECT P&W	Air horn U/S			######## 8980		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Wodonga Workshop	LOADER
LOAD22	Wodonga - Workshop	Body\DAMAGE	Right hand rear of cab pushed in.			######## 8980		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Wodonga Workshop	LOADER
			Right hand rear bussie hose fitting.													
LOAD22	Wodonga - Workshop	Brakes\BOOSTER	Left hand front drive airbae fittina.			######## 8980		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Wodonga Workshop	LOADER
					Fix left hand front airbae hose fittine and right hand rear brake booster hose fittine air leaks.											
					Attempted to repair leaking coolant filter housing isolation tap.											
					Repair coolant leak at tap, rapid supplied new tap and fittings. Found hose to tap was hard, worn and split.											
					Removed hose and built replacement hose. Filled hose and reassembled parts.											
LOAD22	Wodonga - Workshop	Cooling\COOL LEAKS	Coolant filter tap leaking		Folded loader crane and parked.	######## 8980		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Wodonga Workshop	LOADER
LOAD22	Wodonga - Workshop	Workshop\MOVE ASSET	Unfold front arm carrier			######## 8980		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Wodonga Workshop	LOADER
LOAD22	Wodonga - Workshop	Engine\OIL LEAK	Engine multiple oil leaks.			######## 8980		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Wodonga Workshop	LOADER
LOAD22	Wodonga - Workshop	Susp\Torque Rod	Rear track rod bushes.			######## 8980		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Wodonga Workshop	LOADER
LOAD22	Wodonga - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS		######## 8980		Service	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Wodonga Workshop	LOADER
			low beam not working very well													
			inspect headlights for being dull.		inspect headlights for being dull.											
			Found LED's fitted have been modified to suit headlight.		Found LED's fitted have been modified to suit headlight.											
LOAD22	Wodonga - Workshop	Elect\HEAD LIGHT	Will need to look into correct globes to suit.. low beam not workine very well		Will need to look into correct globes to suit.	######## 8081		Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Wodonga Workshop	LOADER
LOAD22	Rosewood - Workshop	Hydraulics\HYD LEAKS	Organised Ezzed to attend to repair hydraulic leaks.			######## 8081		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Rosewood Workshop	LOADER
LOAD22	Rosewood - Workshop	DrCabElect\HEATER REP	test drive and check heater operation. Engine coolant temp not getting high enough suspect thermostat needs changing			######## 7533		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Rosewood Workshop	LOADER
LOAD22	Rosewood - Workshop	Steering\SUSPENSION	straighten steering wheel			######## 7533		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Rosewood Workshop	LOADER
LOAD22	Rosewood - Workshop	DrCabElect\HEATER REP	heater not working a demister was work last Thursday "unsafe"			######## 6286		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Rosewood Workshop	LOADER
LOAD22	Rosewood - Workshop	DrCabElect\HEATER REP	heater not working			######## 6286		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Rosewood Workshop	LOADER
LOAD22	Rosewood - Workshop	DrCabElect\HEATER REP	heater not working			######## 6286		Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Rosewood Workshop	LOADER
LOAD22	Myrtleford - Workshop	DrCabElect\INSTSAUGE	dash folding out		tape dash surround back together as per instuction from Wayne	######## 6027		Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Elect\BATTERY	batteries need checking "flat"			######## 6027		Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Myrtleford Workshop	LOADER
			check battery voltage 11.7 static 13.3 running													
			cleaned battery terminals 12.7v static, 13.8v idle													
			shut down with high beam and driving lights and kept on for 8 mins. 12.2v and started perfectly.13.8v at idle													
LOAD22	Myrtleford - Workshop	Elect\ELECT P&W	will monitor			######## 6027		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	VehService\AS	A Service Due at 5000	VehService\AS		######## 6027		Service	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Myrtleford Workshop	LOADER
LOAD22	Rosewood - Workshop	DrivLine\SUSPENSION	rear diff needs track rod bushes replacing			######## 5664		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Rosewood Workshop	LOADER
LOAD22	Rosewood - Workshop	Steering\SUSPENSION	front springs flattening out, shackle laid back and starting to twist in packs			######## 5664		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Rosewood Workshop	LOADER
LOAD22	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			######## 5664		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Rosewood Workshop	LOADER
LOAD22	Rosewood - Workshop	Steering\SUSPENSION	replace missing nut of RHF shocker top mount			######## 5664		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Rosewood Workshop	LOADER
LOAD22	Rosewood - Workshop	VehService\AS	A Service	VehService\AS		######## 5664		Service	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Rosewood Workshop	LOADER
LOAD22	Rosewood - Workshop	Engine\ELECT P&W	batteries dead flat, very cold and hard to get started			######## 4988		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Rosewood Workshop	LOADER
LOAD22	Rosewood - Workshop	Elect\ELECT P&W	jump start, UHF left on			######## 4829		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Rosewood Workshop	LOADER
					called out to Laurel Hill, lost all drive, both hi & low											
					checked tail shaft movement, none at all											
					when I was checking hi/low it "Locked" like a normal range and has worked ever since											
					test drove, all good											
LOAD22	Rosewood - Workshop	DrivLine\GEARBOX	no gears		*possible froze no issue in a valve? O drained a lot of water out of tanks	######## 4791		Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Rosewood Workshop	LOADER
			3am call, vehicle not starting and running													
			talked driver through some tests over phone. Extremely cold temp lead to me thinking it was diesel waxing													
			I had Rob check when he come in, colant level was found to be low													
			#driver not doing pre-start checks													
LOAD22	Rosewood - Workshop	Engine\FUEL TANK	# couldn't get back to sleep so came to work early			######## 4725		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Rosewood Workshop	LOADER
			truck fires but stops													
LOAD22	Tumut - Workshop	Engine\FAULT CODE	remove crane from crack			######## 1829		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Tumut Workshop	LOADER
			check fluids top up coolant Bliters													
			start truck continues to run													
LOAD22	Tumut - Workshop	Engine\HOUSEKEEP	test drive ok			######## 1829		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Tumut Workshop	LOADER
			truck wont start jump start shuts down in 30 sec turn off key restart shuts down in 30 sec. unload crane left bonnet coolant low add 8 liters coolant. Check oil ok													
LOAD22	Tumut - Workshop	Engine\FAULT CODE	start enable. enaine runs all good			######## 4621		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Tumut Workshop	LOADER
LOAD22	Myrtleford - Workshop	Engine\OIL LEAK	oil leak front of motor			######## 4741		Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Myrtleford Workshop	LOADER
			grease truck check over													
			steering													
			steering wheel not in straight ahead position													
			check drop arm, ackman arm, drag arm													
			bevel ends, spring packs													
			checked too in/out													
LOAD22	Tumut - Workshop	Steering\HOLDSKEEP	#Note: I travelled to Tumut to inspect this vehicle. It was at Ash Mill. I finished and went to Tumut and at 15:45 to clean up and workshop was locked. No sign of Robert or Bowser. Cookie			########		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Tumut Workshop	LOADER
LOAD22	Rosewood - Workshop	Steering\DAMAGE	called to Tumut to asses front end after driver hit wombat hole*			######## 4800		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Rosewood Workshop	LOADER
			-apprentice reported no problems but steering wheel was out 90°, this means something													
			-got to loader at ARA Mill and waited for truck loading to case													
			-inspected and tested, turns one way better than other													
			-photographed and discussed photo with Wayne, he will look asap but I believe grog link is bent past normal slope													
			tread hose													
LOAD22	Rosewood - Workshop	Steering\HOLDSKEEP	left hand back shock reported month ago?			######## 4800		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Rosewood Workshop	LOADER
LOAD22	Rosewood - Workshop	DrivLine\SHOCK ABS	remove blinker stalk			######## 4631		Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Tumut Workshop	LOADER
LOAD22	Rosewood - Workshop	DrCabElect\INSTSAUGE	fit new blinker stalk			######## 4488		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Tumut Workshop	LOADER
LOAD22	Rosewood - Workshop	Elect\WORK LIGHT	temporary repair to work/walkway lights, trucks were waiting to go to work			######## 4464		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Rosewood Workshop	LOADER
LOAD22	Rosewood - Workshop	Elect\ELECT P&W	lots of untidy wiring needs tidying up/repair			######## 3122		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Rosewood Workshop	LOADER
LOAD22	Tumut - Workshop	Tyres\TPI-r2	PCD 2 had a split in it			########		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Tumut Workshop	LOADER
LOAD22	Myrtleford - Workshop	Elect\WORK LIGHT	refit and adjusted reverse light			########		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Myrtleford Workshop	LOADER
LOAD22	Tumut - Workshop	VehService\AS	change oil and filters B	VehService\AS		######## 825		Service	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Tumut Workshop	LOADER
LOAD22	Rosewood - Workshop	DrCabElect\HEATER REP	Turn heater taps on when service done			######## 825		Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Rosewood Workshop	LOADER
LOAD22	Rosewood - Workshop	VehService\AS	Near due for service B	VehService\AS	Finish off B service TCTC started last week	######## 825		Service	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Rosewood Workshop	LOADER
			Called to AKD mill broken shocker in threat of hitting and damaging airbag													
	Tumut - Workshop	DrivLine\SHOCK ABS	Removed shock and ordered parts			########		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Tumut Workshop	LOADER
LOAD22	Tumut - Workshop	Engine\OIL LEAK	Fit new filter cap with clamp on hose			########		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Tumut Workshop	LOADER
	Rosewood - Workshop	Brakes	Record check results as attached to this job			######## 1000127		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Rosewood Workshop	LOADER
LOAD22	Rosewood - Workshop	VehService\AS	A service	VehService\AS		######## 1000127		Service	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Rosewood Workshop	LOADER
			Tumut Auto - Wires off switch on gearbox - Topps can't find them.													
LOAD22	Tumut - Workshop	DrivLine\ELECT P&W	Remove plate on top of gearbox. Located wires that go to reverse light switch and out the terminals on switch and test working fine. Box up truck			########		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Tumut Workshop	LOADER
LOAD22	Tumut - Workshop	Brakes\AIR LEAK	back air leak in left side brake			######## 998194		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Tumut Workshop	LOADER
					remove blown hose											
					get new hose from Tumut hydraulics											
LOAD22	Tumut - Workshop	DrivLine\OIL LEAK	hole in line front diff		fit new hose check ok	######## 998194		Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Tumut Workshop	LOADER
LOAD22	Tumut - Workshop	Hydraulics\HOSES	Tumut Hydraulics supply hose and consumables			########		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Tumut Workshop	LOADER
			Supply and fit 2 tyres													
LOAD22	Tumut - Workshop	Tyres\TPI-r4	2 wheel nuts broken. told mechanic			########		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Tumut Workshop	LOADER
			TRANSMISSION													
			REPORTS OF GEARSHIFT ISSUE.													
			22/03/2021.													
			Removed driveline & exhaust pipes													
			Removed air lines & air tanks													
			Removed gearstick tower & found to be backwards													
			Removed gearbox and inspected for gearshift issue.													
			Removed selector housing and found 3rd & 4th gear selector fork bound up on sliding shaft.													
			Removed fork, cleaned slide and replaced 3rd & 4th gearfork. Refit selector housing and re-installed gearbox as required.													
			Refit gearstick in correct position													
			Re-installed driveline, air tanks, exhaust & fixtures													
			Test drive, all ok.													
LOAD22	Tumut - Workshop	DrivLine\GEARBOX	Part Number			######## 998533		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Tumut Workshop	LOADER
			called out to Greenhills, driver not able to select gears													
			internal fault of gearbox, left in bush so trucks can continue to load off it													
LOAD22	Rosewood - Workshop	DrivLine\BREAKDOWN	will require repair ASAP			######## 607053		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Rosewood Workshop	LOADER
LOAD22	Myrtleford - Workshop	DrCabElect\HOUSEKEEP	clean cabin			######## 997527		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	DrCabElect\HOUSEKEEP	repair sun panel cover			######## 997525		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	DrCabElect\RADIO	relocate am/fm radio			######## 997525		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	DrCabElect\PHONE	fit new bracket to phone speaker			######## 997525		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Elect\HEAD LIGHT	sin head rewire to suit Hi head light			######## 997525		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Body\PAINT&GT	rear bar paint			########		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Body\HOUSEKEEP	grease/check over			########		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Myrtleford Workshop	LOADER
					check into a/c operation											
					#no gas, needs repair											
					fit brake shoe											
LOAD22	Unknown - Unknown	DrCabElect\AIR CON	Replace Condensor and Dryer and Fitting and Regas and Test Air Con System			######## 997414		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Workshop\MOVE ASSET	pick up #listech			######## 997414		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Elect\DRV LIGHT	fit up new drive lights/rewire make new mounts			######## 997414		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Brakes\BRAKE ADJ	adjust truck brakes			######## 997416		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Body\MOUNTS	weld chain and hook for grab bar			######## 997416		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	Myrtleford Workshop	LOADER
			back LH shocky mount bracket removed shock													
			compressor bottom plate leaking													
LOAD22	Tumut - Workshop	Brakes	jack manifold bolts loose number 6 5 Hightened			######## 666055		Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	TWIN CITY TRUCK CENTRE - 4 - CLO	LOADER
LOAD22	Tumut - Workshop	VehService\AS	A Service	VehService\AS		######## 666020		Service	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALB	CH308U	TWIN CITY TRUCK CENTRE - 4 - CLO	LOADER
LOAD22	Myrtleford - Workshop	Workshop\MOVE ASSET	take to #clotech for boom repair			######## 997397		Repair	Completed	Greenfreight Logging NSW	LO

LOAD22	Rosewood - Workshop	Body\CHN/RUR/MN	d-shackle. Required for grab chain		######## 392735	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER
LOAD22	Albury - Workshop	Workshop\MOVE ASSET	take truck to Myrtleford and return with ute		########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER
LOAD22	Myrtleford - Workshop	Workshop\MOVE ASSET	take L-22 to Wodonga yard and return		######## 992150	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	DrivLine\WHL HUB	LHR hub seal issue replaced hub with second hand one that had to be cleaned up r10304		######## 991216	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Body\PAINT/RUST	wash truck/loader		######## 991216	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Engine\HOUSEKEEP	fix fire pump		######## 991216	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Engine\FUEL TANK	fit inline G/16 fuel tap R10284		######## 991216	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Body\HOSES	replace fire fighting hose R10282		######## 991216	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Body\MOUNTS	remount fire hose		######## 991216	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Workshop\MOVE ASSET	take L-22 to yard		######## 991216	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Body\HOUSEKEEP	check over fire pump and relocate suction line		######## 991100	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Engine\EXHAUST	exhaust clamp bracket		######## 991100	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	DrivLine\GEARBOX	bend gear shift		######## 991100	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Body\PAINT/RUST	wash truck/loader and check fuel		######## 991100	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Drivline\GEARBOX	Fit Gear Box out of L24 to L22 and test		######## 991100	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Drivline\OIL LEAK	Replace Gaskets and O rings on servo and range change		######## 991100	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Engine\OIL LEAK	replace engine rear main seal		######## 991100	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Engine\HOUSEKEEP	refit machined flywheel and new spigot bearing		######## 991100	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Drivline\TOH PACK	fit new clutch		######## 991100	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Engine\MOUNTS	replace rear engine mounts		######## 991100	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Body\MOUNTS	remount g/box coolant pipes		######## 991053	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Drivline\GEARBOX	check gearbox range change		######## 991053	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Body\PAINT/RUST	wash truck and loader		######## 991053	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Workshop\MOVE ASSET	road test and check g/box		######## 991053	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Steering\HOUSEKEEP	recirc oil & filt kingpins		######## 991058	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Steering\WHEEL BRGS	LH w/bearing adjustment		######## 991058	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Steering\KING PIN	fit RH steer kingpin kit		######## 991058	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Steering\WHEEL BRGS	adjust RH wheel bearing		######## 991058	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Susp\SHOCK ABS	fit 2x steer shockers		######## 991058	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		######## 991058	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Albury - Workshop	VehService\CS	Service As Per Attached Checklist	VehService\CS	######## 991658	Service	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER
LOAD22	Myrtleford - Workshop	Drivline\WHEEL SEAL	R&R LHR drive hub seal		######## 991039	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	ElecCabElect\ELECT P&W	replace outer cab top lights		######## 991039	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	ElecCabElect\INST/GAUGE	Dimmer Switch faulty	fit switch	######## 991039	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Albury - Workshop	Workshop\MOVE ASSET	drop truck off at wodongs yard and bring driver back to Albury yard		########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER
LOAD22	Myrtleford - Workshop	Body\PAINT/RUST	wash truck and loader		######## 991039	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Drivline\SHOCK ABS	RHR drive shocker mount missing		######## 991039	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Steering\OIL LEAK	replace power steering hose T10017		######## 991039	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Body\HOUSEKEEP	check over truck and loader		######## 991039	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Engine\ABS/SYSTEMS	tighten belts		######## 991039	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Elect\HEAD LIGHT	tidy LH h/lamp wiring		######## 991039	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Susp\SHOCK ABS	Replace LH steer lower shocker mount R132169		######## 991039	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	ElecCabElect\AIR CON	Replace air con condensor	regas and repair aircon system MAE	######## 991039	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	ElecCabElect\AIR CON	Regas air con system R10180	repair wirine and fit hath and low sensors off L-24	######## 991039	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Body\AIR LEAK	Replace cab ride height valve & fittings R10018		######## 991039	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Body\DAMAGE	Repair RH water tank RR963		######## 991039	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Body\MOUNTS	Fit tank strap rubbers		######## 991039	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Brakes\BRAKE ADJ	Brake Adjustment	done when TCTC did A Service	######## 993763	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Rosewood - Workshop	Engine\HOUSEKEEP	check oil and coolant		######## 988741	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER
LOAD22	Rosewood - Workshop	ElecCabRep\WIPERS	check washers		######## 988741	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER
LOAD22	Rosewood - Workshop	ElecCabRep\RADIO	refit UHF falling out		######## 988287	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER
			check high beam sticking on											
LOAD22	Rosewood - Workshop	Elect\HEAD LIGHT	reolaced relay		######## 988329	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER
LOAD22	Rosewood - Workshop	Elect\ELECT P&W	suspect combination switch. Wayne ordering one		######## 988280	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER
				diagnose and repair air leak at gearshift hands										
LOAD22	Rosewood - Workshop	Drivline\AIR LEAK	air leak in gear change	will need new knob in near but was holdbur air and functionine when I was finished	######## 986513	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER
LOAD22	Rosewood - Workshop	Engine\HOUSEKEEP	unfold and check oil and coolant and basics		######## 986029	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER
LOAD22	Rosewood - Workshop	ElecCabElect\RADIO	replace UHF radio		######## 985632	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER
LOAD22	Rosewood - Workshop	ElecCabElect\ELECT P&W	repair burned out wiiring to UHF		######## 985632	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER
LOAD22	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		######## 984992	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER
LOAD22	Rosewood - Workshop	VehService\AS	A Service	VehService\AS	######## 984992	Service	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER
LOAD22	Myrtleford - Workshop	Body\PAINT/RUST	wash truck		######## 983801	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Drivline\AIR LEAK	cab airbags fitting		######## 993801	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Workshop\MOVE ASSET	drop off truck to Rotetech		######## 983801	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Chassis\DAMAGE	weld in new LHF leg boss to support leg in frame of loader and refit LHF leg		######## 993801	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Wodonga - Workshop	Drivline\AS	950,000 Service Due. A Service done	RR's pre Jan-20 (system clean out) 05/08/20	########	Service	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Wodonga Workshop	LOADER
LOAD22	Myrtleford - Workshop	Cooling\RADIATOR	replace coolant and cap		######## 993750	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Workshop\MOVE ASSET	pick up		######## 993750	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	ElecCabElect\INST/GAUGE	fit fuse box cover in dash		######## 993750	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Workshop\MOVE ASSET	road test truck		######## 993750	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Body\REFLECTORS	fit fluro tap		######## 993750	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Engine\HOUSEKEEP	replace coolant		######## 993750	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	ElecCabElect\HEATER REP	replace dash and air vents with spear truck		######## 993750	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Engine\ENG FAN	replace and test engine fan		######## 993750	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Drivline\SUSPENSION	refit rear torque rod		######## 993750	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Workshop\MOVE ASSET	road test		######## 993750	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Engine\HOUSEKEEP	retighten hose clamps recheck fluids move eng breather		######## 993750	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Engine\TURBO	replace waste gate and set up		######## 993750	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	ElecCabElect\INST/GAUGE	replace main dash and tidy up elec work		######## 993750	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	ElecCabElect\INST/GAUGE	replace center dash tidy up and replace all globes		######## 993750	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		######## 993777	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	VehService\BS	B Service As Per Attached Checklist	VehService\BS	######## 993777	Service	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Elect\WORK LIGHT	repair work light wiring		######## 993750	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Elect\ELECT P&W	repair electrical junction fuse box next to batteries		######## 993750	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Body\EXHAUST	fit change over exhaust stack		######## 993750	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Engine\OIL LEAK	engine oil leak's replace sump gasket - intermed housing gasket, rocker cover gasket		######## 993750	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Engine\AKE BRAKE	refit jakes and tune-up		######## 993750	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Engine\EXHAUST	refit exhaust manifold and inlet manifold gasket		######## 993750	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Engine\HOUSEKEEP	replace thermostat		######## 993750	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Body\DAMAGE	battery box lid (make one)		######## 993750	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Engine\EXHAUST	remove/replace exhaust manifold is old one out the back		######## 993750	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Engine\OIL SAMPLE	replaced oil codes/filter housing o-rings		######## 993750	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Engine\ENG TUNE	carry out engine tune up		######## 993750	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Body\MUDGUARDS	replace LH & RH inner mTRips		######## 993750	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Elect\ELECT P&W	c/over horn on steering wheel		######## 993750	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Body\TOOLBOX	remove toolbox panel bent and weld cracks and new support inside toolbox		######## 993750	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Body\DAMAGE	fix LH and RH mudguards and walkways		######## 993750	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Body\MOUNTS	make grab rail for back of cab		######## 993750	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Body\PAINT/RUST	wash truck, loader and engine for inspection		######## 993750	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Brakes\DAMAGE	drill drive-s-cam tube broken		######## 993750	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Drivline\WHEEL BRGS	recheck all drive wheel's bearing adjustment and steer wheels		######## 993750	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Steering\SUSPENSION	On axle 2 right side - tyre rubbing on steering box pitman arm	inspected rubbing due to super single's	######## 993750	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Steering\TIE ROD	On axle 1 left side - tie rod end excessive play / movement	inspected all good	######## 993750	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Insp\DEFECT	wash off and inspect defects for parts	done	######## 993750	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Susp\SUSPENSION	replace shock absorbers x 4 ,replace wear pads and rebound rollers, replace staberiliser arm	inspected all good	######## 993750	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Susp\SHOCK ABS	On axle 3 - check absorber insecure/loose	inspected all good	######## 993750	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Susp\AIR LEAK	On axle 3 left side - check absorber leaking	inspected all good	######## 993750	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
				replaced yellow/red button and tested										
LOAD22	Myrtleford - Workshop	Brakes\DAMAGE	ADR-35 system fault, with one tank drained and when service brake is applied, maxi brake automatically applies	all mood	######## 993750	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Brakes\AIR LEAK	Between axle 2 and 3 -audible air leaks	replaced RHR airbag	######## 993750	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Susp\SUSPENSION	On axle 1, both sides - spring pack misaligned	inspected all good	######## 993750	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Engine\FUEL TANK	Fuel system leaks on left rear of engine	inspected all good	######## 993750	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Susp\SUSPENSION	On axle 1 - U bolt/s insecure	inspected all good	######## 993750	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Susp\SUSPENSION	On axle 2 and 3 both sides - U bolts insecure	inspected and tighten all good	######## 993750	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Brakes\SLACK ADJ	On axle 1 left side - excessive movement between S cam shaft and slack adjuster	inspected all good	######## 993750	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
				(brake tube broken)										
				diff needs reseal still good for now										
LOAD22	Myrtleford - Workshop	Drivline\OIL LEAK	On axle 2 - differential oil leaks	retathree all bolts	######## 993750	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Tyres\STEER TYRE	On axle 2 left side inner - tyre is insufficient tread	inspected all good	######## 993750	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Susp\AIR BAG	On axle 2 and 3 both sides - airbag suspension component mounting bolts loose(at base of air bag)	inspected all good	######## 993750	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Chassis\WINCH/STRP	On axle 2 right side - control arm safety strap frayed - check all	inspected all good chains fitted to axle's	######## 993750	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Brakes\BRAKE ADJ	On axle 2 service brake's uneven efficiency(right side low)	inspected all good	######## 993750	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Brakes\BRAKE ADJ	On axle 3 left side - service brake indicator indicates adjustment required	inspected all good	######## 993750	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Susp\SUSPENSION	On axle 2 left side - radius rod excessive movement at rear end check all	rebushed front and rear rods	######## 993750	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Chassis\DRV LN SER	realigned front drive z springs	inspected all good	######## 993750	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Susp\SHOCK ABS	repaired drive shocker dust shield	inspected all good	######## 993750	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Drivline\DRV LN SER	tightened "z" spring rear bolts front drive	tighten all good	######## 993750	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
				replaced RHR inspected others										
LOAD22	Myrtleford - Workshop	ElcCabRep\AIR BAG	replaced 1x airbag	all mood	######## 993750	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Elect\ELECT P&W	replaced 2x side marker and electrical repairs	inspected all good	######## 993750	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Drivline\SPRING HANG	replaced worn wear pads in hangers	inspected all good	######## 993750	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Susp\SUSPENSION	REPLACED WORN COMPONENTS ON FRONT AXLE.	REPLACED worn components on front replaced LH/RH shaker's	######## 993750	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Engine\ABS/SYSTEMS	ordered new belts through TCTC		######## 993750	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Body\ANTI-TITTN	replaced 2 rear most air tank chains. Wet tank was full	fit cables to and clamp brackets	######## 993750	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Brakes\SPACK PLATE	front drive lower dust covers missing	done	######## 993750	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Steering\SUSPENSION	needs new front shockers (oil leaking)		######## 993750	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Brakes\DRK CJ/HAUL	RHR drive-s-cam tube cracked	found LHR cracked RHS all good	######## 993750	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
				relcted and tune-up										
LOAD22	Myrtleford - Workshop	Engine\AKE BRAKE	no engine brake at all	tested very weak	######## 993750	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Engine\OIL LEAK	oil leak left hand side off motor	inspected all good	######## 993750	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Air Con\AIR CON	look like no belt for ac	new belts fitted	######## 993750	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER
LOAD22	Myrtleford - Workshop	Engine\OIL LEAK	oil leak rear turbo	reseaded filter housing	######## 993750	Fault	Completed	Green

				remove clutch cable															
LOAD22	Tumut - Workshop	DrivLine\CLUTCH		fit new clutch cable			######## 681157	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Tumut Workshop	LOADER			
LOAD22	Tumut - Workshop	DrivLine\CLUTCH		adjust cable			######## 682964	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Tumut Workshop	LOADER			
LOAD22	Rosewood - Workshop	DrivLine\ANGLE REPLC		call out to Pound Creek. Clutch pedal not doing anything			######## 682964	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
				found broken clutch cable															
LOAD22	Rosewood - Workshop	DrivLine\CLUTCH		drive back to yard and material for brace to service parts			######## 681964	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Tumut - Workshop	Workshop\MOVE ASSIST		travel L22 P22 to rosewood for work to be done			######## 682330	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Tumut Workshop	LOADER			
LOAD22	Tumut - Workshop	Workshop\MOVE ASSIST		travel L22 P22 to Tumut fro work to be done			######## 682330	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Tumut Workshop	LOADER			
LOAD22	Myrtleford - Workshop	DrivCabRep\MOUNTS		CAB HEV LEAKING. HCV ORDERED			######## 930693	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER			
LOAD22	Myrtleford - Workshop	DrivCabRep\AIR LEAK		Bad leak- air bag under cab			######## 930693	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER			
LOAD22	Tumut - Workshop	Body\SUSPENSION		remove and replace cab ride height valve			######## 930693	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Tumut Workshop	LOADER			
LOAD22	Rosewood - Workshop	Engine\[&]LTS/TENS		ordered new belts through TCTC			######## 681688	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	Body\AIR FITTIN		replaced 2 rear mod air tank chains. Wet tank was full			######## 681688	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	Brakes\BACK PLATE		front drive lower dust covers missing			######## 681688	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	Engine\OIL LEAK		oil leak from sump			######## 681688	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	Engine\OIL LEAK		oil leak from compressor area			######## 681688	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	Steering\SUSPENSION		needs new front shockers (oil leaking)			######## 681688	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	Brakes\BRK CHAUL		RHR drive s-cam tube cracked			######## 681688	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	Brakes		Record Check Results As Attached To This Job			######## 681688	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	VehService\AS		A Service		VehService\AS	######## 681688	Service	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	VehService\AS		A Service Due		VehService\AS	######## 681688	Service	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Tumut - Workshop	DrivLine\SUSPENSION		Weld Chain On Rear Right Air Bag			######## 680777	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Tumut Workshop	LOADER			
LOAD22	Tumut - Workshop	Elect\TRL LIGHTS		Replace Broken Clearance Lights			######## 680777	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Tumut Workshop	LOADER			
LOAD22	Tumut - Workshop	Engine\[&]LTS/TENS		check idlers pulleys			######## 681080	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Tumut Workshop	LOADER			
LOAD22	Tumut - Workshop	Elect\ALT		check alternator			######## 681080	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Tumut Workshop	LOADER			
LOAD22	Tumut - Workshop	Engine\[&]LTS/TENS		check belts			######## 681080	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Tumut Workshop	LOADER			
LOAD22	Tumut - Workshop	Engine\HOUSEKEEP		noise in motor		check noise in motor	######## 681080	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Tumut Workshop	LOADER			
				check fluids															
				all ok															
LOAD22	Tumut - Workshop	Engine\HOUSEKEEP		no noise			######## 681080	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Tumut Workshop	LOADER			
LOAD22	Tumut - Workshop	Engine\HOUSEKEEP		noise in motor		check noise in motor	######## 681080	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Tumut Workshop	LOADER			
				check idlers pulleys															
				check alternator															
LOAD22	Tumut - Workshop	Engine\[&]LTS/TENS		check belts			######## 681080	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Tumut Workshop	LOADER			
				check fluids															
				all ok															
LOAD22	Tumut - Workshop	Engine\HOUSEKEEP		no noise			######## 681080	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Tumut Workshop	LOADER			
LOAD22	Rosewood - Workshop	Brakes\BRAKE ADJ		brakes need adjustment		adjust brakes	######## 679013	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	Elect\HEAD LIGHT		headlights need adjusting (can't see when driving lights are off)		attempt to adjust lights. Need disassembly	######## 679013	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	Engine\HOUSEKEEP		engine has no horse power			######## 679013	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	Engine\AXLE BRAKE		jake brake not working properly			######## 679013	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	DrivLine\GEARBOX		gearbox range change won't pre-select			######## 679013	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	Engine\HOUSEKEEP		engine oil coolant needs checking		check over	######## 679013	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	DrivCabRep\AIR LEAK		diagnose range change issue. Ordered new cab height valve			######## 679013	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
				check vibration in drive line															
				found suspension ride height had been increased, jack shaft uni joints out of line															
LOAD22	Rosewood - Workshop	DrivLine\SUSPENSION		adjusted and had 681 test drive. all eood			######## 678440	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
						done RT.													
				diagnose heater fan not working		fit cab fan in truck													
LOAD22	Myrtleford - Workshop	DrivCabElect\HEATER REP		ordered new from TCTC		check operation. Ok	######## 678340	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER			
LOAD22	Myrtleford - Workshop	Air Con\AIR CON		Fan control for heater is broken		done RT	######## 678340	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER			
				fit cab fan in truck															
LOAD22	Tumut - Workshop	DrivCabElect\HEATER REP		check operation ok			######## 678340	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Tumut Workshop	LOADER			
				call out to Rosewood depot, truck not starting															
				tested static battery voltage 12.8volts. This is good															
				inspected battery terminals, slightly look broken															
				tightened/replaced as needed started fine															
LOAD22	Rosewood - Workshop	Elect\BATTERY		chareine voltage is 14.1 volt. All eood			######## 676551	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	Brakes		Record Check Results As Attached To This Job			######## 676411	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
						Dust Covers Missing On Front Drive Axel 3/206													
LOAD22	Rosewood - Workshop	Elect\HEAD LIGHT		Repair Headlight, Modify LED Globe & ReWire Plug To Suit.		Needs Front Shockers 13795	######## 676411	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	VehService\BS		B Service As Per Attached Checklist		VehService\BS	######## 676411	Service	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	Elect\HEAD LIGHT		RHS high beam headlight not working			######## 676078	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	DrivCabElect\ELECT P&W		RHS mirror light not working			######## 676078	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	Body\HEATER REP		no heater			######## 676078	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	DrivCabElect\ELECT P&W		windscreen washers not working			######## 676078	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	DrivCabRep\HOUSEKEEP		floor rubber on guestisk needs fixing			######## 676078	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	Body\MOUNTS		RHS top step broken mount		re-attach top step	######## 675827	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
				diagnose heater fan not working															
LOAD22	Rosewood - Workshop	DrivCabElect\HEATER REP		ordered new from TCTC			######## 674471	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	Brakes\BRAKE ADJ		brake need adjustment		adjust brakes	######## 673182	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	DrivCabElect\HEATER REP		nob missing on heater fan (can't turn)		check heater knob, will need to make something	######## 673182	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	Body\FUEL TANK		remove holed fuel tank and disassemble for sublet repair			######## 673182	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	Body\HOUSEKEEP		replace non serviceable hardware			######## 671200	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	Engine\FUEL TANK		bleed detroit as it was ran out			######## 671200	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	Elect\BATTERY		flat batteries change to new batteries		replace batteries	######## 622829	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	Elect\BREAKDOWN		call out not starting			######## 622829	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	Body\FUEL TANK		diesel pump not working			######## 670040	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Myrtleford - Workshop	DrivCabElect\HEATER REP		no heater			######## 667433	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER			
LOAD22	Myrtleford - Workshop	Air Con\HEATER		fix heater			######## 667433	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER			
LOAD22	Myrtleford - Workshop	DrivCabElect\HEATER REP		fan and heater switches needs knobs			######## 667433	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER			
LOAD22	Myrtleford - Workshop	Air Con\AIR CON		no aircon in truck			######## 667433	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER			
LOAD22	Myrtleford - Workshop	Air Con\AIR CON		no aircon very hot			######## 667433	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Myrtleford Workshop	LOADER			
LOAD22	Albury - Workshop	Elect		replaced RH side marker lights			########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER			
LOAD22	Albury - Workshop	Elect		repaired wiring to RH side marker lights			######## 671200	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER			
LOAD22	Albury - Workshop	Elect\HEAD LIGHT		replaced headlight globes with led inserts			########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER			
LOAD22	Albury - Workshop	Elect\HEAD LIGHT		repaired broken LH headlight and mounts			########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER			
LOAD22	Albury - Workshop	Elect\INDICATORS		repaired broken LH indicator and mounts			########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER			
LOAD22	Albury - Workshop	Elect\ALT DR		replace alternator, converted to new style i-mount			######## 960638	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER			
LOAD22	Albury - Workshop	Air Con\AIR CON		help bin (Auto elec) with a/c			######## 960638	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER			
LOAD22	Albury - Workshop	Engine\ENG FAN		replace engine fan			######## 960638	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER			
LOAD22	Albury - Workshop	Workshop\MOVE ASSIST		unfold loader and throw bonnet			######## 960638	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER			
LOAD22	Albury - Workshop	Elect\DAMAGE		replace condensor and set up for Auto elec			######## 960638	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER			
LOAD22	Albury - Workshop	Elect\HOUSEKEEP		ordered cooling fan			######## 960638	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER			
LOAD22	Albury - Workshop	Engine\ANGLE[&]LTS/TENS		replaced alternator and belts			######## 960638	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER			
LOAD22	Tumut - Workshop	Air Con\AIR CON		no aircon in truck			######## 667211	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Tumut Workshop	LOADER			
LOAD22	Tumut - Workshop	Elect\HOUSEKEEP		LHS headlight and bliner about to fall out anytime			######## 667211	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Tumut Workshop	LOADER			
						LOADED FOR TRANSPORT TO ROSEWOOD													
						RE-ASSEMBLED DASH ECT													
LOAD22	Albury - Workshop	DrivCabElect\DOOR LOCK		REMOVED DOOR INLUDING ELECTRICS & PHONE ARIEL & GSAD FROM L24		FITTED TEMPORARY COVER FOR DOOR MISSING ON L24	########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER			
LOAD22	Rosewood - Workshop	Hydraulics\OIL LEAK		hydric leaks under motor hydric hoses			########	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	DrivCabRep\RADIO		needs new aerial for radio			########	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	DrivCabRep\DAMAGE		arm rest			######## 960638	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	Engine\AXLE BRAKE		air brake engine			########	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	Hydraulics\OIL LEAK		main lifting ram leak seal			######## 960638	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	Hydraulics\OIL LEAK		main lifting ram O-ring leaking			########	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	Hydraulics\RAM		pins in grab need redoing			######## 960638	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	DrivCabRep\WINDOW REG		need new window handles			########	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	Body\TRL FLOOR		cracks on deck			########	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	Hydraulics\OIL LEAK		hydraulic leak on motor			########	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	Engine\OIL LEAK		hydraulic in grab manor leak			########	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	Engine\OIL LEAK		leak in main boom			########	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
				air leak brakes															
LOAD22	Rosewood - Workshop	Brakes\AIR LEAK		Brakes value not order!			########	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	DrivCabRep\WINDSCREEN		Loader needs new front windows			########	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	Hydraulics\OIL/FILTER		Check hydraulics oil when opp a chater throw the hyd			########	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	DrivCabRep\SEAT		Seating still not right			########	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	Hydraulics\HYD LEAKS		Right lift RAM leaking hyd oil			########	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	Elect\ELECT P&W		light off, boom all loose			########	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	Body\AIR LEAK		air leak in truck			########	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	DrivCabRep\DOOR LOCK		R/H door hard to open			########	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	Brakes\BOOSTER		R/H back brake boost leaking			########	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	DrivCabElect\ELECT P&W		no cab light			########	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	DrivCabElect\DOOR LOCK		REMOVE DRIVERS DOOR		REPLACED WITH DOOR FROM LOADER 24	########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
						call out damaged door will not stay closed													
LOAD22	Tumut - Workshop	DrivCabRep\DOOR LOCK		call out door will not stay close on truck		adjust striker and latch to set door to close	######## 964666	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Tumut Workshop	LOADER			
LOAD22	Rosewood - Workshop	Air Con\AIR CON		no aircon very hot			######## 964350	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	DrivCabRep\DOOR LOCK		door don't close RHS			######## 964350	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	Body\MIRRORS		RHS mirror broken			######## 964350	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	Engine\FAULT CODE		motor fally week			######## 964350	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	Elect\WORK LIGHT		need light behind cab so can see where walking			######## 964350	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Tumut - Workshop	DrivCabElect\HOUSEKEEP		check engine oil			######## 962088	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Tumut Workshop	LOADER			
LOAD22	Rosewood - Workshop	Elect\BATTERY		replace broken negative battery terminal			########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	DrivCabRep\DAMAGE		dash at key and starter switch needs fixing maybe move key and switch to right hand side of dash			######## 962585	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	Elect\DRV LIGHT		right hand driving light need tightening			######## 962585	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	DrivCabRep\DOOR LOCK		right door trim needs to be screwed down			######## 962585	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	DrivCabElect\HEATER REP		fan and heater switches needs knobs			######## 962585	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	Engine\FAULT CODE		motor not pulling well very dead on hills			######## 962585	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	Engine\AXLE BRAKE		jake brake not holding well down hill			######## 962585	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	Body\RWC COMP		regs label out of date			######## 962585	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	Body\FUEL TANK		hose on top of fuel tank loose			######## 962585	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	Body\TOOLBOX		door on toolbox r hand side comes open			######## 962585	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	Body\RWC COMP		needs walkway to loader over battery box before someone gets injuries			######## 962161	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
				no low beam headlights only high beam with driving lights truck uncroadworthy															
LOAD22	Rosewood - Workshop	Elect\HEAD LIGHT		refer to request no.117601			######## 962361	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	DrivCabElect\ELECT P&W		no interior light			######## 962261	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	Elect\BATTERY		replaced battery		called into TAE and got new batteries installed	######## 961465	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	Elect\BATTERY		call out to Bordo		called out to Bordo, batteries dead, not having charge	######## 961465	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Rosewood - Workshop	Elect\ALT		tested alternator output was 14.0 volt, perfect			######## 961465	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER			
LOAD22	Tumut - Workshop	Air Con\HEATER		fix heater			######## 960320	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Tumut Workshop	LOADER			
LOAD22	Tumut - Workshop	Elect\TAIL LIGHT		fix reverse lights			######## 960320	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Tumut Workshop	LOADER			
LOAD22	Tumut - Workshop	Elect\ELECT P&W		high beam dimmer switch is faulty			######## 960320	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Tumut Workshop	LOADER			
				jump start															
LOAD22	Albury - Workshop	Elect\BATTERY		out on charee			########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER			
						Filled up fuel pod & travelled to scene													
LOAD22	Wodonga - Workshop	Workshop\MOVE ASSIST		Called out to breakdown at Thurgoona on ramp - possible fuel problem		Assisted with traffic control	########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR

LOAD22	Albury - Workshop	Engine|JAKE BRAKE	NO ENGINE BRAKE		REPAIRED WIRING BY TCTC	######## 854815	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
LOAD22	Tumut - Workshop	Engine|JAKE BRAKE	no engine brake			######## 952815	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Tumut Workshop	LOADER
LOAD22	Tumut - Workshop	Engine|FAULT CODE	check engine light staying on			######## 952815	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Tumut Workshop	LOADER
LOAD22	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job			######## 949390	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U EXPRESS TRUCK SERVICE - 4	LOADER
LOAD22	Tumut - Workshop	VehService|AS	Service As Per Attached Checklist	VehService|AS		######## 949390	Service	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U EXPRESS TRUCK SERVICE - 4	LOADER
LOAD22	Albury - Workshop	Air Con|AIR CON	aircon stop working			########	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
LOAD22	Albury - Workshop	Air Con|AIR CON	a/c			########	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
LOAD22	Albury - Workshop	Air Con|AIR CON	a/c needs fixing before summer			########	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
LOAD22	Albury - Workshop	Air Con|AIR CON	a/c not working - blowing warm air			########	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
LOAD22	Albury - Workshop	Air Con|AIR CON	ac not working			########	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
			move loader leg pin back grind off											
			old broken retaining bolt pregare bolt and reweld a new one on refit pin											
			tighten retainer bolt											
LOAD22	Rosewood - Workshop	Body|DAMAGE	check hydraulic tank make plan to fix problems			########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Rosewood Workshop	LOADER
LOAD22	Tumut - Workshop	VehService|AS	A SERVICE	VehService|AS		########	Service	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Tumut Workshop	LOADER
LOAD22	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job			########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Tumut Workshop	LOADER
LOAD22	Rosewood - Workshop	Engine|BATTERY	flat battery		jump started truck started loader	######## 948308	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Rosewood Workshop	LOADER
LOAD22	Rosewood - Workshop	Air Con|AIR CON	ac not working			######## 948308	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Rosewood Workshop	LOADER
LOAD22	Albury - Workshop	Air Con|AIR CON	REPAIR AC			######## 347036	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
			remove track rod from rear suspension											
			push on new bushes at sixt's yard											
			refit track rod											
LOAD22	Rosewood - Workshop	Susp|Torque Rod	travel to and from Tumut			########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Rosewood Workshop	LOADER
LOAD22	Albury - Workshop	DrtCabRep|WIPERS	new windscreen wipers		replaced wiper blades, repaired washers	######## 945875	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
LOAD22	Albury - Workshop	DrtCabElect|RADIO	new UHF handpiece		replaced UHF handpiece	######## 945875	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
LOAD22	Albury - Workshop	Body|MIRRORS	tightened loose mirrors			######## 945875	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
			no AC											
			clean out a/c evaporator											
			secure fan											
			repair holes in ducting											
			secure direction actuator											
LOAD22	Albury - Workshop	Air Con|AIR CON	test ok			########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
LOAD22	Albury - Workshop	Air Con|AIR CON	a/c not working			######## 945428	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
LOAD22	Albury - Workshop	Body|DAMAGE	tank step LHS is broken			######## 945428	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
LOAD22	Albury - Workshop	Body|TOOLBOX	toolbox door needs new latch, comes open traveling			######## 945428	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
LOAD22	Albury - Workshop	VehService|AS	B SERVICE	VehService|AS		######## 945230	Service	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Tumut Workshop	LOADER
LOAD22	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			######## 945230	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Tumut Workshop	LOADER
			top step R/H side bent											
			remove step. Straighten step mount											
LOAD22	Tumut - Workshop	Body|DAMAGE	refit step			########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Tumut Workshop	LOADER
LOAD22	Albury - Workshop	Body|DAMAGE	RHS step bent			######## 941120	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
LOAD22	Albury - Workshop	Elect|HEAD LIGHT	hi beam comes on by itself			######## 941120	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
			diagnose hydraulic oil leak											
			replace blown o-ring in main boom lift hose											
			test unit											
LOAD22	Rosewood - Workshop	Hydraulics|HYD LEAKS	clean up oil mess			######## 23407	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Rosewood Workshop	LOADER
LOAD22	Albury - Workshop	Body|DAMAGE	Damaged Equipment		other job caried out also	######## 939283	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
LOAD22	Albury - Workshop	VehService|AS	VehService|AS	VehService|AS	A service completed	######## 939283	Service	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
					power steering spraying fluid out of reservoir									
LOAD22	Rosewood - Workshop	Steering|PWR STEER	power steering blowing oil out cap		diagnosed and repaired loose/fallen off filter	######## 940644	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Rosewood Workshop	LOADER
LOAD22	Rosewood - Workshop	Steering|PWR STEER	power steering making winding noise. Filled up reservoir 3 times		cleaned up area and tested. All good	########	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Rosewood Workshop	LOADER
LOAD22	Albury - Workshop	Hydraulics|BREAKDOWN	LOAD 22 breakdown tumba		check power steering fluid tested ok	########	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
LOAD22	Rosewood - Workshop	Steering|PWR STEER	power steering noise		engineer	########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
LOAD22	Albury - Workshop	Body|MUDGUARDS	fitted LH guard		noisy power steering pump check power steering oil a bit low refilled noisy still after refilling it. Drive to 2 mile creek RD and return to Rosewood	######## 439703	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Rosewood Workshop	LOADER
LOAD22	Albury - Workshop	Elect|LEC T B/W	replaced wiring to LH guard			######## 939583	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
LOAD22	Albury - Workshop	Body|MUDGUARDS	repaired RH guard			######## 939583	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
LOAD22	Albury - Workshop	Elect|LEC T B/W	replaced RHR side marker light			######## 939583	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
LOAD22	Albury - Workshop	Workshop|CLEAN	washed and cleaned workshop after job completion			######## 939583	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
			check over											
			replaced missing bolt on LH hanger											
LOAD22	Albury - Workshop	Susp|SUSPENSION	fit chains to suspension			########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
LOAD22	Albury - Workshop	DrtLine|WHL HUB	finished LHR wheel assembly			########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
LOAD22	Albury - Workshop	Elect|LEC T B/W	fit lights to LH wheel guard			########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
LOAD22	Albury - Workshop	DrtLine|WHL HUB	relined LHR axle (hub seal)			########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
LOAD22	Albury - Workshop	Body|DAMAGE	replaced damaged spider			########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
LOAD22	Albury - Workshop	Susp|SUSPENSION	replaced rear axle slack adjusters			########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
					replaced 2 universal joints - rear tail front jack									
LOAD22	Albury - Workshop	DrtLine|AXLE REPLC	CRACKED AXLE HOUSING		replaced shacks	######## 939582	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
LOAD22	Albury - Workshop	Susp|SUSPENSION	REPLACED WORN COMPONENTS ON FRONT AXLE.		made new axle hold-us chains and fitted	######## 939582	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
LOAD22	Albury - Workshop	Tyres|FITMENT	Job Added From Invoice			######## 941280	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
LOAD22	Albury - Workshop	Tyres|BETREAD	Job Added From Invoice			######## 941280	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
LOAD22	Tumut - Workshop	Body|DAMAGE	broken studs in L/F track rod cuddle			######## 939396	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Tumut Workshop	LOADER
			BLOWN FRONT DIFF fit new f/diffsm											
LOAD22	Albury - Workshop	DrtLine|DIFF REPAIN	fit second hand front diff housing (badly cracked)		TOWED FROM BONDO TO TUMUT WORKSHOP	########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
LOAD22	Albury - Workshop	Workshop|CLEAN	pack and travel Rosewood			######## 939396	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
LOAD22	Albury - Workshop	Workshop|CLEAN	load diff and parts			######## 939396	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
LOAD22	Albury - Workshop	Workshop|MOVE ASSET	travel to Tumut			######## 939396	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
LOAD22	Rosewood - Workshop	Workshop|MOVE ASSET	back ute and travel to Tumut			######## 939396	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Rosewood Workshop	LOADER
LOAD22	Rosewood - Workshop	Workshop|CLEAN	clean workshop			######## 939396	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Rosewood Workshop	LOADER
			blown off at Dosettes (Bondo)											
LOAD22	Rosewood - Workshop	Hydraulics|DAMAGE	oravisw WTT to recover			######## 939396	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Rosewood Workshop	LOADER
LOAD22	Rosewood - Workshop	Workshop|MOVE ASSET	drop off at Tumut yard			######## 939396	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Rosewood Workshop	LOADER
					replace broken door handle out									
					remove inner door cover to acess handle									
					replace handle and resecure									
LOAD22	Rosewood - Workshop	DrtCabRep|DOOR LOCK	DRIVERS DOOR HARD TO OPEN		test ok	######## 938900	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Rosewood Workshop	LOADER
LOAD22	Albury - Workshop	Chassis	Job Added From Invoice			######## 0	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
LOAD22	Albury - Workshop	Cooling|ENG FAN	engine fan not turning off or on with switch / engine not heading up as normal			######## 938301	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
LOAD22	Albury - Workshop	Body|TRL DOORS	right hand door not opening normally			######## 938301	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
LOAD22	Wodonga - Workshop	Body|TRL REPS	refit LH curtain ratchet and pole, closed curtains, move trailer to truck shed			######## 187517	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Wodonga Workshop	LOADER
LOAD22	Rosewood - Workshop	Workshop|CLEAN	pack and lock up shed			######## 937850	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Rosewood Workshop	LOADER
LOAD22	Rosewood - Workshop	Workshop|MOVE ASSET	travel to Tumut			######## 937850	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Rosewood Workshop	LOADER
			tight cam support truck on legs											
			remove tyres, drum. Found hub seal leaking											
			remove hub. Clean parts refit hub assy											
			remove lining, cam etc. replace bushes, seals											
			reassemble brake assy. Refit hub assy wheel etc											
LOAD22	Rosewood - Workshop	DrtLine|DRV LN SSR	adjust all brakes and areaa			######## 937850	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Rosewood Workshop	LOADER
LOAD22	Rosewood - Workshop	Engine|BREAKDOWN	call out to germans, greenhills			######## 937396	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Rosewood Workshop	LOADER
					LHR brake dragging									
					Travel to site. Back brake off. Tight cam. Lube cam									
					tet. Still tight. Requires hub stripping down and cleaning									
LOAD22	Rosewood - Workshop	Brakes|BRAKE ADJ	LHR brake dragging		booked in 12/09 at Tumut w/shop	######## 937396	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Rosewood Workshop	LOADER
LOAD22	Albury - Workshop	DrtCabRep|DOOR LOCK	DRIVERS DOOR HARD TO OPEN			########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
LOAD22	Albury - Workshop	DrtCabRep|WIPERS	needs new wiper blades			######## 937018	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
LOAD22	Albury - Workshop	Cooling|ENG FAN	engine fan wont turn off			######## 937018	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
LOAD22	Albury - Workshop	Tyres	Job Added From Invoice			######## 0	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
LOAD22	Albury - Workshop	Tyres|FITMENT	Job Added From Invoice			######## 0	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
LOAD22	Albury - Workshop	DrtCabRep|AIR BAG	replace cab air bags			########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
			BRAKE ADJ.											
LOAD22	Tumut - Workshop	Brakes|BRAKE ADJ	[illegible]			######## 936151	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Tumut Workshop	LOADER
			travel Tumut											
LOAD22	Rosewood - Workshop	Workshop|MOVE ASSET	remove universal key. Plue wiine back into oriainal ianition switch. Twt ok			########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Rosewood Workshop	LOADER
LOAD22	Rosewood - Workshop	Workshop|MOVE ASSET	TCTC - took keys back to Wodonga leaving loader inoperable			########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Rosewood Workshop	LOADER
LOAD22	Rosewood - Workshop	Workshop|MOVE ASSET	Tumut Auto fitted universal key to enable truck to be moved. TCTC returned keys to Tumut yard			########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Rosewood Workshop	LOADER
LOAD22	Albury - Workshop	Engine|FAULT CODE	Check engine lights on all the time			######## 936040	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
LOAD22	Albury - Workshop	Engine|JAKE BRAKE	jake brake not working			######## 936040	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
LOAD22	Albury - Workshop	Engine|FUEL TANK	REPLACE FUEL UNCK-UP			########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
LOAD22	Tumut - Workshop	DrtCabRep|ENG COVER	tighten loose bonnet hinges			######## 935101	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Tumut Workshop	LOADER
LOAD22	Tumut - Workshop	Engine|FUEL TANK	fuel pick up loose			######## 935101	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Tumut Workshop	LOADER
LOAD22	Tumut - Workshop	Body|DAMAGE	pull off guard off charge air cooler			######## 935101	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Tumut Workshop	LOADER
LOAD22	Tumut - Workshop	Engine|FAULT CODE	check eng codes. Locate rubbed wiring			######## 935101	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Tumut Workshop	LOADER
LOAD22	Albury - Workshop	DrtCabRep|ENG COVER	Bolts to ring to bonnet need fixing left hand side			######## 935101	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
LOAD22	Albury - Workshop	Air Con|AIR CON	Fan control for heater is broken			######## 935101	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
LOAD22	Albury - Workshop	DrtCabRep|AIR LEAK	Bad leak- air bag under cab			######## 935400	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
LOAD22	Albury - Workshop	Engine|FAULT CODE	check engine light still comes on			######## 935400	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
LOAD22	Albury - Workshop	Body|DAMAGE	Needs non slip tape on walk way & tanks			######## 935400	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
LOAD22	Albury - Workshop	VehService|AS	Service due	VehService|AS		######## 935400	Service	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
LOAD22	Albury - Workshop	DrtCabRep|AIR LEAK	Air leek under cab bad			######## 934888	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
			eng miss and derating											
			wiring harness at TCTC required fitting											
			truck did not arrive. Left in bush											
			I was not to know											
			To and from Rosewood Tumut											
			check cables #6 injector and viss											
LOAD22	Rosewood - Workshop	Engine|FAULT CODE	clear codes will check new time in Tumut			########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Rosewood Workshop	LOADER
LOAD22	Rosewood - Workshop	Engine|FAULT CODE	engine light coming on			######## 934400	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Rosewood Workshop	LOADER
LOAD22	Rosewood - Workshop	Body|AIR LEAK	air leak			######## 934400	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Rosewood Workshop	LOADER
LOAD22	Rosewood - Workshop	Brakes|BOOSTER	found that R/H/F steer booster hose was leaking replace with new hose fitted up tested ok			######## 934400	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Rosewood Workshop	LOADER
LOAD22	Rosewood - Workshop	Cooling|RADIATOR	check coolant. Coolant was down put 8 liters in			######## 934400	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Rosewood Workshop	LOADER
LOAD22	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			######## 934400	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Rosewood Workshop	LOADER
LOAD22	Rosewood - Workshop	VehService|AS	Service	VehService|AS		######## 934400	Service	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Rosewood Workshop	LOADER
LOAD22	Albury - Workshop	Engine|FAULT CODE	check engine light still on			######## 934494	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
LOAD22	Albury - Workshop	Brakes|AIR LEAK	REPLACE RH STEER BRAKE HOSE			########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
LOAD22	Albury - Workshop	Engine|FAULT CODE	Check engine light still on			######## 934494	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
LOAD22	Rosewood - Workshop	Brakes|AIR LEAK	right hand front brake leaking			######## 934400	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Rosewood Workshop	LOADER
LOAD22	Rosewood - Workshop	Engine|FAULT CODE	check engine light comes on			######## 934400	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Rosewood Workshop	LOADER
LOAD22	Rosewood - Workshop	DrtCabRep|DOOR LOCK	RHS door hard to open handle fault			######## 934400	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Rosewood Workshop	LOADER
LOAD22	Rosewood - Workshop	VehService|AS	due for Service in 800km	VehService|AS		######## 934400	Service	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Rosewood Workshop	LOADER
LOAD22	Tumut - Workshop	Elect|LEC T B/W	AUXILIARY FUEL PUMP NOT WORKING. REQUIRE NEW SWITCHING WIRE RAN		replaced wiring - relay	########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Tumut Workshop	LOADER
LOAD22	Tumut - Workshop	Hydraulics|PUMP	transfer pump not working			######## 931600	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Tumut Workshop	LOADER
LOAD22	Albury - Workshop	DrtCabRep|MOUNTS	CAB HCV LEAKING			########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
LOAD22	Albury - Workshop	Elect|HEAD LIGHT	headlights on off same times when going on to high beam			########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
					REPAIRED BY TAC.									
					DIAGNOSED AS FAULTY WIRING TO RELAY									
LOAD22	Albury - Workshop	Elect|LEC T B/W	AUXILIARY FUEL PUMP NOT WORKING		aus aumte fault. Found broken switch needs meairne	########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
LOAD22	Tumut - Workshop	Workshop|MOVE ASSET	travel to Tumut. Take Rodeo back from Rosewood			######## 931889	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Tumut Workshop	LOADER
					STEERING BOX FAILED.									
LOAD22	Tumut - Workshop	Steering|PWR STEER	EMERGENCY TWO DRIVE UTT - CHECKED WHOLE TRUCK 3 DIFF DRIVERS NOT A SOLID BACK TO UTT - BOOKED ORIGINAL D/W WITH BOOT DRIVE UTT BOOKED D/W - BOOT - BOOKED D/W WAS INCORRECT WORKS EITHER SIDE/NOT D/W AND BOTH BACK TO UTT - TWO CHECKED ANOTHER BOOKED D/W - EITHER TEST FW			######## 931889	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Tumut Workshop	LOADER
LOAD22	Tumut - Workshop	Workshop|CLEAN	return to Rosewood. Paperwork			######## 931889	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Tumut Workshop	LOADER
			STEERING VERY HEAVY ONE WAY.											
LOAD22	Albury - Workshop	Steering|PWR STEER	REPLACE STEERING BOX		fit reco steering box for 3rd time	######## 931889	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
LOAD22	Albury - Workshop	Workshop|CLEAN	travel Tumut		had trouble buildline us	######## 931889	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
LOAD22	Albury - Workshop	Engine|FILTERS	replaced dipstick - filter			######## 931889	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
LOAD22	Albury - Workshop	Workshop|CLEAN	return to Rosewood			######## 931889	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Tumut Workshop	LOADER
			power steering box											
			refit power steering box tested aero box and it was wrong											
LOAD22	Albury - Workshop	Steering|STEER UNI	pull off the power steering box. Workshop no parts		steering box o/h	######## 931889	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Tumut Workshop	LOADER
LOAD22	Albury - Workshop	Workshop|CLEAN	Travel to Tumut and return			######## 931800	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER
LOAD22	Tumut - Workshop	Air Con|AIR CON	heater not working no heat		disconect a/c will fit switch to a/c next service	######## 931800	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Tumut Workshop	LOADER
LOAD22	Tumut - Workshop	Steering|PWR STEER	power steer			######## 931800	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Tumut Workshop	LOADER
			travel Tumut. Replace p/s pump. Replaced suction hose											
LOAD22	Tumut - Workshop	Hydraulics|PUMP	bleed system test ok			######## 931800	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Tumut Workshop	LOADER
LOAD22	Tumut - Workshop	Hydraulics|OIL/FILTER	check oil and coolant			######## 931800	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Tumut Workshop	LOADER
LOAD22	Rosewood - Workshop	Hydraulics|PUMP	organise p/s pump			######## 931800	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Rosewood Workshop	LOADER
LOAD22	Rosewood - Workshop	Workshop|MOVE ASSET	travel to Holbrook pick up pump - return to Tumba			######## 931800	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Rosewood Workshop	LOADER
			called at 11:00pm no p/s washed to 12.30am. Driver was going to return call to tell me if fluid level was ok											
			got # off pump on 24 to try and find a pump											
LOAD22	Tumut - Workshop	Hydraulics|OIL/FILTER	could not source one in Albury/Wodonga only could get one from Hydro steer Melb. Will arrive 28/6 calls at 11.00 am 26/06 12:30am 27/06			######## 931747	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Tumut Workshop	LOADER
LOAD22	Albury - Workshop	Steering|PWR STEER	NO POWER STEERING			######## 931747	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U Albury Workshop	LOADER

LOAD22	Albury - Workshop	Workshop\MOVE ASSET	Drop off to TCTC			########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	DrivLine\AXLE REPLC	Removed and replaced drive axles			########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Body\MOUNTS	repaired broken grab holder mounts replaced LH headligh assembly ordered parts			########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Elect\HEAD LIGHT	operated engine repairs Replaced fan speed switch Replaced fan speed switch wiring Replaced fan speed switch control knob Repaired dash			########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Elect\ELECT P&W	Reapired air leaks in dask - trans shifter			########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Workshop	Job Added From Invoice			######## 0	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Contract	Job Added From Invoice			######## 0	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Elect\BATTERY	Replaced batteries			########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Dri\Cabdrag\SEAT	Fitted seat			########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Drivline\WHL HUB	Repaired leaking LHR. Leaking hub seal including brakes Reapired air leak RHS air lines			########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Body\DAMAGE	HIT KANGAROO. BROKE HEAD LIGHT ASSY,		FIBRE GLASS BONNET AND HEAD LIGHT ASSY.	########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Body\PANELS	repaired door and cabin trims on RHS			######## 925830	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Dri\Cabdrag\SEAT	removed seat for reupholstering			######## 925830	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Insp\WHC COMP	roadworthy inspection			######## 925830	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Body\PANELS	refit grille to bonnet			######## 925830	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Engine\FILTERS	replaced out dated air filters			######## 925830	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Body\HOUSEKEEP	washed and cleaned out cab			######## 925830	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Engine\FAULT CODE	checked and identified codes - no. 6 injector			######## 925830	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Elect\BATTERY	charged, load tested and replaced batteries			######## 925830	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Elect\BATTERY	jump start check over		REPLACE BATTERIES	######## 925729	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Engine\FAULT CODE	check engine light on. Checked codes			######## 925643	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Drivline\OIL LEAK	filled with coolant codes also for 6th injector			######## 925643	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Engine\FAULT CODE	cleared and tested			######## 925643	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Elect\ELECT P&W	replaced wiring to RHS side marker lights			######## 925643	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Dri\Cabdrag\WINDSCREEN	Loader needs new front windows			########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Hydraulics\OIL/FILTER	Check hydraulics oil when opp a chater throw the hyd			########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Dri\Cabdrag\SEAT	Seating still not right			########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Hydraulics\HYD LEAKS	Right lift RAM leaking hyd oil			########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Elect\ELECT P&W	switch to change legs back on forward playing up			########	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Elect\ELECT P&W	light off, boom all loose			########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	VehService\JBS	Service Due	VehService\JBS		######## 925565	Service	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Brakes	Record Check Results As Attached To This Job tightened drive shaft uni cap bolts unsealed RHR bottom shackle pin replaced s/c bolts tightened rear axle u-bolts replaced boom holder mount bolt tightened loose stays on hood			######## 925565	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Body\MOUNTS	jump start truck wash and check batteries			######## 925565	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Workshop\W/S MAINT	make up 4 new battery hold down rods batteries flat-key left on			######## 725565	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Elect\BATTERY	turns-start			########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Engine\FAULT CODE	engine stop light on engine wont run			########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Engine\COOL LEAKS	re-filled coolant			########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Engine\COOL LEAKS	tightened loose coolant hose clamps			########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Engine\COOL LEAKS	checked leaks while running			########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Susp\SUSPENSION	SUPPLY PARTS TO WODONGA WORKSHOP TO CARRY OUT REPAIRS.			########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Wodonga - Workshop	Insp\DEFECT	Defect clearance			######## 924702	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Wodonga Workshop	LOADER
LOAD22	Albury - Workshop	Tyres\ROTATION	Job Added From Invoice			######## 924702	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Tyres\RUN OUT	Job Added From Invoice Strip down rear axle for welding Reassemble rear axle			######## 924702	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Wodonga - Workshop	Chassis	Wash off and test			######## 924702	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Wodonga Workshop	LOADER
LOAD22	Wodonga - Workshop	Body\CAB/RUB/MN	tortion rod (weld join)			########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Wodonga Workshop	LOADER
LOAD22	Albury - Workshop	Tyres	Job Added From Invoice			######## 924702	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Tyres\STEER TYRE	Job Added From Invoice			######## 924702	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice			######## 924702	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Wodonga - Workshop	Susp\SUSPENSION	replace shock absorbers x 4 ,replace wear pads and rebound rollers, replace stabeliser arm			########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Wodonga Workshop	LOADER
LOAD22	Wodonga - Workshop	Body\FUEL TANK	replace fuel tank steps x3 and spot mirrors x2		steps - ok spot mirrors replaced	########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Wodonga Workshop	LOADER
LOAD22	Wodonga - Workshop	Air Con\AIR CON	replace A/C condenser		n/c	########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Wodonga Workshop	LOADER
LOAD22	Wodonga - Workshop	Air Con\AIR CON	replace fan thermister speed switch			########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Wodonga Workshop	LOADER
LOAD22	Wodonga - Workshop	Brakes\BRK RELINE	reline rear drive brakes replace drums		previously completed	########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Wodonga Workshop	LOADER
LOAD22	Wodonga - Workshop	Dri\Cabdrag\AIR CON	replace a/c fan resistor switch		n/c	########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Wodonga Workshop	LOADER
LOAD22	Wodonga - Workshop	Dri\Cabdrag\RADIO	needs new aerial for radio		n/c	########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Wodonga Workshop	LOADER
LOAD22	Wodonga - Workshop	Susp\SHOCK ABS	LH rear shocker needs replacing		tested ok	########	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Wodonga Workshop	LOADER
LOAD22	Wodonga - Workshop	Dri\Cabdrag\DAMAGE	arm rest		n/c	########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Wodonga Workshop	LOADER
LOAD22	Wodonga - Workshop	Air Con\AIR CON	aircon stop working		n/c	########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Wodonga Workshop	LOADER
LOAD22	Wodonga - Workshop	Engine\AXLE BRAKE	air brake engine			########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Wodonga Workshop	LOADER
LOAD22	Wodonga - Workshop	Hydraulics\OIL LEAK	main lifting ram leak seal		n/c	########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Wodonga Workshop	LOADER
LOAD22	Wodonga - Workshop	Hydraulics\OIL LEAK	main lifting ram Oring leaking		n/c	########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Wodonga Workshop	LOADER
LOAD22	Wodonga - Workshop	Hydraulics\OIL LEAK	hydric leaks under motor hydric hoses		completed previously	########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Wodonga Workshop	LOADER
LOAD22	Wodonga - Workshop	Chassis\CHAS CRACK	cracks on deck		completed previously	########	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Wodonga Workshop	LOADER
LOAD22	Wodonga - Workshop	Engine\BATTERY	hard to start sometimes		completed previously	########	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Wodonga Workshop	LOADER
LOAD22	Wodonga - Workshop	Hydraulics\ARM	pins in grab need redoing		n/c	########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Wodonga Workshop	LOADER
LOAD22	Wodonga - Workshop	VehService\DS	Service Due	VehService\DS	Service	########	Service	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Wodonga Workshop	LOADER
LOAD22	Wodonga - Workshop	VehService\AS	A Service Due 600km	VehService\AS		########	Service	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Wodonga Workshop	LOADER
					Please see attached Defect notice with faults realigned steer spring packs diagnosed horn issue - needs new relay - fix washes and replaced and repair wipers replace parker globe, wash truck, straighten step and tighten, replace pinion seal, pick up truck from Albury check over, help test horn removed axle cables tensioned steer and front drive Ubolts replaced sub frame bolt and tightened bolts reslaned bent steer stopper L side Tightened and Straightened the Step. Replaced Parker Globe Diagnose horn issue - needs new relay fix washes and replaced and repair wipers fix washes and replaced and repair wipers					
LOAD22	Albury - Workshop	Insp\DEFECT	Defect on Load22 on 14/9/17			######## 924500	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Body\MOUNTS	On right - fuel tank upper step insecure			######## 924600	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Elect\ELECT P&W	On left front - park light inoperative			######## 924600	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Elect\DRV LIGHT	On left front - Alternate or driving light not fitted			######## 924600	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Elect\ELECT P&W	Horn inoperative			######## 924600	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Dri\Cabdrag\WIPERS	Windscreen washers are inoperative/incorrectly aimed			######## 924600	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Dri\Cabdrag\WIPERS	Wiper blades are insecure/missing/not clearing screen			######## 924600	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Susp\SHOCK ABS	On axle 3 - shock absorber insecure/loose			######## 924500	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Susp\AIR LEAK	On axle 3 left side - shock absorber leaking			######## 924500	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Brakes\DAMAGE	ABK 2/1 system fault, with one tank drained and when service brake is applied, maxi brake automatically applies			######## 924500	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Brakes\AIR LEAK	Between axle 2 and 3 - audible air leaks			######## 924500	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Steering\SUSPENSION	On axle 1 right side - tyre rubbing on steering box pitman arm			######## 924500	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Susp\SUSPENSION	On axle 1, both sides - spring pack misaligned			######## 924500	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Engine\FUEL TANK	Fuel system leaks on left rear of engine			######## 924500	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Susp\SUSPENSION	On axle 1 - U bolt/s insecure			######## 924500	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Susp\SUSPENSION	On axle 2 and 3 both sides - U bolts insecure			######## 924500	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Steering\TIE ROD	On axle 1 left side - tie rod end excessive play / movement			######## 924500	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Brakes\SLACK ADJ	On axle 3 left side - excessive movement between S cam shaft and slack adjuster			######## 924500	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Drivline\OIL LEAK	On axle 2 - differential oil leaks			######## 924500	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Tyres\STEER TYRE	On axle 3 left side inner - tyre is insufficient tread			######## 924500	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Susp\AIR BAG	On axle 2 and 3 both sides - airbag suspension component mounting bolts loose(at base of air bag)			######## 924500	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Chassis\WINCH/STRP	On axle 2 right side - control arm safety strap frayed - check all			######## 924500	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Brakes\BRAKE ADJ	On axle 2 service brake/s uneven efficiency(right side low)			######## 924500	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Brakes\BRAKE ADJ	On axle 3 left side - service brake indicator indicates adjustment required			######## 924500	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Susp\SUSPENSION	On axle 1 left side - radius rod excessive movement at rear end check all			######## 924500	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Insp\DEFECT	wash off and inspect defects for parts			######## 924500	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Chassis\DRV LN SER	realigned front drive c springs			######## 924500	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Susp\SHOCK ABS	repaired drive shocker dust shield			######## 924500	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Drivline\DRV LN SER	tightened "z" spring rear bolts front drive			######## 924500	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Dri\Cabdrag\AIR BAG	replaced 1x airbag			######## 924500	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Elect\ELECT P&W	replaced 2x side marker and electrical repairs			######## 924500	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Drivline\SPRING HANG	replaced worn wear pads in hangers			######## 924500	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Drivline\AXLE REPLC	weld cracks at boom cradle base and boom pivot point and rear axle O ring Bearing cup Bearing seal - pinion kit pinion nut			######## 924600	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Drivline\GEARBOX	oil sump assembly		Twin city - 486644	########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Drivline\DRIVES	REBUILD POWER DIVIDER			########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Brakes\BRK RELINE	adjust brakes			######## 923875	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
					Work performed on 7/9/17 Check brakes and loose pinion, park truck										
LOAD22	Albury - Workshop	Brakes\BRAKE ADJ	Adjust brakes		snow trucks - 00038376	########	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Elect\ELECT P&W	checked over lights, checked power to cab work light, remove and replace faulty connector, tested, secured looms air leak brakes		Tumut electric - 00173210	########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Brakes\AIR LEAK	(dumo valve on order)			########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
					Work performed on 24/8/17 Inspect air leak - replaced fittings, still leaking out of dump valve as well. NEED TO ORDER NEW DUMP VALVE										
			Air leak brake front												
LOAD22	Albury - Workshop	Brakes\AIR LEAK	need new dumo valve		Snowy trucks - 38208	######## 921705	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Drivline\OIL LEAK	leak in grab ram seal			########	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Hydraulics\OIL LEAK	main lifting ram leak seal			########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Hydraulics\OIL LEAK	main lifting ram Oring leaking			########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Body\CTRL RODS	left hand back leg pin broken			########	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Hydraulics\OIL LEAK	hydric leaks under motor hydric hoses		secure m.C.U	########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Chassis\CHAS CRACK	cracks on deck			########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Engine\BATTERY	motor will not turn off sometimes			########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Engine\BATTERY	hard to start sometimes			########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Body\CTRL LEGS	Work performed on 4/7/17		Replace pin in rear leg RH side	########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Tyres\STEER TYRE	Job Added From Invoice			######## 917396	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Tyres\ALIGNMENT	Job Added From Invoice			######## 917396	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Body\CTRL LEGS	left hand rear leg pin broken			########	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Brakes\BOOSTER	work performed on booster		snowy trucks - 00037794	########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	VehService\JBS	B SERVICE	VehService\JBS	PAPERWORK ASKED FOR B SERVICE, WAS SUPPOSE TO BE AN A SERVICE BUT HAD ALREADY STARTED TO CARRY OUT B SERVICE WHEN ROSEWOOD MECHANIC RANG	######## 915205	Service	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
					travel to 6G feeder adjust brakes secure m.C.U										
LOAD22	Rosewood - Workshop	Brakes\AIR BAG	brake need fixing		travel to Rosewood	######## 915010	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Rosewood Workshop	LOADER
LOAD22	Rosewood - Workshop	Engine\AXLE BRAKE	air brake engine			######## 915010	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Rosewood Workshop	LOADER
			Fit pivot pin back in stabiliser leg and tack weld												
LOAD22	Tumut - Workshop	Body\MOUNTS	rmv stove			######## 912271	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Tumut Workshop	LOADER
LOAD22	Albury - Workshop	Dri\Cabtest\HEATER REP	CHECK OVER VENDER MOTOR NOT WORKING, HAD JAMMED, SECURED ROD UP TO ALLOW HEATER FUNCTION TO WORK, 22 AT DEMIST/FRONT PANEL AROUND 30 AT IDLE, INFORMED PHIL		AS PER INVOICE - 00172079	########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Tumut - Workshop	VehService\JBS	Service	VehService\JBS		######## 911112	Service	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Tumut Workshop	LOADER
LOAD22	Rosewood - Workshop	Engine\COOL LEAKS	replace coolant hose			########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Rosewood Workshop	LOADER
LOAD22	Rosewood - Workshop	Elect\ELECT P&W	fix-duct in driving lights			########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Rosewood Workshop	LOADER
LOAD22	Rosewood - Workshop	VehService\DS	Service			########	Service	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Rosewood Workshop	LOADER
LOAD22	Albury - Workshop	Susp\AIR LEAK	keep loosing air pressure			######## 906562	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Tumut - Workshop	Elect\ELECT P&W	L/H boom light			######## 20680	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Tumut Workshop	LOADER
LOAD22	Tumut - Workshop	Steering\OIL LEAK	leak in rotator seal			######## 20680	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Tumut Workshop	LOADER
LOAD22	Tumut - Workshop	Brakes\BRK RELINE	reline rear drive axle			########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Tumut Workshop	LOADER
LOAD22	Albury - Workshop	Drivline\TAIL SHAFT	FAILED UNI.		DROP TAIL SHAFT OFF AT THE HARE TRUCK AND PICK IT UP.	########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Dri\Cabtest\AIR CON	replace a/c fan resistor switch		TAE	########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Elect\DRV LIGHT	replace blown driving lights		Tumut auto electrics 2-3-17	########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	VehService\AS	Ford prime mover A service	VehService\AS	Snowy truck repairs 10-1-17	########	Service	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH308U	Albury Workshop	LOADER
LOAD22	Albury - Workshop	Brakes\BRK RELINE	reline rear drive brakes and replace drums		rosewood

			Defect notice.															
LOAD22	Albury - Workshop	Insp\DEFECT	Suzuki earts for reseirs															
LOAD22	Tumut - Workshop	Elect\ELECT P&W	repair horn cab light and dash lights		Tumut auto electrics 10-11-16		########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER		
LOAD22	Albury - Workshop	Tyres\TP03	Job Added From Invoice				######## 894783	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER		
LOAD22	Tumut - Workshop	Hydraulics\HOSES	replace hydraulic hoses on grab		Tumut hydraulic services 15-11-16		########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Tumut Workshop	LOADER		
LOAD22	Tumut - Workshop	Susp\SHOCK ABS	remove broken shock absorber		Snowy truck repairs 31-10-16		########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Tumut Workshop	LOADER		
LOAD22	Tumut - Workshop	Susp\SHOCK ABS	remove broken swhock absorbers		Snowy truck service 4-11-16		########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Tumut Workshop	LOADER		
LOAD22	Tumut - Workshop	Steering\TIE ROD	Fit new tie rod ends to drag link and adjust and fit new shock absorbers to rear axle		snowy truck repairs 3-11-16		########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Tumut Workshop	LOADER		
LOAD22	Rosewood - Workshop	Steering\WHEEL ALIGN	pull to the right bad				######## 893000	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER		
LOAD22	Rosewood - Workshop	DrivLine\SHOCK ABS	shock left hand side				######## 893000	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER		
LOAD22	Rosewood - Workshop	Body	right and left shocks need replacing				######## 892141	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER		
LOAD22	Tumut - Workshop	Brakes\BRAKE ADJ	adjust brakes ,adjust clutch, and tyighten v Cams		Snowy truck service 21-10-16		########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Tumut Workshop	LOADER		
LOAD22	Rosewood - Workshop	Body\DAMAGE	tips on grab				######## 20200	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER		
LOAD22	Rosewood - Workshop	Engine\COOL LEAKS	coolant leaking				######## 20200	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER		
LOAD22	Rosewood - Workshop	Hydraulics\OIL LEAK	hyd leaks				######## 20200	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER		
LOAD22	Rosewood - Workshop	Engine\START MOTR	starter motor				######## 20200	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER		
LOAD22	Tumut - Workshop	Brakes\BRAKE ADJ	adjust clutch and all brakes		snowy truck service 19-9-16		########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Tumut Workshop	LOADER		
LOAD22	Albury - Workshop	DrivLine	L/H back shock broken				######## 887220	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER		
LOAD22	Rosewood - Workshop	Brakes	engine brake not working				######## 887172	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER		
LOAD22	Tumut - Workshop	Dr\CabReg\DAMAGE	windscreen leaks				######## 19976	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Tumut Workshop	LOADER		
LOAD22	Tumut - Workshop	Dr\CabElect\ELECT P&W	horn not working				######## 19976	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Tumut Workshop	LOADER		
LOAD22	Tumut - Workshop	Engine\FAULT CODE	gauges x 5 lights not working				######## 19976	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Tumut Workshop	LOADER		
LOAD22	Tumut - Workshop	Dr\CabElect\ELECT P&W	throtel too hard to pull				######## 19976	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Tumut Workshop	LOADER		
LOAD22	Tumut - Workshop	Dr\CabReg\DAMAGE	arm rest				######## 19976	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Tumut Workshop	LOADER		
LOAD22	Rosewood - Workshop	Veh\service	B Service				######## 289244	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER		
LOAD22	Rosewood - Workshop	Body	airleak nat sure if in truck or trailer				######## 289244	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER		
LOAD22	Rosewood - Workshop	Engine	radiator support bars need adjusting				######## 289244	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER		
LOAD22	Albury - Workshop	Dr\CabElect\RADIO	Replaced UHF mic		as above		######## 882777	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER		
LOAD22	Albury - Workshop	Steering\STEER LINK	Steering wheel out of alignment. Blocking dash.		removed steering wheel and straighten		######## 881935	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER		
LOAD22	Albury - Workshop	Susp\SHOCK ABS	press in stud in shocker mount		Have stud pressed in to old shocker mount to have as a spare		########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER		
LOAD22	Albury - Workshop	Elect\HEAD LIGHT	No low beam		Repaired wiring. Found blow fuse		######## 880272	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER		
LOAD22	Albury - Workshop	Brakes	check and record brakes				######## 880272	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER		
					as above													
					replaced alt belts													
					R/H airbag													
LOAD22	Albury - Workshop	Veh\service\AS	B serv due @ 880030km	VehServiceJAS	L/F drive shocker		######## 880272	Service	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER		
LOAD22	Albury - Workshop	Dr\CabElect\PHONE	Phone not working in truck				######## 879643	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER		
LOAD22	Albury - Workshop	Body\TOOLBOX	Toolbox full of water.				######## 879643	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER		
					fit new shocker and repaired mount.													
					Subbie:. Aldonga Eng.													
					Fit stud to mount													
LOAD22	Albury - Workshop	Susp\SHOCK ABS	LH steer shocker broken		had shocker mount modified for neoiar. Fitted mount & new steer shocker		########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER		
					Travel to Shelley. Remove shocker which has a broken top mount.													
LOAD22	Albury - Workshop	Susp\SHOCK ABS	LH steer shocker broken		Parts ordered		######## 876652	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER		
					replaced broken fitting													
LOAD22	Albury - Workshop	Brakes\AIR LEAK	air line needs flaing		aoart of #68611		######## 876652	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER		
LOAD22	Albury - Workshop	Brakes\SLACK ADJ	replaced steer slack adjusters and adjust brakes		as above. 1x slack adjuster had broken its auto adjuster.		######## 876652	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER		
					Inspect for rubbed wiring.													
					Wash down batteries and replace 4 terminals.													
LOAD22	Albury - Workshop	Elect\TAIL LIGHT	side markers flashing with indicators		Reolace 2x side markers		######## 876268	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER		
LOAD22	Albury - Workshop	Elect\DRV LIGHT	needs new driving lights		replaced driving lights		######## 876268	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER		
LOAD22	Albury - Workshop	Elect\DRV LIGHT	needs new driving lights		ordered lights		########	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER		
LOAD22	Albury - Workshop	Dr\CabReg\WIPERS	needs new wiper blades		replaced wiper blades		######## 876703	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER		
LOAD22	Albury - Workshop	Elect\HEAD LIGHT	RH parker out.		replaced park light globe		########	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER		
					Replaced inner door handle and door latch.													
LOAD22	Albury - Workshop	Dr\CabReg\DOOR LOCK	LH door won't shut		Reolaced door latch assembly to inside door handle		######## 875704	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER		
					1/07/2016. Replaced LH eng mount. Supplied incorrect mount for RH.													
LOAD22	Albury - Workshop	Engine\MOUNTS	requires rear engine mounts		6/07/2016. Reolaced RH ene mount.		######## 876507	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER		
LOAD22	Albury - Workshop	Engine\FUEL TANK	fuel nozzle broken		repaired fuel nozzel		######## 875376	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER		
LOAD22	Albury - Workshop	Air Con\HEATER	heater not working		manually turned on heater valve		######## 875376	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER		
LOAD22	Albury - Workshop	Dr\CabElect\PHONE	Phone needs looking at. Not ringing thru to numbers		updated software with supplied sim.		######## 875376	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER		
LOAD22	Albury - Workshop	Brakes	check and record brakes				######## 875376	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER		
LOAD22	Albury - Workshop	Veh\service\AS	A service	VehServiceJAS	as above		######## 875376	Service	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER		
LOAD22	Albury - Workshop	Dr\CabReg\DOOR LOCK	LH door won't shut properley		adjusted striker		######## 875703	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER		
					faulty pressure switch. Ordered off Hartwigs.													
LOAD22	Albury - Workshop	Cooling\ENG FAN	horton staying on		Reolaced switch. Test ok.		######## 872791	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER		
LOAD22	Albury - Workshop	Air Con\HEATER	heater taps need turning on.		heater taps are turned on. Disconnected A/C		######## 871874	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER		
LOAD22	Albury - Workshop	Elect\DRV LIGHT	needs new driving light , dont seem to good		driving light x ere ok.		######## 871874	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER		
LOAD22	Albury - Workshop	Susp\SHOCK ABS	LHS rear shocker needs replacing		replaced L and R rear shockers		######## 871691	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER		
LOAD22	Albury - Workshop	Elect\TAIL LIGHT	LHS rear marker not working		replaced side marker		######## 871691	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER		
LOAD22	Albury - Workshop	Susp\SHOCK ABS	LH steer top shocker mount broken		replaced top mount		######## 871691	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER		
					replaced both headlight plugs													
					topped up fluids													
LOAD22	Albury - Workshop	Elect\HEAD LIGHT	RH head light plug needs replacing		removed broken bonnet strao		######## 871591	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER		
LOAD22	Albury - Workshop	Air Con\HEATER	replaced leaking heater tap.		as above		######## 870078	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER		
LOAD22	Albury - Workshop	Tyres\STEER TYRE	Job Added From Invoice				######## 869401	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER		
LOAD22	Albury - Workshop	Tyres\STEER TYRE	Job Added From Invoice				######## 869401	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER		
LOAD22	Albury - Workshop	Tyres\STEER TYRE	Job Added From Invoice				######## 0	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER		
LOAD22	Albury - Workshop	DrivLine\TAIL SHAFT	yokes worn on tailshaft		Tailshaft repaied by The Haire		########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER		
LOAD22	Albury - Workshop	Susp\SHOCK ABS	front steer shockers		as above		######## 869401	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER		
LOAD22	Albury - Workshop	Susp\SUSPENSION	RR "u" bolts loose		tightened u bolts		######## 869401	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER		
LOAD22	Albury - Workshop	Susp\AIR BAG	RF drive air bag		replaced airbag		######## 869401	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER		
					reset steering box poppets													
LOAD22	Albury - Workshop	Steering\TIE ROD	drag link u/s.		fit new adjust steer stopper bolts		######## 869401	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER		
					replaced cam tube													
LOAD22	Albury - Workshop	Brakes\BOOSTER	RF 'c' cam tube/booster mount u/s		replaced booster		######## 869401	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER		
LOAD22	Albury - Workshop	Brakes\AIR LEAK	air leak under cab RH side.				######## 869401	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER		
					sent linkage to Aldonga Eng. for repair													
LOAD22	Albury - Workshop	DrivLine\CLUTCH	clutch lever/bush worn.		adjusted clutch freeplay		######## 869401	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER		
			RF guard loose.															
LOAD22	Albury - Workshop	Body\MUDGUARDS	Fit flares around steer auards.		fit new indicators to 1/4 eaurds		######## 869401	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER		
LOAD22	Albury - Workshop	DrivLine	inspect front end abnormal noise				########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER		
			replaced slew motor															
LOAD22	Albury - Workshop	Hydraulics\MOTOR	replaced slew gear				########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER		
LOAD22	Albury - Workshop	Hydraulics\HOSES	boom hose - no clips				######## 868786	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER		
LOAD22	Rosewood - Workshop	Brakes	check and record brakes				######## 868923	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER		
LOAD22	Rosewood - Workshop	Veh\service\AS	A Service	VehServiceJAS			######## 868923	Service	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER		
LOAD22	Rosewood - Workshop	Dr\CabReg\ENG COVER	Damage to LHS bonnet		replaced bonnet		########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER		
LOAD22	Rosewood - Workshop	Chassis	repair shackel pins and bushes				########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER		
LOAD22	Rosewood - Workshop	Steering\TIE ROD	tie rod ends L/H and R/H				########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER		
LOAD22	Rosewood - Workshop	Engine	engine oil leaks				########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER		
LOAD22	Albury - Workshop	Tyres\TP03	Job Added From Invoice				######## 864796	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER		
LOAD22	Albury - Workshop	Tyres\TP03	Job Added From Invoice				######## 0	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER		
LOAD22	Albury - Workshop	Tyres\TP03	Job Added From Invoice				######## 0	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER		
LOAD22	Albury - Workshop	Comp\ANN INSP	rego check and repairs				########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER		
LOAD22	Albury - Workshop	Susp\SUSPENSION	replace rear shackels and tie rod ends				########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER		
			repairs to damaged bonnet.															
LOAD22	Albury - Workshop	Dr\CabReg\ENG COVER	Purchased Bonnet thru SWP.				########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER		
LOAD22	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job				######## 865457	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER		
LOAD22	Rosewood - Workshop	Dr\CabReg\ENG COVER	Damage to LHS bonnet				######## 865457	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER		
LOAD22	Rosewood - Workshop	Chassis	repair shacket pins and bushes				######## 865457	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER		
LOAD22	Rosewood - Workshop	Steering\TIE ROD	tie rod ends L/H and R/H				######## 865457	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER		
LOAD22	Rosewood - Workshop	Engine	engine oil leaks				######## 865457	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER		
LOAD22	Rosewood - Workshop	Veh\service\AS	Service As Per Attached Checklist	VehServiceJAS			######## 865457	Service	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER		
LOAD22	Rosewood - Workshop	Brakes\AIR LEAK	air leak brakes				######## 865264	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER		
LOAD22	Rosewood - Workshop	Elect\ELECT P&W	R/H side light				######## 865264	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER		
LOAD22	Rosewood - Workshop	Engine\FUEL TANK	fuel nozzle broken				######## 865264	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER		
LOAD22	Albury - Workshop	Tyres\TP04	Job Added From Invoice				######## 862168	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER		
LOAD22	Albury - Workshop	Tyres\STEER TYRE	Job Added From Invoice				######## 862256	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER		
LOAD22	Albury - Workshop	Tyres\STEER TYRE	Job Added From Invoice				######## 862256	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER		
LOAD22	Rosewood - Workshop	Elect\HEAD LIGHT	no low beam		replace blown fuse		######## 862904	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER		
LOAD22	Rosewood - Workshop	Elect\ELECT P&W	relays				########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER		
LOAD22	Rosewood - Workshop	Engine	fire pump intake house				######## 861970	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER		
LOAD22	Rosewood - Workshop	Dr\CabReg\DOOR LOCK	r/h door trim				######## 861970	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER		
LOAD22	Rosewood - Workshop	Susp\SHOCK ABS	r/h back shock				######## 861970	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER		
LOAD22	Rosewood - Workshop	Elect\HEAD LIGHT	no low beam				######## 861970	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER		
LOAD22	Rosewood - Workshop	Elect\HEAD LIGHT	driving light out				######## 861970	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER		
			fitters															
LOAD22	Albury - Workshop	Engine\FILTERS	tctc		COMPLETED		########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER		
LOAD22	Albury - Workshop	Veh\service\AS	Service As Per Attached Checklist	VehServiceJAS			######## 861346	Service	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER		
LOAD22	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				######## 861346	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER		
			shockers															
LOAD22	Albury - Workshop	Susp\SHOCK ABS	maxioarts		completed		########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER		
			shocker mount															
LOAD22	Albury - Workshop	Susp\SUSPENSION	maxioarts		completed		########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER		
LOAD22	Rosewood - Workshop	Susp\SHOCK ABS	r/h back shock				######## 859160	Fault	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Rosewood Workshop	LOADER		
			repair radio															
LOAD22	Albury - Workshop	Elect\RADIO	r/c		completed		########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER		
			shockers															
LOAD22	Albury - Workshop	Susp\SHOCK ABS	maxioarts		completed		########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER		
LOAD22	Albury - Workshop	Air Con\AIR CON	repair air con		completed		########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury Workshop	LOADER		
			welding repairs															
LOAD22	Tumut - Workshop	Body\MOUNTS	Radio Engineering - no S provided		purchase order on completed		########	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Tumut Workshop	LOADER		
LOAD22	Albury - Workshop	Tyres\TP03	Job Added From Invoice				######## 856018	Repair	Completed	Greenfreight Logging NSW	LOADFORD	Albury	ALR	CH30BU	Albury