EquipmentName	Workshop	CodeAndSubCode	Description	Schedule	CompletionComments	DateDone	DistanceDone	Worktype	Workstate	EquipmentOwner	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
T623	Mt Gambier - Mt Gambier	Susp\AIR BAG	cracks in rear airbag mounts		Fault: - Cracks in rear airbag mounts Cause: - Structural fatigue Correction: - Removed rear axle airbags - Repaired cracked airbag mount gussets - Fabricated and installed gusset strengthening bars - Welded gussets and painted all bare metal surfaces - Reinstalled airbags and checked airbag function — all OK	14/10/2026	524772	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	HALLORAN DIESEL - 3	TRAILER
T623	Mt Gambier - Mt Gambier	Chassis\CHAS CRACK	Repair crack in chassis, LHS (old repair has recracked)		Fault: - Crack in chassis Cause: - Structural fatigue Correction: - Ground old weld pad off and V'd out cracks - Welded cracks and ground welds flat - Welded new pad over chassis crack repair - Welded up crossmember crack	14/10/2026	524772	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	HALLORAN DIESEL - 3	TRAILER
T623	Mt Gambier - Mt Gambier	VehService\DS	VehService\DS D Service	VehService\DS	Completed "D Service" as per attached service sheet	26/09/2026	524772	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	HALLORAN DIESEL - 3	TRAILER
T623	Colac - Colac	Tyres\TP9+10	Tyres\TP9+10		2 NEW TYRES P 29.30 2 NWR DONE IN COLAC	08/09/2026	524772	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	BORDER BANDAG PTY LTD -3	TRAILER
T623	Myrtleford - Workshop	Brakes\EBS FAULTS	REPLACE & REPROGRAM EBS MODULE			04/09/2026	448998	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	TWIN CITY TRUCK CENTRE - 3	TRAILER
T623	Mt Gambier - Mt Gambier	VehService\DS	VehService\DS D Service	VehService\DS	TENSION PIVOT BUSHES & U BOLTS \TENSION BOLSTER BOLTS Disconnect trailers, check over turntable and king pin. Greased all components, all within spec. Reconnect.	28/08/2026	524772	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		20/08/2026	524772	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	HALLORAN DIESEL - 3	TRAILER
T623	Myrtleford - Workshop	Tyres\TP7+8	Tyres\TP7+8 (27-28)			25/07/2026	448998	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	BORDER BANDAG PTY LTD -3	TRAILER
T623	Myrtleford - Workshop	DrCabElect\SCALES	Weigh gauge n/w and air leak at gauge need to extend air line to prevent leaking		Source air line to suit. Remove and replace airline with new joiner to suit. Check over for leaks, all OK NG02NK26-02 1/8 SOCKET 1 2.75 NG22NPM03-0802 BMMX1/8 CONNECTOR 1 10.59 NG22NP03-0402 STRAIGHT CONNECTOR	22/07/2026	448998	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	VehService\DS	VehService\DS D Service L134667	VehService\DS	Jack up, remove hub cap and tension wheel bearings on all	09/07/2026	448998	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Body\WHL HUB	CHECK WHEEL BEARINGS		axles. all OK	07/07/2026	448998	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Tyres\TP3+4	Tyres\TP3+4 (23-24)			07/07/2026	448998	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	BORDER BANDAG PTY LTD -3	TRAILER
T623	Myrtleford - Workshop	Chassis\STRAPS	REPLACE FRONT BINDER STRAP		Remove old binder strap, source new strap and fit as required, all okay NG60/WC-S-10 WEBBING-75MMX10MTR	11/06/2026	448998	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Insp\ANN INSP	Insp\ANN INSP Annual Inspection As Per Checklist L134215	Insp\ANN INSP		11/06/2026	448998	PreventativeMaintenance	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	VehService\DS	VehService\DS D Service L134212	VehService\DS		11/06/2026	448998	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Susp\AIR LEAK	CHECK AIR BAG LEAKING ON RH SIDE REAR		Spray over RH air components, dumped and refilled with air - unable to detect leak	14/05/2026	448998	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	VehService\DS	VehService\DS D Service L133750	VehService\DS		12/05/2026	448998	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Steering\WHEEL ALGN	NEED WHEEL ALIGNMENT			25/04/2026	448998	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	BORDER BANDAG PTY LTD -3	TRAILER
T623	Myrtleford - Workshop	Susp\SHOCK ABS	REPLACE SHOCKER STRAPS		Found 1st and 3rd axle RH side shocker straps were badly worn. Removed old straps and replaced with new. KWAS002S/4710 RESTRAINT STRAP-SHOCKER 471MM Jacked up third axle and removed wheels and brakes. Found brakes were low and s-cams were worn. Removed s-cams and bushes, fit new bushes and s-cams. Fit new brake drums and shoes. Refit wheels, adjust wheel bearings to spec and adjust brakes. KWDB001TRP TRP BRAKE DRUM SUIT BPW 419MM X 180MM 10 2 317.48 KW0509705254 C/SHAFT A=547.5MM L=666MM LH 1 98.92 KW0509705264 C/SHAFT A=547.5MM L=666MM RH 1 98.92	14/04/2026	448998	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Brakes\BRK O/HAUL	S-CAM MOVEMENT 3rd AXLE WORN **PLEASE CHECK AND ADVISE ON CONDITION** VehService\DS D Service		KW0509146320BH95 BPW B/SHOE & H/WARE 4218 20.5' CAN USE T 2 408.18 KW0509700KIT KIT-CAMSHAFT REPAIR ONE AXLE	14/04/2026	448998	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	VehService\DS	L133294	VehService\DS		13/04/2026	448998	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Tyres\TP1+2	Tyres\TP1+2 (21-22)			10/04/2026	448998	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	BORDER BANDAG PTY LTD -3	TRAILER
T623	Myrtleford - Workshop	Tyres\TP5+6	Tyres\TP5+6			13/03/2026	448998	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	BORDER BANDAG PTY LTD -3	TRAILER
T623	Myrtleford - Workshop	Tyres\TP9+10	Tyres\TP9+10 (29-30)			13/03/2026	448998	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	BORDER BANDAG PTY LTD -3	TRAILER
T623	Myrtleford - Workshop	Susp\AIR BAG	check air bags, ride height valve, straps on shockers REPAIR LH MIDDLE SPRING - SNAPPED U BOLTS AND SADDLES		Support spring, remove snapped u bolts. Unbolt shocker and removed, remove snapped saddle. Installed new saddle and remount shocker. Installed new u bolts, secured spring and tensioned all bolts. KW0514525470 PLATE - SPRING AU L/H WELDED 5 1 146.04 KW0313841014 U-BOLT M24X152X268 RINGFEDER FRONT MOUNT 1 72.38 KW0254012507 WASHER- HARDENED 25/44/4 4 4.08 KW0328136140AL2US PLATE ALIGNMENT C/W DOWEL 58mm RINGFEDER 1 47.40 KW0252207412 NUT - LOCK M24 GRADE 10.9 4 10.60 KW0313841194 U BOLT-M24x152x280	28/02/2026	448998	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Chassis\WINCH/STRP	straighten binder front bay STRAIGHTEN WINCH OR WINCH MOUNT		Check over binders and winch mounts - all looked OK. 1st binder mounts all looked OK. Possible already reqaired ?	28/02/2026	448998	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Chassis\WINCH/STRP	grease all binders DONE ON D/SERVICE			28/02/2026	448998	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Susp\DAMAGE	REMOVE AIRBAG FOR JD'S TO WELD MOUNT AND REFIT NEW AIR BAG DUE TO BEING BENT & REPLACE AIR BAG		Remove RH rear air bag and kinked over air lines, so JDs could repair air bag bracket. Original air bag mounting plate was bent, supply and installed new air bag. Replaced section of air line, joined and checked operation, no further leaks. KWTRP8093 AIR SPRING-TRP BPW D30 SUITS BPW 0542943 1 213.09 Sublet1S112887 AIRBAG WELD REPAIR	28/02/2026	448998	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Chassis\WHL HUB	CHECK WHEEL BEARINGS - LH FRONT		Jacked LH front axle to inspect wheel bearing movement. Found to be out of spec. Take brakes off, remove hub cap and adjust wheel bearing to correct end float. Refit hub cap, lowered axle. Carried out trailer service as per Greenfreight checklist. Customer Instructions: Place vehicle on shaker & Inspected	28/02/2026	448998	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	VehService\DS	VehService\DS D Service L099178	VehService\DS	Carried out General Inpection & Checkover Greased vehicle	26/02/2026	448998	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Susp\DAMAGE	CHECK AIR BAG GUSSETS BROKEN		Inspect air bag gussets on trailer, found to be okay, but will continue to monitor. Repair would need to be carried out by JDs Metal Fab.	24/02/2026	448531	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Tyres\Punct	Tyres\Punct POS 32			11/02/2026	448531	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	BORDER BANDAG PTY LTD -3	TRAILER
T623	Myrtleford - Workshop	Tyres\TP3+4	Tyres\TP3+4 (23-24)			28/01/2026	448531	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	BORDER BANDAG PTY LTD -3	TRAILER
T623	Myrtleford - Workshop	Tyres\TP7+8	Tyres\TP7+8 (27-28)			28/01/2026	448531	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	BORDER BANDAG PTY LTD -3	TRAILER
T623	Myrtleford - Workshop	VehService\DS	VehService\DS D Service L098555	VehService\DS		19/01/2026	448531	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Tyres\TP1+2	Tyres\TP1+2 (21-22)			06/01/2026	448531	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	BORDER BANDAG PTY LTD -3	TRAILER
T623	Myrtleford - Workshop	Tyres\Punct	Tyres\Punct 32			12/12/2025	448531	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	BORDER BANDAG PTY LTD -3	TRAILER
T623	Myrtleford - Workshop	VehService\DS	VehService\DS D Service L098073	VehService\DS		12/12/2025	448531	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Body\BOLSTER	ROTATE BACK BOLSTER PIN DRIVERS SIDE MOVE BOLSTERS & LOAD BINDERS FOR OFO COMPLIANCE		ROTATE RH REAR BOLSTER PIN Undo bolster bolt and rotate pin. Found 2nd bolster on LH side of B trailer also needed rotating. Undo bolts and rotate as required, all okay.	11/12/2025	448531	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Body\BOLSTER	DONE AT COLAC			11/12/2025	448531	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Brakes\BOOSTER	CHECK BRAKES - REAR AXLE BOOSTER RODS PUSHED OUT		Upon service found booster rods sticking out on service. Check air supply to boosters and found air line connected into wrong side of booster. Remove airline and connect airline correctly. check operation. all okay	11/12/2025	448531	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Elect\WORK LIGHT	WORK LIGHTS N/W		Check over lights for power and earth, all okay. Remove and replace RH rear work light as required and check operation, all okay.	11/12/2025	448531	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Brakes\BREAKDOWN	AFTER H'RS BREAKDOWN CALL OUT FEE		AIR LEAK @ WORKSHOP Inspect and found push fitting un-serviceable. Remove and replace with new compression fitting. Replace 300mm 3/8 airline. Check over for air leaks. all ok	18/11/2025	448531	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Chassis\WINCH/STRP	REPLACE BINDER FITTINGS		Remove and replace broken air fitting as supplied. Test over for leaks, all ok Remove all components holding scales in place. Separate scales from box and remove old box. Fit new box and mount scales. Fit air lines and wiring. Found Bluetooth not connecting, remove all scale components and refit everything with new scale, wiring and air lines. Test and all worked as should.	14/11/2025	448531	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	DrCabElect\SCALES	REPLACE RIGHT WEIGH LOAD SCALES BOX		NG201-EBT-018 S/INPUT WEIGHT GAUGE	14/11/2025	448531	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Chassis\CHAS CRACK	INSPECT CRACK ON PREVIOUS REPAIR WD INSPECTED REPAIRS ALL OK VehService\DS D Service L097772		INSPECT CRACK ON PREVIOUS REPAIR Inspect trailer for cracks, unable to find any. Check over trailer history for any other cracking jobs, did not find anything. Need more information.	14/11/2025	448531	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	VehService\DS	VehService\DS	VehService\DS		14/11/2025	448531	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Body\MOUNTS	FIT CAB GUARD MOUNTS TO FRONT OF TRAILER TO REFIT CAB GUARD CAB GUARD SUPPLIED BY G/F M/FORD			14/11/2025	448531	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	ELPHINSTONE ENGINEERING - 3	TRAILER

			Steering\WHEEL ALGN																		
T623	Myrtleford - Workshop	Steering\WHEEL ALGN	L097679				11/11/2025	448531	Reapir	Completed	Greenfreight Loxaine Vic	FlatTow	Mt Gambier	STK	091935	BORDER BANDAG PTY LTD -3	TRAILER
T623	Myrtleford - Workshop	ElecLab	TRACE & REPAIR FAULT IN LOADING LIGHTS				04/11/2025	448531	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	JF MECHANICALS - 3	TRAILER
T623	Myrtleford - Workshop	ChassisLab	STRAIGHTEN MUD GUARD BRACKETS, REMOVE AIR WINCHES & STRAIGHTEN BRACKETS & REMOUNT WINCHES, FIT CAB GUARD TO THE MOUNTS & REPLACE WO				04/11/2025	448531	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	JF MECHANICALS - 3	TRAILER
T623	Myrtleford - Workshop	BrakesLab	REPLACE BROKEN AIR HOSES ON MIDDLE AXLE X 2				04/11/2025	448531	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	JF MECHANICALS - 3	TRAILER
T623	Myrtleford - Workshop	Body\FIFTH WHEE	LH FOOT BUSH HAS MOVEMENT - CHECK AND ADVISE		Checked movement all in spec.		29/10/2025	448531	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	BARRY MANEY - 3	TRAILER
					Inspect and found air leak coming from supply line into												
					trailer. Found leak coming from push fitting . Unplug line												
					and replaced fitting, also fit new hose clamp and clean up												
			REPLACE LEAKING AIR LINE FITTING THAT SUPPLIES AIR TO B		wear spots at end of hose. Build up air and re-check, all ok												
T623	Myrtleford - Workshop	Body\AIR FITTIN	TRAILER		KWASA93-87 CONNECTOR 1/2" NPSF FEMALE 1 26.24KWHS08P CLAMP-HOSE,PERFORATED 1		29/10/2025	448531	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	BARRY MANEY - 3	TRAILER
			3 88ZZZZZ207 CHECK BRAKES														
			Tech(s):														
			8050 0.005-CAM MOVEMENT														
			Work order 200051														
			Inspect s-cam movement. Found to have movement and will		LH FRONT AND LH MIDDLE BRAKES TO BE REPLACED												
			need to be replaced when linings are replaced		(CHECK OVER ALL S-CAMS PLEASE)												
T623	Myrtleford - Workshop	Brakes\BRK O/HAUL	<<< Total For J		Checked over brakes all okay and within spec		29/10/2025	448531	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	JF MECHANICALS - 3	TRAILER
			LH front and middle brakes to be repalced next service														
			LH FRONT AND LH MIDDLE BRAKES TO BE REPLACED		LH FRONT AND LH MIDDLE BRAKES TO BE REPLACED												
			(CHECK OVER ALL S-CAMS PLEASE)		(CHECK OVER ALL S-CAMS PLEASE)												
T623	Myrtleford - Workshop	Brakes\BRK RELINE	Checked over brakes all okay and within spec		Checked over brakes all okay and within spec		29/10/2025	448531	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	JF MECHANICALS - 3	TRAILER
			VehService\DS D Service														
T623	Myrtleford - Workshop	VehService\DS	L097437	VehService\DS			24/10/2025	448531	Service	Completed	Greenfreight Loxaine Vic	FlatTow	Mt Gambier	STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Tyres\RUN OUT	Tyres\RUN OUT POS 26-27				23/10/2025	448531	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	BORDER BANDAG PTY LTD -3	TRAILER
T623	Myrtleford - Workshop	Tyres\Punct	Tyres\Punct POS 23				23/10/2025	448531	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	BORDER BANDAG PTY LTD -3	TRAILER
					CHECK AIR LEAKS												
					Found middle axle to have rubbed air line. Wrap thick												
					silicon hosing around rub and secure, all ok												
T623	Myrtleford - Workshop	Body\AIR LEAK	Body\AIR LEAK		NISCRAPHOSE scrap hose		10/09/2025	448531	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	BARRY MANEY - 3	TRAILER
					Repair hook for landing leg												
					Make up new bracket for landing leg winder. Weld and paint												
T623	Myrtleford - Workshop	Chassis\TRL LEGS	NEEDS NEW HOOK FOR LEG HANDLE TO HANG UP		as necessary, all ok		10/09/2025	448531	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	BARRY MANEY - 3	TRAILER
			VehService\DS D Service														
T623	Myrtleford - Workshop	VehService\DS	L096673	VehService\DS			10/09/2025	448531	Service	Completed	Greenfreight Loxaine Vic	FlatTow	Mt Gambier	STK	091935	BARRY MANEY - 3	TRAILER
					REPLACE BARRELLS WITH ONES SUPPLIED												
					Work order 200051												
					Removed straps then remove binders that need to be												
			CHANGE BARRELS ON WINCH FROM CHAIN STYLE TO STRAP STYLE		replaced. Fit new binders to truck and refit binder straps.												
T623	Myrtleford - Workshop	Chassis\EXTE TU	SEE SCOTT FOR REPLACEMENT BARRELLS		Tighten as required, all ok		19/08/2025	448531	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	BARRY MANEY - 3	TRAILER
					BOLSTERS NEED STRAIGHTENING AND/OR MOVED CLOSER TOGETHER AS												
					TOP OF PINS TOO WIDE FOR SHORT LEGS												
					Work order 200051												
			bolsters need straightening and or moved closer together as top of pins to wide for short legs.		Remove deck plate and unbolt bolster. Lift with forklift.												
			SPEAK TO SCOTT FOR MEASUREMENTS.		Span bolster 180 degrees then bolt back to chassis. Turned												
T623	Myrtleford - Workshop	Chassis\BOLSTER			clearance isleft around so thev were correct. all ok		19/08/2025	448531	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	BARRY MANEY - 3	TRAILER
					S-CAM MOVEMENT												
					Work order 200051												
					Inspect s-cam movement. Found to have movement and will												
T623	Myrtleford - Workshop	Brakes\SLACK ADJ	SLIGHT S - CAM MOVEMENT		need to be reolaced when linines are reolaced		19/08/2025	448531	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	BARRY MANEY - 3	TRAILER
					MUDFLAP R&R												
					Work order 200051												
T623	Myrtleford - Workshop	Body\MUDGUARDS	replace mudflaps		Remove and reolace mudflao as reouired		19/08/2025	448531	Reapir	Completed	Greenfreight Loxaine Vic	FlatTow	Mt Gambier	STK	091935	BARRY MANEY - 3	TRAILER
					GREENFREIGHT SERVICE												
					Carried out trailer service as per Greenfreight checklist.												
					Customer Instructions:												
					Place vehicle on shaker & Inspected												
					Carried out General Inpection & Checkover												
					Greased vehicle												
					TENSION PIVOT BUSHES & U BOLTS												
					Check over and retension pivot bushes & u bolts												
					TENSION BOLSTER BOLTS												
					Check over and tensioned all bolster bolts as required.												
					DISCONNECT TRUCK OR TRAILER												
					Disconnect trailers, check over turntable and king pin.												
T623	Myrtleford - Workshop	VehService\DS	VehService\DS D Service	VehService\DS	Greased all comoonents. all within spec. Reconnect.		13/08/2025	448531	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Body\MUDGUARDS	replace passenger side middle guard				01/08/2025	448531	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Chassis\WINCH/STRP	REPLACE STRAP & WINCH ON 2ND BINDER				01/08/2025	448531	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	BARRY MANEY - 3	TRAILER
					GREENFREIGHT SERVICE												
					Carried out trailer service as per Greenfreight checklist.												
					Customer Instructions:												
					Place vehicle on shaker & Inspected												
					Carried out General Inpection & Checkover												
					Greased vehicle												
					TENSION PIVOT BUSHES & U BOLTS												
					Check over and retension pivot bushes & u bolts												
					TENSION BOLSTER BOLTS												
T623	Myrtleford - Workshop	VehService\DS	VehService\DS D Service	VehService\DS	Check over and tensioned all bolster bolts as required		30/07/2025	448531	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	BARRY MANEY - 3	TRAILER
					Travel to workshop, check power at lights, found no power.												
					Inspect and found short before rear bar. Cut out short and												
					re-join, test operation, still not working. Inspect further												
					and found another short in chassis, cut and re-join, check												
					operation, still not working. Check plugs from A trailer to												
					truck, all looked fine. Inspect further and found squished												
					wiring where a log had been dropped on deck plate. Cut 6												
					core wiring and rejoin all 6 wires, also add wiring and												
					reroute wires. Check operation, still not working. Check												
					over all fuses and relays, all looked ok. Keep inspecting												
					for broken wiring, no luck. Will have driver come back with												
T623	Myrtleford - Workshop	Elect\TAIL LIGHT	REAR BAR LIGHTS N/W		truck and both trailers another time to proverly check over		23/07/2025	448531	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	VehService\DS	VehService\DS D Service	VehService\DS			18/07/2025	448531	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	BARRY MANEY - 3	TRAILER
					Instructed to remove all load binder ropes and chains and												
					replace with normal straps. Sourced bolts to hold straps												
T623	Myrtleford - Workshop	Chassis\WINCH/STRP	REPLACE ROPES WITH STRAPS		into barrels		28/06/2025	448531	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	DrivLine\WHEEL BRGS	CHECK WHEEL BEARINGS		Jack up and check wheel bearings all in spec		28/06/2025	448531	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	BARRY MANEY - 3	TRAILER
			CHECK FOR AIR LEAKS - THOUGHT HEARD AIR LEAK WHEN LOADED BUT		Check over air leaks found rear LH air bag line was												
T623	Myrtleford - Workshop	Susp\AIR LEAK	WENT AWAY WHEN UNLOADED		leaking, replaced air line all okay		28/06/2025	448531	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	BARRY MANEY - 3	TRAILER
					Inspect winch and found operation okay, slightly harder												
					then the others. Lubricate and operate numerous times to												
T623	Myrtleford - Workshop	Chassis\WINCH/STRP	#2 & #3 WINCH HARD TO WIND. SORE WRIST.		free up. Checked with others and all ooerating correctlv.		28/06/2025	448531	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	BARRY MANEY - 3	TRAILER
					Found indicator n/w, remove and wire broken at back of												
T623	Myrtleford - Workshop	Elect\INDICATORS	RH REAR INDICATOR N/W		light. Fit new and check operation all okay.		28/06/2025	448531	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	BARRY MANEY - 3	TRAILER
					Carried out trailer service as per Greenfreight checklist.												
					Customer Instructions:												
					Place vehicle on shaker & Inspected												
					Carried out General Inpection & Checkover												
					Greased vehicle												
					TENSION PIVOT BUSHES & U BOLTS												
					Check over and retension pivot bushes & u bolts												
					TENSION BOLSTER BOLTS												
T623	Myrtleford - Workshop	VehService\DS	VehService\DS D Service	VehService\DS	Check over and tensioned all bolster bolts as required		18/06/2025	448531	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	BARRY MANEY - 3	TRAILER
					Weld new hook onto no.2 and no.4. Bent straight, weld cross												
T623	Myrtleford - Workshop	Chassis\EXTE TU	WELD NEW STRAP HOOKS ON WINCH NO.2 AND NO.4		member. weld airbae bracket.		17/06/2025	448531	Fault	Completed	Greenfreight Loxaine Vic	FlatTow	Mt Gambier	STK	091935	BARRY MANEY - 3	TRAILER
					Remove clearance light, fit mount and refit light to												
T623	Myrtleford - Workshop	Elect\TRL LIGHTS	CHECK ALL LIGHTS - CLEARANCE LIGHT OUT		bracket.		17/06/2025	448531	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Tyres\TP3+4	Tyres\TP3+4				16/06/2025	448531	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	BEAUREPAIRES - 3	TRAILER
T623	Myrtleford - Workshop	Tyres\TP1+2	Tyres\TP1+2				16/06/2025	448531	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	BEAUREPAIRES - 3	TRAILER
					Remove and replace ball race as seized												
					Split A and B trailers, remove turn table Base plate.												
					Remove ball race and turn table. Install turn table to												
					new ballrace, then reinstall turn table base plate. Tension												
					mount bolts, reinstall base plate to trailer and tension.												
T623	Myrtleford - Workshop	Chassis\FIFTH WHEE	Chassis\FIFTH WHEE		Reconnect A and B trailers.		12/06/2025	448531	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection	Insp\ANN INSP			30/05/2025	448531	PreventativeMaintenance	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	VehService\DS	VehService\DS D Service	VehService\DS			30/05/2025	448531	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	VehService\DS	VehService\DS D Service	VehService\DS			24/05/2025	448531	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	VehService\DS	VehService\DS D Service	VehService\DS			24/05/2025	1356426	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	VehService\DS	VehService\DS D Service	VehService\DS			16/04/2025	448531	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Tyres\TP11+12	Tyres\TP11+12				26/03/2025	448531	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	BEAUREPAIRES - 3	TRAILER
T623	Myrtleford - Workshop	Tyres\TP7+8	Tyres\TP7+8				26/03/2025	448531	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	BEAUREPAIRES - 3	TRAILER
T623	Myrtleford - Workshop	VehService\DS	VehService\DS D Service	VehService\DS			18/03/2025	448531	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	BARRY MANEY - 3	TRAILER
					Found broken u bolt on LH middle axle. Removed broken u												
					bolt and repalced with new. Found other u bolt showed signs												
					of cracks and nuts were seized. Cut off u bolt and replaced												
T623	Myrtleford - Workshop	Susp\SUSPENSION	REPLACE BROKEN U BOLT & TENSION		with new. Tensioned bolts.		13/03/2025	448531	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	BARRY MANEY - 3	TRAILER
					CHECK OVER FOR AIR LEAKS - AIR TANK LEAKING												
					Found air leak at fuel tank at front of trailer, got new												
					fitting and install check for leaks all okay. Found other												
T623	Myrtleford - Workshop	Brakes\AIR TANKS	Brakes\AIR TANKS		fittine leakine remove and re seal all okav		27/02/2025	349921	Repair	Unlocked	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	BARRY MANEY - 3	TRAILER
			GOODYEAR AUTOCARE MOUNT GAMBIER.														
T623	Myrtleford - Workshop	Tyres\TP5+6	REPLACED TYRES P5+6.				26/02/2025	448531	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	BEAUREPAIRES - 3	TRAILER
T623	Myrtleford - Workshop	VehService\DS	VehService\DS D Service	VehService\DS			26/02/2025	448531	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	BARRY MANEY - 3	TRAILER
					CHECK OVER FOR AIR LEAKS - AIR TANK LEAKING												
					Found air leak at fuel tank at front of trailer, got new												
					fitting and install check for leaks all okay. Found other												
T623	Myrtleford - Workshop	Brakes\AIR TANKS	Brakes\AIR TANKS		fittine leakine remove and re seal all okav.		26/02/2025	448531	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Tyres\TP9+10	Tyres\TP9+10				24/02/2025	448531	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	BEAUREPAIRES - 3	TRAILER

					1 8922222228 MISC TRAILER REPAIR Tech(s): 8097 150.00CHECK OVER FOR AIR LEAKS - AIR TANK LEAKING Found air leak at fuel tank at front of trailer, got new fitting and install check for leaks all okay. Found other fitting leaking remove and re seal all okay. KWAQ69-D0TS-E0B PTC ELBW 3/8 X 1/2 M 1 13.63<<< Total For Job 1 >>> 163.63Misc: E-2 ENVIRONMENTAL LEVY 10.00Misc:										
T623	Myrtleford - Workshop	Body\AIR LEAK	air leak in trailer messing with scales		SHOPT SHOP SUPPLIE	21/02/2025	448531	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Elect\TRL LIGHTS	Elect\TRL LIGHTS		R&R TRAILER PLUG Tested plug and found to have earth pin 1/2 missing. Removed deck plate and removed old trailer plug. Fit new base. reassembled and test. all okay	19/02/2025	349921	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Chassis\WINCH/STRP	Chassis\WINCH/STRP		STRAIGHTEN HANDLE ON SECOND BINDER Work order 193822 Disassembled binder mounts. Used oxy to heat up and straightened. Repeated process until handle was straight. heated up and straightened chassis mount. Changed over handle and check operation all working correctly	19/02/2025	349921	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	VehService\DS	VehService\DS	VehService\DS		17/02/2025	448531	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Chassis\SCALES	BROKEN SCALES PLUG ON TRAILERS		On inspection found plug needed to be re wired as it was broken off. Cut end & fit new plug supplied by GF, wired in & tested. All ok.	28/01/2025	448531	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Chassis\STRAPS	BINDER STRAP TANGLED		Driver advised binder strap was tangled. Removed strap and untanelled & refit. All ok	28/01/2025	448531	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Chassis\MUDGUARDS	replace damaged guard		Unbolt and removed mud guard. Removed bracket and straightened out in press. Welded bracket to chassis. Drilled holes in new guard and installed with new bolts, tensioned	24/01/2025	448531	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	VehService\DS	VehService\DS	VehService\DS		22/01/2025	448531	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Body\BOLSTER	Body\BOLSTER		SADDLE ON SECOND BOLSTER RH SIDE Found cracked saddle on RH second bolster. Unbolted from chassis, prepped surface area for welding. Welded over surfaces and painted. Refit to trailer.	18/12/2024	448531	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Body\STRAPS	Body\STRAPS		REMOVE BINDERS AND CHANGE OVER TO OTHER SIDE Unbolt and removed all binders. Change over to other side, change over handle to suit	18/12/2024	448531	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Chassis\SCALES	Chassis\SCALES		REPLACE SCALES TEMP LEAD FROM A TO B TRAILER Removed scales lead and replaced with new.	11/12/2024	448531	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Body\BOLSTER	Body\BOLSTER		STRAIGHTEN BOLSTERS AS REQUIRED Loosen mounting bolts and straightened front bolster. Found mounting brackets were bent, no parts or time for replacement. Installed new bolts and tensioned.	11/12/2024	448531	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Body\STRAPS	Body\STRAPS		REPLACE 1ST BINDER BARRELL Removed bolts securing binder in position. Pull binder barrell out, remove binder strap and fit to new barrell. Fit new barrell, refit all bolts and test operation, all okay.	11/12/2024	448531	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Body\LIGHTS	Body\LIGHTS		RH INNER TAIL LIGHT N/W Remove tail light and check for power and earth, all okay. Cut wiring and removed light, installed new light, joined wirine. test operation. all okay.	11/12/2024	448531	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Body\MUDGUARDS	Body\MUDGUARDS		CHECK MUD GUARDS, REPLACE WHERE NECASSARY Inspect guards, found all were loose. Tightened loose guards as required. Carried out trailer service as per Greenfreight checklist. Customer instructions: Place vehicle on shaker & Inspected Carried out General Inpection & Checkover Greased vehicle Completed paperwork & Cleaned area	11/12/2024	448531	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	VehService\DS	VehService\DS	VehService\DS	TENSION PIVOT BUSHES & U BOLTS Check over and retension oivot bushes & u bolts	30/11/2024	448531	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Tyres\TP3+4	Replace Tyres On Position 3&4. (Mount Gambier Goodyear Autocare P/O: L090549)			26/11/2024	448531	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BEAUREPAIRES - 3	TRAILER
T623	Myrtleford - Workshop	Body\BOLSTER	needs all bolsters re positioned straight		STRAIGHTEN BOLSTERS AS REQUIRED Loosen mounting bolts and straightened front bolster. Found mounting brackets were bent, no parts or time for replacement. Installed new bolts and tensioned.	01/11/2024	448531	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Body\MUDGUARDS	Body\MUDGUARDS		CHECK MUD GUARDS, REPLACE WHERE NECASSARY Inspect guards, found all were loose. Tightened loose guards as required	01/11/2024	448531	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Chassis\SCALES	needs new scale plugs fitted on rear of A trailer where lead goes from A trailer to B trailer. end of lead and where it connects to A trailer in front of turn table. remove temosrarv lead that Scott out in place.		REPLACE SCALES TEMP LEAD FROM A TO B TRAILER Removed scales lead and reslaced with new	01/11/2024	448531	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Body\BOLSTER	front bolster brackets loose. bolster leaning forward.		BRACKET LOOSE ON CHASSIS Found the bracket over air controls was close to falling off. Removed reaming bolts and replaced with 4 x new bolts. Secured in place.	01/11/2024	448531	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Chassis\EXTE TU	1st binder barrel needs replacing. Supplied by Scott GF		REPLACE 1ST BINDER BARRELL Removed bolts securing binder in position. Pull binder barrell out, remove binder strap and fit to new barrell. Fit new barrell, refit all bolts and test operation, all okay	01/11/2024	448531	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Elect\TRL LIGHTS	rear side clearance light popped out of bracket		RH INNER TAIL LIGHT N/W Remove tail light and check for power and earth, all okay. Cut wiring and removed light, installed new light, joined wirine. test operation. all okay. repair rear guard on a-trailer - may require weld job	01/11/2024	448531	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Body\MUDGUARDS	Body\MUDGUARDS		On inspection found guard to be broken & bracket had snapped off chassis. Removed existing guard from trailer, ground down broken section from bracket & chassis and re welded back to chassis. Measure and drilled holes in new guard, installed new guard to trailer and tensioned bolts. BRACKET LOOSE ON CHASSIS Found the bracket over air controls was close to falling off. Removed reaming bolts and replaced with 4 x new bolts.	31/10/2024	448531	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Body\MUDGUARDS	Body\MUDGUARDS		Secured in place.	31/10/2024	448531	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	VehService\DS	VehService\DS	VehService\DS		29/10/2024	448531	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Chassis	Chassis		Welding repairs to be done at JD's metal	15/10/2024	448531	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	VehService\DS	VehService\DS	VehService\DS		04/10/2024	448531	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Body\MUDGUARDS	RIGHT REAR AND FRONT MUDGUARD NEED REPLACING		RH FRONT AND REAR MUD GUARDS NEED REPLACING R&R front right and rear right mudguards as per usual. Also used 16x bolts and 16x nuts, all okay	27/09/2024	448531	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Susp\AXLES	Susp\AXLES		DOWEL LOCATING FRONT LH AXLE BROKEN Removed u-bolts, shock and all spring plates, disconnected air bag. Inspect and clean metal from saddle and repair alignment plate. Line axle up and refit all components, weld alignment plate in place, paint and tension u bolts to spec. refit and tension everythine else. All okav	27/09/2024	448531	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Susp\AIR BAG	Susp\AIR BAG		LEAKING RH REAR AIR BAG Carried out by Cooky's diesel repairs. Attend breakdown, support trailer. Disconnect air line and replace air bag. Reconnect air lines, test operation, all okay. *no after hrs rates charged*	26/09/2024	448531	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Chassis\BOLSTER	front bolster loose in bracket allowing bolster to lean forward		REMOVE AND REPLACE RH FRONT SADDLE On inspection, found front left saddle was snapped. Jacked airbag & removed weights. Unbolted & removed saddle. Straighten u-bolts to fit new saddle. Found axle had moved, adjusted to correct position. Secured saddle to spring & welded a-liner in, tensioned to spec.	24/09/2024	448531	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Brakes\BOOSTER	replace brake booster		Brought truck into workshop. Built up air. Activated black push button, rod would not retract. Plugged in shop air, still would not retract. Removed shop air one backed off brakes. Unbolted booster and removed air hoses. Measured up rod & cut to length. Fit new booster. Once driver moved truck, was showing 2nd booster was unserviceable. Repeated procedure for 2nd brake booster.	20/09/2024	448531	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Brakes\BREAKDOWN	brakes locked on and lost all air to trailers		BRAKES LOCKED ON & LOST ALL AIR At Qube block - UHF channel 16 Travelled to truck broken down. Inspect for fault, found air line had snapped. Cut off ends and joined new air line with ioiners. Tested operation. no further faults.	19/09/2024	448531	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	VehService\DS	VehService\DS	VehService\DS		09/09/2024	448531	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Tyres\TP3+4	Tyres\TP3+4			27/08/2024	448531	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BEAUREPAIRES - 3	TRAILER
T623	Myrtleford - Workshop	Tyres\TP05	Tyres\TP05			27/08/2024	448531	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BEAUREPAIRES - 3	TRAILER
T623	Myrtleford - Workshop	Tyres\TP02	Tyres\TP02 Elect\WORK LIGHT WORK LIGHTS N/W			27/08/2024	448531	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BEAUREPAIRES - 3	TRAILER
T623	Myrtleford - Workshop	Elect\WORK LIGHT	Inspected lights, all lights working. No faults Elect\HOUSEKEEPING REAR CLEARANCE LIGHT POPPED OUT OF BRACKET			23/08/2024	448531	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Elect\HOUSEKEEP	Reinstalled clearance light			23/08/2024	448531	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	VehService\DS	VehService\DS	VehService\DS		19/08/2024	448531	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Chassis\MUDGUARDS	mud flaps splitting need replacing			05/07/2024	448531	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Chassis\MUDGUARDS	left front guard needs replacing			05/07/2024	448531	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Chassis\BOLSTER	front binder bracket bent			05/07/2024	448531	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Brakes\AIR LEAK	Brakes\AIR LEAK			27/06/2024	448531	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	Myrtleford Workshop	TRAILER

T623	Myrtleford - Workshop	VehService\DS	VehService\DS	VehService\DS		27/06/2024	448531	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Tyres\TP3+4	Tyres\TP3+4			18/06/2024	448531	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BEAUREPAIRES - 3	TRAILER
T623	Myrtleford - Workshop	Tyres\TP1+2	Tyres\TP1+2			23/05/2024	448531	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BEAUREPAIRES - 3	TRAILER
T623	Myrtleford - Workshop	Tyres\TP11+12	Tyres\TP11+12			22/05/2024	448531	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BEAUREPAIRES - 3	TRAILER
			AXLE MOVING ON SPRING INSPECT CENTRE BOLT IN SPRING - Used shaker to inspect												
			suspension components. Found axle moving and U-bolts nuts loose. Removed nuts and inspected												
T623	Myrtleford - Workshop	Susp\AXLES	centre bolt. Reslaced nuts & washers on u bolts & tensioned to ssec. All okav. recheck next service.			27/04/2024	448531	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Chassis\BOLSTER	2X BOLSTER PINS BENT AND OUTSIDE LEGAL BOUNDARY.			26/04/2024	448531	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Chassis\WINCH/STRP	ALL ROPES ARE FRAYED DAMAGED & WORN A & B TRAILER.			26/04/2024	448531	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Brakes\BRAKE ADJ	ADJUST BRAKES.			26/04/2024	448531	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Elect\ELECT P&W	CHANNEL 2 ON SCALES ABOUT 6-7T OUT.			26/04/2024	448531	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			26/04/2024	448531	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist												
T623	Myrtleford - Workshop	VehService\DS	PO# L085538	VehService\DS		26/04/2024	448531	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
			BOOSTER R&R RH FRONT - Backed brakes off and disconnected airlines. Removed old one and												
T623	Myrtleford - Workshop	Brakes\BOOSTER	swapped over fitting. Cut rod to length & mounted new one - connected everything, adjusted brake - ok			09/03/2024	147803	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			09/03/2024		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist												
T623	Myrtleford - Workshop	VehService\DS	PO# L084542	VehService\DS		09/03/2024		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
					REPLACE RH REAR MUD GUARD - Found RH rear mud guard was broken. Unbolt & removed mud										
			RUBBER INTERNAL MATS BETWEEN RAILS NEED FIXING. MANY TEARS.		guard. Straightened out bracket. Measure & drilled holes in new guard, mounted guard & tightened										
T623	Myrtleford - Workshop	Chassis\MUDGUARDS	GF TO SUPPLY RUBBER MAT.		bolts, all okay.	10/02/2024		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
			RH WORK LIGHT N/W - Removed light and tested wiring, all okay. Mounted new light & joined wiring.												
T623	Myrtleford - Workshop	Elect\WORK LIGHT	Secured wiring & checked operation. all okav.			10/02/2024		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Susp\AIR BAG	AIR LEAK MIDDLE AXLE - Inspect for air leak, found loose hose clamp. Tightened hose clamp, okay.			10/02/2024		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			10/02/2024		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist												
T623	Myrtleford - Workshop	VehService\DS	PO# L083889	VehService\DS		10/02/2024		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Tyres\TP9+10	Tyre Position 9 + 10			07/02/2024		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	Albury Workshop	TRAILER
T623	Myrtleford - Workshop	Tyres\Punct	4			26/01/2024		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	Albury Workshop	TRAILER
			CHECK WHY SCALES ARE 6-7 TON OUT - Inspect scale components, inspect filter for breather												
			scales, found to be locked. Check over all wiring & plugs, cleaned out plugs. Cleaned out filter &												
T623	Myrtleford - Workshop	Chassis\SCALES	tested scales, all working within spec.			24/01/2024	147803	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	Albury Workshop	TRAILER
			WELD CRACKS CROSS MEMBER - Grind back surface and welded crack on cross member &												
T623	Myrtleford - Workshop	Chassis\CROSS MBR	chassis rail.			24/01/2024	147803	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	Albury Workshop	TRAILER
T623	Myrtleford - Workshop	Chassis\MUDGUARDS	RUBBER INTERNAL MATS BETWEEN RAILS NEED FIXING. MANY TEARS.			18/01/2024		Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			18/01/2024		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist												
T623	Myrtleford - Workshop	VehService\DS	PO# L083431	VehService\DS		18/01/2024		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
			RH MIDDLE HUT GETTING HOT - Adjusted the brakes to specification, still dragging slightly. Jacked												
			up RH middle axle, removed wheels & brake drum. Found s-cams & bushes were worn. Removed the												
			s-cam & bushes. Replaced the bushes, s-cams and slack adjusters. Refitted the drum & wheels.												
T623	Myrtleford - Workshop	Susp\Torque Rod	Adjusted wheel bearings, adjust brakes.			15/12/2023	241154	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Tyres\TP07	Tyre Position 7			13/12/2023		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	Albury Workshop	TRAILER
			TRAILER AXLE CAUGHT FIRE - Travelled to loaded trailer in bush and inspect for damage. Driver had put out fire with												
			extinguishers. Found 3x boosters, 2x airbags & 1x brake was damaged. Cut & kinked over the airlines to the airbags.												
			Caged off boosters & kinked over airlines. Ride height was snapped. Used cable ties & altered ride height to get												
			working until back at workshop. Removed the backing plate on damaged brake, removed melted brakes & backed off.												
			melted tyre & damaged rim. Returned to BMG for repairs. Attempt to move into shed, could not build up air pressure,												
			& both middle axle. Cut push rod to length on new boosters, installed & connect air lines. Replaced height control valve												
			Disconnect B trailer & move into shed. Removed RH M hub assembly. Disconnect lines, removed x3 boosters. RH front												
			found another air bag had blown. Disconnect lines, unbolt & removed LH front air bag, installed new. Built up air, okay.												
			Removed cap & checked bearings, all okay. Built up air & checked, okay. Driver moved to harder ground, remove												
			Found some air lines to middle axle were rubbed. Disconnect & installed new length of air line.On RH middle axle, replaced brake linings and drum. Replaced												
			wheel speed sensor. Fit new bearings, seals &												
			hub nut. Reinstalled hub, adjust brakes. Replaced RH middle and LH front air bag. Replaced inner wheel. Tensioned												
T623	Myrtleford - Workshop	Susp\DAMAGE	wheel nuts. Arrange fire extinguishers to be refilled. Connected to B trailer and deliver back to yard.			13/12/2023		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Tyres\TP04	Tyre Position 4			09/12/2023		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	Albury Workshop	TRAILER
T623	Myrtleford - Workshop	Chassis\BOLSTER	BENT BOLSTER, FRONT BAY R/H SIDE.			02/12/2023	76572	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Chassis\WINCH/STRP	QUICK RELEASE WIRE BROKEN ON A-TRAILER.			02/12/2023	76572	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			02/12/2023	76572	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Chassis\MUDGUARDS	RUBBER INTERNAL MATS BETWEEN RAILS NEED FIXING. MANY TEARS.			02/12/2023	76572	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Chassis\BOLSTER	BENT FRONT BOLSTER BRACKETS ON CHASSIS RAILS.			02/12/2023	76572	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Body\MUDGUARDS	LHF MUDGUARD NEEDS REPLACING.			02/12/2023	76572	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		02/12/2023	76572	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	DrivLine\WHEEL BRGS	CHECK WHEEL BEARINGS		Jack each axle, removed hub caps. Adjusted bearings to spec. Refit caps & lowered axles	01/12/2023	1096573	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
					Cut out seized bolts, removed guard. Measure and drill holes in new guard, mounted										
T623	Myrtleford - Workshop	Body\MUDGUARDS	REPLACE LH REAR MUD GUARD		with new nuts and bolts.	01/12/2023	1096573	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Elect\INDICATORS	INDICATOR N/W -			01/12/2023	1096573	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
					Remove deck plate, loosen bolster bolts and straightened bent brackets. Moved bolster to be										
T623	Myrtleford - Workshop	Body\BOLSTER	STRAIGHTEN BOLSTER		straight. Tensioned bolster brackets. Refit deck plates	01/12/2023	1096573	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
					Removed the binder bolts and prepped crack to weld. welded crack, primed and painted										
T623	Myrtleford - Workshop	Chassis\STRAPS	WELD BINDER BRACKET		surface. Position binder in place & fit new bolts. secured	01/12/2023	1096573	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Tyres\TP3+4	Tyre Position 3 + 4			30/11/2023		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	Albury Workshop	TRAILER
T623	Myrtleford - Workshop	Tyres\TP11+12	replace tyres			22/11/2023	69555	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	Myrtleford Workshop	TRAILER
					Found quick release wire broken. Remove the										
					broken section of wire and run new quick release wire. Crimped onto the quick release & crimped										
T623	Myrtleford - Workshop	Body\STRAPS	QUICK RELEASE WIRE BROKEN ON A-TRAILER		handle.	11/11/2023	1103202	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
					Removed damaged guard and measured holes. Drilled new										
T623	Myrtleford - Workshop	Body\MUDGUARDS	LF FRONT MUDGUARD REPLACING		holes & installed new guard.	11/11/2023	1103202	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			11/11/2023	1064634	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist												
T623	Myrtleford - Workshop	VehService\DS	PO# L082165	VehService\DS		11/11/2023	1064634	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Tyres\TP7+8	Tyre Position 7 + 8			08/11/2023		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	Albury Workshop	TRAILER
T623	Myrtleford - Workshop	Tyres\TP7+8	Tyre Position 7 + 8			02/11/2023		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	Albury Workshop	TRAILER
T623	Myrtleford - Workshop	Tyres\ROTATION	3			02/11/2023		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	Albury Workshop	TRAILER
			BROKEN BOLSTER BOLT CONNECTING TO CHASSIS - Applied lube to bolster bolt & removed.												
T623	Myrtleford - Workshop	Chassis\BOLSTER	Installed new bolt. nut & washer. Tensioned to ssec.			28/10/2023	1092443	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	Albury Workshop	TRAILER
			D Service As Per Attached Checklist												
T623	Myrtleford - Workshop	VehService\DS	PO# L081703	VehService\DS		20/10/2023	448531	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			20/10/2023	448531	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Elect\WORK LIGHT	WORK LIGHTS NOT WORKING- KEEPS BLOWING FUSES.done on D service refer invoice 370181. WORK LIGHTS NOT WORKING- KEEPS BLOWING FUSES.			05/10/2023	1055220	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Chassis\BOLSTER	PLS TIGHTEN ALL BOLSTERS. VERY LOOSE.done on D service refer invoice 370181. PLS TIGHTEN ALL BOLSTERS. VERY LOOSE.			05/10/2023	1055220	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			05/10/2023	1055220	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	Wodonga Workshop	TRAILER
T623	Myrtleford - Workshop	Elect\ELECT P&W	CLEARANCE LIGHT NOT WORKING AT TRAILER PASSENGER.			05/10/2023	1055220	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	Wodonga Workshop	TRAILER
T623	Myrtleford - Workshop	Chassis\EXTE TU	AIR TAP LOOSE & LEAKING ON FSRT BINDER.			05/10/2023	1055220	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	Wodonga Workshop	TRAILER
T623	Myrtleford - Workshop	Chassis\BOLSTER	PLS TIGHTEN BOLSTERS. POSTS.			05/10/2023	1055220	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	Wodonga Workshop	TRAILER
T623	Myrtleford - Workshop	Elect\ELECT P&W	BROKEN BLACK WIRES UNDER LAST BOLSTER RACK.			05/10/2023	1055220	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	Wodonga Workshop	TRAILER
T623	Myrtleford - Workshop	Elect\ELECT P&W	LOAD/ WORKING LIGHTS NOT WORKING- WIRING ISSUE.			05/10/2023	1055220	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	Wodonga Workshop	TRAILER
T623	Myrtleford - Workshop	Chassis\BOLSTER	PLS TIGHTEN BOLSTER. POSTS.			05/10/2023	1055220	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	Wodonga Workshop	TRAILER
T623	Myrtleford - Workshop	Susp\AIR LEAK	AIR LEAK MIDDLE TRI DRIVER SIDE UNDER PLATE.THE RIGHT HIGH (RIDE HEIGHT?) VALVE IS CAUSING ALL PROBLEMS.			05/10/2023	1055220	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist												
T623	Myrtleford - Workshop	VehService\DS	Barry Maney PO# L081442	VehService\DS		05/10/2023	1055220	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	Wodonga Workshop	TRAILER
			REPLACE SEIZED BALL RACE - Split trailers, remove turntable top. Unbolt bull race, clean up												
			mounting plate. Install ball race with new bolts, tension all bolts. Fit turntable top with new bushes and												
T623	Myrtleford - Workshop	Chassis\FIFTH WHEE	wear pads. Tension all bolts. grease new bull race and spin. Reconnect trailers. all okav.			23/09/2023	1047072	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	Albury Workshop	TRAILER
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			14/09/2023	1147072	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist												
T623	Myrtleford - Workshop	VehService\DS	Barry Maney PO# L081038	VehService\DS		14/09/2023	1147072	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	Wodonga Workshop	TRAILER
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			25/08/2023	38720	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist												
T623	Myrtleford - Workshop	VehService\DS	Barry Maney PO# L080508	VehService\DS		25/08/2023	38720	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	Wodonga Workshop	TRAILER
					Traced air leak to faulty brake valve in trailer. Disconnect air lines & removed valve. Installed new valve,										
T623	Albury - Workshop	Brakes\AIR LEAK	AIR LEAK SOMEWHERE UNDER OR AROUND BRAKE BOOSTERS. CAN HEAR IT SOMETIMES BUT CAN'T TRACK IT DOWN. LOSES AIR DOWN TO 500KPA SOMETIMES \		connect air lines, tested operation, all okay.	23/08/2023		Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	Albury Workshop	TRAILER
					Received call for binder fault on trailer, travel to yard, truck was not there, wait for trailer to arrive.										
					Found snapped fitting, removed fitting and replaced with new. Refitted binder and check operation,										
T623	Myrtleford - Workshop	Chassis\WINCH/STRP	AFTER HOURS BREAKDOWN - BROKEN BINDER		all okay.	19/08/2023	1134804	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	Albury Workshop	TRAILER
					Inspected trailer, found bracket was broken. Removed damaged bracket. Welded bracket to repair.										
T623	Myrtleford - Workshop	Chassis\BOLSTER	BROKEN BOLSTER BRACKET RH SIDE		Re installed and checked over all brackets for cracks or loose bolts. All ok.	10/08/2023	1130170	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	Albury Workshop	TRAILER
T623	Myrtleford - Workshop	Tyres\Punct	10			09/08/2023		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	Albury Workshop	TRAILER
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			03/08/2023	25697	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist												
T623	Myrtleford - Workshop	VehService\DS	Barry Maney PO# L080035	VehService\DS		03/08/2023	25697	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist												
T623	Wodonga - Workshop	VehService\DS	Barry Maney PO# L079595	VehService\DS		18/07/2023	180152	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	Wodonga Workshop	TRAILER
T623	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			18/07/2023	180152	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	Wodonga Workshop	TRAILER
T623	Myrtleford - Workshop	Elect\TRL LIGHTS	replace blown fuse			13/07/2023	1014374	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	Albury Workshop	TRAILER
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			29/06/2023		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist												
T623	Myrtleford - Workshop	VehService\DS	Barry Maney PO# L079262	VehService\DS		29/06/2023		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	Wodonga Workshop	TRAILER
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			09/06/2023	999395	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist												
T623	Myrtleford - Workshop	VehService\DS	PO# L078844	VehService\DS		09/06/2023	999395	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
			Annual Inspection As Per Checklist												
T623	Myrtleford - Workshop	Insp\ANN INSP	PO# L078848	Insp\ANN INSP		09/06/2023	999395	PreventativeMaintenance	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Tyres\TP9+10	Tyre Position 9 + 10			07/06/2023		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	Albury Workshop	TRAILER
T623	Myrtleford - Workshop	Brakes\AIR LEAK	After Hours Breakdown - repair air leak			26/05/2023	987430	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	Albury Workshop	TRAILER
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			19/05/2023	985168	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist												
T623	Myrtleford - Workshop	VehService\DS	Barry Maney PO# L078443	VehService\DS		19/05/2023	985168	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	Wodonga Workshop	TRAILER
T623	Myrtleford - Workshop	Tyres\TP11+12	Tyre Position 11 + 12			18/05/2023		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	Albury Workshop	TRAILER
T623	Myrtleford - Workshop	Tyres\TP1+2	Tyre Position 1 + 2			18/05/2023		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	Albury Workshop	TRAILER
T623	Myrtleford - Workshop	Tyres\TP03	Tyre Position 3			18/05/2023		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	Albury Workshop	TRAILER
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			27/04/2023	973689	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist												
T623	Myrtleford - Workshop	VehService\DS	Barry Maney PO# L077961	VehService\DS		27/04/2023	973689	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	Wodonga Workshop	TRAILER
T623	Wodonga - Workshop	Chassis\BOLSTER	REMOVED AND CRACK TESTED BOLSTER PINS. FITTED WITH NEW BOLTS.			12/04/2023		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	091935	Wodonga Workshop	TRAILER

				Crack Test Bolster Pins															
				Remove all bolster pins for testing. Found bolts were seized, got undone and refit pins with new numts and bolts.															
				LH1-S test ok. RH1-S test ok															
				LH6 had worn bolt holes, flipped pin top to bottom.															
				RH6 also worn, flipped pin.															
T623	Myrtleford - Workshop	Chassis\BOLSTER	Tensioned all bolts						12/04/2023	967132	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Albury Workshop	TRAILER	
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job						12/04/2023	967132	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Wodonga Workshop	TRAILER	
			D Service As Per Attached Checklist																
T623	Myrtleford - Workshop	VehService\DS	Barrv Manev PO# L077709	VehService\DS					12/04/2023	967132	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Wodonga Workshop	TRAILER	
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job						21/03/2023	956532	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	BARRY MANEY - 3	TRAILER	
			D Service As Per Attached Checklist																
T623	Myrtleford - Workshop	VehService\DS	PO# L077277	VehService\DS					21/03/2023	956532	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	BARRY MANEY - 3	TRAILER	
T623	Myrtleford - Workshop	Body\MUDGUARDS	BACK R/H GUARD, BOLT IS BROKEN ON BACK.						07/03/2023		Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Myrtleford Workshop	TRAILER	
T623	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job						01/03/2023	947772	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Wodonga Workshop	TRAILER	
			D Service As Per Attached Checklist																
T623	Wodonga - Workshop	VehService\DS	Barry Maney PO# L076998	VehService\DS					01/03/2023	947772	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Wodonga Workshop	TRAILER	
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job						10/02/2023	937402	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	BARRY MANEY - 3	TRAILER	
			D Service As Per Attached Checklist																
T623	Myrtleford - Workshop	VehService\DS	PO# L076510	VehService\DS					10/02/2023	937402	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	BARRY MANEY - 3	TRAILER	
T623	Myrtleford - Workshop	Brakes\BRK RELINE	RELINE RF.						10/02/2023	937402	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	BARRY MANEY - 3	TRAILER	
			Breakdown - brakes locked on																
T623	Myrtleford - Workshop	Brakes\AIR FITTIN	Travelled to trailer, inspect for concern. Found airline rubbed. Cut out section and rejoined. No further leaks						03/02/2023	932875	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Albury Workshop	TRAILER	
			Air bag leaking																
			support chassis and release air. Removed bolts and airlines. Removed leaking RH rear airbag. Installed new air bag, connect fittings and tighten mounting bolts,																
T623	Myrtleford - Workshop	Susp\AIR BAG	lftsl airbaes . removed chassis supoort. checked. no further leaks						02/02/2023	932135	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Albury Workshop	TRAILER	
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job						25/01/2023	928774	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Albury Workshop	TRAILER	
			D Service As Per Attached Checklist																
T623	Myrtleford - Workshop	VehService\DS	PO # L076282	VehService\DS					25/01/2023	928774	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Albury Workshop	TRAILER	
T623	Myrtleford - Workshop	Brakes\BACK PLATE	inspect trailer for noise with trailer rolling, move into workshop remove backing plate and check for foreign objects in brake assembly, ok refit backing pplate						20/01/2023	926459	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Albury Workshop	TRAILER	
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job						16/12/2022	916364	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Wodonga Workshop	TRAILER	
T623	Myrtleford - Workshop	Chassis\WINCH/STRP	WINCH CONTROL BOX ON SIDE OF TRAILER MISSING HINGE.						16/12/2022	916364	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Wodonga Workshop	TRAILER	
T623	Myrtleford - Workshop	Chassis\AIR TANKS	SHORT AIR TANK ON DRIVER SIDE NOT DRAINING.		UNABLE TO FAULT.				16/12/2022	916364	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Wodonga Workshop	TRAILER	
T623	Myrtleford - Workshop	Elect\ELECT P&W	SCALES PLUG FRONT OF A TRAILER POSSIBLE BROKEN WIRE. SCALES KEEP GOING OFF AND ON.		REPLACED PLUGS.				16/12/2022	916364	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Wodonga Workshop	TRAILER	
T623	Myrtleford - Workshop	Elect\WORK LIGHT	LOAD LIGHTS NOT WORKING.						16/12/2022	916364	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Wodonga Workshop	TRAILER	
			D Service As Per Attached Checklist																
T623	Myrtleford - Workshop	VehService\DS	Barry Maney PO# L075766	VehService\DS					16/12/2022	916364	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Wodonga Workshop	TRAILER	
			Complaint air bags not building up air, go to yard & all tested ok, spoke to JB & he advised to replace ride height valve, Repplaced & sent trailer.																
T623	Myrtleford - Workshop	Susp\AIR BAG	Plaved up aaain next dav bosaht in while not workine found dump valve bv oassine air intermittnalv. removed valve & tested ok						13/12/2022	913947	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Albury Workshop	TRAILER	
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job						30/11/2022	908081	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Wodonga Workshop	TRAILER	
T623	Myrtleford - Workshop	Chassis\WINCH/STRP	WINCH CONTROL BOX ON SIDE OF TRAILER MISSING HINGE.						30/11/2022	908081	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Wodonga Workshop	TRAILER	
T623	Myrtleford - Workshop	Chassis\AIR TANKS	SHORT AIR TANK ON DRIVER SIDE NOT DRAINING.						30/11/2022	908081	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Wodonga Workshop	TRAILER	
T623	Myrtleford - Workshop	Elect\WORK LIGHT	Work Lights not working.						30/11/2022	908081	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Wodonga Workshop	TRAILER	
T623	Myrtleford - Workshop	Elect\ELECT P&W	SCALES PLUG FRONT OF A TRAILER POSSIBLE BROKEN WIRE. SCALES KEEP GOING OFF AND ON.						30/11/2022	908081	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Wodonga Workshop	TRAILER	
			D Service As Per Attached Checklist																
T623	Myrtleford - Workshop	VehService\DS	Barrv Manev PO# L075391	VehService\DS					30/11/2022	908081	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Wodonga Workshop	TRAILER	
T623	Myrtleford - Workshop	Tyres\TP9+10	Tyre Position 9 + 10						30/11/2022		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Albury Workshop	TRAILER	
T623	Myrtleford - Workshop	Tyres\TP11+12	Tyre Position 11 + 12						30/11/2022		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Albury Workshop	TRAILER	
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job						11/11/2022	896971	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Wodonga Workshop	TRAILER	
T623	Myrtleford - Workshop	Chassis\WINCH/STRP	WINCH CONTROL BOX ON SIDE OF TRAILER MISSING HINGE.						11/11/2022	896971	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Wodonga Workshop	TRAILER	
T623	Myrtleford - Workshop	Chassis\AIR TANKS	SHORT AIR TANK ON DRIVER SIDE NOT DRAINING.						11/11/2022	896971	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Wodonga Workshop	TRAILER	
			D Service As Per Attached Checklist																
T623	Myrtleford - Workshop	VehService\DS	Barrv Manev PO# L075063	VehService\DS					11/11/2022	896971	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Wodonga Workshop	TRAILER	
T623	Myrtleford - Workshop	Elect\ELECT P&W	Replace damaged trailer plug						05/11/2022		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Myrtleford Workshop	TRAILER	
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job						27/10/2022		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Wodonga Workshop	TRAILER	
T623	Myrtleford - Workshop	Chassis\WINCH/STRP	WINCH CONTROL BOX ON SIDE OF TRAILER MISSING HINGE.						27/10/2022		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Wodonga Workshop	TRAILER	
T623	Myrtleford - Workshop	Chassis\AIR TANKS	SHORT AIR TANK ON DRIVER SIDE NOT DRAINING.						27/10/2022		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Wodonga Workshop	TRAILER	
			D Service As Per Attached Checklist																
T623	Myrtleford - Workshop	VehService\DS	Barrv Manev PO# L074759	VehService\DS					27/10/2022		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Wodonga Workshop	TRAILER	
			Scales lead broken off at female screw in plug.																
			Replaced and soldered in.																
T623	Myrtleford - Workshop	Elect\ELECT P&W	Barry Maney PO# L074775						22/10/2022		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Wodonga Workshop	TRAILER	
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job						05/10/2022	877973	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Wodonga Workshop	TRAILER	
T623	Myrtleford - Workshop	Chassis\WINCH/STRP	WINCH CONTROL BOX ON SIDE OF TRAILER MISSING HINGE.						05/10/2022	877973	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Wodonga Workshop	TRAILER	
T623	Myrtleford - Workshop	Elect\ELECT P&W	R/H REAR CLEARANCE LIGHT NOT WORKING. (ALL OTHER LIGHT ON TRAILER WORKING)						05/10/2022	877973	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Wodonga Workshop	TRAILER	
T623	Myrtleford - Workshop	Chassis\AIR TANKS	SHORT AIR TANK ON DRIVER SIDE NOT DRAINING.						05/10/2022	877973	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Wodonga Workshop	TRAILER	
			D Service As Per Attached Checklist																
T623	Myrtleford - Workshop	VehService\DS	Barry Maney PO# L074428	VehService\DS					05/10/2022	877973	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Wodonga Workshop	TRAILER	
T623	Myrtleford - Workshop	Tyres\Re-Tor	Re-Torque						21/09/2022		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Myrtleford Workshop	TRAILER	
			air bags not pumping up																
			Checked air bags and ride height valve. Height valve																
			secure, checked operation of dump valve, all okay. could																
T623	Myrtleford - Workshop	Susp\HCV	not fault - NO CHARGE						15/09/2022		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	BARRY MANEY - 3	TRAILER	
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job						13/09/2022	869708	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Wodonga Workshop	TRAILER	
T623	Myrtleford - Workshop	Chassis\WINCH/STRP	WINCH CONTROL BOX ON SIDE OF TRAILER MISSING HINGE.						13/09/2022	869708	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Wodonga Workshop	TRAILER	
			D Service As Per Attached Checklist																
T623	Myrtleford - Workshop	VehService\DS	Barrv Manev PO# L074000	VehService\DS					13/09/2022	869708	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Wodonga Workshop	TRAILER	
T623	Myrtleford - Workshop	Tyres\TP1+2	Tyre Position 1 + 2						20/08/2022		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Myrtleford Workshop	TRAILER	
T623	Myrtleford - Workshop	Tyres\TP7+8	Tyre Position 7 + 8						20/08/2022		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Myrtleford Workshop	TRAILER	
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job						18/08/2022	856285	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Wodonga Workshop	TRAILER	
			D Service As Per Attached Checklist																
T623	Myrtleford - Workshop	VehService\DS	Barrv Manev PO# L073520	VehService\DS					18/08/2022	856285	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Wodonga Workshop	TRAILER	
T623	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job						03/08/2022		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Wodonga Workshop	TRAILER	
T623	Wodonga - Workshop	Body\MUDGUARDS	MUDGUARDS NEED REPLACING DUE TO FAILED HEIGHT VALVE. REAR DRIVER'S SIDE NOT ATTACHED TO BOLTS.						03/08/2022		Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Wodonga Workshop	TRAILER	
T623	Wodonga - Workshop	Body							03/08/2022		Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Wodonga Workshop	TRAILER	
			D Service As Per Attached Checklist																
T623	Wodonga - Workshop	VehService\DS	Barry Maney PO# L073285	VehService\DS					03/08/2022		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Wodonga Workshop	TRAILER	
			Air Bags wont pump up.		Call out 3.30am 224kms														
T623	Myrtleford - Workshop	Chassis\BREAKDOWN	Barrv Manev Called out.		Travel tobreakdown as no one closer would take call. Replace heiaht valve				20/07/2022		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Wodonga Workshop	TRAILER	
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job						19/07/2022	836689	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Wodonga Workshop	TRAILER	
T623	Myrtleford - Workshop	Brakes\BRAKE ADJ	Adjust brakes						19/07/2022	836689	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Wodonga Workshop	TRAILER	
			D Service As Per Attached Checklist																
T623	Myrtleford - Workshop	VehService\DS	Barry Maney PO# L072977	VehService\DS					19/07/2022	836689	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Wodonga Workshop	TRAILER	
T623	Myrtleford - Workshop	Tyres\TP5+6	supply and fit 2tyres						14/07/2022		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Myrtleford Workshop	TRAILER	
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job						28/06/2022	825742	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Wodonga Workshop	TRAILER	
			D Service As Per Attached Checklist																
T623	Myrtleford - Workshop	VehService\DS	Barry Maney PO# L072616	VehService\DS					28/06/2022	825742	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Wodonga Workshop	TRAILER	
T623	Myrtleford - Workshop	Elect\ELECT P&W	Blowing fuses when reversing, have been chasing issue for over 1 month we fitted fuses between each trailer to see which was blowing, was trailer A, split wiring						21/06/2022	825742	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Myrtleford Workshop	TRAILER	
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job						09/06/2022	815255	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Wodonga Workshop	TRAILER	
T623	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP					09/06/2022	815255	PreventativeMaintenance	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Wodonga Workshop	TRAILER	
T623	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS					09/06/2022	815255	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Wodonga Workshop	TRAILER	
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job						09/06/2022	815255	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Wodonga Workshop	TRAILER	
			D Service As Per Attached Checklist																
T623	Myrtleford - Workshop	VehService\DS	Barry Maney PO# L072323	VehService\DS					09/06/2022	815255	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Wodonga Workshop	TRAILER	
T623	Myrtleford - Workshop	Tyres\TP9+10	supply and fit 2tyres						28/05/2022		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Myrtleford Workshop	TRAILER	
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job						24/05/2022	805650	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Wodonga Workshop	TRAILER	
			D Service As Per Attached Checklist																
T623	Myrtleford - Workshop	VehService\DS	Barry Maney PO# L071929	VehService\DS					24/05/2022	805650	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Wodonga Workshop	TRAILER	
T623	Myrtleford - Workshop	Tyres\TP07	fit runout						19/05/2022		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Myrtleford Workshop	TRAILER	
T623	Myrtleford - Workshop	Tyres\TP3+4	supply and fit 2tyres						03/05/2022		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Myrtleford Workshop	TRAILER	
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job						30/04/2022	792804	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Wodonga Workshop	TRAILER	
			D Service As Per Attached Checklist																
T623	Myrtleford - Workshop	VehService\DS	Barrv Manev PO# L071556	VehService\DS					30/04/2022	792804	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Wodonga Workshop	TRAILER	
T623	Myrtleford - Workshop	Susp\AIR BAG	Air bag line leaking, straighten ride height rod						28/04/2022		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Myrtleford Workshop	TRAILER	
T623	Myrtleford - Workshop	Tyres\TP1+2	fit runouts						15/04/2022		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Myrtleford Workshop	TRAILER	
T623	Myrtleford - Workshop	Tyres\TP03	Tyre Position 3						15/04/2022		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Myrtleford Workshop	TRAILER	
T623	Myrtleford - Workshop	Chassis\WINCH/STRP	Repair Winch						15/04/2022		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Myrtleford Workshop	TRAILER	
			D Service As Per Attached Checklist																
T623	Myrtleford - Workshop	VehService\DS	Barry Maney PO# L071233	VehService\DS					11/04/2022	448531	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Wodonga Workshop	TRAILER	
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job						11/04/2022	448531	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Wodonga Workshop	TRAILER	
T623	Myrtleford - Workshop	Tyres\TP11+12	supply and fit 2tyres						08/04/2022		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Myrtleford Workshop	TRAILER	
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job						25/03/2022	773170	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Wodonga Workshop	TRAILER	
			D Service As Per Attached Checklist																
T623	Myrtleford - Workshop	VehService\DS	PO # L070891	VehService\DS					25/03/2022	773170	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Wodonga Workshop	TRAILER	
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job						10/03/2022	763102	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Wodonga Workshop	TRAILER	
			D Service As Per Attached Checklist																
T623	Myrtleford - Workshop	VehService\DS	Barrv Manev PO# L070606	VehService\DS					10/03/2022	763102	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Wodonga Workshop	TRAILER	
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job						23/02/2022	753670	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Wodonga Workshop	TRAILER	
			D Service As Per Attached Checklist																
T623	Myrtleford - Workshop	VehService\DS	PO # L070311	VehService\DS					23/02/2022	753670	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Wodonga Workshop	TRAILER	
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job						03/02/2022	743760	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Wodonga Workshop	TRAILER	
			D Service As Per Attached Checklist																
T623	Myrtleford - Workshop	VehService\DS	PO # L069937	VehService\DS					03/02/2022	743760	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Wodonga Workshop	TRAILER	
T623	Myrtleford - Workshop	Tyres\TP3+4	fit 2 runouts						19/01/2022		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	Myrtleford Workshop	TRAILER	
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job						14/01/2022	731346	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	09193S	BARRY MANEY - 3	TRAILER	

			D Service As Per Attached Checklist O/N L12876		Checked springs for broken leaves and centre bolts Checked tension of spring U bolts and tighten where necessary Jacked up axles and checked wheel bearing movement and adjust Checked all rockers,rocker bushes and rocker bolts Checked all radius rod and bushes for wear Checked main frame for cracks Checked skid plate bolts Checked king pin for wear and tightness of bolts Checked all air tanks and mountings Checked all brake hoses for chaffing and replace if necessary Checked all brake camshafts and bushes for wear Greased all lube points Adjusted all brakes and check booster mounting nuts Checked and repair all lights Checked and repair mudguards and flaps Checked wheel nuts and replace as required										
T623	Myrtleford - Workshop	VehService\DS	Completed trailer service per Greenfreight check list.	VehService\DS	Checked for air leaks	14/01/2022	731346	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Body\DAMAGE	RHR GUARD DAMAGED, RIDE HEIGHT ROD OFF. REPLACE GUARD			11/01/2022	722438	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	Myrtleford Workshop	TRAILER
T623	Woodonga - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist			15/12/2021	722438	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	BARRY MANEY - 3	TRAILER
T623	Woodonga - Workshop	VehService\DS	O/N L12784	VehService\DS		15/12/2021	722438	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Tyres\TP1+2	fit 2 runouts			10/12/2021	719866	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist			03/12/2021	716298	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	VehService\DS	O/N L 12725 air valve on trailer need replacing	VehService\DS		03/12/2021	716298	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Body\AIR LEAK	fit new tao		fit tao to front winch	25/11/2021	235433	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Tyres\TP12	puncture repair			25/11/2021		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist			18/11/2021	708298	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	VehService\DS	O/N L12630	VehService\DS		18/11/2021	708298	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Body\MUDGUARDS	replace mudguards and brackets and straighten and weld bracket supports, new mudflap			09/11/2021	702714	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Chassis\WINCH/STRP	fitted new top to binder			09/11/2021	702714	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Tyres\TP7+8	supply and fit 2 tyres			07/11/2021	702593	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist			05/11/2021	698080	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	VehService\DS	O/N L12533	VehService\DS		05/11/2021	698080	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist		trailer service grease/adjust	28/10/2021	698080	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	VehService\DS	O/N L12464	VehService\DS	check chassis	28/10/2021	698080	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Elect\TRL LIGHTS	lights go out after 1st bolster, start flickering and go out			23/10/2021		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist			19/10/2021	691769	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	VehService\DS	O/N L12417	VehService\DS		19/10/2021	691769	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Tyres\TP9+10	supply and fit 2 tyres			15/10/2021	691509	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	Myrtleford Workshop	TRAILER
T623	Woodonga - Workshop	Susp\WIGHT GAUGE	FITTED PLUMBING TO SCALES TRANSDUCER			05/10/2021		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	Woodonga Workshop	TRAILER
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist			01/10/2021	687256	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	VehService\DS	O/N L12334	VehService\DS		01/10/2021	687256	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Susp\DAMAGE	LH middle axle pivot bush			30/09/2021	685508	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Susp\SUSPENSION	top shocker bush's RH side			30/09/2021	685508	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Elect\ELECT P&W	lift up axle n/w			30/09/2021	685508	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Chassis\FIFTH WHEE	turntable ball race			30/09/2021	685508	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist			15/09/2021	685508	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	VehService\DS	O/N L12236	VehService\DS		15/09/2021	685508	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist			06/08/2021	675196	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	VehService\DS	ORDER # L12018	VehService\DS		06/08/2021	675196	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist			29/06/2021	669984	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	VehService\DS	O/N L11745	VehService\DS		29/06/2021	669984	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Tyres\TP1+2	Supply and fit 2 tyres Annual Inspection As Per Checklist			11/06/2021	661086	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Insp\ANN INSP	ORDER # L11606	Insp\ANN INSP		05/06/2021	659513	PreventativeMaintenance	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist			05/06/2021	659513	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	VehService\DS	O/N L11603	VehService\DS		05/06/2021	659513	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist			07/05/2021		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	VehService\DS	L11375	VehService\DS		07/05/2021		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Tyres\TP11+12	Supply and fit 2 tyres			29/04/2021	646574	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist			14/04/2021	638884	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	VehService\DS	L11187	VehService\DS		14/04/2021	638884	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist			23/03/2021	629024	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	VehService\DS	BARRY MANNEY L11104	VehService\DS		23/03/2021	629024	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist			23/02/2021	618028	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	VehService\DS	L10876	VehService\DS		23/02/2021	618028	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Body\DAMAGE	remove broken key from lock and get key out			19/02/2021	616510	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist			13/01/2021		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	VehService\DS	Order Number L10541	VehService\DS		13/01/2021		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist			01/12/2020	597655	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	VehService\DS	Order number L10265	VehService\DS		01/12/2020	597655	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Insp\RWC COMP	prepare area, grind out vee and reweld crack, prime and paint to clear defect			19/11/2020	593982	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Body\AIR LEAK	repair leak main feed hose fitted joiner			12/11/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist			10/11/2020	588613	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	VehService\DS	ORDER # L10118	VehService\DS		10/11/2020	588613	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist			22/10/2020	578674	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	VehService\DS	Order Number L9974	VehService\DS		22/10/2020	578674	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Chassis\WINCH/STRP	replace air tap on binder			22/10/2020	575997	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Chassis\BOLSTER	replaced missing bolt in bolster extender frame pivot			22/10/2020	575997	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist			01/10/2020	566748	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	VehService\DS	Order Number L9825	VehService\DS		01/10/2020	566748	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist			15/09/2020	557684	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	VehService\DS	ORDER # L9676	VehService\DS		15/09/2020	557684	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist			26/08/2020	545053	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	VehService\DS	Order Number # L9476	VehService\DS		26/08/2020	545053	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist			06/08/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	VehService\DS	Order number # L9281	VehService\DS		06/08/2020		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice			23/07/2020	528867	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice			23/07/2020	528867	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Tyres\SCRAP TYRE	Job Added From Invoice			23/07/2020	528867	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Tyres\Punct	Job Added From Invoice			23/07/2020	527203	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist			16/07/2020	526570	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	VehService\DS	Order Number # L9111	VehService\DS		16/07/2020	526570	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Body\MOUNTS	repair water tank mount and tap and tighten up loose mudguard broken on both sides			03/07/2020	520671	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist			17/06/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	VehService\DS	Order Number # L8845	VehService\DS		17/06/2020		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Susp\AIR BAG	replaced leaking airbag middle LH airbag			16/06/2020	514087	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist			22/05/2020	505614	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	VehService\DS	Order # L8628	VehService\DS		22/05/2020	505614	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist			07/05/2020	437745	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	VehService\DS	ORDER # L8493	VehService\DS		07/05/2020	437745	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	BARRY MANEY - 3	TRAILER
T623	Myrtleford - Workshop	Body\PAINT/REST	wash trailers			24/04/2020	487473	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Insp\ANN INSP	Annual inspection As Per Checklist	Insp\ANN INSP		23/04/2020	487473	PreventativeMaintenance	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		replaced mudguard replaced 2x mudflaps moved bolster	23/04/2020	487473	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	tidy up light wiring	23/04/2020	487473	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Insp\RWC COMP	Engineer & test EBS System			07/04/2020	487469	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	JASON UNDERWOOD DESIGN - 4	TRAILER
T623	Myrtleford - Workshop	Chassis\WINCH/STRP	Fit Dinnema rope and chain to 3 winches			21/03/2020	487468	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			20/03/2020	487468	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		20/03/2020	487468	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Elect\ELECT P&W	Fit Elphinstone Scales18404			04/03/2020	487468	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Brakes\BRK RELINE	Crack test and reline all wheels			22/02/2020	487468	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Susp\AXLES	Replace axle lift stopper			14/11/2019	487470	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			13/11/2019	487467	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	fit lift axle solenoids L8192 remove all chassis covers to fit EBS	13/11/2019	487467	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Brakes\EBS Kit	Fit EBS		move bolsters	13/11/2019	487468	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Body\MUDGUARDS	fit RHM mudguard			31/08/2019	487465	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	09193S	Myrtleford Workshop	TRAILER

T623	Myrtleford - Workshop	Brakes\AIR LEAK	repair brake service hose			30/08/2019	487464	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			28/08/2019	487462	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		28/08/2019	487462	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Elect\ELECT P&W	repair scales not reading			09/08/2019	481207	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Susp\AIR BAG	repair airbag all folded up on bells			09/08/2019	481207	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			02/08/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	MAHONYS TRANSPORT SERVICES -3	TRAILER
			D Service As Per Attached Checklist													
T623	Myrtleford - Workshop	VehService\DS	Order # L6785	VehService\DS		02/08/2019		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	MAHONYS TRANSPORT SERVICES -3	TRAILER
T623	Myrtleford - Workshop	Chassis\WINCH/STRP	winder replaced on air binder			31/07/2019	478250	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			05/07/2019	470198	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	MAHONYS TRANSPORT SERVICES -3	TRAILER
			D Service As Per Attached Checklist		replaced x1 mudflap											
T623	Myrtleford - Workshop	VehService\DS	Order # L6591	VehService\DS	adjusted brakes	05/07/2019	470198	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	MAHONYS TRANSPORT SERVICES -3	TRAILER
					complete service											
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		reolace LHR mudguard	08/06/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	MAHONYS TRANSPORT SERVICES -3	TRAILER
			D Service As Per Attached Checklist													
T623	Myrtleford - Workshop	VehService\DS	Order # L6571	VehService\DS		08/06/2019		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	MAHONYS TRANSPORT SERVICES -3	TRAILER
T623	Albury - Workshop	Susp\AXLES	replaced lift axle bump stops			26/05/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Albury Workshop	TRAILER
T623	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			26/05/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Albury Workshop	TRAILER
T623	Albury - Workshop	VehService\DS	D Service	VehService\DS		26/05/2019		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Albury Workshop	TRAILER
T623	Albury - Workshop	Workshop\CLEAN	unhook 969 from T391. hook up to T623/T624			26/05/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Albury Workshop	TRAILER
T623	Albury - Workshop	Elect\ELECT P&W	more extension hoses and loom to suit			26/05/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Albury Workshop	TRAILER
T623	Albury - Workshop	Chassis\HOUSEKEEP	fabricate and fit holding points for trailer lines			26/05/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Albury Workshop	TRAILER
T623	Albury - Workshop	Susp\SUSPENSION	REPLACE BROKEN LOWER SADDLES		REPLACED BY HTT	19/05/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Albury Workshop	TRAILER
T623	Albury - Workshop	Susp\WHEEL ALIGN	WHEEL ALIGN			19/05/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Albury Workshop	TRAILER
T623	Albury - Workshop	Body\AIR BAG	replaced lift axle airbag			18/05/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Albury Workshop	TRAILER
T623	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			18/05/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Albury Workshop	TRAILER
T623	Albury - Workshop	VehService\DS	D Service	VehService\DS		18/05/2019		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Albury Workshop	TRAILER
T623	Albury - Workshop	Chassis\SUSPENSION	check-over and note suspension failures for Hume TT			18/05/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Albury Workshop	TRAILER
T623	Albury - Workshop	Workshop\MOVE ASSET	unhook and deliver, pick up, hook up			18/05/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Albury Workshop	TRAILER
T623	Albury - Workshop	Susp\SUSPENSION	LR, LM bottom suspension plates cracked			09/05/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Albury Workshop	TRAILER
T623	Albury - Workshop	Body\FIFTH WHEE	turntable jaws remote grease line broken			09/05/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Albury Workshop	TRAILER
T623	Albury - Workshop	Susp\WHEEL ALGN	requires wheel alignment			09/05/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Albury Workshop	TRAILER
T623	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			09/05/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Albury Workshop	TRAILER
T623	Albury - Workshop	VehService\DS	D Service	VehService\DS		09/05/2019		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Albury Workshop	TRAILER
T623	Albury - Workshop	Susp\AIR BAG	RF airbag			02/05/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Albury Workshop	TRAILER
T623	Albury - Workshop	Susp\SUSPENSION	lift axle springs (nuts?)			02/05/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Albury Workshop	TRAILER
T623	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			02/05/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Albury Workshop	TRAILER
T623	Albury - Workshop	VehService\DS	D Service	VehService\DS		02/05/2019		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Albury Workshop	TRAILER
T623	Albury - Workshop	DrCabElect\SCALES	calibrate scales			16/04/2019		Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Albury Workshop	TRAILER
T623	Albury - Workshop	VehService\DS	Service	VehService\DS		16/04/2019		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Albury Workshop	TRAILER
T623	Myrtleford - Workshop	Chassis\WINCH/STRP	lower quick release latches on T623			27/03/2019	423179	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			27/03/2019	423179	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		27/03/2019	423179	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Susp\HOUSEKEEP	Replace lift axle stopper			14/03/2019	415088	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			13/03/2019	413009	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		13/03/2019	413009	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Brakes\BRAKE ADJ	brake adjust			09/03/2019	410229	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Body\MUDGUARDS	Replace LHR Mudguard			01/03/2019	404211	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			28/02/2019	401531	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		28/02/2019	401531	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Body\MUDGUARDS	adjust guards - to tow			21/02/2019		Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			19/02/2019	392609	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		19/02/2019	392609	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Susp\SUSPENSION	Replace LHF lower shocker mount		fit axle lift stopper and springs	06/02/2019	382939	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		06/02/2019	382249	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			06/02/2019	382249	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Susp\SUSPENSION	LH front axle lower shock mount broken			05/02/2019	380871	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Elect\ELECT P&W	power faulty to scales (intermittant)			05/02/2019	380871	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Brakes\BRAKE ADJ	adjust brakes			01/02/2019		Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Elect\WORK LIGHT	no rev/work light on rear not working			25/01/2019		Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Body\AIR FITTIN	check winch air lines			15/01/2019	367743	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Body\AIR FITTIN	make up air tank drain cable			15/01/2019	367743	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Chassis\FIFTH WHEE	remove block for template - Rinlatech and refit			12/01/2019	366359	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Chassis\FIFTH WHEE	Tsable top block			12/01/2019	366359	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Elect\WORK LIGHT	fit new LED work light RHS			12/01/2019	366359	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Body\WHL HUB	tension trailer wheel nuts			12/01/2019	366359	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Chassis\FIFTH WHEE	fit turntable block and new bolts			10/01/2019	366195	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Insp\ANN INSP	Roadworthy Check on trailer			10/01/2019	366358	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Body\PAINT/REST	wash trailers			09/01/2019	366145	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Body\PAINT/REST	acid wash wheels			09/01/2019	366145	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Chassis\WINCH/STRP	move position of winch handles			04/01/2019	366194	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Chassis\WINCH/STRP	replace winch tap			04/01/2019	366194	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Body\AIR LEAK	check for air leaks			04/01/2019	366194	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Chassis\CHAS CRACK	Chassis ross member repair			11/12/2018	366188	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Chassis\WINCH/STRP	Replace air winch tap			11/12/2018	366188	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Chassis\CROSS MBR	Repair chassis cross member brace			11/12/2018	366188	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Susp\SUSPENSION	Replace spring wraps & stopper			11/12/2018	366188	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Tyres	Replace tyres as needed			11/12/2018	366188	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Susp\HOUSEKEEP	Replace axle lift pivot bushes			11/12/2018	366188	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Body\MUDGUARDS	Replace RHM mudguard			11/12/2018	366188	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Body\FIFTH WHEE	Hook up Traiker			11/12/2018	366188	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Elect\TRL LIGHTS	Check lights			11/12/2018	366188	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Myrtleford Workshop	TRAILER
T623	Myrtleford - Workshop	Insp\ANN INSP	Roadworthy inspection			11/12/2018	366188	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	091935	Myrtleford Workshop	TRAILER