EquipmentName	Workshop	CodeAndSubCode	Description	Schedule	CompletionComments	DateDone	DistanceDone	Worktype	WorkState	EquipmentOwner	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
T624	Mt Gambier - Mt Gambier	Elect\TRL LIGHTS	Elect\TRL LIGHTS			15/10/2026	460209	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454459	FERGUSONS DIESEL SERVICES	TRAILER
T624	Mt Gambier - Mt Gambier	VehService\DS	VehService\DS D Service	VehService\DS		25/09/2026	460209	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454459	HALLORAN DIESEL - 3	TRAILER
T624	Myrtleford - Workshop	Chassis\CONSUMABLE	Replace damaged rear fog signs		Removed damaged/faded fog signs and replaced with new units	11/09/2026	460209	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454459	HALLORAN DIESEL - 3	TRAILER
T624	Myrtleford - Workshop	Chassis\CHAS CRACK	Repair cracked chassis (cross brace (middle axle), near rear mudguard mounts and near LH load binder hook)		- Reairied chassis crack. LHS	11/09/2026	460209	Fault	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	0454459	HALLORAN DIESEL - 3	TRAILER
T624	Myrtleford - Workshop	Brakes\BOOSTER	Replace missing RHM cage bolt		Installed new RHM cage bolt	11/09/2026	460209	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454459	HALLORAN DIESEL - 3	TRAILER
T624	Mt Gambier - Mt Gambier	VehService\DS	VehService\DS D Service	VehService\DS	Check over and tensioned all bolster bolts as required	29/08/2026	460209	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454459	BARRY MANEY - 3	TRAILER
T624	Mt Gambier - Mt Gambier	Body\MUDGUARDS	broken guard bracket and guard accident with light pole			24/08/2026	460209	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454459	BARRY MANEY - 3	TRAILER
T624	Myrtleford - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		13/08/2026	455992	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454459	HALLORAN DIESEL - 3	TRAILER
T624	Myrtleford - Workshop	Elect\TAIL LIGHT	CLEARENCE LIGHTS BOTH SIDES ON REAR BOLSTER NOT WORKING		Repaired rear light wiring, tested, ok	06/08/2026	360644	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454459	HALLORAN DIESEL - 3	TRAILER
T624	Myrtleford - Workshop	Body\AIR LEAK	AIR LEAK AROUND AXELS		Tightened loose hose clamps around axles	06/08/2026	360644	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454459	HALLORAN DIESEL - 3	TRAILER
T624	Myrtleford - Workshop	Susp\AIR BAG	MULTIPUL CRACKS ON AIRBAG MOUNTS		- Welded cracked rear airbag mount- Noted RHR airbag starting to leak	06/08/2026	360644	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454459	HALLORAN DIESEL - 3	TRAILER
T624	Myrtleford - Workshop	Chassis\MUDGUARDS	CRACKS IN MUD GUARD MOUNTS		Welded cracked mudguard bracket- Tightened loose mudguard bolts	06/08/2026	360644	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454459	HALLORAN DIESEL - 3	TRAILER
					Inspect trailer for air leak, found to have rubbed section of air line. Cut out rubbed section and joined in new length of hose. Secure hose to prevent further rubbing.											
T624	Myrtleford - Workshop	Body\AIR LEAK	MIDDLE AXLE AIR LEAKS AND REAR AXLE POSSIBLE AIR BAG		Checked over. no further air leaks.	30/07/2026	360644	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454459	BARRY MANEY - 3	TRAILER
T624	Myrtleford - Workshop	Tyres\TP9+10	Tyres\TP9+10 (29-30)			25/07/2026	360644	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454459	BORDER BANDAG PTY LTD -3	TRAILER
T624	Myrtleford - Workshop	Body\MOUNTS	AIR WINCH - CHASSIS MOUNT CRACKED		Remove winch and mount. Prep area and weld repair. Refit mount and winch. all OK	09/07/2026	360644	Repair	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	0454459	BARRY MANEY - 3	TRAILER
					Inspect and found broken saddle. Remove and replace RH front saddle as required.											
					KW0514525460 PLATE - SPRING AU R/H WELDED 5 1 146.04											
					KW0252207412 NUT - LOCK M24 GRADE 10.9 4 10.60											
T624	Myrtleford - Workshop	Susp\AXLES	FRH AXLE - BROKEN SADDLE		KW0318411194 U BOLT-M24x152x280	09/07/2026	360644	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454459	BARRY MANEY - 3	TRAILER
T624	Myrtleford - Workshop	Body\WHL HUB	ADJUST WHEEL BEARINGS VehService\DS D Service		Jack up all axles, check and adjust wheel bearings to spec.	09/07/2026	360644	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454459	BARRY MANEY - 3	TRAILER
T624	Myrtleford - Workshop	VehService\DS	L134668	VehService\DS		09/07/2026	360644	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454459	BARRY MANEY - 3	TRAILER
T624	Myrtleford - Workshop	Tyres\TP1+2	Tyres\TP1+2 (21-22)			07/07/2026	360644	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454459	BORDER BANDAG PTY LTD -3	TRAILER
					Found rear trailer light bar n/w, inspected wiring loom and found multiple shorts and bare wires. Cut rear light bar loom out and re ran new wiring. Joined in and tested, all okay. Fitted conduit and cable tied up. Found LH rear light n/w, unbolted light and found snapped wire, re joined and tested. all okay.											
T624	Myrtleford - Workshop	Elect\TRL LIGHTS	B TRAILER LIGHTS N/W			30/06/2026	360644	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454459	BARRY MANEY - 3	TRAILER
					REPAIR BOLSTER LIGHTS, FLICKERING - BROKEN WIRE IN BOLSTER Inspect wiring along chassis and found broken wiring and corrosion. Cut out wiring, strip and repin as required, all okay											
T624	Myrtleford - Workshop	Elect\TRL LIGHTS	rear bolster side clearance lights flicking. wire inside bolster		LH SIDE 3RD BOLSTER FROM REAR NEEDS BOLT REPLACED	11/06/2026	360644	Fault	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	0454459	BARRY MANEY - 3	TRAILER
					Found on service bolster needs new bolster bolt. Fit new											
T624	Myrtleford - Workshop	Chassis\BOLSTER	3RD BOLSTER FROM BACK NEEDS BOLT REPLACED LHS Insp\ANN INSP Annual Inspection As Per Checklist		bolt as required.	11/06/2026	360644	Fault	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	0454459	BARRY MANEY - 3	TRAILER
T624	Myrtleford - Workshop	Insp\ANN INSP	L134214	Insp\ANN INSP		11/06/2026	360644	PreventativeMaint	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	0454459	BARRY MANEY - 3	TRAILER
T624	Myrtleford - Workshop	VehService\DS	VehService\DS D Service L134213	VehService\DS		11/06/2026	360644	Service	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	0454459	BARRY MANEY - 3	TRAILER
T624	Myrtleford - Workshop	Chassis\BOLSTER	Removed bent bolster and replaced with new.		send bent peg to be straightened	15/05/2026	360644	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454459	BARRY MANEY - 3	TRAILER
T624	Myrtleford - Workshop	Tyres\Punct	Tyres\Punct POS 21			13/05/2026	360644	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454459	BORDER BANDAG PTY LTD -3	TRAILER
T624	Myrtleford - Workshop	VehService\DS	VehService\DS D Service L133751	VehService\DS		12/05/2026	360644	Service	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	0454459	BARRY MANEY - 3	TRAILER
T624	Myrtleford - Workshop	Chassis\WINCH/STRP	grease all binders		THIS JOB WOULD HAVE BEEN DONE ON TRAILER D/SERVICES (WD)	14/04/2026	360644	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454459	BARRY MANEY - 3	TRAILER
					Check over for air leaks, found LH middle booster line had a rubbed section. Cut out rubbed section and rejoined.											
T624	Myrtleford - Workshop	Susp\AIR BAG	check air bags, ride height valvle and straps on shockers		Found numerous shocker straps were worn. Carried out on iob	14/04/2026	360644	Fault	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	0454459	BARRY MANEY - 3	TRAILER
					Found all axles, except LH front axle, shocker straps were excessively worn. Removed straps and replaced with new.											
					KWA50001 RETAINER-WEBBING SLING SUIT BPW SHOCKER 1 11.77											
T624	Myrtleford - Workshop	Susp\SHOCK ABS	REPLACE SHOCKER STRAPS VehService\DS D Service		KWA50025/4710 RESTRAINT STRAP-SHOCKER 4710MM - BPW	14/04/2026	360644	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454459	BARRY MANEY - 3	TRAILER
T624	Myrtleford - Workshop	VehService\DS	L133295	VehService\DS		13/04/2026	360644	Service	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	0454459	BARRY MANEY - 3	TRAILER
T624	Myrtleford - Workshop	Tyres\TP5+6	Tyres\TP5+6 (25-26)			10/04/2026	360644	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454459	BORDER BANDAG PTY LTD -3	TRAILER
T624	Myrtleford - Workshop	Steering\WHEEL ALGN	NEED WHEEL ALIGNMNENT			01/04/2026	360644	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454459	BORDER BANDAG PTY LTD -3	TRAILER
T624	Myrtleford - Workshop	Tyres\TP1+2	Tyres\TP1+2 (21-22)			13/03/2026	360644	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454459	BORDER BANDAG PTY LTD -3	TRAILER
T624	Myrtleford - Workshop	Tyres\TP3+4	Tyres\TP3+4 (23-24)			13/03/2026	360644	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454459	BORDER BANDAG PTY LTD -3	TRAILER
					Found susi fitting leaking on front of B trailer remove and replace fittings. Check for leaks all okay.											
					KWABF218 SELF-SEAL CPLING 1/2 F 1 20.84											
T624	Myrtleford - Workshop	Body\AIR LEAK	Replace leaking Susi fittings		KWABF108 NON-SEAL CPLING ADAPTER 1/2 F	11/03/2026	360644	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454459	BARRY MANEY - 3	TRAILER
					Jack axle and check pre-load. Remove hub cap and adjust LH											
T624	Myrtleford - Workshop	Chassis\WHL HUB	CHECK WHEEL BEARINGS LH FRONT		front wheel bearing to spec. Refit hub cab, all OK	27/02/2026	360644	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454459	BARRY MANEY - 3	TRAILER
T624	Myrtleford - Workshop	Susp\SHOCK ABS	LOOSE SHOCKERS		Go over and tighten loose shocker bolts as required, all OK	27/02/2026	360644	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454459	BARRY MANEY - 3	TRAILER
					Carried out trailer service as per Greenfreight checklist.											
					Customer Instructions:											
					Place vehicle on shaker & Inspected											
			VehService\DS D Service		Carried out General Inpection & Checkover											
T624	Myrtleford - Workshop	VehService\DS	L099179	VehService\DS	Greased vehicle	26/02/2026	399507	Service	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	0454459	BARRY MANEY - 3	TRAILER
T624	Myrtleford - Workshop	Brakes\BOOSTER	REPLACE RHR 30/30 BOOSTER			22/01/2026	330644	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454459	BARRY MANEY - 3	TRAILER
					Remove U bolts and pivot bush bolts. Drop spring down and replace RH rear BBQ tong retaining strip as required. Refit and tension U bolts and pivot bush bolts. Check over LH rear pivot bush, all looked ok did not need replacing.											
T624	Myrtleford - Workshop	Susp\SPRING HANG	REPLACE RHR SPRING WRAPER		KW0534830160 RETAINING STRIP	22/01/2026	330644	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454459	BARRY MANEY - 3	TRAILER
					Remove U bolts and pivot bush bolts. Drop spring down and replace RH rear BBQ tong retaining strip as required. Refit and tension U bolts and pivot bush bolts. Check over LH rear pivot bush, all looked ok did not need replacing.											
			REPLACE LH REAR PIVOT BUSH													
T624	Myrtleford - Workshop	Susp\SUSPENSION	REPLACE SPRING WRAPER RH REAR AXLE		KW0534830160 RETAINING STRIP	22/01/2026	330644	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454459	BARRY MANEY - 3	TRAILER
T624	Myrtleford - Workshop	Body\RWC COMP	do not overtake turning vehicle sign missing from rear of trailer VehService\DS D Service		Remove and replace rear 'Do not overtake' sign as required. KWTRP31-A DO NOT OVERTAKE SIGN 331 ALUM 320 X 100M	22/01/2026	330644	Fault	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	0454459	BARRY MANEY - 3	TRAILER
T624	Myrtleford - Workshop	VehService\DS	L098556	VehService\DS		19/01/2026	330644	Service	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	0454459	BARRY MANEY - 3	TRAILER
					REAR AXLE S-CAM BUSHES HAVE MOVEMENT Check RHR s-cam movement, found to be excessive. Jack axle and remove hub. Remove brake and s-cam and replace s-cam as required. Refit all components removed then adjust wheel bearings and brakes, all okay. *s-cam kit from tool room, not charged*											
T624	Myrtleford - Workshop	Brakes\BRAKE ADJ	Rear axle s-cam bushes slight movement - monitor		KW0509705264 C/SHAFT A=547.5MM L=686MM RH LH REAR WHEEL BEARING NEEDS ADJUSTING Jack axle and check wheel bearing adjustment, found movement to be excessive. Remove cap, nut and washer and found washer worn, replace washer then refit nut and cap. Readjust wheel bearing and check all tensions, all okay.	16/12/2025	330644	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454459	BARRY MANEY - 3	TRAILER
T624	Myrtleford - Workshop	DrivLine\WHEEL BRGS	Middle LH wheel bearing movement - adjust next service		KW0332004010 WASHER-STD HUB ECO-BEARING	16/12/2025	330644	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454459	BARRY MANEY - 3	TRAILER
T624	Myrtleford - Workshop	Chassis\WINCH/STRP	STRAPS NEED REPLACING		x2 front binder handles need fixing, Fit new handles and straighten bent ones as reauired. all okay.	16/12/2025	330644	Repair	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	0454459	BARRY MANEY - 3	TRAILER
					Check wiring to LH rear side marker, found no power or earth. Trace wiring back and found broken wire. Use heat shrink joiner to repair then check operation, all working as should. Check work lights not working, check power and earth, all okay. Remove and replace work light then check operation, all working as should.											
T624	Myrtleford - Workshop	Elect\WORK LIGHT	Trailer work lights not working VehService\DS D Service		KW72425 9-33V LED FLOOD W/LAMP 900LM	16/12/2025	330644	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454459	BARRY MANEY - 3	TRAILER
T624	Myrtleford - Workshop	VehService\DS	L098074	VehService\DS		12/12/2025	330644	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454459	BARRY MANEY - 3	TRAILER
					Check wiring to LH rear side marker, found no power or earth. Trace wiring back and found broken wire. Use heat shrink joiner to repair then check operation, all working as should. Check work lights not working, check power and earth, all okay. Remove and replace work light then check											
T624	Myrtleford - Workshop	Elect\TRL LIGHTS	FIX CLEARANCE LIGHTS. BACK LEFT CLEARANCE LIGHT OUT THIS JOB WAS DONE 4/12/25 AT B/M		operation. all workine as should.	09/12/2025	330644	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454459	BARRY MANEY - 3	TRAILER
T624	Myrtleford - Workshop	VehService\DS	VehService\DS D Service L097773	VehService\DS		14/11/2025	330644	Service	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	0454459	BARRY MANEY - 3	TRAILER
					Remove rear axle mudguard mounting bracket. Clean off all surfaces and weld all cracks. Prime and paint surfaces, let											
T624	Myrtleford - Workshop	Chassis\MUDGUARDS	INSPECT CRACKS ON DRIVERS SIDE REAR GUARD MOUNT		paint drv then re-mount euard mounts. all okav	14/11/2025	330644	Fault	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	0454459	BARRY MANEY - 3	TRAILER
					Inspect and found broken power wire. Fit joiner to wire											
T624	Myrtleford - Workshop	Elect\TRL LIGHTS	LAST BOLSTER CLEARANCE LIGHTS FAULTY		then check liaht operation. all workine as should.	14/11/2025	330644	Fault	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	0454459	BARRY MANEY - 3	TRAILER
					WD inspected brakes they are all at 80% and dont require a reline											
T624	Myrtleford - Workshop	Brakes\BRK RELINE	Replace front brakes next service		11/11/25	14/11/2025	330644	Fault	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	0454459	BARRY MANEY - 3	TRAILER
					Remove all components attached to ride height valve, remove valve and fittings. Fit fittings and airlines to new valve and check operation, all working as should.											
T624	Myrtleford - Workshop	Susp\HCV	CHECK/REPLACE RIDE HEIGHT VALVE Steering\WHEEL ALGN		KWT03-1701 VALVE-HCV-BPW BASIC	14/11/2025	330644	Fault	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	0454459	BARRY MANEY - 3	TRAILER
T624	Myrtleford - Workshop	Steering\WHEEL ALGN	L097680			11/11/2025	330644	Repair	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	0454459	BORDER BANDAG PTY LTD -3	TRAILER
T624	Myrtleford - Workshop	Tyres\Punct	Tyres\Punct POS 26			07/11/2025	330644	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454459	BORDER BANDAG PTY LTD -3	TRAILER
T624	Myrtleford - Workshop	Elec\lab	TRACE & REPAIR FAULT IN LOADING LIGHTS VehService\DS D Service			04/11/2025	330644	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454459	JF MECHANICALS - 3	TRAILER
T624	Myrtleford - Workshop	VehService\DS	L097438	VehService\DS		24/10/2025	330644	Service	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	0454459	BARRY MANEY - 3	TRAILER
T624	Myrtleford - Workshop	Tyres\RUN OUT	Tyres\RUN OUT POS 22 & 27			23/10/2025	330644	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454459	BORDER BANDAG PTY LTD -3	TRAILER
T624	Myrtleford - Workshop	Chassis\SCALES	Replace Riteway scale unit. bluetooth not working.			19/10/2025	330644	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454459	BARRY MANEY - 3	TRAILER
T624	Myrtleford - Workshop	Brakes\ABS	REPLACE BROKEN ABS CABLES			19/09/2025	330644	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454459	JF MECHANICALS - 3	TRAILER
T624	Myrtleford - Workshop	Brakes\BRK O/HAUL	FL & FR Brakes need replacing			17/09/2025	330644	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454459	JF MECHANICALS - 3	TRAILER
					CHECK ALL LIGHTS - LHR PARKER OUT Found LHR clearance light faulty. Check wiring and run new wire through bolster. Check operation, all ok											
T624	Myrtleford - Workshop	Elect	Elect/CHECK ALL LIGHTS - LHR PARKER LIGHT OUT		CHECK OVER TRAILER FOR AIR LEAKS	10/09/2025	330644	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454459	BARRY MANEY - 3	TRAILER
					Found rubbed booster hose, cut out rubbed section and joined toaether. Check and found no more leaks. all ok											
T624	Myrtleford - Workshop	Brakes\BOOSTER	Brakes\BOOSTER REPAIR BOOSTER HOSE VehService\DS D Service			10/09/2025	330644	Repair	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	0454459	BARRY MANEY - 3	TRAILER
T624	Myrtleford - Workshop	VehService\DS	L098674	VehService\DS		10/09/2025	330644	Service	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	0454459	BARRY MANEY - 3	TRAILER
T624	Myrtleford - Workshop	Tyres\TP9+10	Tyres\TP9+10 (29-30)			08/09/2025	330644	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454459	BORDER BANDAG PTY LTD -3	TRAILER
T624	Myrtleford - Workshop	Tyres\ROTATION	Tyres\ROTATION POS 25-26			08/09/2025	330644	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454459	BORDER BANDAG PTY LTD -3	TRAILER
					Remove mudguards and brackets on RHS. Found brackets ordered to be incorrect. Clean out old bracket to find part number but unable to find one. Measure bracket then											
T624	Myrtleford - Workshop	Chassis\MUDGUARDS	REPAIR REPLACE R/H GAURD MOUNTS SO ALL LOOK STRAIGHT		reinstall old mudauard and bracket.	18/08/2025	330644	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454459	JF MECHANICALS - 3	TRAILER

						STRAIGHTEN BOLSTERS Work order 200052													
T624	Myrtleford - Workshop	Chassis\BOLSTER	STRAIGHTEN BOLSTERS			Remove chassis brackets from bolster and straighten in press. Refitted brackets and tightened. Second bay bolster needs realacine as it is buckled.	18/08/2025	330644	Repair	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	045459	JF MECHANICALS - 3	TRAILER	
T624	Myrtleford - Workshop	Brakes\SLACK ADJ	ML / MR S-CAMS WORN AT GREASE RUBBER			REPLACE FRONT BRAKES Checked brake % found brakes to still be within spec and not required replacing.	18/08/2025	330644	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	045459	JF MECHANICALS - 3	TRAILER	
						REPLACE BARRELLS WITH ONES SUPPLIED Work order 200052													
			REPLACE ALL BINDER BARRELS FROM CHAIN STYL TO STRAP STYLE			Remove and replace x3 barrells as supplied. Found rear													
T624	Myrtleford - Workshop	Chassis\EXTE TU	SEE SCOTT FOR REPLACEMENT BARRELLS			winch strap was worn, remove and replaced with new.	18/08/2025	330644	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	045459	JF MECHANICALS - 3	TRAILER	
T624	Myrtleford - Workshop	Chassis\CROSS MBR	Middle support crack			CHECK CRACKS - RH AREA, MIDDLE SUPPORT ON BOLSTER Previously repaired	18/08/2025	330644	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	045459	JF MECHANICALS - 3	TRAILER	
T624	Myrtleford - Workshop	Susp\AIR BAG	MIDDLE LEFT AIRBAG BASE CRACKED			CHECK MIDDLE AIR BAG CRACKED - ADVISE Inspect air bae. all okay.	18/08/2025	330644	Fault	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	045459	JF MECHANICALS - 3	TRAILER	
T624	Myrtleford - Workshop	Chassis\SUSPENSION	FRONT R/H CRACKS			CHECK CRACKS - RH AREA, MIDDLE SUPPORT ON BOLSTER Previously repaired	18/08/2025	330644	Fault	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	045459	JF MECHANICALS - 3	TRAILER	
						MIDDLE S-CAMS WORN RHM S-CAM BRACKET BROKEN - INSPECT AND ADVISE													
T624	Myrtleford - Workshop	Brakes\SLACK ADJ	MR s-cam movement and broken bracket broken			Inspect s-cams, all okay. Will continue to monitor when brakes are low.	18/08/2025	330644	Fault	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	045459	JF MECHANICALS - 3	TRAILER	
						GREENFREIGHT SERVICE Carried out trailer service as per Greenfreight checklist. Customer Instructions: Place vehicle on shaker & Inspected Carried out General Inpection & Checkover Greased vehicle TENSION PIVOT BUSHES & U BOLTS Check over and retension pivot bushes & u bolts TENSION BOLSTER BOLTS												
T624	Myrtleford - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		Check over and tensioned all bolster bolts as reouired	11/08/2025	330644	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	045459	BARRY MANEY - 3	TRAILER	
						GREENFREIGHT SERVICE Carried out trailer service as per Greenfreight checklist. Customer Instructions: Place vehicle on shaker & Inspected Carried out General Inpection & Checkover Greased vehicle TENSION PIVOT BUSHES & U BOLTS Check over and retension pivot bushes & u bolt TENSION BOLSTER BOLTS												
T624	Myrtleford - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		Check over and tensioned all bolster bolts as required.	11/08/2025	330644	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	045459	BARRY MANEY - 3	TRAILER	
						CHECK ML WHEEL BEARING MOVEMENT													
T624	Myrtleford - Workshop	DrivLine\WHEEL BRGS	DrivLine\WHEEL BRGS			Jack up axle, remove cap and adjust bearings. Reinstall cap. all ok	08/08/2025	330644	Repair	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	045459	BARRY MANEY - 3	TRAILER	
						REPLACE LH Rear BRAKE SHOE Found LH rear brake was past wear limit. Jacked up axle, undo hub nut and removed wheels and brakes. Found outer s-cam bush was worn and bearings wheel bearings had wear marks. Knock out bearing caps and fit new. Pack new bearings with grease. Cleaned out hub and pack with grease. Remove s-cam and bushes. Cleaned surfaces, fit new s-cam and kit as required. Installed new brakes and refit hub assembly. Adjust bearings and brakes and tensioned wheel nuts.												
T624	Myrtleford - Workshop	Brakes\BRK O/HAUL	Brakes\BRK O/HAUL			RECHECK PIVOT BUSH MOVEMENT LH FRONT Work order 198549	08/08/2025	330644	Repair	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	045459	BARRY MANEY - 3	TRAILER	
T624	Myrtleford - Workshop	Susp\Torque Rod	LH front pivot bush slight movement			Undo all bolts holding in spring, and undo pivot bolt. Removed spring and pushed out bush, then pushed in and install new bush. Tension all bolts to spec. all ok TIGHTEN BOLT BETWEEN 1ST AND 2ND MUD GUARD RH SIDE Work order 198549	08/08/2025	330644	Fault	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	045459	BARRY MANEY - 3	TRAILER	
T624	Myrtleford - Workshop	Body\MUDGUARDS	TIGHTEN BOLT BETWEEN 1ST-2ND MUDGUARD RHS			Tiehten bolts between 1st and 2nd euards on both sides	08/08/2025	330644	Fault	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	045459	BARRY MANEY - 3	TRAILER	
T624	Myrtleford - Workshop	Tyres\TP1+2	Tyres\TP1+2 (21-22)				04/08/2025	330644	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	045459	BORDER BANDAG PTY LTD -3	TRAILER	
T624	Myrtleford - Workshop	Tyres\RUN OUT	Tyres\RUN OUT POS 2S				04/08/2025	330644	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	045459	BORDER BANDAG PTY LTD -3	TRAILER	
T624	Myrtleford - Workshop	VehService\DS	VehService\DS D Service	VehService\DS			18/07/2025	330644	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	045459	BARRY MANEY - 3	TRAILER	
						Repair low brakes RH rear and LH middle brakes past wear limit. Jack up axles, remove hub nut, removed brake shoes and brake drum. Replace with new brake shoes and drum. Removed old seal and dust seal, and replaced with new seals. Fit hub and adjust												
T624	Myrtleford - Workshop	Brakes\BRK O/HAUL	Brakes\BRK O/HAUL			brakes. Check operation, all ok REPLACE PASS SIDE MIDDLE AND REAR GUARDS REALIGN FRONT GUARD Work order 198973	16/07/2025	330644	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	045459	BARRY MANEY - 3	TRAILER	
T624	Myrtleford - Workshop	Body\MUDGUARDS	tighten drivers side rear guard			Remove LHM and LHR guards and brackets. Straighten guard bracket then fit new euards. Adjust brackets to suit. all ok BROKEN MUD GUARD OR POLE Inspect and found guard bracket on chasis to mudguard broken. Remove bracket off mounting piece to chasis, bent new piece of steel to correct angle then machined and welded into guard bracket. Weld is a temporary fix, until new bracket arrives. Reinstalled welded bracket, all ok for time being.	16/07/2025	330644	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	045459	BARRY MANEY - 3	TRAILER	
T624	Myrtleford - Workshop	Body\MUDGUARDS	Body\MUDGUARDS			New bracket arrived, removed bolts from old bracket and unmounted. Installed new bracket and tighten bolts and nuts to spec Carried out trailer service as per Greenfreight checklist. Customer Instructions: Place vehicle on shaker & Inspected Carried out General Inpection & Checkover Greased vehicle TENSION PIVOT BUSHES & U BOLTS Check over and retension pivot bushes & u bolts TENSION BOLSTER BOLTS	01/07/2025	330644	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	045459	BARRY MANEY - 3	TRAILER	
				VehService\DS D Service															
T624	Myrtleford - Workshop	VehService\DS	D Service	VehService\DS		Check over and tensioned all bolster bolts as reouired	18/06/2025	330644	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	045459	BARRY MANEY - 3	TRAILER	
T624	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection	Insp\ANN INSP			30/05/2025	330644	PreventativeMaint	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	045459	BARRY MANEY - 3	TRAILER	
T624	Myrtleford - Workshop	VehService\DS	VehService\DS D Service	VehService\DS			30/05/2025	330644	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	045459	BARRY MANEY - 3	TRAILER	
						REMOVE AND REPLACE ALL LOAD BINDER STRAPS Instructed to replace all load binder chain and straps with new straps, remove old straps and install new with new bolts. All okay												
T624	Myrtleford - Workshop	Chassis\WINCH/STRP	REPLACE ROPE WITH STRAPS. RELEASE CABLE ON BACK STUCK. PLEASE FIX.			CHECK WHEEL BEARINGS	30/05/2025	330644	Fault	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	045459	BARRY MANEY - 3	TRAILER	
T624	Myrtleford - Workshop	DrivLine\WHEEL BRGS	DrivLine\WHEEL BRGS			Jacked up and checked wheel bearing movement all in spec. CHECK FOR AIR LEAKS WHEN LOADED	30/05/2025	330644	Repair	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	045459	BARRY MANEY - 3	TRAILER	
T624	Myrtleford - Workshop	Brakes\AIR LEAK	Brakes\AIR LEAK			Checked over for air leaks, found slight leak at air bag	30/05/2025	330644	Repair	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	045459	BARRY MANEY - 3	TRAILER	
T624	Myrtleford - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		fittine re seal and check all okav.	24/05/2025	330644	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	045459	BARRY MANEY - 3	TRAILER	
						Replace snapped bolt Broken bolt in dummy bolster, Removed bracket and bush.													
T624	Myrtleford - Workshop	Body\BOLSTER	Body\BOLSTER			Replace new bush. Reinstalled bracket. Tightened bolts to spec	16/04/2025	277946	Repair	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	045459	BARRY MANEY - 3	TRAILER	
T624	Myrtleford - Workshop	Brakes\AIR LEAK	Brakes\AIR LEAK			AIR LEAKS - CHECK OVER TRAILER Cut new hose and joined to stop air leak. Tighten/check mudguards LH side loose and needs straightening Mark and re drill hole in front guard to square up and make all level. New nuts and bolts fitted to rear guard.	16/04/2025	277946	Repair	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	045459	BARRY MANEY - 3	TRAILER	
						Tightened loose bracket support. Cracks in supporting													
T624	Myrtleford - Workshop	Body\MUDGUARDS	Body\MUDGUARDS			bracket need weldina.	16/04/2025	277946	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	045459	BARRY MANEY - 3	TRAILER	
T624	Myrtleford - Workshop	VehService\DS	VehService\DS D Service	VehService\DS			16/04/2025	330644	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	045459	BARRY MANEY - 3	TRAILER	
T624	Myrtleford - Workshop	Chassis\BOLSTER	SUPPLY 2 X 2.5mtr BOLSTER PEGS				26/03/2025	330644	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	045459	ELPHINSTONE ENGINEERING - 3	TRAILER	
T624	Myrtleford - Workshop	Tyres\TP02	Tyres\TP02				26/03/2025	330644	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	045459	BEAUREPAIRES - 3	TRAILER	
T624	Myrtleford - Workshop	Tyres\TP7+8	Tyres\TP7+8				26/03/2025	330644	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	045459	BEAUREPAIRES - 3	TRAILER	
T624	Myrtleford - Workshop	VehService\DS	VehService\DS D Service	VehService\DS			19/03/2025	330644	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	045459	BARRY MANEY - 3	TRAILER	
						LH rear wheel bearing was loose. Jacked up axle, remove hub cap and adjusted bearing to end float, refit hub cap and lowered axle. all okay													
T624	Myrtleford - Workshop	Chassis\WHEEL BRGS	CHECK & ADJUST LHR WHEEL BEARING			REPLACE BOLSTER BOLTS Found bolts on bolster to chassis were loose, attempt to tighten, no good. Attempt to remove, found bolts were seized. Used oxy to heat up all bolts and cut off.	13/03/2025	330644	Fault	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	045459	BARRY MANEY - 3	TRAILER	
T624	Myrtleford - Workshop	Chassis\BOLSTER	replace bolster bolts			Installed new bolts to all bolsters onto chassis. Applied loctite to bolts and tensioned RH indicator keeps dropping out fault in drivers book. Inspect wiring and plug, indicator was working on time of inspection, no faults found. Found LH front bolster clearance light not working. Retested wiring, all okay. Removed light and replaced with new.	13/03/2025	330644	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	045459	BARRY MANEY - 3	TRAILER	
T624	Myrtleford - Workshop	Elect\INDICATORS	RIGHT INDICATORS KEEP DROPPING OUT - CHECK PLUG			Fit new reflectors where neouired.	13/03/2025	330644	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	045459	BARRY MANEY - 3	TRAILER	
T624	Myrtleford - Workshop	Susp\SHOCK ABS	FR SHOCK ABSORBER LOOSE - RETIGHTEN			Tighten loose shocker bolt RH rear top bolt.	13/03/2025	330644	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	045459	BARRY MANEY - 3	TRAILER	
						Undo bolts and removed RH middle guard. Measure and drilled holes in new mud guard. Found guard bracket was broken. Removed guard bracket, straightened out, grind back surfaces and welded to repair. Reinstalled bracket with new bolts. mounted new euard and tensioned bolts												
T624	Myrtleford - Workshop	Body\MUDGUARDS	RHS MIDDLE MUDGUARD NEED REPLACING			Removed euard bracket and tensioned bolts	13/03/2025	330644	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	045459	BARRY MANEY - 3	TRAILER	
T624	Myrtleford - Workshop	Elect\INDICATORS	right indicator keeps going out			Removed indicator cover, found to have a broken wire. Tidy up wires and reioned. test operation. all okay.	08/03/2025	330644	Fault	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	045459	Myrtleford Workshop	TRAILER	
T624	Myrtleford - Workshop	VehService\DS	VehService\DS D Service	VehService\DS			26/02/2025	330644	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	045459	BARRY MANEY - 3	TRAILER	
						Repair shocker strap Removed LHF, LHR and RHM shockers. Fit straps and retainers re fit shockers and tension bolts all okay.													
T624	Myrtleford - Workshop	Susp\SHOCK ABS	Susp\SHOCK ABS			WELDING REPAIR - BROKEN CROSS MEMBER FRONT AND MIDDLE AXLE Clean up surface with grinder, weld up crack, cut length of steel to suit and for extra support. Weld in place and clean up tolls and area.	26/02/2025	330644	Repair	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	045459	BARRY MANEY - 3	TRAILER	
T624	Myrtleford - Workshop	Chassis\CHAS CRACK	Chassis\CHAS CRACK				26/02/2025	330644	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	045459	BARRY MANEY - 3	TRAILER	
T624	Myrtleford - Workshop	Tyres\TP9+10	Tyres\TP9+10				24/02/2025	330644	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	045459	BEAUREPAIRES - 3	TRAILER	
T624	Myrtleford - Workshop	Tyres\TP11+12	Tyres\TP11+12				24/02/2025	330644	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	045459	BEAUREPAIRES - 3	TRAILER	
						Check operation of all binders Checked operation of all binders as requested, all worked													
T624	Myrtleford - Workshop	Chassis\EXTE TU	Chassis\EXTE TU			correctly.	19/02/2025	330644	Repair	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	045459	Myrtleford Workshop	TRAILER	

T624	Myrtleford - Workshop	Brakes\AIR LEAK	Brakes\AIR LEAK		Trailer fitting leaking air Sprayed fittings and hoses, located tear in hose. Unplug fitting and removed hose. Cut off hose flush and reconnect back to fitting. reconnect fitting to trailer and tested, no further leaks	19/02/2025	330644	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	045459	Myrtleford Workshop	TRAILER
T624	Myrtleford - Workshop	Chassis\CROSS MBR	Chassis\CROSS MBR		weld broken cross member Found cross member were majorly cracked. Cleaned area and removed bark from cross member. Cut off cross member and grinded back surfaces flush on trailer. Cut two new squares of flat steel and a cross bar. Tack welded squares to each corner and welded cross bar across. Completed welds, tidy up	19/02/2025	330644	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	045459	Myrtleford Workshop	TRAILER
T624	Myrtleford - Workshop	Steering\SUSPENSION	Steering\SUSPENSION		REMOVE AND REPLACE WORN BUSHES RH front pivot bush worn. Jacked up axle, Removed air bag bolts, undo u bolts and removed pivot bush bolt. Pressed out worn bush and installed new. Refit spring and tong. Refit pivot bolt and fit air bag bolts. Installed u bolts and refit shocker. Tensioned all points and removed axles.	19/02/2025	330644	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	045459	Myrtleford Workshop	TRAILER
T624	Myrtleford - Workshop	VehService\DS	VehService\DS	VehService\DS		17/02/2025	330644	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	045459	BARRY MANEY - 3	TRAILER
T624	Myrtleford - Workshop	Body\MUDGUARDS	Body\MUDGUARDS		CHECK OVER ALL GUARDS AND BRACKETS - REPLACE WHAT IS UNSERVICEABLE Check over all euards and brackets and tighten as required	24/01/2025	330644	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	045459	Myrtleford Workshop	TRAILER
T624	Myrtleford - Workshop	Susp\SHOCK ABS	Susp\SHOCK ABS		REPLACE LHR SHOCKER AND CHECK OTHERS Unbolt LH rear shocker and removed. Installed new shocker and tensioned bolts. Also tightened loose bolts on RH middle shocker	24/01/2025	330644	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	045459	Myrtleford Workshop	TRAILER
T624	Myrtleford - Workshop	VehService\DS	VehService\DS	VehService\DS		22/01/2025	330644	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	045459	BARRY MANEY - 3	TRAILER
T624	Myrtleford - Workshop	Chassis\AIR TANKS	FIT NEW BOLT ON AIR TANK COVER LHS		Remove broken bolt, fitted new bolt and drilled another hole to install an second bolt. Fitted new bolt with new nut and washers cracks on bolster brackets	18/01/2025	330644	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	045459	BARRY MANEY - 3	TRAILER
T624	Myrtleford - Workshop	Body\BOLSTER	Body\BOLSTER		Found third bolster mount strap was cracked. Removed and grind out cracked surfaces. Welded over cracked section and painted. Reinstalled with new rubber. REMOVE BINDER BARRELL AND CHANGE OVER TO OTHER SIDE	19/12/2024	330644	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	045459	Myrtleford Workshop	TRAILER
T624	Myrtleford - Workshop	Chassis\WINCH/STRP	Chassis\WINCH/STRP		Unbolt and removed all binders. Change over to other side, chanae over handle to suit REMOVE DECK PLATE AND GET REPAIRED	19/12/2024	330644	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	045459	Myrtleford Workshop	TRAILER
T624	Myrtleford - Workshop	Chassis\DAMAGE	Chassis\DAMAGE		Remove deck plates and measure up to have new ones made at multi metals. Collect once ready and install when truck available next REMOVE BARKER MUDFLAP U/S	19/12/2024	330644	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	045459	Myrtleford Workshop	TRAILER
T624	Myrtleford - Workshop	Body\MUDGUARDS	back barker mudflap ripped need replacing of taken off		Removed rear mud flaps REPLACE 1ST BINDER BARRELL	05/12/2024	330644	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	045459	BARRY MANEY - 3	TRAILER
T624	Myrtleford - Workshop	Chassis\EXTE TU	1st binder needs barrel replaced supplied by Scott GF		Removed bolts securing binder in position. Pull binder barrell out, remove binder strap and fit to new barrell. Fit new barrell, refit all bolts and test operation, all okay.	05/12/2024	330644	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	045459	BARRY MANEY - 3	TRAILER
T624	Myrtleford - Workshop	Body\MUDGUARDS	needs mud guard replaced L/H rear		Mud guard broken at yard, isn't going out till Monday morning Removed LH front mud guard. Sourced new guard, measure and drilled holes in new guard, mounted new guard and tensioned mountine bolts	05/12/2024	330644	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	045459	BARRY MANEY - 3	TRAILER
T624	Myrtleford - Workshop	Susp\AIR BAG	Susp\AIR BAG		RH FRONT AIR BAG Lift ride height, fit jack between spring and chassis. Lowered ride height. Removed leaking RH front air bag, change over fittings and installed new air bag. Connect air lines and tighten mounting bolts. Remove jack and reset ride heiaht.	05/12/2024	330644	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	045459	BARRY MANEY - 3	TRAILER
T624	Myrtleford - Workshop	Body\LIGHTS	Body\LIGHTS		LH TAIL LIGHT ASSEMBLY BROKEN BOLSTER LIGHT H/W Remove and replace rear light assembly, Repair bolster light n/w Carried out trailer service as per Greenfreight checklist. Customer Instructions: Place vehicle on shaker & Inspected Carried out General Inpection & Checkover Greased vehicle	05/12/2024	330644	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	045459	BARRY MANEY - 3	TRAILER
T624	Myrtleford - Workshop	VehService\DS	VehService\DS	VehService\DS		30/11/2024	330644	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	045459	BARRY MANEY - 3	TRAILER
T624	Myrtleford - Workshop	Tyres\TP09	Replaced Tyre Position 9. (Mount Gambier Goodyear Autocare P/O: L090005)		Replace Tyre On Position 9	06/11/2024	330644	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	045459	BEAUREPAIRES - 3	TRAILER
T624	Myrtleford - Workshop	Tyres\TP1+2	Tyres\TP1+2			31/10/2024	330644	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	045459	BEAUREPAIRES - 3	TRAILER
T624	Myrtleford - Workshop	Tyres\TP05	Tyres\TP05			31/10/2024	330644	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	045459	BEAUREPAIRES - 3	TRAILER
T624	Myrtleford - Workshop	VehService\DS	VehService\DS	VehService\DS		29/10/2024	330644	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	045459	BARRY MANEY - 3	TRAILER
T624	Myrtleford - Workshop	Chassis\MUDGUARDS	REPLACE REAR TARP SPRINGS THAT ARE MISSING		REPLACE REAR TARP SPRINGS THAT ARE MISSING Found two missing springs on rear of tarp over chassis, went to oarts and aot new ones. fitted all okav Replaced missing cable for release straps as required.	25/10/2024	330644	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	045459	BARRY MANEY - 3	TRAILER
T624	Myrtleford - Workshop	Chassis\STRAPS	CHECK AND REPLACE RELEASE STRAPS WHERE REQUIRED		Sourced new cable from taylor marine. R&R SADDLE Found LH front saddle was broken. Supported spring, removed u bolts and shocker. Got new saddle from parts along with new u bolt nuts and washers. Lined up locating pins and put everything together. Tensioned everything and cleaned up.	25/10/2024	330644	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	045459	BARRY MANEY - 3	TRAILER
T624	Myrtleford - Workshop	Susp\SUSPENSION	R&R SADDLE		All okav. DRIVER STATES 1X BOLSTER LOOSE. NEEDS SECURING	25/10/2024	330644	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	045459	BARRY MANEY - 3	TRAILER
T624	Myrtleford - Workshop	Chassis\BOLSTER	DRIVER STATES 1X BOLSTER LOOSE. NEEDS SECURING		Prepped, cleaned and welded on new fixing frame plate to secure bolster	25/10/2024	330644	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	045459	BARRY MANEY - 3	TRAILER
T624	Myrtleford - Workshop	Tyres\TP1+2	Tyres\TP1+2 need new springs on guard mat rear section		Sourced new cable from taylor marine.	25/10/2024	330644	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	045459	BEAUREPAIRES - 3	TRAILER
T624	Myrtleford - Workshop	Body\DAMAGE	(fit new springs to rubber mating)		MUDGUARD R&R	18/10/2024	330644	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	045459	BARRY MANEY - 3	TRAILER
T624	Myrtleford - Workshop	Body\MUDGUARDS	Body\MUDGUARDS		Found RH front mudguard bracket had broken off. Cleaned mounting surfaces on trailer and cleaned end of bracket. Rewelded bracket to trailer. Measure and drilled holes in new guard. Mounted new guard with new nuts and bolts. Installed new mud flap and tightened all bolts. Replaced springs for deck plate rubber.	18/10/2024	330644	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	045459	BARRY MANEY - 3	TRAILER
T624	Myrtleford - Workshop	Tyres\TP3+4	Tyres\TP3+4			16/10/2024	330644	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	045459	BEAUREPAIRES - 3	TRAILER
T624	Myrtleford - Workshop	Chassis\CHAS CRACK	FOUND CRACKS IN CHASSIS OF TRAILER		Weld trailers cracks at JD's	15/10/2024	330644	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	045459	Myrtleford Workshop	TRAILER
T624	Myrtleford - Workshop	VehService\DS	VehService\DS	VehService\DS		04/10/2024	330644	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	045459	BARRY MANEY - 3	TRAILER
T624	Myrtleford - Workshop	Body\LIGHTS	REAR REVERSING LIGHT WORK LIGHT NEEDS REPLACING		REAR REVERSE LIGHT WORK LIGHT NEEDS REPLACING Removed and fit new reverse light as requested. Cut out and removed unnecessary wiring, make area tidy and secure. Tested light. all okav.	01/10/2024	330644	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	045459	Myrtleford Workshop	TRAILER
T624	Myrtleford - Workshop	Chassis\MUDGUARDS	Chassis\MUDGUARDS		ADJUST GUARD AND REPLACE BOLTS Removed guard and bolts, replaced with new bolts and tested. All okav. RH REAR TRAILER SHOCKER	01/10/2024	330644	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	045459	Myrtleford Workshop	TRAILER
T624	Myrtleford - Workshop	Susp\SHOCK ABS	Susp\SHOCK ABS		Found RH rear shocker was broken. Remove and replace shocker as required. tensioned bolts	01/10/2024	330644	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	045459	Myrtleford Workshop	TRAILER
T624	Myrtleford - Workshop	VehService\DS	VehService\DS	VehService\DS		09/09/2024	330644	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	045459	BARRY MANEY - 3	TRAILER
T624	Myrtleford - Workshop	Chassis\MUDGUARDS	LH guard broken LH rear needs mudflap RH middle euard needs replacing		LH guard bracket broken LH rear needs new mudflap RH middle guard needs replacing LH Middle Guard & Bracket - Remove LH side middle front guard front bracket. Straighten as required. Grind cracks on both sides. Held in place with g-clamp, tack weld in place. Remove clamps and weld both sides of crack. Cleaned up welds and painted. Re-fit bracket & lined up guards. Bolted in place on bracket.	02/09/2024	330644	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	045459	BARRY MANEY - 3	TRAILER
T624	Myrtleford - Workshop	Chassis\MUDGUARDS	Replace Missing Guard. (Barry Maney P/O: L088467)		RH Middle Guard - Unable to replace due to time. Secured cracked auard with cable ties. Replace next service Repair and re fit missing guard Travel to Greenfreight yard, found LH rear mud guard was missing and brackets were bent and cracked. Removed brackets, return to BMG yard and repaired brackets. Reinstalled brackets. Measured and drilled holes in new euard. mounted euard. tensioned bolts. REAR RIGHT MUD GUARD & BRACKET DAMAGED;	30/08/2024	330644	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	045459	BARRY MANEY - 3	TRAILER
T624	Myrtleford - Workshop	Chassis\MUDGUARDS	R/H Rear Guard & Bracket Damaged. (Barry Maney P/O: L088245)		Unbolt and removed R/H rear mud guard. Measure and drilled holes in new guard. Removed bracket and straightened out. Remounted bracket and painted. Reinstalled mud guard, tensioned all bolts.	20/08/2024	330644	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	045459	BARRY MANEY - 3	TRAILER
T624	Myrtleford - Workshop	VehService\DS	VehService\DS	VehService\DS		19/08/2024	330644	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	045459	BARRY MANEY - 3	TRAILER
T624	Myrtleford - Workshop	Elect\TRL LIGHTS	clearance light not working rear bolster both sides			15/08/2024	330644	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	045459	BARRY MANEY - 3	TRAILER
T624	Myrtleford - Workshop	Elect\WORK LIGHT	work lights not working both trailers			15/08/2024	330644	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	045459	BARRY MANEY - 3	TRAILER
T624	Myrtleford - Workshop	Chassis\MUDGUARDS	L/H front mud guard bracket loose			15/08/2024	330644	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	045459	BARRY MANEY - 3	TRAILER
T624	Myrtleford - Workshop	Chassis\EXTE TU	second binder bracket is bent down requires straightening			15/08/2024	330644	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	045459	BARRY MANEY - 3	TRAILER
T624	Myrtleford - Workshop	Chassis\BOLSTER	L/H side second bolster pin bent outwards may require replacing or turned 180 degrees			15/08/2024	330644	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	045459	BARRY MANEY - 3	TRAILER
T624	Myrtleford - Workshop	Chassis\BOLSTER	Hurdle on 4th bolster mounting bolts missing whole unit has excessive side movement			15/08/2024	330644	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	045459	BARRY MANEY - 3	TRAILER
T624	Myrtleford - Workshop	Tyres\TP7+8	Tyres\TP7+8			23/07/2024	172206	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	045459	BEAUREPAIRES - 3	TRAILER
T624	Myrtleford - Workshop	Tyres\TP05	Tyres\TP05			23/07/2024	172206	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	045459	BEAUREPAIRES - 3	TRAILER
T624	Myrtleford - Workshop	Body\WINCH/STRP	SUPPLY 8 X LH & 8 X RH EXTE WINCH BRAKETS number 5 air binder very slow to ratchet up and extremely hard to wind.		removed faulty binder	11/07/2024	172206	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	045459	FOREST CENTRE PTY LTD - 3	TRAILER
T624	Myrtleford - Workshop	Chassis\STRAPS			removed air fitting and clutch handle from old binder and fitted to replacement binder	10/07/2024	172206	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	045459	Myrtleford Workshop	TRAILER
T624	Myrtleford - Workshop	Chassis\CROSS MBR	checker plate at front of trailer (above turn table) bent out of place requires replacing or straightening		attempted to straighten checkerplate with little improvement will need more time to completely remove plate and re fabricate new cover	05/07/2024	172206	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	045459	BARRY MANEY - 3	TRAILER
T624	Myrtleford - Workshop	Body\STCH GUARD	rubber mat at front of trailer split requires re attaching			05/07/2024	172206	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	045459	BARRY MANEY - 3	TRAILER
T624	Myrtleford - Workshop	Chassis\MUDGUARDS	right hand guard bracket bent and loose			05/07/2024	172206	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	045459	BARRY MANEY - 3	TRAILER
T624	Myrtleford - Workshop	Chassis\BOLSTER	number 4 bolster base bent			05/07/2024	172206	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	045459	BARRY MANEY - 3	TRAILER
T624	Myrtleford - Workshop	Chassis\MUDGUARDS	mud flaps in front of guards need replacing			05/07/2024	172206	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	045459	BARRY MANEY - 3	TRAILER
T624	Myrtleford - Workshop	Chassis\MUDGUARDS	rear left guard needs replacing			05/07/2024	172206	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	045459	BARRY MANEY - 3	TRAILER
T624	Myrtleford - Workshop	Chassis\MUDGUARDS	all guards need aligning			05/07/2024	172206	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	045459	BARRY MANEY - 3	TRAILER
T624	Myrtleford - Workshop	Chassis\AIR FITTIN	front binder leaking air from squashed air fitting		removed broken air fitting and squashed hose replaced fitting and length of hose tested ok	03/07/2024	172206	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	045459	Unknown	TRAILER
T624	Myrtleford - Workshop	Chassis\STRAPS	quick release latch wont lock into place as bent out of shape		un bolted quick release and straightened rebolted and tested ok	03/07/2024	172206	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	045459	Unknown	TRAILER
T624	Myrtleford - Workshop	Susp\SHOCK ABS	LOOSE SHOCKER Tightened loose shockers as required AIR LEAK Inspect for air leaks, found fittings on air tank were leaking. Removed fittings and applied sealant to threads,			28/06/2024	172206	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	045459	Myrtleford Workshop	TRAILER
T624	Myrtleford - Workshop	Brakes\AIR LEAK	reinstalled.			28/06/2024	172206	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	045459	Myrtleford Workshop	TRAILER

| | | |

			D Service As Per Attached Checklist																
T624	Myrtleford - Workshop	VehService\DS	Barry Manev PO# L080036	VehService\DS		03/08/2023	59751	Service	Completed	Greenfreight Loxtne Vic	FlatTow	Mt Gambier	STK	045459	Wodonwa Workshop		TRAILER		
T624	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			03/08/2023	59751	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454619	Wodonga Workshop		TRAILER		
			AFTER HRS CALL OUT - LEAKING AIR BAG																
T624	Myrtleford - Workshop	Susp\AIR BAG	Inspect trailer for air leak fault, checked taps on suzi coils, okay. Checked trailer, found RH Middle air bae was leakine. Removed fittine and kinked line over. Built us air: all okay.			02/08/2023	1054926	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454619	Albury Workshop		TRAILER		
			BLOWN AIR BAGS & DAMAGED - rear air bags leaking and bent mounting plates. No air bags would pump up. Removed ride height valve and replaced with new. Air bags holding pressure.																
T624	Myrtleford - Workshop	Susp\AIR BAG	LH Front air bag s/s. Removed and replaced. Lift rear axle, removed air bags, arranged fabrication for air bag brackets. Fit new air bags to rear axle, lowered, all okay.			27/07/2023	1054921	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454619	Albury Workshop		TRAILER		
			MUD GUARDS DAMAGED - removed LH middle and both rear mud guards. Repaired broken bracket on RH Rear guard. Measure and installed new mud guards.																
T624	Myrtleford - Workshop	Body\MUDGUARDS	MUD GUARDS DAMAGED - removed LH middle and both rear mud guards. Repaired broken			27/07/2023	1054921	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454619	Albury Workshop		TRAILER		
T624	Myrtleford - Workshop	Body\DAMAGE	REAR SUPPORT BAR CRACKED - Grind out surfaces and welded over cracks in rear bar.			27/07/2023	1054921	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454619	Albury Workshop		TRAILER		
T624	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			18/07/2023	1052135	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454619	Wodonga Workshop		TRAILER		
			D Service As Per Attached Checklist																
T624	Myrtleford - Workshop	VehService\DS	Barry Manev PO# L0759596	VehService\DS		18/07/2023	1052135	Service	Completed	Greenfreight Loxtne Vic	FlatTow	Mt Gambier	STK	0454619	Wodonwa Workshop		TRAILER		
T624	Myrtleford - Workshop	Body\DAMAGE	Repair damaged guard from roo			01/07/2023	1041200	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454619	Albury Workshop		TRAILER		
T624	Myrtleford - Workshop	Susp\AIR LEAK	Repair Air Leak			01/07/2023	1041200	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454619	Albury Workshop		TRAILER		
T624	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			29/06/2023		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454459	Wodonga Workshop		TRAILER		
			D Service As Per Attached Checklist																
T624	Myrtleford - Workshop	VehService\DS	Barry Manev PO# L0752623	VehService\DS		29/06/2023		Service	Completed	Greenfreight Loxtne Vic	FlatTow	Mt Gambier	STK	0454459	Wodonwa Workshop		TRAILER		
T624	Myrtleford - Workshop	Susp\AIR BAG	Air bag leaking			17/06/2023	1037495	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454459	Albury Workshop		TRAILER		
T624	Myrtleford - Workshop	Susp\HCV	ride height falling off			17/06/2023	1037495	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454459	Albury Workshop		TRAILER		
T624	Myrtleford - Workshop	Susp\AIR FITTIN	rubbed air line			17/06/2023	1037495	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454459	Albury Workshop		TRAILER		
T624	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			09/06/2023	1033836	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454459	BARRY MANEY - 3		TRAILER		
			D Service As Per Attached Checklist																
T624	Myrtleford - Workshop	VehService\DS	PO# L0788845	VehService\DS		09/06/2023	1033836	Service	Completed	Greenfreight Loxtne Vic	FlatTow	Mt Gambier	STK	0454459	BARRY MANEY - 3		TRAILER		
			Annual Inspection As Per Checklist																
T624	Myrtleford - Workshop	Insp\ANN INSP	PO# L0788849	Insp\ANN INSP		09/06/2023	1033836	PreventativeMaint	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454459	BARRY MANEY - 3		TRAILER		
T624	Myrtleford - Workshop	Body\DAMAGE	Broken Guard Pole			30/05/2023		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454519	Albury Workshop		TRAILER		
T624	Myrtleford - Workshop	Tyres\TP01	runout			26/05/2023		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454519	Albury Workshop		TRAILER		
T624	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			19/05/2023	1019514	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454459	Wodonga Workshop		TRAILER		
			D Service As Per Attached Checklist																
T624	Wodonga - Workshop	VehService\DS	Barry Manev PO# L0788444	VehService\DS		19/05/2023	1019514	Service	Completed	Greenfreight Loxtne Vic	FlatTow	Mt Gambier	STK	0454459	Wodonwa Workshop		TRAILER		
T624	Myrtleford - Workshop	Tyres\TP11+12	Tyre Position 11 + 12			18/05/2023		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454519	Albury Workshop		TRAILER		
T624	Myrtleford - Workshop	Tyres\TP5+6	Tyre Position 5 + 6			18/05/2023		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454519	Albury Workshop		TRAILER		
T624	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			27/04/2023	1008104	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454459	Wodonga Workshop		TRAILER		
			D Service As Per Attached Checklist																
T624	Myrtleford - Workshop	VehService\DS	Barry Maney PO# L0779763	VehService\DS		27/04/2023	1008104	Service	Completed	Greenfreight Loxtne Vic	FlatTow	Mt Gambier	STK	0454459	Wodonwa Workshop		TRAILER		
T624	Myrtleford - Workshop	Tyres\TP07	Tyre Position 7			18/04/2023		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454519	Albury Workshop		TRAILER		
T624	Myrtleford - Workshop	Tyres\TP9+10	Tyre Position 9 + 10			18/04/2023		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454519	Albury Workshop		TRAILER		
T624	Wodonga - Workshop	Chassis\BOLSTER	REMOVED AND CRACK TESTED BOLSTER PEGS. TURNED WHEN FITTED.			12/04/2023		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454459	Wodonga Workshop		TRAILER		
T624	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			12/04/2023	1001591	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454519	Wodonga Workshop		TRAILER		
T624	Myrtleford - Workshop	Body\MUDGUARDS	MIDDLE R/H BACK GUARD NOT SECURED.			12/04/2023	1001591	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454519	Wodonga Workshop		TRAILER		
			D Service As Per Attached Checklist																
T624	Myrtleford - Workshop	VehService\DS	Barry Manev PO# L077711	VehService\DS		12/04/2023	1001591	Service	Completed	Greenfreight Loxtne Vic	FlatTow	Mt Gambier	STK	0454459	Wodonwa Workshop		TRAILER		
			Remove & crack test bolster pins																
			Remove all bolsters and crack test as below.																
			LH1 test ok, RH1 test ok.																
			RH2 test ok, RH2 test ok.																
T624	Myrtleford - Workshop	Chassis\BOLSTER	Refit sins facine forward			12/04/2023	1001591	Repair	Completed	Greenfreight Loxtne Vic	FlatTow	Mt Gambier	STK	0454519	Albury Workshop		TRAILER		
T624	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			21/03/2023	991047	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454519	BARRY MANEY - 3		TRAILER		
			D Service As Per Attached Checklist																
T624	Myrtleford - Workshop	VehService\DS	PO# L077278	VehService\DS		21/03/2023	991047	Service	Completed	Greenfreight Loxtne Vic	FlatTow	Mt Gambier	STK	0454519	BARRY MANEY - 3		TRAILER		
T624	Myrtleford - Workshop	Chassis\WINCH/STRP	Winches & Straps			16/03/2023	172206	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454519	Albury Workshop		TRAILER		
T624	Myrtleford - Workshop	Tyres\TP7+8	Tyre Position 7 + 8			16/03/2023		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454519	Albury Workshop		TRAILER		
T624	Myrtleford - Workshop	Tyres\TP03	Tyre Position 3			15/03/2023		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454519	Albury Workshop		TRAILER		
T624	Myrtleford - Workshop	Elect\ELECT P&W	L/H & R/H REAR LOAD LIGHT NOT WORKING.			08/03/2023	982298	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454459	Myrtleford Workshop		TRAILER		
T624	Myrtleford - Workshop	Chassis\BOLSTER	2ND BOLSTERS MOVE SIDE TO SIDE.			08/03/2023	982298	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454459	Wodonga Workshop		TRAILER		
T624	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			01/03/2023	982298	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454459	Wodonga Workshop		TRAILER		
			D Service As Per Attached Checklist																
T624	Wodonga - Workshop	VehService\DS	Barry Manev PO# L0785899	VehService\DS		01/03/2023	982298	Service	Completed	Greenfreight Loxtne Vic	FlatTow	Mt Gambier	STK	0454459	Wodonwa Workshop		TRAILER		
T624	Myrtleford - Workshop	Tyres\TP3+4	Tyre Position 3 + 4			14/02/2023		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454519	Albury Workshop		TRAILER		
T624	Myrtleford - Workshop	Tyres\TP9+10	Tyre Position 9 + 10			14/02/2023		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454519	Albury Workshop		TRAILER		
T624	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			10/02/2023	971827	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454519	BARRY MANEY - 3		TRAILER		
			D Service As Per Attached Checklist																
T624	Myrtleford - Workshop	VehService\DS	PO# L0785611	VehService\DS		10/02/2023	971827	Service	Completed	Greenfreight Loxtne Vic	FlatTow	Mt Gambier	STK	0454519	BARRY MANEY - 3		TRAILER		
			No Power to B Trailer Scales																
			Tested fuses, ok. Disconnect trailer and test, no good. Disconnect A trailer, no good. Test power, earth and signal, all ok. Change over ECU boxes on trailers, no																
T624	Myrtleford - Workshop	Elect\ELECT P&W	chanee. Rewire elue in truck. no chanee. Run iumo wire from B Trailer olue to B Trailer ECO. ok. Rewired B Trailer as reouired. ok			31/01/2023		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454459	Albury Workshop		TRAILER		
T624	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			25/01/2023	963164	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454459	Albury Workshop		TRAILER		
			D Service As Per Attached Checklist																
T624	Myrtleford - Workshop	VehService\DS	PO# L0762283	VehService\DS		25/01/2023	963164	Service	Completed	Greenfreight Loxtne Vic	FlatTow	Mt Gambier	STK	0454459	Albury Workshop		TRAILER		
T624	Myrtleford - Workshop	Body\MUDGUARDS	REMOVED BROKEN GUARD MOUNT. TOOK TO BARRY MANEY FOR WELDING REPAIR. FITTED.			21/01/2023		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454519	Myrtleford Workshop		TRAILER		
T624	Myrtleford - Workshop	Susp\AIR LEAK	Found damaged service line, causing airleak, cut out damaged section and rejoined			17/01/2023	960782	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454619	Albury Workshop		TRAILER		
			Guards & Brackets Broken																
			Removed broken guard & bracket so truck could get unloaded. Grind back surfaces and prep for welding. Welded bracket back on. Measure and drilled holes in new																
T624	Myrtleford - Workshop	Body\MUDGUARDS	guards, installed new guards and refit original mudflap. Check all ok			13/01/2023	956138	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454519	Albury Workshop		TRAILER		
T624	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			16/12/2022	950636	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454519	Wodonga Workshop		TRAILER		
T624	Myrtleford - Workshop	Elect\WORK LIGHT	LOAD LIGHTS NOT WORKING.			16/12/2022	950636	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454519	Wodonga Workshop		TRAILER		
T624	Myrtleford - Workshop	Elect\ELECT P&W	CLEARANCE LIGHTS ON R/H LAST BOLSTER BROKEN.			16/12/2022	950636	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454519	Wodonga Workshop		TRAILER		
T624	Myrtleford - Workshop	Body\MUDGUARDS	2x RED WHEEL GUARDS NEED REPLACING. (DRIVER SIDE REAR)			16/12/2022	950636	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454519	Wodonga Workshop		TRAILER		
			D Service As Per Attached Checklist																
T624	Myrtleford - Workshop	VehService\DS	Barry Manev PO# L0757767	VehService\DS		16/12/2022	950636	Service	Completed	Greenfreight Loxtne Vic	FlatTow	Mt Gambier	STK	0454519	Wodonwa Workshop		TRAILER		
T624	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			30/11/2022	942274	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454519	Wodonga Workshop		TRAILER		
T624	Myrtleford - Workshop	Elect\WORK LIGHT	Work lights not working.			30/11/2022	942274	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454459	Wodonga Workshop		TRAILER		
			D Service As Per Attached Checklist																
T624	Myrtleford - Workshop	VehService\DS	Barry Manev PO# L0753912	VehService\DS		30/11/2022	942274	Service	Completed	Greenfreight Loxtne Vic	FlatTow	Mt Gambier	STK	0454459	Wodonwa Workshop		TRAILER		
T624	Myrtleford - Workshop	Tyres\TP11+12	Tyre Position 11 + 12			30/11/2022		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454519	Albury Workshop		TRAILER		
T624	Myrtleford - Workshop	Susp\AIR LEAK	inspect air leak and found fittings leaking and split air line. Remove and run new air line & fittings. Started and checked no further leaks			24/11/2022		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454619	BARRY MANEY - 3		TRAILER		
T624	Myrtleford - Workshop	Tyres\TP1+2	Tyre Position 1 + 2			22/11/2022		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454519	Albury Workshop		TRAILER		
T624	Myrtleford - Workshop	Tyres\TP5+6	Tyre Position 5 + 6			22/11/2022		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454519	Albury Workshop		TRAILER		
T624	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			11/11/2022	931030	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454519	Wodonga Workshop		TRAILER		
			D Service As Per Attached Checklist																
T624	Myrtleford - Workshop	VehService\DS	Barry Maney PO# L0750564	VehService\DS		11/11/2022	931030	Service	Completed	Greenfreight Loxtne Vic	FlatTow	Mt Gambier	STK	0454519	Wodonwa Workshop		TRAILER		
			No lights on B Trailer, rubbed & broken wiring, cut out section & rejoined.																
T624	Myrtleford - Workshop	Elect\TRL LIGHTS	After hours			03/11/2022		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454519	Myrtleford Workshop		TRAILER		
T624	Myrtleford - Workshop	Elect\TAIL LIGHT	Lh tail not working, no power, trace fault to wiring break in loom, repair			02/11/2022	925814	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454519	Albury Workshop		TRAILER		
T624	Myrtleford - Workshop	Chassis\BOLSTER	2ND BOLSTER FROM REAR NEEDS TO BE PULLED BACKWARDS & STRAIGHTENED.			27/10/2022		Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454519	Wodonga Workshop		TRAILER		
T624	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			27/10/2022		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454519	Wodonga Workshop		TRAILER		
T624	Myrtleford - Workshop	Chassis\BOLSTER	BENT PIN PASENGER SIDE- 1ST TRI.			27/10/2022		Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454519	Wodonga Workshop		TRAILER		
T624	Myrtleford - Workshop	Elect\ELECT P&W	REAR L/S BOLSTER LIGHT NOT WORKING. (BROKEN WIRE BELOW)			27/10/2022		Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454519	Wodonga Workshop		TRAILER		
			D Service As Per Attached Checklist																
T624	Myrtleford - Workshop	VehService\DS	Barry Manev PO# L0747760	VehService\DS		27/10/2022		Service	Completed	Greenfreight Loxtne Vic	FlatTow	Mt Gambier	STK	0454519	Wodonwa Workshop		TRAILER		
			AIR LINE LEAKING																
			Inspect air line, rubbed at ride height valve.																
			Removed rubbed air line and installed new section of hose.		Labour - $87.50														
			Secured line all ok.		Hose - $ 1.63														
T624	Myrtleford - Workshop	Chassis\AIR LEAK	Barry Manev PO# L0747764		TOTAL - $98.05	26/10/2022		Repair	Completed	Greenfreight Loxtne Vic	FlatTow	Mt Gambier	STK	0454519	Wodonwa Workshop		TRAILER		
T624	Myrtleford - Workshop	Susp\HCV	Leaking line going to ride height valve rubbed, shorten & refit			12/10/2022		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454519	Myrtleford Workshop		TRAILER		
T624	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			05/10/2022	911846	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454519	Wodonga Workshop		TRAILER		
T624	Myrtleford - Workshop	Susp\WHEEL ALIGN	TRAILER TRACKS TO THE RIGHT. NEEDS WHEEL ALIGNMENT.		NO ADJUSTMENT. HAS BEEN AUGNED BEFORE.	05/10/2022	911846	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454519	Wodonga Workshop		TRAILER		
T624	Myrtleford - Workshop	Susp\SHOCK ABS	FRONT R/H AXLE- SHOCKER STRAP SNAPPED.		REPLACED 2 SHOCKS AND STRAPS.	05/10/2022	911846	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454519	Wodonga Workshop		TRAILER		
			D Service As Per Attached Checklist																
T624	Myrtleford - Workshop	VehService\DS	Barry Manev PO# L0746429	VehService\DS		05/10/2022	911846	Service	Completed	Greenfreight Loxtne Vic	FlatTow	Mt Gambier	STK	0454519	Wodonwa Workshop		TRAILER		
T624	Myrtleford - Workshop	Tyres\Re-Tor	Re-Torque			21/09/2022		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454519	Myrtleford Workshop		TRAILER		
T624	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			13/09/2022		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454519	Wodonga Workshop		TRAILER		
T624	Myrtleford - Workshop	Susp\WHEEL ALGN	TRAILER TRACKS TO THE RIGHT. NEEDS WHEEL ALIGNMENT.			13/09/2022		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454519	Wodonga Workshop		TRAILER		
			D Service As Per Attached Checklist																
T624	Myrtleford - Workshop	VehService\DS	Barry Manev PO# L0741001	VehService\DS		13/09/2022		Service	Completed	Greenfreight Loxtne Vic	FlatTow	Mt Gambier	STK	0454519	Wodonwa Workshop		TRAILER		
T624	Myrtleford - Workshop	Elect\TRL LIGHTS	R- REAR LIGHT FALLEN OUT, BOLTS PULLED THROUGH HOUSING & BROKEN. Removed LED and fitted large body washers to housing, refitted			25/08/2022		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454519	BARRY MANEY - 3		TRAILER		
T624	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			18/08/2022	890023	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454519	Wodonga Workshop		TRAILER		
T624	Myrtleford - Workshop	Body\MUDGUARDS	Bolt missing from right back mudguard bracket			18/08/2022	890023	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454519	Wodonga Workshop		TRAILER		
			D Service As Per Attached Checklist																
T624	Myrtleford - Workshop	VehService\DS	Barry Maney PO# L0735521	VehService\DS		18/08/2022	890023	Service	Completed	Greenfreight Loxtne Vic	FlatTow	Mt Gambier	STK	0454519	Wodonwa Workshop		TRAILER		
T624	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			03/08/2022		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454519	Wodonga Workshop		TRAILER		
T624	Wodonga - Workshop	Chassis\EXTE TU	NO. 6 BINDER NEEDS NEW ROPE.			03/08/2022		Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454519	Wodonga Workshop		TRAILER		
T624	Wodonga - Workshop	Chassis\EXTE TU	BINDER ASSEMBLY NEEDS REPAIR/ REPLACE. SHOWES SCOTT ALEXANDER.			03/08/2022		Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454519	Wodonga Workshop		TRAILER		
			D Service As Per Attached Checklist																
T624	Wodonga - Workshop	VehService\DS	Barry Manev PO# L0733286	VehService\DS		03/08/2022		Service	Completed	Greenfreight Loxtne Vic	FlatTow	Mt Gambier	STK	0454519	Wodonwa Workshop		TRAILER		
T624	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			19/07/2022	870506	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454519	Wodonga Workshop		TRAILER		
T624	Myrtleford - Workshop	Brakes\BRAKE ADJ	Adjust brakes			19/07/2022	870506	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454519	Wodonga Workshop		TRAILER		
T624	Myrtleford - Workshop	Body\MUDGUARDS	Bolt missing from right back mudguard bracket			19/07/2022	870506	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454519	Wodonga Workshop		TRAILER		
			D Service As Per Attached Checklist																
T624	Myrtleford - Workshop	VehService\DS	Barry Manev PO# L0732978	VehService\DS		19/07/2022	870506	Service	Completed	Greenfreight Loxtne Vic	FlatTow	Mt Gambier	STK	0454519	Wodonwa Workshop		TRAILER		
T624	Myrtleford - Workshop	Tyres\TP9+10	supply and fit 2tyres			14/07/2022		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454519	Myrtleford Workshop		TRAILER		
T624	Myrtleford - Workshop	Tyres\TP06	runout			14/07/2022		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454519	Myrtleford Workshop		TRAILER		
T624	Myrtleford - Workshop	Tyres\TP02	puncture repair			14/07/2022		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454519	Myrtleford Workshop		TRAILER		
T624	Myrtleford - Workshop	Tyres\FITMENT	pos 5			13/07/2022		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454519	Myrtleford Workshop		TRAILER		
T624	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			28/06/2022		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454459	Wodonga Workshop		TRAILER		
			D Service As Per Attached Checklist																
T624	Myrtleford - Workshop	VehService\DS	Barry Manev PO# L0721617	VehService\DS		28/06/2022		Service	Completed	Greenfreight Loxtne Vic	FlatTow	Mt Gambier	STK	0454519	Wodonwa Workshop		TRAILER		
			rear winch tap leaking replace supplied tap																
T624	Myrtleford - Workshop	Chassis\WHEEL SEAL	1st winch drum bent and badly bent not turnine remove and straighten			21/06/2022	854047	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454519	Myrtleford Workshop		TRAILER		
T624	Myrtleford - Workshop	Tyres\TP01	fit run out			17/06/2022		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454519	Myrtleford Workshop		TRAILER		
T624	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			09/06/2022	849512	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454519	Wodonga Workshop		TRAILER		
T624	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		09/06/2022	849512	Service	Completed	Greenfreight Loxtne Vic	FlatTow	Mt Gambier	STK	0454519	Wodonwa Workshop		TRAILER		
T624	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP		09/06/2022	849512	PreventativeMaint	Completed	Greenfreight Loxtne Vic	FlatTow	Mt Gambier	STK	0454519	Wodonwa Workshop		TRAILER		
T624	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			09/06/2022		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454519	Wodonga Workshop		TRAILER		
			D Service As Per Attached Checklist																
T624	Myrtleford - Workshop	VehService\DS	Barry Maney PO# L0723324	VehService\DS	TIGHTENED LOOSE GUARD.	09/06/2022		Service	Completed	Greenfreight Loxtne Vic	FlatTow	Mt Gambier	STK	0454519	Wodonwa Workshop		TRAILER		
T624	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			24/05/2022	845714	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454519	Wodonga Workshop		TRAILER		
			D Service As Per Attached Checklist																
T624	Myrtleford - Workshop	VehService\DS	Barry Manev PO# L0721930	VehService\DS		24/05/2022	845714	Service	Completed	Greenfreight Loxtne Vic	FlatTow	Mt Gambier	STK	0454519	Wodonwa Workshop		TRAILER		
			Bolster been hit & pushed across.																
			Job done after hors																
T624	Myrtleford - Workshop	Chassis\BOLSTER	note: no call out charee or extra labour rate charved			21/05/2022		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454519	Myrtleford Workshop		TRAILER		
T624	Myrtleford - Workshop	Body\DAMAGE	Replace broken guard bracket, fitted with universal bracket			03/05/2022		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454519	Myrtleford

T624	Myrtleford - Workshop	Tyres\TP3+4	supply and fit 2tyres					30/04/2022		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Brakes\AIR FITTIN	Air hose rubbed through cut section out & fitted joiner					20/04/2022		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	BARRY MANEY - 3		TRAILER
T624	Myrtleford - Workshop	Chassis\WINCH/STRP	Repair 2 winches					15/04/2022		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	Myrtleford Workshop		TRAILER
			D Service As Per Attached Checklist																	
T624	Myrtleford - Workshop	VehService\DS	Barry Maney POM L071234	VehService\DS				11/04/2022	172206	Service	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	0454/59	Wodonwa Workshop		TRAILER
T624	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					11/04/2022	172206	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	Wodonga Workshop		TRAILER
T624	Myrtleford - Workshop	Chassis\CROSS MBR	WELD UP CRACKS TO CROSS BEAMS					11/04/2022	172206	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	Wodonga Workshop		TRAILER
T624	Myrtleford - Workshop	Brakes\VALVES	CHECK MAYBE SERVICE REGULATOR VALVE.					11/04/2022	172206	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	Wodonga Workshop		TRAILER
T624	Myrtleford - Workshop	Elect\ELECT PB/W	CHANNEL 3 ON SCALES STILL READING 10-14 TONNE MORE THAN IT SHOULD, DOESN'T DO IT ALLTHE TIME.					11/04/2022	172206	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	Wodonga Workshop		TRAILER
T624	Myrtleford - Workshop	Elect\ELECT PB/W	STILL POPPING FUSES ON INDICATORS AND BRAKE LIGHTS. SUSPECT PROBLEM IN UMBILICAL BETWEEN A/B.					11/04/2022	172206	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	Wodonga Workshop		TRAILER
T624	Myrtleford - Workshop	Elect\ELECT PB/W	CHANNEL 3 ON SCALES STILL READ HEAVY SOMETIMES.					11/04/2022	172206	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	Wodonga Workshop		TRAILER
T624	Myrtleford - Workshop	Tyres\TP7+8	fit 2 runouts					08/04/2022		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					25/03/2022	807017	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	Wodonga Workshop		TRAILER
T624	Myrtleford - Workshop	Chassis\CROSS MBR	WELD UP CRACKS TO CROSS BEAMS					25/03/2022	807017	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	Wodonga Workshop		TRAILER
T624	Myrtleford - Workshop	Brakes\VALVES	CHECK MAYBE SERVICE REGULATOR VALVE.					25/03/2022	807017	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	Wodonga Workshop		TRAILER
T624	Myrtleford - Workshop	Elect\ELECT PB/W	CHANNEL 3 ON SCALES STILL READING 10-14 TONNE MORE THAN IT SHOULD, DOESN'T DO IT ALLTHE TIME.					25/03/2022	807017	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	Wodonga Workshop		TRAILER
T624	Myrtleford - Workshop	Chassis\WINCH/STRP	FIT CABLE TO LAST WINCH.					25/03/2022	807017	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	Wodonga Workshop		TRAILER
			D Service As Per Attached Checklist																	
T624	Myrtleford - Workshop	VehService\DS	PO # L070892	VehService\DS				25/03/2022	807017	Service	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	0454/59	Wodonwa Workshop		TRAILER
T624	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					10/03/2022	796857	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	Wodonga Workshop		TRAILER
			D Service As Per Attached Checklist																	
T624	Myrtleford - Workshop	VehService\DS	Barry Maney POM L070927	VehService\DS				10/03/2022	796857	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	Wodonga Workshop		TRAILER
T624	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					23/02/2022	787299	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	Wodonga Workshop		TRAILER
			D Service As Per Attached Checklist																	
T624	Myrtleford - Workshop	VehService\DS	PO # L070313	VehService\DS				23/02/2022	787299	Service	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	0454/59	Wodonwa Workshop		TRAILER
T624	Myrtleford - Workshop	Susp\SPRING HANG	Supply BPW Springs					19/02/2022		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Susp\HCV	Replace ride height valve					19/02/2022		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Tyres\TP9+10	supply and fit 4 tyres					19/02/2022	785520	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Tyres\TP11+12	Tyre Position 11 + 12					19/02/2022	785520	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					03/02/2022	777328	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	Wodonga Workshop		TRAILER
			D Service As Per Attached Checklist																	
T624	Myrtleford - Workshop	VehService\DS	PO # L069938	VehService\DS				03/02/2022	777328	Service	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	0454/59	Wodonwa Workshop		TRAILER
T624	Myrtleford - Workshop	Body\AIR LEAK	Repair Airleak trailer, repair rubbed section					28/01/2022	772362	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					14/01/2022	764767	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	BARRY MANEY - 3		TRAILER
					Checked springs for broken leaves and centre bolts															
					Checked tension of spring U bolts and tighten where necessary															
					Jacked up axles and checked wheel bearing movement and adjust															
					Checked all rockers,rocker bushes and rocker bolts															
					Checked all radius rod and bushes for wear															
					Checked main frame for cracks															
					Checked skid plate bolts															
					Checked king pin for wear and tightness of bolts															
					Checked all air tanks and mountings															
					Checked all brake hoses for chaffing and replace if necessary															
					Checked all brake camshafts and bushes for wear															
					Greased all lube points															
					Adjusted all brakes and check booster mounting nuts															
					Checked and repair all lights															
					Checked and repair mudguards and flaps															
			D Service As Per Attached Checklist		Checked wheel nuts and replace as required															
T624	Myrtleford - Workshop	VehService\DS	O/N L12877	VehService\DS	Checked for air leaks			14/01/2022	764767	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	BARRY MANEY - 3		TRAILER
					Check and retensioned pivot bushes and u bolts.															
					Unbolted shockie on both sides of rear axle. Unbolted pivot															
					bolts and lowered axle. Oxy out bush, cleaned all															
T624	Myrtleford - Workshop	Susp\Torque Rod	RETENSION PIVOT BUSHES AND U BOLTS		mounting surfaces. Pressed in new bush and refitted axle.			14/01/2022	764767	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	BARRY MANEY - 3		TRAILER
					Tensioned pivot bolts and checked. all okay.															
					Inspected rear bolster lights for operation, found to have															
					broken wiring. Cut out broken section and reconnected with															
T624	Myrtleford - Workshop	Elect\LTRL LIGHTS	rear bolster lights n/w		new wire. Checked operation. all okay.			14/01/2022	764767	Repair	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	0454/59	BARRY MANEY - 3		TRAILER
T624	Myrtleford - Workshop	Susp\AIR BAG	Call out to replce leaking air bag when truck loaded					14/01/2022	764222	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	BARRY MANEY - 3		TRAILER
T624	Myrtleford - Workshop	Body\MUDGUARDS	Cut pice of angle steel to be fitted to trailer using drill press drill holes for mudguard into new bracket. Weld new bracket onto trailer. fit mudguard to truck					06/01/2022		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	Myrtleford Workshop		TRAILER
T624	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job					15/12/2021	755765	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	BARRY MANEY - 3		TRAILER
			D Service As Per Attached Checklist																	
T624	Wodonga - Workshop	VehService\DS	O/N L12785	VehService\DS				15/12/2021	755765	Service	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	0454/59	BARRY MANEY - 3		TRAILER
T624	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					03/12/2021	749559	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	BARRY MANEY - 3		TRAILER
			D Service As Per Attached Checklist																	
T624	Myrtleford - Workshop	VehService\DS	O/N L12726	VehService\DS				03/12/2021	749559	Service	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	0454/59	BARRY MANEY - 3		TRAILER
T624	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					18/11/2021	741485	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	BARRY MANEY - 3		TRAILER
			D Service As Per Attached Checklist																	
T624	Myrtleford - Workshop	VehService\DS	O/N L12631	VehService\DS				18/11/2021	741485	Service	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	0454/59	BARRY MANEY - 3		TRAILER
T624	Myrtleford - Workshop	Body\MUDGUARDS	replace LH front guard and straighten bracket and turn front one up other way to lift up guard					09/11/2021	735859	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					05/11/2021	735674	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	BARRY MANEY - 3		TRAILER
			D Service As Per Attached Checklist																	
T624	Myrtleford - Workshop	VehService\DS	O/N L12534	VehService\DS				05/11/2021	735674	Service	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	0454/59	BARRY MANEY - 3		TRAILER
T624	Myrtleford - Workshop	Brakes\BOOSTER	replaced RH rear brake booster and supply and fit new brake hose					30/10/2021	731838	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					28/10/2021		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	BARRY MANEY - 3		TRAILER
			D Service As Per Attached Checklist																	
T624	Myrtleford - Workshop	VehService\DS	O/N L12465	VehService\DS				28/10/2021		Service	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	0454/59	BARRY MANEY - 3		TRAILER
T624	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					19/10/2021	724725	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	BARRY MANEY - 3		TRAILER
			D Service As Per Attached Checklist																	
T624	Myrtleford - Workshop	VehService\DS	O/N L12418	VehService\DS				19/10/2021	724725	Service	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	0454/59	BARRY MANEY - 3		TRAILER
T624	Myrtleford - Workshop	Tyres\TP9+10	supply and fit 2 tyres					10/10/2021		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					01/10/2021	729168	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	BARRY MANEY - 3		TRAILER
			D Service As Per Attached Checklist																	
T624	Myrtleford - Workshop	VehService\DS	O/N L12335	VehService\DS				01/10/2021	729168	Service	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	0454/59	BARRY MANEY - 3		TRAILER
T624	Myrtleford - Workshop	Susp\SHOCK ABS	LH shocker and straps and bushes					29/09/2021	718400	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Body\MUDGUARDS	replace 2 damaged guards					29/09/2021	718400	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Susp\DAMAGE	fit middle axle pivot bush					29/09/2021	718400	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	Myrtleford Workshop		TRAILER
			new convey belt cover trailer																	
T624	Myrtleford - Workshop	Body\STCH GUARD	straighten brackets and fit uo					29/09/2021	718400	Repair	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	0454/59	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					15/09/2021		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	BARRY MANEY - 3		TRAILER
			D Service As Per Attached Checklist																	
T624	Myrtleford - Workshop	VehService\DS	O/N L12237	VehService\DS				15/09/2021		Service	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	0454/59	BARRY MANEY - 3		TRAILER
T624	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					09/08/2021	707921	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	BARRY MANEY - 3		TRAILER
			D Service As Per Attached Checklist																	
T624	Myrtleford - Workshop	VehService\DS	ORDER # L12019	VehService\DS				09/08/2021	707921	Service	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	0454/59	BARRY MANEY - 3		TRAILER
			replace mudguard and mount brackets L12010																	
T624	Myrtleford - Workshop	Body\MUDGUARDS	supplied mmudeuard bracket					23/07/2021		Repair	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	0454/59	Mrtrleford Workshop		TRAILER
T624	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					29/06/2021	702620	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	BARRY MANEY - 3		TRAILER
			D Service As Per Attached Checklist																	
T624	Myrtleford - Workshop	VehService\DS	O/N L11746	VehService\DS				29/06/2021	702620	Service	Comoleted	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	0454/59	BARRY MANEY - 3		TRAILER
			Annual Inspection As Per Checklist																	
T624	Myrtleford - Workshop	Insp\ANN INSP	ORDER # L11607	Insp\ANN INSP				05/06/2021	691721	PreventativeMaint	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	BARRY MANEY - 3		TRAILER
T624	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					05/06/2021	691721	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	BARRY MANEY - 3		TRAILER
			D Service As Per Attached Checklist																	
T624	Myrtleford - Workshop	VehService\DS	O/N L11604	VehService\DS				05/06/2021	691721	Service	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	0454/59	BARRY MANEY - 3		TRAILER
T624	Myrtleford - Workshop	Chassis\WINCH/STRP	remove front binder rope and replace					26/05/2021	68800738	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	Myrtleford Workshop		TRAILER
			unbolt 3 bolster pin bolts and rotate pins back into trailer																	
T624	Myrtleford - Workshop	Chassis\WINCH/STRP	loowen bolster clamps and use forklift to push bolster across chassis to be centered. 3rd bolster back on trailer moved					26/05/2021	68800738	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	Myrtleford Workshop		TRAILER
			replace broken mudflaps																	
T624	Myrtleford - Workshop	Body\MUDGUARDS	fitted broken one to middle RHS and new to RH front					14/05/2021	683295	Reoair	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	0454/59	Mrtrleford Workshop		TRAILER
T624	Myrtleford - Workshop	Tyres\TP3+4	Supply and fit 4 tyres					08/05/2021	679753	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Tyres\TP9+10	Tyre Position 9 + 10					08/05/2021	679753	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					07/05/2021		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	BARRY MANEY - 3		TRAILER
			D Service As Per Attached Checklist																	
T624	Myrtleford - Workshop	VehService\DS	L11376	VehService\DS				07/05/2021		Service	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	0454/59	BARRY MANEY - 3		TRAILER
T624	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					14/04/2021	670940	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	BARRY MANEY - 3		TRAILER
			D Service As Per Attached Checklist																	
T624	Myrtleford - Workshop	VehService\DS	L11188	VehService\DS				14/04/2021	670940	Service	Comoleted	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	0454/59	BARRY MANEY - 3		TRAILER
T624	Rosewood - Workshop	Body\MUDGUARDS	replace both rear guard brackets and paint					10/04/2021	666752	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	Rosewood Workshop		TRAILER
T624	Myrtleford - Workshop	Tyres\TP9+10	Supply and fit 2 tyres					09/04/2021	667391	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Body\MUDGUARDS	weld broken brackets for mudguards and cross braces. Adjudt mudguards and fit large washers to prevent bolts pulling through					26/03/2021	659290	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					23/03/2021	660995	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	BARRY MANEY - 3		TRAILER
			D Service As Per Attached Checklist																	
T624	Myrtleford - Workshop	VehService\DS	BARRY MANNEY L11105	VehService\DS				23/03/2021	660995	Service	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	0454/59	BARRY MANEY - 3		TRAILER
T624	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					23/03/2021	660995	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	BARRY MANEY - 3		TRAILER
T624	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS				23/03/2021	660995	Service	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	0454/59	BARRY MANEY - 3		TRAILER
T624	Myrtleford - Workshop	Body\DAMAGE	Barry Maney - Came in after hours to weld rear guard bracket					17/03/2021		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					23/02/2021	649972	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	BARRY MANEY - 3		TRAILER
			D Service As Per Attached Checklist																	
T624	Myrtleford - Workshop	VehService\DS	L10877	VehService\DS				23/02/2021	649972	Service	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	0454/59	BARRY MANEY - 3		TRAILER
T624	Myrtleford - Workshop	Body\ELECT PB/W	check axles (switch turned off)					19/02/2021	648438	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	Myrtleford Workshop		TRAILER
			check scales checked wiring all ok																	
T624	Myrtleford - Workshop	Body\MUDGUARDS	realaxed auard					19/02/2021	648438	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					13/01/2021		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	BARRY MANEY - 3		TRAILER
			D Service As Per Attached Checklist																	
T624	Myrtleford - Workshop	VehService\DS	Order Number L10542	VehService\DS				13/01/2021		Service	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	0454/59	BARRY MANEY - 3		TRAILER
T624	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					01/12/2020	629417	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	BARRY MANEY - 3		TRAILER
			D Service As Per Attached Checklist																	
T624	Myrtleford - Workshop	VehService\DS	Order number L10266	VehService\DS				01/12/2020	629417	Service	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	0454/59	BARRY MANEY - 3		TRAILER
T624	Myrtleford - Workshop	Insp\WHC COMP	grid out and prepare area, we cut crack reweld and paint to clear defect					19/11/2020	625750	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Susp\DAMAGE	shocker straps frayed had ordered last service and fitted now					11/11/2020	620247	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					10/11/2020	620247	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	BARRY MANEY - 3		TRAILER
			D Service As Per Attached Checklist																	
T624	Myrtleford - Workshop	VehService\DS	ORDER # L10119	VehService\DS				10/11/2020	620247	Service	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	0454/59	BARRY MANEY - 3		TRAILER
T624	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					22/10/2020	610870	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	BARRY MANEY - 3		TRAILER
			D Service As Per Attached Checklist																	
T624	Myrtleford - Workshop	VehService\DS	Order Number L9975	VehService\DS				22/10/2020	610870	Service	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	0454/59	BARRY MANEY - 3		TRAILER
T624	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					01/10/2020	598382	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	BARRY MANEY - 3		TRAILER
			D Service As Per Attached Checklist																	
T624	Myrtleford - Workshop	VehService\DS	Order Number L9826	VehService\DS				01/10/2020	598382	Service	Comoleted	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	0454/59	BARRY MANEY - 3		TRAILER
			oxy cut out the broken bracket piece and clean up the area																	
T624	Myrtleford - Workshop	Chassis\CROSS MBR	find a piece of slate to weld into corner and oreoared it for weldine. Weld olate and cross brace in "B" trailer. Reolaced a small piece of air line					22/09/2020	594533	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Chassis\CROSS MBR	cut off Barry Maney fold repair job. Grind up and weld properly on both sides of the cracked cross member					17/09/2020	589934	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	Myrtleford Workshop		TRAILER
			winch reported as being stiff and broken grease nipple																	
T624	Myrtleford - Workshop	Chassis\WINCH/STRP	found no defect, sealed unit - no grease nipples. Replaced ball valve for air supply to 2nd winch ex.Greenfreight cupboard\ L11168					16/09/2020	582988	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					15/09/2020	585257	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	BARRY MANEY - 3		TRAILER
			D Service As Per Attached Checklist																	
T624	Myrtleford - Workshop	VehService\DS	ORDER # L9677	VehService\DS				15/09/2020	585257	Service	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	0454/59	BARRY MANEY - 3		TRAILER
T624	Myrtleford - Workshop	Chassis\BOLSTER	bolster moved, loosened use forklist to put back in place and retighten, checked all other ok					05/09/2020	579493	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					26/08/2020	576531	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454/59	BARRY MANEY - 3		TRAILER

			D Service As Per Attached Checklist																
T624	Myrtleford - Workshop	VehService\DS	Order number # L9477	VehService\DS			26/08/2020	576531	Service	Comolated	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	0454S9	BARRY MANEY - 3		TRAILER
T624	Myrtleford - Workshop	Susp\DAMAGE	repair then replace RHF shocker mount				14/08/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Body\AIR LEAK	repair air leaks				14/08/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				06/08/2020	565103	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	BARRY MANEY - 3		TRAILER
			D Service As Per Attached Checklist																
T624	Myrtleford - Workshop	VehService\DS	Order number # L9282	VehService\DS			06/08/2020	565103	Service	Comolated	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	0454S9	BARRY MANEY - 3		TRAILER
T624	Wodonga - Workshop	Elect\WORK LIGHT	mount and wire in load lights				24/07/2020	556534	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Wodonga Workshop		TRAILER
T624	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice				23/07/2020	558290	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Tyres\ROTATION	Job Added From Invoice				23/07/2020	558290	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice				23/07/2020	558290	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Tyres\SCRAP TYRE	Job Added From Invoice				23/07/2020	558290	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
			loosen bolster clamps push bolsters to centre replace damaged clamps bolts																
			tighten clamps																
			measure clamps to make new plates																
T624	Myrtleford - Workshop	Chassis\BOLSTER	check other bolster bolts				18/07/2020	558284	Repair	Comolated	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				16/07/2020	558005	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	BARRY MANEY - 3		TRAILER
			D Service As Per Attached Checklist																
T624	Myrtleford - Workshop	VehService\DS	Order Number # 19112	VehService\DS			16/07/2020	558005	Service	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	0454S9	BARRY MANEY - 3		TRAILER
T624	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice				10/07/2020	552664	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice				10/07/2020	552664	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Tyres\SCRAP TYRE	Job Added From Invoice				10/07/2020	553664	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
			repair air leak, sealed winch fitting																
			removed valve seal and seal top fitting																
T624	Myrtleford - Workshop	Body\AIR FITTIN	fitted washers to bulk head thread, put c over to reduce rubbing				08/07/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
			tighten up loose mudguard and brackets and mounts																
T624	Myrtleford - Workshop	Body\MOUNTS	weld up cracked mudguard bracket (L/H rear)				03/07/2020	552042	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
			replace air ball valve on B Trailer T624																
			leak ratchet strap																
			no reducer in stock. Informed driver that fitting will be fitted when he return																
T624	Myrtleford - Workshop	Chassis\WINCH/STRP	removed ball valve fitted reducer and installed ball valve				26/06/2020	550179	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				17/06/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	BARRY MANEY - 3		TRAILER
			D Service As Per Attached Checklist																
T624	Myrtleford - Workshop	VehService\DS	Order Number # L8846	VehService\DS			17/06/2020		Service	Comolated	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	0454S9	BARRY MANEY - 3		TRAILER
			D Service As Per Attached Checklist																
T624	Myrtleford - Workshop	VehService\DS	Order # L8629	VehService\DS			22/05/2020	537333	Service	Comolated	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	0454S9	BARRY MANEY - 3		TRAILER
T624	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				22/05/2020	537333	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	BARRY MANEY - 3		TRAILER
T624	Myrtleford - Workshop	Body\STCH GUARD	move bolster and cut holes in deck as per driver request				20/05/2020	534493	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
			loosened off retainer bolts, used forklift and ratchet strap to move bolster to desired position																
T624	Myrtleford - Workshop	Chassis\BOLSTER	tightened down bolster. mount retainine bolts				20/05/2020	534493	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Body\STCH GUARD	cut hole in rubber deck to ease cleaning as requested by driver				20/05/2020	534493	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				07/05/2020	529574	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	BARRY MANEY - 3		TRAILER
			D Service As Per Attached Checklist																
T624	Myrtleford - Workshop	VehService\DS	ORDER # L8494	VehService\DS			07/05/2020	529574	Service	Comolated	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	0454S9	BARRY MANEY - 3		TRAILER
T624	Myrtleford - Workshop	Chassis\BOLSTER	loosened the bolster then pushed it sideways back into the correct position, do bolts back up tight				02/05/2020	496644	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Chassis\WINCH/STRP	Sat - 2/05/20: "B Trailer" remove previously installed winch from front bav. Return to stock in workshop. Remove spare from rear bav and fit to front bav swap strap/d				02/05/2020	496644	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Chassis\BOLSTER	loosened off retaining bolts, used ratchet straps to pull bolster into position. Tightened retaining bolts				29/04/2020	520859	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Chassis\WINCH/STRP	removed chain shortening devices on all ratchet straps				29/04/2020	520859	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Body\PAINT/REST	wash trailers				24/04/2020	519506	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP			23/04/2020		PreventativeMaint	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				23/04/2020	519506	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
						replaced 2x mudflaps													
						rewired brake lights													
T624	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		moved 2x winches	23/04/2020	519506	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Body\PANELS	repair checker plate covers				09/04/2020	519503	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Chassis\SPAREWHEEL	strenghten tyre holder				09/04/2020	519503	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Chassis\CROSS MBR	weld cross braces				09/04/2020	519503	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Chassis\HOUSEKEEP	repair other cracks				09/04/2020	519503	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Body\STCH GUARD	refit cover mats				09/04/2020	519503	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Insp\RWC COMP	Engineer & test EBS System				07/04/2020	519503	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	JASON UNDERWOOD DESIGN - 4		TRAILER
T624	Myrtleford - Workshop	Chassis\BOLSTER	Move bolsters to fit 3 bays of 2.8 L8354				03/04/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Chassis\BOLSTER	Fit 2 x Extra Bolsters L8320				03/04/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Chassis\WINCH/STRP	Fit 3 extra Winches			remove winch off T623 and fit to T624	03/04/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Chassis\WINCH/STRP	Fit Dinemma Rope and Chain to Winches				03/04/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Chassis\HOUSEKEEP	remove log rack				27/03/2020	519502	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Brakes\BRK RELINE	Crack test and reline all wheels				27/03/2020	519502	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Elect\ELECT P&W	Fit Elphinstone Scales				04/03/2020	519506	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Susp\AXLES	Replace axle lift stopper				14/11/2019	519503	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				13/11/2019	519499	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
						replaced 2x shocker straps													
						welded cracked mudguard outrigger													
T624	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		repaired damaged winch handle	13/11/2019	519499	Service	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Brakes\EBS Kit	Fit EBS				13/11/2019	519503	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Body\STCH GUARD	fit chassis mat springs				30/08/2019	519496	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Chassis\SUSPENSION	Replace UTE spring stop				30/08/2019	519506	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Chassis\MUDGUARDS	Replace LHM mud guard				30/08/2019	519506	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				28/08/2019	519495	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
						straighten RHF m/guard bracket													
						LHR shocker strap													
T624	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		RHF shocker strap	28/08/2019	519495	Service	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				02/08/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	MAHONYS TRANSPORT SERVICES -3		TRAILER
			D Service As Per Attached Checklist																
T624	Myrtleford - Workshop	VehService\DS	Order # L8786	VehService\DS			02/08/2019		Service	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	0454S9	MAHONYS TRANSPORT SERVICES -3		TRAILER
T624	Myrtleford - Workshop	Elect\TRL LIGHTS	lights plug replaced			complete A Service	31/07/2019	510387	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Chassis\WINCH/STRP	air binder straightened and repaired				31/07/2019	510387	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Chassis\WINCH/STRP	repair winch bracket off chassis				31/07/2019	510387	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
			repair winch mount and fit new air																
			winch cradle and strap																
T624	Myrtleford - Workshop	Chassis\DAMAGE	fit m/euard				25/07/2019		Repair	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				05/07/2019	502435	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	MAHONYS TRANSPORT SERVICES -3		TRAILER
						replaced x1 mudflap													
			D Service As Per Attached Checklist			adjusted brakes													
T624	Myrtleford - Workshop	VehService\DS	Order # L8592	VehService\DS		replaced electrical male oluar	05/07/2019	502435	Service	Comolated	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	0454S9	MAHONYS TRANSPORT SERVICES -3		TRAILER
						complete A Service													
T624	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			tighten RHR mudguard	08/06/2019		Repair	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	0454S9	MAHONYS TRANSPORT SERVICES -3		TRAILER
			D Service As Per Attached Checklist																
T624	Myrtleford - Workshop	VehService\DS	Order # L8372	VehService\DS			08/06/2019		Service	Completed	Greenfreight Loxeine Vic	FlatTow	Mt Gambier	STK	0454S9	MAHONYS TRANSPORT SERVICES -3		TRAILER
T624	Albury - Workshop	Susp\AXLES	replaced lift axle bump stops				26/05/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Albury Workshop		TRAILER
T624	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				26/05/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Albury Workshop		TRAILER
T624	Albury - Workshop	VehService\DS	D Service	VehService\DS			26/05/2019		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Albury Workshop		TRAILER
T624	Albury - Workshop	Workshop\CLEAN	unhook 969 from T391. hook -up to T623/T624				25/05/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Albury Workshop		TRAILER
T624	Albury - Workshop	Elect\ELECT P&W	more extension hoses and loom to suit				26/05/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Albury Workshop		TRAILER
T624	Albury - Workshop	Chassis\HOUSEKEEP	fabricate and fit holding points for trailer lines				26/05/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Albury Workshop		TRAILER
T624	Albury - Workshop	Susp\SUSPENSION	REPLACE BROKEN LOWER SADDLES.			REPLACED BY HTT	19/05/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Albury Workshop		TRAILER
T624	Albury - Workshop	Susp\WHEEL ALIGN	WHEEL ALIGN				19/05/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Albury Workshop		TRAILER
T624	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				18/05/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Albury Workshop		TRAILER
T624	Albury - Workshop	VehService\DS	D Service	VehService\DS			18/05/2019		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Albury Workshop		TRAILER
T624	Albury - Workshop	Chassis\SUSPENSION	check over and note suspension failures for Hume TT				19/05/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Albury Workshop		TRAILER
T624	Albury - Workshop	Workshop\MOVE ASSET	unhook and deliver, pick up, hook-up				18/05/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Albury Workshop		TRAILER
T624	Albury - Workshop	Susp\SUSPENSION	RR, RM, LM, RF bottom suspension plates cracked				09/05/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Albury Workshop		TRAILER
T624	Albury - Workshop	Body\AIR BAG	RR airbag mount stiffner broken				09/05/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Albury Workshop		TRAILER
T624	Albury - Workshop	Susp\SUSPENSION	LR basking plate anchor spring broken				09/05/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Albury Workshop		TRAILER
T624	Albury - Workshop	Susp\WHEEL ALIGN	requires wheel alingment				09/05/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Albury Workshop		TRAILER
T624	Albury - Workshop	Body\MUDGUARDS	removed dress strip broken LH bottom of mudflaps				09/05/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Albury Workshop		TRAILER
T624	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				09/05/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Albury Workshop		TRAILER
T624	Albury - Workshop	VehService\DS	D Service	VehService\DS			09/05/2019		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Albury Workshop		TRAILER
T624	Albury - Workshop	Susp\SUSPENSION	lift axle bump stop, spring (nuts)				02/05/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Albury Workshop		TRAILER
T624	Albury - Workshop	Susp\SUSPENSION	RF spring wrap, alignment plate broken				02/05/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Albury Workshop		TRAILER
T624	Albury - Workshop	Elect\TRL LIGHTS	cab rack lights				02/05/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Albury Workshop		TRAILER
T624	Albury - Workshop	Susp\AIR BAG	RHF airbag				02/05/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Albury Workshop		TRAILER
T624	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				02/05/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Albury Workshop		TRAILER
T624	Albury - Workshop	VehService\DS	D Service	VehService\DS			02/05/2019		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Albury Workshop		TRAILER
T624	Albury - Workshop	DrCabElect\INDICATORS	L/H indicator				24/04/2019		Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Albury Workshop		TRAILER
T624	Albury - Workshop	DrCabElect\SCALES	calibrate scales				16/04/2019		Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Albury Workshop		TRAILER
T624	Albury - Workshop	VehService\DS	Service	VehService\DS			16/04/2019		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Albury Workshop		TRAILER
T624	Myrtleford - Workshop	Chassis\FIFTH WHEE	separate trailers				11/04/2019	446636	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Body\HOUSEKEEP	fit cab guard to trailer 624				11/04/2019	446636	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Body\HOUSEKEEP	fit broom to trailer				11/04/2019	446636	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Susp\AIR LEAK	repair air leak to LHM airbag				04/04/2019	445956	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Body\HOUSEKEEP	check trailer				04/04/2019	445956	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Chassis\WINCH/STRP	lower quick release latches on T624				27/03/2019	440528	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Elect\TRL LIGHTS	Repair trailer light plug & check lights				27/03/2019	426570	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				27/03/2019	440528	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			27/03/2019	440528	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Brakes\DAMAGE	middle axle on trl hot to touch on return				20/03/2019		Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Body\MUDGUARDS	replace R/H side rear mudguard				13/03/2019	430493	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				13/03/2019	430493	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			13/03/2019	430493	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Brakes\BRAKE ADJ	brake adjust				09/03/2019	427802	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
						fit mudflaps to rear axle													
T624	Myrtleford - Workshop	Susp\HOUSEKEEP	Replace Lift Axle Stopper			ooo rivet iam to t/fabt bar	01/03/2019	421820	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Body\MUDGUARDS	Replace LHF Mudguard & Bracket				01/03/2019	421820	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				28/02/2019	414179	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			28/02/2019	414179	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Susp\SHOCK ABS	Replace LHR bottom shocker mount				20/02/2019	413108	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				19/02/2019	410387	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			19/02/2019	410387	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Chassis\BOLSTER	move bolster to 2.5m spacing on 1st bay				08/02/2019	400861	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
			rear scale still intermittent																
T624	Myrtleford - Workshop	Elect\ELECT P&W	-power fault				06/02/2019	400180	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Elect\TRL LIGHTS	repair bolster light wiring				06/02/2019	400180	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				06/02/2019	400180	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrtleford Workshop		TRAILER
T624	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	repair bolster wiring		06/02/2019	400180	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0454S9	Myrt

T624	Myrtleford - Workshop	Body\PAINT/REST	acid wash wheels		09/01/2019	384375	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	045459	Myrtleford Workshop	TRAILER
T624	Myrtleford - Workshop	Body\PAINT/REST	wash trailers		09/01/2019	384375	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	045459	Myrtleford Workshop	TRAILER
T624	Myrtleford - Workshop	Tyres\TPS1	fit spare tyre		09/01/2019	384375	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	045459	Myrtleford Workshop	TRAILER
T624	Myrtleford - Workshop	Tyres\LTI Drive	remove all tyre pressure sensor equipment		04/01/2019	384374	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	045459	Myrtleford Workshop	TRAILER
T624	Myrtleford - Workshop	Chassis\WINCH/STRP	move position of winch handles		04/01/2019	384374	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	045459	Myrtleford Workshop	TRAILER
T624	Myrtleford - Workshop	Chassis\WINCH/STRP	replace winch tap		04/01/2019	384374	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	045459	Myrtleford Workshop	TRAILER
T624	Myrtleford - Workshop	Body\TOOLBOX	remove locks to access toolbox		04/01/2019	384374	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	045459	Myrtleford Workshop	TRAILER
T624	Myrtleford - Workshop	Body\AIR LEAK	check for air leaks		04/01/2019	384374	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	045459	Myrtleford Workshop	TRAILER
T624	Myrtleford - Workshop	Susp\SUSPENSION	Replace spring wraps as needed		18/12/2018	384368	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	045459	Myrtleford Workshop	TRAILER
T624	Myrtleford - Workshop	Susp\SUSPENSION	Fit shocker straps 7 repair spare wheel carrier		18/12/2018	384368	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	045459	Myrtleford Workshop	TRAILER
T624	Myrtleford - Workshop	Tyres	Replace tyres as needed	completed by Beaurepairs	18/12/2018	384368	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	045459	Myrtleford Workshop	TRAILER
T624	Myrtleford - Workshop	Elect\TRL LIGHTS	Check lights		18/12/2018	384368	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	045459	Myrtleford Workshop	TRAILER
T624	Myrtleford - Workshop	Insp\ANN INSP	Roadworthy Inspection		18/12/2018	384368	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	045459	Myrtleford Workshop	TRAILER