EquipmentName	Workshop	CodeAndSubCode	Description	Schedule	CompletionComments	DateDone	DistanceDone	Worktype	Workstate	EquipmentOwner	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
T621	Mt Gambier - Mt Gambier	VehService\DS	VehService\DS D Service	VehService\DS		26/09/2026	731376	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	BARRY MANEY - 3	TRAILER
					REKIT AND REPAIR LANDING LEG AS REQUIRED											
			A Trailer leg handle shaft snapped off, will need replacing		Dismantle and disassemble landing legs to access. Fit new											
			Inspect quickly, found handle broken off inside of leg. Will		gear set and plates as required. Tension and test operation.											
T621	Mt Gambier - Mt Gambier	Chassis\DAMAGE	need new legs. To get photo and quoted up when truck returns.		Grease landing legs	25/09/2026	731376	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	BARRY MANEY - 3	TRAILER
					Jacked up axle and spring, removed chain. Source new saddle,											
			TRAILER COMING BACK FROM PORTLAND AXLE CHAINED UP - FIT NEW		installed and secured with new u bolts. Refit wheels and											
			SADDLE AND U BOLTS, ALSO REFIT WHEELS ETC		tensioned. Lowered axle. Refit shocker											
T621	Mt Gambier - Mt Gambier	DrivLine\AXLE REPLC			AFTER H'RS BREAKDOWN	21/09/2026	731376	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	BARRY MANEY - 3	TRAILER
T621	Mt Gambier - Mt Gambier	VehService\DS	VehService\DS D Service	VehService\DS		11/09/2026	731376	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	HALLORAN DIESEL - 3	TRAILER
T621	Mt Gambier - Mt Gambier	Body\MUDGUARDS	Damaged mudguard. LHR		Removed damaged LHR mudguard and reolaced with new unit	04/09/2026	731376	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	HALLORAN DIESEL - 3	TRAILER
T621	Mt Gambier - Mt Gambier	Elect\WORK LIGHT	missing work liaht head board		installed new LHF lower work liaht	04/09/2026	731376	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	HALLORAN DIESEL - 3	TRAILER
T621	Mt Gambier - Mt Gambier	Body\MUDGUARDS	TIGHTENED L/R MUDGUARD BRACKET			04/09/2026	731376	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	HALLORAN DIESEL - 3	TRAILER
T621	Mt Gambier - Mt Gambier	Tyres\TP08	Tyres\TP08			04/09/2026	731376	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	BORDER BANDAG PTY LTD -3	TRAILER
T621	Myrtleford - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		19/08/2026	731376	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	HALLORAN DIESEL - 3	TRAILER
					Inspect air leak, found to be coming for air tap. Driver											
					advised he does not use this air tap. Disconnect air line											
T621	Myrtleford - Workshop	Body\AIR LEAK	Check for air leak on middle axle where air tap is		and kinked off. All okay.	30/07/2026	731376	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	BARRY MANEY - 3	TRAILER
			VehService\DS D Service													
T621	Myrtleford - Workshop	VehService\DS	L134924	VehService\DS		28/07/2026	731376	Service	Unlocked	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	BARRY MANEY - 3	TRAILER
T621	Myrtleford - Workshop	Tyres\RUN OUT	Tyres\RUN OUT POS 21			07/07/2026	731376	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	BORDER BANDAG PTY LTD -3	TRAILER
			VehService\DS D Service													
T621	Myrtleford - Workshop	VehService\DS	L134648	VehService\DS		03/07/2026	731376	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	BARRY MANEY - 3	TRAILER
					Inspect wiring to RH tail light, found to have numerous											
					broken wires. Run new wire from LH side tail light through											
					junction box and joined to RH side tail light. Tested											
T621	Myrtleford - Workshop	Elect\TRL LIGHTS	R/H TAIL LIGHTS ON A TRAILER NOT WORKING		lights, all okay. Also joined wiring to number plate light,	18/06/2026	731376	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	BARRY MANEY - 3	TRAILER
					tested, all okay.											
					Inspect wiring to RH tail light, found to have numerous											
					broken wires. Run new wire from LH side tail light through											
					junction box and joined to RH side tail light. Tested											
T621	Myrtleford - Workshop	Elect\TAIL LIGHT	NUMBER PLATE LIGHT NOT WORKING		lights, all okay. Also joined wiring to number plate light,	18/06/2026	731376	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	BARRY MANEY - 3	TRAILER
					tested, all okay.											
					Go over and inspect all binders for missing bolts - all											
					bolts where should be. Tension all bolts to ensure all tight											
T621	Myrtleford - Workshop	Chassis\WINCH/STRP	NUMBER 2 WINCH - MISSING BOLTS		and wont fall out	18/06/2026	731376	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	BARRY MANEY - 3	TRAILER
			VehService\DS D Service													
T621	Myrtleford - Workshop	VehService\DS	L134291	VehService\DS		17/06/2026	731376	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	BARRY MANEY - 3	TRAILER
T621	Myrtleford - Workshop	Tyres\Punct	Tyres\Punct POS 28			15/06/2026	731376	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	BORDER BANDAG PTY LTD -3	TRAILER
T621	Myrtleford - Workshop	Tyres\RUN OUT	Tyres\RUN OUT POS 27			15/06/2026	731376	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	BORDER BANDAG PTY LTD -3	TRAILER
			VehService\DS D Service													
T621	Myrtleford - Workshop	VehService\DS	L133920	VehService\DS		26/05/2026	731376	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	BARRY MANEY - 3	TRAILER
			NO 1 BINDER 1 NUT MISSING													
					Replaced missing winch nuts on #1. Unable to replace missing											
T621	Myrtleford - Workshop	Chassis\WINCH/STRP			bolt on #2 due to time restrictions	25/05/2026	731376	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	BARRY MANEY - 3	TRAILER
			VehService\DS D Service													
T621	Myrtleford - Workshop	VehService\DS	L133572	VehService\DS		30/04/2026	731376	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	BARRY MANEY - 3	TRAILER
					Repair lights n/w											
					Inspect and found RH rear clearance light not working.											
					Check for power at light - no power. Trace wiring back to											
					junction box and found numerous rubbed and broken wires.											
					While repairing wires found other lights had stopped											
					working. Pull apart power and earth connections, cut out											
					all faulty wiring. Run new wire for clearance light and											
					joined. Tidy up and solder faulty wiring in junction box.											
T621	Myrtleford - Workshop	Elect\TRL LIGHTS	FIX CLEARANCE LIGHTS D/S ON MAIN REAR BUMPER BESIDE TAIL LIGHT SET UP		Refit connectors, tested operation, all okay.	17/04/2026	731376	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	BARRY MANEY - 3	TRAILER
T621	Myrtleford - Workshop	Tyres\TP9+10	Tyres\TP9+10 (29-30)			17/04/2026	731376	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	BORDER BANDAG PTY LTD -3	TRAILER
T621	Myrtleford - Workshop	Tyres\TP3+4	Tyres\TP3+4 (23-24)			17/04/2026	731376	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	BORDER BANDAG PTY LTD -3	TRAILER
T621	Myrtleford - Workshop	Tyres\TP11+12	Tyres\TP11+12 (31-32)			17/04/2026	731376	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	BORDER BANDAG PTY LTD -3	TRAILER
T621	Myrtleford - Workshop	Tyres\Punct	Tyres\Punct (25-26)			17/04/2026	731376	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	BORDER BANDAG PTY LTD -3	TRAILER
			VehService\DS D Service													
T621	Myrtleford - Workshop	VehService\DS	L133341	VehService\DS		17/04/2026	731376	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	BARRY MANEY - 3	TRAILER
			RHF & RHR SPRING EYE BUSHES HAVE SOME SLITE MOVEMENT		Check over RHF and RHR spring bushes, all looked OK.											
T621	Myrtleford - Workshop	Susp\HOUSEKEEP	(RECHECK BUSHES NEXT D SERVICE) DONE ON 20/3/26 AT B/M		Inspect when on shaker, minor movement. Continue to monitor	01/04/2026	731376	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	BARRY MANEY - 3	TRAILER
			VehService\DS D Service													
T621	Myrtleford - Workshop	VehService\DS	L133057	VehService\DS		27/03/2026	731376	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	BARRY MANEY - 3	TRAILER
			VehService\DS D Service													
T621	Myrtleford - Workshop	VehService\DS	L099252	VehService\DS		19/03/2026	731376	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	BARRY MANEY - 3	TRAILER
					Inspect and found air leak coming from fitting to booster											
					line. Remove fitting and apply thread sealant. Refit											
T621	Myrtleford - Workshop	Brakes\AIR LEAK	AIR LEAKS		fitting with new clamp. all OK	11/03/2026	731376	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	BARRY MANEY - 3	TRAILER
			VehService\DS D Service													
T621	Myrtleford - Workshop	VehService\DS	L099045	VehService\DS		20/02/2026	731376	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	BARRY MANEY - 3	TRAILER
			WORK LIGHTS TO BE RUN TO SWITCH ON DS HEADBOARD & WORKING		Inspect work light wiring. Remove and re-run wiring to											
T621	Myrtleford - Workshop	Elect\WORK LIGHT	NOT CONNECTED TO REVERSE LAMPS		switch on dash headboard as required. Check, all working ok	02/02/2026	731376	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	BARRY MANEY - 3	TRAILER
					Check scales not connecting. Disconnect and reconnect											
T621	Myrtleford - Workshop	DrCabElect\SCALES	GET SCALES BLUETOOTH WORKING ON TABLET		Bluetooth, scales connecting fine, could not fault	02/02/2026	731376	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	BARRY MANEY - 3	TRAILER
					Remove hoses from ABS module then plug in in and attempt to											
					collect ABS data - unable to retrieve data. Unbolt and											
					inspect ABS module, found faulty. Remove and replace ABS											
					module as required and re-check, all ok.											
					KWB23034001-3A-FV MODULE WITH FITTINGS 1 2525.93											
					KWA8F232 HOSE UNION 1/2 2 6.18											
					KWT02-3502-152M HOSE-RUBBER 1/2' SAE J1 1 6.00											
					KWHS010-20 PERFORATED HOSECLAMP BA 8 20.48											
			ABS Module needs replacing - Roadworthy component		KWA8F241 PIPE SCRT 1/2 X 1/2 2 17.00											
T621	Myrtleford - Workshop	Brakes\ABS	REPLACE TRAILER ABS MODULE		KWHS012P CLAMP-HOSE,PERFORATED 1	02/02/2026	731376	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	BARRY MANEY - 3	TRAILER
T621	Myrtleford - Workshop	Brakes\BACK PLATE	BACKING PLATE FOR BRAKES BROKEN		Remove and replace backing plate as required. *plate from	02/02/2026	731376	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	BARRY MANEY - 3	TRAILER
					tool room*											
					Removed broken mud guard and bracket. Removed mud guard											
					from bracket. Grind back surfaces and welded up bracket.											
					Refit bracket. Measure and drilled holes in new mud guard,											
					mounted guard and fitted new mud flap.											
					KWK127-1116-08A FENDER RED SPRAYSAFE 1 49.95											
					KWK197-4934 REINFORCEMENT-REAR MUDFLAP 1 39.17											
T621	Myrtleford - Workshop	Body\MUDGUARDS	R&R TRAILER LH MUDGUARD, BRACKET AND MUDFLAP		KWLS2424-WRCKW MUDFLAP-LOSPRAY	31/01/2026	731376	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	BARRY MANEY - 3	TRAILER
			VehService\DS D Service													
T621	Myrtleford - Workshop	VehService\DS	L098728	VehService\DS		31/01/2026	731376	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	BARRY MANEY - 3	TRAILER
			VehService\DS D Service													
T621	Myrtleford - Workshop	VehService\DS	L098305	VehService\DS		05/01/2026	731376	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	BARRY MANEY - 3	TRAILER
					Plug in and inspect B trailer module, all ok, no faults											
					present. Attempt to connect to A trailer but unsuccessful.											
					Test and trace wiring, all tested ok. Test at module and											
					found all powers and earths present. Make up test lead and											
					connect straight to module, no good. Diagnose as module											
T621	Myrtleford - Workshop	Brakes\EBS FAULTS	PLUG IN AND CHECK TRAILER ABS/EBS FAULT CODES		un-serviceable. waiting p and a	05/01/2026	731376	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	BARRY MANEY - 3	TRAILER
T621	Myrtleford - Workshop	Brakes\EBS Kit	CHECK & ENGINEER EBS SYSTEM			24/12/2025	731376	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	JASON UNDERWOOD DESIGN - 3	TRAILER
T621	Myrtleford - Workshop	Chassis\BOLSTER	REPOSITION BOLSTERS & LOAD BINDERS AS REQUIRED TO SUIT 6M LOGS			15/12/2025	731376	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	JF MECHANICALS - 3	TRAILER
					Scales on trailer not Bluetooth compatible. Fit new											
					Bluetooth scales as required, all okay											
T621	Myrtleford - Workshop	DrCabElect\SCALES	R&R WEIGHT SCALE		NG201-EBT-01B S/INPUT WEIGHT GAUGE	11/12/2025	731376	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	BARRY MANEY - 3	TRAILER
T621	Myrtleford - Workshop	Chassis\BOLSTER	TURN BENT BOLSTER AROUND 180 - FIRST DRIVERS SIDE		Undo bolster and turn 180 degrees, tighten, all okay	11/12/2025	731376	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	BARRY MANEY - 3	TRAILER
T621	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection	Insp\ANN INSP		14/11/2025	731376	PreventativeMaintenance	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Myrtleford Workshop	TRAILER
					FIT NEW SHOCKER STRAP RETAINERS											
					FIT LIFT AXLE RUBBERS											
					REPLACE LOWER SPRING SADDLE											
T621	Myrtleford - Workshop	VehService\DS	VehService\DS	VehService\DS	FITTED RAKE HOWE BRACKET	14/11/2025	731376	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Myrtleford Workshop	TRAILER
			FIT EBS TO 2ND & 3RD AXLES													
T621	Myrtleford - Workshop	Brakes\EBS Kit	CARRY OUT END OF LINE TEST (EOL)			13/11/2025	731376	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	MYRTLEFORD AUTO ELECTRICS - 3	TRAILER
T621	Myrtleford - Workshop	Chassis\HOUSEKEEP	FIT , DRILL AND PAINT CHECKER PLATE TO CHASSIS			06/11/2025	731376	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Myrtleford Workshop	TRAILER
T621	Myrtleford - Workshop	Body\ELECT P&W	REFIT AND REWIRE ELE WIRES TO HEAD BOARD			21/10/2025	731376	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Myrtleford Workshop	TRAILER
			PREP AND PAINT BOLSTERS AND PEGS REPAINT SOCKET ENDS WHITE													
T621	Myrtleford - Workshop	Body\PAINT/REST	REFIT PEGS AND NEW BOLTS			21/10/2025	731376	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Myrtleford Workshop	TRAILER
T621	Myrtleford - Workshop	Brakes\EBS Kit	FIT UP EBS COMPONENTS TO 2ND AND 3RD AXLES			14/07/2025	731376	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Myrtleford Workshop	TRAILER
T621	Myrtleford - Workshop	Chassis\BOLSTER	CRACK TEST ALL BOLSTER PEGS & REPLACE MOUNT BOLTS			10/07/2025	731376	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	FOREST CENTRE PTY LTD - 3	TRAILER
			MOVE BOLSTERS TO 3MTR BAY & 3.6MTR LOGGS													
T621	Myrtleford - Workshop	Chassis\BOLSTER	FIT EXTE TU AIR WINCHES & QUICK RELEACES			10/07/2025	731376	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	FOREST CENTRE PTY LTD - 3	TRAILER
T621	Myrtleford - Workshop	Body\MUDGUARDS	REPLACE ALL 6 X M/GUARDS			10/07/2025	731376	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	FOREST CENTRE PTY LTD - 3	TRAILER
			REMOVE ALL WHEEL & INSPECT BRAKE ¾ AND WHEEL BEARINGS CRACK TEST ALL AXLES													
T621	Myrtleford - Workshop	Body\WHL HUB	INSPECT & REPACK ALL WHEEL BEARINGS & REPLACE AS REQUIERED			09/07/2025	731376	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	FOREST CENTRE PTY LTD - 3	TRAILER
			CHECK BALL RACE (ALL OK)													
			FIT JAW KIT & FOOT BUSHES													
T621	Myrtleford - Workshop	Chassis\FIFTH WHEE	fit up remount arease lines and block			09/07/2025	731376	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	FOREST CENTRE PTY LTD - 3	TRAILER
T621	Myrtleford - Workshop	Tyres\RUN OUT	Tyres\RUN OUT TYRE POS 1-12			28/05/2025	731376	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	BEAUREPAIRES - 3	TRAILER
T621	Wodonga - Workshop	VehService\DS	D Service	VehService\DS		31/10/2024	731376	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonga Workshop	TRAILER
T621	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			05/12/2023		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonga Workshop	TRAILER
T621	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		05/12/2023		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonga Workshop	TRAILER
T621	Wodonga - Workshop	Chassis\EXTE TU	NO WINCHES FITTED.			05/12/2023		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonga Workshop	TRAILER

T621	Wodonga - Workshop	Brakes\EBS Kit	NO EBS FITTED.			05/12/2023		Reapair	Comoleted	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonga Workshop		TRAILER
T621	Myrtleford - Workshop	Como\Truck Safe	no sticker		NHVAS	26/10/2021		Reapair	Comoleted	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Myrtleford Workshop		TRAILER
T621	Myrtleford - Workshop	Body\STRAPS	replace front air ratchet			26/10/2021	731376	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Myrtleford Workshop		TRAILER
T621	Myrtleford - Workshop	Body\LIGHTS	RHR indicator lense damaged			26/10/2021	731376	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Myrtleford Workshop		TRAILER
			front L & R alignment plates														
			bottom shocker plate														
T621	Myrtleford - Workshop	Susp\SPRNG PACK	RM & LM seb			26/10/2021	731376	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Myrtleford Workshop		TRAILER
T621	Myrtleford - Workshop	Elect\TRL LIGHTS	RH clearance lights			26/10/2021	731376	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Myrtleford Workshop		TRAILER
T621	Myrtleford - Workshop	Comp\Truck Safe	fitted truck safe ordered NHVAS		order	26/10/2021		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Myrtleford Workshop		TRAILER
T621	Myrtleford - Workshop	Elect\ELECT P&W	NO SCALES SET UP ON TRAILER		scales work, truck not supplying enough volts	26/10/2021	731376	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Myrtleford Workshop		TRAILER
T621	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP		22/10/2021	731376	PreventativeMaintenance	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Myrtleford Workshop		TRAILER
T621	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			22/10/2021	731735	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Myrtleford Workshop		TRAILER
T621	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		22/10/2021	731735	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Myrtleford Workshop		TRAILER
T621	Myrtleford - Workshop	Chassis\BOLSTER	move bolsters and winches to suit 3.7 logs			22/10/2021	731375	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Myrtleford Workshop		TRAILER
T621	Albury - Workshop	Tyres\TP1+2	supply and fit 2 tyres			19/10/2021	753413	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Albury Workshop		TRAILER
T621	Wodonga - Workshop	Chassis\FIFTH WHEE	Fit turntable block.			17/10/2021	731312	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonga Workshop		TRAILER
T621	Wodonaa - Workshop	Insp	CHECK OVER.			14/10/2021	731376	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonaa Workshop		TRAILER
T621	Wodonaa - Workshop	Elect\ELECT P&W	NO SCALES SET UP ON TRAILER			14/10/2021		Reapair	Comoleted	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonaa Workshop		TRAILER
T621	Albury - Workshop	Tyres\TP10	Supply and fit 1 tyre			16/03/2021	725413	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Albury Workshop		TRAILER
T621	Albury - Workshop	Elect\ELECT P&W	repair broken and corroded wiring in junction box for tail light circuit as required			10/03/2021		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Albury Workshop		TRAILER
T621	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			07/10/2020	701821	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonga Workshop		TRAILER
T621	Wodonga - Workshop	Body\STRAPS	replace front air ratchet			07/10/2020	701821	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonga Workshop		TRAILER
T621	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		07/10/2020	701821	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonga Workshop		TRAILER
T621	Wodonga - Workshop	Body\LIGHTS	RHR indicator lense damaged			07/10/2020	701821	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonga Workshop		TRAILER
T621	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			11/09/2020	699202	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonga Workshop		TRAILER
T621	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		11/09/2020	699202	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonga Workshop		TRAILER
T621	Wodonga - Workshop	Comp\Truck Safe	no sticker			11/09/2020	699202	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonga Workshop		TRAILER
T621	Albury - Workshop	Chassis\BOLSTER	rotate 2nd bolster pin on L/H side		turned 2nd LH bolster peg and replaced bolt and nut	03/09/2020	177968	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Albury Workshop		TRAILER
T621	Wodonaa - Workshop	Brakes	Record Check Results As Attached To This Job			27/08/2020		Reapair	Comoleted	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonaa Workshop		TRAILER
T621	Wodonaa - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		27/08/2020		Service	Comoleted	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonaa Workshop		TRAILER
T621	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			27/08/2020		Reapair	Comoleted	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonga Workshop		TRAILER
T621	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		27/08/2020		Service	Comoleted	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonga Workshop		TRAILER
T621	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			22/08/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonga Workshop		TRAILER
T621	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		22/08/2020		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonga Workshop		TRAILER
T621	Wodonga - Workshop	Elect	Job Added From Invoice			08/08/2020	0	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonga Workshop		TRAILER
T621	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			07/08/2020	690240	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonga Workshop		TRAILER
			front L & R alignment plates														
			bottom shocker plate														
T621	Wodonga - Workshop	Susp\SPRNG PACK	RM & LM seb			07/08/2020	690240	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonga Workshop		TRAILER
T621	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		07/08/2020	690240	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonga Workshop		TRAILER
T621	Wodonga - Workshop	Elect\TRL LIGHTS	RH clearance lights			07/08/2020	690240	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonga Workshop		TRAILER
T621	Wodonga - Workshop	Comp\Truck Safe	fitted truck safe ordered NHVAS			07/08/2020	690240	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonga Workshop		TRAILER
T621	Wodonga - Workshop	Body\AIR BAG	check airbags for leaks 5 leakig		rapid for parts PO056762. replaced 3 airags RR RM and LR	01/08/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonga Workshop		TRAILER
			front L & R alignment plates														
			bottom shocker plate														
T621	Wodonga - Workshop	Susp\SPRNG PACK	RM & LM seb		parts on order	01/08/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonga Workshop		TRAILER
T621	Wodonga - Workshop	Comp\Truck Safe	No NHVAS sticker			01/08/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonga Workshop		TRAILER
T621	Wodonga - Workshop	Elect\TRL LIGHTS	RH load light not working		fit new light	01/08/2020		Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonga Workshop		TRAILER
T621	Wodonga - Workshop	Chassis\WINCH/STRP	replaced and swap 2 ratchet fix air fittings and hoses			31/07/2020	688921	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonga Workshop		TRAILER
T621	Wodonaa - Workshop	Body\AIR BAG	check airbaas for leaks 5 leakie			20/07/2020	686299	Reapair	Comoleted	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonaa Workshop		TRAILER
T621	Wodonaa - Workshop	Brakes\BRAKE ADJ	ceck whv r/r bosster locked out adiust braks			20/07/2020	686299	Repair	Comoleted	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonaa Workshop		TRAILER
T621	Wodonga - Workshop	Workshop\CLEAN	clean service bay			20/07/2020	686299	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonga Workshop		TRAILER
T621	Wodonga - Workshop	Workshop\MOVE ASSET	move trailers			20/07/2020	686299	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonga Workshop		TRAILER
			front L & R alignment plates														
			bottom shocker plate														
T621	Wodonga - Workshop	Susp\SPRNG PACK	RM & LM seb			18/07/2020	686151	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonga Workshop		TRAILER
T621	Wodonga - Workshop	Chassis\MUDGUARDS	RHR mudflap damaged		Cut bolts off & replaced	18/07/2020	686151	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonga Workshop		TRAILER
T621	Wodonga - Workshop	Body\LIGHTS	RHR indicator broken		Still operational	18/07/2020	686151	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonga Workshop		TRAILER
T621	Wodonga - Workshop	Chassis\MUDGUARDS	LHR mudflap missing		Cut bolts off & replaced	18/07/2020	686151	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonga Workshop		TRAILER
T621	Wodonga - Workshop	Comp\Truck Safe	No NHVAS sticker			18/07/2020	686151	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonga Workshop		TRAILER
T621	Wodonga - Workshop	Chassis\MUDGUARDS	missing mudflap		As per #295355 & #295357	18/07/2020	686151	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonga Workshop		TRAILER
T621	Wodonga - Workshop	DrCabElect\WGHT GAUGE	no scales			18/07/2020	686151	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonga Workshop		TRAILER
T621	Wodonga - Workshop	Elect\TRL LIGHTS	RH load light not working		Wiring torn out of light - parts are on order	18/07/2020	686151	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonga Workshop		TRAILER
T621	Wodonga - Workshop	Susp\AIR BAG	some air bags on left side of trailers don't seem to be inflated			18/07/2020	686151	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonga Workshop		TRAILER
T621	Wodonga - Workshop	Chassis\MUDGUARDS	missing mudflap			09/07/2020	684701	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonga Workshop		TRAILER
T621	Wodonaa - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP		09/07/2020	684701	PreventativeMaintenance	Comoleted	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonaa Workshop		TRAILER
T621	Wodonaa - Workshop	Brakes	Record Check Results As Attached To This Job			09/07/2020		Reapair	Comoleted	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonaa Workshop		TRAILER
			front L & R alignment plates														
			bottom shocker plate														
T621	Wodonga - Workshop	Susp\SPRNG PACK	RM & LM seb		more information needed allianment plates look ok no damaae or cracks bottom shock olate has no damaae sorina eve bushes ok	09/07/2020		Reapair	Comoleted	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonaa Workshop		TRAILER
T621	Wodonaa - Workshop	Chassis\MUDGUARDS	RHR mudflap damaaed			09/07/2020		Reapair	Comoleted	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonaa Workshop		TRAILER
T621	Wodonaa - Workshop	Body\LIGHTS	RHR indicator broken			09/07/2020		Reapair	Comoleted	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonaa Workshop		TRAILER
T621	Wodonga - Workshop	Chassis\MUDGUARDS	LHR mudflap missing			09/07/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonga Workshop		TRAILER
T621	Wodonga - Workshop	Comp\Truck Safe	No NHVAS sticker		office to notify mark bennet	09/07/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonga Workshop		TRAILER
T621	Wodonga - Workshop	DrCabElect\WGHT GAUGE	no scales		driver best person to calibrate weight guage no weigh bridge at wodonga	09/07/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonga Workshop		TRAILER
T621	Wodonga - Workshop	Elect\TRL LIGHTS	RH load light not working		need replacement light by the look of it	09/07/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonga Workshop		TRAILER
T621	Wodonga - Workshop	Chassis\AIR LEAK	have to keep revs up when loading to keep air up?			09/07/2020		Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonga Workshop		TRAILER
T621	Wodonga - Workshop	Susp\AIR BAG	some air bags on left side of trailers don't seem to be inflated			09/07/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonga Workshop		TRAILER
T621	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		09/07/2020		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonga Workshop		TRAILER
T621	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice			03/07/2020	670613	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Albury Workshop		TRAILER
T621	Albury - Workshop	Tyres\CLEANSKIN	Job Added From Invoice			03/07/2020	670613	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Albury Workshop		TRAILER
T621	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice			03/07/2020	670613	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Albury Workshop		TRAILER
T621	Alburv - Workshop	Tyres\CLEANSKIN	Job Added From Invoice			03/07/2020	670613	Repair	Comoleted	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Alburv Workshop		TRAILER
T621	Wodonaa - Workshop	Brakes	Record Check Results As Attached To This Job			23/06/2020	674156	Reapair	Comoleted	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonaa Workshop		TRAILER
T621	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		23/06/2020	674156	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonga Workshop		TRAILER
T621	Wodonga - Workshop	Comp\Truck Safe	No NHVAS sticker			23/06/2020	674156	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonga Workshop		TRAILER
T621	Wodonga - Workshop	Chassis\MUDGUARDS	RHR mudflap damaged			23/06/2020	674156	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonga Workshop		TRAILER
T621	Wodonga - Workshop	Body\LIGHTS	RHR indicator broken			23/06/2020	674156	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonga Workshop		TRAILER
T621	Wodonga - Workshop	Chassis\MUDGUARDS	LHR mudflap missing			23/06/2020	674156	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonga Workshop		TRAILER
T621	Wodonga - Workshop	Body	Job Added From Invoice			20/06/2020	0	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonga Workshop		TRAILER
T621	Wodonga - Workshop	DrCabElect\SCALES	944 scales need adjusting			23/05/2020		Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonga Workshop		TRAILER
T621	Albury - Workshop	DrCabElect\SCALES	checked scales			03/05/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Albury Workshop		TRAILER
T621	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			03/05/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Albury Workshop		TRAILER
T621	Albury - Workshop	VehService\DS	D Service	VehService\DS		03/05/2020		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Albury Workshop		TRAILER
					scales not working												
					checked wiring ok. Power and earth ok												
					found low voltage from truck												
T621	Albury - Workshop	DrCabElect\WGHT GAUGE	no scales		will consult with manufacturer about requirements	21/04/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Albury Workshop		TRAILER
T621	Wodonga - Workshop	Body\ELECT P&W	remove block from skid plate and expose the trailer plug wiring to replace base plug			16/04/2020	650235	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonga Workshop		TRAILER
T621	Wodonga - Workshop	Body\ELECT P&W	replaced base plug and fix wire		and bring 915 to check light and air bag	16/04/2020	650235	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonga Workshop		TRAILER
T621	Albury - Workshop	Brakes	BRAKE TEST RESULTS			24/11/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Albury Workshop		TRAILER
			REPAIRE														
T621	Albury - Workshop	Chassis\AIR LEAK	AIR LEAK			24/11/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Albury Workshop		TRAILER
T621	Albury - Workshop	Susp\SHOCK ABS	TIGHTENED SHOCKERS			24/11/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Albury Workshop		TRAILER
T621	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS		24/11/2019		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Albury Workshop		TRAILER
T621	Albury - Workshop	Brakes				14/11/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Albury Workshop		TRAILER
T621	Albury - Workshop	Elect\INDICATORS	REPLACED L/H INDICTOR			14/11/2019		Reapair	Comoleted	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Albury Workshop		TRAILER
T621	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS		14/11/2019		Service	Comoleted	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Alburv Workshop		TRAILER
T621	Albury - Workshop	Body\AIR BAG	check airbaa dumo valve			17/09/2019		Fault	Comoleted	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Alburv Workshop		TRAILER
T621	Albury - Workshop	Brakes				17/09/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Albury Workshop		TRAILER
T621	Albury - Workshop	VehService\DS	D SERVIES	VehService\DS		17/09/2019		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Albury Workshop		TRAILER
T621	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			10/08/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Albury Workshop		TRAILER
T621	Albury - Workshop	VehService\DS	D Service	VehService\DS		10/08/2019		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Albury Workshop		TRAILER
T621	Wodonga - Workshop	Brakes	Brake test results attached			23/07/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonga Workshop		TRAILER
T621	Wodonga - Workshop	VehService\DS	D Service	VehService\DS		23/07/2019		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonga Workshop		TRAILER
T621	Wodonga - Workshop	Susp\WGHT GAUGE	Fit & calibrate scale unit			16/07/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonga Workshop		TRAILER
T621	Albury - Workshop	Elect\TRL LIGHTS	replaced broken side marker light (RHR)			07/07/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Albury Workshop		TRAILER
T621	Albury - Workshop	Chassis\WINCH/STRP	replaced 2nd winch strap			07/07/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Albury Workshop		TRAILER
T621	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			07/07/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Albury Workshop		TRAILER
T621	Alburv - Workshop	VehService\DS	D Service	VehService\DS		07/07/2019		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Alburv Workshop		TRAILER
T621	Albury - Workshop	Elect\TRL LIGHTS	R/H/S bumoer light broke			06/07/2019		Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Albury Workshop		TRAILER
T621	Albury - Workshop	Chassis\WINCH/STRP	middle bay middle winch strap comes off			06/07/2019		Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Albury Workshop		TRAILER
T621	Wodonga - Workshop	Chassis\WINCH/STRP	Repaired Broken winch handle			03/07/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonga Workshop		TRAILER
T621	Albury - Workshop	Body\DAMAGE	rubber mat damage		chassis mat and wiring damaged by loader	25/06/2019		Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Albury Workshop		TRAILER
T621	Albury - Workshop	Elect\TRL LIGHTS	front bolster light not working		removed mat and repaired wiring to bolsters	25/06/2019		Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Albury Workshop		TRAILER
T621	Wodonga - Workshop	VehService\DS	D service	VehService\DS		22/06/2019		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonga Workshop		TRAILER
T621	Albury - Workshop	DrivLine\WHEEL BRGS	changed R/F seb and L/R			15/06/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Albury Workshop		TRAILER
T621	Albury - Workshop	Susp\CONSUMABLE	R/F boss u/s			15/06/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Albury Workshop		TRAILER
T621	Albury - Workshop	Susp\WHEEL ALGN	HTT wheel align - replaced r/f 30ss			15/06/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Albury Workshop		TRAILER
T621	Albury - Workshop	DrivLine\WHEEL BRGS	press seb x 2			15/06/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Albury Workshop		TRAILER
T621	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			15/06/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Albury Workshop		TRAILER
T621	Albury - Workshop	VehService\DS	D Service	VehService\DS		15/06/2019		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Albury Workshop		TRAILER
T621	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			05/06/2019		Repair	Comoleted	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Alburv Workshop		TRAILER
T621	Albury - Workshop	VehService\DS	Service	VehService\DS		05/06/2019		Service	Comoleted	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Alburv Workshop		TRAILER
T621	Albury - Workshop	Susp\AXLES	replaced lift axle bumper			01/06/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Albury Workshop		TRAILER
T621	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			01/06/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Albury Workshop		TRAILER
T621	Albury - Workshop	VehService\DS	D Service	VehService\DS		01/06/2019		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Albury Workshop		TRAILER

			front L & R alignment plates bottom shocker plate															
T621	Albury - Workshop	Susp\SPRNG PACK	RM & LM seb			17/05/2019	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Albury Workshop	TRAILER			
T621	Albury - Workshop	Tyres\TP01	repair spare tyre carrier			17/05/2019	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Albury Workshop	TRAILER			
T621	Albury - Workshop	Susp\SPRNG PACK	replaced LHM - RHM seb spring eye bush			17/05/2019	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Albury Workshop	TRAILER			
T621	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			17/05/2019	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Albury Workshop	TRAILER			
T621	Albury - Workshop	VehService\DS	D Service	VehService\DS		17/05/2019	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Albury Workshop	TRAILER			
					breakdown at Ironbark truck stop no trailer lights check fuses wiring. Check trailer supply wiring in battery box found 24v fuse to reducer blow. replaced fuse. Blow again bypass, reducer to supply trailer circuit test ok truck returned to Albury pack up parts to repair travel to depot replaced reducer, replaced fuses now supply 12v to trailer return truck to work									
T621	Albury - Workshop	Elect\TRL LIGHTS	no trailer lights		80km travel	09/05/2019	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Albury Workshop	TRAILER			
T621	Albury - Workshop	VehService\DS	D Service	VehService\DS		07/05/2019	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Albury Workshop	TRAILER			
T621	Albury - Workshop	Susp\SUSPENSION	tightened RHF sebolt			07/05/2019	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Albury Workshop	TRAILER			
T621	Albury - Workshop	Susp\SHOCK ABS	tightened LHM shocker bolts			07/05/2019	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Albury Workshop	TRAILER			
T621	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			07/05/2019	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Albury Workshop	TRAILER			
T621	Wodonga - Workshop	Chassis\FIFTH WHEE	Job Added From Invoice			02/05/2019	0	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Wodonga Workshop	TRAILER		
T621	Wodonaa - Workshop	Body\FIFTH WHEE	repair damaae to turn table		reolaced handle bar and horse shoe	02/05/2019	517666	Reoair	Completed	Greenfreight Loaaina Vic	FlatTow	Mt Gambier	STK	013845	Wodonaa Workshoo	TRAILER		
T621	Wodonaa - Workshoo	Chassis\FIFTH WHEE	check turntable		insoect damaaed turntable	01/05/2019	517666	Fault	Completed	Greenfreight Loaaina Vic	FlatTow	Mt Gambier	STK	013845	Wodonaa Workshoo	TRAILER		
T621	Wodonaa - Workshoo	Elect\RADIO	c/o for dav shift to reoair			01/05/2019	517666	Reoair	Completed	Greenfreight Loaaina Vic	FlatTow	Mt Gambier	STK	013845	Wodonaa Workshoo	TRAILER		
T621	Albury - Workshop	Brakes	Record Check Results As Attached To This Job D Service replaced R/R seb			17/04/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Albury Workshop	TRAILER		
T621	Albury - Workshop	VehService\DS	reolaced arease nipples on ballrace	VehService\DS		17/04/2019		Service	Comoleted	Greenfreight Loaaina Vic	FlatTow	Mt Gambier	STK	013845	Albury Workshoo	TRAILER		
					reposition handle bracket													
T621	Myrtleford - Workshop	Body\TRL LEGS	Repair or Replace Trailer Legs		adiust leas	02/04/2019	506608	Reoair	Comoleted	Greenfreight Loaaina Vic	FlatTow	Mt Gambier	STK	013845	Myrtleford Workshoo	TRAILER		
T621	Myrtleford - Workshop	Chassis\WINCH/STRP	fit new quick release latches to trailers			28/03/2019	504515	Reoair	Comoleted	Greenfreight Loaaina Vic	FlatTow	Mt Gambier	STK	013845	Myrtleford Workshoo	TRAILER		
T621	Myrtleford - Workshop	Chassis\WINCH/STRP	fit new quick release cables to trailers			28/03/2019	504515	Reoair	Comoleted	Greenfreight Loaaina Vic	FlatTow	Mt Gambier	STK	013845	Myrtleford Workshoo	TRAILER		
T621	Myrtleford - Workshop	Elect\TRL LIGHTS	clearance light RHS top needs wiring reattached on cab guard move quick release latches down to prevent damage			27/03/2019	504512	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Myrtleford Workshop	TRAILER		
T621	Myrtleford - Workshop	Chassis\WINCH/STRP	repair cables as needed			23/03/2019	502430	Reoair	Comoleted	Greenfreight Loaaina Vic	FlatTow	Mt Gambier	STK	013845	Myrtleford Workshoo	TRAILER		
T621	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			23/03/2019	562430	Reoair	Comoleted	Greenfreight Loaaina Vic	FlatTow	Mt Gambier	STK	013845	Myrtleford Workshoo	TRAILER		
T621	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	tightened LHM spring eye bolt	23/03/2019	562430	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Myrtleford Workshop	TRAILER		
T621	Myrtleford - Workshop	Susp\AIR BAG	Replace LHM Air Bag			15/03/2019	497599	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Myrtleford Workshop	TRAILER		
T621	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			13/03/2019	493085	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Myrtleford Workshop	TRAILER		
T621	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist	VehService\DS	replaced lift axle stopper rubber	13/03/2019	493085	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Myrtleford Workshop	TRAILER		
T621	Myrtleford - Workshop	Chassis\WINCH/STRP	remove middle air winch front bay			08/03/2019	489010	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Myrtleford Workshop	TRAILER		
T621	Myrtleford - Workshop	Brakes\BRAKE ADJ	adjust brakes			08/03/2019	489010	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Myrtleford Workshop	TRAILER		
T621	Myrtleford - Workshop	Chassis\WINCH/STRP	replace log strap latch 2nd winch			03/03/2019	483630	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Myrtleford Workshop	TRAILER		
T621	Myrtleford - Workshop	Susp\SUSPENSION	Replace LHM Spring Eye Bush			02/03/2019	483629	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Myrtleford Workshop	TRAILER		
					fit L&R top side lights make new section 7 core trailer light wiring													
T621	Myrtleford - Workshop	Elect\WORK LIGHT	Move work Lights & Fit 2 X Extra Work Lights		jump cable	02/03/2019	562430	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Myrtleford Workshop	TRAILER		
T621	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			28/02/2019	482284	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Myrtleford Workshop	TRAILER		
T621	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist	VehService\DS		28/02/2019	482284	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Myrtleford Workshop	TRAILER		
T621	Myrtleford - Workshop	Body\HOUSEKEEP	wash trailer and acid wash rimsSUPPLY JACK & W/BRACE			16/02/2019	472684	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Myrtleford Workshop	TRAILER		
T621	Myrtleford - Workshop	Elect\ELECT P&W	reoair and check scales			09/02/2019	472517	Reoair	Completed	Greenfreight Loaaina Vic	FlatTow	Mt Gambier	STK	013845	Myrtleford Workshoo	TRAILER		
T621	Myrtleford - Workshop	Tyres\CTI Drive	remove tyre inflation			23/01/2019	472512	Reoair	Comoleted	Greenfreight Loaaina Vic	FlatTow	Mt Gambier	STK	013845	Myrtleford Workshoo	TRAILER		
T621	Myrtleford - Workshop	Elect\TRL LIGHTS	replace trailer plug			23/01/2019	472512	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Myrtleford Workshop	TRAILER		
T621	Myrtleford - Workshop	Brakes\AIR LEAK	tighten up booster and brake hose clamps			19/01/2019	472510	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013845	Myrtleford Workshop	TRAILER		
					scales need calibrating													
T621	Myrtleford - Workshop	Insp\ANN INSP	Roadworthy Check on Trailer(LS483)(LS513)I5599		2 air winches. rebuil	10/01/2019	472508	Reoair	Comoleted	Greenfreight Loaaina Vic	FlatTow	Mt Gambier	STK	013845	Myrtleford Workshoo	TRAILER		