EquipmentName	Workshop	CodeAndSubCode	Description	Schedule	CompletionComments	DateDone	DistanceDone	Worktype	Workstate	EquipmentOwner	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
T355	Albury - Workshop	DrivLine\AXLE REPLC	Refit front Axle.			16/01/2026	344055	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	Albury Workshop	TRAILER
T355	Albury - Workshop	Tyres\TP1+2	Tyres\TP1+2 (21-22)			13/01/2026	344055	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	BORDER BANDAG PTY LTD - 4	TRAILER
T355	Albury - Workshop	VehService\JDS	VehService\JDS D Service	VehService\JDS		21/12/2025	344055	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	Wodonga Workshop	TRAILER
T355	Albury - Workshop	VehService\JDS	VehService\JDS D Service	VehService\JDS		16/12/2025	344055	Service	Unlocked	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	Wodonga Workshop	TRAILER
T355	Albury - Workshop	Tyres\Punct	Tyres\Punct POS 21			05/12/2025	344055	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	BORDER BANDAG PTY LTD - 4	TRAILER
T355	Albury - Workshop	Tyres\TP11+12	Tyres\TP11+12 (31-32)			05/12/2025	344055	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	BORDER BANDAG PTY LTD - 4	TRAILER
T355	Albury - Workshop	Tyres\TP9+10	Tyres\TP9+10 (29-30)		LOW TREAD	04/12/2025	344055	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	BORDER BANDAG PTY LTD - 4	TRAILER
T355	Albury - Workshop	VehService\JDS	VehService\JDS D Service	VehService\JDS		21/11/2025	344055	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	Wodonga Workshop	TRAILER
T355	Albury - Workshop	VehService\JDS	VehService\JDS D Service	VehService\JDS		13/11/2025	344055	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	Wodonga Workshop	TRAILER
T355	Albury - Workshop	Tyres\TP3+4	Tyres\TP3+4 (23-24)			12/11/2025	344055	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	BORDER BANDAG PTY LTD - 4	TRAILER
T355	Albury - Workshop	Tyres\TP7+8	Tyres\TP7+8 (27-28)			12/11/2025	344055	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	BORDER BANDAG PTY LTD - 4	TRAILER
T355	Albury - Workshop	VehService\JDS	VehService\JDS D Service	VehService\JDS		23/10/2025	344055	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	Wodonga Workshop	TRAILER
T355	Albury - Workshop	Tyres\TP1+2	Tyres\TP1+2 (21-22)			22/10/2025	344055	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	BORDER BANDAG PTY LTD - 4	TRAILER
T355	Albury - Workshop	Tyres\TP5+6	Tyres\TP5+6 (25-26)			22/10/2025	344055	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	BORDER BANDAG PTY LTD - 4	TRAILER
T355	Albury - Workshop	Tyres\Punct	Tyres\Punct POS 29			20/10/2025	344055	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	BORDER BANDAG PTY LTD - 4	TRAILER
T355	Albury - Workshop	Tyres\Punct	Tyres\Punct POS 31			11/10/2025	344055	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	BORDER BANDAG PTY LTD - 4	TRAILER
					Rebuild bolster cylinder new rod etc. 180.00											
					360mm x 1" crome 16.80											
T355	Albury - Workshop	Hydraulics\RAM	REPAIR SPARE BOLSTER RAM		seals	10/10/2025	344055	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	Albury Workshop	TRAILER
T355	Albury - Workshop	Susp\AIR LEAK	Replace Air Line T Piece & Kinked Hose Behind Ride Height Lever			10/10/2025	344055	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	Albury Workshop	TRAILER
T355	Albury - Workshop	Body\STRAPS	Replace 2nd & 3rd quick release cable			08/10/2025	344055	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	Wodonga Workshop	TRAILER
T355	Albury - Workshop	DrCabElec\ELECT P&W	SCALES NOT WORKING.			08/10/2025	344055	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	Wodonga Workshop	TRAILER
T355	Albury - Workshop	VehService\JDS	VehService\JDS D Service	VehService\JDS		08/10/2025	344055	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	Wodonga Workshop	TRAILER
T355	Albury - Workshop	Tyres\Punct	Tyres\Puncture POS 27			26/09/2025	344055	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	BORDER BANDAG PTY LTD - 4	TRAILER
T355	Albury - Workshop	Tyres\TP9+10	Tyres\TP9+10 (29-30)			25/09/2025	344055	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	BORDER BANDAG PTY LTD - 4	TRAILER
T355	Albury - Workshop	Tyres\TP11+12	Tyres\TP11+12 (31-32)			30/08/2025	344055	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	BORDER BANDAG PTY LTD - 4	TRAILER
T355	Albury - Workshop	Body	Front hangers cracked at chassis		Inspected previously done	08/08/2025	344055	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	Albury Workshop	TRAILER
T355	Albury - Workshop	Susp	Rightfofront shock mount broken		Completed in saddle repair	08/08/2025	344055	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	Albury Workshop	TRAILER
T355	Albury - Workshop	Susp	Lhm and rhr spring eye bushes warn no movement with bar but snigs of movment			08/08/2025	344055	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	Albury Workshop	TRAILER
T355	Albury - Workshop	Body	Front cross member bent and chassis mount cracked			08/08/2025	344055	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	Albury Workshop	TRAILER
T355	Albury - Workshop	Susp	Right rear spring eye bush needs replacing		Previously done	08/08/2025	344055	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	Albury Workshop	TRAILER
T355	Albury - Workshop	Susp	Boss saddles cracked on middle Axel		Inspected and welded crack saddles	08/08/2025	344055	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	Albury Workshop	TRAILER
T355	Albury - Workshop	Susp	Front Axel mounts cracked welds		Welded saddle cracks and replaced shockie mounts front axle and welded saddles on middle axle	08/08/2025	344055	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	Albury Workshop	TRAILER
T355	Albury - Workshop	DrivLine\AXLE REPLC	Replace middle axle.			08/08/2025	344055	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	Albury Workshop	TRAILER
T355	Albury - Workshop	VehService\JDS	VehService\JDS D Service	VehService\JDS		22/07/2025	344055	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	Wodonga Workshop	TRAILER
					-checked over scale fault, had missing data plug											
T355	Albury - Workshop	Elect\ELECT P&W	SCALES NOT WORKING		-new plugs made and replaced, scales tested	22/07/2025	344055	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	Wodonga Workshop	TRAILER
T355	Albury - Workshop	Tyres\RUN OUT	Tyres\RUN OUT POS 29			21/07/2025	344055	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	BORDER BANDAG PTY LTD - 4	TRAILER
T355	Albury - Workshop	Body\BOLSTER	Rotate bent pag - 3rd along RHS			09/07/2025	344055	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	Wodonga Workshop	TRAILER
					-lights check done.											
T355	Albury - Workshop	Susp\WIGHT GAUGE	Test scales		-weigh scales checked, dirty plugs in center of chasis	09/07/2025	344055	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	Wodonga Workshop	TRAILER
T355	Albury - Workshop	Body\BOLSTER	Front bolster bent out on the last bay		Rotated 3rd pag along RHS	07/07/2025	344055	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	Wodonga Workshop	TRAILER
T355	Albury - Workshop	Insp\ANN INSP	Insp\ANN INSP	Insp\ANN INSP		03/07/2025	344055	PreventativeMaintenance	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	PACCAR PARTS FLEET SERVICES - 4	TRAILER
T355	Albury - Workshop	VehService\JDS	VehService\JDS D Service (TCTC POWT095238)	VehService\JDS		03/07/2025	344055	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	PACCAR PARTS FLEET SERVICES - 4	TRAILER
T355	Albury - Workshop	VehService\JDS	VehService\JDS D Service	VehService\JDS		18/06/2025	344055	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	Wodonga Workshop	TRAILER
T355	Albury - Workshop	VehService\JDS	VehService\JDS D Service	VehService\JDS		11/06/2025	344055	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	Wodonga Workshop	TRAILER
T355	Albury - Workshop	VehService\JDS	VehService\JDS D Service	VehService\JDS		13/05/2025	344055	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	Wodonga Workshop	TRAILER
T355	Albury - Workshop	Body\DAMAGE	Trailer tie down chain broken			06/05/2025	344055	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	Wodonga Workshop	TRAILER
T355	Albury - Workshop	Tyres\FITMENT	ARRANGED TYRE REPLACEMENT.			28/04/2025	344055	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	Albury Workshop	TRAILER
T355	Myrtleford - Workshop	Tyres\TP5+6	Tyres\TP5+6			27/04/2025	344055	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	BEAUREPAIRES - 3	TRAILER
T355	Myrtleford - Workshop	Tyres\TP09	Tyres\TP09			27/04/2025	344055	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	BEAUREPAIRES - 3	TRAILER
T355	Albury - Workshop	VehService\JDS	VehService\JDS D Service	VehService\JDS		23/04/2025	344055	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	Wodonga Workshop	TRAILER
T355	Albury - Workshop	VehService\JDS	VehService\JDS D Service	VehService\JDS		15/04/2025	344055	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	Albury Workshop	TRAILER
					T355											
					R81-OBM QRC nib 2 24.85 49.70											
					330 air fitt 3 12.85 38.55											
			REPAIR CRACKS		Repairs to skid plate. 212.50											
			REPAIR BOLSTER RAM		Repairs to bolster cylinder. 195.00											
T355	Albury - Workshop	Body\HOUSEKEEP	SUPPLY PARTS		Seal kit and misc	15/04/2025	344055	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	RINLATECH ENGINEERING-3	TRAILER
T355	Myrtleford - Workshop	Susp\WHEEL ALGN	WHEEL ALIGN ALL 3 AXLES			29/03/2025	344055	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	Myrtleford Workshop	TRAILER
T355	Myrtleford - Workshop	VehService\JDS	VehService\JDS	VehService\JDS		15/03/2025	344055	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	Myrtleford Workshop	TRAILER
T355	Myrtleford - Workshop	Susp\AXLES	remove rear axle for s-cam bush repair on both sides and refit			19/02/2025	344055	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	Myrtleford Workshop	TRAILER
T355	Myrtleford - Workshop	Susp\SHOCK ABS	replace lower LH shocker mount stud		removed and replaced stud as needed	24/07/2024	344055	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	Myrtleford Workshop	TRAILER
T355	Myrtleford - Workshop	Susp\AXLES	inspect and replace axle and shocker straps as needed on all axles			21/07/2024	344055	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	Myrtleford Workshop	TRAILER
T355	Myrtleford - Workshop	Brakes\BRK RELINE	carry out full brake reline wash and inspect wheel bearings replace as needed			21/07/2024	344055	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	Myrtleford Workshop	TRAILER
T355	Wodonga - Workshop	VehService\JDS	D Service	VehService\JDS		21/06/2024	344055	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	Wodonga Workshop	TRAILER
T355	Wodonga - Workshop	Insp\ANN INSP	Insp\ANN INSP	Insp\ANN INSP		21/06/2024	344055	PreventativeMaintenance	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	Wodonga Workshop	TRAILER
T355	Myrtleford - Workshop	Brakes\BOOSTER	check and replace brake boosters as needed		inspected and all good	01/06/2024	344055	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	Myrtleford Workshop	TRAILER
T355	Myrtleford - Workshop	Susp\SHOCK ABS	check shockers for looseness and tighten as needed			01/06/2024	344055	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	Myrtleford Workshop	TRAILER
T355	Myrtleford - Workshop	Chassis\WINCH/STRP	replace winch release cables as needed			01/06/2024	344055	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	Myrtleford Workshop	TRAILER
T355	Myrtleford - Workshop	Brakes\EBS FAULTS	carry out EBS valve service			01/06/2024	344055	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	Myrtleford Workshop	TRAILER
T355	Myrtleford - Workshop	Brakes\ABS	check and repair abs/ebs system as needed replace power lead from plug to valve			01/06/2024	344055	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	Myrtleford Workshop	TRAILER
			inspect folding of bolsters and all pivot bushes													
T355	Myrtleford - Workshop	Chassis\BOLSTER	check baw width and adiust as needed			01/06/2024	344055	Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	T899FL	Myrtleford Workshop	TRAILER
T355	Myrtleford - Workshop	Chassis\CROSS MBR	repair broken chassis brace above 2nd axle			01/06/2024	344055	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	Myrtleford Workshop	TRAILER
			replace all reflectors and reflective tape as needed													
T355	Myrtleford - Workshop	Chassis\BOLSTER	inspect and fit SRT tape to bolster oears			01/06/2024	344055	Fault	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	T899FL	Myrtleford Workshop	TRAILER
T355	Myrtleford - Workshop	Elect\WORK LIGHT	inspect and repair no work lights on rear of trailer			01/06/2024	344055	Fault	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	T899FL	Myrtleford Workshop	TRAILER
T355	Myrtleford - Workshop	Body\BOLSTER	remove and crack test all bolster pegs as needed			01/06/2024	344055	Fault	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	T899FL	Myrtleford Workshop	TRAILER
T355	Myrtleford - Workshop	Chassis\WINCH/STRP	replace 4th winch and strap			01/06/2024	344055	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	Myrtleford Workshop	TRAILER
			INTERMITTENTLY NO AIR TO BINDERS - Inspected and found valve for load binders was sticking.													
			Removed valve & replaced with new. Also found some trailer drain cords were leaking. Removed cords													
			& replaced with new. Tightened loose bolts on air tank.													
			Inspect brakes for fault, driver said they were very slow to release. Replaced pressure protection valve													
T355	Myrtleford - Workshop	Body\AIR LEAK	as required.			28/05/2024	344055	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist													
T355	Myrtleford - Workshop	VehService\JDS	PO# L085420	VehService\JDS		20/04/2024	344055	Service	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	T899FL	BARRY MANEY - 3	TRAILER
T355	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			20/04/2024	344055	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	BARRY MANEY - 3	TRAILER
			REPAIR REAR LIGHT - Removed RH Rear light & found to have broken wires at the plug. Replaced													
T355	Myrtleford - Workshop	Elect\TRL LIGHTS	light and clue. ioined wires and tested operation. all ok.			18/04/2024		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	T899FL	BARRY MANEY - 3	TRAILER
			REPAIR TARP OVER WHEELS - tightened each bolt and nut on both ends of the tarp over wheels.													
T355	Myrtleford - Workshop	Body	Reelaced nuts and bolts on LH side tars. tightened.			18/04/2024		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	T899FL	BARRY MANEY - 3	TRAILER
			REPAIR TRAILER SHOCKER - Inspected and found RH middle shocker was missing a bolt & caused													
			damage to shocker. Unbolt bottom of shocker & removed. Installed new shocker and tensioned bolts.													
			Found rear RH bottom mount bolt broken off. Grind back surfaces & cleaned area. Rewelded shocker													
T355	Myrtleford - Workshop	Susp\SHOCK ABS	mount & tensioned bolts.			18/04/2024		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	BARRY MANEY - 3	TRAILER
T355	Myrtleford - Workshop	Tyres\TP1+2	Tyre Position 1 + 2			14/04/2024		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	Albury Workshop	TRAILER
T355	Myrtleford - Workshop	Tyres\TP9+10	Tyre Position 9 + 10			10/04/2024		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	Albury Workshop	TRAILER
T355	Myrtleford - Workshop	Tyres\TP11+12	Tyre Position 11 + 12			10/04/2024		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	Albury Workshop	TRAILER
T355	Myrtleford - Workshop	Tyres\Ww-Tor	9-12			10/04/2024		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	Albury Workshop	TRAILER
T355	Albury - Workshop	Susp\SHOCK ABS	SHOCKER BRACKET BROKEN AGAIN.		LH WHEEL BEARING - Jack & support axle, checked wheel bearing adjustment, all okay	01/04/2024		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	Albury Workshop	TRAILER
T355	Albury - Workshop	Steering\WHEEL BRGS	SHOCKER BRACKET - Grind back area, welded broken shocker bracket as required.			01/04/2024		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	Albury Workshop	TRAILER
			CROSS BRACE CRACKED - Removed cross brace and cleaned all surfaces with grinder. Tack welded cross brace,													
T355	Albury - Workshop	Chassis\CROSS MBR	in position & then welded. Bolted cross brace back in.			01/04/2024		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	T899FL	Albury Workshop	TRAILER
			R&R SHOCKER - Unbolt & remove leaking shocker. Installed new shocker, tensioned bolts. Check over & tightened all													
T355	Albury - Workshop	Susp\SHOCK ABS	other loose bolts.			01/04/2024		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	T899FL	Albury Workshop	TRAILER
T355	Albury - Workshop	Chassis\BOLSTER	BENT BOLSTER PIN - Undo bolts, turned bent pin 180 degrees.			01/04/2024		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	Albury Workshop	TRAILER
			LEAKING AIR BAG - LH rear air bag leaking. Jacked & supported chassis. Disconnect air lines & undo mounting bolts.													
T355	Albury - Workshop	Susp\AIR BAG	Removed air bae & reolaced with new. Connect lines & tightened mountine bolts. Tested for air leaks. okav.			01/04/2024		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	Albury Workshop	TRAILER
T355	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			22/03/2024		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist													
T355	Myrtleford - Workshop	VehService\JDS	PO# L084896	VehService\JDS		22/03/2024		Service	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	T899FL	BARRY MANEY - 3	TRAILER
T355	Myrtleford - Workshop	Tyres\TP7+8	Tyre Position 7 + 8			15/03/2024		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	Albury Workshop	TRAILER
					1) SHOCKER BRACKET BROKEN - LH front shocker loose & worn through shocker bracket,causing surface to be											
T355	Myrtleford - Workshop	Susp\SHOCK ABS	SHOCKER BRACKET BROKEN. NEEDS WELDING.		uneven.Unbolt shocker, grind back surface until flat. Reinstalled shocker with new spacer.	06/03/2024		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	BARRY MANEY - 3	TRAILER
T355	Myrtleford - Workshop	Body\PARC COMP	LONG VEHICLE SIGN NEEDS SECURING.		2)SECURE LONG VEHICLE SIGN - R&R rivets in sign	06/03/2024		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	BARRY MANEY - 3	TRAILER
T355	Myrtleford - Workshop	Brakes\AIR LEAK	3) REPAIR AIR LEAKS - LH rear brake booster hose rubbed though. Cut out section and shorten hose, resecured.		4) LOOSE AIR TANK BOLTS - Retensioned loose air tank bolts.	06/03/2024		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	BARRY MANEY - 3	TRAILER
T355	Myrtleford - Workshop	Elect\ELECT P&W	5) LICENCE PLATE LIGHT N/W - tested wiring, all okay. Removed light & installed new. Joined wiring & mounted.			06/03/2024		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	BARRY MANEY - 3	TRAILER
T355	Myrtleford - Workshop	Chassis\BOLSTER	6)BOLSTER BOLTS - tensioned all bolster bolts as required			06/03/2024		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	BARRY MANEY - 3	TRAILER
T355	Myrtleford - Workshop	Chassis\CHAS CRACK	7) WELD TRAILER CRACKS - cross brace was cracked. Grind back surface & welded over cracks. Checked all secure.			06/03/2024		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	BARRY MANEY - 3	TRAILER
T355	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			02/03/2024		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist													
T355	Myrtleford - Workshop	VehService\JDS	PO# L084433	VehService\JDS		02/03/2024		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	BARRY MANEY - 3	TRAILER
T355	Myrtleford - Workshop	Chassis\BOLSTER	STRAIGHTEN BOLSTER PIN - sand pin to be straightened, previously replaced.			23/02/2024		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	Albury Workshop	TRAILER
T355	Myrtleford - Workshop	Tyres\TP3+4	Tyre Position 3 + 4			21/02/2024		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	Albury Workshop	TRAILER
T355	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			16/02/2024		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist													
T355	Myrtleford - Workshop	VehService\JDS	PO# L084039	VehService\JDS		16/02/2024		Service	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	T899FL	BARRY MANEY - 3	TRAILER
					Back left mud flap bracket missing - Removed broken mud flap and bracket. Source new parts. Cut new											
T355	Myrtleford - Workshop	Body\MUDGUARDS	BACK LEFT MUDFLAP AND BRACKET MISSING.		new mudflap to correct size. mounted new mudflap & bracket. Tightened mountine bolts. all okay.	16/02/2024		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	Albury Workshop	TRAILER
					AIR TAP BINDER NOT RELEASING - Removed air fittings and air binder tap. Change fittings over											
T355	Myrtleford - Workshop	Chassis\EXTE TU	AIR TAP ON 1ST BINDER NOT RELEASING ALL THE AIR. NEED REPLACING.		to new tao and installed. Connect air lines. test operation. all okav.	16/02/2024		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	Albury Workshop	TRAILER
					CLEARANCE LIGHT N/W - Found clearance light had been smashed. Removed light & cut wiring.											
T355	Myrtleford - Workshop	Elect\ELECT P&W	CLEARANCE LIGHT ON REAR LIGHT BAR IS BROKEN (LEFT HAND SIDE)		Tidv us wires. installed new light & ioined wrine. tested. all okav.	16/02/2024		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	Albury Workshop	TRAILER
			REPLACE BETN BOLSTER PIN - Found third LH bolster pin bent. Removed bolt and replaced pin													
T355	Myrtleford - Workshop	Chassis\BOLSTER	with spare. Sand pin to be straightened.			14/02/2024		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	T899FL	Albury Workshop	TRAILER
			A/HRS BREAKDOWN - BOLSTER BOLT BROKEN													
			Arranged to meet driver at workshop. Removed broken bolster bolt from LH front pin & installed new													
T355	Myrtleford - Workshop	Chassis\BOLSTER	Tensioned to spec, all okay.			13/02/2024		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	BARRY MANEY - 3	TRAILER
T355	Myrtleford - Workshop	Tyres\TP5+6	Tyre Position 5 + 6			02/02/2024		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	Albury Workshop	TRAILER
			REMOVE SHOCKER - Found LH front shocker was unserviceable & had also damaged the mount. Remove shocker. Truck													
			needed to go, complete repair at service next day. Straightened out shocker mount, installed new shocker & fit spacer as													
T355	Myrtleford - Workshop	Susp\SHOCK ABS	reauired. Tightened bolts. all okav.			01/02/2024		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	Albury Workshop	TRAILER
T355	Myrtleford - Workshop	Chassis\BOLSTER	TURN BOLSTER - Remove bolster pin, turn pin 180 degrees. Refit mounting bolt, okay.			01/02/2024		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	Albury Workshop	TRAILER
			LH FRONT MUD FLAP & BRACKET NEEDS REPLACING - Undo bolts, removed mud flap and bracket. Installed new &													
T355	Myrtleford - Workshop	Body\MUDGUARDS	refit bolts. tightened to spec.			01/02/2024		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	T899FL	Albury Workshop	TRAILER
			JACK UP & CHECK WHEEL BEARINGS - Jacked up all axles & adjust wheel bearings on all wheels to spec. Lowered													
T355	Myrtleford - Workshop	Steering\WHEEL BRGS	axles, refit caps.			01/02/2024		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	Albury Workshop	TRAILER
T355	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			26/01/2024		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist													
T355	Myrtleford - Workshop	VehService\JDS	PO# L083544	VehService\JDS		26/01/2024		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	T899FL	BARRY MANEY - 3	TRAILER
T355	Myrtleford - Workshop	Tyres\TP1+2	Tyre Position 1 + 2			23/01/2024		Repair	Completed	Greenfreight Logging NSW	Kennedy

T355	Myrtleford - Workshop	Tyres\RUN OUT	5-6 BROKEN TRAILER RAM - Removed damaged hydraulic ram from LH side, second from near.				23/01/2024	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Myrtleford - Workshop	Hydraulics\RAM	Connect hose to trailer fitting to prevent oil leak. Cable tied hose to secure.				17/01/2024	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Myrtleford - Workshop	Chassis\CHAS CRACK	WELD TRAILER CRACKS - sublet repairer to weld trailer cracks, RH side chassis infront of bolster. saturday rate axxlies.				13/01/2024	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Myrtleford - Workshop	Tyres\TP9+10	Tyre Position 9 + 10		REPLACE TARP ON RH OVER WHEELS - Cut off mounting bolts and removed RH tarp over wheels.		12/01/2024	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Myrtleford - Workshop	Body\TRL REPS	TARP NEEDS REPLACING HAD TO RE-SECURE 1 DAY AFTER SERVICE WITH CABLE TIES. NUMEROUS HOLES IN IT (R/H SIDE)		Removed steel plates from old taro and fitted to new taro. Fitted new nuts & bolts. tensioned. all okav.		07/01/2024	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	BARRY MANEY - 3	TRAILER
T355	Myrtleford - Workshop	Elect\WORK LIGHT	REAR BAR WORK LIGHTS NOT WORKING PROPERLY.		working OK on arival		07/01/2024	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	BARRY MANEY - 3	TRAILER
T355	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist				07/01/2024	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	BARRY MANEY - 3	TRAILER
T355	Myrtleford - Workshop	VehService\DS	PO# 1083218	VehService\DS			07/01/2024	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	BARRY MANEY - 3	TRAILER
T355	Myrtleford - Workshop	Tyres\TP9+10	Tyre Position 9 + 10 REPLACE MUD FLAPS		Replaced damaged mud flaps & installed new anti sail brackets.		06/01/2024	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Myrtleford - Workshop	Body\MUDGUARDS	REPLACE TARP ON RH TRI		inspect tarp, all okay, only minor rip. Will replace when hole develops.		02/12/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	BARRY MANEY - 3	TRAILER
T355	Myrtleford - Workshop	DrivLine\WHEEL BRGS	CHECK WHEEL BEARINGS		Jack each axle, removed hub caps. Adjusted bearings to spec. Refit caps		02/12/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	BARRY MANEY - 3	TRAILER
T355	Myrtleford - Workshop	Elect\INDICATORS	RH INDICATOR & BRAKE LIGHT		Test power supply, okay. Removed lights and replaced wiht new		02/12/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	BARRY MANEY - 3	TRAILER
T355	Myrtleford - Workshop	Brakes\BOOSTER	REPLACE BOOSTER		Found LH middle booster leaking. Disconnect lines and removed booster. Change fittings over to new booster. Cut push rod to length & installed.		02/12/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	BARRY MANEY - 3	TRAILER
T355	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				01/12/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	BARRY MANEY - 3	TRAILER
T355	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			01/12/2023	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	BARRY MANEY - 3	TRAILER
T355	Myrtleford - Workshop	Body\BOLSTER	A/HRS BREAK DOWN - BENT BOLSTER		Meet driver at BMG workshop & inspected the bolster. Removed the bolster pin bolt & replaced the bolster pin. Refit bolster pin bolts and tensioned to spec.		17/11/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	BARRY MANEY - 3	TRAILER
T355	Albury - Workshop	Body\MUDGUARDS	RIGHT HAND FRONT MUDGUARD BRACKET IS BROKEN. NEEDS A NEW ONE. WELD CRACKED LH HANGER 1ST AXLE - Found 2 cracks on LH hanger 1st axle. Grind out cracks		RH FRONT GUARD BRACKET BROKEN - Unbolt & removed RH front antisail bracket. Install new bracket and secured.		17/11/2023	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Albury - Workshop	Susp\SPRING HANG	& rewelded. Cleaned surfaces. BOLT MISSING ON REAR BOLSTER RAM - Removed ram and bracket. Install new bolt, refit ram				17/11/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Albury - Workshop	Chassis\BOLSTER	bracket & tensioned. (Ram to be fitted to different trailer.)				17/11/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist				04/11/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	BARRY MANEY - 3	TRAILER
T355	Myrtleford - Workshop	VehService\DS	PO# 1082051	VehService\DS			04/11/2023	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	BARRY MANEY - 3	TRAILER
T355	Albury - Workshop	Chassis\WINCH/STRP	winch repairs				31/10/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Myrtleford - Workshop	Tyres\FITMENT	9+11				26/10/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Myrtleford - Workshop	Body\MUDGUARDS	NEW MUDFLAPS NEED FITTING AND A BRACKET BEHIND THEM SO WIND DOESN'T PUSH THEM AGAINST WHEELS AND BURN EM OUT.		MUD FLAP R&R - Removed worn mud flaps & bracket on front of trailer. Fit new GF mud flaps with new bracket. Tiehtened. all okav.		18/10/2023	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Myrtleford - Workshop	Elect\ELECT P&W	NUMBER PLATE LIGHT NOT WORKING PROPERLY.		NUMBER PLATE LIGHT N/W - inspect & found both number plate lights were damaged. Removed		18/10/2023	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Myrtleford - Workshop	Body\MUDGUARDS	BACK R/H TARP GUARD NEEDS REPLACING BROKEN BOLTS. RH REAR PIVOT BUSH - Jack & support chassis. Attempt to remove pivot bolts, but were seized.		lights & wirina. Installed new lights & run wirina. ioined to tail light supply. Tested. all okav.		18/10/2023	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
			Use oxy to loosen bolt, no good, cut bolt out. Lowered front axle, hangers were bent in. Hit out wear plate from RH side. Lowered spring eyes out of hangers. Removed pivot bush & fit new. Lift back into hanger. Aligned wear plates & fit new pivot bolt. Welded in wear plates. LH wear plates were worn, fit												
T355	Myrtleford - Workshop	Susp\Torque Rod	new. Lift chassis, remove supports. Set ride heiaht. tension bolts.				18/10/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist				18/10/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	BARRY MANEY - 3	TRAILER
T355	Myrtleford - Workshop	VehService\DS	PO# 1081694	VehService\DS			18/10/2023	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	BARRY MANEY - 3	TRAILER
T355	Myrtleford - Workshop	Tyres\FITMENT	1 SCALES DROPPING WEIGHTS INTERMITTENTLY - Found silencers on trailer were blocked.				04/10/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Myrtleford - Workshop	Chassis\SCALES	Removed & replaced with new. Found fitting was broken through air line. Removed t piece fitting & joined in new. Tested, no further air leaks, scales holding.				28/09/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Myrtleford - Workshop	Chassis\BOLSTER	suply parts				27/09/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist				27/09/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
T355	Myrtleford - Workshop	VehService\DS	Barry Maney PO# LOB1276	VehService\DS			27/09/2023	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
T355	Myrtleford - Workshop	Tyres\ROTATION	2-3				18/09/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Myrtleford - Workshop	Chassis\BOLSTER	REPLACE CRACKED BOLSTER - R&R cracked bolster. Wired in clearance lights.				08/09/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Myrtleford - Workshop	Body	MARKER PLATES - Replaced marker plates on rear of trailer		WELD CRACKS - Found multiple cracks in trailer. Grind out & weld cracks, painted.		08/09/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Myrtleford - Workshop	Brakes\BRAKE ADJ	REPLACE LH MIDDLE BRAKE - Jacked axle, removed and replaced brake shoes and drum. Refit wheels. adiust brakes and tensioned wheel nuts.				08/09/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist				06/09/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
T355	Myrtleford - Workshop	VehService\DS	Barry Maney PO# LOB0812	VehService\DS			06/09/2023	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
T355	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist				19/08/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
T355	Myrtleford - Workshop	VehService\DS	Barry Maney PO# LOB0418	VehService\DS			19/08/2023	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
T355	Myrtleford - Workshop	Brakes\BOOSTER	BRAKE RETURN SPRINGS MISSING.jobs done on Dservice refer invoice 368320. BRAKE RETURN SPRINGS MISSING.				19/08/2023	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	BARRY MANEY - 3	TRAILER
T355	Myrtleford - Workshop	Body\MUDGUARDS	MUDFLAPS ON FRONT OF GUARDS NEED FITTING. ON FRONT OF TRUCKI iobs done on D service refer invoice 368320. MUDFLAPS ON FRONT OF GUARDS NEED FITTING. ON				19/08/2023	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	BARRY MANEY - 3	TRAILER
T355	Myrtleford - Workshop	Brakes\BRAKE ADJ	TRAILER BRAKES ON "A" AND "B" TRAILER NEED ADJUSTING.brakes were adiusted on D service refer invoice 368320. TRAILER BRAKES ON "A" AND "B" TRAILER NEED ADJUST				19/08/2023	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	BARRY MANEY - 3	TRAILER
T355	Myrtleford - Workshop	Tyres\TP9+10	Tyre Position 9 + 10				03/08/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Myrtleford - Workshop	Tyres\TP7+8	Tyre Position 7 + 8				01/08/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Myrtleford - Workshop	Tyres\TP7+8	Tyre Position 7 + 8				01/08/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Myrtleford - Workshop	Tyres\TP11+12	Tyre Position 11 + 12				01/08/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Myrtleford - Workshop	Chassis\BOLSTER	AFTER HRS CALL OUT - BROKEN BOLT		Arrange to meet driver at workshop. Removed broken bolster bolt and replaced with new.		01/08/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Myrtleford - Workshop	Tyres\TP09	Tyre Position 9				28/07/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				21/07/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
T355	Myrtleford - Workshop	Elect\TAIL LIGHT	LEFT HAND TAIL LIGHT.				21/07/2023	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
T355	Myrtleford - Workshop	Elect\ELECT P&W	BOTH CLEARANCE LIGHTS ON REAR BUMPER OUT. D Service As Per Attached Checklist				21/07/2023	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
T355	Myrtleford - Workshop	VehService\DS	Barry Maney PO# LO79708	VehService\DS			21/07/2023	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
T355	Myrtleford - Workshop	Tyres\TP5+6	Tyre Position 5 + 6				29/06/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Myrtleford - Workshop	Tyres\TP07	Tyre Position 7				29/06/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				24/06/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
T355	Myrtleford - Workshop	Chassis\CHAS CRACK	TRAILER HAS A CRACK ON THE (B) AT THE BACK RIGHT BEFORE GUARD. D Service As Per Attached Checklist				24/06/2023	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
T355	Myrtleford - Workshop	VehService\DS	Barry Maney PO# LO79185	VehService\DS			24/06/2023	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
T355	Myrtleford - Workshop	Susp\WHEEL ALIGN	TRAILER NEED ALIGN ON ALL WHEELS.				24/06/2023	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
T355	Myrtleford - Workshop	Chassis\CHAS CRACK	TRAILER HAS CRACKS				24/06/2023	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
T355	Myrtleford - Workshop	Brakes	BRAKES VERY NOISY. (CHECK LININGS)				24/06/2023	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
T355	Myrtleford - Workshop	Chassis\AIR LEAK	AIR LEAKS- FRONT AIR TANK.				24/06/2023	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
T355	Myrtleford - Workshop	Susp\AIR BAG	FAR BACK PASSENGER SIDE AIRBAG. (PHOTOS SENT TO JOHN)				24/06/2023	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
T355	Myrtleford - Workshop	Tyres\FITMENT	11				06/06/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Myrtleford - Workshop	Tyres\TP07	puncture repair D Service As Per Attached Checklist				02/06/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Myrtleford - Workshop	VehService\DS	PO# LO78654	VehService\DS			30/05/2023 344055	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	BARRY MANEY - 3	TRAILER
T355	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				30/05/2023 344055	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	BARRY MANEY - 3	TRAILER
T355	Myrtleford - Workshop	Tyres\TP3+4	Tyre Position 3 + 4				17/05/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist				12/05/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
T355	Myrtleford - Workshop	VehService\DS	Barry Maney PO# LO78253 Brakes wont release	VehService\DS			12/05/2023	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
T355	Myrtleford - Workshop	Brakes\BOOSTER	Travel to Mill & inspect fault, RHR booster leaking, cage off booster and airlines to release brakes. Trailer returned to BMG. Removd brake booster & replace with new. Found one barb fittine was leakine. Rvolace fittine. no further leaks				06/05/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
			Remove & crack test Bolsters Remove bolster pins & carry out crack test, results below: LH1 had cracks, replaced pin with spare. RH2 had cracks, replaced pin with spare. LH2 test ok, RH2 test ok. LH3 test ok, RH3 test ok. LH4 found to have cracks replaced pin with spare, RH4 ok.												
T355	Myrtleford - Workshop	Chassis\BOLSTER	Refit pins with new nuts & bolts D Service As Per Attached Checklist				19/04/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Wodonga - Workshop	VehService\DS	Barry Maney PO# LO77835	VehService\DS			18/04/2023 344055	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
T355	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				18/04/2023 344055	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
T355	Myrtleford - Workshop	Tyres\TP1+2	Tyre Position 1 + 2				21/03/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist				15/03/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
T355	Myrtleford - Workshop	VehService\DS	Barry Maney PO# LO77236	VehService\DS			15/03/2023	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
T355	Myrtleford - Workshop	Chassis\EXTE TU	REPLACED WINCH TAP HANDLE.				01/03/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
T355	Myrtleford - Workshop	Chassis\BOLSTER	Bolster				23/02/2023 344055	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Albury - Workshop	Tyres\TP9+10	Tyre Position 9 + 10				12/02/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist				11/02/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	BARRY MANEY - 3	TRAILER
T355	Myrtleford - Workshop	VehService\DS	PO# LO76614	VehService\DS			11/02/2023	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	BARRY MANEY - 3	TRAILER
T355	Myrtleford - Workshop	Tyres\TP01	Tyre Position 1				25/01/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Myrtleford - Workshop	Tyres\TP7+8	Tyre Position 7 + 8				25/01/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				21/01/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
T355	Myrtleford - Workshop	DrivLine\SPLINE	STEERING WHEEL AT 10 TO 2.				21/01/2023	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
T355	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			21/01/2023	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
T355	Myrtleford - Workshop	Steering	STEERING RUNS BUSH TO THE LEFT Replace rear marker plates				21/01/2023	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
T355	Myrtleford - Workshop	Body	Suzuliv and fit new rear marker olates				03/12/2022 257383	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Myrtleford - Workshop	Tyres\TP11+12	Tyre Position 11 + 12				01/12/2022 257383	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist				25/11/2022 257383	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
T355	Myrtleford - Workshop	VehService\DS	Barry Maney PO# LO75314 booster broken off rear axle.	VehService\DS			25/11/2022 257383	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
T355	Myrtleford - Workshop	Brakes\BOOSTER	Booster & fittings & hose				18/11/2022 257383	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist				10/11/2022 257383	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
T355	Myrtleford - Workshop	VehService\DS	Barry Maney PO# LO75039	VehService\DS			10/11/2022 257383	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
T355	Myrtleford - Workshop	Tyres\TP3+4	Tyre Position 3 + 4				03/11/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
T355	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist				21/10/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
T355	Myrtleford - Workshop	VehService\DS	Barrv Maney PO# LO74689	VehService\DS			21/10/2022	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
T355	Myrtleford - Workshop	Susp\AIR LEAK	log hit module & bent bracket, leaking air, remove cover and bracket & replace valve, raise/lower straighten bracket & refit air leak				15/10/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
T355	Myrtleford - Workshop	Susp\HCV	inspected . found ride heiaht was u/s. replaced heiaht valve. adiusted. all ok				08/10/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
T355	Myrtleford - Workshop	Elect\ELECT P&W	Lights flickering repaired shorted wiring clearance light replace LH tail lights half LED 's out				21/09/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
T355	Myrtleford - Workshop	Tyres\TP9+10	supply and fit 2 tyres				21/09/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
T355	Myrtleford - Workshop	Tyres\Re-Tor	Re-Torque				13/09/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
T355	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist				08/09/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
T355	Myrtleford - Workshop	VehService\DS	Barry Maney PO# LO73929	VehService\DS			08/09/2022	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
T355	Myrtleford - Workshop	Elect\BRK LIGHT	SHORT IN REAR TAIL LIGHT CLUSTER. (3 OR 4 BRAKE LIGHTS ON THEN GO OFF AND ON WHEN HITTING BUMPS)				30/08/2022	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
T355	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				30/08/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER

			2ND BOLSTER TO HAVE NYLON BLOCK PUT UNDER TO STRAIGHTEN UP RIGHT "B" NOT "A"																
T355	Myrtleford - Workshop	Chassis\BOLSTER	NYLON BLOCK NOT WORN. ISSUE IS NO HYDRALICS TO HOLD BOLSTER UP.			30/08/2022		Repair	Comoleted	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
T355	Myrtleford - Workshop	Elect\BRK LIGHT	BRAKE LIGHTS FLICKER OFF AND ON WITH TAIL LIGHTS.			30/08/2022		Fault	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist																
T355	Myrtleford - Workshop	VehService\DS	Barry Maney POH L073752	VehService\DS		30/08/2022		Service	Comoleted	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
					Replace rubber mudguard, rubber supplied bolted up & tension using new bolts														
T355	Albury - Workshop	Body\MUDGUARDS	L/H GUARD (MAT COVERING ALL 3 TYRES) NEEDS REPLACING.		Rubber strip euard above 3 wheels	24/08/2022		Repair	Comoleted	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Albury - Workshop	Body\MUDGUARDS	MISSING MUDGUARD LHS.			24/08/2022		Fault	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Myrtleford - Workshop	Brakes\BOOSTER	Brake booster leaking remove & replace. Also repair another booster line			16/08/2022		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	BARRY MANEY - 3	TRAILER
					ELPHINSTONE TO SUPPLY PARTS														
T355	Myrtleford - Workshop	DrCabElect\SCALES	SCALES TRANSDUCER FAULTY REQUIRES REPLACEMENT		PO # L073230	29/07/2022 344055		Repair	Comoleted	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
T355	Myrtleford - Workshop	Tyres\TP9+10	supply and fit 2tyres			14/07/2022		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
					barry maney group warrnambool POww072833														
T355	Wodonga - Workshop	Brakes\DAMAGE	LH rear set of duels have came off		replace rear axle assembly drum to drum	13/07/2022		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
T355	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			13/07/2022		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
T355	Myrtleford - Workshop	Body\MUDGUARDS	L/H GUARD (MAT COVERING ALL 3 TYRES) NEEDS REPLACING.		CABLE TIED TOGETHER. NO MAT SUPPLY.	13/07/2022		Fault	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
T355	Myrtleford - Workshop	Chassis\BOLSTER	2ND BOLSTER TO HAVE NYLON BLOCK PUT UNDER TO STRAIGHTEN UP RIGHT "B" NOT "A"			13/07/2022		Fault	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist																
T355	Myrtleford - Workshop	VehService\DS	Barry Maney POH L072891	VehService\DS		13/07/2022		Service	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
			Lost Duals in Transit																
			Barry Maney Attended.																
T355	Wodonga - Workshop	DrivLine\WHEEL BRGS	POH WWO72833			13/07/2022		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
T355	Myrtleford - Workshop	DrCabElect\UNIT/GAUGE	Replace raise/lower valve on trailer			25/06/2022		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
T355	Myrtleford - Workshop	DrCabElect\SCALES	Repair wiring to scales, replace filter			25/06/2022		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
T355	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			23/06/2022		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist																
T355	Myrtleford - Workshop	VehService\DS	PO # L072546	VehService\DS		23/06/2022		Service	Comoleted	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
T355	Myrtleford - Workshop	Body\ELECT P&W	Reverse buzzer not working trace fault to B Trailer LH rear reverse light wiring rubbed & shorted to parker light wiring, repair wiring & isolate, rassumable and tested ok			10/06/2022		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
T355	Albury - Workshop	Tyres\TP7+8	supply and fit 2tyres			07/06/2022		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Myrtleford - Workshop	Chassis\BOLSTER	TCTC supply parts		Removed pins from bolster, unbolted and removed bolster, run cable and installed lights yo new bolster. Fit new bolster and wired in lights. Refit bolster pi	03/06/2022		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
T355	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			02/06/2022		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist																
T355	Myrtleford - Workshop	VehService\DS	Barry Maney POH L072194	VehService\DS		02/06/2022		Service	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
T355	Myrtleford - Workshop	Elect\TRL LIGHTS	Repair broken wiring in rear & clearance lights			28/05/2022		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
T355	Albury - Workshop	Tyres\TP5+6	supply and fit 2tyres			26/05/2022		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			20/05/2022		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist																
T355	Myrtleford - Workshop	VehService\DS	PO # L071878	VehService\DS		20/05/2022		Service	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
T355	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			05/05/2022		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist																
T355	Myrtleford - Workshop	VehService\DS	Barry Maney POH L071612	VehService\DS		05/05/2022		Service	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
T355	Myrtleford - Workshop	Tyres\TP3+4	fit 4 tyres and 1 tyre rotation			27/04/2022		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
T355	Myrtleford - Workshop	Tyres\TP9+10	Tyre Position 9 + 10			27/04/2022		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
T355	Myrtleford - Workshop	Tyres\TP05	Tyre Position 5			27/04/2022		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
			D Service As Per Attached Checklist																
T355	Myrtleford - Workshop	VehService\DS	Barry Maney POH L071362	VehService\DS		20/04/2022 344055		Service	Comoleted	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
T355	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			20/04/2022 344055		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
T355	Myrtleford - Workshop	Tyres\TP11+12	supply and fit 2tyres			09/04/2022		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
T355	Albury - Workshop	Tyres\TP1+2	supply and fit 4 tyres and one tyre rotation			09/04/2022		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
T355	Albury - Workshop	Tyres\TP11+12	Tyre Position 11 + 12			09/04/2022		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
T355	Albury - Workshop	Tyres\TP09	Tyre Position 9			09/04/2022		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
T355	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			09/04/2022		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist																
T355	Myrtleford - Workshop	VehService\DS	Barry Maney POH L071117	VehService\DS		09/04/2022		Service	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
T355	Myrtleford - Workshop	Steering\WHEEL BRGS	Remove and repack all wheel bearings, replace all seal & washers			09/04/2022		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
T355	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			22/03/2022		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist																
T355	Myrtleford - Workshop	VehService\DS	Barry Maney POH L070808	VehService\DS		22/03/2022		Service	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
T355	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			08/03/2022		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist																
T355	Myrtleford - Workshop	VehService\DS	Barry Maney POH L070571	VehService\DS		08/03/2022		Service	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
T355	Myrtleford - Workshop	Tyres\TP07	puncture repair			02/03/2022		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
			D Service As Per Attached Checklist																
T355	Myrtleford - Workshop	Chassis\DS	PO # L070298			22/02/2022		Service	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
T355	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			22/02/2022		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
T355	Albury - Workshop	Brakes\ABS	ABS LIGHT ON PLUG IN B TRAILER FAULT A1 SENSOR REMOVE PLATE WIRING VERY LIGHT LEAD OK, CHECK AIR GAP REPOSITION LOOM, FAULT CLEARED			16/02/2022 138918		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Albury - Workshop	Tyres\TP04	supply and fit 1tyre - tyre rotation on pos 1;2;3			15/02/2022		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
T355	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			03/02/2022		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist																
T355	Myrtleford - Workshop	VehService\DS	PO # L069936	VehService\DS		03/02/2022		Service	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
T355	Myrtleford - Workshop	Tyres\TP11+12	supply and fit 2 tyres			26/01/2022		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
T355	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			14/01/2022		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist																
T355	Myrtleford - Workshop	VehService\DS	O/N L12880	VehService\DS		14/01/2022		Service	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	BARRY MANEY - 3	TRAILER
T355	Myrtleford - Workshop	Tyres\TP12	fit runout			05/01/2022		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
T355	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			18/12/2021		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist																
T355	Wodonga - Workshop	VehService\DS	O/N L12810	VehService\DS		18/12/2021		Service	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	BARRY MANEY - 3	TRAILER
T355	Myrtleford - Workshop	Tyres\TP7+8	supply and fit 2 tyres			10/12/2021		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
T355	Myrtleford - Workshop	Tyres\TP1+2	supply and fit 2 tyres			09/12/2021		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
T355	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			04/12/2021		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist																
T355	Myrtleford - Workshop	VehService\DS	O/N L12734	VehService\DS		04/12/2021		Service	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	BARRY MANEY - 3	TRAILER
T355	Albury - Workshop	Tyres\TP3+4	fit 2 runouts			01/12/2021		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			24/11/2021		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist																
T355	Myrtleford - Workshop	VehService\DS	O/N L 12659	VehService\DS		24/11/2021		Service	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	BARRY MANEY - 3	TRAILER
T355	Myrtleford - Workshop	Tyres\TP5+6	supply and fit 4 tyres			18/11/2021		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
T355	Myrtleford - Workshop	Tyres\TP9+10	Tyre Position 9 + 10			18/11/2021		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
T355	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			17/11/2021		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist																
T355	Myrtleford - Workshop	VehService\DS	O/N L12616	VehService\DS		17/11/2021		Service	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	BARRY MANEY - 3	TRAILER
T355	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			06/11/2021		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist																
T355	Myrtleford - Workshop	VehService\DS	O/N L12554B	VehService\DS		06/11/2021		Service	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	BARRY MANEY - 3	TRAILER
			removed and replaced LH spring																
T355	Myrtleford - Workshop	Susp\SPRING PACK	check and correct ride haight			31/10/2021		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
T355	Myrtleford - Workshop	Tyres\TP06	fit runout			30/10/2021		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
T355	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			30/10/2021		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist																
T355	Myrtleford - Workshop	VehService\DS	ORDER # L12511	VehService\DS		30/10/2021		Service	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	BARRY MANEY - 3	TRAILER
T355	Myrtleford - Workshop	Body\AIR LEAK	air leak, hose between air tanks, replace hose			29/10/2021		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
T355	Albury - Workshop	Tyres\TP08	supply and fit 1 tyre			29/10/2021 723369		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			26/10/2021		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist																
T355	Myrtleford - Workshop	VehService\DS	O/N L12459	VehService\DS		26/10/2021		Service	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	BARRY MANEY - 3	TRAILER
T355	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			16/10/2021		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist																
T355	Myrtleford - Workshop	VehService\DS	O/N L12424	VehService\DS		16/10/2021		Service	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	BARRY MANEY - 3	TRAILER
T355	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			06/10/2021		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist																
T355	Myrtleford - Workshop	VehService\DS	O/N L12367	VehService\DS		06/10/2021		Service	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	BARRY MANEY - 3	TRAILER
T355	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			28/09/2021		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist																
T355	Myrtleford - Workshop	VehService\DS	L12295	VehService\DS		28/09/2021		Service	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	BARRY MANEY - 3	TRAILER
T355	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			21/09/2021		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist																
T355	Myrtleford - Workshop	VehService\DS	O/N L12252	VehService\DS		21/09/2021		Service	Comoleted	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	BARRY MANEY - 3	TRAILER
T355	Myrtleford - Workshop	Susp\AIR BAG	replaced RH middle airbag (holed)			17/09/2021 698010		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
			replacing RHR was also leaking																
T355	Myrtleford - Workshop	Susp\AIR BAG	2 baes reolaced			17/09/2021 698010		Repair	Comoleted	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
T355	Myrtleford - Workshop	Tyres\TP11+12	supply and fit 2 tyres			15/09/2021		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
T355	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			10/09/2021		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist																
T355	Myrtleford - Workshop	VehService\DS	ORDER # L12213	VehService\DS		10/09/2021		Service	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	BARRY MANEY - 3	TRAILER
T355	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			31/08/2021		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist																
T355	Myrtleford - Workshop	VehService\DS	O/N L12143	VehService\DS		31/08/2021		Service	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	BARRY MANEY - 3	TRAILER
T355	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			24/08/2021		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
			D Service As Per Attached Checklist																
T355	Myrtleford - Workshop	VehService\DS	O/N L 12110	VehService\DS		24/08/2021		Service	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
T355	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			07/08/2021		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist																
T355	Myrtleford - Workshop	VehService\DS	ORDER # L12040	VehService\DS		07/08/2021		Service	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	BARRY MANEY - 3	TRAILER
T355	Myrtleford - Workshop	Tyres\TP9+10	Supply and fit 2 tyres			05/08/2021		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
T355	Myrtleford - Workshop	Chassis\WINCH/STRP	Replace 3x load strap			15/07/2021		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
T355	Myrtleford - Workshop	Elect\ELECT P&W	repair trailer wiring			15/07/2021		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
T355	Myrtleford - Workshop	Body\PAINT/REST	wash			15/07/2021		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
T355	Myrtleford - Workshop	Elect\ELECT P&W	replace trailer electrical plugs at rear			15/07/2021		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
T355	Myrtleford - Workshop	Chassis\BOLSTER	repair bolster pivots			15/07/2021		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
T355	Myrtleford - Workshop	Brakes\DAMAGE	replace damaged suspension control valve			15/07/2021		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
T355	Myrtleford - Workshop	Body\PAINT/REST	paint T355 bolster			15/07/2021		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
T355	Myrtleford - Workshop	Chassis\BOLSTER	rebush bolster pivots			15/07/2021		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
T355	Myrtleford - Workshop	Body\PAINT/REST	wash trailer			15/07/2021		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
T355	Myrtleford - Workshop	Body\MUDGUARDS	adjust mudguard			15/07/2021		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
T355	Myrtleford - Workshop	Susp\WHEEL ALGN	wheel align all 3 axles			13/07/2021		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
T355	Myrtleford - Workshop	Susp\BRK RELINE	completed brake reline on 3 axles			10/07/2021		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
T355	Myrtleford - Workshop	Susp\SHOCK ABS	replace middle axle shocks			10/07/2021		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
T355	Myrtleford - Workshop	Body\MUDGUARDS	replaced mudflaps			10/07/2021		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
T355	Myrtleford - Workshop	Chassis\BOOSTER	shortened booster rod			10/07/2021		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
T355	Myrtleford - Workshop	Chassis\DAMAGE	Aldonga repaired cracks			10/07/2021		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
T355	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			10/07/2021		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
T355	Myrtleford - Workshop	VehService\DS	complete D.Service	VehService\DS		10/07/2021		Service	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			17/06/2021		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	D Service	VehService\DS		17/06/2021		Service	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER

T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			01/06/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\JDS	D Service	VehService\JDS		01/06/2021	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			08/05/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\JDS	D Service	VehService\JDS		08/05/2021	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
			change bolster ram												
			heat to remove end of ram												
			remove block												
			fit to new ram												
			install ram												
T355	Rosewood - Workshop	Hydraulics\RAM	check operation			06/05/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Tyres\TP3+4	Supply and fit 2 tyres			29/04/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			23/04/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
			D Service		D Service										
T355	Rosewood - Workshop	VehService\JDS	blown air bag	VehService\JDS	replace RHR airbag, blown	23/04/2021	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Elect\TRL LIGHTS	2nd last bolster lights and left back bolster light very dull			17/04/2021	Fault	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes\BRK RELINE	completed reline on LHM and LHR wheels			13/04/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Chassis\BOLSTER	replace bent/cracked peg from loader at Hyne Mill			08/04/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\JDS	D Service Due	VehService\JDS		07/04/2021	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			07/04/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\JDS	D Service	VehService\JDS		07/04/2021	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\JDS	Service	VehService\JDS		25/03/2021	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Tyres\TP1+2	Supply and fit 2 tyres			13/03/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Tumut - Workshop	Susp\SUSPENSION	prepare and weld cracks in suspension			13/03/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
T355	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job			13/03/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
			D Service												
T355	Tumut - Workshop	VehService\JDS	oreoare cracks in chassis weld cracks	VehService\JDS		13/03/2021	Service	Comoleted	Greenfreight Loaxine NSW	Kennedy\BPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
					CARRY OUT GREENFREIGHT LOG TRAILER D-SERVICE AS PER ATTACHED SERVICE SHEET.										
					12/03/2021										
					DURING SEVRICE:										
T355	Rosewood - Workshop	VehService\JDS	D Service Due	VehService\JDS	* Prepare cracks in chassis weld cracked	12/03/2021	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Tyres\TP9+10	Supply and fit 2 tyres			11/03/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			02/03/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\JDS	carried out D Service	VehService\JDS		02/03/2021	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
			intermittent tail lights not working												
T355	Rosewood - Workshop	Elect\TRL LIGHTS	repair oaen circuit. door connection at trailer dlue			02/03/2021	Repair	Comoleted	Greenfreight Loaxine NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			19/02/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
T355	Myrtleford - Workshop	VehService\JDS	D Service	VehService\JDS		19/02/2021	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
T355	Rosewood - Workshop	Tyres\TP5+6	replace 2 tyres			12/02/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
T355	Rosewood - Workshop	Tyres\TP7+8	replace 2 tyres			12/02/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
					2nd bay bolster bent										
T355	Rosewood - Workshop	Chassis\BOLSTER	2nd bay bolster peg bent		turn bolster 180°	11/02/2021	Fault	Comoleted	Greenfreight Loaxine NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			09/02/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\JDS	D Service fit bolster ram	VehService\JDS		09/02/2021	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
			broken pisel on bolster												
T355	Tumut - Workshop	Chassis\BOLSTER	chanee aistel			06/02/2021	Repair	Comoleted	Greenfreight Loaxine NSW	Kennedy\BPW	Albury	ATK	TB99FL	Tumut Workshoa	TRAILER
T355	Rosewood - Workshop	Tyres\TP11	replaced tyre		Bolted on by driver	06/02/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
T355	Rosewood - Workshop	VehService\JDS	D Service Due	VehService\JDS		21/01/2021	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Body\REFLECTORS	refit long vehicle sign			20/01/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes\RETREAD	replace LHR wheel speed sensor			15/01/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Tyres\TP9+10	replace 2 tyres			07/01/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			31/12/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\JDS	D Service & RELINE REAR AXLE &LHM & RHF	VehService\JDS		31/12/2020	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\JDS	D Service	VehService\JDS		30/12/2020	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Chassis\WINCH/STRP	air tap on 3rd winch loose and leaking			15/12/2020	Fault	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\JDS	D Service Due	VehService\JDS		15/12/2020	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			08/12/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	TWIN CITY TRUCK CENTRE - 4 - OLD	TRAILER
			D Service As Per Attached Checklist												
T355	Myrtleford - Workshop	VehService\JDS	ORDER # 810326	VehService\JDS		08/12/2020	Service	Comoleted	Greenfreight Loaxine NSW	Kennedy\BPW	Albury	ATK	TB99FL	TWIN CITY TRUCK CENTRE - 4 - OLD	TRAILER
T355	Rosewood - Workshop	VehService\JDS	D Service Due	VehService\JDS		05/12/2020	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Body\WHL HUB	check and adjust all wheel bearings			25/11/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Susp\HOUSEKEEP	tighten spring eye bolts and u-bolts			25/11/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\JDS	D Service	VehService\JDS		25/11/2020	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\JDS	D Service Due	VehService\JDS		14/11/2020	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
			replace height control valve												
			repair linkages to HCV and set ride height												
T355	Rosewood - Workshop	Susp\HCV	advise driver of likely/hood of scales being affected			03/11/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Elect\TRL LIGHTS	repair bad connection at front bolster wiring			23/10/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\JDS	D Service	VehService\JDS		23/10/2020	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			23/10/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Susp\HCV	repair ride height control valve mounting and rod			16/10/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Tyres\FITMENT	Job Added From Invoice			02/10/2020 1	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Tyres\CLEANSKIN	Job Added From Invoice			02/10/2020 1	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Tyres\DAMAGE	driver changed damaged rim by hidden rock in bush			29/09/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Wodonga - Workshop	Body\REFLECTORS	Job Added From Invoice			27/09/2020 0	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
T355	Rosewood - Workshop	Tyres\BREAKDOWN	replace flat tyre			26/09/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Tumut - Workshop	Chassis\HOUSEKEEP	welded up cracks			16/09/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
T355	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job			16/09/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
T355	Tumut - Workshop	VehService\JDS	carried out D Service	VehService\JDS		16/09/2020	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			05/09/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\JDS	D Service	VehService\JDS		05/09/2020	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Hydraulics\RAM	hydraulic leak on ram			26/08/2020	Fault	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\JDS	D Service Due	VehService\JDS		25/08/2020	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			25/08/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\JDS	D Service	VehService\JDS		25/08/2020	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\JDS	D Service	VehService\JDS		13/08/2020	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			13/08/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Body\STCH GUARD	LH stretch guard			04/08/2020	Fault	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Elect\WORK LIGHT	work lights			04/08/2020	Fault	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\JDS	Service Trailer	VehService\JDS		04/08/2020	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Chassis\BOLSTER	try to turn RHR bolster pin, siezed in place			30/07/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			30/07/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\JDS	D Service	VehService\JDS		30/07/2020	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Chassis\WINCH/STRP	replace 2 rear bay straps			22/07/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			22/07/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\JDS	D Service	VehService\JDS		22/07/2020	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
					replace bent bolster peg. Damaged by Sam at Hyne Tumba when unloading										
T355	Rosewood - Workshop	Chassis\DAMAGE	bent peg n third bay left side loader at Hyne damaged		siezed bolt retaining bolster	17/07/2020	Fault	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Susp\SHOCK ABS	weld on new lowwer RHR check mount and fit new shock			11/07/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			11/07/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\JDS	D Service	VehService\JDS		11/07/2020	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			10/07/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\JDS	D Service	VehService\JDS		10/07/2020	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Body\STCH GUARD	replace LH stretch guard			05/07/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Elect\WORK LIGHT	replace work lights with flush mount type and repair wiring			05/07/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			05/07/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\JDS	D Service	VehService\JDS		05/07/2020	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes\BRK RELINE	reline all 6 brakes as needed with Zac and Colby from TCTC			02/07/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			02/07/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\JDS	D Service	VehService\JDS		02/07/2020	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Body\AIR LEAK	replace air line at winch, damaged by loader			29/06/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Myrtleford - Workshop	Body\MUDGUARDS	Right Side Guard Tarp Ripped			23/06/2020	Fault	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
T355	Myrtleford - Workshop	Body\STCH GUARD	RH stretch guard			23/06/2020	Fault	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
T355	Rosewood - Workshop	Susp\SUSPENSION	Replace LHR spring eye bush			18/06/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To this Job			18/06/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\JDS	D Service	VehService\JDS		18/06/2020	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			10/06/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\JDS	D Service	VehService\JDS		10/06/2020	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Chassis\CROSS MBR	cracks on load ramps in front of front axle			28/05/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Susp\SPRING HANG	LHF spring hanger box badly cracked			28/05/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Susp\DAMAGE	needs RHR lower shock mount			28/05/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			28/05/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\JDS	Service	VehService\JDS		28/05/2020	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			22/05/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\JDS	D Service	VehService\JDS		22/05/2020	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\JDS	D Service	VehService\JDS		21/05/2020	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			13/05/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\JDS	D Service	VehService\JDS		13/05/2020	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Chassis\BOLSTER	replace 2nd on left side Ned Kelly pistol			12/05/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Body\STCH GUARD	RH stretch guard			12/05/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\JDS	D Service Due	VehService\JDS		12/05/2020	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
			LUBE WINCHES.												
T355	Myrtleford - Workshop	Chassis\WINCH/STRP	ORIDERED NEW END CAPS.		winches checked on Service ok	02/05/2020	Repair	Comoleted	Greenfreight Loaxine NSW	Kennedy\BPW	Albury	ATK	TB99FL	Myrtleford Workshoa	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			01/05/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\JDS	Service	VehService\JDS		01/05/2020	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes\AIR LEAK	left brake booster leaking on second axle			21/04/2020	Fault	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes\BOOSTER	replace middle axle brake chambers			21/04/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			21/04/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\JDS	Service	VehService\JDS		21/04/2020	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			08/04/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\JDS	D Service	VehService\JDS		08/04/2020	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			02/04/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	TWIN CITY TRUCK CENTRE - 4 - OLD	TRAILER
			D Service As Per Attached Checklist												
T355	Rosewood - Workshop	VehService\JDS	ORDER # R8249	VehService\JDS		02/04/2020	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	TWIN CITY TRUCK CENTRE - 4 - OLD	TRAILER
T355	Rosewood - Workshop	Susp\SHOCK ABS	replace RHR lower shock mount			01/04/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
			recheck all brake %												
T355	Rosewood - Workshop	Brakes\BRK O/HAUL	ll at 50%			01/04/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			21/03/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\JDS	D Service	VehService\JDS		21/03/2020	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes\SLACK ADJ	Replace LHR Slack Adjuster			21/03/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			13/03/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\JDS	Service	VehService\JDS		13/03/2020	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached to This Job			06/03/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\JDS	D Service	VehService\JDS		06/03/2020	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			03/03/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER

T355	Rosewood - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		03/03/2020	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			20/02/2020	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
			D Service												
T355	Rosewood - Workshop	VehService\DS	reslace multisle brake booster return sorines	VehService\DS		20/02/2020	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			13/02/2020	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	D Service	VehService\DS		13/02/2020	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Elect\WORK LIGHT	LH Worklight not working			01/02/2020	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			30/01/2020	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
			Service												
T355	Rosewood - Workshop	VehService\DS	tiahten LHC SEB	VehService\DS		30/01/2020	Service	Comsleted	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Elect\TAIL LIGHT	replace side light tail light reverse light			22/01/2020	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Albury - Workshop	Body\LIGHTS	repaired RH indicator			11/01/2020	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Rosewood - Workshop	Elect\TRL LIGHTS	PO to replace led rear light ass			10/01/2020	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
T355	Rosewood - Workshop	Brakes\BOOSTER	po for 3030 booster			10/01/2020	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
					locate air leak remove replace rear axle LH brake booster check										
T355	Albury - Workshop	Brakes\BOOSTER	replace booster		re-set brake	09/01/2020	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Albury - Workshop	Body\ELECT P&W	repair inoperative LH indicator and wiring			08/01/2020	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Brake test results			24/12/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	D service	VehService\DS		24/12/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	TEST RESULTS			30/11/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	D SERVICE	VehService\DS		30/11/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	BRAKE TEST RESULTS			22/11/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	D SERVICE	VehService\DS		22/11/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Albury - Workshop	Elect\WORK LIGHT	work lights not working			20/11/2019	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Albury - Workshop	VehService\AS	A Service			20/11/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Albury - Workshop	Chassis\BOLSTER	FOUND 3RD R/H BOLSTER PEG SEVERELY BENT		REPLACED PEG	14/11/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Albury - Workshop	Chassis\WINCH/STRP	REPAIRED LEAKING 1ST WINTCH		LUBE ALL WITCHES	12/11/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Albury - Workshop	Brakes				08/11/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Albury - Workshop	Chassis\BOLSTER	CRACKS IN 1ST & 4TH BOLSTERS			08/11/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Albury - Workshop	Tyres\TPD2	POSITION 2 TYRE FLAT - BEAUREPAIRES REPLACED			08/11/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Albury - Workshop	Elect\ELECT P&W	TIED UP HOSE & LOOMS			08/11/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Albury - Workshop	Chassis\CONSUMABLE	REPLACED GREASE NIPPLES			08/11/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS		08/11/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Albury - Workshop	Body\CPN/RLN/MN	drilled hole and mount hold down chain			06/11/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Wodonga - Workshop	Chassis\BOLSTER	Replaced 3rd bolster wear pads			01/11/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
T355	Wodonga - Workshop	Chassis\MUDGUARDS	Replaced RHS stretch guard			01/11/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
T355	Wodonga - Workshop	Elect\INDICATORS	Repaired wiring for RHS indicator			01/11/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
T355	Wodonga - Workshop	Elect\TRL LIGHTS	Replaced missing/broken reflectors			01/11/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
			Skid plate repair, Hyd couplings chassis cracks at load ramps, LH outrigger bolts, LH bolster rams x 3												
			LHR air bag, Rear lower x member bolts replace, RHM air bag, LHF & RHF suspension eye boss cracked replace, LHF & RHM & LHR suspension eye bolts and adjust												
T355	Albury - Workshop	Chassis\CHAS CRACK	suspension		list of faults found trailer taken th Haire Truck & Bus to have repalired	03/10/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
T355	Albury - Workshop	Body	R/H front shock top bolt broken			24/09/2019	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Albury - Workshop	Body	no back L/H shock			24/09/2019	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Albury - Workshop	Body	2 shocks missing			24/09/2019	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Albury - Workshop	Body	cross member broken hitting height			24/09/2019	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Albury - Workshop	Body	control valve			24/09/2019	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Albury - Workshop	Workshop\MOVE ASSET	WASH TRAILER			24/09/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Albury - Workshop	VehService\DS	D Service	VehService\DS		24/09/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Rosewood - Workshop	Chassis\BOLSTER	Broken "Ned Kelly Pistol" on rear bolster		Cut off siezed bolts, replaced with new ones & replaced "Ned Kelly Pistol"	11/07/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Chassis\BOLSTER	broken lift arm on back bolster LHS			11/07/2019	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Wodonga - Workshop	Brakes	Brake test results attached			09/07/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
T355	Wodonga - Workshop	VehService\DS	D-Service	VehService\DS		09/07/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	D Service	VehService\DS		06/07/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			26/06/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	D Service			26/06/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job	VehService\DS		14/06/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	Service	VehService\DS		14/06/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			31/05/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
			Service												
T355	Rosewood - Workshop	VehService\DS	tighten spring eye bush nuts and u-bolts	VehService\DS		31/05/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			22/05/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	D Service	VehService\DS		22/05/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			14/05/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	D Service	VehService\DS		14/05/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	D Service Due	VehService\DS		02/05/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			02/05/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	Service	VehService\DS		02/05/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			16/04/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	D Service	VehService\DS		16/04/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
			D Service												
T355	Albury - Workshop	VehService\DS	doe chain broken	VehService\DS		16/04/2019	Service	Comsleted	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	D Service	VehService\DS		13/04/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	carry out trailer service	VehService\DS		04/04/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			15/03/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	Service	VehService\DS		15/03/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			08/03/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	Service	VehService\DS		08/03/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			13/02/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	Service	VehService\DS		13/02/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
					called out at 12:00, waited until 2am to coincide with shift change										
					travel to Rosewood depot and pack tools, ect and pick up driver										
					travel to Wandalga and chain up middle axel, supply safe amount of air to suspension and follow back to Rosewood										
T355	Rosewood - Workshop	Susp\SUSPENSION	broken ubolts on second axle right side		replace RH centre and ubolts, alignment plate, shocker and set back in place	12/02/2019	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	Service	VehService\DS		30/01/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
					clearance lamp fix broken wires trace and solder										
					reverse lamp inspect remove replace solder										
T355	Rosewood - Workshop	Elect\TRL LIGHTS	back left hand guard park light not working		tape uo convulsted tube around wires	19/01/2019	Fault	Comsleted	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			11/01/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	Service	VehService\DS		11/01/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes\BRK RELINE	Reline			08/01/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			22/12/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	D Service	VehService\DS		22/12/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			22/12/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	D Service	VehService\DS		22/12/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes\BRK RELINE	Reline			22/12/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
			D Service												
T355	Myrtleford - Workshop	VehService\DS	R & R No: 111022	VehService\DS		20/12/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Myrtleford Workshop	TRAILER
T355	Rosewood - Workshop	Elect\TRL LIGHTS	replace side marker			13/12/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Albury - Workshop	Brakes	Job Added From Invoice			11/12/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			08/12/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	Service	VehService\DS		08/12/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	Service	VehService\DS		07/12/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes\BRK RELINE	Reline			06/12/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice			27/11/2018 125669	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB32FL	Wodonga Workshop	TRAILER
T355	Wodonga - Workshop	Tyres\RETREAD	Job Added From Invoice			27/11/2018 125669	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
T355	Tumut - Workshop	VehService\DS	Service	VehService\DS		25/11/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
T355	Albury - Workshop	Susp	Job Added From Invoice			23/11/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	VehService\DS	VehService\DS	D service completed	21/11/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Chassis\FIFTH WHEE	replace quick release cable			14/11/2018	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	Service Due	VehService\DS		14/11/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			14/11/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	D Service	VehService\DS		14/11/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Susp\SUSPENSION	RH middle axle z beam bolt broken		replace 2 spring eye bolt and check over suspension	09/11/2018	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			03/11/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	D Service	VehService\DS		03/11/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Chassis\CHAS CRACK	grind out all cracks in the webbing of the trailer and reweild up cracks			30/10/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Chassis\BOLSTER	tighten up boulster			30/10/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	B2 Service Due	VehService\DS		23/10/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			23/10/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	D Service	VehService\DS		23/10/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			12/10/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	Service	VehService\DS		12/10/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			27/09/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	Service	VehService\DS		27/09/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	D Service	VehService\DS		27/09/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Susp\AIR FITTIN	Replaced rubbed air lines			19/09/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			19/09/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	D Service	VehService\DS		19/09/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Susp\SUSPENSION	REPLACE WORN AXLE CABLES		replace axle cables front axle	15/09/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	DrivLine\AXLE REPLC	two broken wire hangers on first axle			15/09/2018	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Hydraulics\HOSES	tighten loose hyd fitting			01/09/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	D Service	VehService\DS		01/09/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			01/09/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Tyres	Job Added From Invoice			01/09/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Tyres\FITMENT	Job Added From Invoice			01/09/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Susp\SHOCK ABS	tightened RM shocker			21/08/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Susp\SUSPENSION	replaced L/F usb bolt			21/08/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Susp\SUSPENSION	tightened R/F wb bolt			21/08/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			21/08/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	Service	VehService\DS		21/08/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
			air leak												
			got some soapy water and stray the airbags and found that the L/H/F was leaking so replace airbag												
			tested ok												
T355	Rosewood - Workshop	Body\AIR LEAK	hydraulic leak from ram fittine 90° was loose tiathen tested ok			10/08/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			10/08/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	Service	VehService\DS		10/08/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Albury - Workshop	Susp\AIR BAG	REPLACE AIR BAG			10/08/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Tumut - Workshop	VehService\DS	Service	VehService\DS		08/08/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
T355	Tumut - Workshop	Hydraulics\HYD LEAKS	first bay has got hydraulic leak			27/07/2018	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
T355	Rosewood - Workshop	DrivLine\WHEEL BRGS	check wheel bearings			24/07/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			24/07/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	Service	VehService\DS		24/07/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes\ABS	check ABS fault's tested clean			12/07/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Elect\INDICATORS	RH indicator not working		repair short indicators	11/07/2018	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Elect\ELECT P&W	clean out light plug			11/07/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER

T355	Rosewood - Workshop	Hydraulics\HYD LEAKS	repair leaking hydraulic ram fitting			11/07/2018	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			11/07/2018	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService/\DS	Service	VehService\DS		11/07/2018	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Albury - Workshop	Body\DAMAGE	LOG DAMAGE			05/07/2018	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Rosewood - Workshop	Body\DAMAGE	log damage. Incident report written			04/07/2018	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Elect\TAIL LIGHT	broken tail light, left side		replaced stop/tail light assy	04/07/2018	Fault	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			29/06/2018	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService/\DS	Service	VehService\DS		29/06/2018	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Tyres	Job Added From Invoice			27/06/2018 0	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Tyres\FITMENT	Job Added From Invoice			27/06/2018 0	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Tyres\RETREAD	Job Added From Invoice			27/06/2018 0	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Chassis\WINCH/STRP	lube winches			16/06/2018	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService/\DS	D Service	VehService\DS		16/06/2018	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Susp\SHOCK ABS	replaced LF top shocker bolt			16/06/2018	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			16/06/2018	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			06/06/2018	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService/\DS	Service	VehService\DS		06/06/2018	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Chassis\WINCH/STRP	3rd and 4th winch need lubricating			05/06/2018	Fault	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService/\DS	Service	VehService\DS		05/06/2018	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Chassis\WINCH/STRP	lubricate air winch		lube 1st winch	26/05/2018	Fault	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Body\REFLECTORS	replaced long vehicle sign			25/05/2018	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			24/05/2018	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService/\DS	Service	VehService\DS		24/05/2018	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	DrCabElect\RWC COMP	scale's playing up (R&RM110751)			22/05/2018	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Susp\HCV	check ride height valve had heap off play in the arm and boot was nearly worn way. Replace height control valve and rubber boot set ride height tested ok			22/05/2018	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Susp\SUSPENSION	replace L/R sets fit c/o spring			09/05/2018	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Chassis\WINCH/STRP	c/o 1st winch damaged fitting from 4/5			08/05/2018	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			08/05/2018	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService/\DS	D Service	VehService\DS		08/05/2018	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Tyres	Job Added From Invoice			25/04/2018 0	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Tyres\FITMENT	Job Added From Invoice			25/04/2018 0	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Tyres\RETREAD	Job Added From Invoice			25/04/2018 0	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Susp\SUSPENSION	tighten loose z spring bolts			20/04/2018	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			20/04/2018	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService/\DS	D Service	VehService\DS		20/04/2018	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService/\DS	Service	VehService\DS		06/04/2018	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			06/04/2018	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Albury - Workshop	Susp\SUSPENSION	press seb			27/03/2018	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Rosewood - Workshop	Susp\HCV	re-set height control valve			23/03/2018	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Elect\BRK LIGHT	repair brake lights.repaired wiring			21/03/2018	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Chassis\WINCH/STRP	replaced winch cap's. Front winch (greaseable type)			21/03/2018	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	DriveLine\WHEEL BRGS	check wheel bearings			21/03/2018	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			21/03/2018	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService/\DS	D Service	VehService\DS		21/03/2018	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Albury - Workshop	Elect\WORK LIGHT	NO WORK LIGHTS		CHANGED IN PLUG ON TRUCK	07/03/2018	Fault	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Albury - Workshop	Chassis\WINCH/STRP	LUBE WINCHES		change caps in winch old cap on winch was making hard to wind up 3rd winch	07/03/2018	Fault	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Albury - Workshop	Chassis\BOLSTER	tried to turn rear right bolster peg will straighten at mill			07/03/2018	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Albury - Workshop	Elect\INDICATORS	no blinker lights			03/03/2018	Fault	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Albury - Workshop	Susp\SHOCK ABS	R/H front shock top bolt broken			03/03/2018	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Albury - Workshop	Susp\SHOCK ABS	no back L/H shock			03/03/2018	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Albury - Workshop	Susp\SHOCK ABS	2 shocks missing			03/03/2018	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Albury - Workshop	Chassis\CROSS MBR	cross member broken hitting height			03/03/2018	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Albury - Workshop	Susp\HCV	control valve			03/03/2018	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Albury - Workshop	Elect\INDICATORS	R/H blinker not working			03/03/2018	Fault	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Albury - Workshop	Body\STCH GUARD	both stretch guards need replacing		stretch guards good	03/03/2018	Fault	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Albury - Workshop	VehService/\DS	D SERVICE	VehService\DS		03/03/2018	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Albury - Workshop	Elect\ELECT P&W	lights good			03/03/2018	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Albury - Workshop	Chassis\CHAS CRACK	weld ramp crack			03/03/2018	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			03/03/2018	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Albury - Workshop	Susp\HOUSEKEEP	REPLACE BROKEN AXLE STRAP		change broken axle cable R/H/R	22/02/2018	Fault	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Albury - Workshop	Tyres	Job Added From Invoice			17/02/2018 0	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice			17/02/2018 0	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice			17/02/2018 0	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Albury - Workshop	Brakes	Record Check Results As Attachec To This Job			10/02/2018	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Albury - Workshop	VehService/\DS	D Service	VehService\DS		10/02/2018	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Albury - Workshop	DriveLine/DAMAGE	REPLACED CRACKED RIM			10/02/2018	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Albury - Workshop	Workshop\CLEAN	Removed hydraulic ram and washed for repairs			10/01/2018	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
					removed old winchs										
					run 8mm air line for air winch supply										
					weld in new winch mounts										
T355	Albury - Workshop	Chassis\EXTE TU	FIT UP EXTE WINCHES.		remount o/r cables and hooks	10/12/2017	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
					finish 2nd and 4th bolster light wiring										
					replaced RH stretch guard										
					replaced LHM seb and spring wrap										
					brake adjust										
					grease										
					test bolster sequence and adjust as necessary										
T355	Albury - Workshop	Chassis\BOLSTER	CHANGE BOLSTERS TO 2.8MT SPACINGS AND FOLDING SEQUENCE		hook up and bring trailer into workshop	10/12/2017	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Tumut - Workshop	Tyres\RUN OUT	Job Added From Invoice			05/12/2017 0	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
T355	Albury - Workshop	Body\RWC COMP	removed and fitted rego labels			25/11/2017	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Albury - Workshop	Brakes\BRK RELINE	SUPPLY PARTS TO WODONGA WORKSHOP FOR RELINES.			04/11/2017	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Albury - Workshop	Susp\SUSPENSION	SUPPLY AXLE CABLE			02/11/2017	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Albury - Workshop	Brakes\EBS Kit	PARTS SUPPLIED TO HWY WORKSHOP FOR EBS FIT UP		end of line test	27/10/2017	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
			check over trailer												
T355	Albury - Workshop	Susp\HCV	reseained HCV mount/adiusted ride heiaht			10/10/2017	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Albury - Workshop	Brakes\BRAKE ADJ	repaired mast relay line			10/10/2017	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Tumut - Workshop	Tyres	Job Added From Invoice			07/10/2017 0	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
T355	Tumut - Workshop	Tyres\FITMENT	Job Added From Invoice			07/10/2017 0	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
T355	Tumut - Workshop	Tyres\RETREAD	Job Added From Invoice			07/10/2017 0	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
			Slack adjuster												
			Brake shoe kit												
T355	Tumut - Workshop	Brakes\SLACK ADJ	S Cam		twin city - 488133	27/09/2017	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
T355	Tumut - Workshop	Tyres	Job Added From Invoice			23/09/2017 0	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
T355	Tumut - Workshop	Tyres\FITMENT	Job Added From Invoice			23/09/2017 0	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
T355	Tumut - Workshop	Tyres\RETREAD	Job Added From Invoice			23/09/2017 0	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
T355	Rosewood - Workshop	DriveLine\SPRING HANG	1x '2' spring excessive movement from bush			23/09/2017	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Body\STCH GUARD	stretch guards were ordered frm Nich via email (Friday 15/9/17)			23/09/2017	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job			13/08/2017	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
T355	Rosewood - Workshop	VehService/\DS	Service	VehService\DS		13/08/2017	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Tumut - Workshop	Tyres	Job Added From Invoice			03/08/2017 0	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
T355	Tumut - Workshop	Tyres\FITMENT	Job Added From Invoice			03/08/2017 0	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
T355	Tumut - Workshop	Tyres\RETREAD	Job Added From Invoice			03/08/2017 0	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
T355	Tumut - Workshop	Tyres	Job Added From Invoice			27/07/2017 0	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
T355	Tumut - Workshop	Tyres\FITMENT	Job Added From Invoice			27/07/2017 0	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
T355	Tumut - Workshop	Tyres\RETREAD	Job Added From Invoice			27/07/2017 0	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
T355	Tumut - Workshop	Tyres	Job Added From Invoice			21/07/2017 0	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
T355	Tumut - Workshop	Tyres\FITMENT	Job Added From Invoice			21/07/2017 0	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
T355	Tumut - Workshop	Tyres\ROTATION	Job Added From Invoice			21/07/2017 0	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
T355	Tumut - Workshop	Tyres\RETREAD	Job Added From Invoice			21/07/2017 0	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
T355	Rosewood - Workshop	Body\CHN/RLR/MN	tie down chain broken (again)			20/07/2017	Fault	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			20/07/2017	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService/\DS	Service Due	VehService\DS		20/07/2017	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService/\DS	Replaced middle shockers in service	VehService\DS		04/07/2017	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			24/06/2017	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService/\DS	Service	VehService\DS		24/06/2017	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Tumut - Workshop	Brakes\AIR LEAK	As per Parts quotation 479113			24/06/2017	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
T355	Tumut - Workshop	Tyres	Job Added From Invoice			23/06/2017 313626	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
T355	Rosewood - Workshop	Brakes\EBS Kit	Ordering New Install kit for EBS from BPW		fitted EBS	15/06/2017	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
T355	Rosewood - Workshop	Susp\SHOCK ABS	replace shock			15/06/2017	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
T355	Rosewood - Workshop	Susp\SHOCK ABS	replace axle strap			15/06/2017	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
T355	Rosewood - Workshop	Chassis\CROSS MBR	repaired cracks			15/06/2017	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
					REMOVED BOLSTER FROM T223. FIT NEW WEAR PADS AND SEND TO ROSEWOOD TO FIT UP TO T355.										
T355	Albury - Workshop	Chassis\BOLSTER	CRACKED BOLSTER		BOLSTER ORDERED	06/06/2017	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Albury Workshop	TRAILER
T355	Rosewood - Workshop	Elect\ELECT P&W	Back LH Bolster Light Needs Replacing			03/06/2017	Fault	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService/\DS	A Service Due	VehService\DS		03/06/2017	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Tumut - Workshop	Brakes\AIR LEAK	L/H/S front axle brake stickiing on we backed it off			03/06/2017	Fault	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
T355	Tumut - Workshop	Tyres	Job Added From Invoice			19/05/2017 0	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
T355	Tumut - Workshop	Tyres\FITMENT	Job Added From Invoice			19/05/2017 0	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
T355	Tumut - Workshop	Tyres\RETREAD	Job Added From Invoice			19/05/2017 0	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
T355	Tumut - Workshop	Tyres	Job Added From Invoice			06/05/2017 0	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
T355	Tumut - Workshop	Tyres\FITMENT	Job Added From Invoice			06/05/2017 0	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
T355	Tumut - Workshop	Tyres\RETREAD	Job Added From Invoice			06/05/2017 0	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
T355	Rosewood - Workshop	Chassis\WINCH/STRP	winch knob missing			29/04/2017	Fault	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService/\DS	service	VehService\DS		24/03/2017	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Susp\SUSPENSION	replace 2 spring			12/03/2017	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes\BRAKE ADJ	brakes need adjustment			11/03/2017	Fault	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Tumut - Workshop	Tyres\TP16	Job Added From Invoice			04/03/2017 0	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
T355	Rosewood - Workshop	VehService/\DS	Service	VehService\DS		24/02/2017	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService/\DS	Service	VehService\DS		19/02/2017	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService/\AS	A Service Due 500km			16/02/2017	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Tumut - Workshop	Tyres\TP19	Job Added From Invoice			09/02/2017 0	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
T355	Rosewood - Workshop	VehService/\DS	Service	VehService\DS		07/02/2017	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Tumut - Workshop	Tyres\TP19	Job Added From Invoice			07/02/2017 0	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
T355	Rosewood - Workshop	VehService/\BS	B Service Due			24/01/2017	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Body\STCH GUARD	LH stretch guard needs replacing			24/01/2017	Fault	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Elect\INDICATORS	RH indicator not working all the time			24/01/2017	Fault	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService/\DS	Service	VehService\DS	fix short in trailers lights	24/01/2017	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Chassis\WINCH/STRP	replace winch strapps		rosewood w/shop	24/01/2017	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService/\DS	Service	VehService\DS		10/01/2017	Service	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Wodonga - Workshop	Chassis\WINCH/STRP	TCTC supplied 4 straops fitted be wk shop			10/01/2017	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Wodonga Workshop	TRAILER
T355	Tumut - Workshop	Tyres\TP21	Job Added From Invoice			26/12/2016 279637	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
T355	Rosewood - Workshop	Tyres\TP16	replace alloy rim		Bridgestone wagga	16/12/2016	Repair	Completed	Greenfreight Logging NSW	Kennedy\BPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Tumut - Workshop	VehService/\AS	300 off A Service			16/12/2

T355	Rosewood - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			02/12/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	Service	VehService\DS			02/12/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes\BOOSTER	replace 30/30 booster			rosewood w/shop	19/11/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes\AIR LEAK	replace leaking valve			Rosewood w/shop	18/11/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes\BRK RELINE	reline brakes and fit bearings			Rosewood w/shop	18/11/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Susp\AIR BAG	replace leaking air bag			rosewood w/shop	18/11/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Susp\AIR BAG	replace air bags			Rosewood W/shop	16/11/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			10/11/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	Service	VehService\DS			10/11/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job				10/11/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Replace front RHS brake booster				01/11/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Tumut - Workshop	Tyres\TP13	Job Added From Invoice				14/10/2016 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
T355	Rosewood - Workshop	Elect	short in work lights				06/10/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Elect	RH blinker not working all the time				06/10/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			06/10/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job				06/10/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService	service				06/10/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Susp\SHOCK ABS	replace shock absorbers				22/09/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Tumut - Workshop	Tyres\TP15	Job Added From Invoice				13/09/2016 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
T355	Tumut - Workshop	Tyres\TP15	Job Added From Invoice				13/09/2016 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
T355	Tumut - Workshop	Tyres\TP15	Job Added From Invoice				13/09/2016 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
T355	Rosewood - Workshop	VehService	B Service Due				10/09/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Tumut - Workshop	Tyres\TP15	Job Added From Invoice				08/09/2016 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
T355	Tumut - Workshop	Tyres\TP21	Job Added From Invoice				08/09/2016 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job				01/09/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService	service				01/09/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService	A Service Due				01/09/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Body	RH stretch guard ripped				01/09/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			01/09/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job				20/08/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			20/08/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Tumut - Workshop	Tyres\TP15	Job Added From Invoice				30/07/2016 256518	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job				22/07/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Body	2 shocks missing				22/07/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Body	cross member broken hitting height				22/07/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Body	control valve				22/07/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			22/07/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Tumut - Workshop	Elect\TRL LIGHTS	inspect fault in triler indecator RHS (found to be working when inspected couldn't get fault to occour checked over wiring loom)			completed by Tumut auto electrics on the 8 june	12/07/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
T355	Rosewood - Workshop	Elect	R/H blinker not working properly				10/07/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job				08/07/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService	A Service Due				08/07/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			08/07/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job				06/07/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService	A Service Due				06/07/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			06/07/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job				23/06/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			23/06/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Chassis\BOLSTER	replaced " rear bolster light				22/06/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Body	no back L/H shock				11/06/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Body	slide lock not releasing				11/06/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Body	R/H front shock top bolt broken				11/06/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Chassis\BOLSTER	R/H back bolster light not working				11/06/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job				08/06/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			08/06/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Elect	replace back left side light				04/06/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job				28/05/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			28/05/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job				01/05/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			01/05/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job				17/04/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes\BRK RELINE	replace maxi lines				17/04/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	DriveLine\SUSPENSION	tension suspension bolts				17/04/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Elect\TRL LIGHTS	repair rear bolster clearance lights				17/04/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			17/04/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Tumut - Workshop	Tyres\TP19	Job Added From Invoice				16/04/2016 236474	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
T355	Rosewood - Workshop	VehService	B Service Due 500kms				06/04/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job				06/04/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			06/04/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes\BRK RELINE	reline brakes				31/03/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job				20/03/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			20/03/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job				09/03/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			09/03/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService	Due for A Service				05/03/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job				21/02/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			21/02/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job				13/02/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			13/02/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Susp\AIR BAG	replace air bags				11/02/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Elect\TRL LIGHTS	work lights on back of B Trailer not working				06/02/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes\BRK RELINE	brake reline x3 wheels 3 relines reline l/h/m				06/02/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes\BRK RELINE	reline r/h/r and r/h/m				05/02/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Susp\AIR BAG	replace middle axle air bags				05/02/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			03/02/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job Reline L/H/F and L/H/R and replace drums and Scams				03/02/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes\BRK RELINE	Replace wheeling bearings on L/H/R				19/01/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			19/01/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job				19/01/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes\BRK RELINE	crack test and reline lhf and replace s-cam and drum, reline lhr and replace s-cam and drum and bearings				19/01/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Tumut - Workshop	Tyres\TP17	Job Added From Invoice				01/01/2016 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
T355	Tumut - Workshop	Tyres\TP17	Job Added From Invoice				01/01/2016 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
T355	Tumut - Workshop	Tyres\TP17	Job Added From Invoice				01/01/2016 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job				25/12/2015	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			25/12/2015	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Body	rh stretch guard gone missing				19/12/2015	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Tumut - Workshop	Tyres\TP11	Job Added From Invoice				18/12/2015 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
T355	Tumut - Workshop	Tyres\TP11	Job Added From Invoice				18/12/2015 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
T355	Tumut - Workshop	Tyres\TP14	Job Added From Invoice				15/12/2015 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
T355	Tumut - Workshop	Tyres\TP14	Job Added From Invoice				15/12/2015 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
T355	Tumut - Workshop	Tyres\TP14	Job Added From Invoice				15/12/2015 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job				15/12/2015 964575	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			15/12/2015 964575	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Elect	no indicators				12/12/2015	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Chassis	bent guard inside lh chassis rail				12/12/2015	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job				28/11/2015	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	D Service As Per Attached Checklist Shocks	VehService\DS			28/11/2015	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Tumut - Workshop	Susp\SHOCK ABS	Maxiparts-$300.00			purchase order on completed	27/11/2015	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
T355	Tumut - Workshop	Tyres\TP12	Job Added From Invoice				26/11/2015 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
T355	Tumut - Workshop	Tyres\TP16	Job Added From Invoice				26/11/2015 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
T355	Tumut - Workshop	Tyres\TP16	Job Added From Invoice				26/11/2015 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
T355	Tumut - Workshop	Tyres\TP16	Job Added From Invoice				26/11/2015 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
T355	Tumut - Workshop	Tyres\TP12	Job Added From Invoice				26/11/2015 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
T355	Tumut - Workshop	Tyres\TP12	Job Added From Invoice				26/11/2015 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
T355	Tumut - Workshop	Insp\INT INSP	Roadworthy				21/11/2015	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job				13/11/2015	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			13/11/2015	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Susp	Bolt on left hand back shock broken			repaired	10/11/2015	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job				03/11/2015	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			03/11/2015	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Tumut - Workshop	Tyres\TP20	Job Added From Invoice				27/10/2015 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
T355	Rosewood - Workshop	Chassis	crack in lhf hanger			welded by Steel Formation Tumba	21/10/2015	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Body	cable for air tank broken				21/10/2015	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			21/10/2015	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job				21/10/2015	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Elect\TRL LIGHTS	lhr work light not working, lh side light on 2nd bolster broken				21/10/2015	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Tumut - Workshop	Tyres\DAMAGE	trailer rims x 2 - maxiparts			completed	14/10/2015	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Tumut Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			07/10/2015	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job				07/10/2015	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Chassis	replace lhr axle strap				07/10/2015	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job				22/09/2015	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			22/09/2015	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			02/09/2015	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER
T355	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job				02/09/2015	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	TB99FL	Rosewood Workshop	TRAILER