PATTISON AGRICULTURE LIMITED
Hwy 5 East, Box 2109
Humboldt, SK S0K 2A0
Phone: (306) 682-2572
Fax: (306) 682-2510
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

PATTISON AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice Number:	**3502902**
Invoice Date	11/04/2025
Location:	08
Work Order Number:	517209
Payment Type:	Credit Card
Authorization Number:	M 08073J
Page:	1 of 18

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S680	2296	1H0S680SPH0796439	764986	4

Service Reminders:

JGLC JD S SERIES ALL Retail

COMPLAINT:

01 S SERIES COMBINE VALUEMAX GREEN LIGHT SERVICE INSPECTION CHECKOVER

*** DO NOT CHANGE–ENGINE OIL AND FILTER

*** DO NOT CHANGE AIR FILTER

CAUSE:

CORRECTION:

VALUEMAX GREEN LIGHT SELF PROPELLED COMBINE CHECKLIST
****
HEADER SERIAL # _____
ENGINE HOURS _____2296_____
SEPERATOR HOURS _____1621_____
****
DOES THIS UNIT GET A VALUEMAX STICKER _X_ YES __ NO
HAS THE STICKER BEEN INSTALLED _X_ YES __ NO
THIS UNIT HAS HAD THE CAB CLEANED _____(INITIAL)
THIS UNIT HAS HAD A FINAL CHECKOVER _____(INITIAL)
THIS UNIT HAS HAD A COMPLETE GREASE JOB ____JF_____(INITIAL)
****
THINGS NOTED BUT NOT REPAIRED ON CUSTOMERS INSTRUCTIONS:

Paid M/C
Thanks!

Job Total: $3,307.00

J10030100 JD S680 Retail

COMPLAINT:

02 REPLACE ENGINE FUEL FILTERS

CAUSE:

CORRECTION:

REPLACED PRIMARY AND SECONDARY FUEL FILTERS.
REMOVED AND CLEANED FUEL STRAINER.
BLED FUEL SYSTEM.
FUNCTION AND LEAK CHECKED.

PATTISON AGRICULTURE LIMITED
Hwy 5 East, Box 2109
Humboldt, SK S0K 2A0
Phone: (306) 682-2572
Fax: (306) 682-2510
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2693	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

PATTISON AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice Number:	**3502902**
Invoice Date	11/04/2025
Location:	08
Work Order Number:	517209
Payment Type:	Credit Card
Authorization Number:	M 08073J
Page:	2 of 18

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S680	2296	1H0S680SPH0796439	764986	4

Service Reminders:

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
DZ112918	FINAL FUEL FILTER	1.00	217.82	$217.82	Y
DZ130550	FILTER ELE	1.00	214.37	$214.37	Y
Miscellaneous	**Description**	**Quantity**	**Net Price**	**Extended Price**	**Taxed Ind**
EF100	ENVIRO FEE	2.00	1.25	$2.50	Y

Labor: $160.00 **Parts: $432.19** **OL&M: $0.00** **Misc: $2.50** **Sub-Total: $594.69**

J06070004 JD S680 Retail

COMPLAINT:

03 REPLACE HYDROSTATIC CHARGE FILTER. PRODRIVE

CAUSE:

CORRECTION:

REPLACED HYDROSTATIC CHARGE FILTER

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AN207368	Hydro Charge Filter	1.00	179.87	$179.87	Y
N309233	O-RING	1.00	29.41	$29.41	Y
Miscellaneous	**Description**	**Quantity**	**Net Price**	**Extended Price**	**Taxed Ind**
EF100	ENVIRO FEE	1.00	1.25	$1.25	Y

Labor: $70.00 **Parts: $209.28** **OL&M: $0.00** **Misc: $1.25** **Sub-Total: $280.53**

J06070005 JD S680 Retail

COMPLAINT:

04 REPLACE HYDRAULIC FILTER

CAUSE:

CORRECTION:

REPLACED PRODRIVE FILTER

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AH128449	HYDRAULIC	1.00	135.92	$135.92	Y
Miscellaneous	**Description**	**Quantity**	**Net Price**	**Extended Price**	**Taxed Ind**
EF100	ENVIRO FEE	1.00	1.25	$1.25	Y

PATTISON AGRICULTURE LIMITED
Hwy 5 East, Box 2109
Humboldt, SK S0K 2A0
Phone: (306) 682-2572
Fax: (306) 682-2510
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2535
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

PATTISON AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice Number:	**3502902**
Invoice Date	11/04/2025
Location:	08
Work Order Number:	517209
Payment Type:	Credit Card
Authorization Number:	M 08073J
Page:	3 of 18

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S680	2296	1H0S680SPH0796439	764986	4

Service Reminders:

Labor: $100.00 **Parts: $135.92** **OL&M: $0.00** **Misc: $1.25** **Sub-Total: $237.17**

J06070003 JD S680 Retail

COMPLAINT:

05 REPLACE MAIN HYDRAULIC RESERVOIR FILTER.

CAUSE:

CORRECTION:

REPLACE HYDRAULIC RESERVOIR FILTER.
REPLACED FILTER

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AXE12964	HYDRAULIC	1.00	163.86	$163.86	Y
Miscellaneous	**Description**	**Quantity**	**Net Price**	**Extended Price**	**Taxed Ind**
EF50	ENVIRO FEE	1.00	0.55	$0.55	Y

Labor: $50.00 **Parts: $163.86** **OL&M: $0.00** **Misc: $0.55** **Sub-Total: $214.41**

JGEN10- Retail

COMPLAINT:

06 02 REPLACE CAB DOOR HANDLE, BUTTON IS BROKEN

CAUSE:

CORRECTION:

removed panel to replace door handle and found screw had backed out causing button to spin, loctited and reinstalled screw, door handle didnt need to be replaced

Labor: $124.00 **Parts: $0.00** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $124.00**

J06171082 JD S680 Retail

COMPLAINT:

07 REPLACE FEEDERHOUSE CONVEYOR DRIVE CHAIN GUIDES AND OR PLASTIC WEAR STRIPS.

CAUSE:

PATTISON AGRICULTURE LIMITED
Hwy 5 East, Box 2109
Humboldt, SK S0K 2A0
Phone: (306) 682-2572
Fax: (306) 682-2510
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

PATTISON AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice Number:	**3502902**
Invoice Date	11/04/2025
Location:	08
Work Order Number:	517209
Payment Type:	Credit Card
Authorization Number:	M 08073J
Page:	4 of 18

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S680	2296	1H0S680SPH0796439	764986	4

Service Reminders:

CORRECTION:

REMOVED DRIVE CHAIN GUIDE ASSEMBLIES.
REPLACED PLASTIC WEAR STRIPS.(IF REQUIRED)
INSTALLED DRIVE CHAIN GUIDE ASSEMBLIES.
ADJUSTED TO PROPER HEIGHT.
REPLACED UPPER WEAR STRIPS

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
H171960	FH ConveyChain Return Strip	4.00	42.12	$168.48	Y

Labor: $100.00 **Parts: $168.48** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $268.48**

JGEN08- Retail

COMPLAINT:

08 REMOVE CONCAVES AND REPLACE 4 SEPERATOR BULK HEAD BOLTS

CAUSE:

CORRECTION:

REMOVED CONCAVES AND DRIVESHAFTS, REPLACED 4 BOLTS AND NUTS

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
14M7296	M10x1.5 FlangeNut	4.00	2.16	$8.64	Y
H174755	M10x30 Carr10.9carbide	4.00	3.66	$14.64	Y

Labor: $120.00 **Parts: $23.28** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $143.28**

J06180261 JD S680 Retail

COMPLAINT:

09 PERFORM FACTORY CALIBRATION AND LEVELING OF ACTIVE CONCAVES.

CAUSE:

CORRECTION:

INSTALLED CONCAVES. (ENSURE THAT THE CONCAVES ARE TIGHT TO ONE ANOTHER AND THERE IS ADEQUATE BULKHEAD CLEARANCE)
LEVELED CONCAVES AS PER SERVICE ADVISOR.

PATTISON AGRICULTURE LIMITED
Hwy 5 East, Box 2109
Humboldt, SK S0K 2A0
Phone: (306) 682-2572
Fax: (306) 682-2510
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

PATTISON AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice Number:	**3502902**
Invoice Date	11/04/2025
Location:	08
Work Order Number:	517209
Payment Type:	Credit Card
Authorization Number:	M 08073J
Page:	5 of 18

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S680	2296	1H0S680SPH0796439	764986	4

Service Reminders:
PERFORMED CONCAVE CALIBRATION.

Labor: $440.00 **Parts: $0.00** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $440.00**

J06171092 JD S680 Retail

COMPLAINT:

10 REPLACE FEEDER FEED PLATE SEAL

CAUSE:

CORRECTION:

REMOVED AND REPLACED FEED PLATE SEAL

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
H173904	SEAL	1.00	341.45	$341.45	Y

Labor: $200.00 **Parts: $341.45** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $541.45**

J06171011 JD S680 Retail

COMPLAINT:

11 REPLACE FEEDERHOUSE TENSIONER J-BOLT.

CAUSE:

CORRECTION:

REMOVED TENSIONER AND REPLACED PLASTIC BUSHING, TENSIONED BELT

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
H129208	PIVOT	1.00	7.93	$7.93	Y

Labor: $140.00 **Parts: $7.93** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $147.93**

J06171103 JD S680 Retail

COMPLAINT:

12 REMOVE FEEDERHOUSE AND REPLACE TOP SPROCKETS

CAUSE:

PATTISON AGRICULTURE LIMITED
Hwy 5 East, Box 2109
Humboldt, SK S0K 2A0
Phone: (306) 682-2572
Fax: (306) 682-2510
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

PATTISON AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice Number:	**3502902**
Invoice Date	11/04/2025
Location:	08
Work Order Number:	517209
Payment Type:	Credit Card
Authorization Number:	M 08073J
Page:	6 of 18

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S680	2296	1H0S680SPH0796439	764986	4

Service Reminders:

CORRECTION:

REMOVED DRIVE CHAIN, SPLIT CONVEYOR CHAIN, REMOVED FEED PLATE DOOR BAR, REMOVED TOP SHAFT AND SPROCKETS, INSTALLED SPROCKETS AND BEARINGS ONTO NEW SHAFT AND INSTALLED IN COMBINE, RECONNECTED FEEDERCHAIN AND SET SPROCKET POSITION, REINSTALLED DRIVE CHAIN AND FEED PLATE BAR

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
11M7032	COTTER PIN	1.00	1.05	$1.05	Y
14M7189	M24x3.0 CastleNut	1.00	16.62	$16.62	Y
HXE42567	SHAFT	1.00	1,726.88	$1,726.88	Y
JD10020	BALL BEARI	1.00	67.26	$67.26	Y
JD9373	BALL BEARI	1.00	68.20	$68.20	Y

Labor: $1,900.00 **Parts: $1,880.01** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $3,780.01**

J06050011 JD S680 Retail

COMPLAINT:

13 REPLACE TRANSMISSION OUTPUT DRIVE SHAFT SEAL

CAUSE:

CORRECTION:

removed driveshafts, repalced seals on both sides and reinstalled drive shafts

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AZ42575	SEAL	2.00	51.56	$103.12	Y

Labor: $390.00 **Parts: $103.12** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $493.12**

JGEN18- Retail

COMPLAINT:

14 REPLACE HEADER CLUTCH STRAP

CAUSE:

CORRECTION:

REPLACED STRAP

PATTISON AGRICULTURE LIMITED
Hwy 5 East, Box 2109
Humboldt, SK S0K 2A0
Phone: (306) 682-2572
Fax: (306) 682-2510
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

PATTISON AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice Number:	**3502902**
Invoice Date	11/04/2025
Location:	08
Work Order Number:	517209
Payment Type:	Credit Card
Authorization Number:	M 08073J
Page:	7 of 18

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S680	2296	1H0S680SPH0796439	764986	4

Service Reminders:

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
H134773	STRAP	1.00	8.37	$8.37	Y

Labor: $56.00 **Parts: $8.37** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $64.37**

J06180113 JD S680 Retail

COMPLAINT:

15 REPLACE ALL SIEVE AND CHAFFER PITMAN ARMS.

CAUSE:

CORRECTION:

REMOVED GRAIN LOSS MONITORS AND TAILBOARD
REMOVED CHAFFER DIVIDERS
REMOVED CHAFFER AND SIEVE ELEMENTS
REMOVED THE BOLTS HOLDING THE CHAFFER FRAME TO PITMAN ARMS AND REAR HANGERS
BACKED THE CHAFFER FRAME OUT FAR ENOUGH TO ACCESS SIEVE BOLTS
PROCEEDED WITH CHANGING FRONT SIEVE FRAME PITMAN ARMS
REPLACED ALL FRONT CHAFFER PITMAN ARMS
REINSTALLED CHAFFER FRAME
TIME THE CHAFFER AND SIEVE FRAME AND TORQUE ALL BOLTS TO SPEC
REINSTALLED CHAFFER AND SIEVE ELEMENT
REINSTALLED CHAFFER DIVIDERS
REINSTALLED GRAIN LOSS MONITORS AND TAILBOARD
FACTORY CALIBRATE SIEVE AND CHAFFER

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
11M7028	COTTER PIN	1.00	0.79	$0.79	Y
14M7291	M16x2.0 FlangeNut	10.00	5.03	$50.30	Y
14M7299	M12x1.75 FlangeNut	4.00	2.91	$11.64	Y
19M10533	SCREW	2.00	9.76	$19.52	Y
19M7820	Screw M12x100 Flg 10.9	2.00	10.07	$20.14	Y
19M7829	SCREW	2.00	18.37	$36.74	Y
19M7830	Screw M16x150 Flg 10.9	2.00	16.56	$33.12	Y
19M8486	Cap Screw M16x180 10.9	2.00	23.49	$46.98	Y
AH222366	ARM	2.00	357.77	$715.54	Y
AH223014	LH Shoe Arm	1.00	835.15	$835.15	Y
AH223015	RH Shoe Arm	1.00	835.15	$835.15	Y
H154928	BOLT	2.00	9.28	$18.56	Y

PATTISON AGRICULTURE LIMITED
Hwy 5 East, Box 2109
Humboldt, SK S0K 2A0
Phone: (306) 682-2572
Fax: (306) 682-2510
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

PATTISON AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice Number:	**3502902**
Invoice Date	11/04/2025
Location:	08
Work Order Number:	517209
Payment Type:	Credit Card
Authorization Number:	M 08073J
Page:	8 of 18

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S680	2296	1H0S680SPH0796439	764986	4

Service Reminders:

H231095	Bolt	2.00	17.18	$34.36	Y
Miscellaneous	**Description**	**Quantity**	**Net Price**	**Extended Price**	**Taxed Ind**
EF15	ENVIRO FEE	1.00	0.15	$0.15	Y

Labor: $2,800.00 **Parts: $2,657.99** **OL&M: $0.00** **Misc: $0.15** **Sub-Total: $5,458.14**

J06175007 JD S680 Retail

COMPLAINT:

16 REPLACE LEFT AND RIGHT HAND LOWER TAILINGS AUGER BEARINGS.

CAUSE:

CORRECTION:

REMOVED BOTTOM BATTERY FROM BATTERY BOX, REMOVED AND REPLACED LEFT HAND TAILINGS AUGER BEARING AND REINSTALLED BATTERY

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
03M7184	BOLT	3.00	1.29	$3.87	Y
14M7298	M8x1.25 FlangeNut	4.00	1.54	$6.16	Y
19M7866	SCREW	1.00	1.81	$1.81	Y
H103264	PRESSED FL	1.00	3.80	$3.80	Y
H152940	Gasket	1.00	5.66	$5.66	Y
JD39102	Ball Bearing 205F	1.00	32.97	$32.97	Y
M84309	5/16" RETAINER/PUSH NUT	4.00	2.76	$11.04	Y

Labor: $500.00 **Parts: $65.31** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $565.31**

J06172055 JD S680 Retail

COMPLAINT:

17 REPLACE REAR CHOPPER FLOOR--weld

CAUSE:

CORRECTION:

GROUND OF PAINT, WELDED IN A PIECE OF FLAT IRON, AND PAINTED FLOOR

Labor: $378.00 **Parts: $0.00** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $378.00**

PATTISON AGRICULTURE LIMITED
Hwy 5 East, Box 2109
Humboldt, SK S0K 2A0
Phone: (306) 682-2572
Fax: (306) 682-2510
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

PATTISON AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice Number:	**3502902**
Invoice Date	11/04/2025
Location:	08
Work Order Number:	517209
Payment Type:	Credit Card
Authorization Number:	M 08073J
Page:	9 of 18

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S680	2296	1H0S680SPH0796439	764986	4

Service Reminders:

J06175004 JD S680 Retail

COMPLAINT:

18 REPLACE ACTIVE TAILINGS DRIVE CHAIN.

CAUSE:

CORRECTION:

REMOVED SAFETY SHIELDS
REMOVED OLD ACTIVE TAILINGS DRIVE CHAIN.
INSTALLED NEW ACTIVE TAILINGS DRIVE CHAIN.
ADJUSTED CHAIN TO PROPER TENSION.
RAN UNIT, CHECK AND ADJUSTED CHAIN AS NECESSARY.

REMOVED SHIELDS, REPLACED CHAIN AND TENSIONED

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AXE54619	60@ 114links Rethresher	1.00	339.98	$339.98	Y

Labor: $190.00 **Parts: $339.98** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $529.98**

J06230170 JD S680 Retail

COMPLAINT:

19 REPLACE CLEAN GRAIN ELEVATOR PADDLE CHAIN

CAUSE:

CORRECTION:

DISCONNECTED CONNECTOR LINK AND ATTACHED NEW PADDLE CHAIN.
ROLLED NEW CHAIN INTO ELEVATOR.
ADJUSTED TENSION.
RAN UNIT AND FUNCTION CHECKED.
ADJUSTED CHAIN AS REQUIRED.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AXE72667	CLEAN GRAIN ELEVATOR CHAIN 35 PDLS	1.00	1,146.20	$1,146.20	Y

Labor: $360.00 **Parts: $1,146.20** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $1,506.20**

JGEN21- Retail

PATTISON AGRICULTURE LIMITED
Hwy 5 East, Box 2109
Humboldt, SK S0K 2A0
Phone: (306) 682-2572
Fax: (306) 682-2510
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3689	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

PATTISON AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice Number:	**3502902**
Invoice Date	11/04/2025
Location:	08
Work Order Number:	517209
Payment Type:	Credit Card
Authorization Number:	M 08073J
Page:	10 of 18

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S680	2296	1H0S680SPH0796439	764986	4

Service Reminders:

COMPLAINT:

20 REPLACE SUPER CHARGER DRIVE BELT IDLER, ROUGH BEARING

CAUSE:

CORRECTION:

REPLACED SUPERCHARGER DRIVE BELT IDLER

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AXE37647	DMS Belt Idler	1.00	307.80	$307.80	Y

Labor: $84.00 **Parts: $307.80** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $391.80**

JWELD2 JD ALL Retail

COMPLAINT:

21 WELD CRACK IN CLEAN GRAIN ELEVATOR DIVIDER

CAUSE:

CORRECTION:

WELDED CRACK IN CLEAN GRAIN ELEVATOR DIVIDER

Labor: $300.00 **Parts: $0.00** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $300.00**

J06680055 JD S680 Retail

COMPLAINT:

22 INSTALL ADJUSTABLE FRONT CHAFFER BXE10692

CAUSE:

CORRECTION:

REPLACED ALL 4 PRE CLEANER ELEMENTS

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
BXE10692	Adjustable Front Chaffer	1.00	1,768.23	$1,768.23	Y

PATTISON AGRICULTURE LIMITED
Hwy 5 East, Box 2109
Humboldt, SK S0K 2A0
Phone: (306) 682-2572
Fax: (306) 682-2510
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3689	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

PATTISON AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice Number:	**3502902**
Invoice Date	11/04/2025
Location:	08
Work Order Number:	517209
Payment Type:	Credit Card
Authorization Number:	M 08073J
Page:	11 of 18

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S680	2296	1H0S680SPH0796439	764986	4

Service Reminders:

Labor: $780.00 **Parts: $1,768.23** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $2,548.23**

JWELD3 JD ALL Retail

COMPLAINT:

23 WELD CRACKS IN FRONT ROTOR BULKHEAD

CAUSE:

CORRECTION:

WELDED CRACKS IN ROTOR BULKHEAD AND GROUND WELDS SMOOTH SO CONCAVES WOULDNT CATCH

Labor: $300.00 **Parts: $0.00** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $300.00**

J06175011 JD S680 Retail

COMPLAINT:

24 REPLACE GRAIN TANK UNLOADING CROSS AUGER LEFT HAND BEARING

CAUSE:

CORRECTION:

REMOVED UNLOADING AUGER DRIVE CHAIN.
REMOVED CROSS AUGER DRIVE SPROCKET.
CLEANED AUGER SHAFT AND REMOVED BEARING MOUNTS WITH BEARING.
CLEANED OFF INNER PART OF AUGER SHAFT.
REMOVED BEARING FROM BEARING MOUNTS.
CLEANED OFF OLD SILICONE SEALANT FROM EDGES OF BEARING MOUNTS AND COMBINE FRAME.
INSTALLED NEW BEARING TO BEARING MOUNTS.
INSTALLED BEARING MOUNTS ONTO AUGER.
RE-SEALED BEHIND MOUNTING PANEL.
FASTENED UP BEARING MOUNTS AND FLANGES.
INSTALLED NEW BEARING LOCKING COLLAR.
RE-INSTALLED DRIVE SPROCKET.
RE-INSTALLED DRIVE CHAIN AND SET TENSION TO SPEC.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
03M7191	M10x25 CarrSN	3.00	1.73	$5.19	Y
14M7296	M10x1.5 FlangeNut	3.00	2.16	$6.48	Y
AH133191	ECCENTRIC	1.00	24.41	$24.41	Y

PATTISON AGRICULTURE LIMITED
Hwy 5 East, Box 2109
Humboldt, SK S0K 2A0
Phone: (306) 682-2572
Fax: (306) 682-2510
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2535
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

PATTISON AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice Number:	**3502902**
Invoice Date	11/04/2025
Location:	08
Work Order Number:	517209
Payment Type:	Credit Card
Authorization Number:	M 08073J
Page:	12 of 18

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S680	2296	1H0S680SPH0796439	764986	4

Service Reminders:

H161529	PRESSED FL	2.00	10.44	$20.88	Y
JD39104	BALL BEARI	1.00	54.33	$54.33	Y

Labor: $400.00 **Parts: $111.29** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $511.29**

J10180360 JD S680 Retail

COMPLAINT:

25 REPLACE PRIMARY COUNTERSHAFT GEARCASE OIL.

CAUSE:

CORRECTION:

DRAINED OIL AND REFILLED WITH NEW OIL.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
TY6296	80W90 946ml GL5	2.00	14.39	$28.78	Y
Miscellaneous	**Description**	**Quantity**	**Net Price**	**Extended Price**	**Taxed Ind**
EF15	ENVIRO FEE	2.00	0.15	$0.30	Y

Labor: $220.00 **Parts: $28.78** **OL&M: $0.00** **Misc: $0.30** **Sub-Total: $249.08**

J06001007 JD S680 Retail

COMPLAINT:

26 REPLACE FRONT FINAL DRIVE OIL. (ONE SIDE)

CAUSE:

CORRECTION:

DRAINED OIL FROM FRONT FINAL DRIVE.
INSTALLED NEW OIL AND CHECKED LEVELS.
CHECKED FOR LEAKS.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
TY6296	80W90 946ml GL5	8.00	14.39	$115.12	Y
Miscellaneous	**Description**	**Quantity**	**Net Price**	**Extended Price**	**Taxed Ind**
EF15	ENVIRO FEE	4.00	0.15	$0.60	Y

Labor: $140.00 **Parts: $115.12** **OL&M: $0.00** **Misc: $0.60** **Sub-Total: $255.72**

PATTISON AGRICULTURE LIMITED
Hwy 5 East, Box 2109
Humboldt, SK S0K 2A0
Phone: (306) 682-2572
Fax: (306) 682-2510
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

PATTISON AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice Number:	**3502902**
Invoice Date	11/04/2025
Location:	08
Work Order Number:	517209
Payment Type:	Credit Card
Authorization Number:	M 08073J
Page:	13 of 18

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S680	2296	1H0S680SPH0796439	764986	4

Service Reminders:

JENGEARCSEPD JD S680 Retail

COMPLAINT:

27 REPLACE MAIN ENGINE GEARCASE OIL

CAUSE:

CORRECTION:

DRAINED MAIN ENGINE GEARCASE AND TRANSMISSION OIL. FILLED GEARCASE AND TRANSMISSION WITH OIL AND RAN COMBINE, TOPPED UP OIL

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AR69444	HY-GARD J20C 18.9L PAIL	1.00	142.61	$142.61	Y
Miscellaneous	**Description**	**Quantity**	**Net Price**	**Extended Price**	**Taxed Ind**
EF100	ENVIRO FEE	1.00	1.25	$1.25	Y
EF300	ENVIRO FEE	1.00	3.00	$3.00	Y

Labor: $400.00 **Parts: $142.61** **OL&M: $0.00** **Misc: $4.25** **Sub-Total: $546.86**

J06001283 JD S680 Retail

COMPLAINT:

28 CHANGE HYDRAULIC OIL

CAUSE:

CORRECTION:

CHANGED HYDRAULIC OIL

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AR69444	HY-GARD J20C 18.9L PAIL	3.00	142.61	$427.83	Y
Miscellaneous	**Description**	**Quantity**	**Net Price**	**Extended Price**	**Taxed Ind**
EF300	ENVIRO FEE	3.00	3.00	$9.00	Y

Labor: $300.00 **Parts: $427.83** **OL&M: $0.00** **Misc: $9.00** **Sub-Total: $736.83**

J06140020 JD S680 Retail

COMPLAINT:

29 REPLACE RADIATOR PROPELLER BEARINGS.

PATTISON AGRICULTURE LIMITED
Hwy 5 East, Box 2109
Humboldt, SK S0K 2A0
Phone: (306) 682-2572
Fax: (306) 682-2510
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

PATTISON AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice Number:	**3502902**
Invoice Date	11/04/2025
Location:	08
Work Order Number:	517209
Payment Type:	Credit Card
Authorization Number:	M 08073J
Page:	14 of 18

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S680	2296	1H0S680SPH0796439	764986	4

Service Reminders:

CAUSE:

CORRECTION:

OPENED UP ROTARY SCREEN DOOR.
REMOVED PROPELLERS FROM SUPPORTS.
REPLACED BEARINGS AS NEEDED.
REINSTALLED PROPELLERS AND GIVE A TEST SPIN.
CLOSED ROTARY SCREEN DOOR.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
JD29980	NEEDLE BEA	2.00	8.69	$17.38	Y

Labor: $100.00 **Parts: $17.38** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $117.38**

J06520010 JD S680 Retail

COMPLAINT:

30 REPLACE ONBOARD AIR COMPRESSOR DRIVE BELT.

CAUSE:

CORRECTION:

REMOVE ENGINE FAN BELT.
LOOSEN TENSIONER AND REPLACE COMPRESSORE DRIVE BELT.
REPLACED BELT

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
HXE71061	OBA Compressor V-Belt T4	1.00	49.06	$49.06	Y

Labor: $137.28 **Parts: $49.06** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $186.34**

JSOFTWARE JD S680 Retail

COMPLAINT:

31 UPDATE ALL CONTROLLER SOFTWARE

CAUSE:

CORRECTION:

PATTISON AGRICULTURE LIMITED
Hwy 5 East, Box 2109
Humboldt, SK S0K 2A0
Phone: (306) 682-2572
Fax: (306) 682-2510
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

PATTISON AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice Number:	**3502902**
Invoice Date	11/04/2025
Location:	08
Work Order Number:	517209
Payment Type:	Credit Card
Authorization Number:	M 08073J
Page:	15 of 18

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S680	2296	1H0S680SPH0796439	764986	4

Service Reminders:
UPDATED SOFTWARE ON ___RC1_____ CONTROLLERS.
HAD TO PREFORM THE FOLLOWING CALIBRATIONS.

Labor: $198.00 **Parts: $0.00** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $198.00**

JADJCHAFSIEV JD S680 Retail

COMPLAINT:

32 FACTORY CALIBRATION OF SIEVE AND CHAFFER

CAUSE:

CORRECTION:

PERFORM FACTORY CALIBRATION AS PER SERVICE ADVISOR
COMPLETED FACTORY CALIBRATION OF SIEVE AND CHAFFER

Labor: $200.00 **Parts: $0.00** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $200.00**

J06030031 JD S680 Retail

COMPLAINT:

33 ADJUST ROTARY SCREEN JACKSHAFT DRIVE BELT

CAUSE:

CORRECTION:

MAKE ADJUSTMENT TO ROTARY SCREEN JACKSHAFT BELT.
ADJUSTED PULLEY SO BELT TRACKS CENTER OF IDLER PULLEY

Labor: $80.00 **Parts: $0.00** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $80.00**

J06020110 JD S680 Retail

COMPLAINT:

34 ADJUST ENGINE VALVE CLEARANCE.

CAUSE:

PATTISON AGRICULTURE LIMITED
Hwy 5 East, Box 2109
Humboldt, SK S0K 2A0
Phone: (306) 682-2572
Fax: (306) 682-2510
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

PATTISON AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice Number:	**3502902**
Invoice Date	11/04/2025
Location:	08
Work Order Number:	517209
Payment Type:	Credit Card
Authorization Number:	M 08073J
Page:	16 of 18

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S680	2296	1H0S680SPH0796439	764986	4

Service Reminders:

CORRECTION:

REMOVED APPLICABLE ENGINE SHIELDS AND SUPPORTS TO GAIN ACCESS TO VALVE COVER, (ALONG WITH TURBO AIR CROSS OVER TUBE, AND AIR FILTER HOUSING).
REMOVED VALVE COVER FROM ENGINE.
FOLLOWED SERVICE ADVISOR PROCEDURE FOR SETTING VALVES AND INJECTOR PRE-LOADS.
REMOVED SEAL FROM VALVE COVER, REPLACED WITH NEW.
RE-INSTALLED VALVE COVER TO MACHINE.
RE-INSTALLED ALL REMOVED COMPONENTS AND SHIELDS.
RAN UNIT, FUNCTION AND LEAK CHECKED.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
DZ128752	Gasket	1.00	31.35	$31.35	Y
R528620	GASKET	2.00	122.90	$245.80	Y
R531581	GASKET	1.00	90.48	$90.48	Y
R531582	GASKET	1.00	91.30	$91.30	Y
RE285844	CLAMP	1.00	171.08	$171.08	Y
RE541291	GASKET	1.00	34.06	$34.06	Y

Labor: $1,600.00 **Parts: $664.07** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $2,264.07**

J06230160 JD S680 Retail

COMPLAINT:

35 REPLACE CLEAN GRAIN DRIVE BELT

CAUSE:

CORRECTION:

REPLACED BELT

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
H223230	CleanGrainElevator V-Belt	1.00	503.20	$503.20	Y
Miscellaneous	**Description**	**Quantity**	**Net Price**	**Extended Price**	**Taxed Ind**
FRT	FREIGHT	1.00	35.00	$35.00	Y

Labor: $320.00 **Parts: $503.20** **OL&M: $0.00** **Misc: $35.00** **Sub-Total: $858.20**

JGEN38- Retail

COMPLAINT:

36 REPAIR HEADER

PATTISON AGRICULTURE LIMITED
Hwy 5 East, Box 2109
Humboldt, SK S0K 2A0
Phone: (306) 682-2572
Fax: (306) 682-2510
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

PATTISON AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice Number:	**3502902**
Invoice Date	11/04/2025
Location:	08
Work Order Number:	517209
Payment Type:	Credit Card
Authorization Number:	M 08073J
Page:	17 of 18

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S680	2296	1H0S680SPH0796439	764986	4

Service Reminders:
TENSION AUGER DRIVE CHAIN
REPLACED 1 WIND SCREEN FINGER
REMOVE AND RESEAL RIGHT HAND WIND SCREEN CYLINDER

CAUSE:

CORRECTION:

REMOVED CYLINDER, DIASSEMBLED, CLEANED, REASSEMBLED WITH NEW SEALS AND REINSTALLED.
REPLACED BROKEN WINDSCREEN FINGER
TENSIONED AUGER DRIVE CHAIN

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AH231461	FINGER	1.00	43.25	$43.25	Y
AHC16979	HYDRAULIC	1.00	31.56	$31.56	Y
AHC17587	Header Wing Tilt Hyd Cylinder HDF/R	1.00	101.40	$101.40	Y

Labor: $500.00 **Parts: $176.21** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $676.21**

JDISC JD ALL Retail

COMPLAINT:

37 GREEN LIGHT INSPECTION DISCOUNTS

CAUSE:

CORRECTION:

Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
DISC	Parts Discount	-1.00	1,199.49	-$1,199.49	Y

Miscellaneous Charges:

SERVICE ACCESSORIES	$150.00

Labor: $0.00 **Parts: $0.00** **OL&M: $0.00** **Misc: -$1,049.49** **Sub-Total: -$1,049.49**

PATTISON AGRICULTURE LIMITED
Hwy 5 East, Box 2109
Humboldt, SK S0K 2A0
Phone: (306) 682-2572
Fax: (306) 682-2510
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

PATTISON AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice Number:	**3502902**
Invoice Date	11/04/2025
Location:	08
Work Order Number:	517209
Payment Type:	Credit Card
Authorization Number:	M 08073J
Page:	18 of 18

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S680	2296	1H0S680SPH0796439	764986	4

Service Reminders:

Customer PO No:
Tax Exempt No:
Advisor: Sheila Lefebvre

Credit Card Information

Type: Credit Card
Auth No: M 08073J
Amount: $29,866.82

Labor:	$18,652.28
Parts:	$12,130.94
OL&M:	$0.00
Misc:	-$2,338.63
GST:	$1,422.23
PST:	$0.00
Grand Total:	$29,866.82

TERMS AND CONDITIONS

I hereby authorize the above repair work be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery. I agree to pay cash for such repair parts and labour on delivery of machine(s) or on terms satisfactory to you, and until paid in full, any such unpaid balance shall constitute a lien on this machinery. I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft or other causes beyond your control

Received by: ..... Date: .....