EquipmentName	Workshop	CodeAndSubCode	Description	CompletionComments	DateDone	Workstate	Location	Division	Rego	Supplier	EquipmentType
				265/70R19.5108V2							
T382	Colac - Colac	Tyres\FITMENT	Tyres\FITMENT	2 NEW TYRES P23.24 2 NWR DONE IN COLAC	04/09/2026	Unlocked	Colac	GTK	37689S	BORDER BANDAG PTY LTD -3	TRAILER
T382	Albury - Workshop	Brakes\ABS	abs fault		01/09/2026	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Colac - Colac	Susp\WHEEL ALGN	WHEEL ALIGNMENT		25/08/2026	Completed	Colac	GTK	37689S	GEELONG TRUCK AND STEERING	TRAILER
T382	Colac - Colac	Tyres\TP1+2	REPLACE TYRES WITH RUNOUTS POS 21 22		19/08/2026	Completed	Colac	GTK	37689S	BORDER BANDAG PTY LTD	TRAILER
T382	Albury - Workshop	VehService\DS	VehService\DS D Service		05/08/2026	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Chassis\WINCH/STRP	new quick release wire front winch		05/08/2026	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	VehService\DS	service		05/08/2026	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Elect\WORK LIGHT	replace broken work light		05/08/2026	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Tyres\FITMENT	Need tyres LH centre axle		05/08/2026	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Body\CONSUMABLE	both wear pads need replacing		05/08/2026	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Body\CONSUMABLE	Bolster pad's need replacing		05/08/2026	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	VehService\DS	VehService\DS D Service		25/07/2026	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Prevent\CONSUMABLE	Replace quick release wire front winch		25/07/2026	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Elect\WORK LIGHT	Replace broken work light RHS		25/07/2026	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Tyres\RUN OUT	Tyres\RUN OUT POS 25		25/07/2026	Completed	Colac	GTK	37689S	BORDER BANDAG PTY LTD - 4	TRAILER
T382	Albury - Workshop	VehService\DS	VehService\DS D Service	completed by SMc	09/07/2026	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	DrivLine\AXLE REPLC	Replace middle axle		01/07/2026	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Brakes\BOOSTER	Brakes\BOOSTER		15/06/2026	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Susp\AIR BAG	1. LEAKING AIRBAG L/R		15/06/2026	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
				Perform laser wheel alignment on triaxle A trailer. Fleet No : T382 Note : Found trailer tracking severally to the left - all axles. Cut out effected alignment plates and reposition axles as required. Reweld plates after							
T382	Albury - Workshop	DrivLine\WHEEL ALGN	Trailer need's wheel alignment, tracking to the Left.	correction	26/05/2026	Completed	Colac	GTK	37689S	HUME TRUCK TECHNICSP/L-4	TRAILER
T382	Albury - Workshop	Tyres\ALIGNMENT	hangs out to the left chasing cows		26/05/2026	Completed	Colac	GTK	37689S	HUME TRUCK TECHNICSP/L-4	TRAILER
T382	Albury - Workshop	Tyres\ALIGNMENT	needs wheel alignment		26/05/2026	Completed	Colac	GTK	37689S	HUME TRUCK TECHNICSP/L-4	TRAILER
				Perform laser wheel alignment on triaxle A trailer. Fleet No : T382 Note : Found trailer tracking severally to the left - all axles. Cut out effected alignment plates and reposition axles as required. Reweld plates after							
T382	Albury - Workshop	Tyres\ALIGNMENT	Needs wheel alignment tracking out 6 inches to the left	correction	26/05/2026	Completed	Colac	GTK	37689S	HUME TRUCK TECHNICSP/L-4	TRAILER
				Perform laser wheel alignment on triaxle A trailer. Fleet No : T382 Note : Found trailer tracking severally to the left - all axles. Cut out effected alignment plates and reposition axles as required. Reweld plates after							
T382	Albury - Workshop	Susp\WHEEL ALGN	Trailer is tracking down the road like a crab walking. T134028	correction	26/05/2026	Completed	Colac	GTK	37689S	HUME TRUCK TECHNICSP/L-4	TRAILER
T382	Albury - Workshop	Brakes\DAMAGE	brakes wheel bearing making horrible noise on both trailers		25/05/2026	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Brakes\SLACK ADJ	mr slack adjuster needs replacing		25/05/2026	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	VehService\DS	VehService\DS D Service		25/05/2026	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Tyres\RUN OUT	Tyres\RUN OUT POS 25		23/05/2026	Completed	Colac	GTK	37689S	BORDER BANDAG PTY LTD - 4	TRAILER
T382	Albury - Workshop	Tyres\TP11+12	Tyres\TP11+12 (31-32)		11/05/2026	Completed	Colac	GTK	37689S	BORDER BANDAG PTY LTD - 4	TRAILER
T382	Albury - Workshop	VehService\DS	VehService\DS D Service	completed by JS SMc	08/05/2026	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Tyres\Punct	Tyres\Punct POS 22		07/05/2026	Completed	Colac	GTK	37689S	BORDER BANDAG PTY LTD - 4	TRAILER
T382	Albury - Workshop	Tyres\RUN OUT	Tyres\RUN OUT	POS 21-21 + 23-24	01/05/2026	Completed	Colac	GTK	37689S	BORDER BANDAG PTY LTD - 4	TRAILER
T382	Albury - Workshop	Brakes\BRAKE ADJ	Brake adjustment	completed by TP	30/04/2026	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Chassis\CHN/RLR/MN	CHAIN ADJUSTMENT PULLEY BEARING IS COMPPLETELY WORN OUT.	ok KR	30/04/2026	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	VehService\DS	VehService\DS D Service	completed by SMc	30/04/2026	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Insp\ANN INSP	Insp\ANN INSP Annual Inspection As Per Checklist	completed by SMc	30/04/2026	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	VehService\DS	VehService\DS D Service	completed by SMc	14/04/2026	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Tyres\TP9+10	Tyres\TP9+10 (29-30)	CALL OUT	31/03/2026	Completed	Colac	GTK	37689S	BORDER BANDAG PTY LTD - 4	TRAILER
T382	Albury - Workshop	Elect\TRL LIGHTS	right rear blinker missing	CP MN	24/03/2026	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Body\AIR LEAK	air leak	SMc	18/03/2026	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Tyres\TP7+8	Tyres\TP7+8 (27-28)		26/02/2026	Completed	Colac	GTK	37689S	BORDER BANDAG PTY LTD - 4	TRAILER
T382	Albury - Workshop	Elect\TAIL LIGHT	REPAIR RR TAIL LIGHT		24/02/2026	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Elect\TAIL LIGHT	REPLACE LIGHTS IN REAR BAR		24/02/2026	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	VehService\DS	VehService\DS D Service		24/02/2026	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Body\BOLSTER	snapped 2 rear clamp bolts on the front bolster Needs reline middle axle		20/02/2026	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Brakes\BRK RELINE	Hydraulics\HYD LEAKS	FOUND AXLE UNSERVICABLE-REPLACED	29/01/2026	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Hydraulics\HYD LEAKS	leaking hydraulic lines to be replaced in umbilical arms		23/01/2026	Completed	Colac	GTK	37689S	RAPID HYDRAULICS	TRAILER
T382	Albury - Workshop	Susp\WHEEL ALGN	TRACKING LEFT		25/12/2025	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Susp\WHEEL ALGN	TRACKING LEFT		25/12/2025	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Susp\WHEEL ALGN	TRAILERS LEAD TO THE LEFT BY ABOUT 6 INCHES		25/12/2025	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	VehService\DS	VehService\DS D Service		23/12/2025	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Tyres\TP5+6	Tyres\TP5+6 (25-26)		04/12/2025	Completed	Colac	GTK	37689S	BORDER BANDAG PTY LTD - 4	TRAILER
T382	Albury - Workshop	Tyres\TP11+12	Tyres\TP11+12 (31-32)		04/12/2025	Completed	Colac	GTK	37689S	BORDER BANDAG PTY LTD - 4	TRAILER
T382	Albury - Workshop	VehService\DS	VehService\DS D Service		01/12/2025	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Brakes\BRK RELINE	Brake Reline R/H Centre, L/H Rear & L/H Front		01/12/2025	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Chassis\FIFTH WHEE	Chassis\FIFTH WHEE	inspect turn tables on all log trucks and trailers	30/11/2025	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Elect\TAIL LIGHT	Replace R/H Middle Tail Light		25/10/2025	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Chassis\AIR LEAK	Air Leak		25/10/2025	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	VehService\DS	VehService\DS D Service		25/10/2025	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Hydraulics\HYD LEAKS	HOOKED TO 1010. TESTED HYDRAULICS.		18/10/2025	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	DrivLine\WHEEL ALGN	Trailer Tracks To The Left		14/10/2025	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Body\STRAPS	CHECK STRAPS. SOME NEED REPLACING.		14/10/2025	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	VehService\DS	VehService\DS D Service		14/10/2025	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Chassis\AIR TANKS	WIRES TO AIR TANK NEEDS FIXING D/SIDE.		14/10/2025	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Chassis\WINCH/STRP	CHECK STRAPS. SOME NEED REPLACING		14/10/2025	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Tyres\Punct	Tyres\Puncture 26		10/10/2025	Completed	Colac	GTK	37689S	BORDER BANDAG PTY LTD - 4	TRAILER
T382	Albury - Workshop	Tyres\TP9+10	Tyres\TP9+10 (29-30)		10/10/2025	Completed	Colac	GTK	37689S	BORDER BANDAG PTY LTD - 4	TRAILER
T382	Albury - Workshop	Tyres\TP11+12	Tyres\TP11+12 (31-32)		07/10/2025	Completed	Colac	GTK	37689S	BORDER BANDAG PTY LTD - 4	TRAILER

T382	Albury - Workshop	Susp\SUSPENSION	Replace Broken U-Bolts R/H/S Middle Axle		04/10/2025	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Susp\WHEEL ALGN	TRACKING TO LEFT		04/10/2025	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Susp\WHEEL ALGN	TRACKING TO LEFT.		04/10/2025	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Elect\ELECT P&W	CLEARANCE LIGHT KEEP TRIPPING FUSE AND BLINKERS.		03/10/2025	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Elect\INDICATORS	R/H/S indicator Not Working		03/10/2025	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	VehService\DS	Service		03/10/2025	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Elect\ELECT P&W	CLEARANCE LIGHT KEEP TRIPPING FUSE AND BLINKERS		03/10/2025	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	VehService\DS	VehService\DS D Service		03/10/2025	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Elect\TRL LIGHTS	Repair taillight issues.	-tail lights wiring repaired and replaced as required	01/10/2025	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Tyres\TP1+2	Tyres\TP1+2	FRONT AXLE OUT OF ALIGNMENT THIS CAUSED ABNORMAL TYRE WEAR	24/09/2025	Completed	Colac	GTK	37689S	BORDER BANDAG PTY LTD - 4	TRAILER
T382	Albury - Workshop	Tyres\TP3+4	Tyres\TP3+4	FRONT AXLE OUT OF ALIGNMENT THIS CAUSED ABNORMAL TYRE WEAR	24/09/2025	Completed	Colac	GTK	37689S	BORDER BANDAG PTY LTD - 4	TRAILER
T382	Albury - Workshop	Tyres\TP11+12	Tyres\TP11+12 (31-32)		22/09/2025	Completed	Colac	GTK	37689S	BORDER BANDAG PTY LTD - 4	TRAILER
T382	Albury - Workshop	Susp\AXLES	ADJUST WHEEL ALIGNMENT ON FRONT AND REAR AXLE.		03/09/2025	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Brakes\BRK RELINE	RELINED LM		03/09/2025	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Tyres\Punct	Tyres\Puncture POS 31		02/09/2025	Completed	Colac	GTK	37689S	BORDER BANDAG PTY LTD - 4	TRAILER
T382	Albury - Workshop	VehService\DS	VehService\DS D Service		02/09/2025	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	VehService\DS	VehService\DS D Service		02/09/2025	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Chassis\FIFTH WHEE	Dog Bones		02/09/2025	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Chassis\FIFTH WHEE	Ball Race Has Movement		02/09/2025	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Chassis\FIFTH WHEE	Turn Table Bushes		02/09/2025	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Brakes\CONSUMABLE	Right Rear Backing Plate		02/09/2025	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Brakes\BOOSTER	Needs All New Booster Lines		02/09/2025	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Susp\SUSPENSION	Front Right Spring Wrap & Bunch Of Alignment Plates		02/09/2025	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Susp\SUSPENSION	Right Rear Spring Eye Bushes		02/09/2025	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Chassis\FIFTH WHEE	Turn Table Wear Pads (Slide Pads)		02/09/2025	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Brakes\BRAKE ADJ	Right Rear Brake Pad Kicking		02/09/2025	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Chassis\CROSS MBR	Rear Bar Cracked Through		02/09/2025	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Susp\SUSPENSION	Right Rear Spring Wrap		02/09/2025	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Susp\WHEEL ALGN	Right Rear Alignment Plate		02/09/2025	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Chassis\CROSS MBR	Cross Brace Loose		02/09/2025	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Body\CHN/RLR/MN	Adjust load chain		02/09/2025	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Tyres\RUN OUT	Tyres\RUN OUT 9-10 11-12		29/07/2025	Completed	Colac	GTK	37689S	BORDER BANDAG PTY LTD - 4	TRAILER
T382	Albury - Workshop	Elect\ELECT P&W	CLEARANCE LIGHT NOT WORKING ON GUARD R/S.		18/07/2025	Completed	Colac	GTK	37689S	TUMUT AUTO ELECTRICS PTY LTD -4	TRAILER
T382	Albury - Workshop	Tyres\TP3+4	Tyres\TP3+4 (23-24)		02/07/2025	Completed	Colac	GTK	37689S	BORDER BANDAG PTY LTD - 4	TRAILER
T382	Albury - Workshop	Tyres\TP1+2	Tyres\TP1+2 (21-22)		02/07/2025	Completed	Colac	GTK	37689S	BORDER BANDAG PTY LTD - 4	TRAILER
T382	Albury - Workshop	Tyres\TP7+8	Tyres\TP7+8 (27-28)		02/07/2025	Completed	Colac	GTK	37689S	BORDER BANDAG PTY LTD - 4	TRAILER
T382	Albury - Workshop	Chassis\AIR TANKS	Tank Loose		30/06/2025	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Elect\INDICATORS	Left blinker not working		30/06/2025	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	VehService\DS	VehService\DS D Service		30/06/2025	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Body\CHN/RLR/MN	Rear trailer load up rollers need replacing		30/06/2025	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Elect\INDICATORS	Indicators on rear bar not working	Inspected indicators on both sides of rear bar. Found broken wiring for both. Repaire	03/06/2025	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Elect\ELECT P&W	Plug on 2nd bolster lights damaged	Extended wiring and replaced plugs with magnetic couplings	03/06/2025	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	VehService\DS	VehService\DS D Service		03/06/2025	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Tyres	Tyres - SPARE		29/05/2025	Completed	Colac	GTK	37689S	BEAUREPAIRES - 4	TRAILER
T382	Albury - Workshop	Tyres\TP5+6	Tyres\TP5+6		26/05/2025	Completed	Colac	GTK	37689S	BEAUREPAIRES - 4	TRAILER
T382	Albury - Workshop	VehService\DS	VehService\DS D Service		03/05/2025	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
			Check over Short issue with clearance lights, found two not working at all on a trailer, removed and replaced had shorted section through pipe, repaired. Still shorting isolated to A Trailer, disconnected sections where possible at rear and to swing arm feeding B trailer. Found some rubbing in rear tail light. Insulated refitted lights, rechecked still shorting, cut cable tyres and inspected over middle section opened up found hot at junction point, cut out 2 metres and repaired								
T382	Albury - Workshop	Elect\TRL LIGHTS	section, resecured and tested not shorting now, all lights working ok		02/05/2025	Completed	Colac	GTK	37689S	TUMUT AUTO ELECTRICS PTY LTD -4	TRAILER
T382	Wodonga - Workshop	Tyres	Tyres UNKNOWN		23/04/2025	Completed	Colac	GTK	37689S	BEAUREPAIRES	TRAILER
T382	Wodonga - Workshop	Tyres\TP1+2	Tyres\TP1+2		23/04/2025	Completed	Colac	GTK	37689S	BEAUREPAIRES	TRAILER
T382	Albury - Workshop	Insp\ANN INSP	Annual Inspection		11/04/2025	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	VehService\DS	VehService\DS D Service		11/04/2025	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	VehService\DS D Service	Change narva heavy duty light plug at back of trailer Replaced missing xmember boltsc Alignment plates axel 1 and 2 broken at weld truck loaded needs to come back empty	04/03/2025	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	VehService\DS	VehService\DS D Service		19/02/2025	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Body\TRL LEGS	Re-fit Trailer Leg Post/Tube.		11/02/2025	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Susp\SHOCK ABS	F/L shocker mount plate to be replaced.		11/02/2025	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	VehService\DS	This job was not done by me	28/01/2025	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Tyres\PRES CHECK	CHECK TYRES	Referred to tyre people	28/01/2025	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes\AIR LEAK	air valve leaking		28/01/2025	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Comp\Truck Safe	No nhvr sticker trucksafe out of date		28/01/2025	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Tyres\TP1+2	Tyres\TP1+2	Fix air leak lhs chassis Hydrolic fitting leak	21/01/2025	Completed	Colac	GTK	37689S	BEAUREPAIRES - 4	TRAILER
T382	Wodonga - Workshop	VehService\DS	VehService\DS	Llhr tail light replace	21/12/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	VehService\DS	I	05/12/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
			REPLACED TYRES AT GOODYEAR GUNDAGAI.								
T382	Wodonga - Workshop	Tyres\FITMENT	PO ORDER NO. T090258 &T090259		14/11/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Tyres\CASE STOCK	Tyres For Stock. (Tuckerbox Tyres Gundagai P/O: T090046)		12/11/2024	Completed	Colac	GTK	37689S	BEAUREPAIRES - 4	TRAILER
T382	Albury - Workshop	Tyres\TP10	Replace Tyres On Position 10. (Tuckerbox Tyres Gundagai P/O: T090045)		12/11/2024	Completed	Colac	GTK	37689S	BEAUREPAIRES - 4	TRAILER
T382	Albury - Workshop	Tyres\TP09	Replace Tyres On Position 9. (Tuckerbox Tyres Gundagai P/O: T090045)		12/11/2024	Completed	Colac	GTK	37689S	BEAUREPAIRES - 4	TRAILER
T382	Wodonga - Workshop	VehService\DS	VehService\DS		11/11/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	VehService\DS		21/10/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	VehService\DS		13/09/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Tyres\ALIGNMENT	Carry Out Wheel Alignment (Hume Truck Technics P/O: T088160)		09/08/2024	Completed	Colac	GTK	37689S	HUME TRUCK TECHNICSP/L-4	TRAILER
T382	Wodonga - Workshop	Chassis\FIFTH WHEE	LOAD CHAIN NEEDS FIXING.		06/08/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	VehService\DS	Front right and rear right spring wraps are broken	06/08/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	VehService\DS		18/07/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Tyres\FITMENT	CHECK TYRES.		18/07/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Susp\SUSPENSION	Replace right front spring arm	Remove bent spring wrap and repair air leak in truck 1000 towing t382 Spring was not damaged	17/07/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER

T382	Wodonga - Workshop	Chassis\FIFTH WHEE	SERVICED TOP HALF OF TRAILER. CHECKED BALLRACE AND GREASED THOROUGHLY. REPAII		27/06/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	VehService\DS		24/06/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Elect\ELECT P&W	LIGHTS NEED FIXING ON LIGHT BAR.		24/06/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Elect\INDICATORS	L/H BLINKER NEED FIXING.		24/06/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Elect\ELECT P&W	NO SCALES.		24/06/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Tyres\TP11+12	Tyres\TP11+12		15/06/2024	Completed	Colac	GTK	37689S	BEAUREPAIRES - 4	TRAILER
T382	Albury - Workshop	Tyres\TP7+8	Tyres\TP7+8		15/06/2024	Completed	Colac	GTK	37689S	BEAUREPAIRES - 4	TRAILER
T382	Albury - Workshop	Tyres\TP3+4	Tyres\TP3+4		15/06/2024	Completed	Colac	GTK	37689S	BEAUREPAIRES - 4	TRAILER
T382	Albury - Workshop	Tyres\TP9+10	Tyres\TP9+10		15/06/2024	Completed	Colac	GTK	37689S	BEAUREPAIRES - 4	TRAILER
T382	Albury - Workshop	Tyres\TP5+6	Tyres\TP5+6		15/06/2024	Completed	Colac	GTK	37689S	BEAUREPAIRES - 4	TRAILER
T382	Albury - Workshop	Tyres\FITMENT	CHECK TYRES.		15/06/2024	Completed	Colac	GTK	37689S	BEAUREPAIRES - 4	TRAILER
T382	Wodonga - Workshop	Chassis\CROSS MBR	X members cracked		13/06/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Susp\AIR BAG	Front right airbag minor airleak		13/06/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Chassis\CROSS MBR	X members cracked First Axel. Top saddle lhs cracked	i	13/06/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Chassis\CROSS MBR	Cross members cracked rear bar cracked		13/06/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Unknown\No Show	Gypsy chain not connected at turntable due to broken weld chain wrapped around cross member on chassis Replace broken anchor mounts for load chain. fit load chain around Gypsy		13/06/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Body\CHN/RLR/MN	Replace rear anchors & hammerlocks.		13/06/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	VehService\DS		07/06/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Myrtleford - Workshop	VehService\DS	D Service	REPAIRED LH INDICATOR WIRING. ADJUST WHEEL BEARINGS.	07/06/2024	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Wodonga - Workshop	Elect\ELECT P&W	REVERSE LIGHTS NOT WORKING. WORK LIGHTS NOT WORKING. Indicators Short Out When Turning Left Or Right		20/04/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Elect	*T R/S Only Truck Ok*		20/04/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Elect\WORK LIGHT	Rear Work Light Not Working		20/04/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Tyres	Worn Tyres Front Axle L/H/S		20/04/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Elect\TRL LIGHTS	Rewire Taillight Bar - Shorts R/H/S Indicator Currently Disconected		20/04/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		20/04/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	REPLACED UMBILICAL ARM BEARINGS.	20/04/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Chassis\FIFTH WHEE	REPLACE TURNTABLE DOGBONES.		20/04/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Chassis\CROSS MBR	REAR CROSSMEMBER CRACKED.		20/04/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Tyres\TP1+2	Tyre Position 1 + 2		13/04/2024	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Tyres\TP10	Tyre Position 10		07/04/2024	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Wodonga - Workshop	Elect\ELECT P&W	REPLACE 2ND BOLSTER MAGNETIC LIGHTS CONNECTOR.		04/04/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes\BRK RELINE	RELINED LF		04/04/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Comp\Truck Safe	REPLACE NHVR STICKER.		04/04/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Chassis\CROSS MBR	REPAIR CRACKED CROSSMEMBERS.		04/04/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Susp\SUSPENSION	RF SPRING WRAP BROKEN.		04/04/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Chassis\CROSS MBR	CRACKED CROSSMEMBER 3RD AXLE RHS.		04/04/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		04/04/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		04/04/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes\EBS FAULTS	CHECKED CODES. REPLACED LR SENSOR CABLE. CLEARED CODES.	PREVIOUSLY COMPLETED.	20/03/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Comp\Truck Safe	REPLACE NHVR STICKER.		20/03/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Chassis\CROSS MBR	REPAIRED CRACKED CROSSMEMBERS.		20/03/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Susp\SUSPENSION	RF SPRING WRAP BROKEN.		20/03/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Chassis\CROSS MBR	CRACKED CROSSMEMBER 3RD AXLE RHS.		20/03/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Susp\AXLES	RF AXLE U-BOLT BRACKET CRACKED.		20/03/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		20/03/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		20/03/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes\BRK RELINE	RELINE RF.		20/03/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes\EBS FAULTS	CHECKED CODES. REPLACED LR SENSOR CABLE. CLEARED CODES.		05/03/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		05/03/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	REPAIRED LH INDICATOR.	05/03/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Tyres\TP12	Tyre Position 12		27/02/2024	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Tyres\TP06	Tyre Position 6		27/02/2024	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Wodonga - Workshop	Susp\SUSPENSION	REPLACED LF SEB.		20/02/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		20/02/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		20/02/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		19/02/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		19/02/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Elect\WORK LIGHT	Work lights not working		06/02/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Elect\INDICATORS	LEFT INDICATOR NOT WORKING.		06/02/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes\EBS FAULTS	TRAILER ABS LIGHT ON.		06/02/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Elect\ELECT P&W	KEEPS THROWING CIRCUIT BREAKER "RIGHT HAND"		06/02/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Susp\SUSPENSION	RF SPRING WRAP BROKEN.		06/02/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Chassis\CROSS MBR	CRACKED CROSSMEMBER 3RD AXLE RHS.		06/02/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		06/02/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		06/02/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Comp\Truck Safe	REPLACE NHVR STICKER.		06/02/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Chassis\CROSS MBR	REPAIRED CRACKED CROSSMEMBERS.		06/02/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Susp\AXLES	RF AXLE U-BOLT BRACKET CRACKED.		06/02/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes\BRK RELINE	RELINE RF.		06/02/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Elect\TRL LIGHTS	Short in R/H indicator		06/02/2024	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		29/12/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		29/12/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Chassis\CROSS MBR	COMPLETED WELDING REPAIRS.		09/12/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Susp\SUSPENSION	RF SPRING WRAP BROKEN.		08/12/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Chassis\CROSS MBR	CRACKED CROSSMEMBER 3RD AXLE RHS.		08/12/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Brakes\BRK RELINE	reline L/M and rear axle		08/12/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Insp\ANN INSP	Annual Inspection		08/12/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Brakes\AIR LEAK	HAS AN AIR WHEN BRAKES APPLIED. LEAKING FROM CETRE AXLE AREA. TRUCK FEELS HARD		08/12/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Hydraulics\OIL LEAK	OIL LEAKING AT COUPLING.	REPLACED COUPLINGS.	08/12/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Tyres\RETREAD	Check Tyres		08/12/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Elect\INDICATORS	LEFT INDICATOR NOT WORKING.	REPLACED PLUG TO INDICATOR.	08/12/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Brakes\EBS FAULTS	TRAILER ABS LIGHT ON.		08/12/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Elect\ELECT P&W	KEEPS THROWING CIRCUIT BREAKER "RIGHT HAND"		08/12/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER

T382	Albury - Workshop	Comp\Truck Safe	NHVR sticker missing		08/12/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Chassis\CHAS CRACK	1st winch cracked and missing bolt		08/12/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		08/12/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	VehService\DS	Service As Per Attached Checklist	REPLACED RR SHOCK AND SIDE MARKER. REPAIRED AIR HOSES AND HYDRAULIC COU	08/12/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Workshop\MOVE ASSET	FOLDED AND MOVED TRAILERS.		07/12/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Tyres\TP7+8	replace tyres		30/11/2023	Completed	Colac	GTK	37689S	BEAUREPAIRES - 4	TRAILER
T382	Albury - Workshop	Tyres\TP3+4	replace tyres		30/11/2023	Completed	Colac	GTK	37689S	BEAUREPAIRES - 4	TRAILER
			TRAVEL OUT TO GREENFRIGHT YARD, CHECK EBS ON TRAILER FOUND LIGHT TSAYING ON WHEN B TRAILER IS CONNECTED CHECK WIRING AND EBS PLUGS PLUS SOCKET ON TRAILER ARE OKAY. CHECL POWER AND EARTH ALL OKAY, CHECK WIRING AT EBS MODULE, TESTS ALL OKAY DISSCONNECT PLUG ON MOUDLE, EBS LIGHT WENT AWAY. CHECK OUTPUT ON MODULE PLUG, TEST ALL OKAY ISSUE WITH EBS MODULE OR SENSORS HAVENT GOT HALDEX SOFTWARE,								
T382	Albury - Workshop	Elect\ELECT P&W	TO CHECK CODES AND WORKSHOP WAS SHUT		28/11/2023	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		28/11/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	REPLACED UMBILICAL ARM BEARINGS AND REAR ARM.	28/11/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Tyres\RETREAD	Check Tyres		16/11/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Elect\TRL LIGHTS	Only One Tail Light Left Hand		16/11/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Elect\INDICATORS	LEFT INDICATOR NOT WORKING.		16/11/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Brakes\BRAKE ADJ	ADJUST BRAKE.		16/11/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Brakes\EBS FAULTS	TRAILER ABS LIGHT ON.		16/11/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Elect\ELECT P&W	KEEPS THROWING CIRCUIT BREAKER "RIGHT HAND"		16/11/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Comp\Truck Safe	NHVR sticker missing		16/11/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Chassis\CHAS CRACK	1st winch cracked and missing bolt		16/11/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Brakes	Record Check Results As Attached To This Job Service As Per Attached Checklist (TCTC)		16/11/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	VehService\DS	Purchase Order Number: T082287	ADJUSTED LM RF WHEEL BEARINGS.	16/11/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Tyres\FITMENT	1-2		09/11/2023	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Wodonga - Workshop	Chassis\CROSS MBR	Repair All Cross Member Cracks Electrical Short In PTO Circuit (Hagan's)		21/10/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Elect\ELECT P&W	Purchase Order Number: WW081526		10/10/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Elect\INDICATORS	LEFT INDICATOR NOT WORKING.		10/10/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes\BRAKE ADJ	ADJUST BRAKE.		10/10/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes\EBS FAULTS	TRAILER ABS LIGHT ON.		10/10/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
				Perform laser wheel alignment on triaxle A trailer. Partial suspension rebuild by GF workshop. Found broken alignment plate left rear . Cut out plate and replace. Weld all plates							
T382	Wodonga - Workshop	Susp\WHEEL ALGN	R/H front axld out of alignment	as required	10/10/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Elect\ELECT P&W	KEEPS THROWING CIRCUIT BREAKER "RIGHT HAND"		10/10/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Susp\SUSPENSION	Left middle and front rght spring wrapper broken	REPLACED LM RM SPRING WRAPS AND RM ALIGNMENT PLATE.	10/10/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Comp\Truck Safe	NHVR sticker missing		10/10/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Chassis\CHAS CRACK	1st winch cracked and missing bolt		10/10/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Body\CHN/RLR/MN	needs links cut out of chain	CUT 4 LINKS OUT. WELDED NEW PULL UP LUGS.	10/10/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Chassis\CROSS MBR	Cracked cross member gussets.		10/10/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Susp\SUSPENSION	Left middle and front rght spring wrapper broken		23/09/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Comp\Truck Safe	NHVR sticker missing		23/09/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Chassis\CHAS CRACK	1st winch cracked and missing bolt		23/09/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Body\CHN/RLR/MN	needs links cut out of chain		23/09/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Tyres	CHECK TYRES.	tyres look fine	23/09/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
				Wire came out of terminal, put new terminal on.							
T382	Wodonga - Workshop	Elect\INDICATORS	RIGHT HAND BLINKER NOT WORKING.	Terminal used is wrong size due to not having correct size.	23/09/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Elect\ELECT P&W	KEEPS THROWING CIRCUIT BREAKER "RIGHT HAND"		23/09/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Chassis\CROSS MBR	Cracked cross member gussets.		23/09/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		23/09/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	RR u olt Loose and Nut missing - replaced U bolt	23/09/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Tyres\TP11+12	Tyre Position 11 + 12		21/09/2023	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Tyres\TP9+10	Tyre Position 9 + 10		21/09/2023	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		03/09/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
				CHECK INDICATORS SHORTING OUT FOUND FAULTY CONNECTOR UNDER A TRAILER REPLACE AS REQUIRED FOUND WIRES BROKEN AT INDICTATOR LIGHTS ON A AND B TRAILER							
T382	Wodonga - Workshop	Elect\INDICATORS	BLINKERS KEEPS POPPING CIRCUIT BREAKER.	REPAIR AS REQUIRED OPERATION OK	03/09/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Chassis\CROSS MBR	Cracked cross member gussets.	TOO DIRTY AND LOADED TO FIND CRACKS.	03/09/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		03/09/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		13/08/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		13/08/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Tyres\TP7+8	Tyre Position 7 + 8		12/08/2023	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Tyres\TP5+6	Tyre Position 5 + 6		12/08/2023	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Tyres\TP3+4	Tyre Position 3 + 4		12/08/2023	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Wodonga - Workshop	Susp\WHEEL ALGN	A TRAILER TRACK TO THE LEFT.	SIGNED OFF BY COCHISE LOVE.	29/07/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job	PERFORMED BY COCHISE LOVE.	29/07/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	COCHISE LOVE LABOUR 10:00-12:00.	29/07/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Elect\INDICATORS	BLINKERS KEEPS POPPING CIRCUIT BREAKER.		15/07/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Chassis\CROSS MBR	Cracked cross member gussets.		15/07/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		15/07/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
				Replaced 4 x bolts middle axle U bolts. Tightened rear right shock mount.							
T382	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	Replaced slide lock mechanism.	15/07/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER

			REPLACE SCALE MASTER LEAD WITH CUSTOMER SUPPLIED PART - Cut cable ties and remove wrapping from umbilical - Disconnect and remove cable. - Fit new cable and secure into harness. - Insulate using silicone hose. - Wire in new plugs to cable and none on lead. - Resecure and wrap umbilical and harness.								
T382	Wodonga - Workshop	Chassis\SCALES	- Operate trailers and check for clearance, all ok.	Drive to TCTC and sort out scale issue with Mechanic.	24/06/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Elect\ELECT P&W	Scales	Returned and give correct connections to loom.	24/06/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Chassis	TRAVELLED TO AND FROM TCTC. INSPECTED T382. PICKED UP 1066.		22/06/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		21/06/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	REPLACED BROKEN BACKING PLATES	21/06/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Chassis\CROSS MBR	Cracked cross member gussets.		15/06/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Elect\INDICATORS	Blinker keeps tripping circuit breaker.	Refer job # 412586	15/06/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Elect\INDICATORS	BLINKERS KEEPS POPPING CIRCUIT BREAKER.		15/06/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Susp\WHEEL ALGN	A TRAILER TRACK TO THE LEFT.		15/06/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		15/06/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		15/06/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Body\AIR LEAK	air leak on A trailer winch		03/06/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Body\AIR LEAK	replace leaking winch tap		03/06/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Susp\SUSPENSION	broken V U Bolt plate mount saddle	drive to shelly & inspect shock. Found bottom saddle on L/M has snapped with 3 nuts missing on U bolts. Chaned axle to spring arm as heigh control valve is run off L/M position, chaining axle would interfere with HCV. Follow back to yard and swap trailers. REPAIRED BROKEN LHM SADDLE.	03/06/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Workshop\CLEAN	Clean workshop while waiting on parts.		23/05/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Elect\ELECT P&W	SCALES BAY 1 NEED FIXING. IT'S ONLY BEEN 3 MONTHS.	Refer Job # 410791	23/05/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	DrCabElect\SCALES	SCALES BAY 1 NEED FIXING IT'S ONLY BEEN 3 MONTHS.	Refer Job # 410791	23/05/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Elect\ELECT P&W	NO SCALES ON 1ST BAY.	Refer Job # 410791	23/05/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Elect\ELECT P&W	NO SCALES ON FRONT BAY.	Refer Job # 410791	23/05/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Elect\ELECT P&W	NO SCALES ON 1ST BAY.	Refer Job # 410791 Test wiring harness from front of trailer to master slave. Found pin D for constant poer open line. Pin A & C in spec, Pin B not used ordered new harness. Replace harness. Wire new socket at front of trailer and secure harness throughout chassis. Includes loading up ball race out of the way. Finish securing harness & plug into master slave. Park trailers and unhook.	23/05/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Elect\ELECT P&W	NO SCALES ON 1ST BAY A TRAILER.	Still requires testing with a truck fitted with scales.	23/05/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Workshop\MOVE ASSET	Pick up from TCTC		16/05/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Unknown	SERVICE.		16/05/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection		16/05/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Elect\INDICATORS	Blinker keeps tripping circuit breaker.		16/05/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Elect\INDICATORS	BLINKERS KEEPS POPPING CIRCUIT BREAKER.		16/05/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Susp\WHEEL ALGN	A TRAILER TRACK TO THE LEFT.		16/05/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Susp\SPRNG HANG	DURING SERVICE FOUND RHF & RHR SPRING WRAPS BROKEN - Raise and support axles. Remove u-bolts - Remove spring eye bolt and lower spring - Replace spring wrap and refit spring and removed components. - Lower axles and tension as required. A TRAILER TRACKS TO THE LEFT.		16/05/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		16/05/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		16/05/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Tyres\TP1+2	runouts		11/05/2023	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Tyres\TP11+12	Tyre Position 11 + 12		11/05/2023	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Tyres\TP9+10	Tyre Position 9 + 10		11/05/2023	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Wodonga - Workshop	Elect\ELECT P&W	NO SCALES ON 1ST BAY.		29/04/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Elect\ELECT P&W	NO SCALES ON FRONT BAY.		29/04/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Elect\ELECT P&W	NO SCALES ON 1ST BAY.		29/04/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Elect\ELECT P&W	NO SCALES ON 1ST BAY A TRAILER.		29/04/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		29/04/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	job changed to 4:30	29/04/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Hydraulics\HYD LEAKS	Repair Hydraulic Leak on umbilical arm (Rapid Hyrdaulics) Purchase Order Number: WW077871	replaced hose on umbilical arm was leaking throw the o-ring on the swivel fitting tested to make sure hoses went back in place	21/04/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Elect\ELECT P&W	NO SCALES ON 1ST BAY.		20/04/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Elect\ELECT P&W	NO SCALES ON FRONT BAY.		20/04/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Elect\ELECT P&W	NO SCALES ON 1ST BAY.		20/04/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Elect\ELECT P&W	NO SCALES ON 1ST BAY A TRAILER.		20/04/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Susp\WHEEL ALGN	A TRAILER TRACK TO THE LEFT.		20/04/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Susp\WHEEL ALGN	A TRAILER TRACKS TO THE LEFT.		20/04/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		20/04/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		20/04/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Unknown	SERVICE.		06/04/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		06/04/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		06/04/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Unknown	DUE FOR B SERVICE.		06/04/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		31/03/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		31/03/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		24/03/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		24/03/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Elect\ELECT P&W	NO SCALES ON 1ST BAY.		24/03/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Elect\ELECT P&W	NO SCALES ON 1ST BAY A TRAILER.		24/03/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		17/03/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		17/03/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Susp\WHEEL ALGN	A TRAILER TRACK TO THE LEFT.		08/03/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Elect\ELECT P&W	LIGHTS ON SECOND BOLSTER NOT WORKING.		08/03/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Elect\INDICATORS	R/H BLINKER NOT WORKING.		08/03/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER

T382	Wodonga - Workshop	Susp\WHEEL ALGN	A TRAILER TRACKS TO THE LEFT.		08/03/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		08/03/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		08/03/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Unknown	DUE FOR B SERVICE.		08/03/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Tyres\TP7+8	Tyre Position 7 + 8		08/03/2023	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Tyres\TP5+6	Tyre Position 5 + 6		08/03/2023	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Tyres\TP1+2	Tyre Position 1 + 2		08/03/2023	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		24/02/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		24/02/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Tyres\TP7+8	Tyre Position 7 + 8		17/02/2023	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Wodonga - Workshop	Chassis\AMB ARM	TIGHTENED UMBILICAL ARMS.		10/02/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Elect\ELECT P&W	PLUGGED RR INDICATOR IN. REPLACED RR WORKLIGHT AND REPAIRED REAR BAR TO FIT. R		10/02/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Chassis\BOLSTER	TURNED RF LR RR PEGS.		10/02/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Susp\WHEEL ALGN	A TRAILER TRACKS TO THE LEFT.		10/02/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Susp\SUSPENSION	REAR AXLE MOVING AROUND.	REPLACED LR SEB.	10/02/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		10/02/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	ADJUSTED RM WHEEL BEARING AND LOAD CHAIN.	10/02/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Tyres\TP9+10	Tyre Position 9 + 10		25/01/2023	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		19/01/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		19/01/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Susp\WHEEL ALGN	TRAILER STILL TRACKS TO THE L/H/S ABOUT 65MM.		19/01/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Susp\WHEEL ALGN	TRAILERS TRACK OUT OF LINE TOO. L/H/S.		19/01/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Susp\SUSPENSION	RF SPRING WRAP BROKEN.		19/01/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Chassis\CROSS MBR	CROSSMEMBER GUSSETS BEHIND 2ND BOLSTER CRACKED.		19/01/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Chassis\CHAS CRACK	CRACK AT LF TOP RAIL. OLD WELD.		19/01/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Susp\AXLES	Replaced Broken Shock Mount & Alignment Plate		19/01/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Elect\INDICATORS	RIGHT SIDE INDICATOR MISSING.		14/01/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Tyres\TP1+2	Tyre Position 1 + 2		14/01/2023	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		10/01/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Susp\WHEEL ALGN	TRAILER STILL TRACKS TO THE L/H/S ABOUT 65MM.		10/01/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Comp\Truck Safe	REPLACE NHVAS STICKER.		10/01/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Susp\SUSPENSION	RF SPRING WRAP BROKEN.		10/01/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Chassis\CROSS MBR	CROSSMEMBER GUSSETS BEHIND 2ND BOLSTER CRACKED.		10/01/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		10/01/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Comp\Truck Safe	REPLACE NHVAS STICKER.		04/01/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Elect\ELECT P&W	CLEARANCE LIGHT NOT WORKING L/H FRONT ON MUD GUARD.		04/01/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		04/01/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		04/01/2023	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Tyres\TP10	runout		23/12/2022	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Wodonga - Workshop	Susp\SUSPENSION	RF SPRING WRAP BROKEN.		17/12/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Chassis\CROSS MBR	CROSSMEMBER GUSSETS BEHIND 2ND BOLSTER CRACKED.		17/12/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		17/12/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		17/12/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Tyres\TP11+12	Tyre Position 11 + 12		17/12/2022	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Tyres\TP02	puncture repair		17/12/2022	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		07/12/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	WELDED ALIGNMENT PLATE.	07/12/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Tyres\TP9+10	Tyre Position 9 + 10		30/11/2022	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Wodonga - Workshop	Chassis\CHAS CRACK	CRACK AT LF TOP RAIL. OLD WELD.		30/11/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Susp\WHEEL ALGN	TRAILERS TRACK OUT OF LINE TOO. L/H/S.		30/11/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		30/11/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		30/11/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		23/11/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		23/11/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	DrivLine\WHEEL BRGS	R/H/MIDDLE AXLE GETTING HOT (SMOKIN) GRAEME CHAINED IT UP.	UNHOOKED. INSPECTED HUB. REBUILT HUB. CHECKED AND REPACKED ALL BEARINGS	17/11/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Tyres\TP07	Tyre Position 7		16/11/2022	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Tyres\TP5+6	Tyre Position 5 + 6		16/11/2022	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Wodonga - Workshop	DrivLine\WHEEL BRGS	TRAVELLED TO AND FROM JINGELLIC. CHAINED UP RM AXLE. ADJUSTED BRAKES.		16/11/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Susp\WHEEL ALGN	TRAILERS TRACK OUT OF LINE TOO. L/H/S.		16/11/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		16/11/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		16/11/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Myrtleford - Workshop	Body\WHL HUB	front R/H axle missing cap	fit wheel bearing cap	10/11/2022	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Wodonga - Workshop	Workshop\CLEAN	Clean workshop after relines.		09/11/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Susp\SHOCK ABS	Shock mounts centre left rear right.		09/11/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes\AIR LEAK	REPAIR AIR LEAK.		09/11/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes\BRK RELINE	FULL RELINE.	Relined all brakes, bearings, S cams, & Bushes, Slack adjusters & LHR Drum.	09/11/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes\BRK RELINE	RELINE REAR.	Refer Job# 395365	09/11/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job	Reline completed	09/11/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		09/11/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes\BRK RELINE	FULL RELINE.		29/10/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		29/10/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		29/10/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Susp\AIR BAG	Replaced RHM Airbag		24/10/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		21/10/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		21/10/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Tyres\TP08	fit runout		21/10/2022	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Wodonga - Workshop	Unknown	SERVICE.		14/10/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes\BRK RELINE	RELINE REAR.		14/10/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Hydraulics\HYD LEAKS	HYDRAULIC LEAK IN UMBILICAL ARM.		14/10/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes\ABS	Trailer ABS coming on empty or loaded		14/10/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		14/10/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		14/10/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Chassis\STRAPS	FIT NEW RATCHET ON SAFETY CHAIN.		11/10/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Body\STRAPS	Replace Ratchet Dog		11/10/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		05/10/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		05/10/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		01/10/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		01/10/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	DrivLine\DAMAGE	LEFT HAND REAR AXLE STRIPPED STUD.		22/09/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		22/09/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER

T382	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		22/09/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Elect\WORK LIGHT	INSPECT WORK LIGHTS.	CHECKED FUSES. TESTED POWER. CHECKD PLUG. FOUND WIRED WRONG. REPAIRED.	17/09/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Susp\SHOCK ABS	LHR SHOCK STUD SNAPPED	- Clean up stud surface. Weld new stud and fit new shock with strap.	17/09/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Chassis\CHAS CRACK	WELD REPAIR CRACKS IN CHASSIS	Grind out cracks and prepare. Weld cracks and clean surfaces. Paint.	17/09/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Susp\AIR LEAK	T-PIECE AT THE RIDE HEIGHT VALVE LEAKING.		17/09/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Susp\AIR BAG	L/H/R AIRBAG LEAK.		17/09/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	DrivLine\DAMAGE	STRIPPED WHEEL STUD L/H REAR AXLE.		17/09/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		17/09/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		17/09/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Unknown	SERVICE.		17/09/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Unknown	SERVICE.		17/09/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Tyres\TP11+12	Tyre Position 11 + 12		08/09/2022	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Tyres\TP3+4	Tyre Position 3 + 4		08/09/2022	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Tyres\TP1+2	supply and fit 6 tyres		08/09/2022	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Wodonga - Workshop	Susp\AIR LEAK	REPAIRED AIR LEAKS AT HCV.		03/09/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Susp\AIR FITTIN	RE-ROUTE AIR SUPPLY TO SCALES TRANSDUCER FROM RR AIRBAG TO HCV. HOOKED UP TO		02/09/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes\BRK RELINE	RELINED RM. REPLACED BEARINGS. Change position of where scales plumb into air bags.		02/09/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Susp\AIR FITTIN	Refer Ash.	REPLUMBED TRANSDUCER TO NEXT TO HCV.	02/09/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Susp\AIR BAG	Both rear air bags leaking	REPLACED.	02/09/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		02/09/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		02/09/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Body\FIFTH WHEE	Broken Shackle		01/09/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Susp\SUSPENSION	WELD ON ALIGNMENT PLATE BROKEN REAR AXLE.		27/08/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	DrivLine\DAMAGE	LEFT HAND REAR AXLE STRIPPED STUD.		27/08/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Hydraulics\HYD LEAKS	HYDRAULIC LEAK IN UMBILICAL ARM.		27/08/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes\ABS	Trailer ABS coming on empty or loaded		27/08/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		27/08/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		27/08/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		17/08/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		17/08/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Unknown	SERVICE.		17/08/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Elect\ELECT P&W	NO LIGHTS.	CLEANED AND REPAIRED PLUG AT REAR BAR. REPAIRED MULTIPLE RUBBED WIRES IN	17/08/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Tyres\TP11+12	supply and fit 2 tyres		03/08/2022	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		29/07/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		29/07/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService	Service		23/07/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Body\FIFTH WHEE	Slide pins not always locking in - LHS mainly		23/07/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Susp\AXLES	Check U bolt RHS front axle	Tightened RHF U bolts	23/07/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		23/07/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	Tightened RHF U bolts	23/07/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Susp\SUSPENSION	Check front axle - appears out of alignment	Inspected front axle movement, found both U bolts loose & worn & alignment plate v	20/07/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Tyres\TP5+6	supply and fit 2 tyres		17/07/2022	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Wodonga - Workshop	Unknown	A SERVICE.		16/07/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Susp\AIR LEAK	Air leak in suspension, bags always going flat	COULDN'T FAULT.	16/07/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Body\FIFTH WHEE	Slide pins not always locking in - LHS mainly		16/07/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Tyres\ALIGNMENT	Front axle scrubbing badly		16/07/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes\ABS	Trailer ABS coming on empty or loaded		16/07/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService	Service LHR shock missing		16/07/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Susp\SHOCK ABS	LHR saddle shock mount snapped off		16/07/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		16/07/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		16/07/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Tyres\TP5+6	supply and fit 2tyres		15/07/2022	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		07/07/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	REMOVED ALL WINCHES AND LUBRICATED. REFITTED.	07/07/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Tyres\TP9+10	supply and fit 2tyres		07/07/2022	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		01/07/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		01/07/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Chassis\AIR LEAK	Air leak at rear of trailer	Refer job # 384819	28/06/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes\AIR LEAK	fix air leaks		28/06/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	DrCabElect\SCALES	Chanel 2 scales not working very slow to bring the weight up	Refer Job # 384819	28/06/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Body\FIFTH WHEE	Air line pulled out of slide locks ram	Trimmed broken slide lock ram hose. Refitted & parked combination	25/06/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Chassis\HOUSEKEEP	surce air lines to slide locks		24/06/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Body\FIFTH WHEE	Airline for slide lock hanging down (cable tie up)		24/06/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
				Split trailers & move into awning for reline							
				Reline brakes & bearings. Adjust brakes. Hook back up to T383 & fold trailers.							
T382	Wodonga - Workshop	Brakes\BRK RELINE	RELINE LM.	Parktruck & clean bay.	24/06/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		24/06/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
				Cleaned 2nd bolster plugs							
T382	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist LHR shock missing	Cleared EBS faults	24/06/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Susp\SHOCK ABS	LHR saddle shock mount snapped off		24/06/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		21/06/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		21/06/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Chassis\FIFTH WHEE	Bolt missing from support to chassis to skidplate		21/06/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Chassis\HOUSEKEEP	Adjust load chain		21/06/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Elect\INDICATORS	RH indicator not working		21/06/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		16/06/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	Shorten b/booster hoses at 1st axle	16/06/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes\BOOSTER	Shorten b/booster hoses at 1st axle		16/06/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Chassis\FIFTH WHEE	REPAIR SLIDE- LOCK. 1 PIN MISSING.		07/06/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		07/06/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		07/06/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Unknown	SERVICE.		07/06/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Chassis\BOLSTER	REPLACED BOLSTER PEGS. (100MM LONGER)		02/06/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		01/06/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	HOOKED UP T383. REPLACED WIRING, PLUG AND SOCKET TO 2ND BOLSTER LIGHTS.	01/06/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Chassis\FIFTH WHEE	Fifth Wheel/Turntable		31/05/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Chassis\FIFTH WHEE	replace wear pads and turntable locks		30/05/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER

T382	Albury - Workshop	Tyres\TP5+6	SUPPLY AND FIT 2TYRES		24/05/2022	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Wodonga - Workshop	Brakes\BRK RELINE	RELINE LM.		20/05/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes\BOOSTER	FRONT AXLE LEFT SIDE BOOSTER.		20/05/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		20/05/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	REPLACED LM AIRBAG.	20/05/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		12/05/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		12/05/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		07/05/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	REPLACED 1ST WINCH STRAP.	07/05/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Unknown	SERVICE.		07/05/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		28/04/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	REPLACED LH OUTER STOP/ TAIL INSERT AND REPAIRED WIRING. RE-ALIGN RF AXLE B	28/04/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Susp\SUSPENSION	TRAILER CRAB WALKING.	INSPECTED ALL SUSPENSION COMPONENTS. COULDN'T FAULT.	28/04/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		21/04/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		21/04/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Tyres\CLEANSKIN	no pos given - fitted by driver		20/04/2022	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Wodonga - Workshop	Elect\ELECT P&W	2ND BOLSTER LIGHT NEEDS REPAIR.		13/04/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Susp\AIR BAG	AIR LEAK UNDER TRI- AIR BAGS GOING FLAT QUICKLY.	COULDN'T FAULT.	13/04/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		13/04/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		13/04/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Unknown	SERVICE. REPLACED HCV AND ADJUSTED SUSPENSION.		13/04/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Susp\HCV	CLEANED OUT SCALE PLUG/ SOCKET.		08/04/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Tyres\FITMENT	Fitment		08/04/2022	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		06/04/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		06/04/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Tyres\TP1+2	SUPPLY AND FIT 2TYRES		06/04/2022	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		29/03/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	REPAIRED 2ND BOLSTER LIGHT PLUG. CLEARED EBS CODES.	29/03/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Tyres\TP09	puncture repair		22/03/2022	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Wodonga - Workshop	Unknown	SERVICE		16/03/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		16/03/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		16/03/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		09/03/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	TIGHTENED LOOSE RM DUST COVER.	09/03/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Tyres\TP3+4	supply and fit 2tyres		03/03/2022	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Wodonga - Workshop	Susp\AIR BAG	REPLACED LF AIRBAG. 1 TOP NUT SEIZED.		02/03/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Body\AMB ARM	UMBILICAL CORD FRONT ARM BENT.		01/03/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		01/03/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		01/03/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection		15/02/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Elect\TRL LIGHTS	LH clearance light broken		15/02/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	DriCabRep	front air tank valve is leaking seen it last night when it was raining		15/02/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	DriCabRep\AIR LEAK	front air tank valve is leaking seen it last night when it was raining		15/02/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Elect\TRL LIGHTS	LH Mudguard clearance light broken.		15/02/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Elect\TRL LIGHTS	LH tail light (inner) not working		15/02/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes\BRAKE ADJ	need new LHR slack adjuster		15/02/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Susp\SUSPENSION	LHR spring eye bush may be on its way out. To monitor		15/02/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		15/02/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	REPLACED FRONT UMBILICAL ARM. REMOVED 2 LINKS AT FRONT OF LOAD CHAIN AN	15/02/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Tyres\TP11+12	Tyre Position 11 + 12		12/02/2022	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Tyres\TP1+2	supply and fit 4 tyres		12/02/2022	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Tyres\TP9+10	supply and fit 2tyres		01/02/2022	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Wodonga - Workshop	VehService\DS	SERVICE AS PER CHECK SHEET	TIGHTENED LOOSE RR TOP SHOCK MOUNT.	29/01/2022	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Tyres\TP03	supply and fit 1 tyre		20/01/2022	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Rosewood - Workshop	Hydraulics\HOSES	Hartrites - Supply Ryco field attachable fittings as requested Deliverd to Rosewood w/shop by Rohan		21/12/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
				* Raised & supported front & rear axles * Removed required wheel equipment from axles * Found the rear axle stub had excessive wear * Informed findings & was advised to remove for repair * Inspected front axle & found mounts for brake clips had excessive wear * Was advised to remove axle as well * Removed axles as required * Stripped down hubs & found 1 had excessve wear * Ordered in new hub * Stripped down axles & sent off for repair * Repacked wheel bearings & assembled hubs * Reinstalled axles upon return * Replaced s-cams & bushes * Reinstalled hubs & suspension components * Adjusted wheel bearings & brakes * Greased required components * Lowered down axles & tensioned wheels * Road tested then rechecked wheel bearing adjustments/all ok							
T382	Albury - Workshop	Brakes\BRK RELINE	CARRY OUT BRAKE RELINE ON R/H FRONT & R/H REAR AXLES - 29/11/21 - 10/12/21	* Repair complete	30/11/2021	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	VehService\DS	CARRIED OUT GREENFREIGHT TRAILER D-SERVICE WITH SERVICE SHEET PROVIDED - 29/11/		30/11/2021	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
				Repair axle as required Setup Pre-machine Rebuild and re-machine seal and journals to original diameters Repair axle as required Setup Pre-machine Rebuild and re-machine seal and bearing journals to original diameter Setup axle and remove worn brake support pins Manufacture 4 new pins							
T382	Albury - Workshop	Susp\AXLES	SBLT#7270387 WODONGA ENGINEERING CENTRE	Fit and weld to axle	30/11/2021	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER

T382	Albury - Workshop	Body	REPAIR CRACKS IN BODY AS REQUIRED - 30/11/21	* Found multiple cracks in body * Grinded out cracks as required * Heat treated cracks * Welded up cracks as required * Repair complete * Removed broken booster off trailer * Removed/replaced air lines * Measured & cut rod on new booster * Installed booster & secured with air lines * Tested booster operation/all ok	30/11/2021	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Brakes\BOOSTER	REPLACE BROKEN BOOSTER & REPLACE CRACKED LINES - 30/11/21	* Repair complete	30/11/2021	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Susp\SHOCK ABS	REPAIR LOOSE SHOCKERS - 29/11/21	* Tightened loose shockers as required	30/11/2021	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Elect	REPAIR BOLSTER LIGHTS - 29/11/21	* Found bolster lights not working during service * Tested 2nd boltser light wiring * Found power not getting top the light * Pulled apart the light & found wire holders corroded * Cleaned corroded holders as required * Tested light but found still not getting power * Traced wiring & found a broken wire * Found section of wire corroded * Replaced corroded section of wire * Tested light operation/all ok * Repair complete	30/11/2021	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Body	REPLACE R/H FRONT WHEEL SPEED SENSOR	* Removed/replaced wheel speed sensor as required	30/11/2021	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Rosewood - Workshop	Air Con\AIR CON	tested a/c vent temp was 6-9°c engine brakes work perfectly with no unusual noises -test drove vehicle after long running mis-informed complaint from 1 particular driver. Other driver has none of the issues -did a load ex Rosewood empty to Shelley folded up, Shelley to Tumbarumba at 64 B double -not once did trailer brakes "slam on" by themselves -vehicle does not pull to the left, it actually drives very well		19/11/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Workshop\MOVE ASSET	-one gear shift was a bit clunky, but I feel that was my fault		19/11/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job D Service		17/11/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	VehService\DS	adjust ride height, was 10mm low brakes slammed on 3 times this morning - empty - 1st one back 3 gears to get going come on once loaded		17/11/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Brakes\DAMAGE	dangerous		12/11/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		11/11/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Brakes\ABS	ABS code LA inactive. 7 counts could not replicate fault		11/11/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Susp\SUSPENSION	replace LHR spring eye bush		11/11/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	VehService\DS	D Service		11/11/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Albury - Workshop	Tyres\TP10	Tyre Position 10		11/11/2021	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Tyres\TP06	replaced pos 6 & 10 due to low pressure - 15 psi		11/11/2021	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Brakes\BRK ROTOR	CARRY OUT BRAKE RELINE - 8/11/21	* Raised & supported all axles * Removed L/H front, R/H middle & L/H rear wheel equipment * Removed required brakes * Removed/replaced s-cams & bushes * Cleaned & repacked wheel bearings * Reinstalled wheel equipment * Adjusted wheel bearings & brakes * Lowered down axles * Repair complete	09/11/2021	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Rosewood - Workshop	Brakes\EBS Kit	check ABS/EBS codes. LA + 2B signal and output. Will get back to workshop for repairs ASAF		04/11/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	VehService\DS	D Service		04/11/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		04/11/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Albury - Workshop	Tyres\TP9+10	supply and fit 2 tyres		04/11/2021	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		21/10/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Chassis\BOLSTER	turn 2 left pegs, 2 right pegs		21/10/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	VehService\DS	D Service		21/10/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		21/10/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Chassis\BOLSTER	turn 2 left pegs, 2 right pegs		21/10/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	VehService\DS	D Service		21/10/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	DriCabRep\AIR LEAK	front air tank valve is leaking seen it last night when it was raining		20/10/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Chassis\BOLSTER	left hand bolsters need turning around		20/10/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	DriCabRep\AIR LEAK	front air tank valve is leaking seen it last night when it was raining		20/10/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Chassis\BOLSTER	left hand bolsters need turning around		20/10/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	DrivLine\AIR LEAK	air leaks		14/10/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Elect\TRL LIGHTS	LH clearance light broken		14/10/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	VehService\DS	Service		14/10/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	DrivLine\AIR LEAK	air leaks		14/10/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Elect\TRL LIGHTS	LH clearance light broken		14/10/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	VehService\DS	Service		14/10/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		14/10/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Body\MUDGUARDS	replace LH rear guard side marker		14/10/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	VehService\DS	D Service		14/10/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Albury - Workshop	Tyres\TP1+2	supplya nd fit 2 tyres		13/10/2021	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Rosewood - Workshop	Elect\TRL LIGHTS	LH clearance light broken		08/10/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		07/10/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	VehService\DS	D Service		07/10/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Tumut - Workshop	Tyres\TP1+2	supply and fit 2 tyres		29/09/2021	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		17/09/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	VehService\DS	D Service		17/09/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		11/09/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	VehService\DS	D Service		11/09/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Wodonga - Workshop	Tyres\TP9+10	supplya nd fit 2tyres		10/09/2021	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Rosewood - Workshop	Body\LIGHTS	LH side light broken		08/09/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	VehService\DS	Service		08/09/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER

T382	Tumut - Workshop	Tyres\TP10	fit runout		08/09/2021	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Tyres\TP3+4	Supply and fit 2 tyres		01/09/2021	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		27/08/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Brakes\AIR LEAK	repair air leak at RHM brake booster and twist clamp to clear hoses		27/08/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	VehService\DS	D Service		27/08/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Tumut - Workshop	Tyres\TP11+12	Supply and fit 2 tyres		21/08/2021	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Rosewood - Workshop	VehService\DS	D Service		20/08/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		20/08/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Brakes\BRK RELINE	reline LHC brake repair hammer lock failure and subsequent damage		11/08/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Body\CHN/RLR/MN	refit load chain		11/08/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		30/07/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Body\WHL HUB	adjust all wheel bearings		30/07/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Elect\TRL LIGHTS	replace LH indicator light		30/07/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Elect\TRL LIGHTS	Repair LH inner tail light wiring and replace tail light		30/07/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	VehService\DS	D Service	* Inspected & found faulty tail light * Removed light & tested for power * Found light had no power * Found corrosion in plug * Cleaned corrosion out of plug then tested light/all ok	30/07/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Tumut - Workshop	Elect\TAIL LIGHT	REPAIR FAULTY TAIL LIGHT	* Repair complete	25/07/2021	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Brakes\SLACK ADJ	REPLACE L/H REAR SLACK ADJUSTER AS REQUIRED	* Removed/replaced L/H rear slack adjuster as required	25/07/2021	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	VehService\DS	CARRY OUT GREENFREIGHT LOG TRAILER D-SERVICE AS PER ATTACHED SERVICE SHEET - 24		25/07/2021	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		21/07/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	VehService\DS	D Service		21/07/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Tumut - Workshop	Tyres\TP1+2	Supply and fit 2 tyres		21/07/2021	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		26/06/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Elect\TRL LIGHTS	LH tail light (inner) not working		26/06/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Brakes\BRAKE ADJ	need new LHR slack adjuster		26/06/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	VehService\DS	D Service		26/06/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Chassis\WINCH/STRP	needs new strap		16/06/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Elect\TRL LIGHTS	number plate light needs replacing		16/06/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Elect\WORK LIGHT	no work lights	outsource work lights to TAE on shift change	16/06/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Chassis\WINCH/STRP	need new winch and strap on the first winch	change winch change strap	16/06/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Tumut - Workshop	Chassis\WINCH/STRP	lubricate winches x6		16/06/2021	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Chassis\WINCH/STRP	change winch straps		16/06/2021	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Elect\ELECT P&W	organise to head to Tumut Autos		16/06/2021	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Chassis\WINCH/STRP	change winch straps x2		16/06/2021	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Chassis\WINCH/STRP	change winches x2		16/06/2021	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		03/06/2021	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	VehService\DS	D Service		03/06/2021	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Tumut - Workshop	Tyres\TP3+4	Supply and fit 2 tyres		02/06/2021	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Susp\HCV	adjust ride height valves	adjust ride height valve	29/05/2021	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		27/05/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	VehService\DS	D Service		27/05/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Tumut - Workshop	Tyres\TP01	Fit Runout no left blinker find fault broken wires fitted new blinker and soldered wires		26/05/2021	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Elect\INDICATORS	heat shrink to insulate		25/05/2021	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Tyres\TP9+10	Supply and fit 2 tyres		19/05/2021	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Myrtleford - Workshop	Brakes	Record Check Results As Attached To this Job		13/05/2021	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	VehService\DS	D Service		13/05/2021	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Rosewood - Workshop	Brakes\BRK O/HAUL	replaced SR-2 valve, tested all good		05/05/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Brakes\BRK O/HAUL	trailer brakes slow to release and sometimes went lock on with hand piee or when air supp		05/05/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		04/05/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Susp\SUSPENSION	LHR spring eye bush may be on its way out. To monitor		04/05/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	VehService\DS	D Service		04/05/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Tumut - Workshop	Tyres\TP5+6	Supply and fit 2 tyres Checked for codes in EBS found "slow to release" code , not current but only 200 km ago. Cleared!		28/04/2021	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Rosewood - Workshop	Brakes\EBS Kit	Seems ok. Contracted driver mid shift and he reported no further problems Called to fuel depot, brakes not releasing Temp fix to get to workshop (across the road)		27/04/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Brakes\AIR LEAK	Found leak at booster hose, repaired		27/04/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		21/04/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	VehService\DS	D Service		21/04/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Body\CHN/RLR/MN	remove old 3/8" chain and associated parts and convert to 1/2" chain		20/04/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Body\FIFTH WHEE	split up and put in workshop repair bay		20/04/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Tumut - Workshop	Body\CHN/RLR/MN	Supply chains, connectors, chain guide		09/04/2021	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Body\STRAPS	Supply Hammerlock Connector remove broken chain from turntable plate and unload trailer		09/04/2021	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Rosewood - Workshop	Chassis\STRAPS	ubhook trailers from 1011		08/04/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Tumut - Workshop	Tyres\TP09	Tyre Position 9		07/04/2021	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Tyres\TP11+12	Supply and fit 2 tyres and 1 runout		07/04/2021	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		07/04/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	VehService\DS	D Service load chain de-railed		07/04/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Chassis\STRAPS	fit up and cut 2 links from rear and 4 from front of chain and tension		07/04/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Tumut - Workshop	Chassis\HYDRAULICS	hyd oil leak in umbilical. hyd oil leak in ambilical		02/04/2021	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	VehService\DS	D Service		02/04/2021	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Tyres\TP11	Fit Runout		31/03/2021	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Chassis\WINCH/STRP	winches tight		26/03/2021	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Body\ELECT P&W	stop/tail light not working broken wires in loom right rear bushbar locate solder new wires cable tie		26/03/2021	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Body\ELECT P&W	fit light check ok		26/03/2021	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Chassis\WINCH/STRP	lubricate winches		26/03/2021	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER

			CARRY OUT GREENFREIGHT LOG TRAILER D-SERVICE AS PER ATTACHED SERVICE SHEET. 24/03/2021 . DURING SERVICE FOUND: * LHM airbag fitting leaking .								
T382	Tumut - Workshop	VehService\DS	Grease		25/03/2021	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
			INDICATOR LH REAR INDICATOR NOT WORKING. 22/03/2021 Removed light and found wire had broken at plug Cut wires and soldiered new plug into wires as required. Reconnected lights and tested operation. Found parker was flickering – found earth wire had broken in plug and wouldn't make continuous contact. Cut plug off and soldiered new plug on. Tested – now working								
T382	Tumut - Workshop	Elect\INDICATORS	All ok.		23/03/2021	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
				CARRY OUT BRAKE RELINE. 17/03/2021 Put trailer over pit and inspected brakes Found LH middle requires reline. Removed hub assembly Removed and washed bearings Cleaned hub and removed s-cams Replaced s-cam bushes and seals as required Re-utilised s-cams Repacked bearings and hub Refit hub and adjusted bearings as required Adjusted brakes						
T382	Albury - Workshop	Brakes\BRK RELINE	Supply brake Shoe kit, Hub seal, and consumables for reline on LHM	All ok.	19/03/2021	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Tumut - Workshop	Chassis\HOUSEKEEP	grease		12/03/2021	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Chassis\H/Fittings	tighten bolts in slide lock paddles		12/03/2021	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job		10/03/2021	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	VehService\DS	D Service		10/03/2021	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		10/03/2021	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	VehService\DS	D Service		10/03/2021	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job		10/03/2021	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	VehService\DS	D Service		10/03/2021	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
				LH blinker not working remove light found connectors unplugged test refit to light reinstall							
T382	Tumut - Workshop	Elect\INDICATORS	LHS indicator not working	check operation ok	06/03/2021	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		04/03/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	VehService\DS	Carried out D Service		04/03/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
				air leak in trailer find fault replace joiners check ok							
T382	Rosewood - Workshop	Body\AIR LEAK	air leak supply line	cable tie hoses	04/03/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Tumut - Workshop	Brakes\EBS Kit	repair ebs wiring and clear all codes R&R122951 no blinker remove light find break in wires solder new light plug in place		03/03/2021	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Elect\TRL LIGHTS	refit and check ok		26/02/2021	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		16/02/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	VehService\DS	D Service		16/02/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Tumut - Workshop	Tyres\TP11+12	replace 2 tyres		05/02/2021	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Tumut - Workshop	Tyres\TP7+8	replace 2 tyres		05/02/2021	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Tumut - Workshop	Tyres\TP3+4	replace 2 tyres		05/02/2021	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Tumut - Workshop	Tyres\TP1+2	replace 2 tyres		05/02/2021	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		02/02/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	VehService\DS	trailers not serviced properly by TCTC on fri, not greased properly so I serviced from scratch		02/02/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		02/02/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	VehService\DS	D Service		02/02/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
			Travel to Rosewood. Check trailer ABS light on. Found no power at ABS plug (Atrailer to B trailer) - Diagnosed 2 x broken wires in umbilical cord, used 2 x sparewires in harness to supply missing power and earth and ordered repllacement harness through Lavington workshop. Noticed booster on front axle hitting ABS distribution block when air bags deflated.								
T382	Albury - Workshop	Elect\ELECT P&W	Relocated block as needed		30/01/2021	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Tumut - Workshop	Tyres\TP9+10	replace 2 tyres		20/01/2021	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		12/01/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	VehService\DS	D Service		12/01/2021	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Chassis\WINCH/STRP	lubricate winch shafts and free up		18/12/2020	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job		15/12/2020	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	VehService\DS	D Service		15/12/2020	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Rosewood - Workshop	Elect\WORK LIGHT	found work lights inoperative, TCTC attending Rosewood repaired. All good (was wired wro		08/12/2020	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Chassis\DAMAGE	check over from return from TCTC (new skid plate)		08/12/2020	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER

			Replace Skid Plate removed dirt and bark from around skit plate area Removed cover from above skid plate and removed more dirt and bark Undo electrical lead and pulled through-undo suzi leads and Hydraulic lines. Undo Skid Plate outer bolts as required. Attempted to undo inner skid plate bolts-all seized. Cleaned out more bark from around bolts. Cut out all inner bolts with oxy-removed skid plate. Cleaned off rust from chassis around skid plate area and prep for painting. Bolted up skid plate and fit up electrical and hydraulic lines as required. Fit up suzi leads as required. Driilled new holes in so skid plate to mount EBS plug. Secured everything into position. Refit cover onto skid plate as required and tested light operation check over for hydraulic leaks-								
T382	Tumut - Workshop	Body	all ok		05/12/2020	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
			Check Trailer EBS light always on but no fault codes. Check wiring harness, locate damaged harness at junction block ablove front axle. Replace junction block, repair harness and secure. Remove old style elpihinstone wiring connector (small 7 pin round) modify bulk head and								
T382	Tumut - Workshop	Elect\TRL LIGHTS	fit updated Deustch style plug		03/12/2020	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Rosewood - Workshop	VehService\DS	D Service Due 500km		20/11/2020	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Myrtleford - Workshop	Susp\SPRNG PACK	replaced spring and bush RHM		06/11/2020	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Brakes\BRK RELINE	carried out brake reline rear axle both sides and middle axle RHS		06/11/2020	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Albury - Workshop	Workshop\MOVE ASSET	unhook from #1011		30/10/2020	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Workshop\MOVE ASSET	unload trailers		30/10/2020	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Body\CHN/RLR/MN	travel to TCTC and refit load chain onto gypsy and tension		30/10/2020	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Tumut - Workshop	Brakes\AIR LEAK	brake booster hose	blown airline	29/10/2020	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		21/10/2020	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	VehService\DS	D Service		21/10/2020	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Tumut - Workshop	Elect\ELECT P&W	park light		13/10/2020	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Elect\ELECT P&W	bar rear		13/10/2020	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Elect\ELECT P&W	circuit keeps popping short in light		13/10/2020	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Elect\ELECT P&W	no indicators		13/10/2020	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Tyres\BREAKDOWN	flat tyres	change 2 flat tyres	01/10/2020	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Body\FIFTH WHEE	slide locks jammed	slide locks jammed loosen grease check operation	01/10/2020	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Hydraulics\OIL LEAK	umbilical arm hydraulic hose leaking	umbilical arm hydraulic hose blown	01/10/2020	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Tyres\DS	D Service		17/09/2020	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Elect\TRL LIGHTS	no tail lights		17/09/2020	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		16/09/2020	Completed	Colac	GTK	37689S	TWIN CITY TRUCK CENTRE - OLD	TRAILER
				D Service repaired broken wires in light bar and replaced RM indicator							
			Service As Per Attached Checklist	carried out D Service							
T382	Myrtleford - Workshop	VehService\DS	Order number TU9687 removed load chain and adjuster bolt. Cut links (4) from chain and replaced bolt. Tensioned and tested ok	fixed rear lights on trailer	16/09/2020	Completed	Colac	GTK	37689S	TWIN CITY TRUCK CENTRE - OLD	TRAILER
T382	Rosewood - Workshop	Body\CHN/RLR/MN	travel back home		03/09/2020	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Elect\ELECT P&W	replaced valve		03/09/2020	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Elect\BREAKDOWN	call out to Tumut, sliders locked "out" folded up full system diagnosis found intermittently faulty "new" slider actuator valve		03/09/2020	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
				replace siezed load chain adjuster bolt remove 4 links from rear side of slider (chain) refit chain and tension, test operation test slider operation. All good							
T382	Rosewood - Workshop	Body\CHN/RLR/MN	load chain needs adjusting	travel back home called out to Tumut, slider locks wont work even manually	02/09/2020	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Body\ELECT P&W	slide locks not locking in	diagnosed and replaced faulty (new) lock actuator	02/09/2020	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Elect\TRL LIGHTS	a brake light not working		01/09/2020	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Body\AIR LEAK	change valve		01/09/2020	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Body\CHN/RLR/MN	loading chain loose		01/09/2020	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Body\CHN/RLR/MN	attempt to adjust chain		01/09/2020	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Elect\ELECT P&W	replace slider valve		01/09/2020	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Elect\TRL LIGHTS	TCTC repair lights		01/09/2020	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	VehService\DS	TCTC - D Service at Tumut		01/09/2020	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job LH middle axle brake reline, s-cam and bushes		01/09/2020	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Brakes\BRK RELINE	inspecred bearing ok		01/09/2020	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Body\CHN/RLR/MN	air valve adjusted gypsy chain		01/09/2020	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Elect\TRL LIGHTS	number plate light, brake light indicator		01/09/2020	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	VehService\DS	D Service		01/09/2020	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Myrtleford - Workshop	Elect\TRL LIGHTS	no number plate light		21/08/2020	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Tumut - Workshop	Engine\ELECT P&W	PO FOR SOLENOID PARTS		14/08/2020	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job		12/08/2020	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	VehService\DS	D Service		12/08/2020	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job repair wiring at LH work light repair wiring at LH tail light		31/07/2020	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Elect\TRL LIGHTS	Phil Nolte helped		31/07/2020	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	VehService\DS	D Service		31/07/2020	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job Service As Per Attached Checklist	greased B adjusted brakes as required	16/07/2020	Completed	Colac	GTK	37689S	TWIN CITY TRUCK CENTRE - 4 - OLD	TRAILER
T382	Tumut - Workshop	VehService\DS	Order Number # TU 9120	carried out service as required	16/07/2020	Completed	Colac	GTK	37689S	TWIN CITY TRUCK CENTRE - 4 - OLD	TRAILER
T382	Rosewood - Workshop	Body\HOUSEKEEP	attend Tumut depot to check over for Service and repairs needed		08/07/2020	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job Service As Per Attached Checklist		24/06/2020	Completed	Colac	GTK	37689S	TWIN CITY TRUCK CENTRE - 4 - OLD	TRAILER
T382	Tumut - Workshop	VehService\DS	Order Number # TU8915		24/06/2020	Completed	Colac	GTK	37689S	TWIN CITY TRUCK CENTRE - 4 - OLD	TRAILER
				tighten load chain							
T382	Tumut - Workshop	Body\CHN/RLR/MN	load chain needs tightening	R/R 120651	05/06/2020	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Elect\WORK LIGHT	LHS work light out		05/06/2020	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Elect\TRL LIGHTS	no number plate light		05/06/2020	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	VehService\DS	D Service TU8899		05/06/2020	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job		05/06/2020	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Body\CHN/RLR/MN	adj load chain		05/06/2020	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	VehService\DS	D Service		05/06/2020	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER

T382	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job		23/05/2020	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	VehService\DS	D Service		23/05/2020	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Elect\TRL LIGHTS	L/H rear blinker out remove and replace		23/05/2020	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
			L/H blinker shorting								
			find start tape up wires								
			L/H tail light plugged inoperable								
T382	Tumut - Workshop	Elect\TRL LIGHTS	replace plug		16/05/2020	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Elect\TRL LIGHTS	fit new rear tail light/brake light x2		13/05/2020	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
			LHS indicator not working								
T382	Tumut - Workshop	Elect\TRL LIGHTS	RHS mudguard clearance light a drift		13/05/2020	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		09/05/2020	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	VehService\DS	Service		09/05/2020	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Tumut - Workshop	Chassis\STRAPS	order new Exte winches for trailer		28/04/2020	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Myrtleford - Workshop	Susp\SUSPENSION	requires full suspension re-torque	torque up suspension	21/04/2020	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Rosewood - Workshop	VehService\DS	D Service		18/04/2020	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		18/04/2020	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		28/03/2020	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	VehService\DS	Service As Per Attached Checklist		28/03/2020	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Tumut - Workshop	Elect\TRL LIGHTS	LHS Tail Light Out		15/03/2020	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Body\CHN/RLR/MN	LHS Load Roller Broken		15/03/2020	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Elect\WORK LIGHT	No Work Lights		15/03/2020	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job		15/03/2020	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	VehService\DS	D Service		15/03/2020	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Elect\WORK LIGHT	work lights not working off switch		06/03/2020	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Brakes\BRK O/HAUL	rear axle running hot/passengers side more than drivers side	check bearing temps on trailer all 50°-55°	06/03/2020	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Chassis\SPAREWHEEL	Make up holding bolts for spare carrier		05/03/2020	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Chassis\AIR TANKS	repaired air tank mounts		28/02/2020	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Chassis\TRL LEGS	replaced bolts in leg		28/02/2020	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Brakes\EBS FAULTS	brake drag issues. Downloaded ecm and sent to bpw engineer for review. Followed advised		28/02/2020	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Workshop\MOVE ASSET	test drove, found hub still overheating		28/02/2020	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Susp\WGHT GAUGE	scales not working		28/02/2020	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Brakes\ABS	codes for sensors on axle tied-up		28/02/2020	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
			un-tied and checked booster hoses								
T382	Albury - Workshop	Brakes\BOOSTER	checked ABS codes	measured booster performance and replaced	28/02/2020	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Elect\WORK LIGHT	load lights not working		28/02/2020	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
				LHR hub getting hot. Checked components							
				fitted cam bearing correctly							
				adjusted bearing							
				replaced backing plates							
T382	Albury - Workshop	Brakes\BRAKE ADJ	L/H rear brake over heated	tested brakes. Replaced relay valve. Replaced fittings. Tested	28/02/2020	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
			check for EBS codes								
T382	Albury - Workshop	Brakes\ABS	replaced ABS fuse		28/02/2020	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Brakes\BRK O/HAUL	adjust bearings re-set brake		28/02/2020	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
				parts ordered TCTC							
				check hot brake rear axle LHS remove assembly replace drum linings wash							
T382	Albury - Workshop	Brakes\DAMAGE	over heated brake LH rear strip and repair	brearing re-pack and fit road test re-check	28/02/2020	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Brakes\EBS FAULTS	place brake hoses to correct ports on unit		22/02/2020	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Brakes\EBS FAULTS	fit ABS cables to correct locations on unit		22/02/2020	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Brakes\EBS FAULTS	reset ABS sensors		22/02/2020	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Brakes\EBS FAULTS	config EBS control unit		22/02/2020	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	DrivLine\WHEEL BRGS	adjusted all wheel bearings		22/02/2020	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Chassis\WINCH/STRP	Set up air winches fit protection valve order valve		21/02/2020	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		14/02/2020	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Susp\SUSPENSION	requires full suspension re-torque		14/02/2020	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Chassis\WINCH/STRP	remove all old manual winch's		14/02/2020	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Body\CHN/RLR/MN	tension load chain		14/02/2020	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	VehService\DS	carry out trailer service and inspection after EBS fit up		14/02/2020	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Myrtleford - Workshop	Brakes\EBS Kit	test and certify ebs system		31/01/2020	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Chassis\SPAREWHEEL	repair RH spare wheel carrier		16/10/2019	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Chassis\BOLSTER	replace bolster wear pads and pivots		16/10/2019	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Body\MOUNTS	repair T/light bar cracks and mounting bolts		16/10/2019	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Body\MUDGUARDS	repair m/guards and replace mount bolts		16/10/2019	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Susp\SUSPENSION	replace RHF spring wrap		16/10/2019	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Susp\SHOCK ABS	replace LHR shocker		16/10/2019	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Susp\SHOCK ABS	replace RHR top shocker bolt		16/10/2019	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Chassis\CHAS CRACK	repair all trailer crack		16/10/2019	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Elect\TRL LIGHTS	repair all lights and damaged wiring		16/10/2019	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Body\AIR FITTIN	replace all damaged air lines		16/10/2019	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Body\CHN/RLR/MN	fit new rear trailer rollers		16/10/2019	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Body\CHN/RLR/MN	fit new load chain and rollers and guides		16/10/2019	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Body\MOUNTS	replace umbilical arm bearings and repair arm		16/10/2019	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Body\FIFTH WHEE	replace T/table slides and angles		16/10/2019	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Chassis\CROSS MBR	repair axle x members and cracks and loose bolts		16/10/2019	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Chassis\CROSS MBR	repair x member behind skid plate		16/10/2019	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Brakes\BRK O/HAUL	remove 2x axles and repair s/cam bushes		16/10/2019	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Brakes\BRK RELINE	reline all 3 axles and fit 6x drums		16/10/2019	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Brakes\EBS Kit	fit EBS kit		16/10/2019	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Albury - Workshop	Body\RWC COMP	full check over, write out full list of repairs		03/10/2019	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Chassis\CROSS MBR	REMOVE BROKEN X - MEMBER		01/10/2019	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Chassis\MUDGUARDS	LHS mudflap		01/10/2019	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Elect\WORK LIGHT	no work lights		01/10/2019	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Elect\ELECT P&W	short in clearance lights when unloading flashing off but stay on once unloaded		01/10/2019	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Elect\ELECT P&W	short in clearane lights when unloading flashing off but stay on once unloaded		01/10/2019	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	DrivLine\WHL HUB	align front axle on A Trailer		01/10/2019	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Prod Hose\WORK LIGHT	spot lights not working on rear of trailer		01/10/2019	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Susp\SPRNG HANG	Broken spring hanger		01/10/2019	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Tumut - Workshop	Chassis\TRL ROLLBK	roller broken		26/09/2019	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Albury - Workshop	Chassis\MUDGUARDS	LHS mudflap		15/08/2019	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Elect\TRL LIGHTS	clearance light RHS 2nd bolster		15/08/2019	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		10/08/2019	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER

T382	Rosewood - Workshop	Brakes\AIR LEAK	repair multiple booster hose leaks		10/08/2019	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	VehService\DS	Service		10/08/2019	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Albury - Workshop	VehService\DS	D Service Due in 1,200km		10/08/2019	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Tumut - Workshop	Chassis\WINCH/STRP	2nd winch needs tightening to chassis		07/08/2019	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Rosewood - Workshop	VehService\DS	D Service		02/08/2019	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Tumut - Workshop	Chassis\TRL ROLLBK	slider locks not working		26/07/2019	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Rosewood - Workshop	DrCabElect\SCALES	scales not working	scales not working pull out connector spray male and female ends with contact clean	20/07/2019	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Wodonga - Workshop	Brakes\BRAKE ADJ	Adjusted brakes		19/07/2019	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job		03/07/2019	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	VehService\DS	D Service		03/07/2019	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	VehService\DS	Service		28/06/2019	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Chassis\MUDGUARDS	LHS mudflap		28/06/2019	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		15/06/2019	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Albury - Workshop	VehService\DS	D SERVICE		15/06/2019	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	VehService\DS	D Service		14/06/2019	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Rosewood - Workshop	Body\CHN/RLR/MN	adjust chain as best I could on my own and without cutting links out. Will return Wednesda		11/06/2019	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Albury - Workshop	Chassis\CHAS CRACK	2nd last bolster still wont lift by itself		22/05/2019	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	VehService\DS	D SERVICE		21/05/2019	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Tumut - Workshop	VehService\DS	D Service Due		21/05/2019	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	DrivLine\AIR LEAK	middle axle air valve leaking		16/05/2019	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	VehService\DS	D Service Due		10/05/2019	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		10/05/2019	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Albury - Workshop	Susp\SHOCK ABS	tightened RHR shock		10/05/2019	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Albury - Workshop	Chassis\CROSS MBR	welded cross member infront of rear cross brace		10/05/2019	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Albury - Workshop	Elect\TRL LIGHTS	repair LHR tail light		10/05/2019	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Albury - Workshop	VehService\DS	D SERVICE		10/05/2019	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Albury - Workshop	Chassis\CHAS CRACK	weld crack on chassis at umbilical arm		18/04/2019	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		18/04/2019	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Albury - Workshop	VehService\DS	D SERVICE		18/04/2019	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	VehService\DS	D Service		06/04/2019	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Albury - Workshop	Susp\SHOCK ABS	tightened RHR shock		06/04/2019	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		06/04/2019	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Albury - Workshop	VehService\DS	D SERVICE		06/04/2019	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
			REPAIR SHORT CIRCUIT IN INDICATORS.								
T382	Albury - Workshop	Elect\INDICATORS	AS PER INVOICE		14/03/2019	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job		09/03/2019	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	VehService\DS	D SERVICE		09/03/2019	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
				call out							
				chain off gypsy wheel							
				lot of adjustment refit chain readjust							
T382	Rosewood - Workshop	Body\CHN/RLR/MN	chain off gypsy wheel	check to make sure it loads	05/03/2019	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job		28/02/2019	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	VehService\DS	D SERVICE		28/02/2019	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Body\HOSES	oil hose blown where tape is on billary cord		17/02/2019	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Albury - Workshop	Hydraulics\HOSES	REPAIR BLOWN HOSE		17/02/2019	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Rosewood - Workshop	Body\CHN/RLR/MN	load chain came off gypsy wheel	refit chain adjust	08/02/2019	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Body\CHN/RLR/MN	load chain off gypsy wheel		03/02/2019	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Body\CHN/RLR/MN	load chain off trailer release and refit and adjust		03/02/2019	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Albury - Workshop	Susp\AXLES	load chain off gypsy wheel		02/02/2019	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	VehService\DS	D Service		02/02/2019	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Tumut - Workshop	Body\CHN/RLR/MN	REFIT CHAIN TO GYPSY.		02/02/2019	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Rosewood - Workshop	Insp\ANN INSP	D Service	need to check correct paper work?	31/01/2019	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Body\CHN/RLR/MN	check trailers broken chain go to Rosewood source chain return to Tumut help John fit new		31/01/2019	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		31/01/2019	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Albury - Workshop	VehService\DS	SERVICE		31/01/2019	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Albury - Workshop	Body\CHN/RLR/MN	REPLACE BROKEN LOAD CHAIN		31/01/2019	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Rosewood - Workshop	Body\CHN/RLR/MN	chain broken on A Trailer		30/01/2019	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Tumut - Workshop	Body\CHN/RLR/MN	chain broken on A Trailer		30/01/2019	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		17/01/2019	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Albury - Workshop	VehService\DS	D SERVICE		17/01/2019	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	VehService\DS	D Sevice Due		15/01/2019	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Elect\INDICATORS	L/H turn signal not working		15/01/2019	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Elect\TAIL LIGHT	LH rear tail light not work		20/12/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		19/12/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Albury - Workshop	VehService\DS	D SERVICE		19/12/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Albury - Workshop	Susp\SUSPENSION	press s.e.b x1		11/12/2018	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Tumut - Workshop	Tyres\CLEANSKIN	Job Added From Invoice		07/12/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Tyres\FITMENT	Job Added From Invoice		07/12/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Tyres\RUN OUT	Job Added From Invoice		30/11/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Tyres\CLEANSKIN	Job Added From Invoice		30/11/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Tyres\FITMENT	Job Added From Invoice		30/11/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Albury - Workshop	Body	Job Added From Invoice		29/11/2018	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Susp\WHEEL ALGN	WHEEL ALIGNMENT	REPLACE WRAP ETC	29/11/2018	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Brakes\BRK RELINE	RELINE LHF		28/11/2018	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Body\CHN/RLR/MN	made load chain v-stay mounts		21/11/2018	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Elect\ELECT P&W	repaired lights wiring		21/11/2018	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Body\MOUNTS	repaired broken chassis skin		21/11/2018	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Chassis\FIFTH WHEE	fit turnion's and turntable		21/11/2018	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Chassis\FIFTH WHEE	Fifth Wheel/Turntable	remove table top, remove trunions	20/11/2018	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
			reline LHF								
			crack tested axle and inspected hub								
			replaced missing front for brake drum								
			tightened all brake drum bolts								
			replaced missing b/booster return springs								
T382	Albury - Workshop	DrivLine\WHEEL BRGS	replaced b/booster hosing		15/11/2018	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER

			fit tail light bar								
			fit up load chain and adjust								
			wheel alignment performed at Hume Truck technics								
			removed and fitted all new brake hoses								
			repaired cracked chassis skin and cross member mounts								
			tested suspension and checked for ail leaks								
			replaced LHF airbag								
			replaced LHF seb, wrap, u-bolts and alignment plate								
			repaired lights wiring								
			replaced no. plate light								
			replaced umbilical arm bearings								
T382	Albury - Workshop	Engine\FUEL TANK	replaced missing front crossmember bolts		15/11/2018	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Body\MUDGUARDS	fit RH guard		15/11/2018	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
			CHAIN ANCHOR PULLED OUT OF CHASSIS RAIL.								
			CRACKED TAIL LIGHT BAR								
T382	Albury - Workshop	Chassis\DAMAGE	NUMEROUS OTHER CRACKS.	dismantled and repaired broken load chain anchor points. Repaired mud guards and (	15/11/2018	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		24/10/2018	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Body\CHN/RLR/MN	shorten chain		24/10/2018	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	VehService\DS	D Service		24/10/2018	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Brakes\BRK RELINE	Reline		24/10/2018	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Albury - Workshop	Elect	Job Added From Invoice		18/10/2018	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Brakes	Job Added From Invoice		17/10/2018	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Rosewood - Workshop	Brakes\BRK RELINE	reline		12/10/2018	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Body\CHN/RLR/MN	put on load chain back on the gypsy gear		10/10/2018	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		09/10/2018	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	VehService\DS	D Service		09/10/2018	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Tumut - Workshop	Tyres\RETREAD	Job Added From Invoice		05/10/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Tyres\FITMENT	Job Added From Invoice		05/10/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Rosewood - Workshop	Susp\SUSPENSION	tighten loose u-bolts		27/09/2018	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Brakes\BOOSTER	replace maxi line for booster		27/09/2018	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Body\AIR LEAK	air leak		27/09/2018	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Elect\WORK LIGHT	spot lights not working on rear of trailer		23/09/2018	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Elect\WORK LIGHT	WORK LIGHTS NOT WORKING	work lights u/s replaced	23/09/2018	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Albury - Workshop	Elect\TAIL LIGHT	REPLACE #PLATE LIGHT		23/09/2018	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		22/09/2018	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Elect\WORK LIGHT	replaced damaged work lights 22/09		22/09/2018	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	VehService\DS	D Service		22/09/2018	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Albury - Workshop	Cooling	Job Added From Invoice		22/09/2018	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Tumut - Workshop	Tyres\RETREAD	Job Added From Invoice		21/09/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Tyres\FITMENT	Job Added From Invoice		21/09/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Tyres	Job Added From Invoice		21/09/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Albury - Workshop	Workshop	Job Added From Invoice		19/09/2018	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Workshop	Job Added From Invoice		15/09/2018	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
			repaired wiring at umbilical arm								
T382	Rosewood - Workshop	Elect\ELECT P&W	repaired wiring in L tail light bar		14/09/2018	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
			refit chain								
T382	Rosewood - Workshop	Body\CHN/RLR/MN	shorten chain by removing 6 links		14/09/2018	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Body\AIR LEAK	air leak rear hose between valve and brake booster		12/09/2018	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Susp\SUSPENSION	replace L/H/F z spring		11/09/2018	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Elect\BRK LIGHT	replaced loom to brake lights		11/09/2018	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Elect\INDICATORS	left indicators not working	repair wiring at L indicator	11/09/2018	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
			2nd bolster cracked badly require replacing								
			remove 2nd bolster off T323								
T382	Rosewood - Workshop	Chassis\BOLSTER	repaired 2nd elect plug wiring	prepare bolster to fit on to T323	07/09/2018	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Tumut - Workshop	Tyres\RETREAD	Job Added From Invoice		06/09/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Tyres	Job Added From Invoice		06/09/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Tyres\FITMENT	Job Added From Invoice		06/09/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		06/09/2018	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Susp\HCV	repair air on top HCV		06/09/2018	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Elect\INDICATORS	repair left hand indicators		06/09/2018	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	VehService\DS	D Service		06/09/2018	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Tumut - Workshop	Tyres\ROTATION	Job Added From Invoice		01/09/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Tyres\FITMENT	Job Added From Invoice		01/09/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	VehService\DS	Service Due 110,000		30/08/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	VehService\DS	Service Due 110,000		30/08/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
				Call out Cararoo Rd. Carabost							
				air line pulled out of relay valve							
T382	Rosewood - Workshop	Susp\AIR FITTIN	air leak	replaced fitting test ok	29/08/2018	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	VehService\DS	Service		23/08/2018	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		23/08/2018	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	VehService\DS	D Service		23/08/2018	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Albury - Workshop	Chassis\WINCH/STRP	REPLACE 2X STRAPS		22/08/2018	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Tumut - Workshop	Elect\TAIL LIGHT	reverse/work lights not working		16/08/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Body\AIR LEAK	air leak on tri		16/08/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
			remove slide lock key and fit spare								
T382	Rosewood - Workshop	Body\DOOR LOCK	remove broken bolt - refit original key		15/08/2018	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
				piece of wood jammed in gypsy and spat chain off							
				remove wood. loosen chain, refit							
T382	Rosewood - Workshop	Body\CHN/RLR/MN	chain came of gypsy	remove twists and tension	15/08/2018	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
			call out:								
			2nd winch mount broken. Removed old mount								
			drill chasis mount and fit new extension								
T382	Rosewood - Workshop	Chassis\WINCH/STRP	refit winch		15/08/2018	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		14/08/2018	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
			repair broken tie dog chain holder bolt through chassis								
T382	Rosewood - Workshop	Body\CHN/RLR/MN	replace bolt		14/08/2018	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	VehService\DS	Service		14/08/2018	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
				CHANGED WIRING IN PLUG ON TRUCK							
				no work lights had power at the plugs and at the rear off the trailer found that black							
T382	Rosewood - Workshop	Elect\WORK LIGHT	WORK LIGHTS N/W	and blue were change swap back tested ok	07/08/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER

			RH TAIL LIGHT BROKEN	REPLACED LIGHT ASSY.							
T382	Rosewood - Workshop	Elect\TAIL LIGHT	LH TAIL LIGHT N/W	Replace 2x park light assembly's	07/08/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Rosewood - Workshop	Body\AIR LEAK	replace winch handle nob and repair air leak		04/08/2018	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Body\CHN/RLR/MN	remove links - reift load chain		01/08/2018	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Albury - Workshop	Body\CHN/RLR/MN	REPLACE BROKEN LOAD CHAIN	pick up load chain from border lifting	31/07/2018	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
			broken load chain. Remove chain tie up gypsy so we could lower bolsters return truck to Rosewood								
T382	Tumut - Workshop	Body\CHN/RLR/MN	trailers were at Tumut		31/07/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Rosewood - Workshop	Workshop\MOVE ASSET	hook up to T383		31/07/2018	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
			replace worn gypsy gear and chain roller's re run new bad chain and welded new lugs on load chain								
T382	Rosewood - Workshop	Body\CHN/RLR/MN	tested load and unload tested ok		31/07/2018	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Workshop\MOVE ASSET	drop B trailer & unhook		31/07/2018	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Tumut - Workshop	VehService\DS	Service		25/07/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Elect\TAIL LIGHT	LH tail brake blinker		25/07/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Elect\WORK LIGHT	no work lights		25/07/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job		25/07/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	VehService\DS	D SERVICE		25/07/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Albury - Workshop	VehService	Job Added From Invoice		11/07/2018	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Tumut - Workshop	VehService\DS	Service		07/07/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	VehService\DS	Service		07/07/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job		07/07/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	VehService\DS	Service		07/07/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Elect\TAIL LIGHT	RHS tail stop lamp		29/06/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Body\MUDGUARDS	RHS mudflap		29/06/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Body\AIR LEAK	air leak between brake booster		29/06/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Brakes	Record Check Results A Attached To This Job		23/06/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	VehService\DS	Service		23/06/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Elect\ELECT P&W	short in clearane lights when unloading flashing off but stay on once unloaded		22/06/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	VehService\DS	D Service		22/06/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Elect\ELECT P&W	short in clearance lights when unloading flashing off but stay on once unloaded		22/06/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	VehService\DS	D Service		22/06/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Body\AIR LEAK	air leak		05/06/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Susp\SUSPENSION	replace u-bolts		05/06/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	VehService\DS	D Service		05/06/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		05/06/2018	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Susp\SUSPENSION	replace 2 spring wrap and 2 sets off ubolts and 2 alignment plates and bottom saddle		05/06/2018	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	VehService\DS	Service		05/06/2018	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job		26/05/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	VehService\DS	Service		26/05/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
			travel to Depot. Remove chain. Set bolsters								
T382	Rosewood - Workshop	Workshop\MOVE ASSET	chain of gypsy and stand up B trailer bolsters		25/05/2018	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Chassis\FIFTH WHEE	broken off front of turntable for load chain		25/05/2018	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Body\BREAKDOWN	call out		25/05/2018	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Workshop\MOVE ASSET	travel to Tumut return		25/05/2018	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Chassis\FIFTH WHEE	cut off old welded lug on the tunrtable and rewelded new log on. Replace worn gypsy gear t		25/05/2018	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Chassis\FIFTH WHEE	broken load chain. Log on front of turntable	broken log off the front off the turntable	25/05/2018	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Albury - Workshop	Brakes\BRAKE ADJ	RH rear brakes replaced		12/05/2018	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Brakes\BRAKE ADJ	LH front brakes replaced		12/05/2018	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	VehService\DS	D Service		12/05/2018	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Tumut - Workshop	Brakes\BRAKE ADJ	RH rear brakes replaced		12/05/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Brakes\BRAKE ADJ	LH front brakes replaced		12/05/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	VehService\DS	Service		12/05/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job		12/05/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	VehService\DS	D Service		12/05/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Tyres\RETREAD	Job Added From Invoice		04/05/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Tyres\FITMENT	Job Added From Invoice		04/05/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Tyres	Job Added From Invoice		04/05/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	DriCabRep\DOOR LOCK	slide locks not working		04/05/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	DriCabRep\DOOR LOCK	slide locks not working		04/05/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Elect\INDICATORS	LHS indicator not working		03/05/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Chassis\WINCH/STRP	weld cracked winch bracket		02/05/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Chassis\WINCH/STRP	cracked winch mount 2nd		02/05/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Susp\SUSPENSION	suspension		24/04/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	VehService\DS	D Service		24/04/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job		24/04/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	VehService\DS	D Service Due		24/04/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Rosewood - Workshop	Susp\SUSPENSION	fit c/o springs LM & RM seb		24/04/2018	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Workshop\MOVE ASSET	drop off parts at ETS		24/04/2018	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
			chain came off gypsy refit chain, unload trailers found chain to be loose. Remove chain and cut out 6 links. Refit and test. Ok								
T382	Rosewood - Workshop	Body\CHN/RLR/MN	return truck to work		12/04/2018	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Body\BREAKDOWN	call out		12/04/2018	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Tumut - Workshop	VehService\DS	D Service		10/04/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job		10/04/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	VehService\DS	Service	refer to job no. 165567	10/04/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Tyres\RETREAD	Job Added From Invoice		28/03/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Tyres\FITMENT	Job Added From Invoice		28/03/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Tyres	Job Added From Invoice		28/03/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Rosewood - Workshop	VehService\DS	D Service		25/03/2018	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Tumut - Workshop	VehService\DS	Service		24/03/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Hydraulics\MOTOR	change P.T.O motor		24/03/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	VehService\DS	D Service		24/03/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job		24/03/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job		13/03/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	VehService\DS	D Service		13/03/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Albury - Workshop	VehService\DS	D Service		13/03/2018	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Tumut - Workshop	Tyres\RETREAD	Job Added From Invoice		01/03/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Tyres\FITMENT	Job Added From Invoice		01/03/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER

T382	Tumut - Workshop	Tyres	Job Added From Invoice		01/03/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job		27/02/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	VehService\DS	D Service		27/02/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Albury - Workshop	VehService\DS	D Service		24/02/2018	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
				Travel to Tumut. R/H wiring loom damaged from strap that had come unwound							
				replace wiring 1x stop/tail complete							
T382	Albury - Workshop	Elect\TRL LIGHTS	NO TRAILER LIGHTS. LOOM DAMAGED FROM STRAP COMING OFF.	1x rubber	23/02/2018	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		14/02/2018	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Elect\INDICATORS	RHS blinker not working		14/02/2018	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	DrivLine\WHL HUB	align front axle on A Trailer		14/02/2018	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	VehService\DS	D Service		14/02/2018	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Tumut - Workshop	Tyres\RETREAD	Job Added From Invoice		11/02/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Tyres\FITMENT	Job Added From Invoice		11/02/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Tyres	Job Added From Invoice		11/02/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job		26/01/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Elect\ELECT P&W	rear LH tail light broken wire at plug		26/01/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	VehService\DS	D Service		26/01/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
				CALLOUT.							
				TRAVEL TO TUMUT AND REPLACE AIR BAG.							
T382	Albury - Workshop	Susp\AIR BAG	LHR AIR BAG HAS A HOLE IN IT	Then travel to Holbrook.	25/01/2018	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	DrCabElect\RWC COMP	no truck safe sticker		13/01/2018	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Brakes\CONSUMABLE	replace wear nipples		13/01/2018	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		13/01/2018	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	VehService\DS	D SERVICE	BOLSTER WEAR PADS, 4 GREASE NIPPLES, 1 GREASE CARTRIDGE	13/01/2018	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Wodonga - Workshop	Hydraulics\ELECT P&W	LHS brake lens gone		09/01/2018	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
				No indicators							
				repaired broken wires to L and R indicator							
				repaired wiring in cable arm for rear							
T382	Rosewood - Workshop	Elect\INDICATORS	No blinkers	R indicatro on B trailer	06/01/2018	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Tumut - Workshop	Elect\INDICATORS	no RH blinker	no R indicator	03/01/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
				found plug on to light u/s							
T382	Tumut - Workshop	Body\LIGHTS	no lights	bypass plug requires new plug for light	03/01/2018	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Albury - Workshop	VehService\DS	D SERVICE		23/12/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		23/12/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Tumut - Workshop	Tyres\RETREAD	Job Added From Invoice		09/12/2017	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Tyres\FITMENT	Job Added From Invoice		09/12/2017	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Tyres	Job Added From Invoice		09/12/2017	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Albury - Workshop	VehService\DS	D SERVICE	DONE @ ETS.	09/12/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Elect\ELECT P&W	LHS tail light out		02/12/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Body\LIGHTS	left HS blinker not working		02/12/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Tumut - Workshop	Tyres\RETREAD	Job Added From Invoice		24/11/2017	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Tyres\FITMENT	Job Added From Invoice		24/11/2017	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Tyres	Job Added From Invoice		24/11/2017	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		24/11/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
				SERVICED BY ETS.							
T382	Albury - Workshop	VehService\DS	D SERVICE	REPLACED CA700	24/11/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Elect\TRL LIGHTS	REPLACE BROKEN LIGHTS		21/11/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Body\MOUNTS	hand rail loose driver side		18/11/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Body\MOUNTS	log rack loose		18/11/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Tumut - Workshop	Body\CHN/RLR/MN	weld lug on load chain		17/11/2017	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Albury - Workshop	Elect\TRL LIGHTS	REPAIR TRAILER LIGHTS	AS PER INVOICE	15/11/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Tumut - Workshop	Tyres\RETREAD	Job Added From Invoice		14/11/2017	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Tyres\FITMENT	Job Added From Invoice		14/11/2017	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Tyres	Job Added From Invoice		14/11/2017	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Albury - Workshop	Susp\SUSPENSION	SUPPLY LOWER SHOCKER PLATE TO TUMUT.		14/11/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		12/11/2017	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	VehService\DS	Service		12/11/2017	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Tumut - Workshop	Tyres\RETREAD	Job Added From Invoice		11/11/2017	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Tyres\FITMENT	Job Added From Invoice		11/11/2017	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Tyres	Job Added From Invoice		11/11/2017	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Rosewood - Workshop	Body\ELECT P&W	repaired broken wire		09/11/2017	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Body\LIGHTS	work lights not working	repair lights	09/11/2017	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		09/11/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	VehService\DS	D SERVICE	COMPLETED BY EXPRESS TRUCK SERVICE	09/11/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Brakes\BRK RELINE	RELINE LF, LM AND LR.		31/10/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Body\MUDGUARDS	replaced mudflaps		31/10/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Susp\SPRNG PACK	replace R/F spring wrap		31/10/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Susp\AIR BAG	REPLACE LEAKING AND RERISHED AIR BAGS		31/10/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
			hook up and tow in to workshop								
T382	Rosewood - Workshop	Workshop\MOVE ASSET	wash down for relines		29/10/2017	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Body\HOUSEKEEP	grease ball race		29/10/2017	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Susp\SHOCK ABS	replace missing shocker L/F		29/10/2017	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Chassis\FIFTH WHEE	weld alignment plate		29/10/2017	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Rosewood - Workshop	Susp\UNI JOINTS	tighten Ubolts R/F		29/10/2017	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Wodonga - Workshop	Susp\DAMAGE	Travel to site , jack up front axle , pull axle back into alignment . Fit new spring & Ubolts . Te	Snowy Trucks	28/10/2017	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Rosewood - Workshop	Body\CHN/RLR/MN	fit new load chain		28/10/2017	Completed	Colac	GTK	37689S	Rosewood Workshop	TRAILER
T382	Wodonga - Workshop	Brakes\AIR LEAK	Repair air leak at fitting	Snowy Trucks	26/10/2017	Completed	Colac	GTK	37689S	Wodonga Workshop	TRAILER
T382	Tumut - Workshop	Susp\AXLES	broken Ubolts on RHS 1st axle		26/10/2017	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Albury - Workshop	Body\CHN/RLR/MN	BROKEN LOAD CHAIN		24/10/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Tumut - Workshop	Body\AIR LEAK	air leak		24/10/2017	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice		02/10/2017	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice		02/10/2017	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Tyres	Job Added From Invoice		02/10/2017	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Albury - Workshop	Tyres\RUN OUT	Job Added From Invoice		21/09/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Elect\TAIL LIGHT	Removed damaged tail light, lengthened loom, fitted plug, fitted LED tail light, tested, remo	Tumut auto electrics - 00173400	20/09/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER

			Checked lights, checked power to side clearance lights, checked chassis looms, found and repaired faulty wiring, tested, checked LED work lights, checked trailer plug wiring, reconfigured wiring correcrtly, tested, checked wiring to LED work lights.								
T382	Albury - Workshop	Elect\ELECT P&W	Repaired wiring to work lights and number plate light, tested	Tumut electrics - 00173391 Work performed on 12/9/17 D service as per GF service sheet	19/09/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	VehService\DS	D service	00038405	13/09/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	DrivLine\SPRNG HANG	broken spring hanger		09/09/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Body\CHN/RLR/MN	loose Ubolts on trailer	Work performed on 8/9/17 Tighten U bolts	09/09/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Susp\SUSPENSION	Loose U bolts on trailer	Snowy trucks - 00038385 Fit new red valve to trailer	09/09/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	VehService\DS	Carry out D service	Snowy trucks - 00038300	02/09/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Tumut - Workshop	Tyres\RETREAD	Job Added From Invoice		25/08/2017	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Tyres\FITMENT	Job Added From Invoice		25/08/2017	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Tumut - Workshop	Tyres	Job Added From Invoice		25/08/2017	Completed	Colac	GTK	37689S	Tumut Workshop	TRAILER
T382	Albury - Workshop	VehService\DS	Service Work performed on 9/8/17 Inspect breakdown, found air bag to need replacing, kinked air line to get truck back to workshop.	Work performed on 22/8/17 carry out D service as per GF sheet LHF shock needs replacing, LHF brakes low Snowy trucks - 00038178	23/08/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Body\AIR BAG	Remove and replace air bag Work performed on 8/8/17	Snowy truck - 00038041	10/08/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	VehService\DS	Carry out D service as per GF service sheet	Snowy trucks - 00038013	09/08/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Susp\SUSPENSION	WELD CRACKS ON HANGER, SPRING EYE BOSS AND GUSSETS.		25/07/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Elect\TRL LIGHTS	TAIL LIGHTS FLASHING ON/OFF. TAIL LIGHTS FLASHIUNG ON/OFF		21/07/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Body\CHN/RLR/MN	REPLACE SAFETY CHAIN AND DOG		21/07/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Chassis\BOLSTER	Replace upright 2nd bolster, bolt was never through hole, upright laying on LH mudguard	Refit bolster peg correctly - check other pegs replace hyd coupling	19/07/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Hydraulics\HYD LEAKS	HYD LEAK AT FRONT OF TRAILER	topped up hyd oil in 903. cleaned up excess oil. Test unit for leaks	16/07/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		14/07/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	VehService\DS	D SERVICE		14/07/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice		12/07/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice		12/07/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Tyres	Job Added From Invoice		12/07/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Tyres\BLOWOUTS	flat spare tyre puncture		05/07/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Brakes\AIR LEAK	Air leak	Replace rubbed hose	05/07/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	VehService\DS	D SERVICE		30/06/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Tyres\RUN OUT	Job Added From Invoice		22/06/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Tyres\RUN OUT	Job Added From Invoice		21/06/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	VehService\DS	D SERVICE		21/06/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Brakes\EBS Kit	EBS KIT		14/06/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	VehService\DS	D SERVICE		11/06/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	VehService\DS	D SERVICE LHF SHOCKER MOUNT CRACKING OUT IN HANGER.		04/06/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Susp\SHOCK ABS	WILL ORGANISE TO BE REPAIRED 31/05/2017	Repaired various other small cracks	01/06/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Body\PANELS	umbilical arm cracked replaced bolts		01/06/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Susp\SHOCK ABS	LHF SHOCKER MOUNT CRACKING OUT IN HANGER.		28/05/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	VehService\DS	D SERVICE		28/05/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice		26/05/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice		26/05/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Tyres	Job Added From Invoice NO NUMBER PLATE AND WORK LIGHTS	replaced connector for work and no plate lights (damaged)	26/05/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Elect\TRL LIGHTS	LH OUT SIDE BRAKE LIGHT FLICKERING	reconnect light to plug for brake light	25/05/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	VehService\DS	D SERVICE		19/05/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	VehService\DS	D SERVBICE		12/05/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Tyres\RUN OUT	Job Added From Invoice		12/05/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Chassis\FIFTH WHEE	REPLACE WORN TURNTABLE WEAR PADS	removed 4 links from front of T/table and adjusted load chain	03/05/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Brakes	Record Check Results		02/05/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	VehService\DS	D SERVICE		02/05/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Brakes\BOOSTER	REPLACE RM BRAKE BOOSTER LEAKING	REPLACED 24/30 BOOSTER	02/05/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Chassis\WINCH/STRP	REPAIR FRONT WINCH	repaired winch check air leak found rubbed fitting in bottom of rear of tank removed air tank from trailer	02/05/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Body\AIR FITTIN	AIR LEAK	refitted tank	02/05/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Brakes\AIR LEAK	AIR LEAK	AS PER ENTRY #53048	02/05/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Insp\ANN INSP	Annual Inspection		30/04/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		23/04/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	VehService\DS	Service		23/04/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Chassis\WINCH/STRP	1st winch - hard to do up at times sticking		23/04/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Body\CHN/RLR/MN	BROKEN HAMMER LOCK ON CHAIN ADJUSTER FRAME		09/04/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	VehService\DS	D SERVICE	checked work light	09/04/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Elect\WORK LIGHT	BACK WORK LIGHTS NOT WORKING	cleaned plug test ok removed winch from T383. middle winch replaced 2nd winch	05/04/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Chassis\WINCH/STRP	FIX 2ND WINCH-BUSHES	will refit when repaired	05/04/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Myrtleford - Workshop	Tyres\TP13	Job Added From Invoice		04/04/2017	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Albury - Workshop	Brakes\AIR LEAK	AIR LEAK		02/04/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Chassis\WINCH/STRP	STRAP PULLS OUT OF 1ST WINCH		02/04/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	VehService\DS	D SERVICE		02/04/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER

T382	Albury - Workshop	Body\HOUSEKEEP	UMBILICAL ARM RUBBING ON DRIVE GUARD	SHORTENED UMBILICAL LOOM.	02/04/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Tyres\TP19	Job Added From Invoice		30/03/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Chassis\WINCH/STRP	REPLACE WINCH HANDLE 1ST WINCH	REPLACED HANDLE	29/03/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
				AS ABOVE. RELINE SHEET ATTACHED							
				relined R/F and R/R axles							
				washed and inpsected bearing and hubs							
T382	Albury - Workshop	Brakes\BRK RELINE	RELINE RHF AND RHR WHEELS	crack tested axles	26/03/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Tyres\TP13	Job Added From Invoice		24/03/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Body\CHN/RLR/MN	FIX DOG AND CHAIN. LOOSE AT BOTTOM MOUNT.		23/03/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Chassis\WINCH/STRP	1ST WINCH SEIZING UP.		23/03/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
				remove old shocker strap							
T382	Albury - Workshop	VehService\DS	D SERVICE	replaced R/F shocker	23/03/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Tyres\DAMAGE	CRACKED RIM		21/03/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Tyres\TP15	Job Added From Invoice		17/03/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Elect\INDICATORS	LH INDICATOR DULL	REPAIRED WIRING IN UMBILICAL ARM. NO INDICATOR ON 'B' TRAILER	17/03/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Brakes\AIR LEAK	REPAIR AIR LEAKS	replace rubbed hose	14/03/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Susp\AIR BAG	RF AIR BAG LEAKING	REPLACE AIR BAG	14/03/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
			REPLACED MISSING MOUNTING BOLTS IN BOTH GUARDS.								
			TIGHTENED TAIL LIGHT MOUNTING BOLTS								
T382	Albury - Workshop	Body\MOUNTS	REPLACED MISSING REFLECTORS		14/03/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	VehService\DS	D SERVICE	SUPPLY DRIVER WITH SPARE TYRE LIFT BAR	14/03/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Tyres\TP21	Job Added From Invoice		11/03/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Brakes\AIR LEAK	repaired air leak at B trailer brake valve		11/03/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	DrivLine\WHEEL BRGS	CHECK AND ADJUST WHEEL BEARINGS	adjusted wheel bearings on front & rear axles	11/03/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Chassis\WINCH/STRP	REPLACED FRONT STRAP		11/03/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	DrivLine\WHEEL BRGS	CHECK MIDDLE AXLE WHEEL BEARINGS	check and adj	09/03/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Chassis\FIFTH WHEE	SLIDER PINS WON'T UNLOCK	grease	09/03/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
				FOUND SERVICE VALVE FAULTY.							
T382	Albury - Workshop	Brakes\AIR LEAK	BRAKES STICKING ON.	REPLACED VALVE	07/03/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
			replace height control bottom mount								
			replaced broken backinf plate bolt, RL								
T382	Albury - Workshop	Susp\HCV	replaced backing plates RL		04/03/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Brakes\BRK RELINE	RELINE LM AND LR WHEELS	RELINE AND CRACK TEST AXLES.	04/03/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Brakes\AIR LEAK	AIR LEAKS / PREVENTIVE MAINTENANCE	REPOSITION BRAKE BOOSTERS AND REPLACED RUBBED HOSES	04/03/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Susp\SUSPENSION	LM 'U' BOLTS LOOSE	REPLACED SEB, WRAP, WEAR PLATES SEB BOLT, ALIGNMENT PLATE AND LH LOWER S	04/03/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	VehService\DS	D SERVICE		03/03/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Brakes\BRK RELINE	repair brake lines		02/03/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Chassis\WINCH/STRP	WINCHES HARD TO WIND UP		02/03/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Tyres\TP18	Job Added From Invoice		16/02/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Body\CHN/RLR/MN	NEEDS PLACE TO HANG HOLD DOWN DOG.		12/02/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Chassis\CROSS MBR	REPAIR CRACKED REAR X-MEMBER		09/02/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Chassis\WINCH/STRP	PLEASE FIX 2ND STRAP TO WINCH REEL	FITTED NEW STRAP AND SECURE TO WINCH	09/02/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Elect\TRL LIGHTS	Repair - no side lights	AS PER JOB #46148	09/02/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Elect\TRL LIGHTS	REPLACED LIGHT ON LH SIDE MARKER		08/02/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Elect\TRL LIGHTS	REPAIRED WIRING TO 2ND BOLSTER.		08/02/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	VehService\DS	D service	LH park light out	01/02/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Tyres\TP16	Job Added From Invoice		26/01/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Tyres\TP12	Job Added From Invoice		26/01/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Chassis\CHAS CRACK	Weld cracks in winch mounts, bolsters and x-members		26/01/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Elect\TRL LIGHTS	Repair wirng to 1st bolster		26/01/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Albury - Workshop	Body\HOUSEKEEP	Replaced front umbilical arm bearings		26/01/2017	Completed	Colac	GTK	37689S	Albury Workshop	TRAILER
T382	Myrtleford - Workshop	Chassis\FIFTH WHEE	check and repair slide locks		19/01/2017	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Brakes\BRAKE ADJ	adjust brakes		17/01/2017	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Elect\ELECT P&W	repair slide locks		17/01/2017	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Elect\TRL LIGHTS	Rewire 2nd Bolster		17/01/2017	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
			Repair reverse work light wiring								
			Repair LHS 2nd bolster light wiring								
T382	Myrtleford - Workshop	Elect\TRL LIGHTS	Fit new RHS LED tail light & RHS LED indicator		13/01/2017	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Elect\WORK LIGHT	Fit new heavy duty plug		13/01/2017	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Chassis\FIFTH WHEE	Check ball race, foot pins & bushes		13/01/2017	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Brakes\BRK RELINE	Fit 40% Runout brake shoes to LHM & LHR & check bearings		13/01/2017	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		12/01/2017	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		12/01/2017	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
			Repair chassis crack in front of spring hanger								
			Repair trailer & bolster cracks	Shepparton Motor Panels							
T382	Myrtleford - Workshop	Chassis\CHAS CRACK	Wheel alignment & paint	Complete	01/12/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Tyres\TP15	Job Added From Invoice		17/11/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Body\HOUSEKEEP	wash trailer		17/11/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		15/11/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		15/11/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Elect\TRL LIGHTS	LHS Clearance light needs rewiring		05/11/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Elect\TRL LIGHTS	repair no side lights		04/11/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Brakes\AIR LEAK	Replace leaking trailer valve	replace tractor protection valve on RH side of chains	03/11/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		01/11/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		01/11/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Tyres\DAMAGE	Replace 2 x cracked rims		29/10/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Brakes\AIR LEAK	Repair broken booster		28/10/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Hydraulics\HYD LEAKS	repair hyd hose under turntable		26/10/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Brakes\BRK RELINE	fit 40% run out to LHR axle + check bearings		18/10/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		13/10/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		13/10/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		04/10/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist	repair reverse light wiring	04/10/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Tyres\TP19	Job Added From Invoice		30/09/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Tyres\TP15	Job Added From Invoice		30/09/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Chassis\HOUSEKEEP	Wash trailer		27/09/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		17/09/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		17/09/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Tyres\TP16	Job Added From Invoice		15/09/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Tyres\TP11	Job Added From Invoice		15/09/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER

T382	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		07/09/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
				fit missing front xmener bolts x 3 fit 2 winch knobs							
T382	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist	fit bolt to LH chai adjust bracket	07/09/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Elect\ELECT P&W	repair slide lock wiring		02/09/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Brakes\BRAKE ADJ	adjust brakes		02/09/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Brakes\BRK RELINE	fit 40% runout shoes to LHM + check bearings		02/09/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Brakes\BRK RELINE	fit 40% runout shoes to LHR + check bearings		02/09/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Brakes\AIR LEAK	inspect low brake percentages		30/08/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		20/08/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		20/08/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Tyres\TP16	Job Added From Invoice		17/08/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Tyres\TP16	Job Added From Invoice		17/08/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Tyres\TP16	Job Added From Invoice		17/08/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Elect\TRL LIGHTS	no brake light		14/08/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Elect\TRL LIGHTS	no brake lights		13/08/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Elect\ELECT P&W	slide lock not working		11/08/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Tyres\TPS1	Job Added From Invoice		11/08/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Elect\TRL LIGHTS	2nd bolster lights not working		10/08/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Brakes\AIR LEAK	air leak LHF b/booster hose		10/08/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		10/08/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		10/08/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Tyres\TP19	Job Added From Invoice		30/07/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		29/07/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		29/07/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Chassis\FIFTH WHEE	check slide locks		21/07/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Comp\TRL LIGHTS	check side lights		21/07/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		19/07/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		19/07/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	DrCabElect\SCALES	calibrate scales - span weight at CHH weighbridge. calibrate scales - span weight at weight b		15/07/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Chassis\WINCH/STRP	replace front winch strap		15/07/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Tyres\TP13	Job Added From Invoice		08/07/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Tyres\TP13	Job Added From Invoice		08/07/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Tyres\TP13	Job Added From Invoice		08/07/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Chassis\BOLSTER	Replace 2nd Winch strap	Complete	06/07/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	DrCabElect\SCALES	Calibrate Scales - scales not reading	Complete	06/07/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	DrCabElect\SCALES	check & recalibrate scales		06/07/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		01/07/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		01/07/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Elect\ELECT P&W	check scales & settings		24/06/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		22/06/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		22/06/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Chassis\FIFTH WHEE	Check Slide Locks switch & wiring	Complete	21/06/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Tyres\TPS2	Fit Spare Wheel - # 2	Complete	21/06/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Tyres\TPS1	Fit spare Wheel - # 1	Complete	21/06/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Body\MOUNTS	Fit safety chain dog	Complete	21/06/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Tyres\TP17	Job Added From Invoice		15/06/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Tyres\TP17	Job Added From Invoice		15/06/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Tyres\TP17	Job Added From Invoice		15/06/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Brakes\BRAKE ADJ	adjust brakes		10/06/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		20/04/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
				fit transducer & air fittings							
T382	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist	repair hold down chain	20/04/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection		20/04/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
			rewire tail light bar								
T382	Myrtleford - Workshop	Chassis\CROSS MBR	supply bolts	completed	25/01/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Body\DAMAGE	repair taillight bar cracks	completed	15/01/2016	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Tyres\TP19	Job Added From Invoice		01/12/2015	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Tyres\TP19	Job Added From Invoice		01/12/2015	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Tyres\TP19	Job Added From Invoice		01/12/2015	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job	completed	26/11/2015	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist	completed	26/11/2015	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Tyres\TP21	Job Added From Invoice		27/10/2015	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Tyres\DAMAGE	Skidz to change flat tyre + replace spare	completed	24/10/2015	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Brakes\BRK O/HAUL	fit 50% run out brake shoes to lhr axle	completed	22/10/2015	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
			reset circuit breaker + check trailer plug								
T382	Myrtleford - Workshop	Elect\TRL LIGHTS	fit plug to rh indicator wiring	completed	22/10/2015	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job	completed	21/10/2015	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist	completed	21/10/2015	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
			check lights								
T382	Myrtleford - Workshop	Elect\ELECT P&W	lh side light - ref ent no 1907 job no 3121	completed	16/10/2015	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job	completed	08/10/2015	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist	completed	08/10/2015	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job	completed	25/09/2015	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist	completed	25/09/2015	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Tyres\DAMAGE	Job Added From Invoice		24/09/2015	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Tyres\TP17	Job Added From Invoice		24/09/2015	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Tyres\TP17	Job Added From Invoice		24/09/2015	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Tyres\TP17	Job Added From Invoice		24/09/2015	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Susp\SHOCK ABS	Service Job Added From Invoice		16/09/2015	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Susp	replace lhm shocker	completed	15/09/2015	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job	completed	15/09/2015	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER
T382	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist	completed	15/09/2015	Completed	Colac	GTK	37689S	Myrtleford Workshop	TRAILER