EquipmentName	Workshop	CodeAndSubCode	Description	Schedule	CompletionComments	DateDone	Worktype	Workstate	EquipmentOwner	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
T238	Wodonga - Workshop	Body\CHN/RLR/MN	tie down chain broken		RR's pre Jan 20 (system clean out) 05/08/20	06/08/2020	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Wodonga Workshop	TRAILER
T238	Wodonga - Workshop	Elect\ELECT P&W	RH mudguard light flicking on and off			06/08/2020	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Wodonga Workshop	TRAILER
T238	Wodonga - Workshop	Elect\ELECT P&W	right hand mudguard not working			06/08/2020	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Wodonga Workshop	TRAILER
T238	Wodonga - Workshop	Chassis\WINCH/STRP	crack left side chassis just behind skid plate hook up			06/08/2020	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Wodonga Workshop	TRAILER
T238	Albury - Workshop	Workshop\MOVE ASSET	move trailer pick up bolster for T238 check out used bolsters for sale at private seller			16/03/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER
T238	Albury - Workshop	Chassis\BOLSTER	pick up load chains for border lifting and safety			09/02/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER
T238	Rosewood - Workshop	Body\DOOR LOCK	slide locks please check			06/02/2019	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Albury - Workshop	Chassis\FIFTH WHEE	REPLACE WEAR PADS ETC.			27/01/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER
T238	Albury - Workshop	Brakes\EBS Kit	EBS		need another tank for air capasity	24/01/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER
T238	Albury - Workshop	Chassis\FIFTH WHEE	Fifth Wheel/Turntable		replaced t/table wear pads	22/01/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER
T238	Albury - Workshop	Body\TRL LEGS	Trailer Landing Legs		repaired legs	22/01/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER
T238	Albury - Workshop	Brakes\EBS Kit	Fit up EBS		strip out old system	15/01/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER
T238	Albury - Workshop	Wash\WASH	Truck or Trailer wash		WASH TRAILER	15/01/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER
T238	Albury - Workshop	Insp\ANN INSP	inspection R/W as EBS been fitted			15/01/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER
T238	Albury - Workshop	VehService\DS	SERVICE AND REPAIRS	VehService\DS		10/01/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			10/01/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Albury - Workshop	Brakes\BRK RELINE	BRAKE RELINE			22/12/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Albury - Workshop	Elect\TAIL LIGHT	LH tail light needs replacing - light and plate missing			20/12/2018	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER
T238	Tumut - Workshop	Tyres\FITMENT	Job Added From Invoice			20/12/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	Tyres\RETREAD	Job Added From Invoice			20/12/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS		19/12/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			19/12/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	Brakes\BRK RELINE	RELINE AS REQUIRED			01/12/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	VehService\DS	CARRY OUT D SERVICE	VehService\DS		01/12/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job			01/12/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Albury - Workshop	VehService\DS	Service	VehService\DS		21/11/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER
T238	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job			21/11/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	VehService\DS	D SERVICE	VehService\DS		21/11/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	VehService\DS	Service	VehService\DS		21/11/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice			21/11/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER
T238	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice			21/11/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER
T238	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS	D service completed	10/11/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER
T238	Albury - Workshop	VehService\DS	VehService\DS	VehService\DS	D service completed- see attached	10/11/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER
T238	Tumut - Workshop	Body\CHN/RLR/MN	tie down chain broken			01/11/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	VehService\DS	D Service	VehService\DS		01/11/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job			01/11/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Albury - Workshop	VehService\DS	Service	VehService\DS		31/10/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER
T238	Albury - Workshop	Body\AIR LEAK	slide lock valve sticking. Put finger over air leak to release			27/10/2018	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER
T238	Albury - Workshop	Tyres\DRV TYRES	RH side centre outside tyre needs replacing			23/10/2018	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER
T238	Tumut - Workshop	VehService\DS	D SERVICE	VehService\DS		23/10/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job			23/10/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Albury - Workshop	Chassis\BOLSTER	front RH bolster needs turning 180°			20/10/2018	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER
T238	Albury - Workshop	Chassis\BOLSTER	back LH bolster needs turning 180°			20/10/2018	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER
T238	Albury - Workshop	Chassis\WINCH/STRP	front bolster leaning forward Teflon plates worn out			20/10/2018	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER
T238	Albury - Workshop	Chassis\WINCH/STRP	crack left side chassis just behind skid plate			20/10/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER
T238	Albury - Workshop	VehService\DS	SERVICE	VehService\DS		10/10/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER
T238	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice			01/10/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Wodonga Workshop	TRAILER
T238	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			26/09/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	VehService\DS	Service	VehService\DS		26/09/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Albury - Workshop	Workshop	Job Added From Invoice			22/09/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER
T238	Rosewood - Workshop	Body\DAMAGE	B Trailer wouldn't always load check hyd pressure on 1000. 1800psi			19/09/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Hydraulics\OIL/FILTER	check hyd oil level. 3/4 full replace hyd motor on deduction drive box			19/09/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Hydraulics\MOTOR	test ok			19/09/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Workshop\MOVE ASSET	travel to and from Tumut/Rosewood			19/09/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Albury - Workshop	Hydraulics\MOTOR	TRAILERS WOULD NOT ALWAYS LOAD			19/09/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER
T238	Tumut - Workshop	Tyres	Job Added From Invoice			15/09/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	Tyres\FITMENT	Job Added From Invoice			15/09/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	Tyres\RETREAD	Job Added From Invoice			15/09/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	Tyres	Job Added From Invoice			15/09/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	Tyres\FITMENT	Job Added From Invoice			15/09/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	Tyres\RETREAD	Job Added From Invoice			15/09/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	VehService\DS	D SERV	VehService\DS		12/09/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job			12/09/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	Hydraulics\HYD LEAKS	hydraulic fitting LH side leaking			11/09/2018	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	Tyres	Job Added From Invoice			06/09/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	Tyres\FITMENT	Job Added From Invoice			06/09/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	Tyres\RETREAD	Job Added From Invoice			06/09/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Rosewood - Workshop	Brakes\BOOSTER	replace service line to the booster			23/08/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			23/08/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	VehService\DS	D Service	VehService\DS		23/08/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	VehService\DS	D SERVICE	VehService\DS		09/08/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			09/08/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Body\CHN/RLR/MN	fit new A-frame for load chain		A frame broken. Replace with new A frame and new hammer locks. Replace A frame. Anchor plate's.	07/08/2018	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Body\CHN/RLR/MN	replace loading rollers		untwist load chain and replace rear load rollers and oulled out slider lock saddle clean up and shanfa a edge on th saddle to make it loc	07/08/2018	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS	repair side light	01/08/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER
T238	Albury - Workshop	Body\TRL FLOOR	bolts missing checker plate		ok	01/08/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER
T238	Albury - Workshop	Body\AIR LEAK	air leak in tri when brake is on possibly booster rubber		no leak	01/08/2018	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER
T238	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			01/08/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER
T238	Rosewood - Workshop	Body\DOOR LOCK	slider lock fault		slide locks jammed up	27/07/2018	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Body\CHN/RLR/MN	remove 8 links from load chain			27/07/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Body\DOOR LOCK	check slide lock operation			27/07/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	VehService\DS	D Service	VehService\DS		20/07/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Susp\AIR FITTIN	repair air line			20/07/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			20/07/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Tumut - Workshop	Elect\TAIL LIGHT	NO RH TAIL LIGHTS		no lights on RR of tail light bar	07/07/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	Elect\ELECT P&W	replaced light assy			07/07/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	Elect\ELECT P&W	repair wiring			07/07/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	Workshop\MOVE ASSET	travel to and from Tumut			07/07/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Albury - Workshop	Workshop	Job Added From Invoice			06/07/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER
T238	Rosewood - Workshop	Elect\ELECT P&W	repair broken wires to side marker			05/07/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			05/07/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	VehService\DS	Service	VehService\DS		05/07/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Brakes\BRK RELINE	reline			05/07/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Albury - Workshop	Body\CHN/RLR/MN	pick up load chain			30/06/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER
T238	Rosewood - Workshop	Body\CHN/RLR/MN	broken load chain		replace load chain	30/06/2018	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			27/06/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	VehService\DS	Service	VehService\DS		27/06/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Tumut - Workshop	Tyres	Job Added From Invoice			27/06/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Rosewood - Workshop	VehService\DS	D Service	VehService\DS		22/06/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Elect\TAIL LIGHT	rewire R/H tail lights			22/06/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Elect\ELECT P&W	replaced R/R backing plate			22/06/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			07/06/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	VehService\DS	Service	VehService\DS		07/06/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Tumut - Workshop	Tyres	Job Added From Invoice			04/06/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Rosewood - Workshop	Susp\SUSPENSION	replace worn 2 spring and warp and wear plate			01/06/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Body\DAMAGE	replace 4x bolts in the cross brace in the trailer			01/06/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Susp\SUSPENSION	press new bush in z spring			01/06/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			01/06/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	VehService\DS	D Service	VehService\DS		01/06/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Elect\BRK LIGHT	left hand brake light found loom rubber rght through so cut all old loom out off the L/H side and replace with loom off wire			19/05/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Elect\ELECT P&W	tested ok			19/05/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			19/05/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	VehService\DS	D Service	VehService\DS		19/05/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Elect\ELECT P&W	Front RH bolster - side light flicking			18/05/2018	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Elect\BRK LIGHT	No brake lights			10/05/2018	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Elect\ELECT P&W	replace trailer plug			09/05/2018	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Elect\ELECT P&W	check lights working			09/05/2018	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Brakes\BRK RELINE	Reline			02/05/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			26/04/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Body\CHN/RLR/MN	un twist load chain cut and shorten load chain			26/04/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	VehService\DS	D Service	VehService\DS		26/04/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Hydraulics\VALVES	Hydraulics coupling leaking			24/04/2018	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Elect\BRK LIGHT	No brake lights			23/04/2018	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Elect\TRL LIGHTS	No clearance lights			23/04/2018	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER

T238	Tumut - Workshop	Tyres	Job Added From Invoice			19/04/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER		
T238	Tumut - Workshop	Tyres\FITMENT	Job Added From Invoice			19/04/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER		
T238	Tumut - Workshop	Tyres\RETREAD	Job Added From Invoice			19/04/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER		
T238	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			12/04/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER		
T238	Rosewood - Workshop	VehService\DS	Service	VehService\DS		12/04/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER		
T238	Tumut - Workshop	Tyres	Job Added From Invoice			11/04/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER		
T238	Tumut - Workshop	Tyres\FITMENT	Job Added From Invoice			11/04/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER		
T238	Tumut - Workshop	Tyres\RETREAD	Job Added From Invoice			11/04/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER		
T238	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			27/03/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER		
T238	Rosewood - Workshop	VehService\DS	D Service	VehService\DS		27/03/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER		
T238	Albury - Workshop	Hydraulics\MOTOR	TRAILER WILL NOT LOAD			17/03/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER		
T238	Albury - Workshop	Elect\BRK LIGHT	no brake lights			15/03/2018	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER		
T238	Albury - Workshop	Elect\INDICATORS	no blinkers indicators			15/03/2018	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER		
T238	Albury - Workshop	Body\LIGHTS	no clearance lamps			15/03/2018	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER		
T238	Albury - Workshop	Elect\ELECT P&W	start in clearance lamps to blinkers in truck			15/03/2018	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER		
T238	Rosewood - Workshop	Brakes\BOOSTER	Replace 24/30 booster			10/03/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER		
T238	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			10/03/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER		
T238	Rosewood - Workshop	VehService\DS	D Service	VehService\DS		10/03/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER		
T238	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS		01/03/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER		
T238	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			01/03/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER		
T238	Albury - Workshop	Elect\BRK LIGHT	NO BRAKE LIGHTS		replaced service valves	23/02/2018	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER		
T238	Albury - Workshop	Body\HOUSEKEEP	REPLACE DAMAGED CABLE ARMS		replaced umbilical arms	23/02/2018	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER		
T238	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS		23/02/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER		
T238	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			23/02/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER		
T238	Albury - Workshop	Body\CHN/RLR/MN	REPLACE LOAD ROLLERS			22/02/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER		
					repair work lights												
T238	Albury - Workshop	Elect\WORK LIGHT	NO WORK LIGHTS		changed wiring in the plug	13/02/2018	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER		
T238	Albury - Workshop	Elect\TRL LIGHTS	1ST BOLSTER LIGHTS NEED REPAIRNG		repaired connection for 1st bolster lights	13/02/2018	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER		
T238	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS	replace air line re-run so it doesn't rubber booster	13/02/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER		
T238	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			13/02/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER		
T238	Tumut - Workshop	Body\CHN/RLR/MN	replace hold down chain			09/02/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER		
T238	Albury - Workshop	Body\CHN/RLR/MN	Load Rollers stuffed need replacing			08/02/2018	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER		
T238	Tumut - Workshop	Tyres	Job Added From Invoice			03/02/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER		
T238	Tumut - Workshop	Tyres\FITMENT	Job Added From Invoice			03/02/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER		
T238	Tumut - Workshop	Tyres\RETREAD	Job Added From Invoice			03/02/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER		
T238	Tumut - Workshop	Tyres	Job Added From Invoice			24/01/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER		
T238	Tumut - Workshop	Tyres\FITMENT	Job Added From Invoice			24/01/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER		
T238	Tumut - Workshop	Tyres\RETREAD	Job Added From Invoice			24/01/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER		
T238	Albury - Workshop	Brakes\HOUSEKEEP	TIDY UP AIR LINES AND WRAP			23/01/2018	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER		
T238	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS		23/01/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER		
T238	Rosewood - Workshop	Brakes\BRAKE ADJ	adjust brakes			23/01/2018	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER		
T238	Rosewood - Workshop	Chassis\HOUSEKEEP	tie up and wrap air brake lines			23/01/2018	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER		
T238	Rosewood - Workshop	VehService\AS	A Service			23/01/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER		
			air leaks														
			remove 2 hoses with 6 joiners														
T238	Tumut - Workshop	Body\AIR LEAK	replace hoses. Test ok			17/01/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER		
T238	Tumut - Workshop	Tyres	Job Added From Invoice			16/01/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER		
T238	Tumut - Workshop	Tyres\FITMENT	Job Added From Invoice			16/01/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER		
T238	Tumut - Workshop	Tyres\RETREAD	Job Added From Invoice			16/01/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER		
T238	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			10/01/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER		
					BOOSTER/BACKING PLATES												
					Service: air leak												
					Replaced LR 30/30 booster												
T238	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS	Repair air leaks	10/01/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER		
T238	Tumut - Workshop	Tyres	Job Added From Invoice			23/12/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER		
T238	Tumut - Workshop	Tyres\FITMENT	Job Added From Invoice			23/12/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER		
T238	Tumut - Workshop	Tyres\RETREAD	Job Added From Invoice			23/12/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER		
T238	Tumut - Workshop	VehService\DS	Perform D Servive as per GF service sheet .Replace Brakes , drum on RHF . Adjust wheel bearings , weld up gusset on front guards . Replace rear & centre	VehService\DS	Snowy trucks .	22/12/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER		
					replaced broken bolt in slide lock key												
T238	Rosewood - Workshop	Body\CHN/RLR/MN	slide lock not operational		clean out plug and lube slidelocks	19/12/2017	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER		
T238	Rosewood - Workshop	Body\GOV VALVE	replace back bolt			19/12/2017	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER		
T238	Wodonga - Workshop	Brakes\BRAKE ADJ	Adjust brakes		Snowy Trucks .	07/12/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Wodonga Workshop	TRAILER		
T238	Wodonga - Workshop	VehService\DS	Perforem D service as per GF service sheet . Remove & replace all 4 teflon slides , remove & replace both rear mud flaps .	VehService\DS	Snowy trucks .	29/11/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Wodonga Workshop	TRAILER		
T238	Albury - Workshop	Susp\AIR BAG	REPLACE RH AIR BAG		replace leaking airbag	28/11/2017	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER		
T238	Albury - Workshop	Brakes\AIR LEAK	BLOWN BRAKE HOSE			28/11/2017	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER		
T238	Albury - Workshop	Elect\TAIL LIGHT	REPAIR TAIL LIGHTS			18/11/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER		
T238	Albury - Workshop	Elect\WORK LIGHT	no work lights			17/11/2017	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER		
T238	Rosewood - Workshop	VehService\AS	A Service			14/11/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER		
T238	Rosewood - Workshop	Susp\SPRNG HANG	2 spring broken			14/11/2017	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER		
T238	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			14/11/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER		
			no work lights														
T238	Albury - Workshop	Chassis\LIGHTS	clearance lights blowing fuse(s)			14/11/2017	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER		
T238	Rosewood - Workshop	Susp\SPRNG PACK	replace 2 2 springs/ubolts			14/11/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER		
T238	Rosewood - Workshop	Susp\SHOCK ABS	replace shock			14/11/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER		
			REPLACE 2X SEB BUSHES AND "U" BOLTS		replace 2 2 springs/ubolts												
T238	Albury - Workshop	Susp\SUSPENSION	1X SHOCKER		replace shock	14/11/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER		
T238	Albury - Workshop	Body\CHN/RLR/MN	REPLACE BROKEN LOAD CHAIN		replace broken load chain	04/11/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER		
T238	Albury - Workshop	Elect\INDICATORS	short in indicator			03/11/2017	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER		
T238	Albury - Workshop	Body\ELECT P&W	electrical fault in a trailer circuit RHS only			03/11/2017	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER		
T238	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			01/11/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER		
T238	Rosewood - Workshop	VehService\DS	Service	VehService\DS		01/11/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER		
T238	Albury - Workshop	Elect\INDICATORS	NO INDICATORS		reset circuit breaker in	31/10/2017	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER		
T238	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS		07/10/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER		
T238	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			07/10/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER		
					replaced - load rollers												
					chain rollers and long axle												
					remove chain links												
					replace slide long keys												
T238	Albury - Workshop	Body\CHN/RLR/MN	TRAILER WON'T LOAD.			07/10/2017	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER		
T238	Albury - Workshop	Hydraulics\HOSES	blown hydraulic hose on trailer, blown in the coil			30/09/2017	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER		
T238	Albury - Workshop	Hydraulics\OIL/FILTER	refill with oil			30/09/2017	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER		
T238	Albury - Workshop	Body\CHN/RLR/MN	SUPPLY REAR ROLLERS			28/09/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER		
T238	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job			22/09/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER		
T238	Tumut - Workshop	VehService\DS	Service	VehService\DS		22/09/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER		
T238	Tumut - Workshop	VehService\DS	D Service	VehService\DS	Work performed on the 21/09/2017 As per GF sheet 00038488	22/09/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER		
					Work performed on 13/9/17												
					D service as per GF service sheet												
T238	Rosewood - Workshop	VehService\DS	D service	VehService\DS	Replace brakes and repack wheel bearings on LHF and LHC wheels	14/09/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER		
T238	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job			05/09/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER		
T238	Tumut - Workshop	VehService\DS	D Service	VehService\DS		05/09/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER		
					Work performed on 4/9/17												
					Carry out D service as per sheet												
T238	Rosewood - Workshop	VehService\DS	D service	VehService\DS	00038329	05/09/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER		
T238	Rosewood - Workshop	Tyres	Job Added From Invoice			01/09/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER		
T238	Rosewood - Workshop	Tyres\FITMENT	Job Added From Invoice			01/09/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER		
T238	Rosewood - Workshop	Tyres\RETREAD	Job Added From Invoice			01/09/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER		
					Work performed on 28/8/17												
					carry out D service as per GF sheet												
T238	Rosewood - Workshop	VehService\DS	D service	VehService\DS	Fitted new brake boosters to RHF and RHR brakes	29/08/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER		
T238	Rosewood - Workshop	Tyres	Job Added From Invoice			22/08/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER		
T238	Rosewood - Workshop	Tyres\FITMENT	Job Added From Invoice			22/08/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER		
T238	Rosewood - Workshop	Tyres\RETREAD	Job Added From Invoice			22/08/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER		
T238	Tumut - Workshop	Chassis\WINCH/STRP	Winch handles on 1/2 winch		Replace strap handle	19/08/2017	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER		
					Work performed on 18/8/17												
					Carry out D service as per GF service sheet												
T238	Tumut - Workshop	VehService\DS	Service	VehService\DS	00038149	19/08/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER		
T238	Rosewood - Workshop	Tyres	Job Added From Invoice			15/08/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER		
T238	Rosewood - Workshop	Tyres\FITMENT	Job Added From Invoice			15/08/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER		
T238	Rosewood - Workshop	Tyres\RETREAD	Job Added From Invoice			15/08/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER		
T238	Tumut - Workshop	Hydraulics\VALVES	Fit new slide lock valve			13/08/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER		
T238	Albury - Workshop	Chassis\BOLSTER	REPLACE BOLSTER PIVOT ARMS			04/08/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER		
T238	Rosewood - Workshop	VehService\DS	carried out D service	VehService\DS	snowy trucks - 00037811	21/07/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER		
T238	Tumut - Workshop	Brakes\EBS Kit	Ordering EBS brake kit from BPW			11/07/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Wodonga Workshop	TRAILER		
T238	Rosewood - Workshop	VehService\DS	carry out D service	VehService\DS	snowy truck services - 00037708	08/07/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER		
T238	Rosewood - Workshop	Tyres	Job Added From Invoice			06/07/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER		
T238	Rosewood - Workshop	Tyres\FITMENT	Job Added From Invoice			06/07/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER		
T238	Rosewood - Workshop	Tyres\RETREAD	Job Added From Invoice			06/07/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER		
T238	Rosewood - Workshop	Brakes\BOOSTER	Fit new booster to RH centre wheel, adjust brakes		as per invoice 00037614	29/06/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER		
T238	Rosewood - Workshop	Brakes\BOOSTER	Worked performed on 22 June - check for air leaks on trailer, fit new booster hose and clamps			24/06/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER		

T238	Rosewood - Workshop	Brakes\BRK RELINE	Brake relgns			Remove wheels and hubs from LH front, RH front and RH centre axles. Fit new brakes to LH front, RH front and RH centre. Fit new wheel bearing kits to LH front and RH front. Clean and repack bearings on RH centre. Fit wheels and hubs back on and adjust wheel bearings and all brakes.	21/06/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Susp\SPRNG HANG	Cut out old wear plates and weld in boss. Grind up hanger and weld in new boss and wear plates. Fit spring back in and tension U Bolts.				21/06/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Tumut - Workshop	Brakes\BRK RELINE	reline three brakes				15/06/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job				14/06/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	VehService\DS	D service	VehService\DS			14/06/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job				31/05/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	VehService\DS	D Service	VehService\DS			31/05/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Albury - Workshop	Chassis\FIFTH WHEE	SLIDE LOCK NOT WORKING			SENT SLIDE LOCK VALVE TO ROSEWOOD TO FIT. ORDERED NEW VALVE	18/05/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER
T238	Albury - Workshop	Body\TRL FLOOR	bolts missing checker plate				18/05/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER
T238	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job				13/05/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	VehService\DS	A Service	VehService\DS			13/05/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Rosewood - Workshop	Tyres	Job Added From Invoice				29/04/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Tyres\FITMENT	Job Added From Invoice				29/04/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Tyres\RETREAD	Job Added From Invoice				29/04/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Tyres	Job Added From Invoice				29/04/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Tyres\FITMENT	Job Added From Invoice				29/04/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Tyres\RETREAD	Job Added From Invoice				29/04/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Tumut - Workshop	Brakes	Record Check Results				27/04/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	VehService\DS	Service	VehService\DS			27/04/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Rosewood - Workshop	Tyres	Job Added From Invoice				22/04/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Tyres\FITMENT	Job Added From Invoice				22/04/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Tyres\RETREAD	Job Added From Invoice				22/04/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job				11/04/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	Brakes\BRK RELINE	reline				11/04/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	VehService\DS	Service	VehService\DS			11/04/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS			11/04/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER
T238	Tumut - Workshop	Brakes\BRK RELINE	reline brakes				30/03/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	VehService\DS	Service	VehService\DS	please refer to 99458		29/03/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	VehService\DS	A Service	VehService\DS			29/03/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Rosewood - Workshop	Tyres\TP14	Job Added From Invoice				18/03/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Tumut - Workshop	VehService\DS	A Service Due	VehService\DS			16/03/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	VehService\DS	A Service	VehService\DS			04/03/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Rosewood - Workshop	Tyres\TP19	Job Added From Invoice				23/02/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Tumut - Workshop	VehService\DS	service	VehService\DS			14/02/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Rosewood - Workshop	Tyres\TP17	Job Added From Invoice				07/02/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Tumut - Workshop	Brakes\BRK RELINE	brake reline LHC new bearings				02/02/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	VehService\DS	Elphinestone trailer D service	VehService\DS	Snowy truck service 23-1-17		01/02/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Rosewood - Workshop	Tyres\TP15	Job Added From Invoice				28/01/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Tumut - Workshop	VehService\DS	Elphinestone trailer D service	VehService\DS	Snowy truck repairs 16-1-17		25/01/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Rosewood - Workshop	Tyres\TP13	Job Added From Invoice				21/01/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Tumut - Workshop	Brakes\BRK RELINE	reline brake x 1				19/01/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	VehService\DS	service	VehService\DS			17/01/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Rosewood - Workshop	Tyres\TP17	Job Added From Invoice				14/01/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Tumut - Workshop	Tyres\DAMAGE	Tyres low on air				14/01/2017	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	VehService\AS	A Service				13/01/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	Body\MUDGUARDS	c-lights not working on guards				13/01/2017	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	Brakes\BRAKE ADJ	brake adjust req				13/01/2017	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	VehService\DS	Elphinedstone trailer D service and replace spring eye bushes X 2rh rear and LH Center	VehService\DS	Snowy truck service 28-10-16		22/11/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Albury - Workshop	Elect\INDICATORS	LHS blinkers u/s		checked - working ok		18/11/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER
T238	Albury - Workshop	Brakes\AIR LEAK	air leak				18/11/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER
T238	Tumut - Workshop	Susp\SPRNG HANG	Eepair spring eye hanger and re bush spring		Snowy truck repairs 14-9-16		12/11/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Albury - Workshop	Brakes\BOOSTER	Remount LHF booster. Turn table wear plates and angels. Repair grease lines.				12/11/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER
T238	Albury - Workshop	Chassis\FIFTH WHEE	Repair air leak at slide lock valve.				12/11/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER
T238	Albury - Workshop	Body\CHN/RLR/MN	Idler bearings and umbilical arm bearings Tighten rear bar mount bolts and guard bolts. Replace rear load rollers.				12/11/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER
T238	Albury - Workshop	Body\MUDGUARDS	Weld mud guard. Replace SEB bolt. Tidy suspension air lines up.				12/11/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER
T238	Albury - Workshop	Susp\SUSPENSION	Weld cracked bosses and replace LM top shocker mount				12/11/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER
T238	Tumut - Workshop	VehService\DS	Elphinestone trailer D service	VehService\DS	Snowy truck service 8-9-16		12/11/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	Body\STCH GUARD	rempve and replace stretch guard		Snowy truck repairs 25-10-16		04/11/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	VehService\DS	Service	VehService\DS			29/10/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Rosewood - Workshop	Elect	No work lights				25/10/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Tumut - Workshop	Brakes\AIR LEAK	repair air leaks on booster hose		Snowy truck service 11-10-16		18/10/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Rosewood - Workshop	Tyres\TP19	Job Added From Invoice				14/10/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Body	replace broken dog (hold down)				30/09/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Tyres\TP21	Job Added From Invoice				24/09/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Tyres\TP22	Job Added From Invoice				13/09/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Tyres\TP22	Job Added From Invoice				13/09/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Tyres\TP22	Job Added From Invoice				13/09/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Tyres\TP22	Job Added From Invoice				13/09/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Tumut - Workshop	Body\MUDGUARDS	straighten mud guard of wheel and repair tye down chain		Snowy truck service 6-9-16		09/09/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job				09/09/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			09/09/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	Brakes\BRK RELINE	replace brakes and bearings LHF				01/09/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	Chassis\BOLSTER	replace 2 bolsters and air valve				01/09/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	VehService\DS	Elpinestone trailer D service	VehService\DS	Snowy truck service 24-8-16		31/08/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Rosewood - Workshop	Body	replaced RHF shock absorber				30/08/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Albury - Workshop	Body\CHN/RLR/MN	supply load chain				30/08/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER
T238	Tumut - Workshop	Elect\ELECT P&W	replace tail lights		tumut w/shop		25/08/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job				25/08/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			25/08/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	VehService\DS	Elphinestone trailer D service & repair air leak	VehService\DS	Snowy truck service 3-8-16		24/08/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Rosewood - Workshop	Body	front winch has no handle				23/08/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Body	air leak				23/08/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job				13/08/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			13/08/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job				12/08/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			12/08/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Rosewood - Workshop	VehService	A Service (900k off). A Service (900km off)				11/08/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Elect	clearance light broken R/H front guard				11/08/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Tumut - Workshop	Brakes\BRAKE ADJ	Adjust brakes		completed by snowy trucks on the 1st August		05/08/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Rosewood - Workshop	Body	turntable grease lines need replacing				04/08/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Tumut - Workshop	VehService\DS	D service on Ephinstone trailer	VehService\DS	completed by Snowy truck service on the 19th july		27/07/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job				20/07/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	Repaired air leak		20/07/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	Tyres	LHF RHF LHC RHC LHR RHR				19/07/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	Brakes	needs new brakes				19/07/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	Tyres	RHC flat tyre				19/07/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	VehService\DS	D service on Elphinestone trailer	VehService\DS	completed by snowy trucks service on the 21 june		24/06/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job				22/06/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			22/06/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	VehService	D Service				22/06/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	Brakes\AIR LEAK	Find air leak and repair with hose joiner (supplied by G/F)		Comp-leted by snowy trucks on the 10 june by Tom Moute		21/06/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	VehService\DS	D Service Elphinestone trailer doubled up work order	VehService\DS	Completed by snowy truck service on the 9th of june by Tom Moute		21/06/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	VehService\DS	D service Elphinestone Trailer	VehService\DS	Completed nby snowy truck service on the 9-6-16 by Tom moute		17/06/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	Brakes\AIR LEAK	repaire brake booster hose		snowy Truck service 20-6-16		16/06/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job				10/06/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			10/06/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job				28/05/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			28/05/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Tyres\TP21	Job Added From Invoice				20/05/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Tyres\TP21	Job Added From Invoice				20/05/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Tyres\TP22	Job Added From Invoice				20/05/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Tyres\TP22	Job Added From Invoice				20/05/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Tyres\TP22	Job Added From Invoice				20/05/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job				18/05/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			18/05/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Tyres\TP20	Job Added From Invoice				14/05/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER

T238	Rosewood - Workshop	Tyres\TP20	Job Added From Invoice				14/05/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Tyres\TP20	Job Added From Invoice				14/05/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Tyres\TP19	Job Added From Invoice				29/04/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Tyres\TP19	Job Added From Invoice				29/04/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Tyres\TP19	Job Added From Invoice				29/04/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Tumut - Workshop	Elect\ELECT P&W	rewire trailer lights				27/04/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job				20/04/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Susp\SUSPENSION	tighten suspension				20/04/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Susp\SUSPENSION	weld up cracks				20/04/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Susp\SUSPENSION	replace height control valve				20/04/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Susp\SUSPENSION	tighten bolster pivot				20/04/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			20/04/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Tumut - Workshop	Brakes\BRK O/HAUL	replace bpw eco hub				20/04/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Tyres\TP21	Job Added From Invoice				16/04/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Tyres\TP21	Job Added From Invoice				16/04/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Tyres\TP21	Job Added From Invoice				16/04/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Chassis\CROSS MBR	welded up new spare wheel brase				16/04/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	VehService\BS	B Service due				13/04/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Body\LIGHTS	blinkers left hand side				23/03/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Body\LIGHTS	blinkers not working again				19/03/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Tumut - Workshop	Brakes\BRK RELINE	reline brake and replace air bagsx2				17/03/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job				16/03/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Chassis\RWC COMP	repair defect list				16/03/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Brakes\BRK RELINE	reline R/H/M				16/03/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			16/03/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Tumut - Workshop	Comp\ANN INSP	clear defect				16/03/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Tyres\TP11	Job Added From Invoice				11/03/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Tyres\TP11	Job Added From Invoice				11/03/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Tyres\TP11	Job Added From Invoice				11/03/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Tyres\TP13	Job Added From Invoice				08/03/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Tyres\TP13	Job Added From Invoice				08/03/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Tyres\TP13	Job Added From Invoice				08/03/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Tyres\TP11	Job Added From Invoice				01/03/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Tyres\TP11	Job Added From Invoice				01/03/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Tyres\TP11	Job Added From Invoice				01/03/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Tyres\TP13	Job Added From Invoice				01/03/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Tyres\TP13	Job Added From Invoice				01/03/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Tyres\TP13	Job Added From Invoice				01/03/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Chassis\AIR LEAK	repair air leaks				24/02/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job				24/02/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			24/02/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Tyres\TP15	Job Added From Invoice				20/02/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job				06/02/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Body\MUDGUARDS	fix mudflaps				06/02/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			06/02/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Body\MUDGUARDS	RHS mudguard bracket cracked				02/02/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Susp\SUSPENSION	replace 2 spring/wrap				24/01/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Steering\WHEEL BRGS	adjusted left hand side wheel bearings				24/01/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Chassis\BOLSTER	turn bolsters				24/01/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Susp\HCV	replace air bag valve				24/01/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Tyres\TP12	Job Added From Invoice				23/01/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job				17/01/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			17/01/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Elect\TAIL LIGHT	replace lh tail light				15/01/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Body\MUDGUARDS	replace lh mudguard				15/01/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Elect\WORK LIGHT	work lights not working				15/01/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job				08/01/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	VehService\DS	D Service As Per Attached Checklist bearings + lights	VehService\DS			08/01/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Elect\TRL LIGHTS	tctc rollers/chain guides		COMPLETED		18/12/2015	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Body\MOUNTS	elphinstone reline+suspension		complete		18/12/2015	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Brakes\BRK RELINE	tctc bolster		COMPLETED		11/12/2015	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Chassis\BOLSTER	elphinstone bolster		COMPLETEd		09/12/2015	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Chassis\BOLSTER	elphinstone		completed		08/12/2015	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			05/12/2015	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job				05/12/2015	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Tyres\TP21	Job Added From Invoice				04/12/2015	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Tyres\TP21	Job Added From Invoice				04/12/2015	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Tyres\TP21	Job Added From Invoice				04/12/2015	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				25/11/2015	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER
T238	Albury - Workshop	Elect	repair lh side light				25/11/2015	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER
T238	Albury - Workshop	Susp	spring wrap broken lhm				25/11/2015	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER
T238	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			25/11/2015	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER
T238	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				17/11/2015	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER
T238	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			17/11/2015	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER
T238	Rosewood - Workshop	Elect	scales don't work				14/11/2015	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Insp\UNT INSP	Roadworthy				29/10/2015	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Body\LIGHTS	rh reverse light lense, clearance light on lh mudguard. rh reverse light lense, clearnace light on lh mudguard				28/10/2015	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job				22/10/2015	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			22/10/2015	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Body\MOUNTS	bolster wear pads elphinstone		completed		14/10/2015	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Albury - Workshop	Chassis\KING PIN	Job Added From Invoice				09/10/2015	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Albury Workshop	TRAILER
T238	Rosewood - Workshop	Chassis\SUSPENSION	Job Added From Invoice				07/10/2015	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Comp\DAMAGE	Job Added From Invoice				07/10/2015	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Susp\AIR FITTIN	Job Added From Invoice				01/10/2015	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Myrtleford - Workshop	Comp\ANN INSP	rego check trailer		completed		26/09/2015	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Myrtleford Workshop	TRAILER
T238	Rosewood - Workshop	Tyres\TP12	Job Added From Invoice				19/09/2015	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Chassis\AIR LEAK	air leak under turntable				15/09/2015	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Wodonga - Workshop	Chassis	cut links out of load chain				11/09/2015	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Wodonga Workshop	TRAILER
T238	Wodonga - Workshop	Susp	replace HCV				11/09/2015	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Wodonga Workshop	TRAILER
T238	Unknown - Unknown	Engine\BOOST HOSE	Service Job Added From Invoice				08/09/2015	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Tumut - Workshop	Brakes\BRK O/HAUL	Service Job Added From Invoice				08/09/2015	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Tumut Workshop	TRAILER
T238	Unknown - Unknown	Body\MOUNTS	Service Job Added From Invoice				08/09/2015	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			08/09/2015	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job				08/09/2015	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Chassis\AIR LEAK	lh middle axle booster broken, middle regulator leaking air				05/09/2015	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER
T238	Rosewood - Workshop	Brakes\BRK RELINE	remove wheels to reline rhr brakes and inspect and clean bearings				29/08/2015	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Tumut	TTK	TB65FK	Rosewood Workshop	TRAILER