EquipmentName	Workshop	CodeAndSubCode	Description	Schedule	CompletionComments	DateDone	DistanceDone	Worktype	Workstate	EquipmentOwner	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
			Job Created from Purchase Order #: 104683													
T378	Myrtleford - Workshop	Brakes\AIR FITTIN	SUPPLY AIR FITTING			14/03/2025	11570	Service	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	OT DIESEL SERVICES - 3	TRAILER
T378	Myrtleford - Workshop	Tyres\TP9-10	Replace Tyres On Positions 9+10. (Goodyear Auto Care Colac P/O: L090153)			11/11/2024	11570	Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	BEAUREPAIRES - 3	TRAILER
T378	Myrtleford - Workshop	Tyres\RUN OUT	Tyres\RUN OUT pos 5			27/09/2024	11570	Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	BEAUREPAIRES - 3	TRAILER
T378	Myrtleford - Workshop	VehService\DS	VehService\DS	VehService\DS		14/09/2024	11570	Service	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	MINI DIESEL - 3	TRAILER
T378	Myrtleford - Workshop	Chassis\BOLSTER	MOVE BINDER & BOLSTER FORWARD			18/08/2024	11570	Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	JF MECHANICALS - 3	TRAILER
			Chassis\SCALES													
			Greenfreight Logging, 29 July 2024, CH2 reading high on tare &													
			loaded, Elphinstone Trailer VIN #6L9T2SDD82EL01888, Rego #37681-													
			S, Fleet #T378.													
			Repairs: unload trailer, check A/T cable, replace cable and filter, reset													
T378	Myrtleford - Workshop	Chassis\SCALES	tare. reload trailer and check scales.			02/08/2024	11570	Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	ELPHINSTONE ENGINEERING - 3	TRAILER
T378	Myrtleford - Workshop	Tyres\TP1-2	Tyres\TP1-2			02/08/2024	11570	Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	BEAUREPAIRES - 3	TRAILER
T378	Myrtleford - Workshop	Tyres\TP3-4	Tyres\TP3-4			30/07/2024	11570	Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	BEAUREPAIRES - 3	TRAILER
T378	Myrtleford - Workshop	Tyres\TP1-2	Tyres\TP1-45			27/06/2024	11570	Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	BEAUREPAIRES - 3	TRAILER
T378	Myrtleford - Workshop	VehService\DS	VehService\DS	VehService\DS		19/06/2024	11570	Service	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	QT DIESEL SERVICES - 3	TRAILER
T378	Myrtleford - Workshop	VehService\DS	VehService\DS POH 1048260	VehService\DS		05/06/2024	11570	Service	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	QT DIESEL SERVICES - 3	TRAILER
T378	Myrtleford - Workshop	VehService\DS	VehService\DS	VehService\DS		01/06/2024	11570	Service	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	QT DIESEL SERVICES - 3	TRAILER
T378	Myrtleford - Workshop	Elect\TAIL LIGHT	Elect\TAIL LIGHT REPAIR WIRING IN T/LIGHT BAR			31/05/2024	11570	Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	QT DIESEL SERVICES - 3	TRAILER
T378	Myrtleford - Workshop	Chassis\WINCH/STRP	REPLACE FRONT AIR WINCH FIT C/OVER UNIT & TEST			27/05/2024	11570	Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	JF MECHANICALS - 3	TRAILER
T378	Myrtleford - Workshop	Tyres\TP9-10	Tyres\TP9-10			24/05/2024	11570	Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	BEAUREPAIRES - 3	TRAILER
T378	Myrtleford - Workshop	Tyres\TP11+12	Tyres\TP11+12			24/05/2024	11570	Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	BEAUREPAIRES - 3	TRAILER
T378	Wodonga - Workshop	Tyres\TP7-8	Tyres\TP7-8			21/05/2024	11570	Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Tyres\ROTATION	Tyres\ROTATION			21/05/2024	11570	Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Myrtleford - Workshop	Tyres\TP07	Tyres\TP07			21/05/2024	11570	Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	BEAUREPAIRES - 3	TRAILER
T378	Myrtleford - Workshop	Elect\ELECT P&W	Repair wiring on light bar			21/05/2024	11570	Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	QT DIESEL SERVICES - 3	TRAILER
			Service As Per Attached Checklis													
T378	Myrtleford - Workshop	VehService\DS	POH LBE5499		REPAIRED RF CLEARANCE LIGHT. LH PARK LIGHTS AND MIDDLE HANGER. WELDED WEAR PLATES.	27/04/2024		Service	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	QT DIESEL SERVICES - 3	TRAILER
T378	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This.Iob			27/04/2024		Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	QT DIESEL SERVICES - 3	TRAILER
T378	Myrtleford - Workshop	Tyres\TP7-8	REPLACE RM TYRE.			27/04/2024		Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	QT DIESEL SERVICES - 3	TRAILER
T378	Myrtleford - Workshop	Susp\AIR BAG	FIT NEW AIR BAG LHR			22/03/2024		Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	QT DIESEL SERVICES - 3	TRAILER
T378	Myrtleford - Workshop	Susp\HCV	FIT NEW RIDE HEIGHT CONTROL VALVE			22/03/2024		Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	QT DIESEL SERVICES - 3	TRAILER
			Service As Per Attached Checklist													
T378	Myrtleford - Workshop	VehService\DS	POH LBE4915			22/03/2024		Service	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	QT DIESEL SERVICES - 3	TRAILER
T378	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This.Iob			22/03/2024		Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	QT DIESEL SERVICES - 3	TRAILER
T378	Wodonga - Workshop	Brakes\EBS Kit	replace broken EBS test plug			22/03/2024		Fault	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Myrtleford - Workshop	Elect\INDICATORS	REPLACE LH INDICATOR			13/03/2024		Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	QT DIESEL SERVICES - 3	TRAILER
					fit new stop light to LHR											
			Service As Per Attached Checklist		Fit new reverse light to LHR											
T378	Myrtleford - Workshop	VehService\DS	POH LBE4624		Fit new clearance lahts to LHR	07/03/2024		Service	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	QT DIESEL SERVICES - 3	TRAILER
T378	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This.Iob			07/03/2024		Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	QT DIESEL SERVICES - 3	TRAILER
T378	Myrtleford - Workshop	Elect\ELECT P&W	repair wiring fault			07/03/2024		Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	QT DIESEL SERVICES - 3	TRAILER
T378	Myrtleford - Workshop	Tyres\TP1-2	Tyre Position 1 + 2			28/02/2024		Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Albury Workshop	TRAILER
T378	Myrtleford - Workshop	Tyres\TP3-4	Tyre Position 3 + 4			28/02/2024		Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Albury Workshop	TRAILER
T378	Myrtleford - Workshop	Body\HOUSEKEEP	secure zebra signs			08/02/2024		Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	QT DIESEL SERVICES - 3	TRAILER
T378	Myrtleford - Workshop	Elect\TAIL LIGHTS	SECURE REVERSE LIGHTS ON TAIL BOARD, REPLACE NUMBER PLATE LIGHT			08/02/2024		Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	QT DIESEL SERVICES - 3	TRAILER
T378	Myrtleford - Workshop	Steering\WHEEL ALIGN	Wheel Alignment			07/02/2024		Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	BIG WHEELS TRUCK ALIGNMENT - 3	TRAILER
T378	Myrtleford - Workshop	Susp\Torque Rod	Remove and replace all 6 eye bushes			07/02/2024		Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	BIG WHEELS TRUCK ALIGNMENT - 3	TRAILER
T378	Myrtleford - Workshop	Brakes\BOOSTER	REPAIR AIR LEAK IN BRAKE BOOSTER			18/01/2024		Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Albury Workshop	TRAILER
T378	Myrtleford - Workshop	Tyres\TP1-2	Tyre Position 1 + 2			18/01/2024		Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Albury Workshop	TRAILER
T378	Myrtleford - Workshop	Elect\TAIL LIGHTS	LOACTE AND REPAIR TAIL LIGHT WIRING ON LHR			17/01/2024		Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Albury Workshop	TRAILER
T378	Myrtleford - Workshop	Body\CHN/RUB/MN	repair broken load dog			10/01/2024		Fault	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER
T378	Wodonga - Workshop	Chassis\HOUSEKEEP	Fit Cab Rack & Rewire Cab Rack Lights			09/01/2024		Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Chassis\STRAPS	FIND & COLLECT PARTS FOR CABGUARD.			03/01/2024		Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Brakes\BRK RELINE	FULL RELINE.		REPLACED ALL S-CAM BUSHES AND WHEEL SENSORS.	28/12/2023		Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Susp\AXLES	REPLACED LR LOWER AXLE PLATE, U-BOLTS AND RF LF AIRBAGS. REPAIRED HCV BODS.			28/12/2023		Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Chassis\STRAPS	FIT LOG RACK. REMOVED OLD BOLTS WITH OXY. WELDED CRACKED MUDGUARD AND HANGER. REPLACED STRAPS.			28/12/2023		Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Chassis\FIFTH WHEE	REPLACED DOGBONE IN TURNTABLE.			28/12/2023		Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Elect\ELECT P&W	REPAIRED WIRING TO TAIL LIGHTS AND SIDE MARKER.			28/12/2023		Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Rosewood - Workshop	Workshop\ABOVE ASSET	UN HOOKED 1001. TRAVELLED TO TCTC. PICKED UP TRAILERS. PRESSURE WASHED TRAILERS FOR REPAIRS. TRAVELLED TO ROSEWOOD. PICKING UP TOOLS ON THE WAY. INSPECTED AND LISTED REPAIRS REQUIRD			28/12/2023		Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			28/12/2023		Service	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Brakes	Record Check Results As Attached To This.Iob			28/12/2023		Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection	Insp\ANN INSP-deactivated 15/5/2024 3:43:44 am utc		28/12/2023		PreventativeMaintenance	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Susp\AIR BAG	LEAKING AIRBAG LHR AROUND THE TOP.			02/12/2023		Fault	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			13/11/2023	11570	Service	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Brakes	Record Check Results As Attached To This.Iob			13/11/2023	11570	Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Elect\ELECT P&W	NO SCALES ON TRAILER.			13/11/2023	11570	Fault	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Susp\AIR LEAK	Air Leak Left Rear Air Bag			13/11/2023	11570	Fault	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
			Service As Per Attached Checklist (TCTC)													
T378	Albury - Workshop	VehService\DS	Purchase Order Number: TOB0895			09/09/2023		Service	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Albury - Workshop	Brakes	Record Check Results As Attached To This.Iob			09/09/2023		Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Albury - Workshop	Elect\ELECT P&W	NO SCALES ON TRAILER.			09/09/2023		Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Albury - Workshop	Tyres\PRES CHECK	1-12			07/09/2023		Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Albury Workshop	TRAILER
T378	Albury - Workshop	Brakes	Record Check Results As Attached To This.Iob			05/09/2023	11570	Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
			Service As Per Attached Checklist (TCTC)													
T378	Albury - Workshop	VehService\DS	Purchase Order Number: TOB0789			05/09/2023	11570	Service	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Albury - Workshop	Chassis\FIFTH WHEE	TURNTABLE SLIDE-LOCK STICKING.			05/09/2023	11570	Fault	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Albury - Workshop	Tyres\RUN OUT	4			29/08/2023		Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Albury Workshop	TRAILER
T378	Wodonga - Workshop	Elect\TAIL LIGHT	RH TAIL LIGHT NOT WORKING.			25/08/2023		Fault	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Chassis\STRAPS	REPLACE TIE DOWN DOG AND FIX BROKEN CHAIN.			25/08/2023		Fault	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Elect\TAIL LIGHT	R/H TAIL LIGHT.			25/08/2023		Fault	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Brakes\AIR LEAK	REPAIR BOOSTER AIR LINE.			25/08/2023		Fault	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Brakes\VALVES	Replaced Mast Valve @ 1st Air Tank			25/08/2023		Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Elect\INDICATORS	No RH Indicator		CLEANEDOUT PLUG AND SOCKET. REPAIRTED WIRING TO RH INDICATOR.	25/08/2023		Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Elect\TAIL LIGHT	R/H TAIL LIGHT.			25/08/2023		Fault	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Elect\INDICATORS	R/H BLINKERS NOT WORKING.			25/08/2023		Fault	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Brakes\VALVES	RELAY VALVE 1ST AIR TANK R/S PLEASE REPLACE.			25/08/2023		Fault	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
			Service As Per Attached Checklist (TCTC)													
T378	Albury - Workshop	VehService\DS	Purchase Order Number: TOB0223			11/08/2023	11570	Service	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Albury - Workshop	Brakes	Record Check Results As Attached To This.Iob			11/08/2023	11570	Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Albury - Workshop	Chassis\WINCH/STRP	Winches & Straps			09/08/2023		Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Albury Workshop	TRAILER
T378	Albury - Workshop	Tyres\TP3-4	Tyre Position 3 + 4			04/08/2023		Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Albury Workshop	TRAILER
T378	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			02/08/2023		Service	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Brakes	Record Check Results As Attached To This.Iob			02/08/2023		Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Elect\TAIL LIGHT	RH TAIL LIGHT NOT WORKING.			02/08/2023		Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Chassis\STRAPS	REPLACE TIE DOWN DOG AND FIX BROKEN CHAIN.			02/08/2023		Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			25/07/2023	11570	Service	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Brakes	Record Check Results As Attached To This.Iob			25/07/2023	11570	Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Tyres\TP10	LR INNER TYRE NEEDS REPLACING TODAY.			25/07/2023	11570	Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Chassis\SPAREWHEEL	SPARE WHEEL CARRIER CRACKED.			25/07/2023	11570	Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Elect\WORK LIGHT	NO WORK LIGHTS.			25/07/2023	11570	Fault	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Chassis\EXTE TU	2ND BINDER WON'T RELEASE.			25/07/2023	11570	Fault	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Susp\SHOCK ABS	FRONT L/H SHOCKER.			25/07/2023	11570	Fault	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
			Repair Electrical Fault (Hagan's)													
T378	Albury - Workshop	Elect\BRK LIGHT	Purchase Order Number: TOT9808			25/07/2023	11570	Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			19/07/2023		Service	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Brakes	Record Check Results As Attached To This.Iob			19/07/2023		Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Brakes\EBS FAULTS	EBS PULLING ON.			19/07/2023		Fault	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Elect\ELECT P&W	SCALES NOT WORK/ FAULT.			19/07/2023		Fault	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Elect\ELECT P&W	SCALES PERFORMING ERRATICALLY.			19/07/2023		Fault	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Elect\WORK LIGHT	WORK LIGHTS NOT WORKING.			19/07/2023		Fault	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Chassis\EXTE TU	2ND WINCH JAMMING UNDER LOAD.			15/07/2023		Fault	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Susp\SHOCK ABS	BOLT MISSING IN FRONT PASSENGER SIDE SHOCK ABSORBER.		REPLACED SHOCK, STRAP, TOP BOLT AND RETAINERS.	15/07/2023		Fault	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Elect\ELECT P&W	LIGHTS SHORTED OUT- BLINKERS @ BRAKE LIGHTS.		FOUND WATER IN LH TAIL LIGHT OF 1011. FOUND LH PARK, INDICATOR AND RH INDICATOR WIRES BROKEN.	28/06/2023		Fault	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			23/06/2023		Service	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Brakes	Record Check Results As Attached To This.Iob			23/06/2023		Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Tyres\TP10	LR INNER TYRE NEEDS REPLACING TODAY.			23/06/2023		Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Chassis\WINCH/STRP	MISSING 1ST & 3RD QUICK RELEASE CABLE.			23/06/2023		Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Chassis\SPAREWHEEL	SPARE WHEEL CARRIER CRACKED.			23/06/2023		Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Hydraulics\HOSES	HYDRAULIC LINES RUBBING THROUGH AT UMBILICAL ARM.			23/06/2023		Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Brakes\EBS FAULTS	EBS PULLING ON.			23/06/2023		Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Elect\ELECT P&W	SCALES NOT WORK/ FAULT.			23/06/2023		Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Chassis\EXTE TU	1ST BINDER CAUGHT UP AFTER ROO HIT CTI AND BINDER.			23/06/2023		Fault	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Chassis\EXTE TU	FRONT WINCH NEEDS REPLACING.			23/06/2023		Fault	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Chassis\FIFTH WHEE	CHAIN ON GYPSY COG MAKING LOTS OF CRUNCHING NOISES.			23/06/2023		Fault	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Elect\TAIL LIGHT	REAR PARKER LIGHTS NOT WORKING. (SEE SHAUN ABOUT IT)			23/06/2023		Fault	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Elect\WORK LIGHT	LOADING LIGHT ON LEFT SIDE NOT WORKING.			23/06/2023		Fault	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Elect\WORK LIGHT	LEFT HAND LOADING LIGHT NEED FIXING AS PER R&R #128629.			23/06/2023		Fault	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Susp\HCV	Replaced HCV & Adjusted height.			23/06/2023		Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist			17/06/2023		Service	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Brakes	Record Check Results As Attached To This.Iob			17/06/2023		Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Chassis\STRAPS	Replace Quick Release Cable			17/06/2023		Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Brakes\BRK RELINE	Brake Reline			17/06/2023		Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Albury - Workshop	Tyres\TP11	Tyre Position 1			09/06/2023		Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Albury Workshop	TRAILER
T378	Albury - Workshop	Tyres\TP3-4	Tyre Position 3 + 4			09/06/2023		Repair	Completed	Greenfreight Logging Vic	ElpidiPW	Mt Gambier	GTK	376815	Albury Workshop	TR

			CHECK LIGHTS N/W												
			TRAVEL TO GREENFREIGHTS YARD												
			test and found park lights shorting out												
			test and found short in A-trailer rear bar												
			remove lights and found burnt out wiring												
			remove and replace faulty wiring												
			test and found all lights working fine												
T378	Albury - Workshop	Elect/TRL LIGHTS	pack us and travel back		09/05/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Albury Workshop	TRAILER
T378	Albury - Workshop	Tyres/TP1+2	Tyre Position 1 + 2		03/05/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Albury Workshop	TRAILER
T378	Albury - Workshop	Tyres/TP5+6	Tyre Position 5 + 6		03/05/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Albury Workshop	TRAILER
T378	Wodonga - Workshop	VehService/DS	Service As Per Attached Checklist		03/05/2023	Service	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		03/05/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Brakes/EBS FAULTS	EBS PULLING ON.		03/05/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Tyres/TP10	LR INNER TYRE NEEDS REPLACING TODAY.		03/05/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Susp/SPRING HANG	RR SPRING HANGER BADLY CRACKED.		03/05/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Chassis/BOLSTER	REPLACE BOLSTER WEAR PADS.		03/05/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Elect/ELECT P&W	REPAIRED BROKEN WIRING ON LR. TESTED. OK.		22/04/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	VehService/DS	Service As Per Attached Checklist		21/04/2023	Service	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		21/04/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Brakes/BRK RELINE	RELINE LF LM.		21/04/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Chassis/WINCH/STRP	MISSING 1ST & 3RD QUICK RELEASE CABLE.		21/04/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Chassis/BOLSTER	Repair Cracks In Bolsters		21/04/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Hydraulics/HOSES	HYDRAULIC LINES RUBBING THROUGH AT UMBILICAL ARM.		21/04/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Chassis/SPAREWHEEL	SPARE WHEEL CARRIER CRACKED.		21/04/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Elect/ELECT P&W	SCALES NOT WORK/ FAULT.		21/04/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Chassis/WINCH/STRP	STRAPS NEED REPLACING.		21/04/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Elect/TAIL LIGHT	LH1 TAIL LIGHT BROKEN WIRE.		21/04/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Chassis/EXTE TU	1ST BINDER CAUGHT UP AFTER ROO HIT CTI AND BINDER.		21/04/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
				CRACK TEST BOLSTER PEGS AS REQUIRED											
				NO CRACKS FOUND											
T378	Wodonga - Workshop	Chassis/BOLSTER	Repair Cracks In Bolsters	REFIT PEGS WITH NEW BOLTS AS REQUIRED	21/04/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
			CHECK WORK LIGHTS N/W												
			CALLOUT AFTER HOURS												
			TRAVEL TO JOB												
			test and found working lights working could not fault												
			remove and replace x2 work lights as some LED's not working												
T378	Albury - Workshop	Elect/WORK LIGHT	test and found all ok pack up and travel back		12/04/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Albury Workshop	TRAILER
T378	Wodonga - Workshop	VehService/DS	Service As Per Attached Checklist		12/04/2023	Service	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		12/04/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Brakes/BRK RELINE	RELINE LF LM.		12/04/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Chassis/WINCH/STRP	MISSING 1ST & 3RD QUICK RELEASE CABLE.		12/04/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Chassis/BOLSTER	Repair Cracks In Bolsters		12/04/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Brakes/EBS FAULTS	EBS PULLING ON.		12/04/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Elect/ELECT P&W	SCALES NOT WORK/ FAULT.		12/04/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Chassis/WINCH/STRP	STRAPS NEED REPLACING.		12/04/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Elect/TAIL LIGHT	LH1 TAIL LIGHT BROKEN WIRE.		12/04/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Chassis/EXTE TU	1ST BINDER CAUGHT UP AFTER ROO HIT CTI AND BINDER.		12/04/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Chassis/SPAREWHEEL	SPARE WHEEL CARRIER CRACKED.		12/04/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Hydraulics/HOSES	HYDRAULIC LINES RUBBING THROUGH AT UMBILICAL ARM.		12/04/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Albury - Workshop	Tyres/TP11+12	Tyre Position 11 + 12		05/04/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Albury Workshop	TRAILER
T378	Wodonga - Workshop	VehService/DS	Service As Per Attached Checklist		05/04/2023	Service	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		05/04/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Chassis/CROSS MBR	CRACKED 5TH CROSSMEMBER.		05/04/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Chassis/WINCH/STRP	MISSING 1ST & 3RD QUICK RELEASE CABLE.		05/04/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Elect/ELECT P&W	SCALES NOT WORK/ FAULT.		05/04/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Chassis/WINCH/STRP	STRAPS NEED REPLACING.		05/04/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Elect/TAIL LIGHT	LH1 TAIL LIGHT BROKEN WIRE.		05/04/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Chassis/EXTE TU	1ST BINDER CAUGHT UP AFTER ROO HIT CTI AND BINDER.		05/04/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Chassis/BOLSTER	Repair Cracks In Bolsters		05/04/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Brakes/BRK RELINE	RELINE LF LM.		05/04/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Chassis/CROSS MBR	CRACKED 5TH CROSSMEMBER.		04/04/2023 11570	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Chassis/BOLSTER	Bolster Crack Repairs		04/04/2023 11570	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Chassis/SPAREWHEEL	CRACK BEHIND RHS SPARE.		04/04/2023 11570	Fault	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	VehService/DS	Service As Per Attached Checklist	REPAIRED RR WIRING FOR CLEARANCE LIGHT & INDICATOR.	29/03/2023	Service	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		29/03/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Chassis/WINCH/STRP	MISSING 1ST & 3RD QUICK RELEASE CABLE.		29/03/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Chassis/SPAREWHEEL	CRACK BEHIND RHS SPARE.		29/03/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Brakes/EBS FAULTS	EBS PULLING ON.		29/03/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Elect/ELECT P&W	SCALES NOT WORK/ FAULT.		29/03/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Chassis/WINCH/STRP	STRAPS NEED REPLACING.		29/03/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Elect/TAIL LIGHT	LH1 TAIL LIGHT BROKEN WIRE.		29/03/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Chassis/EXTE TU	1ST BINDER CAUGHT UP AFTER ROO HIT CTI AND BINDER.		29/03/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Elect/ELECT P&W	NO TRAILER LIGHTS		29/03/2023	Fault	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	VehService/DS	Service As Per Attached Checklist	REPLACED BRAKE LINE ON REAR AXLE.	18/03/2023	Service	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		18/03/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Chassis/WINCH/STRP	MISSING 1ST & 3RD QUICK RELEASE CABLE.		18/03/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Elect/ELECT P&W	SCALES NOT WORK/ FAULT.		18/03/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Chassis/WINCH/STRP	STRAPS NEED REPLACING.		18/03/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Elect/TAIL LIGHT	LH1 TAIL LIGHT BROKEN WIRE.		18/03/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Chassis/EXTE TU	1ST BINDER CAUGHT UP AFTER ROO HIT CTI AND BINDER.		18/03/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Elect/ELECT P&W	NO TRAILER LIGHTS		18/03/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Albury - Workshop	Tyres/TP7+8	runouts		18/03/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Albury Workshop	TRAILER
T378	Wodonga - Workshop	VehService/DS	Service As Per Attached Checklist	REPAIRED LH INDICATOR.	11/03/2023	Service	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		11/03/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	VehService/DS	Service As Per Attached Checklist		04/03/2023	Service	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		04/03/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
			TRAVEL TO JOB.												
			CHECK AND FOUND PARK LIGHTS SHORTING TO BRAKE AND FLASHERS.												
			INSPECT WIRING AND TRACE SHORT												
			LOCATE AND REPAIR SHORT AS REQUIRED												
T378	Albury - Workshop	Elect/TRL LIGHTS	TEST OPERATION ALL OK		02/03/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Albury Workshop	TRAILER
T378	Albury - Workshop	Tyres/TP9+10	Tyre Position 9 + 10		23/02/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Albury Workshop	TRAILER
T378	Wodonga - Workshop	VehService/DS	Service As Per Attached Checklist		17/02/2023	Service	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		17/02/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Chassis/WINCH/STRP	Replace Winch Straps		17/02/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	VehService/DS	Service As Per Attached Checklist	TURNED BOLSTER PEGS.	07/02/2023 11570	Service	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		07/02/2023 11570	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Chassis/CROSS MBR	CRACKED 5TH CROSSMEMBER.		07/02/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Chassis/WINCH/STRP	MISSING 1ST & 3RD QUICK RELEASE CABLE.		07/02/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Chassis/FIFTH WHEE	FRONT UMBILICAL ARM BEARINGS WORN.		07/02/2023 11570	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Body/MUDGUARDS	REPLACE CRACKED RH GUARD.		07/02/2023 11570	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Chassis/SPAREWHEEL	CRACK BEHIND RHS SPARE.		07/02/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Brakes/EBS FAULTS	EBS PULLING ON.		07/02/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Elect/ELECT P&W	NO TRAILER LIGHTS.		07/02/2023 11570	Fault	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Elect/ELECT P&W	SCALES NOT WORK/ FAULT.	COULDN'T FAULT.	07/02/2023 11570	Fault	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Albury - Workshop	Tyres/TP3+4	Tyre Position 3 + 4		01/02/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Albury Workshop	TRAILER
T378	Wodonga - Workshop	OnCab/Repl/AIR CON	CABIN FIRE CONTAINED TO LH DOG BOX STARTED BY COOLABAH COOLER.	RANG AROUND SYDNEY FOR REPAIRER TO GO AND ISOLATE COOLER. GILBERT AND RANCH AUTO ELEC ISOLOATED COOLER.	26/01/2023 11570	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	VehService/DS	Service As Per Attached Checklist		26/01/2023 11570	Service	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		26/01/2023 11570	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Chassis/CROSS MBR	CRACKED 5TH CROSSMEMBER.		26/01/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Chassis/WINCH/STRP	MISSING 1ST & 3RD QUICK RELEASE CABLE.		26/01/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Chassis/FIFTH WHEE	FRONT UMBILICAL ARM BEARINGS WORN.		26/01/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Chassis/SPAREWHEEL	CRACK BEHIND RHS SPARE.		26/01/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Brakes/EBS FAULTS	EBS PULLING ON.		26/01/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Body/MUDGUARDS	REPLACE CRACKED RH GUARD.		26/01/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Elect/INDICATORS	REPAIRED BROKEN EARTH FOR INDICATORS.		19/01/2023 11570	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Elect/WORK LIGHT	WORK LIGHTS.		10/01/2023 11570	Fault	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Chassis/CROSS MBR	CRACKED 5TH CROSSMEMBER.		10/01/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Chassis/WINCH/STRP	MISSING 1ST & 3RD QUICK RELEASE CABLE.		10/01/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Chassis/FIFTH WHEE	FRONT UMBILICAL ARM BEARINGS WORN.		10/01/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Chassis/SPAREWHEEL	CRACK BEHIND RHS SPARE.		10/01/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Brakes/EBS FAULTS	EBS PULLING ON.		10/01/2023	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Elect/TRL LIGHTS	Park Lights coming on When Brakes Applied, Brakes Lights Coming On When Park Lights Are Turned On	REPLACED LIGHT SOCKET. REPAIRED WIRING.	10/01/2023 11570	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Albury - Workshop	Tyres/TP7+8	Tyre Position 7 + 8		10/01/2023 11570	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Albury Workshop	TRAILER
T378	Albury - Workshop	Tyres/TP11+12	Tyre Position 11 + 12		10/01/2023 11570	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Albury Workshop	TRAILER
T378	Wodonga - Workshop	VehService/DS	Service As Per Attached Checklist		23/12/2022	Service	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		23/12/2022	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Chassis/CROSS MBR	CRACKED 5TH CROSSMEMBER.		23/12/2022	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Chassis/WINCH/STRP	MISSING 1ST & 3RD QUICK RELEASE CABLE.		23/12/2022	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Chassis/FIFTH WHEE	FRONT UMBILICAL ARM BEARINGS WORN.		23/12/2022	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Chassis/SPAREWHEEL	CRACK BEHIND RHS SPARE.		23/12/2022	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Brakes/BRAKE ADJ	BRAKE ADJUST.		23/12/2022	Fault	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Elect/ELECT P&W	CHECK LIGHTS. PARKER. INDICATORS.		23/12/2022	Fault	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Brakes/EBS FAULTS	EBS PULLING ON.		23/12/2022	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Elect/HEAD LIGHT	RHS PARKER LIGHT OUT.		23/12/2022	Fault	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Elect/WORK LIGHT	WORK LIGHTS POPPING FUSE.		23/12/2022	Fault	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Elect/TRL LIGHTS	TRAILER LIGHTS PARKERS POPPING FUSE.		23/12/2022	Fault	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Rosewood - Workshop	VehService/DS	Service As Per Attached Checklist	TIGHTENED BACKING PLATES.	22/12/2022	Service	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER
T378	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		22/12/2022	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER
T378	Rosewood - Workshop	Elect/TRL LIGHTS	TRAILER LIGHTS NOT WORKING.	REPAIRED BAD CONNECTION AT TRAILER PLUG.	22/12/2022	Fault	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER
T378	Rosewood - Workshop	Elect/ELECT P&W	CLEARANCE LIGHTS.	REPAIRED 2ND BOLSTER WIRING.	22/12/2022	Fault	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER
T378	Wodonga - Workshop	Workshop/(MOVE ASSET	UNHOOKED T381. HOOKED UP T379. PARKED.		17/12/2022	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	VehService/DS	Service As Per Attached Checklist		16/12/2022	Service	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		16/12/2022	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER
T378	Wodonga - Worksh

T378	Albury - Workshop	Tyres\TP3-4	Tyre Position 3 + 4			26/11/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Albury Workshop	TRAILER				
T378	Albury - Workshop	Tyres\TP7-8	Tyre Position 7 + 8			26/11/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Albury Workshop	TRAILER				
T378	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			25/11/2022	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	Brakes	Record Check Results As Attached To This.Iob			25/11/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			19/11/2022	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	Brakes	Record Check Results As Attached To This.Iob			19/11/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	DrivLine\AXLE REPLC	No Straps on middle axle			19/11/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	Chassis\FIFTH WHEE	ADJUST CHAIN.			19/11/2022	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
					CARRY OUT BRAKE RELINE TO ALL AXLES.														
					- Raise and support axles. Remove wheels, drums and hubs.														
					- Inspect and found all s-cams to have excessive movements.														
					- Measure drums, ok.														
					- Remove and replace all s-cams and bushes.														
					- Fit new brake shoes.														
					- Replace As ABS sensors as per customer request.														
					- Clean and inspect bearings, all ok.														
					- Refit hubs and adjust bearings.														
T378	Albury - Workshop	Brakes\BRK RELINE	Reline all axles.		- Grease and adjust brakes. Lower axles.	10/11/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			10/11/2022	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER				
T378	Wodonga - Workshop	Brakes	Record Check Results As Attached To This.Iob			10/11/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER				
T378	Wodonga - Workshop	Chassis\AIR TANKS	TOP FRONT AIR TANK BRACKET BROKEN OR LOOSE.			10/11/2022	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER				
T378	Wodonga - Workshop	Susp\SUSPENSION	L/H MIDDLE AXLE MOVEMENT.			10/11/2022	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER				
T378	Wodonga - Workshop	Chassis\FIFTH WHEE	ADJUST CHAIN.			10/11/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER				
T378	Wodonga - Workshop	Susp\SHOCK ABS	RHR Shock Worn.			10/11/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER				
T378	Wodonga - Workshop	DrivLine\AXLE REPLC	No Straps on middle axle			10/11/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER				
T378	Wodonga - Workshop	Workshop\ABOVE ASSET	Hook SBR up to T379/379.			10/11/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER				
T378	Wodonga - Workshop	Susp\SUSPENSION	Replaced Ubolts			22/10/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	Body\BOLSTER	Weld LH Stopper			22/10/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	Body\HOUSEKEEP	Replaced QR Cables			22/10/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			11/10/2022 11570	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	Brakes	Record Check Results As Attached To This.Iob			11/10/2022 11570	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Albury - Workshop	Tyres\TP1-2	supply and fit 2tyres			11/10/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Albury Workshop	TRAILER				
T378	Wodonga - Workshop	Susp\SUSPENSION	L/H FRONT SPRING MOVEMENT.			11/10/2022	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		RTEPLACED LF SEB.	11/10/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	Brakes	Record Check Results As Attached To This.Iob		REPAIRED LH TAIL LIGHT.	07/10/2022	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
						07/10/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
					- Middle axle shocks missing straps - Replace next service														
					- LHF of trailer locking hinge broken - No time to repair														
T378	Wodonga - Workshop	VehService\DS	CARRY OUT GREEN\REIGHT LOG TRAILER D-SERVICE AS PER ATTACHED SERVICE SHEET.		- 2nd bolster both sides cracked - Repair next service	30/09/2022	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	Brakes	Record Check Results As Attached To This.Iob			30/09/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
					- Remove light assembly and test power, found none.														
					- Inspect wiring and found break.														
			ABS TRAILER LIGHT ON.		- Repair wiring and test operation, all ok.														
T378	Wodonga - Workshop	Brakes\EBS FAULTS	LH R BRAKE LIGHT N/W. ABS TRAILER LIGHT ON.		- Refit lahns	30/09/2022	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	Hydraulics\MOTOR	TRAILER NOT FOLDING UP ALL THE TIME. PTO JUST WINDING.			30/09/2022	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	Brakes\BOOSTER	AXLE 3 LH BRAKE BOOSTER AIRLINE SPLIT AND LEAKING		Remove hose and cut out split section. Refit hose and check for leaks, all ok.	30/09/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Albury - Workshop	Tyres\TP5-6	SUPPLY AND FIT 4 TYRES			22/09/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Albury Workshop	TRAILER				
T378	Albury - Workshop	Tyres\TP9-10	Tyre Position 9 + 10			22/09/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Albury Workshop	TRAILER				
T378	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			20/09/2022	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	Brakes	Record Check Results As Attached To This.Iob			20/09/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection	Insp\ANN INSP-deactivated 15/5/2024 3:43:44 am utc		20/09/2022	PreventativeMaintenance	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			13/09/2022	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	Brakes	Record Check Results As Attached To This.Iob		- Inspect wiring and found break.	13/09/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	Workshop\ABOVE ASSET	UNHOOKED FROM 1001.			03/09/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			27/08/2022	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	Brakes	Record Check Results As Attached To This.Iob			27/08/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	Brakes\EBS FAULTS	ABS TRAILER LIGHT ON.			27/08/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	Hydraulics\MOTOR	TRAILER NOT FOLDING UP ALL THE TIME. PTO JUST WINDING.			27/08/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			19/08/2022	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	Brakes	Record Check Results As Attached To This.Iob			19/08/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	Chassis\STRAPS	DOG CHAIN MISSING.			19/08/2022	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	Workshop\ABOVE ASSET	DROPPED OFF TCTC FOR BRAKE TEST. JUMP STARTED B77.			17/08/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	Insp\RWC COMP	Carry out repairs from attached Roadworthy inspection.		INSPECTED AND REWIRED LIGHT PLUG. REWIRED WORK LIGHTS TO REVERSE FOR ROADWORTHY. TIGHTENED BALLRACE BE	12/08/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Albury - Workshop	Tyres\TP11-12	Tyre Position 11 + 12			28/07/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Albury Workshop	TRAILER				
T378	Albury - Workshop	Tyres\TP1-2	supply and fit 6 tyres			28/07/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Albury Workshop	TRAILER				
T378	Albury - Workshop	Tyres\TP3-4	Tyre Position 3 + 4			28/07/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Albury Workshop	TRAILER				
T378	Wodonga - Workshop	Elect\TRL LIGHTS	Rear bar clearance lights out		REPLACED LIGHTS. REPAIRED WIRING.	27/07/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	Chassis\AIR LEAK	Air leak LHS rear axle			27/07/2022	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	Brakes\AIR LEAK	AIR LEAK A TRAILER.		UNHOOKED. WASHED. REPLACED RR AND LM AIRBAGS. REPAIRED LR AND RR BRAKE HOSES. TIGHTENED HOSE CLAMPS. RE	27/07/2022	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	Elect\SELECT P&W	PAINER OUT x 1.			27/07/2022	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
			CONDUCT R/WORTHY INSPECTION N° 8834654																
			DEFECT N°D6815127																
			CLEARANCE N° R08TR223																
			REPLACE REAR MARKER PLATES.																
			CORRECT BRAKE IMBALANCE AXLE 2 + 3.																
			CORRECTLY WIRE STOPLIGHTS.																
			THOROUGHLY CLEAN ALL SIDELIGHTS.																
			FIT SELF SEALING COUPLING FOR 'B' TRAILER SERVICE LINE																
			AXLE 3 ROLLING RESISTANCE HIGH (PROBABLE BRAKE OVER																
			ADJUSTS.																
			TIGHTEN SOME LOOSE T/TABLE FOOT PLATE BOLTS / NUTS.																
			AXLE 3 SLACKADJUSTER/BOOSTER LENGTHS + FITTING																
			INCORRECT																
T378	Wodonga - Workshop	Insp\RWC COMP	FIT DINOT SIGNAGE (RT+C)			27/07/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			21/07/2022	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	Brakes	Record Check Results As Attached To This.Iob			21/07/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	Susp\AIR LEAK	A - Trailer leaking air rear LHS		Previously completed	21/07/2022	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	Elect\ELECT P&W	Light plug on bolster		Completed	21/07/2022	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	Elect\TRL LIGHTS	Rear bar clearance lights out			21/07/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	Workshop\ABOVE ASSET	UNHOOKED 1010.			12/07/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		ADJUSTED RF LM LR RR WHEEL BEARINGS.	05/07/2022	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	Brakes	Record Check Results As Attached To This.Iob			05/07/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	Susp\AIR BAG	REPLACE LEAKING LM AIRBAG.		COULDN'T FAULT.	05/07/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	Body\CHN/RUB/MIN	Chain rollers need replacing X3		COULDN'T FAULT.	05/07/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	Elect\TRL LIGHTS	Reverse and work lights 2nd bolster		REPAIRED BOLSTER PLUGS. COULDN'T FAULT REVERSE.	05/07/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	Brakes\BRK RELINE	RELINES DUE.			30/06/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	Brakes\BRK RELINE	RELINES DUE.			30/06/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	Brakes\BREAKDOWN	Check right hand rear axle (smoking)		Found brake was not backed off.	27/06/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			26/06/2022	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	Brakes	Record Check Results As Attached To This.Iob			26/06/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	Elect\WORK LIGHT	REAR WORK LIGHT OUT.			26/06/2022	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Albury - Workshop	Susp\AIR BAG	Air Bag			23/06/2022 11570	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Albury Workshop	TRAILER				
			Change LH front brake booster																
T378	Wodonga - Workshop	Brakes\BOOSTER	Adjust brake			22/06/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	Brakes\AIR LEAK	Travelled to Wanawarrata side of freeway attended trailer T378 with air leak on tri. found un-secured hose had rubbed on centre axle brake boosters causine maior air leaks. replace 2 damaged brake hoses and resec			21/06/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	Brakes\AIR LEAK	Repaired air leak at LHC brake booster service hose rubbed through, replace hose to EBS valve and retested all good.			17/06/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			15/06/2022	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	Brakes	Record Check Results As Attached To This.Iob			15/06/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
					Reline all axles														
					Replaced all bearings														
					Replaced LHR brake drum														
					Replaced RHM hub cap														
					Brake adjust														
					Grease														
					Hook up to T379														
					Cleaned up after job														
T378	Wodonga - Workshop	Brakes\BRK RELINE	DUE FOR RELINE.		Reslaced missine bolts (LH Guard)	15/06/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	Brakes\BRK RELINE	NEEDS RELINES.			15/06/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	Body\CHN/RUB/MIN	Chain rollers need replacing X3			15/06/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	Elect\TRL LIGHTS	Reverse and work lights 2nd bolster			15/06/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			08/06/2022	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	Brakes	Record Check Results As Attached To This.Iob			08/06/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	Brakes\BRK RELINE	RELINES DUE.			08/06/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	Susp\AIR BAG	REPLACE LEAKING LM AIRBAG.			08/06/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			02/06/2022	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	Brakes	Record Check Results As Attached To This.Iob			02/06/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	Brakes\BRK RELINE	NEEDS RELINES.			02/06/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	Elect\INDICATORS	NO BLINKERS.		INSPECTED TRUCK POWER. RESET CIRCUIT BREAKER. TEST DROVE. DIAGNOSED SHORT IN WIRING AND REPAIRED AT LH IND	26/05/2022	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		REPLACED RM SM SHOCKS, NUT AND BOLTS. DIAGNOSED AD REPAIRED TRAILER LIGHTS AND RH INDICATORS.	25/05/2022	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	Brakes	Record Check Results As Attached To This.Iob			25/05/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	Brakes\BRK RELINE	DUE FOR RELINE.			25/05/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	Chassis\FIFTH WHEE	SLIDE-LOCKS BARELY WORKING- VERY SLOW.			25/05/2022	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			21/05/2022	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	Brakes	Record Check Results As Attached To This.Iob			21/05/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			04/05/2022	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	Brakes	Record Check Results As Attached To This.Iob			04/05/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	Brakes\BRK RELINE	DUE FOR RELINE.			04/05/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			22/04/2022	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	Brakes	Record Check Results As Attached To This.Iob			22/04/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
			SLIDE-LOCKS BARELY WORKING- VERY SLOW.																
T378	Wodonga - Workshop	Chassis\FIFTH WHEE	FILTERS ON ORDER.			22/04/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	Chassis\FIFTH WHEE	SLIDE-LOCKS BARELY WORKING- VERY SLOW.		ISPECTED. TESTED WITHOUT BLOCKED EXHAUST FILTERS. REPLACED SOLONOID VALVE. IMPROVED OPERATION. ORDERED	09/04/2022	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	Chassis\FIFTH WHEE	TURNTABLE SLIDE-LOCKS NOT WORKING. TRAILER.			09/04/2022	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	Susp\AIR BAG	REPAIR AIRBAG FITTING.		TRIMMED HOSE AND REPLACED NUT AND OLIVE.	03/04/2022	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			25/03/2022	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	Brakes	Record Check Results As Attached To This.Iob			25/03/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	Chassis\STRAPS	TIE DOWN DOG CHAIN BROKEN.			25/03/2022	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	Elect\ELECT P&W	AIR SOLONOID VERY SLOW IN MORNINGS TO OPERATE TURNTABLE SLIDE LOCK.			25/03/2022	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Albury - Workshop	Tyres\CLEANSKIN	SUPPLY AND FIT 2 TYRES - NO POS GIVEN			25/03/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Albury Workshop	TRAILER				
T378	Wodonga - Workshop	Chassis\EXTE TU	REPLACED 2ND WINCH QUICK RELEASE CABLE.			22/02/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		REPLACED TRUCKSAFE STICKER.	16/02/2022	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	Brakes	Record Check Results As Attached To This.Iob			16/02/2022	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	G

T378	Myrtleford - Workshop	Tyres\TP7+8	supply and fit 2tyres			22/12/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Body\CHN/RUL9/MN	drive chain refitment and reset			21/12/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER
			Service As Per Attached Checklist												
T378	Myrtleford - Workshop	VehService\DS	O/N L12722			03/12/2021	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	BIG WHEELS TRUCK ALIGNMENT - 3	TRAILER
T378	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			03/12/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	BIG WHEELS TRUCK ALIGNMENT - 3	TRAILER
			Service As Per Attached Checklist												
T378	Myrtleford - Workshop	VehService\DS	O/N L12415			15/10/2021	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	BIG WHEELS TRUCK ALIGNMENT - 3	TRAILER
T378	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			15/10/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	BIG WHEELS TRUCK ALIGNMENT - 3	TRAILER
T378	Myrtleford - Workshop	Tyres\TP1+2	supplya nd fit 2 tyres			02/10/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER
			Service As Per Attached Checklist												
T378	Myrtleford - Workshop	VehService\DS	O/N L12329			01/10/2021	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	BIG WHEELS TRUCK ALIGNMENT - 3	TRAILER
T378	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			01/10/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	BIG WHEELS TRUCK ALIGNMENT - 3	TRAILER
			D Service As Per Attached Checklist												
T378	Myrtleford - Workshop	VehService\DS	ORDER # L12214			10/09/2021	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	BIG WHEELS TRUCK ALIGNMENT - 3	TRAILER
T378	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			10/09/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	BIG WHEELS TRUCK ALIGNMENT - 3	TRAILER
			Service As Per Attached Checklist												
T378	Myrtleford - Workshop	VehService\DS	O/N L12102			21/08/2021	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	BIG WHEELS TRUCK ALIGNMENT - 3	TRAILER
T378	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			21/08/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	BIG WHEELS TRUCK ALIGNMENT - 3	TRAILER
T378	Myrtleford - Workshop	Brakes\BRAKE ADJ	grease and brake adjust			17/08/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Susp\HOUSEKEEP	recheck all u-bolts and spring eye bolts			17/08/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Body\MUDGUARDS	straighten guard			06/08/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			29/07/2021	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			29/07/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER
			hook up												
T378	Myrtleford - Workshop	Body\FIFTH WHEE	test			23/07/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Brakes\EBS Kit	check ebs			23/07/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Chassis\WINCH/STRP	check winchs and straps and quick release			23/07/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Body\PAINT/REST	wash trailer and acid wash wheels			23/07/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Body\MOUNTS	rear light bar cracked			23/07/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Body\AIR LEAK	airline supports are bracing air			23/07/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Chassis\WINCH/STRP	2nd winch straps u/s			23/07/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Body\CHN/RUL9/MN	chain rollers u/s			23/07/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Chassis\BOLSTER	2nd bolster cracked on angle brackets			23/07/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Body\CHN/RUL9/MN	replace chain down dog			23/07/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Body\MOUNTS	1st winch bracket cracked			23/07/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Hydraulic\HYD LEAKS	hyd couplings u/s			23/07/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Body\MOUNTS	bolster peg bolts u/s			23/07/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Chassis\BOLSTER	both bolster pegs bolts			23/07/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Body\MUDGUARDS	LH5 mudguard bolts u/s			23/07/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Susp	LHM top shock bolt			23/07/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Chassis\FIFTH WHEE	ball race u/s R11963			23/07/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Body\DAMAGE	gypsy motor cover			23/07/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Chassis\FIFTH WHEE	skid plate bolts loose need replacing			23/07/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Body\MUDGUARDS	RH5 mudguard at front loose			23/07/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Elect\WORK LIGHT	replace work lights L12014			23/07/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Body\CHN/RUL9/MN	tension spring hammer locks u/s			23/07/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Body\CHN/RUL9/MN	trailer roller u/s			23/07/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Susp\AIR BAG	LHR airbag bell			23/07/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Susp\WHEEL ALIGN	front and rear axle wheel bearing adj			23/07/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Body\HOUSEKEEP	check over make list			23/07/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Body\AIR FITTIN	untangle umbilical chord and rewrap			23/07/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Susp\AIR BAG	replace LHR airbag bell			23/07/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Hydraulic\HYD LEAKS	replace hydraulic couplings to B Trailer and shorten hydraulic hose L12031			23/07/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Body\AIR FITTIN	shorten and repair light plug wiring to B Trailer			23/07/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Body\FIFTH WHEE	remove turntable slide lock and extract broken slide bolt, refit and test L11992			23/07/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Body\AIR LEAK	protection valve leaking			23/07/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Body\AIR FITTIN	tank line leaking			23/07/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection	Insp\ANN INSP-deactivated 15/5/2024 3:43:44 am utc		23/07/2021	PreventativeMaintenance	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Body\AIR LEAK	air leak near rear axle			23/07/2021	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Body\DAMAGE	umbilical cord bracket bent down			23/07/2021	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Susp\WHEEL ALIGN	wheel align all 3 axles and repairs			22/07/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	VehService\DS	completed service and appraisal			16/07/2021	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Chassis\CROSS MBR	tightened ubolts and cross member bolts			16/07/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Elect\TIL LIGHTS	repaired body mounts and lights			16/07/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Body\MOUNTS	replaced umbilical beerings			16/07/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Susp\WHEEL ALIGN	wheel alignment needs checking	done		29/06/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Brakes\BOOSTER	LH9 brake booster rod seems short	couldn't find any fault		29/06/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Body\CHN/RUL9/MN	slider locks need removing and grease parts cleaned	done		29/06/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	VehService\DS	D Service			29/06/2021	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			29/06/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER
T378	Rowewood - Workshop	Tyres\TP11	Fit runout			09/06/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rowewood Workshop	TRAILER
			remove SR2 valve												
			fit new valve												
T378	Tumut - Workshop	Brakes\AIR LEAK	check operation			26/05/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Tumut Workshop	TRAILER
T378	Myrtleford - Workshop	Elect\TIL LIGHTS	trailer lights not working	lights all checked on T/Service		14/05/2021	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	VehService\DS	D Service			14/05/2021	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Body\CHN/RUL9/MN	cut 4 links from load chain, refit and adjust			14/05/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Chassis\BOLSTER	weld on new rear bolster catch			14/05/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			14/05/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER
T378	Rowewood - Workshop	Body\AIR LEAK	air leak near rear axle			04/05/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rowewood Workshop	TRAILER
T378	Rowewood - Workshop	Body\DAMAGE	umbilical cord bracket bent down			04/05/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rowewood Workshop	TRAILER
T378	Rowewood - Workshop	Chassis\WINCH/STRP	2nd winch strap needs replacing			04/05/2021	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rowewood Workshop	TRAILER
T378	Rowewood - Workshop	Tyres\TP9+10	Supply and fit 2 tyres			01/05/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rowewood Workshop	TRAILER
T378	Rowewood - Workshop	Body\FIFTH WHEE	remove slider locks and nipples. Unblock and reinstall. Check and grease. All good			28/04/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rowewood Workshop	TRAILER
T378	Rowewood - Workshop	Chassis\WINCH/STRP	replace 2 straps			28/04/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rowewood Workshop	TRAILER
			check lights												
			fit new number plate light												
T378	Tumut - Workshop	Elect\TIL LIGHTS	run new wirines in bush bar			28/04/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Tumut Workshop	TRAILER
T378	Rowewood - Workshop	VehService\DS	D Service			21/04/2021	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rowewood Workshop	TRAILER
T378	Rowewood - Workshop	Susp\WHEEL ALIGN	wheel alignment needs checking			21/04/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rowewood Workshop	TRAILER
T378	Rowewood - Workshop	Brakes\BOOSTER	LH9 brake booster rod seems short			21/04/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rowewood Workshop	TRAILER
T378	Rowewood - Workshop	Body\CHN/RUL9/MN	slider locks need removing and grease parts cleaned			21/04/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rowewood Workshop	TRAILER
T378	Rowewood - Workshop	Brakes	Record Check Results As Attached To This Job			21/04/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rowewood Workshop	TRAILER
T378	Rowewood - Workshop	Elect\BRK LIGHT	loose wires near plug at back of trailer (brake lights flickering on/off)			14/04/2021	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rowewood Workshop	TRAILER
T378	Rowewood - Workshop	Body\SUSPENSION	check noise under trailer, found it to be a spring wrap touching 2 spring. No repairs needed			07/04/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rowewood Workshop	TRAILER
T378	Rowewood - Workshop	Tyres\TP11+12	Supply and fit 2 tyres			01/04/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rowewood Workshop	TRAILER
T378	Albury - Workshop	Elect\TIL LIGHTS	Supply Red/Amber Markers			24/03/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Albury Workshop	TRAILER
T378	Rowewood - Workshop	Tyres\TP5+6	Supply and fit 2 tyres			23/03/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rowewood Workshop	TRAILER
T378	Rowewood - Workshop	VehService\DS	Carried Out D-Service			23/03/2021	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rowewood Workshop	TRAILER
			DURING SERVICE FOUND RHF MARKER LIGHT OUT. $66.70												
			Checked for power at plugs for light - power present												
			Removed light and found wire broken at light												
			Cut all cable ties and removed light												
			Fitted new light and ran wires and secured into position.												
			Cut wires and fitted terminals and secured.												
T378	Rowewood - Workshop	Elect\TIL LIGHTS	Tested. found all ok.			23/03/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rowewood Workshop	TRAILER
T378	Tumut - Workshop	Body\CHN/RUL9/MN	cut excess links from load chain adjust properly			05/03/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rowewood Workshop	TRAILER
T378	Rowewood - Workshop	Body\CHN/RUL9/MN	slide locks not greassing	remove grease nipples.digout old grease clean replace nipples and grease		04/03/2021	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rowewood Workshop	TRAILER
T378	Rowewood - Workshop	Brakes\SLACK ADJ	return springs on slack adjusters missing	fit/return springs on slack adjusters		04/03/2021	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rowewood Workshop	TRAILER
T378	Rowewood - Workshop	Body\MOUNTS	cable tie brake hoses to back	cable tie brake hoses together		04/03/2021	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rowewood Workshop	TRAILER
T378	Albury - Workshop	Tyres\TP7+8	Supply and fit 2 tyres			25/02/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Albury Workshop	TRAILER
T378	Myrtleford - Workshop	Body\CHN/RUL9/MN	load chain playing up on front cog	this would have been done on this job		24/02/2021	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER
			broken hammerlock on boomerang												
			adjuster bolt seized												
			cut off bolt												
			refit new adjuster bolt and hammerlock												
			adjust chain												
T378	Myrtleford - Workshop	Body\CHN/RUL9/MN	check operation			24/02/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER
			front left hand side front axle												
T378	Rowewood - Workshop	Body\WH L HUB	flat tyre second stud stribed 2nd one clockwise from air valve			19/02/2021	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rowewood Workshop	TRAILER
T378	Myrtleford - Workshop	VehService\DS	D Service			18/02/2021	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			18/02/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER
				replace bent quick release											
T378	Rowewood - Workshop	Chassis\WINCH/STRP	quick release bent at Hyne mill	reolace quick release cable		18/02/2021	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rowewood Workshop	TRAILER
T378	Rowewood - Workshop	VehService\DS	D Service			10/02/2021	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rowewood Workshop	TRAILER
T378	Rowewood - Workshop	Brakes	Record Check Results As Attached To This Job			10/02/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rowewood Workshop	TRAILER
			major tidy up/rewire where necessary of rear lights. Melted cables and plugs												
T378	Rowewood - Workshop	Elect\TIL LIGHTS	replace side markers as needed			03/02/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rowewood Workshop	TRAILER
T378	Tumut - Workshop	Elect\TIL LIGHTS	newire light bar			03/02/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Tumut Workshop	TRAILER
				diagnose electrical short in trailer lights											
				plug at rear bar melted/shorted											
T378	Rowewood - Workshop	Elect\TIL LIGHTS	trailer lights not working	needs newair asap. removed trailer from service		02/02/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rowewood Workshop	TRAILER
T378	Rowewood - Workshop	VehService\DS	D Service			29/01/2021	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rowewood Workshop	TRAILER
T378	Rowewood - Workshop	Brakes	Record Check Results As Attached To This Job			29/01/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rowewood Workshop	TRAILER
T378	Rowewood - Workshop	Tyres\TP3+4	replace 2 tyres			28/01/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rowewood Workshop	TRAILER
T378	Rowewood - Workshop	Tyres\TP9+10	replace 2 tyres			28/01/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rowewood Workshop	TRAILER
T378	Myrtleford - Workshop	Brakes\ABS	"ABS" for trailer on all the time	repair wiring issue with EBS		19/01/2021	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER
				Check trailer ABS light on found fuse blown, replace with self reset breaker as supplied by workshop.											
				Check wiring and locate pins pulled out of trailer EBS plug (A trailer to B trailer plug). Replace plug as needed											
				(plug from Lavington stock - Booked out)											
T378	Albury - Workshop	Elect\CONSUMABLE	7 Pin EBS Plug	Clear codes and check - okay		16/01/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Albury Workshop	TRAILER
T378	Rowewood - Workshop	VehService\DS	D Service			12/01/2021	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rowewood Workshop	TRAILER
T378	Rowewood - Workshop	Brakes	Record Check Results As Attached To This Job			12/01/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rowewood Workshop	TRAILER
T378	Rowewood - Workshop	Chassis\WINCH/STRP	repair air leak at front winch (replace fitting)			08/01/2021	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rowewood Workshop	TRAILER
T378	Rowewood - Workshop	VehService\DS	D Service and jobs			05/01/2021	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rowewood Workshop	TRAILER
T378	Rowewood - Workshop	Tyres\TP3+4	replace 2 tyres			24/12/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rowewood Workshop	TRAILER
T378	Rowewood - Workshop	Brakes\BRAKE ADJ	assist TCTC brakes			22/12/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rowewood Workshop	TRAILER
T378	Rowewood - Workshop	Brakes\BRK RELINE	relines as needed with TCTC			22/12/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rowewood Workshop	TRAILER
T378	Rowewood - Workshop	Brakes\BRK RELINE	reline LHF and LHR wheels			22/12/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rowewood Workshop	TRAILER
			cut off broken shock mount												
			prepare for welding												
			fabricate mounts												
T378	Rowewood - Workshop	Body\SUSPENSION	weld in place			22/12/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rowewood Workshop	TRAILER
T378	Rowewood - Workshop	Elect\TIL LIGHTS	lights playing up			22/12/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rowewood Workshop	TRAILER
T378	Rowewood - Workshop	Body\CHN/RUL9/MN	adjusted load chain			19/12/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rowewood Workshop	TRAILER
T378	Rowewood - Workshop	Brakes\BRK RELINE	relines as required RHM			19/12/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rowewood Workshop	TRAILER
T378	Rowewood - Workshop	Brakes\BRK RELINE	reline RHF axle			19/12/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rowewood Workshop	TRAILER
T378	Rowewood - Workshop	Body\CHN/RUL9/MN	adjust load chain			19/12/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rowewood Workshop	TRAILER
T378	Tumut - Workshop	Chassis\WINCH/STRP	travel to Tumut pick up parts from forest centre			11/12/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Tumut Workshop	TRAILER
T378	Rowewood - Workshop	Elect\INDICATORS	blinker and stop lights L/H/Side back not working. blinker and stop lights L/H/Side back not working			10/12/2020	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rowewood Workshop	TRAILER
T378	Rowewood - Workshop	Elect\TIL LIGHTS	lead on lights 2nd bolster too short			10/12/2020	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rowewood Workshop	TRAILER
T378	Rowewood -

				D Service Rear Axle A Trailer Incorrect rod lught on LHS push rod length guide inspection as short of time and driver was awaiting														
T378	Rosewood - Workshop	VehService\DS		areased and adjusted brakes		08/12/2020	Service	Completed	Greenfreight Loxeine Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Brakes		Record Check Results As Attached To This.Job remove front winch and build a good unit from 2		08/12/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Chassis\WINCH/STRP		refit unit		05/12/2020	Repair	Completed	Greenfreight Loxeine Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Body\CHN/RUL/MN		hammer lock replaced for tie down		05/12/2020	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Body\CHN/RUL/MN		load chain playing up on front cog		05/12/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	VehService\DS		Carry Out Greenfreight log trailer D-Service as per service sheet During Service found rear left indicator, brake, reverse and parker lights not working. Removed lights and found damaged wiring, repaired wiring and secured		02/12/2020	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Elec\TRL LIGHTS		refitted lights and reslaced ones reauired		02/12/2020	Repair	Completed	Greenfreight Loxeine Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Body\CHN/RUL/MN		cut links from chain and adjust		20/11/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Elec\TRL LIGHTS		run new wiring through 2nd bolster		20/11/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Chassis\WINCH/STRP		replace two load straps	CARRY OUT GREENFREIGHT LOG TRAILER D-SERVICE AS PER ATTACHED SERVICE SHEET	18/11/2020	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	VehService\DS		Service As Per Attached Checklist	GREASE	17/11/2020	Service	Completed	Greenfreight Loxeine Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Brakes		Record Check Results As Attached To This.Job		17/11/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Brakes\BOOSTER		RHR BRAKE BOOSTER NEEDS REPLACING	Removed and cut new rod to length. Fitted and adjusted brake as required	17/11/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Brakes\BOOSTER		replaced RHR booster		13/11/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	VehService\DS		D Service		13/11/2020	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Brakes		Record Check Results As Attached To This.Job		13/11/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Chassis\FIFTH WHEE		replace both turntable pedistals, bushes, dogbones and pins		10/11/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Body\CHN/RUL/MN		tighten load chain		06/11/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Susp\HCV		adjust ride height		06/11/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Body\REFLECTORS		pop rivert red and yellow sign back on		03/11/2020	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Body\REFLECTORS		refit "do not overtake turning vehicle sign		03/11/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	VehService\DS		D Service		30/10/2020	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Brakes		Record Check Results As Attached To This.Job		30/10/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Tumut - Workshop	Hydraulic\HYD LEAKS		blown hydraulic hose		24/10/2020	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Tumut Workshop	TRAILER			
T378	Rosewood - Workshop	Hydraulic\HYD LEAKS		blown hydraulic hose	sublet repair on umbilical hose	24/10/2020	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	VehService\DS		D Service and check over		24/10/2020	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Brakes		Record Check Results As Attached To This.Job		24/10/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Hydraulic\HYD LEAKS		sublet repair (hydraulink), I assisted with re-assembling and testing		24/10/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Elec\TRL LIGHTS		trailer lights short trips		16/10/2020	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	VehService\DS		D Service and check over		07/10/2020	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Brakes\BOOSTER		Replace RHF brake chamber		07/10/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Susp\HOUSEKEEP		replace RHD shock strap and keepers R10025		07/10/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Susp\HOUSEKEEP		tightened u-bolts and weld		07/10/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Brakes		Record Check Results As Attached To This.Job		07/10/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Body\CHN/RUL/MN		continue refurb work		29/09/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Chassis\FIFTH WHEE		replace turntable slider pads upper and lower R10148		29/09/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Tumut - Workshop	Body\CHN/RUL/MN		fit new bolster chain guides		26/09/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Tumut Workshop	TRAILER			
T378	Tumut - Workshop	Body\CHN/RUL/MN		fit new rear roller guide broken crossmember		26/09/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Tumut Workshop	TRAILER			
T378	Tumut - Workshop	Chassis\DAMAGE		orexare and weld check load chain following unauthorised replacement on Friday. Driver complaining very loose found dangerously excessive chain slop		23/09/2020	Repair	Completed	Greenfreight Loxeine Vic	ElpidPW	Mt Gambier	GTK	376815	Tumut Workshop	TRAILER			
T378	Rosewood - Workshop	Body\CHN/RUL/MN		stopped loadline\unloadline of trailer for shifts until repairs could be made		22/09/2020	Repair	Completed	Greenfreight Loxeine Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Body\CHN/RUL/MN		remove broken chain from trailer and set up in workshop for repairs		22/09/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Body\CHN/RUL/MN		continue with big chain conversion and repairs		22/09/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Body\CHN/RUL/MN		continue big chain conversion works		22/09/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Chassis\BOLSTER		start bolster slide pads replacement		22/09/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	VehService\DS		D Service		11/09/2020	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Brakes		Record Check Results As Attached To This.Job		11/09/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Elec\TRL LIGHTS		R/H Side tail brake lights not failing out	diagnose and repair short in brake lights	29/08/2020	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Body\AIR LEAK		air leak middle axle TU9538. air leak middle axle		27/08/2020	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	VehService\DS		D Service		27/08/2020	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Brakes		Record Check Results As Attached To This.Job check for codes and problems with EBS system		27/08/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Brakes\EBS Kit		all eood		21/08/2020	Repair	Completed	Greenfreight Loxeine Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Brakes\EBS Kit		cleared history codes, not been any for some time		21/08/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Body\WH\ HUB		TCTC checked and adjusted all wheel bearings		20/08/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Body\AIR LEAK		repair air leak - rear axle		19/08/2020	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	VehService\DS		D Service		15/08/2020	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Brakes		Record Check Results As Attached To This.Job		15/08/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	VehService\DS		D Service		06/08/2020	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Susp\SHOCK ABS		replace RHR shocker, strap and keepers		06/08/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Brakes		Record Check Results As Attached To This.Job		06/08/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	VehService\DS		D Service		05/08/2020	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Body\CHN/RUL/MN		replace broken hold down chain dog		04/08/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Tyres\ITTMENT		Job Added From Invoice		17/07/2020 531838	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Tyres\CLEANSKIN		Job Added From Invoice		17/07/2020 531838	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Body\CHN/RUL/MN		removed 4 more links from chain and adjust		16/07/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Myrtleford - Workshop	Body\CHN/RUL/MN		needs chain links cutting out of load chain	remove 4x chain links load chain had come off gypsie cut 2 links from either end of chain and refitted and tensioned	16/07/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Rosewood - Workshop	Body\CHN/RUL/MN		load chain come off gypsie wheel	*could do with 2 more links out of back end of s'bale	14/07/2020	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	VehService\DS		D Service		11/07/2020	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Body\CHN/RUL/MN		need links cut out of load chain		11/07/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Brakes		Record Check Results As Attached To This.Job		11/07/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Tyres\ITTMENT		Job Added From Invoice		09/07/2020 529146	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Tyres\CLEANSKIN		Job Added From Invoice		09/07/2020 529146	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	VehService\DS		D Service		01/07/2020	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Body\HOUSEKEEP		wrap umbilical under turntable with ty flat		01/07/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Brakes\AIR LEAK		repair multiple brake hose leaks rewire RHR mudguard side marker		01/07/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Elec\TRL LIGHTS		replace RHR mudguard side marker		01/07/2020	Repair	Completed	Greenfreight Loxeine Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Body\CHN/RUL/MN		needs chain links cutting out of load chain		01/07/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Brakes		Record Check Results As Attached To This.Job diagnose. EBS fault causing light on dash		01/07/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Brakes\EBS Kit		#reeds wheels removed and all sensors checkine has inactive fault codes		27/06/2020	Repair	Completed	Greenfreight Loxeine Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Myrtleford - Workshop	Hydraulic\MOTOR		Fit new trailer winch motor		25/06/2020	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Rosewood - Workshop	Brakes\ABS		"ABS" for trailer on all the time	repair air leak at EBS module	24/06/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Hydraulic\MOTOR		winch pump leaking bad	replace gypsy motor	24/06/2020	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Myrtleford - Workshop	Elec\INDICATORS		R/H blinker missing	check on service there and working	23/06/2020	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Rosewood - Workshop	VehService\DS		D Service		18/06/2020	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Brakes\BOOSTER		diagnose air leak, needs 2 brake no. 24/30 in stock. Ordered some (RHF & RHR)		18/06/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Brakes		Record Check Results As Attached To This.Job		18/06/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	VehService\DS		D Service		12/06/2020	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Brakes		Record Check Results As Attached To This.Job		12/06/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Chassis\CROSS MBR		cross member broken one end	remove broken cross member below chain adjuster and straighten. Weld up and reinstall	03/06/2020	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Body\CHN/RUL/MN		replace chain hold down dampner		03/06/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Brakes\AIR LEAK		tidy up and recover several brake hoses		03/06/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	VehService\DS		Service		28/05/2020	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Brakes		Record Check Results As Attached To This.Job		28/05/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	VehService\DS		Service		16/05/2020	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Brakes		Record Check Results As Attached To This.Job		16/05/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Tumut - Workshop	Hydraulic\MOTOR		pull top off winch pump check seats	clean down hydraulic motor confirm leak all motor off and disassemble seals and o-rings leaking go to Tumut hydraulics no parts rang TCTC ordered new motor reassemble motor and put back on gearbox	07/05/2020	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Tumut Workshop	TRAILER			
T378	Rosewood - Workshop	VehService\DS		D Service		22/04/2020	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Brakes		Record Check Results As Attached To This.Job make up new hold down dog bolt (mount)		22/04/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Body\CHN/RUL/MN		replace misste doe & chain		10/04/2020	Repair	Completed	Greenfreight Loxeine Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Body\HOUSEKEEP		find check off after major works and roadworthy		09/04/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Insp\ANN INSP		Annual Inspection	Insp\ANN INSP-deactivated 15/5/2024 3:43:44 am utc check off previous works to ensure roadworthiness	08/04/2020	PreventativeMaintenance	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Elec\ELECT PWW		find reverse wires test		07/04/2020	Repair	Completed	Greenfreight Loxeine Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Brakes\BRK RELINE		reline RHR as needed, cam bushes, drum		07/04/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	VehService\DS		D Service		07/04/2020	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Brakes		Record Check Results As Attached To This.Job	tie down chain broken	07/04/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Tumut - Workshop	Body\CHN/RUL/MN		dog chain broken	cut out old one	01/04/2020	Fault	Completed	Greenfreight Loxeine Vic	ElpidPW	Mt Gambier	GTK	376815	Tumut Workshop	TRAILER			
T378	Tumut - Workshop	Body\HOUSEKEEP		hook up trailer take to pitt check for brake reliqn	fit new chain and hammer lock	03/04/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Tumut Workshop	TRAILER			
T378	Tumut - Workshop	Susp\SHOCK ABS		check shockies and mounts		03/04/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Tumut Workshop	TRAILER			
T378	Tumut - Workshop	Body\DAMAGE		prepare and weld in plated to rear light bar		03/04/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Tumut Workshop	TRAILER			
T378	Tumut - Workshop	Elec\WORK LIGHT		fit and wire 2 reverse lights		03/04/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Tumut Workshop	TRAILER			
T378	Tumut - Workshop	Elec\TRL LIGHTS		fit and wire 1 blinker		03/04/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Tumut Workshop	TRAILER			
T378	Myrtleford - Workshop	Elec\WORK LIGHT		work lights not working right	rewire rear of trailer	02/04/2020	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	Susp\SHOCK ABS		shocky enc bolt broken wire R/H rear of trailer	replace bolt and shocker	02/04/2020	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	Elec\TRL LIGHTS		test ok broken wire 2nd bolster find fault		02/04/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	Elec\TRL LIGHTS		rewire all ok replace RHF shocker		02/04/2020	Repair	Completed	Greenfreight Loxeine Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	Susp\SHOCK ABS		check off service and roadworthv		02/04/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Rosewood - Workshop	Body\CHN/RUL/MN		no dog to chain down trailer		27/03/2020	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Elec\INDICATORS		R/H blinker missing		27/03/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	VehService\DS		D Service		26/03/2020	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Brakes		Record Check Results As Attached To This.Job		26/03/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Hydraulic\HYD LEAKS		replace leaking hyd hoses		24/03/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	HARTRITE PTY. LTD -4	TRAILER			
T378	Rosewood - Workshop	Brakes\AIR LEAK		replace unserviceable brake air fitting		21/03/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Elec\TRL LIGHTS		driver side intercator there isn't on just wire hanging out		18/03/2020	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	VehService\DS		D Service after relines		17/03/2020	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Brakes		Record Check Results As Attached To This.Job		17/03/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Brakes\BRK RELINE		reline LHF supply new axle drum to drum & u bolt & speing wraps		17/03/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Susp\SHOCK ABS		replace LHF shocker		17/03/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Susp\SHOCK ABS		replace RHR shocker, keepers and strap		17/03/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Tyres\BREAKDOWN		replace RHR tyres swap middle axle for new one		17/03/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Susp\AXLES		fit new axle to middle		13/03/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Susp\AXLES		the new axle was complete drum to drum		13/03/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	Brakes\BRK RELINE		relines as needed		06/03/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378	Rosewood - Workshop	VehService\DS		Service		04/03/2020	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER			
T378

T378	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			12/02/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Elect/INDICATORS	blinker R/H side back of trailer missing		replace broken RH indicator	31/01/2020	Fault	Completed	Greenfreight Loxeine Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	VehService/DS	Service		repair wirine to LH indicator	30/01/2020	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Elect/INDICATORS	replaced RHR indicator			30/01/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Elect/INDICATORS	rewired LHR indicator			30/01/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			30/01/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Myrtleford - Workshop	Elect/WORK LIGHT	Work lights not working right			25/01/2020	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Chassis/WINCH/STRP	replace one end of tie down dog		replace tie down dog, driver left unattached	22/01/2020	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Elect/WORK LIGHT	work lights not working right			22/01/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Body/MIRRORS	replace one end of tie down dog		replace tie down dog, drive left unattached	22/01/2020	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	VehService/DS	Service As Per Attached Checklist			18/01/2020	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			18/01/2020	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Brakes/AIR LEAK	replace airlines		secure airlines away from brake booster clamp bolt	17/01/2020	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Body/CHN/RLR/MN	broken hammer lock			17/01/2020	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Body/CHN/RLR/MN	load chain adjuster		A frame bracket or load chain adjuster broken, bolt bent	17/01/2020	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
					diagnose and repair boost "supply" leak x/joiner and poor quality hose clamp														
					replaced section of booster hose														
T378	Rosewood - Workshop	Brakes/AIR LEAK	repair bad air leak		tidy up hoses in this area to avoid rubbine	16/01/2020	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	VehService/DS	D service			21/12/2019	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Chassis/AIR LEAK	repair airleak above middle axle			21/12/2019	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Elect/TAIL LIGHT	replace tail lights + indicator and repair wiring			21/12/2019	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Brakes	Brake test results			21/12/2019	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
			call out, chain thrown off with trailer loaded																
			undo chain, untwist and refit																
T378	Rosewood - Workshop	Body/CHN/RLR/MN	remove 2 links from either end of chain and adjust			12/12/2019	Repair	Completed	Greenfreight Loxeine Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	VehService/DS	d service			11/12/2019	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Brakes	test results			11/12/2019	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Brakes/EBS FAULTS	REPLACE EBS PLUG		DAMAGED BY HYNE TIMBER LOADER	26/11/2019	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Elect/TRL LIGHTS	CALL OUT TO ROSEWOOD NO TRAILER LIGHTS@ALL		REPLACE TRAILER LIGHTS ELECTRIAL SOCKET	25/11/2019	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	VehService/DS	D SERVICE			23/11/2019	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Brakes	BRAKE TEST RESULTS			23/11/2019	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Body/CHN/RLR/MN	REPLACED CHAIN ADJUSTMENT BOLT & NUTS		FIT CHAIN , CUT TO LEGENTH & ADJUST TENSION	30/10/2019	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Body/TRL ROLLBK	Trailer Rollback Repairs			30/10/2019	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
			MARK BOLSTER PEG POSITION & WELD IN PLACE																
T378	Rosewood - Workshop	Chassis/BOLSTER	TEST OPERATION ALL GOOD			30/10/2019	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
					ADJUSTING BOLT/NUT THREAD FAILED & STRIPPED OUT UNDER PRESSURE,														
T378	Rosewood - Workshop	Body/CHN/RLR/MN	REPLACED BROCKEN LOAD CHAIN		PARTS ORDERED	29/10/2019	Repair	Completed	Greenfreight Loxeine Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Tumut - Workshop	Elect/TRL LIGHTS	L/H tail light back bar out			29/10/2019	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Tumut Workshop	TRAILER				
T378	Rosewood - Workshop	VehService/DS	D SERVICE			28/10/2019	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Brakes				28/10/2019	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
					SERCURE B/TRAILER IN 'STRECHED OUT' POSITION & READY FOR USE														
T378	Rosewood - Workshop	Body/CHN/RLR/MN	REMOVED BROKEN CHAIN		#LOAD CHAIN BROK WHEN LOADING @ WORKSHOP	28/10/2019	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	VehService/DS	D Service			12/10/2019	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			12/10/2019	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Susp/SHOCK ABS	broken shock L/H/S middle axle			27/09/2019	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Insp/RWC COMP	no number plate light			27/09/2019	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	VehService/DS	D SERVICE			27/09/2019	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Brakes				27/09/2019	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Susp/SHOCK ABS	broken shock absorber			20/09/2019	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Susp/SHOCK ABS	back axle L/H side			20/09/2019	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Susp/SHOCK ABS	repair/replace broken shocker and bolts			20/09/2019	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Elect/INDICATORS	replace LHR indicator assembly. The TRP brand ones it had in it are not robust enough. The wiring broke off at the rear of the light			18/09/2019	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	VehService/DS	D Service			18/09/2019	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Susp/SHOCK ABS	broken shock L/H/S middle axle			18/09/2019	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Insp/RWC COMP	no number plate light			18/09/2019	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Elect/INDICATORS	replace LHR indicator assembly. The TRP brand ones it had in it are not robust enough, the wiring broken off at the rear of the light		refer to work order no.110209	18/09/2019	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	VehService/DS	D Service			31/08/2019	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Brakes				31/08/2019	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Elect/TAIL LIGHT	main light assembly loose		Job previously completed	31/08/2019	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
			R/H park light on back bar out																
T378	Rosewood - Workshop	Elect/TAIL LIGHT	brake lights intermittent			31/08/2019	Fault	Completed	Greenfreight Loxeine Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Body/SCALES	scales not working			31/08/2019	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Elect/TAIL LIGHT	no tail lights		Diagnosed & repaired open circuit in main tail light circuit	31/08/2019	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Susp/SUSPENSION	sling that holds back axle up worn out			31/08/2019	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Elect/TRL LIGHTS	side light on front mudguard not working. side ligh on front mudguard not working		Replaced side lights on front of mudguards both sides & rewired back to main loom	31/08/2019	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Elect/TAIL LIGHT	number plate light not working			31/08/2019	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Tumut - Workshop	Body/CHN/RLR/MN	oil leak on chain winch			30/08/2019	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Tumut Workshop	TRAILER				
T378	Rosewood - Workshop	VehService/DS	D Service			20/08/2019	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			20/08/2019	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	VehService/DS	D Service			06/08/2019	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			06/08/2019	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Elect/TRL LIGHTS	side lgh on front mudguard not working			03/08/2019	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Elect/TAIL LIGHT	number plate light not working			03/08/2019	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	VehService/DS	D Service			23/07/2019	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Brakes				23/07/2019	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Brakes/DAMAGE	Replaced worn & holed section of service brake hose om middle axle			23/07/2019	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	VehService/DS	D service			29/06/2019	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Brakes	Brake test results attached			29/06/2019	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	VehService/DS	Service			16/06/2019	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Elect/WORK LIGHT	fit new worklights			16/06/2019	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Elect/TRL LIGHTS	replace both rear LED side lights			16/06/2019	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Elect/TRL LIGHTS	replace LHR tail light assembly and repair wiring			16/06/2019	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Elect/ELECT P&W	replace 2nd bolster male plug			16/06/2019	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Susp/SUSPENSION	replace LHF s spring mount, alignment plate and u-bolts and nuts			16/06/2019	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			16/06/2019	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	VehService/DS	Service			08/06/2019	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			08/06/2019	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Body/HOUSEKEEP	replace slider pads, bottom and side			30/05/2019	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Chassis/CROSS MBR	re-weld cracks in cross members			30/05/2019	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Brakes/BRK RELINE	relines as needed LHF, LHC & LHR			29/05/2019	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Chassis/FIFTH WHEE	hook up to 1004 and move turntable slide to allow access to work on it			29/05/2019	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Workshop/ABOVE ASSET	set up under awning and hook up to 620			29/05/2019	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Brakes/BRK RELINE	Reline RHF & RHR			28/05/2019	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Brakes/BRK RELINE	reline RHF and RHR			28/05/2019	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	VehService/DS	D Service			15/05/2019	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			15/05/2019	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Albury - Workshop	Brakes/ABS	check ABS faults			11/05/2019	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Albury Workshop	TRAILER				
T378	Rosewood - Workshop	Tyres/DRY TYRES	replace punctured tyre			07/05/2019	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Elect/TAIL LIGHT	check and repair bad tail light connection			07/05/2019	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	VehService/DS	D Service			04/05/2019	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Brakes/BOOSTER	repair booster hose leak near middle axel			04/05/2019	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			04/05/2019	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Body/AIR LEAK	air leak under arnt roll over valve. air trak under anti roll over valve			03/05/2019	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Susp/SUSPENSION	sling that holds back axle up worn out			03/05/2019	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	VehService/DS	D SERVICE COMPLETED			12/04/2019	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Albury - Workshop	Brakes/R.H.M	crack test and reline RHM axle			02/04/2019	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Albury Workshop	TRAILER				
T378	Albury - Workshop	Chassis/BOLSTER	adjusted load chain			02/04/2019	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Albury Workshop	TRAILER				
T378	Albury - Workshop	Chassis/GUZI COIL	all umbilical arm bearings			30/03/2019	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Albury Workshop	TRAILER				
T378	Albury - Workshop	Chassis/GUZI COIL	replaced rear umbilical arm			30/03/2019	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Albury Workshop	TRAILER				
T378	Albury - Workshop	Susp/SUSPENSION	LHR spring wrap			30/03/2019	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Albury Workshop	TRAILER				
T378	Albury - Workshop	Chassis/CROSS MBR	repaired and fitted rear x-bar			30/03/2019	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Albury Workshop	TRAILER				
T378	Albury - Workshop	Chassis/BOLSTER	reqired 1st bolster			30/03/2019	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Albury Workshop	TRAILER				
T378	Albury - Workshop	Chassis/CROSS MBR	weld up cracked web boss			30/03/2019	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Albury Workshop	TRAILER				
T378	Albury - Workshop	Chassis/CROSS MBR	weld up x-member gussets			30/03/2019	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Albury Workshop	TRAILER				
			tightened female coupling fitting																
T378	Albury - Workshop	Elect/ELECT P&W	reolaced female couoline			29/03/2019	Repair	Completed	Greenfreight Loxeine Vic	ElpidPW	Mt Gambier	GTK	376815	Albury Workshop	TRAILER				
T378	Albury - Workshop	Body/MUDGUARDS	replaced lift axle mudflap bolts			29/03/2019	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Albury Workshop	TRAILER				
			replaced chain pully bearings																
			removed 8 chain links																
			welded top cross bar and replaced all bolts																
			welded cracks in mudguards																
T378	Albury - Workshop	Body/CHN/RLR/MN	1st bolster wirine for lights			29/03/2019	Repair	Completed	Greenfreight Loxeine Vic	ElpidPW	Mt Gambier	GTK	376815	Albury Workshop	TRAILER				
T378	Albury - Workshop	Susp/SHOCK ABS	RHF & RHR shockers			27/03/2019	Repair	Completed	Greenfreight Loxeine Vic	ElpidPW	Mt Gambier	GTK	376815	Albury Workshop	TRAILER				
T378	Albury - Workshop	Body/AIR BAG	RHF airbag			27/03/2019	Repair	Completed	Greenfreight Loxeine Vic	ElpidPW	Mt Gambier	GTK	376815	Albury Workshop	TRAILER				
T378	Albury - Workshop	Susp/SPRING HANG	RHR spring wrap			27/03/2019	Repair	Completed	Greenfreight Loxeine Vic	ElpidPW	Mt Gambier	GTK	376815	Albury Workshop	TRAILER				
T378	Albury - Workshop	Brakes/BOOSTER	replaced rear b/boosters link hose			27/03/2019	Repair	Completed	Greenfreight Loxeine Vic	ElpidPW	Mt Gambier	GTK	376815	Albury Workshop	TRAILER				
T378	Albury - Workshop	Body/CHN/RLR/MN	replaced load chain anchor bolts			27/03/2019	Repair	Completed	Greenfreight Loxeine Vic	ElpidPW	Mt Gambier	GTK	376815	Albury Workshop	TRAILER				
T378	Albury - Workshop	Body/CHN/RLR/MN	replaced light bar anchor bolts			27/03/2019	Repair	Completed	Greenfreight Loxeine Vic	ElpidPW	Mt Gambier	GTK	376815	Albury Workshop	TRAILER				
T378	Albury - Workshop	Body/CHN/RLR/MN	replaced HCV and rods			27/03/2019	Repair	Completed	Greenfreight Loxeine Vic	ElpidPW	Mt Gambier	GTK	376815	Albury Workshop	TRAILER				
T378	Albury - Workshop	Body/MOUNTS	replaced trunion mount bolts			27/03/2019	Repair	Completed	Greenfreight Loxeine Vic	ElpidPW	Mt Gambier	GTK	376815	Albury Workshop	TRAILER				
T378	Albury - Workshop	Body/MOUNTS	repaired rear x-member (cracked)			27/03/2019	Repair	Completed	Greenfreight Loxeine Vic	ElpidPW	Mt Gambier	GTK	376815	Albury Workshop	TRAILER				
T378	Albury - Workshop	Body/MUDGUARDS	weld cracked guards			27/03/2019	Repair	Completed	Greenfreight Loxeine Vic	ElpidPW	Mt Gambier	GTK	376815	Albury Workshop	TRAILER				
T378	Albury - Workshop	Workshop/ABOVE ASSET	hook up 1012 and put in workshop			26/03/2019	Repair	Completed	Greenfreight Loxeine Vic	ElpidPW	Mt Gambier	GTK	376815	Albury Workshop	TRAILER				
T378	Wodonga - Workshop	Tyres/FITMENT	Job Added From Invoice			23/03/2019 175378	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
T378	Wodonga - Workshop	Tyres/CLEANSION	Job Added From Invoice			23/03/2019 175378	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Wodonga Workshop	TRAILER				
			check over																
			replaced 2nd winch strap																
T378	Albury - Workshop	Chassis/WINCH/STRP	reolaced female air couoline			21/03/2019	Repair	Completed	Greenfreight Loxeine Vic	ElpidPW	Mt Gambier	GTK	376815	Albury Workshop	TRAILER				
			repaired reverse light wiring LH side																
			repaired indicator light wiring LH side																
			replaced missing side marker LHF																
T378	Rosewood - Workshop	Elect/TRL LIGHTS	cleaned out light plug and socket			19/03/2019	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Elect/TRL LIGHTS	front L/H mudguard light missing			16/03/2019	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	VehService/DS	Service			08/03/2019	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			08/03/2019	Repair	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	VehService/DS	D Service			26/02/2019	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	VehService/DS	D Service		D SERVICE COMPLETED	26/02/2019	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	Brakes/BRAKE ADJ	adjust brakes			14/02/2019	Fault	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376815	Rosewood Workshop	TRAILER				
T378	Rosewood - Workshop	VehService/DS	Service			14/02/2019	Service	Completed	Greenfreight Logging Vic	ElpidPW	Mt Gambier	GTK	376

| | | |

T378	Albury - Workshop	Chassis\WINCH\STRP	replaced spacer in front winch mount	make winch mount spacer for front winch	14/03/2018		Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Albury Workshop	TRAILER
T378	Albury - Workshop	Chassis\BOLSTER	Weld new bolster catches on load chain and test okay/		06/03/2018		Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Albury Workshop	TRAILER
T378	Albury - Workshop	Brakes\ABS	A.B.S light on	checked for active codes (ok)	04/03/2018		Fault	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Albury Workshop	TRAILER
T378	Myrtleford - Workshop	Tyres\PRES CHECK	Job Added From Invoice		24/02/2018	32057	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Tyres\RUN OUT	Job Added From Invoice		24/02/2018	32057	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	grease turntable and hok up cksech and repair lights	23/02/2018	32059	Service	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This.Job		23/02/2018	32059	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Brakes\BOOSTER	move all 6x bolsters to bottom hole on slack adjuster (125m) and move all 6 brake boosters to bottom hole (125)		22/02/2018	32057	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Chassis\BOLSTER	Move Bolster Gap to 2.9		02/12/2017		Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Chassis\WINCH\STRP	Fit 2 x Air Winches		02/12/2017		Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Elect\TAIL LIGHT	Repair LH & RH front side lights		30/11/2017	32057	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Elect\TAIL LIGHT	Repair LH/ bolster light		30/11/2017	32057	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Susp\HOUSEKEEP	Replace RHF & RHR shocker straps		30/11/2017	32057	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Susp\SHOCK ABS	Replace LHR bottom shocker bush		30/11/2017	32057	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Body\AIR FITTIN	Repair air leak at service coupling		30/11/2017	32057	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Chassis\MUDGUARDS	RH mudguard loose		30/11/2017	32057	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Chassis\MUDGUARDS	Repair LH mudguard		30/11/2017	32057	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist		28/11/2017	32053	Service	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This.Job		28/11/2017	32053	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Tyres	Job Added From Invoice		28/11/2017	0	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice		28/11/2017	0	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice		28/11/2017	0	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
				4 shocker straps											
T378	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist	reolaced LHF shocker bolt	17/11/2017	26886	Service	Comeleted	Greenfreight Loxeine Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This.Job		17/11/2017	26886	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Tyres\RUN OUT	Job Added From Invoice		15/11/2017	2112	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Tyres\RUN OUT	Job Added From Invoice		15/11/2017	23608	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection as per checklist		03/11/2017	21120	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist		03/11/2017	21120	Service	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This.Job		03/11/2017	21120	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Tyres	Job Added From Invoice		01/11/2017	17192	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Chassis\WINCH\STRP	need handle on winch		27/10/2017	17850	Fault	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist		24/10/2017	15775	Service	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This.Job		24/10/2017	15775	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		11/10/2017	10582	Service	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This.Job		11/10/2017	10582	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist		28/09/2017	5157	Service	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This.Job		28/09/2017	5157	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
				repair airbag leak middle axle											
T378	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	tahtten RHM slve bolt	19/09/2017		Service	Comeleted	Greenfreight Loxeine Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This.Job		19/09/2017		Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Body\WHL HUB	Fit new hubo meter		13/09/2017		Fault	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Body\WHL HUB	tighten hub caps		12/09/2017		Fault	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Insp\RWC CDMP	fit ID plates		12/09/2017		Fault	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Insp\RWC CDMP	fit new number plate		12/09/2017		Fault	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Albury - Workshop	DriveLine\WHL HUB	REPLACE RHM HUB CAP.		12/09/2017		Fault	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Albury Workshop	TRAILER
			Fit EBS Kit to front & rear axles												
			L3087(Brankos)												
T378	Myrtleford - Workshop	Brakes\EBS Kit	L3146 (albury truck & trl \L3162 Imaw)		08/09/2017	159348	Repair	Comeleted	Greenfreight Loxeine Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
				Replace service arm bearings x 4											
T378	Myrtleford - Workshop	Chassis\FIFTH WHEE	Replace T/Table slide pads & bolts	L3243	06/09/2017	159348	Repair	Comeleted	Greenfreight Loxeine Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Chassis\FIFTH WHEE	Replace T/Table slide lock pads		06/09/2017	159348	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
			Replace load chain tensioner bearings & hammer locks												
T378	Myrtleford - Workshop	Body\CHN/RLR/MN	L3243		06/09/2017	159348	Repair	Comeleted	Greenfreight Loxeine Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Chassis\BOLSTER	Check & repair bolster slides	Weld cracks in bolsters	06/09/2017	159348	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Brakes\EBS Kit	Test & Programme EBS		31/08/2017	159348	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Brakes\EBS Kit	Check & Engineer Trailer		31/08/2017	159348	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
				check short in LHS tail light bar											
				rewire tail bar wiring on RHS											
T378	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist	hook up to T379 and Load TBL	31/08/2017	159348	Service	Completed	Greenfreight Loxeine Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This.Job		31/08/2017	159348	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Brakes\BRK RELINE	Crack test & reline all wheels		25/08/2017	159343	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Elect\TRL LIGHTS	check plug on 2nd bolster light		28/08/2017	157464	Fault	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		23/08/2017	155109	Service	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This.Job		23/08/2017	155109	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		15/08/2017	151228	Service	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This.Job		15/08/2017	151228	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Tyres	Job Added From Invoice		14/08/2017	0	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice		14/08/2017	0	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice		14/08/2017	0	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		01/08/2017	145068	Service	Completed	Greenfreight Loxeine Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This.Job		01/08/2017	145068	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		24/05/2017	141250	Service	Completed	Greenfreight Loxeine Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This.Job		24/05/2017	141250	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Body\CHN/RLR/MN	repair safety chain eye bolt		24/05/2017		Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Tyres\PRES CHECK	Job Added From Invoice		20/05/2017	48672	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Tyres\RUN OUT	Job Added From Invoice		20/05/2017	48672	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
				tighten RHM spring eye bolt											
T378	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist	tahtten bolts LHS chain adiuster bracket	12/05/2017	135643	Service	Comeleted	Greenfreight Loxeine Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This.Job		12/05/2017	135643	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist	repair R/H tail light and reverse light wiring	03/05/2017	130862	Service	Completed	Greenfreight Loxeine Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This.Job		03/05/2017	130862	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Tyres\TP11	Job Added From Invoice		27/04/2017	0	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Tyres\TP21	Job Added From Invoice		27/04/2017	0	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Susp\AIR BAG	fix airline to airbag RHS front		25/04/2017	127812	Fault	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Susp\AIR BAG	Replace RHM air bag		20/04/2017	125889	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Susp\HOUSEKEEP	replace LHR spring eye bush		19/04/2017		Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
				replaced LHR spring eye bush											
T378	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist	RHM airbae leak	19/04/2017		Service	Completed	Greenfreight Loxeine Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This.Job		19/04/2017		Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Tyres\TP21	Job Added From Invoice		05/04/2017	110903	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		05/04/2017	121291	Service	Completed	Greenfreight Loxeine Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This.Job		05/04/2017	121291	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Chassis\WINCH\STRP	fit new winch strap and locking arm on first winch		01/04/2017	120192	Fault	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		22/03/2017	116138	Service	Completed	Greenfreight Loxeine Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This.Job		22/03/2017	116138	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Tyres\TP11	Job Added From Invoice		21/03/2017	0	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Body\MOUNTS	Tighten tail light bar mount bolts		18/03/2017	116138	Fault	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Tyres\TP11	Job Added From Invoice		16/03/2017	0	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		08/03/2017	111667	Service	Completed	Greenfreight Loxeine Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This.Job		08/03/2017	111667	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Tyres\TP15	Job Added From Invoice		01/03/2017	103417	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Tyres\TP21	Job Added From Invoice		01/03/2017	96768	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Tyres\TP22	Job Added From Invoice		01/03/2017	96768	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		23/02/2017	106748	Service	Completed	Greenfreight Loxeine Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This.Job		23/02/2017	106748	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist	repair 2nd bolster light socket wiring	11/02/2017	101960	Service	Completed	Greenfreight Loxeine Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This.Job		11/02/2017	101960	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Susp\AIR BAG	replace RHR airbag		08/02/2017		Fault	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Tyres\TP17	Job Added From Invoice		01/02/2017	62751	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Chassis\WINCH\STRP	first winch strap handle		01/02/2017		Fault	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		01/02/2017		Service	Completed	Greenfreight Loxeine Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This.Job		01/02/2017		Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Tyres\TP18	Job Added From Invoice		31/01/2017	86844	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Tyres\TP15	Job Added From Invoice		29/01/2017	87651	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		19/01/2017	92219	Service	Completed	Greenfreight Loxeine Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This.Job		19/01/2017	92219	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Elect\TRL LIGHTS	repair trailer lights		10/01/2017		Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist	tighten & replace bolts on tail light bar	06/01/2017	87651	Service	Completed	Greenfreight Loxeine Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This.Job		06/01/2017	87651	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Tyres\TP22	Job Added From Invoice		31/12/2016	0	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Tyres\TP19	Job Added From Invoice		30/12/2016	81174	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Tyres\TP12	Job Added From Invoice		29/12/2016	77986	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Elect\ELECT P&W	repair turntable lock (call out)		17/12/2016	82720	Fault	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		16/12/2016		Service	Completed	Greenfreight Loxeine Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This.Job		16/12/2016		Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
				need to wire up plug											
T378	Myrtleford - Workshop	Elect\TRL LIGHTS	wire pulled out of plue RHS		10/12/2016	80156	Fault	Completed	Greenfreight Loxeine Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Elect\TRL LIGHTS	short in plug		07/12/2016	78529	Fault	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Elect\TRL LIGHTS	no side lights		07/12/2016	78529	Fault	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Elect\TRL LIGHTS	wire up guard side light RHF		07/12/2016	78529	Fault	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		06/12/2016	77986	Service	Completed	Greenfreight Loxeine Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This.Job		06/12/2016	77986	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Chassis\HOUSEKEEP	repair cracks		17/11/2016		Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Chassis\FIFTH WHEE	fit new kingpin		17/11/2016		Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Chassis\FIFTH WHEE	fit jaw kit + foot bushes to T/Table		17/11/2016		Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Body\DAMAGE	remove twist in trailer		17/11/2016		Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection	Insp\ANN INSP-deactivated 15/5/2024 3:43:44 am utc	17/11/2016	14698	PreventativeMaintenance	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		17/11/2016	14698	Service	Completed	Greenfreight Loxeine Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This.Job		17/11/2016	14698	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		18/10/2016	74146	Service	Completed	Greenfreight Loxeine Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This.Job		18/10/2016	74146	Repair	Completed	Greenfreight Logging Vic	Elpd6PW	Mt Gambier	GTK	370815	Myrtleford Workshop	TRAILER
T378	Myrtleford - Work

			Tighten loose LHM shocker bolt RHM bolt shocker mount																
T378	Myrtleford - Workshop	Susp\SHOCK ABS	Tighten loose LHM toe shocker bolt	Complete		03/08/2016	49690	Repair	Completed	Greenfreight Loxeine Vic	ElapsPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	Chassis\FIFTH WHEE	Check & grease turn table	Complete		03/08/2016	49690	Repair	Completed	Greenfreight Logging Vic	ElapsPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
			Replace LHF spring eye bush & wrap																
T378	Myrtleford - Workshop	Susp\SPRING PACK	Replace LHM serrine eye bush	Complete		03/08/2016	49690	Repair	Completed	Greenfreight Loxeine Vic	ElapsPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	Body\TOOLBOX	Drill holes in bottom of tool box	Complete		03/08/2016	49690	Repair	Completed	Greenfreight Logging Vic	ElapsPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	Elect\TRL LIGHTS	Check & repair lights - not working	Complete		03/08/2016	49690	Repair	Completed	Greenfreight Logging Vic	ElapsPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
			Adjust load chain																
T378	Myrtleford - Workshop	Body\CHN/RUR/MN	Replace worn chain rollers	Complete		03/08/2016	49690	Repair	Completed	Greenfreight Loxeine Vic	ElapsPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	Brakes\AIR LEAK	Replace worn airlines	Complete		01/08/2016	49690	Repair	Completed	Greenfreight Logging Vic	ElapsPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	Elect\TRL LIGHTS	repair tail light bar			29/07/2016	49690	Repair	Completed	Greenfreight Logging Vic	ElapsPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	Body\HOUSEKEEP	tidy up airlines & hydraulic lines at turntable			29/07/2016	49690	Repair	Completed	Greenfreight Logging Vic	ElapsPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			26/07/2016	49690	Service	Completed	Greenfreight Logging Vic	ElapsPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This.Job			26/07/2016	49690	Repair	Completed	Greenfreight Logging Vic	ElapsPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			14/07/2016	45509	Service	Completed	Greenfreight Logging Vic	ElapsPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This.Job			14/07/2016	45509	Repair	Completed	Greenfreight Logging Vic	ElapsPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	Tyres\TP17	Job Added From Invoice			05/07/2016	40375	Repair	Completed	Greenfreight Logging Vic	ElapsPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	Tyres\TP17	Job Added From Invoice			05/07/2016	0	Repair	Completed	Greenfreight Logging Vic	ElapsPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	Tyres\TP17	Job Added From Invoice			05/07/2016	0	Repair	Completed	Greenfreight Logging Vic	ElapsPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	Tyres\TP16	Job Added From Invoice			05/07/2016	40375	Repair	Completed	Greenfreight Logging Vic	ElapsPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	Tyres\TP19	Job Added From Invoice			01/07/2016	41123	Repair	Completed	Greenfreight Logging Vic	ElapsPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	Tyres\TP19	Job Added From Invoice			01/07/2016	0	Repair	Completed	Greenfreight Logging Vic	ElapsPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	Tyres\TP19	Job Added From Invoice			01/07/2016	0	Repair	Completed	Greenfreight Logging Vic	ElapsPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	Chassis\AIR LEAK	Fit seal kit to slide lock ram	fit new slide lock ram		29/06/2016	41123	Repair	Completed	Greenfreight Logging Vic	ElapsPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	Susp\AIR BAG	Replace LHF airbag			29/06/2016	41123	Repair	Completed	Greenfreight Logging Vic	ElapsPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist	change 2 flat tyres		28/06/2016	40379	Service	Completed	Greenfreight Logging Vic	ElapsPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This.Job			28/06/2016	40379	Repair	Completed	Greenfreight Logging Vic	ElapsPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	Tyres\TP18	Job Added From Invoice			15/06/2016	33361	Repair	Completed	Greenfreight Logging Vic	ElapsPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	Tyres\TP18	Job Added From Invoice			15/06/2016	0	Repair	Completed	Greenfreight Logging Vic	ElapsPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	Tyres\TP18	Job Added From Invoice			15/06/2016	0	Repair	Completed	Greenfreight Logging Vic	ElapsPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			15/06/2016	35663	Service	Completed	Greenfreight Logging Vic	ElapsPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This.Job			15/06/2016	35663	Repair	Completed	Greenfreight Logging Vic	ElapsPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			01/06/2016		Service	Completed	Greenfreight Logging Vic	ElapsPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This.Job			01/06/2016		Repair	Completed	Greenfreight Logging Vic	ElapsPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	Elect\TRL LIGHTS	Repair side light on mudguard	Complete		01/06/2016		Repair	Completed	Greenfreight Logging Vic	ElapsPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	Tyres\TP21	Job Added From Invoice			27/05/2016	26984	Repair	Completed	Greenfreight Logging Vic	ElapsPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	Tyres\TP21	Job Added From Invoice			27/05/2016	0	Repair	Completed	Greenfreight Logging Vic	ElapsPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	Tyres\TP21	Job Added From Invoice			27/05/2016	0	Repair	Completed	Greenfreight Logging Vic	ElapsPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	Tyres\DAMAGE	repair tyre damage			24/05/2016		Fault	Completed	Greenfreight Logging Vic	ElapsPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	Elect\TAIL LIGHT	repair tail light wiring			21/05/2016	26984	Fault	Completed	Greenfreight Logging Vic	ElapsPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			19/05/2016	25940	Service	Completed	Greenfreight Logging Vic	ElapsPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This.Job			19/05/2016	25940	Repair	Completed	Greenfreight Logging Vic	ElapsPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	Elect\TAIL LIGHT	replace 2nd bolster wire plugs	complete		17/05/2016	25517	Repair	Completed	Greenfreight Logging Vic	ElapsPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	Body\CHN/RUR/MN	Adjust Load chain	complete		17/05/2016	25517	Repair	Completed	Greenfreight Logging Vic	ElapsPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	Susp\HOUSEKEEP	check over suspension	complete		17/05/2016	25517	Repair	Completed	Greenfreight Logging Vic	ElapsPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	Body\CHN/RUR/MN	Remove Twist in Load Chain & Adjust			05/05/2016	21232	Repair	Completed	Greenfreight Logging Vic	ElapsPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	Chassis\HOUSEKEEP	Test Load & Unload trailers	Complete		04/05/2016	21234	Fault	Completed	Greenfreight Logging Vic	ElapsPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			04/05/2016	21232	Service	Completed	Greenfreight Logging Vic	ElapsPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This.Job			04/05/2016	21232	Repair	Completed	Greenfreight Logging Vic	ElapsPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	Elect\TRL LIGHTS	check lights etc fit 2 spare wheels on trailer			23/04/2016	17688	Repair	Completed	Greenfreight Logging Vic	ElapsPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	Tyres\TP20	Job Added From Invoice			23/04/2016	13120	Repair	Completed	Greenfreight Logging Vic	ElapsPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	Tyres\TP21	Job Added From Invoice			22/04/2016	0	Repair	Completed	Greenfreight Logging Vic	ElapsPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	Brakes\BRK RELINE	Crack test & reline all wheels	grease & check turntable		21/04/2016	17686	Repair	Completed	Greenfreight Logging Vic	ElapsPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	Chassis\AIR LEAK	Replace air tank drain cock			21/04/2016	17686	Repair	Completed	Greenfreight Logging Vic	ElapsPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			20/04/2016		Service	Completed	Greenfreight Logging Vic	ElapsPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This.Job			20/04/2016		Repair	Completed	Greenfreight Logging Vic	ElapsPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	Body\HOUSEKEEP	repair tool box latch			12/04/2016	14383	Fault	Completed	Greenfreight Logging Vic	ElapsPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	Elect\TRL LIGHTS	RHR side light not working			08/04/2016	13119	Fault	Completed	Greenfreight Logging Vic	ElapsPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			08/04/2016	13119	Service	Completed	Greenfreight Logging Vic	ElapsPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This.Job			08/04/2016	13119	Repair	Completed	Greenfreight Logging Vic	ElapsPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	Chassis\WINCH/STRP	broken lock on front winch			04/04/2016	11106	Fault	Completed	Greenfreight Logging Vic	ElapsPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	Elect\TAIL LIGHT	park light out - LHS	check and repair LHS park light		02/04/2016	10129	Fault	Completed	Greenfreight Logging Vic	ElapsPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	Tyres\TP22	Job Added From Invoice			01/04/2016	9087	Repair	Completed	Greenfreight Logging Vic	ElapsPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	Tyres\TP22	Job Added From Invoice			01/04/2016	0	Repair	Completed	Greenfreight Logging Vic	ElapsPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	Tyres\TP22	Job Added From Invoice			01/04/2016	0	Repair	Completed	Greenfreight Logging Vic	ElapsPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	Brakes\BOOSTER	RHR brake booster			31/03/2016	667402	Fault	Completed	Greenfreight Logging Vic	ElapsPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	Elect\TAIL LIGHT	repair shorted wiring in tail light bar			29/03/2016		Repair	Completed	Greenfreight Logging Vic	ElapsPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	Dr Cab\Bed\EJECT P&W	test pneumatics and hydraulics			29/03/2016		Repair	Completed	Greenfreight Logging Vic	ElapsPW	Mt Gambier	GTK	376815	Myrtleford Workshop	TRAILER			
T378	Myrtleford - Workshop	Tyres\TP11	Job Added From Invoice			23/03/2016	192719