EquipmentName	Workshop	CodeAndSubCode	Description	Schedule	CompletionComments	DateDone	DistanceDone	Worktype	Workstate	EquipmentOwner	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
T379	Myrtleford - Workshop	Body\DAMAGE	unload trailer from roll over			08/05/2025	233545	Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER
T379	Myrtleford - Workshop	Tyres\TP5+6	Tyres\TP5+6			27/09/2024	233545	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	BEAUREPAIRES - 3	TRAILER
T379	Myrtleford - Workshop	Tyres\TP9+10	Tyres\TP9+10			21/09/2024	233545	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	BEAUREPAIRES - 3	TRAILER
T379	Myrtleford - Workshop	VehService\DS	VehService\DS	VehService\DS		14/09/2024	233545	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	MM DIESEL - 3	TRAILER
T379	Myrtleford - Workshop	Tyres\TP11+12	Tyres\TP11+12			27/06/2024	233545	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	BEAUREPAIRES - 3	TRAILER
T379	Myrtleford - Workshop	Tyres\TP11+12	Tyres\TP11+12			27/06/2024	233545	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	BEAUREPAIRES - 3	TRAILER
T379	Myrtleford - Workshop	VehService\DS	VehService\DS	VehService\DS		19/06/2024	233545	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	QT DIESEL SERVICES - 3	TRAILER
T379	Myrtleford - Workshop	VehService\DS	D Service PO #L048261	VehService\DS		05/06/2024	233545	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	QT DIESEL SERVICES - 3	TRAILER
T379	Myrtleford - Workshop	VehService\DS	VehService\DS	VehService\DS		01/06/2024	233545	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	QT DIESEL SERVICES - 3	TRAILER
T379	Myrtleford - Workshop	Tyres\TP9+10	Tyres\TP9+10			21/05/2024	233545	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	BEAUREPAIRES - 3	TRAILER
T379	Myrtleford - Workshop	Tyres\TP03	Tyres\TP03 Service As Per Attached Checklist			21/05/2024	233545	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	BEAUREPAIRES - 3	TRAILER
T379	Myrtleford - Workshop	VehService\DS	PO# L085500			27/04/2024		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	QT DIESEL SERVICES - 3	TRAILER
T379	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job Service As Per Attached Checklist			27/04/2024		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	QT DIESEL SERVICES - 3	TRAILER
T379	Myrtleford - Workshop	VehService\DS	PO# L084943			23/03/2024		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	QT DIESEL SERVICES - 3	TRAILER
T379	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			23/03/2024		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	QT DIESEL SERVICES - 3	TRAILER
T379	Wodonga - Workshop	Elect\ELECT P&W	SCALES PLAYING UP AT TIMES. READING HEAVY.			23/03/2024		Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Elect\ELECT P&W	SCALES NOT READING CORRECTLY. SPIN BOLSTER PINS			23/03/2024		Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Myrtleford - Workshop	Chassis\BOLSTER	FIT NEW SLING STRAPS TO LHR & RHF			22/03/2024		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	QT DIESEL SERVICES - 3	TRAILER
T379	Myrtleford - Workshop	Tyres\TP1+2	Tyre Position 1 + 2 Service As Per Attached Checklist			19/03/2024		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER
T379	Myrtleford - Workshop	VehService\DS	PO# L084626			07/03/2024		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	QT DIESEL SERVICES - 3	TRAILER
T379	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			07/03/2024		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	QT DIESEL SERVICES - 3	TRAILER
T379	Myrtleford - Workshop	Tyres\TP3+4	Tyre Position 3 + 4			18/02/2024		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER
T379	Myrtleford - Workshop	Steering\WHEEL ALGN	Wheel Alignment			07/02/2024		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	BIG WHEELS TRUCK ALIGNMENT - 3	TRAILER
T379	Myrtleford - Workshop	Susp\AXLES	Remove axle from trailer straightin and refit			07/02/2024		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	BIG WHEELS TRUCK ALIGNMENT - 3	TRAILER
T379	Myrtleford - Workshop	Tyres\TP3+4	Tyre Position 3 + 4			30/01/2024		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER
T379	Albury - Workshop	Tyres\FITMENT	3-4			03/01/2024		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER
T379	Wodonga - Workshop	Brakes\BRK RELINE	FULL RELINE.		REPLACED ALL S-CAMS AND WHEEL BEARINGS. REPAIRED EBS FAULTS.	31/12/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Body\MUDGUARDS	REPLACED RH STRETCHGUARD AND REPAIRED OUTRIGGER. WELDED CRACKS.			31/12/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Chassis\WINCH/STRP	REPLACED 4 STRAPS.			31/12/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			28/12/2023		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			28/12/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Elect\ELECT P&W	NO SCALES ON TRAILER.			28/12/2023		Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Susp\AIR BAG	BLOWN AIRBAG RHR.		OK	28/12/2023		Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection	Insp\ANN INSP-deacti		28/12/2023		PreventativeMaintenance	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Brakes\AIR LEAK	Brakes stuck on			21/12/2023		Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Susp\AIR BAG	REPLACED LR AIRBAG.			22/12/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			13/11/2023	233545	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			13/11/2023	233545	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Chassis\EXTE TU	WINCH NO.5 LEAKS AIR BADLY.			13/11/2023	233545	Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Elect\ELECT P&W	3RD BAY SCALERS NOT GIVING CORRECT READINGS.			13/11/2023	233545	Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Elect\ELECT P&W	Back Bay Scales Works Sometimes Service As Per Attached Checklist (TCTC)			13/11/2023	233545	Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Albury - Workshop	VehService\DS	Purchase Order Number: T080894			09/09/2023		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			09/09/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Albury - Workshop	Elect\ELECT P&W	NO SCALES ON TRAILER.			09/09/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Myrtleford - Workshop	Brakes\BOOSTER	BRAKE BOOSTER R-L.		REPLACED RR BOOSTER.	08/09/2023		Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER
T379	Myrtleford - Workshop	Susp\AIR BAG	REAR AIRBAG 1ST AXLE L/S.			08/09/2023		Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER
T379	Myrtleford - Workshop	DrivLine\WHEEL BRGS	ADJUST WHEEL BEARING.			08/09/2023		Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER
T379	Albury - Workshop	Tyres\PRES CHECK	1-12 Service As Per Attached Checklist (TCTC)			07/09/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER
T379	Albury - Workshop	VehService\DS	Purchase Order Number: T080790			05/09/2023	233545	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			05/09/2023	233545	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Albury - Workshop	Elect\ELECT P&W	SCALES OUT.			05/09/2023	233545	Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Albury - Workshop	Tyres\TP3+4	Tyre Position 3 + 4			05/09/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER
T379	Albury - Workshop	Tyres\TP7+8	Tyre Position 7 + 8			29/08/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER
T379	Wodonga - Workshop	Elect\ELECT P&W	BRAKE LIGHTS SHORTING WITH TAIL LIGHTS.			25/08/2023		Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Elect\INDICATORS	No RH Indicator			25/08/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Albury - Workshop	Tyres\TP9+10	Tyre Position 9 + 10			23/08/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER
T379	Albury - Workshop	Tyres\Re-Tor	3-4			23/08/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER
T379	Albury - Workshop	Tyres\TP3+4	Tyre Position 3 + 4 Service As Per Attached Checklist (TCTC)			22/08/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER
T379	Wodonga - Workshop	VehService\DS	Purchase Order Number: T080225			11/08/2023	233545	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			11/08/2023	233545	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Albury - Workshop	Chassis\WINCH/STRP	Winches & Straps			09/08/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER
T379	Albury - Workshop	Tyres\TP5+6	Tyre Position 5 + 6			08/08/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER
T379	Albury - Workshop	Tyres\TP3+4	Tyre Position 3 + 4			04/08/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER
T379	Albury - Workshop	Tyres\TP05	runout			04/08/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER
T379	Albury - Workshop	Tyres\TP07	runout			04/08/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER
T379	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			02/08/2023		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			02/08/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Elect\ELECT P&W	BRAKE LIGHTS SHORTING WITH TAIL LIGHTS.			02/08/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			25/07/2023	233545	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			25/07/2023	233545	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Body\MUDGUARDS	STRAIGHTEN AND WELD RF GUARD.			25/07/2023	233545	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Elect\WORK LIGHT	NO WORK LIGHTS.			25/07/2023	233545	Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Tyres\IMPACT	Replaced Damaged Pos4 Rim & Tyre			19/07/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Body\DAMAGE	Replaced Broken/Missng RHF Outrigger Bolts		STRAIGHTENED OUTRIGGER & FIT BOLTS.	19/07/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Susp\AXLES	Inspect RHF Axle For Damage		CHECKED. OK.	19/07/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Body\MUDGUARDS	STRAIGHTEN AND WELD RF GUARD.			19/07/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			19/07/2023		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			19/07/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Elect\WORK LIGHT	WORK LIGHTS NOT WORKING.			19/07/2023		Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Albury - Workshop	Tyres\TP03	Tyre Position 3 The following breakdown repair for Greenfreight Logging Pty Ltd, to a Elphinstone B-Trailer Truck, vin#6L9T25000K2EL0389, registration#337682.S & fleet number fleet number#T375 included: . * Customer contacted dealership technician with information regarding breakdown * Customer reported that trailer brakes were smoking * Technician sourced additional parts * Technician travelled to breakdown location, Mullengandra, NSW * Checked all wheels on trailer to diagnose * Located RHS rear axle hub adjustment out * Ballast axle * Check & adjust to specification * Returned trailer to service & followed for period * Rechecked & confirmed no issues * Returned trailer to service			19/07/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER
T379	Albury - Workshop	Brakes\BREAKDOWN	* Technician returned home			17/07/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER
T379	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			15/07/2023		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			15/07/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Elect\ELECT P&W	SCALES OUT.			15/07/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Elect\ELECT P&W	SCALES PERFORMING ERRATICALLY.		Refer job # 414722	15/07/2023		Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Brakes\BRK RELINE	Brake Reline			08/07/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Brakes\AIR FITTIN	UNHOOKED T378. HAD TROUBLE WITH COUPLINGS.			07/07/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		REPLACED NKP, WORK LIGHT AND PARK LIGHT.	23/06/2023		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			23/06/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Elect\ELECT P&W	SCALES OUT.			23/06/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist			17/06/2023		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			17/06/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Chassis\EXTE TU	Needs new pull cord for rear strap release.			17/06/2023		Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			07/06/2023		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			07/06/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Elect\TRL LIGHTS	No Clearance lights			07/06/2023		Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Chassis\FIFTH WHEE	FITTED TURNTABLE BLOCK. HOOKED UP T378.			27/05/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		PARKED. UNHOOKED.	24/05/2023		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			24/05/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Elect\ELECT P&W	SCALES OUT.			24/05/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Brakes\BRK RELINE	Reline Right Middel Axle			24/05/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			03/05/2023		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			03/05/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Albury - Workshop	VehService\DS	Service As Per Attached Checklist			21/04/2023		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			21/04/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Albury - Workshop	DrivLine\WHEEL BRGS	REAR AXLE HOT (WHEEL MOVING & MAYBE BEARING) BOTH SIDES. CALL GRAHAM WODONGA.			21/04/2023		Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Albury - Workshop	Elect\ELECT P&W	SCALES NOT WORK/ FAULT.			21/04/2023		Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER

T379	Albury - Workshop	Elect\ELECT P&W	LIGHTS NOT WORKING.			21/04/2023		Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Albury - Workshop	Elect\ELECT P&W	SCALES NOT WORK/FAULT.			21/04/2023		Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Albury - Workshop	Chassis\WINCH/STRP	STRAPS NEED REPLACING.			21/04/2023		Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Albury - Workshop	Elect\ELECT P&W	WORK LIGHTS FLASH ON/OFF.			21/04/2023		Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Albury - Workshop	Elect\WORK LIGHT	WORK LIGHTS FLASH ON/OFF.			21/04/2023		Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
			CRACK TEST PEGS AS REQUIRED													
			NO CRACKS FOUND													
T379	Albury - Workshop	Chassis\BOLSTER	REFIT PEGS WITH NEW BOLTS			21/04/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			12/04/2023		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			12/04/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	DrivLine\WHEEL BRGS	REAR AXLE HOT (WHEEL MOVING & MAYBE BEARING) BOTH SIDES. CALL GRAHAM WODONGA.			12/04/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Elect\ELECT P&W	SCALES NOT WORK/ FAULT.			12/04/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Elect\ELECT P&W	LIGHTS NOT WORKING.			12/04/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Elect\ELECT P&W	SCALES NOT WORK/FAULT.			12/04/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Chassis\WINCH/STRP	STRAPS NEED REPLACING.			12/04/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Albury - Workshop	Tyres\TP9+10	Tyre Position 9 + 10			06/04/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER
T379	Albury - Workshop	Tyres\TP11+12	Tyre Position 11 + 12			06/04/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER
T379	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			05/04/2023		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			05/04/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	DrivLine\WHEEL BRGS	REAR AXLE HOT (WHEEL MOVING & MAYBE BEARING) BOTH SIDES. CALL GRAHAM WODONGA.			05/04/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Elect\ELECT P&W	SCALES NOT WORK/ FAULT.			05/04/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Elect\ELECT P&W	LIGHTS NOT WORKING.			05/04/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Elect\ELECT P&W	SCALES NOT WORK/FAULT.			05/04/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Chassis\WINCH/STRP	STRAPS NEED REPLACING.			05/04/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Body\CHN/RLR/MIN	Tiedown chain short		Replaced hold down chain & parked.	30/03/2023		Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		REPAIRED RH TAIL LIGHT WIRING.	29/03/2023		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			29/03/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	DrivLine\WHEEL BRGS	REAR AXLE HOT (WHEEL MOVING & MAYBE BEARING) BOTH SIDES. CALL GRAHAM WODONGA.			29/03/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Elect\ELECT P&W	SCALES NOT WORK/ FAULT.			29/03/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Elect\ELECT P&W	LIGHTS NOT WORKING.			29/03/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Elect\ELECT P&W	SCALES NOT WORK/FAULT.			29/03/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Chassis\WINCH/STRP	STRAPS NEED REPLACING.			29/03/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Body\CHN/RLR/MIN	Tiedown chain short			29/03/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			18/03/2023		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			18/03/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Elect\ELECT P&W	LIGHTS NOT WORKING.			18/03/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Elect\ELECT P&W	SCALES NOT WORK/FAULT.			18/03/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Chassis\WINCH/STRP	STRAPS NEED REPLACING.			18/03/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Elect\ELECT P&W	NO TRAILER LIGHTS.			18/03/2023		Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			11/03/2023		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			11/03/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			04/03/2023		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			04/03/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			17/02/2023		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			17/02/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Chassis\WINCH/STRP	Replace Winch Straps			17/02/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		TURNED 1ST RH AND 2ND LH PEGS.	07/02/2023		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			07/02/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Elect\WORK LIGHT	WORK LIGHT MISSING.			07/02/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	DrivLine\WHEEL BRGS	REAR AXLE HOT (WHEEL MOVING & MAYBE BEARING) BOTH SIDES. CALL GRAHAM WODONGA.			07/02/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Elect\ELECT P&W	NO TRAILER LIGHTS.			07/02/2023		Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Elect\TRL LIGHTS	LIGHTS NOT WORKING.			07/02/2023		Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Elect\ELECT P&W	SCALES NOT WORK/ FAULT.			07/02/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			26/01/2023		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			26/01/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Elect\ELECT P&W	RH REVERSE LIGHT OUT.			26/01/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	DrivLine\WHEEL BRGS	REAR AXLE HOT (WHEEL MOVING & MAYBE BEARING) BOTH SIDES. CALL GRAHAM WODONGA.			26/01/2023		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Elect\ELECT P&W	TRAILER LIGHTS NOT WORKING.			26/01/2023		Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			23/12/2022		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			23/12/2022		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Rosewood - Workshop	Elect\WORK LIGHT	WORK LIGHT MISSING.			22/12/2022		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Elect\ELECT P&W	RH REVERSE LIGHT OUT.			22/12/2022		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	VehService\DS	Service As Per Attached Checklist		TIGHTENED BACKING PLATE BOLTS.	22/12/2022		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			22/12/2022		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Myrtleford - Workshop	Elect\WORK LIGHT	RHR Worklight U/S			19/11/2022		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER
T379	Myrtleford - Workshop	Tyres\TP5+6	Tyre off the Bead.			19/11/2022		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER
					Reline all 3 axles.											
			Inspect all Brakes & Brake Percentages.		Replace all 6 s cams & bushes											
T379	Wodonga - Workshop	Brakes\BRK O/HAUL	Works carried out bv TCTC.		Remove 2 x axles & send for repairs on s cam bushes.	18/11/2022		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Albury - Workshop	Susp\AXLES	Setup axles line bore 5 cam bushes, re-sleeve and fit bushes supplied			18/11/2022		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER
T379	Albury - Workshop	Tyres\TP3+4	Tyre Position 3 + 4			10/11/2022		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER
T379	Wodonga - Workshop	Brakes\BRK O/HAUL	Fit 70% run outs to required hubs from A trailer to the B trailer.		FULL RELINE COMPLETED. REPLACED ALL 5-CAMS.	10/11/2022		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			10/11/2022		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
			Record Check Results As Attached To This Job													
T379	Myrtleford - Workshop	Brakes	Sent to TCTC for Relines.			10/11/2022		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Myrtleford - Workshop	Elect\WORK LIGHT	RHR Worklight U/S			10/11/2022		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Myrtleford - Workshop	Tyres\TP5+6	Tyre off the Bead.			10/11/2022		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
			Disassemble, repair, reassemble tool box locks.													
T379	Myrtleford - Workshop	Body\TOOLBOX	Adiust shape of toolbox.			10/11/2022		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			11/10/2022	233545	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			11/10/2022	233545	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Brakes\BRK RELINE	RELINE LM.			11/10/2022	233545	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			07/10/2022		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			07/10/2022		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Brakes\BRK RELINE	RELINE LM.			07/10/2022		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Albury - Workshop	Tyres\TP1+2	supply and fit 4 tyres			01/10/2022		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER
T379	Albury - Workshop	Tyres\TP5+6	Tyre Position 5 + 6			01/10/2022		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER
			Service As Per Attached Checklist		- Axle 1 LH outer tyre flat - Customer to repair											
T379	Wodonga - Workshop	VehService\DS	CARRY OUT GREENFREIGHT LOG TRAILER D-SERVICE AS PER ATTACHED SERVICE SHEET.		- Axle 1 & 2 brake linings getting low 10-30% - Recommend replace	30/09/2022		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			30/09/2022		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Albury - Workshop	Tyres\TP9+10	supply and fit 2tyres			21/09/2022		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER
T379	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			20/09/2022		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			20/09/2022		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection	Insp\ANN INSP-deacti		20/09/2022		PreventativeMaintenance	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Brakes\BRK RELINE	RELINE LM.			20/09/2022		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			13/09/2022		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			13/09/2022		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Chassis\AIR TANKS	AIR TANK AT REAR OF B TRAILER.			13/09/2022		Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Brakes\AIR LEAK	LEAKING AIR AT RELAY VALVE. PIECE OF WOOD DROPPED ONTO IT. /RAG TIED AROUND IT SO YOU KNOW WHEI			13/09/2022		Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Body\BOLSTER	Replace damaged bolster			11/09/2022		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
			COMPLETED ON 09/09/2022													
			37682S													
			TRAVEL TO WOODEND, FIT STRAP TO TRAILER AND													
T379	Albury - Workshop	Body\STRAPS	CHECK BOLLSTERS			10/09/2022		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER
T379	Albury - Workshop	Tyres\TP7+8	supply and fit 2tyres			03/09/2022		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER
T379	Wodonga - Workshop	Chassis\AIR LEAK	REPAIRED AIR LEAK AT REAR TANK.			03/09/2022		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			27/08/2022		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			27/08/2022		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			19/08/2022		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			19/08/2022		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Elect\WORK LIGHT	Work light out			19/08/2022		Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Elect\TRL LIGHTS	LIGHT PLUG BROKEN AGAIN.. LIGTH PLUG BROKEN AGAIN.			19/08/2022		Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Albury - Workshop	Chassis\WINCH/STRP	winch repairs			26/07/2022		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER
T379	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			21/07/2022		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			21/07/2022		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Chassis\WHEEL SEAL	RHR smoking near melton		maxitrans POww072921	20/07/2022	233545	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		TIGHTENED STRETCH GUARD.	05/07/2022		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			05/07/2022		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Brakes\BRK RELINE	Rear axle needs reline		HOOKED UP. PARKED. CLEANED UP.	05/07/2022		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Elect\TRL LIGHTS	Reverse and work lights			05/07/2022		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Brakes\BRK RELINE	Relines due		#385449	05/07/2022		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Susp\AIR LEAK	Rear air bag leaking top LHS			05/07/2022		Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			26/06/2022		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Elect\ELECT P&W	REAR WORK LIGHTS OUT.			26/06/2022		Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			26/06/2022		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Brakes\BRK RELINE	Rear axle needs reline			26/06/2022		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			15/06/2022		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			15/06/2022		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Elect\TRL LIGHTS	Reverse and work lights			15/06/2022		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Brakes\BRK RELINE	Relines due			15/06/2022		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			08/06/2022		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER

T379	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		08/06/2022	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Brakes\BRK RELINE	RELINE REAR AXLE.		08/06/2022	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		02/06/2022	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		02/06/2022	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Comp\Truck Safe	REPLACE NHVAS STICKER.		02/06/2022	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Elect\INDICATORS	NO BLINKERS.	#382366	27/05/2022	Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		25/05/2022	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		25/05/2022	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Elect\ELECT P&W	ELECTRIC BRAKES NOT WORKING.	NOT PLUMBED UP.	25/05/2022	Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		21/05/2022	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		21/05/2022	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Albury - Workshop	Tyres\TP9+10	supply and fit 2tyres		21/05/2022	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER
T379	Albury - Workshop	Tyres\TP11+12	supply and fit 2tyres		18/05/2022	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER
T379	Wodonga - Workshop	Susp\AIR LEAK	REPAIRED AIR LEAKS AT HCV. REPLACED BROKEN HOLD-DOWN CHAIN.		17/05/2022	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Susp\AIR BAG	replace LH middle air bag		14/05/2022	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	REPAIRED REAR BOLSTER LIGHTS.	04/05/2022	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		04/05/2022	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		22/04/2022	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		22/04/2022	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Elect\ELECT P&W	ELECTRIC BRAKES NOT WORKING.		22/04/2022	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Albury - Workshop	Tyres\CLEANSKIN	SUPPLY AND FIT 2 TYRES - NO POS GIVEN		03/04/2022	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER
T379	Albury - Workshop	Tyres\TP11	supply and fit 2tyres		02/04/2022	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER
T379	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		25/03/2022	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		25/03/2022	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Brakes\BRAKE ADJ	BRAKES NEED ADJUSTING		25/03/2022	Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Myrtleford - Workshop	Tyres\RETREAD	fit tyre to spare		12/03/2022	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER
T379	Myrtleford - Workshop	Tyres\TP1+2	supply and fit 3tyres POS 1,2,3,. Fit runout from POS1 to POS 11		08/03/2022	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER
T379	Myrtleford - Workshop	Tyres\TP03	Tyre Position 3		08/03/2022	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER
T379	Myrtleford - Workshop	Tyres\TP11	Tyre Position 11		08/03/2022	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER
T379	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	REPLACED TRUCKSAFE STICKER. UN HOOKED. HOOKED UP. CHECKED HYDRAULIC OIL.	16/02/2022	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		16/02/2022	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Comp\Truck Safe	REPLACE NHVAS STICKER.		16/02/2022	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Brakes	BRAKE LINES TO BOOSTERS CRACKED		01/02/2022	Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Elect\ELECT P&W	RR BOLSTER CLEARANCE LIGHT NOT FITTED PROPERLY		01/02/2022	Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Brakes\DAMAGE	BRAKE LINES TO BOOSTERS CRACKED	REPLACED BOOSTER HOSES TO MIDDLE AND REAR AXLE.	28/01/2022	Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	UN-HOOKED FROM A TRAILER	26/01/2022	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		26/01/2022	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Brakes\DAMAGE	BRAKE LINES TO BOOSTERS CRACKED		26/01/2022	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Chassis\DAMAGE	REPLACED HOLD DOWN CHAIN AND HAMMERLOCK. REPLACED FITTINGS AND HOSE AT FRONT TANK. REMOVEC		08/01/2022	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Brakes\AIR LEAK	AIR LEAK AROUND BACK AXLE AREA.		08/01/2022	Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Chassis\DAMAGE	HOLD DOWN CHAIN FOR WHEN LOADED NEEDS TO BE LONGER		08/01/2022	Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		24/12/2021	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		24/12/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Myrtleford - Workshop	Tyres\TP04	supply and fit 1tyre		22/12/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER
T379	Myrtleford - Workshop	Body\CHN/RLR/MN	drive chain refitment and reset Service As Per Attached Checklist		21/12/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER
T379	Myrtleford - Workshop	VehService\DS	O/N L12723		03/12/2021	Service	Completed	Greenfreight Logging Vic	ElosBPW	Mt Gambier	GTK	37682S	BIG WHEELS TRUCK ALIGNMENT - 3	TRAILER
T379	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		03/12/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	BIG WHEELS TRUCK ALIGNMENT - 3	TRAILER
T379	Myrtleford - Workshop	VehService\DS	CARRY OUT D-SERVICE Service As Per Attached Checklist		27/10/2021	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER
T379	Myrtleford - Workshop	VehService\DS	O/N L12416		15/10/2021	Service	Completed	Greenfreight Logging Vic	ElosBPW	Mt Gambier	GTK	37682S	BIG WHEELS TRUCK ALIGNMENT - 3	TRAILER
T379	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job Service As Per Attached Checklist		15/10/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	BIG WHEELS TRUCK ALIGNMENT - 3	TRAILER
T379	Myrtleford - Workshop	VehService\DS	O/N L12330		01/10/2021	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	BIG WHEELS TRUCK ALIGNMENT - 3	TRAILER
T379	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job Service As Per Attached Checklist		01/10/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	BIG WHEELS TRUCK ALIGNMENT - 3	TRAILER
T379	Myrtleford - Workshop	VehService\DS	ORDER # L12215		10/09/2021	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	BIG WHEELS TRUCK ALIGNMENT - 3	TRAILER
T379	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job Service As Per Attached Checklist		10/09/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	BIG WHEELS TRUCK ALIGNMENT - 3	TRAILER
T379	Myrtleford - Workshop	VehService\DS	O/N L12103		21/08/2021	Service	Completed	Greenfreight Logging Vic	ElosBPW	Mt Gambier	GTK	37682S	BIG WHEELS TRUCK ALIGNMENT - 3	TRAILER
T379	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		21/08/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	BIG WHEELS TRUCK ALIGNMENT - 3	TRAILER
T379	Myrtleford - Workshop	Brakes\BRAKE ADJ	grease and brake adjust		17/08/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER
T379	Myrtleford - Workshop	Brakes\BOOSTER	replaced brake booster LHF		17/08/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER
T379	Myrtleford - Workshop	Tyres\DAMAGE	inflate RHF inside tyre		17/08/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER
T379	Myrtleford - Workshop	Susp\HOUSEKEEP	recheck all u-bolts and spring eye bolts		17/08/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER
T379	Myrtleford - Workshop	Body\MUDGUARDS	straighten guard		06/08/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER
T379	Myrtleford - Workshop	Brakes\EBS Kit	check EBS		23/07/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER
T379	Myrtleford - Workshop	Chassis\WINCH/STRP	check winches and straps and quick release		23/07/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER
T379	Myrtleford - Workshop	Chassis\BOLSTER	check bolsters pivots R11997 R11964		23/07/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER
T379	Myrtleford - Workshop	Body\PAINT/REST	wash tris and acid wash wheels		23/07/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER
T379	Myrtleford - Workshop	Elect\WORK LIGHT	rear work light not working		23/07/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER
T379	Myrtleford - Workshop	Chassis\WINCH/STRP	1st winch tap loose		23/07/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER
T379	Myrtleford - Workshop	Body\REFLECTORS	long vehicle sign u/s		23/07/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER
T379	Myrtleford - Workshop	Hydraulics\HYD LEAKS	hyd coupling u/s		23/07/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER
T379	Myrtleford - Workshop	Chassis\BOLSTER	bolster peg bolts u/s		23/07/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER
T379	Myrtleford - Workshop	Chassis\BOLSTER	2nd bolster bump stops u/s		23/07/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER
T379	Myrtleford - Workshop	Hydraulics\STCH GUARD	2nd bolster ram leaking		23/07/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER
T379	Myrtleford - Workshop	Susp\DAMAGE	LHR & LHM shocker straps u/s		23/07/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER
T379	Myrtleford - Workshop	Body\WHL HUB	front axle wheel bearing adj		23/07/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER
T379	Myrtleford - Workshop	Body\WHL HUB	LHM wheel bearing adj L12030		23/07/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER
T379	Myrtleford - Workshop	Susp\AIR BAG	RHR & LHR airbags u/s		23/07/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER
T379	Myrtleford - Workshop	Body\MUDGUARDS	check over make list		23/07/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER
T379	Myrtleford - Workshop	Hydraulics\HYD LEAKS	replace hydraulic couplings		23/07/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER
T379	Myrtleford - Workshop	Brakes\EBS Kit	relocate ebs socket and replace as it was damaged		23/07/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER
T379	Myrtleford - Workshop	Body\REFLECTORS	replace rear zebra signs		23/07/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER
T379	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection	Insp\ANN INSP-deacti	23/07/2021	PreventativeMaintenance	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER
T379	Myrtleford - Workshop	Susp\WHEEL ALGN	wheel align all 3 axles and repairs		22/07/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER
T379	Myrtleford - Workshop	Susp\SHOCK ABS	replaced shockers and straps		16/07/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER
T379	Myrtleford - Workshop	Susp\DAMAGE	replaced spring wraps		16/07/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER
T379	Myrtleford - Workshop	VehService\DS	completed service and appraisal		16/07/2021	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER
T379	Myrtleford - Workshop	Brakes\BRK RELINE	completed brake reline middle axle		16/07/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER
T379	Myrtleford - Workshop	Brakes\EBS Kit	replaced EBS valve		16/07/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER
T379	Myrtleford - Workshop	Body\AIR FITTIN	replaced suzi fittings		16/07/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER
T379	Myrtleford - Workshop	VehService\DS	D Service		09/07/2021	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER
T379	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		09/07/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER
T379	Myrtleford - Workshop	Susp\SHOCK ABS	LHF shock missing	removed axle to replace saddle, received wrong saddle, received correct peg. Aldonga to weld new peg into saddle	29/06/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER
T379	Albury - Workshop	Tyres\TP9+10	Supply and fit 2 tyres		16/06/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Myrtleford - Workshop	Susp\HOUSEKEEP	needs LHR axle hang cable	fitted during service	10/06/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER
T379	Myrtleford - Workshop	Elect\TRL LIGHTS	trailer lights not working	lights check on service all ok	10/06/2021	Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER
T379	Rosewood - Workshop	VehService\DS	D Service		05/06/2021	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Susp\HOUSEKEEP	replace LHR axel strap		05/06/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		05/06/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Chassis\BOLSTER	replace bolster, old one cracked		04/06/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Tumut - Workshop	Elect\TRL LIGHTS	fit 2 number plate lights		28/05/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Tumut Workshop	TRAILER
T379	Rosewood - Workshop	VehService\DS	D Service		13/05/2021	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Susp\SUSPENSION	replace LHC spring eye bush		13/05/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		13/05/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Myrtleford - Workshop	Susp\WHEEL ALGN	check wheel alignment		05/05/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER
T379	Myrtleford - Workshop	Susp\WHEEL ALGN	RHF alignment plate needs doing		05/05/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER
T379	Rosewood - Workshop	Tyres\TP11+12	Supply and fit 2 tyres		01/05/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Chassis\WINCH/STRP	Replace 2 straps check wheel alignment realign weld plate		28/04/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Tumut - Workshop	Susp\HOUSEKEEP	tighten all u-bolts		28/04/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Tumut Workshop	TRAILER
T379	Rosewood - Workshop	VehService\DS	D Service		21/04/2021	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Susp\WHEEL ALGN	check wheel alignment		21/04/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Susp\WHEEL ALGN	RHF alignment plate needs doing		21/04/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Susp\SHOCK ABS	LHF shock missing		21/04/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Susp\HOUSEKEEP	needs LHR axle hang cable		21/04/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job Supply and fit 2 tyres		21/04/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Tyres\CLEANSKIN	Bolted on by driver - driver didn't state positions		11/04/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Albury - Workshop	Tyres\TP3+4	Supply and fit 2 tyres		08/04/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER
T379	Rosewood - Workshop	Tyres\TP1+2	Supply and fit 2 tyres		01/04/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Albury - Workshop	Body\STRAPS	Supply Straps		26/03/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER

				CARRY OUT GREENFREIGHT LOG TRAILER D-SERVICE AS PER ATTACHED SERVICE SHEET. 22/03/2021. . DURING SERVICE: * RHF spring keeper broken * LHF bottom shock stud broken										
T379	Rosewood - Workshop	VehService\DS	Carry Out D-service AIR LEAK AIR LEAK AT SERVICE FOUND. Removed hose at valve for size. Nil parts. Cleaned hose, taped around hose and fit as required.	* Main supply hose to EBS valve leaking - temp repair.	23/03/2021	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Brakes\AIR LEAK	Secured into position. All ok.		23/03/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Chassis\WINCH/STRP	2nd strap and 4 strap need replacing		16/03/2021	Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Chassis\BOLSTER	turn all booster pegs		10/03/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Hydraulics\RAM	replace 1 ram		10/03/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Albury - Workshop	Tyres\TP5+6	Supply and fit 2 tyres		04/03/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER
T379	Albury - Workshop	Tyres\TP10	Position 10 was a non fixable puncture		04/03/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER
T379	Myrtleford - Workshop	VehService\DS	D Service		18/02/2021	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER
T379	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		18/02/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER
T379	Rosewood - Workshop	Tyres\TP9+10	replace 2 tyres		18/02/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Rosewood - Workshop	Tyres	driver replaced 2 tyres		13/02/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER
T379	Rosewood - Workshop	VehService\DS	D Service		10/02/2021	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job rewire and tidying		10/02/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Elect\TRL LIGHTS	reolace tail liehts and side markers as needed		03/02/2021	Reair	Completed	Greenfreight Logging Vic	ElosBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
				diagnose electrical problem, wiring behind tail lights needs rewiring asap										
T379	Rosewood - Workshop	Elect\TRL LIGHTS	trailer lights not working	removed trailer from service	02/02/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	VehService\DS	D Service		29/01/2021	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Brakes	Recrd Check Results As Attached To This Job		29/01/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Tyres\TP7+8	replace 2 tyres		21/01/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Myrtleford - Workshop	Brakes\EBS Kit	further works needed on EBS		19/01/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER
T379	Rosewood - Workshop	Brakes\EBS Kit	replace LHR wheel speed sensor		15/01/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	VehService\DS	D Service		12/01/2021	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		12/01/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Tyres\TP3+4	replace 2 tyres		09/01/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Tyres\TP1+2	replace 2 tyres		09/01/2021	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	VehService\DS	D Service and jobs cut off shock mounts prepare weld new ones on fit shackle sling keepers		05/01/2021	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Susp\SHOCK ABS	clean up tools away reline RHF and RHM wheels		31/12/2020	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Brakes\BRK RELINE	fit s/cam bushes		30/12/2020	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Body\CHN/RLR/MN	adjust load chain broken bent stretch guard mount straighten heat prepare to weld		30/12/2020	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Body\MUDGUARDS	fabricate brace bot in olace weld mudauards		30/12/2020	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Brakes\BRK RELINE	relines as needed RHF		19/12/2020	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Brakes\BRK RELINE	reline RHM axle		19/12/2020	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Tumut - Workshop	Chassis\WINCH/STRP	travel to Tumut pick up parts from forest centre		11/12/2020	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Tumut Workshop	TRAILER
T379	Rosewood - Workshop	Elect\TRL LIGHTS	check all side lights		10/12/2020	Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Body\MUDGUARDS	R/H/ side mudguard needs pulling away from wheels		10/12/2020	Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Elect\TRL LIGHTS	side lights not working replace bolster pivot arm and bolts		10/12/2020	Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Chassis\BOLSTER	#R10328 D Service B trailer middle axle RHS shoe walking out of drum very quick inspection as we were running out of time and driver was waiting		08/12/2020	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	VehService\DS	greased and adjusted		08/12/2020	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		08/12/2020	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Chassis\WINCH/STRP	front load strap needs replacing Carry Out Greenfreight Log Trailer D-Service.		02/12/2020	Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	VehService\DS	AdiustedLHF.LHR and RHF wheel bearinas	BOLSTER LIGHTS NOT WORKING	02/12/2020	Service	Completed	Greenfreight Logging Vic	ElosBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Chassis\ELECT P&W	LIGHTS	INSPECTED PFOR POWER AT PLUG POWER BUT PINS BENT, STRAIGHTENED PINS AS REQUIRED. RAN TWIN CORE WIRING AND MOUNTED 2X NEW LIGHTS AS REQUIRED. CARRY OUT GREENFREIGHT LOG TRAILER D-SERVICE AS PER ATTACHED SERVICE SHEET	25/11/2020	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	VehService\DS	Service As Per Attached Checklist	GREASE	17/11/2020	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		17/11/2020	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	DrivLine\WHEEL BRGS	CHECK WHEEL BEARING ADJUSTMENT	ADJUSTED 4X WHEEL BEAIRNG AS REUQIRED	17/11/2020	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Body\WHL HUB	adjusted x3 wheel bearings		13/11/2020	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	VehService\DS	D Service		13/11/2020	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		13/11/2020	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Susp\HCV	adjust ride height		06/11/2020	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Body\REFLECTORS	pop rivert red and yellow sign back on		03/11/2020	Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Tumut - Workshop	Susp\AIR BAG	call out air leak	called out to Laurell Hill area, split brake pipe on RHR airbag	30/10/2020	Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Tumut Workshop	TRAILER
T379	Tumut - Workshop	Susp\AIR BAG	patched up and back to Rosewood workshop for proper repairs		30/10/2020	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Tumut Workshop	TRAILER
T379	Rosewood - Workshop	VehService\DS	D Service		30/10/2020	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Susp\SPRNG PACK	replace RHF spring eye bush		30/10/2020	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		30/10/2020	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Chassis\WINCH/STRP	replace broken quick release cable		28/10/2020	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Elect\TRL LIGHTS	trailer lights short trips		24/10/2020	Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	VehService\DS	D Service and check over		24/10/2020	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		24/10/2020	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Elect\TRL LIGHTS	trailer lights short trips		16/10/2020	Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	VehService\DS	D Service and check over		07/10/2020	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Susp\HOUSEKEEP	tighten u-bolts and seb		07/10/2020	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		07/10/2020	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	VehService\DS	D Service		11/09/2020	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job test run and check EBS/ABS for operation/faults		11/09/2020	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Brakes\EBS Kit	basic look over electrics		05/09/2020	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Brakes\EBS Kit	further works needed on EBS		05/09/2020	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Brakes\EBS Kit	replace LHF and LHR speed sensors		04/09/2020	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Brakes\BRK RELINE	reline LHF as it was found to have missing linings		04/09/2020	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Brakes\EBS Kit	replace RHF speed sensor harness	checked brake adjustment, possibly a bit tight	04/09/2020	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Brakes\BRAKE ADJ	right side third axle bearing hot	reset brake adjustment and set within specs but "off" more than usual	28/08/2020	Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Brakes\BRK O/HAUL	call out to Rosewood. Brake dragging or getting hot anyway RHR		28/08/2020	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	VehService\DS	D Service		27/08/2020	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Susp\SUSPENSION	replace broken shocker		27/08/2020	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job diagnose EBS system putting light on dash 2A continuity, 2A output level 2B continuity 2B output level checked sensor with multi meter and extension leads with spare found faulty LHF (2B) wheelspeed sensor found faulty LHR (2B) wheelspeed sensor found faulty RHF (2A) speed sensor harness		27/08/2020	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Brakes\EBS Kit	to be repaired asap		21/08/2020	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	VehService\DS	D Service		20/08/2020	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Brakes\BRK RELINE	reline rear axel as needed		20/08/2020	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Body\WHL HUB	TCTC checked and adjusted all wheel bearings		20/08/2020	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		20/08/2020	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	VehService\DS	D Service		15/08/2020	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		15/08/2020	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	VehService\DS	D Service		06/08/2020	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		06/08/2020	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	VehService\DS	D Service		05/08/2020	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Myrtleford - Workshop	Elect\TRL LIGHTS	rear bumper mounts need re-welding and painting		21/07/2020	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER
T379	Myrtleford - Workshop	Chassis\BOLSTER	Repair cracks in 1st Bolster RHS	this job was done on the service 10-07-20 126533	16/07/2020	Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER
T379	Rosewood - Workshop	VehService\DS	D Service		11/07/2020	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		11/07/2020	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	VehService\DS	D Service		01/07/2020	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Elect\TRL LIGHTS	replace RH tail light		01/07/2020	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Elect\TRL LIGHTS	rear bumber mounts need re-newing		01/07/2020	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job diagnose EBS fault, light on dash		01/07/2020	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Brakes\EBS Kit	#needs to have all sensor wheels removed and sensors checkinz. Multiole active codes on multiole axles		27/06/2020	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	VehService\DS	D Service		18/06/2020	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER

T379	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job				18/06/2020		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	VehService\DS	D Service				12/06/2020		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job				12/06/2020		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	VehService\DS	Service				28/05/2020		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job				28/05/2020		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	VehService\DS	Service				16/05/2020		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Elect\TRL LIGHTS	repair RH side marker on 3rd bolster				16/05/2020		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Chassis\BOLSTER	spin LHF rear bay bolster				16/05/2020		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job				16/05/2020		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Chassis\AIR LEAK	Repair Brake Hose Air Leak & Restrain Hoses Properly				23/04/2020		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	VehService\DS	D Service				22/04/2020		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Elect\TRL LIGHTS	repair wiring to LH outer brake light				22/04/2020		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job				22/04/2020		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Body\HOUSEKEEP	find check off after major works and roadwothy				09/04/2020		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Body\HOUSEKEEP	check off recount works and finish services				03/04/2020		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
					tie down chain broken																
					cut out old one																
T379	Tumut - Workshop	Body\CHN/RLR/MN	dog chain broken		fit new chain and hammer lock		03/04/2020		Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Tumut Workshop	TRAILER				
T379	Rosewood - Workshop	Brakes\BRK RELINE	reline RHF as needed				02/04/2020		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Body\EBS Kit	replace damaged RHF wheel speed sensor		wire to wheel speed sensor was broken, replaced		02/04/2020		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	VehService\DS	D Service				02/04/2020		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job				02/04/2020		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Susp\SHOCK ABS	cut out from left top shock mount and prepare for weld				02/04/2020		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Susp\SHOCK ABS	cut out rear left lower shock mount and prepare for weld				02/04/2020		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Susp\SHOCK ABS	preheat, weld in shock mounts and braces				02/04/2020		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Brakes\BRK RELINE	reline front right brake				02/04/2020		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Brakes\BRK O/HAUL	change scam and bushes				02/04/2020		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Susp\SHOCK ABS	fit 3 shock absorbers straps and keepers				02/04/2020		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Insp\ANN INSP	Annual Inspection	Insp\ANN INSP-deacti	check off previous repairs to ensure roadworthy		02/04/2020		PreventativeMaintenance	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Susp\SPRNG HANG	L & R front spring hangers cracked				02/04/2020		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Body\MUDGUARDS	L/H mudguard bracket bent				02/04/2020		Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Susp\SHOCK ABS	shocky anc bolt broken		cut out and weld in new shock mount tube		02/04/2020		Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Brakes\BRK RELINE	reline LHM as needed				01/04/2020		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Chassis\WINCH/STRP	release wie missing no1				27/03/2020		Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Elect\WORK LIGHT	right side reversing light loose				25/03/2020		Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Elect\WORK LIGHT	work light R/H side back trailer loose		check worklight loose, seems ok		11/03/2020		Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Chassis\CROSS MBR	cross stay /broken bolts missing on stay		check cross stay, seems ok		11/03/2020		Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	VehService\DS	Service				04/03/2020		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job				04/03/2020		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	VehService\DS	D Service				21/02/2020		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job				21/02/2020		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Elect\TRL LIGHTS	side lights				20/02/2020		Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Chassis\WINCH/STRP	winch straps				20/02/2020		Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Susp\SHOCK ABS	shocky anc bolt broken				20/02/2020		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Chassis\WINCH/STRP	no 5 winch tight				20/02/2020		Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	VehService\DS	D Service				12/02/2020		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job				12/02/2020		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Body\MUDGUARDS	mudguard bracket broken L/H/S				04/02/2020		Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Body\MUDGUARDS	R/H/side mudflap missing				04/02/2020		Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Body\MUDGUARDS	L/H mudguard bracket bent				01/02/2020		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
			RHR indicator not working																		
T379	Rosewood - Workshop	Elect\ELECT P&W	remove & trace open circuit in wiring, repair and refit				01/02/2020		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	VehService\DS	D Service				30/01/2020		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Chassis\MUDGUARDS	temporary repair to bent back front left mudguard/mount				30/01/2020		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job				30/01/2020		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	VehService\DS	Service				18/01/2020		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job				18/01/2020		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	VehService\DS	D service				21/12/2019		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Chassis\BOLSTER	turn bolster pegs multiple				21/12/2019		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Brakes	Brake test results				21/12/2019		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	VehService\DS	D SERVICE				11/12/2019		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Brakes	TEST RESULTS				11/12/2019		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Body\LIGHTS	R/H/S back side light broken				21/11/2019		Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	VehService\DS	D SERVICE				21/11/2019		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Brakes	BRAKE TEST RESULTS				21/11/2019		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	VehService\DS	D SERVICE				28/10/2019		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Brakes					28/10/2019		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	VehService\DS	D Service				12/10/2019		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job				12/10/2019		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	VehService\DS	d service				10/10/2019		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Brakes					10/10/2019		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Elect\INDICATORS	L/H side blinker not working				26/09/2019	233545	Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Tumut Workshop	TRAILER				
T379	Rosewood - Workshop	Chassis\AIR LEAK	air line on L/H middle axle need replacing		Job previously completed		14/09/2019	233545	Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	VehService\DS	D Service				14/09/2019	233545	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Brakes	Brake test results attached				14/09/2019	233545	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Susp\SUSPENSION	Tightened RHR SEB				14/09/2019	233545	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Tumut - Workshop	Susp\SHOCK ABS	broken shock mount on right side axle				13/09/2019	233545	Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Tumut Workshop	TRAILER				
T379	Tumut - Workshop	Elect\BRK LIGHT	brake lights intermittent				13/09/2019	233545	Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Tumut Workshop	TRAILER				
T379	Tumut - Workshop	Chassis\FIFTH WHEE	replace broken quick release wire				13/09/2019	233545	Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Tumut Workshop	TRAILER				
T379	Tumut - Workshop	Elect\TRL LIGHTS	2nd last bolster no lights				13/09/2019	233545	Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Tumut Workshop	TRAILER				
T379	Tumut - Workshop	Susp\AIR BAG	replace blowen air bag RHM				13/09/2019	233545	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Tumut Workshop	TRAILER				
T379	Rosewood - Workshop	VehService\DS	D Service				12/09/2019	233545	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Body\LIGHTS	R/H/S back side light broken				12/09/2019		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	VehService\DS	Service				20/08/2019		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job				20/08/2019		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Susp\SUSPENSION	replace z spring middle axle		replace broken z spring RHC		14/08/2019		Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Susp\AIR BAG	new air line on airbag		replace airbag that had rubbed through on broken z spring RHC		14/08/2019		Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Susp\AIR LEAK	replace leaking length of air bag piping and multiple joiners with new section of pipe				14/08/2019		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Susp\SPRNG PACK	cut out broken spring wrap on RHC position				13/08/2019		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	VehService\DS	D Service				06/08/2019		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Elect\TRL LIGHTS	replaced both rear side lights				06/08/2019		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job				06/08/2019		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Elect\TRL LIGHTS	both side lights broken				03/08/2019		Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Chassis\AIR LEAK	air line on L/H middle axle need replacing				03/08/2019		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	VehService\DS	D Service				23/07/2019		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Brakes					23/07/2019		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	VehService\DS	D Service				29/06/2019		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Brakes	Brake test results attached				29/06/2019		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Wodonga - Workshop	Body\MUDGUARDS	broken rear RH mudguard and tyre bald		repair		28/06/2019	499305	Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Wodonga Workshop	TRAILER				
T379	Rosewood - Workshop	VehService\DS	Service				16/06/2019		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Elect\ELECT P&W	repair rear bolster wiring				16/06/2019		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job				16/06/2019		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	VehService\DS	Service				08/06/2019		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Susp\HCV	repair height control valve rod				08/06/2019		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job				08/06/2019		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Brakes\BRK RELINE	relines as needed				28/05/2019		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Brakes\BOOSTER	replace bolster wear pads				28/05/2019		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Elect\TRL LIGHTS	replace clearance lights				28/05/2019		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Insp\BRK RELINE	reline RHR & RHR				28/05/2019		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Chassis\BOLSTER	weld bolster cracks				28/05/2019		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Brakes\BOOSTER	tidy and repair booster hoses				28/05/2019		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Body\HOUSEKEEP	clean trailer of debris and dirt to allow inspection and repairs				25/05/2019		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Body\HOUSEKEEP	check over and make repair list				25/05/2019		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Workshop\MOVE ASSET	hook up to 620 for moving around yard				25/05/2019		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	VehService\DS	D Service				15/05/2019		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job				15/05/2019		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
			check ABS faults																		
T379	Albury - Workshop	Brakes\ABS	removed RHF wheel cleaned ABS sensor and ABS ring				11/05/2019		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER				
T379	Albury - Workshop	DrivLine\WHEEL BRGS	refitted wheel and adjusted bearing and brake				11/05/2019		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER				
T379	Albury - Workshop	Susp\SHOCK ABS	removed broken shocker				11/05/2019		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER				
T379	Rosewood - Workshop	VehService\DS	D Service				04/05/2019		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
T379	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job				04/05/2019		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER				
			check and adjusted all wheel bearings																		
T379	Albury - Workshop	DrivLine\WHEEL BRGS	hook up to T378				02/04/2019		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER				
			code faults - rear axle looms (replaced)																		
T379	Albury - Workshop	Elect\ELECT P&W	cleared codes				02/04/2019		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER				
			removed ABS extension cables																		
			reroute to avoid looms rubbing on hose																		
T379	Albury - Workshop	Elect\ELECT P&W	tidy up hoses				02/04/2019		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER				
T379	Albury - Workshop	Brakes\BRAKE ADJ	press 2x seb				29/03/2019		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER				
T379	Albury - Workshop	VehService\DS	D Service				26/03/2019		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER				

T379	Albury - Workshop	Body\AIR FITTIN	replaced hosing to front and rear axle b/boosters		26/03/2019	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER
T379	Albury - Workshop	Body\AIR LEAK	repaired air leaks to airbag supply lines		26/03/2019	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER
T379	Albury - Workshop	Elect\ELECT P&W	repaired wiring to 2nd bolster lights and no. plate lights		26/03/2019	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER
T379	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		26/03/2019	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER
T379	Albury - Workshop	Workshop\MOVE ASSET	hook up 1012 and removed trailer from w/shop		26/03/2019	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER
T379	Albury - Workshop	Susp\AIR LEAK	removed RHR tyres for shocker mount repairs tidy up air line's and electrical looms replaced HCV, rods and adjusted suspension replaced rear bolster pivot bushes		23/03/2019	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER
T379	Albury - Workshop	Susp\SUSPENSION	tighted x-stav bolts finished suspension jobs		23/03/2019	Reair	Completed	Greenfreight Logging Vic	ElosBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER
T379	Albury - Workshop	Susp\SHOCK ABS	replaced LHM, LHR and RHR shockers check over		22/03/2019	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER
T379	Albury - Workshop	Susp\SPRNG HANG	replaced RHF & RHM spring wraps		21/03/2019	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER
T379	Rosewood - Workshop	VehService\DS	Service		07/03/2019	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		07/03/2019	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	VehService\DS	D Service		26/02/2019	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Insp\ANN INSP	Annual Inspection	D SERVICE COMPLETED	26/02/2019	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Brakes\BRK RELINE	new brake linings	reline all LH side brakes	20/02/2019	Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Body\AIR LEAK	air leak at valve in tank		14/02/2019	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Brakes\BRAKE ADJ	adjust brakes		14/02/2019	Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	VehService\DS	Service		14/02/2019	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Body\AIR LEAK	fix bad air leak		14/02/2019	Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	VehService\DS	A Service		14/02/2019	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Body\HOUSEKEEP	change grease nipples		14/02/2019	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		14/02/2019	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	VehService\DS	Service		02/02/2019	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		02/02/2019	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Chassis\BOLSTER	repair wiring to bolster side markers		31/01/2019	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	VehService\DS	Service		23/01/2019	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Susp\AIR FITTIN	repair kinked air line		23/01/2019	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Susp\SHOCK ABS	tightened loose shockers (3)		23/01/2019	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job	clearance lights not working on trailer test voltage from A & B 10 volt drop fit new plugs trace wires to rear of trailer B hot wires cut and wire in new loom	23/01/2019	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Elect\TAIL LIGHT	no tail lights	all lights operational	16/01/2019	Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	VehService\DS	Service		09/01/2019	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		09/01/2019	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Body\SCALES	scales not working		21/12/2018	Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	VehService\DS	Service		19/12/2018	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		19/12/2018	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	VehService\DS	D Service	D Service completed	08/12/2018	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Albury - Workshop	VehService\DS	Service		24/11/2018	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER
T379	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		24/11/2018	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER
T379	Rosewood - Workshop	VehService\DS	D Service		23/11/2018	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		23/11/2018	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Susp\SUSPENSION	Suspension	replace RHR 2 spring	10/11/2018	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Susp\SUSPENSION	Suspension	replace RHR 2 springs	10/11/2018	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	VehService\DS	D Service		10/11/2018	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		10/11/2018	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Albury - Workshop	Brakes\BRK RELINE	BRAKE RELINE		10/11/2018	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER
T379	Albury - Workshop	Susp\SUSPENSION	SEB AND WRAP called out McCallums loop air leak in rear airbag line on trailer, driver had fitted repair joiner by the time arrived. Visual inspection appeared to be a good repair		10/11/2018	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER
T379	Rosewood - Workshop	Susp\AIR BAG	followed truck to main road and returned to workshop		27/10/2018	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	VehService\DS	Service		17/10/2018	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		17/10/2018	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	VehService\DS	D Service		16/10/2018	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	VehService\DS	D Service		05/10/2018	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		05/10/2018	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Susp\SUSPENSION	replace worn z spring bush	replaced load strap, worn	27/09/2018	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Chassis\WINCH/STRP	replace load strap	had come off hook and wrapped around arm of winch	21/09/2018	Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	VehService\DS	D Service		20/09/2018	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Body\DAMAGE	replace rear markers		20/09/2018	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Chassis\BOLSTER	turn 2nd, 3rd, 4th bolster pegs		20/09/2018	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Body\ALT2 DR	repair air leak		20/09/2018	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Elect\ELECT P&W	repair 3rd bolster wiring		20/09/2018	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		20/09/2018	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Albury - Workshop	Body	Job Added From Invoice		15/09/2018 0	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER
T379	Rosewood - Workshop	VehService\DS	D Service		05/09/2018	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Elect\ELECT P&W	Repair short in bolster marker light		05/09/2018	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		05/09/2018	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Tyres	Job Added From Invoice		04/09/2018 0	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Tyres\RETREAD	Job Added From Invoice		04/09/2018 0	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Tyres\FITMENT	Job Added From Invoice		04/09/2018 0	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Albury - Workshop	Tyres	Job Added From Invoice		01/09/2018 0	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER
T379	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice		01/09/2018 0	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER
T379	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice		01/09/2018 0	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER
T379	Albury - Workshop	Tyres	Job Added From Invoice		01/09/2018 0	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER
T379	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice		01/09/2018 0	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER
T379	Albury - Workshop	Engine	Job Added From Invoice		31/08/2018 0	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER
T379	Rosewood - Workshop	Chassis\WINCH/STRP	lube winches		28/08/2018	Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Chassis\WINCH/STRP	check no.5 coming loose? CALLOUT;	STRAP HAS COME UNDONE AND CAUGHT UNDER THE TRI. SHEARING OFF ANCHOR BOLTS FOR THE BARREL.	28/08/2018	Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Chassis\BREAKDOWN	REPLACE MISSING WINCH BARREL	Replace winch drum and strap	28/08/2018	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	VehService\DS	D Service		24/08/2018	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		24/08/2018	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Chassis\WINCH/STRP	lube winch		21/08/2018	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Body\AIR LEAK	repair air leak in tri		09/08/2018	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	VehService\DS	D SERVICE	REPLACE LHM AIR BAG	09/08/2018	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Susp\AIR BAG	replace L/M airbag		09/08/2018	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job fit supplied assy.	MAKE UP MUD GUARD @ Aldonga Eng. Remove stretch guard set up mudguard and cut to fit	09/08/2018	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Albury - Workshop	Body\MUDGUARDS	REPLACE STRETCH GUARD AND OUT RIGGER. call out winch strap broke	remove outrigger. Weld assy under load. Refit outrigger. Stretch guard call out travel hill top. Fit up tyres remove guard and cut off old tyre strap fell off. Wrapped around hub. Pulled off guard. Major damage travel in to bush. Pick up guard	04/08/2018	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER
T379	Rosewood - Workshop	Tyres\DRV TYRES	wrapped around mudguard broke guard off. Punchered 4 tyres	Replace 2 blown tyres and replace winch drum from damage from the strap coming loose	03/08/2018	Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Albury - Workshop	VehService\DS	D SERVICE		27/07/2018	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER
T379	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		27/07/2018	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER
T379	Tumut - Workshop	Body\SCALES	scales not working		21/07/2018	Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Tumut Workshop	TRAILER
T379	Albury - Workshop	VehService\DS	D SERVICE	swap over wiring for load lights replaced broken knp on 1st bolster	13/07/2018	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER
T379	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		13/07/2018	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER
T379	Albury - Workshop	VehService\DS	D SERVICE		04/07/2018	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER
T379	Albury - Workshop	Chassis\WINCH/STRP	lube winches		04/07/2018	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER
T379	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		04/07/2018	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER
T379	Rosewood - Workshop	VehService\DS	Service broken wheel stud pull off hub and wheel's found that the tyres have been loose		20/06/2018	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Tyres\DAMAGE	replace all wheel stuf fitted up tested ok		20/06/2018	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		20/06/2018	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Chassis\FIFTH WHEE	replace 2 quick release cables		12/06/2018	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Chassis\WINCH/STRP	lube 3rd winch		08/06/2018	Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	VehService\DS	Service		05/06/2018	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Brakes	Record Check Results As Attached ToThis Job		05/06/2018	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Albury - Workshop	Tyres	Job Added From Invoice		30/05/2018 0	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER
T379	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice		30/05/2018 0	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER
T379	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice		30/05/2018 0	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Albury Workshop	TRAILER
T379	Rosewood - Workshop	VehService\DS	D Service		19/05/2018	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		19/05/2018	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	VehService\DS	D Service		09/05/2018	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		09/05/2018	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	VehService\DS	Service		19/04/2018	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER
T379	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		19/04/2018	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Rosewood Workshop	TRAILER

| | | |

T379	Myrtleford - Workshop	Chassis\WINCH/STRP	broken pull cord			21/02/2017	57577	Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			11/02/2017	55520	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			11/02/2017	55520	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			01/02/2017		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			01/02/2017		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			19/01/2017	49339	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			19/01/2017	49339	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Elect\TRL LIGHTS	repair trailer lights			10/01/2017		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			06/01/2017	46783	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			06/01/2017	46783	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Tyres\TP13	Job Added From Invoice			31/12/2016	0	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Tyres\DAMAGE	repair damage to tarp + mudguard due to tyre blow out			17/12/2016	44667	Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			16/12/2016		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			16/12/2016		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Elect\TRL LIGHTS	no side lights			07/12/2016	42128	Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			06/12/2016	41343	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			06/12/2016	41343	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Chassis\FIFTH WHEE	fit new skid plate assembly			17/11/2016		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Chassis\BOLSTER	fit 2nd hand bolster			17/11/2016		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Chassis\WINCH/STRP	fit 1 winch strap			17/11/2016		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Body\DAMAGE	repair twist in trailer			17/11/2016		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Chassis\HOUSEKEEP	repair cracks			17/11/2016		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection	Insp\ANN INSP-deacti replace LHR bolster light & LH brake + park light		17/11/2016	40080	PreventativeMaintenance	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			17/11/2016	40080	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			17/11/2016	40080	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Susp\HOUSEKEEP	Replace LHR shocker strap			19/10/2016	40080	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			18/10/2016	39977	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			18/10/2016	39977	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist	tighten rear H wheel nuts		28/09/2016	37366	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			28/09/2016	37366	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Tyres\TP21	Job Added From Invoice			23/09/2016	36444	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Tyres\TP22	Job Added From Invoice			20/09/2016	26909	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			15/09/2016	35533	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			15/09/2016	35533	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			02/09/2016	32759	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			02/09/2016	32759	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Tyres\TP19	Job Added From Invoice			20/08/2016	29834	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Tyres\TP19	Job Added From Invoice			20/08/2016	29834	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Tyres\TP19	Job Added From Invoice			20/08/2016	29834	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			18/08/2016	30128	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			18/08/2016	30128	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Tyres\TP18	Job Added From Invoice			17/08/2016	28627	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Tyres\TP19	Job Added From Invoice			17/08/2016	29498	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Brakes\AIR LEAK	booster hose coming off			10/08/2016	28282	Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Brakes\AIR LEAK	check boost hose & clamps			09/08/2016		Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Elect\TRL LIGHTS	Repair bolster light wiring		Complete	03/08/2016	27371	Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Brakes\BRK RELINE	Crack test & reline all 3 axles			27/07/2016	27329	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Elect\TRL LIGHTS	repair trailer lights			26/07/2016	27329	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Susp\AXLES	replace RHR axle cable			26/07/2016	27329	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Brakes\BACK PLATE	replace LHF backing plate bolt			26/07/2016	27329	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Body\RWC COMP	fit sign			26/07/2016	27329	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Hydraulics\RAM	repair rear bolster ram			26/07/2016	27329	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Brakes\AIR LEAK	tidy up air hoses			26/07/2016	27329	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Body\STCH GUARD	replace RHS mudguard			26/07/2016	27329	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			26/07/2016	27329	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			26/07/2016	27329	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			14/07/2016	25185	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			14/07/2016	25185	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Comp\AIR LEAK	check for air leak			09/07/2016	24000	Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Chassis\WINCH/STRP	1st winch strap on last bay (needs replacing)			09/07/2016	24000	Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Tyres\TP13	Job Added From Invoice			05/07/2016	22230	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Susp\SPRNG HANG	Repair RHF & LHF Spring hanger cracks			29/06/2016	27329	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			28/06/2016	22230	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			28/06/2016	22230	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Susp\SPRNG HANG	L & R front spring hangers cracked			28/06/2016	22230	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			15/06/2016	19824	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			15/06/2016	19824	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			01/06/2016		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			01/06/2016		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			19/05/2016	14193	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			19/05/2016	14193	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Body\WHL HUB	bearing cap missing			18/05/2016	14491	Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Susp\HOUSEKEEP	Check over suspension		complete	17/05/2016	13979	Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Tyres\TP19	Job Added From Invoice			05/05/2016	0	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Tyres\TP19	Job Added From Invoice			05/05/2016	0	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Tyres\TP19	Job Added From Invoice			05/05/2016	0	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Tyres\TP19	Job Added From Invoice			05/05/2016	0	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Body\MUDGUARDS	replace lh stretch guard & tidy up tyre damage			05/05/2016		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
			Replace Wheel Guard	Replaced stretch guard															
			Repair torn mudflap. Replace Whel Guard	Cut & remount mudflap															
T379	Myrtleford - Workshop	Body\MUDGUARDS	Repair torn mudflap	Complete		04/05/2016	11858	Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			04/05/2016	11857	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			04/05/2016	11857	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			20/04/2016		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			20/04/2016		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			08/04/2016	7681	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			08/04/2016	7681	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
			RHR stop light - not working																
T379	Myrtleford - Workshop	Elect\TRL LIGHTS	fit new rubber boot to led light, RHR			07/04/2016	7681	Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Insp\RWC COMP	fit rego label			07/04/2016	7681	Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Tyres\TP21	Job Added From Invoice			01/04/2016	5839	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Tyres\TP21	Job Added From Invoice			01/04/2016	0	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Tyres\TP21	Job Added From Invoice			01/04/2016	0	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			17/03/2016	5653	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			17/03/2016	5653	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Elect\TRL LIGHTS	Check & Repair trailer lights	Completed		25/02/2016		Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Tyres\TP19	Job Added From Invoice			06/02/2016	4821	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Tyres\TP19	Job Added From Invoice			06/02/2016	0	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Tyres\TP19	Job Added From Invoice			06/02/2016	0	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Tyres\TP11	Job Added From Invoice			06/02/2016	4821	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Body\HOUSEKEEP	check over	completed		02/02/2016	4821	Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Brakes\BRAKE ADJ	adjust brakes	completed		27/01/2016	4120	Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection	completed		20/01/2016	4119	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist	completed		08/01/2016	1911	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job	completed		08/01/2016	1911	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Body\WHL HUB	hubbo	completed		01/01/2016		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Tyres\TP22	Job Added From Invoice			30/12/2015	47393	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	DrivLine\WHL HUB	fit new hubo to trailer	completed		24/12/2015		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
			check over																
T379	Myrtleford - Workshop	Chassis\HOUSEKEEP	load trailer	completed		24/12/2015		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Brakes\BRAKE ADJ	adjust brakes	completed		24/12/2015		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Chassis\WINCH/STRP	repair centre winch - hard to wind up	completed		23/12/2015	525435	Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Susp\AXLES	repair/replace lhs axle strap	completed		22/12/2015	47955	Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist	completed		19/12/2015	47955	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job	completed		19/12/2015	47955	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Susp\AIR BAG	replace rhr air bag	completed		15/12/2015	46796	Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
			2 bpw air bags																
T379	Myrtleford - Workshop	Susp\AIR BAG	tctc	completed		15/12/2015		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Tyres\TP15	Job Added From Invoice			10/12/2015	45324	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Tyres\TP15	Job Added From Invoice			10/12/2015	0	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Tyres\TP15	Job Added From Invoice			10/12/2015	0	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist	completed		02/12/2015	45329	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job	completed		02/12/2015	45329	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Tyres\TP11	Job Added From Invoice			25/11/2015	41509	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Tyres\TP11	Job Added From Invoice			25/11/2015	41509	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Tyres\TP11	Job Added From Invoice			25/11/2015	41509	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist	completed		18/11/2015	42301	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job	completed		18/11/2015	42301	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
			fit new clearance light																
T379	Myrtleford - Workshop	Elect\TRL LIGHTS	repair wiring in tail light bar rh side	completed		17/11/2015		Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	DrivLine\WHL HUB	checked rhr bearing adjustment - nothing found - driver to monitor	completed		12/11/2015	40663	Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			

T379	Myrtleford - Workshop	Brakes\BRAKE ADJ	adjust brakes	completed	11/11/2015	40395	Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Brakes\BRK RELINE	bpw brake parts+3 axles + 6 bpw drums crack test + reline all wheels	completed	22/10/2015		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Brakes\BRK RELINE	reolace brake drums	completed	21/10/2015	40176	Reoair	Completed	Greenfreight Logging Vic	ElosBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist	completed	10/10/2015	40174	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job	completed	10/10/2015	40174	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Elect\ELECT P&W	refocus rh downlight + tighten	completed	06/10/2015		Fault	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Tyres\TP22	Job Added From Invoice		30/09/2015	36543	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist	completed	29/09/2015		Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job	completed	29/09/2015		Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist	completed	19/09/2015	36207	Service	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			
T379	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job	completed	19/09/2015	36207	Repair	Completed	Greenfreight Logging Vic	ElpsBPW	Mt Gambier	GTK	37682S	Myrtleford Workshop	TRAILER			