EquipmentName	Workshop	CodeAndSubCode	Description	Schedule	CompletionComments	DateDone	DistanceDone	Worktype	Workstate	EquipmentOwner	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
T492	Mt Gambier - Mt Gambier	VehService/DS	VehService/DS D Service	VehService/DS	Completed "D Service" as per attached service sheet Replace blown airbag on left hand center axle. Fit new hose clamp to secure air line. Remove axle straps. Pop other air bags in right way.	14/10/2026	1594872	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Mt Gambier Workshop	TRAILER
T492	Myrtleford - Workshop	Susp\AIR BAG	REPLACE L/H AXLE AIR BAG		Reolace silicone hose to orewent further rub throuah hoses.	26/08/2026	1594872	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	QT DIESEL SERVICES - 3	TRAILER
T492	Myrtleford - Workshop	DrCabElect\SCALES	SUPPLY AIR LINE FITTINGS FOR PLUMBING RIGHT WEIGH SCALE BOX			26/08/2026	1594872	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	QT DIESEL SERVICES - 3	TRAILER
T492	Mt Gambier - Mt Gambier	VehService/DS	VehService/DS D Service	VehService/DS	Carried out trailer service as per Greenfreight checklist. TENSION PIVOT BUSHES & U BOLTS TENSION BOLSTER BOLTS	25/08/2026	1594872	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Susp\SUSPENSION	Worn RHR and LHF pivot bushes			12/08/2026	1594872	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	HALLORAN DIESEL - 3	TRAILER
T492	Myrtleford - Workshop	Chassis\CROSS MBR	Cracks in crossmember			12/08/2026	1594872	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	HALLORAN DIESEL - 3	TRAILER
T492	Myrtleford - Workshop	Susp\SHOCK ABS	Worn shock mount			12/08/2026	1594872	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	HALLORAN DIESEL - 3	TRAILER
T492	Myrtleford - Workshop	Body\AIR LEAK	Air leaks present, as per customer video			12/08/2026	1594872	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	HALLORAN DIESEL - 3	TRAILER
T492	Myrtleford - Workshop	Brakes\ABS	ABS lead disconnected/hanging under deck plate			12/08/2026	1594872	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	HALLORAN DIESEL - 3	TRAILER
T492	Myrtleford - Workshop	VehService/DS	VehService/DS D Service	VehService/DS	Completed "D Service" as per attached service sheet	06/08/2026	1594872	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	HALLORAN DIESEL - 3	TRAILER
T492	Myrtleford - Workshop	Susp\WEIGHT GAUGE	FIT RIGHT WEIGH SCALES SO MT GAMBIER COULD USE TRAILER WHILST R/TRAIN IS OF ROAD FOR FIRE DAMAGE.			31/07/2026	1594872	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	JF MECHANICALS - 3	TRAILER
T492	Myrtleford - Workshop	Tyres\TP1+2	Tyres(TP1+2 (21-22)			13/07/2026	1594872	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BORDER BANDAG PTY LTD -3	TRAILER
T492	Myrtleford - Workshop	Tyres\TP3+4	Tyres(TP3+4 (23-24)			13/07/2026	1594872	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BORDER BANDAG PTY LTD -3	TRAILER
T492	Myrtleford - Workshop	VehService/DS	VehService/DS D Service	VehService/DS		04/06/2026	1594872	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	JF MECHANICALS - 3	TRAILER
T492	Myrtleford - Workshop	Susp\AIR BAG	REPLACE L/H FRONT AXLE AIR BAG			18/05/2026	1594872	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	JF MECHANICALS - 3	TRAILER
T492	Myrtleford - Workshop	Elect\TAIL LIGHT	REPAIR L/H REAR NUMBER PLATE LIGHT WIRING			18/05/2026	1594872	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	JF MECHANICALS - 3	TRAILER
T492	Myrtleford - Workshop	VehService/DS	VehService/DS D Service	VehService/DS		18/05/2026	1594872	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	JF MECHANICALS - 3	TRAILER
T492	Myrtleford - Workshop	Insp\ANN INSP	Insp\ANN INSP Annual Inspection As Per Checklist	Insp\ANN INSP		18/05/2026	1594872	PreventativeMaintenance	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	JF MECHANICALS - 3	TRAILER
T492	Myrtleford - Workshop	VehService/DS	VehService/DS D Service	VehService/DS		13/05/2026	1594872	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Chassis\EXTE TU	1099249 FIT EXTE BINDERS EX T720			07/05/2026	1594872	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	JF MECHANICALS - 3	TRAILER
T492	Myrtleford - Workshop	Susp\AIR BAG	MR AIRBAG BOLTS BROKEN OFF THE BOTTOM		Travel to GF yard and check air bags. Found middle right to need replacing. Remove old airbag and fit new as required. Pack up tools and return to yard, all OK KW0542941690 COMPLETE AIRBAG D36 RINGFEDER FRONT MOUN	25/02/2026	1594872	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Body\MUDGUARDS	REPLACE FRONT PASS SIDE MUD GUARD		Attempt to straighten out front bracket. Found supporting pole would bend, straightened out bracket as best as possible. Removed mud guard, 4 bolts were seized. Use grinder to cut off bolts. Measure and drilled holes in new mud guard. Mounted and fitted new guard, tensioned bolts. KW0127-1116-08A FENDER RED SPRAYSAFE	07/02/2026	1594872	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	VehService/DS	VehService/DS D Service 1098822	VehService/DS		04/02/2026	1594872	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Tyres\TP1+12	Tyres(TP1+12 (31-32)			02/02/2026	1594872	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BORDER BANDAG PTY LTD -3	TRAILER
T492	Myrtleford - Workshop	Tyres\TP7+8	Tyres(TP7+8 (27-28)			02/02/2026	1594872	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BORDER BANDAG PTY LTD -3	TRAILER
T492	Myrtleford - Workshop	Tyres\TP5+6	Tyres(TP5+6 (25-26)			02/02/2026	1594872	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BORDER BANDAG PTY LTD -3	TRAILER
T492	Myrtleford - Workshop	Body\MUDGUARDS	LH MUDGUARD U-BOLT/BRACKET BROKEN		Sourced new u bolt and fit to guard bracket. Sublet15112358	09/01/2026	1594872	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	VehService/DS	VehService/DS D Service 1098456	VehService/DS		09/01/2026	1594872	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	VehService/DS	VehService/DS D Service 1097922	VehService/DS		05/01/2026	1594872	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Chassis\BOLSTER	R/H number 3 bolster peg requires turning around		Turn pin 180 degrees, all okay Remove and replace RH side indicator light, join wiring, tape loom and clip into holder. Check operation, all okay	04/12/2025	1594872	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Elect\TRL LIGHTS	REPAIR LIGHTS N/W		KW2026 AMBER CAB MARKER LAMP	04/12/2025	1594872	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Chassis\WHL HUB	CHECK WHEEL BEARINGS		Check over wheel bearings, all okay Found RH middle pivot bush worn. Undo u bolts, lowered spring. Pressed out worn pivot bush and installed new. Refit spring and installed new pivot bolts. Tension u-bolts	04/12/2025	1594872	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Susp\SUSPENSION	MIDDLE AXLE PIVOT BUSH WORN		and pivot bolts to spec and check allaned. all okay.	04/12/2025	1594872	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Brakes\BRAKE ADJ	Rear axle s-cam bushes slight wear		Check middle s-cam bushes, found movement. Apply grease and re-check. no more movement.	21/11/2025	1594872	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Brakes\BRAKE ADJ	Middle LH s-cam bushes - next service		Check middle LH s-cam bushes, found movement. Apply grease and re-check. no more movement. CHECK RH REAR AND RH MIDDLE PIVOT BUSHES	21/11/2025	1594872	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Susp\SUSPENSION	RH Middle pivot bush slight movement RH Rear pivot bush slight movement		Check middle and rear RH pivot bushes, no movement, all looked ok.	21/11/2025	1594872	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Brakes\BRAKE ADJ	Middle LH s-cam bushes - next service		Check middle LH s-cam bushes, found movement. Apply grease and re-check. no more movement.	21/11/2025	1594872	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	VehService/DS	VehService/DS D Service 1097580	VehService/DS		01/11/2025	1594872	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	VehService/DS	VehService/DS D Service 1097305	VehService/DS		28/10/2025	1594872	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Tyres\TP5+6	Tyres(TP5+6 (25-26)			22/10/2025	1594872	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BORDER BANDAG PTY LTD -3	TRAILER
T492	Myrtleford - Workshop	Tyres\RUN OUT	Tyres(RUN OUT 21-22 + 23-24		Found RH front spring was snapped. Undo u bolts, bottom air bag bolts and pivot bushes. Spring was jammed in, just oxy and hammer to loosen up and remove. Fit new spring and aligning plates. Bolt new spring to air bag. Jack up and refit saddle. Pry axle forward while saddle was fitted. Installed new aligning plates. Tensioned all u-bolts and pivot bushes.	22/10/2025	1594872	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BORDER BANDAG PTY LTD -3	TRAILER
T492	Myrtleford - Workshop	Susp\SPRING PACK	BROKEN FR SPRING - R&R		KW0508212830 S/PACK-550 380/405 2X43 OT SRS 1 864.55KW0316435010 ALINGING PLATE	15/10/2025	1594872	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	VehService/DS	VehService/DS D Service 1097044	VehService/DS		09/10/2025	1594872	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	DrivLine\AXLE REPLC	RH first axle broken cable		RH FIRST AXLE CABLE BROKEN Work order 201127 Remove and replace broken axle strap cable. DONE ON 30/9/25	08/10/2025	1594872	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Chassis\WINCH/STRP	2ND AIR BINDER BENT		Inspect binder, undo strap so can move freely in drum. Straightened drum and refit strap. Check binder for any other damage, all okay. DONE ON 30/9/25	08/10/2025	1594872	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Chassis\BOLSTER	2ND LAST BOLSTER CRACKED		Grind back surfaces of crack on bolster. Welded over cracks and painted. DONE ON 30/9/25	08/10/2025	1594872	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Chassis\WHEEL SEAL	CHECK ML & RL WHEEL BEARING'S		Remove all hub caps. Jack axles and adjust bearings to spec, took all movement out. Lower axles, fit and tensioned all hub caps, all ok. KW0318804100 RING LOCKING FOR WEDGE RINGFEDER FRONT M 1 1.10 KW0327700070	08/10/2025	1594872	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Elect\WORK LIGHT	WORK LIGHTS N/W		Found work lights not working. Inspect and found broken wiring. Remove light and pulled wire out. Ran new wiring to new lahti then refit. all ok.	08/10/2025	1594872	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	DrivLine\AXLE REPLC	Second axle LH s-cam bush worn - monitor JOB CARD IN SYSTEM FOR REPLACMENT NEXT SERVICE		Check over all s-cams. Rear axle s-cams slight movement, greased all points, all okay. LH middle s-cam needs repair next service. RH middle all okay after eressine.	08/10/2025	1594872	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Tyres\RUN OUT	Tyres(RUN OUT POS 5-6			29/09/2025	1594872	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BORDER BANDAG PTY LTD -3	TRAILER
T492	Myrtleford - Workshop	Tyres\Punct	Tyres(Puncture POS 21			17/09/2025	1594872	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BORDER BANDAG PTY LTD -3	TRAILER
T492	Myrtleford - Workshop	VehService/DS	VehService/DS D Service 1096677	VehService/DS		15/09/2025	1594872	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Chassis\BOLSTER	Chassis\BOLSTER Steering\WHEEL BRGS		CHECK AND REPAIR SEIZED BOLSTER BOLT Use oxy to remove seized bolt. Cleaned up bolster and installed new bolt. ADJUST WHEEL BEARINGS	15/09/2025	1594872	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Steering\WHEEL BRGS	Middle axle and rear wheel bearings CHECK NEXT SERVICE		Lift second axle and adjust wheel bearings on both sides. Lift third axle and adjust wheel bearings on both sides MIDDLE AXLE TRACKING LEFT	15/09/2025	1594872	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Chassis\AXLE CT	Chassis\AXLE MIDDLE AXLE TRACKING LEFT		Found axle shitting incorrectly. Un do u bolts and re position axle in correct spot. re tension u bolts all okay RIDE HEIGHT FROM AXLE LH TOP RUBBER LEANS OVER	15/09/2025	1594872	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Susp\HCV	Susp\HCV		Remove ride height arm, loosen bolt and straighten. Move rod to a better position through rubber so rubber cannot bend over. Refit arm back on and tidy up SECOND BINDER QUICK RELEASE BROKEN	15/09/2025	1594872	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Chassis\WINCH/STRP	Chassis\WINCH/STRP SECOND BINDER QUICK RELEASE BROKEN		Inspect binder and found cable to be broken. Removed cable from spare binder on trailer and fit new cable into broken binder. Check operation, all okay. Lubed binder latches	15/09/2025	1594872	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Chassis\WINCH/STRP	Chassis\WINCH/STRP fit new axle catch straps to rear axle		FIT NEW AXLE CATCH STRAPS Install new axle catch straps around axle, tighten into place, all ok NG0532714010NG CATCH STRAP 1220MM 2 219.10NGFREIGHT FRIGHT	29/08/2025	1594872	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	VehService/DS	VehService/DS D Service	VehService/DS		27/08/2025	1594872	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Tyres\Punct	Tyres(Punct POS 29			27/08/2025	1594872	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BORDER BANDAG PTY LTD -3	TRAILER
T492	Myrtleford - Workshop	Body\AIR LEAK	Check for air leaks		AIR LEAKS Found leaking booster hose. Cut out rubbed section and rejoined. KWAQ62-DOT-6 PTC UNION 3/8	27/08/2025	1594872	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Chassis\MUDGUARDS	L/H mud flap ripping needs replacing		MUDFLAP R&R Removed LH rear mud flap and replaced with new. K	27/08/2025	1594872	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Chassis\EXTE TU	last binder not working very well REFER PO L096575 INVOICE 398989 B/M		REPLACE LAST BINDER - GF TO SUPPLY Sprayed oil through lines, binder locked up. Disassembled binder and cleaned out, reassembled and greased. Tested operation. all okay. LH FRONT BOLSER INDICATOR N/W	27/08/2025	1594872	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes\BOOSTER	Front LH bolster indicator not working		Work order 200070 Check indicator on bolster for fault, all bolster lights working.	22/08/2025	1594872	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Brakes\BRK RELINE	Rear LH brake low		REPLACE LOW BRAKE Brake past wear limit LH rear, jack up axle, remove wheels, brakes, backing plate, slack adjuster, and s-cam. Fit new bushes and s-cam then fit new brakes and hard ware kit. Fit backing plate. Remove and replace brake drum, then fit wheels and adjust wheel bearing. Adjust brakes and lower axle. Grease s-cam, all ok KW0509146328BHS BPW B/SHOE & H/WARE 4218 20.5' 1 186.77KWDB001TRP TRP BRAKE DRUM SUIT BPW 419MM X 180MM 10 1 140.91KW0509700K1T KIT-CAMSHAFT REPAIR ONE AXLE 1 94.36KW0509705254 C/SHAFT A=547.5MM L=666MM LH	22/08/2025	1594872	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	DrivLine\WHEEL BRGS	Check all trailer wheel bearings		CHECK WHEEL BEARINGS Work order 200070 Jacked up and checked wheel bearings. all okay	22/08/2025	1594872	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Brakes\EBS FAULTS	Rear LH wheel speed sensor has broken wiring		LH REAR WHEEL SPEED SENSOR BROKEN WIRING Work order 200070 Removed broken wheel speed sensor and installed new. KW0231170500 SENSOR & LEAD - ANGLED	22/08/2025	1594872	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Susp\AIR BAG	LH FRONT IAIR BAGS KEEP FOLDING UP AND NOT INFLATING PROPERLY		AIR BAGS FOLDING UP Check over all airbags, found LH 1st axle leaking. Jack chassis and drop air then removed air fitting. Unbolt remove and replace air bag. Fit new fittings. Build up air and check for leaks, all ok. Check over ride height, found bottom lever bent, straighten lever, all ok KWTRPB104 AIR SPRING-TRP BPW D36 SUITS BPW 0542943 1 218.59NGSCRAPHOSE scrap hose 1 4.55KWAQ62-DOT-6 PTC UNION 3/8 1 8.28K	22/08/2025	1594872	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3	TRAILER

						REPLACE LOW BRAKE Brake past wear limit LH rear, jack up axle, remove wheels, brakes, backing plate, slack adjuster, and s-cam. Fit new bushes and s-cam them fit new brakes and hard ware kit. Fit backing plate. Remove and replace brake drum, them fit wheels and adjust wheel bearing. Adjust brakes and lower axle. Grease s-cam, all ok												
T492	Myrtleford - Workshop	Brakes/SLACK ADJ	Rear LH outer s-cam has slight movement			KW0509146320BHS BPW BJSHOE & H/WARE 4218 20.5' 1 186.77KWO8001TRP TRP BRAKE DRUM SUIT BPW 419MM X 180MM 10 1 140.91KWO5097006KIT KIT-CAMSHAFT REPAIR ONE AXLE 1												
T492	Myrtleford - Workshop	Susp\AXLES	Susp\AXLES R&R REAR RIDE HEIGHT RUBBER			94.36KWO5097052S4 C/SHAFT A=547.5MM L=666MM LH TRAILER RIDE HEIGHT HAS COME OFF REAR AXLE ON B TRAILER Remove and readuce rear ride heiehht rubber as reauired.	22/08/2025	1594872	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Susp\AXLES	Susp\AXLES R&R REAR RIDE HEIGHT RUBBER				18/08/2025	1594872	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
						GREENFREIGHT SERVICE Carried out trailer service as per Greenfreight checklist. Customer Instructions: Place vehicle on shaker & Inspected Carried out General Inspection & Checkover Greased vehicle												
T492	Myrtleford - Workshop	VehService/DS	VehService/DS D Service L096228	VehService/DS		Check over and retension pivot bushes & u bolts Check over and tensioned all bolster bolts as reaquired.	16/08/2025	1594872	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
						SECOND LAST BOLSTER MISSING BOLT AND LOOSE Work order 199837												
T492	Myrtleford - Workshop	Body\BOLSTER	second to last bolster has bolt missing and bolt loose			Checked over second last bolster as indicated, no faults. Checked over all other bolsters for missing or loose bolts, all okay.	13/08/2025	1594872	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
						LH FRONT BOLSTER INDICATOR N/W Test power, found power supply. Remove and replace front LH												
T492	Myrtleford - Workshop	Body\BOLSTER	Body\BOLSTER R&R FRONT LH BOLSTER INDICATOR			bolster indicator, check ooperation. all ok 5TH AIR BINDER MISSING BOLT	13/08/2025	1594872	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
						6TH AIR BINDER VERY SLOW TO TIGHTEN AND RELEASE Replace and tension missing bolt on air binder. Upon inspection found binder mount bracket cracked. Grind back												
T492	Myrtleford - Workshop	Chassis\WINCH/STRP	Chassis\WINCH/STRP CRACKED BRACKET - WELD CRACKS			surfaces and weld over cracks. CHECK LH REAR WHEEL BEARING	13/08/2025	1594872	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Steering\WHEEL BRGS	Steering\WHEEL BRGS CHECKED LH WHEEL BEARING			Jack up axle, check movement on LHR wheel bearing, all looked ok	13/08/2025	1594872	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Susp	PRESENTED TO CCLAC WORKSHOP WITH LF AIRBAG ISSUE, AIRBAG WAS MANIPULATED BACK INTO POSITION & "KINKS" REMOVED.				12/08/2025	1594872	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	JF MECHANICALS - 3	TRAILER
						GREENFREIGHT SERVICE Carried out trailer service as per Greenfreight checklist. Customer Instructions: Place vehicle on shaker & Inspected Carried out General Inspection & Checkover Greased vehicle TENSION PIVOT BUSHES & U BOLTS Check over and retension pivot bushes & u bolts TENSION BOLSTER BOLTS												
T492	Myrtleford - Workshop	VehService/DS	VehService/DS D Service	VehService/DS		Check over and tensioned all bolster bolts as reauired	06/08/2025	1594872	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Tyres\RUN OUT	Tyres\RUN OUT POS 25-26				04/08/2025	1594231	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BORDER BANDAG PTY LTD -3	TRAILER
						30/7/25 Reported Fault: Brakes requiring adjustment; slow air build-up; broken U-bolt observed. Diagnosis & Cause: Brakes required adjustment. Left-hand rear axle U-bolt found broken. Air system slow to build pressure – pressure regulator valve and brake valve suspected faulty. Correction: Adjusted brakes on all wheels. Removed and replaced broken LHR axle U-bolts. Tensioned new U-bolts to specification. Replaced pressure regulator valve and brake valve on rear air tank.												
T492	Myrtleford - Workshop	Brakes/BRAKE ADJ	Brakes\BRAKE ADJ			Rechecked brake system operation – air build-up and braking confirmed as OK.	31/07/2025	1594231	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	HALLORAN DIESEL - 3	TRAILER
						CHECK FOR AIR LEAKS Checked for air leaks, found some hose clamps were loose,												
T492	Myrtleford - Workshop	Brakes/AIR LEAK	Brakes\AIR LEAK			tightened. Also found a joiner was leaking. Removed joiner and reolaced with new. Tested. no further leaks.	25/07/2025	1594231	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
						B TRAILER LIGHTS FLICKERING Inspect and found trailer plug to have high corrosion.												
T492	Myrtleford - Workshop	Elect\BREAKDOWN	Elect\BREAKDOWN			Removed damaged loom and installed new 7 pin plug. Plugged in and test ooeration. all ok	25/07/2025	1594231	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
						CHECK AND REPACK WHEEL BEARINGS Bearing adjustment was okay on shaker. Removed hub caps and checked bearing grease at front, found to be all okay.												
T492	Myrtleford - Workshop	DrivLine\WHEEL BRGS	DrivLine\WHEEL BRGS			Checked bearing end float, all wheels within spec. Refit hub caps and tensioned	25/07/2025	1562758	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
						NO TAIL LIGHTS Rechecked lights on service, found rear tail lights and												
T492	Myrtleford - Workshop	Elect/SLIDI COIL	LIGHT PLUG NEEDS REPLACING			indicator not working. Traced wiring along light bar and found numerous rubbed wires. Cut out and reoaired rubbed	25/07/2025	1562758	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
						TAKES A LONG TIME TO RELEASE BRAKES Swapped susi coil between truck and A trailer. Test trailer release with workshop air, found issue is coming from truck. Inspect truck valves and check air pressure at Susi, all okay. Removed and replaced quick release valve for trailer park brake circuit. Removed tool box and dover module, removed and replaced TPS valve. Reinstall dover and tool box. Upon further inspection found relay valve was taking a long time to operate. Removed air from trailer and removed air hoses. Fit new relay valve and tested. Brakes working as should. Inspect trailers for air leaks, found a few hose clamps to be loose on front and rear axle. Tighten and found joiner in RH front air bag												
T492	Myrtleford - Workshop	Brakes/BRAKE ADJ	BRAKES STILL VERY SLOW TO RELEASE			leaking, remove and replaced joiner with new, recheck over for leaks, all ok	25/07/2025	1562758	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
						GREENFREIGHT SERVICE Carried out trailer service as per Greenfreight checklist. Customer Instructions: Place vehicle on shaker & Inspected Carried out General Inspection & Checkover Greased vehicle TENSION PIVOT BUSHES & U BOLTS Check over and retension pivot bushes & u bolts TENSION BOLSTER BOLTS												
T492	Myrtleford - Workshop	VehService/DS	VehService/DS D Service	VehService/DS		Check over and tensioned all bolster bolts as reauired. Check brake adjustment getting hot and smoking Travel out to sale yard area. Jack up and check wheel bearings, all ok. Adjust all 8 trailer brakes. Got driver to drive forward and backward to test brakes, all ok. Found RH middle tyre to be locking up. Got truck to workshop, remove hub and tyres, check hub all ok. . Repair flat spots in s-cam. Replace linings while apart due to getting hot Refit wheel and adjust wheel bearing to correct end float. Tensioned wheel nuts. Road test and check check brakes	22/07/2025	1594231	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Brakes/BRAKE ADJ	Brakes\BRAKE ADJ			temps. All okay.	10/07/2025	1562758	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	VehService/DS	VehService/DS D Service	VehService/DS			09/07/2025	1562758	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Brakes/BRAKE ADJ	Brakes\BRAKE ADJ			CHECK BRAKES ON B TRAILER Built up air and adjust all brakes, check over all okay REAR INDICATOR N/W	09/07/2025	1562758	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
						Work order 198820 Test and inspect rear indicator plug. Found loow contacts												
T492	Myrtleford - Workshop	Elect/INDICATORS	no back right indicator			in plug. Spread terminals and clean up, check operation, all ok	09/07/2025	1562758	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
						CHECKER PLATE NEEDS NEW BOLTS Work order 198820												
T492	Myrtleford - Workshop	Chassis\DAMAGE	CHECKER PLATE NEEDS NEW BOLTS			Inspect and found all deck plate tags broken. Found flange cracked. Will need further repairs to rectify.	09/07/2025	1562758	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
						FIRST BINDER BOT RELEASING Work order 198820												
T492	Myrtleford - Workshop	Chassis\WINCH/STRP	1st binder not releasing			Test and found binder would not release. Removed air and use hammer to free seized lock oin. lube us. all ok Jack up each axle and adjusted bearings. Found middle axle	09/07/2025	1562758	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
						grease was unserviceable. Removed hub assembly, cleaned and repacked bearings. Reinstalled hub and adjusted bearings to												
T492	Myrtleford - Workshop	DrivLine\WHEEL BRGS	CHECK AND ADJUST ALL WHEEL BEARINGS			correct end float	20/06/2025	1562758	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
						Found Front RH and Rear LH air bags had snapped bottom mounting bolts. Disconnect air lines and removed air bags. Unable to remove snapped bolts from air bag base plate. Installed new air bags with new bottom mounting bolts. Replaced elbow fitting on front RH air bag as was damaged. Connect air lines and secured all bolts, test operation,												
T492	Myrtleford - Workshop	Susp\AIR BAG	Repair broken bolt air bag			all okay. GREENFREIGHT SERVICE Carried out trailer service as per Greenfreight checklist. Customer Instructions: Place vehicle on shaker & Inspected Carried out General Inspection & Checkover Greased vehicle TENSION PIVOT BUSHES & U BOLTS Check over and retension pivot bushes & u bolts TENSION BOLSTER BOLTS	20/06/2025	1562758	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	VehService/DS	VehService/DS D Service	VehService/DS		Check over and tensioned all bolster bolts as reauired	18/06/2025	1562758	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	VehService/DS	VehService/DS D Service	VehService/DS			29/05/2025	1551955	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
						CHECK WHEEL BEARINGS Jacked up each axle, removed bearing caps and adjusted each wheel bearing to correct end float. Refit caps, lowered												
T492	Myrtleford - Workshop	DrivLine\WHEEL BRGS	CHECK WHEEL BEARINGS			axles.	28/05/2025	1551955	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection	Insp\ANN INSP		CARRY OUT ANNUAL INSPECTION AS PER GREENFREIGHT PAPERWORK Replace rear mudflap	27/05/2025	1551955	PreventativeMaintenance	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Body\MUDGUARDS	Body\MUDGUARDS			Removed broken mud flap, installed new. Tightened mounting bolts	20/05/2025	1533219	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	VehService/DS	VehService/DS D Service	VehService/DS			19/05/2025	1533219	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Tyres\TP9+10	Tyres\TP9+10				02/05/2025	1533219	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BEAUREPAIRES - 3	TRAILER
T492	Myrtleford - Workshop	Tyres\TP7+8	Tyres\TP7+8				02/05/2025	1533219	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BEAUREPAIRES - 3	TRAILER
						JACK UP TRAILER AXLE AND CHECK BEARINGS Jacked up middle axle and checked bearing adjustment. Removed caps and carried out adjustment to correct end												
T492	Myrtleford - Workshop	DrivLine\WHEEL BRGS	DrivLine\WHEEL BRGS			float. Refit cap and lowered axle.	15/04/2025	1533219	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER

						SPIN BOLSTERS AROUND DUE TO BEING BENT																			
						Undo bolster bolts, connect up sling and forklift, lift out																			
T492	Myrtleford - Workshop	Chassis\BOLSTER	Chassis\BOLSTER			bent pins and rotate. refit pins and tensioned bolts.		15/04/2025	1533219	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER							
						Weld cracked mount																			
						Grind back surfaces and prep area for welding. Vee out																			
T492	Myrtleford - Workshop	Chassis\CHAS CRACK	Chassis\CHAS CRACK			crack and welded. Painted area when cool.		15/04/2025	1533219	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER							
T492	Myrtleford - Workshop	VehService\DS	VehService\DS D Service	VehService\DS				15/04/2025	1505736	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER							
T492	Myrtleford - Workshop	Tyres\TP1+2	Tyres\TP1+2					02/04/2025	1505736	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BEAUREPAIRES - 3	TRAILER							
T492	Myrtleford - Workshop	Tyres\TP3+4	Tyres\TP3+4					02/04/2025	1505736	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BEAUREPAIRES - 3	TRAILER							
T492	Myrtleford - Workshop	Tyres\TP5+6	Tyres\TP5+6					02/04/2025	1505736	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BEAUREPAIRES - 3	TRAILER							
						AIR BAG FOLDED UP																			
						Removed LH middle airbag and stretched it out. Reinstalled																			
T492	Myrtleford - Workshop	Susp\AIR BAG	Susp\AIR BAG			air bag, tensioned bolts. Built up air and check operation,		26/03/2025	1505736	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER							
T492	Myrtleford - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		all okay.		24/03/2025	1505736	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER							
						weld cracks.																			
T492	Myrtleford - Workshop	Chassis\CHAS CRACK	Chassis\CHAS CRACK			Found 4 different cracks on trailer. Grind back surfaces																			
						and welded cracks on first and second bolsters																			
						JACK UP AND CHECK WHEEL BEARINGS																			
T492	Myrtleford - Workshop	DrivLine\WHEEL BRGS	DrivLine\WHEEL BRGS			Jacked up axles and inspect wheel bearing movement, all		14/03/2025	1505736	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER							
						within spec.																			
						CHECK FOR AIRLEAKS																			
						Sprayed soapy water over trailer to locate air leaks. Found																			
						one loose hose clamp, tightened. On further inspection,																			
						found RH middle booster was leaking. Removed booster, cut																			
						new push rod to length, change over fittings and installed																			
						new booster. Connect air lines. Adjust brake. Checked over,																			
T492	Myrtleford - Workshop	Brakes\AIR LEAK	Brakes\AIR LEAK			no further leaks		14/03/2025	1505736	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER							
T492	Myrtleford - Workshop	VehService\DS	VehService\DS D Service	VehService\DS				11/03/2025	1505736	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER							
T492	Myrtleford - Workshop	Tyres\TP11+12	Tyres\TP11+12					03/03/2025	1505736	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BEAUREPAIRES - 3	TRAILER							
			CLEAN & REPACK ALL WHEEL BEARINGS & REPLACE S/CAM BUSHES ON LM-RF-RM-RR FIT NEW BRAKES RO LM REPLACE ALL SEALS &REPLACE MISSING BRAKE BACKING PLATES																						
T492	Myrtleford - Workshop	Susp	KMS 151095					26/02/2025	1505736	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	MAXI\PARTS P/L - 3	TRAILER							
T492	Myrtleford - Workshop	VehService\DS	VehService\DS	VehService\DS				18/02/2025	1505736	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER							
						REPAIR DAMAGED GUARD MOUNT																			
						CARRY OUT INSPECTION OF TRAILER AND																			
						REPORT																			
T492	Myrtleford - Workshop	Body\DAMAGE	Body\DAMAGE			RHS BINDER HANDLE BROKEN		03/02/2025	1489448	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	TRIPLE S DISTRIBUTORS - 3	TRAILER							
T492	Myrtleford - Workshop	VehService\DS	VehService\DS	VehService\DS				30/01/2025	1494422	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER							
						Inspected brakes. Found all within spec, monitor and																			
T492	Myrtleford - Workshop	Brakes\BRK O/HAUL	Brakes need replacing			recheck next service		30/01/2025	1485689	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER							
						Found trailer ABS wire was unplugged. Re plugged in and																			
T492	Myrtleford - Workshop	Brakes\ABS	ABS wiring hanging down			checked operation. All ok		30/01/2025	1485689	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER							
T492	Myrtleford - Workshop	Susp\SHOCK ABS	Shock bushes worn			Inspected all shocker bushes. All ok		30/01/2025	1485689	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER							
						Attempted to tension bracket, threads were unservicable.																			
						Cut all threads off, sourced 2 x 1/2 bolts & welded to the																			
T492	Myrtleford - Workshop	Chassis\MUDGUARDS	braket holding front mud guard on is loose			u bolt. Re fit to trailer & tightened. All ok		30/01/2025	1485689	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER							
T492	Myrtleford - Workshop	Body\RWC CONFP	Rear reflective sign missing screws			Replaced all missing screws and secured.		30/01/2025	1485689	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER							
						Work order # 193293																			
						Inspected & cut wiring. Removed the original work lights,																			
T492	Myrtleford - Workshop	Elect\WORK LIGHT	Work lights missing LED's			sourced new lights. Fit to trailer and wired in. Secured		30/01/2025	1485689	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER							
T492	Wodonga - Workshop	Tyres\TP9+10	Tyres\TP9+10			winnx in alace and tensioned bolts.		24/01/2025	1485689	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BEAUREPAIRES	TRAILER							
T492	Wodonga - Workshop	Tyres\TP5+6	Tyres\TP5+6					24/01/2025	1485689	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BEAUREPAIRES	TRAILER							
						Removed the lights in the bar. Found wires for tail lights																			
						were pulled apart. Crimped back in place & tested																			
T492	Myrtleford - Workshop	Elect\TRL LIGHTS	Rear light bar lights cutting out			operation. All ok		21/01/2025	1485689	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER							
						Remove and replace leaking brake booster																			
						Inspected all brake boosters, all okay, none leaking. Found																			
						to have a rubbed air line. Remove rubbed section and																			
						installed new length of hose, tightened hose clamps and																			
T492	Myrtleford - Workshop	Brakes\BOOSTER	Brakes\BOOSTER			tested for air leaks. all okay.		14/01/2025	1485689	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER							
T492	Myrtleford - Workshop	VehService\DS	VehService\DS	VehService\DS				08/01/2025	1484857	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER							
						REMOVE ALL BOLSTER PINS AND SEND TO DIMMYS TO BE TESTED																			
						FIT NEW BOLSTER PINS THAT HAVE ALREADY BEEN TESTED BY DIMMY																			
						Work order 192361																			
						Unbolt each bolster pin, connect with sling and removed.																			
						Installed new bolster pin with new bolt and nut. Carry out																			
T492	Myrtleford - Workshop	Body\BOLSTER	remove all pins from bolsters and refit with pretested pins			for all pins on trailer. Tensioned all bolster bolts		18/12/2024	1484857	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER							
T492	Myrtleford - Workshop	VehService\DS	VehService\DS	VehService\DS				22/11/2024	1473438	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER							
						Check operation of scales channel 3 dropping																			
						Test scales, remove fitter and replaced with new. Check																			
						wiring to module, all okay. Check plug from A trailer to B																			
T492	Myrtleford - Workshop	Chassis\SCALES	Chassis\SCALES			trailer. all okay.		09/11/2024	1468308	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER							
			AIR LEAK			AIR LEAK																			
T492	Myrtleford - Workshop	Susp\AIR LEAK	Air leak at exhaust sort for EBS module.			Air leak at exhaust sort for EBS module.		08/11/2024	1472298	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER							
						Unbolt and removed mud guard. Measure and drilled holes in																			
T492	Myrtleford - Workshop	Chassis\MUDGUARDS	replace mud guard R/H middle			new mud auard. fitted new euard to trailer and tightened		08/11/2024	1472298	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER							
T492	Myrtleford - Workshop	Susp	Job Created from Purchase Order # 105083			PLATE SPRING BPW L/H & LOCK NUT		01/11/2024	1403711	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	MAXI\PARTS P/L - 3	TRAILER							
T492	Myrtleford - Workshop	VehService\DS	VehService\DS	VehService\DS				24/10/2024	1403711	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	JF MECHANICALS - 3	TRAILER							
			BRAKES RUNNING HOT 159.50																						
			C: Brakes running hot																						
			C: LH air bag split																						
			C: Service call to vehicle at Port Fairy, brakes running hot. Found																						
			left front air bag split. Raise and support trailer. Replace air bag																						
			and test for leaks, all OK. Returns to workshop.																						
			TI TRAVEL CONTRACTS 130.50																						
			AT KM TRAVEL CHARGE 48 72.00																						
T492	Myrtleford - Workshop	Susp\AIR BAG	T1054294360 AIRBAG TRAILER BPW D36 CMPL WITH PISTON					02/10/2024	1403711	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	CMV TRUCK AND BUS PTY LTD - 3	TRAILER							
			BLOWN AIR BAG - SUBLET REPAIR																						
			Travelled to truck broken down, blown air bag. Bung off air																						
			line to inflate other air bags. Removed mounting bolts and																						
			remove bag. Change over fittings and installed new bag.																						
			Reconnect lines and test, all okay.																						
			Sublet																						
T492	Myrtleford - Workshop	Susp\AIR BAG	15105717 attend breakdown					09/07/2024	1403711	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	PACCAR PARTS FLEET SERVICES - 3	TRAILER							
T492	Myrtleford - Workshop	Tyres\TP9+10	Tyres\TP9+10					27/06/2024	1403711	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER							
			CHECK OPERATION OF SCALES WEINT OVER AT MILL LAST NIGHT																						
T492	Myrtleford - Workshop	Elect\ELECT P&W	Removed breather from transducer. blow out breather as reauiered					26/06/2024	1403711	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	PACCAR PARTS FLEET SERVICES - 3	TRAILER							
			REAR BINDER HARD TO RELEASE																						
			Inspect release mechanism, found cable fouling in brake																						
T492	Myrtleford - Workshop	Chassis\WINCH/STRP	valve. Reroute cable and secured. test operation. all okay					26/06/2024	1403711	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	PACCAR PARTS FLEET SERVICES - 3	TRAILER							
			REAR BINDER HARD TO RELEASE																						
			Inspect release mechanism, found cable fouling in brake																						
T492	Myrtleford - Workshop	Unknown\No Show	valve. Reroute cable and secured. all okay.					26/06/2024	1403711	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER							
T492	Myrtleford - Workshop	VehService\DS	VehService\DS	VehService\DS				25/06/2024	1403711	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER							
			AIR LEAK -Inspect for air leak, found RH middle booster hose was rubbed. Cut out damaged section																						
			& replaced with new hose. Connect with barb joiners & hose clamps. Checked over, no further leaks.																						
T492	Myrtleford - Workshop	Brakes\AIR LEAK	PARTS $16.73 | LABOUR $202.50					21/06/2024	1403711	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	PACCAR PARTS FLEET SERVICES - 3	TRAILER							
T492	Myrtleford - Workshop	VehService\DS	VehService\DS	VehService\DS				07/06/2024	1403711	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER							
T492	Myrtleford - Workshop	DrivLine\WHEEL BRGS	CHECK WHEEL BEARINGS			Jacked all axles, removed hub caps & adjusted wheel bearings to spec. Refit hub caps and lowered axles.		07/06/2024	1403711	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER							
			REMOVE HAMMER LOCK & SECURE CHAIN TO BOLSTER																						
T492	Myrtleford - Workshop	Body\CHN/RLR/MN	KM's 143445 4			Measure & cut lenaths of chain to suit. Cut off old hammerlock and chain. Installed new chain & secured to first bolster.		07/06/2024	1403711	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER							
			24/088299 Cable EW Reach Slave to Front of Trailer 12m 1.00 $260.00 $286.00																						
T492	Myrtleford - Workshop	Elect\ELECT P&W	ZZ834 Freight					06/06/2024	1403711	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	ELPHINSTONE ENGINEERING - 3	TRAILER							
T492	Myrtleford - Workshop	Elect\BREAKDOWN	call AKD COLAC REPAIR TAIL LIGHTS					06/06/2024	1403711	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	CT DIESEL SERVICES - 3	TRAILER							
T492	Myrtleford - Workshop	VehService\DS	VehService\DS ex # 1086239	VehService\DS				04/06/2024	1403711	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER							
T492	Myrtleford - Workshop	Body\BOLSTER	A/HIS BREAKDOWN - BOLSTER FELL OVER AND LIGHTS N/W -			Received breakdown call for trailer lights not workine. arranged to meet driver at workshop. Found first bolster had fallen over & torn all earth wirine from trailer plue. Repaired lights and wirine. Adde		01/06/2024	1403711	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER							
T492	Myrtleford - Workshop	Tyres\TP5+6	Tyres\TP5+6					30/05/2024	1403711	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BEAUREPAIRES - 3	TRAILER							
T492	Myrtleford - Workshop	Tyres\TP07	Tyres\TP07					30/05/2024	1403711	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BEAUREPAIRES - 3	TRAILER							
T492	Myrtleford - Workshop	VehService\DS	D Service PO#:LH48277	VehService\DS				24/05/2024	1403711	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER							
T492	Myrtleford - Workshop	Tyres\TP9+10	Tyres\TP9+10					23/05/2024	1403711	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BEAUREPAIRES - 3	TRAILER							
T492	Myrtleford - Workshop	Susp\AIR BAG	FRONT LEFT AIR BAG LEAKING			Found LH front air bag was leaking & perished. Removed air bag Found LH front air bag was leaking & perished. Removed air bag		15/05/2024	1403711	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER							
T492	Myrtleford - Workshop	Chassis\TRL LEGS	MAKE NEW BOTTOM SECTION OF LANDING LEG			MAKE NEW BOTTOM SECTION OF LANDING LEG MAKE NEW BOTTOM SECTION OF LANDING LEG leg, drilled holes & mounted. Painted leg landing - all ok		15/05/2024	1403711	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER							
						WEIGH SCALES READING DIFFERENT MEASUREMENTS - Driver reported scales were dropping																			
						out and giving false readings. Inspect & trailer wiring and plugs, all okay. Checked transponder fitter &																			
						cleaned. Checked operation of transponder, all okay. Checked operation of slave unit & found it was																			
						faulty. Travel to GF depot for replacement, found both slave units from GF were also faulty. Return to																			
						depot and collect original slave unit. Advised customer of correct part numbers & units to be ordered.																			
T492	Myrtleford - Workshop	Chassis\SCALES	Easyweigh Slave			Refit faulty unit to trailer until new part arrives.		01/05/2024	1403711	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER							
T492	Myrtleford - Workshop	Brakes\AIR FITTIN	WORN BRAKE LINE - Found air lines had multiple rubs & signs of wear. Cut out air line & installed new air lines. Joined in hose & clamped, tested operation, all okay.					25/04/2024	1403711	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER							
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					25/04/2024	1403711	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER							
			D Service As Per Attached Checklist																						
T492	Myrtleford - Workshop	VehService\DS	PO#:LOB5535	VehService\DS				25/04/2024	1403711	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER							
						REPAIR @ WKSHOP - Arranged complete trailer re-wire was required. Cut both ends of 7 core wire, installed new wiring																			
						from front to back of trailer. Secure wiring with conduit. Pulled out wiring from each bolster & run new wiring through bolsters																			
			A/HIS BREAKDOWN NO TAIL LIGHTS - Travel to truck in Tarpeena & inspect lights fault. Inspect trailer plugs & fuses,			& connect to clearance lights. Joined into parkers & indicators, run down to rear bar lights. Removed wiring in rear bar, run &																			
			Found trailer plug s/h. Replaced male & female ends. Lights on & trailer still n/w. Wriggled wiring for rear lights, lights would			join new wiring to all lights. Secured all new wiring & protected. Replace 2 broken clearance lights. Test lights, had earth																			
T492	Myrtleford - Workshop	Elect\TAIL LIGHT	flicker. Cut out section of wirine & re-run new wires. tested liaht. n/w. Needs repair at workshop durine normal hours.			supply faults from A trailer. Found olue was shortine out. hard wired olue for rear liht bar. liahts all okw.		20/04/2024	1396639	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER							
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					03/04/2024	1396273	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER							
			D Service As Per Attached Checklist																						
T492	Myrtleford - Workshop	VehService\DS	PO#:LOB5392	VehService\DS				03/04/2024	1396273	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER							
			BOLSTER LIGHT R/W - RH second bolster light not working. Removed light & tested wiring, found to																						
T492	Myrtleford - Workshop	Elect\ELECT P&W	be faulty. Run new wire from light to connection, joined new wire and tested, all okay. Refit light.					03/04/2024	1396273	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER							
			AFTER HIS BREAKDOWN - CLEARANCE LIGHTS N/W																						
			Met truck at workshop checked for power coming out of A trailer plug. Inspected the socket & found it																						
			was corroded and broken. Cut off plug, joined wires into new plug. Reconnect lights back in & found																						
			still no good. Tested power out the back of the socket & found there was little power coming out.																						
			Removed protective tape & inspected for rubbed wiring. Traced the wiring up to one of the bolsters &																						
			found wirng was rubbed. Removed tape & strip back wiring. Cut out rubbed section & rejoined. Test																						
T492	Myrtleford - Workshop	Elect\BREAKDOWN	lights. all okw.					26/03/2024	1392059	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER							
			AIR SUPPLY BEEN KNOCKED OFF RIDE HEIGHT - Removed damaged fitting & installed new one.																						
T492	Myrtleford - Workshop	Susp\AIR FITTIN	On inspection. found air bae feed fittine was bent. Removed fittine and realaced with new. Secured.					26/03/2024	1391956	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER							
T492	Myrtleford - Workshop	Tyres\TP1+2	Tyre Position 1 + 2					22/03/2024		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	Albury Workshop	TRAILER							
T492	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP		TRAILER ROADWORTHY - trailer roadworthy as per checklist & check over		15/03/2024		PreventativeMaintenance	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER							
			CHECK WHEEL BEARINGS - jack up and check wheel bearings, remove caps and adjust all spec																						
T492	Myrtleford - Workshop	Steering\WHEEL BRGS	Trailer will require repack of bearines.					15/03/2024		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER							
T492	Myrtleford - Workshop	Tyres	REMOVE SPARE TYRE - Remove spare tyres, remove all brackets required to remove spare tyres.					15/03/2024		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER							
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					15/03/2024	1384828	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER							
			D Service As Per Attached Checklist																						
T492	Myrtleford - Workshop	VehService\DS	PO#:LOB4693	VehService\DS				15/03/2024	1384828	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER							
T492	Myrtleford - Workshop	Tyres\TP11+12	Tyre Position 11 + 12					09/03/2024		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	Albury Workshop	TRAILER							
						NEEDS SCALE WIRE FRONT TO SLAVE FITTED CORRECTLY - Plugged & rewired scales loom,																			
T492	Myrtleford - Workshop	Elect\ELECT P&W	NEEDS SCALE WIRE (FRONT TO SLAVE) FITTED CORRECTLY (OLD ONE REMOVED)			cut & refit scale plue to trailer. Zip tied wirine back in. tested all components. all workine okw.		29/02/2024	1375528	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER							
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					29/02/2024	1375528	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER							
			D Service As Per Attached Checklist																						
T492	Myrtleford - Workshop	VehService\DS	PO#:LOB4392	VehService\DS				29/02/2024	1375528	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER							
T492	Myrtleford - Workshop	Tyres	SPARE TYRE REMOVAL. WE CAN GET THEM OFF. DON'T NEED THEM.					28/02/2024	1403711	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	811165	BARRY MANEY -

			2nd TO LAST BOLSTER RH SIDE LIGHT N/W - Removed light from bolster & found to have a snapped wire. Tested light, all okay. Traced wiring & found to have numerous joins, locate short along chassis. Cut out all joins and fit one joiner to repair short. Tested power on wire going into bolster, all okay. Tested coming out of bolster, no power. Pull wire out from bolster, found corrosion in wire. Cut new twin core wire to length & feed through bolster, joined to wiring at chassis. Tested power, all okay.														
T492	Myrtleford - Workshop	Elect/ELECT P&W	Connect to bolts, w+as wirne & secured. Reinstalled light & checked operation. all okay.			02/02/2024	136834	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3		TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			02/02/2024	136814	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3		TRAILER
T492	Myrtleford - Workshop		D Service As Per Attached Checklist														
T492	Myrtleford - Workshop	VehService/DS	PO#:L083744	VehService/DS		02/02/2024	136814	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3		TRAILER
T492	Myrtleford - Workshop	Tyres/JTP3+4	Tyre Position 3 + 4			23/01/2024		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Albury Workshop		TRAILER
T492	Myrtleford - Workshop	Tyres/JTP7+8	Tyre Position 7 + 8			23/01/2024		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Albury Workshop		TRAILER
			CHECK SCALES - Inspect connection of scales plugs, all correct. Remove & check for contamination, cleaned out all plugs & reconnect. Faults changed to inactive except for CH 1 pow fault fd. Inspect & test, all okay. Uase with Elphinstone tech & was able to reset memory & calibrate scales.Test operation. all okay. Resecured wirirne.														
T492	Myrtleford - Workshop	Chassi/SCALES				18/01/2024	1357400	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Albury Workshop		TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			17/01/2024	1359546	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3		TRAILER
T492	Myrtleford - Workshop		D Service As Per Attached Checklist														
T492	Myrtleford - Workshop	VehService/DS	PO#:L083430	VehService/DS		17/01/2024	1359546	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3		TRAILER
					FIT DECK PLATE TO CHASSIS - Repair from deck plate being ripped by grab. Unbolt existing smaller deck plate to move over AXEL/BEL module. Cleaned up surfaces for welding. Measure & cut flat bar into tabs & welded onto chasis above module. Drilled holes to suit bolts. Installed deck plate & fitted nuts & bolts. tensioned.								
T492	Myrtleford - Workshop	Body/PANELS	REAR CHASSIS COVER NEEDS NEW BOLTS.			08/12/2023	1348356	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Albury Workshop		TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			07/12/2023	1348356	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3		TRAILER
T492	Myrtleford - Workshop		D Service As Per Attached Checklist														
T492	Myrtleford - Workshop	VehService/DS	PO#:L082826	VehService/DS		07/12/2023	1348356	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3		TRAILER
T492	Albury - Workshop	Elect/TAIL LIGHT	clean wiring plug oin right rear light			01/12/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	QT DIESEL SERVICES - 3		TRAILER
					Deck plate was removed as requested by the driver. Was ripped & damaged by the grab. New deck												
T492	Myrtleford - Workshop	Body/PANELS	REPAIR / REMOVE DECK PLATE - RIPPED OFF BY GRAB		plate to be arranaed with Greenfreight if required	30/11/2023	1342042	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3		TRAILER
					Inspected height rod and found it to be turned 180 degree. Flip rod												
T492	Myrtleford - Workshop	Susp/HCV	CHECK RIDE HEIGHT VALVE		over & dumped the air baes. Built up the air & checked operation. all okay.	23/11/2023	1339168	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3		TRAILER
					Re set the circuit breaker, wriggled the wiring in												
					bolsters. Removed indicators from the rear light bar and inspected wiring. Unable to fault. Replaced												
T492	Myrtleford - Workshop	Elect/INDICATORS	INDICATORS POPPED CIRCUIT BREAKER		a damaged olue on RH indicator.	23/11/2023	1339168	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3		TRAILER
					Jacked and support chassis & rear spring. Undo u bolts,												
					removed saddle. Installed new saddle & tensioned. Replaced shocker & tensioned new bolt. Refit u bolts, tensioned.												
T492	Myrtleford - Workshop	Susp/SHOCK ABS	BROKEN SADDLE RH SIDE & REPLACE SHOCKER		Lowered axle	16/11/2023	1338110	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3		TRAILER
					Tested power, no good. Traced wiring & found damaged section of wires. Cut out												
T492	Myrtleford - Workshop	Elect/TAIL LIGHT	NUMBER PLATE LIGHT N/W		section and tidy up wirine. reioined wires and tested lieht. okav.	16/11/2023	1338110	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3		TRAILER
T492	Myrtleford - Workshop	Body/MUDGUARDS	STRAIGHTEN RH FRONT GUARD BAR		Assited heat to RH front mudcaurd bar & attemot to straighten out. no ecxid. Applied extra heat & use forklift to eet straightened. Once straight. erind back surfaces and welded cracked area Painted w	16/11/2023	1338110	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3		TRAILER
					Cut small part of flat bar ready to install. Secured to the chasis &												
T492	Myrtleford - Workshop	Body/PANELS	REAR CHASSIS COVER NEEDS NEW BOLTS		slate wirne nuts & bolts.	16/11/2023	1338110	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3		TRAILER
					Removed bolster light & traced broken wire, cut out												
T492	Myrtleford - Workshop	Elect/INDICATORS	2ND FROM REAR BOLSTER RH INDICATOR BROKEN WIRE		damaged section and rejoined. Tested light, all okay.	16/11/2023	1338110	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3		TRAILER
T492	Myrtleford - Workshop	Elect/ELECT P&W	ON SECOND BOLSTER THE INDICATOR LIGHT NEED REPLACING.		refer to 181686	16/11/2023		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3		TRAILER
T492	Myrtleford - Workshop	Susp/SUSPINSION	SADDLE ON R/H SIDE NEEDS REPLACING AND SHOCKER PUT BACK ON.		refer to 181686	16/11/2023		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3		TRAILER
T492	Myrtleford - Workshop	Elect/ELECT P&W	ONE NUMBER PLATE LIGHT NOT WORKING.		refer to 181686	16/11/2023		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3		TRAILER
T492	Myrtleford - Workshop	Body/MUDGUARDS	STRAIGHTEN RH FRONT MUDGUARD BAR.		refer to 181686	16/11/2023		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3		TRAILER
T492	Myrtleford - Workshop	Elect/ELECT P&W	2ND FROM REAR BOLSTER RH INDICATOR BROKEN WIRE.		refer to 181686	16/11/2023		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3		TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			16/11/2023	1338110	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3		TRAILER
T492	Myrtleford - Workshop		D Service As Per Attached Checklist														
T492	Myrtleford - Workshop	VehService/DS	PO#:L082266	VehService/DS		16/11/2023	1338110	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3		TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			01/11/2023	1329698	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3		TRAILER
T492	Myrtleford - Workshop		D Service As Per Attached Checklist														
T492	Myrtleford - Workshop	VehService/DS	PO#:L081993	VehService/DS		01/11/2023	1329698	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3		TRAILER
			BOLSTER LIGHTS N/W - found two bolster lights n/w on LH front. Removed lights & replaced with														
T492	Myrtleford - Workshop	Elect/ELECT P&W	new. Joined wiring, tested, all okay.			01/11/2023	1329698	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Albury Workshop		TRAILER
			AIR BAG FOLDED ON ITSELF - Front left air bag was folded in. Raised all bags, would not pop out.														
T492	Myrtleford - Workshop	Susp/AIR BAG	Removed shockers & axle straps. raised air bae. pooped out. All workine okay and hobbine air.			01/11/2023	1329698	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Albury Workshop		TRAILER
T492	Myrtleford - Workshop	Chassis	WORN BUSHES IN CHASSIS PIVOTS.			31/10/2023	1403711	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3		TRAILER
T492	Myrtleford - Workshop	Tyres/JTP9+10	Tyre Position 9 + 10			27/10/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Albury Workshop		TRAILER
T492	Myrtleford - Workshop	Tyres/JTP11+12	Tyre Position 11 + 12			27/10/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Albury Workshop		TRAILER
T492	Myrtleford - Workshop	Tyres/JRUN OUT	5-8			27/10/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Albury Workshop		TRAILER
T492	Albury - Workshop	Brakes/JBRAKE ADJ	CAN WE GET OPERATION OF BRAKES CHECKED, ON BOTH PARK AND FOOT, HAD A WHEEL ABLE TO TURN WHEN TORQUING WHEEL NUTS.		RH MIDDLE BRAKE - remove & replace RH middle axle brake linings & drum.	13/10/2023	1318625	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Albury Workshop		TRAILER
					CRACKED BOLSTER 2ND FROM REAR - grind out surfaces on cracked bolster. Weld new horizontal												
					stitch to crack. Tidy up welds & painted.												
					FRONT BOLSTER LIGHT INSIDE - Found bolster light n/w. Remove light & test power, all okay.												
T492	Albury - Workshop	Chassis	WORN CHASSIS UNDER BOLSTERS.		Removed & replaced light. Joined wiring to light, tested, all okay.	13/10/2023	1318625	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Albury Workshop		TRAILER
T492	Albury - Workshop	Chassis	WORN CHASSIS UNDER BOLSTERS.			13/10/2023	1318625	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Albury Workshop		TRAILER
T492	Albury - Workshop	Chassi/BOLSTER	CRACKED 2ND FROM REAR BOLSTER NEAR BOLTS.			13/10/2023	1318625	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Albury Workshop		TRAILER
T492	Albury - Workshop	Body/MUDGUARDS	OUTER MUDFLAPS ON REAR TORN.		REAR MUD FLAPS - remove & replaced rear mud flaps.	13/10/2023	1318625	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Albury Workshop		TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			13/10/2023	318625	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3		TRAILER
T492	Myrtleford - Workshop		D Service As Per Attached Checklist														
T492	Myrtleford - Workshop	VehService/DS	PO#:L081605	VehService/DS		13/10/2023	318625	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3		TRAILER
T492	Myrtleford - Workshop	Elect/ELECT P&W	CLEARANCE LIGHT FRONT BOLSTER UH SIDE BROKENAND FLICKERS OFF/ON AT TIMES.all lights were checked on D service and were all workine refer invioce 370602. CLEARANCE LIGHT FRONT B			13/10/2023	1318628	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3		TRAILER
T492	Myrtleford - Workshop	Tyres/JITMENT	1+2+6			27/09/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Albury Workshop		TRAILER
T492	Myrtleford - Workshop		D Service As Per Attached Checklist														
T492	Myrtleford - Workshop	VehService/DS	Barry Maney PO#:L081261	VehService/DS		25/09/2023	1403711	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Wodonga Workshop		TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			25/09/2023	1403711	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Wodonga Workshop		TRAILER
T492	Myrtleford - Workshop	Chassis	REAR CHASSIS COVERS TO BE REFITTED CRSQMETHING PUT OVER ABS VALVE TO PROTECT IT.			25/09/2023	1403711	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Wodonga Workshop		TRAILER
T492	Myrtleford - Workshop	Chassi/AIR LEAK	CHECK ALL CONNECTIONS AROUND AIR TANKS, VALVES, AIRBAGS etc FOR AIR LEAKS PLEASE.			25/09/2023	1403711	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Wodonga Workshop		TRAILER
			CHECK BRAKES, ABLE TO TURN WHEEL WHEN TORQUING WHEEL NUTS - carry out brake roller														
T492	Myrtleford - Workshop	Brakes	test. all axles passed okay on both service and park brake.			14/09/2023	1298887	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Albury Workshop		TRAILER
T492	Myrtleford - Workshop	Chassi/BOLSTER	WELD CRACKS ON BOLSTER AND PIN - cleaned area, grind out cracks. Welded & paint over, okay			14/09/2023	1298887	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Albury Workshop		TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			13/09/2023	1298887	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Wodonga Workshop		TRAILER
T492	Myrtleford - Workshop		D Service As Per Attached Checklist														
T492	Myrtleford - Workshop	VehService/DS	Barry Maney PO#:L080683	VehService/DS		13/09/2023	1298887	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Wodonga Workshop		TRAILER
T492	Myrtleford - Workshop	Tyres/Puncr	9			06/09/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Albury Workshop		TRAILER
T492	Myrtleford - Workshop	Brakes/JBRK O/HAUL	REPLACE WORN BRAKES - Jack up axle, replaced RH rear brakes. refit wheels, tensioned.			01/09/2023	1288470	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Albury Workshop		TRAILER
			ADJUST W/BEARINGS - Front and rear axle bearings out of adjustment. Removed caps, jack up axle														
T492	Myrtleford - Workshop	Steering/WHEEL BRGS	adjust bearings to spec. Refit caps and lowered axles.			01/09/2023	1288470	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Albury Workshop		TRAILER
			AIR LEAK -air tank fitting was leaking. Drained air tank, removed damaged fitting. Installed new fitting														
T492	Myrtleford - Workshop	Susp/AIR LEAK	with sealant. Filled tank with air. tested. all okay.			01/09/2023	1288470	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Albury Workshop		TRAILER
T492	Myrtleford - Workshop	Body/MUDGUARDS	REPAIR DAMAGED GUARD - inspect guard and secured with cable ties.			01/09/2023	1288470	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Albury Workshop		TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			31/08/2023	1288470	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Wodonga Workshop		TRAILER
T492	Myrtleford - Workshop		D Service As Per Attached Checklist														
T492	Myrtleford - Workshop	VehService/DS	Barry Maney PO#:L080668	VehService/DS		31/08/2023	1288470	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Wodonga Workshop		TRAILER
T492	Myrtleford - Workshop	Tyres/JITMENT	7+9			30/08/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Albury Workshop		TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			22/08/2023	1280404	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Wodonga Workshop		TRAILER
					AIR LEAKS 25/08/2023												
					Check over trailer for air leaks, found air leak. Had to get correct fitting from GWB. Removed old fitting												
T492	Myrtleford - Workshop	Susp/AIR BAG	AIRBAGS LEAKING.		and flut new. build up air and check air leaks. all okay.	22/08/2023	1280404	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Wodonga Workshop		TRAILER
T492	Myrtleford - Workshop		D Service As Per Attached Checklist														
T492	Myrtleford - Workshop	VehService/DS	Barry Maney PO#:L080453	VehService/DS		22/08/2023	1280404	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Wodonga Workshop		TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			11/08/2023	127254	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Wodonga Workshop		TRAILER
T492	Myrtleford - Workshop		D Service As Per Attached Checklist														
T492	Myrtleford - Workshop	VehService/DS	Barry Maney PO#:L080212	VehService/DS		11/08/2023	127254	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Wodonga Workshop		TRAILER
T492	Myrtleford - Workshop	Chassis	REAR CHASSIS COVERS ALL MOUNTS ARE BROKEN. PLATES ARE SITTING ON WIRING/ AIR LINE/ QUICK RELEASE CABLES.done on D service refer 367949. REAR CHASSIS COVERS ALL MOUNTS ARE			11/08/2023	127254	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3		TRAILER
T492	Myrtleford - Workshop	Chassis	DECK PLATES LOOSE.done on D service refer 367949. DECK PLATES LOOSE.			11/08/2023	127254	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3		TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			28/07/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Wodonga Workshop		TRAILER
T492	Myrtleford - Workshop		D Service As Per Attached Checklist														
T492	Myrtleford - Workshop	VehService/DS	Barry Maney PO#:L079909	VehService/DS		28/07/2023		Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Wodonga Workshop		TRAILER
T492	Myrtleford - Workshop	Tyres/JTP3	Tyre Position 3			27/07/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Albury Workshop		TRAILER
T492	Myrtleford - Workshop	Tyres/JTP5+6	Tyre Position 5 + 6			27/07/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Albury Workshop		TRAILER
T492	Myrtleford - Workshop	Tyres/JTP7+8	Tyre Position 7 + 8			27/07/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Albury Workshop		TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			05/07/2023	1248450	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Wodonga Workshop		TRAILER
T492	Myrtleford - Workshop	Elect/INDICATORS	INDICATOR NOT WORKING ON L/H WHEN LOADED. OK EMPTY.			05/07/2023	1248450	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Wodonga Workshop		TRAILER
T492	Myrtleford - Workshop	Body/AWC COMP	LONG VEHICLE SIGN TO BE REPLACED, NON-REFLECTIVE.			05/07/2023	1248450	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Wodonga Workshop		TRAILER
T492	Myrtleford - Workshop	Susp/AIR LEAK	CHECK FOR LEAKS AROUND AIRBAGS, HEAR SOME SMALL LEAKS WHEN LOADED.			05/07/2023	1248450	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Wodonga Workshop		TRAILER
T492	Myrtleford - Workshop		D Service As Per Attached Checklist														
T492	Myrtleford - Workshop	VehService/DS	Barry Maney PO#:L079401	VehService/DS		05/07/2023	1248450	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Wodonga Workshop		TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			23/06/2023	1239906	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Wodonga Workshop		TRAILER
T492	Myrtleford - Workshop		D Service As Per Attached Checklist														
T492	Myrtleford - Workshop	VehService/DS	Barry Maney PO#:L079136	VehService/DS		23/06/2023	1239906	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Wodonga Workshop		TRAILER
T492	Myrtleford - Workshop	Tyres/JTP1+2	Tyre Position 1 + 2			16/06/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Albury Workshop		TRAILER
T492	Myrtleford - Workshop	Tyres/JTP7+8	Tyre Position 7 + 8			16/06/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Albury Workshop		TRAILER
T492	Myrtleford - Workshop	Tyres/JTP11+12	Tyre Position 11 + 12			16/06/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Albury Workshop		TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			09/06/2023	1232266	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3		TRAILER
T492	Myrtleford - Workshop		D Service As Per Attached Checklist														
T492	Myrtleford - Workshop	VehService/DS	PO#:L078803	VehService/DS		09/06/2023	1232266	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3		TRAILER
T492	Myrtleford - Workshop	Elect/INDICATORS	Indicators cutting out circuit breaker			08/06/2023	1231266	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Albury Workshop		TRAILER
T492	Myrtleford - Workshop	Tyres/JTP9+10	Tyre Position 9 + 10			30/05/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Albury Workshop		TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			28/05/2023	1221778	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3		TRAILER
T492	Myrtleford - Workshop		D Service As Per Attached Checklist														
T492	Myrtleford - Workshop	VehService/DS	PO#:L078618	VehService/DS		28/05/2023	1221778	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3		TRAILER
T492	Myrtleford - Workshop	Steering/WHEEL ALGN	Carry Out Wheel Alignment			16/05/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Albury Workshop		TRAILER
T492	Myrtleford - Workshop	Body/MUDGUARDS	repaired damaged mudguard bracket			12/05/2023	1211849	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Albury Workshop		TRAILER
T492	Wodonga - Workshop	Chassi/SKID PLATE	SKID PLATE BOLT LOOSE RH SIDE REAR BOLT.			09/05/2023	1403711	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Wodonga Workshop		TRAILER
T492	Myrtleford - Workshop		D Service As Per Attached Checklist														
T492	Myrtleford - Workshop	VehService/DS	Barry Maney PO#:L078197	VehService/DS		08/05/2023	1403711	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Wodonga Workshop		TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			08/05/2023	1403711	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Wodonga Workshop		TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			19/04/2023	142972	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Wodonga Workshop		TRAILER
T492	Myrtleford - Workshop		D Service As Per Attached Checklist														
T492	Myrtleford - Workshop	VehService/DS	Barry Maney PO#:L077839	VehService/DS		19/04/2023	142972	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Wodonga Workshop		TRAILER
T492	Wodonga - Workshop	Chassi/BOLSTER	REMOVED AND CRACK TESTED ALL BOLSTER PEGS. FOUND LH3 AND RH3 CRACKED. REPLACED. CLEANED OUT BOLSTER SOCKETS AND PEGS.			07/04/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Wodonga Workshop		TRAILER
			Remove & crack test bolsters														
			LH1 test ok, RH1 test ok														
			LH2 test ok, RH2 test ok														
			LH3 cracked. Replaced with GF spare. Drilled holes and cut to suit. RH3 also cracked. Repeat same for RH side. Install new pins with new nuts & bolts.														
			LH4 test ok, RH4 test ok														
T492	Myrtleford - Workshop	Chassi/BOLSTER	All bolsters and pins needed to be cleaned for removal & refitment			07/04/2023	1132244	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Albury Workshop		TRAILER
T492	Albury - Workshop	VehService/DS	D Service As Per Attached Checklist	VehService/DS		04/04/2023	1403711	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Albury Workshop		TRAILER
T492	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			04/04/2023	1403711	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	Albury Workshop		TRAILER
T492	Myrtleford - Workshop	Susp/HCV	REPLACE RIDE HEIGHT VALVE, PLASTIC BROKEN WHERE ROD GOES THROUGH.			04/04/2023	1330667	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B1116S	BARRY MANEY - 3		TRAILER
T492	Myrtleford - Workshop	Chassi/BOLSTER	2ND REAR BOLSTER CRACKING AGAIN WHERE ITS BEEN WELDED BEFORE ON REAR SIDE NEAR MOUNT BOLTS.			04/04/2023

			D Service As Per Attached Checklist																
T492	Myrtleford - Workshop	VehService/DS	PO#:L076411	VehService/DS			01/02/2023	1152195	Service	Completed	Greenfreight Loxeine Vic	KennedyBPW	Mt Gambier	STK	B11165	BARRY MANEY - 3	TRAILER
			Repack Bearings																
			Jack up all axles, removed wheels and hubs. Removed bearings and cleaned off seals. Clean and repack bearings. Replace LH middle & RH rear bearings. Refit bearings with new seals, refit																
T492	Myrtleford - Workshop	Steering\WHEEL BRGS	wheels new dust seals & gaskets. Tensioned wheel nuts.				23/12/2022	1141911	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Elect/ELECT P&W	CLEARANCE LIGHT MISSING 2ND BOLSTER FROM FRONT OF TRAILER RH SIDE.				17/12/2022	1139926	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Chassis\BOLSTER	3RD BOLSTER FROM FRONT CRACKED RH SIDE FRONT IN FROM MOUNTING BOLTS AND LH SIDE BACK WHERE IT'S BEEN WELDED BEFORE.				17/12/2022	1139926	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				13/12/2022	1139926	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist																
T492	Myrtleford - Workshop	VehService/DS	Barry Maney PO#:L076682	VehService/DS			13/12/2022	1139926	Service	Completed	Greenfreight Loxeine Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonwa Workshop	TRAILER
T492	Wodonga - Workshop	Chassis\FIFTH WHEE	BACK SKID PLATE BOLT LOOSE NEAR AIR WINCH.				03/12/2022		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonga Workshop	TRAILER
T492	Wodonga - Workshop	Chassis\BOLSTER	2ND FROM REAR BOLSTER LOOSE BOLT DRIVER'S SIDE.				03/12/2022		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonga Workshop	TRAILER
T492	Wodonga - Workshop	Drivline\WHL HUB	HUBOMETER FULL OF CONDENSATION.				03/12/2022		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonga Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				02/12/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist																
T492	Myrtleford - Workshop	VehService/DS	Barry Maney PO#:L075476	VehService/DS			02/12/2022		Service	Completed	Greenfreight Loxeine Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonwa Workshop	TRAILER
T492	Myrtleford - Workshop	Chassis\BOLSTER	BOLT THAT STOPS TRAILER FROM BENDING BEHIND FRONT BOLSTER MISSING.				02/12/2022		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonga Workshop	TRAILER
T492	Myrtleford - Workshop	Elect	Scales Fault				30/11/2022	1403711	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Albury Workshop	TRAILER
T492	Myrtleford - Workshop	Tyres\TP1+2	Tyre Position 1 + 2				19/11/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Albury Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				17/11/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist																
T492	Myrtleford - Workshop	VehService/DS	Barry Maney PO#:L075160	VehService/DS			17/11/2022		Service	Completed	Greenfreight Loxeine Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonwa Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				08/11/2022	1114204	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist																
T492	Myrtleford - Workshop	VehService/DS	Barry Maney PO#:L074987	VehService/DS			08/11/2022	1114204	Service	Completed	Greenfreight Loxeine Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonwa Workshop	TRAILER
T492	Myrtleford - Workshop	Chassis\BOLSTER	THIRD BOLSTER CRACKED ON R/H SIDE.				03/11/2022		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Susp\AIR BAG	AIR LEAK LHS MIDDLE AXLE AIRBAG WHEN LOADED.				03/11/2022		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				29/10/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonga Workshop	TRAILER
T492	Myrtleford - Workshop	Susp\WHEEL ALIGN	RUNS TO THE LEFT (NOT TRACKING) BY ABOUT 2 (ILLEGIBLE). DANGEROUS ON A BRIDGE.		NOT ADJUSTABLE. HAVE REPLACED PIVOT BUSHES ON A TRAILER.		29/10/2022		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonga Workshop	TRAILER
T492	Myrtleford - Workshop	Chassis\EXTR TU	NEED NEW AIR TAP HANDLE ON FRONT BINDER.		NOT IN BOOK.		29/10/2022		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonga Workshop	TRAILER
T492	Myrtleford - Workshop	Body\MUDGUARDS	NEED NEW MUD FLAP L/H SIDE.		NOT IN BOOK.		29/10/2022		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonga Workshop	TRAILER
T492	Myrtleford - Workshop	Chassis\WINCH/S/TRP	REPLACE REAR 3 STRAPS ONLY.		REPLACED.		29/10/2022		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist																
T492	Myrtleford - Workshop	VehService/DS	Barry Maney PO#:L074780	VehService/DS			29/10/2022		Service	Completed	Greenfreight Loxeine Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonwa Workshop	TRAILER
T492	Myrtleford - Workshop	Susp\AIR BAG	AIRBAG CONNECTION R/H CENTRE ON TOP.		Repair Air leak at airbag fitting removed and repaired		07/10/2022		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				07/10/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist																
T492	Myrtleford - Workshop	VehService/DS	Barry Maney PO#:L074475	VehService/DS			07/10/2022		Service	Completed	Greenfreight Loxeine Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonwa Workshop	TRAILER
T492	Myrtleford - Workshop	Chassis\CHAS CRACK	Major crack in chassis, separate trailer make adaptor trailer connection & deliver to welder, pick up truck & reconnect to Trailer & deliver				28/09/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				20/09/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist																
T492	Myrtleford - Workshop	VehService/DS	Barry Maney PO#:L074167	VehService/DS			20/09/2022		Service	Completed	Greenfreight Loxeine Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonwa Workshop	TRAILER
T492	Myrtleford - Workshop	Tyres\Re-Tor	Re-Torque				13/09/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				25/08/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonga Workshop	TRAILER
T492	Myrtleford - Workshop	Elect/ELECT P&W	SCALES SAME ISSUE AS ALWAYS, READ HIGH THEN COUNT DOWN TO CORRECT WEIGHT WHILST LOADING. (CH1)		SEEMS OK- UNABLE TO TEST ISSUE AS DESCRIBED.		25/08/2022		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonga Workshop	TRAILER
T492	Myrtleford - Workshop	Elect/ELECT P&W	SCALES SAME ISSUE AS ALWAYS, READ HIGH THEN COUNT DOWN TO CORRECT WEIGHT WHILST LOADING. (CH1)		#389730		25/08/2022		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonga Workshop	TRAILER
T492	Myrtleford - Workshop	Elect/ELECT P&W	SCALES WHEN LOADING JUMP UP EXCESSIVELY IN WEIGHT ONCE LOADED TO DESIRED WEIGHT. HAVE TO WAIT FOR SCALES TO COUNT DOWN. ONCE COUNTED DOWN IS -10 MINUTES! TH WE		#389730		25/08/2022		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonga Workshop	TRAILER
T492	Myrtleford - Workshop	Tyres	CHANGE x2 TYRES.				25/08/2022		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonga Workshop	TRAILER
T492	Myrtleford - Workshop	Susp	BY-PASSED DUMP VALVE ON B TRAILER AS PER INSTRUCTIONS OF ELPHINESTONE.				25/08/2022		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist																
T492	Myrtleford - Workshop	VehService/DS	Barry Maney PO#:L073663	VehService/DS			25/08/2022		Service	Completed	Greenfreight Loxeine Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonwa Workshop	TRAILER
T492	Myrtleford - Workshop	Tyres\Re-Tor	Re Tension all wheels - Re-Torque of truck wheels				25/08/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Elect/ELECT P&W	no tail lights rear of trailer, no power to rear power at plug, run new wire to rear section				23/08/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	BARRY MANEY - 3	TRAILER
			Replace brakes LH centre incl. s-cam bushes.																
			Replace RHF brakes inc s-cam bushes																
			Replace 2 x pivot bushes																
			Replace 4 x pivot bolts																
			replace wear plates on 4 hangers																
T492	Myrtleford - Workshop	Brakes/JBRK O/HAUL	reolace line kit also				19/08/2022	1107321	Repair	Completed	Greenfreight Loxeine Vic	KennedyBPW	Mt Gambier	STK	B11165	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				11/08/2022	1107321	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonga Workshop	TRAILER
T492	Myrtleford - Workshop	Elect\INDICATORS	LH OUTER INDICATOR ON LIGHT BAR N/W.				11/08/2022	1107321	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonga Workshop	TRAILER
T492	Myrtleford - Workshop	Chassis\SKID PLATE	LOOSE SKID PLATE BOLT RH SIDE, LAST ONE. CLOSEST TO REAR OF TRAILER.				11/08/2022	1107321	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonga Workshop	TRAILER
T492	Myrtleford - Workshop	Susp\HCV	FIT RIDE HEIGHT VALVE FROM ELPHINSTONE. RE: SCALES ISSUE.				11/08/2022	1107321	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist																
T492	Myrtleford - Workshop	VehService/DS	Barry Maney PO#:L073409	VehService/DS			11/08/2022	1107321	Service	Completed	Greenfreight Loxeine Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonwa Workshop	TRAILER
T492	Myrtleford - Workshop	Tyres\TP3+4	supply and fit 2 tyres				11/08/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Tyres\ROTATION	pos 7 & 8				11/08/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Susp\AXLES	go to servo to replace broken pivot bolt in LH middle axle				09/08/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Tyres\TP9+10	supply and fit 4 tyres				09/08/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Tyres\TP11+12	Tyre Position 11 + 12				09/08/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Susp\AIR BAG	Replace leaking airbag after hours				05/08/2022	1096163	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Tyres	CHANGE x2 TYRES.				03/08/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonwa Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				03/08/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonga Workshop	TRAILER
T492	Myrtleford - Workshop	Body\MUDGUARDS	R/H MUDGUARD NEEDS REPLACING.				03/08/2022		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonga Workshop	TRAILER
T492	Myrtleford - Workshop	Elect/ELECT P&W	LIGHT ON FRONT BOLSTER L/H SIDE BROKEN.				03/08/2022		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist																
T492	Myrtleford - Workshop	VehService/DS	Barry Maney PO#:L073284	VehService/DS			03/08/2022		Service	Completed	Greenfreight Loxeine Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonwa Workshop	TRAILER
T492	Myrtleford - Workshop	Elect/ELECT P&W	SCALES STILL NO GOOD. (SAME ISSUE AS 125432, 125434, 125436. MAYBE RING WAYNE FOR SOME ADVICE ON HOW TO FIX???		REPLACED RIDE HEIGHT VALVE AS SUGGESTED BY ELPHINSTONE.		03/08/2022		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonga Workshop	TRAILER
T492	Myrtleford - Workshop	Susp	BY-PASSED DUMP VALVE ON B TRAILER AS PER INSTRUCTIONS OF ELPHINESTONE.		REPLACED HCV.		03/08/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonga Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				19/07/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonga Workshop	TRAILER
T492	Myrtleford - Workshop	Elect/ELECT P&W	SCALES SAME ISSUE AS ALWAYS, READ HIGH THEN CUNT DOWN TO CORRECT WEIGHT WHILST LOADING. (CH1)				19/07/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonga Workshop	TRAILER
T492	Myrtleford - Workshop	Elect/ELECT P&W	SCALES SAME ISSUE AS ALWAYS, READ HIGH THEN CUNT DOWN TO CORRECT WEIGHT WHILST LOADING. (CH1)				19/07/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonga Workshop	TRAILER
T492	Myrtleford - Workshop	Elect/ELECT P&W	SCALES WHEN LOADING JUMP UP EXCESSIVELY IN WEIGHT ONCE LOADED TO DESIRED WEIGHT. HAVE TO WAIT FOR SCALES TO COUNT DOWN. ONCE COUNTED DOWN IS -10 MINUTES! TH WE				19/07/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist																
T492	Myrtleford - Workshop	VehService/DS	Barry Maney PO#:L072975	VehService/DS			19/07/2022		Service	Completed	Greenfreight Loxeine Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonwa Workshop	TRAILER
			Loose Guard pole, would not tighten.																
			Replaced Bolts.																
T492	Wodonga - Workshop	Body\MUDGUARDS	Barry Maney PO#:L072957				13/07/2022	107818	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonga Workshop	TRAILER
T492	Wodonga - Workshop	Body\BOLSTER	Bolster bolts loose had to replace 2.				13/07/2022	107818	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonga Workshop	TRAILER
T492	Wodonga - Workshop	Body\PANELS	Also tightened rear light bar as it was loose.				13/07/2022	107818	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonga Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				05/07/2022	1074681	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist																
T492	Myrtleford - Workshop	VehService/DS	Barry Maney PO#:L072744	VehService/DS			05/07/2022	1074681	Service	Completed	Greenfreight Loxeine Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonwa Workshop	TRAILER
T492	Myrtleford - Workshop	Tyres\TP5+6	supply and fit 2tyres				30/06/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				21/06/2022	1065866	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonga Workshop	TRAILER
T492	Myrtleford - Workshop	Elect/ELECT P&W	SCALES SAME ISSUE AS ALWAYS, READ HIGH THEN COUNT DOWN TO CORRECT WEIGHT WHILST LOADING. (CH1)				21/06/2022	1065866	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonga Workshop	TRAILER
T492	Myrtleford - Workshop	Tyres	CHECK TYRES. CHANGE TYRES WHERE NEEDED.				21/06/2022	1065866	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonga Workshop	TRAILER
T492	Myrtleford - Workshop	Elect/ELECT P&W	SCALES SAME ISSUE AS ALWAYS, READ HIGH THEN CUNT DOWN TO CORRECT WEIGHT WHILST LOADING. (CH1)				21/06/2022	1065866	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonga Workshop	TRAILER
T492	Myrtleford - Workshop	Elect/ELECT P&W	SCALES WHEN LOADING JUMP UP EXCESSIVELY IN WEIGHT ONCE LOADED TO DESIRED WEIGHT. HAVE TO WAIT FOR SCALES TO COUNT DOWN. ONCE COUNTED DOWN IS -10 MINUTES! TH WE				21/06/2022	1065866	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist																
T492	Myrtleford - Workshop	VehService/DS	Barry Maney PO#:L072477	VehService/DS			21/06/2022	1065866	Service	Completed	Greenfreight Loxeine Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonwa Workshop	TRAILER
T492	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				07/06/2022	1053446	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonga Workshop	TRAILER
			CHECK TYRES.																
T492	Wodonga - Workshop	Tyres	CHANGE TYRES WHERE NEEDED.				07/06/2022	1053446	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonga Workshop	TRAILER
T492	Wodonga - Workshop	Elect/ELECT P&W	SCALES SAME ISSUE AS ALWAYS, READ HIGH THEN COUNT DOWN TO CORRECT WEIGHT WHILST LOADING. (CH1)				07/06/2022	1053446	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist																
T492	Wodonga - Workshop	VehService/DS	Barry Maney PO#:L072269	VehService/DS			07/06/2022	1053446	Service	Completed	Greenfreight Loxeine Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonwa Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes\ABS	ABS light on, repaired wiring replaced trailer module & program				18/05/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Susp\AXLES	Cable catch axle straps broken RH & LH front				18/05/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Chassis\BOLSTER	Weld cracks 3rd bolsters RHS & brace straighten deck plate				18/05/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				14/05/2022	1040489	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist																
T492	Myrtleford - Workshop	VehService/DS	Barry Maney PO#:L071779	VehService/DS			14/05/2022	1040489	Service	Completed	Greenfreight Loxeine Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonwa Workshop	TRAILER
T492	Myrtleford - Workshop	Susp\AIR LEAK	Leaking Airline (fitted joiner)				12/05/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				03/05/2022	1032211	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist																
T492	Myrtleford - Workshop	VehService/DS	Barry Maney PO#:L071570	VehService/DS			03/05/2022	1032211	Service	Completed	Greenfreight Loxeine Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonwa Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				15/04/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonga Workshop	TRAILER
T492	Myrtleford - Workshop	Chassis\FUEL TANK	LOOSE AND MISSING SKID PLATE BOLTS.				15/04/2022		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonga Workshop	TRAILER
T492	Myrtleford - Workshop	Elect/ELECT P&W	FIT SLAVE SCALE MODULE.				15/04/2022		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist																
T492	Myrtleford - Workshop	VehService/DS	PO #:L071319	VehService/DS			15/04/2022		Service	Completed	Greenfreight Loxeine Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonwa Workshop	TRAILER
T492	Myrtleford - Workshop	Chassis\BOLSTER	Replace broken bolts 3 bolster				15/04/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				07/04/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonga Workshop	TRAILER
T492	Myrtleford - Workshop	Elect/ELECT P&W	CLEARANCE LIGHT DRIVER'S SIDE 2ND BOLSTER FROM FRONT N/W.				07/04/2022		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist																
T492	Myrtleford - Workshop	VehService/DS	Barry Maney PO#:L071112	VehService/DS			07/04/2022		Service	Completed	Greenfreight Loxeine Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonwa Workshop	TRAILER
T492	Myrtleford - Workshop	Tyres\TP3+4	supply and fit 2tyres				02/04/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				23/03/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist																
T492	Myrtleford - Workshop	VehService/DS	Barry Maney PO#:L070843	VehService/DS			23/03/2022		Service	Completed	Greenfreight Loxeine Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonwa Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				10/03/2022	993191	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist																
T492	Myrtleford - Workshop	VehService/DS	Barry Maney PO#:L070612	VehService/DS			10/03/2022	993191	Service	Completed	Greenfreight Loxeine Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonwa Workshop	TRAILER
T492	Myrtleford - Workshop	Tyres\TP9+10	supply and fit 2tyres				02/03/2022	983561	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
			Annual Inspection As Per Checklist																
T492	Myrtleford - Workshop	Insp\ANN INSP	PO #:L070332	Insp\ANN INSP			24/02/2022	980362	PreventativeMaintenance	Completed	Greenfreight Loxeine Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonwa Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				24/02/2022	980362	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
			D Service As Per Attached Checklist																
T492	Myrtleford - Workshop	VehService/DS	PO #:L070331	VehService/DS			24/02/2022	980362	Service	Completed	Greenfreight Loxeine Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonwa Workshop	TRAILER
T492	Myrtleford - Workshop	Tyres\TP1+2	supply and fit 2tyres				20/02/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				11/02/2022	971110	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist																
T492	Myrtleford - Workshop	VehService/DS	PO #:L070111	VehService/DS			11/02/2022	971110	Service	Completed	Greenfreight Loxeine Vic	KennedyBPW	Mt Gambier	STK	B11165	Wodonwa Workshop	TRAILER
T492	Myrtleford - Workshop	Tyres\TP03	fit runout			

T492	Myrtleford - Workshop	Susp\DAMAGE	replace pivot bushes 1st and 2nd axle					11/09/2021	879138	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Body\WH\ HUB	adjust wheel bearings 1st & 2nd axle					11/09/2021	879138	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes\BRK RELINE	replace brakes rear axle repack w/bearing					11/09/2021	879138	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Body\MUDGUARDS	weld RH front mudguard cross bar					11/09/2021	879138	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					01/09/2021	879138	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist															
T492	Myrtleford - Workshop	VehService\DS	O/N L12165	VehService\DS				01/09/2021	879138	Service	Completed	Greenfreight Loxeine Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Elect\TRL LIGHTS	travel to yard and repair trailer wiring plug					29/08/2021		Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
			RH front lower shocker mount broken															
T492	Myrtleford - Workshop	Susp\DAMAGE	replace mount and refit shocker					21/08/2021	B69705	Repair	Completed	Greenfreight Loxeine Vic	Kennedy&PW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Insp\RWC COMP	clear clearing defect					21/08/2021	B69705	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					20/08/2021		Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist															
T492	Myrtleford - Workshop	VehService\DS	O/N L12099	VehService\DS				20/08/2021		Service	Completed	Greenfreight Loxeine Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Chassis\BOLSTER	tighten all loose bolster bolts and replace bolts					11/08/2021		Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Chassis\DAMAGE	remove and repair damage to chassis cover and repair and replace mounts and bolts					11/08/2021		Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Tyres\TP5-6	Supply and fit 2 tyres					23/07/2021	853277	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					23/07/2021	853276	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist															
T492	Myrtleford - Workshop	VehService\DS	ORDER # L11931	VehService\DS				23/07/2021	853276	Service	Completed	Greenfreight Loxeine Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Tyres\TP3-4	REPLACE 2 TYRES					14/07/2021		Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	Wodonga Workshop	TRAILER
T492	Myrtleford - Workshop	Tyres\TP9-10	REPLACE 2 TYRES					14/07/2021		Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	Wodonga Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					08/07/2021	843937	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	O/N L11831			08/07/2021	843937	Service	Completed	Greenfreight Loxeine Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					24/06/2021	835554	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist															
T492	Myrtleford - Workshop	VehService\DS	O/N L11714	VehService\DS				24/06/2021	835554	Service	Completed	Greenfreight Loxeine Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Tyres\TP1+2	Supply and fit 4 tyres					12/06/2021	826913	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Tyres\TP11+12	Tyre Position 11 + 12					12/06/2021	826913	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					08/06/2021	824150	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist															
T492	Myrtleford - Workshop	VehService\DS	O/N L11610	VehService\DS				08/06/2021	824150	Service	Completed	Greenfreight Loxeine Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					25/05/2021		Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist															
T492	Myrtleford - Workshop	VehService\DS	L11488	VehService\DS				25/05/2021		Service	Completed	Greenfreight Loxeine Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Susp\DAMAGE	trailer broken down. L/2 way to easterlies, broken ubolts spring damaged, airbag, pivot bolt, etc.					18/05/2021	802965	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					12/05/2021	802965	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	L11407			12/05/2021	802965	Service	Completed	Greenfreight Loxeine Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Body\WH\ HUB	replace hub cap and hubs, clean and check bearing					30/04/2021	792795	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					29/04/2021		Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist															
T492	Myrtleford - Workshop	VehService\DS	ORDER # L11278	VehService\DS				29/04/2021		Service	Completed	Greenfreight Loxeine Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Chassis\DAMAGE	repair trailer cracks					17/04/2021		Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Chassis\BOLSTER	paint bolster peg					17/04/2021		Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
			D SERVICE															
T492	Myrtleford - Workshop	VehService\DS	L11167	VehService\DS				10/04/2021	783716	Service	Completed	Greenfreight Loxeine Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					10/04/2021	783716	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Chassis\BOLSTER	replace LH bolster peg					07/04/2021		Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					19/03/2021	770141	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist															
T492	Myrtleford - Workshop	VehService\DS	Order Number: L11093	VehService\DS				19/03/2021	770141	Service	Completed	Greenfreight Loxeine Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Tyres\TP06	Supply and fit 1 tyre					17/03/2021	767317	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
			replace blown airbag and damaged booster															
T492	Myrtleford - Workshop	Susp\DAMAGE	pivot bolt broken in Hamilton Lobar					12/03/2021		Repair	Completed	Greenfreight Loxeine Vic	Kennedy&PW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job					11/03/2021	763541	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist															
T492	Wodonga - Workshop	VehService\DS	L10998	VehService\DS				11/03/2021	763541	Service	Completed	Greenfreight Loxeine Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Tyres\TP7+8	Supply and fit 4 tyres					06/03/2021	759172	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	Albury Workshop	TRAILER
T492	Myrtleford - Workshop	Tyres\TP9-10	Tyre Position 9 + 10					06/03/2021	759172	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	Albury Workshop	TRAILER
T492	Myrtleford - Workshop	Susp\SPRING PACK	broken spring LH middle axle					04/03/2021	757304	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Susp\HOUSEKEEP	tighten pivot bolts					04/03/2021	757304	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Chassis\BOLSTER	bolster bolts loose (replace weized bolts)					04/03/2021	757304	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Chassis\WINCH/STRP	winch bolts brake					04/03/2021	757304	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					20/02/2021	751238	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist															
T492	Myrtleford - Workshop	VehService\DS	L10816	VehService\DS				20/02/2021	751238	Service	Completed	Greenfreight Loxeine Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
			Annual Inspection As Per Checklist															
T492	Myrtleford - Workshop	Insp\ANN INSP	ORDER # L10706	Insp\ANN INSP				02/02/2021	742472	PreventativeMaintenance	Completed	Greenfreight Loxeine Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					02/02/2021	742472	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist															
T492	Myrtleford - Workshop	VehService\DS	ORDER # L10704	VehService\DS	replace RHM scrine sack			02/02/2021	742472	Service	Completed	Greenfreight Loxeine Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Tyres\TP7+8	REPLACE 2 TYRES					28/01/2021		Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	Wodonga Workshop	TRAILER
T492	Myrtleford - Workshop	Body\PAINT/REST	prepare, paint trailer bolsters on T492					07/01/2021		Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					18/12/2020	731023	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist															
T492	Myrtleford - Workshop	VehService\DS	L10414	VehService\DS				18/12/2020	731023	Service	Completed	Greenfreight Loxeine Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					27/11/2020	722144	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist															
T492	Myrtleford - Workshop	VehService\DS	Order number: L10237	VehService\DS				27/11/2020	722144	Service	Completed	Greenfreight Loxeine Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					06/11/2020	712975	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist															
T492	Myrtleford - Workshop	VehService\DS	Order Number: L10098	VehService\DS				06/11/2020	712975	Service	Completed	Greenfreight Loxeine Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Susp\AIR BAG	repair airbag and broken bolts					30/10/2020	708442	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					20/10/2020	702506	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist															
T492	Myrtleford - Workshop	VehService\DS	ORDER # L9958	VehService\DS				20/10/2020	702506	Service	Completed	Greenfreight Loxeine Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Brakes\AIR LEAK	replaced damaged hose & ran to avoid fusther damage					10/10/2020	695587	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Unknown - Unknown	Brakes	Record Check Results As Attached To This Job					02/10/2020	195165	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist															
T492	Unknown - Unknown	VehService\DS	Order Number L9839	VehService\DS				02/10/2020	195165	Service	Completed	Greenfreight Loxeine Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Chassis\DAMAGE	replace 4x bent bolster pegs					19/09/2020	683090	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					17/09/2020	682750	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist															
T492	Myrtleford - Workshop	VehService\DS	Order number L9684	VehService\DS				17/09/2020	682750	Service	Completed	Greenfreight Loxeine Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					02/09/2020	672201	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist															
T492	Myrtleford - Workshop	VehService\DS	Order number # L9569	VehService\DS				02/09/2020	672201	Service	Completed	Greenfreight Loxeine Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					20/08/2020	662345	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist															
T492	Myrtleford - Workshop	VehService\DS	Order Number # L9403	VehService\DS				20/08/2020	662345	Service	Completed	Greenfreight Loxeine Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
			went to yard and tested lights all worked															
			took trailer back to workshop lights went out															
			followed wiring removed tap cover, found rubs cut out damaged section and reconnected still ok															
T492	Myrtleford - Workshop	Elect\TRL LIGHTS	drooped back to depot					19/08/2020		Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
			drive to Greenfreight depot. Locate air leak. Cut out and replace damaged hose. Recheck for leaks															
T492	Myrtleford - Workshop	Body\AIR LEAK	all ok					16/08/2020		Repair	Completed	Greenfreight Loxeine Vic	Kennedy&PW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Elect\TRL LIGHTS	replace bolster light and check lights					14/08/2020		Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes\BRK RELINE	LHM brake needs replacing					09/08/2020	654854	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Body\MOUNTS	replace missing bolts in airbag					09/08/2020	654854	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Wodonga - Workshop	Air Con\AIR CON	Air Conditioning			RR's pre Jan 20 (system clean out) 05/08/20		06/08/2020		Fault	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	Wodonga Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					05/08/2020	652003	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist															
T492	Myrtleford - Workshop	VehService\DS	Order Number # L9279	VehService\DS				05/08/2020	652003	Service	Completed	Greenfreight Loxeine Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					23/07/2020		Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist															
T492	Myrtleford - Workshop	VehService\DS	Order Number # L9163	VehService\DS				23/07/2020		Service	Completed	Greenfreight Loxeine Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					09/07/2020		Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist															
T492	Myrtleford - Workshop	VehService\DS	Order Number # L9063	VehService\DS				09/07/2020		Service	Completed	Greenfreight Loxeine Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
			find air leak on B Trailer															
			repair air hose leak at middle brake actuator on L/H side															
T492	Myrtleford - Workshop	Brakes\AIR LEAK	shorten and refit hose					08/07/2020	630419	Repair	Completed	Greenfreight Loxeine Vic	Kennedy&PW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					25/06/2020	621504	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist															
T492	Myrtleford - Workshop	VehService\DS	Order Number # L8923	VehService\DS				25/06/2020	621504	Service	Completed	Greenfreight Loxeine Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					11/06/2020	612162	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist															
T492	Myrtleford - Workshop	VehService\DS	Order Number # L8813	VehService\DS				11/06/2020	612162	Service	Completed	Greenfreight Loxeine Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
			find light that wasn't working. Cut the wire															
			solder new one onto the wiring in the bolster															
T492	Myrtleford - Workshop	Elect\TRL LIGHTS	heat shrink the join and install the light the correct way around					04/06/2020	607441	Repair	Completed	Greenfreight Loxeine Vic	Kennedy&PW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					22/05/2020	601042	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist															
T492	Myrtleford - Workshop	VehService\DS	ORDER # L8632	VehService\DS				22/05/2020	601042	Service	Completed	Greenfreight Loxeine Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Body\MUDGUARDS	change pos 1 mudguard (7th)					08/05/2020	592034	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Body\MUDGUARDS	change pos 3 mudguard (11th) 593772km					08/05/2020	592034	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Chassis\DAMAGE	repaired binder latch					08/05/2020	592034	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					07/05/2020	593530	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist															
T492	Myrtleford - Workshop	VehService\DS	ORDER # L8497	VehService\DS				07/05/2020	593530	Service	Completed	Greenfreight Loxeine Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Tyres\TITMENT	Job Added From Invoice					30/04/2020	584505	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Tyres\SCRAP TYRE	Job Added From Invoice					30/04/2020	584505	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					22/04/2020	216185	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist															
T492	Myrtleford - Workshop	VehService\DS	Order number # L8365	VehService\DS				22/04/2020	216185	Service	Completed	Greenfreight Loxeine Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
			loosen binder strap. Knock out broken bolt in binder use a taper punch to realign the drum spacer and pin. Put new bolt through hole and tighten nylon nut. Retighten strap.															
T492	Myrtleford - Workshop	Chassis\WINCH/STRP	Replace winch strap mount bolt and test					09/04/2020	592952	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					03/04/2020	568971	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist															
T492	Myrtleford - Workshop	VehService\DS	Order number # L8261	VehService\DS				03/04/2020	568971	Service	Completed	Greenfreight Loxeine Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					20/03/2020	561578	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist															
T492	Myrtleford - Workshop	VehService\DS	Order Number # L8134	VehService\DS				20/03/2020	561578	Service	Completed	Greenfreight Loxeine Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					06/03/2020	551780	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist															
T492	Myrtleford - Workshop	VehService\DS	Order number # L8038	VehService\DS				06/03/2020	551780	Service	Completed	Greenfreight Loxeine Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					21/02/2020	534168	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist															
T492	Myrtleford - Workshop	VehService\DS	Order Number # L7910	VehService\DS				21/02/2020	534168	Service	Completed	Greenfreight Loxeine Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					07/02/2020		Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	811165	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist															

T492	Myrtleford - Workshop	Chassis\DAMAGE	Replace skip plate assembly			weld tri cracks also	17/01/2020	497322	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	ONETRAK-3	TRAILER
T492	Myrtleford - Workshop	Chassis\KING PIN	Fit new king pin (L7660)				17/01/2020	497322	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	ONETRAK-3	TRAILER
T492	Myrtleford - Workshop	Body\HOUSEKEEP	Replace all trailer connections				17/01/2020	497322	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	ONETRAK-3	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist				09/01/2020	514864	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	VehService/DS	Order number #: L 7601	VehService/DS			09/01/2020	514864	Service	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist				06/12/2019		Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	VehService/DS	Order number #: L 7494 repair spare tyre holder winch	VehService/DS			06/12/2019		Service	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Chassis\SPAREWHEEL	remove shaft and newald into position LHF clearance light not working remove wiring and strip back insulation repair broken wire by soldering together				29/11/2019	497322	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Elect\TRL LIGHTS	check all park and hazard lights - all ok			broken u-bolt	29/11/2019	497322	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist			LH middle axle wheel locked up booster replaced	22/11/2019	494601	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	VehService/DS	Order number #: L 7389	VehService/DS			22/11/2019	494601	Service	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Brakes\AIR LEAK	check tension of all hose clamps on brake boosters and brake valves. Replace x2 hose clamps				15/11/2019	487782	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist				08/11/2019	483813	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	VehService/DS	ORDER # L7349 broken booster pin	VehService/DS			08/11/2019	483813	Service	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Chassis\BOLSTER	source and install new pin				01/11/2019	476790	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist				11/10/2019	463810	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	ONETRAK-3	TRAILER
T492	Myrtleford - Workshop	VehService/DS	Order number #: L7223	VehService/DS			11/10/2019	463810	Service	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	ONETRAK-3	TRAILER
T492	Myrtleford - Workshop	Susp\SUSPENSION	replace all 6 spring eye bushes				05/10/2019	459178	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Body\WH. HUB	clean and repair all wheel bearings				05/10/2019	459178	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist				26/09/2019	454780	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	VehService/DS	Order number # L7130	VehService/DS			26/09/2019	454780	Service	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist				14/09/2019	444214	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	ONETRAK-3	TRAILER
T492	Myrtleford - Workshop	VehService/DS	Order number #: L7074	VehService/DS			14/09/2019	444214	Service	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	ONETRAK-3	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist				31/08/2019	434972	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	ONETRAK-3	TRAILER
T492	Myrtleford - Workshop	VehService/DS	ORDER # L7003	VehService/DS			31/08/2019	434972	Service	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	ONETRAK-3	TRAILER
T492	Myrtleford - Workshop	Susp\AIR BAG	change out RH front airbag as it was leaking				29/08/2019	432443	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Body\MUDGUARDS	fit new mudguards x 3 to left hand side damaged from blown out tyres on previous night. Re-route quick release cable on front bay				23/08/2019	478059	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist				16/08/2019	424860	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	VehService/DS	ORDER NUMBER L6874	VehService/DS			16/08/2019	424860	Service	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist				02/08/2019	371604	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	ONETRAK-3	TRAILER
T492	Myrtleford - Workshop	VehService/DS	Order #L6778	VehService/DS	carried trailer service		02/08/2019		Service	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	BARRY MANEY - 3	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist				20/07/2019	406478	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	ONETRAK-3	TRAILER
T492	Myrtleford - Workshop	VehService/DS	Order #L6581	VehService/DS			20/07/2019	406478	Service	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	ONETRAK-3	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist				05/07/2019	395767	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	ONETRAK-3	TRAILER
T492	Myrtleford - Workshop	VehService/DS	Order #L6583	VehService/DS			05/07/2019	395767	Service	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	ONETRAK-3	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist				14/06/2019	380634	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	ONETRAK-3	TRAILER
T492	Myrtleford - Workshop	VehService/DS	Order #L6403\L6430	VehService/DS			14/06/2019	380634	Service	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	ONETRAK-3	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist				01/06/2019	371604	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	ONETRAK-3	TRAILER
T492	Myrtleford - Workshop	VehService/DS	Order #L6304 replace broken LHF shocky mount and shocky removed broken shock mount cleaned surfaces installed new mount installed shock	VehService/DS	LHF shock/mount (MS057-1)		01/06/2019	371604	Service	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	ONETRAK-3	TRAILER
T492	Myrtleford - Workshop	Body\MOUNTS					30/05/2019	368257	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist				17/05/2019	360222	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	ONETRAK-3	TRAILER
T492	Myrtleford - Workshop	VehService/DS	Order #L6175	VehService/DS			17/05/2019	360222	Service	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	ONETRAK-3	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist				04/05/2019	348132	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	ONETRAK-3	TRAILER
T492	Myrtleford - Workshop	VehService/DS	Order #L6077	VehService/DS			04/05/2019	348132	Service	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	ONETRAK-3	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist				13/04/2019		Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	ONETRAK-3	TRAILER
T492	Myrtleford - Workshop	VehService/DS	Order #L5984 scales on "3" trailer not working harness on trailer previously repaired hook up test slave supplied by Greenfreight -still not working fault find issue - found power at #3 slave not in correct pin on plug remove wires on now harness and solder into correct positions	VehService/DS			13/04/2019		Service	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	ONETRAK-3	TRAILER
T492	Myrtleford - Workshop	Elect\ELECT P&W	test scales - all ok				04/04/2019	322048	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist				02/04/2019	328533	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	WRECKETT PTY. LTD - 3	TRAILER
T492	Myrtleford - Workshop	VehService/DS	ORDER # L5913	VehService/DS			02/04/2019	328533	Service	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	WRECKETT PTY. LTD - 3	TRAILER
T492	Myrtleford - Workshop	Elect\ELECT P&W	run new wiring loom from junction box through to skid plate for scales				31/03/2019	323613	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Elect\ELECT P&W	driver complaint scales intermitted, repaired wiring under skid plate spoke to Greenfreight and new loom to be fitted				26/03/2019	322596	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	WRECKETT PTY. LTD - 3	TRAILER
T492	Myrtleford - Workshop	Susp\SPRING PACK	remove broken spring on LHS rear axle and replace with new spring and u-bolts				21/03/2019	320309	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				20/03/2019	320309	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	WRECKETT PTY. LTD - 3	TRAILER
T492	Myrtleford - Workshop	VehService/DS	D Service As Per Attached Checklist	VehService/DS	PO L5810 two tyres on rear axle need reolacine		20/03/2019	320309	Service	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	WRECKETT PTY. LTD - 3	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		replace R/H/P binder strap with new		02/03/2019	308775	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	WRECKETT PTY. LTD - 3	TRAILER
T492	Myrtleford - Workshop	VehService/DS	D Service As Per Attached Checklist	VehService/DS	checked for air leak that driver had mentioned. couldn't find but will monitor		02/03/2019	308775	Service	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	WRECKETT PTY. LTD - 3	TRAILER
T492	Myrtleford - Workshop	Elect\ELECT P&W	repair tail/brake light assembly on R/H rear of trailer				20/02/2019	300617	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Susp\SHOCK ABS	replaced broken shocker mount on L/H rear axle				20/02/2019	300617	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		repair R/H tail brake light		20/02/2019	300617	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	VehService/DS	D Service As Per Attached Checklist	VehService/DS	reolace broken shocker mount		20/02/2019	300617	Service	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				08/02/2019	292576	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	VehService/DS	D Service As Per Attached Checklist	VehService/DS	replace clearance and brake lights		08/02/2019	292576	Service	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Elect\ELECT P&W	Repair RHS 2nd bolster light wiring		brake light wiring		30/01/2019	292576	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Drivline\AIR LEAK	air winch air line leak				26/01/2019	286367	Fault	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				26/01/2019	286367	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	VehService/DS	D Service As Per Attached Checklist	VehService/DS	repair RHR tail light wiring		26/01/2019	286367	Service	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Dr.Cab\Elect\SCALES	diagnose fault with weight scales found wiring under cab damaged -reseated wirrie				19/01/2019	872698	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Hydraulics\LIFTD LEAKS	replaced leaking hydraulic hose at front				19/01/2019	872698	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Chassis\FIFTH WHEE	turntable has a lot of play between pin or plate				11/01/2019	280176	Fault	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Chassis\WINCH/STRP	no.4 strap needs inspection				11/01/2019	280176	Fault	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Susp\AIR BAG	replace LHR airbag				11/01/2019	280176	Fault	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	VehService/DS	D Service As Per Attached Checklist	VehService/DS			11/01/2019	280176	Service	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				11/01/2019	280176	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Chassis\CHAS CRACK	Repair Skid Plate Cracks & Order New Skid Plate				20/12/2018	277603	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				19/12/2018	276945	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	VehService/DS	D Service As Per Attached Checklist	VehService/DS			19/12/2018	276945	Service	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Hydraulics\RAM	Repair front bolster ram		fit new ram shaft and seals		18/12/2018	277603	Fault	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Susp\AIR BAG	hole in airbag - replace				15/12/2018		Fault	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				15/12/2018	273527	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	VehService/DS	D Service As Per Attached Checklist	VehService/DS			15/12/2018	273527	Service	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				01/12/2018	265908	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	VehService/DS	D Service As Per Attached Checklist	VehService/DS			01/12/2018	265908	Service	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				28/11/2018	261964	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	VehService/DS	D Service As Per Attached Checklist	VehService/DS			28/11/2018	261964	Service	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				17/11/2018	257613	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	VehService/DS	D Service As Per Attached Checklist	VehService/DS			17/11/2018	257613	Service	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Susp\SPRING HANG	Repair LHM Spring Hanger Crack				02/11/2018	251042	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				31/10/2018	251042	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	VehService/DS	D Service As Per Attached Checklist	VehService/DS	replaced RHM shock absorber uncrunched airbaes		31/10/2018	251042	Service	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Body\AIR LEAK	Check repairs on hose above airbag on LHF axle				30/10/2018	251042	Fault	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes\BRK RELINE	Crack test & reline all wheels				27/10/2018	251042	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Body\FIFTH WHEE	unhook B Trailer				26/10/2018		Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice				25/10/2018	248566	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice				25/10/2018	248566	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				20/10/2018	247636	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	VehService/DS	D Service As Per Attached Checklist	VehService/DS	replace reg label		20/10/2018	247636	Service	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Insp\RWC COMP	Replace long vehicle sign & reposition				09/10/2018	247636	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				06/10/2018	242636	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	VehService/DS	D Service As Per Attached Checklist	VehService/DS			06/10/2018	242636	Service	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice				27/09/2018	0	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Tyres	Job Added From Invoice				27/09/2018	0	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice				27/09/2018	0	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Body\AIR LEAK	cut in hose line on driver side inside chassis at the front of spare tyre				22/09/2018	236633	Fault	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP			22/09/2018	236633	PreventativeMaintenance	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist				22/09/2018	236633	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	VehService/DS	D Service As Per Attached Checklist	VehService/DS	unscrunch front and middle air bags		22/09/2018	236633	Service	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice				15/09/2018	0	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Elect\INDICATORS	RHS (driver side) indicators have a fault somewhere and don't always work				08/09/2018	230027	Fault	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				08/09/2018	230028	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	VehService/DS	D Service As Per Attached Checklist	VehService/DS	LH front spring eye		08/09/2018	230028	Service	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				24/08/2018	223861	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	VehService/DS	D Service As Per Attached Checklist	VehService/DS	changed RHF shocker		24/08/2018	223861	Service	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Tyres	Job Added From Invoice				17/08/2018	0	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice				17/08/2018	0	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice				17/08/2018	0	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Body\MUDGUARDS	fit 2 mudflaps				11/08/2018		Fault	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Elect\INDICATORS	indicators L&R still going out a lot of times				11/08/2018		Fault	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Susp\SPRING PACK	Replace LHR spring eye bush LH indicator fault				08/08/2018	718345	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Elect\INDICATORS	Check wirine & repair as necessary		checked indicator operation. wiresled okans and checked wirine couldn't fault		08/08/2018	223861	Fault	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Elect\TRL LIGHTS	trailer plug? All lights work except for indicators which don't work for most of the time				07/08/2018		Fault	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				07/08/2018	217501	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	VehService/DS	D Service As Per Attached Checklist	VehService/DS			07/08/2018	217501	Service	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Body\BOLSTER	Move Bolsters and repair cracks				07/08/2018	217501	Repair	Completed	Greenfreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B1116S	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Susp\HOUSEKEEP	Replace LHR & LHF spring eye bushes				26/07/2018	63711	Repair	Completed	Green

T492	Myrtleford - Workshop	Chassis\WINCH/STRP	Reco middle air winch				rebuilt winch, refitted and tested 206019km				05/07/2018	207300	Fault	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Body\PANELS	Check & Repair checker plate mounts								05/07/2018	207300	Fault	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Elect\TRL LIGHTS	replace tail light LHS								04/07/2018	205335	Fault	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job								27/06/2018	201967	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS							27/06/2018	201967	Service	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Chassis\WINCH/STRP	Repair air leak at front winch				replace leaking diaphram, replace damaged hose fitting, cut off striped nuts and replaced				22/06/2018	200183	Fault	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Chassis\WINCH/STRP	rear air winch weak tightening of strap								21/06/2018	199579	Fault	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
			remove skid plate and repair cracks																		
T492	Myrtleford - Workshop	Chassis\CHAS CRACK	and refit skid plate and wirine								13/06/2018	197228	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Chassis\CHAS CRACK	remove front bolster and repair cracks and fit extra plates to chassis webb								13/06/2018	197228	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Elect\TRL LIGHTS	check and repair trailer lights and side markers(14516)								13/06/2018	197228	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Chassis\WINCH/STRP	fit new winch cable release								13/06/2018	197228	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job								08/06/2018	19657	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS							08/06/2018	19657	Service	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Chassis\WINCH/STRP	front quick release bent outwards								26/05/2018	195195	Fault	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Elect\ELECT P&W	Check & repair scale wiring								19/05/2018	195192	Fault	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job								19/05/2018	192090	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS							19/05/2018	192090	Service	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Elect\TRL LIGHTS	T492 - check lights								08/05/2018	89046	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Body\FIFTH WHEE	hook up to s/line								08/05/2018	89046	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Body\MUDGUARDS	remove mudflaps								08/05/2018	189046	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Body\HOUSEKEEP	check over trailer								08/05/2018	189046	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Susp\AIR BAG	Straightened air bag								04/05/2018	189145	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Susp\HOUSEKEEP	Fit Axle Cable								04/05/2018	189145	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Susp\HOUSEKEEP	Fit axle straps to rear axle								04/05/2018	189145	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Body\HOUSEKEEP	Check over trailer								04/05/2018	189145	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job								25/04/2018	185932	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	R&R middle axle mudguard						25/04/2018	185932	Service	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job								14/04/2018	180198	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS							14/04/2018	180198	Service	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job								05/04/2018	175334	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS							05/04/2018	175334	Service	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Chassis\WINCH/STRP	Front winch cable broken								24/03/2018		Fault	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Tyres	Job Added From Invoice								24/03/2018	0	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice								24/03/2018	0	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice								24/03/2018	0	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job								24/03/2018	170514	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS							24/03/2018	170514	Service	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Chassis\WINCH/STRP	Replace front winch strap release cable. front winch release cable, handle broken								20/03/2018	170514	Fault	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Tyres	Job Added From Invoice								14/03/2018	0	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice								14/03/2018	0	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice								14/03/2018	0	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job								14/03/2018	164980	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS							14/03/2018	164980	Service	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job								01/03/2018		Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS							01/03/2018		Service	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Tyres	Job Added From Invoice								21/02/2018	0	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice								21/02/2018	0	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Tyres\ROTATION	Job Added From Invoice								21/02/2018	0	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice								21/02/2018	0	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job								15/02/2018	154875	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
							fit new 2 pin trailer plug														
T492	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	weld hook for load strap and fit new load step						15/02/2018	154875	Service	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Chassis\WINCH/STRP	Replace front log strap release cable								09/02/2018	154875	Fault	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Chassis\WINCH/STRP	front winch release cable, handle broken								08/02/2018	151917	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Susp\AIR BAG	driver side middle axle airbag hole in it								08/02/2018	151917	Fault	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
			check for air leak																		
T492	Myrtleford - Workshop	Body\AIR LEAK	check ride heisht valve								07/02/2018	150181	Fault	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
							move all boosters down to bottom hose 125mm														
T492	Myrtleford - Workshop	Brakes\BRK RELINE	Crack test & reline all wheels				fit ausnt over tri valve				06/02/2018	154889	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job								03/02/2018	15018	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS							03/02/2018	15018	Service	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Chassis\DAMAGE	Replace checker plate bolts								24/01/2018	154889	Fault	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job								23/01/2018	145267	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS							23/01/2018	145267	Service	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Tyres	Job Added From Invoice								19/01/2018	137755	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job								11/01/2018	139723	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS							11/01/2018	139723	Service	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Body\MUDGUARDS	Replace LHR mudguard brackets								10/01/2018	140255	Fault	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Hydraulics\OIL LEAK	2x new hydraulic fittings (male)								03/01/2018	135812	Fault	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Susp\HOUSEKEEP	scrunched airbag on front axle, pass/side								03/01/2018	135812	Fault	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job								28/12/2017	134696	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS							28/12/2017	134696	Service	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice								16/12/2017	129247	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice								16/12/2017	129247	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Susp\SUSPENSION	rear axle strap broken, one next to it looks in poor shape								14/12/2017	129868	Fault	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Tyres	Job Added From Invoice								14/12/2017	0	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice								14/12/2017	0	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice								14/12/2017	0	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job								14/12/2017	129861	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS							14/12/2017	129861	Service	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Body\AIR FITTIN	check for oil leaks								10/12/2017	128083	Fault	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Hydraulics\HYD LEAKS	2x hydraulic fittings - worn and leaking								10/12/2017	128083	Fault	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Tyres\RUN OUT	Job Added From Invoice								06/12/2017	12389	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Body\HOUSEKEEP	Clean out bark from behind front bolster								06/12/2017	717882	Fault	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Elect\ELECT P&W	Repair scale wiring								06/12/2017	717882	Fault	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Elect\INDICATORS	Repair RHR indicator								02/12/2017	125028	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Susp\HOUSEKEEP	Replace RHM spring eye bush								02/12/2017	125028	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes\AIR LEAK	Repair air leak on service brake								02/12/2017	125028	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job								01/12/2017	125027	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS							01/12/2017	125027	Service	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Body\PANELS	Repair or Replace chassis covers & repair mounts				weld missing logs for rovers				30/11/2017	125026	Fault	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Chassis\SPAREWHEEL	wheel carrier - bolt broken in crank handle								29/11/2017	12389	Fault	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Body\PANELS	Inspect checker plate covers				Cherokar plates x 2 need repair or replacement				29/11/2017	12389	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Susp\SHOCK ABS	Repair / Replace RHM shocker mount								21/11/2017	125018	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job								18/11/2017	119965	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS							18/11/2017	119965	Service	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Chassis\SPAREWHEEL	spare tyre winch assembly - handle needs welding on inside and fit spare wheel								15/11/2017	118131	Fault	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice								15/11/2017	116304	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice								15/11/2017	116304	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Tyres\RUN OUT	Job Added From Invoice								15/11/2017	116304	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Body\REFLECTORS	"long vehicle" sign missing some rivets								11/11/2017	116881	Fault	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job								07/11/2017	115083	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS							07/11/2017	115083	Service	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes\BRK OVHAUL	inspect squeeking brakes								02/11/2017	113947	Fault	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes\EBS Kit	re-connect EBS plug to wires. re-connect EBS plug to wire								26/10/2017	110338	Fault	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job								26/10/2017	110338	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS							26/10/2017	110338	Service	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Susp\AIR FITTIN	driver side/middle axle airbag faulty								20/10/2017	107992	Fault	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Susp\AIR BAG	front axle airbags scrunched due to extra load pressure								20/10/2017	107992	Fault	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job								12/10/2017	106159	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
							adjust ride height														
T492	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	reolace 1x LED blinker						12/10/2017	106159	Service	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
			fit new u-bolt																		
			fit wheel alignment plate																		
T492	Myrtleford - Workshop	Susp\SUSPENSION	fit new centre bolt								05/10/2017	103244	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Insp\INT INSP	srt stickers				fit srt stickers to pegs				28/09/2017	100295	Fault	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job								28/09/2017	100295	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS							28/09/2017	100295	Service	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Susp\HCV	fit new height control valve to rear axle								22/09/2017	97004	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Susp\AIR BAG	Replace LHM airbag								21/09/2017	97004	Fault	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Chassis\FITTN WHEE	Repair skid plate crack								21/09/2017	100295	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Chassis\CHAS CRACK	Repair chasis rail crack under front bolster								21/09/2017	100295	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Susp\AIR BAG	check airbags for leaks								20/09/2017	95718	Fault	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job								20/09/2017	95718	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
							cracked skid plate														
T492	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	chasis rail crack under front bolster						20/09/2017	95718	Service	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Body\MIRRORS	Repair chassis cover plates & mounts								15/09/2017	125028	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Body\AIR LEAK	repair air leak for air supply to transducer								14/09/2017	93079	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Insp\RWC COMP	remove and replace number plate								14/09/2017	93078	Repair	Completed	Greenfreight Logging Vic	Kennedy\BPW	Mt Gambier	STK	811165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist

T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				05/07/2017	51233	Repair	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	VehService/LDS	D Service As Per Attached Checklist	VehService/LDS			05/07/2017	51233	Service	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes/BRK RELINE	Reline all wheels				23/06/2017	48818	Repair	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes/BRK RELINE	Fit s/cams & bushes		fit s/cam bushes only s/cams		23/06/2017	48818	Repair	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				16/06/2017	47703	Repair	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	VehService/LDS	D Service As Per Attached Checklist	VehService/LDS			16/06/2017	47703	Service	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Tyres	Job Added From Invoice				14/06/2017	0	Repair	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes/JBS Kit	Fit EBS Kit to front & rear axles				10/06/2017	48818	Repair	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Tyres	Job Added From Invoice				08/06/2017	0	Repair	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Tyres/UTIMENT	Job Added From Invoice				08/06/2017	0	Repair	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Tyres/RETREAD	Job Added From Invoice				08/06/2017	0	Repair	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes/BRK RELINE	fit 405 run outs to LHR axle				03/06/2017	42130	Repair	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				03/06/2017	42130	Repair	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	VehService/LDS	D Service As Per Attached Checklist	VehService/LDS			03/06/2017	42130	Service	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Chassis/WINCH/STRP	Replace damaged winch drum bolts		Complete		31/05/2017	41055	Fault	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				24/05/2017	37351	Repair	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	VehService/LDS	D Service As Per Attached Checklist	VehService/LDS			24/05/2017	37351	Service	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Tyres	Job Added From Invoice				12/05/2017	0	Repair	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Tyres/UTIMENT	Job Added From Invoice				12/05/2017	0	Repair	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Tyres/RETREAD	Job Added From Invoice				12/05/2017	0	Repair	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
			Replace LHF axle cable														
T492	Myrtleford - Workshop	Susp/HOUSEKEEP	swear trl cracks. Replace LHF axle cable				10/05/2017	32338	Fault	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				09/05/2017	32309	Repair	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	VehService/LDS	D Service As Per Attached Checklist	VehService/LDS			09/05/2017	32309	Service	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Body/AIR LEAK	Middle air tank - hose leak		Complete		08/05/2017	32309	Fault	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Tyres	Job Added From Invoice				29/04/2017	27171	Repair	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				28/04/2017	27868	Repair	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	VehService/LDS	D Service As Per Attached Checklist	VehService/LDS			28/04/2017	27868	Service	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Tyres/BUN OUT	Job Added From Invoice				27/04/2017	22219	Repair	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	DrivLine/TRL LIGHTS	plug/wiring? Lights flicker on and off even the plug is tight				22/04/2017	25928	Fault	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes/AIR LEAK	air supply line to B Trailer broken				19/04/2017	24031	Fault	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Tyres/TP15	Job Added From Invoice				12/04/2017	20147	Repair	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				12/04/2017	22215	Repair	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	VehService/LDS	D Service As Per Attached Checklist	VehService/LDS			12/04/2017	22215	Service	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				30/03/2017	17665	Repair	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	VehService/LDS	D Service As Per Attached Checklist	VehService/LDS			30/03/2017	17665	Service	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Body/HOUSEKEEP	check over trailer				18/03/2017	14229	Fault	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Chassis/WINCH/STRP	load restraint latch at rear on pass/side, loader has pushed down on it, can it please be fixed along with a new cable handle				16/03/2017	12981	Fault	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				15/03/2017	12281	Repair	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	VehService/LDS	D Service As Per Attached Checklist	VehService/LDS			15/03/2017	12281	Service	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Chassis/WINCH/STRP	Refit test air winch & fit test rope to front winch on rear bay		Complete		09/03/2017	11089	Fault	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Susp/AIR BAG	Replace LHM airbag		Complete		09/03/2017	11089	Fault	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	DrCabElect/SCALES	Replace female scale plug. Replace femal scale plug				03/03/2017	11089	Fault	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				02/03/2017	8385	Repair	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	VehService/LDS	D Service As Per Attached Checklist	VehService/LDS			02/03/2017	8385	Service	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Tyres/TP13	Job Added From Invoice				01/03/2017	705	Repair	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Chassis/WINCH/STRP	remove test winch & refit original				21/02/2017	3656	Fault	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes/BRK RELINE	Crack test & reline middle axle		fit 2x new drums		14/02/2017		Repair	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Body/PANELS	checker plate at rear has been hot again				11/02/2017	3173	Fault	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Chassis/WINCH/STRP	fit test winch & rope to trailer				11/02/2017	3173	Fault	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				11/02/2017	3173	Repair	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	VehService/LDS	D Service As Per Attached Checklist	VehService/LDS			11/02/2017	3173	Service	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Tyres/TP21	Job Added From Invoice				01/02/2017	107102	Repair	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Body/WH. HUB	Replace hubo				01/02/2017		Repair	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Body/PANELS	Repair chassis covers				01/02/2017		Repair	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		#6 order hubbo		31/01/2017		Repair	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	VehService/LDS	D Service As Per Attached Checklist	VehService/LDS			31/01/2017		Service	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				19/01/2017	109820	Repair	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	VehService/LDS	D Service As Per Attached Checklist	VehService/LDS			19/01/2017	109820	Service	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Tyres/DAMAGE	replace RHR mudguard + mudflap				13/01/2017		Fault	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Tyres/DAMAGE	replace rear air winch tag/valve				13/01/2017		Fault	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Elect/TRL LIGHTS	Replace LHR tail light bar side light				11/01/2017	109820	Repair	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				10/01/2017	105097	Repair	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	VehService/LDS	D Service As Per Attached Checklist	VehService/LDS			10/01/2017	105097	Service	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes/BRK RELINE	Crack test & reline rear axle				22/12/2016	101249	Repair	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	VehService/LDS	D Service As Per Attached Checklist	VehService/LDS			21/12/2016	100430	Service	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				21/12/2016	100430	Repair	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				06/12/2016	95766	Repair	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	VehService/LDS	D Service As Per Attached Checklist	VehService/LDS			06/12/2016	95766	Service	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Tyres/TP18	Job Added From Invoice				26/11/2016	91002	Repair	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Chassis/FIFTH WHEE	Repair skid plate crack		remove covers + clean skid plate + repair cracks + paint + refit covers		23/11/2016	99340	Fault	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				22/11/2016	90512	Repair	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	VehService/LDS	D Service As Per Attached Checklist	VehService/LDS			22/11/2016	90512	Service	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	DrCabElect/SCALES	check scales - not working properly				18/11/2016	89598	Fault	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Chassis/WINCH/STRP	fit 3 new straps to rear bay				18/11/2016	89598	Fault	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				11/11/2016	86311	Repair	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	VehService/LDS	D Service As Per Attached Checklist	VehService/LDS			11/11/2016	86311	Service	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Body/PANELS	Remove & repair checker plate & re-fit		Complete		04/11/2016	83803	Fault	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Body/MUDGUARDS	Fit new mudguard to RH middle		Complete		04/11/2016	83803	Fault	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Tyres/TP19	Job Added From Invoice				01/11/2016	79819	Repair	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				28/10/2016	8132	Repair	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	VehService/LDS	D Service As Per Attached Checklist	VehService/LDS			28/10/2016	8132	Service	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes/BRK RELINE	Crack test & reline front middle axles				14/10/2016	76764	Repair	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				13/10/2016	76763	Repair	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	VehService/LDS	D Service As Per Attached Checklist	VehService/LDS	repair air leak at air winch		13/10/2016	76763	Service	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Tyres/TP20	Job Added From Invoice				11/10/2016	72914	Repair	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Body/AIR BAG	2x blown airbags - rear axle				08/10/2016	74703	Fault	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Body/AIR BAG	front axle, pass/side, bag greased, cant blow out				04/10/2016	74703	Fault	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Chassis	rear winch no longer tightening				04/10/2016	72095	Fault	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		fit 3 new brake booster hose to front axle		04/10/2016	72095	Repair	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	VehService/LDS	D Service As Per Attached Checklist	VehService/LDS			04/10/2016	72095	Service	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Comp/WH. HUB	driver/side front axle missing hub cap				30/09/2016	71250	Repair	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Body/AIR LEAK	driver/side above middle axle - air leak				30/09/2016	71250	Repair	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Body/PANELS	broken cleat from check floor rubbed on it				30/09/2016	71250	Repair	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Elect/TRL LIGHTS	brake lights not working				30/09/2016	71250	Repair	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Elect/TAIL LIGHT	brake & blinkers out				21/09/2016	67199	Fault	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				21/09/2016	67199	Repair	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	VehService/LDS	D Service As Per Attached Checklist	VehService/LDS			21/09/2016	67199	Service	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	DrCabElect/SCALES	calibrate scales				13/09/2016	63909	Fault	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes/BRK RELINE	Crack test & reline rear axle				09/09/2016	63169	Repair	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	DrCabElect/SCALES	Check & repair scales				08/09/2016	63165	Fault	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				08/09/2016	62453	Repair	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	VehService/LDS	D Service As Per Attached Checklist	VehService/LDS			08/09/2016	62453	Service	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				27/08/2016	57555	Repair	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	VehService/LDS	D Service As Per Attached Checklist	VehService/LDS			27/08/2016	57555	Service	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				17/08/2016	52600	Repair	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	VehService/LDS	D Service As Per Attached Checklist	VehService/LDS			17/08/2016	52600	Service	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes/AIR LEAK	check air valve at rear of trailer for broken				12/08/2016		Fault	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes/BOOSTER	pass/side brake booster hose broken rear axle				12/08/2016		Fault	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	DrCabElect/SCALES	Repair scales		repair scale wiring		09/08/2016	60686	Repair	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				02/08/2016	47295	Repair	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	VehService/LDS	D Service As Per Attached Checklist	VehService/LDS			02/08/2016	47295	Service	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Susp/AXLES	Replace RHR Auto axle nut + lock assembly				29/07/2016	46302	Repair	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				20/07/2016	42777	Repair	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	VehService/LDS	D Service As Per Attached Checklist	VehService/LDS			20/07/2016	42777	Service	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Chassis/WH. HUB	fit hubo meter to rear axle				15/07/2016	41837	Repair	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Chassis/WINCH/STRP	remove & replace winch strap				15/07/2016	41837	Repair	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				15/07/2016	41837	Repair	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	VehService/LDS	D Service As Per Attached Checklist	VehService/LDS			15/07/2016	41837	Service	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Insp/ANN INSP	Annual Inspection As Per Checklist	Insp/ANN INSP			15/07/2016		PreventativeMaintenance	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Chassis/WINCH/STRP	Fit new winches		Complete		12/07/2016	41837	Repair	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Chassis/BOLSTER	Make & fit bolster stoppers		Complete		12/07/2016	41837	Repair	Completed	GreenFreight Logging Vic	Kennedy&PW	Mt Gambier	STK	B11165	Myrtleford Workshop	TRAILER
T492	Myrtleford - Workshop	Tyres/TP21	Job Added From Invoice				08/07/2016	0