EquipmentName	Workshop	CodeAndSubCode	Description	Schedule	CompletionComments	DateDone	DistanceDone	Worktype	Workstate	EquipmentOwner	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
T470	Mt Gambier - Mt Gambier	Brakes\ABS	LEFT WHEEL SENSOR DAMAGED		Fault: - Damaged wheel sensor, LHS Cause: - Impact damage Correction: - Removed damaged LHS wheel sensor - Installed new unit - Tested, ok	14/10/2026	1218245	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	HALLORAN DIESEL - 3	TRAILER
T470	Mt Gambier - Mt Gambier	Body\BOLSTER	NO SIDE LIGHT 2ND BOLSTER		Fault: - Second bolster marker lights not working Cause: - Split and corroded wiring between bolster and plug Correction: - Removed conduit and inspected wiring — found split - Checked plug for 12V, OK - Removed corroded wiring between bolster and plug - Installed new wiring and covered to protect from weather - Confirmed lights operating correctly	14/10/2026	1218245	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	HALLORAN DIESEL - 3	TRAILER
T470	Mt Gambier - Mt Gambier	Susp\SHOCK ABS	Susp\SHOCK ABS			14/10/2026	1218245	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	HALLORAN DIESEL - 3	TRAILER
T470	Mt Gambier - Mt Gambier	VehService\DS	VehService\DS D Service	VehService\DS	Completed "D Service" as per attached service sheet	14/10/2026	1218245	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Mt Gambier Workshop	TRAILER
T470	Mt Gambier - Mt Gambier	Chassis\WINCH/STRP	REPLACE TAP ON 1ST DRUM/BINDER		completed by Scott Alexander in depot	09/09/2026	1218245	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Mt Gambier Workshop	TRAILER
T470	Myrtleford - Workshop	Elect\TAIL LIGHT	DIAGNOSE & REPAIR TAIL LIGHT FAULT			04/09/2026	1218245	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	JF MECHANICALS - 3	TRAILER
T470	Myrtleford - Workshop	DrCabElect\SCALES	FIT RIGHT WEIGH SCALE BOX & FINISH AXLE INSTALL		Carried out trailer service as per Greenfreight checklist.	04/09/2026	1218245	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	JF MECHANICALS - 3	TRAILER
T470	Mt Gambier - Mt Gambier	VehService\DS	VehService\DS D Service	VehService\DS	TENSION PIVOT BUSHES & U BOLTS TENSION BOLSTER BOLTS	25/08/2026	1218245	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	BARRY MANEY - 3	TRAILER
T470	Mt Gambier - Mt Gambier	Susp\AIR LEAK	REPAIR LEAKING AIR BAG FITTING RH MIDDLE AXLE			25/08/2026	1218245	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Brakes\ABS	SUPPLY ONLY 1 X ABS PLUG			22/08/2026	1218245	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	OT DIESEL SERVICES - 3	TRAILER
T470	Colac - Colac	Susp\AXLES	FIT AXLE BACK IN TRAILER			02/08/2026	1218245	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	JF MECHANICALS - 3	TRAILER
T470	Colac - Colac	Susp\AXLES	RE-ASSEMBLE AXLE & TURNTABLE CONTROLS ON THE SIDE OF TRAILER			26/07/2026	1218245	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	JF MECHANICALS - 3	TRAILER
T470	Myrtleford - Workshop	Susp\AXLES	STRIP AXLE BARE FOR BPW TO REPAIR			18/06/2026	1218245	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	JF MECHANICALS - 3	TRAILER
T470	Myrtleford - Workshop	Susp\AXLES	MIDDLE AXLE NEEDS SPRING SADDLES REPLACING.			18/06/2026	1218245	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	TRANSPEC BPW	TRAILER
T470	Myrtleford - Workshop	Susp\AXLES	MIDDLE AXLE NEEDS NEW SPRING CRADLES, AXLE IS MOVING. REMOVE TO ASSESS			29/05/2026	1218245	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	JF MECHANICALS - 3	TRAILER
T470	Myrtleford - Workshop	Brakes\BRAKE ADJ	LH front brake 4mm Check brake. found still at 4mm. recheck next service 3/3/26			13/05/2026	1218245	Fault	Completed	Greenfreight Loxxina Vic	KennedyBPW	Mt Gambier	STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Brakes\AIR FITTIN	REPLACE AIR FITTING ON TRAILER FOR SERVICE BRAKE			26/04/2026	1218245	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	JF MECHANICALS - 3	TRAILER
T470	Myrtleford - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		24/04/2026	1218245	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	JF MECHANICALS - 3	TRAILER
T470	Myrtleford - Workshop	VehService\DS	VehService\DS D Service VehService\DS D Service	VehService\DS		10/04/2026	1218245	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	JF MECHANICALS - 3	TRAILER
T470	Myrtleford - Workshop	VehService\DS	L098248	VehService\DS		10/04/2026	1218245	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Tyres\TP11+12	Tyres\TP11+12 (31-32)			01/04/2026	1218245	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	BORDER BANDAG PTY LTD -3	TRAILER
T470	Myrtleford - Workshop	Tyres\TP9+10	Tyres\TP9+10 (29-30)		Inspect leak and found hose rubbed through. Remove and replace rubbed section of hose with new clamps as required. Cable tie hose secure to prevent from rubbing, all OK	01/04/2026	1218245	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	BORDER BANDAG PTY LTD -3	TRAILER
T470	Myrtleford - Workshop	Brakes\AIR LEAK	Middle axle A trailer brake booster leaking		KWABF232 HOSE UNION 1/2 1 3.09 KWHS010-20 PERFORATED HOSECLAMP BA Inspect and found NR booster hose leaking. Fit joiner where hose leaking and secure, all OK KWABF232 HOSE UNION 1/2 1 3.09	13/03/2026	1218245	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Brakes\AIR LEAK	Brakes\AIR LEAK		KWHS010-20 PERFORATED HOSECLAMP BA Remove wheels, die grind mount where broken and weld repair. Refit wheels and tension, all OK	13/03/2026	1218245	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Susp\DAMAGE	MIDDLE RIGHT TRAILER SHOCKER MOUNT SNAPPED		Sublet1S1121940 Labour	13/03/2026	1218245	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Chassis\EXTE TU	REPLACE FAULTY FIRST LOAD BINDER			26/02/2026	1218245	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	JF MECHANICALS - 3	TRAILER
T470	Myrtleford - Workshop	Tyres\TP05	Tyres\TP05 VehService\DS D Service		CALL OUT	24/02/2026	1218245	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	BORDER BANDAG PTY LTD -3	TRAILER
T470	Myrtleford - Workshop	VehService\DS	L098821	VehService\DS		07/02/2026	1218245	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Susp\SHOCK ABS	RH MIDDLE AXLE BROKEN SHOCKER BOLT		Inspect, found broken bolt on RH middle axle shocker. Make uo new bolt then fit to shocker. Tension to spec. all OK Found LHM brake light not working. Cut wiring out and re-join into neighbouring light. Test light operation, all working as should. Also found x4 bolster lights snapped. Remove and replace 4 bolster lights as required, all OK	07/02/2026	1218245	Repair	Completed	Greenfreight Loxxina Vic	KennedyBPW	Mt Gambier	STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Elect\BRK LIGHT	TAIL LIGHTS, BRAKE LIGHTS AND INDICATORS ALL LOOSE AND FALLING OUT		KWS0205BLUE RED/AMBER SIDE MARKER LAMP 4 90.72 KWS6472BL CONNECTOR-WATERPROOF.2 WAY 20AMP I2 PACK	07/02/2026	1218245	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Tyres\TP1+2	Tyres\TP1+2 (21-22)		PROFORMA SAYS 31-32 BUT CORRECT POS IS 21-22	06/02/2026	1218245	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	BORDER BANDAG PTY LTD -3	TRAILER
T470	Myrtleford - Workshop	Brakes\BRK O/HAUL	STRIP AND REBUILD AXLE (CRACK TEST / REPLACE WHEEL BEARINGS / REPLACE BRAKES / S-CAM BUSHES / BRAKE DRUMS AND ABS SENSORS) REPLACE SPR		RILATECH REPAIRED THE SHOCKER MOUNT Repairs to shocker mount. LOAD AXLE ONTO RESIN TRAILER SENT TO MELB FOR PICK UP & THEN SENT TO MT GAMBIER FOR FITTING OVER THE XMAS BREAK CHECK WHEEL BEARINGS	02/02/2026	1218245	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Susp\AXLES	CHECK NEW AXLE (WHEELS GETTING HOT)		ALL OK	19/01/2026	1218245	Repair	Completed	Greenfreight Loxxina Vic	KennedyBPW	Mt Gambier	STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Susp\HCV	CHECK AND ADJUST RIDE HEIGHT AFTER AP		ound air bags were not pumping up. Inspect and found ride height rod was stuck on cross member. Removed rod and cut to lenath. Reinstalled. tested. al okav.	14/01/2026	1218245	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Susp\DAMAGE	MIDDLE AXLE BROKEN SHOCKER		Shocker bolt broken, jack up and remove wheels. Remove old shocker bolt. Fit new bolt and weld into place, re fit shocker all okav.	14/01/2026	1218245	Repair	Completed	Greenfreight Loxxina Vic	KennedyBPW	Mt Gambier	STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	DrivLine\WHEEL BRGS	WHEEL BREAING RUNNING HOT ON AXEL THAT WAS REPLACED		Adjusted LH front adjusted bearing to spec. Take truck for a test drive and check, all okay.	14/01/2026	1218245	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Tyres\TP11	Tyres\TP11 (31)		Travelled out to truck on Mt Salt Road and inspect damage. Removed deck pate and chained up axle. Locate wheel and hub, return to BMG workshop. Customer arranged new axle. Undo pivot bolts, air bags, boosters and shockers. Removed wheels, undo chains and removed axle. Installed new axle, secure on stands. Fit new springs and u bolts as supplied. Installed new pivot bolts. Refit wheels and tensioned. Greased all points and adjuster. Tensioned u bolts and pivot bolts. Welded bracket for ride height. Measure and cut ride height rod to length. Found air not supplying to air bags as ride height valve was faulty.	13/01/2026	1218245	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	BORDER BANDAG PTY LTD -3	TRAILER
T470	Myrtleford - Workshop	Chassis\WHL HUB	REAR AXLE HUB FALLEN OFF BROKEN DOWN CORNER MT SALT RD AND BELLUM HOTEL VehService\DS D Service		Remove and replaced ride height valve. Checked over, all okay. Take for a test drive and recheck hub temps, all	09/01/2026	1218245	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	VehService\DS	L098455 VehService\DS D Service	VehService\DS		09/01/2026	1218245	Service	Completed	Greenfreight Loxxina Vic	KennedyBPW	Mt Gambier	STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	VehService\DS	L097921	VehService\DS		05/01/2026	1218245	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Tyres\RUN OUT	Tyres\RUN OUT POS 29 Found excessive movement in front LH s-cam, to be		Check S cam movement on front LH	09/12/2025	1218245	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	BORDER BANDAG PTY LTD -3	TRAILER
T470	Myrtleford - Workshop	Brakes\BRAKE ADJ	re-inspected and rectified next service		Check over s-cams for movement, all okay Found axle had moved across and shocker bolt was rubbing on tyre, inspect axle and found locater had broken and caused axle to move, jack up axle and remove wheels, loosen all u bolts. Connect up chain block to pull axle to one side. Once axle in correct place re weld into place and tension u bolts. Re fit wheels and tension wheel nuts to spec. All	04/12/2025	1218245	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Susp\AXLES	SHOCKER MOUNT DIGGING INTO TYRE		okay.	04/12/2025	1218245	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Elect\TRL LIGHTS	Repair lights n/w		Check rear LH side tail and clearance lights. Trace wiring and found breaks in loom. Cut open and repair broken wiring as required. Check operation, all working as should	04/12/2025	1218245	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Chassis\MUDGUARDS	Cecker plate mounting bracket broken of requires welding		Unbolt and remove checker plate. Clean and realign cracks around mounting surfaces then weld. Cut flat metal bar to correct size, clean chassis surface and weld onto mounting plate. Drill holes and fit checker plate with new bolts.	21/11/2025	1218245	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	DrivLine\AXLE REPLC	Rear axle requires replacement bearing not tight on stub end. JB spoke to WD		Sublet1S111956 FLAT BAR CHECK REAR LEFT WHEEL BEARING FOR MOVEMENT Jack all axles and adjust all bearings to spec. Rear LH still had excessive movement. Remove and disassemble hub assembly to inspect. Found all components in hub assembly all ok but stub axle damaged. Temporary fixed axle and reassemble. New axle will need to be ordered. KW03D3093340 D/COVER - BRG SHIELD H91/10 1 3.27 KW03104B130 SEAL-DUST H91/H10 ECO HUB 1 10.89 KW03D3040I0 WASHER-STD HUB ECO BEAMH91 1 9.76 NGFREIGHT FREIGHT	14/11/2025	1218245	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Brakes\EBS FAULTS	Brakes\EBS FAULTS REPAIR BROKEN WIRING ON REAR LEFT SPEED SENSOR		Found speed sensor on LH rear axle had broken wiring. Remove and crimp in new twin core. Fit conduit and spiral wrap to wiring. Zip tie into place, all ok.	14/11/2025	1218245	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Chassis\FIFTH WHEE	TURN TABLE FOOT BUSHES		Split trailers, remove turn table and worn foot bushes. Hit in new bushes, fit pad to turn table, put pin and locking bolts through joined trailers, all ok KWT05-RK06356P KIT-FOOT PIN & BUSH FW351-342 POLY BUSH 1 147.45 KWT05-RK10210 KIT-URETHANE FOOT POCKET FW341 I2 PER KI	14/11/2025	1218245	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Body\TRL LEGS	Body\TRL LEGS		REMOVE PEG LEG - TAKE TO JD'S FOR REPAIR Found landing leg to be damaged. Removed leg and send to JDs metal fab for reapir.	14/11/2025	1218245	Repair	Completed	Greenfreight Loxxina Vic	KennedyBPW	Mt Gambier	STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Elect\TRL LIGHTS	REPAIR REAR RIGHT HAND LIGHTBAR N/W		Tail light bar not working. Inspect and found corroded earth in light bar. Due to heavy corrosion needed replacing. Cut out and join in new loom. Test operation, all ok. Put conduit around wiring to protect and zip tie out way.	14/11/2025	1218245	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	BARRY MANEY - 3	TRAILER

						Found shocker bolt loose, causing damage inside of tyre. Top bush pulled through causing movement in bolt. Heat shocker bolt as was seized then remove and replace shock. Found wheels to be too close to hanger and bolt. Followed axle alignment measurements, suspect tyre size different.										
T470	Myrtleford - Workshop	Susp\SHOCK ABS	TIGHTEN MIDDLE RIGHT SHOCKER		KWF5481 SHOCK ABSORBER-BPW SHORT RFS	14/11/2025	1218245	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	VehService\DS	VehService\DS D Service												
T470	Myrtleford - Workshop	VehService\DS	L097579	VehService\DS		01/11/2025	1218245	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Tyres\TP7+8	Tyres\TP7+8 (27-28)			31/10/2025	1218245	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	BORDER BANDAG PTY LTD -3	TRAILER
			VehService\DS D Service												
T470	Myrtleford - Workshop	VehService\DS	L097304	VehService\DS		28/10/2025	1218245	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Tyres\RUN OUT	Tyres\RUN OUT POS 21-22 + 23			22/10/2025	1218245	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	BORDER BANDAG PTY LTD -3	TRAILER
					R&R BALLRACE AS REQUIRED										
					Remove turn table top off ball race then remove ball race. Cut off bolts for ball race and clean base plate. Fit new										
			Ball race has slight movement (monitor)		ball race and tighten all bolts to spec. Fit turn table to										
T470	Myrtleford - Workshop	Chassis\FIFTH WHEE	REPLACE BALL RACE & ALL MOUNT BOLTS		and tighten. Grease ball race. all ok	14/10/2025	1218245	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	BARRY MANEY - 3	TRAILER
					CHECK BRAKES GETTING HOT										
					RH rear brakes getting hot. Inspect and found adjustment										
					too tight. Adjust brake as required. Remove backing plate										
T470	Myrtleford - Workshop	Brakes\BRAKE ADJ	Brakes\BRAKE ADJ		to check brake condition and ensure they were releasing correctly. All ok. Brakes low, to be replaced next service	10/10/2025	1218245	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	BARRY MANEY - 3	TRAILER
			VehService\DS D Service												
T470	Myrtleford - Workshop	VehService\DS	L097043	VehService\DS		09/10/2025	1218245	Service	Comoleted	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	BARRY MANEY - 3	TRAILER
					QUICK RELEASE BROKEN ON 2ND BINDER										
T470	Myrtleford - Workshop	Body\STRAPS	Body\STRAPS QUICK RELEASE BROKEN 2ND BINDER		Measured out cable, cut to length and crimped a loop on end	08/10/2025	1218245	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	BARRY MANEY - 3	TRAILER
					TRAVEL TO STONYFORD										
T470	Myrtleford - Workshop	Body\BOLSTER	front bolster sitting up could be pulled down to stop movement		RECONNECT AIR LINE TO BOOSTER ON RIGHT HAND SIDE AXLE JOINER IN AIRLINE CAME APART	03/10/2025	1218245	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	OT DIESEL SERVICES - 3	TRAILER
T470	Myrtleford - Workshop	Tyres\TP5+6	Tyres\TP5+6			22/09/2025	1218245	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	BORDER BANDAG PTY LTD -3	TRAILER
					RUBBED AIRLINE BETWEEN TANKS										
					Inspect air leak, found rubbed section to main supply air										
T470	Myrtleford - Workshop	Brakes\AIR LEAK	Brakes\AIR LEAK		line. Cut out rubbed section and reioined	16/09/2025	1218245	Repair	Comoleted	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	BARRY MANEY - 3	TRAILER
			VehService\DS D Service												
T470	Myrtleford - Workshop	VehService\DS	L096676	VehService\DS		15/09/2025	1218245	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	BARRY MANEY - 3	TRAILER
					MIDDLE AXLE SLACK ADJUSTER NEEDS SHIMMING										
T470	Myrtleford - Workshop	Brakes\SLACK ADJ	Brakes\SLACK ADJ MIDDLE AXLE SLACK ADJUSTER NEEDS SHIMMING		Reinspect slack adjuster, found to be all okay	15/09/2025	1218245	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	BARRY MANEY - 3	TRAILER
					CLEARANCE LIGHT ON SECOND BOLSTER BROKEN										
					Check all lights and found to have broken clearance light.										
					Removed light and installed new, wired in as required.										
T470	Myrtleford - Workshop	Elect\TRL LIGHTS	Elect\TRL LIGHTS CLEARANCE LIGHT BROKEN		Check operation, all okay	15/09/2025	1218245	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	BARRY MANEY - 3	TRAILER
					ADJUST WHEEL BEARINGS										
			Steering\WHEEL BRGS MIDDLE AXLE WHEEL BEARINGS		Jacked up LH middle axle and adjust wheel bearings as										
T470	Myrtleford - Workshop	Steering\WHEEL BRGS	CHECK NEXT SERVICE		required	15/09/2025	1218245	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	BARRY MANEY - 3	TRAILER
					MIDDLE AXLE TRACKING LEFT										
					Undo u bolts, shift axle back in line. Refit u bolts and										
T470	Myrtleford - Workshop	Chassis\AXLE CT	Chassis\AXLE MIDDLE AXLE TRACKING LEFT		tensioned to spec.	15/09/2025	1218245	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	BARRY MANEY - 3	TRAILER
					BROKEN SPRING LH FRONT										
					Remove ride height, air bag bolts, shocker, u-bolts, and										
			Susp\SPRING		pivot bolt. Fit new LH front spring. Refit and tension all										
T470	Myrtleford - Workshop	Susp\SPRING HANG	SNAPPED SPRING		components previously removed	02/09/2025	1218245	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		27/08/2025	1218245	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Tyres\RUN OUT	Tyres\RUN OUT POS 27			27/08/2025	1218245	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	BORDER BANDAG PTY LTD -3	TRAILER
					GREENFREIGHT SERVICE										
					Carried out trailer service as per Greenfreight checklist.										
					Customer Instructions:										
					Place vehicle on shaker & Inspected										
					Carried out General Inpection & Checkover										
					Greased vehicle										
			VehService\DS D Service		Check over and retension pivot bushes & u bolt										
T470	Myrtleford - Workshop	VehService\DS	L096227	VehService\DS	Check over and tensioned all bolster bolts as require	27/08/2025	1218245	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	BARRY MANEY - 3	TRAILER
					CHECK LH REAR WHEEL BEARING										
					Work order 200068										
T470	Myrtleford - Workshop	DrivLine\WHEEL BRGS	Check all trailer wheel bearings - LH rear is worst		Jack up and checked wheel bearing. all okay	22/08/2025	1218245	Fault	Comoleted	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	BARRY MANEY - 3	TRAILER
					REPLACE TURNTABLE WEAR PLATES										
T470	Myrtleford - Workshop	Susp\SUSPENSION	REPLACE WEAR PADS		Work order 200068	22/08/2025	1218245	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	BARRY MANEY - 3	TRAILER
					RECHECK LH REAR PIVOT BUSH MOVEMENT										
					Work order 199835										
					Check over all pivot bushes, all seemed ok and to not have										
T470	Myrtleford - Workshop	Susp\SHOCK ABS	Rear left pivot bush, monitor slight movement		movement. Tensioned all pivot bolts to spec. all ok	14/08/2025	1218245	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	BARRY MANEY - 3	TRAILER
					FIRST BOLSTER R/S BOLSTER CHAIN NEEDS FIXING TO BOLSTER										
					Work order 199835										
					Inspect bolster that had dropped down, found lug for chain										
					broken that secures bolster. Make up suitable lug weld into										
					position, remove hammer lock pin and place hammerlock										
T470	Myrtleford - Workshop	Body\BOLSTER	first bolster R/S bolster chain needs fixing to bolster		through lug and insert pin. Fit new bolt	14/08/2025	1218245	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	BARRY MANEY - 3	TRAILER
					REPLACE x4 HUB NUTS										
					Jacked up axles, remove hub caps and replaced hub nuts										
			Replace rear middle and rear axle nuts,		where required. Checked bearing movement on LH rear axle,										
T470	Myrtleford - Workshop	DrivLine\CONSUMABLE			all within spec.	14/08/2025	1218245	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	BARRY MANEY - 3	TRAILER
					R&R FOOT BUSHES										
			Susp\TURNTABLE REPAIR		Split trailers and removed turn table top. Removed foot										
T470	Myrtleford - Workshop	Susp\Torque Rod	R&R FOOT BUSHES		bushes and replaced with new. Inspect wear pads, found to										
					be low and will need to be reolaced next service	14/08/2025	1218245	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	BARRY MANEY - 3	TRAILER
					Carried out trailer service as per Greenfreight checklist.										
					Customer Instructions:										
					Place vehicle on shaker & Inspected										
					Carried out General Inpection & Checkover										
					Greased vehicle										
					TENSION PIVOT BUSHES & U BOLTS										
					Check over and retension pivot bushes & u bolts										
					TENSION BOLSTER BOLTS										
					Check over and tensioned all bolster bolts as required										
					DISCONNECT TRUCK OR TRAILER										
T470	Myrtleford - Workshop	VehService\DS	VehService\DS D Service	VehService\DS	Disconnect trailers. check over turntable and kina pin. Greased all components. all within spec. Reconnect.	12/08/2025	1218245	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	BARRY MANEY - 3	TRAILER
					Labour										
					Reported Fault:										
					Brakes not functioning correctly; suspension movement noted during inspection.										
					Diagnosis & Cause:										
					Brake fault diagnosed – adjustment required.										
					Found excessive movement in LHR spring eye bush, indicating bush failure.										
					Correction:										
					Adjusted all brakes.										
					Removed LHR spring, U-bolts, and worn spring eye bush.										
					Organised and installed new spring eye bush.										
					Cleaned U-bolts and airbag bolts.										
					Reinstalled spring to trailer with new pivot bolt.										
T470	Myrtleford - Workshop	Brakes\BRAKE ADJ	Brakes\BRAKE ADJ		Refit and tensioned U-bolts and all associated hardware to specification.	05/08/2025	1218245	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	HALLORAN DIESEL - 3	TRAILER
T470	Myrtleford - Workshop	Tyres\RUN OUT	Tyres\RUN OUT POS 25-26			04/08/2025	1218245	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	BORDER BANDAG PTY LTD -3	TRAILER
T470	Myrtleford - Workshop	Tyres\TP9+10	Tyres\TP9+10			04/08/2025	1218245	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	BORDER BANDAG PTY LTD -3	TRAILER
					WORN PIVOT BUSH RH FRONT										
					Undid shocker nuts and removed shocker. Undid bolts and										
					removed saddle. Undid air bag bolts and removed spring,										
					then pressed out old bush. Pressed in new bush, lifted										
					spring and put new pivot bolt in. Insert side plates, then										
					jacked up rear end of spring to reinstall saddle. Reinstall										
T470	Myrtleford - Workshop	Steering\SUSPENSION	Steering\SUSPENSION		air bag bolts and tighten nuts. Reinstall shocker and tighten bolts. Tensioned all bolts and u bolts, all ok	25/07/2025	1214569	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	BARRY MANEY - 3	TRAILER
					CHECK & REPACK OR REPLACE BEARINGS AS REQUIRED										
					Work order 199055										
					Inspect movement on shaker, found all axles had excessive										
					movement.										
					Jacked up all axles and removed hub assembly to inspect										
					bearings. Found bearings to have minimal or grease, hub										
					grease was okay. Hit out all bearings. Cleaned										
					bearings in parts washer. Found some axle nuts had pitting on										
					them. Ordered parts. Repacked all bearings with new BPW										
					grease and ensured all rollers were greased properly.										
					Reinstalled bearings to hubs with new seals. Refit hub										
			Trailer wheel bearings need re pack and possible replacement (Re check		assembly and adjusted all bearings to BPW spec. Secured hub										
T470	Myrtleford - Workshop	DrivLine\WHEEL BRGS	next service)		caps and tensioned hub caps	25/07/2025	1214569	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	BARRY MANEY - 3	TRAILER
					AIR TANK BUNG LOSING AIR FROM IT										
					Work order # 199055										
T470	Myrtleford - Workshop	Body\AIR LEAK	AIR TANK BUNG LOSING AIR FROM IT		Remove and replace bung with new, all ok	25/07/2025	1214569	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	BARRY MANEY - 3	TRAILER
					COVER FOR SLAVE UNIT BROKEN SCREWS OFF										
					Work order # 199055										
					Need new slave for weigh scales in near future. Glued cover										
T470	Myrtleford - Workshop	Chassis\SCALES	COVER FOR SLAVE UNIT BROKEN SCEWS OFF		back on for now. New part S2340, part # 23/128116	25/07/2025	1214569	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	BARRY MANEY - 3	TRAILER
					AIR LEAKS										
					Inspect and found split booster hose. Cut out split, fit a										
T470	Myrtleford - Workshop	Brakes\AIR LEAK	AIR LEAKS		joined and x2 clamps. Check, all ok	23/07/2025	1218245	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	BARRY MANEY - 3	TRAILER

						GREENFREIGHT SERVICE Carried out trailer service as per Greenfreight checklist. Customer instructions: Place vehicle on shaker & Inspected Carried out General Inspection & Checkover Greased vehicle TENSION PIVOT BUSHES & U BOLTS Check over and retension pivot bushes & u bolts TENSION BOLSTER BOLTS												
T470	Myrtleford - Workshop	VehService\DS	VehService\DS D Service	VehService\DS	Check over and tensioned all bolster bolts as reauired.	18/07/2025	1214569	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
T470	Myrtleford - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		09/07/2025	1186708	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
					SECOND BOLSTER FALLING FWD Work order 198819 Inspect 2nd bolster. Found lock bolt to be broken and bent. Flipped bolster and used oxy to cut bolt off. Straightened													
T470	Myrtleford - Workshop	Body\BOLSTER	second bolster keeps falling forward		bolt bracket and lifted bolster. Installed new bolt, all ok	09/07/2025	1186708	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
					CHECK WHEEL BEARINGS Jacked and supported front axle. Removed hub caps and checked wheel bearings. Adjusted both side wheel bearings, reinstall caps, all ok. Trailer will need to come back for													
T470	Myrtleford - Workshop	DrivLine\WHEEL BRGS	DrivLine\WHEEL BRGS		repack and ootentially new bearinas	09/07/2025	1186708	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
T470	Myrtleford - Workshop	DrivLine\WHEEL BRGS	CHECK ALL BEARINGS & ADJUST		Jacked up each axle, removed hub caps and adjusted wheel bearings to spec	21/06/2025	1184105	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
T470	Myrtleford - Workshop	Body\AIR LEAK	REPAIR RUBBED AIR LINES		Cut rubbed section of hose out, and rejoined hose. Check over for leaks. all ok	21/06/2025	1184105	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
T470	Myrtleford - Workshop	Elect\TAIL LIGHT	TAIL LIGHTS AND INDICATOR LIGHTS N/W		RH rear tail lights and indicators not working. Removed lights and found damaged wiring. Repair loom and reconnect lights. Test operation, all ok	21/06/2025	1184105	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
					GREENFREIGHT SERVICE Carried out trailer service as per Greenfreight checklist. Customer instructions: Place vehicle on shaker & Inspected Carried out General Inspection & Checkover Greased vehicle TENSION PIVOT BUSHES & U BOLTS Check over and retension pivot bushes & u bolts TENSION BOLSTER BOLTS												
T470	Myrtleford - Workshop	VehService\DS	VehService\DS D Service	VehService\DS	Check over and tensioned all bolster bolts as reauired.	18/06/2025	1186708	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
T470	Myrtleford - Workshop	Tyres\TP3+4	Tyres\TP3+4			17/06/2025	1184105	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BEAUREPAIRES - 3	TRAILER			
T470	Myrtleford - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		29/05/2025	1184105	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
T470	Myrtleford - Workshop	Chassis\SCALES	CH2 SCLAES N/W		CH2 SCLAES N/W Checked plugs for correct connections. Check fault light, okay. Found air bag overide handle in manual position, pulled out and scales went to operating range. Replaced dirty transducer fitter.	28/05/2025	1184105	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
T470	Myrtleford - Workshop	Body\AIR LEAK	AIR LEAKS		AIR LEAKS Found supply line on trailer was leaking. Pulled mounting plate off and tightened bulk head, all okay. This air leak may have affected scales.	28/05/2025	1184105	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
					CHECK WHEEL BEARINGS Jacked up each axle, removed bearing caps and adjusted each wheel bearing to correct end float. Refit caps, lowered													
T470	Myrtleford - Workshop	DrivLine\WHEEL BRGS	CHECK WHEEL BEARINGS		axles.	28/05/2025	1184105	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
T470	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection	Insp\ANN INSP	CARRY OUT ANNUAL INSPECTION AS PER GREENFREIGHT PAPERWORK	27/05/2025	1184105	PreventativeMaintenance	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
T470	Myrtleford - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		19/05/2025	1177372	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
T470	Myrtleford - Workshop	DrivLine\WHEEL BRGS	check wheel bearings			15/05/2025	1177372	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
T470	Myrtleford - Workshop	Tyres\TP11+12	Tyres\TP11+12			02/05/2025	1165076	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BEAUREPAIRES - 3	TRAILER			
T470	Myrtleford - Workshop	Tyres\TP9+10	Tyres\TP9+10			02/05/2025	1165076	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BEAUREPAIRES - 3	TRAILER			
					Jacked up LH front and LH middle axles. Checked wheel bearing adjustment, found to be excessive. Removed hub cap and adjusted to correct end float. Refit caps, lowered													
T470	Myrtleford - Workshop	DrivLine\WHEEL BRGS	DrivLine\WHEEL BRGS		axles.	15/04/2025	1165076	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		15/04/2025	1153450	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
T470	Myrtleford - Workshop	Tyres\TP1+2	Tyres\TP1+2			02/04/2025	1153450	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BEAUREPAIRES - 3	TRAILER			
T470	Myrtleford - Workshop	Tyres\TP7+8	Tyres\TP7+8			02/04/2025	1153450	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BEAUREPAIRES - 3	TRAILER			
T470	Myrtleford - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		24/03/2025	1153450	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
					CHECK FOR AIR LEAKS Driver requested to check for air leaks. built up air, released brakes, sprayed soapy water over all components,													
T470	Myrtleford - Workshop	Brakes\AIR LEAK	Brakes\AIR LEAK		no air leaks found	13/03/2025	1145508	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		11/03/2025	1145952	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
T470	Myrtleford - Workshop	Susp\SHOCK ABS	rear shocker on LH side needs looking at shocker was reolaced bv JF MECHANICAL 22/2/25			03/03/2025	1136497	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	JF MECHANICALS - 3	TRAILER			
			WHEEL BEARING ASSESMENT & GREASE AS WELL AS REPAIRS.															
T470	Myrtleford - Workshop	Brakes	REPAACK ALL WHEEL BEARINGS & REPLACE MISSING GREASE HUB SLINGERS REPLACE ALL 6 HUB CAPS REPLACE RHM SHOCKER DONE AT 114174KMS			03/03/2025	1136497	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	MAXIPARTS P/L - 3	TRAILER			
T470	Myrtleford - Workshop	Tyres\TP3+4	Tyres\TP3+4			03/03/2025	1136497	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BEAUREPAIRES	TRAILER			
T470	Myrtleford - Workshop	Tyres\TP7+8	Tyres\TP7+8			03/03/2025	1136497	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BEAUREPAIRES	TRAILER			
T470	Myrtleford - Workshop	Tyres\TP12	Tyres\TP12			03/03/2025	1136497	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BEAUREPAIRES	TRAILER			
T470	Myrtleford - Workshop	Tyres\RUN OUT	Tyres\RUN OUT 11			03/03/2025	1136497	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BEAUREPAIRES	TRAILER			
					MIDDLE AXLE S-CAM BUSHES jacked up middle axle, removed both hubs and brakes. Disassembled s-cams and replaced s-cams with new kit. Refit													
T470	Myrtleford - Workshop	Susp\AXLES	Middle axle s-cam bushes very worn		brakes and hub assembly. Adjusted bearings to spec, tensioned wheel nuts. Adjusted brakes and greased s-cams, all okay	19/02/2025	1136497	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
					AIR BINDER LEAKING INTERNALLY Check binder operation, unbolt and removed strap roller. Unbolt and remove binder, change over bolts to new binder.													
T470	Myrtleford - Workshop	Body\STRAPS	second air binder leaks air inside the unit when turned on		installed new binder. Tightened rear mounting bolts and change over air fittings. Fit strap roller, fit air line. Checked operation, all okay	19/02/2025	1136497	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
					CHECK AND ADJUST ALL WHEELBEARINGS Inspect bearings for movement, removed all caps and found grease is unserviceable. Trailer needs to be rebooked for													
T470	Myrtleford - Workshop	Steering\WHEEL BRGS	Steering\WHEEL BRGS		trailer bearing re-pack.	19/02/2025	1136497	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
T470	Myrtleford - Workshop	VehService\DS	VehService\DS	VehService\DS		18/02/2025	1136497	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
					LABOUR: GREENFREIGHT - 789575 CARRY OUT INSPECTION OF TRAILER AND REPORT													
T470	Myrtleford - Workshop	Body\DAMAGE	Body\DAMAGE		REPAIR DAMAGED GUARD MOUNT	12/02/2025	1119620	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	TRIPLE S DISTRIBUTORS - 3	TRAILER			
T470	Myrtleford - Workshop	VehService\DS	VehService\DS	VehService\DS		30/01/2025	1125221	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
					DIAGNOSE AIR LEAK AT RIDE HEIGHT VALVE AND REPAIR work order # 193289 Inspect for air leak at ride height, could not fault.													
T470	Myrtleford - Workshop	Susp	DIAGNOSE AIR LEAK AT RIDE HEIGHT VALVE & REPAIR.		Insoect over all of trailer. no air leaks.	30/01/2025	1125221	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
					WORN SHOCKER BUSHES work order # 193289 Insoect all shocker bushes. all within spec.													
T470	Myrtleford - Workshop	Susp\SHOCK ABS	Loose shock, shock bushes worn, and one is weeping		CHECK MOVEMENT IN SPRING EYE BUSHES FRONT AXLE Work order # 193289 Found LH front pivot bush was worn. Jacked up chassis and supported. Dumped air and undo air bag an u bolts. Found shocker was snapped, unbolt and removed shocker. Lowered out spring, undo pivot bolt, use pry bar to remove spring. Pressed out worn pivot bush, cleaned mounting surface and installed new pivot bush. Reinstalled spring, refit u bolts with new wear plates. Fit new shocker, tensioned bolts.	30/01/2025	1125221	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
T470	Myrtleford - Workshop	Susp\AXLES	Slight movement in spring eye bushes on front axle		Refit air bae. tensioned all bolts.	30/01/2025	1125221	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
					ABS SENSOR AT RH REAR HUB HANGING OUT Work order # 193289													
T470	Myrtleford - Workshop	Brakes\ABS	ABS sensor at RHR hub hanging out		Refit sensor.	30/01/2025	1125221	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
					RH brake light n/w Removed light and inspect wiring, found numerous rubbed wires going into the plug. Installed new light and wires													
T470	Myrtleford - Workshop	Elect\BRK LIGHT	Elect\BRK LIGHT		in. Checked operation. all okav.	30/01/2025	1125221	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
					FIT BOLTS WHERE MISSING Remove bolts and use for sample. Got new 1/2inch bolts and fit in place where bolts missing. Used 22 bolts in total													
T470	Myrtleford - Workshop	Body\DAMAGE	Body\DAMAGE		with washers and tension.	30/01/2025	1125221	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
T470	Myrtleford - Workshop	Tyres\TP9+10	Tyres\TP9+10			24/01/2025	1119620	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BEAUREPAIRES - 3	TRAILER			
T470	Myrtleford - Workshop	Brakes\BREAKDOWN	Brakes\BREAKDOWN		AFTER H'RS BREAKDOWN Removed cables ties from temp repair on breakdown. Fitted new hose clamp. Checked operation and for further air	14/01/2025	1119620	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
T470	Myrtleford - Workshop	Brakes\AIR FITTIN	Brakes\AIR FITTIN		leaks. All ok Attended brake down on Caroline Rd. Inspected & found air line popped off air tank. Reinstalled air line, advised driver to return to workshop in hours to fit hose clamp	14/01/2025	1119620	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
T470	Myrtleford - Workshop	Brakes\AIR FITTIN	Brakes\AIR FITTIN		securely.	14/01/2025	1119620	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
T470	Myrtleford - Workshop	VehService\DS	VehService\DS	VehService\DS		08/01/2025	1104587	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
					REMOVE ALL BOLSTER PINS AND SEND TO DIMMYS TO BE TESTED FIT NEW BOLSTER PINS THAT HAVE ALREADY BEEN TESTED BY DIMMY Work order 192360 Unbolt each bolster pin, connect with sling and removed. Installed new bolster pin with new bolt and nut. Carry out												
T470	Myrtleford - Workshop	Body\BOLSTER	Remove pins from bolters and replace with pretested pins		for all pins on trailer. Tensioned all bolster bolts. All bolsters were fitted with new nuts and bolts	19/12/2024	1108183	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			

T470	Myrtleford - Workshop	Chassis\CROSS MBR	checker plate needs securing as caused rubbing through air hose		RESECURE CHECKER PLATE AS RUBBING THROUGH AIR HOSE Work order 192360 Cut steel and welded nuts to steel. Fit under deck plate and secured with bolts.	19/12/2024	1108183	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Steering\WHEEL BRGS	Steering\WHEEL BRGS		JACK UP AND CHECK WHEELBEARINGS Jacked up front axle and adjusted wheel bearing. Found still had too much free play. Replaced washer behind nut and recheck end float, still no good. Needs to be rebooked for bearing repack.	19/12/2024	1108183	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Susp\AIR BAG	Susp\AIR BAG		Repair leaking air bag Unbolted airbag mount, cut small bar to gain access to tops nuts. Cleaned out top section above airbag as nuts were covered in dirt. Removed air fitting and air bag. Dropped ride height & fit new air bag. Secured & tested. All ok. Replaced fitting on LH rear booster.	26/11/2024	1105275	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Body\AIR FITTIN	Body\AIR FITTIN		AIR LEAK IN SUPPLY LINE On inspection found the supply line to be split. Removed damaged section of line, ran new length and fit olive. Joined and secured. Tested for leaks. All ok.	26/11/2024	1105275	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Chassis\AIR LEAK	REPAIR RUBBED AIR LINES		Found leaking fitting in ride height valve. Remove fitting and reolace with new. Tested. no further leaks.	26/11/2024	1108183	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	VehService\DS	VehService\DS	VehService\DS		22/11/2024	1104587	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Body\BOLSTER	Body\BOLSTER		TENSION BOLSTER BOLTS Check over all bolster bolts and tightened as resuired	21/11/2024	1104587	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	DrivLine\WHEEL BRGS	DrivLine\WHEEL BRGS		RETENSION LHR WHEELBEARING DUE TO BEING LOOSE Jacked up LH rear wheel and adjusted wheel bearing to correct end float. Lowered axle. all okay. Checked over all brakes, found Front axle and LH rear brakes were past wear limit. All other still had plenty left. Jacked up required axles, removed hub assembly. Removed brake linings and replaced with new. Replaced brake drums from hub assemblies, inspect wheel bearings and found grease was no good. Remove bearings and cleaned, repaired with new grease. Cleaned stubs and applied new grease. Installed new brake drums to hub assemblies, reinstalled hubs to axles. Tensioned wheel nuts and adjust brakes.	21/11/2024	1104587	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Brakes\BRK RELINE	brakes require re-lining		Adjust wheel bearings to correct end float.	08/11/2024	1096533	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Body\MUDGUARDS	REPLACE LF MUDGUARD.		Unbolt and removed LH front mud guard. Measure and drilled holes in new guard, mounted guard to trailer and secured with nuts and bolts. Inspect ride height valve for fault., Found fittings were leaking on ride height valve. Removed fittings and replaced with new. Checked over, no further leaks.	08/11/2024	1096533	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Chassis\SCALES	R&R RIDE HEIGHT VALVE			08/11/2024	1096533	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Tyres\TP11+12	Replace Tyres Position 11 & 12. (Mount Gambier Goodyear Autocare P/O: L090004)		Traveled To Vehicle Replaced Tyres On Position 11 & 12.	07/11/2024	1096533	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BEAUREPAIRES - 3	TRAILER
T470	Myrtleford - Workshop	Brakes\AIR LEAK	Job Created from Purchase Order #: 104867		REPAIRED RUBBED AIR LINE	01/11/2024	1076050	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	JF MECHANICALS - 3	TRAILER
T470	Myrtleford - Workshop	VehService\DS	VehService\DS	VehService\DS		24/10/2024	1096533	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	JF MECHANICALS - 3	TRAILER
T470	Myrtleford - Workshop	Tyres\TP3+4	Tyres\TP3+4 CHECK OPERATION OF SCALES WENT OVER AT MILL LAST NIGHT Removed transducer vent, cleaned out breather vent until			09/10/2024	1076050	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BEAUREPAIRES - 3	TRAILER
T470	Myrtleford - Workshop	Chassis\AIR FITTIN	clean re check ooeration all seemed to be workine okav AIR TANK BEHIND SECOND BOLSTER LEAKING AT RH BUNG			28/06/2024	1076050	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Brakes\AIR LEAK	Remove and reolace air fittine DECKPLATE NEEDS MORE NUTS AND BOLTS			28/06/2024	1076050	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Body\PANELS	Fit new bolts to deck plate as required.			28/06/2024	1076050	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Tyres\TP7+8	Tyres\TP7+8			27/06/2024	1076050	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BEAUREPAIRES - 3	TRAILER
T470	Myrtleford - Workshop	VehService\DS	VehService\DS	VehService\DS		27/06/2024	1076050	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Tyres\TP9+10	Tyres\TP9+10			13/06/2024	1035700	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BEAUREPAIRES - 3	TRAILER
T470	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		07/06/2024	1035700	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER
T470	Wodonga - Workshop	DrivLine\WHEEL BRGS	CHECK WHEEL BEARINGS		Jacked each axle, removed hub caps and adjusted wheel bearings to spec. Refit caps and lowered axles.	07/06/2024	1035700	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	VehService\DS	VehService\DS pork: L086238	VehService\DS		04/06/2024	1035700	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Elect\WORK LIGHT	R/H SIDE IN LIGHT BAR ONLY 1 CLEARANCE LIGHT.			29/05/2024	1035700	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Elect\WORK LIGHT	NO WORK LIGHTS ON LOG BACK.			29/05/2024	1035700	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Brakes\AIR LEAK	REPAIR AIR LEAK AT LH REAR BOOSTER - Found rubbed hoses on booster. Loosened clamps & removed lines. installed new hoses and tightened.			27/05/2024	1035700	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Susp\SUSPENSION	BROKEN SPRING PLATE		Unbolt shocker, found to be leaking. Removed plate & installed new. Fit new shocker, tensioned bolts.	27/05/2024	1035700	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Elect\BRK LIGHT	BRAKE LIGHT OUT		Tested wiring from junction to rear bar. Found broken power wire in rear bar. Repaired wire and refit lights, all okay.	27/05/2024	1035700	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Body\AIR LEAK	AIR LEAKS		Inspect for air leak, found supply hose was worn & leaking. Replaced push in joiner & cut out worn section, Tested, no further leaks.	27/05/2024	1035700	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	VehService\DS	D Service P0# L048276	VehService\DS		24/05/2024	1035700	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Tyres\TP9+10	Tyres\TP9+10			23/05/2024	1035700	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BEAUREPAIRES - 3	TRAILER
T470	Myrtleford - Workshop	Tyres\TP9+10	Tyres\TP9+10 REPAIR AIR LEAK AT LH REAR BOOSTER - Found rubbed hoses on booster. Loosened clamps &			23/05/2024	1035700	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BEAUREPAIRES - 3	TRAILER
T470	Myrtleford - Workshop	Brakes\AIR LEAK	removed lines, installed new hoses and tightened. WORK LIGHTS & REVERSE LIGHTS FAULTING - Tested for power in trailer plug from truck, all okay. When plugged into A trailer, fuse would blow. Removed deck plate at front of trailer & inspected wiring, all okay. Removed deck plate above front axle &found issue in rear light bar of A trailer. Run new 7 core wiring from light bar, tee into existing wiring from front of trailer & up to B trailer. Wired in rear light bar & checked operation, all okay. Secured new wiring & refitted deck plates Wired up work lights on			04/05/2024	1035700	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Elect\TRL LIGHTS	B trailer. tested. all okay.		Travelled to breakdown location, inspected air components & found brake booster hose blown. Repair	25/04/2024	1035257	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist			25/04/2024	1035257	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	VehService\DS	P0# L085534	VehService\DS		25/04/2024	1035257	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Brakes\AIR LEAK	REPLACE BOOSTER LINE. (TOO MANY JOINERS IN IT)			25/04/2024	1035257	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Elect\TRL LIGHTS	CLEARANCE LIGHTS N/W ON TRAILERS - Disconnected suzi to A trailer, tested for 12volts, found not being supplied to trailers. Tested fuses and found blown fuse. Reset fuse & tested power at truck, A trailer & B trailer. All had 12 + volts. leave liehts turned on for 20 minutes. did not blown fuse aeain.			20/04/2024	1029098	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Brakes	CHECKED ALL BRAKES (LOCKED UP & LEAKED OIL)		AFTER HRS BREAKDOWN - BRAKES LOCKED UP Travelled to breakdown location, inspected air components & found brake booster hose blown. Repair line with new ioiner and hose clamos. Tested. all okav and brakes released.	10/04/2024	1029098	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Tyres\TP11+12	Tyre Position 11 + 12			06/04/2024		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Albury Workshop	TRAILER
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist			03/04/2024	1026808	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	VehService\DS	P0# L085091 WORK LIGHT N/W - inspect & tested wiring at work light, no good. Traced back to plug, disconnected	VehService\DS		03/04/2024	1026808	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Elect\WORK LIGHT	& found to be dirty. Cleaned out plug & reconnected, light started working. Secured with tape & heat shrink to prevent dirt enterine plug again.			03/04/2024	1026808	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Tyre\TP1+2	Tyre Position 1 + 2			22/03/2024		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Albury Workshop	TRAILER
T470	Myrtleford - Workshop	Tyres\TP5+6	Tyre Position 5 + 6 CHECK WHEEL BEARINGS - check middle axle wheel bearings, remove cap jack up & adjust to			22/03/2024		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Albury Workshop	TRAILER
T470	Myrtleford - Workshop	Steering\WHEEL BRGS	specs. re peat for all wheels . Found washer worn removed & replaced. RH TAIL LIGHT NW - Check no inner RH inner tail light remove insert found damaged wiring broken			15/03/2024		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Elect\TAIL LIGHT	out of rear light. Fit new lights & repair tail light wiring with check operation-ok BRAKES NOT HOLDING - Inspected S/cams linings, adjusted and greased - seems ok.			15/03/2024		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Brakes\BRAKE ADJ	Will monitor next service.			15/03/2024		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP	TRAILER ROADWORTHY - trailer roadworthy as per checklist & check over	15/03/2024		PreventativeMaintenance	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist			15/03/2024	101642	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	VehService\DS	P0# L084692	VehService\DS		15/03/2024	101642	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Elect\ELECT P&W	THE CORD FOR THE SCALES FROM THE A TRAILER TO THE B TRAILER. A NEW ONE IS ORDERED. This fault was in the scale lead from 1033 refer entry 183362			15/03/2024	101642	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Elect\TRL LIGHTS	LIGHTS ON 2ND BOLSTER N/W - Inspect bolser light, found plug was broken. Removed plug & installed new. Tested ooeration. all okav. PARTS 59.50 I LABOUR $67.50			12/03/2024	1035700	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	PACCAR PARTS FLEET SERVICES - 3	TRAILER
T470	Myrtleford - Workshop	Tyres\FITMENT	12 AIRLINE BLEW OFF AIR TANK AT OTR - Travel to truck broken down, inspect for air leak.			09/03/2024		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Albury Workshop	TRAILER
T470	Myrtleford - Workshop	Brakes\AIR TANKS	Found air line on front of air tank had come off. Sourced new parts, return to trailer, installed clamps and refit air line to tank. Tightened clamo. checked over. no further leaks.			01/03/2024	1010692	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Body\MUDGUARDS	R/H FRONT GUARD BRACKET BENT.		RH GUARD BRACKET BENT - Used jacks to bend back into position, jacked up until straight, okay.	29/02/2024	1007255	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist			29/02/2024	1007255	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	VehService\DS	P0# L084391 FIT SKID PLATE PIVOT PINS BOSSES BUSHES & BOLTS	VehService\DS		29/02/2024	1007255	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Chassis\SKID PLATE	ALSO REPAIR CRACKS			16/02/2024		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	WRECKETT PTY. LTD - 3	TRAILER
T470	Myrtleford - Workshop	Tyres\TP3+4	Tyre Position 3 + 4			07/02/2024		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Albury Workshop	TRAILER
T470	Myrtleford - Workshop	Susp\SHOCK ABS	LHF TOP SHOCKER BOLT LOOSE - Tightened loose bolt, checked all others. RELINE LOW BRAKE - Removed hub cap, jacked up axle & removed wheel & hub assembly.			02/02/2024	999108	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Brakes\BRK RELINE	Removed brake linings & replaced with new. Removed bearings from hub, cleaned & repacked. Refit repacked bearings to hub. Reinstalled hub assembly, adjusted bearings & brakes. Refit hub cap.			02/02/2024	999108	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Brakes\BOOSTER	BOOSTER LINE LEAKING- Locate air leak to LH front boost air line. Cut booster hose, joined new length of hose with barb fitting. Cable tied lines to prevent further rubs. Also found drain bung leaking. Drained air from tank, remove drain fitting & installed new. Built up air, checked, no further leaks.			02/02/2024	999108	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist			02/02/2024	999108	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	VehService\DS	P0# L083743	VehService\DS		02/02/2024	999108	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Tyres\TP9+10	Tyre Position 9 + 10			31/01/2024		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Albury Workshop	TRAILER
T470	Myrtleford - Workshop	Chassis\CHAS CRACK	Chassis Crack REPAIR CRACKED HEAD BOARD - Remove remaining pole from headboard. Straightened pole with			30/01/2024		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Albury Workshop	TRAILER
T470	Myrtleford - Workshop	Body\DAMAGE	press. Found suitable pole to replace missing one. Prepped welding area with grinder and rewelded poles in position. Found one pole starting to crack, welded over crack. Painted area.			26/01/2024		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Tyres\Rims	pos 9			23/01/2024		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Albury Workshop	TRAILER
T470	Myrtleford - Workshop	Elect\ELECT P&W	L/H CLEARANCE LIGHT ON NOT WORKING.jobs were done refer invoice 374717. L/H CLEARANCE LIGHT ON NOT WORKING.			17/01/2024	991410	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Elect\INDICATORS	FIRST BINDER HARD TO PUT IN AND OUT OF GEAR. NEW HANDLE WOULD BE GOOD.jobs were done refer invoice 374717 G/F supplied the parts. FIRST BINDI			17/01/2024	991410	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist			17/01/2024		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	VehService\DS	P0# L083429	VehService\DS		17/01/2024		Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Elect\TRL LIGHTS	LH CLEARANCE LIGHT N/W - Removed light & found broken earth wire. Cut out & repaired, tested light, no change. Replaced light with new, cheked, all okay FIRST BINDER HARD TO GET IN/OUT OF GEAR - Removed broken stud from winch handle. Installed			17/01/2024	991410	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Albury Workshop	TRAILER
T470	Myrtleford - Workshop	Chassis\WINCH/STRP	new handle from GF stock. AIR LEAKS - Removed damaged air lines x2, cut out damaged section & replaced air line to tank.		REPLACE AIR TANK BOLTS - Unable to tighten loose bolts. Removed rear deck plate, cut off old bolts	17/01/2024	991410	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Albury Workshop	TRAILER
T470	Myrtleford - Workshop	Susp\AIR LEAK	Reconnect & cabnle tied to prevent rubbing.		and installed new. Refit deck plate.	17/01/2024	991410	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Albury Workshop	TRAILER
T470	Myrtleford - Workshop	Susp\HCV	REPLACE RIDE HEIGHT - Removed valve & replaced with new. Set ride height & adjusted.			17/01/2024	991410	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Albury Workshop	TRAILER

			CLEARANCE LIGHT ON REAR LIGHT BAR RH SIDE - Inspect rear light, removed light and found																	
T470	Myrtleford - Workshop	Elect\TRL LIGHTS	to have broken wire. Repaired wirine and reioined. tested liaht. all okav. Refit liaht to bracket.					04/01/2024	984386	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Albury Workshop	TRAILER
T470	Myrtleford - Workshop	Tyres\TP3+4	Tyre Position 3 + 4					17/12/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Albury Workshop	TRAILER
T470	Myrtleford - Workshop	Tyres\TP9+10	Tyre Position 9 + 10					17/12/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Albury Workshop	TRAILER
			AIR LEAKS - Inspect for air leaks, found loose hose clamp on booster. Checked air tanks for leak &																	
			found three bungs were leaking. Drained air from system and removed two bungs. Applied thread																	
T470	Myrtleford - Workshop	Brakes\AIR LEAK	sealant and reinstalled. Third bung was damaged. installed new bung. Tested operation. all okav.					08/12/2023	980326	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Albury Workshop	TRAILER
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					07/12/2023	980326	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist																	
T470	Myrtleford - Workshop	VehService\DS	PO# L082825	VehService\DS				07/12/2023	980326	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	BARRY MANEY - 3	TRAILER
							Arranged Portland repairer to attend trailer and chain up axle so it could return to BMG workshop.													
							Moved into workshop, jack & support chassis. Removed wheels. Removed boosters and airbags.													
							Removed pivot bolts & then removed the entire axle. Cleaned all surfaces & installed new axle. Moved													
							into position and fit the pivot bolts. Fit axle straps. Jacked axle & put wheels on. Tensioned all ubolts													
T470	Myrtleford - Workshop	Susp\SUSPENSION	BREAKDOWN IN PORTLAND - SNAPPED SPRING				pivot bolts and wheel nuts. Greased all components.	01/12/2023	972972	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	BARRY MANEY - 3	TRAILER
			A/HRS BREAKDOWN - EBS & SCALES PLUG PULLED OUT																	
			Inspect wiring loom going from A to B trailer. Found EBS & scales plugs has wiring pulled out of plug.																	
			Remove and replaced EBS plug, tidy up wiring loom. Repair scales plug following day.																	
			Truck returned to workshop next day, cut old plug out and joined in new. Tidy wiring & checked sclaes																	
T470	Myrtleford - Workshop	Elect\ELECT P&W	all workine okav.					16/11/2023	973742	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Albury Workshop	TRAILER
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					16/11/2023	974159	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist																	
T470	Myrtleford - Workshop	VehService\DS	PO# L082265	VehService\DS				16/11/2023	974159	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Tyres\TP7+8	Tyre Position 7 + 8					09/11/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Albury Workshop	TRAILER
T470	Myrtleford - Workshop	Chassis\AIR TANKS	AIR TANK LOOSE.					01/11/2023	936245	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Brakes\BRAKE ADJ	CAN WE GET OPERATION OF BRAKES CHECKED ON BOTH PARK AND FOOT, HAD A WHEEL ABLE TO TURN WHEN TORQUING WHEEL NUTS.					01/11/2023	936245	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Susp\SPRING HANG	CRACKED SUSPENSION HANGER RH MIDDLE.					01/11/2023	936245	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					01/11/2023	96681	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist																	
T470	Myrtleford - Workshop	VehService\DS	PO# L081992	VehService\DS				01/11/2023	96681	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Chassis\BOLSTER	THE CHAIN THAT HOLDS THE FRONT BOLSTER UP WHERE IT ATTACHES TO CHASSIS ON L/H SIDE NEEDS FIXING.		refer job 180865			01/11/2023		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Elect\ELECT P&W	ONE NUMBER PLATE LIGHT NOT WORKING.		refer job 180865			01/11/2023		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	BARRY MANEY - 3	TRAILER
			LH CHAIN ANCHOR POINT FOR FIRST BOLSTER BROKEN - Inspected trailer & found anchor point																	
T470	Myrtleford - Workshop	Chassis\BOLSTER	to be broken. Cut steel to fit the broken axo. Weld the components & paint anchor point.					01/11/2023	955454	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Albury Workshop	TRAILER
T470	Myrtleford - Workshop	Tyres\Punct	5					31/10/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Albury Workshop	TRAILER
T470	Myrtleford - Workshop	Tyres\Punct	5					26/10/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Albury Workshop	TRAILER
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					13/10/2023	955454	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist																	
T470	Myrtleford - Workshop	VehService\DS	PO# L081604	VehService\DS				13/10/2023	955454	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Tyres\Punct	8					04/10/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Albury Workshop	TRAILER
T470	Myrtleford - Workshop	Tyres\FITMENT	3+5+7					27/09/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Albury Workshop	TRAILER
			LOOSE BALLRACE BOLTS - Disconnect A and B trailer, found damaged air line to turntable lock.																	
			Cut out damaged section and rejoined. Unlock turntable and lift, tension loose ball race bolts to spec.																	
T470	Myrtleford - Workshop	Chassis\FIFTH WHEE	Modified deckplate to unlock turntable mechanism. Lowered turntable and reconnect trailers.					27/09/2023	946331	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Albury Workshop	TRAILER
			D Service As Per Attached Checklist																	
T470	Myrtleford - Workshop	VehService\DS	Barry Maney PO# L081260	VehService\DS				25/09/2023	1076050	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Wodonga Workshop	TRAILER
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					25/09/2023	1076050	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Wodonga Workshop	TRAILER
T470	Myrtleford - Workshop	Susp\AIR FITTIN	AIR TANK - Tightened loose bolts. Cut off and replace two bolts, tightened.					14/09/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Albury Workshop	TRAILER
			CHECK BRAKES, ABLE TO TURN WHEEL WHEN TORQUING WHEEL NUTS - carry out brake roller																	
			test, all passed. LH middle would not lock park brake, faulty booster. Remove & replace booster. Cut rod																	
T470	Myrtleford - Workshop	Brakes\BOOSTER	to length, adjust brakes. Re-brake roll test.					14/09/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Albury Workshop	TRAILER
T470	Myrtleford - Workshop	Susp\SPRING HANG	CRACKED SUSPENSION HANGER RHM -lift axle, remove wheels. Clean surfaces, grind out crack welded and painted area.					14/09/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Albury Workshop	TRAILER
T470	Myrtleford - Workshop	Susp\SHOCK ABS	REPAIR SHOCKERS					14/09/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Albury Workshop	TRAILER
T470	Myrtleford - Workshop	Body\MUDGUARDS	WELD CRACK ON M/GUARD BRACKET - welded bracket, painted.					14/09/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Albury Workshop	TRAILER
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					13/09/2023	936245	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist																	
T470	Myrtleford - Workshop	VehService\DS	Barry Maney PO# L080982	VehService\DS				13/09/2023	936245	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Wodonga Workshop	TRAILER
T470	Myrtleford - Workshop	Tyres\FITMENT	7					06/09/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Albury Workshop	TRAILER
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					31/08/2023	926181	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist																	
T470	Myrtleford - Workshop	VehService\DS	Barry Maney PO# L080567	VehService\DS				31/08/2023	926181	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Wodonga Workshop	TRAILER
T470	Myrtleford - Workshop	Tyres\FITMENT	11					28/08/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Albury Workshop	TRAILER
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					22/08/2023	918417	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Wodonga Workshop	TRAILER
							RH TAIL LIGHT N/W													
							RH taillight n/w remove old lenses found corroded wiring, cut out and replace fit new connector,													
T470	Myrtleford - Workshop	Elect\TAIL LIGHT	RH OUTER TAIL LIGHT NOT WORK PROPERLY.				test operation, all okay.	22/08/2023	918417	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Wodonga Workshop	TRAILER
T470	Myrtleford - Workshop	Elect\ELECT P&W	CAN WIRING FOR LIGHTS BE CHECKED WHERE IT COMES THROUGH THE DECK PLATE IN FRONT OF THE TURNTABLE AND UP INTO THE B TRAILER. HAD TO TIE					22/08/2023	918417	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist																	
T470	Myrtleford - Workshop	VehService\DS	Barry Maney PO# L080451	VehService\DS				22/08/2023	918417	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Wodonga Workshop	TRAILER
T470	Myrtleford - Workshop	DrivLine\WHL HUB	HOBOMETER NOT WORKING.new hubo fitted on D service refer invoice 367948. HOBOMETER NOT WORKING.					22/08/2023	910727	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					11/08/2023	910727	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist																	
T470	Myrtleford - Workshop	VehService\DS	Barry Maney PO# L080211	VehService\DS				11/08/2023	910727	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Wodonga Workshop	TRAILER
T470	Myrtleford - Workshop	Tyres\TP3+4	Tyre Position 3 + 4					09/08/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Albury Workshop	TRAILER
T470	Myrtleford - Workshop	Tyres\TP5+6	Tyre Position 5 + 6					09/08/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Albury Workshop	TRAILER
T470	Myrtleford - Workshop	Tyres\TP3+4	Tyre Position 3 + 4					08/08/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Albury Workshop	TRAILER
T470	Myrtleford - Workshop	Tyres\TP06	pucture					08/08/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Albury Workshop	TRAILER
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					28/07/2023	910727	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist																	
T470	Myrtleford - Workshop	VehService\DS	Barry Maney PO# L079908	VehService\DS				28/07/2023	910727	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Wodonga Workshop	TRAILER
T470	Myrtleford - Workshop	Tyres\TP9+10	Tyre Position 9 + 10					27/07/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Albury Workshop	TRAILER
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					05/07/2023	897463	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Wodonga Workshop	TRAILER
T470	Myrtleford - Workshop	Elect\ELECT P&W	CLEARANCE LIGHT R/H SIDE OF LIGHT BAR NOT WORKING.					05/07/2023	897463	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist																	
T470	Myrtleford - Workshop	VehService\DS	Barry Maney PO# L079400	VehService\DS				05/07/2023	897463	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Wodonga Workshop	TRAILER
T470	Myrtleford - Workshop	Tyres\TP1+2	Tyre Position 1 + 2					03/07/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Albury Workshop	TRAILER
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					23/06/2023	888950	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist																	
T470	Myrtleford - Workshop	VehService\DS	Barry Manv PO# L079135	VehService\DS				23/06/2023	888950	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Wodonga Workshop	TRAILER
T470	Myrtleford - Workshop	Elect\TAIL LIGHT	Tail lights not working					15/06/2023	882941	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Albury Workshop	TRAILER
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					10/06/2023	881281	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist																	
T470	Myrtleford - Workshop	VehService\DS	PO# L078868	VehService\DS				10/06/2023	881281	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Body\STRAPS	Rewald chains into place					01/06/2023	873378	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Albury Workshop	TRAILER
T470	Myrtleford - Workshop	Tyres\TP1+2	Tyre Position 1 + 2					01/06/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Albury Workshop	TRAILER
T470	Myrtleford - Workshop	Tyres\TP11+12	Tyre Position 11 + 12					01/06/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Albury Workshop	TRAILER
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					28/05/2023	871003	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist																	
T470	Myrtleford - Workshop	VehService\DS	PO# L078637	VehService\DS				28/05/2023	871003	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Steering\WHEEL ALGN	carried out wheel alignment, alignment plate was cracked. Supply and fit new plate					16/05/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Albury Workshop	TRAILER
T470	Wodonga - Workshop	Chassis\SKID PLATE	SKID PLATE PIVOT PINS CRACKED AGAIN AROUND WHERE PIN WELDS INTO KEEPER PLATE.					09/05/2023	1076050	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Wodonga Workshop	TRAILER
T470	Wodonga - Workshop	Elect\BRK LIGHT	INNER BRAKE LIGHT RH SIDE NOT WORKING.					09/05/2023	1076050	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist																	
T470	Myrtleford - Workshop	VehService\DS	Barry Maney PO# L078196	VehService\DS				08/05/2023	1076050	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Wodonga Workshop	TRAILER
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					08/05/2023	1076050	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Wodonga Workshop	TRAILER
T470	Myrtleford - Workshop	Chassis\FIFTH WHEE	MAKE NEW PN UP TO GO THROUGH TURNTABLE PIVOT.					08/05/2023	1076050	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Wodonga Workshop	TRAILER
T470	Myrtleford - Workshop	DrivLine\WHL HUB	CAN'T READ HUBOMETER.					08/05/2023	1076050	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Wodonga Workshop	TRAILER
T470	Myrtleford - Workshop	Chassis\FIFTH WHEE	PIN TO GO THROUGH TURNTABLE PIVOT RHS.					08/05/2023	1076050	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Wodonga Workshop	TRAILER
T470	Myrtleford - Workshop	Tyres\TP3+4	Tyre Position 3 + 4					03/05/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Albury Workshop	TRAILER
T470	Myrtleford - Workshop	Tyres\TP5+6	Tyre Position 5 + 6					03/05/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Albury Workshop	TRAILER
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					19/04/2023	849357	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Wodonga Workshop	TRAILER
T470	Myrtleford - Workshop	Chassis\FIFTH WHEE	MAKE NEW PN UP TO GO THROUGH TURNTABLE PIVOT.					19/04/2023	849357	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Wodonga Workshop	TRAILER
T470	Myrtleford - Workshop	DrivLine\WHL HUB	CAN'T READ HUBOMETER.					19/04/2023	849357	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Wodonga Workshop	TRAILER
T470	Myrtleford - Workshop	Chassis\FIFTH WHEE	PIN TO GO THROUGH TURNTABLE PIVOT RHS.					19/04/2023	849357	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist																	
T470	Myrtleford - Workshop	VehService\DS	Barry Maney PO# L077838	VehService\DS				19/04/2023	849357	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Wodonga Workshop	TRAILER
			Remove & crack test bolster pins																	
			Remove and crack test, results below.																	
			LH1 test ok, RH1 test ok																	
			LH2 test ok, RH2 test ok																	
			LH3 test ok, RH3 test ok																	
T470	Myrtleford - Workshop	Chassis\BOLSTER	Turned all bolster pins around so facing out					07/04/2023	838629	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Albury Workshop	TRAILER
			Repack & replace worn bearings																	
			Rear axle. Removed wheels, clean bearings & hub assembly. Repack bearings, replace seals and spacers. Refit wheels & hub. Front axle. Remove wheels,																	
T470	Myrtleford - Workshop	Steering\WHEEL BRGS	bearings were worn. Hit out old cones and fit new ones. Repack new bearings and replace seals					24/03/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Albury Workshop	TRAILER
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					23/03/2023	837052	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist																	
T470	Myrtleford - Workshop	VehService\DS	Barry Manev PO# L077400	VehService\DS				23/03/2023	837052	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Wodonga Workshop	TRAILER
T470	Myrtleford - Workshop	Tyres\TP9+10	Tyre Position 9 + 10					17/03/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Albury Workshop	TRAILER
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					15/03/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Wodonga Workshop	TRAILER
T470	Myrtleford - Workshop	Chassis\CONSUMABLE	L/H BOLT WHERE TRAILER FOLDS BEHIND FIRST BOLSTER MISSING.					15/03/2023		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist																	
T470	Myrtleford - Workshop	VehService\DS	Barry Maney PO# L077203	VehService\DS				15/03/2023		Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Wodonga Workshop	TRAILER
T470	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP				15/03/2023		PreventativeMaintenance	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Wodonga Workshop	TRAILER
T470	Myrtleford - Workshop	Tyres\Re-Tor	4 & 5					07/03/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Albury Workshop	TRAILER
T470	Myrtleford - Workshop	Tyres\TP3+4	Tyre Position 3 + 4					04/03/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Albury Workshop	TRAILER
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					25/02/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist																	
T470	Myrtleford - Workshop	VehService\DS	PO# L076912	VehService\DS				25/02/2023		Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	BARRY MANEY - 3	TRAILER
T470	Myrtleford - Workshop	Tyres\TP1+2	Tyre Position 1 + 2					17/02/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Albury Workshop	TRAILER
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					15/02/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist																	
T470	Myrtleford - Workshop	VehService\DS	PO# L076683	VehService\DS				15/02/2023		Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	BARRY MANEY - 3	TRAILER
			Broken Shocker Mount & Saddle																	
			Lift axle and support spring. Removed mounting plate, cracked in half. Fit new base and tensioned studs. Fit new shocker tensioned. Also replaced LHM																	
T470	Myrtleford - Workshop	Susp\SHOCK ABS	shocker was worn					11/02/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Albury Workshop	TRAILER
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					01/02/2023	620982	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist																	
T470	Myrtleford - Workshop	VehService\DS	PO# L076408	VehService\DS				01/02/2023	620982	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	BARRY MANEY - 3	TRAILER

				Barry Maney - Repplace Ballrace																	
				Fit new ball race to base plate. Found to be bent, arranged new base plate. Removed ballrace, installed new baseplate and firt new ball																	
T470	Albury - Workshop	Chassis\FIFTH WHEE	Replace link member bass plate and pins and bushes & also fit new ball race and bolts (which barry maney have in stock)		race. ** Charaed Kennedy's for new base olate repairs		12/01/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Albury Workshop		TRAILER	
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				13/12/2022	608713	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Wodonga Workshop		TRAILER	
			D Service As Per Attached Checklist																		
T470	Myrtleford - Workshop	VehService\DS	Barrv Maney PO# L075691	VehService\DS			13/12/2022	608713	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Wodonga Workshop		TRAILER	
T470	Myrtleford - Workshop	Tyres\TP3+4	Tyre Position 3 + 4				09/12/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Albury Workshop		TRAILER	
			no trailer lights																		
			sublet repainer attended after hours call out.																		
T470	Myrtleford - Workshop	Elect\TRL LIGHTS	Traced wirine found short. repaired & recheck found second short in wirine across rear liaht bar. repaired. okav				08/12/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Albury Workshop		TRAILER	
T470	Wodonga - Workshop	Brakes\AIR LEAK	AIR LEAK AROUND FRONT AXLE AREA ON FOOT BRAKE APPLICATION.				03/12/2022	603604	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Wodonga Workshop		TRAILER	
T470	Wodonga - Workshop	Elect\ELECT P&W	RH NUMBER PLATE LIGHT N/W.				03/12/2022	603604	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Wodonga Workshop		TRAILER	
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				02/12/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Wodonga Workshop		TRAILER	
			D Service As Per Attached Checklist																		
T470	Myrtleford - Workshop	VehService\DS	Barry Maney PO# L075475	VehService\DS			02/12/2022		Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Wodonga Workshop		TRAILER	
T470	Myrtleford - Workshop	Tyres\TP11+12	Tyre Position 11 + 12				19/11/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Albury Workshop		TRAILER	
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				17/11/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Wodonga Workshop		TRAILER	
			D Service As Per Attached Checklist																		
T470	Myrtleford - Workshop	VehService\DS	Barry Maney PO# L075359	VehService\DS			17/11/2022		Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Wodonga Workshop		TRAILER	
			REPLACE SKID PLATE PIVOT PINS & BUSHES																		
T470	Myrtleford - Workshop	Chassis\FIFTH WHEE	KENNEDY SUPPLY PARTS		Barry Maney - Reolace ball race & Turntable too		09/11/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Albury Workshop		TRAILER	
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				08/11/2022	SB3107	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Wodonga Workshop		TRAILER	
			D Service As Per Attached Checklist																		
T470	Myrtleford - Workshop	VehService\DS	Barrv Maney PO# L074986	VehService\DS			08/11/2022	SB3107	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Wodonga Workshop		TRAILER	
T470	Myrtleford - Workshop	Elect\ELECT P&W	SECOND BOLSTER LIGHTS WORK SOMETIMES. SECOND BOLSTER LIGHTSWORK SOMETIMES.				03/11/2022		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop		TRAILER	
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				29/10/2022	576372	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Wodonga Workshop		TRAILER	
T470	Myrtleford - Workshop	Chassis\WINCH/STRP	ALL STRAPS NEED REPLACING. FREYED AND DAMAGED- NOT COMPLIANT.		SCOTTY SAID THEY ARE ALL OK.		29/10/2022	576372	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Wodonga Workshop		TRAILER	
T470	Myrtleford - Workshop	Chassis\EXTE TU	NEED NEW BOLT IN FRONT OF 2ND BINDER.		COULDN'T FAULT. OK.		29/10/2022	576372	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Wodonga Workshop		TRAILER	
			D Service As Per Attached Checklist																		
T470	Myrtleford - Workshop	VehService\DS	Barry Maney PO# L074779	VehService\DS			29/10/2022	576372	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Wodonga Workshop		TRAILER	
T470	Myrtleford - Workshop	Tyres\TP1+2	SUPPLY AND FIT 4 TYRES				19/10/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop		TRAILER	
T470	Myrtleford - Workshop	Tyres\TP3+4	Tyre Position 3 + 4				19/10/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop		TRAILER	
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				07/10/2022	615655	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Wodonga Workshop		TRAILER	
			D Service As Per Attached Checklist																		
T470	Myrtleford - Workshop	VehService\DS	Barrv Maney PO# L074474	VehService\DS			07/10/2022	615655	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Wodonga Workshop		TRAILER	
T470	Myrtleford - Workshop	Tyres\TP9+10	SUPPLY AND FIT 2TYRES				29/09/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop		TRAILER	
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				20/09/2022	553765	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Wodonga Workshop		TRAILER	
			D Service As Per Attached Checklist																		
T470	Myrtleford - Workshop	VehService\DS	Barrv Maney PO# L074165	VehService\DS			20/09/2022	553765	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Wodonga Workshop		TRAILER	
T470	Myrtleford - Workshop	Tyres\We-Tor	Re-Torque				13/09/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop		TRAILER	
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				25/08/2022	536111	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Wodonga Workshop		TRAILER	
			D Service As Per Attached Checklist																		
T470	Myrtleford - Workshop	VehService\DS	Barry Maney PO# L073662	VehService\DS			25/08/2022	536111	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Wodonga Workshop		TRAILER	
T470	Myrtleford - Workshop	Tyres\We-Tor	Retension all wheels - loose wheel nuts POS 9,10,11,12				25/08/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop		TRAILER	
T470	Myrtleford - Workshop	Susp\Torque Rod	noted at service needed pivot bushes & pivot bushes wear plates, replaced 2 pivot bushes & 4 wear plates cut out old ones & weld new ones in				19/08/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	BARRY MANEY - 3		TRAILER	
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				11/08/2022	529226	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Wodonga Workshop		TRAILER	
			D Service As Per Attached Checklist																		
T470	Myrtleford - Workshop	VehService\DS	Barry Maney PO# L073408	VehService\DS			11/08/2022	529226	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Wodonga Workshop		TRAILER	
T470	Myrtleford - Workshop	Tyres\TP5+6	supply and fit 2tyres				11/08/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop		TRAILER	
T470	Myrtleford - Workshop	Tyres\TP3+4	supply and fit 2 tyres				09/08/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop		TRAILER	
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				03/08/2022	521997	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Wodonga Workshop		TRAILER	
T470	Myrtleford - Workshop	Elect\ELECT P&W	LIGHTS ON 2ND BOLSTER GO DULL THEN BRIGHT.				03/08/2022	521997	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Wodonga Workshop		TRAILER	
T470	Myrtleford - Workshop	Elect\ELECT P&W	LIGHT ON L/H OF LIGHT BAR NOT WORKING.				03/08/2022	521997	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Wodonga Workshop		TRAILER	
T470	Myrtleford - Workshop	Elect\TAIL LIGHT	TAIL LIGHT OUT RH SIDE LIGHT BAR.				03/08/2022	521997	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Wodonga Workshop		TRAILER	
T470	Myrtleford - Workshop	Elect\ELECT P&W	LH TAIL LIGHTS AND CLEARANCE LIGHT ON LIGHT BAR.				03/08/2022	521997	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Wodonga Workshop		TRAILER	
			D Service As Per Attached Checklist																		
T470	Myrtleford - Workshop	VehService\DS	Barrv Maney PO# L073283	VehService\DS			03/08/2022	521997	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Wodonga Workshop		TRAILER	
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				19/07/2022	509439	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Wodonga Workshop		TRAILER	
			D Service As Per Attached Checklist																		
T470	Myrtleford - Workshop	VehService\DS	Barrv Maney PO# L072074	VehService\DS			19/07/2022	509439	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Wodonga Workshop		TRAILER	
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				05/07/2022	502746	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Wodonga Workshop		TRAILER	
			D Service As Per Attached Checklist																		
T470	Myrtleford - Workshop	VehService\DS	Barrv Maney PO# L072473	VehService\DS			05/07/2022	502746	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Wodonga Workshop		TRAILER	
T470	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				21/06/2022	493931	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Wodonga Workshop		TRAILER	
T470	Wodonga - Workshop	Tyres	CHECK TYRES. CHANGE TYRES WHERE NEEDED.				21/06/2022	493931	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Wodonga Workshop		TRAILER	
			D Service As Per Attached Checklist																		
T470	Wodonga - Workshop	VehService\DS	Barrv Maney PO# L072476	VehService\DS			21/06/2022	493931	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Wodonga Workshop		TRAILER	
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				07/06/2022	481511	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Wodonga Workshop		TRAILER	
			CHECK TYRES.																		
T470	Myrtleford - Workshop	Tyres	CHANGE TYRES WHERE NEEDED.				07/06/2022	481511	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Wodonga Workshop		TRAILER	
			D Service As Per Attached Checklist																		
T470	Myrtleford - Workshop	VehService\DS	Barry Maney PO# L072268	VehService\DS			07/06/2022	481511	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Wodonga Workshop		TRAILER	
T470	Myrtleford - Workshop	Tyres\TP1+2	supply and fit 2tyres				01/06/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop		TRAILER	
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				14/05/2022	468554	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Wodonga Workshop		TRAILER	
			D Service As Per Attached Checklist																		
T470	Myrtleford - Workshop	VehService\DS	Barry Maney PO# L071778	VehService\DS			14/05/2022	468554	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Wodonga Workshop		TRAILER	
T470	Myrtleford - Workshop	Tyres\FITMENT	Call Out Bolt on 2 Tyres POS 11 & 12				04/05/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop		TRAILER	
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				03/05/2022	467870	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Wodonga Workshop		TRAILER	
			D Service As Per Attached Checklist																		
T470	Myrtleford - Workshop	VehService\DS	Barry Maney PO# L071569	VehService\DS			03/05/2022	467870	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Wodonga Workshop		TRAILER	
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				15/04/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Wodonga Workshop		TRAILER	
			D Service As Per Attached Checklist																		
T470	Myrtleford - Workshop	VehService\DS	PO # L071318	VehService\DS			15/04/2022		Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Wodonga Workshop		TRAILER	
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				07/04/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Wodonga Workshop		TRAILER	
			D Service As Per Attached Checklist																		
T470	Myrtleford - Workshop	VehService\DS	Barry Maney PO# L071111	VehService\DS			07/04/2022		Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Wodonga Workshop		TRAILER	
T470	Myrtleford - Workshop	Tyres\TP3+4	SUPPLY AND FIT 2TYRES				07/04/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop		TRAILER	
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				23/03/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Wodonga Workshop		TRAILER	
			D Service As Per Attached Checklist																		
T470	Myrtleford - Workshop	VehService\DS	Barry Maney PO# L070842	VehService\DS			23/03/2022		Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Wodonga Workshop		TRAILER	
T470	Myrtleford - Workshop	Tyres\TP7+8	supply and fit 2tyres				17/03/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop		TRAILER	
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				10/03/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Wodonga Workshop		TRAILER	
			D Service As Per Attached Checklist																		
T470	Myrtleford - Workshop	VehService\DS	Barry Maney PO# L070611	VehService\DS			10/03/2022		Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Wodonga Workshop		TRAILER	
T470	Myrtleford - Workshop	Tyres\TP9+10	supply and fit 4 tyres				02/03/2022	65533	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop		TRAILER	
T470	Myrtleford - Workshop	Tyres\TP11+12	Tyre Position 11 + 12				02/03/2022	65533	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop		TRAILER	
			Annual inspection As Per Checklist																		
T470	Myrtleford - Workshop	Insp\ANN INSP	PO # L070330	Insp\ANN INSP			24/02/2022		PreventativeMaintenance	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Wodonga Workshop		TRAILER	
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				24/02/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Wodonga Workshop		TRAILER	
			D Service As Per Attached Checklist																		
T470	Myrtleford - Workshop	VehService\DS	PO # L070329	VehService\DS			24/02/2022		Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Wodonga Workshop		TRAILER	
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				11/02/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Wodonga Workshop		TRAILER	
			D Service As Per Attached Checklist																		
T470	Myrtleford - Workshop	VehService\DS	PO # L070109	VehService\DS			11/02/2022		Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Wodonga Workshop		TRAILER	
T470	Myrtleford - Workshop	Chassis\BOLSTER	Weld front bolster pin				11/02/2022	478124	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop		TRAILER	
T470	Myrtleford - Workshop	Susp\AIR BAG	Call out to replace blown air bag				09/02/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop		TRAILER	
T470	Myrtleford - Workshop	Tyres\TP3+4	fit 2 runouts				29/01/2022	447404	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop		TRAILER	
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				26/01/2022	446900	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop		TRAILER	
T470	Myrtleford - Workshop	Elect\TRL LIGHTS	tail light				26/01/2022	446900	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop		TRAILER	
			D Service As Per Attached Checklist																		
T470	Myrtleford - Workshop	VehService\DS	PO# L069778	VehService\DS			26/01/2022	446900	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop		TRAILER	
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				11/01/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	BARRY MANEY - 3		TRAILER	
			D Service As Per Attached Checklist																		
T470	Myrtleford - Workshop	VehService\DS	O/N L 12869	VehService\DS			11/01/2022		Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	BARRY MANEY - 3		TRAILER	
T470	Myrtleford - Workshop	Body\WHL HUB	replace Hubcap; clean and repack bearings				08/01/2022	437181	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop		TRAILER	
T470	Myrtleford - Workshop	Tyres\TP1+2	supply and fit 2tyres				05/01/2022	435829	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop		TRAILER	
			LH front pivot bush																		
T470	Myrtleford - Workshop	Susp\DAMAGE	L12853				24/12/2021	435820	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop		TRAILER	
T470	Myrtleford - Workshop	DrivLine\WHEEL BRGS	adjust 5 of the 6 wheel bearing				24/12/2021	435820	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop		TRAILER	
T470	Myrtleford - Workshop	Tyres\TP06	fit runout				16/12/2021		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop		TRAILER	
T470	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				10/12/2021	430484	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	BARRY MANEY - 3		TRAILER	
			D Service As Per Attached Checklist																		
T470	Wodonga - Workshop	VehService\DS	O/N L12776	VehService\DS			10/12/2021	430484	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	BARRY MANEY - 3		TRAILER	
T470	Myrtleford - Workshop	Body\MOUNTS	bolts in trailer pivot				26/11/2021	419700	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop		TRAILER	
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		trailer service, replaced missing cross member boltsx3 kinked service brake line cut fitting off replaced with new		25/11/2021	420129	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	BARRY MANEY - 3		TRAILER	
			D Service As Per Attached Checklist																		
T470	Myrtleford - Workshop	VehService\DS	O/N L12670	VehService\DS			25/11/2021	420129	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	BARRY MANEY - 3		TRAILER	
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				12/11/2021	409635	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	BARRY MANEY - 3		TRAILER	
			D Service As Per Attached Checklist																		
T470	Myrtleford - Workshop	VehService\DS	O/N L12584	VehService\DS			12/11/2021	409635	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	BARRY MANEY - 3		TRAILER	
			D Service As Per Attached Checklist																		
T470	Myrtleford - Workshop	VehService\DS	ORDER # L12508	VehService\DS			30/10/2021	398593	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	BARRY MANEY - 3		TRAILER	
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				30/10/2021	398593	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	BARRY MANEY - 3		TRAILER	
			airbag LH rear axle																		
T470	Myrtleford - Workshop	Susp\DAMAGE	cut bolts off and reolace fittina also				23/10/2021	393183	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop		TRAILER	
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				19/10/2021	389805	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	BARRY MANEY - 3		TRAILER	
			D Service As Per Attached Checklist																		
T470	Myrtleford - Workshop	VehService\DS	O/N L12431	VehService\DS			19/10/2021	389805	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	BARRY MANEY - 3		TRAILER	
T470	Myrtleford - Workshop	Tyres\TP3+4	supply and fit 2 tyres				18/10/2021	388586	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop		TRAILER	
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				02/10/2021	379252	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	BARRY MANEY - 3		TRAILER	
			D Service As Per Attached Checklist																		
T470	Myrtleford - Workshop	VehService\DS	O/N L12347	VehService\DS			02/10/2021	379252	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	BARRY MANEY - 3		TRAILER	
T470	Myrtleford - Workshop	Chassis\DAMAGE	gauge out, grind weld up turntable pivot on returning plates				28/09/2021	374688	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop		TRAILER	
T470	Myrtleford - Workshop	Brakes\DAMAGE	LH wheel missing hub damaged, brakes low rear axle, replaced				11/09/2021	368216	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop		TRAILER	
T470	Myrtleford - Workshop	Body\WHL HUB	adjust all other wheel bearings				11/09/2021	368216	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop		TRAILER	
T470	Myrtleford - Workshop	Elect\TRL LIGHTS	work light n/w, replace and repair wiring				11/09/2021	368216	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop		TRAILER	
T470	Myrtleford - Workshop	Tyres\CLEANSKIN	Drop off 2 new tyres and rims to Maneys				09/09/2021		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop		TRAILER	
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				01/09/2021	368216	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	BARRY MANEY - 3		TRAILER	

			D Service As Per Attached Checklist																
T470	Myrtleford - Workshop	VehServicel\DS	O/N L12164	VehService\DS			01/09/2021	368216	Service	Comoleted	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
T470	Myrtleford - Workshop	Tyres\TP7+8	Supply and fit 4 tyres				26/08/2021	362560	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Tyres\TP9+10	Tyre Position 9 + 10				26/08/2021	362560	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				20/08/2021	358837	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
			D Service As Per Attached Checklist																
T470	Myrtleford - Workshop	VehServicel\DS	O/N L12098	VehService\DS			20/08/2021	358837	Service	Comoleted	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
T470	Myrtleford - Workshop	Body\DAMAGE	repair chassis covers and mounts				17/08/2021	355216	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Tyres\TP11+12	Supply and fit 2tyres				08/08/2021	350014	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Myrtleford Workshop	TRAILER			
			EBS light on																
			connected tester and fault code																
T470	Myrtleford - Workshop	Brakes\EBS Kit	RH rear axle sensor R&R wheel and hub to replace sensor				28/07/2021	343905	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes\BOOSTER	replace RHR brake booster				27/07/2021	392861	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				23/07/2021	342229	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
			D Service As Per Attached Checklist																
T470	Myrtleford - Workshop	VehServicel\DS	ORDER # L11930	VehService\DS			23/07/2021	342229	Service	Comoleted	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
			brakes hanging on both trailers, slow to release																
T470	Myrtleford - Workshop	Brakes\AIR LEAK	spring release park brake replace valve				15/07/2021	336326	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Tyres\TP1+2	replace 2 tyres				14/07/2021		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Wodonga Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				08/07/2021	332890	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
T470	Myrtleford - Workshop	VehServicel\DS	D Service As Per Attached Checklist	VehService\DS	O/N L11830		08/07/2021	332890	Service	Comoleted	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				24/06/2021		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
			D Service As Per Attached Checklist																
T470	Myrtleford - Workshop	VehServicel\DS	O/N L11713	VehService\DS			24/06/2021		Service	Comoleted	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
T470	Myrtleford - Workshop	Body\MUDGUARDS	replace bracket for rear mudflap and install new mudflap				23/06/2021	333919	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Body\AIR LEAK	air leaks rear axle area				12/06/2021		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Tyres\TP3+4	Supply and fit 2 tyres				12/06/2021	32731	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes\BACK PLATE	replaced all missing backing plate				09/06/2021	324506	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Susp\DAMAGE	pivot bushes replaced RH middle and LH rear				09/06/2021	324506	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Body\WHL HUB	adjust base w/bearings/ check also				09/06/2021	324506	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Susp\HOUSEKEEP	missing bolt airbag				09/06/2021	324506	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				08/06/2021		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
			D Service As Per Attached Checklist																
T470	Myrtleford - Workshop	VehServicel\DS	O/N L11609	VehService\DS			08/06/2021		Service	Comoleted	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				25/05/2021		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
			D Service As Per Attached Checklist																
T470	Myrtleford - Workshop	VehServicel\DS	L11487	VehService\DS			25/05/2021		Service	Comoleted	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
T470	Myrtleford - Workshop	Brakes\BOOSTER	replace broken booster				25/05/2021	313257	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Susp\SPRING PACK	replace LH middle spring and u-bolts				25/05/2021	313257	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Susp\AIR BAG	replace LH middle airbag				25/05/2021	313257	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Susp\AIR BAG	replace RHR airbag (cracked)				25/05/2021	313257	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				12/05/2021		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
T470	Myrtleford - Workshop	VehServicel\DS	D Service As Per Attached Checklist	VehService\DS	L11406		12/05/2021		Service	Comoleted	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				29/04/2021		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
			D Service As Per Attached Checklist																
T470	Myrtleford - Workshop	VehServicel\DS	ORDER # L11277	VehService\DS			29/04/2021		Service	Comoleted	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
T470	Myrtleford - Workshop	Chassis\DAMAGE	repair trailer cracks				17/04/2021		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Tyres\TP08	Fit runout				14/04/2021	285219	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				10/04/2021	284778	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
			D Service As Per Attached Checklist																
T470	Myrtleford - Workshop	VehServicel\DS	L11166	VehService\DS			10/04/2021	284778	Service	Comoleted	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
T470	Myrtleford - Workshop	Susp\SHOCK ABS	Repair Broken U Bolt & Suspension, base plate and Shockers				24/03/2021	272134	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				19/03/2021	272134	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
			D Service As Per Attached Checklist																
T470	Myrtleford - Workshop	VehServicel\DS	Order Number L11092	VehService\DS			19/03/2021	272134	Service	Comoleted	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
T470	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				11/03/2021		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
			D Service As Per Attached Checklist																
T470	Wodonga - Workshop	VehServicel\DS	L10997	VehService\DS			11/03/2021		Service	Comoleted	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
T470	Albury - Workshop	Tyres\TP1+2	Supply and fit 6 tyres				05/03/2021	260779	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Albury Workshop	TRAILER			
T470	Albury - Workshop	Tyres\TP3+4	Tyre Position 3 + 4				05/03/2021	260779	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Albury Workshop	TRAILER			
T470	Albury - Workshop	Tyres\TP11+12	Tyre Position 11 + 12				05/03/2021	260779	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Albury Workshop	TRAILER			
T470	Myrtleford - Workshop	Tyres\TP9+10	replace 2 tyres				23/02/2021	253021	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Wodonga Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				20/02/2021	253020	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
			D Service As Per Attached Checklist																
T470	Myrtleford - Workshop	VehServicel\DS	L10855	VehService\DS			20/02/2021	253020	Service	Comoleted	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
			Annual inspection As Per Checklist																
T470	Myrtleford - Workshop	Insp\ANN INSP	ORDER # L10705	Insp\ANN INSP			02/02/2021	244540	PreventativeMaintenance	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
			D Service As Per Attached Checklist																
T470	Myrtleford - Workshop	VehServicel\DS	ORDER # L10703	VehService\DS			02/02/2021	244540	Service	Comoleted	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				02/02/2021	244540	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
T470	Albury - Workshop	Tyres\TP3+4	Fit 2 Tyres				20/01/2021	239372	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Albury Workshop	TRAILER			
T470	Wodonga - Workshop	Workshop\MOVE ASSET	unload trailer				12/01/2021	153029	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Wodonga Workshop	TRAILER			
T470	Wodonga - Workshop	Workshop\MOVE ASSET	move and split				12/01/2021	153029	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Wodonga Workshop	TRAILER			
T470	Wodonga - Workshop	Workshop\MOVE ASSET	pit (B) 470 back in shed for repairs				12/01/2021	153029	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Wodonga Workshop	TRAILER			
T470	Myrtleford - Workshop	Body\PAINT/REST	prepare, paint trailer bolsters on T470				07/01/2021	106833	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				18/12/2020	233524	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
			D Service As Per Attached Checklist																
T470	Myrtleford - Workshop	VehServicel\DS	L10413	VehService\DS			18/12/2020	233524	Service	Comoleted	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				27/11/2020	224926	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
			D Service As Per Attached Checklist																
T470	Myrtleford - Workshop	VehServicel\DS	order number L10236	VehService\DS			27/11/2020	224926	Service	Comoleted	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				06/11/2020	216008	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
			D Service As Per Attached Checklist																
T470	Myrtleford - Workshop	VehServicel\DS	Order Number L10097	VehService\DS			06/11/2020	216008	Service	Comoleted	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
T470	Myrtleford - Workshop	Brakes\BRK RELINE	relign all 3 axles, shoes, drums, s cams and bushes, clean and repack all wheel bearings				03/11/2020	213372	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				20/10/2020	205714	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
			D Service As Per Attached Checklist																
T470	Myrtleford - Workshop	VehServicel\DS	ORDER # L9957	VehService\DS			20/10/2020	205714	Service	Comoleted	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
T470	Unknown - Unknown	Brakes	Record Check Results As Attached To This Job				02/10/2020	691770	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
			D Service As Per Attached Checklist																
T470	Unknown - Unknown	VehServicel\DS	Order Number L9838	VehService\DS			02/10/2020	691770	Service	Comoleted	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
T470	Myrtleford - Workshop	Susp\AIR BAG	RH middle airbag leaking				23/09/2020		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				17/09/2020	186368	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
			D Service As Per Attached Checklist																
T470	Myrtleford - Workshop	VehServicel\DS	Order Number L9683	VehService\DS			17/09/2020	186368	Service	Comoleted	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				02/09/2020	175947	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
			D Service As Per Attached Checklist																
T470	Myrtleford - Workshop	VehServicel\DS	Order Number # L9568	VehService\DS			02/09/2020	175947	Service	Comoleted	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
T470	Myrtleford - Workshop	Body\DAMAGE	replace damaged rh/guard x bar and paint				20/08/2020		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				20/08/2020	166208	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
			D Service As Per Attached Checklist																
T470	Myrtleford - Workshop	VehServicel\DS	Order Number # L9402	VehService\DS			20/08/2020	166208	Service	Comoleted	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
T470	Myrtleford - Workshop	Brakes\BRK RELINE	RHR brake low - replacd				09/08/2020	158827	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Susp\SUSPENSION	pivot pin LHS missing bolt and worn - needs replacing				09/08/2020	158827	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Chassis\HOUSEKEEP	weld crack near skid plate				09/08/2020	158827	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Myrtleford Workshop	TRAILER			
T470	Wodonga - Workshop	Body\PANELS	1 broken cleat needs re-welding underneath checker plate floor		RR's pre Jan 20 (system clean out) 05/08/20		06/08/2020		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Wodonga Workshop	TRAILER			
T470	Wodonga - Workshop	Elect\SELECT P&W	1 marker light out RHS				06/08/2020		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Wodonga Workshop	TRAILER			
T470	Wodonga - Workshop	Chassis\BOLSTER	2nd bolster passenger side turn around				06/08/2020		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Wodonga Workshop	TRAILER			
T470	Wodonga - Workshop	Body\AIR LEAK	air line/nipple, needs replacing on break control valve where I put 2 hose claps (keeps blowing off)				06/08/2020		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Wodonga Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				05/08/2020	156024	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
			D Service As Per Attached Checklist																
T470	Myrtleford - Workshop	VehServicel\DS	Order Number # L9278	VehService\DS			05/08/2020	156024	Service	Comoleted	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
			remove broken bolster pin collect new pin from plunkett trailers																
T470	Myrtleford - Workshop	Chassis\DAMAGE	cut new pin to correct length install pin loctite bolt				23/07/2020	145717	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				23/07/2020		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
			D Service As Per Attached Checklist																
T470	Myrtleford - Workshop	VehServicel\DS	Order Number # L9162	VehService\DS			23/07/2020		Service	Comoleted	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
T470	Myrtleford - Workshop	Body\PANELS	remove cover over axles and clean area. Prepare the cracks in the cover to be welded. Weld the cracks up and give a coat of paint. Refit cover with new bolt				18/07/2020	143031	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Body\MUDGUARDS	tighten bracket that holds the mudguard to the chassis				18/07/2020	143031	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice				10/07/2020	521921	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice				10/07/2020	521921	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Tyres\SCRAP TYRE	Job Added From Invoice				10/07/2020	521921	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				09/07/2020		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
			D Service As Per Attached Checklist																
T470	Myrtleford - Workshop	VehServicel\DS	Order Number # L9062	VehService\DS			09/07/2020		Service	Comoleted	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				25/06/2020	126125	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
			D Service As Per Attached Checklist																
T470	Myrtleford - Workshop	VehServicel\DS	Order Number # L8922	VehService\DS			25/06/2020	126125	Service	Comoleted	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				11/06/2020	117793	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
			D Service As Per Attached Checklist																
T470	Myrtleford - Workshop	VehServicel\DS	Order Number # L 8812	VehService\DS			11/06/2020	117793	Service	Comoleted	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				22/05/2020	106600	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
			D Service As Per Attached Checklist																
T470	Myrtleford - Workshop	VehServicel\DS	ORDER # L8631	VehService\DS			22/05/2020	106600	Service	Comoleted	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
			tail light flickering on L/H side A Trailer #470																
			open up male bullet terminals, clean and plug open in on outer tail light																
T470	Myrtleford - Workshop	Elect\TRL LIGHTS	replace alue with bullet terminals on inner tail liiht (back wire broken off at oluel				19/05/2020	103986	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Chassis\WINCH/STRP	change pos 1 binder strap				08/05/2020	97550	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				07/05/2020	99060	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
			D Service As Per Attached Checklist																
T470	Myrtleford - Workshop	VehServicel\DS	ORDER # L8496	VehService\DS			07/05/2020	99060	Service	Comoleted	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				22/04/2020	87362	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
			D Service As Per Attached Checklist																
T470	Myrtleford - Workshop	VehServicel\DS	Order number # L 8364	VehService\DS			22/04/2020	87362	Service	Comoleted	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				03/04/2020	74390	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
			D Service As Per Attached Checklist																
T470	Myrtleford - Workshop	VehServicel\DS	Order Number # L8260	VehService\DS			03/04/2020	74390	Service	Comoleted	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				20/03/2020	66976	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	789575	BARRY MANEY - 3	TRAILER			

			D Service As Per Attached Checklist																
T470	Myrtleford - Workshop	VehService\DS	Order Number # L8133	VehService\DS			20/03/2020	66976	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	BARRY MANEY - 3	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				06/03/2020	57133	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	BARRY MANEY - 3	TRAILER			
			D Service As Per Attached Checklist																
T470	Myrtleford - Workshop	VehService\DS	Order number # L8037	VehService\DS			06/03/2020	57133	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	BARRY MANEY - 3	TRAILER			
			pull truck over put a cut cable ties holding mudguard bracket in position. Hold bracket in position and tack. Make sure it was reasonably square then																
			welded in place. Bracket was on LHS between the middle and rear axle.																
T470	Myrtleford - Workshop	Body\MOUNTS	When in for service will require whole bracket to be removed and fully welded properly as couldn't get to all sides.				05/03/2020	54413	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Body\MUDGUARDS	repair broken mudguard bracket u-bolt				27/02/2020	49405	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				21/02/2020	38168	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	BARRY MANEY - 3	TRAILER			
			D Service As Per Attached Checklist																
T470	Myrtleford - Workshop	VehService\DS	Order Number # L 7909	VehService\DS			21/02/2020	38168	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	BARRY MANEY - 3	TRAILER			
T470	Myrtleford - Workshop	Body\PANELS	remove and repair cracked cover over chassis				07/02/2020	35518	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				07/02/2020		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	BARRY MANEY - 3	TRAILER			
			D Service As Per Attached Checklist																
T470	Myrtleford - Workshop	VehService\DS	Order number # L 7822	VehService\DS			07/02/2020		Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	BARRY MANEY - 3	TRAILER			
			fault find broken wire in scales loom from trailer to B trailer																
			found broken wire at scales plug at channel 2 slave																
			rejoined wire to plug with solder																
T470	Myrtleford - Workshop	Elect\ELECT P&W	channel 3 scales operational aaain				01/02/2020	31700	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Elect\TRL LIGHTS	repair lights				31/01/2020		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	Myrtleford Workshop	TRAILER			
			Annual Inspection As Per Checklist																
T470	Myrtleford - Workshop	Insp\ANN INSP	ORDER # L7702	Insp\ANN INSP			25/01/2020	126377	PreventativeMaintenance	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	BARRY MANEY - 3	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				25/01/2020	28673	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	BARRY MANEY - 3	TRAILER			
			D Service As Per Attached Checklist																
T470	Myrtleford - Workshop	VehService\DS	ORDER # L7700	VehService\DS			25/01/2020	28673	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	BARRY MANEY - 3	TRAILER			
T470	Myrtleford - Workshop	Body\MUDGUARDS	replace A trailer 1st axle mudguard x1				21/01/2020	24621	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				09/01/2020	20136	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	BARRY MANEY - 3	TRAILER			
			D Service As Per Attached Checklist																
T470	Myrtleford - Workshop	VehService\DS	Order number # L7600	VehService\DS			09/01/2020	20136	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	BARRY MANEY - 3	TRAILER			
T470	Myrtleford - Workshop	Body\DAMAGE	kangaroo damaged mudguard LH front remove broken mudguard, straighten mounting brackets, drill holes jaw new mudguard and fit to trailer				12/12/2019	30871	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				06/12/2019		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	BARRY MANEY - 3	TRAILER			
			D Service As Per Attached Checklist																
T470	Myrtleford - Workshop	VehService\DS	Order Number # L 7493	VehService\DS			06/12/2019		Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	BARRY MANEY - 3	TRAILER			
			replace hinge on L/H mudflap																
			replace 2nd in from L/H mudflap																
T470	Myrtleford - Workshop	Body\MUDGUARDS	drive to Barry mainy and pick up mudflap				05/12/2019	4942	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes\BOOSTER	remove and replace broken brake booster 2nd axle L/H side				03/12/2019	4942	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes\AIR LEAK	rubbed air hoses done w/shop				22/11/2019	908015	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				22/11/2019		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	BARRY MANEY - 3	TRAILER			
			D Service As Per Attached Check list																
T470	Myrtleford - Workshop	VehService\DS	Order number # L 7588	VehService\DS	fitted new hubo meter		22/11/2019		Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	BARRY MANEY - 3	TRAILER			
T470	Myrtleford - Workshop	Body\WHL HUB	Fit new hubo				20/11/2019		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes\AIR LEAK	check tension of all hose clamps on boosters and brake valves, found shocker				15/11/2019		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Susp\SUSPENSION	worn out eye bush and bottom eye of shocker damaged beyond repair, replaced shocker RH rear axle				15/11/2019		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				08/11/2019		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	BARRY MANEY - 3	TRAILER			
			D Service As Per Attached Checklist																
T470	Myrtleford - Workshop	VehService\DS	ORDER # L7348	VehService\DS			08/11/2019		Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	BARRY MANEY - 3	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				11/10/2019	244454	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	ONETRAK-3	TRAILER			
			D Service As Per Attached Checklist																
T470	Myrtleford - Workshop	VehService\DS	Order number # L7222	VehService\DS			11/10/2019	244454	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	ONETRAK-3	TRAILER			
T470	Myrtleford - Workshop	Susp\SUSPENSION	replace front axle and middle axle spring eye bushes				05/10/2019	239822	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Body\WHL HUB	clean and repair all wheel bearings				05/10/2019	239822	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes\BRK RELINE	Reline all 3 axles				05/10/2019	239822	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				26/09/2019	235393	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	BARRY MANEY - 3	TRAILER			
			D Service As Per Attached Checklist																
T470	Myrtleford - Workshop	VehService\DS	Order Number # L7129	VehService\DS			26/09/2019	235393	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	BARRY MANEY - 3	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				14/09/2019	224677	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	ONETRAK-3	TRAILER			
			D Service As Per Attached Checklist																
T470	Myrtleford - Workshop	VehService\DS	Order number # L7073	VehService\DS			14/09/2019	224677	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	ONETRAK-3	TRAILER			
T470	Myrtleford - Workshop	Body\WHL HUB	check LHR wheel bearings and repack				07/09/2019	218076	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Body\WHL HUB	replace missing LHR hub cap				07/09/2019	218076	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				31/08/2019	215368	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	ONETRAK-3	TRAILER			
			D Service As Per Attached Checklist																
T470	Myrtleford - Workshop	VehService\DS	ORDER # L7002	VehService\DS			31/08/2019	215368	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	ONETRAK-3	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				16/08/2019	205335	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	BARRY MANEY - 3	TRAILER			
			D Service As Per Attached Checklist																
T470	Myrtleford - Workshop	VehService\DS	ORDER NUMBER L6873	VehService\DS			16/08/2019	205335	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	BARRY MANEY - 3	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				02/08/2019		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	BARRY MANEY - 3	TRAILER			
			D Service As Per Attached Checklist																
T470	Myrtleford - Workshop	VehService\DS	Order #L6777	VehService\DS			02/08/2019		Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	BARRY MANEY - 3	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				20/07/2019	187089	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	ONETRAK-3	TRAILER			
			D Service As Per Attached Checklist & FIT BOTTOM SHOCKER MOUNT PLATE		replaced front left shock mount saddle														
T470	Myrtleford - Workshop	VehService\DS	Order #L6630	VehService\DS	replaced rear left clearance light		20/07/2019	187089	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	ONETRAK-3	TRAILER			
			remove and replace hose to RH rear axle brake booster																
			replace hoses with new clamps																
T470	Myrtleford - Workshop	Brakes\AIR LEAK	test for leaks				17/07/2019	183384	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				05/07/2019	176399	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	ONETRAK-3	TRAILER			
			D Service As Per Attached Checklist																
T470	Myrtleford - Workshop	VehService\DS	Order #L6582	VehService\DS			05/07/2019	176399	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	ONETRAK-3	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				14/06/2019	160964	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	ONETRAK-3	TRAILER			
			D Service As Per Attached Checklist																
T470	Myrtleford - Workshop	VehService\DS	Order #6402	VehService\DS			14/06/2019	160964	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	ONETRAK-3	TRAILER			
			Broken LHR U Bolt, Recover Truck From Side Of Road, Source Parts, Repair -Requires 2 x New Air Bag Bases																
T470	Myrtleford - Workshop	Susp\DAMAGE	Order #L6409				08/06/2019	156623	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	ONETRAK-3	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				01/06/2019	151639	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	ONETRAK-3	TRAILER			
			D Service As Per Attached Checklist																
T470	Myrtleford - Workshop	VehService\DS	Order #L6303	VehService\DS			01/06/2019	151639	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	ONETRAK-3	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				17/05/2019	144519	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	ONETRAK-3	TRAILER			
			D Service As Per Attached Checklist																
T470	Myrtleford - Workshop	VehService\DS	Order #L6174	VehService\DS			17/05/2019	144519	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	ONETRAK-3	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				04/05/2019	137858	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	ONETRAK-3	TRAILER			
			D Service As Per Attached Checklist																
T470	Myrtleford - Workshop	VehService\DS	Order #L6076 L6145	VehService\DS			04/05/2019	137858	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	ONETRAK-3	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				13/04/2019		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	ONETRAK-3	TRAILER			
			D Service As Per Attached Checklist																
T470	Myrtleford - Workshop	VehService\DS	Order #L5983	VehService\DS			13/04/2019		Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	ONETRAK-3	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				02/04/2019	127136	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	WRECKETT PTY. LTD - 3	TRAILER			
			D Service As Per Attached Checklist																
T470	Myrtleford - Workshop	VehService\DS	ORDER # L5912	VehService\DS	replaced split air fitting		02/04/2019	127136	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	WRECKETT PTY. LTD - 3	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		reolaced airbae		20/03/2019	122833	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	WRECKETT PTY. LTD - 3	TRAILER			
T470	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	PO L5809		20/03/2019	122833	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	WRECKETT PTY. LTD - 3	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				02/03/2019	116428	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	WRECKETT PTY. LTD - 3	TRAILER			
T470	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			02/03/2019	116428	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	WRECKETT PTY. LTD - 3	TRAILER			
T470	Rosewood - Workshop	Chassis\BOLSTER	2nd bolster passenger side flip				26/02/2019	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	Rosewood Workshop	TRAILER			
T470	Rosewood - Workshop	VehService\AS	A service due				26/02/2019	0	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	Rosewood Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				20/02/2019	112063	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			20/02/2019	112063	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Chassis\BOLSTER	weld up chain bracket which holds up first bolster				08/02/2019	107915	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Susp\AIR BAG	remove and replace damaged airbag on middle RHS axle				08/02/2019	107915	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				08/02/2019	107915	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	Myrtleford Workshop	TRAILER			
					welded chain holder on bolster														
T470	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	reolaced airbae		08/02/2019	107915	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	Myrtleford Workshop	TRAILER			
T470	Rosewood - Workshop	Susp\AIR BAG	airbag randomly go done on trailer going down on tyres				31/01/2019		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	Rosewood Workshop	TRAILER			
T470	Myrtleford - Workshop	Susp\SUSPENSION	Replace RHF axle strap		replace RHF and LHF axle straps		30/01/2019	141416	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Elect\ELECT P&W	1 marker light out RHS				26/01/2019		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	DriCabRep\AIR LEAK	can I please have a metre or 2 of air winch hose for spare backup				26/01/2019		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				26/01/2019	103061	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			26/01/2019	103061	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				11/01/2019	99848	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			11/01/2019	99848	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Elect\INDICATORS	repair indicators under skid plate - jammed				05/01/2019		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Chassis\HOUSEKEEP	Repair LHF Pivot Pin Crack		check and grease ball race and turntable		20/12/2018	98631	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				19/12/2018	97955	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			19/12/2018	97955	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				15/12/2018	95160	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			15/12/2018	95160	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	Myrtleford Workshop	TRAILER			
T470	Rosewood - Workshop	Brakes\AIR LEAK	Air Leak's		get trailer into workshop with bad air leak, diagnose and repair booster hose leak		07/12/2018		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	Rosewood Workshop	TRAILER			
T470	Rosewood - Workshop	Brakes\BOOSTER	Booster		repair hose leaking and booster		07/12/2018		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	Rosewood Workshop	TRAILER			
T470	Rosewood - Workshop	Brakes\AIR LEAK	air leak in hose that attaches to right brake booster				06/12/2018		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	Rosewood Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				01/12/2018	90688	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			01/12/2018	90688	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				01/12/2018		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			01/12/2018		Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				30/11/2018	1076050	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			30/11/2018	1076050	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				28/11/2018	8756	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			28/11/2018	8756	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				17/11/2018	85021	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	Myrtleford Workshop	TRAILER			
					repair rubbed electrical wiring														
T470	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	reolace and tighten ram cross member bolts		17/11/2018	85021	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Chassis\WINCH/STRP	fit 2 new winch straps				10/11/2018	83383	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Body\MUDGUARDS	fit 2x centre mudflaps and hinges				06/11/2018	82628	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Chassis\FIFTH WHEE	Replace ball race & bolts		hook up and test		01/11/2018	81942	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Chassis\FIFTH WHEE	Check foot pins & bushes				01/11/2018	81942	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				31/10/2018	81940	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	Myrtleford Workshop	TRAILER			
					repair blinker wiring														
T470	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	reolace broken u-bolt outrieaer mount		31/10/2018	81940	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier STK	78957S	Myrtleford Workshop	TRAILER			

T470	Myrtleford - Workshop	Body\FIFTH WHEE	unhook A Trailers				26/10/2018		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				20/10/2018	80670	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			20/10/2018	80670	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Hydraulics\HYD LEAKS	replace blown hydraulic hose on A Trailer				11/10/2018	78377	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				06/10/2018	77621	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			06/10/2018	77621	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Elect\TRL LIGHTS	parker light on driver side only 10% working				22/09/2018	74849	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP			22/09/2018	74849	PreventativeMaintenance	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				22/09/2018	74849	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			22/09/2018	74849	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Body\PANELS	rear checker plate, crack developing on RHS at stud				08/09/2018	71707	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				08/09/2018	71707	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	check lights and repair bolster lights		08/09/2018	71707	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				24/08/2018	68614	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	changed broken shocker mount and fitted new shocker on RHM axle		24/08/2018	68614	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Body\PANELS	crack on checker plate needs welding				18/08/2018	67425	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice				17/08/2018	65255	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Body\PANELS	1 broken cleat needs re-welding underneath checker plate floor				09/08/2018		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Susp\SUSPENSION	Repair or Replace RHM top & bottom shocker mounts		fitted new bottom shocker mount and shocker to RHM axle		08/08/2018	68614	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Body\MUDGUARDS	2x mudguards/1x mudflap and hinge				07/08/2018	65628	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Elect\INDICATORS	1x indicator				07/08/2018	65628	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Elect\TRL LIGHTS	1x hella side light				07/08/2018	65628	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				07/08/2018	65628	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Body\BOLSTER	Move Bolsters				07/08/2018	65628	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			07/08/2018	65628	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Susp\SHOCK ABS	Replace RHM bottom shocker mount				26/07/2018	68614	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Body\DAMAGE	1 broken stud on steel plate, got hit by loader forks				25/07/2018	62846	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				25/07/2018	62484	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			25/07/2018	62484	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Body\MUDGUARDS	wire on R/H side mudflap u/s				18/07/2018	60559	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Chassis\WINCH/STRP	move air winch				18/07/2018	60559	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				07/07/2018	60559	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			07/07/2018	60559	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Body\PANELS	Repair checker plate mounts				05/07/2018	60560	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
			Crack test & reline all wheels																	
T470	Myrtleford - Workshop	Brakes\BRK RELINE	FIT 6 X 8PW BRAKE DRUMS				28/06/2018	60561	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				27/06/2018	57571	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			27/06/2018	57571	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				08/06/2018	54505	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			08/06/2018	54505	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Elect\ELECT P&W	Check & repair scale wiring				19/05/2018	54013	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				19/05/2018	52418	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			19/05/2018	52418	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Body\FIFTH WHEE	hook up to s/line				08/05/2018	51113	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Elect\TRL LIGHTS	T-470 - check lights				08/05/2018	51113	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Body\HOUSEKEEP	check over trailer				08/05/2018	5113	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Body\MUDGUARDS	remove guards and straighten brackets				08/05/2018	5113	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Tyres	Job Added From Invoice				02/05/2018	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice				02/05/2018	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice				02/05/2018	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes\BACK PLATE	Replace Missing Brake Backing Plate				27/04/2018	1115	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				25/04/2018	49817	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	fit LH front backing plate		25/04/2018	49817	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				14/04/2018	47190	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			14/04/2018	47190	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			05/04/2018	44965	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				05/04/2018	44965	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Tyres	Job Added From Invoice				27/03/2018	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice				27/03/2018	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice				27/03/2018	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				24/03/2018	42654	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			24/03/2018	42654	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				14/03/2018	39838	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			14/03/2018	39838	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				01/03/2018	36884	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			01/03/2018	36884	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
			Replace hydraulics lines and fitting 2x																	
T470	Myrtleford - Workshop	Hydraulics\HOSES	FIT COVER OVER EBS VALVE				20/02/2018	34283	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Body\MOUNTS	Replace hinge pin bolts				20/02/2018	34283	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes\BRK RELINE	Crack test & reline all wheels				16/02/2018	34283	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes\SLACK ADJ	Move boosters down on slack adjuster to bottom hole 125mm				16/02/2018	34283	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				15/02/2018	34274	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			15/02/2018	34274	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Body\AIR LEAK	check for air leaks				07/02/2018	31575	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				03/02/2018	31575	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			03/02/2018	31575	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			23/01/2018	29161	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				23/01/2018	29161	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Tyres	Job Added From Invoice				19/01/2018	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice				19/01/2018	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice				19/01/2018	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				11/01/2018	26416	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			11/01/2018	26416	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Tyres\RUN OUT	Job Added From Invoice				30/12/2017	23738	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				28/12/2017	23736	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			28/12/2017	23736	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Tyres\RUN OUT	Job Added From Invoice				16/12/2017	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Chassis\BOLSTER	2x chains have snapped away from trailer eyellets - both eyelets are broken off				16/12/2017	21946	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Chassis\WINCH/STRP	middle winch pull cable snapped				15/12/2017	21677	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				14/12/2017	21379	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	unscrunch LHF & LHM air bags - again		14/12/2017	21379	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Body\AIR FITTIN	check for oil leaks				10/12/2017	20450	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Hydraulics\HYD LEAKS	1x hydraulic fitting - worn and leaking				10/12/2017	20450	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Susp\AIR BAG	pass/side middle axle air bag blown				07/12/2017	19826	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Chassis\FIFTH WHEE	grease turntable				02/12/2017	25881	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				01/12/2017	18851	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			01/12/2017	18851	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				18/11/2017	16416	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	replace RH outer indicator plug		18/11/2017	16416	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes\BRK RELINE	Crack test & reline all wheels				07/11/2017	14020	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes\BRK O/HAUL	brakes squeaking - inspect				07/11/2017	14020	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				07/11/2017	14394	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			07/11/2017	14394	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Body\HOSES	Tidy up all wiring & hoses to front of T492				27/10/2017	112250	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				26/10/2017	12481	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			26/10/2017	12481	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Tyres\RUN OUT	Job Added From Invoice				17/10/2017	9872	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				12/10/2017	10255	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			12/10/2017	10255	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice				07/10/2017	8810	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice				07/10/2017	8810	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Insp\UNT INSP	srt stickers				28/09/2017	7464	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				28/09/2017	7463	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			28/09/2017	7463	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Tyres	Job Added From Invoice				23/09/2017	5221	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice				23/09/2017	5221	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Chassis\FIFTH WHEE	Repair or Replace Turn table top		fit new t/table top		21/09/2017	7464	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Hydraulics\RAM	2x hyd ram pins for bolster - keep 1 spare)				20/09/2017	5220	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Susp\AIR BAG	check air bags for leaks				20/09/2017	5220	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				20/09/2017	522	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	turntable top has cracked webbing		20/09/2017	522	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Body\AIR LEAK	check for air leaks				14/09/2017	3803	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Susp\AIR BAG	unscrunch 4 airbags				14/09/2017	3803	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				09/09/2017	2818	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			09/09/2017	2818	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Tyres\RUN OUT	Job Added From Invoice				06/09/2017	116967	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Tyres\RUN OUT	Job Added From Invoice				06/09/2017	116642	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Susp\AIR BAG	unscrunch air bags x 1				01/09/2017		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				01/09/2017		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	78957S	Myrtleford Workshop	TRAILER			
T470	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			01/09/2017		Service	Completed	Gre

T470	Myrtleford - Workshop	Elect\TRL LIGHTS	replace A & B trailer light plug				13/07/2017	103694	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Body\AIR FITTIN	tidy up suzie coils from catching on turntable				13/07/2017	103694	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				11/07/2017	102450	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	VehServeal\DS	D Service As Per Attached Checklist	VehServeal\DS	replaced LH inner tail light LED		11/07/2017	102450	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	VehServeal\DS	D Service As Per Attached Checklist	VehServeal\DS			05/07/2017	100425	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				05/07/2017	100425	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Tumut - Workshop	Tyres	Job Added From Invoice				23/06/2017	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Tumut Workshop	TRAILER
					BPW Melbourne												
T470	Myrtleford - Workshop	Brakes\BRK RELINE	Reline all wheels		fit 6x new slack adiusters		17/06/2017	100425	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				16/06/2017	99492	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
			D Service As Per Attached Checklist														
T470	Myrtleford - Workshop	VehServeal\DS	REPACE DAMAGED AXLE CABLES	VehServeal\DS			16/06/2017	99492	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Tyres	Job Added From Invoice				14/06/2017	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Brakes\EBS Kit	Fit EBS Kit to front & rear axles		BPW workshop Melbourne		10/06/2017	100425	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Tyres\RUN OUT	Job Added From Invoice				08/06/2017	96665	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				03/06/2017	99996	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	VehServeal\DS	D Service As Per Attached Checklist	VehServeal\DS			03/06/2017	59996	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Chassis\WINCH/STRP	Replace damaged winch drum bolts		Complete		31/05/2017	95997	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				24/05/2017	93969	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	VehServeal\DS	D Service As Per Attached Checklist	VehServeal\DS			24/05/2017	93969	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Elect\TRL LIGHTS	Replace LH outer tail light plug		check lights and replace RH inner brake/parker		10/05/2017	9056	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				09/05/2017	90560	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	VehServeal\DS	D Service As Per Attached Checklist	VehServeal\DS			09/05/2017	90560	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Elect\TRL LIGHTS	tail light				09/05/2017	90560	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Tyres	Job Added From Invoice				29/04/2017	86881	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				28/04/2017	87423	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	VehServeal\DS	D Service As Per Attached Checklist	VehServeal\DS			28/04/2017	87423	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Tyres	Job Added From Invoice				27/04/2017	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice				27/04/2017	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice				27/04/2017	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Chassis\FIFTH WHEE	Repair crack in RHS of ball race mount plate				13/04/2017	90564	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				12/04/2017	84606	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	VehServeal\DS	D Service As Per Attached Checklist	VehServeal\DS			12/04/2017	84606	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				30/03/2017		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	VehServeal\DS	D Service As Per Attached Checklist	VehServeal\DS			30/03/2017		Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Tyres	Job Added From Invoice				24/03/2017	80848	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Body\PANELS	repair checker plate chassis cover				18/03/2017	80849	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Body\HOUSEKEEP	check over trailer				18/03/2017	80849	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Tyres\TP13	Job Added From Invoice				16/03/2017	79388	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				15/03/2017	79903	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	VehServeal\DS	D Service As Per Attached Checklist	VehServeal\DS			15/03/2017	79903	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Chassis\WINCH/STRP	Air leak in 3rd air winch		Complete		09/03/2017	79288	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Body\MUDGUARDS	Replace RHF mudguard		Complete		09/03/2017	79288	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Chassis\FIFTH WHEE	Grease turn table		Complete		09/03/2017	79288	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Susp\AIR BAG	Replace RHR airbag		Complete		09/03/2017	79288	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Chassis\BOLSTER	Fit lay flat to front bolster chains		Complete		09/03/2017	79288	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Susp\AIR BAG	pass/side mid axle - bolt was lost under airbag base				03/03/2017	78249	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	DrCabElect\SCALES	Replace female scale plug at front of trailer				03/03/2017	79288	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	DrCabElect\SCALES	Replace male scale plug at rear of trailer		check plug - ok		03/03/2017	79288	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				02/03/2017	77937	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	VehServeal\DS	D Service As Per Attached Checklist	VehServeal\DS			02/03/2017	77937	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Chassis\WINCH/STRP	Repair quick release cable handle on middle winch		Complete		01/03/2017	77397	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Tyres\TP21	Job Added From Invoice				01/03/2017	75323	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Tyres\TP12	Job Added From Invoice				01/03/2017	75648	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
					Remove 2nd bolster ram for repairs & fit new pin												
T470	Myrtleford - Workshop	Hydraulics\RAM	Rear bolster - pin missing from ram to bolster		Comolete		23/02/2017	76248	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Chassis\FIFTH WHEE	Fit 2 x higher turn table feet & bushes				16/02/2017	3175	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Chassis\FIFTH WHEE	Fit new turn table top				16/02/2017	3175	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Brakes\BRK O/HAUL	Fit 50% runout brake shoes to LHM & check bearings				14/02/2017	75320	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				11/02/2017	75320	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	VehServeal\DS	D Service As Per Attached Checklist	VehServeal\DS			11/02/2017	75320	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				31/01/2017	71884	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	VehServeal\DS	D Service As Per Attached Checklist	VehServeal\DS			31/01/2017	71884	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Susp\HOUSEKEEP	2x broken axle straps - rear axle				24/01/2017	70068	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				19/01/2017	68407	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	VehServeal\DS	D Service As Per Attached Checklist	VehServeal\DS			19/01/2017	68407	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Susp\AIR BAG	Replace LHM Airbag				11/01/2017	66462	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				10/01/2017	65497	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	VehServeal\DS	D Service As Per Attached Checklist	VehServeal\DS			10/01/2017	65497	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	VehServeal\DS	D Service As Per Attached Checklist	VehServeal\DS			21/12/2016	63223	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				21/12/2016	63223	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	VehServeal\DS	D Service As Per Attached Checklist	VehServeal\DS			06/12/2016	60754	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				06/12/2016	60754	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Susp\HOUSEKEEP	LHS front axle - broken axle strap				30/11/2016	59550	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				22/11/2016	57953	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	VehServeal\DS	D Service As Per Attached Checklist	VehServeal\DS			22/11/2016	57953	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Chassis\WINCH/STRP	fit rope strap to middle winch				18/11/2016	57405	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	VehServeal\DS	D Service As Per Attached Checklist	VehServeal\DS			11/11/2016	55655	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				11/11/2016	55655	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Body\PANELS	Remove & repair checker plate & refit. Remove & repair checker plate		Complete		04/11/2016	54385	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Chassis\MUDGUARDS	Make up U Bolt & nylon spacer + fit to LHS mudguard bracket				29/10/2016	54385	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				28/10/2016	53149	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	VehServeal\DS	D Service As Per Attached Checklist	VehServeal\DS			28/10/2016	53149	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Tyres\TP19	Job Added From Invoice				19/10/2016	49871	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Brakes\BRK RELINE	Crack test & reline all axles				14/10/2016	59905	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				13/10/2016	50665	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	VehServeal\DS	D Service As Per Attached Checklist	VehServeal\DS			13/10/2016	50665	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Tyres\TP19	Job Added From Invoice				12/10/2016	49363	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Tyres\DAMAGE	rear LHS axle - wheel damage broken stud & some missing nuts, wheel has come loose				11/10/2016	49871	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Susp\AIR BAG	front axle, pass/side, broken airbag				04/10/2016	48247	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				04/10/2016	48247	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	VehServeal\DS	D Service As Per Attached Checklist	VehServeal\DS			04/10/2016	48247	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Elect\TAIL LIGHT	brake lights not working				30/09/2016	47737	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Tyres\TP16	Job Added From Invoice				23/09/2016	45835	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Chassis\WINCH/STRP	rear winch - broken spring inside				21/09/2016	45461	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Elect\TAIL LIGHT	brake & blinkers out				21/09/2016	45461	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				21/09/2016	45461	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	VehServeal\DS	D Service As Per Attached Checklist	VehServeal\DS			21/09/2016	45461	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	DrCabElect\SCALES	calibrate scales				13/09/2016		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Brakes\AIR LEAK	repair supply line hose				13/09/2016		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	DrCabElect\SCALES	Check & repair scales		fitr 2nd hand scale slave		09/09/2016	42986	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Brakes\BRK RELINE	Fit 40% runout brake shoes & check bearings		fit new brake shoes to LHR		09/09/2016	42986	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				08/09/2016	42597	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	VehServeal\DS	D Service As Per Attached Checklist	VehServeal\DS	repair 2x mudguard outrigger u bolts		08/09/2016	42597	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Body\PANELS	tighten all checker plate floor bolts				27/08/2016	39548	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Body\WHL HUB	tighten all hub caps				27/08/2016	39548	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				27/08/2016	39548	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	VehServeal\DS	D Service As Per Attached Checklist	VehServeal\DS			27/08/2016	39548	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Body\MUDGUARDS	Fit longer rear mudflaps				18/08/2016	41564	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				17/08/2016	36667	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	VehServeal\DS	D Service As Per Attached Checklist	VehServeal\DS			17/08/2016	36667	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Susp\AIR BAG	Blow out 3 creased Airbags		Complete		16/08/2016	36667	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	DrCabElect\SCALES	Repair scales		repair scale wiring		09/08/2016	41564	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				02/08/2016	33750	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	VehServeal\DS	D Service As Per Attached Checklist	VehServeal\DS			02/08/2016	33750	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Body\PANELS	Replace cover plate bolts on checker plate				28/07/2016	33230	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	DrCabElect\SCALES	Check trailer wiring for scales				23/07/2016	45141	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	DrCabElect\SCALES	Make up new scale cable fromt T470 to T492				20/07/2016	31261	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				20/07/2016	31261	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	VehServeal\DS	D Service As Per Attached Checklist	VehServeal\DS			20/07/2016	31261	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				15/07/2016	30726	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	VehServeal\DS	D Service As Per Attached Checklist	VehServeal\DS			15/07/2016	30726	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP			15/07/2016	30726	PreventativeMaintenance	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
			Fit extra air winches														
T470	Myrtleford - Workshop	Chassis\WINCH/STRP	Hook up & Test		Comolete		12/07/2016	30725	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Hydraulics\HOSES	Replace hydraulic fittings		Complete		12/07/2016	30725	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	DrCabElect\SCALES	refit scale transducer + slave				08/07/2016	3072	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER
T470	Myrtleford - Workshop	Elect\ELECT P&W	renew electrical wiring				08/07/2016	3072	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Mt Gambier	STK	789575	Myrtleford Workshop	TRAILER