EquipmentName	Workshop	CodeAndSubCode	Description	Schedule	CompletionComments	DateDone	DistanceDone	Worktype	Workstate	EquipmentOwner	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
T417	Colac - Colac	Tyres	Tyres			07/09/2026	1178148	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BORDER BANDAG PTY LTD -3	TRAILER
T417	Myrtleford - Workshop	Tyres\TP11+12	Tyres\TP11+12 (31-32)		TYRES WERE BALD	17/06/2026	1178148	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BORDER BANDAG PTY LTD -3	TRAILER
T417	Myrtleford - Workshop	Tyres\TP3+4	Tyres\TP3+4 (23-24)		TYRES WERE BALD	17/06/2026	1178148	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BORDER BANDAG PTY LTD -3	TRAILER
T417	Myrtleford - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		04/06/2026	1178148	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	JF MECHANICALS - 3	TRAILER
T417	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection	Insp\ANN INSP		18/05/2026	1178148	PreventativeMaintenance	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	JF MECHANICALS - 3	TRAILER
T417	Myrtleford - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		18/05/2026	1178148	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	JF MECHANICALS - 3	TRAILER
T417	Myrtleford - Workshop	DrCabElect\SCALES	REPLACE DAMAGED SCALE PLUG.		Inspect for air leaks and found air line rubbing on booster. Cut out rubbed section of air line and add joiner and hose clamps. Recheck over for air leaks, all ok. Added silicon hosing to prevent from rubbing through again. Line rubbed through again, remove and replace entire hose, secure in different spot to prevent rubbing. No more air leak, all ok KWABF232 HOSE UNION 1/2 1 3.05 KWHS010-20 PERFORATED HOSECLAMP BA 2 5.12 KWABF232 HOSE UNION 1/2 1 3.05	14/05/2026	1178148	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	JF MECHANICALS - 3	TRAILER
T417	Myrtleford - Workshop	Brakes\AIR LEAK	Check for air leak from booster or booster line		KWHS010-20 PERFORATED HOSECLAMP BA	13/11/2025	1178148	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	VehService\DS	VehService\DS D Service L097682	VehService\DS		13/11/2025	1178148	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Chassis\WHL HUB	CHECK LH WHEEL BEARINGS		Jack front axle and check adjustments. Left side all okay. Jacked up RH side and adjusted wheel bearing to spec. Lowered axle.	11/11/2025	1178148	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Susp\AIR BAG	LH REAR AIR BAG BOLT MISSING		ear LH airbag missing bolt, went to replace bolt but found airbag not centre. Drop ride height, clean thread and put bolt in. Lift ride heiaht. all ok	11/11/2025	1178148	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Elect\TAIL LIGHT	NUMBER PLATE LIGHT N/W		eist power to light with battery, no power found. Fit new light and found still not working. Inspect and found breaks in wiring. Repair breaks and check light operation, all working as should KW91666BL LAMP-LICENSE PLATE,3 LED 8-28V BLACK HOU	11/11/2025	1178148	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Body\AIR LEAK	REPLACE WORN HOSES ON MIDDLE AXLE		Inspect rubbed hoses. Cut out worn sections and installed joiners, secured with hose clamps and wrapped hoses to prevent further rubbing. Tested for leaks, all okay. KWABF232 HOSE UNION 1/2 3 9.15 KWHS010-20 PERFORATED HOSECLAMP BA 6 15.36 KWT02-3502-152M HOSE-RUBBER 1/2' SAE J1 1 6.00	11/11/2025	1178148	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	BrakesLab	REPLACE WORN HOSES ON MIDDLE AXLE		KWV31-TP-1012 HOSE-SILICONE,3'ID RADIATOR 300 MM LENGT	11/11/2025	1178148	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Chassis\WINCH/STRP	replace bolt on 1st winch		REPLACE BOLT ON 1ST WINCH Fit new bolt on 1st winch.	11/11/2025	1178148	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Tyres\TP7+8	Tyres\TP7+8 (27-28)		LH rear pivot bush worn, unbolt airbag, u-bolts and pivot bush. Remove spring, press out old bush and then press in new bush. Refit spring and pivot bolt. Tighten airbag bolts and put saddle back on. Tighten all u-bolts and pivot bolts to spec.	11/11/2025	1178148	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BORDER BANDAG PTY LTD -3	TRAILER
T417	Myrtleford - Workshop	Susp\DAMAGE	REPLACE LHR SPRING EYE BUSH		KW02031690000 BUSH-STEEL CASED BPW PIVOT H/D	27/10/2025	1178148	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Susp\SHOCK ABS	SHOCKER LOOSE BOLT		Tighten loose shocker bolt to spec as required	27/10/2025	1178148	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Body\MUDGUARDS	TIGHTEN LOOSE MUD GUARD BOLT		LH rear mud guard loose bolt to chassis. Tightened as required.	27/10/2025	1178148	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Tyres\TP9+10	Tyres\TP9+10 (29-30) VehService\DS D Service L097434			25/10/2025	1178148	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BORDER BANDAG PTY LTD -3	TRAILER
T417	Myrtleford - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		24/10/2025	1178148	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	VehService\DS	L097164	VehService\DS		13/10/2025	1178148	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Elect\TAIL LIGHT	front left side clearence light broken of		Remove clearance lights, tested wiring, all okay. Cut wires and removed light. Wired in new light and fitted, checked operation, all okay. KW2053 RED/AMBER SIDE MARKER LAMP	10/10/2025	1178148	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Chassis\STRAPS	Straighten 1st binder hook		Loosened binder and straightened out hook as best as possible.	10/10/2025	1178148	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Tyres\Punct	Tyres\Puncture 21			10/10/2025	1178148	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BORDER BANDAG PTY LTD -3	TRAILER
T417	Myrtleford - Workshop	Tyres\RUN OUT	Tyres\RUN OUT POS 21			08/09/2025	1178148	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BORDER BANDAG PTY LTD -3	TRAILER
T417	Myrtleford - Workshop	Tyres\Punct	Tyres\Puncture POS 30 + 22			08/09/2025	1178148	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BORDER BANDAG PTY LTD -3	TRAILER
T417	Myrtleford - Workshop	Brakes\BOOSTER	Brake booster failed Millicent side Hatherleigh R/H mud guards need attention 1st is loose		Brake booster failed Millicent side Hatherleigh Travel to breakdown, inspect and found booster hose had blown off. Fit hose with new clamp. Had to travel back out to breakdown, remove hose clamp and found hose rubbed through. Cut out rub and fit new hose clamp. Check for air leaks. all ok TIGHTEN AND ADJUST GUARDS AS REQUIRED Tighten bolts on front RH guard. Adjust rear mudguard as	03/09/2025	1178148	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Body\MUDGUARDS	3rd is to low		too low. RECHECK TURNTABLE FOOT BUSHES Split A and B trailer, found foot bushes worn. Remove turn table top press out old bushes and install new bushes and pins. Refit turn table top and secure with new pins and lock bolts	01/09/2025	1178148	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Mvrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Chassis\FIFTH WHEE	foot bushes have movement monitor RECHECK FOOT BUSHES		KWT05-RK0635GP KIT-FOOT PIN & BUSH FW351-342 POLY BUSH 1 147.4SNG2HHRK08908 INSERTS DUCTILE IRON	01/09/2025	1178148	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Body\AIR FITTIN	Body\AIR FITTIN oull cords missine		Air leak under A trailer Found rubbed air line on 3/4 hose going to booster. Cut out hose and joined in new length. Protect and insulate hose, secured in position. Also found air tank had 2 snapped bolts in bracket. Remove and replace snapped bolts as required POL 3/4 rubber hose 1.5 51.60POL 3/4 hose ioiner	01/09/2025	1178148	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	VehService\DS	VehService\DS D Service L096534	VehService\DS	Carried out trailer service as per Greenfreight checklist. Check over and retension pivot bushes & u bolts Check over and tensioned all bolster bolts as reauired.	28/08/2025	1178148	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Brakes\BOOSTER	Brakes\BOOSTER		BREAKDOWN - Repairs Carried Out: Travel to site inspect for air leak found RHS front brake booster hose had come off. Re fit with new clamp. Noticed LHS turn table fold up pin halfway out bash pin back in fit new retainer bolt travel return TRAVEL TO AXD - TEMP REPAIR BOOSTER HOSE	28/08/2025	1178148	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	COOKY'S DIESEL MECHANIC REPAIRS - 3	TRAILER
T417	Myrtleford - Workshop	Brakes\BOOSTER	Brakes\BOOSTER REPAIR RHF BRAKE BOOSTER		FOLLWO BACK TO QT DIESEL REPAIR RHF BRAKE BOOSTER	25/08/2025	1178148	Reoair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	QT DIESEL SERVICES - 3	TRAILER
T417	Myrtleford - Workshop	Steering\WHEEL BRGS	Steering\WHEEL BRGS		CHECK LH MIDDLE WHEEL BEARING LOOSE Jacked up LH middle axle, adjusted wheel bearing to spec x1 CLEARANCE LIGHT OUT Work order 200043	18/08/2025	1178148	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Elect\TRL LIGHTS	1 X CLEARENCE LIGHT NOT WORKING		Checked for power at light, no good. Run new twin core wiring through bolster and connected to clearance light. Checked operation. all okay GREENFREIGHT SERVICE Carried out trailer service as per Greenfreight checklist. Customer instructions: Place vehicle on shaker & Inspected Carried out General Inpection & Checkover Greased vehicle TENSION PIVOT BUSHES & U BOLTS Check over and retension pivot bushes & u bolts TENSION BOLSTER BOLTS Check over and tensioned all bolster bolts as required	18/08/2025	1178148	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	VehService\DS	VehService\DS D Service	VehService\DS	Disconnect trailers, check over turntable and king pin. Greased all components. all within spec. Reconnect.	12/08/2025	1178148	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Body\MUDGUARDS	Body\MUDGUARDS		Labour Fault: Broken wheel guard mount. Cause: Mount failure due to damage or fatigue. Correction: Removed broken wheel guard mount. Welded and repaired damaged section. Refit guard and tightened all bolts securely.	11/08/2025	1178148	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	HALLORAN DIESEL - 3	TRAILER
T417	Myrtleford - Workshop	Susp\AIR BAG	Susp\AIR BAG		REPAIRS ✓ Repairs Carried Out: Travel to site, inspect ride height fault diagnose ride height valve faulty remove valve. Travel back to base, collect new valve travel back to site. Transfer air fittings from old valve to new valve, fit new valve test operation all good travel return.	01/08/2025	1178148	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	COOKY'S DIESEL MECHANIC REPAIRS - 3	TRAILER
T417	Myrtleford - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		31/07/2025	1178148	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Body\MUDGUARDS	HOLE IN GUARD FRONT		Found drivers side rear mudguard was worn out. Unbolt and removed mud guard. Aligned new guard and drilled holes as required. installed. tightened bolts	29/07/2025	1178148	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Body\AIR LEAK	Trailer Service Line Leaking Air		Found line to trailer leaking from the push fitting. Disconnect line and replaced push fitting. Reconnect and test ooeration. all okav. Plug in and check codes, found fault for tone wheel on LH rear axle. Jack up rear axle and adjust bearing to spec.	29/07/2025	1178148	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Brakes\EBS FAULTS	EBS COMES ON WHEN TURNING RIGHT		Push pulse sensor in and refit hub cap, all ok	29/07/2025	1178148	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		18/07/2025	1178148	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER

					LH REVERSING LIGHT GOT SHORT IN IT												
T417	Myrtleford - Workshop	Elect\ELECT P&W	Elect\ELECT P&W		Removed light and inspected, found a short. Cut and joined wires back toaether. Check operation. all ok	17/07/2025	1178148	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Elect\SUZI COIL	Elect\SUZI COIL		CHECK SUZI COIL FITTING - LEAKING Removed old Suzi coil fitting and replaced with new. Check for leaks. all ok	17/07/2025	1178148	Reoair	Comoleted	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
					REPLACE BASE PLATE ON LHM AIRBAG DUE TO BOLT BEING SNAPPED AND SEIZED Lowered ride height, disconnected air line and kinked. Undid base plate bolts, tried to get one from spare parts or tool room, but had none in stock. Welded nut to snapped bolt. Put base plate back on and lowered bags. Tighten all												
T417	Myrtleford - Workshop	Susp\AIR BAG	Susp\AIR BAG		bolts then reconnect air line.	17/07/2025	1178148	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Tyres\TP1+2	Tyres\TP1+2			02/07/2025	1178148	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BEAUREPAIRES - 3	TRAILER
T417	Myrtleford - Workshop	Tyres\TP11+12	Tyres\TP11+12			02/07/2025	1178148	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BEAUREPAIRES - 3	TRAILER
					Remove guard off trailer, oxy the old bracket that holds the guard on. Got new steel from multi metals, measure out												
T417	Myrtleford - Workshop	Body\MUDGUARDS	Repair broken front guard		and drill 8 holes. Fit new bracket and weld on. Paint	01/07/2025	1178148	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	VehService\DS	VehService\DS D Service	VehService\DS	bracket, drill holes for mudguard and fit. All ok	28/06/2025	1178148	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
					Jack 2nd and 3rd axle. Removed hub caps and adjust bearings												
T417	Myrtleford - Workshop	DrivLine\WHEEL BRGS	CHECK ALL WHEEL BEARINGS		to spec, then re fit hub caps. Tension to spec, all ok	25/06/2025	1178148	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
					Found middle guard mount loose. Undid U bolt and put												
T417	Myrtleford - Workshop	Body\MUDGUARDS	CHECK AND TIGHTEN ALL MUDGUARDS		washers on to space out U bolt. Tighten up and check, all ok	25/06/2025	1178148	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
					Rear LH indicator N/W. Pulled light out from broken wire and exposed wires. Cleaned up all wiring and joined back												
T417	Myrtleford - Workshop	Elect\INDICATORS	REAR LH INDICATOR N/W		together. Checked operation, all o	25/06/2025	1178148	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Tyres\TP7+8	Tyres\TP7+8		TYRE RAN FLAT - CALL OUT	24/06/2025	1178148	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BEAUREPAIRES - 3	TRAILER
T417	Myrtleford - Workshop	Susp	Right Weigh scale box			23/06/2025	1178148	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	MAXIPARTS P/L - 3	TRAILER
T417	Myrtleford - Workshop	Tyres\RUN OUT	Tyres\RUN OUT PO 1			16/04/2025	1178148	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BEAUREPAIRES - 3	TRAILER
T417	Myrtleford - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		15/04/2025	1178148	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	JF MECHANICALS - 3	TRAILER
T417	Myrtleford - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		19/03/2025	1178148	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	JF MECHANICALS - 3	TRAILER
T417	Myrtleford - Workshop	Tyres\TP9+10	Tyres\TP9+10			15/03/2025	1178148	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BEAUREPAIRES - 3	TRAILER
T417	Myrtleford - Workshop	Chassis\WINCH/STRP	REPLACE 2ND LOGGING STRAP ON WINCH			18/02/2025	1178148	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	JF MECHANICALS - 3	TRAILER
T417	Myrtleford - Workshop	VehService\DS	VehService\DS	VehService\DS		13/02/2025	1178148	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	QT DIESEL SERVICES - 3	TRAILER
T417	Myrtleford - Workshop	VehService\DS	VehService\DS	VehService\DS		07/01/2025	1178148	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
					LOOSE MUD GUARD												
T417	Myrtleford - Workshop	Body\MUDGUARDS	Body\MUDGUARDS		Found mud guard was loose. Tension bolts to spec	03/01/2025	1178148	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Body\AIR LEAK	Check for major air leak			03/12/2024	929780	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	VehService\DS	VehService\DS	VehService\DS		27/11/2024	929780	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
			BRACKET WHERE wheel sit when folded up is bent up. needs straightening.		Heat up bracket and bend back into place. Grind out cracks and prepped surfaces for welding. Welded cracked area and painted over welds.												
T417	Myrtleford - Workshop	Chassis\Load Fram	L/H side between bolsters			23/11/2024	929780	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
					Remove axle for access so major crack can be welded JD'S decided to plate chassis axle did not need to be												
T417	Myrtleford - Workshop	Chassis\CHAS CRACK	Chassis\CHAS CRACK		removed. Take trailer to yard. ssilt B off and droo to JD's CHECK AND FIX ALL LIGHTS	11/11/2024	929780	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
					LH front lower clearance light not working. Tested power, no good. Cut cables away from chassis, traced corroded wiring. Cut out corroded wire and joined in new wiring. Found break in joins at junction. Cut out and repaired, tape and secure wiring.												
T417	Myrtleford - Workshop	Body\LIGHTS	Body\LIGHTS		Top LH working not working. Unbolt, cut wiring and removed light. Mounted new light and joined wiring. Also had another clearance light out. Found to have broken wiring, cut out damaged wires and reioined.	11/11/2024	929780	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	VehService\DS	VehService\DS		11/11/2024	929780	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Chassis\CHAS CRACK	repair cracks in chassis			08/11/2024	929780	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
					at mill to get unloaded Drove to breakdown, inspected area of air leak. Found RHF air bag fitting to have snapped off. Joined new air line to by pass leaking air bag. Advised driver once he was unloaded to come back to workshop for repair. Once arrived, removed airline, removed fitting, Cleaned out dirt and loosened top airbag mount off. Installed new fitting and												
T417	Myrtleford - Workshop	Susp\AIR BAG	FRONT DRIVERS SIDE AIR BAG LEAKING		reconnected airline. tiahtened mountine bolts and tested.	07/11/2024	929780	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Chassis\CHAS CRACK	CHASSIS CRACKED IN FRONT OF 1ST HANGER BOTH SIDES		WELD TRAILER CRACK Arranged JD's to carry out welding repair on trailer crack	01/11/2024	929780	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	VehService\DS	VehService\DS		22/10/2024	929780	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Tyres\TP7+8	Tyres\TP7+8			05/10/2024	929780	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BEAUREPAIRES - 3	TRAILER
T417	Myrtleford - Workshop	Tyres\TP5+6	Tyres\TP5+6			05/10/2024	929780	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BEAUREPAIRES - 3	TRAILER
T417	Myrtleford - Workshop	VehService\DS	VehService\DS	VehService\DS		28/09/2024	929780	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
					Suspected leaking brake booster on Coast RD off the Portland Nelson Road Sourced parts required as described by driver. Travelled to trailer and inspect fault. Found all brake boosters were okay, air line had come off of joiner. Replaced joiner and												
T417	Myrtleford - Workshop	Brakes\BOOSTER	Call out air leak brake booster		refit air line. Checked operation. all okay LOOSE GUARD BRACKETS	17/09/2024	929780	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Chassis\MUDGUARDS	Tighten Loose Guard Brackets. (Barry Maney P/O: L088505)		Unbolted mudguard to access bracket bolts. Cleaned out chassis rail to access nut at the rear. Tensioned all components and checked for movement. All ok. RIDE HEIGHT AIR FITTING LEAKING	03/09/2024	929780	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Susp\HCV	Air Leak At HCV. (Barry Maney P/O: L088505)		On inspection found the elbow fitting at top of ride height to be leaking. Removed fitting & replaced with new & secured. Tested for leaks, all ok.	03/09/2024	929780	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Chassis\AIR TANKS	Air Tank Bolts Loose. (Barry Maney P/O: L088470)		AIR TANK BOLTS LOOSE. Removed deck olates and tiahtened air tank bolts.	01/09/2024	929780	Reoair	Comoleted	Greenfreight Loaaina Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
					SCALES NOT READING CORRECT WEIGHT STRAIGHT AWAY inspect weigh scales operation, found transducer filters												
T417	Myrtleford - Workshop	DrCabElect\SCALES	Scales Not Reading Correct weight Straight Away. (Barry Maney P/O: L088470)		were blocked. Removed filters and cleaned out. reinstalled.	01/09/2024	929780	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	VehService\DS	VehService\DS	VehService\DS		31/08/2024	929780	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Tyres\TP7+8	Tyres\TP7+8			23/08/2024	929780	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BEAUREPAIRES - 3	TRAILER
T417	Myrtleford - Workshop	Tyres\TP5+6	Tyres\TP5+6			23/08/2024	929780	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BEAUREPAIRES - 3	TRAILER
T417	Myrtleford - Workshop	Tyres\TP1+2	Tyres\TP1+2			23/08/2024	929780	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BEAUREPAIRES - 3	TRAILER
T417	Myrtleford - Workshop	Chassis\SCALES	scales un reliable doesnt show correct weight until well after leaving the loading crew SCALES NOT READING CORRECT WEIGHT STRAIGHT AWAY inspect weigh scales operation, found transducer filters were blocked. Removed filters and cleaned out. reinstalled.			23/08/2024	929780	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
			Chassis\AIR FITTIN AIR TANK BOLTS LOOSE.														
T417	Myrtleford - Workshop	Chassis\AIR FITTIN	Removed deck olates and tiahtened air tank bolts			23/08/2024	929780	Reoair	Comoleted	Greenfreight Loaaina Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	VehService\DS	VehService\DS	VehService\DS		20/08/2024	929780	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	VehService\DS	VehService\DS Tyres\Re-Tor	VehService\DS		12/08/2024	929780	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Tyres\Re-Tor	9+10+11+12			05/08/2024	929780	PreventativeMaintenance	Completed	Greenfreight Loaaina Vic	Kennedy	Mt Gambier	STK	699795	BEAUREPAIRES - 3	TRAILER
T417	Myrtleford - Workshop	Tyres\TP9+10	Tyres\TP9+10			02/08/2024	929780	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BEAUREPAIRES - 3	TRAILER
T417	Myrtleford - Workshop	Tyres\TP11+12	Tyres\TP11+12 REPAIR WIRE TO WHEEL SPEED SENSOR ? ABS ? Plugged into trailer and checked codes, found code for LH speed sensor wiring, tested sensor, all okay. Tested wiring from sensor to module, found to have an internal break. R&R cable and tested, all okay. Road tested and all good.			02/08/2024	929780	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BEAUREPAIRES - 3	TRAILER
T417	Myrtleford - Workshop	Brakes\ABS	KW0814004401 EBS HALDEX WSS			31/07/2024	929780	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	PACCAR PARTS FLEET SERVICES - 3	TRAILER
T417	Myrtleford - Workshop	Tyres\TP3+4	Tyres\TP3+4			31/07/2024	929780	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BEAUREPAIRES - 4	TRAILER
T417	Myrtleford - Workshop	VehService\DS	VehService\DS OOSE WIRE IN PLUG AT FRONT OF A TRAILER FOR TAIL LIGHTS Removed trailer plug and inspect wires, all okay. Reconnect trailer plug back into trailer, found to have not connected properly, causing intermittent fault. Wriggled wiring and plug, all okay. <<< Total For Job 1 >>> 85.00Job#	VehService\DS		14/07/2024	929780	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
			2 88Z2222219 CHECK LIGHTS Tech(s):														
T417	Myrtleford - Workshop	Elect\INDICATORS	8098 0.00LH INDICATOR N/W ON BOTH TRAILERS Fault due to trailer plug not being connected properly. All			13/07/2024	929780	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	PACCAR PARTS FLEET SERVICES - 3	TRAILER
T417	Myrtleford - Workshop	Tyres\TP3+4	Tyres\TP3+4 VehService\DS P/O: L086813			29/06/2024	929780	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BEAUREPAIRES - 3	TRAILER
T417	Myrtleford - Workshop	VehService\DS		VehService\DS		21/06/2024	929780	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
			REPLACE LOW BRAKE - RH front brake was past wear limit. Jacked up axle, backed off brake and removed wheels & hub assembly. Replaced clips, checked s-cams & bushes, all okay. Removed brake drum & linings, fit new. Found bearing grease was u/s. Removed bearings, cleaned and repacked with wheel nuts, new grease & seals. Refit hub & wheels, tensioned bearings & float. Adjusted brakes & tensioned														
T417	Myrtleford - Workshop	Brakes\BRK RELINE	PARTS $350.20 / LABOUR $337.50 / CONSUM $16			21/06/2024	929780	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	PACCAR PARTS FLEET SERVICES - 3	TRAILER
T417	Wodonga - Workshop	Susp\SUSPENSION	REPLACE MISSING BOLT LH REAR AIR BAG BASE		Lift trailer and drop air out of air bags. Removed base plate for LH rear air bag. Removed broken stud, cleaned up threads & reinst	06/06/2024	929780	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		06/06/2024	929780	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Wodonga - Workshop	Elect\TAIL LIGHT	LH NUMBER PLATE LIGHT		Checked power and earth at light, all okay. Removed light & wired in new light. Checked operation, all okay.	06/06/2024	929780	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Wodonga - Workshop	DrivLine\WHEEL BRGS	JACK UP & CHECK REAR WHEEL BEARINGS		Lifted rear axle, removed hub caps & adjusted axle nuts. Refit caps and lowered axle.	06/06/2024	929780	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service PO # L048361	VehService\DS		04/06/2024	929780	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Chassis\BOLSTER	REPLACE BOLSTER BOLTS		Found bolster bolts were loose & would not tighten. Cut off bolts, installed new bolt and nut, tightened to spec.	31/05/2024	929780	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER

T417	Myrtleford - Workshop	Body\MUDGUARDS	REAR BACK DRIVER SIDE BOLT OUT OF M/GUARD SUPPORT - Installed new bolt into guard pole & tightened. PART $4. | LABOUR $108 CHECK WHEEL BEARINGS FRONT AXLE - Jacked up front axle, removed hub nut & adjusted bearing to spec. Refit hub cap and tightened. Repeat for both sides on front axle. BINDERS LEAKING - Sprayed soapy water around binder roller, hoses and tap. no leaks. D Service As Per Attached Checklist			20/05/2024	909771	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	PACCAR PARTS FLEET SERVICES - 3	TRAILER
T417	Myrtleford - Workshop	VehService\DS	P/O L085796	VehService\DS		07/05/2024	920765	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Body\MUDGUARDS	FAR BACK DRIVER SIDE BOLTOUT OF MUDGUARD SUPPORT.			07/05/2024	920765	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			07/05/2024	920765	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Chassis\EXTE TU	FIRST STAP SPINDLE NOT WORING ALWAYS.			07/05/2024	920765	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Elect\WORK LIGHT	MISSING WORK LIGHT - Found RH rear work light not working. Removed light & tested power & earth all okay. Installed new light, joined wiring. D Service As Per Attached Checklist			19/04/2024	909771	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	VehService\DS	PO# L085416	VehService\DS		19/04/2024	929780	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			19/04/2024	929780	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Elect\TRL LIGHTS	FRONT RH CLEARANCE LIGHT N/W - LOOSE WIRING - Found broken wire and wires hanging down. re join wirine and re secure wirine. Check operation all okay. WHEEL STUD LOOSE - Lift axle, remove front L hand wheels, remove hub and drum. Inspect hub Parts $51.96 | Labour $607.50 and found 1 wheel stud spinning and 2 damaged. Replaced studs, Removed bearings and cleaned and re pack. Fit seal and re fit hub to axle, tension hub nut to spec, adjust brake, tension wheel nuts.			20/03/2024	899452	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Steering\WHEEL STUD	Monitor studs to ensure they don't spin again,re check at next service.			16/03/2024		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Albury Workshop	TRAILER
T417	Myrtleford - Workshop	Tyres\TP1+2	Tyre Position 1 + 2			16/03/2024		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Albury Workshop	TRAILER
T417	Myrtleford - Workshop	Tyres\TP07	Tyre Position 7			16/03/2024	899446	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist			16/03/2024	899446	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	VehService\DS	PO# L084695	VehService\DS		16/03/2024	899446	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Susp\AIR LEAK	AIR LEAK DRIVER SIDE ABOVE LAST AIRBAG AGAIN. 3 x AIR LEAKS. *MAJOR* 1x AIR LINE AT FRONT 1x AIR LINE ANT MIDDLE		AIR LEAKS - Found two air leaks from rubbed air lines & leaking fittings. Disconnect length to RH air bag, cut out length & joined in new. Also replaced rubbed section at height control valve. Built up air and tested, all okay. CHECK & REPAIR AIR LEAKS - inspected trailer for air leaks, used pictures supplied for reference. Found 2 X 3/8 T joiners next to scales module to be leaking. Removed & replaced joiners, re tested for leaks. Found RH rear airbag airline to be leaking, cut rubbed section out & installed 3/8 push joiner.	07/03/2024	896363	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Brakes\AIR LEAK	1x AIR LINE AT BACK DRIVER SIDE.		Re tested all okay. Found scales airline to be crimped. removed & reolaced with new air line all okay.	28/02/2024	894371	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist			21/02/2024		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	VehService\DS	PO# L084199	VehService\DS		21/02/2024		Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Chassis\SPAREWHEEL	SPARES & RACKS OFF.			21/02/2024	892644	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Elect\WORK LIGHT	WORK LIGHTS ON A&BTRAILER ONLY WORK SOMETIMES.		WORK LIGHTS ON TRAILERS ONLY WORK SOMETIMES - Remove light plug from truck to A trailer found to have contamination. Cleaned out plug with contact cleaner, reconnect. Tested lights, ok.	21/02/2024	892644	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Body\MUDGUARDS	BACK DRIVER SIDE MUDGUARD LOOSE.		RH REAR MUD GUARD LOOSE - Unbolt RH rear mud guard, tightened bracket. Refit mudguard with new nuts. bolts. washers.	21/02/2024	892644	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Wodonga - Workshop	Tyres\TP5+6	Tyre Position 5 + 6			09/02/2024		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Albury Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist			07/02/2024	880819	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	VehService\DS	PO# L083881	VehService\DS		07/02/2024	880819	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Elect\ELECT P&W	R/H FRONT CLEARANCE LIGHT BASE WIRE. This job was done on entry183349 job 430496. R/H FRONT CLEARANCE LIGHT BASE WIRE.			07/02/2024	880819	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Elect\TRL LIGHTS	BOLSTER LIGHTS N/W - Found both bottom lights on the log rack n/w, test for power at the first light and found no power. Inspect wiring & found broken wire, cut out damaged section of wiring & check operation all working found one light n/w. Remove & reolace light all okay.		LEAKING AIR BAGS rh FRONT & rh REAR - Support trailer and drained air, removed both deck plates & clean debris from rails. Cut air lines & removed front air bag. Replaced air fittings & installed new air bag. Access rear air bag, had to cut stud off & removed loom to access air bag bolt. Removed air bag, replaced fittings & installed new. Found rubbed air lines to booster and height control valve. Removed air lines & installed new length & joined as required. Test, no leaks.	07/02/2024	880819	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Susp\AIR BAG	FRONT DRIVER SIDE AIRBAG LEAKING. BACK DRIVER SIDE AIRBAG BASE DAMAGED.			19/01/2024	870438	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Albury Workshop	TRAILER
T417	Myrtleford - Workshop	Chassis\AIR LEAK	AIR LINES LEAKING.			19/01/2024	870438	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Albury Workshop	TRAILER
T417	Myrtleford - Workshop	Elect\ELECT P&W	LIGHT BAR LIGHTS HAD RUBBED WIRES - Inspect light bar issue, cut cable ties and removed covering, locate rubbed wires. Repaired rubbed wires & resecured.			19/01/2024	870438	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Albury Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist			19/01/2024	870438	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	VehService\DS	PO# L083433	VehService\DS		19/01/2024	870438	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Chassis\SPAREWHEEL	SPARES & RACKS OFF.			19/01/2024	870438	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Chassis\EXTE TU	AIR BINDERS NEED ATTENTION.			19/01/2024	870438	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Unknown				19/01/2024	870438	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Chassis\BOLSTER	FRONT BOLSTER RATCHET- CUT OFF?		CHAINS TO BE SHORTENED - First bolster chain was too long & was missing the ratchet. Cut chain down to correct length. Sourced new D shackles and ratchet. Installed ratchet & connect chain to ratchet. Azolied tension to bolster. checked securitv. all okav.	13/12/2023	860633	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Albury Workshop	TRAILER
T417	Myrtleford - Workshop	Susp\AIR LEAK	REPAIR AIR LEAKS - Locate all air leaks. Found numerous fittings leaking. Removed fittings that were unserviceable & replaced with new. Applied sealant to fittings & refit as required. Air line from		A to B trailer had numerous rubs. Disconnect air line, cut & measured new length of hose, installed with new fittings. Tested operation, no further leaks.	13/12/2023	860633	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Albury Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist			09/12/2023	860633	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	VehService\DS	PO# L082831	VehService\DS		09/12/2023	860633	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Brakes\AIR FITTIN	AIR LINE (RED) BETWEEN A & B NEEDS REPLACING.DONE ON INVOICE 373274. AIR LINE (RED) BETWEEN A & B NEEDS REPLACING.		AIR LEAK IN BETWEEN TRAILERS ON CHASSIS & IN FRONT OF AIR TANK ON TRAILER Inspect trailer for air leaks as described by driver. Found RH booster had a loose fitting & LH service line on module was loose. Dropped air from truck and trailer. Disconnect both air lines and removed fittings. Tidy up ends of air lines, cleaned up fittings and applied thread sealant and refit to air line.	08/12/2023	858205	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Brakes\AIR LEAK	AIR LEAKS ON A & B AS PER PHOTOS.		Reconnect air lines and tahten fittinas. Secured hose clamps. all okav.	08/12/2023	858205	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Albury Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes\BOOSTER	DRIVERS SIDE BOOSTER LEAKING		Inspect all brake booster for leak as advised. Could not fault any boosters. Activated service brake, found leak at ABS module. Tighten loose hose clamp, all okay.	30/11/2023	851578	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Body\MUDGUARDS	MUDFLAP BRACKET ADD WIRE TO STOP IT HITTING WHEEL		Found mud flap was missing anti sail bracket on front. Undo bolts & removed mud flao. reinstalled with anti sail bracket. tightened bolts.	30/11/2023	851578	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			29/11/2023		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Chassis\SPAREWHEEL	SPARES & RACKS OFF.			29/11/2023		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		29/11/2023		Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Tyres\TP3+4	replace tyres			25/11/2023	847805	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Body\MUDGUARDS	WHEEL GUARDS REPLACED.(guards were replace under roo damage). WHEEL GUARDS REPLACED.		Undo mounting bolts and removed guard. Grind back surface, re-welded the pole back on & fit the flat plate to the back of the pole for support.	21/11/2023	845717	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Body\DAMAGE	WELD MUD GUARD BRACKET AFTER HITTING ROO		Once all welded, placed guard & mudflap on, secured with new bolts.	21/11/2023	845717	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Brakes\BOOSTER	DRIVER SIDE BOOSTER LEAKING-A TRAILER.(loose booster hose clamps). DRIVER SIDE BOOSTER LEAKING-A TRAILER.			08/11/2023	840799	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Unknown\EBS FAULTS	BRAKES LOCKING UP WHEN TURNING RIGHT.(check brake adjustment and test all ok). BRAKES LOCKING UP WHEN TURNING RIGHT.		LH FRONT & RH MIDDLE PIVOT BUSHES WORN - Undo ubolts & pivot bolts, lowered out spring. pressed out worn bush, cleaned surfaces & installed new. Lift spring into axle, refit u bolts & pivot bolts.	08/11/2023	840799	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Susp\SPRING HANG	LHF & RHM spring eye bushes U/S.		Tensioned all comoonents.	08/11/2023	840799	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Hydraulics\RAM	LH RAM LEAKING. DRIVER SIDE FRONT BOLSTER LEAKING.		LH RAM LEAKING ON TRAILER - inspect all trailer rams, no air or oil leaks.	08/11/2023	840799	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Brakes\BOOSTER	AS PER PHOTOS SENT.		RH FRONT BOOSTER LEAKING - Found loose hose clamps, tightened clamps, all okay.	08/11/2023	840799	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Chassis\WINCH/STRP	REPLACE x2 WINCH STRAPS - Inspected winch straps & found both were worn. Replaced both straps & tested binder operation. all okav.			08/11/2023	840799	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist			08/11/2023		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	VehService\DS	PO# L082140	VehService\DS		08/11/2023		Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Tyres\TP7+8	Tyre Position 7 + 8			03/11/2023		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Albury Workshop	TRAILER
T417	Myrtleford - Workshop	Tyres\TP9+10	Tyre Position 9 + 10			03/11/2023		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Albury Workshop	TRAILER
T417	Myrtleford - Workshop	Tyres\TP11+12	Tyre Position 11 + 12			03/11/2023		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Albury Workshop	TRAILER
T417	Albury - Workshop	Chassis\WINCH/STRP	REPLACE QUICK RELEASE CABLE FRONT WINCH.		REPAIR RELEASE CABLES - Removed front binder cable & removed front panel off trailer. Feed the wire through & looped cable ends. Tested operation, reinstalled front panel. Removed cable from B trailer. Fit new cable. crimos and handle.	27/10/2023		Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Albury Workshop	TRAILER
T417	Albury - Workshop	Chassis\EXTE TU	FRONT WINCH HOOK FOR "D" NEEDS TO BE REPLACED.			27/10/2023		Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Albury Workshop	TRAILER
T417	Albury - Workshop	Chassis\WINCH/STRP	RELEASE CABLES REPLACED.			27/10/2023		Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Albury Workshop	TRAILER
T417	Albury - Workshop	Body\MUDGUARDS	LH FRONT MUD GUARD - Removed guard. Measure and drilled holes in new guard, installed. Fitted with new mud flao and bracket. WORK LIGHT N/W - Inspected for power, no power found. Found adaptor wiring had to be changed. Altered wiring and rechecked. Light still not working, faulty light. No lights in stock, need to replace next service			27/10/2023		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Albury Workshop	TRAILER
T417	Albury - Workshop	Elect\WORK LIGHT				27/10/2023		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Albury Workshop	TRAILER
T417	Wodonga - Workshop	Elect\ELECT P&W	AFTER FINDING SUITABLE TRUCK. HOOKED UP I417/211 IN LOG YARD. NO BRAKE LIGHTS ON B TRAILER. TESTED PLUG. DIAGNOSED AND REPAIRED WIR			20/10/2023		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Wodonga Workshop	TRAILER
T417	Albury - Workshop	Tyres\PRES CHECK	1-12			19/10/2023		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Albury Workshop	TRAILER
T417	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		TIGHTENED LH OUTRIGGER.	20/09/2023		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Wodonga Workshop	TRAILER
T417	Wodonga - Workshop	Brakes\EBS FAULTS	BRAKES LOCKING UP WHEN TURNING RIGHT.			20/09/2023		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Wodonga Workshop	TRAILER
T417	Wodonga - Workshop	Chassis\WINCH/STRP	REPLACE QUICK RELEASE CABLE FRONT WINCH.			20/09/2023		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Wodonga Workshop	TRAILER
T417	Wodonga - Workshop	Chassis\EXTE TU	FRONT WINCH HOOK FOR "D" NEEDS TO BE REPLACED.			20/09/2023		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Wodonga Workshop	TRAILER
T417	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		20/09/2023		Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Wodonga Workshop	TRAILER
T417	Albury - Workshop	Tyres\TP06	Tyre Position 6			16/09/2023		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Albury Workshop	TRAILER
T417	Albury - Workshop	Tyres\RUN OUT	3-4			14/09/2023		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Albury Workshop	TRAILER
T417	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			06/09/2023		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Wodonga Workshop	TRAILER
T417	Albury - Workshop	Chassis\BOLSTER	CRACKS IN BOLSTER MOUNTS.			06/09/2023		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Wodonga Workshop	TRAILER
T417	Albury - Workshop	Chassis\CHAS CRACK	CRACKS AT PIVOTS.			06/09/2023		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Wodonga Workshop	TRAILER
T417	Albury - Workshop	Susp\SHOCK ABS	All 6 x shocks loose.			06/09/2023		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Wodonga Workshop	TRAILER
T417	Albury - Workshop	Susp\SPRING HANG	LHF & RHM spring eye bushes U/S.			06/09/2023		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Wodonga Workshop	TRAILER
T417	Albury - Workshop	Brakes\EBS FAULTS	BRAKES LOCKING UP WHEN TURNING RIGHT.			06/09/2023		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Wodonga Workshop	TRAILER
T417	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		06/09/2023		Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Wodonga Workshop	TRAILER
T417	Albury - Workshop	Hydraulics\RAM	LH RAM LEAKING.			06/09/2023		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Wodonga Workshop	TRAILER
T417	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			24/08/2023		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Wodonga Workshop	TRAILER
T417	Wodonga - Workshop	Chassis\BOLSTER	CRACKS IN BOLSTER MOUNTS.			24/08/2023		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Wodonga Workshop	TRAILER
T417	Wodonga - Workshop	Chassis\CHAS CRACK	CRACKS AT PIVOTS.			24/08/2023		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Wodonga Workshop	TRAILER
T417	Wodonga - Workshop	Susp\SHOCK ABS	All 6 x shocks loose.			24/08/2023		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Wodonga Workshop	TRAILER
T417	Wodonga - Workshop	Susp\SPRING HANG	LHF & RHM spring eye bushes U/S.			24/08/2023		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Wodonga Workshop	TRAILER
T417	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		24/08/2023		Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Wodonga Workshop	TRAILER
T417	Wodonga - Workshop	Brakes\AIR LEAK	FIX BLOWN BRAKE LINE.		REPAIRED RF HOSE FALLING OFF.	22/08/2023		Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Wodonga Workshop	TRAILER
T417	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			03/08/2023		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Wodonga Workshop	TRAILER
T417	Wodonga - Workshop	Chassis\BOLSTER	CRACKS IN BOLSTER MOUNTS.			03/08/2023		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Wodonga Workshop	TRAILER
T417	Wodonga - Workshop	Chassis\CROSS MBR	CROSSMEMBER CRACKS.		Could not Fault.	03/08/2023		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Wodonga Workshop	TRAILER
T417	Wodonga - Workshop	Chassis\CHAS CRACK	CRACKS AT PIVOTS.			03/08/2023		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Wodonga Workshop	TRAILER
T417	Wodonga - Workshop	Brakes\BRAKE ADJ	BRAKES NEED ADJUSTING.			03/08/2023		Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Wodonga Workshop	TRAILER
T417	Wodonga - Workshop	Brakes\AIR LEAK	AIR LEAK FRONT AXLE?		Could not fault	03/08/2023		Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Wodonga Workshop	TRAILER
T417	Wodonga - Workshop	Body\MUDGUARDS	TIGHTENED RHR GUARD BRACKET.			03/08/2023		Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Wodonga Workshop	TRAILER
T417	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		03/08/2023		Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Wodonga Workshop	TRAILER
T417	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP		03/08/2023		PreventativeMaintenance	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Wodonga Workshop	TRAILER

T417	Wodonga - Workshop	Susp\SHOCK ABS	All 6 x shocks loose.				03/08/2023		Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Susp\SPRING HANG	LHF & RHM spring eye bushes U/S.				03/08/2023		Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Myrtleford - Workshop	Brakes\AIR LEAK	repair brake air line			fit air line to air fitting	13/07/2023	800838	Fault	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Myrtleford Workshop		TRAILER
			Chassis has welds that are cracked (around folding area and no. 2 bolster) As per defect notice HVND653577 Part Inspection Required. (Border Truck Repairs)																
T417	Wodonga - Workshop	Insp\DEFECT	Purchase Order Number: T080055				18/05/2023		Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Elect\ELECT P&W	DIAGNOSED AND REPAIRED WIRING TO RH INDICATOR. REPLACED REAR AND 2ND BOLSTER CLEARANCE LIGHTS.				03/05/2023		Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Brakes\EBS FAULTS	TRAILER ABS FAULTS.			INSPECTED. CHECKED FUSES. DIAGNOSED AND PLUGGED 1B SENSOR LEAD CORRECTLY. CLEARED CODES. TEST DROVE. STILL HAS FAU	03/05/2023		Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				05/04/2023		Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Chassis\BOLSTER	CRACKS IN BOLSTER MOUNTS.				05/04/2023		Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Chassis\CROSS MBR	CROSSMEMBER CRACKS.				05/04/2023		Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Chassis\CHAS CRACK	CRACKS AT PIVOTS.				05/04/2023		Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Brakes\BRAKE ADJ	BRAKES NEED ADJUSTING.				05/04/2023		Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			05/04/2023		Service	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP			05/04/2023		PreventativeMaintenance	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
			DURING SERVICE FOUND 2ND BOLSTER LIGHTS NOT WORKING. - Inspect and found wiring missing. - Run new wiring to bolsters and connect to lights.																
T417	Wodonga - Workshop	Elect\TRL LIGHTS	- Test ooeration. all ok Repair Trailer Light Fault/s (Hagan's)				05/04/2023		Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Elect\TRL LIGHTS	Purchase Order Number: WW077569				30/03/2023	929780	Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Elect\ELECT P&W	INSPECTED LIGHT ISSUE. REPLACED SOCKET.				29/03/2023		Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				25/03/2023		Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Elect\WORK LIGHT	Work Lights not working.			HAGANS REPAIRED.	25/03/2023		Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			25/03/2023		Service	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
			NO CLEARANCE, BRAKE OR TAIL LIGHTS.																
T417	Wodonga - Workshop	Elect\ELECT P&W	HAGANS REPAIRED.				25/03/2023		Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Chassis\BOLSTER	CRACKS IN BOLSTER MOUNTS.				25/03/2023		Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Chassis\CHAS CRACK	CRACKS AT PIVOTS.				25/03/2023		Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Chassis\CROSS MBR	CROSSMEMBER CRACKS.				25/03/2023		Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				08/02/2023		Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Body\MUDGUARDS	REAR GUARD LOOSE.				08/02/2023		Fault	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			08/02/2023		Service	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
			CHECK BRAKE LIGHTS SHORTING ON TRAILERS TRAVEL TO GF YARD AND FOUND BRAKE LIGHTS WORKING COULD NOT FAULT																
			OVER LOOK WIRE AND FOUND SHORT AT REAR OFF A TRAILER																
T417	Albury - Workshop	Elect\BRK LIGHT	REPAIR AND TEST FOUND ALL OK PACK UP AND TRAVEL BACK				02/02/2023		Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Albury Workshop		TRAILER
T417	Wodonga - Workshop	Elect\ELECT P&W	NO LIGHTS.			DIAGNOSED AND REPAIRED EARTH IN SOCKET.	21/01/2023		Fault	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Elect\BRK LIGHT	NO BRAKE LIGHTS.				21/01/2023		Fault	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Elect\ELECT P&W	BLOWING BRAKE FUSE.				21/01/2023		Fault	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				20/01/2023		Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Elect\ELECT P&W	NO REVERSE/ WORK LIGHTS				20/01/2023		Fault	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			20/01/2023		Service	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Body\MUDGUARDS	REAR R/H OUTRIGGER LOOSE.				21/12/2022		Fault	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Elect\WORK LIGHT	NO WORK LIGHTS.				21/12/2022		Fault	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Elect\ELECT P&W	replace scale plug				21/12/2022		Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				14/12/2022		Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			14/12/2022		Service	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Albury - Workshop	Tyres\TP3+4	Tyre Position 3 + 4				09/12/2022		Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Albury Workshop		TRAILER
T417	Albury - Workshop	Tyres\TP7+8	Tyre Position 7 + 8				09/12/2022		Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Albury Workshop		TRAILER
T417	Wodonga - Workshop	Chassis	CHASSIS WEBBING CRACKED AT RR OUTRIGGER. R/H REAR GUARD LOOSE. (DEFECTED BY NHVR) SEE JAMES.			MADE FISH PLATE, DRILLED AND WELDED TO WEBBING.	07/12/2022	752090	Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Insp\DEFECT	DEFECT NUMBER DE616726. R/H REAR GUARD LOOSE. (DEFECTED BY NHVR) SEE JAMES.			DEFECT SELF CLEARING	07/12/2022	752090	Fault	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				02/12/2022		Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			02/12/2022		Service	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Chassis	CHASSIS WEBBING CRACKED AT RR OUTRIGGER.				02/12/2022		Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				30/11/2022		Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Body\PANELS	FRONT PLATE COME LOOSE. SHORTING BLINKERS.			WELDED NEW MOUNT PLATE. TAPPED BOLT HOLES. SECURED LIGHT PLATE.	30/11/2022		Fault	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Body\PANELS	FRONT PLATE LOOSE.				30/11/2022		Fault	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			30/11/2022		Service	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Albury - Workshop	Tyres\TP9+10	Tyre Position 9 + 10				26/11/2022		Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Albury Workshop		TRAILER
T417	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				25/11/2022		Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			25/11/2022		Service	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Albury - Workshop	Tyres\TP11+12	Tyre Position 11 + 12 REPAIR REAR R/H GUARD.				22/11/2022		Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Albury Workshop		TRAILER
T417	Albury - Workshop	Body\MUDGUARDS	OUTRIGGER CHASSIS WEBBING CRACKED.				21/11/2022	929780	Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Albury Workshop		TRAILER
T417	Wodonga - Workshop	Body\MUDGUARDS	REPAIR REAR R/H GUARD.			BOLTED TO MUDFLAP. TEMPORARY FIX.	17/11/2022		Fault	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				15/11/2022		Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
						REQUIRED NEXT SERVICE - Multiple mudguards damaged/loose - Front and rear walkways missing bolts/cracked - Front connector plate missing bolts														
			D Service As Per Attached Checklist - Replaced broken reflectors as required.			- RHR air bag has damaged pedestal													
T417	Wodonga - Workshop	VehService\DS	- Moisture in air tanks. Drained - Attempt to tension bolt, found seized. - Remove mudguard and walkway for access. - Cut seized bolt and fit new bolt.	VehService\DS		- LHR bolster is cracked at mounts	15/11/2022		Service	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Body\MUDGUARDS	- Refit walkway and mudguard.				15/11/2022		Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				10/11/2022		Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			10/11/2022		Service	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			29/10/2022		Service	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				29/10/2022		Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			21/10/2022		Service	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				21/10/2022		Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				14/10/2022		Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
			BUSHES SECOND BOLSTER WORN OUT. METAL ON METAL.			- Disconnect and move bolster for access. - Remove and install bushes as required.													
T417	Wodonga - Workshop	Chassis\BOLSTER	2ND BOLSTER PIVOT BUSHES WORN. BUSHES SECOND BOLSTER WORN OUT. METAL ON METAL.			- Refit bolster and check movement, all ok	14/10/2022		Fault	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Body\MUDGUARDS	DURING SERVICE FOUND AXLE 2 & 3 MUDGUARDS CRACKED/BROKEN BOTH SIDES				14/10/2022		Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
			D Service As Per Attached Checklist			- Replace missing/broken reflectors as required. - Replace missing backing plates.													
T417	Wodonga - Workshop	VehService\DS	CARRY OUT GREENFREIGHT LOG TRAILER D-SERVICE AS PER ATTACHED SERVICE SHEET.	VehService\DS		- Adjust wheel bearings as required and replace 1x seized cap	14/10/2022		Service	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Brakes\BACK PLATE	INSPECTED BRAKE COVERS FOR PART NUMBERS. PARKED. REPLACED BALLRACE BLOCK BOLTS.				08/10/2022	708835	Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			28/09/2022	929780	Service	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				28/09/2022	929780	Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Brakes\BRK RELINE	RELINE MIDDLE AXLE.				28/09/2022	929780	Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Brakes\BRK RELINE	Brake reline due both middle axles and RHR axle. ABS SLOWING ME DOWN INTERMITTENTLY.				28/09/2022	929780	Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Brakes\EBS FAULTS	(DIAGNOSED 1B CONTINUITY FAULT.)				28/09/2022	929780	Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Brakes\BRK RELINE	RELINE MIDDLE AXLE.				28/09/2022	929780	Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Albury - Workshop	Tyres\TP1+2	supply and fit 4 tyres				22/09/2022		Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Albury Workshop		TRAILER
T417	Albury - Workshop	Tyres\TP5+6	Tyre Position 5 + 6				22/09/2022		Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Albury Workshop		TRAILER
T417	Albury - Workshop	Susp\AXLES	TCTC supply parts				09/09/2022	929780	Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Albury Workshop		TRAILER
T417	Wodonga - Workshop	Body\MUDGUARDS	REPAIRED LR GUARD OUTRIGGER.				19/08/2022	703033	Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				12/08/2022		Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		REPIRED AIR LEAKS. REPLACED FRONT AXLE CABLES.	12/08/2022		Service	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Brakes\BRK RELINE	RELINE MIDDLE AXLE.				12/08/2022		Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Chassis\HOUSEKEEP	surce fitting plate			DRILLED AND TAPPED ALL HOLES AND FITTED.	03/08/2022		Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Chassis\MUDGUARDS	mudflap bracket broken				03/08/2022		Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Body\PANELS	FRONT AIR LINE PLATE FLOPPING AROUND.				03/08/2022		Fault	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Body\MUDGUARDS	REAR LEFT GUARD OUTRIGGER BROKEN OFF.				03/08/2022		Fault	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Brakes\EBS FAULTS	ABS SLOWING ME DOWN INTERMITTENTLY.			1B CONTINUITY FAULT. TRAILER LOADED.	27/07/2022		Fault	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				16/07/2022		Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			16/07/2022		Service	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				10/06/2022		Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Brakes\BRK RELINE	Brake reline due both middle axles and RHR axle.				10/06/2022		Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			10/06/2022		Service	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				04/06/2022	670569	Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Brakes\BRAKE ADJ	BRAKE ADJUSTMENT.				04/06/2022	670569	Fault	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		REPAIRED WIRING TO 1ST AND 2ND BOLSTERS.	04/06/2022	670569	Service	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Brakes\BRK RELINE	RELINE MIDDLE AXLE.				04/06/2022	670569	Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Elect\WORK LIGHT	WORK LIGHTS COMING ON WITH L/H INDICATOR.			FOUND WIRING TO B TRAILER COME APART. REPARED WIRING. TESTED. PARKED.	26/05/2022	338296	Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				21/05/2022	663069	Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Susp\HCV	REPLACE WORN HCV.				21/05/2022	663069	Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Chassis\FIFTH WHEE	REPLACE WORN BALL RACE.				21/05/2022	663069	Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		REPLACED MISSING LF AIRBAG MOUNT BOLT.	21/05/2022	663069	Service	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				12/05/2022		Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			12/05/2022		Service	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Elect\ELECT P&W	NO A OR B TRAILER LIGHTS.			TRAILER LIGHTS TRIPPING FUSE. FOUND AND REPAIRED RUBBED WIRES ON 2 BOLSTERS.	27/04/2022		Fault	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Comply\Truck Safe	NO NHVAS STICKER				27/04/2022		Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Elect\ELECT P&W	WORK LIGHTS DULL			REPLACED DAMAGED 7-PIN SOCKET AND REAR WORK LIGHTS.	01/04/2022		Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				31/03/2022	645127	Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		REPLACED LF, LM BOOSTERS AND AIR LINES.	31/03/2022	645127	Service	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Elect\INDICATORS	INDICATORS NOT WORKING.			#376533	26/03/2022		Fault	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Elect\ELECT P&W	ELECTRICAL PLUG BROKEN.			REPLACED TRAILER PLUG THAT WAS RIPPED OUT. RE-ROUTE HARNESS TO PLUG TO HOPEFULLY CLEAR BETTER.	12/03/2022		Fault	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Albury - Workshop	Tyres\TP11	PUNCTURE REPAIR				08/03/2022		Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Albury Workshop		TRAILER
T417	Albury - Workshop	Tyres\TP9+10	supply and fit 2tyres				04/03/2022		Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Albury Workshop		TRAILER
T417	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				24/02/2022		Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			24/02/2022		Service	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP			24/02/2022		PreventativeMaintenance	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Myrtleford - Workshop	Chassis\FIFTH WHEE	TCTC BALL RACE-DOUBLE ROW-UN				14/02/2022	929780	Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Myrtleford Workshop		TRAILER
T417	Myrtleford - Workshop	Chassis\FIFTH WHEE	Aldonga Eng. Drill holes in turntable roller and fit 10 hours				14/02/2022	929780	Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Myrtleford Workshop		TRAILER
T417	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				09/02/2022	626676	Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop		TRAILER
T417	Wodonga - Workshop	Susp\SHOCK ABS	LHR SHOCK MISSING AND BOTTOM MOUNT SNAPPED				09/02/2022	626676	Repair	Completed	Greenfreight Logging Vic	Kennedy		Mt Gambier	STK	699795	Wodonga Workshop

T417	Woolonga - Workshop	Comp\Truck Safe	NO NHVAS STICKER			09/02/2022	626676	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Body\MUDGUARDS	REPLACED BROKEN RR MUDGUARD OUTRIGGER BOLT. SECURED MUDGUARD.			09/02/2022	626676	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Chassis\FIFTH WHEE	REPLACE WORN BALL RACE.			09/02/2022	626676	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Brakes\BRK RELINE	RELINED LR RF LF. CLEANED AND REPACKED LR WHEEL BEARINGS.			09/02/2022	626676	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Chassis\EXTE TU	REPLACED DAMAGED LOAD STRAP AND BARREL AN FIRST WINCH. PARKED.			08/02/2022		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Elect\ELECT P&W	SCALES NOT WORKING		ISOLATED FAULT TO LOOM FROM A SLAVE TO B TRAILER. DIAGNOSED AND RE-SOLDERED CONNETOR TO B TRAILER. TESTED.	02/02/2022		Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Brakes	Record Check Results As Attached To This Job			22/01/2022		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Susp\SHOCK ABS	LR SHOCK MOUNT SNAPPED. SHOCK MISSING.			22/01/2022		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Brakes\BRK O/HAUL	broken shocker bolt LH rear			22/01/2022		Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Brakes\ABS	EBS PULLING ON AT THE DROP OF A HAT			22/01/2022		Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Brakes\EBS FAULTS	EBS LOCKS UP EASY ON LHS BACK 2 AXLES			22/01/2022		Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Elect\ELECT P&W	NO SCALES		FOUND AND REPAIRED BARE WIRE SHORTING SCALES OUT.	22/01/2022		Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Elect\ELECT P&W	NO SCALES			22/01/2022		Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		22/01/2022		Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Chassis\BOLSTER	REPAIRED 2ND BOLSTER CRACKS			22/01/2022		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Brakes	Record Check Results As Attached To This Job			07/01/2022	615137	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	UNHOOK FROM 877, HOOK UP TO 929. MAKE UP ADAPTER LEAD FOR TRAILER PLUG.	07/01/2022	615137	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Brakes	Record Check Results As Attached To This Job			11/12/2021		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Brakes\BRK O/HAUL	broken shocker bolt LH rear			11/12/2021		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Brakes\ABS	EBS PULLING ON AT THE DROP OF A HAT			11/12/2021		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Brakes\EBS FAULTS	EBS LOCKS UP EASY ON LHS BACK 2 AXLES			11/12/2021		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Brakes\AIR LEAK	REPAIR AIR LINE TO BRAKE BOOSTER			11/12/2021		Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Elect\ELECT P&W	NO SCALES			11/12/2021		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	TIGHTENED OUTRIGGER BOLTS AND GUARD BRACKETS.	11/12/2021		Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Brakes	Record Check Results As Attached To This Job			02/12/2021		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Brakes\AIR LEAK	REPAIR AIR LINE TO BRAKE BOOSTER			02/12/2021		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		02/12/2021		Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Susp\SHOCK ABS	LR SHOCK MOUNT SNAPPED. SHOCK MISSING.			02/12/2021		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Brakes\BRK RELINE	REPLACED RR BRAKES			02/12/2021		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Workshop\MOVE ASSET	ASSIST HOOK UP. CLEAN UP.			02/12/2021		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Body\STRAPS	Replace pos 1 winch siezed			26/11/2021		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Chassis\EXTE TU	REPLACE POS 1 WINCH EXTE TU.			26/11/2021		Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Brakes\EBS FAULTS	EBS LOCKS UP EASY ON LHS BACK 2 AXLES			24/11/2021		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Brakes	Record Check Results As Attached To This Job			23/11/2021	598418	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Brakes\BRK O/HAUL	broken shocker bolt LH rear EBS PULLING ON AT THE DROP OF A HAT			23/11/2021	598418	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Brakes\ABS	CANNOT TEST, DIAGNOSTIC UNIT IN ROSEWOOD. EBS LOCKS UP EASY ON LHS BACK 2 AXLES.			23/11/2021	598418	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Brakes\EBS FAULTS	CANNOT TEST. DIAGNOSTIC UNIT IN ROSEWOOD.			23/11/2021	598418	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Body				23/11/2021	598418	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Body				23/11/2021	598418	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		23/11/2021	598418	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Brakes	Record Check Results As Attached To This Job			16/11/2021	593254	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Susp\SHOCK ABS	LHR SHOCK MISSING AND BOTTOM MOUNT SNAPPED			16/11/2021	593254	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Brakes\BRK O/HAUL	broken shocker bolt LH rear			16/11/2021	593254	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Brakes\ABS	EBS PULLING ON AT THE DROP OF A HAT			16/11/2021	593254	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Brakes	BRAKES ARE SHIT			16/11/2021	593254	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Brakes\EBS FAULTS	EBS LOCKS UP EASY ON LHS BACK 2 AXLES			16/11/2021	593254	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	REPAIRED AIR LEAKS IN CHASSIS RAIL.	16/11/2021	593254	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Unknown	DUE FOR A SERVICE			16/11/2021	593254	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Brakes\AIR LEAK	HAD AIR LEAK FRONT AXLE I FIXED IT BUT HAVE A LOOK PLEASE		REPLACED RUBBED AIR HOSES	10/11/2021		Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Brakes	Record Check Results As Attached To This Job			07/11/2021		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Chassis\BOLSTER	2nd bolster LH inside hinge cracked.			07/11/2021		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Susp\SHOCK ABS	LHR SHOCK MISSING AND BOTTOM MOUNT SNAPPED			07/11/2021		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Elect\WORK LIGHT	No work lights			07/11/2021		Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Elect\WORK LIGHT	No work lights.			07/11/2021		Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Chassis\BOLSTER	Front bolster leaking oil.			07/11/2021		Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Elect\WORK LIGHT	No work lights.			07/11/2021		Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Elect\WORK LIGHT	No work lights.			07/11/2021		Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		07/11/2021		Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Unknown	DUE FOR A SERVICE			07/11/2021		Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Albury - Workshop	Tyres\TP9+10	supply and fit 4 tyres			31/10/2021	SB1322	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Albury Workshop	TRAILER
T417	Albury - Workshop	Tyres\TP11+12	Tyre Position 11 + 12			31/10/2021	SB1322	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Albury Workshop	TRAILER
T417	Woolonga - Workshop	Brakes	Record Check Results As Attached To This Job			21/10/2021	576642	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Brakes\ABS	EBS PULLING ON AT THE DROP OF A HAT			21/10/2021	576642	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		21/10/2021	576642	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Brakes	Record Check Results As Attached To This Job			02/10/2021		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Brakes\BRAKE ADJ	Please adjust brakes			02/10/2021		Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		02/10/2021		Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Susp\SHOCK ABS	LHR SHOCK MISSING AND BOTTOM MOUNT SNAPPED			02/10/2021		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Elect\TRL LIGHTS	Work lights coming on with left indicator Checked trailer plugs.		TRACED BACK LOAD LIGHT WIRING FROM LIGHTS FOUND LEFT INDICATOR WIRE AND LOAD LIGHT WIRE TOUCHING RHS BEHIND LIG	01/10/2021		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Elect\ELECT P&W	Repaired cut/broken wiring to both work/load lights.			30/09/2021		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Susp\AIR LEAK	LOOSING AIR		REPLACED RUBBED AIR LINE AND JOINER AT HCV	17/09/2021		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Susp\AIR LEAK	Trailer loosing air.		Refer Job# 354295	17/09/2021		Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Brakes	Record Check Results As Attached To This Job			15/09/2021		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Elect\WORK LIGHT	No work lights			15/09/2021		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Elect\WORK LIGHT	No work lights.			15/09/2021		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Chassis\BOLSTER	Front bolster leaking oil.			15/09/2021		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Elect\WORK LIGHT	No work lights.			15/09/2021		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Brakes\BRK O/HAUL	broken shocker bolt LH rear			15/09/2021		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Elect\WORK LIGHT	No work lights			15/09/2021		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	VehService\DS	D Service As Per Attached Checklist Record Check Results As Attached To This Job	VehService\DS		15/09/2021		Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Brakes	Brake readinas not on paperwork.			11/09/2021		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		11/09/2021		Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Chassis\MUDGUARDS	Right hand rear mudguard brackets broken.		Replaced broken mudguard brackets.	11/09/2021		Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Chassis\BOLSTER	2nd bolster LH inside hinge cracked.			11/09/2021		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	VehService\DS	D Service over due.	VehService\DS	Refer Job# 353499	11/09/2021		Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Tyres\TP7+8	supply and fit 2 tyres Travel to Greenfreight. Inspect wiring to find short. Found lights flickering on A-trailer. Dis-assemble lights, found minor rubbed wiring damage.Tape up and tube, secure wires. Test and unable to fault further. Re-assemble			11/09/2021	558493	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Albury - Workshop	Elect\ELECT P&W	and test. Return to Arkon.			10/09/2021		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Albury Workshop	TRAILER
T417	Woolonga - Workshop	Brakes	Record Check Results As Attached To This Job			04/09/2021	554831	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		04/09/2021	554831	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	VehService\DS	Service Due.	VehService\DS	Refer Job# 352649 call out to Hyne Mill Tumbarumba, brakes locking on multiple brakes jumped the cam brake percentages as per below: 30% 10% 20% 80% 10% 10%	04/09/2021	554831	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Rosewood - Workshop	Brakes\BRK O/HAUL	brakes locked on			27/08/2021		Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Rosewood Workshop	TRAILER
T417	Rosewood - Workshop	Brakes\BRK O/HAUL	broken shocker bolt LH rear Check over.			27/08/2021		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Rosewood Workshop	TRAILER
T417	Woolonga - Workshop	Brakes\BRAKE ADJ	Backed off all brakes and insoected percentaaes and readiusted.			27/08/2021		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Susp\SHOCK ABS	Removed left hand rear due to broken mount.			27/08/2021		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Brakes	Record Check Results As Attached To This Job			27/08/2021		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Elect\WORK LIGHT	No work lights			27/08/2021		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		27/08/2021		Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Brakes	Record Check Results As Attached To This Job			20/08/2021		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		20/08/2021		Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	VehService\DS	Service Due.	VehService\DS	Refer Job# 350714	20/08/2021		Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Elect\WORK LIGHT	Worklight Flickering when moving.		Replaced fuse	17/08/2021		Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Brakes	Record Check Results As Attached To This Job			13/08/2021	534272	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		13/08/2021	534272	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Chassis\EXTE TU	drum came off		Fitted barrel and new strap.	08/08/2021		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Chassis\EXTE TU	Repair winch.		Refer Job# 349463	08/08/2021		Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Brakes	Record Check Results As Attached To This Job			31/07/2021	523010	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Brakes\BRK RELINE	Crack test & reline all wheels			31/07/2021	523010	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Susp\SPRING HANG	Slight movement in all. Record Check Results As Attached To This Job		SUSPENSION OK	31/07/2021	523010	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Brakes	Reline Needed.			31/07/2021	523010	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		31/07/2021	523010	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Unknown	Service due.			31/07/2021	523010	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Chassis\BREAKDOWN	Bolt air winch back together.			25/07/2021		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Brakes	Record Check Results As Attached To This Job			24/07/2021	516610	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		24/07/2021	516610	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Elect\TAIL LIGHT	Replaced left hand Stop/Tail and repaired wiring.			24/07/2021	516610	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Susp\SPRING HANG	Tightened LHM + RHF U-Bolts.			24/07/2021	516610	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Brakes\L.H.F	RELINED RHF Record Check Results As Attached To This Job			20/07/2021		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Brakes	Reline Needed.			16/07/2021		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		16/07/2021		Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Woolonga - Workshop	Susp\SPRING HANG	Slight movement in all.			16/07/2021		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Woolonga Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist			16/06/2021	500273	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	VehService\DS	O/N L11646 tail light fuse blowing disconnect trailers found fault in A Trailer replace damaged LH clearance light repair damaged wires check wiring in rear bar found RH light wiring damaged repair wiring	VehService\DS		16/06/2021	500273	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Elect\TRL LIGHTS	reinstall lights			10/06/2021		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Tyres\TP3+4	Supply and fit 4 tyres			08/06/2021		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Tyres\TP5+6	Tyre Position 5 + 6			08/06/2021		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist			21/05/2021		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	VehService\DS	L11462	VehService\DS		21/05/2021		Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			01/05/2021		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3	TRAILER

			D Service As Per Attached Checklist																
T417	Myrtleford - Workshop	VehService\DS	L11325	VehService\DS		01/05/2021		Service	Completed	Greenfreight Loxxine Vic	Kennedv	Mt Gambier	STK	699795	BARRY MANEY - 3		TRAILER		
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			15/04/2021		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3		TRAILER		
			D Service As Per Attached Checklist																
T417	Myrtleford - Workshop	VehService\DS	L11190	VehService\DS		15/04/2021		Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3		TRAILER		
T417	Myrtleford - Workshop	Tyres\TP9+10	Supply and fit 2 tyres			14/04/2021	470149	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop		TRAILER		
T417	Myrtleford - Workshop	Body\WHL HUB	studs spinning &eaurepairs trying to get wheel off, replaced all stock and pins			14/04/2021	470146	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop		TRAILER		
T417	Myrtleford - Workshop	Tyres\TP1+2	Supply and fit 2 new tyres			25/03/2021	461703	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop		TRAILER		
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			23/03/2021	462351	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3		TRAILER		
			D Service As Per Attached Checklist																
T417	Myrtleford - Workshop	VehService\DS	BARRY MANNEY L11109	VehService\DS		23/03/2021	462351	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3		TRAILER		
T417	Myrtleford - Workshop	Tyres\TP11+12	Replace 4 tyres (2 new)			11/03/2021	453894	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Albury Workshop		TRAILER		
T417	Myrtleford - Workshop	Tyres\TP7+8	2 retreads			11/03/2021	453894	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Albury Workshop		TRAILER		
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			02/03/2021	451739	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3		TRAILER		
			D Service As Per Attached Checklist																
T417	Myrtleford - Workshop	VehService\DS	L10955	VehService\DS		02/03/2021	451739	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3		TRAILER		
			Annual Inspection As Per Checklist																
T417	Myrtleford - Workshop	Insp\ANN INSP	ORDER # L10301	Insp\ANN INSP		13/02/2021	440578	PreventativeMaintenance	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3		TRAILER		
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			13/02/2021	440565	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3		TRAILER		
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	order #L10798	13/02/2021	440565	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3		TRAILER		
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			29/01/2021		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3		TRAILER		
			D Service As Per Attached Checklist																
T417	Myrtleford - Workshop	VehService\DS	L10669	VehService\DS		29/01/2021		Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3		TRAILER		
T417	Myrtleford - Workshop	Tyres\TP1+2	replace tyres			13/01/2021	422207	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop		TRAILER		
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			12/01/2021	542791	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3		TRAILER		
			D Service As Per Attached Checklist																
T417	Myrtleford - Workshop	VehService\DS	Order # L10538	VehService\DS		12/01/2021	542791	Service	Completed	Greenfreight Loxxine Vic	Kennedv	Mt Gambier	STK	699795	BARRY MANEY - 3		TRAILER		
T417	Myrtleford - Workshop	Body\PAINT/REST	prepare, paint trailer bolsters on T417			07/01/2021		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop		TRAILER		
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			01/12/2020	411505	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3		TRAILER		
			D Service As Per Attached Checklist																
T417	Myrtleford - Workshop	VehService\DS	Order numer L10262	VehService\DS		01/12/2020	411505	Service	Completed	Greenfreight Loxxine Vic	Kennedv	Mt Gambier	STK	699795	BARRY MANEY - 3		TRAILER		
T417	Myrtleford - Workshop	Body\DAMAGE	check trailer damage to repair lights broken off and reflector			12/11/2020		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop		TRAILER		
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			07/11/2020	402461	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3		TRAILER		
			D Service As Per Attached Checklist																
T417	Myrtleford - Workshop	VehService\DS	Order Number L10108	VehService\DS		07/11/2020	402461	Service	Completed	Greenfreight Loxxine Vic	Kennedv	Mt Gambier	STK	699795	BARRY MANEY - 3		TRAILER		
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			27/10/2020	393759	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3		TRAILER		
			D Service As Per Attached Checklist																
T417	Myrtleford - Workshop	VehService\DS	ORDER # L9985	VehService\DS		27/10/2020	393759	Service	Completed	Greenfreight Loxxine Vic	Kennedv	Mt Gambier	STK	699795	BARRY MANEY - 3		TRAILER		
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			10/10/2020	383091	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3		TRAILER		
			D Service As Per Attached Checklist																
T417	Myrtleford - Workshop	VehService\DS	Order Number L9878	VehService\DS		10/10/2020	383091	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3		TRAILER		
T417	Myrtleford - Workshop	Body\AIR FITTIN	pulled truck over pit, removed and replaced damaged hose, fitted, built up air to check all ok			01/10/2020	377107	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop		TRAILER		
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			26/09/2020		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3		TRAILER		
			D Service As Per Attached Checklist																
T417	Myrtleford - Workshop	VehService\DS	Order Number L9766	VehService\DS		26/09/2020		Service	Completed	Greenfreight Loxxine Vic	Kennedv	Mt Gambier	STK	699795	BARRY MANEY - 3		TRAILER		
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			12/09/2020	364062	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3		TRAILER		
			D Service As Per Attached Checklist																
T417	Myrtleford - Workshop	VehService\DS	Order number L9648	VehService\DS		12/09/2020	364062	Service	Completed	Greenfreight Loxxine Vic	Kennedv	Mt Gambier	STK	699795	BARRY MANEY - 3		TRAILER		
T417	Myrtleford - Workshop	Brakes\AIR LEAK	air line to booster leaking			09/09/2020	360885	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop		TRAILER		
T417	Myrtleford - Workshop	Elect\TRL LIGHTS	replace 7 pin plug (kept falling out)			09/09/2020	360885	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop		TRAILER		
T417	Myrtleford - Workshop	Chassis\HOUSEKEEP	check kingpin (disconnect trailer and check (all ok)			05/09/2020	360120	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop		TRAILER		
T417	Myrtleford - Workshop	Brakes\EBS Kit	EBS/ABS light on ecu module only had 6 volts traced wire back to wheel 12 volts was found connection in wirinr at A Trailer has corrosion reapired anc			05/09/2020	360120	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop		TRAILER		
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			20/08/2020		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3		TRAILER		
			D Service As Per Attached Checklist																
T417	Myrtleford - Workshop	VehService\DS	Order Number # L 9405	VehService\DS		20/08/2020		Service	Completed	Greenfreight Loxxine Vic	Kennedv	Mt Gambier	STK	699795	BARRY MANEY - 3		TRAILER		
T417	Myrtleford - Workshop	Chassis\DAMAGE	gauge, grind and weld cracks in bolster bracket and chassis			11/08/2020	349244	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop		TRAILER		
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			30/07/2020	343971	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3		TRAILER		
			D Service As Per Attached Checklist																
T417	Myrtleford - Workshop	VehService\DS	Order Number # L9220	VehService\DS		30/07/2020	343971	Service	Completed	Greenfreight Loxxine Vic	Kennedv	Mt Gambier	STK	699795	BARRY MANEY - 3		TRAILER		
T417	Myrtleford - Workshop	Body\AIR LEAK	there was an air leak under the turntable but once found it was just a hose, so removed it and cut a new hose and fitted it			24/07/2020	340803	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop		TRAILER		
T417	Myrtleford - Workshop	Elect\TAIL LIGHT	found there was also a brake light not working, which ended up being a broken wire between the light and main wiring harness which was repaired			24/07/2020	340803	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop		TRAILER		
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			14/07/2020	336241	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3		TRAILER		
			D Service As Per Attached Checklist																
T417	Myrtleford - Workshop	VehService\DS	ORDER # L9081	VehService\DS		14/07/2020	336241	Service	Completed	Greenfreight Loxxine Vic	Kennedv	Mt Gambier	STK	699795	BARRY MANEY - 3		TRAILER		
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			27/06/2020	326172	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3		TRAILER		
			D Service As Per Attached Checklist																
T417	Myrtleford - Workshop	VehService\DS	L8977	VehService\DS		27/06/2020	326172	Service	Completed	Greenfreight Loxxine Vic	Kennedv	Mt Gambier	STK	699795	BARRY MANEY - 3		TRAILER		
T417	Myrtleford - Workshop	Brakes\AIR LEAK	booster hose rubbed through RH front booster parts and lobar			16/06/2020		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop		TRAILER		
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			05/06/2020	317068	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3		TRAILER		
			D Service As Per Attached Checklist																
T417	Myrtleford - Workshop	VehService\DS	Order number # L8766	VehService\DS		05/06/2020	317068	Service	Completed	Greenfreight Loxxine Vic	Kennedv	Mt Gambier	STK	699795	BARRY MANEY - 3		TRAILER		
T417	Myrtleford - Workshop	Chassis\FIFTH WHEE	replace turntable foot bushes and turntable top			24/05/2020	310618	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop		TRAILER		
T417	Myrtleford - Workshop	Body\REFLECTORS	replace 7 reflectors			24/05/2020	310618	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop		TRAILER		
T417	Myrtleford - Workshop	Insp\RWC COMP	trailer inspection before Roadworthy inc brake roller test			22/05/2020	310200	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop		TRAILER		
T417	Myrtleford - Workshop	Body\DAMAGE	repair wiring after driver disconnected trailer without unplugging connection			22/05/2020	310200	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop		TRAILER		
T417	Myrtleford - Workshop	Susp\SPRING PACK	replace LHR spring pack			22/05/2020	310200	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop		TRAILER		
T417	Myrtleford - Workshop	Brakes\BRAKE ADJ	brake adjust and roller			22/05/2020	310200	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop		TRAILER		
T417	Myrtleford - Workshop	Elect\ELECT P&W	repair wiring and damage			22/05/2020	310200	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop		TRAILER		
T417	Myrtleford - Workshop	Elect\TRL LIGHTS	light number plate ass			22/05/2020	310200	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop		TRAILER		
T417	Myrtleford - Workshop	Chassis\CHAS CRACK	open up A Trailer folding hinge grind out cracks and weld up			20/05/2020	307519	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop		TRAILER		
			grind fuel weld other cracks around that area																
T417	Myrtleford - Workshop	Chassis\CHAS CRACK	oaint			20/05/2020	307519	Repair	Completed	Greenfreight Loxxine Vic	Kennedv	Mt Gambier	STK	699795	Myrtleford Workshop		TRAILER		
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			14/05/2020	306585	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3		TRAILER		
			D Service As Per Attached Checklist																
T417	Myrtleford - Workshop	VehService\DS	Order Number # L 8557	VehService\DS		14/05/2020	306585	Service	Completed	Greenfreight Loxxine Vic	Kennedv	Mt Gambier	STK	699795	BARRY MANEY - 3		TRAILER		
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			01/05/2020	296152	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3		TRAILER		
			D Service As Per Attached Checklist																
T417	Myrtleford - Workshop	VehService\DS	Order number # L8453	VehService\DS		01/05/2020	296152	Service	Completed	Greenfreight Loxxine Vic	Kennedv	Mt Gambier	STK	699795	BARRY MANEY - 3		TRAILER		
			travel to sisters rd., u-bolts broke																
T417	Myrtleford - Workshop	Susp\BREAKDOWN	repairs on side of road and bring back and replace spring and part needs airbag, spring, u-bolts and shocker mount			22/04/2020	287621	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop		TRAILER		
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			22/04/2020	257621	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3		TRAILER		
			D Service As Per Attached Checklist																
T417	Myrtleford - Workshop	VehService\DS	Order Number # L 8361	VehService\DS		22/04/2020	257621	Service	Completed	Greenfreight Loxxine Vic	Kennedv	Mt Gambier	STK	699795	BARRY MANEY - 3		TRAILER		
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			03/04/2020	277302	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3		TRAILER		
			D Service As Per Attached Checklist																
T417	Myrtleford - Workshop	VehService\DS	Order number # L8257	VehService\DS		03/04/2020	277302	Service	Completed	Greenfreight Loxxine Vic	Kennedv	Mt Gambier	STK	699795	BARRY MANEY - 3		TRAILER		
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			20/03/2020	268783	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3		TRAILER		
			D Service As Per Attached Checklist																
T417	Myrtleford - Workshop	VehService\DS	order number # L 8127	VehService\DS		20/03/2020	268783	Service	Completed	Greenfreight Loxxine Vic	Kennedv	Mt Gambier	STK	699795	BARRY MANEY - 3		TRAILER		
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			06/03/2020	260890	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3		TRAILER		
			D Service As Per Attached Checklist																
T417	Myrtleford - Workshop	VehService\DS	Order Number # L 8034	VehService\DS		06/03/2020	260890	Service	Completed	Greenfreight Loxxine Vic	Kennedv	Mt Gambier	STK	699795	BARRY MANEY - 3		TRAILER		
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			21/02/2020	250870	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3		TRAILER		
			D Service As Per Attached Checklist																
T417	Myrtleford - Workshop	VehService\DS	Order Number # L 7906	VehService\DS		21/02/2020	250870	Service	Completed	Greenfreight Loxxine Vic	Kennedv	Mt Gambier	STK	699795	BARRY MANEY - 3		TRAILER		
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			12/02/2020	242313	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	ONETRAK - 4		TRAILER		
			D Service As Per Attached Checklist																
T417	Myrtleford - Workshop	VehService\DS	ORDER # L7837	VehService\DS		12/02/2020	242313	Service	Completed	Greenfreight Loxxine Vic	Kennedv	Mt Gambier	STK	699795	ONETRAK - 4		TRAILER		
			Annual Inspection As Per Checklist																
T417	Myrtleford - Workshop	Insp\ANN INSP	ORDER # L7707	Insp\ANN INSP		25/01/2020	240156	PreventativeMaintenance	Completed	Greenfreight Loxxine Vic	Kennedv	Mt Gambier	STK	699795	BARRY MANEY - 3		TRAILER		
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			25/01/2020		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3		TRAILER		
			D Service As Per Attached Checklist																
T417	Myrtleford - Workshop	VehService\DS	ORDER # L7705	VehService\DS		25/01/2020		Service	Completed	Greenfreight Loxxine Vic	Kennedv	Mt Gambier	STK	699795	BARRY MANEY - 3		TRAILER		
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			09/01/2020	224223	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3		TRAILER		
			D Service As Per Attached Checklist																
T417	Myrtleford - Workshop	VehService\DS	Order number # L7597	VehService\DS		09/01/2020	224223	Service	Completed	Greenfreight Loxxine Vic	Kennedv	Mt Gambier	STK	699795	BARRY MANEY - 3		TRAILER		
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			06/12/2019	211922	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	ONETRAK-3		TRAILER		
			D Service As Per Attached Checklist																
T417	Myrtleford - Workshop	VehService\DS	Order Number # L 7496	VehService\DS		06/12/2019	211922	Service	Completed	Greenfreight Loxxine Vic	Kennedv	Mt Gambier	STK	699795	ONETRAK-3		TRAILER		
T417	Myrtleford - Workshop	Brakes\AIR LEAK	rubbed air hoses done one track			22/11/2019	201114	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop		TRAILER		
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			22/11/2019		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3		TRAILER		
			D Service As Per Attached Checklist																
T417	Myrtleford - Workshop	VehService\DS	Order Number # L 7391	VehService\DS		22/11/2019		Service	Completed	Greenfreight Loxxine Vic	Kennedv	Mt Gambier	STK	699795	BARRY MANEY - 3		TRAILER		
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			08/11/2019	193249	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3		TRAILER		
			D Service As Per Attached Checklist																
T417	Myrtleford - Workshop	VehService\DS	ORDER # L7345	VehService\DS		08/11/2019	193249	Service	Completed	Greenfreight Loxxine Vic	Kennedv	Mt Gambier	STK	699795	BARRY MANEY - 3		TRAILER		
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			18/10/2019	178989	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	ONETRAK-3		TRAILER		
			D Service As Per Attached Checklist																
T417	Myrtleford - Workshop	VehService\DS	Order Number # L7247	VehService\DS		18/10/2019	178989	Service	Completed	Greenfreight Loxxine Vic	Kennedv	Mt Gambier	STK	699795	ONETRAK-3		TRAILER		
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			05/10/2019	169207	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	ONETRAK-3		TRAILER		
			D Service As Per Attached Checklist																
T417	Myrtleford - Workshop	VehService\DS	ORDER # L7196	VehService\DS		05/10/2019	169207	Service	Completed	Greenfreight Loxxine Vic	Kennedv	Mt Gambier	STK	699795	ONETRAK-3		TRAILER		
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			20/09/2019	159247	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3		TRAILER		
			D Service As Per Attached Checklist																
T417	Myrtleford - Workshop	VehService\DS	order number L7097	VehService\DS		20/09/2019	159247	Service	Completed	Greenfreight Loxxine Vic	Kennedv	Mt Gambier	STK	699795	BARRY MANEY - 3		TRAILER		
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			06/09/2019	149437	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3		TRAILER		
			D Service As Per Attached Checklist																
T417	Myrtleford - Workshop	VehService\DS	Order number # L7028	VehService\DS		06/09/2019	149437	Service	Completed	Greenfreight Loxxine Vic	Kennedv	Mt Gambier	STK	699795	BARRY MANEY - 3		TRAILER		
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			21/08/2019	140608	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	ONETRAK-3		TRAILER		
			D Service As Per Attached Checklist																
T417	Myrtleford - Workshop	VehService\DS	ORDER # L6930	VehService\DS		21/08/2019	140608	Service	Completed	Greenfreight Loxxine Vic	Kennedv	Mt Gambier	STK	699795	ONETRAK-3		TRAILER		
T417	Myrtleford - Workshop	Body\MUDGUARDS	remove old mudguard and duplicate holes on new guard bolt back up			14/08/2019	138724	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop		TRAILER		
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			02/08/2019	135393	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	ONETRAK-3		TRAILER		
			D Service As Per Attached Checklist																
T417	Myrtleford - Workshop	VehService\DS	Order # L6780	VehService\DS		02/08/2019	135393	Service	Completed	Greenfreight Loxxine Vic	Kennedv	Mt Gambier	STK	699795	ONETRAK-3		TRAILER		
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			20/07/2019	127594	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3		TRAILER		
			D Service As Per Attached Checklist																
T417	Myrtleford - Workshop	VehService\DS	Order # L6677	VehService\DS	carried out trailer service as per paperwork	20/07/2019	127594	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3		TRAILER		
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			05/07/2019		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	BARRY MANEY - 3		TRAILER		

			D Service As Per Attached Checklist																
T417	Myrtleford - Workshop	VehService\DS	Order # L6588	VehService\DS		05/07/2019		Service	Completed	Greenfreight Loxxine Vic	Kennedy	Mt Gambier STK	699795	BARRY MANEY - 3	TRAILER				
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			21/06/2019	112270	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	ONETRAK-3	TRAILER				
			D Service As Per Attached Checklist																
T417	Myrtleford - Workshop	VehService\DS	PO # L6455	VehService\DS		21/06/2019	112270	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	ONETRAK-3	TRAILER				
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			01/06/2019	101556	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	ONETRAK-3	TRAILER				
			D Service As Per Attached Checklist																
T417	Myrtleford - Workshop	VehService\DS	Order # L6309	VehService\DS		01/06/2019	101556	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	ONETRAK-3	TRAILER				
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			21/05/2019	93095	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	ONETRAK-3	TRAILER				
			D Service As Per Attached Checklist																
T417	Myrtleford - Workshop	VehService\DS	Order # L6198	VehService\DS	replace RHM spring pack	21/05/2019	93095	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	ONETRAK-3	TRAILER				
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			08/05/2019	83036	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	ONETRAK-3	TRAILER				
			D Service As Per Attached Checklist																
T417	Myrtleford - Workshop	VehService\DS	Order # L6114	VehService\DS		08/05/2019	83036	Service	Completed	Greenfreight Loxxine Vic	Kennedy	Mt Gambier STK	699795	ONETRAK-3	TRAILER				
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			19/04/2019	72707	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	ONETRAK-3	TRAILER				
			D Service As Per Attached Checklist																
T417	Myrtleford - Workshop	VehService\DS	ORDER # L6021	VehService\DS		19/04/2019	72707	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	ONETRAK-3	TRAILER				
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			04/04/2019	63095	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	ONETRAK-3	TRAILER				
			D Service As Per Attached Checklist																
T417	Myrtleford - Workshop	VehService\DS	ORDER # L5939	VehService\DS		04/04/2019	63095	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	ONETRAK-3	TRAILER				
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			22/03/2019	51291	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	WRECKETT PTY. LTD - 3	TRAILER				
			D Service As Per Attached Checklist																
T417	Myrtleford - Workshop	VehService\DS	ORDER # L5831	VehService\DS	driver complaint - middle axle running at 59°c and front and rear running at 34°c, advise if you wish you pull hubs off and check - req	22/03/2019	51291	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	WRECKETT PTY. LTD - 3	TRAILER				
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			08/03/2019	41569	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	WRECKETT PTY. LTD - 3	TRAILER				
					repair wiring at front booster														
			D Service As Per Attached Checklist		replaced perished airbag														
T417	Myrtleford - Workshop	VehService\DS	ORDER # L5761	VehService\DS	replaced damaged ebs valve	08/03/2019	41569	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	WRECKETT PTY. LTD - 3	TRAILER				
T417	Myrtleford - Workshop	Body\DAMAGE	straighten LHS mudguard brackets and tightened, replaced L/H/M mudguard			07/03/2019	40559	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
					replace LHM airbag not LHF														
T417	Myrtleford - Workshop	Susp\AIR BAG	Replace LHF Air Bag		LHF airbag is ok	26/02/2019	41569	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Susp\DAMAGE	Replace EBS Air Bag Valve On Chassis			26/02/2019	41569	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Body\MUDGUARDS	replaced RHF mudguard			22/02/2019	31489	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			22/02/2019	31489	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		22/02/2019	31489	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			13/02/2019	22935	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		13/02/2019	22935	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			26/01/2019	17121	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		26/01/2019	17121	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			12/01/2019	10710	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	tightened chassy plate bolts	12/01/2019	10710	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Brakes\BRK RELINE	Crack test & reline all wheels			01/01/2019	7453	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Tyres	flat tyre LHF inner			29/12/2018	5768	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Tyres	fit spare tyre			29/12/2018	5768	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			25/12/2018	6155	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		25/12/2018	6155	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			18/12/2018		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		18/12/2018		Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			08/12/2018	204824	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		08/12/2018	204824	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Brakes\BRK RELINE	Crack test & reline all wheels			04/12/2018		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			01/12/2018	280743	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		01/12/2018	280743	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Body\WHL HUB	Replace Hubo			27/11/2018		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Tyres\CASE STOCK	Job Added From Invoice			27/11/2018	193358	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice			27/11/2018	193358	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice			27/11/2018	193358	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			24/11/2018		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		24/11/2018		Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Tyres\CASE STOCK	Job Added From Invoice			24/11/2018	183999	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice			24/11/2018	183999	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice			24/11/2018	183999	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			20/11/2018	193357	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		20/11/2018	193357	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Susp\AIR LEAK	Replace LHR RHM & LHF Air Bags			16/11/2018	191271	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			14/11/2018	189862	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		14/11/2018	189862	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			03/11/2018	183999	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		03/11/2018	183999	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			20/10/2018	178258	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		20/10/2018	178258	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Chassis\CHAS CRACK	Repair LHF hanger & chassis cracks			06/10/2018	171657	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			05/10/2018	170935	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		05/10/2018	170935	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Chassis\BOLSTER	check all bolsters and pegs for cracks			24/09/2018	10559	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP		22/09/2018	165508	PreventativeMaintenance	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		22/09/2018	165508	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			22/09/2018	165508	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Hydraulics\HYD LEAKS	fit new male and female hyd coupling			15/09/2018	161304	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Chassis\CHAS CRACK	Repair LHF hanger chassis crack			15/09/2018	161304	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			14/09/2018	161303	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		14/09/2018	161303	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	DrCabElect\SCALES	calibrate scales			07/09/2018	157306	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Elect\ELECT P&W	replace transducer filter and clean scale connections and check air bag pressure			07/09/2018	157306	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			06/09/2018	156633	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		06/09/2018	156633	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Chassis\FIFTH WHEE	Replace turn table foot pins & bushes			29/08/2018	6861	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Body\MUDGUARDS	Replace RHM mudguard		straighten rear m/guards	29/08/2018	6861	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Chassis\BOLSTER	shorten front bolster chain			28/08/2018	6861	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Chassis\BOLSTER	move 2nd bolster and fit stoppers			28/08/2018	6861	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Chassis\WINCH/STRP	fit new air winches			28/08/2018	6861	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Elect\TRL LIGHTS	check lights			28/08/2018	6861	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Elect\TRL LIGHTS	repair faulty tail light and wiring			28/08/2018	6861	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Chassis\HOUSEKEEP	fit hinge lock pins			28/08/2018	6861	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Chassis\HOUSEKEEP	fit front hinge lock pins			28/08/2018	6861	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Chassis\WINCH/STRP	repair winch release cable			28/08/2018	6861	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Chassis\FIFTH WHEE	unhook and hook up trailers 417 & 211			28/08/2018	6861	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Chassis\CHAS CRACK	weld up cracks			28/08/2018	6861	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			28/08/2018	154608	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		28/08/2018	154608	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Tyres	Job Added From Invoice			26/06/2018	0	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice			26/06/2018	0	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice			26/06/2018	0	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			20/06/2018	151582	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		20/06/2018	151582	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Chassis\CHAS CRACK	Repair crack in RHS hinge point			08/06/2018	151229	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			07/06/2018	149154	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		07/06/2018	149154	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Brakes\BRK O/HAUL	Replace LHF Brake Shoes & Check Bearings			30/05/2018	147745	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			29/05/2018	147128	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		29/05/2018	147128	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Chassis\BOLSTER	Fit 2nd bolster ram and mount and hook yp hydraulics and test (L4373)			22/05/2018	145440	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Body\TRL LEGS	Move trailer leg			22/05/2018	145440	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Hydraulics\OIL LEAK	Change hydraulics fittings			22/05/2018	145440	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Body\REFLECTORS	Replace rear signs			22/05/2018	145440	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Body\FIFTH WHEE	Hook up / test/ fold			22/05/2018	145440	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			17/05/2018	144479	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		17/05/2018	144479	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			09/05/2018	142182	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		09/05/2018	142182	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Chassis\CROSS MBR	Repair Turntable Ram Support Bracket		repair checker plate tab and weld nut	28/04/2018	147745	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
					139948km														
T417	Myrtleford - Workshop	Brakes\BRK O/HAUL	Replace RHM Brake Linings		fitted new linines	28/04/2018	147745	Repair	Completed	Greenfreight Loxxine Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			27/04/2018	139581	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		27/04/2018	139581	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Chassis\HOUSEKEEP	Repair LH trailer hinge cracks			19/04/2018	145440	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Chassis\CROSS MBR	Repair RHM cross member gusset crack			19/04/2018	145440	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			18/04/2018	137284	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		18/04/2018	137284	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Tyres	Job Added From Invoice			14/04/2018	0	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice			14/04/2018	0	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice			14/04/2018	0	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Chassis\BOLSTER	Replace damaged bolster cable		fit 2nd bolster ram and mount and hoses cable and pulleys not in use	07/04/2018	145440	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Body\HOUSEKEEP	Carry out repairs to stop cable hitting on cross member			07/04/2018	145440	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			07/04/2018	134615	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		07/04/2018	134615	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Elect\BRK LIGHT	no brake lights			28/03/2018	132565	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			27/03/2018	132148	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		27/03/2018	132148	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Tyres	Job Added From Invoice			24/03/2018	0	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier STK	699795	Myrtleford Workshop	TRAILER				
T417	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice			24/03/2018	0	Repair	Completed	Greenfreight

T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				03/03/2018	126802	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	weld RHF mudflap bar		03/03/2018	126802	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Tyres	Job Added From Invoice				24/02/2018	0	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice				24/02/2018	0	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice				24/02/2018	0	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Chassis\BOLSTER	Replace bolster cable				22/02/2018	126804	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Chassis\HOUSEKEEP	modified gusset on hinge for bloster cable				22/02/2018	126804	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				21/02/2018		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			21/02/2018		Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Tyres	Job Added From Invoice				16/02/2018	0	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice				16/02/2018	0	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice				16/02/2018	0	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Chassis\FIFTH WHEE	hook up T417 & T211				15/02/2018	122865	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Chassis\CROSS MBR	Check crack on hydraulic ram area				14/02/2018	122865	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Chassis\HOUSEKEEP	Check cracks over all. Check crack over all				14/02/2018	122865	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Chassis\CROSS MBR	Repair turn table ram mounts & braces		grease and check ball rack and t/table top		07/02/2018	122865	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Chassis\HYDRAULICS	Repair trailer ram pins & mounts				07/02/2018	122865	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				06/02/2018	121541	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			06/02/2018	121541	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Tyres	Job Added From Invoice				31/01/2018	0	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice				31/01/2018	0	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice				31/01/2018	0	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				24/01/2018	119059	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			24/01/2018	119059	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Tyres\DAMAGE	Tyre blow out and damage to rear left				20/01/2018	118443	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Tyres\RUN OUT	Job Added From Invoice				20/01/2018	0	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Body\MUDGUARDS	Replace LHM mudguard		tighten m/guard bracket		12/01/2018	117132	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Wodonga - Workshop	Tyres\RUN OUT	Job Added From Invoice				11/01/2018	115364	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Wodonga Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				11/01/2018	116415	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			11/01/2018	116415	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Body\AIR FITTIN	front air winch valve leaking air when released				09/01/2018	115710	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Chassis\BOLSTER	Replace bolster cable				04/01/2018	116415	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Body\CHN/RLR/MN	Replace bolster cable pulley bearings				04/01/2018	116415	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Chassis\BOLSTER	remove bolster cable - to be repaired				03/01/2018		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				22/12/2017	113375	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
					Replaced LHR brake shoes												
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	replaced RHR booster		22/12/2017	113375	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				09/12/2017	110752	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			09/12/2017	110752	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Body\MUDGUARDS	staighten and tighten mudguard outrigger and mudguard				30/11/2017	10865	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				29/11/2017	108394	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			29/11/2017	108394	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Chassis\BOLSTER	replace 2nd bolster cable pivot & refit and adjust & test bolster cable				21/11/2017	106632	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Elect\TRL LIGHTS	fit side light keeper				21/11/2017	106632	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Chassis\BOLSTER	test bolster folding operation				21/11/2017	106632	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Chassis\DAMAGE	refit cable onto 2nd bolster roller guide				17/11/2017	106219	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Chassis\CHAS CRACK	cracked roller shaft				17/11/2017	106219	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				16/11/2017	105883	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			16/11/2017	105883	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice				04/11/2017	98160	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice				04/11/2017	98160	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				02/11/2017	103464	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
					replace bolster cable pulley												
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	replace LH ram pin bolt		02/11/2017	103464	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				21/10/2017	101100	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			21/10/2017	101100	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes\BRK RELINE	Crack test and reline all wheels		check and repair tail lights		17/10/2017	101807	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Insp\INT INSP	fit SRT stickers to pegs				06/10/2017	99511	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Susp\HOUSEKEEP	Replace LHM spring eye bush				05/10/2017	9951	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				04/10/2017	98980	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	fit bolt in L/H ram pin keeps braking		04/10/2017	98980	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				23/09/2017	96679	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	fit ram pin bolts		23/09/2017	96679	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				14/09/2017	94242	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
					repair (RH inner) indicator wiring												
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	replace (LH) reverse light and repair wiring		14/09/2017	94242	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Susp\HOUSEKEEP	Replace RHR spring eye bush				06/09/2017	92653	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				05/09/2017	91407	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			05/09/2017	91407	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Insp\RWC COMP	fit new number plate				29/08/2017	89206	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				25/08/2017	88553	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			25/08/2017	88553	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
			change brake line worn out hole														
T417	Rosewood - Workshop	Brakes\BRK RELINE	Rosewood Dezo				18/08/2017	86901	Fault	Completed	Greenfreight Loxiina Vic	Kennedy	Mt Gambier	STK	699795	Rosewood Workshop	TRAILER
T417	Myrtleford - Workshop	Elect\WORK LIGHT	no work lights				12/08/2017		Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Elect\WORK LIGHT	Repair rear work lights				11/08/2017	8534	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP			11/08/2017	85694	PreventativeMaintenance	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				11/08/2017	85694	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	replaced ram pin bolts		11/08/2017	85694	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Susp\AIR BAG	R/S airbag rear (need checking)				10/08/2017	85067	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Body\MUDGUARDS	replace outside mudflaps on both sides				10/08/2017	85067	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Body\PANELS	nut bracket need welding back on plate cover				10/08/2017	85067	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Elect\INDICATORS	repair LH indicator wiring				10/08/2017	85067	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Tyres	Job Added From Invoice				08/08/2017	0	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice				08/08/2017	0	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice				08/08/2017	0	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Susp\HOUSEKEEP	Replace LHR spring eye bush				05/08/2017	85067	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Body\MUDGUARDS	Replace rear mudflaps				05/08/2017	85067	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Tyres\PRES CHECK	Job Added From Invoice				04/08/2017	0	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				04/08/2017	83163	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	fit new h/control rubber		04/08/2017	83163	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				28/07/2017	80759	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			28/07/2017	80759	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Hydraulics\OIL LEAK	replace hyd fitting				22/07/2017	78828	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Body\HOUSEKEEP	tidy up hyd hoses				22/07/2017	78828	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Susp\HCV	Move ride height valve on rear axle				21/07/2017	79141	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Chassis\FIFTH WHEE	make up and fit new t/table hinge pins and bushes and supply parts				20/07/2017	78416	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				20/07/2017	78175	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	need to move ride height valve has been hitting booster		20/07/2017	78175	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Hydraulics\HYD LEAKS	call out : Replaced 2x hydraulic lines (from A & B trailer) and check hydraulic fluid and fold				17/07/2017	76780	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes\AIR LEAK	replace brake hose (split)		air leak under t/table		12/07/2017	75020	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				11/07/2017	74816	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			11/07/2017	74816	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes\EBS Kit	test and program EBS				10/07/2017	74816	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes\EBS Kit	check and engineer trailer				10/07/2017	74816	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				24/06/2017	72740	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			24/06/2017	72740	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
			plate that holds all hydraulic hose wiring through bottom came off														
T417	Myrtleford - Workshop	Body\MOUNTS	no.1 bolster (all bolts are missing)		repair and replace and remount front plate that houses all hoses and electrical		17/06/2017	70865	Fault	Completed	Greenfreight Loxiina Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				15/06/2017	70160	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			15/06/2017	70160	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes\EBS Kit	Fit EBS Kit to front & rear axles				14/06/2017		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Body\MUDGUARDS	replace LH side guard front axle				09/06/2017	69067	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Body\MOUNTS	bracket needs welding where cracked				09/06/2017	69067	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Susp\HOUSEKEEP	Replace RHF spring eye bush and LHF bush				06/06/2017	70865	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				03/06/2017	67645	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			03/06/2017	67645	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Tyres	Job Added From Invoice				31/05/2017	0	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Elect\ELECT P&W	A Trailer electric brake faulty working sometimes				25/05/2017	64987	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				25/05/2017		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			25/05/2017		Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				13/05/2017	61090	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			13/05/2017	61090	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes\AIR LEAK	service line cracked and brittle				09/05/2017	59477	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Elect\WORK LIGHT	no work lights				09/05/2017	59477	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				04/05/2017	58201	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			04/05/2017	58201	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Elect\ELECT P&W	Rewire A trailer		also rewire scales front to rear		03/05/2017	74816	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Elect\TRL LIGHTS	no brake lights				02/05/2017	57462	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Body\HOUSEKEEP	Check over trailer		Complete		29/04/2017		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes\AIR LEAK	Tighten all booster & brake valve hose clamps		Complete		29/04/2017		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes\BRK RELINE	Crack test & reline all wheels		repair brake light wiring		29/04/2017	57049	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Elect\TRL LIGHTS	Repair Brake light wiring				29/04/2017	57049	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Tyres\TP11	Job Added From Invoice				27/04/2017	0	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				21/04/2017	55668	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	repair brake light		21/04/2017	55668	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				07/04/2017

T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			07/03/2017	46827	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	tidy up hydraulic hoses & air lines along chassis	07/03/2017	46827	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			24/02/2017		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		24/02/2017		Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			14/02/2017	42052	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		14/02/2017	42052	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Elect\TRL LIGHTS	2nd bolster light out			04/02/2017	39564	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			04/02/2017	39564	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		04/02/2017	39564	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Tyres\TP17	Job Added From Invoice			01/02/2017	37475	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Tyres\TP15	Job Added From Invoice			01/02/2017	37475	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Tyres\TP13	Job Added From Invoice			01/02/2017	33344	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			24/01/2017	36453	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		24/01/2017	36453	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			13/01/2017	33344	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		13/01/2017	33344	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Chassis\FIFTH WHEE	check & fit turntable pins & clean			07/01/2017	31865	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Chassis\HOUSEKEEP	grease turntable			07/01/2017	31865	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Tyres\TP19	Job Added From Invoice			30/12/2016	29208	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Chassis\HOUSEKEEP	Repair crack in trailer hinge			24/12/2016	31865	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		20/12/2016	30903	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			20/12/2016	30903	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	check anf tighten L/H hydraulic ram fittings & fit bolt & nut to pin	08/12/2016	28465	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			08/12/2016	28465	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Elect\TRL LIGHTS	no R/S indicators working			02/12/2016	27396	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Elect\TAIL LIGHT	replace LED tail light			02/12/2016	27396	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			25/11/2016	25946	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		25/11/2016	25946	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		15/11/2016	23725	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			15/11/2016	23725	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			03/11/2016	21453	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		03/11/2016	21453	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Tyres\TP18	Job Added From Invoice			01/11/2016	19875	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		20/10/2016	18954	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			20/10/2016	18954	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes\AIR LEAK	air line hose to brake booster has hole in it			13/10/2016	17317	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Elect\ELECT P&W	no electric brake			12/10/2016	17194	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Elect\ELECT P&W	no electric brake			12/10/2016	17194	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			06/10/2016	15957	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		06/10/2016	15957	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			23/09/2016	1370	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		23/09/2016	1370	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Tyres\TP17	Job Added From Invoice			15/09/2016	0	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	replaced bolster cable pulley	14/09/2016	10806	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			14/09/2016	10806	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Elect\TRL LIGHTS	no left side indicators			03/09/2016	7597	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			02/09/2016	7597	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		02/09/2016	7597	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes\AIR LEAK	air leaking when brake hand piece is pulled on. air leaking when brake hand piece is puleed on			26/08/2016	4680	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			25/08/2016	4126	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		25/08/2016	4126	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			13/08/2016	1071	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		13/08/2016	1071	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Body\WHL HUB	Replace Hubo			06/08/2016		Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
			Replace light rubber grommet													
T417	Myrtleford - Workshop	Elect\TRL LIGHTS	Repair trailer olue to B-Trailer		Comolete	04/08/2016	319460	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			04/08/2016	319460	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		04/08/2016	319460	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			26/07/2016	316394	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		26/07/2016	316394	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Tyres\TP11	Job Added From Invoice			22/07/2016	314998	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP	repair checker plate floor & refit to chassis	15/07/2016	314692	PreventativeMaintenance	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Tyres\TP21	Job Added From Invoice			14/07/2016	312670	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Tyres\TP21	Job Added From Invoice			14/07/2016	0	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Tyres\TP21	Job Added From Invoice			14/07/2016	0	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			09/07/2016	313390	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		09/07/2016	313390	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Chassis\HOUSEKEEP	Repair all cracks & paint			01/07/2016	316097	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			30/06/2016	311217	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		30/06/2016	311217	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Body\CHN/RLR/MN	Repair Cable pulley - flogged out		Complete	29/06/2016	311085	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Chassis\BOLSTER	Repair cracks under bolsters (as per defect)			28/06/2016	316097	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Chassis\HOUSEKEEP	Repair trailer hinge cracks (as per defect)			28/06/2016	316097	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Chassis\AIR LEAK	Repair air leak in hose where trailer folds		Complete	24/06/2016	310105	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Elect\TRL LIGHTS	Replace missing LHS marker light		Complete	24/06/2016	310105	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			22/06/2016	308848	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		22/06/2016	308848	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			10/06/2016	306203	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		10/06/2016	306203	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			31/05/2016	303933	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		31/05/2016	303933	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
					Remove all lights from tail light bar, check wiring looms & 7 pin plugs											
			No Clearance Lights		fault located at hinge. Remove damaged section & solder new section in											
T417	Myrtleford - Workshop	Elect\TRL LIGHTS	No Indicators		Comolete	25/05/2016	302439	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Elect\TRL LIGHTS	check tail light bar - indicator stop			25/05/2016	302028	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Chassis\FIFTH WHEE	Repair skid plate crack RHS			24/05/2016	302869	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			21/05/2016	301236	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		21/05/2016	301236	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Chassis	RHS skid plate crack			21/05/2016	301236	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Tyres\TP19	Job Added From Invoice			18/05/2016	298653	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Tyres\TP19	Job Added From Invoice			18/05/2016	0	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Tyres\TP19	Job Added From Invoice			18/05/2016	0	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Tyres\TP15	Job Added From Invoice			18/05/2016	298230	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Tyres\TP15	Job Added From Invoice			18/05/2016	0	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Tyres\TP15	Job Added From Invoice			18/05/2016	0	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			12/05/2016	298948	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		12/05/2016	298948	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
					remove hub assembly tighten drum/wheel studs nuts											
T417	Myrtleford - Workshop	Body\WHL HUB	left hand rear wheel studs loose		refit hub assembly. adjust brake	11/05/2016	298654	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			05/05/2016	296970	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		05/05/2016	296970	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
			crack test & reline all 3 x axles		2 x axles complete 27-04-16											
T417	Myrtleford - Workshop	Brakes\BRK RELINE	Fit 6 x Slack Adiuster Return Ssrinas		1 x axle comolete 28-4-16	28/04/2016	295480	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			21/04/2016	294292	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		21/04/2016	294292	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		11/04/2016	929780	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			11/04/2016	929780	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Tyres\TP12	Job Added From Invoice			09/04/2016	290613	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			09/04/2016	291809	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		09/04/2016	291809	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			31/03/2016	289074	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		31/03/2016	289074	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Tyres\TP12	Job Added From Invoice			18/03/2016	284208	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		11/03/2016	286409	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			11/03/2016	286409	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			01/03/2016	284208	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		01/03/2016	284208	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Tyres\TP19	Job Added From Invoice			26/02/2016	0	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			17/02/2016	281231	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		17/02/2016	281231	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			08/02/2016	279091	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		08/02/2016	279091	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
			Fit 50% run out brake shoes to LHM axle													
			check & adjust bearing													
T417	Myrtleford - Workshop	Brakes\BRK RELINE	check tere eressories & pump to correct PSI		comoleted	03/02/2016	277932	Repair	Comoleted	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes\BOOSTER	1x 30/30 booster			30/01/2016		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Elect\TRL LIGHTS	repair wiring to RH number plate light		completed	29/01/2016	277439	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes\AIR LEAK	replace LHR brake booster hose - worn through and leaking		completed	29/01/2016	277439	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes\BOOSTER	replace RHF brake booster		completed	29/01/2016	277439	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Chassis\HOUSEKEEP	check over		completed	29/01/2016	277439	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes\AIR LEAK	replace RHF axle air line on booster - too short & comes off fitting		completed	27/01/2016	277115	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
			check brakes & leaks													
T417	Myrtleford - Workshop	Brakes\AIR LEAK	fit new air lines		completed	25/01/2016	276877	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Elect\TRL LIGHTS	repair wiring for RH indicator & check lights		completed	25/01/2016	276877	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Elect\TRL LIGHTS	replace no. 2 marker light RHS - shorting out		completed	23/01/2016		Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		completed	20/01/2016	276354	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	completed	20/01/2016	276354	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
					repaired fault in 1st bolster parker lights											
T417	Myrtleford - Workshop	Elect\TRL LIGHTS	check & repair no marker lights		comoleted	20/01/2016	276354	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
					repair LH inner tail light wiring											
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	completed	07/01/2016	273619	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes

T417	Myrtleford - Workshop	Tyres\TP21	Job Added From Invoice			01/12/2015	266665	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Tyres\TP02	Job Added From Invoice			01/12/2015	0	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Tyres\TP21	Job Added From Invoice			01/12/2015	0	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	completed	25/11/2015	265873	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		completed	25/11/2015	265873	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		completed	13/11/2015	263139	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist weld plate+make up + fit hinge pins+bushes+supply parts	VehService\DS	completed	13/11/2015	263139	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Body\MOUNTS	rinlatech replace winch cable			10/11/2015		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Chassis\WINCH/STRP	replace lhf u-bolt weld plate+make up + fit hinge pins+bushes+supply parts		completed	07/11/2015	26158	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Body\MOUNTS	rinl repalce turntable hinge pins + bushes		comoleted	06/11/2015		Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Chassis\FIFTH WHEE	replace front hinge pins + bushes		completed	03/11/2015	260662	Fault	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		completed	22/10/2015	260362	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	completed	22/10/2015	260362	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		completed	09/10/2015	257493	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	completed	09/10/2015	257493	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Susp\SUSPENSION	repair crack in ball race mount plate		completed	30/09/2015	260662	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		completed	30/09/2015	255356	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	completed	30/09/2015	255356	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Chassis\WHL HUB	Job Added From Invoice			22/09/2015	0	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	completed	17/09/2015	252901	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		completed	17/09/2015	252901	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	crack test + reline all wheels		completed	17/09/2015	253507	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Tyres\TP17	Job Added From Invoice			08/09/2015	0	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Tyres\TP17	Job Added From Invoice			08/09/2015	0	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Tyres\TP17	Job Added From Invoice			08/09/2015	0	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		completed	04/09/2015	146623	Repair	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER
T417	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	completed	04/09/2015	146623	Service	Completed	Greenfreight Logging Vic	Kennedy	Mt Gambier	STK	699795	Myrtleford Workshop	TRAILER