Mike's Truck & Trailer Repair Ltd
Box 73
Cudworth, SK S0K 1B0

Invoice

Date	Invoice #
7/24/2019	7053

GST/HST No. 802244418

Vehicle Information	Serial Number	Mileage
2001 Advance Tridem	2AESGXEHX1S000184	----------

Quantity	Description	Price Each	Ext Amount
1	Tri-Axle Trailer Certification	87.50	87.50
1	SGI Safety Sticker charge	15.00	15.00
2	Hub Cap Gasket	1.70	3.40
1	13HD Hardware Kit	6.99	6.99
2	Trailer Wheel Seal	34.83	69.66
2	Hub Oil/Litre	4.49	8.98
2	Enviro Charges	0.05	0.10
2	1/2" Clevis Pin	1.29	2.58
2	E11864 Cam 10 spine	41.72	83.44
1	336 ABS Sensor Kit	39.14	39.14
1	E11450 HD Camshaft Repair Kit	64.52	64.52
2	S24691 Pivot Bushing Kit	152.98	305.96
4	70357501 Steel Spacer	28.42	113.68
4	70357502 Plastic Spacer	15.89	63.56
6	Air Bag Mounting Kit	23.25	139.50
6	8709 Air Bag	102.00	612.00
6	Small heat shrink connector	0.79	4.74
2	67000 3 Way pigtail	1.86	3.72
2	Gladhand seal	0.55	1.10
2	Aeolus HN266 11R24.5 tires installed	397.41	794.82
2	SK Scrap Tire Fee	14.00	28.00
2	TR572 Valve Stem	3.96	7.92
	ABS Diagnostic Hookup	65.00	65.00
	Shop supplies & miscellaneous expenses	28.50	28.50

Wheels must be re-torqued between 60 & 100 KMS of use. THIS IS YOUR RESPONSIBILITY.

Cab Card or PST Exp #

Subtotal

THIS INVOICE IS DUE UPON RECEIPT
A service charge of 2% per month (24% per annum) is charged on unpaid invoices.The parts and labour listed hereon are acknowlegded and I express lien thereon to secure the full amount of the endebtedness. Signature _____

Total

Mike's Truck & Trailer Repair Ltd
Box 73
Cudworth, SK S0K 1B0

Invoice

Date	Invoice #
7/24/2019	7053

GST/HST No. 802244418

Vehicle Information	Serial Number	Mileage
2001 Advance Tridem	2AESGXEHX1S000184	----------

Quantity	Description	Price Each	Ext Amount
17.25	Labour: R & R six air bags R & R rear suspension bushings and install new bushings and wear discs. Repair lights Replace driverside middle s-cam bushings and wheel seal. R & R driverside rear s-cam and bushings and install new. Check ABS codes and repair new sensors and erase codes.	98.50	1,699.13

Wheels must be re-torqued between 60 & 100 KMS of use. THIS IS YOUR RESPONSIBILITY.

Cab Card or PST Exp #

THIS INVOICE IS DUE UPON RECEIPT
A service charge of 2% per month (24% per annum) is charged on unpaid invoices.The parts and labour listed hereon are acknowlegded and I express lien thereon to secure the full amount of the endebtedness. Signature:_____

Subtotal	$4,248.94
GST@5.0%	212.45
PST (SK)@6.0%	247.11
Total Tax	459.56
Total	$4,708.50

Paid Aug 28, 2019