EquipmentName	Workshop	CodeAndSubCode	Description	Schedule	CompletionComments	DateDone	DistanceDone	Worktype	Workstate	EquipmentOwner	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			03/04/2024		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	CHECKED EBS. LUBED WINCHES. REPLACED AIR LINE AT 2ND WINCH. HOOKED UP.	03/04/2024		Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Wodonga - Workshop	Chassis\WINCH/STRP	Winch bolt - fit bolt to winch shaft for handle			20/12/2023	278891	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Wodonga Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			19/12/2023	278821	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	REPLACED LF LM MUDGUARDS. REPAIRED BOLSTER LIGHTS.	19/12/2023	278821	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres	wheelnut indicators			22/09/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Albury Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			21/09/2023	276191	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		21/09/2023	276191	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			30/08/2023	275088	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	CHECKED ALL BEARINGS.	30/08/2023	275088	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Wodonga - Workshop	Tyres\TP01	LEFT HAND SIDE FRONT TRI AXLE OUT TYRE FLAT		REPLACED	02/08/2023		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Wodonga Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\TP1+2	Tyre Position 1 + 2			19/07/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Albury Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			19/07/2023	271465	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	ADJUSTED RM WHEEL BEARING AND RIDE HEIGHT. REPLACED 1ST WINCH, RR AIRBAG MUDGUARD AND BRACKET LF TYRE.	19/07/2023	271465	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\TP9+10	Tyre Position 9 + 10			28/06/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Albury Workshop	TRAILER
T308	Myrtleford - Workshop	Elect\ELECT P&W	right hand side trailer indicator			23/06/2023	266602	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Elect\TAIL LIGHT	3rd bolster LH side light not working			23/06/2023	266602	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			23/06/2023	26660	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		23/06/2023	26660	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Elect\TRL LIGHTS	left hand side 3rd axle side light		3rd LH side light out	08/06/2023	262015	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Elect\INDICATORS	no left hand indicator on trailer		no left hand indicator	08/06/2023	262015	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Susp\HOUSEKEEP	adjust LHM wheel bearing			08/06/2023	262518	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	DrCabElect\SCALES	REPAIR SCALES		inspected all good	08/06/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			06/06/2023	262015	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	replace LHR spring and spring eye bolt	06/06/2023	262015	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP		23/05/2023	45017	PreventativeMaintenance	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\TP5+6	Tyre Position 5 + 6			20/05/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Albury Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\TP11+12	Tyre Position 11 + 12			19/05/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Albury Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			19/05/2023	45817	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	DrivLine\CTCH PACK	park lights RHS rear			19/05/2023	45817	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		19/05/2023	45817	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			02/05/2023	251415	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		02/05/2023	251415	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	DrivLine\CTCH PACK	park lights RHS rear			30/04/2023	251415	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\WINCH/STRP	2 load road needs replacing		2nd winch rope	30/04/2023	251415	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\WINCH/STRP	no.4 quick release tight to connect		4th winch release cable	30/04/2023	251415	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\TP09	puncture repair			05/04/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Albury Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		04/04/2023	247163	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			04/04/2023	247163	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\TP3+4	Tyre Position 3 + 4			23/03/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Albury Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			18/03/2023	241945	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		18/03/2023	241945	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			23/02/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		23/02/2023		Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			09/02/2023	231810	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		09/02/2023	231810	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\TP7+8	Tyre Position 7 + 8			07/02/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Albury Workshop	TRAILER
T308	Wodonga - Workshop	Tyres\TP10	L/H REAR AXLE INSIDE TYRE FLAT.		REPLACED.	28/01/2023	228768	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Wodonga Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\TP10	puncture repair			28/01/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Albury Workshop	TRAILER
T308	Wodonga - Workshop	Brakes\SLACK ADJ	REPLACED RF SLACK ADJUSTER.			19/01/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Wodonga Workshop	TRAILER
T308	Myrtleford - Workshop	Body\DAMAGE	straps frayed		STRAPS OK.	18/01/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\WINCH/STRP	wire release not working but I think is the hooks on the straps		ALL OK.	18/01/2023		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Susp\AIR BAG	Air leak on trailer			18/01/2023		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			18/01/2023	226736	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist front axle not tracking straight	VehService\DS	CHEDCKED ALL WHEEL BEARINGS.	18/01/2023	226736	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Susp\AXLES	(broken spring)			02/12/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			02/12/2022	225137	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Wodonga Workshop	TRAILER
T308	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		02/12/2022	225137	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Wodonga Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\TP10	flat tyre on trailer RHS middle axle		change RHM tyre	22/11/2022	12122	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\TP03	ouncture reoair			12/11/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Albury Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			11/11/2022	218787	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
					adjusted LHR & RHF wheel bearings											
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	check EBS	11/11/2022	218787	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\WINCH/STRP	chanae hammer lock's on winches please to smaller ones			10/11/2022		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes\EBS Kit	check ebs comes on often			10/11/2022		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Albury - Workshop	Tyres\TP1+2	Tyre Position 1 + 2			10/11/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Albury Workshop	TRAILER
T308	Myrtleford - Workshop	DrCabElect\SCALES	swap out transducers			01/11/2022	216214	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	DrCabElect\SCALES	replace scales with Elphinstone scales			28/10/2022	216124	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Elect\TRL LIGHTS	rewire rear bolster lights			28/10/2022	216124	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\HOUSEKEEP	make up new front mat/cover			28/10/2022	216124	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\SPAREWHEEL	spare wheel carrier			26/10/2022	5488	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
			CARRY OUT BRAKE REUINE AS REQUIRED - Raise and support axles. - Remove wheels, brakes and hubs. - Clean and inspect bearings, ok for reuse. - Inspect brakes and found all s-cams to have excessive movement. - Found all but RHM brake linings under spec, advised to replace all. - Remove and replace all s-cams and tubes. Replace slack adjusters. - Fit new brake shoes and repack wheel bearings. - Pack hubs and refit. Adjust bearings. - Fit new drums as were over size and severely lipped. - Refit wheels and tension. Lower axles.													
T308	Myrtleford - Workshop	Brakes\BRK RELINE				21/10/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Albury Workshop	TRAILER
T308	Myrtleford - Workshop	Elect\TRL LIGHTS	Test power to light ok. Remove and replace light.			21/10/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Albury Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	CARRY OUT GREENFREIGHT LOG TRAILER D-SERVICE AS PER ATTACHED SERVICE SHEET.	VehService\DS		21/10/2022		Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Albury Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			30/09/2022	213315	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
					Replace brake hose line Replace height control rod & rubbers											
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	Air baes air leaks	30/09/2022	213315	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Susp\WGHT GAUGE	Test & Repair Easvweigh & Air Transducers			30/09/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Susp\AIR BAG	Air leak on trailer			27/09/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\MUDGUARDS	Left hand rear mudguard		LHR airbag us	27/09/2022		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\HOUSEKEEP	Protector plate bolts need tightening		chassis cover	27/09/2022		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Insurance\WINCH/STRP	replace winch strap flanner locks with 10mm size			27/09/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Body\MUDGUARDS	LHR mudguard			27/09/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\TP9+10	supply and fit 2tyres			22/09/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Body\MUDGUARDS	Guard need replace		Fitted new guard LHF	18/09/2022		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Body\WHL HUB	Fitted New Hubo			18/09/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Elect\TAIL LIGHT	light bar light			13/09/2022	208998	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\MUDGUARDS	broken outrigger			13/09/2022	208998	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			09/09/2022	208494	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	fit hammer locks	09/09/2022	208494	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\TP11+12	supply and fit 2tyres			08/09/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			24/08/2022	208770	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	inside RHM tyre shoulder worn	24/08/2022	208770	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\TP3+4	supply and fit 6 tyres			17/08/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\TP5+6	Tyre Position 5 + 6			17/08/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\TP9+10	Tyre Position 9 + 10			17/08/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			09/08/2022	198556	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		09/08/2022	198556	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Body\MUDGUARDS	left hand side front and middle guard needs bolt			02/08/2022		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			26/07/2022	194753	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	adjust RHR and RHM wheel bearing replaced 2x guards replaced 2x mudflaps 2x zebra signs	26/07/2022	194753	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Body\MUDGUARDS	REPAIR LHM MUDGAURD		do not over take sign	22/07/2022	194753	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\HOUSEKEEP	bolts loose on top plate		tighten loose bolts	21/07/2022	193934	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Elect\BRK LIGHT	brake lights not working on trailer		brake light	21/07/2022	193934	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			05/07/2022	188460	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		05/07/2022	188460	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Susp\AIR BAG	right hand front airbae needs replacement		right hand front airbae	23/06/2022	183815	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Susp\AIR BAG	REPLACE LHF AIR BAG			23/06/2022	185630	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\TP1+2	supply and fit 2 tyres			23/06/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			21/06/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
					RHF airbag leaking											
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	checked E.B.S	21/06/2022		Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\WINCH/STRP	wire release not working but i think is the hooks on the straps			03/06/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			03/06/2022	178724	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		03/06/2022	178724	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\TP7+8	SUPPLY AND FIT 2 TYRES			02/06/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\WINCH/STRP	wire release on air winches wont work			01/06/2022	17762	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Workshop\MOVE ASSET	hook up to B72			24/05/2022	17630	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\WINCH/STRP	reinstall old winch modify bracket			18/05/2022	174129	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\WINCH/STRP	repair/replace rear air winch on trailer		swap winch from T662	17/05/2022	173862	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			07/05/2022	172343	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	LHR tyre fitted	07/05/2022	172343	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP		03/05/2022	170790	PreventativeMaintenance	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER

T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			03/05/2022	170790	Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
					fit 4x winchs												
					fit new work light												
					rewire 1st bolster lights												
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	check EBS	03/05/2022	170790	Service		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\HOUSEKEEP	set up for welding			21/10/2020	170790	Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Body\AIR LEAK	fix air leak to air winch			21/10/2020	170790	Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\HOUSEKEEP	weld trailer cracks			21/10/2020	170790	Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
					wash pivot points on front of trailer												
T308	Myrtleford - Workshop	Chassis\DAMAGE	Weld cracks in Hydraulic ram Mounts		crack on hyd ram pivot	17/10/2020	170788	Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes\EBS Kit	check EBS			15/10/2020	170789	Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Body\WHL HUB	jack up and check wheel bearing adjustment			14/10/2020	170788	Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Body\REFLECTORS	fit sign			14/10/2020	170788	Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Body\PANELS	weld bue for center cover			14/10/2020	170788	Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Body\PAINT/REST	wash trailer			14/10/2020	170788	Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Body\PANELS	fit spring body washers to floor			14/10/2020	170788	Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			14/10/2020	170788	Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		14/10/2020	170788	Service		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\WINCH/STRP	middle strap freyed		inspected all good	14/10/2020		Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
					need repairing 3rd bolster												
T308	Myrtleford - Workshop	Chassis\BOLSTER	middle bolster near pads cracked		cracks under 2nd bolster LH/RH sides	14/10/2020		Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\CHAS CRACK	trailing arm bush wear pads		ok	14/10/2020		Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\TP01	R/H/R tyres		inspected all good	14/10/2020		Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\CHAS CRACK	trailing arm bush wear plates all cracked		ok	14/10/2020		Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes\BRAKE ADJ	pads worn second from rear			14/10/2020		Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Body\DAMAGE	load straps frayed		inspected all good	14/10/2020		Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes\BRAKE ADJ	wear pads worn under middle upright			14/10/2020		Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\CASE STOCK	Job Added From Invoice			09/07/2020	167112	Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice			09/07/2020	167112	Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
					replace												
T308	Myrtleford - Workshop	Brakes\MUDGUARDS	Replace RHR mud guards		fit mudguard and mudflap to LHF	01/07/2020	170788	Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			30/06/2020	167845	Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		30/06/2020	167845	Service		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Suso\AIR LEAK	airbag problem with suspension			25/06/2020	16606	Fault		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP		18/06/2020	162930	PreventativeMaintenance		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			18/06/2020	162930	Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		18/06/2020	162930	Service		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			03/06/2020	159878	Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		03/06/2020	159878	Service		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\DAMAGE	Replace spare wheel			27/05/2020	154600	Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes\BOOSTER	Replace RHR broken booster			27/05/2020	154600	Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			26/05/2020	153977	Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		26/05/2020	153977	Service		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\WINCH/STRP	repair 4th air winch			24/05/2020	153184	Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\WINCH/STRP	reolace second winch strao			19/05/2020	149800	Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\WINCH/STRP	insoect quick release latch ok			19/05/2020	149800	Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			15/05/2020	148018	Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
					hook up to S72												
					replaced wind air fittings												
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	unscrunched airbaes	15/05/2020	148018	Service		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			12/02/2020	148009	Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	inflate all tyres	12/02/2020	148009	Service		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\WINCH/STRP	Repair faulty air winch			21/11/2019	148009	Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			20/11/2019	147039	Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
					replaced RHR spring eye bush												
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	refit reflector signs on mudflaps	20/11/2019	147039	Service		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\WINCH/STRP	repair air winch not working			08/11/2019	142906	Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			07/11/2019		Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Rosewood Workshop	TRAILER
			D Service														
T308	Rosewood - Workshop	VehService\DS	-attempt repair on winch, with Wayne re-procedures. Replacement to be set up. Still works manually	VehService\DS		07/11/2019		Service		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Rosewood Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			24/10/2019		Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		24/10/2019		Service		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			27/09/2019	130430	Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
					tighten LHR spring eye bolt												
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	replace/remake damaged LH bolster pin	27/09/2019	130430	Service		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\WINCH/STRP	please fit new middle strap			19/09/2019	129395	Fault		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Elect\TRL LIGHTS	repair LH brake light			06/09/2019	128751	Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes\BRK RELINE	Reline 3x axles			30/08/2019	128751	Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes\SLACK ADJ	replace RHM slack adjuster			29/08/2019	126850	Fault		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Susp\HCV	ride height slow to come down			29/08/2019	126850	Fault		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			29/08/2019	126850	Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		29/08/2019	126850	Service		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes\BRAKE ADJ	check brakes - ok			15/08/2019		Fault		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Body\PANELS	check bolts on trailer please			15/08/2019		Fault		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Elect\TRL LIGHTS	check lights tyres - ok			15/08/2019		Fault		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			15/08/2019	122023	Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	tighten winch bolts	15/08/2019	122023	Service		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			02/08/2019	118068	Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	TWIN CITY TRUCK CENTRE - 3 - OLD	TRAILER
			D Service As Per Attached Checklist														
T308	Myrtleford - Workshop	VehService\DS	Order # L6783	VehService\DS	carried out trailer service	02/08/2019	118068	Service		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	TWIN CITY TRUCK CENTRE - 3 - OLD	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			20/07/2019	111317	Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	TWIN CITY TRUCK CENTRE - 3 - OLD	TRAILER
			D Service As Per Attached Checklist														
T308	Myrtleford - Workshop	VehService\DS	Order # L6683	VehService\DS		20/07/2019	111317	Service		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	TWIN CITY TRUCK CENTRE - 3 - OLD	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			12/07/2019		Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	TWIN CITY TRUCK CENTRE - 3 - OLD	TRAILER
			D Service As Per Attached Checklist														
T308	Myrtleford - Workshop	VehService\DS	Order # L6639	VehService\DS	carried out trailer service as per service sheet	12/07/2019		Service		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	TWIN CITY TRUCK CENTRE - 3 - OLD	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			06/07/2019	101707	Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	TWIN CITY TRUCK CENTRE - 3 - OLD	TRAILER
			D Service As Per Attached Checklist														
T308	Myrtleford - Workshop	VehService\DS	Order # L6602	VehService\DS	completed	06/07/2019	101707	Service		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	TWIN CITY TRUCK CENTRE - 3 - OLD	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			29/06/2019	93311	Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	TWIN CITY TRUCK CENTRE - 3 - OLD	TRAILER
			D Service As Per Attached Checklist		FIT LHR AIR BAG												
T308	Myrtleford - Workshop	VehService\DS	Order # L6533	VehService\DS	completed D Service as per attached checklist	29/06/2019	93311	Service		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	TWIN CITY TRUCK CENTRE - 3 - OLD	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			21/06/2019	86490	Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	TWIN CITY TRUCK CENTRE - 3 - OLD	TRAILER
			D Service As Per Attached Checklist														
T308	Myrtleford - Workshop	VehService\DS	Order # L6461	VehService\DS	D Service Complete	21/06/2019	86490	Service		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	TWIN CITY TRUCK CENTRE - 3 - OLD	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		complete	15/06/2019	79192	Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	TWIN CITY TRUCK CENTRE - 3 - OLD	TRAILER
			D Service As Per Attached Checklist														
T308	Myrtleford - Workshop	VehService\DS	Order # L6411	VehService\DS	complete	15/06/2019	79192	Service		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	TWIN CITY TRUCK CENTRE - 3 - OLD	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			08/06/2019	73409	Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	TWIN CITY TRUCK CENTRE - 3 - OLD	TRAILER
			D Service As Per Attached Checklist														
T308	Myrtleford - Workshop	VehService\DS	Order # L6380	VehService\DS		08/06/2019	73409	Service		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	TWIN CITY TRUCK CENTRE - 3 - OLD	TRAILER
T308	Myrtleford - Workshop	Body\FIFTH WHEE	hook up T308 to 861			30/05/2019	62042	Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Body\FIFTH WHEE	unhook T308 off 835			29/05/2019	62092	Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Body\PANELS	Repair Chassis Check Plates			24/05/2019	62042	Fault		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\WINCH/STRP	Check Winch Strao Cables			24/05/2019	62042	Fault		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			23/05/2019	61084	Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		23/05/2019	61084	Service		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\WINCH/STRP	strap release latch			21/05/2019	59469	Fault		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\WINCH/STRP	Fit Cover 3rd Air Winch & Repair Old Winch			16/05/2019	58674	Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Susp\SPRING PACK	RHF broke spring			12/05/2019	56954	Fault		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			11/05/2019	56954	Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	RH front spring broken	11/05/2019	56954	Service		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			08/05/2019		Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Wodonga Workshop	TRAILER
T308	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		08/05/2019		Service		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Wodonga Workshop	TRAILER
T308	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		completed	02/05/2019	46814	Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Wodonga Workshop	TRAILER
T308	Wodonga - Workshop	Body\MUDGUARDS	R/H/R guard hanger broken		replace right hand guard	02/05/2019	46814	Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Wodonga Workshop	TRAILER
T308	Wodonaa - Workshop	Chassis\WINCH/STRP	middle strao freyed			02/05/2019	46814	Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Wodonaa Workshop	TRAILER
T308	Wodonaa - Workshop	Chassis\BOLSTER	middle bolster near oads cracked			02/05/2019	46814	Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Wodonaa Workshop	TRAILER
T308	Wodonaa - Workshop	Chassis\CHAS CRACK	trailine arm bush wear oads			02/05/2019	46814	Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Wodonaa Workshop	TRAILER
T308	Wodonga - Workshop	Tyres\TP01	R/H/R tyres			02/05/2019	46814	Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Wodonga Workshop	TRAILER
T308	Wodonga - Workshop	Chassis\CHAS CRACK	trailing arm bush wear plates all cracked			02/05/2019	46814	Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Wodonga Workshop	TRAILER
T308	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	included smoko	02/05/2019	46814	Service		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Wodonga Workshop	TRAILER
T308	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection per checklist			25/04/2019	56955	Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			25/04/2019		Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		25/04/2019		Service		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Body\DAMAGE	straps frayed			25/04/2019		Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes\BRAKE ADJ	pads worn second from rear			25/04/2019		Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Body\DAMAGE	load straps frayed			25/04/2019		Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes\BRAKE ADJ	wear pads worn under middle upright			25/04/2019		Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes\EBS Kit	no oower to trailer EBS - check			16/04/2019		Fault		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			16/04/2019	37891	Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		16/04/2019	37891	Service		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			06/04/2019	32555	Repair		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		06/04/2019	32555	Service		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Body\AIR FITTIN	red and blue air light into trailer leaking with button in black			04/04/2019		Fault		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Hydraulics\VALVES	hydraulic ram valve in side frame falling off			04/04/2019		Fault		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Body\AIR FITTIN	replace air guage			02/04/2019	30477	Fault		Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER

				repair 2nd bolster indicators and light wiring																	
T308	Myrtleford - Workshop	Elect\TRL LIGHTS	fit new LH bolster side light				28/03/2019	29634	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				22/03/2019	27751	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS		22/03/2019	27751	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Body\PANELS	repair broken checker plate floor loas				19/03/2019	26851	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Susp\SHOCK ABS	Reolace RHM Shocker				07/03/2019	22864	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\WINCH/STRP	Reco rear air winch				07/03/2019	22864	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				06/03/2019	22861	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
			D Service As Per Attached Checklist																		
T308	Myrtleford - Workshop	VehService\DS	reolace sorine oack & booster vokes		VehService\DS		06/03/2019	22861	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\SPAREWHEEL	crack on spare wheel winder				20/02/2019	18177	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\SPAREWHEEL	needs new T-piece				20/02/2019	18177	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				20/02/2019	18177	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS		20/02/2019	18177	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				07/02/2019		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS		07/02/2019		Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	DrivLine\AIR LEAK	bad air leak when park brakes are off or black button in				30/01/2019	11052	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Body\PANELS	tighten checker plate guard				25/01/2019	10105	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\BOLSTER	replace 3rd bolster chain hammerlock				25/01/2019	10105	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Elect\WORK LIGHT	Repair Reverse Lights			rewire trailer plug to suit	23/01/2019	11052	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Elect\WORK LIGHT	repair reverse liahts				22/01/2019	8954	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				22/01/2019	8954	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS		22/01/2019	8954	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				05/01/2019	4207	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS		05/01/2019	4207	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				12/12/2018	30416	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS	repaired bolster light plug	12/12/2018	30416	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Body\WHL HUB	Replace hubo meter				11/12/2018	304355	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
						replace 1x axle strap															
T308	Myrtleford - Workshop	Susp\HOUSEKEEP	Replace 2 x middle axle straps			26851 km	11/12/2018	304355	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes\AIR LEAK	Travel to breakdown & repair brake line				07/12/2018		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Elect\INDICATORS	LH indicator missing				06/12/2018	302505	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Elect\WORK LIGHT	work (reverse) light stays on				06/12/2018	302505	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Elect\ELECT P&W	scales not working				06/12/2018	302505	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Rosewood - Workshop	Body\AIR LEAK	air leak booster hose			repair air leak	27/11/2018		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Rosewood Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\CASE STOCK	Job Added From Invoice				27/11/2018	28269	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice				27/11/2018	28269	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice				27/11/2018	28269	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				20/11/2018	233412	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS		20/11/2018	233412	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Susp\SHOCK ABS	Replace RHF Shocker				08/11/2018	295679	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				06/11/2018	295678	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
						replace spring eye bush and centre bolt															
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS	needs a wheel alignment	06/11/2018	295678	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice				28/10/2018	295260	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice				28/10/2018	295260	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\Punct	Job Added From Invoice				28/10/2018	295260	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				23/10/2018	294948	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
						straighten RHF m/guard outrigger															
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS	repair front chassis - member bracket cracks	23/10/2018	294948	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\WINCH/STRP	fix air winch				18/10/2018	294237	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres	Job Added From Invoice				18/10/2018	291567	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Body\MUDGUARDS	trailer guards loose				17/10/2018	293769	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Body\HOUSEKEEP	winch bar for middle winch and bullbar				17/10/2018	293769	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice				10/10/2018	288138	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\BOLSTER	bent peg - back bay back peg RHS				04/10/2018	289834	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\WINCH/STRP	air leak - back air winch				04/10/2018	289834	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				04/10/2018	289834	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
						repair second bolster wiring and replace blinker															
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS	replace winch air fitting and supply line	04/10/2018	289834	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\WINCH/STRP	replace defective air winch at rear of trailer				03/10/2018	289259	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres	Job Added From Invoice				28/09/2018	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice				28/09/2018	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice				28/09/2018	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes\AIR LEAK	air leak on brake hoses				27/09/2018	287858	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\WINCH/STRP	third winch air fitting				27/09/2018	287858	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				14/09/2018	285099	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS	replaced LHR brake booster	14/09/2018	285099	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\WINCH/STRP	check rear air winch and lube and test				08/09/2018	283728	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres	Job Added From Invoice				30/08/2018	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice				30/08/2018	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice				30/08/2018	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Body\PANELS	flat cover over centre of trailer - all bolts loose				24/08/2018	27937	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				22/08/2018	278476	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS	fit stop tail light and clean wiring and glues	22/08/2018	278476	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				29/06/2018	275157	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS		29/06/2018	275157	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Body\MUDGUARDS	RHS rear mudguard loose				14/06/2018	275157	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice				13/06/2018	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice				13/06/2018	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				09/06/2018	270215	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS		09/06/2018	270215	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				24/05/2018	265353	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS		24/05/2018	265353	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist		Insp\ANN INSP		10/05/2018	264813	PreventativeMaintenance	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				10/05/2018	264813	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
						fitted new ride height rubbers and mount															
						adjusted ride height															
						repaired air leaks on winches															
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS	redirected brake lines away from ride height valve	10/05/2018	264813	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres	Job Added From Invoice				17/04/2018	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice				17/04/2018	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice				17/04/2018	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes\BRK RELINE	Crack test & reline all wheels				10/04/2018		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes\BRK RELINE	Fit 6 x new brake drums				10/04/2018		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
			Fit winch strap quick release system																		
			repair spare wheel carrier & cracks(L4201)(L4216)(I4239)(L4275)(L4357)																		
T308	Myrtleford - Workshop	Chassis\WINCH/STRP	)				10/04/2018		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\TP19	change flat tyre				06/04/2018	264086	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes\BACK PLATE	Reolace RHM brake backing olates			straighten out old backing olates	24/03/2018	262265	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				23/03/2018	261342	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
			D Service As Per Attached Checklist																		
T308	Myrtleford - Workshop	VehService\DS	relace bolster liahts		VehService\DS		23/03/2018	261342	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
			replace straps																		
T308	Myrtleford - Workshop	Chassis\WINCH/STRP	1st and 3rd air winches				20/03/2018	259743	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\BOLSTER	crack in bracket on bolster - 2nd on RHS				14/03/2018	258800	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Susp\SHOCK ABS	Reolace both shockers on rear axle				02/03/2018	257036	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Susp\HOUSEKEEP	Reolace LHR sprine eve bush			fit new fine thread bolt and nut	01/03/2018	256682	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				28/02/2018	256681	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS		28/02/2018	256681	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				10/02/2018	251523	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS		10/02/2018	251523	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				25/01/2018	247308	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS		25/01/2018	247308	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes\BRAKE ADJ	adjust brakes				23/01/2018	246262	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Susp\AIR FITTIN	fit air pressure guage to air bags				16/01/2018	243529	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Elect\TRL LIGHTS	fir side bolster markers				16/01/2018	243529	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\RUN OUT	Job Added From Invoice				12/01/2018	243582	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Susp\AIR BAG	DSR back airbaa locks RHS				10/01/2018	243528	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Susp\SUSPENSION	Reolace LHM sprine eve bush				05/01/2018	243528	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Susp\AIR BAG	Fit air pressure aauge to air baas			refer entry no. 69984	05/01/2018	243528	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				04/01/2018	242582	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS		04/01/2018	242582	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\RUN OUT	Job Added From Invoice				16/12/2017	239600	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\RUN OUT	Job Added From Invoice				14/12/2017	239063	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres	Job Added From Invoice				14/12/2017	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice				14/12/2017	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice				14/12/2017	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				12/12/2017	239600	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS		12/12/2017	239600	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Wodonga - Workshop	Susp\AIR BAG	replace right front airbag				08/12/2017	104729	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Wodonga Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				25/11/2017	237308	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS		25/11/2017	237308	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Hydraulics\RAM	replace ram pin				17/11/2017	235956	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				09/11/2017	234953	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS		09/11/2017	234953	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				18/10/2017	23237	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS		18/10/2017	23237	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes\AIR LEAK	replace RHR brake booster diaphragm				03/10/2017	23042	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER

T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				26/09/2017	229690	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	fit srt stickers		26/09/2017	229690	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\PRES CHECK	Job Added From Invoice				20/09/2017	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\BOLSTER	Replace RHR Peg - bent forward				19/09/2017	289834	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\WINCH/STRP	1st/2nd & 3rd winch straps				16/09/2017	228224	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\BOLSTER	Replace bolster folding pads				13/09/2017	227649	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\CHAS CRACK	weld cracks on chassis				13/09/2017	227649	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Body\HOUSEKEEP	check over trailer				13/09/2017	227649	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Elect\TRL LIGHTS	check lights				13/09/2017	227649	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Hydraulics\OIL LEAK	replace hydraulic couplings				13/09/2017	227649	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Insp\RWC COMP	replace number plate				13/09/2017	227649	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				08/09/2017	227074	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			08/09/2017	227074	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres	Job Added From Invoice				06/09/2017	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice				06/09/2017	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice				06/09/2017	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				25/08/2017	224343	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			25/08/2017	224343	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Body\MUDGUARDS	L/R/R guard and pole				20/08/2017		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Body\MUDGUARDS	L/C guard - replace				20/08/2017		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				12/08/2017	221497	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			12/08/2017	221497	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres	Job Added From Invoice				11/08/2017	220728	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice				11/08/2017	220728	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Body\MUDGUARDS	tighten R/L wheel auard and rail				08/08/2017	220600	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Body\MUDGUARDS	repair reolace c/l auard				08/08/2017	220600	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Body\MUDGUARDS	lower R/H middle wheel auard/winch handle iammine				28/07/2017	218804	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				28/07/2017	218804	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
					lower m/guards RHS middle												
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	tidy up brake hoses		28/07/2017	218804	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Elect\ELECT P&W	Rewire trailer front to rear				23/07/2017	218035	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Elect\ELECT P&W	Replace scale wiring front to rear				23/07/2017	218035	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes\EBS Kit	FIT EBS KIT TO FRONT & REAR AXLES				22/07/2017	218035	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes\BRK RELINE	Crack test & reline all wheels				22/07/2017	218035	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes\EBS Kit	program EBS				22/07/2017	218035	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes\EBS Kit	check and engineer trl				22/07/2017	218035	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\PRES CHECK	Job Added From Invoice				11/07/2017	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\WINCH/STRP	Replace 3rd winch chain & refit strap & roller to winch				28/06/2017	217300	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				23/06/2017	216776	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			23/06/2017	216776	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres	Job Added From Invoice				14/06/2017	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice				14/06/2017	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice				14/06/2017	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\WINCH/STRP	broken bolt in air winch bracket. broken bolt air winch bracket				14/06/2017	214523	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				09/06/2017	213989	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			09/06/2017	213989	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
			replace mudflaps														
T308	Myrtleford - Workshop	Body\MUDGUARDS	mudguard is to close				02/06/2017	212592	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\WINCH/STRP	winch hard to turn				02/06/2017	212592	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				26/05/2017	211300	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			26/05/2017	211300	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Body\MUDGUARDS	R/S mudguard - replace				24/05/2017	210650	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes\BRAKE ADJ	adjust brakes				24/05/2017	210650	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\WINCH/STRP	straighten winch handle (rear)				24/05/2017	210650	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\RUN FLAT	Job Added From Invoice				19/05/2017	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				17/05/2017	208722	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			17/05/2017	208722	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Body\MUDGUARDS	refit LHS mudflao				13/05/2017	206264	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes\BRAKE ADJ	Adiust brakes		Comolete		11/05/2017	207995	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Body\PANELS	Back checker plate bolts loose and tighten all bolts		Comolete		11/05/2017	207995	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				03/05/2017	203309	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			03/05/2017	203309	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\TP16	Job Added From Invoice				27/04/2017	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\BOLSTER	block/hold chain R/H/S 3 bolster cracks				13/04/2017	203308	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				13/04/2017	203309	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			13/04/2017	203309	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes\AIR LEAK	replace brake air hose				04/04/2017	201670	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\TP21	Job Added From Invoice				29/03/2017	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				28/03/2017	200791	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			28/03/2017	200791	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Body\WHL HUB	fit second hand hub cap to L/H middle axle				25/03/2017	200604	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes\AIR LEAK	Reoair air leaks in brake svstem				18/03/2017	200791	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes\BRAKE ADJ	Adiust brakes		Complete		16/03/2017	911311	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\TP13	Job Added From Invoice				16/03/2017	198262	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\TP16	Job Added From Invoice				16/03/2017	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Body\MUDGUARDS	R/H rear mudflap "replace"				11/03/2017	198801	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				09/03/2017	198262	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			09/03/2017	198262	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
					Found broken wire at solenoid												
					replaced plug												
T308	Myrtleford - Workshop	Elect\ELECT P&W	Switch to stand bolster faulty		Complete		01/03/2017	197263	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				18/02/2017	196266	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			18/02/2017	196266	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP			16/02/2017	196266	PreventativeMaintenance	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\WINCH/STRP	check rear winch strap roller replace				31/01/2017	194101	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				31/01/2017	194101	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			31/01/2017	194101	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes\AIR LEAK	repair air leak				25/01/2017	193358	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Body\HOUSEKEEP	check over trailer				25/01/2017	193358	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\WINCH/STRP	check winch straps				25/01/2017	193358	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Body\PANELS	tighten bolts on checker plate floor				25/01/2017	193358	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\WINCH/STRP	replace hold down strap				07/01/2017	191593	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Susp\SPRING PACK	fit new spring pack to LHF axle				06/01/2017	191474	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Susp\AIR BAG	fit new LHF airbag				06/01/2017	191474	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				06/01/2017	191474	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			06/01/2017	191474	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	DrCabElect\SCALES	Scales not working Line B. Scales no working Line B		Complete		03/01/2017	191384	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\WINCH/STRP	Spring on middle strap broken. Lock comes off when chains tighten		Complete		03/01/2017	191384	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\TP11	Job Added From Invoice				31/12/2016	197909	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			08/12/2016	189290	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				08/12/2016	189290	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Susp\BREAKDOWN	travel to breakdown				29/11/2016	187795	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Susp\HOUSEKEEP	check suspension				29/11/2016	187795	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Body\WHL HUB	check wheel bearing play				29/11/2016	187795	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Susp\BREAKDOWN	return to workshop + check				29/11/2016	187795	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Body\TOOLBOX	repair + re-fit chain box				29/11/2016	187795	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes\BRAKE ADJ	adjust brakes				29/11/2016	187795	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	wash & clean out skid plate + hinge area		23/11/2016	186833	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				23/11/2016	186833	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes\AIR LEAK	LHM brake booster - replace				18/11/2016	185994	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Body\MUDGUARDS	repair - LHM mudguard				10/11/2016	184642	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes\BOOSTER	air leak on trailer				05/11/2016	184251	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
			rear bolster clearance lights														
T308	Myrtleford - Workshop	Elect\TRL LIGHTS	wires pulled out of plug				05/11/2016	184251	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			05/11/2016	184251	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				05/11/2016	184251	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes\BRK RELINE	Fit 50% runouts to front axle				29/10/2016	183634	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	DrvLine\WHEEL BRGS	Check wheel bearing adiustment				29/10/2016	183634	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				19/10/2016	182151	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			19/10/2016	182151	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\WINCH/STRP	Replace No. 3 winch strap. Replace straps on air winches		replace no. 3 & no. 1 winch straps		06/10/2016	181063	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				05/10/2016	179302	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			05/10/2016	179302	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\TP17	Job Added From Invoice				23/09/2016	176645	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				20/09/2016	176645	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			20/09/2016	176645	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				07/09/2016	174112	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			07/09/2016	174112	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes\SLACK ADJ	cut down front axle slack adiusters, replaced RHR slack adi				03/09/2016		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes\BRAKE ADJ	adiust brakes				03/09/2016		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Susp\SPRING HANG	check spring eyes & body				03/09/2016		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Elect\TRL LIGHTS	check lights				03/09/2016		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				05/08/2016	171326	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			05/08/2016	171326	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\TP19	Job Added From Invoice				30/07/2016	169341	Repair	Completed	Greenfreight

T308	Myrtleford - Workshop	Chassis\FIFTH WHEE	cracks in webbine front of trailer/ main lift ram			23/07/2016	16934	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Body\PANELS	tiehten chassis cover plates			23/07/2016	16934	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			20/07/2016	168879	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		20/07/2016	168879	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			06/07/2016	166266	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		06/07/2016	166266	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Elect\TRL LIGHTS	R/H 2nd side/ marker light broken			11/06/2016	163247	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			11/06/2016	163696	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		11/06/2016	163696	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\TP11	Job Added From Invoice			04/06/2016	161870	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\TP11	Job Added From Invoice			04/06/2016	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\TP11	Job Added From Invoice			04/06/2016	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\TP12	Job Added From Invoice			28/05/2016	160896	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			27/05/2016	161189	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		27/05/2016	161189	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Elect\TRL LIGHTS	Repair last marker light on RHS - flickering on/off		Complete	26/05/2016	161189	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\TP20	Job Added From Invoice			24/05/2016	159508	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\TP17	Job Added From Invoice			20/05/2016	159092	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes\BRK RELINE	Crack Test & Reline all wheels			11/05/2016	158859	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Hydraulics\HOSES	2x damaged + leaking hyd hoses		replaced hyd hoses + rested to see if they get caught	10/05/2016	158587	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			09/05/2016	158587	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		09/05/2016	158587	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			28/04/2016	156271	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		28/04/2016	156271	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			14/04/2016	153613	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		14/04/2016	153613	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Body\MUDGUARDS	R/H mudflap hold clio broken off			12/04/2016	153113	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			01/04/2016	151138	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist Check air leaks at air tank	VehService\DS		01/04/2016	151138	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Body\AIR LEAK	Fit new hose clamps		Complete	21/03/2016	149539	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes\BRAKE ADJ	Adjust Brakes		Complete	21/03/2016	149539	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			10/03/2016	148468	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		10/03/2016	148468	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Body\MUDGUARDS	R/H mudflap hold clip			04/03/2016	14825	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			19/02/2016	146272	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		19/02/2016	146272	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Elect\TRL LIGHTS	Re-fit RH indicator		Completed	19/02/2016	146272	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Elect\ELECT P&W	Replace broken switch to stand bolster		Completed	19/02/2016	146272	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\WINCH/STRP	repair spring lock on centre rear winch		Completed	10/02/2016	144512	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			05/02/2016	143735	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		05/02/2016	143735	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection			04/02/2016	143476	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Hydraulics\RAM	replace hydraulic ram pin on 2nd bolster		completed	02/02/2016	142771	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		19/01/2016	141043	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			19/01/2016	141043	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Hydraulics\RAM	repair & replace peg ram pin		completed	15/01/2016	140323	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	DrCabElect\SCALES	install 2nd hand transducer & calibrate		completed	14/01/2016	140233	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Susp\AIR BAG	SUPPLY 1 AIR BAG		completed	14/01/2016		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Susp\AIR BAG	Rear LH airbag leaking		replace leaking airbag	12/01/2016	139816	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\HOUSEKEEP	check over trailer check scales. check scales plug at trailer		completed check scales plug at trailer check tare link connection and transducer plug	07/01/2016	139431	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Elect\ELECT P&W	check tare link connection and transducer plug		completed	07/01/2016	139431	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\TP21	Job Added From Invoice			30/12/2015	138201	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\TP21	Job Added From Invoice			30/12/2015	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\TP21	Job Added From Invoice			30/12/2015	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\TP21	Job Added From Invoice			30/12/2015	137974	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\TP21	Job Added From Invoice			30/12/2015	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\TP21	Job Added From Invoice fit new mudguard to rh rear wheel			30/12/2015	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Body\MUDGUARDS	repair zebra sian		completed	19/12/2015	138369	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\WINCH/STRP	fit chain rinas to chain		completed	19/12/2015	138369	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\SUSPENSION	refit checker plate floorine		completed	19/12/2015	138369	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Body\MOUNTS	weld new gusset for last winch remove 4th winch		completed	19/12/2015	138369	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\WINCH/STRP	rinlatech winch straps+rollers+mudflap hinges		completed	19/12/2015		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\WINCH/STRP	kennedy trls 2 packs of 4m rings			18/12/2015		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\WINCH/STRP	dahlsens tube+valve		completed	18/12/2015		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\WINCH/STRP	tctc supply bolts		completed	09/12/2015		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\CROSS MBR	rinlatech		completed	09/12/2015		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		completed	03/12/2015	137974	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist make new ruber mount for rear air tank repair cracks in rear cross member straighten/repair chassis coversreplace plastic blocks for 3rd bolster replace rhf mud guard fit 4x air winchs	VehService\DS	completed	03/12/2015	137974	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\PAINT/REST	fit chain restraint system 4 air tap kits		completed	27/11/2015	137974	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\WINCH/STRP	Forest centre 4 chains+straps for winches		COMPLETED	27/11/2015		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\WINCH/STRP	Kennedy trailers		completed	27/11/2015		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\TP11	Job Added From invoice			21/11/2015	136620	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\TP11	Job Added From Invoice			21/11/2015	136620	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\TP11	Job Added From Invoice repair air leak in trailer check airbags+booster valves			21/11/2015	136620	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\AIR LEAK	repair blocked port on valve check front axle tyre wearing		completed	21/11/2015	137226	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Tyres\DAMAGE	replace lhf axle cable rubber		completed	10/11/2015	135159	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		completed	10/11/2015	135375	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	completed	10/11/2015	135375	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		completed	24/10/2015	132853	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	completed	24/10/2015	132853	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes\BRAKE ADJ	adjust brakes		completed	22/10/2015	132107	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\BOLSTER	fit new limit switch to turntable+test hyd for 1st bolster		completed	22/10/2015	132107	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Susp\AIR BAG	replace lhm air bag		completed	13/10/2015	130862	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Susp\AIR BAG	1 air bag		completed	10/10/2015		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Chassis\AIR BAG	Job Added From Invoice replace broken rhf winch handle		completed	09/10/2015	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Body\DAMAGE	replace last winch handle replace rhf air bag		completed completed	06/10/2015	130445	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Susp\AIR BAG	replace lh + rhr zebra signs		fit rhr mudflap + lhr bolster side light	06/10/2015	130449	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	completed	06/10/2015	130445	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		completed	06/10/2015	130445	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Elect\ELECT P&W	tested bolster micro-switch unable to fault+cleaned switch and connections		completed	19/09/2015	129198	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	completed	11/09/2015	127962	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		completed	11/09/2015	127962	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER
T308	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP		10/09/2015	278891	PreventativeMaintenance	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	3706BS	Myrtleford Workshop	TRAILER