EquipmentName	Workshop	CodeAndSubCode	Description	Schedule	CompletionComments	DateDone	DistanceDone	Worktype	Workstate	EquipmentOwner	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
T274	Myrtleford - Workshop	Body\CHN/RLR/MN	replaced 2x chain dogs			27/09/2022	156975	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes\BRAKE ADJ	No brakes on Trailer		order brake exhausts	21/09/2022	156523	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	DrivLine\WHEEL BRGS	Adjust wheel bearings			21/09/2022	156523	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Susp\AXLES	REPLACE AXLE CABLES AS NEEDED			20/09/2022	156975	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	DrivLine\WHEEL BRGS	REPLACE SHOCKER BUSHES AS NEEDED		inspected all good	20/09/2022	156975	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Susp\SHOCK ABS	REPLACE SHOCKER BUSHES AS NEEDED		inspected all good	20/09/2022	156975	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Body\TRL ROLLBK	CHECK AND TIGHTEN LH/RH SIDE ROLLERS		Rinlatech - machine 2 rollers as per sample	20/09/2022	156975	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection as per checklist	Insp\ANN INSP		20/09/2022	156314	PreventativeMaintenance	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			20/09/2022	156314	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			20/09/2022	156314	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Chassis\WINCH/STRP	Winch tap broken		Replace winch tap	17/09/2022	155918	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Elect\TAIL LIGHT	RH Rear tail light u/s		Replace tail light	17/09/2022	155918	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Body\DAMAGE	Repair damage by log loaded bent frame		Repair damage by log loaded on trailer unable to fold up	09/09/2022	155205	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			25/08/2022	153615	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			25/08/2022	153615	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres\TP3+4	supply and fit 2tyres			24/08/2022		Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Chassis\WHL HUB	front hub warm			23/08/2022	152961	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Elect\BRK LIGHT	replaced hub switch			23/08/2022	152961	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres\CLEANSKIN	POS 15			30/07/2022		Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			28/07/2022		Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			28/07/2022		Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Elect\ELECT P&W	no back scales on back bay there reading but not moving when getting loaded		scale wire	15/07/2022	149425	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Chassis\BOLSTER	REPLACE 3RD BOLSTER			13/07/2022	156975	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			13/07/2022	144174	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			13/07/2022	144174	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Body\FIFTH WHEE	hook up to 693			12/07/2022	148414	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres\CLEANSKIN	Supply and fit 4tyres - POS 13,14,15,16			02/07/2022		Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Body\MUDGUARDS	L/H side mudguard bent on rear on trailer			28/06/2022	14661	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Body\ELECT P&W	Rebuild A Frame Hitch			24/06/2022		Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Chassis\TRL ROLLBK	trailer wont extend out		trailer wont extend out side lock LHS jammed up	22/06/2022	145701	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Chassis\CHAS CRACK	REMOVE A FRAME FOR REPAIR AND REFIT			16/06/2022	145676	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres\TP5+6	supply and fit 2 tyres			16/06/2022		Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		replaced LH roller	15/06/2022	145664	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			15/06/2022	145664	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		check EBS operation	26/05/2022	742875	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			26/05/2022	742875	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres\TP9+10	supply and fit 2 tyres			26/05/2022		Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Body\MUDGUARDS	fit mudguard to RHF dolly		front dolly rear mudguard	17/05/2022		Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Elect\ELECT P&W	reversing lights very dull		fit new reverse lights	17/05/2022		Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Chassis\WINCH/STRP	second release cable damaged need to be longer		release cable	17/05/2022		Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			03/05/2022	143007	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		order axle straps (93)	03/05/2022	143007	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes\BRAKE ADJ	last axle axle no brakes on trailer			29/04/2022	139551	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes\BRK RELINE	reline rear axle			21/04/2022	138819	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Body\TRL ROLLBK	replaced slide lock roller			21/04/2022	138819	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Susp\SHOCK ABS	replaced shocker bushings			21/04/2022	138819	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Chassis\WINCH/STRP	replaced winch strap			21/04/2022	138819	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Body\STCH GUARD	repair allum guard			07/04/2022		Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
					reweld airbag protector											
					replaced RHR dolly shocker bushings											
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		rewired dolly bolster light	01/04/2022	137050	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			01/04/2022	137050	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres\TP11	supply and fit 1tyre			31/03/2022		Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes\ABS	CHECK AND REPAIR ABS LIGHT			31/03/2022	138819	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Chassis\WINCH/STRP	replaced 3rd winch fittings			30/03/2022	136550	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes\BRK RELINE	reline			24/03/2022	134082	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes\BRK RELINE	reline front axle on trailer			24/03/2022	134082	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Chassis\WINCH/STRP	rebuild winch and fit to trailer			24/03/2022	134082	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
					scales not working or reading correct weight											
T274	Myrtleford - Workshop	DrCabElect\SCALES	scales not working		(problem was at dolly)	18/03/2022	134180	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			17/03/2022	134082	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			17/03/2022	134082	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
			trailer will not go up													
T274	Myrtleford - Workshop	Hydraulics\RAM	hydraulic taps - eg		trailer not able to fold hyd tap turned off	12/03/2022	133353	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Chassis\TRL ROLLBK	side locks not working (broken)			10/03/2022	132689	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Wodonga - Workshop	Susp\SHOCK ABS	REPLACE LHF SHOCKER			05/03/2022	132803	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Wodonga Workshop	TRAILER
T274	Wodonga - Workshop	Susp\SHOCK ABS	REPLACE FRONT DOLLY SHOCKER BUSHES			05/03/2022	132803	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Wodonga Workshop	TRAILER
T274	Myrtleford - Workshop	DrCabRep\SEAT	replace seat cover			04/03/2022	131834	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Engine\COOL LEAKS	recheck coolant leak on compressor			04/03/2022	131834	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres\DAMAGE	change boggy right hand side outer front wheel			04/03/2022	131834	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			04/03/2022	131834	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			04/03/2022	131834	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Hydraulics\RAM	Dismantle and repair hyd cylinders, make new hoses, replace and repair rod eyes, reseal, machine new pins			27/02/2022		Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Hydraulics\RAM	remove trailer lift cylinders and refit cylinders			25/02/2022	130717	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Body\MOUNTS	replaced rubbers on a frame to dolly			20/02/2022	130248	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Chassis\WINCH/STRP	move winch cable			18/02/2022	129934	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			09/02/2022	128520	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Wodonga Workshop	TRAILER
T274	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			09/02/2022	128520	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Wodonga Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes\BRAKE ADJ	brake adjustment		adjust brakes	09/02/2022	128520	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Body\ELECT P&W	repair scale plug			09/02/2022	128520	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Body\CHN/RLR/MN	REPLACE LH5 SLIDE LOCK GREASE NIPPLE			25/01/2022	126663	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Susp\SHOCK ABS	REPLACE RHR DOLLY SHOCKER RUBBER		LHF	25/01/2022	126663	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Elect\TAIL LIGHT	REPLACE NUMBER PLATE LIGHT			25/01/2022	126663	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres\TP04	supply and fit 1 tyre			22/01/2022	126154	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			21/01/2022	125887	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			21/01/2022	125887	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres\DAMAGE	change boggy right hand side outer front wheel		tyre seemed fine, get TF to have a look	21/01/2022	125887	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes\BRAKE ADJ	adjust trailer brakes			14/01/2022	124555	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres\TP1+2	supply and fit 4 tyres			13/01/2022		Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres\TP5+6	Tyre Position 5 + 6			13/01/2022		Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Chassis\HOUSEKEEP	RH outer slide lock broken		broken slide lock	05/01/2022	122904	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Chassis\HOUSEKEEP	RH roller for slide lock broken			05/01/2022	122904	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
			REPAIR PLATE PROTECTOR FOR REAR AIRBAG													
T274	Myrtleford - Workshop	Body\DAMAGE	WLED UP BROKEN ROD MOUNT FOR AIRLINE			01/01/2022		Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	MARIO BARBISAN	TRAILER
T274	Myrtleford - Workshop	Body\MOUNTS	WELD UP BROKEN ROD MOUNT FOR AIRLINE			01/01/2022		Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	MARIO BARBISAN	TRAILER
			check brake %													
T274	Myrtleford - Workshop	Brakes\BRAKE ADJ	percentage			30/12/2021		Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Wodonga - Workshop	Susp\HOUSEKEEP	REPLACE DAMAGED AXLE CABLES		940 axle straps x4	21/12/2021	125887	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Wodonga Workshop	TRAILER
T274	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			10/12/2021	120226	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Wodonga Workshop	TRAILER
T274	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			10/12/2021	120226	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Wodonga Workshop	TRAILER
T274	Myrtleford - Workshop	Susp\AIR BAG	right hand side rear dolly airbag needs replacing		replace RHR airbag on front dolly	26/11/2021	117842	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			26/11/2021	117842	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			26/11/2021	117842	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Body\MUDGUARDS	REPLACE 2X 19.5 MUDGUARDS			11/11/2021	115500	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Hydraulics\RAM	B Trailer - hydraulic ram pin lost security nut and bolts holds pin inn			10/11/2021		Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			10/11/2021	115257	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			10/11/2021	115257	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			22/10/2021	112309	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			22/10/2021	112309	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Chassis\AIR LEAK	setting 3 back of trailer scales not working at all. Were working next load not working		scale issues	21/10/2021		Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Susp\AIR BAG	rear dolly broken A/bay and shocker bolt bent A/bay mount/shock mount		suspension damage	21/10/2021		Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Chassis\AIR LEAK	loosing air on trailer		air leak on trailer	19/10/2021		Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres\TP03	supply and fit 2 tyres			14/10/2021	110502	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres\TP09	Tyre Position 9			14/10/2021	110502	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres\DAMAGE	replace flat tyre on dolly 2nd axle RHS inside			12/10/2021	110218	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Body\CHN/RLR/MN	replaced chassi rollers			12/10/2021	110313	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Susp\DAMAGE	REPLACE REAR AXLE AIR BAG RAMPS			08/10/2021	122601	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		rewire bolster lights	07/10/2021	104671	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			07/10/2021	104671	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Chassis\DAMAGE	slide on left hand side missing a bolt		remove snapped bolt and replaced	06/10/2021	109431	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Elect\TRL LIGHTS	rewire list bolster plug and lights		rewire bolster lights	06/10/2021	109431	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Elect\TRL LIGHTS	replaced LHR bolster clearance light		replace clearance light	06/10/2021	109431	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	DrCabRep\SEAT	replace seat cover			06/10/2021	109431	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Engine\COOL LEAKS	recheck coolant leak on compressor			06/10/2021	109431	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
			park lights not working													
T274	Myrtleford - Workshop	Elect\TRL LIGHTS	slide - skid for trailer missing at the back			24/09/2021	107687	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Body\CHN/RLR/MN	replace RHS slide roller			18/09/2021	10670	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Elect\TRL LIGHTS	repair tail lights wiring			18/09/2021	10670	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			17/09/2021	106706	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			17/09/2021	106706	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER

T274	Myrtleford - Workshop	Tyres\TP9+10	supply and fit 2 tyres and 1 runout			17/09/2021	106707	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres\TP04	Tyre Position 4 RECKECK BRAKE PERCENTAGE			17/09/2021	106707	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes\BRK RELINE	FD 30% SD 30% MA 50% RA 30%			14/09/2021	122601	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection as per checklist	Insp\ANN INSP		09/09/2021	105782	PreventativeMaintenance	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Susp\SHOCK ABS	REPLACE RHR DOLLY SHOCKER BUSHES			28/08/2021	105782	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Susp\AIR BAG	REPLACE LHF DOLLY AIR BAG		replace LHR airbag also	28/08/2021	105782	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		replace LHF mudguard	27/08/2021	104071	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			27/08/2021	104071	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres\TP11+12	supply and fit 2tyres			25/08/2021	103784	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			11/08/2021	107892	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			11/08/2021	107892	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres\BREAKDOWN	Take to Beaurepairs to repair & change tyres			07/08/2021		Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Body\MUDGUARDS	mudguard damage			06/08/2021	100815	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres\TP03	Supply and fit 1 tyre			05/08/2021	100527	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres\TP7+8	Supply and fit 2 tyres			29/07/2021	99412	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist			28/07/2021	99169	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			28/07/2021	99169	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres\DAMAGE	flat tyre - workshop for changing		replaced flat tyre LHS rear on dolly inside	24/07/2021	98455	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Susp\SUSPENSION	REPLACE RHR SHOCKER			15/07/2021	99169	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist		mudguard outrigger loose	14/07/2021	96805	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			14/07/2021	96805	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Body\HOUSEKEEP	REPLACE GREASE NIPPLE ON RHR AXLE			21/05/2021		Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
					checked ebs											
					repaired faults											
T274	Myrtleford - Workshop	Brakes\EBS Kit	CHECK EBS FAULTS		took download - found overspeeds up to 133km hr	21/05/2021		Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		replaced 1x indicator	20/05/2021	94044	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			20/05/2021	94044	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Chassis\FIFTH WHEE	check turntable looks like has movement			04/05/2021	85026	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
					repair rear bolster lights wiring											
					replace LHF bolster indicator											
T274	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist		reolace 4x shocker rubbers	04/05/2021	85026	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			04/05/2021	85026	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres\RETREAD	Supply and fit 2 tyres POS 13&14 tyre blown			28/04/2021	91010	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres\DAMAGE	mudsuard need reolaced x2 strap needs replacement			21/04/2021	89620	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Chassis\WINCH/STRP	LHS of trailer			21/04/2021	89620	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres\DAMAGE	1x mudflap			21/04/2021	89620	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres\TP5+6	Supply and fit 2 tyres			21/04/2021	89620	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Susp\AIR BAG	replace RHR airbag			17/04/2021	89234	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Susp\DAMAGE	repair RHR airbag mount L11528			17/04/2021	89234	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			16/04/2021	892341	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			16/04/2021	892341	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Body\AIR BAG	REPAIR DAMAGE TO AIR BAG AND PEDESTAL LHR DOLLY			27/03/2021	88020	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			25/03/2021	861822	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			25/03/2021	861822	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Chassis\WINCH/STRP	quick unhitch wire under spring		repair quick release cable for strap to long	19/03/2021	35377	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Susp\DAMAGE	REPAIR REAR AIR BAG RAMP			13/03/2021	85455	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
					replaced 2x clearance lights											
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		check ebs and take download	12/03/2021	84297	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			12/03/2021	84297	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Chassis\WINCH/STRP	remove winch off trailer and fit rebuilt winch			06/03/2021	83343	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Wodonga - Workshop	Chassis\WINCH/STRP	REAR WINCH NEEDS REBUILDING			04/03/2021	82802	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Wodonga Workshop	TRAILER
T274	Myrtleford - Workshop	Chassis\WINCH/STRP	repair rear winch			03/03/2021	82584	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Susp\SHOCK ABS	REPLACE LHF SHOCKER			27/02/2021	82584	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
					replaced rear winch strap											
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		1x slide roller	26/02/2021	81644	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			26/02/2021	81644	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Albury - Workshop	Tyres\Re-Tor	Re-Torque POS 1,2,5,6.			17/02/2021		Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Albury Workshop	TRAILER
T274	Myrtleford - Workshop	Susp\DAMAGE	Replace RHS rear air bag ramp			16/02/2021	80171	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		checked ebs	13/02/2021	79302	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			13/02/2021	79302	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Body\CHN/RLR/MN	replace chassis roller		unblocked nozzles	03/02/2021		Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			02/02/2021	76888	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			02/02/2021	76888	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres\TP08	replace tyre			21/01/2021	75085	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres\BREAKDOWN	RHR dolly tyre flat		changed flat tyre RHR dolly	20/01/2021	74768	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Elect\TRL LIGHTS	LH daytime light not working - cleaned plug all good			20/01/2021	74768	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		repair bolster light wiring	16/01/2021	74753	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			16/01/2021	74753	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres\TP1+2	Replace 2 tyres			16/01/2021	74266	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			16/12/2020	71757	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			16/12/2020	71757	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		replaced clearance lights	04/12/2020	69333	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			04/12/2020	69333	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
					has air lock issue in fuel occasssionaly											
T274	Myrtleford - Workshop	VehService\AS	A Service As Per Attached Checklist		checked fuel pick up and hoses ok	04/12/2020	354904	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			04/12/2020	354904	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Chassis\BOLSTER	crack in under dolly RHS boster pivot			25/11/2020	71893	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Hydraulics\RAM	replace broken ram pin			24/11/2020	351580	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Elect\TRL LIGHTS	replaced clearance and indicator lights			24/11/2020	67710	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Body\HOUSEKEEP	check under trailer			19/11/2020	67709	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes\BOOSTER	check booster hoses and clamps			19/11/2020	67709	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Susp\AIR LEAK	check airbag for leaks			19/11/2020	67709	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Chassis\WINCH/STRP	Fit 4 x Winches and Air Lines L10156			12/11/2020	67709	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Chassis\HOUSEKEEP	LHS mudguards cracks in mount			07/11/2020	66515	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Body\MOUNTS	LHS mudguards cracks in mount			07/11/2020	66515	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Chassis\HOUSEKEEP	weld trailer cracks			07/11/2020	66515	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Body\MOUNTS	weld trailer cracks			07/11/2020	66515	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Body\MUDGUARDS	straighten RH mudguard and bracket			07/11/2020	66515	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Body\DAMAGE	straighten LH sign mount			07/11/2020	66515	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Body\SUSPENSION	Repair LHR Trailer shock bolt		replace other shocker bolts as well	07/11/2020	66513	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Chassis\CROSS MBR	Tighten up cross member bolts			07/11/2020	66513	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Body\DAMAGE	Repair LHR trailer light bar and cracks			07/11/2020	66513	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		replaced RHF dolly & LHR trailer bushings	06/11/2020	66513	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			06/11/2020	66513	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Body\FIFTH WHEE	hook up and test			29/10/2020	64982	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Elect\TRL LIGHTS	fix bolster wiring			29/10/2020	64982	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
					weld trailer crack also											
T274	Myrtleford - Workshop	Chassis\BOLSTER	Front Bolster Needs Welding		replace slide locks	15/10/2020	64982	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Chassis\BOLSTER	Check all Bolster Pivot Bushes and Pins L10065			15/10/2020	64982	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		rewelded shocker cover	14/10/2020	63920	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			14/10/2020	63920	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
					tow eye twisted u/s											
T274	Unknown - Unknown	Chassis\DAMAGE	Replace tow eye L10037		replace tow eye	03/10/2020	64982	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Unknown - Unknown	Susp\SUSPENSION	Replace Rear Dolley Front Axle Spring Eye Bushes			02/10/2020	61731	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		fitted broken top shocky bolt	30/09/2020	61462	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job middle dolly shocker			30/09/2020	61462	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Susp\SHOCK ABS	left hand side bolt mising		replace shocker bolt	25/09/2020	60334	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Susp\SHOCK ABS	middle boggy shocker mounts broken left hand side			17/09/2020		Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			11/09/2020	58364	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			11/09/2020	58364	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Body\MUDGUARDS	mudguards damaged due to blow out			04/09/2020	57117	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Chassis\WINCH/STRP	quick release latch damaged			04/09/2020	57117	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Susp\SHOCK ABS	Replace front dolley LHR shocker Bushes			29/08/2020	56052	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Susp\DAMAGE	Repair Rear dolly LHS axle saddle cracks			29/08/2020	56052	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist			28/08/2020	56650	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			28/08/2020	56650	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Chassis\WINCH/STRP	PO FOR STRAPS			26/08/2020		Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection as per checklist	Insp\ANN INSP		18/08/2020	53785	PreventativeMaintenance	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist			18/08/2020	53785	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			18/08/2020	53785	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Body\WHL HUB	back trailer stud has come out of LH side front wheel			12/08/2020		Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Body\WHL HUB	R/H side front wheel on dolley wheel bearing			12/08/2020		Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Elect\TRL LIGHTS	replaced trailer clearance light			08/08/2020	51697	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Body\MUDGUARDS	straighten guard			08/08/2020	51697	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Wodonga - Workshop	Body\WHL HUB	hubo u/s		RR's pre Jan 20 (system clean out) 05/08/20	06/08/2020		Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Wodonga Workshop	TRAILER
T274	Myrtleford - Workshop	Susp\AXLES	Replace 2nd axle assembly on front dolley			05/08/2020	51696	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Susp\DAMAGE	inspect 2nd axle wheeel bearing failure			04/08/2020		Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER

T274	Myrtleford - Workshop	Body\WHL HUB	remove LH wheels/hub			04/08/2020		Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Body\WHL HUB	check all other wheel bearings			04/08/2020		Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Susp\AXLES	get ready to remove 2nd axle on front dolly			04/08/2020		Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		repair first bolster clearance/blinker lights wiring	31/07/2020		Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			31/07/2020		Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Body\MUDGUARDS	broken mudguard			28/07/2020	50281	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Susp\SUSPENSION	check spring eye bushes			28/07/2020	50281	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		replace shocker rubbers and bolts x8	18/07/2020	48481	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			18/07/2020	48481	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes\BRK RELINE	Crack test and Reline 2nd Axle on Front Dolley and Both Axles on Rear Dolley			10/07/2020	47110	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Elect\TRL LIGHTS	Repair Bolster Light on LHS			10/07/2020	47169	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			08/07/2020	46558	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			08/07/2020	46558	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes\BOOSTER	last trailer booster loose			02/07/2020	4495	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			25/06/2020	43271	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			25/06/2020	43271	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist		replaced LHR dolly airbag	16/06/2020	41040	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			16/06/2020	41040	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Susp\SHOCK ABS	Replace LHR shocker on front dolly			05/06/2020	38799	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		replaced slack adjuster	04/06/2020	38405	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			04/06/2020	38405	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			28/05/2020	36449	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			28/05/2020	36449	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Chassis\DAMAGE	Replace LHS A Frame bush & pin			20/05/2020	34835	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist			19/05/2020	33416	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			19/05/2020	33416	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Susp\SHOCK ABS	Replace LHF shocker on front dolly			12/05/2020	33014	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Susp\SHOCK ABS	Replace LHR shocker on rear dolly			12/05/2020	33014	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Elect\TRL LIGHTS	LHS inner tail light/brake light faulty led's		trailer lights	10/05/2020	31052	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist			08/05/2020	31052	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			08/05/2020	31052	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Body\WHL HUB	replace trailer hub and bearings and seal and fit 2x new rims and tyres			02/05/2020		Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			29/04/2020	28522	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			29/04/2020	28522	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
					air leaks, tidy up rubiing hoses														
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		tiehten mudeuard	18/04/2020	26041	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			18/04/2020	26041	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist			07/04/2020	23602	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			07/04/2020	23602	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Susp\SHOCK ABS	Replace RHR shocker on rear dolly			27/03/2020	21600	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Susp\SHOCK ABS	Replace LHF dolley shocker			27/03/2020	21600	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			26/03/2020	21011	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			26/03/2020	21011	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Susp\AIR LEAK	air leak rear axle LHS dolly airbag			17/03/2020	18603	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Body\AIR LEAK	air leak somewhere around airtank area in front of 3rd axle			17/03/2020	18603	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist		1x winch strap	17/03/2020	18603	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			17/03/2020	18603	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			04/03/2020	16068	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			04/03/2020	16068	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Body\DAMAGE	Repair or replace RHS Dolley bump stop			21/02/2020	13730	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			20/02/2020	13540	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			20/02/2020	13540	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
			Back off and recheck all low brake %		back off and recheck all low brake % all at 50%														
T274	Myrtleford - Workshop	Brakes\BRK RELINE	All at 50 %		rechecked all low brake % all 50%	01/02/2020	12782	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			31/01/2020	10963	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			31/01/2020	10963	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
					change RHR slack adjuster														
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		fit keeper to bolster side light	14/01/2020	8252	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			14/01/2020	8252	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
					changed rear dolly LHF tyre														
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		repair clearance light wiring	12/12/2019	6136	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			12/12/2019	6136	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Elect\ELECT P&W	no.3. channel scales not working properly		inspected no scales at bay 3 and to power at controller need more time to find fault	08/12/2019	5278	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Chassis\CROSS MBR	crack in trailer			08/12/2019	5278	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Chassis\BOLSTER	2nd last winch handle and strap replace		replaced 3rd bolster strap and handle	27/11/2019	3668	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
					front axle completed 5/7/19														
T274	Myrtleford - Workshop	Brakes\BRK RELINE	Reline all 4 wheels on front dolley		comoleted 6/12/19	20/11/2019	5278	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
					rear air tank bolts snapped														
T274	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist		light not working fourth bolster	19/11/2019	2950	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			19/11/2019	2950	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Body\PANELS	back light bent			09/11/2019	1122	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Elect\ELECT P&W	air for electic line broken			02/11/2019		Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
					straightened tail light bracket														
					rewelded bracket														
T274	Myrtleford - Workshop	Chassis\DAMAGE	L.H.B light bar bent		fixed lights	24/10/2019	310	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			23/10/2019	285	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			23/10/2019	285	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Chassis\DAMAGE	straighten rear bar			17/10/2019		Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Body\WHL HUB	hubo u/s			17/10/2019		Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist replace 1 x air bag			02/10/2019	262503	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			02/10/2019	262503	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Wodonga - Workshop	Prod Hose\DAMAGE	replace cam locks + clamps			13/09/2019		Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Wodonga Workshop	TRAILER			
T274	Myrtleford - Workshop	Body\WHL HUB	Replace LHF hub assembly on rear bogie and check drum and brake linings			12/09/2019	260025	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Chassis\WINCH/STRP	crank handle missing			10/09/2019	259449	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist			06/09/2019	258838	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			06/09/2019	258838	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Elect\ELECT P&W	scales not working			05/09/2019	258838	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Chassis\WINCH/STRP	knob broken off winch			31/08/2019	257791	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			21/08/2019	25562	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			21/08/2019	25562	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Hydraulics\HOSES	split hose between trailers			20/08/2019	255262	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Hydraulics\OIL/FILTER	refill hydraulic oil			20/08/2019	255262	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			06/08/2019	252533	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			06/08/2019	252533	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Body\DAMAGE	weld up crack on light bracket			30/07/2019	257662	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Body\REFLECTORS	reattached zebra sign			30/07/2019	257662	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes\EBS Kit	EBS faults			30/07/2019	257662	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Chassis\BOLSTER	tighten bolster mounts bolts			30/07/2019	257662	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Body\CHN/RLR/MN	replace chassy roller bearings LH&RH sides			30/07/2019	257662	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Elect\TRL LIGHTS	check lights			30/07/2019	257662	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	DrCabElect\SCALES	trailer scales playing up saying -97 unloaded re-loaded			25/07/2019	251336	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	DrCabElect\SCALES	check scales			23/07/2019	250716	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Chassis\WINCH/STRP	Fit 2nd Hand Elphinstone Winches L6743			10/07/2019	248139	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Body\WHL HUB	adjust and check all wheel bearings			09/07/2019	248137	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		check and adjust wheel bearings	06/07/2019	248136	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			06/07/2019	248136	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection as per checklist	Insp\ANN INSP		06/07/2019	248136	PreventativeMaintenance	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
					fit 2x bolster lights to LH bolsters														
					fit 1x indicator light to LHM bolster														
					fit 1x rear indicator and rubber														
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		remove shockers and fit bushes	06/07/2019	248136	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job unhook trl 245 off s-line			06/07/2019	248136	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Body\FIFTH WHEE	hook up s-line to trl 274			05/07/2019		Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Chassis\BOLSTER	Repair Cracks In 5th & 6th Bolsters			22/06/2019		Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			19/06/2019	744758	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			19/06/2019	744758	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Chassis\WINCH/STRP	new strap for last winch on trailer			18/06/2019	244758	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Body\DAMAGE	blinker bar bent			04/06/2019	242918	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Elect\ELECT P&W	reverse lights not working			04/06/2019	242918	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			25/05/2019	241148	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			25/05/2019	241148	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Chassis\WINCH/STRP	springs on trailer winchs need replacing			17/05/2019	238390	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Susp\SHOCK ABS	Replace RHF Shocker On Rear Dolly		checked still ok	16/05/2019	243865	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			15/05/2019	237895	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		bottom shoes 20% top shoes 40% on rear axle	15/05/2019	237895	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist			30/04/2019	235029	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			30/04/2019	235029	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
					also replaced RHF shocker mount														
T274	Myrtleford - Workshop	Susp\SHOCK ABS	Replace LHF bottom shocker mount		fitted 1x new shock absorber	17/04/2019	248138	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		fit mudguard bracket	11/04/2019	231798	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			

T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				11/04/2019	231798	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist		replaced LHR s/adj rear dolly		27/03/2019		Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				27/03/2019		Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Susp\SHOCK ABS	Replace LHF Shock On Front Dolly				19/03/2019	226334	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Susp\HOUSEKEEP	Replace RHF Shock Rubbers On Front Dolly				19/03/2019	226334	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Susp\HOUSEKEEP	Replace 3 x Shockers Rubbers On Rear Dolly		replaced LHR shocker		19/03/2019	226334	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Elect\TRL LIGHTS	bolster lights n/w				16/03/2019		Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist				16/03/2019	225071	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				16/03/2019	225071	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Chassis\WINCH/STRP	strap on second bay needs replacing..the front one				06/03/2019	222186	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
			Replace LH reverse light														
T274	Myrtleford - Workshop	Elect\TRL LIGHTS	SUPPLY 2 X LOG STRAPS		replace L&R reverse lights		06/03/2019	228386	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
					fit rap to hyd hoses												
T274	Myrtleford - Workshop	Hydraulics\HOSES	Extend or replace RH lift ram hoseLS878		223836 km		06/03/2019	228386	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Chassis\WINCH/STRP	second bay missing quick release cable				05/03/2019	221608	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist				05/03/2019	221656	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				05/03/2019	221656	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Body\FIFTH WHEE	hook up trailer and test				01/03/2019	22118	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
			repair wiring problem in trailer														
T274	Myrtleford - Workshop	Elect\ELECT P&W	& tidy up cables				01/03/2019	22118	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Elect\ELECT P&W	fit new trailer plug				01/03/2019	22118	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Elect\ELECT P&W	fit new scale plug 7pin male				01/03/2019	22118	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Chassis\CROSS MBR	replace nut on bolts on cross member				01/03/2019	22118	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes\BRAKE ADJ	adjust brakes				01/03/2019	22118	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes\AIR LEAK	check booster hose clamps				01/03/2019	22118	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Body\HOUSEKEEP	Tie up air lines				01/03/2019	22118	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Hydraulics\RAM	check hydraulic rams				21/02/2019	221178	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Hydraulics\VALVES	relief valves				21/02/2019	221178	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Body\FIFTH WHEE	unhook trailer				09/02/2019	221176	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist				30/01/2019	218907	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				30/01/2019	218907	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes\BRAKE ADJ	adjust brakes				25/01/2019	218296	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Susp\AIR BAG	replace LHR & RHR airbags on rear dolley				22/01/2019	216724	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Susp\DAMAGE	replace RH and LH suspension feet on rear axle				22/01/2019	216724	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Body\HOUSEKEEP	test fold				22/01/2019	216724	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Elect\INDICATORS	rear trailer blinker's not working				16/01/2019	216057	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist				15/01/2019	215780	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				15/01/2019	215780	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Body\MUDGUARDS	Repair & replace mudguards & mounts				04/01/2019	218907	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Hydraulics\VALVES	trailer dropping on its own				03/01/2019	213572	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Chassis\CROSS MBR	Repair crack in LHR cross member hanger				22/12/2018	221178	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres	Replace rear dolley tyres				22/12/2018	221178	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist				21/12/2018	212577	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				21/12/2018	212577	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Body\DAMAGE	Repair rear bar on trailer		Rinlatech		12/12/2018	22178	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Body\MUDGUARDS	Replace RHF mudguard on front dolly				12/12/2018	22178	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Body\CHAS CRACK	Repair crack in draw bar stops				12/12/2018	22178	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
					repaired side indicator wiring												
					welded handle on winch												
					replaced 1x winch strap												
					repaired winch spring												
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		rear axle airbag mounts needs repair		11/12/2018	209455	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				11/12/2018	209455	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Susp\SUSPENSION	Replace front Axle suspension bushes on front dolly				07/12/2018	221180	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Susp\SUSPENSION	Replace front Axle suspension bushes on rear dolly		fit new LHR mudguard		07/12/2018	221180	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Chassis\HOUSEKEEP	Replace A frame bushes & pins				07/12/2018	221180	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist		replaced 2 shockers front dolly rear axle		05/12/2018	206357	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				05/12/2018	206357	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist				16/11/2018	203596	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				16/11/2018	203596	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist				31/10/2018	200522	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				31/10/2018	200522	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Chassis\CROSS MBR	Repair ram cross member cracks				06/10/2018	221178	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist				05/10/2018	197299	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				05/10/2018	197299	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Susp\SHOCK ABS	replace leaking shocker				04/10/2018	197299	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Body\CHN/RLR/MN	trailer lock broken on RHS				03/10/2018	196782	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice				23/09/2018	0	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice				23/09/2018	0	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Elect\TRL LIGHTS	repaired 2nd bolster clearance light wiring (rear dolly)				22/09/2018	195757	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist		replace missing RH outer slide roller		13/09/2018	194320	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				13/09/2018	194320	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres	Job Added From Invoice				11/09/2018	0	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice				11/09/2018	0	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice				11/09/2018	0	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Susp\HOUSEKEEP	replace both rear axle suspension stoppers				04/09/2018	192785	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
			repair RH lift ram leaking														
T274	Myrtleford - Workshop	Hydraulics\RAM	(fit seals and new chrome rod)				04/09/2018	192785	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres	Job Added From Invoice				01/09/2018	0	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice				01/09/2018	0	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres\CLEANSKIN	Job Added From Invoice				01/09/2018	0	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	DrCabElect\ELECT P&W	check slide locks				28/08/2018	191832	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres\BREAKDOWN	change LHR outer tyre - front dolly				28/08/2018	191832	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes\BRAKE ADJ	adjust brakes				25/08/2018	191787	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Workshop\MOVE ASSET	test fold				25/08/2018	191787	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes\BRK RELINE	Reline brakes on 3 x axles				02/08/2018	191784	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice				11/07/2018	141552	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres\CLEANSKIN	Job Added From Invoice				11/07/2018	141552	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres\RUN OUT	Job Added From Invoice				11/07/2018	141552	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist				06/07/2018	191552	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				06/07/2018	191552	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres\RUN OUT	Job Added From Invoice				03/07/2018	0	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres\RUN OUT	Job Added From Invoice				03/07/2018	0	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Elect\TRL LIGHTS	LH indicator and brake lights out				28/06/2018	190064	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Hydraulics\RAM	replace leaking trailer ram and test				27/06/2018	189794	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Hydraulics\OIL/FILTER	top up hydraulic oil				27/06/2018	189794	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
			cut hole for mudguard bracket														
			fit new bolt														
T274	Myrtleford - Workshop	Body\MUDGUARDS	(f-dolly LHR mudguard)				23/06/2018	189225	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Hydraulics\RAM	remove new hydraulic ram and refit old one				23/06/2018	189225	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Chassis\WINCH/STRP	fit 2x quick release cables				22/06/2018	189223	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Elect\WORK LIGHT	Repair reverse light wiring				22/06/2018	189225	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Elect\WORK LIGHT	no reverse lights				21/06/2018	189029	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist		replace (LHF) airbag		14/06/2018	188403	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				14/06/2018	188403	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Elect\WORK LIGHT	reverse liights not working				13/06/2018	188250	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice				13/06/2018	0	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres\CLEANSKIN	Job Added From Invoice				13/06/2018	0	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres\TP18	change flat tyre on front dolly				07/06/2018	186997	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Body\CHN/RLR/MN	Trailer lock brokenRHS				02/06/2018	186408	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes\BRK RELINE	Crack test & reline rear axle on 2nd dolly				31/05/2018	185917	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Body\WHL HUB	Replace LHF Hub on Front Dolley				30/05/2018	189225	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Body\WHL HUB	Fit 2 x New Steel 8 Stud Rims				30/05/2018	189225	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist				30/05/2018	185916	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				30/05/2018	185916	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Hydraulics\RAM	Repair LH Ram leak		(new ram on order) fit new ram		03/05/2018	189225	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Chassis\CROSS MBR	Repair crack in cross member in rear dolly				03/05/2018	189225	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Chassis\CROSS MBR	Repair crack in lift ram cross member				03/05/2018	189225	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice				02/05/2018	0	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist				02/05/2018	182754	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				02/05/2018	182754	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Body\MUDGUARDS	fit new outrigger on LHR front dolly				06/04/2018	179816	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection as per checklist	Insp\ANN INSP			06/04/2018	179816	PreventativeMaintenance	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist				06/04/2018	179816	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				06/04/2018	179816	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice				24/03/2018	79745	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres\CLEANSKIN	Job Added From Invoice				24/03/2018	79745	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist		leaking (LH) lift ram		21/03/2018	177648	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				21/03/2018	177648	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Chassis\WINCH/STRP	weld winch in front of truck and fold back up				10/03/2018	175262	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER

			refit LHS slide lock assembly and remove all broken studs															
T274	Myrtleford - Workshop	Chassis\DAMAGE	replace LHS and RHS slide lock stops		02/03/2018	173681	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Elect\TRL LIGHTS	check lights and indicators		02/03/2018	173681	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Body\MOUNTS	repair rear tail light bar mount		02/03/2018	173681	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Body\CHN/RLR/MN	tighten loose roller		02/03/2018	173681	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Chassis\HOUSEKEEP	disconnect trailer		02/03/2018	173681	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Chassis\HOUSEKEEP	hook up trailer and test		02/03/2018	173681	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		22/02/2018	172976	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		22/02/2018	172976	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Elect\INDICATORS	RH rear blinker not working		20/02/2018	172224	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Elect\TRL LIGHTS	LH tail light keeps falling out		20/02/2018	172224	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		09/02/2018	170710	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		09/02/2018	170710	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Chassis\HOUSEKEEP	grind rough edge & REPAIR AXLE SADDLE CRACKS. grind rough edge	clean rough metal burrs off chassis rail	08/02/2018	170316	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Body\MOUNTS	bolt in hitch broken		06/02/2018	170075	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Elect\TRL LIGHTS	LHR indicator - not working		06/02/2018	170075	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice		06/02/2018	168764	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Tyres\CLEANSKIN	Job Added From Invoice		06/02/2018	168764	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist		20/01/2018	167314	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		20/01/2018	167314	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Tyres\PRES CHECK	Job Added From Invoice		12/01/2018	0	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	fit split pin and washer on rear hcv rod	04/01/2018	164629	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		04/01/2018	164629	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Tyres	Job Added From Invoice		30/12/2017	163720	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice		30/12/2017	163720	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Elect\ELECT P&W	Repair scales on front bay	Needs new pacific scales transducer	30/12/2017	165497	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Elect\ELECT P&W	Check scales on centre bay - not working		29/12/2017	16395	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Insp\UNT INSP	check over and check tyres		28/12/2017		Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Susp\WHEEL ALGN	wheel align all 4 axles		13/12/2017	161623	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Body\MUDGUARDS	refit RHF and LHF mudguard		13/12/2017	161623	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Tyres	Job Added From Invoice		12/12/2017	160553	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Susp\AIR BAG	Check all air bags for leaks		07/12/2017	16162	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Body\AIR LEAK	Check for any air leaks in system	replaced booster diaphram trl front 37.8 32.8 31 31 all ok trl rear 28 30.4 31 29 all ok	07/12/2017	16162	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Susp\SHOCK ABS	Check all shockers - hot & cold		07/12/2017	16162	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Body\MOUNTS	Check all trailer bushes & pins		07/12/2017	16162	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Chassis\CHAS CRACK	Repair crack in draw bar stopper on RHS		07/12/2017	161622	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Body\MOUNTS	Replace shocker mount bolt		07/12/2017	161622	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Susp\SUSPENSION	Replace 2nd Axle spring eye bushes		07/12/2017	161622	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Susp\SUSPENSION	Replace 3rd Axle spring eye bushes		07/12/2017	161622	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist		06/12/2017	161302	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		06/12/2017	161302	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Body\AIR LEAK	check air dropping		05/12/2017	161302	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes\SLACK ADJ	Check front axle locking up		05/12/2017	161302	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Susp\SHOCK ABS	front axle missing bolt out of shocker		21/11/2017	158875	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Susp\SHOCK ABS	replace shock absorbers as required		17/11/2017	158645	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Susp\SHOCK ABS	replace shocker bushes as required		17/11/2017	158645	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		17/11/2017	158433	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		17/11/2017	158433	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice		15/11/2017	156286	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Tyres\CLEANSKIN	Job Added From Invoice		15/11/2017	156286	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Tyres\RUN OUT	Job Added From Invoice		15/11/2017	156286	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Body\MOUNTS	Replace tow pin and bush	fit new tow eye asm hook up trailers and test tested shocker temp LHR shocker rear dolly u/s LHF shocker front dolly u/s	14/11/2017	161622	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	DrivLine\SHOCK ABS	Check shock absorbers when loaded	most shocker rubbers u/s top and bottom	14/11/2017	161622	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Body\MOUNTS	Check Dolley bushes and pins in draw bar		11/11/2017	157170	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Elect\TRL LIGHTS	Replace clearance lights		11/11/2017	157170	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Body\MOUNTS	Replace tow pin & bush		11/11/2017	157170	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Chassis\CHAS CRACK	Repair cracks in trailer		11/11/2017	157170	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Body\CHN/RLR/MN	LHS roller on slider very loose		11/11/2017	157170	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	DrivLine\SHOCK ABS	Check shockers		11/11/2017	157170	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Body\MOUNTS	Pins and Bushes		11/11/2017	157170	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Body\CHN/RLR/MN	Slider lock will not unlock		11/11/2017	157170	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		28/10/2017	154091	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job jack rear dolly axles, check wheel bearings		28/10/2017	154091	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes\BRK O/HAUL	remove rocks from brake drums		25/10/2017	15320	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice		17/10/2017	150449	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Tyres\CLEANSKIN	Job Added From Invoice		17/10/2017	150449	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Body\AIR LEAK	airline has a hole under slider		12/10/2017	151568	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Body\CHN/RLR/MN	roller has come loose LHS		12/10/2017	151568	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Body\CHN/RLR/MN	Replace bearings in RH chassis roller		12/10/2017	151568	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Body\CHN/RLR/MN	LHS roller on slider	fit bearings to LH chassis roller	11/10/2017	151248	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Body\HOUSEKEEP	fix locking plates on slider		11/10/2017	151248	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	repaired side blinker wiring	04/10/2017	149470	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job brakes not releasing losing air		04/10/2017	149470	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Body\AIR LEAK	will not open slider to extend trailer out		21/09/2017	147375	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		13/09/2017	145468	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		13/09/2017	145468	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Tyres	Job Added From Invoice		01/09/2017	140670	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		31/08/2017	142000	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		31/08/2017	142000	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Body\STCH GUARD	floor mat needs new spring		30/08/2017	141664	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Body\HOUSEKEEP	LHS rear log stuck log stuck between tyres and mudguard		30/08/2017	141664	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes\EBS Kit	program EBS		22/08/2017	139580	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes\EBS Kit	check and engineers trailer		22/08/2017	139580	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Elect\TRL LIGHTS	refit panels and check the reverse lights and repair		22/08/2017	139580	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Workshop\CLEAN	clean up		18/08/2017		Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Elect\ELECT P&W	rewire rear of trailer		17/08/2017	13958	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Susp\SHOCK ABS	Replace RHF shocker on front dolly		30/06/2017	139580	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		29/06/2017	138716	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		29/06/2017	138716	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Tyres	Job Added From Invoice		21/06/2017	0	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		17/06/2017	135393	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		17/06/2017	135393	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Hydraulics\HYD LEAKS	broken hyd line on dolley FIT EBS KIT TO FRONT & REAR AXLES L3016 (CUMMINS)		16/06/2017	135004	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes\EBS Kit	L3124 (rinlatech)L3086(bankos) L3147 (albury truck & trl)		15/06/2017	139580	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Susp\SPRNG HANG	Repair LHR hanger crack on rear dolly		08/06/2017	134697	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	tighten (LHR F-Dolly) mudguard outrigger and replaced bolt	07/06/2017	132645	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		07/06/2017	132645	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		25/05/2017	128904	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		25/05/2017	128904	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice		23/05/2017	0	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Tyres\CLEANSKIN	Job Added From Invoice		23/05/2017	0	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Chassis\HOUSEKEEP	replace tow pin eye bush and coupling bushes		19/05/2017		Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Body\HOUSEKEEP	Fold up trailer on truck	Complete	15/05/2017		Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		10/05/2017	125331	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		10/05/2017	125331	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Tyres	Job Added From Invoice		27/04/2017	0	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Chassis\WINCH/STRP	Cut hooks off staps	Complete	21/04/2017	122100	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Susp\HOUSEKEEP	Check dolley bushes	Complete	21/04/2017	122100	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Body\PAINT/REST	Supply can of crome bright	Complete	21/04/2017	122100	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		21/04/2017	122100	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		21/04/2017	122100	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Susp\AIR BAG	Replace RHF air bag on rear dolley		07/04/2017	119906	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Tyres\TP19	Job Added From Invoice		06/04/2017	1849	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Body\CHN/RLR/MN	re attach R/H dog slide lock tag under seat		31/03/2017	118904	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Susp\SPRNG HANG	Repair LHR dolly hanger cracks		31/03/2017	118904	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Chassis\CROSS MBR	Repair rear dolly cross member cracks		31/03/2017	118904	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Body\CHN/RLR/MN	replace L/H slide lock roller (outer)		30/03/2017	118582	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	replace shocker and bush	30/03/2017	118727	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		30/03/2017	118727	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		30/03/2017	118727	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			

T274	Myrtleford - Workshop	Susp\AIR BAG	airbag leaking R/H side last axle			22/03/2017	117185	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Tyres\TP11	Job Added From Invoice			10/03/2017	0	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Tyres\TP20	Job Added From Invoice			10/03/2017	0	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Body\MUDGUARDS	please replace/repair (if possible) rear mudflaps on trailer			10/03/2017	115542	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			10/03/2017	115542	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			10/03/2017	115542	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Tyres\TP13	Job Added From Invoice			01/03/2017	113353	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes\BRK RELINE	crack test & reline front axle			24/02/2017	114020	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Susp\HCV	ride leveller leak? Back dolly			24/02/2017	114020	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			15/02/2017	112570	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			15/02/2017	112570	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Chassis\WINCH/STRP	Replace rear winch strap & 2nd last winch strap		Complete	14/02/2017	112570	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Chassis\WINCH/STRP	Replace quick release cable - last on rear		Complete	14/02/2017	112570	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Tyres\TP13	Job Added From Invoice			01/02/2017	108359	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Tyres\TP15	Job Added From Invoice			01/02/2017	108359	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			28/01/2017	109291	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			28/01/2017	109291	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			11/01/2017	106310	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			11/01/2017	106310	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Body\HOUSEKEEP	fit lay flat hose to brake hoses			06/01/2017	10561	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Elect\TRL LIGHTS	repair bolster sidelight fit new tow pin bush fit new tow pin			06/01/2017	10561	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Chassis\HOUSEKEEP	fit new nylon spacer washer			06/01/2017	10561	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Chassis\WINCH/STRP	fit winch strap + spring to RHF winch			06/01/2017	10561	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
					fit 4x brake drums														
T274	Myrtleford - Workshop	Brakes\BRK RELINE	Crack test & reline 2nd & 3rd axles		fit 2x rear signs	23/12/2016	105651	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Body\MOUNTS	slide lock L/H side bolt broken			17/12/2016	104566	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	DrCabElect\SCALES	no scales last bay (channel)			17/12/2016	104566	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Body\HOUSEKEEP	fit hooks to cross member for gibbo rubbers			13/12/2016	103314	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		fit new RH outer tail light	13/12/2016	103314	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			13/12/2016	103314	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			30/11/2016	100374	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			30/11/2016	100374	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
					Fit new mount for hoses														
T274	Myrtleford - Workshop	Body\MOUNTS	Trailer slide umbilical too low - P bracket broken off		Complete	29/11/2016		Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Tyres\TP19	Job Added From Invoice			26/11/2016	96523	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Tyres\TP11	Job Added From Invoice			26/11/2016	0	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Tyres\TP19	Job Added From Invoice			26/11/2016	0	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Elect\TRL LIGHTS	repair short in lights on second last bolster			16/11/2016	97057	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			16/11/2016	97057	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			16/11/2016	97057	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes\AIR LEAK	repair split hose - park brake side trailer slidelock			08/11/2016	94937	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			29/10/2016	93935	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			29/10/2016	93935	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Chassis\BOLSTER	Weld crack on RHR bolster mount			18/10/2016	105651	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Chassis\HOUSEKEEP	Weld crack on RHR of chassis			18/10/2016	105651	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			15/10/2016	91002	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			15/10/2016	91002	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Tyres\TP13	Job Added From Invoice			11/10/2016	87326	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Susp\SHOCK ABS	replace detached shock absorber			07/10/2016		Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			04/10/2016	88212	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			04/10/2016	88212	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Tyres\TP15	Job Added From Invoice			23/09/2016	89061	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Tyres\TP20	Job Added From Invoice			23/09/2016	89061	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			17/09/2016	84982	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			17/09/2016	84982	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Body\MUDGUARDS	Tighten outrigger bolt on front dolly - LHR mudguard. Tighten outrigger bolt front dolly - LHR mudguard brake booster leak (service side) trailer		Complete	16/09/2016	84982	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes\AIR LEAK	front dolly - front axle			16/09/2016	84627	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Susp\SHOCK ABS	Replace front axle shockers on front dolly			07/09/2016	84982	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			06/09/2016	81705	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			06/09/2016	81705	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Elect\TRL LIGHTS	Repair indicator LHR - out of socket		Complete	05/09/2016	81705	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Tyres\TP15	Job Added From Invoice			01/09/2016	79715	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			23/08/2016	78746	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			23/08/2016	78746	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Chassis\SPAREWHEEL	replace spare wheel safety chain bolt			13/08/2016	78231	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Chassis\WHL HUB	check front dolly wheel bearings			29/07/2016		Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			29/07/2016	75282	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			29/07/2016	75282	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Elect\TRL LIGHTS	Replace wiring from A frame to 7 pin plug under turntable		replace scale wiring	27/07/2016	75283	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
					locate broken wire in 7 core tralier wires. Repair wiring, replace broken 7 pin plug under checker plate														
T274	Myrtleford - Workshop	Elect\TRL LIGHTS	Repair no parklights, brakes lights, indicators & slide locks		Complete	25/07/2016	14020	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Chassis\HOUSEKEEP	Replace A Frame bushes			19/07/2016	75283	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			16/07/2016	72575	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			16/07/2016	72575	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes\BRK O/HAUL	LH side rear dolly front axle check bearings and brake adjustment - ran hot			08/07/2016	71245	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Susp\SHOCK ABS	Replace LHR & RHR Shockers on rear axle			30/06/2016	69524	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			29/06/2016	69524	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			29/06/2016	69524	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Insp\UNT INSP	srt measurements			21/06/2016		Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Elect\HOUSEKEEP	please replace broken "rubber band" on slide lock umbilical I added one the other day but I think it needs 2 linked together			10/06/2016		Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			10/06/2016	66042	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job Check over Split trailer & replace roller wear pads			10/06/2016	66042	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Chassis\HOUSEKEEP	Reolace tow eve bush Replace 3 x bolster peg bolts Replace bolts on rear bay bolsters		Complete	02/06/2016	64542	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Chassis\BOLSTER	Replace bush in front bolster stay		Complete	02/06/2016	64542	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Body\MUDGUARDS	LHF rear dolly mudguard Replace truck to trailer lights & accessory wiring		Complete	02/06/2016	64542	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Elect\TRL LIGHTS	Replace front trailer clearance lights		Complete	02/06/2016	64542	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Elect\HOUSEKEEP	Fit protective cover to scale wiring		Complete	02/06/2016	64542	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Tyres\TP15	Job Added From Invoice			28/05/2016	63839	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			20/05/2016	62730	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			20/05/2016	62730	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Elect\TAIL LIGHT	replace 2nd lh bolster light			18/05/2016	62043	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Chassis\HOUSEKEEP	slide lock roller R/H outer		replace RH outer slide roller	13/05/2016	61315	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			06/05/2016	59731	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			06/05/2016	59731	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			28/04/2016	57476	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			28/04/2016	57476	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Tyres\TP21	Job Added From Invoice			23/04/2016	54140	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Tyres\TP21	Job Added From Invoice			23/04/2016	0	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Chassis\HOUSEKEEP	slide lock bent/cracked		checked slide lock valve on trailer	17/04/2016	54002	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Body\ELECT P&W	check slide lock operation		operated slide locks repeatedly	17/04/2016	54002	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Elect\TRL LIGHTS	repair R/H side light on bolster. repair R/H side light onm bolster			15/04/2016	54064	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Body\HOUSEKEEP	slide lock still sticky			15/04/2016	54064	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection as per checklist	Insp\ANN INSP		15/04/2016	54064	PreventativeMaintenance	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			15/04/2016	54063	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			15/04/2016	54063	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Elect\ELECT P&W	7 pin pulled wires			13/04/2016	52998	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Susp\SHOCK ABS	Replace 2 x shockers on rear dolly			07/04/2016	52140	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			06/04/2016	51230	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			06/04/2016	51230	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Susp\SHOCK ABS	rear axle on dolly shocks x2 u/s			06/04/2016	51230	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes\SLACK ADJ	replace rear dolly LHF slack adjuster			05/04/2016	51230	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes\BOOSTER	replace LHR brake booster			05/04/2016	51230	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Chassis\HOUSEKEEP	slide lock not working			02/04/2016		Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Hydraulics\RAM	Repair leaking LHS Turntable Lift Ram		check ram for leaks - ok at this stage	23/03/2016	48158	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist			22/03/2016	48002	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			22/03/2016	48002	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
					Tighten mudguard bolt														
T274	Myrtleford - Workshop	Body\MUDGUARDS	Loose front dolly RHR mudguard		Complete	21/03/2016		Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Brakes\AIR LEAK	fit 1/2" joiner to air line & test. fit 1/2 joiner to air line & test		Complete	16/03/2016	46473	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Chassis\AIR LEAK	check trailer for air leaks. check tri for air leaks		Complete	16/03/2016	46473	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Body\MUDGUARDS	replace LHF mudguard bolts			09/03/2016	45253	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			
T274	Myrtleford - Workshop	Susp\SUSPENSION	Replace LHF shocker on front dolley			08/03/2016	45252	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER			

T274	Myrtleford - Workshop	Susp\HOUSEKEEP	Replace LHF suspension eye bush on LHF of rear dolley	fit new eye bush to RHF as well	08/03/2016	45252	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Body\MUDGUARDS	Replace damaged mudguards		08/03/2016	45252	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Chassis\WHL HUB	Replace RHR Hub Assembly & Bearings		08/03/2016	48158	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes\BRK RELINE	Crack Test & Reline RHR Wheel on rear dolley		04/03/2016	44798	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		03/03/2016	44705	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		03/03/2016	44705	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres\TP11	Job Added From Invoice		03/03/2016	35451	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres\TP11	Job Added From Invoice		03/03/2016	0	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres\TP13	Job Added From Invoice		27/02/2016	40856	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres\TP13	Job Added From Invoice		27/02/2016	0	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
				Replace with second hand winch											
T274	Myrtleford - Workshop	Chassis\WINCH/STRP	Second last Winch claw worn out	Completed	24/02/2016	41705	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Chassis\MUDGUARDS	Tighten LHR front dolly outrigger. Tighten LHR fornt dolly out rigger	Completed	24/02/2016	41705	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		23/02/2016	41174	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		23/02/2016	41174	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres\TP13	Job Added From Invoice		16/02/2016	36930	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres\TP13	Job Added From Invoice		16/02/2016	0	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres\TP13	Job Added From Invoice		16/02/2016	0	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres\TP19	Job Added From Invoice		16/02/2016	36930	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres\TP19	Job Added From Invoice		16/02/2016	0	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		12/02/2016	38069	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		12/02/2016	38069	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
				repair RHR tail light wiring											
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist	completed	02/02/2016	35056	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		02/02/2016	35056	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Elect\TRL LIGHTS	repair RH tail light wiring and fit new LED light and rubber boot	completed	02/02/2016	35056	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres\TP11	Job Added From Invoice		20/01/2016	32320	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres\TP11	Job Added From Invoice		20/01/2016	32320	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist	completed	13/01/2016	32120	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job	completed	13/01/2016	32120	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
				fit new nylon striker to LHS lock											
T274	Myrtleford - Workshop	Body\MOUNTS	nylon striker on trailer slidelock colosed LHS	comeleted	13/01/2016	32120	Fault	Comeleted	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
			check rubber bands on trailer umbilicle - hanging to close to the ground												
T274	Myrtleford - Workshop	Hydraulics\HOSES	when trailer stretched out	completed	13/01/2016	32120	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres\TP21	Job Added From Invoice		12/01/2016	0	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres\TP21	Job Added From Invoice		30/12/2015	27417	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres\TP17	Job Added From Invoice		30/12/2015	65236	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Chassis\WINCH/STRP	fit new quick release cable to 3rd last winch	completed	29/12/2015	29717	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist	completed	19/12/2015	28537	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job	completed	19/12/2015	28537	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes\BOOSTER	change fromt dolly rear axle boosters to 2 x 24 boosters	completed	15/12/2015	27417	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes\BOOSTER	replace rear brake boosters on front dolly	completed	12/12/2015	27189	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
			2 boosters												
T274	Myrtleford - Workshop	Brakes\BOOSTER	tctc	completed	12/12/2015		Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
			fit new linings + hub + bearings to 2nd wheel on front dolley rhs												
			also check lhs wheel												
T274	Myrtleford - Workshop	Brakes\BRK RELINE	r	completed	11/12/2015	27084	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
			8 stud hub + parts												
T274	Myrtleford - Workshop	Brakes\BRK RELINE	tctc	completed	11/12/2015		Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres\TP19	Job Added From Invoice		01/12/2015	26074	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Hydraulics\RAM	tighten hyd fitting on ram + wash down	completed	26/11/2015	25328	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist	completed	25/11/2015	25328	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job	completed	25/11/2015	25328	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres\TP12	Job Added From Invoice		25/11/2015	22719	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
			1 tone link												
T274	Myrtleford - Workshop	Body\ELECT P&W	pacific scales	COMPLETED	17/11/2015		Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
			replace tonne link												
T274	Myrtleford - Workshop	Elect\ELECT P&W	replace 7 pin male + female plugs	completed	14/11/2015	26894	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Body\ELECT P&W	check all plug connections +clean and check switch to slide lock - could not fault	completed	12/11/2015	21558	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist	completed	12/11/2015	21905	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job	completed	12/11/2015	21905	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Chassis\MUDGUARDS	tighten lh mudguard	completed	11/11/2015	21205	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
				completed											
T274	Myrtleford - Workshop	Brakes\BRK RELINE	crack test + reline front axle on rear dolly	replace hub- reak dikkt fribt axke rgs+fit new bearings+1 wheel stud	23/10/2015	19184	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Elect\TRL LIGHTS	fit new male 7 pin plug+repair female plug wiring	completed	22/10/2015	18769	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist	completed	21/10/2015	18769	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job	completed	21/10/2015	18769	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist	completed	02/10/2015	16864	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job	completed	02/10/2015	16864	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres\TP15	Job Added From Invoice		30/09/2015	13293	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres\TP15	Job Added From Invoice		30/09/2015	13293	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres\TP15	Job Added From Invoice		30/09/2015	13293	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Body\DAMAGE	Job Added From Invoice		29/09/2015	0	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
			fit new bearing in lhr wheel on front dolley												
			check 2nd axle rh side trailer dolly												
T274	Myrtleford - Workshop	Susp\SUSPENSION	replaced rhr + lhr slack adjusters	completed	29/09/2015	14485	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Body\DAMAGE	Job Added From Invoice		24/09/2015	0	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Susp	replaced rhf air bag	completed	19/09/2015		Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Susp	replace 2nd rhs axle cable	completed	19/09/2015	14485	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist	completed	19/09/2015		Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job	completed	19/09/2015		Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Body	replace 1 winch strap	completed	16/09/2015	11573	Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Body	replace 2 winch straps	completed	15/09/2015		Fault	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Tyres\TP11	Job Added From Invoice		08/09/2015	0	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	Susp\SPRNG HANG	Job Added From Invoice		05/09/2015	0	Repair	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
			replace lh+rh mudguards												
T274	Myrtleford - Workshop	Susp	reolace lhr air bae	comeleted	05/09/2015	9528	Fault	Comeleted	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER
T274	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist	completed	05/09/2015	9528	Service	Completed	Greenfreight Logging Vic	KennedyFB	Myrtleford	MTK	PS9180	Myrtleford Workshop	TRAILER