| EquipmentName | Workshop | CodeAndSubCode | Description | Schedule | CompletionComments | DateDone | DistanceDone | Worktype | Workstate | EquipmentOwner | MaintenanceGroup | Location | Division | Rego | Supplier | EquipmentType |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| T174 | Myrtleford - Workshop | Chassis\HOUSEKEEP | adjusted wheel bearings | | | 18/03/2021 | 7442 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Chassis\BOLSTER | REPAIR BOLSTER CABLE | | shorton cable 1 link | 13/03/2021 | 7442 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres\TPS1 | FIT SPARE WHEEL | | | 13/03/2021 | 7442 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Body\MUDGUARDS | REPAIR MUD GUARD AND OUTRIGGER | | | 13/03/2021 | 7442 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Chassis\BREAKDOWN | REPAIROR REPLACE BENT PEGS | | | 13/03/2021 | 7442 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Chassis\BOLSTER | REPLACE REAR BOLSTER MOUNT BOLTS | | | 13/03/2021 | 7442 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Elect\INDICATORS | REPLACE LHF BOLSTER INDICATOR x2 | | Myrtleford Auto Electrics - Supply LED | 13/03/2021 | 7442 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Chassis\WINCH/STRP | FIT REAR WINCH CABLE | | | 13/03/2021 | 7442 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Susp\SHOCK ABS | REPLACE LHF SHOCK | | | 13/03/2021 | 7442 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes\SLACK ADJ | REPLACE LHF SLACK ADJUSTER | | | 13/03/2021 | 7442 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Susp\DAMAGE | REPLACE LHR & RHR SPRING EYE BUSHES | | TCTC | 13/03/2021 | 7442 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Susp\HOUSEKEEP | TIGHTEN ALL AXLE 'U' BOLTS | | replaced LHF axle u-bolts | 13/03/2021 | 7442 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Chassis\WINCH/STRP | REPLACE RHR LOG STRAP | | check all straps and replaced hooks | 13/03/2021 | 7442 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Chassis\HOUSEKEEP | VARIOUS CRACKS | | | 13/03/2021 | 7442 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes\EBS Kit | checked EBS | | | 13/03/2021 | 7442 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 11/03/2021 | 7439 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | wash trailer | 11/03/2021 | 7439 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 12/02/2021 | 5180 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | ACELOCH EARTHMOVING -3 | TRAILER |
| | | | D Service As Per Attached Checklist | | | | | | | | | | | | | |
| T174 | Myrtleford - Workshop | VehService\DS | L10790 | VehService\DS | | 12/02/2021 | 5180 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | ACELOCH EARTHMOVING -3 | TRAILER |
| T174 | Myrtleford - Workshop | Tyres\TP07 | fit run out | | | 10/02/2021 | 4422 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| | | | Annual Inspection As Per Checklist | | | | | | | | | | | | | |
| T174 | Myrtleford - Workshop | Insp\ANN INSP | Order Number L10730 | Insp\ANN INSP | | 04/02/2021 | | PreventativeMaintenance | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | ACELOCH EARTHMOVING -3 | TRAILER |
| T174 | Myrtleford - Workshop | Brakes\SLACK ADJ | replace worn slack adjuster - centre axle passenger side | | | 30/01/2021 | 3077 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | DrCabRep\WIPERS | prepare and weld crack at front pedastle passenger side | | | 30/01/2021 | 3077 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 29/01/2021 | 3077 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | ACELOCH EARTHMOVING -3 | TRAILER |
| | | | D Service As Per Attached Checklist | | | | | | | | | | | | | |
| T174 | Myrtleford - Workshop | VehService\DS | L10667 | VehService\DS | | 29/01/2021 | 3077 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | ACELOCH EARTHMOVING -3 | TRAILER |
| T174 | Myrtleford - Workshop | Susp\DAMAGE | replace damaged u-bolts | | | 23/01/2021 | 2177 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | ON TIME DIESEL REPAIRS P/L -3 | TRAILER |
| T174 | Myrtleford - Workshop | Susp\AIR BAG | remove raptured air spring and replace with 2nd hand unit to keep T174 in service | | | 15/01/2021 | 750 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Susp\AIR BAG | replace 2nd hand unit with new | | | 15/01/2021 | 750 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Body\MUDGUARDS | fit new 2 mudflaps to rear of trailer | | | 15/01/2021 | 750 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 13/01/2021 | 554794 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | ACELOCH EARTHMOVING -3 | TRAILER |
| | | | D Service As Per Attached Checklist | | | | | | | | | | | | | |
| T174 | Myrtleford - Workshop | VehService\DS | Order Number L10546 | VehService\DS | | 13/01/2021 | 554794 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | ACELOCH EARTHMOVING -3 | TRAILER |
| T174 | Myrtleford - Workshop | Body\WHL HUB | supply and fit new hubometer | | | 19/12/2020 | | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 09/12/2020 | | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | ACELOCH EARTHMOVING -3 | TRAILER |
| | | | D Service As Per Attached Checklist | | | | | | | | | | | | | |
| T174 | Myrtleford - Workshop | VehService\DS | #L 10334 | VehService\DS | | 09/12/2020 | | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | ACELOCH EARTHMOVING -3 | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 20/11/2020 | 368154 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | ACELOCH EARTHMOVING -3 | TRAILER |
| | | | D Service As Per Attached Checklist | | | | | | | | | | | | | |
| T174 | Myrtleford - Workshop | VehService\DS | Order Number L10187 | VehService\DS | | 20/11/2020 | 368154 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | ACELOCH EARTHMOVING -3 | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 06/11/2020 | 366446 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | ACELOCH EARTHMOVING -3 | TRAILER |
| | | | D Service As Per Attached Checklist | | | | | | | | | | | | | |
| T174 | Myrtleford - Workshop | VehService\DS | Order Number L10095 | VehService\DS | | 06/11/2020 | 366446 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | ACELOCH EARTHMOVING -3 | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 20/10/2020 | 363767 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | ACELOCH EARTHMOVING -3 | TRAILER |
| | | | D Service As Per Attached Checklist | | replace axle u-bolt | | | | | | | | | | | |
| T174 | Myrtleford - Workshop | VehService\DS | ORDER # L9960 | VehService\DS | centre axle left hand side | 20/10/2020 | 363767 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | ACELOCH EARTHMOVING -3 | TRAILER |
| T174 | Unknown - Unknown | Brakes | Record Check Results As Attached To This Job | | | 03/10/2020 | 361834 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | ACELOCH EARTHMOVING -3 | TRAILER |
| | | | D Service As Per Attached Checklist | | | | | | | | | | | | | |
| T174 | Unknown - Unknown | VehService\DS | Order Number L9841 | VehService\DS | | 03/10/2020 | 361834 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | ACELOCH EARTHMOVING -3 | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 18/09/2020 | 359356 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | ACELOCH EARTHMOVING -3 | TRAILER |
| | | | D Service As Per Attached Checklist | | | | | | | | | | | | | |
| T174 | Myrtleford - Workshop | VehService\DS | Order Number # L9712 | VehService\DS | | 18/09/2020 | 359356 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | ACELOCH EARTHMOVING -3 | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 03/09/2020 | 356999 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | ACELOCH EARTHMOVING -3 | TRAILER |
| | | | D Service As Per Attached Checklist | | | | | | | | | | | | | |
| T174 | Myrtleford - Workshop | VehService\DS | Order Number # L9576 | VehService\DS | | 03/09/2020 | 356999 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | ACELOCH EARTHMOVING -3 | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 18/08/2020 | 354565 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | ACELOCH EARTHMOVING -3 | TRAILER |
| | | | D Service As Per Attached Checklist | | | | | | | | | | | | | |
| T174 | Myrtleford - Workshop | VehService\DS | ORDER # L9383 | VehService\DS | | 18/08/2020 | 354565 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | ACELOCH EARTHMOVING -3 | TRAILER |
| T174 | Myrtleford - Workshop | Chassis\CHAS CRACK | Repair Chassis crack RHS front axle area | | | 08/08/2020 | 353677 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 31/07/2020 | | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | ACELOCH EARTHMOVING -3 | TRAILER |
| | | | D Service As Per Attached Checklist | | | | | | | | | | | | | |
| T174 | Myrtleford - Workshop | VehService\DS | Order Number # L9227 | VehService\DS | | 31/07/2020 | | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | ACELOCH EARTHMOVING -3 | TRAILER |
| T174 | Myrtleford - Workshop | Tyres\CASE STOCK | Job Added From Invoice | | | 09/07/2020 | 350257 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres\FITMENT | Job Added From Invoice | | | 09/07/2020 | 350257 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres\RETREAD | Job Added From Invoice | | | 09/07/2020 | 350257 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres\AH Callout | Job Added From Invoice | | | 09/07/2020 | 350257 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres\SCRAP TYRE | Job Added From Invoice | | | 09/07/2020 | 350257 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 01/07/2020 | 350305 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | ACELOCH EARTHMOVING -3 | TRAILER |
| | | | D Service As Per Attached Checklist | | | | | | | | | | | | | |
| T174 | Myrtleford - Workshop | VehService\DS | Order Number # L8996 | VehService\DS | | 01/07/2020 | 350305 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | ACELOCH EARTHMOVING -3 | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 20/06/2020 | 348323 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | ACELOCH EARTHMOVING -3 | TRAILER |
| | | | D Service As Per Attached Checklist | | | | | | | | | | | | | |
| T174 | Myrtleford - Workshop | VehService\DS | Order number # L8893 | VehService\DS | | 20/06/2020 | 348323 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | ACELOCH EARTHMOVING -3 | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 12/06/2020 | 346550 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | ACELOCH EARTHMOVING -3 | TRAILER |
| | | | D Service As Per Attached Checklist | | | | | | | | | | | | | |
| T174 | Myrtleford - Workshop | VehService\DS | Order Number # L8835 | VehService\DS | | 12/06/2020 | 346550 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | ACELOCH EARTHMOVING -3 | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 26/05/2020 | | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | ON TIME DIESEL REPAIRS P/L -3 | TRAILER |
| | | | D Service As Per Attached Checklist | | | | | | | | | | | | | |
| T174 | Myrtleford - Workshop | VehService\DS | ORDER # L8642 | VehService\DS | | 26/05/2020 | | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | ON TIME DIESEL REPAIRS P/L -3 | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 08/05/2020 | | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | ON TIME DIESEL REPAIRS P/L -3 | TRAILER |
| | | | D Service As Per Attached Checklist | | | | | | | | | | | | | |
| T174 | Myrtleford - Workshop | VehService\DS | ORDER # L8503 | VehService\DS | | 08/05/2020 | | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | ON TIME DIESEL REPAIRS P/L -3 | TRAILER |
| | | | air leak on trailer inspected and found air line to be broken and leaking | | | | | | | | | | | | | |
| T174 | Myrtleford - Workshop | Body\DAMAGE | cut line and fitted joiner | | | 23/04/2020 | | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 23/04/2020 | | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | ON TIME DIESEL REPAIRS P/L -3 | TRAILER |
| | | | D Service As Per Attached Checklist | | | | | | | | | | | | | |
| T174 | Myrtleford - Workshop | VehService\DS | ORDER # L8369 | VehService\DS | | 23/04/2020 | | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | ON TIME DIESEL REPAIRS P/L -3 | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 07/04/2020 | | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | ON TIME DIESEL REPAIRS P/L -3 | TRAILER |
| | | | D Service As Per Attached Checklist | | | | | | | | | | | | | |
| T174 | Myrtleford - Workshop | VehService\DS | ORDER # L8271 | VehService\DS | | 07/04/2020 | | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | ON TIME DIESEL REPAIRS P/L -3 | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 20/03/2020 | 334195 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | ON TIME DIESEL REPAIRS P/L -3 | TRAILER |
| | | | D Service As Per Attached Checklist | | | | | | | | | | | | | |
| T174 | Myrtleford - Workshop | VehService\DS | ORDER # L8125 | VehService\DS | | 20/03/2020 | 334195 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | ON TIME DIESEL REPAIRS P/L -3 | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 06/03/2020 | 332434 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | ON TIME DIESEL REPAIRS P/L -3 | TRAILER |
| | | | D Service As Per Attached Checklist | | | | | | | | | | | | | |
| T174 | Myrtleford - Workshop | VehService\DS | Order number # L8040 | VehService\DS | | 06/03/2020 | 332434 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | ON TIME DIESEL REPAIRS P/L -3 | TRAILER |
| T174 | Myrtleford - Workshop | Chassis\BOLSTER | move 2 bolster and alter bolster chain | | | 25/02/2020 | 330863 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 21/02/2020 | | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | ON TIME DIESEL REPAIRS P/L -3 | TRAILER |
| | | | D Service As Per Attached Checklist | | | | | | | | | | | | | |
| T174 | Myrtleford - Workshop | VehService\DS | Order Number # L7912 | VehService\DS | | 21/02/2020 | | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | ON TIME DIESEL REPAIRS P/L -3 | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 31/01/2020 | | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | MAHONYS TRANSPORT SERVICES -3 | TRAILER |
| | | | D Service As Per Attached Checklist | | | | | | | | | | | | | |
| T174 | Myrtleford - Workshop | VehService\DS | ORDER # L7773 | VehService\DS | | 31/01/2020 | | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | MAHONYS TRANSPORT SERVICES -3 | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 08/01/2020 | | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | MAHONYS TRANSPORT SERVICES -3 | TRAILER |
| | | | D Service As Per Attached Checklist | | | | | | | | | | | | | |
| T174 | Myrtleford - Workshop | VehService\DS | Order number # L 7577 | VehService\DS | | 08/01/2020 | | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | MAHONYS TRANSPORT SERVICES -3 | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 11/12/2019 | | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | MAHONYS TRANSPORT SERVICES -3 | TRAILER |
| | | | D Service As Per Attached Checklist | | D Service as per attached sheet | | | | | | | | | | | |
| T174 | Myrtleford - Workshop | VehService\DS | Order number # L7516 | VehService\DS | adjusted left hand front wheel bearing | 11/12/2019 | | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | MAHONYS TRANSPORT SERVICES -3 | TRAILER |
| T174 | Myrtleford - Workshop | Body\PAINT/REST | wash trailer | | | 20/11/2019 | 319895 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 20/11/2019 | 319895 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| | | | | | replaced 1x mudguard | | | | | | | | | | | |
| | | | | | replaced 2x mudflaps | | | | | | | | | | | |
| | | | | | replaced 2x indicators | | | | | | | | | | | |
| | | | | | weld chassis cracks | | | | | | | | | | | |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | replaced 2x winch straps | 20/11/2019 | 319895 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Susp\AIR BAG | Air Bag | | | 01/11/2019 | | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 26/10/2019 | 318021 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | replace RHM airbag | 26/10/2019 | 318021 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes\BRK RELINE | Crack test and reline all axles | | check brake and adjust | 12/10/2019 | 317127 | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 26/09/2019 | 315118 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |

| | | | | | | | | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | welded up cracks on trailer | 26/09/2019 | 315118 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 03/09/2019 | 312425 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 03/09/2019 | 312425 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Elect\INDICATORS | Replace front bolster indicator | | | 23/08/2019 | 312429 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 22/08/2019 | 310091 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | welded cracked pivot pin retainer | 22/08/2019 | 310091 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Elect\TRL LIGHTS | replace RHR inner LED light and repair wiring | | | 14/08/2019 | 307995 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Body\MUDGUARDS | fix broken guard RHS | | | 13/08/2019 | 307741 | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Susp\SUSPENSION | Tighten all suspension U bolts | | | 10/08/2019 | 415590 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 08/08/2019 | 307394 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | replace LHF spring pack | 08/08/2019 | 307394 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Body\MUDGUARDS | replace right front guard | | | 01/08/2019 | 305694 | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Body\MUDGUARDS | replace mudflap | | | 01/08/2019 | 305694 | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Body\HOSES | fit giggo rubber to cables and line at pivot and test | | | 31/07/2019 | 305318 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Body\MUDGUARDS | replace right hand front mudguard | | | 30/07/2019 | 29812 | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 24/07/2019 | 304175 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 24/07/2019 | 304175 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Body\FIFTH WHEE | unhook T156 and hook up to T124 and test | | | 10/07/2019 | 301460 | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Chassis\BOLSTER | adjust bolster cable | | | 10/07/2019 | 301460 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 09/07/2019 | 301460 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| | | | | | fit bearings to cable booster pulley | | | | | | | | | | | |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | tighten brake hose clamps | 09/07/2019 | 301460 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 28/06/2019 | 301459 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 28/06/2019 | 301459 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Body\FIFTH WHEE | replaced turntable pins | | | 28/06/2019 | 301459 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Body\HOUSEKEEP | check over trailer | | | 21/06/2019 | 297857 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes\BRAKE ADJ | grease and adjust brakes | | | 21/06/2019 | 297857 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Elect\TRL LIGHTS | check lights | | | 21/06/2019 | 297857 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Body\FIFTH WHEE | supply T/table pivot pins x2 | | | 21/06/2019 | 297857 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Body\DAMAGE | repair damaged hyd hose, air line and wiring | | | 15/06/2019 | 297118 | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 01/06/2019 | 295955 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 01/06/2019 | 295955 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes\BRK O/HAUL | checked RHF brakes - readjusted and fixed bent backing plate | | | 26/05/2019 | 294467 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Insp\ANN INSP | Annual Inspection As Per Checklist | Insp\ANN INSP | straighten RH middle backing pit | 22/05/2019 | 293784 | PreventativeMaintenance | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Body\HOUSEKEEP | wash trailer | | | 16/05/2019 | 293701 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Susp\AIR BAG | replace RHF airbag | | | 16/05/2019 | 293701 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes\BACK PLATE | backing plate | | | 16/05/2019 | 293701 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| | | | crack test and reline all wheels | | | | | | | | | | | | | |
| | | | fit inner & outer w/brgs to LH front | | | | | | | | | | | | | |
| T174 | Myrtleford - Workshop | Brakes\BRK RELINE | REPAIR BOLSTER CRACKS | | | 16/05/2019 | 293782 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 10/05/2019 | | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | MAUDE DIESEL SERVICE - 3 | TRAILER |
| | | | D Service As Per Attached Checklist | | | | | | | | | | | | | |
| T174 | Myrtleford - Workshop | VehService\DS | Order #L6130 | VehService\DS | | 10/05/2019 | | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | MAUDE DIESEL SERVICE - 3 | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 02/05/2019 | | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | MAUDE DIESEL SERVICE - 3 | TRAILER |
| | | | D Service As Per Attached Checklist | | | | | | | | | | | | | |
| T174 | Myrtleford - Workshop | VehService\DS | Order # L6060 | VehService\DS | | 02/05/2019 | | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | MAUDE DIESEL SERVICE - 3 | TRAILER |
| T174 | Myrtleford - Workshop | Body\MUDGUARDS | replaced p/s mudguards x2 | | | 12/04/2019 | 286625 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Elect\TRL LIGHTS | replaced wiring to left hand outer brake light and replaced and light gram its light rubbers | | | 12/04/2019 | 286625 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 12/04/2019 | 286675 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | MAUDE DIESEL SERVICE - 3 | TRAILER |
| | | | | | replaced p/s mudguards x2 | | | | | | | | | | | |
| | | | D Service As Per Attached Checklist | | replaced wirng too left hand outer brakelights | | | | | | | | | | | |
| T174 | Myrtleford - Workshop | VehService\DS | Order # L5964 | VehService\DS | replaced 6 light/light rubber | 12/04/2019 | 286675 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | MAUDE DIESEL SERVICE - 3 | TRAILER |
| | | | D Service As Per Attached Checklist | | | | | | | | | | | | | |
| | | | | | fitted rev lights | | | | | | | | | | | |
| T174 | Myrtleford - Workshop | VehService\DS | ORDER # L5932 | VehService\DS | carried out D Service | 04/04/2019 | 284598 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | MAUDE DIESEL SERVICE - 3 | TRAILER |
| | | | | | driver needs to brake a bit easier | | | | | | | | | | | |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | brakes where way out of adjustment | 04/04/2019 | 284598 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | MAUDE DIESEL SERVICE - 3 | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 23/03/2019 | 281685 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | MAUDE DIESEL SERVICE - 3 | TRAILER |
| | | | D Service As Per Attached Checklist | | | | | | | | | | | | | |
| T174 | Myrtleford - Workshop | VehService\DS | ORDER # L5836 | VehService\DS | | 23/03/2019 | 281685 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | MAUDE DIESEL SERVICE - 3 | TRAILER |
| T174 | Myrtleford - Workshop | Brakes\BRK RELINE | Replace 3 x Brake shoes | | | 16/03/2019 | 278839 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 08/03/2019 | 278839 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | MAUDE DIESEL SERVICE - 3 | TRAILER |
| | | | D Service As Per Attached Checklist | | | | | | | | | | | | | |
| T174 | Myrtleford - Workshop | VehService\DS | ORDER # L5759 | VehService\DS | | 08/03/2019 | 278839 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | MAUDE DIESEL SERVICE - 3 | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 26/02/2019 | 276036 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | MAUDE DIESEL SERVICE - 3 | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 26/02/2019 | 276036 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | MAUDE DIESEL SERVICE - 3 | TRAILER |
| T174 | Myrtleford - Workshop | Chassis\WINCH/STRP | fit new winch strap 2nd winch | | | 17/02/2019 | | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 13/02/2019 | 273410 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 13/02/2019 | 273410 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes\BRK O/HAUL | check and adjust/bearing at end RHF (L5530) | | | 05/02/2019 | 269775 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes\BRK RELINE | check other w/bearing and reline brakes on f/axle and RHM | | | 05/02/2019 | 269775 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 01/02/2019 | | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| | | | D Service As Per Attached Check | | | | | | | | | | | | | |
| | | | reline rhf wheel & check bearings | | | | | | | | | | | | | |
| T174 | Myrtleford - Workshop | VehService\DS | trl ser & check | VehService\DS | | 01/02/2019 | | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 10/01/2019 | | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 10/01/2019 | | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Chassis\BOLSTER | Front RH Bolster Pin Needs Reversing | | Leon check this job its been done by Maude Diesel | 19/12/2018 | 273410 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | MAUDE DIESEL SERVICE - 3 | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 15/12/2018 | | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | MAUDE DIESEL SERVICE - 3 | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 15/12/2018 | | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | MAUDE DIESEL SERVICE - 3 | TRAILER |
| T174 | Myrtleford - Workshop | Brakes\EBS Kit | Secured Air Control Box On Trailer For EBS | | | 12/12/2018 | 29812 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | MAUDE DIESEL SERVICE - 3 | TRAILER |
| T174 | Myrtleford - Workshop | Tyres\Punct | Job Added From Invoice | | | 11/12/2018 | 263206 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 05/12/2018 | | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| | | | | | completed | | | | | | | | | | | |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | adjusted brakes | 05/12/2018 | | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Chassis\WINCH/STRP | replace rear bay middle winch and strap | | | 02/12/2018 | 261177 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Chassis\WINCH/STRP | replace rear winch strap | | | 02/12/2018 | 261177 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres\CASE STOCK | Job Added From Invoice | | | 27/11/2018 | 258319 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres\FITMENT | Job Added From Invoice | | | 27/11/2018 | 258319 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres\RETREAD | Job Added From Invoice | | | 27/11/2018 | 258319 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Body\HOUSEKEEP | wash trailer & supply spare log strap | | | 24/11/2018 | | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Susp\HCV | Fit Ride Height Value To Rear Axle | | test fold, fit hold down chains | 20/11/2018 | 258320 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Susp\HCV | make bracket for rear axle ride height valve and set up | | | 16/11/2018 | 258319 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Chassis\BOLSTER | Repair LHR Bolster Peg | | | 03/11/2018 | 2583200 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Chassis\HOUSEKEEP | Repair Trailer Cracks | | | 03/11/2018 | 2583200 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Chassis\MUDGUARDS | Fit Folding Mud Flaps(L5343) | | | 03/11/2018 | 2583200 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Body\HOUSEKEEP | Mount Trailer Onto 848 | | check lights | 03/11/2018 | 2583200 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Rosewood - Workshop | Body\MUDGUARDS | right hand side mudguard need retighten | | guard missing 3 bottom bolts replace with new bolts and re-drill holes | 23/10/2018 | | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Rosewood Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 17/10/2018 | 255728 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | repair clearance light wiring | 17/10/2018 | 255728 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Body\AIR LEAK | check for air leak LHS middle axle. check for air lewak LHS middle axle | | | 13/10/2018 | 254573 | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Body\MUDGUARDS | mudguards RHS loose | | | 13/10/2018 | 254573 | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Elect\TRL LIGHTS | Rewire rear bolster | | | 28/09/2018 | 255728 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 27/09/2018 | 250491 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 27/09/2018 | 250491 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres | Job Added From Invoice | | | 23/09/2018 | 248700 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres\RETREAD | Job Added From Invoice | | | 20/09/2018 | 247420 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres\FITMENT | Job Added From Invoice | | | 20/09/2018 | 247420 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Rosewood - Workshop | Body\MUDGUARDS | repair to front right hand side mudguard | | repair guard | 12/09/2018 | 246258 | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Rosewood Workshop | TRAILER |
| | | | | | repaired side marker lights | | | | | | | | | | | |
| | | | | | repaired blinker wiring | | | | | | | | | | | |
| | | | | | repaired number plate wiring | | | | | | | | | | | |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | replaced leaking LHF booster | 07/09/2018 | 24529 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 07/09/2018 | 24529 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres\FITMENT | Job Added From Invoice | | | 06/09/2018 | 24397 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Rosewood - Workshop | Body\MUDGUARDS | R.H.F Mud guard | | Tighten loose guard | 05/09/2018 | 244278 | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Rosewood Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Body\MUDGUARDS | RHS fron t trailer mudguard loose | | | 01/09/2018 | 243967 | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres | Job Added From Invoice | | | 30/08/2018 | 241440 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Body\MUDGUARDS | Replace LHF & RHR mudguards | | | 25/08/2018 | 242227 | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| | | | check RHR - mudguards | | | | | | | | | | | | | |
| T174 | Myrtleford - Workshop | Body\MUDGUARDS | grub screws loose | | | 24/08/2018 | 241793 | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Chassis\CHAS CRACK | Repair RHS hanger & chassis cracks | | also weld other cracks | 21/08/2018 | 245615 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 18/08/2018 | 240438 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |

| | | | | | | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist<br>quick fix rear right guard<br>front rear washer and nut loose | VehService\DS | guards were loose put new bolts in guard and re-tighten | 18/08/2018 | 240438 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Rosewood - Workshop | Body\MUDGUARDS | guard is not bolted | | tested ok | 14/08/2018 | | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Rosewood Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Body\MUDGUARDS | Replace RHR mudguard | | | 14/08/2018 | 242227 | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Chassis\BOLSTER | move rear bolster to 2.9m spacing | | | 11/08/2018 | 239048 | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 31/07/2018 | 235291 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 31/07/2018 | 235291 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Chassis\BOLSTER | rear right peg bent | | | 20/07/2018 | 232543 | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Susp\HCV | right rear guard (rubbing) | | | 19/07/2018 | 231930 | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Susp\AIR BAG | replace RHR air bag | | | 15/07/2018 | 231227 | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Body\MUDGUARDS | replace 3 mudguards | | | 15/07/2018 | 231227 | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres | Job Added From Invoice | | | 12/07/2018 | 0 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres\FITMENT | Job Added From Invoice | | | 12/07/2018 | 0 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres\RETREAD | Job Added From Invoice | | | 12/07/2018 | 0 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 11/07/2018 | 2310410 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 11/07/2018 | 2310410 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Body\FIFTH WHEE | hook up to T174 and test | | | 03/07/2018 | 227955 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Body\MUDGUARDS | straighten mudguard | | | 27/06/2018 | 226010 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes\AIR LEAK | brakes stuck on at CHH yard | | | 27/06/2018 | 226010 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Body\HOUSEKEEP | hook up T174 and test | | | 20/06/2018 | | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes\BRK O/HAUL | brakes not dumping when red button is out | | | 20/06/2018 | | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 13/06/2018 | 225488 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 13/06/2018 | 225488 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes\BRK O/HAUL | check over all brake % for next reline | | | 05/06/2018 | 224398 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 23/05/2018 | 2200869 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | replace RHR bolster light | 23/05/2018 | 2200869 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres | Job Added From Invoice | | | 15/05/2018 | 0 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres\FITMENT | Job Added From Invoice | | | 15/05/2018 | 0 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres\RETREAD | Job Added From Invoice | | | 15/05/2018 | 0 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes\BRK RELINE | Crack test & reline all wheels | | | 08/05/2018 | 225489 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Elect\LLECT P&W | check and repair lights | | | 08/05/2018 | 225489 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Body\MUDGUARDS | check and repair mudflaps | | | 08/05/2018 | 225489 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Chassis\WINCH/STRP | check and repair straps on winches | | | 08/05/2018 | 225489 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 05/05/2018 | 215620 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 05/05/2018 | 215620 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Chassis\BOLSTER | Repair 3rd Bolster Cracked RHS Gusset Upright | | | 28/04/2018 | 223319 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Chassis\HOUSEKEEP | Repair Cracked RHS Pin Retainer | | | 28/04/2018 | 223319 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Chassis\HOUSEKEEP | Repair Crack Above RHS Pivot | | | 28/04/2018 | 223319 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 27/04/2018 | 212846 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 27/04/2018 | 212846 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Body\WHL HUB | replace LHR hub and drum and wheel bearings | | | 24/04/2018 | 211452 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Body\WHL HUB | check and adjust all other wheel bearings | | | 24/04/2018 | 211452 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 20/04/2018 | 211452 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | replace log strap | 20/04/2018 | 211452 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 29/03/2018 | 206504 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 29/03/2018 | 206504 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes\BRAKE ADJ | brake adjust | | | 27/03/2018 | 205169 | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres\RUN OUT | Job Added From Invoice | | | 27/03/2018 | 204967 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres\RUN OUT | Job Added From Invoice | | | 24/03/2018 | 202438 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Chassis\WINCH/STRP | replace cable on quick release | | | 21/03/2018 | 203580 | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres | Job Added From Invoice | | | 14/03/2018 | 0 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres\FITMENT | Job Added From Invoice | | | 14/03/2018 | 0 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Elect\TRL LIGHTS | repair RHR bolster light | | | 10/03/2018 | | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Body\MUDGUARDS | weld rear mudguards | | | 10/03/2018 | | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Body\RWC COMP | fit new LH zebra sign | | | 10/03/2018 | | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Chassis\WINCH/STRP | fit new RHR bolster peg, bolt and nut | | | 10/03/2018 | | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 10/03/2018 | 201288 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 10/03/2018 | 201288 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres | Job Added From Invoice | | | 01/03/2018 | 0 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres\FITMENT | Job Added From Invoice | | | 01/03/2018 | 0 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres\RETREAD | Job Added From Invoice | | | 01/03/2018 | 0 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres | Job Added From Invoice | | | 21/02/2018 | 0 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres\FITMENT | Job Added From Invoice | | | 21/02/2018 | 0 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 20/02/2018 | 196970 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 20/02/2018 | 196970 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes\BRK RELINE | Crack test & reline all wheels | | pick up trailer at Rouse | 07/02/2018 | 196784 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Susp\SPRNG HANG | Repair LHR spring hanger crack | | | 07/02/2018 | 196784 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 06/02/2018 | 191605 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 06/02/2018 | 191605 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Chassis\CHAS CRACK | Repair chassis crack - UHF hanger | | | 23/01/2018 | 196784 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Chassis\BOLSTER | Bent peg - straightened | | | 20/01/2018 | | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 20/01/2018 | 186648 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 20/01/2018 | 186648 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres\RUN OUT | Job Added From Invoice | | | 19/01/2018 | 183931 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres\TP18 | change flat tyre | | | 09/01/2018 | | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 03/01/2018 | 180778 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | Weld cracks on pivot retainer and on bolsters<br>Make bracket for clearance light, weld on and replace light and repair wiring | 03/01/2018 | 180778 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres | Job Added From Invoice | | | 30/12/2017 | 180250 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes\BRAKE ADJ | brakes need adjusting | | | 28/12/2017 | 180245 | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres\TP14 | RHF tyre puncture fit red spare<br>mudguard missing | | | 27/12/2017 | 179807 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Body\MUDGUARDS | fit new mudguard to RHR | | | 22/12/2017 | 179354 | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Body\FIFTH WHEE | hook up trailer to FI944 | | | 15/12/2017 | 117563 | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Chassis\BOLSTER | pin needs replacing on third bolster | | | 15/12/2017 | 117563 | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Elect\TRL LIGHTS | rewire 7 pin plug | | | 15/12/2017 | 117563 | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Elect\TRL LIGHTS | repair 3rd bolster lights<br>check brakes for hanging on | | | 15/12/2017 | 117563 | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes\BRK O/HAUL | check slack adjuster | | | 07/12/2017 | | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes\BRAKE ADJ | brake adjustment | | | 07/12/2017 | | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 30/11/2017 | 173395 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | Replace RH inner LED tail light and rubber boot<br>Repair H outer wiring brake light | 30/11/2017 | 173395 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Elect\TRL LIGHTS | repair tail light wiring and change trailer plug | | | 28/11/2017 | 172709 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Chassis\FIFTH WHEE | hook up trailer to FL 837 | | | 28/11/2017 | 172709 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes\BRK RELINE | Crack test & reline all wheels | | | 28/11/2017 | 172709 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres | Job Added From Invoice | | | 28/11/2017 | 0 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres\FITMENT | Job Added From Invoice | | | 28/11/2017 | 0 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres\RETREAD | Job Added From Invoice | | | 28/11/2017 | 0 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Chassis\WINCH/STRP | cable on front winch broken | | | 24/11/2017 | 172708 | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres\FITMENT | Job Added From Invoice | | | 23/11/2017 | 170107 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres\RETREAD | Job Added From Invoice | | | 23/11/2017 | 170107 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres\RUN OUT | Job Added From Invoice | | | 15/11/2017 | 168438 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Insp\ANN INSP | Annual Inspection As Per Checklist | Insp\ANN INSP | weld pivot pin retainer | 11/11/2017 | 169058 | PreventativeMaintenance | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 11/11/2017 | 169053 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 11/11/2017 | 169053 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Chassis\WINCH/STRP | Repair front winch mount | | repair t/table locks | 21/10/2017 | 163534 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Chassis\HOUSEKEEP | Repair LH hinge pin retainer crack | | | 21/10/2017 | 163534 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Susp\AIR BAG | Replace LHM airbag | | | 21/10/2017 | 163534 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 20/10/2017 | 163533 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 20/10/2017 | 163533 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes\BRAKE ADJ | adjust brakes | | | 07/10/2017 | 161692 | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes\SLACK ADJ | fit slack adjuster to RH front | | | 07/10/2017 | 161692 | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres\PRES CHECK | Job Added From Invoice | | | 07/10/2017 | 0 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 27/09/2017 | 158926 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 27/09/2017 | 158926 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Insp\JNT INSP | fit srt stickers to pegs | | | 24/09/2017 | 158134 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Chassis\CHAS CRACK | Repair crack in chassis above LHR airbag | | remove rear cover plate clean, repair number plate light wiring | 20/09/2017 | 156560 | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Body\HOUSEKEEP | Replace scale slave cover | | | 20/09/2017 | 156560 | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Chassis\WINCH/STRP | repair quick release cables | | | 19/09/2017 | 156351 | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Body\WHL HUB | hub cap missing LHM axle | | | 19/09/2017 | 156351 | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 09/09/2017 | 153796 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |

| | | | | | | | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | repair number plate light wiring | 09/09/2017 | 153796 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 29/08/2017 | 149392 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 29/08/2017 | 149392 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Body\MUDGUARDS | R/H mudflap on trailer not there | | r/hand mudflap missing | 22/08/2017 | 147282 | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Body\MUDGUARDS | L/Hand rear m/guard bracket u/s | | l/hand rear mudguard bracket u/s | 22/08/2017 | 147282 | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Body\CONSUMABLE | L/Hand rear bolster bolt missing | | | 22/08/2017 | 147282 | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres\PRES CHECK | Job Added From Invoice | | | 22/08/2017 | 0 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 15/08/2017 | 144996 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 15/08/2017 | 144996 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Chassis\WINCH/STRP | handle on wrench broken | | | 12/08/2017 | 144101 | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Chassis\FIFTH WHEE | hook up T174 | | | 11/08/2017 | | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Susp\HOUSEKEEP | broken axle strap RHS | | | 05/08/2017 | 675842 | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 03/08/2017 | 141091 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 03/08/2017 | 141091 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 21/07/2017 | 135610 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 21/07/2017 | 135610 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Body\HOUSEKEEP | tension wheels | | | 18/07/2017 | 134678 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Elect\ELECT P&W | check scales | | | 18/07/2017 | 134678 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes\EBS Kit | Test & Program EBS | | | 12/07/2017 | 134679 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes\EBS Kit | Check & Engineer trailer | | | 12/07/2017 | 134679 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes\BRK O/HAUL | replace rear axle RH & LH wheel bearings | | | 05/07/2017 | 178095 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 27/06/2017 | 131334 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 27/06/2017 | 131334 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres\PRES CHECK | Job Added From Invoice | | | 21/06/2017 | 0 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 16/06/2017 | 125156 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 16/06/2017 | 125156 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes\EBS Kit | FIT EBS KIT TO FRONT & REAR AXLES | | | 15/06/2017 | | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes\BRK RELINE | Check & adjust trailer brakes | | Complete | 05/06/2017 | 120734 | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 02/06/2017 | 119679 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 02/06/2017 | 119679 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Chassis\WINCH/STRP | Re-attach No. 1 load binder release hook cable on LHS. Re-attach No. 1 load binder realease hook cable on LHS | | Complete | 01/06/2017 | 119679 | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Elect\HOUSEKEEP | scale/slave box has broken bolts | | | 30/05/2017 | 118200 | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres\FITMENT | Job Added From Invoice | | | 20/05/2017 | 0 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres | Job Added From Invoice | | | 20/05/2017 | 0 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres\RETREAD | Job Added From Invoice | | | 20/05/2017 | 0 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| | | | | | remove rear bolster pegs | | | | | | | | | | | |
| | | | | | repair L/hand bolster peg in hyd press (r-tech) | | | | | | | | | | | |
| T174 | Myrtleford - Workshop | Chassis\BOLSTER | turn LHR & RHR pegs | | rotate bent r/hand peg - check for cracks | 19/05/2017 | 114813 | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 19/05/2017 | 114813 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 19/05/2017 | 114813 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Body\MUDGUARDS | Replace LHR muuard | | fit winch knob to front winch | 03/05/2017 | 110384 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Chassis\SPAREWHEEL | Fit spare wheel carrier | | | 03/05/2017 | 110384 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Body\MUDGUARDS | L/hand rear outrigger loose | | | 02/05/2017 | 110382 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 02/05/2017 | 110382 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| | | | | | hook up trailer to s-line | | | | | | | | | | | |
| | | | | | fit turntable locking pins | | | | | | | | | | | |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | repair light wiring | 02/05/2017 | 110382 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres\TP14 | Job Added From Invoice | | | 22/03/2017 | 110283 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes\BRAKE ADJ | adjust brakes | | | 21/03/2017 | 110324 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres\TP11 | Job Added From Invoice | | | 21/03/2017 | 110283 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres\TP13 | Job Added From Invoice | | | 21/03/2017 | 110283 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Chassis\HOUSEKEEP | replace front & rear hyd ram mounts on trailer | | | 07/02/2017 | 110282 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Hydraulics\RAM | repair front & rear ram eyes | | | 07/02/2017 | 110282 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Hydraulics\VALVES | reset hyd ram cross over relief valves | | | 07/02/2017 | 110282 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Hydraulics\RAM | fit hydraulic rams | | | 07/02/2017 | 110282 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Chassis\BOLSTER | repair LHR bolster peg and socket | | | 07/02/2017 | 110282 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Chassis\HOUSEKEEP | hook up to A Trailer | | | 07/02/2017 | 110282 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Hydraulics\RAM | Remove rams for repair | | | 07/02/2017 | 110282 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Body\HOUSEKEEP | wash trailer 174 and check over | | | 21/01/2017 | 110282 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Susp\AIR BAG | fit new airbag LHF axle | | | 21/01/2017 | 110282 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 13/01/2017 | 108401 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 13/01/2017 | 108401 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Body\HOUSEKEEP | check over | | | 07/01/2017 | 106922 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Chassis\HOUSEKEEP | repair crack in RHS pivot point | | | 07/01/2017 | 106922 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 21/12/2016 | 106922 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 21/12/2016 | 106922 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| | | | | | weld s-cam tube | | | | | | | | | | | |
| | | | | | fit reverse light | | | | | | | | | | | |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | repair wiring for 2nd bolster light | 10/12/2016 | 104726 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 10/12/2016 | 104726 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes\BRK RELINE | Crack test & reline all wheels | | | 08/12/2016 | 104726 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres\TP15 | Job Added From Invoice | | | 01/12/2016 | 102080 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 29/11/2016 | 103169 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Chassis\HOUSEKEEP | Repair cracks in RH Hinge & Ram area | | | 19/11/2016 | 104726 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 18/11/2016 | 100988 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 18/11/2016 | 100988 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Insp\ANN INSP | Annual Inspection As Per Checklist | Insp\ANN INSP | | 12/11/2016 | 93667 | PreventativeMaintenance | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Susp\SUSPENSION | Replace LHM spring eye bush | | | 09/11/2016 | 98667 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 08/11/2016 | 98543 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 08/11/2016 | 98543 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Chassis\WINCH/STRP | fit new handle on winch | | | 08/11/2016 | 98543 | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 27/10/2016 | 96340 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 27/10/2016 | 96340 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 15/10/2016 | 93927 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | repaired RHM mudguard | 15/10/2016 | 93927 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 06/10/2016 | 91320 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 06/10/2016 | 91320 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres\TP19 | Job Added From Invoice | | | 30/09/2016 | 89198 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres\TP11 | Job Added From Invoice | | | 24/09/2016 | 89197 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres\TP12 | Job Added From Invoice | | | 24/09/2016 | 89197 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 21/09/2016 | 89197 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 21/09/2016 | 89197 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes\AIR LEAK | value leaking with hand piece applied | | | 17/09/2016 | 88298 | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes\AIR LEAK | air leak over tri (with black button in) | | | 17/09/2016 | 88298 | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 09/09/2016 | 86261 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 09/09/2016 | 86261 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Elect\TRL LIGHTS | no indicators | | | 03/09/2016 | 84719 | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 30/08/2016 | 82895 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 30/08/2016 | 82895 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes\BRK RELINE | fit 40% runout to LHM axle | | | 24/08/2016 | 82230 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes\BRAKE ADJ | adjust brakes | | | 24/08/2016 | 82230 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Susp\SPRNG HANG | Repair RHM spring eye boss crack | | | 19/08/2016 | 82230 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 18/08/2016 | 81489 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 18/08/2016 | 81489 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | DrCabElect\AXLES | axle strap broken | | | 11/08/2016 | 79793 | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 06/08/2016 | 78666 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 06/08/2016 | 78666 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 29/07/2016 | 76266 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 29/07/2016 | 76266 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres\TP15 | Job Added From Invoice | | | 28/07/2016 | 75107 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres\TP14 | Job Added From Invoice | | | 26/07/2016 | 63721 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres\TP20 | Job Added From Invoice | | | 26/07/2016 | 63913 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Chassis\HOUSEKEEP | check over trailers | | | 15/07/2016 | 75100 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Chassis\CROSS MBR | repair crack in chassis | | | 15/07/2016 | 75100 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Body\STCH GUARD | replace the stretch guard | | | 07/07/2016 | 75106 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Susp\AIR LEAK | repair airbag airline LHM axle | | | 07/07/2016 | 75106 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Chassis\WINCH/STRP | fit new load straps | | | 05/07/2016 | 75105 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Chassis\WINCH/STRP | tighten all winch bracket bolts | | | 05/07/2016 | 75105 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres\DAMAGE | pump up all tyres | | | 05/07/2016 | 75105 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 05/07/2016 | 75105 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 05/07/2016 | 75105 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Body\DAMAGE | tow trailerl to shepparton motor panels & repair minor rollover damage & supply parts | | | 01/07/2016 | | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 27/05/2016 | 73694 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 27/05/2016 | 73694 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |

| | | | | | | | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| T174 | Myrtleford - Workshop | Body\HOUSEKEEP | check over eg. Tighten loose bolster pegs/tighten brake hose clamps/ replace RHF mudguards | | | 20/05/2016 | 72228 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 13/05/2016 | 71398 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 13/05/2016 | 71398 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Chassis\BOLSTER | replace peg at LHR | | | 07/05/2016 | 70019 | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | DrCabElect\MUDGUARDS | replace RHF mudflap | | | 07/05/2016 | 70019 | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 04/05/2016 | 69058 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 04/05/2016 | 69058 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres\TP14 | Job Added From Invoice | | | 03/05/2016 | 65732 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres\TP13 | Job Added From Invoice | | | 29/04/2016 | 65919 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres\TP13 | Job Added From Invoice | | | 29/04/2016 | 0 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres\TP13 | Job Added From Invoice | | | 29/04/2016 | 0 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes\BRAKE ADJ | brake adjust | | | 22/04/2016 | 67126 | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 20/04/2016 | 66521 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 20/04/2016 | 66521 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Chassis\BOLSTER | repair bolster peg | | | 16/04/2016 | 65919 | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 05/04/2016 | 64148 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 05/04/2016 | 64148 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 25/03/2016 | 62934 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 25/03/2016 | 62934 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres\TP19 | Job Added From Invoice | | | 18/03/2016 | 61282 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Chassis\CROSS MBR | repair trailer hinge cracks | | replace LH & RH hinge pins x4 and fit 2x new pins<br>fit 4x new U bolts<br>fit 2x new shockers and bolts | 11/03/2016 | 61921 | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Chassis\AXLES | Fit new york axle assembly from hub to hub & u bolts & shocker bolts | | 2x new w/align plates | 09/03/2016 | 61921 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres\TP15 | Job Added From Invoice | | | 01/03/2016 | 59885 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres\TP15 | Job Added From Invoice | | | 01/03/2016 | 0 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres\TP15 | Job Added From Invoice | | | 01/03/2016 | 0 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 24/02/2016 | 59885 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 24/02/2016 | 59885 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Chassis\BOLSTER | Shorten bolster cable | | Completed | 23/02/2016 | 59660 | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Chassis\BOLSTER | MAKE UP NEW BOLSTER CABLE & REPLACE | | | 10/02/2016 | 57392 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 10/02/2016 | 57392 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 10/02/2016 | 57392 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Body\MOUNTS | repair LHR bottom shocker mount | | | 28/01/2016 | 54886 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Susp\SPRNG HANG | repair LHR axle saddle crack | | | 28/01/2016 | 54886 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 28/01/2016 | 54886 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | | 28/01/2016 | 54886 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Chassis\BOLSTER | move rear bolster back | | completed | 18/01/2016 | 52918 | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Hydraulics\HOSES | repair oil line | | completed | 18/01/2016 | 52918 | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Body\MUDGUARDS | refit RHM mudguard | | completed | 18/01/2016 | 52918 | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | completed | 12/01/2016 | 52115 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | completed | 12/01/2016 | 52115 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Chassis\HOUSEKEEP | check over<br>repair axle saddle crack | | completed | 29/12/2015 | 50403 | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Susp\AXLES | rinlatech | | completed | 24/12/2015 | | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Chassis\AXLE CT | repair lhr axle saddle crack | | completed | 17/12/2015 | 50403 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | completed | 15/12/2015 | 49357 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist<br>parts | VehService\DS | completed | 15/12/2015 | 49357 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Elect\ELECT P&W | mae | | completed | 02/12/2015 | | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | completed | 01/12/2015 | 46468 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | completed | 01/12/2015 | 46468 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | DrCabElect\ELECT P&W | repair scales | | completed | 26/11/2015 | 45539 | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres\TP17 | Job Added From Invoice | | | 25/11/2015 | 43992 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres\TP17 | Job Added From Invoice | | | 25/11/2015 | 43992 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres\TP17 | Job Added From Invoice | | | 25/11/2015 | 43992 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres\TP11 | Job Added From Invoice<br>brakes + 3 axles | | | 25/11/2015 | 43992 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes\BRK RELINE | tctc | | completed | 14/11/2015 | | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes\BRK RELINE | crack test + reline all wheels | | completed | 12/11/2015 | 43992 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Insp\ANN INSP | Annual Inspection As Per Checklist<br>repair cracks | Insp\ANN INSP | completed | 12/11/2015 | 43992 | PreventativeMaintenance | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Chassis\CROSS MBR | rinl | | completed | 06/11/2015 | | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Chassis\MUDGUARDS | remount rhs rear guard | | completed | 29/10/2015 | 43125 | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Elect\TRL LIGHTS | rewire B trailer wiring underneath turntable+rear plug+folding area | | completed | 29/10/2015 | 43992 | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Chassis\BOLSTER | move rear bolster back to old spot | | completed | 29/10/2015 | 43992 | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | completed | 28/10/2015 | 43125 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | completed<br>completed | 28/10/2015 | 43125 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Susp\SUSPENSION | repair rear axle saddle crack on lhs at u-bolt | | (new axle on order) | 14/10/2015 | 40760 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | completed | 13/10/2015 | 40293 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | completed | 13/10/2015 | 40293 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Chassis\HYDRAULICS | supply hose + parts | | completed | 10/10/2015 | | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres\TP19 | Job Added From Invoice | | | 30/09/2015 | 35740 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres\TP19 | Job Added From Invoice | | | 30/09/2015 | 35740 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Tyres\TP19 | Job Added From Invoice | | | 30/09/2015 | 35740 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | completed | 30/09/2015 | 37991 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | completed | 30/09/2015 | 37991 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | completed | 19/09/2015 | 35740 | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | completed | 19/09/2015 | 35740 | Repair | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Elect | calibrate tare on scales | | repaired | 04/09/2015 | | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | Body | fit new mud guard | | repaired | 04/09/2015 | | Fault | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |
| T174 | Myrtleford - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | completed | 02/09/2015 | | Service | Completed | Greenfreight Logging Vic | Kennedy | Myrtleford | MTK | 29812S | Myrtleford Workshop | TRAILER |