EquipmentName	Workshop	CodeAndSubCode	Description	Schedule	CompletionComments	DateDone	DistanceDone	Worktype	Workstate	EquipmentOwner	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
					Fault: - Loose bolster bolts, 3rd bolster Cause: - Loosened from movement/vibration Correction: - Loosened and repositioned centre bolster - Tightened bolster bolts											
			Chassis\BOLSTER													
T626	Mt Gambier - Mt Gambier	Chassis\BOLSTER	LOOSE BOLTS ON 3RD BOLSTER NEED TIGHTENING		- Checked and tightened remainine bolster bolts	09/10/2026	570000	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK		79114S	HALLORAN DIESEL - 3	TRAILER
T626	Mt Gambier - Mt Gambier	Tyres\TP02	Tyres\TP02			06/10/2026	570000	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK		79114S	BORDER BANDAG PTY LTD -3	TRAILER
					Extension bracket for binder cracked/broken r n r with one supplied in RH locker of truck											
T626	Mt Gambier - Mt Gambier	Chassis\EXTE TU	rear binder bracket broken needs replacing with 1 from storeroom and cracked bracket repaired as spare		Remove binder and bracket. Fit new bracket and refit binder. Check over for leaks, all OK	29/09/2026	570000	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK		79114S	BARRY MANEY - 3	TRAILER
					DUMMY BOLSTER BOLT MISSING - REPAIR Found missing dummy bolster bolt. Fit new bolt and tension.											
T626	Mt Gambier - Mt Gambier	Chassis\BOLSTER	Chassis\BOLSTER		Check operation, all okay R&R RHM PIVOT BUSH Undo pivot bush bolt, air bag bolts, and u-bolts. Found air bag base did not have centre bolt. Source new bolt. Press out old bushes then install new. Lift spring and fit plate and u-bolts in. Went to re-secure all components but found plate not going into position. Found axle moved back. Undo u-bolts and use equipment to move axle back. Re-secure u-bolts and tension all components to spac	04/09/2026	570000	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK		79114S	BARRY MANEY - 3	TRAILER
T626	Mt Gambier - Mt Gambier	Steering\STEER UNI	Steering\STEER UNI			04/09/2026	570000	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK		79114S	BARRY MANEY - 3	TRAILER
T626	Mt Gambier - Mt Gambier	VehService\DS	VehService\DS D Service	VehService\DS		04/09/2026	570000	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK		79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	Brakes\ABS	ABS issues present			07/08/2026	570000	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK		79114S	HALLORAN DIESEL - 3	TRAILER
T626	Myrtleford - Workshop	Chassis\CROSS MBR	BEGAN REFITTING CROSS MEMBERS		CHECK OUT CROSS MEMBERS STARTING TO CRACK weld cracks	05/08/2026	570000	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK		79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	Chassis\BOLSTER	Chassis\BOLSTER			05/08/2026	570000	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK		79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	Chassis\WINCH/STRP	Chassis\WINCH/STRP			05/08/2026	570000	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK		79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	DrivLine\ELECT P&W	DrivLine\ELECT P&W			05/08/2026	570000	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK		79114S	BARRY MANEY - 3	TRAILER
			VehService\DS D Service													
T626	Myrtleford - Workshop	VehService\DS	L135046	VehService\DS		01/08/2026	570000	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK		79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	Chassis\TRL LEGS	REPLACE DAMGED/ DEFECTIVE TWO SPEED LANDING LEG. SEPERATE THE TWO TRAILERS			30/07/2026	570000	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK		79114S	JF MECHANICALS - 3	TRAILER
T626	Myrtleford - Workshop	Chassis\WINCH/STRP	Crack starting last air winch mount on b trailer.			21/07/2026	570000	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK		79114S	JF MECHANICALS - 3	TRAILER
T626	Myrtleford - Workshop	Chassis\MUDGUARDS	X3 X BRACKET ALL CRACKED /BROKEN			21/07/2026	570000	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK		79114S	JF MECHANICALS - 3	TRAILER
T626	Myrtleford - Workshop	Susp\SUSPENSION	REMOVE CRACKED CROSS MEMBERS			22/06/2026	570000	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK		79114S	JF MECHANICALS - 3	TRAILER
T626	Myrtleford - Workshop	Tyres\TP5+6	Tyres\TP5+6 (25-26)			15/06/2026	570000	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK		79114S	BORDER BANDAG PTY LTD -3	TRAILER
					Undo bolt and turn bolster 180 dgerees. Tighten bolt, all											
T626	Myrtleford - Workshop	Chassis\BOLSTER	TURN BOLSTER PEG		okay Found air leak on B trailer module. Repaired leaking airline as required. Trailer ABS light present, inspect fault code. Found for wheel speed sensor C on B trailer short circuited. Check wheel spin on all 4 wheel speed sensors, all okay. Check voltage at plug on C, at 5 volts, all okay. Disconnect wiring at module but did not bring up break in codes.	09/06/2026	570000	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK		79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	Brakes\EBS FAULTS	TRAILER ABS LIGHT ON FOR B TRAILER		Diaenose oossible faulty module. to rebook for reoair.	09/06/2026	570000	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK		79114S	BARRY MANEY - 3	TRAILER
			Insp\ANN INSP Annual Inspection As Per Checklist													
T626	Myrtleford - Workshop	Insp\ANN INSP	L134170	Insp\ANN INSP		05/06/2026	570000	PreventativeMaintenance	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK		79114S	BARRY MANEY - 3	TRAILER
			VehService\DS D Service													
T626	Myrtleford - Workshop	VehService\DS	L134157	VehService\DS		05/06/2026	570000	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK		79114S	BARRY MANEY - 3	TRAILER
					Check and found rear ride height valve sitting incorrectly. Remove and replace ride height valve on A and B trailer as required KWT03-1701 VALVE-HCV-BPW BASIC 1 176.78 KWT03-1701 VALVE-HCV-BPW BASIC 1 176.78 KW169PTCNS-4-M12 PTC FTG M12 90 DEG TO 1/4" TUB 1 21.36 NGSCRAPH05E scrap hose 1 4.55 KWMAQG2-DOT-8 PTC UNION BMM 1 9.97											
T626	Myrtleford - Workshop	Susp\HCV	CHECK FAULT WITH SCALES READING INACCURATE. SCOTT THINIS ISSUE WITH RIDE HEIGHT VALVE		Sublwt15113556 OLIVES TO SUIT	22/05/2026	570000	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK		79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	Chassis\HOUSEKEEP	REPAIR TRAILER CRACKS		Inspect and found minor cracks in trailer. Prep area and weld reoair. all okav	22/05/2026	570000	Reoair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK		79114S	BARRY MANEY - 3	TRAILER
			VehService\DS D Service													
T626	Myrtleford - Workshop	VehService\DS	L133803	VehService\DS		21/05/2026	570000	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK		79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	Elect\TRL LIGHTS	PASSENGER SIDE CLEARANCE LIGHT OUT		Check wiring to lights and found broken in bolster. Cut and rejoin section of wire. Test operation, all okay. Secure wiring.	20/05/2026	570000	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK		79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	Chassis\WINCH/STRP	SECOND LAST BINDER LOOSE BOLTS ON BRACKET TO CHASSIS		Grind out binder bracket and weld repair, all okay	20/05/2026	570000	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK		79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	Chassis\WINCH/STRP	LAST AIR BINDER PLATE BRACKET TO CHASSIS NEEDS WELDING.		Fit x2 new bolts to guard as old ones no good. Go over and tighten all other mudguard bolts to spec, all okay	20/05/2026	570000	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK		79114S	BARRY MANEY - 3	TRAILER
					CLEAN AND REPACK BEARINGS Split truck and trailers, crack all axle nuts. Jack all 3 axles and put on stands. Back off brakes and remove wheel assemblys. Remove all bearings, check over brakes then clean bearings and nuts. Re-pack all bearings then fit bearings with new nut spacers. Refit wheel assemblys and adjust wheel bearings to spec. Adjust brakes, remove axle stands and tension axle caps. Road test and check over, all okay KW03320640I0 WASHER-STD HUB ECO BEAMH91 3 30.21 KW0980106890TSSC KIT-W/BRG & SEAL,10T ECO GREAS,INC SEAL 1 187.43 NG03320640I0NG HUB WASHER 1 15.34											
T626	Myrtleford - Workshop	DrivLine\WHEEL BRGS	**All wheel bearings need to be repacked L133707		PCL-BPW GREASE	12/05/2026	570000	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK		79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	Chassis\WINCH/STRP	2ND BINDER FROM REAR LEAKS AIR UNDER PRESSURE		Found air leak at second to last binder, remove damaged section of air line and replaced NGSCRAPH05E scrap hose	12/05/2026	570000	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK		79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	Chassis\WINCH/STRP	3RD BINDER FROM REAR NEEDS NEW LOCKING PIN		Found air leak at second to last binder, remove damaged section of air line and replaced NGSCRAPH05E scrap hose	12/05/2026	570000	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK		79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	Elect\RADIO	R/H INDICATOR TEMPREMENTAL		RH indicator n/w, check over wiring and found trailer plug badly corroded. Disassemble trailer plug and re wire. Also found rubbed section of wirina in A trailer.	12/05/2026	570000	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK		79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	Tyres\TP1+2	Tyres\TP1+2 (21-22)			11/05/2026	570000	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK		79114S	BORDER BANDAG PTY LTD -3	TRAILER
T626	Myrtleford - Workshop	Tyres\TP7+8	Tyres\TP7+8 (27-28)			11/05/2026	570000	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK		79114S	BORDER BANDAG PTY LTD -3	TRAILER
			VehService\DS D Service													
T626	Myrtleford - Workshop	VehService\DS	L133449	VehService\DS		28/04/2026	570000	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK		79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	Chassis\BOLSTER	LH FRONT BOLSTER BENT - TURN		Remove and rotate bolster 180 degrees, tension, all okay Jack and support chassis. Undo air bags, ubolts and pivot bolt. Jack up axle and remove wheels and spring. Press out old bush then press in new bush (from GF stock). Tension ubolts and pivot bolt and refit wheels. Lower suspension back to ride height and tension ubolts, pivot bolt and	24/04/2026	570000	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK		79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	Susp\Torque Rod	PIVOT BUSH WORN - RH FRONT		wheel nuts. all OK	14/04/2026	570000	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK		79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	Brakes\EBS FAULTS	PLUG IN AND CHECK TRAILER ABS FAULT CODES		Plug into B trailer and check codes - wheel speed sensor C to earth active. Unplug sensor from module and found code did not clear. Advise faulty module but would like to further investiaate and diaanose before repair	14/04/2026	570000	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK		79114S	BARRY MANEY - 3	TRAILER
			VehService\DS D Service													
T626	Myrtleford - Workshop	VehService\DS	L133289	VehService\DS		13/04/2026	570000	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK		79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	Chassis\WINCH/STRP	REPLACE MISSING AIR WINCH BOLTS		Fit new nut and washers to binder as required, all OK	19/03/2026	570000	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK		79114S	BARRY MANEY - 3	TRAILER
			CHECK WHEEL BEARINGS LH FRONT RH MIDDLE		Jack up each axle and adjust wheel bearings. Found all LH wheel bearings need washers to be replaced. Replace all LHS washers as required.											
T626	Myrtleford - Workshop	Body\WHL HUB	RH REAR		KW03320640I0 WASHER-STD HUB ECO BEAMH91	19/03/2026	570000	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK		79114S	BARRY MANEY - 3	TRAILER
			VehService\DS D Service													
T626	Myrtleford - Workshop	VehService\DS	L132885	VehService\DS		17/03/2026	570000	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK		79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	Tyres\TP9+10	Tyres\TP9+10 (29-30)			13/03/2026	570000	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK		79114S	BORDER BANDAG PTY LTD -3	TRAILER
			VehService\DS D Service													
T626	Myrtleford - Workshop	VehService\DS	L099049	VehService\DS		23/02/2026	570000	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK		79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	Tyres\TP5+6	Tyres\TP5+6 (25-26)			19/02/2026	570000	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK		79114S	BORDER BANDAG PTY LTD -3	TRAILER
T626	Myrtleford - Workshop	Tyres\TP7+8	Tyres\TP7+8 (27-28)			19/02/2026	570000	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK		79114S	BORDER BANDAG PTY LTD -3	TRAILER
			VehService\DS D Service													
			L098732													
T626	Myrtleford - Workshop	VehService\DS	D Service	VehService\DS		02/02/2026	570000	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK		79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	Tyres\Punct	Tyres\Punct POS 27			30/01/2026	570000	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK		79114S	BORDER BANDAG PTY LTD -3	TRAILER
T626	Myrtleford - Workshop	Chassis\CROSS MBR	REPAIR TRAILER CRACKS		Found trailer to have cracked cross brace brackets. Grind out and weld cradks. LH MIDDLE & LH REAR S-CAM BUSHES	07/01/2026	570000	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK		79114S	BARRY MANEY - 3	TRAILER
			LHM & LHR s-cams and bushes to be done next service		Inspect s-cam movement, only slight movement. Will continue											
T626	Myrtleford - Workshop	Brakes\R.H.F	checked 26/11/25		to monitor.	07/01/2026	570000	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK		79114S	BARRY MANEY - 3	TRAILER
			VehService\DS D Service													
T626	Myrtleford - Workshop	VehService\DS	L098405	VehService\DS		05/01/2026	570000	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK		79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	Susp\AIR LEAK	FITTING ON TOP OF LHF AIRBAG LEAKING		Check over for air leaks, built up full air and spray all air bags and fittings. Found fitting on LH front air bag leaking, fitting would not re seal. Disconnect lines and block off. Removed fitting and replaced with new, reconnect lines and check over, no further leaks. KW0243131300 Remove front left bracket and straighten out in press. Remove remaining guard, then mark, drill and fit new guard as required. Refit bracket, secured to mud guard.	11/12/2025	570000	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK		79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	Body\DAMAGE	HIT ROO AND DAMAGED FRONT LEFT GUARD AND BRACKET		KWK127-1116-08A FENDER RED SPRAYSAFE	11/12/2025	570000	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK		79114S	BARRY MANEY - 3	TRAILER

						Primed and painted new skid plate ready for install.													
						Picked up trailer from yard, bring to BMG workshop,													
						disconnect trailers. Blow off and sweep excess bark off skid													
						plate. Disconnect airlines off fittings and wiring from													
						back of light abs plug. Remove all nuts and bolts then													
						remove skid plate. Use wire brush to clean mounting													
						surfaces and ensure surface area is clean and prepped.													
						Installed new skid plate, tensioned all bolts. Replaced													
						fittings and light plugs as required. Connect trailers and													
						ensure all lights and EBS working as should. All okay,													
						deliver back to GF yard.													
						NG30/177487KIT SKIDPLATE ASSY LAS 1 2200.00													
						NGS20882 RALLY MATT BLACK 3 66.15													
						NGS20882 RALLY MATT BLACK 2 44.10													
						KW15-7205 SOCKET-PHILLIPS METAL 7 PIN 1 38.23													
						KWASA93-87 CONNECTOR 1/2" NPSF FEMALE 1 26.24													
						KWABF349 SELF SEALING ADPTR 1/2 F 2 53.68													
						KWB2098 24V 7 PIN EBS SOCKET 1 49.12													
						KW146846 CONNECTOR-MALE 1 7.07													
						NGCA93-87 FEMALE COUPLING 1 31.09													
T626	Myrtleford - Workshop	Chassis\SKID PLATE	REMOVE AND REPLACE CRACKED SKID PLATE			Sublet15112135 Connector & c/sunk screws 91.12 Sublet15112137 FITTING	10/12/2025	570000	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	BARRY MANEY - 3	TRAILER	
T626	Myrtleford - Workshop	Tyres\Punct	Tyres\Punct POS 21				09/12/2025	570000	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	BORDER BANDAG PTY LTD -3	TRAILER	
T626	Myrtleford - Workshop	Body\WHL HUB	RH FRONT WHEEL BEARING				04/12/2025	570000	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	BARRY MANEY - 3	TRAILER	
						Jack axle and adjust RHF wheel bearing as required.													
T626	Myrtleford - Workshop	Chassis\CROSS MBR	CROSS MEMBER BOLTS			Inspect and tighten cross member bolts as required, all okav.	04/12/2025	570000	Reoair	Comoleted	Greenfreight Loaxina Vic	FlatTow	Mt Gambier	STK	79114S	BARRY MANEY - 3	TRAILER	
						Use oxy to heat up steel then use forklift to lift rear bar													
T626	Myrtleford - Workshop	Body\DAMAGE	top flange on light bar dented need straightening			until straight, all ok	04/12/2025	570000	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	BARRY MANEY - 3	TRAILER	
						Inspect and found both binders to have loose bolts and were													
						cracked. Remove rear binder, grind and weld bracket on													
						trailer. Remove 2nd to rear binder and weld repair crack.													
T626	Myrtleford - Workshop	Body\STRAPS	BOTH REAR BINDERS HAVE LOOSE BRACKET BOLTS			Bolt binders back on, all okay.	04/12/2025	570000	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	BARRY MANEY - 3	TRAILER	
						Inspect and found both binders to have loose bolts and were													
						cracked. Remove rear binder, grind and weld bracket on													
						trailer. Remove 2nd to rear binder and weld repair crack.													
T626	Myrtleford - Workshop	Chassis\EXTE TU	both rear binder brackets have loose bolts on mounting brackets			Bolt binders back on, all okay.	04/12/2025	570000	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	BARRY MANEY - 3	TRAILER	
			VehService\DS D Service																
T626	Myrtleford - Workshop	VehService\DS	L097925		VehService\DS		02/12/2025	570000	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	BARRY MANEY - 3	TRAILER	
T626	Myrtleford - Workshop	Tyres\RUN OUT	Tyres\RUN OUT POS 21-22				27/11/2025	570000	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	BORDER BANDAG PTY LTD -3	TRAILER	
T626	Myrtleford - Workshop	Tyres\Rims	Tyres\Rims POS 25				27/11/2025	570000	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	BORDER BANDAG PTY LTD -3	TRAILER	
T626	Myrtleford - Workshop	Tyres\TP11+12	Tyres\TP11+12				27/11/2025	570000	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	BORDER BANDAG PTY LTD -3	TRAILER	
T626	Myrtleford - Workshop	Tyres\TP9+10	Tyres\TP9+10				27/11/2025	570000	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	BORDER BANDAG PTY LTD -3	TRAILER	
						EPLACE WORN BINDER STRAPS X2													
						Unbolt binder reels and remove old straps, fit new straps													
						and bolt reel back onto trailer. Tighten straps as													
						required, all ok													
T626	Myrtleford - Workshop	Body\STRAPS	both straps on back bay need replacing			NCSL75/09LOOP 75MMX9M ST LOOP	14/11/2025	570000	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	BARRY MANEY - 3	TRAILER	
						TOP FITTING ON LHR AIRBAG LEAKING													
						Inspect and found airbag fitting damaged and leaking.													
						Remove deck plate and undo airline to airbag then remove													
						top airbag fitting. Fit new top air fitting as needed.													
						Advised to replace air line as well, remove air line, cut													
						new line to length, fit new olives and nuts then fit to													
						airbag, Check for leaks, all ok, refit deck plate.													
						KW1025P120109 TUBE NYLON BLACK 12MM 25 m rol 1 5.22													
						KWMAQG2-D0T-12 PTC UNION 12MM 1 12.01													
T626	Myrtleford - Workshop	Susp\AIR LEAK	airbag leaking or hode middle or front axel R/H side			KWMAO72-D0TS-12XM22 PTC TEE BRNCH 12MM X M22 M	14/11/2025	570000	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	BARRY MANEY - 3	TRAILER	
						Unbolt and remove cross member, grind back and clean													
						surfaces. Weld bracket back together then refit cross													
T626	Myrtleford - Workshop	Chassis\CROSS MBR	REAR CROSS MEMBER SNAPPED - WELD REPAIR			member to trailer.	14/11/2025	570000	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	BARRY MANEY - 3	TRAILER	
						REPLACE SIGN AT REAR OF TRAILER AS FADED													
						Unbolt and remove rear sign, line up, mark and drill holes													
T626	Myrtleford - Workshop	Body\RWC COMP	back R/H diagonal sign on light bar is badly faded and needs replacing			into new signs. Bolt new signs onto back of trailer, all ok	14/11/2025	570000	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	BARRY MANEY - 3	TRAILER	
			VehService\DS D Service																
T626	Myrtleford - Workshop	VehService\DS	L097687		VehService\DS		12/11/2025	570000	Service	Comoleted	Greenfreight Loaxina Vic	FlatTow	Mt Gambier	STK	79114S	BARRY MANEY - 3	TRAILER	
						Send x2 bolsters to be straightened.													
T626	Myrtleford - Workshop	Chassis\BOLSTER	STRAIGHTEN 2 x BENT BOLSTER PEGS			Sublet15111607 Straighten bent bolsters	10/11/2025	570000	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	BARRY MANEY - 3	TRAILER	
						Response from Steve at Trident tyres for invoice 318414.													
						Actual tyre positions changed on this call out in Sept were 25,26 by Trident on 19/9/25 not pos 27,28 as per invoice 316947.													
T626	Myrtleford - Workshop	Tyres\TP7+8	Tyres\TP7+8 (27-28)			John Bruttomesso can confirm.	07/11/2025	570000	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	BORDER BANDAG PTY LTD -3	TRAILER	
						Response from Steve at Trident tyres for invoice 318414.													
						Actual tyre positions changed on this call out in Sept were 25,26 by Trident on 19/9/25 not pos 27,28 as per invoice 316947.													
T626	Myrtleford - Workshop	Tyres\TP5+6	Tyres\TP5+6 (25-26)			John Bruttomesso can confirm.	07/11/2025	570000	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	BORDER BANDAG PTY LTD -3	TRAILER	
			VehService\DS D Service																
T626	Myrtleford - Workshop	VehService\DS	L097372		VehService\DS		24/10/2025	570000	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	BARRY MANEY - 3	TRAILER	
						Replace first and second RH pins. Remove bolts for pin and													
						found one seized. Use oxy to remove bolt then use forklift													
						to lift out pins. Replace pins and position as required,													
T626	Myrtleford - Workshop	Chassis\BOLSTER	REPLACE BOTH DRIVER SIDE BOLSTER PINS THAT ARE BENT			all ok.	24/10/2025	570000	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	BARRY MANEY - 3	TRAILER	
T626	Myrtleford - Workshop	DrivLine\WHL HUB	hubbo n/w			NOT A ROAD WORTHY ITEM (WD)	22/10/2025	570000	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	BARRY MANEY - 3	TRAILER	
			VehService\DS D Service																
T626	Myrtleford - Workshop	VehService\DS	L097182		VehService\DS		13/10/2025	570000	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	BARRY MANEY - 3	TRAILER	
						Found fitting and hose leaking. Removed air line, cut new													
						hose to length and installed with new fitting. Checked													
						operation, all okay.													
T626	Myrtleford - Workshop	Chassis\WINCH/STRP	2nd last air binder has a leaking hose/fitting			NGSCRAPH05E scrap hose	09/10/2025	570000	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	BARRY MANEY - 3	TRAILER	
						Cut off round steel that was previously welded on, grind													
			Body\BOLSTER			back surfaces. Measure and cut new stays, ensuring they are													
T626	Myrtleford - Workshop	Body\BOLSTER	Front bolster keeps moving sideways again			bigger than previous ones. Welded new stays onto bolster	09/10/2025	570000	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	BARRY MANEY - 3	TRAILER	
						Found hole in LH middle airbag, undo top and bottom airbag													
						bolts, lower ride height and disconnect airlines. Raise ride													
						height then remove and replace airbag. Tighten all nuts and													
						bolts to spec. Refit airlines and check, all ok													
T626	Myrtleford - Workshop	Body\AIR BAG	middle air bag left hand side needs replacing. leaking badly empty and loaded. centre axel.			KWTRP8177 AIR SPRING-TRP BPW D30K SUITS BPW 054294	09/10/2025	570000	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	BARRY MANEY - 3	TRAILER	
						Cross member cracked in 2 places at the front. Grind area													
T626	Myrtleford - Workshop	Chassis\CROSS MBR	WELD CROSS MEMBER CRACKS			to prep for welding. Weld cracks, all ok	09/10/2025	570000	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	BARRY MANEY - 3	TRAILER	
						When trailer put on shaker booster line blew off at joiner.													
T626	Myrtleford - Workshop	Body\AIR LEAK	Air line blew off when shaking trailer			Cut out worn oart of booster line and reioin. all ok.	09/10/2025	570000	Reoair	Comoleted	Greenfreight Loaxina Vic	FlatTow	Mt Gambier	STK	79114S	BARRY MANEY - 3	TRAILER	
						Inspect and found light to be faulty. Install new LED													
						insert then check brake light operation. Found to RH outer													
						light faulty, replace as needed. Check operation, all													
T626	Myrtleford - Workshop	Elect\TAIL LIGHT	RH OUTER BRAKE LIGHT N/W			lights working as should. KW94608 LAMP-LED.10-30V REAR STOP TAIL 46 SERIES	09/10/2025	570000	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	BARRY MANEY - 3	TRAILER	
						Jack LH front axle and remove airbag and u bolts. Remove													
						pivot bush bolts and remove spring. Press out old bush and													
						then press in new bush. Fit spring, tension u-bolts. Had to													
						replace airbag as bag fell out and found thread stripped													
						and bag was just sitting there. All ok													
T626	Myrtleford - Workshop	Susp\SUSPENSION	R&R FRONT SPRING EYE PIVOT BUSHES			KW0203142K1T-1ALP KIT-BUSH AL2 ALIGN PARALLEL 1 107.10KWTRP8177 AIR SPRING-TRP BPW D30K SUITS BPW 054294	09/10/2025	570000	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	BARRY MANEY - 3	TRAILER	
T626	Myrtleford - Workshop	Tyres\Rims	Tyres\Rims POS 24				30/09/2025	570000	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	BORDER BANDAG PTY LTD -3	TRAILER	
T626	Myrtleford - Workshop	Tyres\TP7+8	Tyres\TP7+8 (27-28)				25/09/2025	570000	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	BORDER BANDAG PTY LTD -3	TRAILER	
T626	Myrtleford - Workshop	Tyres\Rims	Tyres\Rim				25/09/2025	570000	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	BORDER BANDAG PTY LTD -3	TRAILER	
T626	Myrtleford - Workshop	Tyres\Rims	Tyres\Rim				25/09/2025	570000	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	BORDER BANDAG PTY LTD -3	TRAILER	
T626	Myrtleford - Workshop	Tyres\RUN OUT	Tyres\RUN OUT POS 23-24				25/09/2025	570000	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	BORDER BANDAG PTY LTD -3	TRAILER	
						side lights n/w													
						Inspect side lights and all wiring. Remove and replace x2													
T626	Myrtleford - Workshop	Elect\TRL LIGHTS	Elect\TRL LIGHTS SIDE LIGHTS			side lights and check operation. all ok	22/09/2025	570000	Reoair	Comoleted	Greenfreight Loaxina Vic	FlatTow	Mt Gambier	STK	79114S	BARRY MANEY - 3	TRAILER	
						REMOVE MUDFLAP													
T626	Myrtleford - Workshop	Body\MUDGUARDS	Body\MUDGUARDS REMOVE			Removed front mudflap as requested	22/09/2025	570000	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	BARRY MANEY - 3	TRAILER	
						DRIVER HIT A LOG AND BENT GUARD AND BRACKETS													
						Found damage to RH rim, guard and mounting brackets. Remove													
			Body\MUDGUARDS			all broken parts and straightened bent brackets. Fit new													
T626	Myrtleford - Workshop	Body\MUDGUARDS	DRIVER HIT A LOG AND BENT GUARD AND BRACKETS			guard and brackets. all ok	18/09/2025	570000	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	BARRY MANEY - 3	TRAILER	
						Carried out trailer service as per Greenfreight checklist.													
						Customer Instructions:													
						Place vehicle on shaker & Inspected													
						Carried out General Inpection & Checkover													
						Greased vehicle													
			VehService\DS D Service			Check over and retension pivot bushes & u bolts													
T626	Myrtleford - Workshop	VehService\DS	L096927		VehService\DS	Check over and tensioned all bolster bolts as reauired.	18/09/2025	570000	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	BARRY MANEY - 3	TRAILER	
						RH front air bag leaking when loaded													
T626	Myrtleford - Workshop	Susp\AIR BAG	R/H front airbag leaking when loaded			Found supply line to air bag was leaking. Cut out rubbed	02/09/2025	570000	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	BARRY MANEY - 3	TRAILER	
						section and rejoined.													
						Electrical lead back from plug has exposed wires and keeps													
						earthing out, red tape where problem is													
						Inspect wiring as indicated. Tested wiring and inspect													
						fuses and relay. Found plug on B trailer was covered in													
						debris. Cleaned out plugs and checked operation, all lights													
						working okay., LH tail light on A trailer not working,													
						traced wiring back and repaired broken wiring. Checked, all													
T626	Myrtleford - Workshop	Elect\SUZI COIL	Electrical lead (suzie coil) just back from plug has exposed wires keeps earthing indicators			lights okav	02/09/2025	570000	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	BARRY MANEY - 3	TRAILER	
						Front bolster still moving													
						Measure and cut two pieces of round bar steel. Prepped													
						surfaces and welded stoppers on each end of bolster to													
T626	Myrtleford - Workshop	Chassis\BOLSTER	front bolster still moving side to side			prevent side to side movement	02/09/2025	570000	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	BARRY MANEY - 3	TRAILER	

					FRONT LH GUARD SAGGING ON WHEEL Jacked up bracket and straightened out to prevent mud guard sagging.														
T626	Myrtleford - Workshop	Body\MUDGUARDS	Body\MUDGUARDS		CRACKED CROSS MEMBER	02/09/2025	570000	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER				
T626	Myrtleford - Workshop	Chassis\CROSS MBR	Chassis\CROSS MBR CRACKED		Prep area for welding, jacked up cross member and hold in position. Grind back area and welded Bolster light n/w	02/09/2025	570000	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER				
T626	Myrtleford - Workshop	Chassis\BOLSTER	Chassis\BOLSTER LIGHT FAULT		Inspect bolster light for fault, removed light and tested power and earth, no good. Run new wire through bolster and joined to light. Wiring okay but light was faulty. Remove and fit new light, all okay.	02/09/2025	570000	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER				
T626	Myrtleford - Workshop	VehService\DS	VehService\DS D Service		GREENFREIGHT SERVICE														
T626	Myrtleford - Workshop	VehService\DS	L096584	VehService\DS	Carried out trailer service as per Greenfreight checklist.	30/08/2025	570000	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER				
T626	Myrtleford - Workshop	Tyres\Punct	Tyres\Puncture REPAIR 28		DONE IN MT GAMBIER	22/08/2025	555474	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BORDER BANDAG PTY LTD -3	TRAILER				
T626	Myrtleford - Workshop	Tyres\RUN OUT	Tyres\RUN OUT POS 22 + NEW RIM			22/08/2025	555474	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BORDER BANDAG PTY LTD -3	TRAILER				
T626	Myrtleford - Workshop	Chassis\LTRL LEGS	landing legs need removing of new feet put on bottom sled is hitting A trailer on full lock			21/08/2025	555474	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER				
T626	Myrtleford - Workshop	Body\AIR LEAK	air leak from hose or booster middle or front axel			21/08/2025	555474	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER				
T626	Myrtleford - Workshop	Chassis\BOLSTER	front bolster still moving side to side			21/08/2025	555474	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER				
T626	Myrtleford - Workshop	VehService\DS	VehService\DS D Service	VehService\DS	Carried out trailer service as per Greenfreight checklist. Check over and retension pivot bushes & u bolts	14/08/2025	570000	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER				
T626	Myrtleford - Workshop	Body\BOLSTER	front bolster has moved accross to the right needs to be loosened and moved back to the left 2-3 inch. level with other bolsters		Removed old bolster clamps and replaced with new clamps. Alian bolster and tension to spec. all ok	08/08/2025	555474	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER				
T626	Myrtleford - Workshop	Chassis\EXTE TU	BENT HANDLE		Inspect binder handle, found it to need a new bolt as old one was bent. Fit new bolt to handle. all ok	08/08/2025	555474	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER				
T626	Myrtleford - Workshop	Susp\AIR BAG	RH front air bag leaking		Work order 199568ack chassis, and inspect, found bottom of air bag to be leaking. Remove air bag and base. Fit base to new air bag, then fit to chassis. Lift bags and check over, all ok.	08/08/2025	555474	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER				
T626	Myrtleford - Workshop	Brakes\BRK O/HAUL	Replace LH middle S cam		Inspect LH middle s-cam, found to be okay. Will continue to monitor. Labour Fault: Bolster pins bent: Correction: Rotated 1x bolster pin on RHS.	08/08/2025	555474	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER				
T626	Myrtleford - Workshop	Chassis\BOLSTER	Chassis\BOLSTER		Swapped over and rotated 2x bolster pins on LHS GREENFREIGHT SERVICE Carried out trailer service as per Greenfreight checklist. Customer Instructions: Place vehicle on shaker & Inspected Carried out General Inpection & Checkover Greased vehicle TENSION PIVOT BUSHES & U BOLTS Check over and retension pivot bushes & u bolts TENSION BOLSTER BOLTS	07/08/2025	555474	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	HALLORAN DIESEL - 3	TRAILER				
T626	Myrtleford - Workshop	VehService\DS	VehService\DS D Service	VehService\DS	Check over and tensioned all bolster bolts as required.	02/08/2025	555474	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER				
T626	Myrtleford - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		18/07/2025	555474	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER				
T626	Myrtleford - Workshop	Chassis\WINCH/STRP	BOTH BACK BINDER BRACKETS NEED ATTENTION. oNE IS LOOSE AND ONE HAS CRACKS.		BOTH BACK BINDER BRACKETS NEED ATTENTION. ONE IS LOOSE AND ONE HAS CRACKS. Work order 198861 Remove and replace second from rear binder bracket. Inspect rear binder and also found to be cracked. Grind back and weld over cracks. Rear binder bracket needs replacing next service. CHECK BRAKES Work order 198861 Check over all braking components, adjusted as per BPW spec. Connect air gauges for testing next service due to time constraints.	14/07/2025	555474	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER				
T626	Myrtleford - Workshop	Brakes\BRAKE ADJ	Brakes need looking at			14/07/2025	555474	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER				
T626	Myrtleford - Workshop	Elect\TRL LIGHTS	Elect\TRL LIGHTS		REPAIR LH CLEARANCE LIGHT ON 2ND TO LAST BOLSTER Inspect bolster light not working, removed light and found a broken wire. Tidy up wiring and rejoined. Tested operation. all okay. WELD CROSS BRACE BRACKET	25/06/2025	555474	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER				
T626	Myrtleford - Workshop	Chassis\CROSS MBR	Chassis\CROSS MBR		Found cross brace snapped. Removed brace from trailer, cleaned surface for welding. Welded brace together. Once cooled re bolted into trailer. Carried out trailer service as per Greenfreight checklist. Customer Instructions: Place vehicle on shaker & Inspected Carried out General Inpection & Checkover Greased vehicle TENSION PIVOT BUSHES & U BOLTS Check over and retension pivot bushes & u bolts TENSION BOLSTER BOLTS	25/06/2025	555474	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER				
T626	Myrtleford - Workshop	VehService\DS	VehService\DS D Service	VehService\DS	Check over and tensioned all bolster bolts as required	22/06/2025	555474	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER				
T626	Myrtleford - Workshop	Tyres\TP7+8	Tyres\TP7+8			20/06/2025	555474	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BEAUREPAIRES - 3	TRAILER				
T626	Myrtleford - Workshop	Chassis\CROSS MBR	TIGHTEN LOOSE CROSSMEMBERS		Check over and tightened all loose cross members	05/06/2025	555474	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER				
T626	Myrtleford - Workshop	Body\MUDGUARDS	ELPHINSTONE MUDFLAPS ON LIGHT BAR NEED REPLACING .THE 2 ON RHS. (FLAPS IN TRUCK)		Remove worn mud flaps and installed new mud flaps as supplied. GREENFREIGHT SERVICE Carried out trailer service as per Greenfreight checklist. Customer Instructions: Place vehicle on shaker & Inspected Carried out General Inpection & Checkover Greased vehicle Completed paperwork & Cleaned area TENSION PIVOT BUSHES & U BOLTS Check over and retension pivot bushes & u bolts TENSION BOLSTER BOLTS	05/06/2025	555474	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER				
T626	Myrtleford - Workshop	VehService\DS	VehService\DS D Service	VehService\DS	Check over and tensioned all bolster bolts as required. CARRY OUT ANNUAL INSPECTION AS PER GREENFREIGHT CHECKLIST	05/06/2025	555474	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER				
T626	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection	Insp\ANN INSP	Carried out trailer inspection as per Greenfreight checklist CHECK OUT ALL AIR LEAKS ONE COMING FROM MIDDLE AXLE LH SIDE AIRBAG Found LH front and RH middle air bags leaking under load. Jacked chassis and disconnect air lines. Removed bottom bolts but found top bolts were seized. Use oxy heat to loosen up bolts and removed. Change over base plates to new air bags and installed. Replaced air fitting on LH front air bag due to corrosion. Connect air lines and lowered	05/06/2025	555474	PreventativeMaintenance	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER				
T626	Myrtleford - Workshop	Susp\AIR LEAK	Susp\AIR LEAK		chassis. Checked over. no further leaks.	30/05/2025	555474	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER				
T626	Myrtleford - Workshop	Tyres\TP9+10	Tyres\TP9+10			27/05/2025	555474	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BEAUREPAIRES - 3	TRAILER				
T626	Myrtleford - Workshop	Tyres\TP5+6	Tyres\TP5+6			27/05/2025	555474	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BEAUREPAIRES - 3	TRAILER				
T626	Myrtleford - Workshop	Susp\AIR BAG	FEW SMALL AIR LEAKS WHEN LOADED?? POSSIBLY MIDDLE AXEL AIRBAGS.		AIR LEAKS WHEN LOADED Work order 197317 Tightened up loose fittings on ride height. 2ND LAST BINDER REALLY TIGHT Work order 197317	27/05/2025	555474	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER				
T626	Myrtleford - Workshop	Chassis\WINCH/STRP	2ND TO LAST BINDER REALLY TIGHT AND STILL TO WIND UP		Checked binder and greased points, operated, all okay. GREENFREIGHT SERVICE Carried out trailer service as per Greenfreight checklist. Customer Instructions: Place vehicle on shaker & Inspected Carried out General Inpection & Checkover Greased vehicle Completed paperwork & Cleaned area TENSION PIVOT BUSHES & U BOLTS Check over and retension pivot bushes & u bolt TENSION BOLSTER BOLTS	27/05/2025	555474	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER				
T626	Myrtleford - Workshop	VehService\DS	VehService\DS D Service	VehService\DS	Check over and tension bolster bolts as required.	24/05/2025	555474	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER				
T626	Myrtleford - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		09/05/2025	555474	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER				
T626	Myrtleford - Workshop	DriCabRep\AIR LEAK	fix air leakl		Sprayed all hoses and fittings to locate air leak. Found loose screws on ride height valve. Tightened all screws as required. Jack up each axle, removed wheels and replaced washers in wheel bearings. Refit wheels, adjust wheel bearings to correct end float. Refit wheel nuts, lowered axle,	06/05/2025	555474	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER				
T626	Myrtleford - Workshop	DrivLine\WHEEL BRGS	all axels require new washers and adjusting next service		tensioned. Reseat for all axles. Undo bolts and removed mud flaps, installed new mud flaps	06/05/2025	555474	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER				
T626	Myrtleford - Workshop	Chassis\MUDGUARDS	BOTH MUDFLAPS NEED REPLACING ON BACK TRI. (MUDFLAPS IN TRUCK)		and tensioned bolts.	06/05/2025	555474	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER				
T626	Myrtleford - Workshop	Tyres\TP11+12	Tyres\TP11+12		SECOND LAST BOLSTER BRACKET NEEDS STRAIGHTENING Work order 196297 Undo bolster bracket and removed. Straightened out bracket in press, refitted bracket to bolster and bolted in	22/04/2025	555474	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BEAUREPAIRES - 3	TRAILER				
T626	Myrtleford - Workshop	Chassis\BOLSTER	2nd to last bolster bracket damaged needs straightening		position. all okav.	22/04/2025	434957	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER				
T626	Myrtleford - Workshop	Tyres\TP7+8	Tyres\TP7+8			16/04/2025	555474	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BEAUREPAIRES - 3	TRAILER				
T626	Myrtleford - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		11/04/2025	555474	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER				
T626	Myrtleford - Workshop	Chassis\CROSS MBR	WELD CRACKS IN CROSS MEMBER & LOOSE BOLTS		Welded cracks and tightened bolts FIRST AXLE LOOSE WHEEL BEARINGS Jacked up axle, checked play and found to have movement. All axles [presented the same as front axle on shaker. Will	05/04/2025	555474	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER				
T626	Myrtleford - Workshop	Chassis\WHEEL SEAL	FIRST AXLE LOOSE WHEEL BEARINGS		all need new washer and re adiust at next service	05/04/2025	555474	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER				

T626	Myrtleford - Workshop	Body\BOLSTER	Body\BOLSTER		Removed bolt, turned bolster around as required and refit bolt Trailer snapped spring Truck bowds lane Dartmoor near cemetary Travelled to breakdown. Dumped LH middle air bags, jacked and then chained axle up. Removed wheels and secured on trailer. Drove back to workshop. Removed chains and supported axle. Removed u bolts, saddle and broken spring. Removed pivot bolt and spring. Installed new spring. Reinstalled u bolts and saddle. Aligned new axle.	01/04/2025	S55474	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	TRIPLE S DISTRIBUTORS - 3	TRAILER
T626	Myrtleford - Workshop	Susp\SPRING HANG	Susp\SPRING HANG		Reinstalled airbag mount bolts. Tightened u bolts and pivot bolt. Reinstalled wheels and tensioned. BENT AND LOOSE BOLSTER BOLTS	28/03/2025	S55474	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER
			Further Work Required:		Work order 195237										
T626	Myrtleford - Workshop	Body\BOLSTER	All other bolsters require attention bent and loose bolts		Tensioned all bolsters and bolster oin bolts.	27/03/2025	S55474	Fault	Comoleted	Greenfreight Loaxina Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		26/03/2025	S55474	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	Susp\SUSPENSION	Susp\SUSPENSION		Loose Clevis nuts on 2 axles	25/03/2025	S55474	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	TRIPLE S DISTRIBUTORS - 3	TRAILER
T626	Myrtleford - Workshop	Chassis\AIR LEAK	Chassis\AIR LEAK		Diagnosed air leak. Had to locate correct size joiner. Repair air leak. Tighten up crossmember bolts. REPLACE LOAD STRAPS	25/03/2025	S55474	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	TRIPLE S DISTRIBUTORS - 3	TRAILER
T626	Myrtleford - Workshop	Chassis\WINCH/STRP	Chassis\WINCH/STRP		Undo rear loading straps, removed pin and installed new straps. Roll up straps and secured. Replaced bolt and nut on rear straps due to be seized. Disconnected air lines and removed ride height. Installed new ride height, connected air lines. Tested operation, all	14/03/2025	S55474	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	Myrtleford Workshop	TRAILER
T626	Myrtleford - Workshop	Susp\AIR LEAK	ride hight valve leaking		okay. REFIT BOLSTER	08/03/2025	S55474	Reoair	Comoleted	Greenfreight Loaxina Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	Chassis\BOLSTER	refit bolster		Inspect bolster to refit, found to be cracked underneath, not safe. Loosened mounting bolts for third bolster and moved forwards to make 3 bavs. Tensioned bolts.	08/03/2025	S55474	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	Body\STRAPS	rear 2 binder straps need replacing		Undo worn binder straps and installed new. Found clearance light and indicator were smashed. Removed both lights, joined wiring to new lights and installed.	08/03/2025	S55474	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	Elect\TRL LIGHTS	drivers side clearance light broken of		Test operation. all okay. Travel to site found LHS rear bolster hold down bolts broke off and bracket was missing. Truck was loaded and had to be empty for repairs. Travel with truck to PNR get rear bolster unloaded. Use crane to lift booster back into position tried to undo RHS bolt but they were seized cut bolts off with oxy. Remove RHS bracket travel to workshop cut out new bracket measure and drill bolt holes. Weld nuts on for locking bolts. Travel back to site fit brackets with new bolts. Repair wiring tighten 4 other loose bolster bolts. Travel return.	08/03/2025	S55474	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	Body\BOLSTER	Body\BOLSTER			05/03/2025	S55474	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	COOKY'S DIESEL MECHANIC REPAIRS - 3	TRAILER
T626	Myrtleford - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		03/03/2025	S55474	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	Tyres\TP3+4	Tyres\TP3+4			24/02/2025	S52915	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BEAUREPAIRES - 3	TRAILER
T626	Myrtleford - Workshop	Tyres\TP1+2	Tyres\TP1+2			24/02/2025	S52915	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BEAUREPAIRES - 3	TRAILER
T626	Myrtleford - Workshop	VehService\DS	VehService\DS	VehService\DS		21/02/2025	S52915	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	Chassis\CHAS CRACK	Chassis\CHAS CRACK		WELD TRAILER CRACKS Found crack through chassis. Grind back surfaces and welded over crack. Painted over weld, monitor. CHECK WHEEL BEARINGS	21/02/2025	S52915	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	Myrtleford Workshop	TRAILER
T626	Myrtleford - Workshop	Steering\WHEEL BRGS	Steering\WHEEL BRGS		Jacked up axles and checked wheel bearing adjustments, found all wheel bearings need adjusting.next service. Washers need to reolaced. BROKEN BOLSTER BRACKET	21/02/2025	S52915	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	Myrtleford Workshop	TRAILER
T626	Myrtleford - Workshop	Chassis\BOLSTER	REMOVE 2ND BOLSTER BECAUSE BOLSTER MOUNT BRACKETS HAVE BEEN DAMAGED & WILL NEED REPLACING WHEN PARTS ARRIVE		Arranged to meet driver at workshop. Undo bolster pins and removed. Disconnect clearance light wiring, loosened off bolster mounts. Removed bolster brackets, connect sling and removed bolster ELPINSTONE SUPPLIED 4 NEW PEGS Undo all bolster mounts, moved bolsters to specified locations. Connect up new bolster with forklift and installed to trailer. Fit new bolster pins. Connect up second new bolster with forklift and lift onto trailer, fitted new bolster pins. Measure out correct distance for bolsters and retensioned mounting bolts. Run new wiring and mounted clearance lights. Joined wiring and tested	20/02/2025	S52915	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	Myrtleford Workshop	TRAILER
			fit new bolster and old bolster. and 4 new pegs												
T626	Myrtleford - Workshop	Body\BOLSTER	speak with scott regarding possibioning		operation, all okay BROKEN BOLT ON AIR BINDER	13/02/2025	S52915	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	Myrtleford Workshop	TRAILER
T626	Myrtleford - Workshop	Body\STRAPS	Body\STRAPS		Sourced new nuts and bolts to suit, installed to air binder, tightened.	11/02/2025	S52915	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	Tyres\TP5+6	Tyres\TP5+6			31/01/2025	S52915	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BEAUREPAIRES - 3	TRAILER
T626	Myrtleford - Workshop	Chassis\MUDGUARDS	front guard L/H side cracked		REPLACE LHF MUDGUARD AS ITS CRACKED Unbolt and removed cracked mud guard. Measure and drilled holes in new guard. Mounted new guard and tensioned bolts	30/01/2025	S52915	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	VehService\DS	VehService\DS	VehService\DS		30/01/2025	S52915	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	Chassis\BOLSTER	bent bolster pin		Removed existing bent pin out of the bolster & fit new pin in place & secured. Sent the damaged pin to be repaired.	09/01/2025	S52915	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	VehService\DS	VehService\DS	VehService\DS		08/01/2025	S52915	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	Body\BOLSTER	Body\BOLSTER		LOOSE BOLTS NUMEROUS Inspected & found 5 loose bolts on trailer. Tensioned all to spec. WELD TRAILER CRACKS	18/12/2024	S52915	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	Chassis\CROSS MBR	Chassis\CROSS MBR		Found cross member to be cracked. Ground out cracks, re welded section. All ok Loosened bolster bolt & turned bolster 180 degree.	18/12/2024	S52915	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	Chassis\DAMAGE	REPLACE DAMAGED BOLSTER (DAMAGED BY OWP LOADER) (John has the incident report)		Retensioned bolster bolt to spec. Found Mount saddle to be damaged. Removed mount saddle and fit with new mount saddle which was collected from GF yard. All ok	18/12/2024	S52915	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	Tyres\TP11+12	Tyres\TP11+12			17/12/2024	S52915	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BEAUREPAIRES - 3	TRAILER
T626	Myrtleford - Workshop	Tyres\TP5+6	Tyres\TP5+6			02/12/2024	S52915	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BEAUREPAIRES - 3	TRAILER
T626	Myrtleford - Workshop	Chassis\CROSS MBR	Chassis\CROSS MBR		Weld broken cross member Travel to Greenfreight yard and remove broken cross brace from trailer. Return to BMG, grind back surfaces and welded over broken cross brace. Return to Greenfreight and refitted to trailer Carried out trailer service as per Greenfreight checklist. Customer Instructions: Place vehicle on shaker & Inspected Carried out General Inpection & Checkover Greased vehicle Completed paperwork & Cleaned area	21/11/2024	S52915	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	VehService\DS	VehService\DS	VehService\DS	Check over and retension pivot bushes & u bolts	19/11/2024	S52915	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	Chassis\CROSS MBR	bolt in cross member loose			09/11/2024	S52915	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	Chassis\AIR TANKS	air tank loose			09/11/2024	S52915	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	Tyres\TP7+8	Replace Tyres Position's 7&8. (Mount Gambier Goodyear Autocare P/O: L089974)		Replace tyres on position's 7 & 8.	05/11/2024	S52915	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BEAUREPAIRES - 3	TRAILER
T626	Myrtleford - Workshop	VehService\DS	VehService\DS	VehService\DS		22/10/2024	S52915	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	Body\DAMAGE	Body\DAMAGE		WELD CRACKED HANGER PLATE Grind back cracked surfaces and prep area for welding. Weld cracked surfaces and tidy up area. Painted over welds. FRONT BOLSTER MOVING LEFT TO RIGHT IN BRACKETS	22/10/2024	S52915	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	Chassis\BOLSTER	front bolster moving left-right in brackets		Loosened brackets and moved bolster. tightened brackets. LH PARKER LIGHT N/W Removed light and tested wiring, found to have broken wire. Remove broken wire, pull new wire through bolster and joined. Secure and tape wiring, installed new clearance	22/10/2024	S52915	Fault	Comoleted	Greenfreight Loaxina Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	Body\REFLECTORS	clearance light LH side.		light, tested operation, all okay REPLACE LH REAR MUD GUARD AND REPAIR BRACKET REUSE ELPHINSTONE MUD FLAPS Unbolt and removed LH rear mud guard. Heated up bracket and straightened into position. Measure and drilled holes in	22/10/2024	S52915	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	Chassis\MUDGUARDS	back left mudeuard needs reolacine as oart of new light bar invoice. all Elphinstone mudflaps to be reused on new guards please. bracket needs fixing		new guard. Mounted new guard and fitted with original mud flaps	22/10/2024	S52915	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	VehService\DS	VehService\DS	VehService\DS		14/10/2024	S52915	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	Tyres\TP9+10	Tyres\TP9+10			10/10/2024	S52915	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BEAUREPAIRES - 3	TRAILER
T626	Myrtleford - Workshop	Body\DAMAGE	REPLACE REAR LIGHT BAR AS SUPPLIED Loaded tools to attend truck at GF yard for install of light bar. Connected trailer to ute & loaded light bar to trailer and secured. Drove to GF yard. Removed existing light bar from trailer & fit new bar in place. Removed existing mudflaps off the old bar and fitted onto new. Bracket required straightening. Connected all wiring & secured. unable to check operation of light bar as there was no truck connected.			02/10/2024	S52915	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	ELPHINSTONE ENGINEERING - 3	TRAILER
T626	Myrtleford - Workshop	Chassis\DAMAGE	Chassis\DAMAGE		REPLACE REAR LIGHT BAR AS SUPPLIED Loaded tools to attend truck at GF yard for install of light bar. Connected trailer to ute & loaded light bar to trailer and secured. Drove to GF yard. Removed existing light bar from trailer & fit new bar in place. Removed existing mudflaps off the old bar and fitted onto new. Bracket required straightening. Connected all wiring & secured. unable to check operation of light bar as there was no truck connected. REMOVE THIRD BOLSTER FROM THE REAR	24/09/2024	S52915	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	Myrtleford Workshop	TRAILER
T626	Myrtleford - Workshop	Chassis\BOLSTER	remove third bolster		(CONVERT BACK TO 3 BAYS) Removed 3rd bolster from rear of trailer as requested. Repair broken cross brace Cross brace was found to be damaged. Remove bracket & damaged end of brace. Prepped section of brace and welded. Refit to trailer and tension bolts.	19/09/2024	S52915	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	Chassis\CHAS CRACK	repair broken cross brace			19/09/2024	S52915	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER

T626	Myrtleford - Workshop	Chassis\BOLSTER	Chassis\BOLSTER Remove bent bolster and replace with one from rear of trailer 2nd to last Removed bolster pins, unbolted & removed bent bolster from trailer. Removed 3rd bolster & fit in place of damaged bolster. Measured distance between 1st & 2nd bolster & mounted, secured to chassis with brackets. Refit bolster pins. Connected all clearance light wiring. Fit missing reflectors on front of bolster.		LOOSE MOUNTING BOLTS ON AIR BINDER	30/08/2024	552915	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	Chassis\EXTE TU	Loose Mounting Bolts On Air Winch. (Barry Maney P/O: L088340)		On inspection found loose mounting bolts on 1 binder. Tensioned to spec.	24/08/2024	552915	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	Chassis\EXTE TU	2nd Winch Needs Straightening. (Barry Maney)		2ND BINDER NEEDS STRAIGHTENING Inspect binder, found housing was damaged, possibly by grab. Would need to unbolt housing, remove and straighten out. Binder still operating okay. Repair at later date.	24/08/2024	552915	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	VehService\DS	VehService\DS	VehService\DS		22/08/2024	552915	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	Body\STRAPS	AIR BINDER LOOS BOLTS (MOUNTING BOLTS)			18/08/2024	444005	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	Chassis\WINCH/STRP	2nd binder needs straightening			18/08/2024	444005	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	VehService\DS	VehService\DS	VehService\DS		12/08/2024	444005	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	VehService\DS	VehService\DS 1 BBZZZZZ216 AIR LEAKS Tech(s): 8084 375.00CRACKED AIR TANK Disconnect fittings and mounting bolts, removed air tank. Change over fittings to new tank. Make up isolators for tank, tensioned bolts and connect all lines. Tested operation. all okay.	VehService\DS		19/07/2024	400004	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	Brakes\AIR TANKS	3 13ZZZZZ730 CHECK ALL LIGHTS Tech(s): 040472 016030 75.00REPAIR LIGHTS N/W Found damaged clearance light holder on bolster. Removed damaged holder and cut wires. Installed new light and joined wiring. Tested light, all okay. Removed cover for LH brake light, found plug was not plugged in properly. Cleaned surfaces and refit plug, light w			12/07/2024	400004	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	Elect\TRL LIGHTS	CRACK IN PASSENGER SIDE FIRST BOLSTERCRACK IN FIRST BOLSTER PASS. SIDE Inspect crack in bolster, found bolster will need to be			12/07/2024	400004	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	Body\BOLSTER	replaced, non repairable. No spare bolsters here.			12/07/2024	400004	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	Chassis\BOLSTER	Straighten bolster peg.			02/07/2024	400004	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	RINLATECH ENGINEERING-3	TRAILER
T626	Myrtleford - Workshop	VehService\DS	VehService\DS BBZZZZZ224 WELD TRAILER CRACKS Tech(s): 8050 0.00CRACKS IN CHASSIS Arranged JDs metal Fab to repair cracks in chassis. Sublet	VehService\DS		01/07/2024	400004	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	Chassis\CHAS CRACK	15105625 Weld cracked chassis heck reverse buzzer going off Inspected trailer light and found RH indicator bringing the reverse light on. Traced the wiring along the chassis. Fault disappeared then came back on intermittently. On further inspection found rubbed wires on metal bracket at RH rear for supporting loom. Cut open & repaired damaged wires with joiners. Re-tape resecure loom & test. All ok.			28/06/2024	400004	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	PACCAR PARTS FLEET SERVICES - 3	TRAILER
T626	Myrtleford - Workshop	Elect\ELECT P&W	KW56070BLTERMINAL-RING.INS.3MM/4.3IPK25		check reverse buzzer going off Inspected trailer light and found RH indicator bringing the reverse light on. Traced the wiring along the chassis. Fault disappeared then came back on intermittently. On further inspection found rubbed wires on metal bracket at RH rear for supporting loom. Cut open & repaired damaged wires with joiners. Re-tape resecure loom & test. All ok.	28/06/2024	400004	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	PACCAR PARTS FLEET SERVICES - 3	TRAILER
T626	Myrtleford - Workshop	Elect\TRL LIGHTS	Elect\TRL LIGHTS		CRACKS IN CHASSIS	27/06/2024	400004	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	Chassis\CHAS CRACK	Chassis\CHAS CRACK		Arranged JDs metal Fab to repair cracks in chassi	27/06/2024	400004	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	VehService\DS	VehService\DS WELD UP CRACKED CROSS MEMBER - Unbolt cross member & straightened out. Welded up cracks.	VehService\DS		12/06/2024	400004	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	Chassis\CROSS MBR	Cut and welded plates for extra strength. Reinstalled cross member. LABOUR $202.50			12/06/2024	400004	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	PACCAR PARTS FLEET SERVICES - 3	TRAILER
T626	Myrtleford - Workshop	Tyres\PRES CHECK	Tyres\PRES CHECK			29/05/2024	400004	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BEAUREPAIRES - 3	TRAILER
T626	Myrtleford - Workshop	Tyres\TP1+2	Tyres\TP1+2			29/05/2024	400004	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BEAUREPAIRES - 3	TRAILER
T626	Myrtleford - Workshop	VehService\DS	D Service PO # L086385	VehService\DS		29/05/2024	400004	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	Chassis\CROSS MBR	CROSS MEMBER CRACKED LH REAR AIR BAG -Found LHR top plate on airbag leaking. Unbolt air bag & disconnect airlines. Removed air bag, change over fittings to new air bag and installed. Tested operation, no leaks.		Removed cross brace and ground out broken ends. Tack welded into position, heat bar & welded back together. Cleaned weld, refit b	29/05/2024	400004	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	Susp\AIR BAG	Tightened mounting bolts. LEAKING VALVE ON TRAILER - Travelled to Greenfreight yard and inspect trailer for fault. Found			27/05/2024	400004	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	PACCAR PARTS FLEET SERVICES - 3	TRAILER
T626	Myrtleford - Workshop	Brakes\AIR LEAK	brake valve leaking. Removed & reolaced valve. installed new clamos. tested. no further leaks.			23/05/2024	400004	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER
T626	Wodonga - Workshop	Tyres\TP5+6	Tyres\TP5+6			21/05/2024	400004	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	Wodonga Workshop	TRAILER
T626	Myrtleford - Workshop	Tyres\TP7+8	Tyres\TP7+8			21/05/2024	400004	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BEAUREPAIRES - 3	TRAILER
T626	Myrtleford - Workshop	Tyres\Punct	Tyres\Punct			17/05/2024	400004	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BEAUREPAIRES - 4	TRAILER
T626	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist			09/05/2024	400004	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	VehService\DS	POKL085798 AFTER HRS BREAKDOWN - DAMAGED BINDER	VehService\DS		09/05/2024	400004	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	Chassis\WINCH/STRP	Brought vehicle into workshop, disconnect air to binder, removed binder & removed rear binder that was not in use. Moved to damaged binder and tensioned bolts. Tested, all working okay.			07/05/2024	400004	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	BARRY MANEY - 3	TRAILER
T626	Myrtleford - Workshop	Brakes\EBS FAULTS	check and engineer EBS			26/04/2024	400004	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	JU DESIGN - 4	TRAILER
T626	Myrtleford - Workshop	Brakes\EBS Kit	EBS Install Kit			27/02/2024	400004	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	Albury Workshop	TRAILER
T626	Myrtleford - Workshop	Brakes\SLACK ADJ	Slack Adjusters			27/02/2024	400004	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	Albury Workshop	TRAILER
T626	Myrtleford - Workshop	Body\PANELS	STRAIGHTEN & FIT BOLTS TO FRONT COVER PLATE			10/02/2024	14064	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	Myrtleford Workshop	TRAILER
T626	Myrtleford - Workshop	Elect\TRL LIGHTS	REWIRE 4TH BOLSTER FOR TRAILER LIGHTS			10/02/2024	14064	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	Myrtleford Workshop	TRAILER
T626	Myrtleford - Workshop	Chassis\KING PIN	REPLACE KING PIN & BOLTS			08/02/2024	14064	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	Myrtleford Workshop	TRAILER
T626	Myrtleford - Workshop	Chassis\TRL LEGS	REPAIR LANDING LEADS & REPAIR LANDING LEG FEET TO STOP THEM HITTING THE REAR TAIL LIGHT BAR OF THE A TRAILER			08/02/2024	14064	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	Myrtleford Workshop	TRAILER
T626	Myrtleford - Workshop	Chassis\WINCH/STRP	REPAIR AIR WINCH AIR LEAKS & CHECK OPERATION OF AIR WINCHES & ADJUST AIR SUPPLY PRESSURE			08/02/2024	14064	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	Myrtleford Workshop	TRAILER
T626	Myrtleford - Workshop	Body\AIR FITTIN	REPLACE SCALE AND AIR REGEGULATOR BREATHERS			08/02/2024	14064	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	Myrtleford Workshop	TRAILER
T626	Myrtleford - Workshop	Body\AIR LEAK	REPLACE TRAILER COUPLING AIR FITTINGS			08/02/2024	14064	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	Myrtleford Workshop	TRAILER
T626	Myrtleford - Workshop	Body\MUDGUARDS	FIT 2 X EXTRA FRONT M/FLAPS			08/02/2024	14064	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	Myrtleford Workshop	TRAILER
T626	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			07/02/2024	14064	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	Myrtleford Workshop	TRAILER
T626	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		07/02/2024	14064	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	Myrtleford Workshop	TRAILER
T626	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP		07/02/2024		PreventativeMaintenance	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	Myrtleford Workshop	TRAILER
T626	Myrtleford - Workshop	Tyres	R.R tyre need replace			07/02/2024	14064	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	Myrtleford Workshop	TRAILER
T626	Myrtleford - Workshop	Chassis\TRL LEGS	legs handle has bend need replace			07/02/2024	14064	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	Myrtleford Workshop	TRAILER
T626	Myrtleford - Workshop	Elect\WORK LIGHT	Work lights at number plate not working.			07/02/2024	14064	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	Myrtleford Workshop	TRAILER
T626	Myrtleford - Workshop	Chassis\MUDGUARDS	Left front guard needs repairing.			07/02/2024	14064	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	Myrtleford Workshop	TRAILER
T626	Myrtleford - Workshop	Chassis\STRAPS	2ND LAST QUICK RELEASE NEEDS LOOP SHORTENED- WONT RELEASE.			07/02/2024	14064	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	Myrtleford Workshop	TRAILER
T626	Myrtleford - Workshop	Chassis\BOLSTER	Rebuild bolster cylinder, machine new rod and square rod eye.			06/12/2023		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	Albury Workshop	TRAILER
T626	Myrtleford - Workshop	Brakes\BRK O/HAUL	REMOVE ALL WHEELS INSPECT AND REPACE ALL WHEEL BEARINGS & ADJUST CRACK TEST AXLES STUBS (OK) REPLACE RHM SPRING EYE BUSH BOLT AND SIDE PLATES REPLACE RHM U BOLT PLATE			19/09/2023	34065	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	Myrtleford Workshop	TRAILER
T626	Myrtleford - Workshop	Susp\SUSPENSION	REPLACE LHR SPRING WRAPPER		REPAIRS TO SUSPENSION & REPAIR AIR LEAKS	19/09/2023	34065	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	Myrtleford Workshop	TRAILER
T626	Myrtleford - Workshop	Chassis\TRL LEGS	REPAIR TRAILER LANDING LEGS			19/09/2023	34065	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	Myrtleford Workshop	TRAILER
T626	Myrtleford - Workshop	Chassis\CROSS MBR	REPAIR ALL CROSS MEMBER CRACKS & LOOSE BOLTS			19/09/2023	34065	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	Myrtleford Workshop	TRAILER
T626	Myrtleford - Workshop	Susp\SHOCK ABS	REPLACE ALL 6 SHOCKERS & STRAPS			19/09/2023	34065	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	Myrtleford Workshop	TRAILER
T626	Myrtleford - Workshop	Body\MUDGUARDS	REPLACE ALL 6 M/GUARDS AND TIDY UP M/FLAPS & MOUNTS			19/09/2023	34065	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	Myrtleford Workshop	TRAILER
T626	Myrtleford - Workshop	Chassis\BOLSTER	CRACK TEST ALL BOLSTER PEGS			19/09/2023	34065	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	Myrtleford Workshop	TRAILER
T626	Myrtleford - Workshop	Chassis\WINCH/STRP	REPLACE ALL WINCH STRAPS CHECK OPERATION OF ALL AIR WINCHES PAINT ALL BOLSTERSER & PEGS			19/09/2023	34065	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	Myrtleford Workshop	TRAILER
T626	Myrtleford - Workshop	Body\PAINT/REST	WASH AND CLEAN TRAILERS Bolsters Move required bolsters to new position. Fit winches to corresponding positions. Wire in lights & plumb in hoses for winches. Remove worn pegs from bolsters.			19/09/2023	34065	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	Myrtleford Workshop	TRAILER
T626	Albury - Workshop	Chassis\BOLSTER				06/09/2023		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	Albury Workshop	TRAILER
T626	Albury - Workshop	Chassis\WINCH/STRP	Winches & Straps			22/08/2023		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	Albury Workshop	TRAILER
T626	Wodonga - Workshop	Body\BOLSTER	Turn two bent bolster pegs			21/12/2021	148901	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	Wodonga Workshop	TRAILER
T626	Wodonga - Workshop	Body\STRAPS	Replace quick release cable for 2nd last winch strap			21/11/2021	148901	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	Wodonga Workshop	TRAILER
T626	Myrtleford - Workshop	Chassis\BOLSTER	move bolsters and winches to suit 3.7 logs Scales need fixing Inspect scales not working. Check wiring to display, wiring ok. Called Elpinstone for some diagnostic info. Diagnosed B-trailer control box to be faulty. Removed and replaced with a unit supplied by Greenfreight. Test and works correctly.. Scales need fixine		Check scales not working. Found the communication box on the A-Trailer was faulty. Tried putting new scales communication box in to test. Found all boxes Greenfreight has as spare did not work. Cant fix at the moment, need a working unit to fit to trailer for scales to work. Return to workshop. GF will organise new unit. B-Trailer also needed bridalmeboat made up.	19/10/2021	544548	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	Myrtleford Workshop	TRAILER
T626	Albury - Workshop	Susp\WGHT GAUGE				15/10/2021		Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	Albury Workshop	TRAILER
T626	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist			05/10/2021		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	Wodonga Workshop	TRAILER
T626	Wodonga - Workshop	VehService\DS	Service not reauired as Trailers have sat idle since last service.	VehService\DS		05/10/2021		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	Wodonga Workshop	TRAILER
T626	Wodonga - Workshop	Susp\WGHT GAUGE	Mount "Right Weigh" Box + Plumb up housing.			30/09/2021		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	Wodonga Workshop	TRAILER
T626	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			30/06/2021	644810	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	Wodonga Workshop	TRAILER
T626	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		30/06/2021	644810	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	Wodonga Workshop	TRAILER
T626	Wodonga - Workshop	Chassis\SKID PLATE	Removed block.			30/06/2021	644810	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	Wodonga Workshop	TRAILER
T626	Wodonga - Workshop	Elect\TRL LIGHTS	RH rear marker light broken.		Completed.	30/06/2021	644810	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	Wodonga Workshop	TRAILER
T626	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			20/09/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	Wodonga Workshop	TRAILER
T626	Wodonga - Workshop	Chassis\TRL LEGS	landing legs no good and handle bent		inspected all is good working	20/09/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	Wodonga Workshop	TRAILER
T626	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		20/09/2020		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	Wodonga Workshop	TRAILER
T626	Wodonga - Workshop	Tyres	R.R tyre need replace			20/09/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	Wodonga Workshop	TRAILER
T626	Wodonga - Workshop	Chassis\TRL LEGS	legs handle has bend need replace			20/09/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	Wodonga Workshop	TRAILER
T626	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			27/08/2020	26535	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	Wodonga Workshop	TRAILER
T626	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		27/08/2020	26535	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	Wodonga Workshop	TRAILER
T626	Wodonga - Workshop	Chassis\TRL LEGS	landing legs no good and handle bent			27/08/2020	26535	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	Wodonga Workshop	TRAILER
T626	Wodonga - Workshop	Chassis\BOLSTER	left rear bolster out pass guard		awaiting WO	13/08/2020		Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier STK	79114S	Wodonga Workshop	TRAILER

T626	Wodonga - Workshop	Chassis\WINCH/STRP	last 3 winches air operation not working - had to use winch handle to tighten straps		RR's pre Jan 20 (system clean out) 05/08/20	06/08/2020		Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Wodonga Workshop	TRAILER
T626	Wodonga - Workshop	Chassis\WINCH/STRP	air winches not working			06/08/2020		Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Wodonga Workshop	TRAILER
T626	Wodonga - Workshop	Chassis\WINCH/STRP	number 1 3 & 4 air winches not working			06/08/2020		Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Wodonga Workshop	TRAILER
T626	Wodonga - Workshop	Chassis\WINCH/STRP	properly number 3 air winch broken			06/08/2020		Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Wodonga Workshop	TRAILER
T626	Wodonga - Workshop	Chassis\WINCH/STRP	air winches not working properly (middle bay)			06/08/2020		Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Wodonga Workshop	TRAILER
T626	Wodonga - Workshop	Chassis\CROSS MBR	Rewold paint and reinstall bracket			26/07/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Wodonga Workshop	TRAILER
T626	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			26/07/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Wodonga Workshop	TRAILER
T626	Wodonga - Workshop	Chassis\AIR LEAK	air leak		Previously completed	26/07/2020		Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Wodonga Workshop	TRAILER
T626	Wodonga - Workshop	Chassis\AIR LEAK	leaks air		Previously completed	26/07/2020		Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Wodonga Workshop	TRAILER
T626	Wodonga - Workshop	Chassis\AIR FITTIN	90° air fitting hose is out		Previously completed	26/07/2020		Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Wodonga Workshop	TRAILER
T626	Wodonga - Workshop	Chassis\AIR LEAK	air leak		Previously completed	26/07/2020		Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Wodonga Workshop	TRAILER
T626	Wodonga - Workshop	Elect\WORK LIGHT	fit work lights		Fitted to T625	26/07/2020		Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Wodonga Workshop	TRAILER
T626	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		26/07/2020		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Wodonga Workshop	TRAILER
T626	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice			18/07/2020	15061	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Albury Workshop	TRAILER
T626	Albury - Workshop	Tyres\CLEANSKIN	Job Added From Invoice			18/07/2020	15061	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Albury Workshop	TRAILER
T626	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			16/07/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Wodonga Workshop	TRAILER
T626	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		16/07/2020		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Wodonga Workshop	TRAILER
T626	Wodonga - Workshop	Chassis\TRL LEGS	landing legs no good and handle bent			16/07/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Wodonga Workshop	TRAILER
T626	Wodonga - Workshop	Workshop\MOVE ASSET	went to blue metal to check trailers and returned to depot for parts and went and fitted then, got driver to return to yard to tension u bolts and check			05/06/2020	987707	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Wodonga Workshop	TRAILER
T626	Wodonga - Workshop	Chassis\AIR LEAK	air pressure issue, fault find			28/05/2020	979519	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Wodonga Workshop	TRAILER
T626	Wodonga - Workshop	Workshop\MOVE ASSET	move trailers			28/05/2020	979519	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Wodonga Workshop	TRAILER
T626	Wodonga - Workshop	Susp\WGHT GAUGE	inspect weight guageand truck for set		operate forklift to test weight guage	28/05/2020	979519	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Wodonga Workshop	TRAILER
T626	Albury - Workshop	Susp\WGHT GAUGE	FIT WEIGHT GUAGE ORDER PARTS			14/05/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Wodonga Workshop	TRAILER
T626	Albury - Workshop	Susp\WGHT GAUGE	fitted scales			12/05/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Albury Workshop	TRAILER
T626	Albury - Workshop	Elect\TRL LIGHTS	PO FO SIDE MARKER			07/05/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Albury Workshop	TRAILER
T626	Albury - Workshop	Chassis\BOLSTER	moved bolsters			01/05/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Albury Workshop	TRAILER
T626	Albury - Workshop	Chassis\WINCH/STRP	moved winches			01/05/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Albury Workshop	TRAILER
T626	Albury - Workshop	Chassis\BOLSTER	removed bolster		truck that bought 4 back from melbourne	29/04/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Albury Workshop	TRAILER
T626	Albury - Workshop	Chassis\STRAPS	winch hand ratchet assy			25/04/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Wodonga Workshop	TRAILER
T626	Albury - Workshop	Chassis\BOLSTER	repaired bolster mounts			25/04/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Albury Workshop	TRAILER
T626	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			25/04/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Albury Workshop	TRAILER
T626	Albury - Workshop	VehService\DS	D Service	VehService\DS		25/04/2020		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Albury Workshop	TRAILER
T626	Wodonga - Workshop	Workshop\CLEAN	went with greg to get measurement of the pole in the trailermove forward & back			17/04/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Wodonga Workshop	TRAILER
T626	Wodonga - Workshop	Workshop\MOVE ASSET	grab 915 hooked up etc			17/04/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Wodonga Workshop	TRAILER
T626	Wodonga - Workshop	Body\ELECT P&W	remove block from skid plate		remove the base plug and wirig and replace4d with new plug &	16/04/2020	949847	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Wodonga Workshop	TRAILER
T626	Wodonga - Workshop	Workshop\MOVE ASSET	load bolsters & components onto a pallet ,to go to twin city trucks		wiring ix etc and check with primemover all the lights and airbag	06/04/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Wodonga Workshop	TRAILER
T626	Wodonga - Workshop	Chassis\BOLSTER	remove 3& 4 bolster & components			04/04/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Wodonga Workshop	TRAILER
T626	Albury - Workshop	Brakes	TEST RESULTS			11/12/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Albury Workshop	TRAILER
T626	Albury - Workshop	Susp\SUSPENSION	TIGHTENED UHM & RHR SEBOLTS			11/12/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Albury Workshop	TRAILER
T626	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS		11/12/2019		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Albury Workshop	TRAILER
T626	Wodonga - Workshop	Brakes				05/12/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Wodonga Workshop	TRAILER
T626	Wodonga - Workshop	VehService\DS	D Service	VehService\DS		05/12/2019		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Wodonga Workshop	TRAILER
T626	Albury - Workshop	Brakes\BOOSTER	REPAIRED AIR LEAK AT LHF B/BOOSTER			13/11/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Albury Workshop	TRAILER
T626	Albury - Workshop	Susp\HCV	REPAIRED BROCKEN AIR HOSE (SUPPLY) TO HCV			13/11/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Albury Workshop	TRAILER
T626	Albury - Workshop	Brakes				05/11/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Albury Workshop	TRAILER
T626	Albury - Workshop	Susp\SUSPENSION	REPLACED REAR X- BAR BUSHES			05/11/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Albury Workshop	TRAILER
T626	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS		05/11/2019		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Albury Workshop	TRAILER
T626	Albury - Workshop	Brakes			REFIT	25/10/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Albury Workshop	TRAILER
T626	Albury - Workshop	Chassis\CHAS CRACK	REMOVE X-MEMBER & WELD UP			25/10/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Albury Workshop	TRAILER
T626	Albury - Workshop	VehService\DS	d sarcive	VehService\DS		25/10/2019		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Albury Workshop	TRAILER
T626	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS		19/10/2019		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Albury Workshop	TRAILER
T626	Albury - Workshop	Brakes				19/10/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Albury Workshop	TRAILER
T626	Albury - Workshop	Chassis\BOLSTER	STRAIGHTENED 3RD & 5TH BOLSTERS			19/10/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Albury Workshop	TRAILER
T626	Wodonga - Workshop	Chassis\WINCH/STRP	Rebuilt air winches			24/08/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Wodonga Workshop	TRAILER
T626	Albury - Workshop	Chassis\WINCH/STRP	tested winches			20/08/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Albury Workshop	TRAILER
T626	Albury - Workshop	Chassis\WINCH/STRP	replaced air line and fitting on 4th winch			20/08/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Albury Workshop	TRAILER
T626	Albury - Workshop	Chassis\WINCH/STRP	repaired tap on 5th winch			20/08/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Albury Workshop	TRAILER
T626	Albury - Workshop	Chassis\WINCH/STRP	straightened spindle on 1st winch			20/08/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Albury Workshop	TRAILER
T626	Albury - Workshop	Chassis\WINCH/STRP	diagnosed and ordered cylinder for 2nd winch			20/08/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Albury Workshop	TRAILER
T626	Albury - Workshop	Chassis\WINCH/STRP	check winches some are faulty			20/08/2019		Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Albury Workshop	TRAILER
T626	Wodonga - Workshop	Brakes\BRK RELINE	Reline			14/08/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Wodonga Workshop	TRAILER
T626	Wodonga - Workshop	Brakes	Brake test results attached			26/07/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Wodonga Workshop	TRAILER
T626	Wodonga - Workshop	VehService\DS	D Service	VehService\DS		26/07/2019		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Wodonga Workshop	TRAILER
T626	Albury - Workshop	Chassis\BOLSTER	replaced 1st, 2nd, 3rd and last bolster peg bolts			10/07/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Albury Workshop	TRAILER
T626	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			10/07/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Albury Workshop	TRAILER
T626	Albury - Workshop	VehService\DS	D Service	VehService\DS		10/07/2019		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Albury Workshop	TRAILER
T626	Wodonga - Workshop	Body\BOLSTER	Make mounts & fit extra bolsters			03/07/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Wodonga Workshop	TRAILER
T626	Wodonga - Workshop	Chassis\WINCH/STRP	Fit up winches & quick release cables			02/07/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Wodonga Workshop	TRAILER
T626	Wodonga - Workshop	Chassis\BOLSTER	Fit bolsters			02/07/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Wodonga Workshop	TRAILER
T626	Wodonga - Workshop	Body\AIR FITTIN	Replaced constant air couplings & bulkhead		Hooked up to T625	02/07/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Wodonga Workshop	TRAILER
T626	Wodonga - Workshop	Chassis\WINCH/STRP	Winches & Straps			02/07/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Wodonga Workshop	TRAILER
T626	Albury - Workshop	Chassis\BOLSTER	reposition bolster to fit 3x 2.8mt bays			19/06/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Albury Workshop	TRAILER
T626	Albury - Workshop	Chassis\WINCH/STRP	fit extra winch mount			19/06/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Albury Workshop	TRAILER
T626	Albury - Workshop	Chassis\BOLSTER	turn clamps for bolsters to fit			19/06/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Albury Workshop	TRAILER
T626	Albury - Workshop	Chassis\BOLSTER	fit extension to 4th bolster			19/06/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Albury Workshop	TRAILER
T626	Albury - Workshop	Chassis\BOLSTER	set up wire new bolster			19/06/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Albury Workshop	TRAILER
T626	Wodonga - Workshop	Chassis\HOUSEKEEP	Tightened L/H/F & L/H/R U-bolts			18/06/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Wodonga Workshop	TRAILER
T626	Wodonga - Workshop	Chassis\CROSS MBR	Replaced rear cross member bolts			18/06/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Wodonga Workshop	TRAILER
T626	Wodonga - Workshop	VehService\DS	D service	VehService\DS		18/06/2019		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Wodonga Workshop	TRAILER
T626	Myrtleford - Workshop	Chassis\BOLSTER	prepare bolsters for trailers in Albury			13/06/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Myrtleford Workshop	TRAILER
T626	Albury - Workshop	Chassis\BOLSTER	measure up bolsters positions			13/06/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Albury Workshop	TRAILER
T626	Albury - Workshop	Chassis\WINCH/STRP	make winch mounts			13/06/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Albury Workshop	TRAILER
T626	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			06/06/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Albury Workshop	TRAILER
T626	Albury - Workshop	VehService\DS	D Service	VehService\DS		06/06/2019		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Albury Workshop	TRAILER
T626	Albury - Workshop	Body\MUDGUARDS	removed and replaced damaged guard and mounting bracket			03/06/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Albury Workshop	TRAILER
T626	Myrtleford - Workshop	Chassis\CROSS MBR	Repair LH & RH X Member Gusset Cracks		refer to 111879	25/05/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Myrtleford Workshop	TRAILER
T626	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			24/05/2019	862098	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Myrtleford Workshop	TRAILER
T626	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	replace LHR s/eye bush	24/05/2019	862098	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Myrtleford Workshop	TRAILER
T626	Myrtleford - Workshop	Body\HOUSEKEEP	check over trailer			23/05/2019	861311	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Myrtleford Workshop	TRAILER
T626	Myrtleford - Workshop	Body\PAINT/REST	acid wash all wheels			23/05/2019	861311	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Myrtleford Workshop	TRAILER
T626	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			15/05/2019	859072	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Myrtleford Workshop	TRAILER
T626	Myrtleford - Workshop	Body\HOUSEKEEP	Remove Rear Rack Guard			15/05/2019	859072	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Myrtleford Workshop	TRAILER
T626	Myrtleford - Workshop	Insp\UNT INSP	Fit Trailer Stickers			15/05/2019	859072	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Myrtleford Workshop	TRAILER
T626	Myrtleford - Workshop	Chassis\BOLSTER	Remove Bolster Rivets			15/05/2019	859072	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Myrtleford Workshop	TRAILER
T626	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		15/05/2019	859072	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Myrtleford Workshop	TRAILER
T626	Myrtleford - Workshop	Chassis\WINCH/STRP	repair winch strap quick release cables			11/05/2019	859072	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Myrtleford Workshop	TRAILER
T626	Myrtleford - Workshop	Insp\RWC COMP	Re- issue of RWC			09/05/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	79114S	Myrtleford Workshop	TRAILER