



A & T Tire Ltd.

P.O. Box 1620
Moosomin, SK S0G 3N0
P: (306) 435-2220
F: (306) 434-4914

name: _____

Phone #: _____

Vehicle Year: 2008

Model: Sierra 1500 5.3 Fuel

Odometer Reading: _____

Date: Oct 5, 2006

Make: GMC

Vin #: 2G1TIE1K113181811161041218

Job Description(s):

Job 1: Fuel Active Management System

4

1.764

3.278

Miss Fire

Job 2: _____

Job 3: _____

NOTES: Slight miss fire occasionally
on cylinder 3. does not burn oil.
miss fire causes service engine light
to come on placing it into Limp mode
Does not happen often. Motor has
had previous engine work.

Parts Total: \$ _____

Labor Total: \$ _____

Sub-Total: \$ _____

GST: \$ _____

PST: \$ _____

TOTAL: \$

MORE THAN JUST A TIRE STORE