EquipmentName	Workshop	CodeAndSubCode	Description	CompletionComments	DateDone	DistanceDone	Worktype	Workstate	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
			B Service											
723	Wodonga - Workshop	VehService\BS	Serviced @ 478,206 Klms		08/09/2026	471061	Service	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER
723	Wodonga - Workshop	Air Con\AIR CON	Air/Con not working, blowing Hot air.		15/08/2026	471061	Fault	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER
723	Wodonga - Workshop	Brakes\BRK RELINE	Replace Steer & Both Drive Brake Pads		15/08/2026	471061	Repair	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER
723	Wodonga - Workshop	Brakes\BRK RELINE	REPLACE BRAKE PADS		15/08/2026	471061	Repair	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER
723	Wodonga - Workshop	Body\ELECT P&W	Indicator/clearance light on L/H side Not working.		15/08/2026	471061	Fault	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER
723	Wodonga - Workshop	Body\ELECT P&W	R/H Taillight assembly is broken.		15/08/2026	471061	Fault	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER
723	Wodonga - Workshop	VServLab	over due for c service		15/08/2026	471061	Fault	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER
			B Service											
723	Wodonga - Workshop	VehService\BS	Serviced @ 534,815 Klms		15/08/2026	471061	Service	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER
			C Service											
723	Wodonga - Workshop	VehService\CS	Serviced @ 534,815 Klms		15/08/2026	471061	Service	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER
723	Wodonga - Workshop	Body\FUEL TANK	Ad -Blu tank strap has shifted.		15/08/2026	471061	Fault	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER
723	Wodonga - Workshop	Elect\RWC COMP	Air horn doesn'twork		15/08/2026	471061	Fault	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER
			Insp\ANN INSP Annual Inspection As Per Checklist											
723	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection Done @ 534,815 Klms	Annual Inspection Completed By Shaun	15/08/2026	471061	PreventativeMaintenance	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER
723	Wodonga - Workshop	Elect\ELECT P&W	Taillight RH needs replacing		15/08/2026	471061	Fault	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER
723	Wodonga - Workshop	DriCabRep\ELECT P&W	Air Horn not working.		15/08/2026	471061	Fault	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER
723	Wodonga - Workshop	Tyres\Punct	Tyres\Punct POS 8		11/07/2026	471061	Repair	Completed	DAFHWY	Wodonga	LHS	XW63CD	BORDER BANDAG PTY LTD	P/MOVER
723	Wodonga - Workshop	Tyres\TP1+2	Tyres\TP1+2		09/03/2026	461266	Repair	Completed	DAFHWY	Wodonga	LHS	XW63CD	BORDER BANDAG PTY LTD	P/MOVER
723	Wodonga - Workshop	Air Con\AIR CON	A/C Sound's like Fan is working very Hard and not much Air coming Out.		12/02/2026	449581	Fault	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER
723	Wodonga - Workshop	DrivLine\GEARBOX	Transmission Fault Warning.	Fault not present	12/02/2026	449581	Fault	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER
723	Wodonga - Workshop	Engine\EXHAUST	Exhaust Warning. Truck Sensors Repair To Manifold, Brakes, ABS/EBS, Stability Control, Marker Light Exhaust System, Adaptive Cruise, Engine Malfunction, EBS Malfunction, All Shown Warnings, Must Started About 60 Klms Before Pulling Back To Yard	Fault not present	12/02/2026	449581	Fault	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER
723	Wodonga - Workshop	DrCabElect\UNST/GAUGE		Inspected old job	12/02/2026	449581	Fault	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER
723	Wodonga - Workshop	VehService\AS	VehService\AS A Service		12/02/2026	449581	Service	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER
723	Wodonga - Workshop	Engine\EXHAUST	EXHAUST SYS MALFUNCTION LIGHT WARNING CAME ON	Fault not present	12/02/2026	449581	Fault	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER
723	Wodonga - Workshop	Tyres\TP5+6	Tyres\TP5+6		08/01/2026	436538	Repair	Completed	DAFHWY	Wodonga	LHS	XW63CD	BORDER BANDAG PTY LTD	P/MOVER
723	Wodonga - Workshop	Tyres\TP7+8	Tyres\TP7+8		08/01/2026	436538	Repair	Completed	DAFHWY	Wodonga	LHS	XW63CD	BORDER BANDAG PTY LTD	P/MOVER
723	Wodonga - Workshop	Cooling\RADIATOR	Running way to Hot [fan is on 95% of the time]		08/01/2026	436523	Fault	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER
723	Wodonga - Workshop	Cooling\RADIATOR	Truck running Hot [Temp Guage in the RED] Thermo fan running non stop.		08/01/2026	436523	Fault	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER
723	Wodonga - Workshop	Elect\HOUSEKEEP	MARKER LIGHT LH SIDE NOT WORKING	Fuse blown, didn't blow when replaced	08/01/2026	436523	Fault	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER
723	Wodonga - Workshop	Susp\AIR LEAK	Air Leaks		08/01/2026	436523	Fault	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER
723	Wodonga - Workshop	Elect\DRV LIGHT	DRIVING LIGHT NOT WORKING		08/01/2026	436523	Fault	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER
723	Wodonga - Workshop	Elect\INDICATORS	RH indicator on bull bar not working		08/01/2026	436523	Fault	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER
723	Wodonga - Workshop	Body\FUEL TANK	L/H REAR FUEL STRAP HAS BROKEN AGAIN.	REPLACED	27/11/2025	421598	Fault	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER
723	Wodonga - Workshop	Elect\DRV LIGHT	Light bar needs to be remounted under bull bar hoop as interfering hatch for Coolant resivor and oil filler tube	OK	27/11/2025	421598	Fault	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER
723	Wodonga - Workshop	VehService\BS	VehService\BS B Service Truck Won't Start.	* Sourced parts, loaded van & travelled to truck located in Wangaratta * Test operations & confirmed truck not starting but starter motor clicking * Removed battery box cover * Test batteries & confirmed both batteries failed * Disconnected batteries * Removed & replaced batteries * Refit battery mounts & re-connected all components * Refit battery box cover * Started truck & programmed batteries as required * Cleared all codes * Test operations - All ok, fault no longer present * Packed up tools & travelled back to TCTC workshop	27/11/2025	421598	Service	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER
723	Wodonga - Workshop	Elect\BATTERY	(TCTC P/O: WW097207		30/09/2025	443106	Repair	Completed	DAFHWY	Wodonga	LHS	XW63CD	TWIN CITY TRUCK CENTRE - OLD	P/MOVER
723	Wodonga - Workshop	Tyres\Punct	Tyres\Puncture POS 5		26/09/2025	392339	Repair	Completed	DAFHWY	Wodonga	LHS	XW63CD	BORDER BANDAG PTY LTD	P/MOVER
723	Wodonga - Workshop	Tyres\TP11+12	Tyres\TP11+12		06/09/2025	383144	Repair	Completed	DAFHWY	Wodonga	LHS	XW63CD	BORDER BANDAG PTY LTD	P/MOVER
			Elect\ELECT P&W LIGHTS FOG LIGHT WARNING ON DASH . * Inspected & confirmed fault * Found globe to be blown * Removed & replaced globe as required											
723	Wodonga - Workshop	Elect\ELECT P&W	* Test operations - All ok, fault no longer presen		24/07/2025	358196	Repair	Completed	DAFHWY	Wodonga	LHS	XW63CD	TWIN CITY TRUCK CENTRE - OLD	P/MOVER
723	Wodonga - Workshop	Engine\FAULT CODE	EXHAUST MALFUNCTION KEEP SHOWING UP ENGINE MALFUNCTION WARNING KEEP SHOWING UP (TCTC PO WW095838) WARNING LIGHT CUSTOMER REPORTS EXHAUST MALFUNCTION & ENGINE LIGHT ON DASH. DRIVER ALSO REPORTED TRUCK SEEMS TO BE USING EXCESSIVE ADBLUE . * Inspected & confirmed fault * Connected laptop & scanned for faults * Found codes present for DPF * Ballast truck & removed drivers side steer tyre for access * Disassembled & removed DPF element * Inspected & confirmed element to be blocked * Cleaned down all components * Installed replacement DPF element * Refit all removed components * Carried out forced regen		24/07/2025	358196	Fault	Completed	DAFHWY	Wodonga	LHS	XW63CD	TWIN CITY TRUCK CENTRE - OLD	P/MOVER
723	Wodonga - Workshop	Engine\FAULT CODE	* Test operations - All ok, fault no longer present		24/07/2025	358196	Fault	Completed	DAFHWY	Wodonga	LHS	XW63CD	TWIN CITY TRUCK CENTRE - OLD	P/MOVER
723	Wodonga - Workshop	Engine\ADBLUE	USING WAY TOO MUCH ADBLU USED 32LTR TO DO 780KMS		24/07/2025	358196	Fault	Completed	DAFHWY	Wodonga	LHS	XW63CD	TWIN CITY TRUCK CENTRE - OLD	P/MOVER
723	Wodonga - Workshop	Elect\TRL LIGHTS	TRAILER PLUG NEED REPLACING.		11/07/2025	353238	Fault	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER
			Brakes\BRK RELINE REPORTS DRIVE BRAKES ARE GETTING LOW . * Inspected drive brakes & confirmed fault * Ballast axles & removed wheel end equipment * Removed all components as required * Cleaned down all components * Installed replacement brake pads & wear indicators as required * Refit all removed components * Aligned, adjusted & tensioned all to specifications											
723	Wodonga - Workshop	Brakes\BRK RELINE	* Test operations - All ok, fault no longer present		08/07/2025	351031	Repair	Completed	DAFHWY	Wodonga	LHS	XW63CD	PACCAR PARTS FLEET SERVICES	P/MOVER
723	Wodonga - Workshop	DrivLine\TAIL SHAFT	CHECKED DRIVE SHAFT BOLTS.		03/07/2025	348370	Repair	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER
723	Wodonga - Workshop	Workshop\MOVE ASSET	DROP OFF/ PICK UP TCTC.		02/07/2025	348045	Repair	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER
723	Wodonga - Workshop	Tyres\TP1+2	Tyres\TP1+2		24/06/2025	346762	Repair	Completed	DAFHWY	Wodonga	LHS	XW63CD	BORDER BANDAG PTY LTD	P/MOVER
723	Wodonga - Workshop	Tyres\TP9+10	Tyres\TP9+10 C Service.		24/06/2025	346762	Repair	Completed	DAFHWY	Wodonga	LHS	XW63CD	BORDER BANDAG PTY LTD	P/MOVER
723	Wodonga - Workshop	VehService\CS	(TCTC P/O: WW095048)		19/06/2025	345978	Service	Completed	DAFHWY	Wodonga	LHS	XW63CD	TWIN CITY TRUCK CENTRE - OLD	P/MOVER
723	Wodonga - Workshop	Brakes\AIR LEAK	Air dryer exhaust contaminated with oil	Replaced filter and cleaned	19/06/2025	345978	Fault	Completed	DAFHWY	Wodonga	LHS	XW63CD	TWIN CITY TRUCK CENTRE - OLD	P/MOVER
723	Wodonga - Workshop	DriCabRep\AIR LEAK	AIR HORN DOESN'T WORK.	No fault found	19/06/2025	345978	Fault	Completed	DAFHWY	Wodonga	LHS	XW63CD	TWIN CITY TRUCK CENTRE - OLD	P/MOVER
723	Wodonga - Workshop	Body\WINDSCREEN	WARNING DEVICE ON WINDSCREEN NEED REPLACING.	Already sorted	19/06/2025	345978	Fault	Completed	DAFHWY	Wodonga	LHS	XW63CD	TWIN CITY TRUCK CENTRE - OLD	P/MOVER
723	Wodonga - Workshop	Brakes\BRK RELINE	Drive brake pads getting low X4	REplaced all 4 x brake sets	19/06/2025	345978	Fault	Completed	DAFHWY	Wodonga	LHS	XW63CD	TWIN CITY TRUCK CENTRE - OLD	P/MOVER
723	Wodonga - Workshop	VehService\AS	VehService\AS A Service		18/06/2025	345768	Service	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER
723	Wodonga - Workshop	VehService\BS	VehService\BS	Booked TCTC 16/5 #WW094158	27/05/2025	329611	Service	Completed	DAFHWY	Wodonga	LHS	XW63CD	PACCAR PARTS FLEET SERVICES	P/MOVER
723	Wodonga - Workshop	Chassis\FIFTH WHEE	Turn table bushes worn	Adjusted turntable	27/05/2025	329611	Fault	Completed	DAFHWY	Wodonga	LHS	XW63CD	PACCAR PARTS FLEET SERVICES	P/MOVER
723	Wodonga - Workshop	Body\FUEL TANK	FUEL TANK STRAP BROKEN.	REMOVED TANK. REPLACED "J" BRACKET AND BRACE. STRAIGHTENED BRACKET. FIT W	11/04/2025	318781	Fault	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER
723	Wodonga - Workshop	VehService\AS	VehService\AS A Service		09/04/2025	318781	Service	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER
723	Wodonga - Workshop	DriCabRep\DOOR LOCK	Central locking is playing up,keypad doesn't work and key is a bit dickie. A Service.		09/04/2025	318781	Fault	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER
723	Wodonga - Workshop	VehService\AS	Serviced @ 309,540 Klms		21/03/2025	309540	Service	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER
723	Wodonga - Workshop	Elect\TRL LIGHTS	MAKE ELECTRICAL ADAPTOR.		19/03/2025	308431	Repair	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER
723	Wodonga - Workshop	Body\FUEL TANK	L/H SIDE FUEL TANK STRAP NEED REPLACING. (BROKEN)		17/03/2025	306966	Fault	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER

			truck Lost Drive & All Warning Lights ON Dash. Paccar Would Only Cover $450 Of Tow.													
723	Wodonga - Workshop	Elect\BREAKDOWN	(TCTC P/O: WW095269)		12/03/2025	304530	Repair	Completed	DAFHWY	Wodonga	LHS	XW63CD	PACCAR PARTS FLEET SERVICES	P/MOVER		
723	Wodonga - Workshop	Insp\ANN INSP	Insp\ANN INSP		25/02/2025	298401	PreventativeMaintenance	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER		
723	Wodonga - Workshop	VehService\AS	VehService\AS	Front spring Bush's both left and right are worn needs replacing Front bull bar mount t	25/02/2025	298401	Service	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER		
723	Wodonga - Workshop	VehService\BS	VehService\BS	COMPLETED AT TCTC.	29/01/2025	283994	Service	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER		
723	Wodonga - Workshop	Body\LIGHTS	Front right light and housing badly damaged	PREVIOUSLY COMPLETED.	30/10/2024	243679	Fault	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER		
723	Wodonga - Workshop	Body\LIGHTS	No Indicator R/H Front	PREVIOUSLY COMPLETED.	30/10/2024	243679	Fault	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER		
723	Wodonga - Workshop	Elect\INDICATORS	Need A New R/H Light Assembly has No Indicator on R/H Side Front.	PREVIOUSLY COMPLETED.	30/10/2024	243679	Fault	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER		
723	Wodonga - Workshop	Engine\OIL LEAK	Bad Oil Leak Oil Filler Pipe.	PREVIOUSLY COMPLETED.	30/10/2024	243679	Fault	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER		
723	Wodonga - Workshop	VehService\AS	VehService\AS		30/10/2024	243679	Service	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER		
723	Wodonga - Workshop	Chassis\FUEL TANK	R/H Fuel Tank Has Shifted Back Agaist Guard	PREVIOUSLY COMPLETED.	30/10/2024	243679	Fault	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER		
723	Wodonga - Workshop	Engine\OIL LEAK	Bad Oil Leak (Oil Filler Pipe)	PREVIOUSLY COMPLETED.	30/10/2024	243679	Fault	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER		
723	Wodonga - Workshop	Elect\INDICATORS	No Indicator R/H Front	PREVIOUSLY COMPLETED.	30/10/2024	243679	Fault	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER		
723	Wodonga - Workshop	Tyres\TP1+2	Tyres\TP1+2+3+4+5+6		18/10/2024	238918	Repair	Completed	DAFHWY	Wodonga	LHS	XW63CD	BEAUREPAIRES	P/MOVER		
723	Wodonga - Workshop	Chassis\BREAKDOWN	BREAKDOWN. (NO FURTHER INFORMATION)		17/10/2024	238912	Fault	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER		
				- ATTEND CALLOUT TO ALPINE MDF TO VEHICLE WITH REPORTED ENGINE OIL LEAK, FOUND OIL FILLER TUBE RUBBED THROUGH ON COWLING & LEAKING, RECOMMEND REPLACEMENT OF OIL FILLER TUBE, RETURN TO WORKSHOP.												
723	Wodonga - Workshop	Engine\OIL LEAK	Check For Oil Leak & Repair. (Robinson's Truck & Coach P/O: WW088968)	Cody and Doug on this svc Ruby checked brakes Disk brakes	23/09/2024	229440	Repair	Completed	DAFHWY	Wodonga	LHS	XW63CD	ROBINSONS TRUCK AND COACH MAINTENANCE	P/MOVER		
723	Wodonga - Workshop	VehService\AS	A Service		29/08/2024	219162	Service	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER		
723	Wodonga - Workshop	Tyres\TP09	R/H REAR INNER TYRE FLAT.		10/08/2024	211885	Fault	Completed	DAFHWY	Wodonga	LHS	XW63CD	TWIN CITY TRUCK CENTRE - OLD	P/MOVER		
723	Wodonga - Workshop	Unknown	OVERDUE A SERVICE 10,000 B SERVICE 8,000 C SERVICE 8,000. B Service (TCTC P/O: WW087993)		10/08/2024	211885	Fault	Completed	DAFHWY	Wodonga	LHS	XW63CD	TWIN CITY TRUCK CENTRE - OLD	P/MOVER		
723	Wodonga - Workshop	VehService\BS	Serviced @ 211885 Klms		10/08/2024	211885	Service	Completed	DAFHWY	Wodonga	LHS	XW63CD	TWIN CITY TRUCK CENTRE - OLD	P/MOVER		
723	Wodonga - Workshop	Unknown	DUE FOR "A" SERVICE 121000.		10/08/2024	211885	Fault	Completed	DAFHWY	Wodonga	LHS	XW63CD	TWIN CITY TRUCK CENTRE - OLD	P/MOVER		
723	Wodonga - Workshop	Elect\ELECT P&W	R/H TAIL LIGHT MOUNTING BROKEN.		10/08/2024	211885	Fault	Completed	DAFHWY	Wodonga	LHS	XW63CD	TWIN CITY TRUCK CENTRE - OLD	P/MOVER		
723	Wodonga - Workshop	Unknown	Due For A/B/C/E Service		10/08/2024	211885	Fault	Completed	DAFHWY	Wodonga	LHS	XW63CD	TWIN CITY TRUCK CENTRE - OLD	P/MOVER		
723	Wodonga - Workshop	Engine\OIL LEAK	Repair Oil Leak At Filler Tube (TCTC P/O: WW087024)		27/06/2024	191751	Repair	Completed	DAFHWY	Wodonga	LHS	XW63CD	TWIN CITY TRUCK CENTRE - OLD	P/MOVER		
723	Wodonga - Workshop	Engine\BREAKDOWN	Engine\BREAKDOWN Oil Leak Elite Diesel P/O: WW086821		19/06/2024	189900	Repair	Completed	DAFHWY	Wodonga	LHS	XW63CD	VAWDREY AUSTRALIA PTY LTD	P/MOVER		
723	Wodonga - Workshop	Tyres\TP7+8	Tyres\TP7+8		23/05/2024	174250	Repair	Completed	DAFHWY	Wodonga	LHS	XW63CD	BEAUREPAIRES	P/MOVER		
723	Wodonga - Workshop	Tyres\TP9+10	Tyres\TP9+10		23/05/2024	174250	Repair	Completed	DAFHWY	Wodonga	LHS	XW63CD	BEAUREPAIRES	P/MOVER		
723	Wodonga - Workshop	Body\FUEL TANK	MOVED FUEL TANK FORWARD AS IT WAS RUBBING ON GUARD.		20/04/2024	173292	Repair	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER		
723	Wodonga - Workshop	Unknown	OVERDUR "A" SERVICE (121000)		23/03/2024		Fault	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER		
723	Wodonga - Workshop	VehService\BS	B Service As Per Attached Checklist		07/03/2024	194503	Service	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER		
723	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		07/03/2024	194503	Repair	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER		
723	Wodonga - Workshop	Chassis\AIR LEAK	CHECK AIR LEAKS/ DRAIN AIR TANK. WARNING KEEP COMING UP.		07/03/2024	194503	Fault	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER		
723	Wodonga - Workshop	Elect\TAIL LIGHT	L/H REAR LIGHT ASSEMBLY HAS SNAPPED PLASTIC ASSEMBLY.		07/03/2024	194503	Fault	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER		
723	Wodonga - Workshop	Tyres\Punct	3		07/03/2024		Repair	Completed	DAFHWY	Wodonga	LHS	XW63CD	Albury Workshop	P/MOVER		
723	Wodonga - Workshop	Tyres\Punct	3		05/03/2024		Repair	Completed	DAFHWY	Wodonga	LHS	XW63CD	Albury Workshop	P/MOVER		
723	Wodonga - Workshop	Elect\TAIL LIGHT	R/H REAR LIGHT ASSEMBLY HAS SNAP PLASTIC. ONLY HELD ON BY WIRES.. R/H REAR LIGHT ASSEMLY HAS SNAP PLAS	SECURED RH LIGHT ASSEMBLY.	03/02/2024		Fault	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER		
723	Wodonga - Workshop	Tyres\TP01	Tyre Position 1		03/01/2024	111447	Repair	Completed	DAFHWY	Wodonga	LHS	XW63CD	Albury Workshop	P/MOVER		
723	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		16/12/2023	111447	Repair	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER		
723	Wodonga - Workshop	Chassis\AIR LEAK	CHECK AIR LEAKS/ DRAIN AIR TANK. WARNING KEEP COMING UP.		16/12/2023	111447	Repair	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER		
723	Wodonga - Workshop	VehService\BS	B Service As Per Attached Checklist		16/12/2023	111447	Service	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER		
723	Wodonga - Workshop	Unknown	OVERDUE FOR B SERVICE.		16/12/2023	111447	Fault	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER		
				* Service advisor actioned technician to attend * Travell to customer depot, Wodonga * Connected Davie diagnostics * Active code for air system saturation level 2 evident * Removed/replaced air dryer filter * Calibrate saturation level in ECU * Code wentinactive & warning light out now * Pressurised system & check forany possible air leaks - no failure evdient												
723	Wodonga - Workshop	Engine\AIR CLNR	CUSTOMER ADVISED THAT DASH WARNING FOR AIR LEAKS & DRAIN AIR TANKS EVIDENT, DIAGNOSE & REPORT	* Technician cleared code & returned to dealership	10/11/2023	98372	Repair	Completed	DAFHWY	Wodonga	LHS	XW63CD	Albury Workshop	P/MOVER		
723	Wodonga - Workshop	Tyres\PRES CHECK	1-10		27/09/2023	69603	Repair	Completed	DAFHWY	Wodonga	LHS	XW63CD	Albury Workshop	P/MOVER		
				STEERING & BRAKES * Check steering mechanism and linkages * Check steering oil level * Check steering hoses and connections for leaks												
723	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job	* Check brakes for operation and leaks	19/08/2023	60013	Repair	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER		
723	Wodonga - Workshop	Engine\FAULT CODE	WARNING LIGHTS COMING ON (CHECK FOR AIR LEAK) (DRAIN AIR TANK) AND "YES" CHECKED.	NO FAULT FOUND.	19/08/2023	60013	Fault	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER		
723	Wodonga - Workshop	Body\DAMAGE	NEED LIGHT BAR REPLACED. (STOLEN)	PREVIOUSLY COMPLETED.	19/08/2023	60013	Fault	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER		
723	Wodonga - Workshop	Unknown	OVER DUE FOR 20000 SERVICE. NOW DUE FOR S0000 SERVICE USING 4L OF OIL EVERY 10 DAYS		19/08/2023	60013	Fault	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER		
723	Wodonga - Workshop	Unknown	50TH 20TH SERVICE DUE.	NO FAULT FOUND.	19/08/2023	60013	Fault	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER		
723	Wodonga - Workshop	Unknown	DUE FOR "A" SERVICE (20000)		19/08/2023	60013	Fault	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER		
				CAB & ELECTRICAL * Removed/replaced cabin air filter * Check battery fluid level, terminals and cables * Check vehicle earth connections * Check and top up window washer fluid ENGINE & COOLING * Change engine oil & filter * Check for engine oil leaks * Change fuel filter including fuel water separator * Check for fuel leaks * Check V belts, tensioner, fan and hub * Inspect crankcase breather tube * Check hose connections for leaks * Check radiator and CAC for fouling or damage * Check air compressor mounting and compressor head for carbon build up * Check exhaust system * Check coolant level and concentration & inspect for leaks * Check air intake system for leaks or damage												
723	Wodonga - Workshop	VehService\BS	B Service As Per Attached Checklist DAF SERIES (X) -Service schedule included:	* Check & replace air intake filter if required	19/08/2023	60013	Service	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER		
723	Wodonga - Workshop	Tyres\TP07	puncture repair travel to job test and found brake lights on with tail lights only on trailer callout after hours plug in trailer tester and found all working fine test trailer plug on truck and found power at brake lights with tail remove and check wiring (DAF wiring is all the same culor with wire code) did not have info for wire code travel wiring to cab and found not short to power check and found wire from powering up trailer harness recheck trailer plug and found wired up wrong repair and test found working all ok		30/06/2023		Repair	Completed	DAFHWY	Wodonga	LHS	XW63CD	Albury Workshop	P/MOVER		
723	Wodonga - Workshop	Elect\ELECT P&W	pack up and travel back		16/06/2023		Repair	Completed	DAFHWY	Wodonga	LHS	XW63CD	Albury Workshop	P/MOVER		
723	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job C Service As Per Attached Checklist		26/04/2023	194503	Repair	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER		
723	Wodonga - Workshop	VehService\CS	First Service done by TCTC		26/04/2023	194503	Service	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER		
723	Wodonga - Workshop	VehService\CS	First Service due.		26/04/2023	194503	Service	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER		
723	Wodonga - Workshop	Insp\Truck Pre	Truck pre delivery		31/03/2023	648	Repair	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER		
723	Wodonga - Workshop	DrCabElect	No E-Tag as of yet.		31/03/2023	648	Repair	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER		
723	Wodonga - Workshop	Comp\Truck Safe	No Sticker as of Yet		31/03/2023	648	Repair	Completed	DAFHWY	Wodonga	LHS	XW63CD	Wodonga Workshop	P/MOVER		
723	Wodonga - Workshop	Tyres\TP3+4	Tyre Position 3 + 4		14/01/2023		Repair	Completed	DAFHWY	Wodonga	LHS	XW63CD	Albury Workshop	P/MOVER		
723	Wodonga - Workshop	Tyres\TP1+2	Tyre Position 1 + 2		14/01/2023		Repair	Completed	DAFHWY	Wodonga	LHS	XW63CD	Albury Workshop	P/MOVER		
723	Wodonga - Workshop	Tyres\TP5+6	Tyre Position 5 + 6		14/01/2023		Repair	Completed	DAFHWY	Wodonga	LHS	XW63CD	Albury Workshop	P/MOVER		
723	Wodonga - Workshop	Tyres\TP7+8	Tyre Position 7 + 8		14/01/2023		Repair	Completed	DAFHWY	Wodonga	LHS	XW63CD	Albury Workshop	P/MOVER		
723	Wodonga - Workshop	Tyres\TP9+10	Tyre Position 9 + 10		14/01/2023		Repair	Completed	DAFHWY	Wodonga	LHS	XW63CD	Albury Workshop	P/MOVER		