EquipmentName	Workshop	CodeAndSubCode	Description	CompletionComments	DateDone	DistanceDone	Workstate	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
722	Myrtleford - Workshop	Hydraulics\CONSUMABLE	CHANGE FUEL TANK TO A HYD TANK & CHANGE ROTATION OF HYD PUMP & SUPPLY PARTS		09/09/2026	523515	Completed	DAFHWY	Wodonga	LHS	XW59CD	Myrtleford Workshop	P/MOVER
722	Myrtleford - Workshop	Body\HOUSEKEEP	FIT ROLL OVER PROTECTION SYSTEM FOR DANGEROUS GOODS (RESIN) & HYDRAULICES TO OPERATE WALKING FLOOR	KLM AT TIME OF INSPECTION 523515	09/09/2026	523515	Completed	DAFHWY	Wodonga	LHS	XW59CD	Myrtleford Workshop	P/MOVER
722	Myrtleford - Workshop	Comp\Truck Safe	Comp\Truck Safe	FIT NEW DANGEROUS GOODS SIGN	09/09/2026	523515	Completed	DAFHWY	Wodonga	LHS	XW59CD	Myrtleford Workshop	P/MOVER
722	Myrtleford - Workshop	Body\FUEL TANK	REPLACE FUEL TANK STRAP RUBBERS		04/09/2026	523515	Completed	DAFHWY	Wodonga	LHS	XW59CD	Myrtleford Workshop	P/MOVER
722	Myrtleford - Workshop	Body\MUDGUARDS	REPLACE ALL 4 DAMAGED DRIVE M/GUARDS	COMPLETED BY NB	04/09/2026	523515	Completed	DAFHWY	Wodonga	LHS	XW59CD	Myrtleford Workshop	P/MOVER
722	Wodonga - Workshop	Engine\ADBLUE	AD-Blu Dosing malfunction, have left Tank empty incase it is leaking.	CHECK AD BLUE TANK (IT HAS BEEN REPLACED BY G/F WODONGA)	08/07/2026	523515	Completed	DAFHWY	Wodonga	LHS	XW59CD	Wodonga Workshop	P/MOVER
722	Myrtleford - Workshop	DriCabRep\DOOR LOCK	Fridge handle broken.	REPAIR BROKEN FRIGE HANDLE	08/07/2026	523515	Completed	DAFHWY	Wodonga	LHS	XW59CD	Myrtleford Workshop	P/MOVER
722	Myrtleford - Workshop	Body\DAMAGE	L/H side door, no longer able to open/unlock from inside or outside.	TIGHTEN DOOR HANDLE & TEST DOOR ALL OK	08/07/2026	523515	Completed	DAFHWY	Wodonga	LHS	XW59CD	Myrtleford Workshop	P/MOVER
722	Myrtleford - Workshop	Body\ELECT P&W	L/H front driving light is out.	TIGHTEN LOOSE LIGHT & TEST ALL WORKING CORRECTLY	08/07/2026	523515	Completed	DAFHWY	Wodonga	LHS	XW59CD	Myrtleford Workshop	P/MOVER
722	Myrtleford - Workshop	Engine\ADBLUE	Ad-Blu Tank is Leaking.	CHECK AD BLUE TANK & CAP FOR LEAKS ALL OK	08/07/2026	523515	Completed	DAFHWY	Wodonga	LHS	XW59CD	Myrtleford Workshop	P/MOVER
722	Myrtleford - Workshop	DrCabElect\RADIO	UHF Arial Broken	FIT NEW UHF ANTENA	08/07/2026	523515	Completed	DAFHWY	Wodonga	LHS	XW59CD	Myrtleford Workshop	P/MOVER
722	Myrtleford - Workshop	DrCabElect\ELECT P&W	tablet in truck keeps pulling of dash section in transit doesn't seem to charge please mount else where/check wiring	INSPEC MOUNT & CHARGING ALL OK	08/07/2026	523515	Completed	DAFHWY	Wodonga	LHS	XW59CD	Myrtleford Workshop	P/MOVER
722	Myrtleford - Workshop	DriCabRep\HOUSEKEEP	window leaks left hand side	CHEECK REAR WINDOW ITS BEEN SEALED UP	08/07/2026	523515	Completed	DAFHWY	Wodonga	LHS	XW59CD	Myrtleford Workshop	P/MOVER
722	Myrtleford - Workshop	DriCabRep\ELECT P&W	Sort out indercator fault.	CHECK FOR FAULTS ALL WORK CORRECTLY	08/07/2026	523515	Completed	DAFHWY	Wodonga	LHS	XW59CD	Myrtleford Workshop	P/MOVER
722	Myrtleford - Workshop	Body\FUEL TANK	MISSING FUEL TANK CAP DRIVER SIDE.	CHECK AD BLUE TANK & CAP FOR LEAKS ALL OK	08/07/2026	523515	Completed	DAFHWY	Wodonga	LHS	XW59CD	Myrtleford Workshop	P/MOVER
722	Wodonga - Workshop	DrCabElect\ELECT P&W	DrCabElect\ELECT P&W	Respond To Breakdown Call mangers Report Truck Not Starting Travel To Site In Fitzgerald Rd Laverton, Upon Arrival It Was found That Truck was Already Running, Scan Truck For Fault Codes No New Codes Noted,Check Coolant and Oil Levels Turn Truck Off And Start Multiple Times All Ok Couldn't Fault, Mangers Informed of This (labour Charge)1.5Hrs	26/06/2026	517088	Completed	DAFHWY	Wodonga	LHS	XW59CD	CALLAWAY DIESEL	P/MOVER
722	Wodonga - Workshop	VehService\AS	VehService\AS A Service	completed by SMc KR	19/06/2026	517088	Completed	DAFHWY	Wodonga	LHS	XW59CD	Wodonga Workshop	P/MOVER
722	Wodonga - Workshop	DrCabElect\JAP	REPAIR MTDATA NOT TRACKING WW133790	Test drive truck. Found truck going into limp mode and doesnt go over 20kmh. Found an Ad-Blue tank empty code on dash. Insert a inspection camrea into Ad-Blue tank found the tank is indeed empty. Refuel the system with 20L of Ad-Blue. Code went away. Pressurised system by using scan-tool. Found leaking out of Ad-Blue filter. Ordered new filter. Picked up filter and tech specs. Replaced Ad-Blue filter as per to manufactours spec. Filler cap tighten to 80nm. Repressurised system found no leaks. Test drove truck. Removed Ad-Blue tank cover, found filter and tank not leaking anymore. Vehicle isnt going into limp mode anymore. Check MT Data not working. Check power/earth ign all ok. Replaced sim card. Mt data now working all ok.	13/05/2026	507734	Completed	DAFHWY	Wodonga	LHS	XW59CD	ARKON AUTO ELECTRICAL	P/MOVER
722	Wodonga - Workshop	Body\FUEL TANK	Replace LOST Fuel cap.		11/05/2026	502707	Completed	DAFHWY	Wodonga	LHS	XW59CD	TWIN CITY TRUCK CENTRE	P/MOVER
722	Wodonga - Workshop	Engine\FAULT CODE	Truck has Derated,	ROAD TEST & CHECK FOR ENGINE FAULTS ALL OK (WD) BREAKDOWN CALLED IN FROM GREENFREIGHT 04/09/25 DRIVER; GREG 0402713465 SUBLET ROSS NEWTON MECHANICAL TRAVEL TO VEHICLE LOCATION AT AVENEL. INSPECT VEHICLE FOR OIL SPRAY. CLEAN AND WIPE AWAY ALL LEAKING OIL, FILL WITH OIL, START AND RAN VEHICLE, TRIED TO DETERMINE WHERE LEAK WAS COMING FROM. COULD NOT GET TO LEAK. FOLLOWED VEHICLE SOUTH BOUND TO GRASS TREE PARKING BAY, INSPECTED VEHICLE AGAIN, FOUND FILL TUBE TO HAVE SMALL HOLE IN IT. REMOVE FILLER TUBE, CARRY OUT TEMPORARY REPAIR. FILL HOLE WITH SEALANT AND REFIT TUBE. TOP UP OIL AGAIN. REFIT COVERS.	08/05/2026	523515	Completed	DAFHWY	Wodonga	LHS	XW59CD	Wodonga Workshop	P/MOVER
722	Wodonga - Workshop	Engine\AIR LEAK	Engine\AIR LEAK	RETURN VEHICLE TO SERVICE. TRAVEL BACK TO WORKSHOP	25/03/2026	488794	Completed	DAFHWY	Wodonga	LHS	XW59CD	GRAHAM THOMSON MOTORS	P/MOVER
722	Wodonga - Workshop	Engine\FAULT CODE	Engine Malfunction - Maybe Related To Using 1 Tank Of Adblue Per Half Tank Of Fuel	Can not plug in	06/03/2026	483453	Completed	DAFHWY	Wodonga	LHS	XW59CD	Wodonga Workshop	P/MOVER
722	Wodonga - Workshop	Elect\HEAD LIGHT	Left Parker Light Out		06/03/2026	483453	Completed	DAFHWY	Wodonga	LHS	XW59CD	Wodonga Workshop	P/MOVER
722	Wodonga - Workshop	Elect\TRL LIGHTS	Trailer Plug Maybe Missing Pin		06/03/2026	483453	Completed	DAFHWY	Wodonga	LHS	XW59CD	Wodonga Workshop	P/MOVER
722	Wodonga - Workshop	DriCabRep\SEAT	Lumber Support Valves Leak Letting Air Into Lumber Causing Back Pain C Service		06/03/2026	483453	Completed	DAFHWY	Wodonga	LHS	XW59CD	Wodonga Workshop	P/MOVER
722	Wodonga - Workshop	VehService\CS	Serviced @ 483,454 Klms		06/03/2026	483453	Completed	DAFHWY	Wodonga	LHS	XW59CD	Wodonga Workshop	P/MOVER
722	Wodonga - Workshop	Brakes\BRK RELINE	Rear brake pads low	Not due	06/03/2026	483453	Completed	DAFHWY	Wodonga	LHS	XW59CD	Wodonga Workshop	P/MOVER
722	Wodonga - Workshop	Elect\ELECT P&W	REVERSING BUZZER NOT WORKING.		06/03/2026	483453	Completed	DAFHWY	Wodonga	LHS	XW59CD	Wodonga Workshop	P/MOVER
722	Wodonga - Workshop	Elect\ELECT P&W	BULLBAR LIGHT NOT WORKING.	Nil fault	06/03/2026	483453	Completed	DAFHWY	Wodonga	LHS	XW59CD	Wodonga Workshop	P/MOVER
722	Wodonga - Workshop	DriCabRep	No door alarm fitted	Nil factory fit	06/03/2026	483453	Completed	DAFHWY	Wodonga	LHS	XW59CD	Wodonga Workshop	P/MOVER
722	Wodonga - Workshop	Engine\BATTERY	Truck at freight shed , diagnose why truck won't start and repair so truck can be moved .	Turned isolator.	03/03/2026	482028	Completed	DAFHWY	Wodonga	LHS	XW59CD	Wodonga Workshop	P/MOVER
722	Wodonga - Workshop	Tyres\TP5+6	Tyres\TP5+6		28/01/2026	467148	Completed	DAFHWY	Wodonga	LHS	XW59CD	BORDER BANDAG PTY LTD	P/MOVER
722	Wodonga - Workshop	Tyres\TP7+8	Tyres\TP7+8		28/01/2026	467148	Completed	DAFHWY	Wodonga	LHS	XW59CD	BORDER BANDAG PTY LTD	P/MOVER
722	Wodonga - Workshop	Tyres\TP11+12	Tyres\TP11+12		28/01/2026	467148	Completed	DAFHWY	Wodonga	LHS	XW59CD	BORDER BANDAG PTY LTD	P/MOVER
722	Wodonga - Workshop	Tyres\TP9+10	Tyres\TP9+10		28/01/2026	467148	Completed	DAFHWY	Wodonga	LHS	XW59CD	BORDER BANDAG PTY LTD	P/MOVER
722	Wodonga - Workshop	Engine\OIL LEAK	OIL LEAK Body\WINDSCREEN		24/01/2026	465759	Completed	DAFHWY	Wodonga	LHS	XW59CD	Wodonga Workshop	P/MOVER
722	Wodonga - Workshop	Body\WINDSCREEN	WW098519	WINDOW GLASS & WEATHER STRIP REAR WINDOW -light trailer base pins spread to make correct contact with trailer plug -lights check conducted -heavy base checked	08/01/2026	457975	Completed	DAFHWY	Wodonga	LHS	XW59CD	Wodonga Workshop	P/MOVER
722	Wodonga - Workshop	Elect\ELECT P&W	TAIL LIGHT WIRING ON PM "BEEPING EVERY TIME BRAKE APPLIED"	-truck lights and trailer plugs checked, all working	11/12/2025	450428	Completed	DAFHWY	Wodonga	LHS	XW59CD	Wodonga Workshop	P/MOVER
722	Wodonga - Workshop	VehService\AS	VehService\AS A Service	REPAIRED STOP LIGHT AND AIR LEAK AT INTER-AXLE LOCK.	28/11/2025	446171	Completed	DAFHWY	Wodonga	LHS	XW59CD	Wodonga Workshop	P/MOVER
722	Wodonga - Workshop	DrCabElect\ELECT P&W	REPLACED ENGINE BRAKE STALK. Steering\DAMAGE STEERING COLUMN SWITCH		18/11/2025	440487	Completed	DAFHWY	Wodonga	LHS	XW59CD	Wodonga Workshop	P/MOVER
722	Wodonga - Workshop	Steering\DAMAGE	.WW097855		14/11/2025	440494	Completed	DAFHWY	Wodonga	LHS	XW59CD	TWIN CITY TRUCK CENTRE - OL	P/MOVER
722	Wodonga - Workshop	VehService\AS	VehService\AS A Service		08/11/2025	437590	Completed	DAFHWY	Wodonga	LHS	XW59CD	Wodonga Workshop	P/MOVER
722	Wodonga - Workshop	Tyres\TP1+2	Tyres\TP1+2 Major Oil Leak		13/09/2025	414325	Completed	DAFHWY	Wodonga	LHS	XW59CD	BORDER BANDAG PTY LTD	P/MOVER
722	Wodonga - Workshop	Engine\OIL LEAK	(TCTC Warranty) 415,193 Klms Front oil filler neck leaking		10/09/2025	465759	Completed	DAFHWY	Wodonga	LHS	XW59CD	TWIN CITY TRUCK CENTRE - OL	P/MOVER
722	Wodonga - Workshop	Engine\OIL LEAK	(TCTC Warranty) 415,193 Klms Check For Engine Oil Leak, Repair/Diagnose.		10/09/2025	465759	Completed	DAFHWY	Wodonga	LHS	XW59CD	TWIN CITY TRUCK CENTRE - OL	P/MOVER
722	Wodonga - Workshop	Engine\OIL LEAK	(G&S Diesel P/O: WW096805)	ATTEND AFTER HOURS CALLOUT TO ALPINE MDF TO VEHICLE WITH REPORTED TRAILER LIGHT FAULT IN TRUCK, FOUND FAILED FUSE FOR TRAILER TAIL LIGHTS, RENEW FUSE, INSPECT WIRING, UNABLE TO FAULT CIRCUIT, DRIVER	06/09/2025	465759	Completed	DAFHWY	Wodonga	LHS	XW59CD	G & S DIESEL SERVICE	P/MOVER
722	Wodonga - Workshop	Elect\TAIL LIGHT	Elect\TAIL LIGHT - FAILED FUSE	TO MONITOR, RETURN TO WORKSHOP	11/08/2025	403222	Completed	DAFHWY	Wodonga	LHS	XW59CD	ROBINSONS TRUCK AND COACI	P/MOVER
722	Wodonga - Workshop	Tyres\Punct	Tyres\Puncture POS 10		04/08/2025	397949	Completed	DAFHWY	Wodonga	LHS	XW59CD	BORDER BANDAG PTY LTD	P/MOVER
722	Wodonga - Workshop	DriCabRep\WINDSCREEN	front windscreen cracked (PO:WW095806)		24/07/2025	393742	Completed	DAFHWY	Wodonga	LHS	XW59CD	AUTOTEK AUSTRALIA	P/MOVER
722	Wodonga - Workshop	DriCabRep\WINDSCREEN	FRONT WINDOW CRACKED		24/07/2025	393742	Completed	DAFHWY	Wodonga	LHS	XW59CD	AUTOTEK AUSTRALIA	P/MOVER
722	Wodonga - Workshop	Tyres\Punct	Tyres\Puncture POS 11 SERVICE. ODOMETRE NOW 377896.		23/07/2025	393710	Completed	DAFHWY	Wodonga	LHS	XW59CD	BORDER BANDAG PTY LTD	P/MOVER
722	Wodonga - Workshop	VServLab	SERVICE DUE ODOMETRE 375000.		22/07/2025	393710	Completed	DAFHWY	Wodonga	LHS	XW59CD	Wodonga Workshop	P/MOVER
722	Wodonga - Workshop	VehService\AS	VehService\AS A Service		22/07/2025	393710	Completed	DAFHWY	Wodonga	LHS	XW59CD	Wodonga Workshop	P/MOVER
722	Wodonga - Workshop	DrivLine\CONSUMABLE	WHEEL NUT COVERS.		22/07/2025	393710	Completed	DAFHWY	Wodonga	LHS	XW59CD	Wodonga Workshop	P/MOVER
722	Wodonga - Workshop	Body\MUDGUARDS	REAR LH GUARD GUARD NEEDS REPLACING.		18/06/2025	377895	Completed	DAFHWY	Wodonga	LHS	XW59CD	Wodonga Workshop	P/MOVER
722	Wodonga - Workshop	VehService\AS	VehService\AS A Service	Topped up both engine oil and coolant	18/06/2025	377895	Completed	DAFHWY	Wodonga	LHS	XW59CD	Wodonga Workshop	P/MOVER
722	Wodonga - Workshop	Elect\ELECT P&W	Light bar not working	-light bar lume repaired as required, had breaks and poor connections + switch replaced due to being faulty, full lights check conducted	18/06/2025	377895	Completed	DAFHWY	Wodonga	LHS	XW59CD	Wodonga Workshop	P/MOVER
722	Wodonga - Workshop	Body\MUDGUARDS	REMINDER REPLACE REAR LH MUDGUARD tail light truck bare light not working	-resistors for tail lights repaired and mounted as required -rear light wiring repaired as required, several brakes found	18/06/2025	377895	Completed	DAFHWY	Wodonga	LHS	XW59CD	Wodonga Workshop	P/MOVER
722	Wodonga - Workshop	Elect\ELECT P&W	marker light / trailer tail light check fuse is not working	-trailer fuse blown, part replaced	14/06/2025	376410	Completed	DAFHWY	Wodonga	LHS	XW59CD	Wodonga Workshop	P/MOVER
722	Wodonga - Workshop	Tyres\Punct	Tyres\Puncture POS 10		13/06/2025	375937	Completed	DAFHWY	Wodonga	LHS	XW59CD	BORDER BANDAG PTY LTD	P/MOVER
722	Wodonga - Workshop	VehService\BS	VehService\BS	Booked in TCTC 17/5 PO #WW094185	29/05/2025	364324	Completed	DAFHWY	Wodonga	LHS	XW59CD	PACCAR PARTS FLEET SERVICES	P/MOVER
722	Wodonga - Workshop	Elect\TRL LIGHTS	Trailer clearance lights not working	Inspected plug. Couldn't fault. Not getting power. Inspected fuses and found X2 blown. Replaced fuses and retested. Confirmed repair complete	08/04/2025	345112	Completed	DAFHWY	Wodonga	LHS	XW59CD	Wodonga Workshop	P/MOVER
722	Wodonga - Workshop	Chassis\MUDGUARDS	Replace damaged mudguards		01/04/2025	344722	Completed	DAFHWY	Wodonga	LHS	XW59CD	Wodonga Workshop	P/MOVER
722	Wodonga - Workshop	Elect\TRL LIGHTS	DIAGNOSED AND REPAIRED WIRING. REPLACED PLUG.		01/04/2025	344722	Completed	DAFHWY	Wodonga	LHS	XW59CD	Wodonga Workshop	P/MOVER
722	Wodonga - Workshop	Elect\DRV LIGHT	NO LIGHT BAR. NOT WORKING.		31/03/2025	344721	Completed	DAFHWY	Wodonga	LHS	XW59CD	Wodonga Workshop	P/MOVER
722	Wodonga - Workshop	Body\MUDGUARDS	PLEASE FIX 2 REAR GUARDS.	Previously completed	31/03/2025	344721	Completed	DAFHWY	Wodonga	LHS	XW59CD	Wodonga Workshop	P/MOVER
722	Wodonga - Workshop	VehService\AS	VehService\AS	Cab tilt pump leaking	31/03/2025	344721	Completed	DAFHWY	Wodonga	LHS	XW59CD	Wodonga Workshop	P/MOVER
722	Wodonga - Workshop	Elect\HOUSEKEEP	light bar not working		31/03/2025	344721	Completed	DAFHWY	Wodonga	LHS	XW59CD	Wodonga Workshop	P/MOVER
722	Wodonga - Workshop	Elect\TAIL LIGHT	please fix tail light bar on rear		31/03/2025	344721	Completed	DAFHWY	Wodonga	LHS	XW59CD	Wodonga Workshop	P/MOVER
722	Wodonga - Workshop	DrCabElect\ELECT P&W	IGNITION DICKY.	Couldn't fault	31/03/2025	344721	Completed	DAFHWY	Wodonga	LHS	XW59CD	Wodonga Workshop	P/MOVER
722	Wodonga - Workshop	Tyres\TP1+2	Tyres\TP1+2		26/02/2025	337054	Completed	DAFHWY	Wodonga	LHS	XW59CD	BEAUREPAIRES	P/MOVER
722	Wodonga - Workshop	Tyres\TP7+8	Tyres\TP7+8		26/02/2025	337054	Completed	DAFHWY	Wodonga	LHS	XW59CD	BEAUREPAIRES	P/MOVER
722	Wodonga - Workshop	Tyres\TP9+10	Tyres\TP9+10		26/02/2025	337054	Completed	DAFHWY	Wodonga	LHS	XW59CD	BEAUREPAIRES	P/MOVER

				* Connected laptop & scanned for faults * Found no fault codes present for water pump but multiple present for vehicle overheating * Inspected & found radiator to be completely blocked * Removed bullbar & backing plate * Removed the grille * Removed all components off front end as required * Jacked over cab * Drained coolant * Removed all accessories & hoses * Found hoses to be baked on due to excess temperatures reached * Unbolted, disconnected & removed radiator * Stripped radiator assembly - excessive time taken due to extreme blockage * Thoroughly cleaned radiator * Replaced thermostats due to excessive temperatures reached * Reassembled radiator * Refit radiator assembly * Connected all components & replaced damaged hoses * Refit all components & rewired wiring on bullbar * Replaced coolant									
722	Wodonga - Workshop	Cooling\RADIATOR	Truck Over Heating (Possible Water Pump). (TCTC P/O: WW092181)	* Test operations - All ok, fault no longer present	15/02/2025	327083	Completed	DAFHWY	Wodonga	LHS	XWS9CD	TWIN CITY TRUCK CENTRE - OL	P/MOVER	
722	Wodonga - Workshop	VehService\CS	C Service. (TCTC P/O: WW091544)		23/01/2025	322320	Completed	DAFHWY	Wodonga	LHS	XWS9CD	TWIN CITY TRUCK CENTRE - OL	P/MOVER	
722	Wodonga - Workshop	Insp\ANN INSP	Insp\ANN INSP TCTC completing work. (TCTC P/O: WW091544)		23/01/2025	322320	Completed	DAFHWY	Wodonga	LHS	XWS9CD	TWIN CITY TRUCK CENTRE - OL	P/MOVER	
722	Wodonga - Workshop	DriCabRep\WINDSCREEN	Job Created from Purchase Order #: 105733		24/12/2024	316882	Completed	DAFHWY	Wodonga	LHS	XWS9CD	AUTOTEX AUSTRALIA	P/MOVER	
722	Wodonga - Workshop	DrCabElect\INST/GAUGE	Repair Fault Codes On Dash. (TCTC P/O: WW091076) B Service. (TCTC P/O: WW089672)		20/12/2024	315761	Completed	DAFHWY	Wodonga	LHS	XWS9CD	TWIN CITY TRUCK CENTRE - OL	P/MOVER	
722	Wodonga - Workshop	VehService\BS	Serviced @ 288485 Klms. A Service. (TCTC P/O: WW089672)		25/10/2024	288485	Completed	DAFHWY	Wodonga	LHS	XWS9CD	TWIN CITY TRUCK CENTRE - OL	P/MOVER	
722	Wodonga - Workshop	VehService\AS	Serviced @ 288485 Klms. B Service (TCTC P/O: WW087000) Serviced @ 234,058 Klms		25/10/2024	288485	Completed	DAFHWY	Wodonga	LHS	XWS9CD	TWIN CITY TRUCK CENTRE - OL	P/MOVER	
722	Wodonga - Workshop	VehService\BS	Brake Wear Indicator On Dash		24/10/2024	288477	Completed	DAFHWY	Wodonga	LHS	XWS9CD	TWIN CITY TRUCK CENTRE - OL	P/MOVER	
722	Wodonga - Workshop	Brakes\BRK RELINE	INSPECT VEHICLE FOR REPORTED OVER HEATING, FOUND RADIATOR EXCESSIVELY BLOCKED, CLEAN & WASH DEBRIS	Replaced Brake Pads L/H Centre Axle.	24/10/2024	288477	Completed	DAFHWY	Wodonga	LHS	XWS9CD	TWIN CITY TRUCK CENTRE - OL	P/MOVER	
722	Wodonga - Workshop	Engine\RADIATOR	FROM RADIATOR.		17/10/2024	204086	Completed	DAFHWY	Wodonga	LHS	XWS9CD	ROBINSONS TRUCK AND COACI	P/MOVER	
722	Wodonga - Workshop	Chassis\AIR LEAK	Check & repair Air Leak. (Robinson's Truck & Coach P/O: WW089317)		10/10/2024	279266	Completed	DAFHWY	Wodonga	LHS	XWS9CD	ROBINSONS TRUCK AND COACI	P/MOVER	
722	Myrtleford - Workshop	Tyres\TP3+4	Tyres\TP3+4		15/06/2024	229884	Completed	DAFHWY	Wodonga	LHS	XWS9CD	BEAUREPAIRES - 3	P/MOVER	
722	Myrtleford - Workshop	Tyres\TP08	Tyres\TP08		15/06/2024	229884	Completed	DAFHWY	Wodonga	LHS	XWS9CD	BEAUREPAIRES - 3	P/MOVER	
722	Myrtleford - Workshop	Tyres\TP5+6	Tyres\TP5+6		15/06/2024	229884	Completed	DAFHWY	Wodonga	LHS	XWS9CD	BEAUREPAIRES - 3	P/MOVER	
722	Myrtleford - Workshop	Tyres\TP1+2	Tyres\TP1+2 tighten walk plate		15/06/2024	229884	Completed	DAFHWY	Wodonga	LHS	XWS9CD	BEAUREPAIRES - 3	P/MOVER	
722	Wodonga - Workshop	Body\PANELS	Kenworth Melb		13/06/2024	227057	Completed	DAFHWY	Wodonga	LHS	XWS9CD	PACCAR PARTS FLEET SERVICES	P/MOVER	
722	Wodonga - Workshop	Tyres\TP09	Tyres\TP09		30/05/2024	204086	Completed	DAFHWY	Wodonga	LHS	XWS9CD	BEAUREPAIRES	P/MOVER	
722	Wodonga - Workshop	Tyres\TP07	Tyre Position 7		03/04/2024		Completed	DAFHWY	Wodonga	LHS	XWS9CD	Albury Workshop	P/MOVER	
722	Wodonga - Workshop	Tyres\TP10	Tyre Position 10		03/04/2024		Completed	DAFHWY	Wodonga	LHS	XWS9CD	Albury Workshop	P/MOVER	
722	Wodonga - Workshop	Engine\BATTERY	Battery		19/03/2024	235243	Completed	DAFHWY	Wodonga	LHS	XWS9CD	Albury Workshop	P/MOVER	
722	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		28/02/2024	177651	Completed	DAFHWY	Wodonga	LHS	XWS9CD	Wodonga Workshop	P/MOVER	
722	Wodonga - Workshop	VehService\AS	A Service As Per Attached Checklist		28/02/2024	177651	Completed	DAFHWY	Wodonga	LHS	XWS9CD	Wodonga Workshop	P/MOVER	
722	Wodonga - Workshop	Body	TOW FROM NORTHERN HIGHWAY WALLAN TO GREENFREIGHT DEPOT WODONGA		03/02/2024		Completed	DAFHWY	Wodonga	LHS	XWS9CD	Albury Workshop	P/MOVER	
722	Wodonga - Workshop	Tyres	no pos		26/01/2024		Completed	DAFHWY	Wodonga	LHS	XWS9CD	Albury Workshop	P/MOVER	
722	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job	CUSTOMER REPORTS AIR BLOWER TIP BROKEN OFF . * Inspected & confirmed trigger broken	13/01/2024	163899	Completed	DAFHWY	Wodonga	LHS	XWS9CD	Wodonga Workshop	P/MOVER	
722	Wodonga - Workshop	DriCabRep\HOUSEKEEP	AIR GUN FIX.	* Removed & replaced air blower as required	13/01/2024	163899	Completed	DAFHWY	Wodonga	LHS	XWS9CD	Wodonga Workshop	P/MOVER	
722	Wodonga - Workshop	VehService\CS	C Service As Per Attached Checklist	Carried out A, B & C Truck service as per Greenfreight service sheet schedule	13/01/2024	163899	Completed	DAFHWY	Wodonga	LHS	XWS9CD	Wodonga Workshop	P/MOVER	
722	Wodonga - Workshop	Unknown	722 TRUCK FOR SERVICE. TRAILER REVERSE WARNING LIGHT ON DASH. * Inspected fuses * Found blown fuse for trailer reverse * Removed & replaced fuse * Inspected trailer plug * Found reverse wire shorted to earth wire * Removed & replaced trailer plug		13/01/2024	163899	Completed	DAFHWY	Wodonga	LHS	XWS9CD	Wodonga Workshop	P/MOVER	
722	Wodonga - Workshop	DrCabElect\INST/GAUGE	* Test operations - All ok, fault no longer present		13/01/2024	163899	Completed	DAFHWY	Wodonga	LHS	XWS9CD	Wodonga Workshop	P/MOVER	
722	Wodonga - Workshop	Body\CONSUMABLE	Please Repair Cabin Fridge Door No Indicators On Trailer (Elite Diesel)	DROPPED OFF AND PICKED UP AT TCTC.	29/10/2023	130427	Completed	DAFHWY	Wodonga	LHS	XWS9CD	Wodonga Workshop	P/MOVER	
722	Wodonga - Workshop	Elect\BREAKDOWN	Purchase Order Number: WW081851		24/10/2023	235243	Completed	DAFHWY	Wodonga	LHS	XWS9CD	Wodonga Workshop	P/MOVER	
722	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job	tried to adjust locks	17/09/2023	110046	Completed	DAFHWY	Wodonga	LHS	XWS9CD	Wodonga Workshop	P/MOVER	
722	Wodonga - Workshop	Body\CONSUMABLE	Please Repair Cabin Fridge Door B Service As Per Attached Checklist (TCTC)	(parts on order)	17/09/2023	110046	Completed	DAFHWY	Wodonga	LHS	XWS9CD	Wodonga Workshop	P/MOVER	
722	Wodonga - Workshop	VehService\BS	Purchasae Order Number: WW081096		17/09/2023	110046	Completed	DAFHWY	Wodonga	LHS	XWS9CD	Wodonga Workshop	P/MOVER	
722	Wodonga - Workshop	Tyres\TP1+2	Tyre Position 1 + 2		16/08/2023	104838	Completed	DAFHWY	Wodonga	LHS	XWS9CD	Albury Workshop	P/MOVER	
722	Wodonga - Workshop	Body	NO JOB.		21/04/2023		Completed	DAFHWY	Wodonga	LHS	XWS9CD	Wodonga Workshop	P/MOVER	
722	Wodonga - Workshop	VehService\AS	CARRY OUT GREENFREIGHT TRUCK A-SERVICE WITH SERVICE SHEET PROVIDED.		26/03/2023	40819	Completed	DAFHWY	Wodonga	LHS	XWS9CD	Albury Workshop	P/MOVER	
722	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		24/03/2023	235078	Completed	DAFHWY	Wodonga	LHS	XWS9CD	Wodonga Workshop	P/MOVER	
722	Wodonga - Workshop	Brakes\EBS FAULTS	ABS/EBS TRAILER NOT CONNECTED WARNING LIGHT COMES ON WHEN TRAILER IS CONNECTED. (EVERY TRAILER)		24/03/2023	235078	Completed	DAFHWY	Wodonga	LHS	XWS9CD	Wodonga Workshop	P/MOVER	
722	Wodonga - Workshop	Brakes\EBS FAULTS	ABS/EBS WARNING LIGHT COMES ON WHEN TRAILER IS HOOKED UP.		24/03/2023	235078	Completed	DAFHWY	Wodonga	LHS	XWS9CD	Wodonga Workshop	P/MOVER	
722	Wodonga - Workshop	Elect\ELECT P&W	TRANSISTERS AT REAR LIGHTS STILL GETTING HOT.		24/03/2023	235078	Completed	DAFHWY	Wodonga	LHS	XWS9CD	Wodonga Workshop	P/MOVER	
722	Wodonga - Workshop	Elect\ELECT P&W	MARKER LIGHT CHECK FUSE WARNING COMES ON WHEN LIGHTS ARE TURNED ON.		24/03/2023	235078	Completed	DAFHWY	Wodonga	LHS	XWS9CD	Wodonga Workshop	P/MOVER	
722	Wodonga - Workshop	Elect\ELECT P&W	LIGHT BAR DOESN'T WORK.		24/03/2023	235078	Completed	DAFHWY	Wodonga	LHS	XWS9CD	Wodonga Workshop	P/MOVER	
722	Wodonga - Workshop	Brakes\ABS	ABS/ EBS COMES ON WHEN TRAILER IS CONNECTED.		24/03/2023	235078	Completed	DAFHWY	Wodonga	LHS	XWS9CD	Wodonga Workshop	P/MOVER	
722	Wodonga - Workshop	VehService\BS	B Service As Per Attached Checklist		24/03/2023	235078	Completed	DAFHWY	Wodonga	LHS	XWS9CD	Wodonga Workshop	P/MOVER	
722	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		21/03/2023	40819	Completed	DAFHWY	Wodonga	LHS	XWS9CD	Wodonga Workshop	P/MOVER	
722	Wodonga - Workshop	Brakes\EBS FAULTS	ABS/EBS TRAILER NOT CONNECTED WARNING LIGHT COMES ON WHEN TRAILER IS CONNECTED. (EVERY TRAILER) WARRANTY		21/03/2023	40819	Completed	DAFHWY	Wodonga	LHS	XWS9CD	Wodonga Workshop	P/MOVER	
722	Wodonga - Workshop	Elect\INDICATORS	RIGHT HAND REAR BLINKER IS VERY DIM ON TRAILER 91 ABS/EBS WARNING LIGHT COMES ON WHEN TRAILER IS HOOKED UP.		21/03/2023	40819	Completed	DAFHWY	Wodonga	LHS	XWS9CD	Wodonga Workshop	P/MOVER	
722	Wodonga - Workshop	Brakes\EBS FAULTS	WARRANTY TRANSISTERS AT REAR LIGHTS STILL GETTING HOT.		21/03/2023	40819	Completed	DAFHWY	Wodonga	LHS	XWS9CD	Wodonga Workshop	P/MOVER	
722	Wodonga - Workshop	Elect\ELECT P&W	WARRANTY MARKER LIGHT CHECK FUSE WARNING COMES ON WHEN LIGHTS ARE TURNED ON.		21/03/2023	40819	Completed	DAFHWY	Wodonga	LHS	XWS9CD	Wodonga Workshop	P/MOVER	
722	Wodonga - Workshop	Elect\ELECT P&W	WARRANTY LIGHT BAR DOESN'T WORK.		21/03/2023	40819	Completed	DAFHWY	Wodonga	LHS	XWS9CD	Wodonga Workshop	P/MOVER	
722	Wodonga - Workshop	Elect\ELECT P&W	WARRANTY ABS/ EBS COMES ON WHEN TRAILER IS CONNECTED.		21/03/2023	40819	Completed	DAFHWY	Wodonga	LHS	XWS9CD	Wodonga Workshop	P/MOVER	
722	Wodonga - Workshop	Brakes\ABS	WARRANTY		21/03/2023	40819	Completed	DAFHWY	Wodonga	LHS	XWS9CD	Wodonga Workshop	P/MOVER	
722	Wodonga - Workshop	VehService\AS	A Service As Per Attached Checklist FUEL TANKS HAVE MOVED. Tank Leaking Fuel Sent to KW DAF Derrimut		21/03/2023	40819	Completed	DAFHWY	Wodonga	LHS	XWS9CD	Wodonga Workshop	P/MOVER	
722	Wodonga - Workshop	Body\FUEL TANK	Should be covered under Warranty.. FUEL TANKS HAVE MOVED.		09/03/2023		Completed	DAFHWY	Wodonga	LHS	XWS9CD	Wodonga Workshop	P/MOVER	
722	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		19/02/2023	27534	Completed	DAFHWY	Wodonga	LHS	XWS9CD	Wodonga Workshop	P/MOVER	
722	Wodonga - Workshop	Chassis\DAMAGE	TURNTABLE PIN BENT. NEEDS REPLACING.	BEEN REPLACED.	19/02/2023	27534	Completed	DAFHWY	Wodonga	LHS	XWS9CD	Wodonga Workshop	P/MOVER	
722	Wodonga - Workshop	Brakes\EBS FAULTS	ABS/EBS TRAILER NOT CONNECTED WARNING LIGHT COMES ON WHEN TRAILER IS CONNECTED. (EVERY TRAILER)		19/02/2023	27534	Completed	DAFHWY	Wodonga	LHS	XWS9CD	Wodonga Workshop	P/MOVER	
722	Wodonga - Workshop	Elect\INDICATORS	RIGHT HAND REAR BLINKER IS VERY DIM ON TRAILER 91		19/02/2023	27534	Completed	DAFHWY	Wodonga	LHS	XWS9CD	Wodonga Workshop	P/MOVER	
722	Wodonga - Workshop	Brakes\EBS FAULTS	ABS/EBS WARNING LIGHT COMES ON WHEN TRAILER IS HOOKED UP.		19/02/2023	27534	Completed	DAFHWY	Wodonga	LHS	XWS9CD	Wodonga Workshop	P/MOVER	
722	Wodonga - Workshop	Elect\ELECT P&W	MARKER LIGHT/ TRAILER TAIL LIGHT WARNING IS ON.	CHECKED POWER AND FUSES.	19/02/2023	27534	Completed	DAFHWY	Wodonga	LHS	XWS9CD	Wodonga Workshop	P/MOVER	
722	Wodonga - Workshop	Elect\ELECT P&W	TRANSISTERS AT REAR LIGHTS STILL GETTING HOT.		19/02/2023	27534	Completed	DAFHWY	Wodonga	LHS	XWS9CD	Wodonga Workshop	P/MOVER	
722	Wodonga - Workshop	VehService\AS	A Service As Per Attached Checklist		19/02/2023	27534	Completed	DAFHWY	Wodonga	LHS	XWS9CD	Wodonga Workshop	P/MOVER	
722	Wodonga - Workshop	Insp\Truck Pre	Commision New Truck	SUPPLIED PAPERWORK AND E-TAG. CHANGED TRAILER PLUG. GREASED TURNTABLE.	20/12/2022		Completed	DAFHWY	Wodonga	LHS	XWS9CD	Wodonga Workshop	P/MOVER	
722	Wodonga - Workshop	Tyres\TP1+2	Tyre Position 1 + 2		10/11/2022		Completed	DAFHWY	Wodonga	LHS	XWS9CD	Wodonga Workshop	P/MOVER	
722	Wodonga - Workshop	Tyres\TP3+4	Tyre Position 3 + 4		10/11/2022		Completed	DAFHWY	Wodonga	LHS	XWS9CD	Wodonga Workshop	P/MOVER	
722	Wodonga - Workshop	Tyres\TP5+6	Tyre Position 5 + 6		10/11/2022		Completed	DAFHWY	Wodonga	LHS	XWS9CD	Wodonga Workshop	P/MOVER	
722	Wodonga - Workshop	Tyres\TP7+8	Tyre Position 7 + 8		10/11/2022		Completed	DAFHWY	Wodonga	LHS	XWS9CD	Wodonga Workshop	P/MOVER	
722	Wodonga - Workshop	Tyres\TP9+10	Tyre Position 9 + 10		10/11/2022		Completed	DAFHWY	Wodonga	LHS	XWS9CD	Wodonga Workshop	P/MOVER	