EquipmentName	Workshop	CodeAndSubCode	Description	Schedule	CompletionComments	DateDone	DistanceDone	Worktype	Workstate	EquipmentOwner	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
MV\039	Rosewood - Workshop	Air Con\HEATER	HEATER INTERMITTENTLY GOING COLD		FOUND LOW COOLANT. TOPPED UP COOLANT. RAN TO ENSURE THERMOSTAT OPENS AND SYSTEM IS FULLY BLED. TESTED HEATER. OK.	21/07/2026	552000	Repair	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	Wodonga Workshop	UTE
MV\039	Rosewood - Workshop	Cooling\RADIATOR	active leak behind water pump REPLACE WATER PUMP			13/07/2026	552000	Fault	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	Wodonga Workshop	UTE
MV\039	Rosewood - Workshop	Engine\WATER PUMP	Replace Engine Drive belt (Parts Supplied By Burson's P/O: T134533)			13/07/2026	552000	Repair	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	Wodonga Workshop	UTE
MV\039	Rosewood - Workshop	Engine\BELTS/TENS				26/06/2026	444822	Repair	Completed	Greenfreight Loxeine NSW	UTES	Rosewood	OPS	ABL741	Wodonga Workshoao	UTE
MV\039	Rosewood - Workshop	VehService\BS	VehService\BS B Service	VehService\BS	completed by EC SS	19/06/2026	444822	Service	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	Wodonga Workshop	UTE
MV\039	Rosewood - Workshop	BodyLab	cover near bash plate put back on			19/06/2026	444822	Fault	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	Wodonga Workshop	UTE
MV\039	Rosewood - Workshop	BodyLab	rear plastic bumper loose			19/06/2026	444822	Fault	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	Wodonga Workshop	UTE
MV\039	Albury - Workshop	Tyres\TP1+2	Tyres\TP1+2			03/06/2026	444822	Repair	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	BORDER BANDAG PTY LTD - 4	UTE
MV\039	Albury - Workshop	Tyres\TP3+4	Tyres\TP3+4			03/06/2026	444822	Repair	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	BORDER BANDAG PTY LTD - 4	UTE
MV\039	Albury - Workshop	Prevent\WHEEL ALGN	Prevent\WHEEL ALGN			03/06/2026	444822	Repair	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	BORDER BANDAG PTY LTD - 4	UTE
MV\039	Rosewood - Workshop	DrivLine\GEARBOX	Repair Gear Selector			22/05/2026	444822	Repair	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	Wodonga Workshop	UTE
MV\039	Rosewood - Workshop	Engine\MOUNTS	Replace L/H Engine Mount			22/05/2026	444822	Repair	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	Wodonga Workshop	UTE
MV\039	Rosewood - Workshop	VehService\BS	VehService\BS B Service	VehService\BS	Breaks on rear need to be replaced, engine mount scrawked through	06/02/2026	444822	Service	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	Wodonga Workshop	UTE
MV\039	Rosewood - Workshop	Elect\HEAD LIGHT	LH LOW BEAM NOT WORKING			06/02/2026	444822	Fault	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	Wodonga Workshop	UTE
MV\039	Rosewood - Workshop	VServLab	due for service 510000			06/02/2026	444822	Fault	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	Wodonga Workshop	UTE
MV\039	Rosewood - Workshop	Insp\ANN INSP	Insp\ANN INSP Lost Clutch Pedal.	Insp\ANN INSP		06/02/2026	444822	PreventativeMaintenance	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	Wodonga Workshop	UTE
MV\039	Rosewood - Workshop	DrivLine\CLUTCH	(Parts Supplied By Blacklocks R097852)			15/11/2025	444822	Repair	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	Wodonga Workshop	UTE
					-vehicle checked over, earth's cleaned at battery and chasis points, upgraded earth added between engine, chasis and vehicle body. -no codes found											
MV\039	Rosewood - Workshop	DrCabElect\ELECT P&W	DIAGNOSE AND REPAIR MULTIPLE ELECTRICAL FAULTS IN DASH.		-test driven at soeed and full rotation. couldnt fault. vehicle will need to be monitored for further faults.	07/11/2025	444822	Repair	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	Wodonga Workshop	UTE
MV\039	Rosewood - Workshop	Elect\DAY LIGHTS	Inspect and repair left hand headlight fault.			04/07/2025	444822	Fault	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	Rosewood Workshop	UTE
MV\039	Rosewood - Workshop	Elect\HEAD LIGHT	Inspect and repair LH headlight fault		Check light push plug in drive round yard to test all good	26/06/2025	444822	Fault	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	Wodonga Workshop	UTE
MV\039	Rosewood - Workshop	Tyres\TP1+2	Tyres\TP1+2 B Service.		replaced oil/air/fuel and cabin filters in service front pads need replacing next service	23/05/2025	444822	Repair	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	BEAUREPAIRES - 4	UTE
MV\039	Rosewood - Workshop	VehService\BS	(Border Dyno P/O: R0943319)	VehService\BS	rear tyres need replacing	20/05/2025	444822	Service	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	BORDER DYNO SERVICE - 4	UTE
MV\039	Rosewood - Workshop	DrivLine\GEARBOX	Replace Broken Gear Selector Bolt.			15/05/2025	444822	Repair	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	Wodonga Workshop	UTE
MV\039	Rosewood - Workshop	Body\HOUSEKEEP	Replace Tonneau Cover.			16/04/2025	444822	Repair	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	Wodonga Workshop	UTE
MV\039	Rosewood - Workshop	Elect\ELECT P&W	REPLACED LIGHTS SOCKET AND TRAILER PLUG. REPAIRED EARTH.			19/03/2025	444822	Repair	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	Wodonga Workshop	UTE
MV\039	Myrtleford - Workshop	VehService\BS	VehService\BS	VehService\BS		04/03/2025	444822	Service	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	Myrtleford Workshop	UTE
MV\039	Albury - Workshop	VehService\BS	B Service. (Border Dyno Centre P/O: T092476)	VehService\BS		28/02/2025	444822	Service	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	BORDER DYNO SERVICE - 4	UTE
MV\039	Albury - Workshop	Elect\HEAD LIGHT	L/H Head Light Not Working Check BCM			18/02/2025	444822	Repair	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	Wodonga Workshop	UTE
MV\039	Wodonga - Workshop	DrCabRep\SEAT	Replace Seats		Swap seats out sit old out back under awning coverd up on palet	10/01/2025	444822	Fault	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	Wodonga Workshop	UTE
MV\039	Wodonga - Workshop	VServLab\OIL/FILTER	VServLab\OIL/FILTER			20/11/2024	444822	Service	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	Wodonga Workshop	UTE
MV\039	Myrtleford - Workshop	Tyres\TP1+2	Tyres\TP1+2			10/10/2024	391000	Repair	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	BEAUREPAIRES - 3	UTE
MV\039	Albury - Workshop	Tyres\Punct	Tyres\Punct			27/09/2024	391000	Repair	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	BEAUREPAIRES - 4	UTE
MV\039	Myrtleford - Workshop	Engine	Engine SERVICE			27/09/2024	444822	Repair	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	BORDER DYNO SERVICE - 4	UTE
MV\039	Wodonga - Workshop	Tyres\STEER TYRE	Tyres\STEER TYRE			11/05/2024	391000	Repair	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	Wodonga Workshop	UTE
MV\039	Albury - Workshop	Unknown	LOG BOOK SERVICE 391,000KM			01/03/2024	391000	Repair	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	Albury Workshop	UTE
MV\039	Albury - Workshop	Tyres				25/01/2024		Repair	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	Albury Workshop	UTE
MV\039	Albury - Workshop	VehService\BS	service work ute	VehService\BS		23/11/2023	275781	Service	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	BORDER DYNO SERVICE - 4	UTE
MV\039	Albury - Workshop	VehService				18/10/2023	391000	Repair	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	Albury Workshop	UTE
			CHECK STARTING ISSUE. TEST AND DIAGNOSE FAULTY BATTERY. REMOVE AND REPLACE WITH NEW CHECK STARTING AND CHARGING OK CHECK LHS HEADLIGHT NW- CONNECT SCAN TOOL- LOCATE MULTIPLE CODES CLEAR CODES. GET WIRING DIAGRAM TEST AND FOUND BCM GETTING INPUTS BUT NOT OUTPUTTING TO LHS													
MV\039	Albury - Workshop	Engine\BATTERY	DIAGNOSE FAULTY BCM- CONTACTED SHAUN			04/10/2023		Repair	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	Albury Workshop	UTE
MV\039	Albury - Workshop	Tyres				10/09/2023		Repair	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	Albury Workshop	UTE
MV\039	Albury - Workshop	Unknown	Log Book Service 351,400kms			02/08/2023	351400	Repair	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	Albury Workshop	UTE
MV\039	Albury - Workshop	Tyres\Punct	Puncture			27/07/2023		Repair	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	Albury Workshop	UTE
MV\039	Wodonga - Workshop	VehService\BS	requires 340km service	VehService\BS	Grealy Motors to complete	01/06/2023	391000	Service	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	Wodonga Workshop	UTE
MV\039	Wodonga - Workshop	DrivLine\GEARBOX	check over fault with gearstick. No alignment finger gates between gears found rims full of mud and missing weights I resurres wheel balancel FORD RANGER,REGO NO ABL-741@331312KMS		Grealy motors to repair	01/06/2023	391000	Repair	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	Wodonga Workshop	UTE
MV\039	Albury - Workshop	Brakes	REMOVE AND REPLACE TAILSHAFT DAMPNER AND REAR BRAKES FORD RANGER,REGO NO ABL-741@331312KMS			28/04/2023	334920	Repair	Completed	Greenfreight Loxeine NSW	UTES	Rosewood	OPS	ABL741	Albury Workshoao	UTE
MV\039	Albury - Workshop	VehService	330000KM SERVICE AND CHECKOVER,REBOOK WITH CHRIS FOR REAR BRAKES.			02/04/2023	331312	Repair	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	Albury Workshop	UTE
MV\039	Albury - Workshop	Tyres\CLEANSKIN	supply and fit 4 tyres			25/01/2023		Repair	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	Albury Workshop	UTE
MV\039	Albury - Workshop	VehService	320000km service			19/01/2023	321503	Repair	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	Albury Workshop	UTE
					CONNECT GAUGES, RUN AIR CONDITIONER, SYSTEM PRESSURES OK. CHECK AND CLEAN CABIN FILTER / CONDENSER AND INTER COOLER. VENT OUTLET -2 DEG @ 16 DEG AMBIENT TEMPERATURE. ORIGINAL PROBLEM WAS INTERMITTENT COOLING / UNABLE											
MV\039	Albury - Workshop	Air Con\AIR CON	SERVICE CALL TO GREEN FREIGHT TO INSPECT AIR CONDITIONER ON FORD RANGER.		TO FAULT ON TEST.	13/12/2022		Repair	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	Albury Workshop	UTE
MV\039	Albury - Workshop	Body\WINDSCREEN	chip repair			16/11/2022		Repair	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	Albury Workshop	UTE
MV\039	Wodonga - Workshop	DrivLine\CLUTCH	CHECKED GEARBOX AND CLUTCH REPLACEMENT CARRIED OUT AT MERIMBULA. Gear box already removed, total labour is for the box removal and new			28/10/2022		Repair	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	Wodonga Workshop	UTE
MV\039	Albury - Workshop	DrivLine\GEARBOX	reco one out in with new clutch kit			11/10/2022		Repair	Completed	Greenfreight Loxeine NSW	UTES	Rosewood	OPS	ABL741	Albury Workshoao	UTE
MV\039	Albury - Workshop	DrCabRep\WIPERS	TCTC supply parts			01/09/2022	391000	Repair	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	Albury Workshop	UTE
MV\039	Albury - Workshop	VehService	Log Book Service 300,000km's			26/07/2022	300263	Repair	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	Albury Workshop	UTE
MV\039	Rosewood - Workshop	Brakes	CHECKED REAR BRAKE AND WHEEL NUTS.			25/06/2022		Repair	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	Rosewood Workshop	UTE
MV\039	Albury - Workshop	Body\WINDSCREEN	Replace windscreen			27/05/2022		Repair	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	Albury Workshop	UTE
MV\039	Albury - Workshop	VehService\AS	290,000KM SERVICE			20/05/2022		Service	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	Albury Workshop	UTE
					Opened up wiring loom and removed section with broken wires. Made up new loom and soldered in. Replaced both											
MV\039	Albury - Workshop	Brakes\ABS	CUSTOMER REQUEST rewire ABS sensors on diff		senior connectors as pins corroded. Secured wires and reassembled. Cleared codes and took for test drive- tested ok. -Zac	11/03/2022		Repair	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	Albury Workshop	UTE
					Scanned and recorded codes EGR valve - to remove and check/assess - clean or if no good - may need to order replacement. -Steve 12/1- strip down and cleaned intact manifold, removed and replaced glow plugs, removed EGR valve - found to be faulty. Fit new EGR valve. Reassembled car. Test drove - all ok. LH rear WSS fault. Remove and replace wheel speed sensor, tested - all OK Sam Faulted again. Check over ABS codes had right and left rear wheel speed sensor faults. Needs rear harness to be pulled apart and check for and breaks or rubber wires. Possible need loom CODES: P067400 - CYLINDER 4 GLOW PLUG CIRCUIT P119300 - EXHAUST GAS RECIRCULATION DRIVER OVER CURRENT P040314 - EXHAUST GAS RECIRCULATION VALVE P040312 - EXHAUST GAS RECIRCULATION VALVE POSITION CONTROL CIRCUIT P040315 - EXHAUST GAS RECIRCULATION VALVE POSITION CONTROL CIRCUIT U041829 - INVALID DATA RECEIVED FROM BRAKE SYSTEM CONTROL MODULE											
MV\039	Albury - Workshop	Engine\FAULT CODE	CUSTOMER REQUEST diagnostic - feels like wants to surge		C003701 - LEFT REAR WHEEL SPEED SENSOR Codes:- P0674-00 - Cylinder 4 glow plug circuit. P064C-00 - Glow plug control module. P1193-00 - EGR driver over current. P043-11 - EGR control circuit. P0403-14 - EGR control circuit. P0403-12 - EGR control circuit. P0403-15 - EGR control circuit. U0418-29 - Invalid data received from brake system control module. C0037-01 - Left rear wheel speed sensor. P0403 - EGR "A" control circuit/ open. P1193 - Manufacturer specific.	28/01/2022		Repair	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	Albury Workshop	UTE
			check codes in car, found codes relating to EGR and glow plugs, found one code under ABS relating to traction													
MV\039	Albury - Workshop	Engine\FAULT CODE	control, but code cleared out, refer to photos to see codes, test all working okay		U0148 - Invalid data received from brake system control module "A".	19/11/2021		Repair	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	Albury Workshop	UTE
MV\039	Albury - Workshop	VehService\AS	270000km Service			27/08/2021	269281	Service	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	Albury Workshop	UTE
MV\039	Albury - Workshop	Tyres\TP1+2	Supply and fit 4 tyres			07/08/2021		Repair	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	Albury Workshop	UTE
MV\039	Albury - Workshop	Tyres\TP3+4	Tyre Position 3 + 4			07/08/2021		Repair	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	Albury Workshop	UTE
MV\039	Rosewood - Workshop	VehService\AS	260000km Service			04/06/2021		Service	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	Rosewood Workshop	UTE
MV\039	Rosewood - Workshop	Elect\DRV LIGHT	rewire driving lights with additional light and plug wire up put of DRL circuit to be finished ASAP diagnose engine light and abs light on found a flash code for fuel rail pressures test drove and checked for visual problems			06/05/2021	257787	Repair	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	Rosewood Workshop	UTE
MV\039	Rosewood - Workshop	Engine\FAULT CODE	oraenised reaseis at Tumut for ute to eet there repair inoperative (intermittent) driving lights. Blowing fuses suspect faulty, sub quality relay. Replaced			30/12/2020		Repair	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	Rosewood Workshop	UTE
MV\039	Rosewood - Workshop	Elect\DRV LIGHT	fitted auto reset circuit breaker			02/12/2020		Repair	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	Rosewood Workshop	UTE
MV\039	Myrtleford - Workshop	Elect\BATTERY	supply and fit new battery			30/10/2020	241970	Repair	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	Myrtleford Workshop	UTE
MV\039	Albury - Workshop	Air Con\AIR CON	REPAIR AC			25/01/2019		Repair	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	Albury Workshop	UTE
MV\039	Albury - Workshop	Engine\ENG FAN	replace vicious fan hub. Driving light stay broken off bolt in housing		PARTS ORDERED 9/01/2019	10/01/2019		Repair	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	Albury Workshop	UTE
MV\039	Rosewood - Workshop	Elect\DRV LIGHT	drilled it out and fitted washer and self tapping screw			26/10/2018	172858	Repair	Completed	Greenfreight Loxeine NSW	UTES	Rosewood	OPS	ABL741	Rosewood Workshoa	UTE
MV\039	Albury - Workshop	Elect\BATTERY	REPLACE FAULTY BATTERY		REPLACED BY TAE.	04/07/2018	161495	Repair	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	Albury Workshop	UTE
MV\039	Myrtleford - Workshop	VehService	150000KLM SERVICE			15/03/2018		Repair	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	Rosewood Workshop	UTE
MV\039	Albury - Workshop	DrCabElect\RADIO	UHF NOT WORKING		REPLACED HAND PIECE	02/03/2018		Repair	Completed	Greenfreight Logging NSW	UTES	Rosewood	OPS	ABL741	Albury Workshop	UTE