| EquipmentName | Workshop | CodeAndSubCode | Description | Schedule | CompletionComments | DateDone | DistanceDone | Worktype | Workstate | CreatedByUser | EquipmentOwner | MaintenanceGroup | Location | Division | Rego | Supplier | EquipmentType |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| MV4017 | Myrtleford - Workshop | VehService\BS | B Service | VehService\BS | | 02/09/2026 | 400000 | Service | Completed | Brenton Durling | Greenfreight Logging Vic | UTES | Myrtleford | MAD | 1BA6DY | Myrtleford Workshop | UTE |
| MV4017 | Myrtleford - Workshop | Brakes\BRK RELINE | REPLACE BRAKE PADS AND SHOES- FOUND LOW IN SERVICE | | | 02/09/2026 | 400000 | Repair | Completed | Brenton Durling | Greenfreight Logging Vic | UTES | Myrtleford | MAD | 1BA6DY | Myrtleford Workshop | UTE |
| MV4017 | Myrtleford - Workshop | Cooling\COOL LEAKS | COOLANT UNDER UTE ( WATER PUMP NEEDS REPLACING ) | | Removed & replaced water pump, removed & replaced rubbed hose from water pump to block. Removed & replaced coolant & bleed. | 02/09/2026 | 400000 | Repair | Completed | Brenton Durling | Greenfreight Logging Vic | UTES | Myrtleford | MAD | 1BA6DY | Myrtleford Workshop | UTE |
| MV4017 | Myrtleford - Workshop | Elect\ELECT P&W | REPLACE RH HEAD LIGHT GLOBE | | | 10/07/2026 | 400000 | Repair | Completed | Brenton Durling | Greenfreight Logging Vic | UTES | Myrtleford | MAD | 1BA6DY | Myrtleford Workshop | UTE |
| MV4017 | Myrtleford - Workshop | Elect\TAIL LIGHT | REPLACE LHR TAIL LIGHT | | | 26/06/2026 | 344800 | Repair | Completed | Wayne De La Rue | Greenfreight Logging Vic | UTES | Myrtleford | MAD | 1BA6DY | Myrtleford Workshop | UTE |
| MV4017 | Myrtleford - Workshop | Tyres\BALANCE | Tyres\BALANCE | | WHEEL BALANCE | 19/06/2026 | 344800 | Repair | Completed | Jess Fittock | Greenfreight Logging Vic | UTES | Myrtleford | MAD | 1BA6DY | SUNDAY TYRES | UTE |
| | | | | | Checked codes. Found codes for both rear wheels. Checked and inspected plugs on both wheel speed sensor and on the abs unit. Used vacc to get the pin out and the test procedure. After the first test, which was blaming the abs unit, did a continuity test from unit to the plugs and found no continuity for 2 wires. Removed panels on passenger side and did the continuity test between abs unit and the plug behind the panel just before the end of the cabin. Found continuity, tried the same test from the plug to the wheel speed sensors and confirmed fault was under the tub. Inspected harness, had to remove the harness to inspect properly as there was no obvious damage. Unplugged and removed the harness, removed split tube and tape. Found the wires for the wheel speed sensor been damage by the factory p-clamps. 4 wires were damage but only two were damage to the core. Cut and replaced the wires. Secured and tested | | | | | | | | | | |
| MV4017 | Myrtleford - Workshop | DrCabElect\ELECT P&W | DrCabElect\ELECT P&W<br>L134284 | | | 03/06/2026 | 344800 | Repair | Completed | Jess Fittock | Greenfreight Logging Vic | UTES | Myrtleford | MAD | 1BA6DY | ARKON AUTO ELECTRICAL - 3 | UTE |
| MV4017 | Myrtleford - Workshop | Tyres\TP1+2 | Tyres\TP1+2 | | | 30/03/2026 | 344800 | Repair | Completed | Jess Fittock | Greenfreight Logging Vic | UTES | Myrtleford | MAD | 1BA6DY | SUNDAY TYRES | UTE |
| MV4017 | Myrtleford - Workshop | Tyres\TP3+4 | Tyres\TP3+4 | | | 30/03/2026 | 344800 | Repair | Completed | Jess Fittock | Greenfreight Logging Vic | UTES | Myrtleford | MAD | 1BA6DY | SUNDAY TYRES | UTE |
| MV4017 | Myrtleford - Workshop | Prevent\WHEEL ALGN | Prevent\WHEEL ALGN | | | 30/03/2026 | 344800 | Repair | Completed | Jess Fittock | Greenfreight Logging Vic | UTES | Myrtleford | MAD | 1BA6DY | SUNDAY TYRES | UTE |
| MV4017 | Myrtleford - Workshop | VehService\BS | VehService\BS B Service<br>REPLACE RADIATOR ASM | VehService\BS | | 20/02/2026 | 344800 | Service | Completed | Kevin Drum | Greenfreight Logging Vic | UTES | Myrtleford | MAD | 1BA6DY | Wodonga Workshop | UTE |
| MV4017 | Myrtleford - Workshop | Cooling\RADIATOR | REPLACE FAN CLUTCH | | | 06/02/2026 | 344800 | Repair | Completed | Wayne De La Rue | Greenfreight Logging Vic | UTES | Myrtleford | MAD | 1BA6DY | Myrtleford Workshop | UTE |
| MV4017 | Myrtleford - Workshop | Engine\ALT | Engine\ALT | | | 15/01/2026 | 344800 | Repair | Completed | Jess Fittock | Greenfreight Logging Vic | UTES | Myrtleford | MAD | 1BA6DY | ARKON AUTO ELECTRICAL - 3 | UTE |
| MV4017 | Myrtleford - Workshop | Susp\SPRING PACK | replace front & rear suspension spring packs x 4<br>Body\DAMAGE | | | 28/10/2025 | 344800 | Repair | Completed | Wayne De La Rue | Greenfreight Logging Vic | UTES | Myrtleford | MAD | 1BA6DY | WANGARATTA SPRING WORKS - 3 | UTE |
| MV4017 | Myrtleford - Workshop | Body\DAMAGE | repair roo damage to left hand side of ute and polish car | | | 28/10/2025 | 344800 | Repair | Completed | Wayne De La Rue | Greenfreight Logging Vic | UTES | Myrtleford | MAD | 1BA6DY | BRIGHT SMASH REPAIRS | UTE |
| | | | | | Odometer Reading: 391545Km<br>Penrite Engine Flush (Yes)<br>Replaced Engine Oil & Oil Filter (Yes)<br>Replaced Air Filter (Yes)<br>Replaced Cabin Filter (Yes)<br>Replaced Fuel Filter (Yes- as requested)<br>Replaced Sump Plug Washer (Yes)<br>Rapid Windscreen Wash (Yes)<br>Add Diesel Fuel Conditioner (Yes)<br>Battery Test - (Pass)<br>Brake Fluid Test - (Pass)<br>Brake Pad Life Remaining - Front = 80 % Rear = 80 %<br>Invoice Notes<br>SafeTstop Check: Alignment, Brakes & Handbrake With Report (Yes)<br>Alignment Quick Check (Pass)<br>Clean MAF Sensor (Yes)<br>Adjust hand brake (Yes)<br>Transmission Fluid - (Checked)<br>Differential Fluid Front (Checked) Rear (Checked)<br>Transfer Case Fluid - (Checked)<br>Clutch Fluid - (Checked)<br>Brake Fluid - (Checked)<br>Coolant - (Checked)<br>Belts - (Checked)<br>Lights - (Checked)<br>Tyre Tread - Front (Good) Rear - (Good) | | | | | | | | | | |
| MV4017 | Myrtleford - Workshop | VServLab | VEHICLE SERVICE | | Test Drive Vehicle (Yes) | 02/10/2025 | 344800 | Repair | Completed | Jess Fittock | Greenfreight Logging Vic | UTES | Myrtleford | MAD | 1BA6DY | SUNDAY TYRES | UTE |
| MV4017 | Myrtleford - Workshop | VehService\BS | VehService\BS | VehService\BS | COMPLETED BY SUNDAY TYRES | 20/03/2025 | 344800 | Service | Completed | Jenny Pearce | Greenfreight Logging Vic | UTES | Myrtleford | MAD | 1BA6DY | Myrtleford Workshop | UTE |
| | | | | | Service<br>Service kit contains oil filter, fuel filter, air filter and cabin filter.<br>rear brake shoes 2mm<br>front brake pads 10mm<br>driveline oils ok<br>brake fluid ok<br>coolant ok<br><br>Right hand rear wheel speed sensor fault present on diagnostics scan. if code returns rec. wheel speed sensor replacement. | | | | | | | | | | | | |
| MV4017 | Myrtleford - Workshop | VehService\BS | B Service. (Sunday Tyres) | VehService\BS | | 26/10/2024 | 344800 | Service | Completed | Shaun Morton | Greenfreight Logging Vic | UTES | Myrtleford | MAD | 1BA6DY | SUNDAY TYRES | UTE |
| MV4017 | Myrtleford - Workshop | Insp\ANN INSP | Annual Inspection. (Sunday Tyres) | Insp\ANN INSP | | 26/10/2024 | 344800 | PreventativeMaintenance | Completed | Shaun Morton | Greenfreight Logging Vic | UTES | Myrtleford | MAD | 1BA6DY | SUNDAY TYRES | UTE |
| MV4017 | Myrtleford - Workshop | Tyres\TP1+2 | Tyres\TP1+2 | | | 16/08/2024 | 344800 | Repair | Completed | Kristen Murrell | Greenfreight Logging Vic | UTES | Myrtleford | MAD | 1BA6DY | BEAUREPAIRES - 3 | UTE |
| MV4017 | Myrtleford - Workshop | Tyres\TP3+4 | Tyres\TP3+4 | | | 16/08/2024 | 344800 | Repair | Completed | Kristen Murrell | Greenfreight Logging Vic | UTES | Myrtleford | MAD | 1BA6DY | BEAUREPAIRES - 3 | UTE |
| MV4017 | Wodonga - Workshop | DrCabReo\WINDOW REG | REAIRED DRIVERS DOOR WINDOW | | | 18/06/2024 | 344800 | Fault | Completed | Kevin Drum | Greenfreight Logging Vic | UTES | Myrtleford | MAD | 1BA6DY | Wodonga Workshop | UTE |
| MV4017 | Wodonga - Workshop | Elect\DRV LIGHT | REPLACED DRIVING LIGHTS. | | | 18/06/2024 | 344800 | Fault | Completed | Kevin Drum | Greenfreight Logging Vic | UTES | Myrtleford | MAD | 1BA6DY | Wodonga Workshop | UTE |
| MV4017 | Myrtleford - Workshop | VehService\BS | VehService\BS<br>REPLACE BOOST HOSE | VehService\BS | | 29/05/2024 | 343464 | Service | Completed | Dean Salmon | Greenfreight Logging Vic | UTES | Myrtleford | MAD | 1BA6DY | DONDIO'S MECHANICAL REPAIRS-3 | UTE |
| MV4017 | Myrtleford - Workshop | Engine | BLACKLOCKS SUPPLY | | | 21/02/2024 | 335417 | Repair | Completed | Jenny Pearce | Greenfreight Logging Vic | UTES | Myrtleford | MAD | 1BA6DY | Albury Workshoo | UTE |
| MV4017 | Myrtleford - Workshop | VehService | LOG BOOK SERVICE<br>Removed & replaced front brake pads | | | 07/12/2023 | | Repair | Completed | Jenny Pearce | Greenfreight Logging Vic | UTES | Myrtleford | MAD | 1BA6DY | Albury Workshoo | UTE |
| MV4017 | Myrtleford - Workshop | Brakes | Removed & replaced fuel filter | | | 19/04/2023 | | Repair | Completed | Jenny Pearce | Greenfreight Logging Vic | UTES | Myrtleford | MAD | 1BA6DY | Albury Workshop | UTE |
| MV4017 | Myrtleford - Workshop | Engine\BATTERY | Mvrt Auto Supply Battery<br><br>Service details:<br>Replaced engine oil & oil filter with approved OEM specification.<br>Checked air & cabin filters & replaced if required.<br>Check sump plug seal/washer & replace if required.<br>Checked fluid levels & topped up as required.<br>Checked cooling system & associated hoses.<br>Checked for oil & fluid leaks.<br>Grease all required components<br>Checked condition & operation of all relevant safety items;<br>EG: Brakes, steering, suspension, seat belts, lights, horn & wipers ect. | | | 01/04/2023 | | Repair | Completed | Jenny Pearce | Greenfreight Logging Vic | UTES | Myrtleford | MAD | 1BA6DY | Albury Workshoo | UTE |
| MV4017 | Myrtleford - Workshop | VehService | Checked tyre condition & pressure (inc spare). inflated as required. | | | 11/02/2023 | 307009 | Repair | Completed | Jenny Pearce | Greenfreight Logging Vic | UTES | Myrtleford | MAD | 1BA6DY | Albury Workshop | UTE |
| | | | | | NOTES<br>RH tie rod boot split (replaced)<br>LH Tie rod end worn (replaced)<br>Rear tail shaft centre flange nut loose (Tail shaft must be removed to repair & tightened) done | | | | | | | | | | | | |
| MV4017 | Myrtleford - Workshop | Steering\WHEEL ALGN | Wheel Alignment 4X4 | | Replaced fuel filter | 16/09/2022 | 296634 | Repair | Completed | Jenny Pearce | Greenfreight Logging Vic | UTES | Myrtleford | MAD | 1BA6DY | DONDIO'S MECHANICAL REPAIRS-3 | UTE |
| MV4017 | Myrtleford - Workshop | VehService | Vehicle service at Dondio's | | | 06/09/2022 | | Repair | Completed | Jenny Pearce | Greenfreight Logging Vic | UTES | Myrtleford | MAD | 1BA6DY | Myrtleford Workshop | UTE |
| MV4017 | Myrtleford - Workshop | Tyres\CLEANSKIN | fit 4 tyres | | | 02/09/2022 | | Repair | Completed | Jenny Pearce | Greenfreight Logging Vic | UTES | Myrtleford | MAD | 1BA6DY | Myrtleford Workshoo | UTE |
| MV4017 | Myrtleford - Workshop | VehService\AS | 270000km service - blacklocks<br>Check for rattle whilst driving.<br>Confirmed fault. inspected intercooler hose all ok.<br>checked for exhaust leaks all ok<br>found rear uni on tail shaft damaged by excessive movement<br>removed tail shaft<br>removed and replaced uni as per wsm<br>reinstalled shaft | | | 21/08/2021 | 270344 | Service | Completed | Jenny Pearce | Greenfreight Logging Vic | UTES | Myrtleford | MAD | 1BA6DY | Myrtleford Workshoo | UTE |
| MV4017 | Myrtleford - Workshop | DrivLine\UNI JOINTS | roadtest all ok | | | 16/04/2021 | 261000 | Repair | Completed | Jenny Pearce | Greenfreight Logging Vic | UTES | Myrtleford | MAD | 1BA6DY | Myrtleford Workshop | UTE |
| | | | C/S: check and report on injectors were replaced sep 2020 246000kms. vehicle has just started to rattle a bit when accelerating. more in lower gears. seems a bit "fluffy" above idle. customer believes that it could either be the cv joint or the front wheel bearing under hard acceleration<br>Checked engine light on.<br>Injectors were replaced in September 2020 at 246,000kms.<br>Checked for history and current DTC's - found codes for cylinders 1-4 injectors leaking. Carried out injector leak back test, tested all ok. Carried out a PCM software updated, checked for injector configurations. Cleared DTC's - all ok.<br>Checked rattle.<br>Found front drive shaft rear CV boot split, front shaft also has a loud rattle. Requires replacing. Carried out a removal and replacement of the front shaft. Carried out a road test, vehicle does not have a rattle sound after | | | | | | | | | | | | | | |
| MV4017 | Myrtleford - Workshop | DrivLine\DRIVES | replacement. | | | 15/04/2021 | 260181 | Repair | Completed | Jenny Pearce | Greenfreight Logging Vic | UTES | Myrtleford | MAD | 1BA6DY | Myrtleford Workshop | UTE |
| MV4017 | Myrtleford - Workshop | DrCabElect\RADIO | replace UHF antenna | | | 23/12/2020 | 253221 | Repair | Completed | One Half | Greenfreight Logging Vic | UTES | Myrtleford | MAD | 1BA6DY | Myrtleford Workshop | UTE |
| MV4017 | Myrtleford - Workshop | Engine\FAULT CODE | Replace 5 injectors | | | 03/09/2020 | 245000 | Repair | Completed | | Greenfreight Logging Vic | UTES | Myrtleford | MAD | 1BA6DY | BLACKLOCKS - 3 | UTE |
| MV4017 | Myrtleford - Workshop | Engine\FAULT CODE | Replace Glow plugs | | | 03/09/2020 | 245000 | Repair | Completed | | Greenfreight Logging Vic | UTES | Myrtleford | MAD | 1BA6DY | BLACKLOCKS - 3 | UTE |
| MV4017 | Myrtleford - Workshop | Engine\FILTERS | replace fuel filters | | | 03/09/2020 | 245000 | Repair | Completed | | Greenfreight Logging Vic | UTES | Myrtleford | MAD | 1BA6DY | BLACKLOCKS - 3 | UTE |
| MV4017 | Myrtleford - Workshop | Engine\EXHAUST | clean egr valve | | | 30/06/2020 | 241760 | Repair | Completed | | Greenfreight Logging Vic | UTES | Myrtleford | MAD | 1BA6DY | Myrtleford Workshop | UTE |
| MV4017 | Myrtleford - Workshop | VehService\BS | 240,000 Service and replace all filters and check over | VehService\BS | | 30/06/2020 | 241760 | Service | Completed | | Greenfreight Logging Vic | UTES | Myrtleford | MAD | 1BA6DY | Myrtleford Workshop | UTE |
| MV4017 | Myrtleford - Workshop | VehService | carry out 230,000 ser and check over | | | 27/11/2019 | 230812 | Repair | Completed | | Greenfreight Logging Vic | UTES | Myrtleford | MAD | 1BA6DY | Myrtleford Workshop | UTE |
| MV4017 | Myrtleford - Workshop | Elect\BATTERY | supply and fit new battery | | | 05/04/2018 | 189400 | Repair | Completed | | Greenfreight Logging Vic | UTES | Myrtleford | MAD | 1BA6DY | Myrtleford Workshop | UTE |