EquipmentName	Workshop	CodeAndSubCode	Description	Schedule	CompletionComments	DateDone	DistanceDone	Worktype	Workstate	EquipmentOwner	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
T200	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS	Jamie and cheyne on service	08/07/2026	8724	Service	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Tyres\TP9+10	Tyres\TP9+10 (29-30)			25/06/2026	8724	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	BORDER BANDAG PTY LTD	TRAILER
T200	Wodonga - Workshop	Tyres\RUN OUT	Tyres\RUN OUT POS 25-26			25/06/2026	8724	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	BORDER BANDAG PTY LTD	TRAILER
T200	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		12/05/2026	8724	Service	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Insp\ANN INSP	Insp\ANN INSP Annual inspection as per check list	Insp\ANN INSP		12/05/2026	8724	PreventativeMaintenance	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		16/04/2026	8724	Service	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS	John,,,Corey	18/03/2026	8724	Service	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Tyres\TP3+4	Tyres\TP3+4 (23-24)			28/02/2026	8724	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	BORDER BANDAG PTY LTD	TRAILER
T200	Wodonga - Workshop	Tyres\TP11+12	Tyres\TP11+12 (31-32)			28/02/2026	8724	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	BORDER BANDAG PTY LTD	TRAILER
T200	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		14/02/2026	8724	Service	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS	-service	13/12/2025	8724	Service	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		24/10/2025	8724	Service	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Tyres\Punct	Tyres\Punct POS 29			27/08/2025	8724	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	BORDER BANDAG PTY LTD	TRAILER
T200	Wodonga - Workshop	Elect\INDICATORS	No L/H Indicator			28/07/2025	8724	Fault	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		18/07/2025	8724	Service	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Susp\AIR BAG	Replace LHF RHF RHR airbags		Must of been Previously completed uponinspection bag seem to be fine,,,,,	18/07/2025	8724	Fault	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Workshop\MOVE ASSET	Take to TCTC to have inspected to clear defects			27/06/2025	8724	Fault	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Insp\DEFECT	Clear Defect (NSW). (TCTC P/O: WW095203)			26/06/2025	8724	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	TWIN CITY TRUCK CENTRE - OLD	TRAILER
T200	Wodonga - Workshop	Elect\TAIL LIGHT	CLEAR DEFECT- LIGHTS NOT WORKING		DIAGNOSED AND REPAIRED WIRNG. REPLACED SOCKET.	24/06/2025	8724	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		13/06/2025	8724	Service	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Brakes\AIR LEAK	KEEPS DUMPING AIR.		Moved trailers into workshop. Inspected combination for air leaks. Found LHF RHF RHR airbags on T200 leaking. Ordered airbags ready for when in next for service. Parked trailers	01/05/2025	8724	Fault	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Elect\TAIL LIGHT	left side tail light not working			04/04/2025	8724	Fault	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection	Insp\ANN INSP		04/04/2025	8724	PreventativeMaintenance	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		04/04/2025	8724	Service	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Tyres\TP7+8	Tyres\TP7+8			20/03/2025	8724	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	BEAUREPAIRES	TRAILER
T200	Wodonga - Workshop	Tyres\TP9+10	Tyres\TP9+10			20/03/2025	8724	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	BEAUREPAIRES	TRAILER
T200	Wodonga - Workshop	Tyres\TP1+2	Tyres\TP1+2			20/03/2025	8724	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	BEAUREPAIRES	TRAILER
T200	Wodonga - Workshop	Elect\BRK LIGHT	NO BRAKE LIGHTS. TRAILER LIGHTS FLICKERING.		REPLACED LIGHTS PLUG ON #976.	14/03/2025	8724	Fault	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		08/03/2025	8724	Service	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Brakes\AIR LEAK	Losing too much air whilst braking.		Nothing found	20/12/2024	8724	Fault	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		12/12/2024	8724	Service	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Tyres\Punct	Repair Tyre Puncture Position 2. (Wodonga Tyre & Auto P/O: WW090162)			08/11/2024	8724	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	BEAUREPAIRES	TRAILER
T200	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		06/11/2024	8724	Service	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		20/09/2024	8724	Service	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	VehService\DS	D Service	VehService\DS		22/08/2024	8724	Service	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Elect\TRL LIGHTS	New trailer cord needed between A & B trailer		REPAIRED RUBBED LIGHTS LEAD. LEAD HAD BEEN TAPED UP AT SERVICE. CUT TO LENGTH AND WIRED PLUG. TESTED. OK.	04/05/2024	7058	Fault	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Brakes\AIR LEAK	repair air leaks			30/04/2024	273636	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			27/04/2024	273618	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	VehService\DS		27/04/2024	273618	Service	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	DrivLine\WHEEL BRGS	REBUILT HUBS.			25/04/2024	8724	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Brakes\BRK RELINE	Brake Reline.			19/04/2024	273598	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Body\STRAPS	PLEASE ORDER 2 x BOXES 11 METRE STRAPS. MUST BE 11 METRES AS 9M ARE TOO SHORT. PLEASE LET KEN KNOW WHEN THEY SHOW UP.			19/04/2024	273598	Fault	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Insp\DEFECT	repair and clear defect #VN0682897		CLEAR RMS DEFECT NOTICE NUMBER HVN0682897	19/04/2024	273598	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Brakes\BOOSTER	AIR LEAKS. TRAILERS RUN OUT OF AIR WHEN STOPPED AT TRAFFIC LIGHTS. SUSPECT LEAKING BOOSTER.			23/03/2024		Fault	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Brakes\AIR LEAK	AIR LEAKS. TRAILERS RUN OUT OF AIR WHEN STOPPED AT TRAFFIC LIGHTS. SUSPECT			22/03/2024		Fault	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Tyres\TP08	Tyre Position 8			01/02/2024		Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Albury Workshop	TRAILER
T200	Wodonga - Workshop	Tyres\TP11+12	Tyre Position 11 + 12			01/02/2024		Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Albury Workshop	TRAILER
T200	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			04/11/2023	250128	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	VehService\DS	ADJUSTED RR WHEEL BEARING	04/11/2023	250128	Service	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Body\MUDGUARDS	REPLACED 3 GUARDS.			04/11/2023	250128	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Brakes\BRK RELINE	FULL RELINE.			04/11/2023	10226	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Body\TRL GATES	Check All Gates			04/11/2023	10226	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Tyres\TP9+10	Tyre Position 9 + 10			02/11/2023		Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Albury Workshop	TRAILER
T200	Wodonga - Workshop	Elect\ELECT P&W	TRAVEL TO JOB TEST AND FOUND TRAILER LIGHT WORKING FINE IN BOTH TRAILER PLUGS REQUEST TRUCK TO BE HOOKED UP TRAVEL BACK travel to job test and found brake light stuck on test trailer plug and found no power on brake light wire check all lights and found no power on brake light wire diagnose faulty tail lights remove and replace tail light combo on B trailer test and found all ok A trailer still needs to be replaced pack up and travel back			27/10/2023		Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Albury Workshop	TRAILER
T200	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			02/09/2023	242087	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Body\MUDGUARDS	MISSING GUARD REAR RHS.			02/09/2023	242087	Fault	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Body\MUDGUARDS	MISSING GUARD REAR RHS.			02/09/2023	242087	Fault	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Elect\BRK LIGHT	BRAKE LIGHT ISSUE.			02/09/2023	242087	Fault	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Body\MUDGUARDS	MISSING GUARD RHS.			02/09/2023	242087	Fault	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	VehService\DS		02/09/2023	242087	Service	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Brakes\BRK RELINE	FULL RELINE.			02/09/2023	242087	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			15/07/2023	234120	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	VehService\DS		15/07/2023	234120	Service	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Insp\ANN INSP	Annual inspection as per check list	Insp\ANN INSP		15/07/2023	234120	PreventativeMaintenance	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Chassis\MUDGUARDS	Left Rear guard.			15/07/2023	234120	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Brakes\BRAKE ADJ	BRAKES ADJUSTMENT.		ADJUSTED BOTH TRAILERS.	16/06/2023		Fault	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	DrivLine\WHL HUB	REPLACED ODOMETRE MOUNT.			09/05/2023		Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Tyres\TP7+8	Tyre Position 7 + 8			02/05/2023		Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Albury Workshop	TRAILER
T200	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			21/03/2023	217572	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Elect\ELECT P&W	REPAIR NO. PLATE LIGHT.			21/03/2023	217572	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Brakes\BOOSTER	BLOWN BOOSTER FRONT RHS AXLE. BOOSTER HAS BEEN SCREWED OFF.			21/03/2023	217572	Fault	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	VehService\DS	ADJUSTED LR WHEEL BEARING.	21/03/2023	217572	Service	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Tyres\TP9+10	Tyre Position 9 + 10			02/03/2023		Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Albury Workshop	TRAILER
T200	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			26/11/2022	200204	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Myrtleford Workshop	TRAILER
T200	Wodonga - Workshop	Susp\SPRNG HANG	FRONT HANGERS CRACKED. FRONT ARMS CRACKED.			26/11/2022	200204	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Myrtleford Workshop	TRAILER
T200	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	VehService\DS		26/11/2022	200204	Service	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Myrtleford Workshop	TRAILER
T200	Wodonga - Workshop	Body\MUDGUARDS	REPLACED REAR MUDGUARDS AND MUDFLAPS.			26/11/2022	200204	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Myrtleford Workshop	TRAILER
T200	Wodonga - Workshop	Elect\ELECT P&W	REPAIR NO. PLATE LIGHT.			26/11/2022	200204	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Myrtleford Workshop	TRAILER
T200	Wodonga - Workshop	Brakes\BOOSTER	REPLACED RF RR BOOSTERS.			26/11/2022	200204	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Myrtleford Workshop	TRAILER
T200	Wodonga - Workshop	Susp\AIR BAG	REPLACED LF AIRBAG.			26/11/2022	200204	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Myrtleford Workshop	TRAILER
T200	Wodonga - Workshop	Body\PANELS	BRING TO WORKSHOP FOR HYDRAULIC LID TO BE WELDED SHUT.			15/10/2022	187778	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Workshop\MOVE ASSET	MOVED ASSET.			12/10/2022		Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			07/10/2022	190832	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Chassis\CHAS CRACK	Roll back cable rack RHF			07/10/2022	190832	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Chassis\WHEEL BRGS	bearing grease needs inspection		Checked by Prestige.	07/10/2022	190832	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Tyres\TP07	RM INNER TYRE CRACKED.			07/10/2022	190832	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Chassis\TRL LEGS	LANDING LEGS BRACING NEEDS REPLACING.			07/10/2022	190832	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Brakes\BRK RELINE	RELINES DUE.		Reline done by Prestige PO# WW074493	07/10/2022	190832	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Elect\TRL LIGHTS	EARTH PIN ON PLUG LOOSE. ALL LIGHTS FLICKER. NEW PLUG NEEDED.			07/10/2022	190832	Fault	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Body\PANELS	PUMP/ BATTERY BOX DOOR CLIP BROKEN OFF.			07/10/2022	190832	Fault	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Brakes\BRAKE ADJ	BRAKE ADJUSTMENT.			07/10/2022	190832	Fault	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	VehService\DS		07/10/2022	190832	Service	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Unknown	OVERDUE FOR SERVICE.			07/10/2022	190832	Fault	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Workshop\MOVE ASSET	SPLIT TRAILERS.			04/10/2022		Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Brakes\BRAKE ADJ	Adjust Brakes			01/10/2022		Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Tyres\TP1+2	supply and fit 4 tyres			30/09/2022		Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Tyres\TP7+8	Tyre Position 7 + 8			30/09/2022		Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Tyres\TP5+6	supply and fit 4tyres			15/09/2022		Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Tyres\TP9+10	Tyre Position 9 + 10			15/09/2022		Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			10/08/2022	181552	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Chassis\CHAS CRACK	Roll back cable rack RHF			10/08/2022	181552	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Chassis\WHEEL BRGS	bearing grease needs inspection			10/08/2022	181552	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	VehService\DS		10/08/2022	181552	Service	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Brakes\BRK RELINE	RELINES DUE.			10/08/2022	181552	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Tyres\TP07	RM INNER TYRE CRACKED.			10/08/2022	181552	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Susp\SPRNG HANG	FRONT HANGERS CRACKED. FRONT ARMS CRACKED.			10/08/2022	181552	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Chassis\TRL LEGS	LANDING LEGS BRACING NEEDS REPLACING.			10/08/2022	181552	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Brakes\BRAKE ADJ	BRAKE ADJUSTMENT.			13/07/2022	176654	Fault	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			02/06/2022	170340	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	VehService\DS		02/06/2022	170340	Service	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			04/05/2022	614379	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Chassis\MUDGUARDS	Rear right has hole in it.			04/05/2022	614379	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Body\MUDGUARDS	RR MUDGUARD HAS HOLE			04/05/2022	614379	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Body\MUDGUARDS	RR MUDGUARD HAS A HOLE.			04/05/2022	614379	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Body\MUDGUARDS	LF RM GUARDS HAVE HOLES			04/05/2022	614379	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Body\MUDGUARDS	REAR LHS GUARD RIPPED AND WORNOUT.			04/05/2022	614379	Fault	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	VehService\DS		04/05/2022	614379	Service	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Tyres\TP11+12	Rear Right Hand Inner Tyre Flat. Replace by Beaurepairs at Wodonga Yard.. Rear Right Hand Inner Tyre Flat.			29/03/2022		Fault	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Chassis\MUDGUARDS	change LH rear mud guard			26/03/2022		Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			18/03/2022	157067	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Susp\WHEEL ALGN	boss kit movement			18/03/2022	157067	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Chassis\TRL LEGS	Leg supports & mounts bent			18/03/2022	157067	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Chassis\WHEEL BRGS	bearing grease needs inspection			18/03/2022	157067	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Susp\SPRNG PACK	R front axle hanger cracked			18/03/2022	157067	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Chassis\TP06	small body cracks forming			18/03/2022	157067	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Chassis\CHAS CRACK	Cross Brace Crack.			18/03/2022	157067	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Chassis\MUDGUARDS	Rear right has hole in it.			18/03/2022	157067	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Body\MUDGUARDS	RR MUDGUARD HAS HOLE			18/03/2022	157067	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Body\MUDGUARDS	RR MUDGUARD HAS A HOLE.			18/03/2022	157067	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Body\MUDGUARDS	LF RM GUARDS HAVE HOLES			18/03/2022	157067	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Susp\SPRNG HANG	LF RF HANGERS CRACKED			18/03/2022	157067	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Chassis\FIFTH WHEE	REPLACED TURNTABLE.			18/03/2022	157067	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	VehService\DS		18/03/2022	157067	Service	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Tyres\TP3+4	SUPPLY AND FIT 2TYRES			18/03/2022		Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Tyres\PRES CHECK	wheel nut indicators & pressure maint pos 1-12			18/02/2022	151624	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			25/01/2022	146467	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	VehService\DS		25/01/2022	146467	Service	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			23/12/2021	143944	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Elect\ELECT P&W	need trailer ply			23/12/2021	143944	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Body\MUDGUARDS	LF RM GUARDS HAVE HOLES			23/12/2021	143944	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Susp\SPRNG HANG	LF RF HANGERS CRACKED			23/12/2021	143944	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	52931S	Wodonga Workshop	TRAILER

T200	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	VehService\DS	ADJUSTED LF LR WHEEL BEARINGS			23/12/2021	143944	Service	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Tyres\TP9+10	supply and fit 2 tyres					24/11/2021	334325	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job					19/11/2021	136750	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Tyres\TP03	RHF INNER TYRE BALD					19/11/2021	136750	Fault	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	VehService\DS	ADJUSTED FR RR WHEEL BEARINGS.			19/11/2021	136750	Service	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Body\MUDGUARDS	RR MUDGUARD HAS A HOLE.					19/11/2021	136750	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Insp\ANN INSP	Annual inspection as per check list	Insp\ANN INSP				19/11/2021	136750	Preventative/Maintenance	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Tyres\TP3+4	Tyre Position 3 + 4					16/10/2021	129783	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job					05/10/2021	128043	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Elect\BATTERY	Retaining clips on Battery box for roll back motor brocken/missing. Door falls ooen and battery hanes out bv its leads. Retaining clips on Battery box for roll back motor brocken/missing.					05/10/2021	128043	Fault	Comoleted	FL Green Distribution	FRB	Wodonwa	LHB	529315	Wodonwa Workshop	TRAILER
T200	Wodonga - Workshop	Elect\BATTERY	Door falls open and battery hangs out by its leads.		#356007			05/10/2021	128043	Fault	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	VehService\DS				05/10/2021	128043	Service	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Brakes\BOOSTER	PICKED UP TRAILER. REPLACED LF BOOSTER AND DRAIN COCK.					05/10/2021	128043	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Body\MUDGUARDS	RR MUDGUARD HAS HOLE Moving trailers. Cleaning.					05/10/2021	128043	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Chassis\MUDGUARDS	Reolaced LHF Mudaeard.					25/08/2021		Repair	Completed	FL Green Distribution	FRB	Wodonwa	LHB	529315	Wodonwa Workshop	TRAILER
T200	Wodonga - Workshop	Chassis\MUDGUARDS	Front mudgaurd LHS coming off.		Refer Job# 351440			25/08/2021		Fault	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job					13/08/2021	120076	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	VehService\DS				13/08/2021	120076	Service	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Elect\SLID CCtL	Trailer plug is loose.					13/08/2021	120076	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Chassis\MUDGUARDS	Rear right has hole in it.					13/08/2021	120076	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	DriveLine\WHEEL BRGS	Adjusted LF, LR, RM, LM.					13/08/2021	120076	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Workshop\MOVE ASSET	Park outside from shed after repair.					13/08/2021	120076	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Brakes\BRAKE ADJ	Brake Adjustment					29/07/2021		Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Brakes\BRAKE ADJ	Brake Adjustment. All S-cams need shimming/replacement		Refer Job# 348092			29/07/2021		Fault	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Brakes\SLACK ADJ	To be done with Reline.		Refer Job# 346727 FULL RE-LINE, CHECK BEARINGS ETC. $3,522.54 JACKED UP ALL AXLES AND SUPPORT ON STANDS. REMOVED ALL WHEELS AND BRAKE DRUMS. REMOVED ALL HUBS AND BEARINGS. REMOVED ALL BRAKE SHOES AND S-CAMS. CUT OUT OLD S-CAM TUBES. INSTALLED ALL NEW S-CAM TUBES AND PLATES AND WELD INTO POSITION. INSTALLED NEW S-CAMS. REMOVED AND REPLACED ALL ANCOR PINS. CLEANED ALL BEARINGS AND HUBS AND INSPECTED BEARINGS. RE-PACKED ALL WHEEL BEARINGS AND INSTALLED. INSTALLED NEW HUB SEALS AND RE-FITTED HUBS. ADJUSTED WHEEL BEARINGS. INSTALLED NEW BRAKE SHOES AND FITTED NEW DRUMS. RE-FITTED ALL WHEELS AND TENSIONED ALL WHEEL NUTS TO SPEC. GREASED AND ADJUSTED ALL BRAKES.		07/07/2021		Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Brakes\BRK RELINE	Full reline done by Daimler.		REMOVED STANDS AND LOWER AXLES ON GROUND.			07/07/2021		Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Workshop\MOVE ASSET	Pick up from TCTC Record Check Results As Attached To This Job					06/07/2021		Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Brakes	Needs urarent reline. All S-cams need shimming/replacement					24/06/2021	114553	Repair	Comoleted	FL Green Distribution	FRB	Wodonwa	LHB	529315	Wodonwa Workshop	TRAILER
T200	Wodonga - Workshop	Brakes\SLACK ADJ	To be done with Reline.		Refer Job# 343293			24/06/2021	114553	Repair	Comoleted	FL Green Distribution	FRB	Wodonwa	LHB	529315	Wodonwa Workshop	TRAILER
T200	Wodonga - Workshop	Chassis\MUDGUARDS	r/rear guard					24/06/2021	114553	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Chassis\MUDGUARDS	r/rear guard					24/06/2021	114553	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Chassis\FIFTH WHEE	Turntstable needs replacement					24/06/2021	114553	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Chassis\MUDGUARDS	L rear missing L. kicking out 6mm, R kicking out 12mm					24/06/2021	114553	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Brakes\HOUSEKEEP	L kicking out 6mm L kicking R kicking 12mm		Refer Job# 343293			24/06/2021	114553	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Brakes\HOUSEKEEP	L kicking R kicking 4mm		Refer Job# 343293			24/06/2021	114553	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Elect\INDICATORS	RH blinker					24/06/2021	114553	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Brakes\BRK RELINE	LH-kicking 5mm-18mm		Refer Job# 343293			24/06/2021	114553	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Body\MUDGUARDS	guards need replacing					24/06/2021	114553	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Chassis\FIFTH WHEE	turntable need replace (completely)					24/06/2021	114553	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	VehService\DS				24/06/2021	114553	Service	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Chassis\CHAS CRACK	Cross Brace Crack.					24/06/2021	114553	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Tyres\TP01	Puncture repair					22/06/2021	114019	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Tyres\TP13+12	Supply and fit 2 tyres					13/05/2021	106370	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job					13/05/2021	106371	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	VehService\DS				13/05/2021	106371	Service	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Body\MUDGUARDS	guards need replacing					13/05/2021	106371	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Chassis\FIFTH WHEE	turntable need replace (completely)					13/05/2021	106371	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Workshop\CLEAN	clean up shed and relocating parts					13/05/2021	106371	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Body\STRAPS	Job Added From Invoice					07/04/2021	0	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job					11/03/2021	95264	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	VehService\DS				11/03/2021	95264	Service	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Elect\INDICATORS	RH blinker					11/03/2021	95264	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Chassis\TP06	small body cracks forming					11/03/2021	95264	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Brakes\BRK RELINE	LH-kicking 5mm-18mm					11/03/2021	95264	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Susp\SPRING HANG	RHF saddle weld - cracking up into trailing arm, around and inch long		set up welded and weld cracks			11/03/2021	95264	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Workshop\MOVE ASSET	move trailers into qip shed for repairs					11/03/2021	95264	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Elect\ELECT P&W	replace base plug - no LH indicator					11/02/2021		Fault	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Workshop\MOVE ASSET	move trailers					11/02/2021		Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Elect\ELECT P&W	replace base plug					11/02/2021		Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Elect\ELECT P&W	electrical wire repairs					11/02/2021		Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job					04/02/2021	281654	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	VehService\DS				04/02/2021	281654	Service	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Susp\SPRING PACK	R front axle hanger cracked L kicking R kicking 12mm					04/02/2021	281654	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Brakes\HOUSEKEEP	L kicking R kicking 4mm					04/02/2021	281654	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	VehService\DS				29/01/2021	8724	Service	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job					29/01/2021	8724	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Tyres\TP9+10	replace 2 tyres					24/12/2020	83619	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job					24/12/2020		Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Chassis\MUDGUARDS	L rear missing					24/12/2020		Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Chassis\WHEEL BRGS	bearing grease needs inspection					24/12/2020		Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Susp\SUSPENSION	slight bush movement L. kicking out 6mm, R kicking out 12mm					24/12/2020		Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Brakes\HOUSEKEEP	L kickine out 6mm					24/12/2020		Repair	Comoleted	FL Green Distribution	FRB	Wodonwa	LHB	529315	Wodonwa Workshop	TRAILER
T200	Wodonga - Workshop	Chassis\MUDGUARDS	need new guard LHS					24/12/2020		Fault	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	VehService\DS				24/12/2020		Service	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job					25/11/2020	78137	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Susp\WHEEL ALGN	boss kit movement					25/11/2020	78137	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Chassis\FIFTH WHEE	Turntstable needs replacement					25/11/2020	78137	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Chassis\TRL LEGS	Leg supports & mounts bent					25/11/2020	78137	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Brakes\SLACK ADJ	All S-cams need shimming/replacement					25/11/2020	78137	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Chassis\MUDGUARDS	r/rear guard					25/11/2020	78137	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Susp\HCV	needs new height control valve		job completed			25/11/2020	78137	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Body\LIGHTS	2x no. plate lights		completed			25/11/2020	78137	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Chassis\MUDGUARDS	r/rear guard		315405 job related with it			25/11/2020	78137	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Susp\HCV	needs new valve		315406 job no, relateed with this job completed			25/11/2020	78137	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Brakes\AIR LEAK	trailer takes a long time to release		job related 315409			25/11/2020	78137	Fault	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Chassis\AIR LEAK	trl takes long time to release		job completed			25/11/2020	78137	Fault	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Elect\ELECT P&W	need trailer ply		replaced trailer ply A&B			25/11/2020	78137	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Brakes\BRK RELINE	R. middle axle brakes shoes half is out of drum					25/11/2020	78137	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	VehService\DS	move assets			25/11/2020	78137	Service	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Susp\HCV	po for valve height leveling-AWAITING WO					17/10/2020		Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job					13/10/2020	70739	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Body\LIGHTS	2x no. plate lights					13/10/2020	70739	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	VehService\DS				13/10/2020	70739	Service	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Chassis\MUDGUARDS	r/rear guard					13/10/2020	70739	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Susp\HCV	needs new valve					13/10/2020	70739	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Brakes\HOUSEKEEP	RM anchor bushes					13/10/2020	70739	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job					15/09/2020	65789	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Susp\SUSPENSION	inspect suspension					15/09/2020	65789	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Susp\SUSPENSION	RHF trailing arm bush		checked - ok			15/09/2020	65789	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	VehService\DS				15/09/2020	65789	Service	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Body\LIGHTS	2x no. plate lights					15/09/2020	65789	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Chassis\MUDGUARDS	r/rear guard					15/09/2020	65789	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Susp\HCV	needs new height control valve					15/09/2020	65789	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Chassis\MUDGUARDS	Replace L/Rear guard					11/09/2020		Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job					18/08/2020	60679	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Chassis\MUDGUARDS	LHR guard		Previously completed			18/08/2020	60679	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	VehService\DS				18/08/2020	60679	Service	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Brakes\SLACK ADJ	Brakes inspected					18/08/2020	60679	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Insp\UNT INSP	need to order new one u/s					18/08/2020	60679	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Susp\SUSPENSION	RHF trailing arm bush					18/08/2020	60679	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Brakes\BOOSTER	faulty brakes(takes time to release)		replace booster and slack adjuster hand file slack adjuster and scam to suit Rapid Hydrulics to supply parts P/O WW057126			15/08/2020		Fault	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Brakes\AIR LEAK	massive airleak at back of trailer, trailer looses are when maxis used		replace brake valve			15/08/2020		Fault	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Workshop\MOVE ASSET	yard check trailers running out of air as soon as maxis applied.					15/08/2020		Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Chassis\AIR LEAK	TAKE note: trailers are going to comvone 9am 11/8/2020		Brakes kicking in and out Slack adjusters excessive movement D washers U/S L pin and worn			15/08/2020		Fault	Comoleted	FL Green Distribution	FRB	Wodonwa	LHB	529315	Wodonwa Workshop	TRAILER
T200	Wodonga - Workshop	Brakes\SLACK ADJ	Brakes inspected					14/08/2020	60438	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Susp\SUSPENSION	inspect suspension					14/08/2020	60438	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Chassis\CROSS MBR	cross members cracking					31/07/2020	58190	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Chassis\CHAS CRACK	Gusset/chassis cracks					31/07/2020	58190	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Tyres\CASE STOCK	Job Added From Invoice					10/07/2020	53454	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Tyres\PRES CHECK	Job Added From Invoice					10/07/2020	53454	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice					10/07/2020	53454	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Tyres\RETREAD	Job Added From Invoice					10/07/2020	53454	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER

T200	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job															
T200	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	VehService\DS														
T200	Wodonga - Workshop	Workshop\CLEAN	sweep up for service															
T200	Wodonga - Workshop	Chassi\MUDGUARDS	attempt to bend out r/r guard plate															
T200	Wodonga - Workshop	Susp\SHOCK ABS	shock absorber removal and take up top for welding															
T200	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job															
T200	Wodonga - Workshop	Comp\Truck Safe	NVHAS sticker needs replacing															
T200	Wodonga - Workshop	Chassi\FIFTH WHEE	tutntable needs replacement															
T200	Wodonga - Workshop	Chassi\FIFTH WHEE	needs replacing															
T200	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	VehService\DS	Split & move trailers													
T200	Wodonga - Workshop	Chassi\MUDGUARDS	LHR guard															
T200	Wodonga - Workshop	Chassi\TRL LEGS	Leg supports & mounts bent															
T200	Wodonga - Workshop	Brakes\SLACK ADJ	All S-cams need shimming/replacement															
T200	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job															
T200	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	VehService\DS														
T200	Wodonga - Workshop	Chassi\FIFTH WHEE	tutntable needs replacement															
T200	Wodonga - Workshop	Chassi\CHAS CRACK	Gusset/chassis cracks															
T200	Wodonga - Workshop	Chassi\FIFTH WHEE	needs replacing															
T200	Wodonga - Workshop	Workshop\CLEAN	clean up for t200/201															
T200	Wodonga - Workshop	Brakes\BRK O/HAUL	rebuah															
T200	Wodonga - Workshop	Brakes\BRAKE ADJ	grease and adjust brakes															
T200	Wodonga - Workshop	Workshop\MOVE ASSET	hook up to T200 and hook T200 to T201 and drop out in yard															
T200	Wodonga - Workshop	Chassi\WHEEL BRGS	bearing adjust R front R rear															
T200	Wodonga - Workshop	Workshop\MOVE ASSET	move trailer for servicing															
T200	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job															
T200	Wodonga - Workshop	Insp\UNT INSP	need to order new one u/s															
T200	Wodonga - Workshop	Susp\WGHT GAUGE	Need new weight guages		working "ok"													
T200	Wodonga - Workshop	Comp\Truck Safe	NVHAS sticker needs replacing															
T200	Wodonga - Workshop	Chassi\CHAS CRACK	Roll back cable rack RHF															
T200	Wodonga - Workshop	Susp\WHEEL ALGN	boss kit movement															
T200	Wodonga - Workshop	Chassi\CROSS MBR	cross members cracking															
T200	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	VehService\DS	completed													
T200	Wodonga - Workshop	Chassi\FIFTH WHEE	tutntable needs replacement															
T200	Wodonga - Workshop	Elect\ELECT P&W	lighting plug at front worn out. Missing broken pins		Completed by Darren Bishop on 30/3/2020													
			hook up ,to t200 /201after skid plate check checked lights ,guards etc															
T200	Wodonga - Workshop	Workshop\MOVE ASSET	when driver confiicated trailers ifuttile service \															
T200	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job															
T200	Wodonga - Workshop	Elect\INDICATORS	no side blinkers could not fault															
T200	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	VehService\DS														
T200	Wodonga - Workshop	Susp\WHEEL ALGN	boss kit movement															
T200	Wodonga - Workshop	Chassi\CROSS MBR	cross members cracking															
T200	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job															
T200	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	VehService\DS														
T200	Wodonga - Workshop	Elect\INDICATORS	no side blinkers															
T200	Wodonga - Workshop	Comp\Truck Safe	replaced with new one															
T200	Wodonga - Workshop	Chassi\TRL LEGS	slightly bent backwards															
T200	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job															
T200	Wodonga - Workshop	Susp\WGHT GAUGE	Need new weight guages															
T200	Wodonga - Workshop	Elect\ELECT P&W	Faulty wiring		More information needed - lights are operational													
T200	Wodonga - Workshop	Body\SCALES	Outdated		As per #260808													
T200	Wodonga - Workshop	Body\DAMAGE	retaining clips on pump/battery box door have rattled of door cannot be closed (RHS)		Previously completed													
T200	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	VehService\DS														
T200	Wodonga - Workshop	Comp\Truck Safe	NVHAS sticker needs replacing															
T200	Wodonga - Workshop	Chassi\CHAS CRACK	Roll back cable rack RHF															
T200	Wodonga - Workshop	Body\DAMAGE	Remove & replace pump door latches															
T200	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice															
T200	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice															
T200	Wodonga - Workshop	Body\MUDGUARDS	Job Added From Invoice															
T200	Wodonga - Workshop	Chassi\MUDGUARDS	replaced s3 RH guards and repiars done to outriggers															
T200	Wodonga - Workshop	Chassi\HOUSEKEEP	grease set 200/201															
T200	Wodonga - Workshop	Workshop\MOVE ASSET	hook set up and move to yard and drop															
T200	Wodonga - Workshop	Workshop\CLEAN	clean up from job															
T200	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job															
T200	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	VehService\DS														
T200	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	VehService\DS														
T200	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job															
T200	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	VehService\DS														
T200	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job															
T200	Wodonga - Workshop	Tyres	Job Added From Invoice															
T200	Wodonga - Workshop	Tyres\CASE STOCK	Job Added From Invoice															
T200	Wodonga - Workshop	Tyres\PRES CHECK	Job Added From Invoice															
T200	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice															
T200	Wodonga - Workshop	Tyres\RETREAD	Job Added From Invoice															
T200	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job															
T200	Wodonga - Workshop	Chassi\MUDGUARDS	3x R/hand guards dock rubbers															
T200	Wodonga - Workshop	DrivLine\WHEEL BRGS	adjusted r/centre															
T200	Wodonga - Workshop	Chassi\FIFTH WHEE	replaced adjustment bolt nut															
T200	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	VehService\DS														
T200	Wodonga - Workshop	Insp\ANN INSP	Annual inspection as per check list	Insp\ANN INSP														
T200	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job															
T200	Wodonga - Workshop	Elect\ELECT P&W	faulty wiring		specify?													
T200	Wodonga - Workshop	Body\MUDGUARDS	rear bumb stops not secured		previously completed													
T200	Wodonga - Workshop	Chassi\CONSUMABLE	cracked crossmember RHS between front and middle axle		previously completed													
T200	Wodonga - Workshop	Body\SCALES	outdated		pending													
T200	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	VehService\DS	carried out D Service													
T200	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job															
T200	Wodonga - Workshop	VehService\DS	Service	VehService\DS														
T200	Wodonga - Workshop	Chassi\CHAS CRACK	replace binder rail															
T200	Wodonga - Workshop	Body\REFLECTORS	Job Added From Invoice															
T200	Wodonga - Workshop	Elect	Job Added From Invoice															
T200	Wodonga - Workshop	Chassi\WINCH/STRP	load binders and straps															
T200	Wodonga - Workshop	Chassi\WINCH/STRP	Added new winch for driver															
T200	Wodonga - Workshop	Elect\TRL LIGHTS	Replace faulty bulb style lights with LED lights															
T200	Wodonga - Workshop	Body\RWC COMP	Replaced reflective markers															
T200	Wodonga - Workshop	Body\DAMAGE	Weld clearance light brackets on coaming rails															
T200	Wodonga - Workshop	Elect\ELECT P&W	Swap base plug & rewire															
T200	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job															
T200	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	VehService\DS	trailer has not moved since last service													
T200	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job															
T200	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	VehService\DS	trailer hasn't moved since last service													
T200	Wodonga - Workshop	Tyres\CASE STOCK	Job Added From Invoice															
T200	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice															
T200	Wodonga - Workshop	Tyres\RETREAD	Job Added From Invoice															
T200	Wodonga - Workshop	Brakes\BRK O/HAUL	Job Added From Invoice															
T200	Wodonga - Workshop	Workshop\MOVE ASSET	move trailer															
T200	Wodonga - Workshop	Brakes\BRK RELINE	reline															
T200	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job															
T200	Wodonga - Workshop	Brakes	RHR scam tube needs welding		previously done													
T200	Wodonga - Workshop	Insp\UNT INSP	need to order new one u/s															
			cable runner for roll back u/s		spare tyre rack operational													
T200	Wodonga - Workshop	Chassi\CROSS MBR	spare tyre rack u/s		rollback not required													
T200	Wodonga - Workshop	Chassi\HOUSEKEEP	bracing bent u/s		still operational													
T200	Wodonga - Workshop	Susp\WGHT GAUGE	need new weight guages															
T200	Wodonga - Workshop	Air Con\TRL ROLLBK	u/s		rollback not required													
T200	Wodonga - Workshop	Elect\BATTERY	battery u/s		rollback not required													
T200	Wodonga - Workshop	Air Con\TRL ROLLBK	unable to test u/s		rollback not required													
T200	Wodonga - Workshop	Insp\UNT INSP	pinch points not labeled		rollback not required													
T200	Wodonga - Workshop	Susp\SPRING HANG	bushes worn u/s		bushes still ok													
			shoes kicking 2mm															
T200	Wodonga - Workshop	Brakes\BRK O/HAUL	replace all bearings		has had reline													
T200	Wodonga - Workshop	Susp\HCV	HCV faulty repair as required		works fine													
T200	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	VehService\DS														
T200	Wodonga - Workshop	Elect\ELECT P&W	faulty wiring															
T200	Wodonga - Workshop	Body\MUDGUARDS	rear bumb stops not secured															
T200	Wodonga - Workshop	Chassi\CONSUMABLE	cracked crossmember RHS between front and middle axle															
T200	Wodonga - Workshop	Body\SCALES	outdated															
T200	Wodonga - Workshop	Workshop\MOVE ASSET	move trailer															
T200	Wodonga - Workshop	Brakes\BRK RELINE	reline															
T200	Wodonga - Workshop	Body\TRL GATES	chain loop's on end gates and check for fatigue cracks															
T200	Wodonga - Workshop	Elect\TRL LIGHTS	attempt to repair lights - parts on order															
T200	Wodonga - Workshop	Workshop\CLEAN	clean workshop															
T200	Wodonga - Workshop	Body\CHN/RLR/MN	cut chains to length and set up chain and dogs for headboards															
T200	Wodonga - Workshop	Brakes\BRAKE ADJ	grease brakes															
T200	Wodonga - Workshop	Workshop\MOVE ASSET	move trailer															
T200	Wodonga - Workshop	Workshop\CLEAN	clean workshop															
T200	Wodonga - Workshop	Insp\RWC COMP	Job Added From Invoice															
T200	Wodonga - Workshop	Workshop\MOVE ASSET	hook trailer together, do turn test then unhook (not compatible)															
T200	Wodonga - Workshop	Workshop\CLEAN	clean service bay															
T200	Wodonga - Workshop	Workshop\MOVE ASSET	get trailers for service															
T200	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job															
T200	Wodonga - Workshop	Body\REFLECTORS	zebra signs u/s		replace zebra signs													
T200	Wodonga - Workshop	Susp\SHOCK ABS	loose shocky															
T200	Wodonga - Workshop	Susp\AIR BAG	creast airbag															
T200	Wodonga - Workshop	Brakes\BRK O/HAUL	shoes kicking 2mm															
T200	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	VehService\DS	trailer still has rollback gear installed but has had a flat battery since trailer convertion so rollback system has not been used since service previously													
T200	Wodonga - Workshop	Brakes\BRAKE ADJ	brake adjustments															
T200	Wodonga - Workshop	Elect\ELECT P&W	rewire base plug/repairs to wiring															
T200	Wodonga - Workshop	Chassi\CHAS CRACK	weld spinning v-cam tube															
T200	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job															
T200	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	VehService\DS														
T200	Wodonga - Workshop	Body\REFLECTORS	aebra signs u/s															
T200	Wodonga - Workshop	Insp\UNT INSP	need to order new one u/s															
			cable runner for roll back u/s															
T200	Wodonga - Workshop	Chassi\CROSS MBR	spare tyre rack u/s															
T200	Wodonga - Workshop	Chassi\HOUSEKEEP	bracing bent u/s															

T200	Wodonga - Workshop	Susp\WGHT GAUGE	need new weight guages		04/04/2018	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Air Con\TRL ROLLBK	u/s		04/04/2018	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Elect\BATTERY	battery u/s		04/04/2018	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Air Con\TRL ROLLBK	unable to test u/s		04/04/2018	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Insp\UNT INSP	pinch points not labeled		04/04/2018	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Susp\SPRING HANG	bushes worn u/s		04/04/2018	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Susp\SHOCK ABS	loose shocky		04/04/2018	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Susp\AIR BAG	creast airbag		04/04/2018	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Brakes\BRK C/HAUL	shoes kicking 2mm		04/04/2018	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Elect\TRL LIGHTS	7 pin plug		04/04/2018	Fault	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Brakes\BRAKE ADJ	brake adjust can of silicon spray to losen up		04/04/2018	Fault	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Body\HOUSEKEEP	rusty binders please	repairs straped front and rear gates down	04/04/2018	Fault	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Workshop\MOVE ASSET	moving trailers		04/04/2018	Repair	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER
T200	Wodonga - Workshop	Insp\ANN INSP	Annual inspection as per check list	Insp\ANN INSP	04/04/2018	Preventative\Maintenance	Completed	FL Green Distribution	FRB	Wodonga	LHB	529315	Wodonga Workshop	TRAILER