EquipmentName	Workshop	CodeAndSubCode	Description	CompletionComments	DateDone	DistanceDone	Workstate	Rego	Supplier	EquipmentType
1081	Wodonga - Workshop	Engine\COMPRESSOR	Air compressor not building pressure after start up. Truck Won't Build Up Air. (Goulburn) (Cummins Canberra Done Under Warranty)		21/08/2026	301377	Completed	FLG1	CUMMINS SOUTH PACIFIC P/L	P/MOVER
1081	Wodonga - Workshop	Engine\COMPRESSOR	Compressor Replaced @ 475,000 Klms	Cummins replaced compressor under warranty. shane john	21/08/2026	301377	Completed	FLG1	CUMMINS SOUTH PACIFIC P/L	P/MOVER
1081	Wodonga - Workshop	VehService\CS	VehService\CS C Service	Aaron	27/07/2026	301377	Completed	FLG1	Wodonga Workshop	P/MOVER
1081	Wodonga - Workshop	VServLab	-OVERDUE FOR B+C SERVICE	Shane John	27/07/2026	301377	Completed	FLG1	Wodonga Workshop	P/MOVER
1081	Wodonga - Workshop	Insp\ANN INSP	Insp\ANN INSP To Complete R/W within 12 months bad air leak, sounds like coming from area near suzie coils, underneath bunk	Aaron	27/07/2026	301377	Completed	FLG1	Wodonga Workshop	P/MOVER
1081	Wodonga - Workshop	Body\AIR LEAK			22/07/2026	301377	Completed	FLG1	Wodonga Workshop	P/MOVER
1081	Wodonga - Workshop	Elect\ELECT P&W	LEFT HAND MIRROR LIGHT ON.		18/07/2026	301377	Completed	FLG1	TWIN CITY TRUCK CENTRE	P/MOVER
1081	Wodonga - Workshop	DrCabElect\ELECT P&W	Brake light circuit breaker tripping.		18/07/2026	301377	Completed	FLG1	TWIN CITY TRUCK CENTRE	P/MOVER
1081	Wodonga - Workshop	DriCabRep\DOOR LOCK	Door switch not fixed Correctly.		18/07/2026	301377	Completed	FLG1	TWIN CITY TRUCK CENTRE	P/MOVER
1081	Wodonga - Workshop	Elect\BRK LIGHT	brake light- circuit breaker repeatedly tripping out		17/07/2026	301377	Completed	FLG1	TWIN CITY TRUCK CENTRE	P/MOVER
1081	Wodonga - Workshop	Body\ELECT P&W	drivers door micro switch faulty air horn on		17/07/2026	301377	Completed	FLG1	TWIN CITY TRUCK CENTRE	P/MOVER
1081	Wodonga - Workshop	Elect\BRK LIGHT	BRAKE LIGHT C/BREAKER TRIPPING- STILL NOT FIXED		17/07/2026	301377	Completed	FLG1	TWIN CITY TRUCK CENTRE	P/MOVER
1081	Wodonga - Workshop	DrCabElect\ELECT P&W	Brake light curcuit breaker repeatedly tripping.		17/07/2026	301377	Completed	FLG1	TWIN CITY TRUCK CENTRE	P/MOVER
1081	Wodonga - Workshop	Elect\BRK LIGHT	brake light circuit breaker tripping		17/07/2026	301377	Completed	FLG1	TWIN CITY TRUCK CENTRE	P/MOVER
1081	Wodonga - Workshop	DrCabElect\ELECT P&W	DOOR SWITCH NOT FIXED CORRECTLY		17/07/2026	301377	Completed	FLG1	TWIN CITY TRUCK CENTRE	P/MOVER
1081	Wodonga - Workshop	Elect\DAMAGE	coolabah unit not working	completed by kerrs	13/07/2026	301377	Completed	FLG1	Wodonga Workshop	P/MOVER
1081	Wodonga - Workshop	Air Con\AIR CON	-COOLABAH UNIT-ERROR CODES-NOT COOLING	completed by kerrs	13/07/2026	301377	Completed	FLG1	Wodonga Workshop	P/MOVER
1081	Wodonga - Workshop	DriCabRep\WIPERS	replace wiper blades	completed by KR	10/06/2026	301377	Completed	FLG1	Wodonga Workshop	P/MOVER
1081	Wodonga - Workshop	Body\ELECT P&W	Side of Cab, flip up spotlight's Not Working.		07/06/2026	301377	Completed	FLG1	Wodonga Workshop	P/MOVER
1081	Wodonga - Workshop	Elect\BRK LIGHT	brake light circuit breaker tripping		07/06/2026	301377	Completed	FLG1	Wodonga Workshop	P/MOVER
1081	Wodonga - Workshop	Body\ELECT P&W	lights not working in toolbox's.		07/06/2026	301377	Completed	FLG1	Wodonga Workshop	P/MOVER
1081	Wodonga - Workshop	DrCabElect\ELECT P&W	Brake light curcuit breaker Tripping.		07/06/2026	301377	Completed	FLG1	Wodonga Workshop	P/MOVER
1081	Wodonga - Workshop	DrCabElect\INST/GAUGE	voltage and pressure gauge blown globes		07/06/2026	301377	Completed	FLG1	Wodonga Workshop	P/MOVER
1081	Wodonga - Workshop	Elect\DRV LIGHT	worklights not operating properly		07/06/2026	301377	Completed	FLG1	Wodonga Workshop	P/MOVER
1081	Wodonga - Workshop	DrCabElect\INST/GAUGE	Voltage & Pressure Gauges Need Bulbs Replaced		07/06/2026	301377	Completed	FLG1	Wodonga Workshop	P/MOVER
1081	Wodonga - Workshop	Elect\HEAD LIGHT	R/H Headlight - Replacement		07/06/2026	301377	Completed	FLG1	Wodonga Workshop	P/MOVER
1081	Wodonga - Workshop	Elect\WORK LIGHT	Worklights Not Operating Properly		01/06/2026	301377	Completed	FLG1	TWIN CITY TRUCK CENTRE	P/MOVER
1081	Wodonga - Workshop	Elect\BRK LIGHT	Brake Light C/Breaker Tripping Repeatedly		01/06/2026	301377	Completed	FLG1	TWIN CITY TRUCK CENTRE	P/MOVER
1081	Wodonga - Workshop	Tyres\TP11+12	Tyres\TP11+12		08/05/2026	301377	Completed	FLG1	BORDER BANDAG PTY LTD	P/MOVER
1081	Wodonga - Workshop	Tyres\TP5+6	Tyres\TP5+6		08/05/2026	301377	Completed	FLG1	BORDER BANDAG PTY LTD	P/MOVER
1081	Wodonga - Workshop	Tyres\TP7+8	Tyres\TP7+8		08/05/2026	301377	Completed	FLG1	BORDER BANDAG PTY LTD	P/MOVER
1081	Wodonga - Workshop	Tyres\TP9+10	Tyres\TP9+10		08/05/2026	301377	Completed	FLG1	BORDER BANDAG PTY LTD	P/MOVER
1081	Wodonga - Workshop	DrCabElect\ELECT P&W	DrCabElect\ELECT P&W	Dropped the dash panels down to get to the fuses, check the fuse for the worklights. Found the fuse was blown. Check and found the switch wiring on the relay had been changed and was causing a short as soon as the switch was turned on. Swap the wiring back to standard on the relay and test. The lights are working correctly. Check over the wiring to confirm there is no short in the circuit. Found no shorts in the wiring. The work lights have been taped over before i got there. Put the dash back together. Callout. Travel to Greenfreight Wodonga. Worklight fuse is shorting out all the time. Connect the short detector to the wiring to locate the short, disconnected the lights. Followed the wiring back to a plug, disconnected the plug and the short was still there. Removed all dash panels required to get to the wiring in the cab. Found the wiring was shorting inside the cabin, could not locate the short anywhere inside. Cut the wiring from the switch and left the fuse out to prevent any further damage. Wire in a new fuse holder and relay, connect the switch wiring to the relay, cut the out put of the old circuit to the lights and join it into the new relay. Test, the work light are working correctly. Noticed half of the LH work light was not working, the light will need to be replaced soon. Put the truck back together correctly. Return home.	20/03/2026	301377	Completed	FLG1	Wodonga Workshop	P/MOVER
1081	Wodonga - Workshop	Elect\WORK LIGHT	FLIP UP SPOT LIGHTS- SIDE OF CAB- NOT WORKING		13/03/2026	301377	Completed	FLG1	ARKON AUTO ELECTRICAL	P/MOVER
1081	Wodonga - Workshop	VehService\AS	VehService\AS A Service	2.5hrs	28/02/2026	301377	Completed	FLG1	Wodonga Workshop	P/MOVER
1081	Wodonga - Workshop	DrivLine\DIFF OIL	DrivLine\DIFF OIL Replace Diff oils		28/02/2026	301377	Completed	FLG1	Wodonga Workshop	P/MOVER
			Engine\ADBLUE AFTER TREATMENT LIGHT ON	Customer contacted dealership breakdown technician with information regarding breakdown * Customer advised that truck had aftertreatment light on * Technician travelled to breakdown site, GF depot, Wodonga * Connected diagnostic tooling * Located active fault code 3548 - diesel exhaust fluid dosing unit loss of prime * Followed diagnostic trouble shooting * Checked for primary fault codes active or non-active * Followed TSB 200096 * Removed injector, attempted to performed fluid & air system flush but blocked * Cleaned injector from blockage * Carried out doser pump air solenoid click test * Performed successful fluid & air system flush * Cleared codes * Test, confirmed & quality checked after treatment system * Returned truck service						
1081	Wodonga - Workshop	Engine\ADBLUE	WARRANTY REPAIR - TCTC	* Technician returned hom	18/02/2026	301377	Completed	FLG1	TWIN CITY TRUCK CENTRE	P/MOVER
1081	Wodonga - Workshop	Tyres\Punct	Tyres\Punct POS 11		15/02/2026	274355	Completed	FLG1	BORDER BANDAG PTY LTD	P/MOVER
1081	Wodonga - Workshop	Tyres\TP1+2	Tyres\TP1+2		24/01/2026	274355	Completed	FLG1	BORDER BANDAG PTY LTD	P/MOVER
1081	Wodonga - Workshop	DrCabElect\ELECT P&W	Brake light curcuit Breaker repeatedly Tripping.	Tested truck wiring, the fault causing the breaker to trip is in the trailers	23/01/2026	274355	Completed	FLG1	Wodonga Workshop	P/MOVER
1081	Wodonga - Workshop	Steering\TIE ROD	Steering pulling to the left and wobble through steering wheel under acceleration.	Drag link front ball joint has movement, kingpins worn, sent truck to tyre fitters to get steers rotated	23/01/2026	274355	Completed	FLG1	Wodonga Workshop	P/MOVER
1081	Wodonga - Workshop	Elect\ELECT P&W	Replace Suzi lead. B Service Serviced @ 274,355 Klms	Went to test lights on trailers and found that there was a bad earth tested suzi lead had a bad earth testec	19/01/2026	274355	Completed	FLG1	Wodonga Workshop	P/MOVER
1081	Wodonga - Workshop	VehService\BS			10/01/2026	274355	Completed	FLG1	Wodonga Workshop	P/MOVER
1081	Wodonga - Workshop	Air Con\AIR CON	COOLABAH BUNK COOLER NOT WORKING. AT FIRST WAS SHOWING ERROR CODE - ER01. NOW CONTROL PANEL IS DEAD.	fuse was replaced	20/12/2025	274355	Completed	FLG1	Wodonga Workshop	P/MOVER
1081	Wodonga - Workshop	VehService\AS	VehService\AS A Service		13/12/2025	261129	Completed	FLG1	Wodonga Workshop	P/MOVER
1081	Wodonga - Workshop	Elect\ELECT P&W	REVERSE LIGHT CUIRCUT BREAKER - REPEATEDLY TRIPPING	-live pin 2 on truck trailer base possible cause of reverse lights tripping when trailers are connected, pin 2 removed from trailer plug -assisted with trailer eye washer removal and finding replacment	29/11/2025	170701	Completed	FLG1	Wodonga Workshop	P/MOVER

				Labour - Mobile - Breakdown						
				Travelled to Manildra						
				Inspected A trailer						
				Found 3rd axle RHS						
				training arm bolt missing						
			Chassis\AXLES WW098064	Re-aligned axle and fit new bolt						
				Refit tyres and guard						
			Please Note: Axle was not aligned, and correct washer was	Tensioned bolt and tyres						
			not fitted to inner	Trailer returned to service						
			This is a temporary repair. Instalment of correct parts and	Mechanic						
1081	Wodonga - Workshop	Chassis\AXLES	axle alignment advised.	Returned to workshop	28/11/2025	170701	Completed	FLG1	WARREGO TRANSPORT REPAIRS	P/MOVER
1081	Wodonga - Workshop	Prod Hose\H/Fittings	Job Created from Purchase Order #: 106485		27/10/2025	7618	Completed	FLG1	RAPID HYDRAULICS	P/MOVER
1081	Wodonga - Workshop	Engine\ADBLUE	Ad Blue Dash Light	Connected Computer to truck checked for codes, found high NOx code, connected truck up to a set of loa	25/10/2025	170701	Completed	FLG1	Wodonga Workshop	P/MOVER
			Input shaft seal leak8ng							
1081	Wodonga - Workshop	DrivLine	(TCTC Warranty)		10/10/2025	170701	Completed	FLG1	Wodonga Workshop	P/MOVER
			A Service							
1081	Wodonga - Workshop	VehService\AS	Serviced @ 222,000 Klms		10/10/2025	170701	Completed	FLG1	Wodonga Workshop	P/MOVER
			Check & Test Fuel System (Fuel Pressure Test).							
1081	Wodonga - Workshop	Engine\FUEL TANK	(Cummins Wodonga P/O: WW097090		23/09/2025	170701	Completed	FLG1	CUMMINS SOUTH PACIFIC P/L	P/MOVER
			Engine Shut Down While Climbing Mt Ousley.							
1081	Wodonga - Workshop	Engine\BREAKDOWN	(Warrego Transport Repairs P/O: WW097089		22/09/2025	170701	Completed	FLG1	WARREGO TRANSPORT REPAIRS	P/MOVER
			B Service							
1081	Wodonga - Workshop	VehService\BS	Serviced @ 208,000 Klms		18/09/2025	170701	Completed	FLG1	Wodonga Workshop	P/MOVER
1081	Wodonga - Workshop	Workshop\MOVE ASSET	Drop Truck Off To Corowa Truck & Trailer, Pick Truck Up From Corowa Truck & Trailer.		17/09/2025	170701	Completed	FLG1	COROWA TRUCK AND TRAILER	P/MOVER
			Oil Leak From PTO, Transmission Re-curing Fault.							
1081	Wodonga - Workshop	Hydraulics\OIL LEAK	(Corowa Truck & Trailer Warranty Repair)		17/09/2025	170701	Completed	FLG1	COROWA TRUCK AND TRAILER	P/MOVER
1081	Wodonga - Workshop	Engine\DAMAGE	Drop truck at Corowa truck and trailer for repairs.		15/09/2025	170701	Completed	FLG1	Wodonga Workshop	P/MOVER
1081	Wodonga - Workshop	Tyres\TP5+6	Tyres\TP5+6		29/08/2025	170701	Completed	FLG1	BORDER BANDAG PTY LTD	P/MOVER
1081	Wodonga - Workshop	Tyres\TP9+10	Tyres\TP9+10		29/08/2025	170701	Completed	FLG1	BORDER BANDAG PTY LTD	P/MOVER
1081	Wodonga - Workshop	Tyres\TP11+12	Tyres\TP11+12		29/08/2025	170701	Completed	FLG1	BORDER BANDAG PTY LTD	P/MOVER
1081	Wodonga - Workshop	Tyres\TP7+8	Tyres\TP7+8		29/08/2025	170701	Completed	FLG1	BORDER BANDAG PTY LTD	P/MOVER
1081	Wodonga - Workshop	DrivLine\OIL LEAK	Transmission/PTO Leak	CHECKED OIL LEVEL AND LEAK.	13/08/2025	170701	Completed	FLG1	Wodonga Workshop	P/MOVER
1081	Wodonga - Workshop	Tyres\Punct	Tyres\Puncture POS 8		21/07/2025	170701	Completed	FLG1	BORDER BANDAG PTY LTD	P/MOVER
1081	Wodonga - Workshop	Tyres\TP1+2	Tyres\TP1+2		21/07/2025	170701	Completed	FLG1	BORDER BANDAG PTY LTD	P/MOVER
1081	Wodonga - Workshop	VehService\AS	Due "A" Service		19/07/2025	170701	Completed	FLG1	Wodonga Workshop	P/MOVER
1081	Wodonga - Workshop	DrivLine\DIFF OIL	DrivLine\DIFF OIL		19/07/2025	170701	Completed	FLG1	Wodonga Workshop	P/MOVER
1081	Wodonga - Workshop	Engine\FILTERS	Change air dryer filter		19/07/2025	170701	Completed	FLG1	Wodonga Workshop	P/MOVER
1081	Wodonga - Workshop	VehService\AS	VehService\AS		19/07/2025	170701	Completed	FLG1	Wodonga Workshop	P/MOVER
1081	Wodonga - Workshop	Insp\ANN INSP	Insp\ANN INSP		11/06/2025	141588	Completed	FLG1	Wodonga Workshop	P/MOVER
			C Service							
1081	Wodonga - Workshop	VehService\CS	Serviced @ 140,000 Klms		11/06/2025	141588	Completed	FLG1	Wodonga Workshop	P/MOVER
1081	Wodonga - Workshop	DrCabElect\INST/GAUGE	RIGHT HAND MIRROR DASH NOT WORKING.	no fault	26/04/2025	112825	Completed	FLG1	TWIN CITY TRUCK CENTRE - OLD	P/MOVER
1081	Wodonga - Workshop	DriCabRep\WINDOW REG	Drivers Side Window Won't go Up.	No fault	26/04/2025	112825	Completed	FLG1	TWIN CITY TRUCK CENTRE - OLD	P/MOVER
1081	Wodonga - Workshop	Engine\OIL LEAK	Check For Engine Oil Leak Underneath Please.	Diff leak repaired	26/04/2025	112825	Completed	FLG1	TWIN CITY TRUCK CENTRE - OLD	P/MOVER
1081	Wodonga - Workshop	Elect\ELECT P&W	HAZARD LIGHT/ HEAD LIGHT.	No fault found	26/04/2025	112825	Completed	FLG1	TWIN CITY TRUCK CENTRE - OLD	P/MOVER
			B Service. (TCTC P/O: WW093740)							
1081	Wodonga - Workshop	VehService\BS	Serviced @ 112,825 Klms.		26/04/2025	112825	Completed	FLG1	TWIN CITY TRUCK CENTRE - OLD	P/MOVER
1081	Wodonga - Workshop	DrivLine\DIFF OIL	DrivLine\DIFF OIL Replace Diff oils	D.WICKS	28/03/2025	93485	Completed	FLG1	Wodonga Workshop	P/MOVER
1081	Wodonga - Workshop	VehService\AS	VehService\AS A Service		28/03/2025	93485	Completed	FLG1	Wodonga Workshop	P/MOVER
			Elect\WORK LIGHT							
			*Fit light to rear of cab on RHS							
			*Use same switch as LHS light							
			Tap into left hand light wiring, run wires to right side of truck, wire in light.							
1081	Wodonga - Workshop	Elect\WORK LIGHT	Fit bracket and light. Test light, working.		26/03/2025	83722	Completed	FLG1	ARKON AUTO ELECTRICAL	P/MOVER
1081	Wodonga - Workshop	Brakes\AIR FITTIN	Repair Suzi lines	Labour 30 min	21/03/2025	83722	Completed	FLG1	Wodonga Workshop	P/MOVER
1081	Wodonga - Workshop	DrivLine\CLUTCH	Adjust clutch brake	Adjusted clutch	19/03/2025	83722	Completed	FLG1	Wodonga Workshop	P/MOVER
1081	Wodonga - Workshop	Elect\ALT	ALT LIGHT ON.	Called in for breakdown. Found Alternator only charging 5 volts. Still under warranty. Was pulled off the ro	19/03/2025	83722	Completed	FLG1	Wodonga Workshop	P/MOVER
1081	Wodonga - Workshop	Elect\ALT2 DR	Replace Alternator Due To Not Charging. (TCTC Replacing Under Warranty)		19/03/2025	170701	Completed	FLG1	TWIN CITY TRUCK CENTRE - OLD	P/MOVER
				*Fit new work light to light up turn table						
1081	Wodonga - Workshop	Elect\WORK LIGHT	Fit Work Light To Rear Of Cabin. (Arkon Auto Electrical P/O: WW092298)	Supply & fit new work light to light up turn table.	22/02/2025	69077	Completed	FLG1	ARKON AUTO ELECTRICAL	P/MOVER
1081	Wodonga - Workshop	VehService\BS	VehService\BS	63481kms	15/02/2025	63481	Completed	FLG1	Wodonga Workshop	P/MOVER
1081	Wodonga - Workshop	Tyres\TP1+2	Tyres\TP1+2		28/01/2025	7618	Completed	FLG1	Wodonga Workshop	P/MOVER
			C Service. (1st Service) (TCTC P/O: WW090764)							
1081	Wodonga - Workshop	VehService\CS	Serviced @ 7618 Klms.		30/11/2024	7618	Completed	FLG1	TWIN CITY TRUCK CENTRE - OLD	P/MOVER
			A Service. (1st Service) (TCTC P/O: WW090764)							
1081	Wodonga - Workshop	VehService\AS	Serviced @ 7618 Klms.		30/11/2024	7618	Completed	FLG1	TWIN CITY TRUCK CENTRE - OLD	P/MOVER
			B Service. (1st Service) (TCTC P/O: WW090764)							
1081	Wodonga - Workshop	VehService\BS	Serviced @ 7618 Klms.		30/11/2024	7618	Completed	FLG1	TWIN CITY TRUCK CENTRE - OLD	P/MOVER
1081	Wodonga - Workshop	Hot Hose\H/Fittings	Make up 3x Blower Hoses		25/11/2024	1	Completed	FLG1	Wodonga Workshop	P/MOVER
			Pre Delivery							
1081	Wodonga - Workshop	Insp\Truck Pre	Fit Jack, Wire Suzie Lead Correctly, Grease Turn Table, Put R&R Book & cleaning Kit In Cabin,	16.1ks	16/11/2024	1	Completed	FLG1	Wodonga Workshop	P/MOVER
1081	Wodonga - Workshop	Tyres\FITMENT	Replace Drive Tyres On Positions 3,4,5,6,7,8,9,10. (Wodonga Tyre & Auto P/O: WW090148)		08/11/2024	1	Completed	FLG1	BEAUREPAIRES	P/MOVER
1081	Wodonga - Workshop	Tyres\STEER TYRE	Replace Steer Tyres. (Wodonga Tyre & Auto P/O: WW090148)		08/11/2024	1	Completed	FLG1	BEAUREPAIRES	P/MOVER