EquipmentName	Workshop	CodeAndSubCode	Description	Schedule	CompletionComments	DateDone	DistanceDone	Worktype	Workstate	EquipmentOwner	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
1070	Albury - Workshop	VehService\AS	VehService\AS A Service	VehService\AS		24/09/2026	748385	Service	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	JF MECHANICALS - 3	P/MOVER
1070	Colac - Colac	Susp\SHOCK ABS	REPLACE R/REAR SHOCK. NO BOTTOM NUT & THREAD DAMAGED.		DONE AT 748394 KMS	24/09/2026	751781	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	JF MECHANICALS - 3	P/MOVER
1070	Albury - Workshop	Tyres\TP1+2	REPLACE STEER TYRES			24/09/2026	749570	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	BORDER BANDAG PTY LTD. - 4	P/MOVER
1070	Colac - Colac	Brakes\ABS	DIAGNOSE & REPAIR TRUCK ABS, ESC & TRACTION CONTROL FAULT.		DONE AT 748394 KMS	24/09/2026	751781	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	JF MECHANICALS - 3	P/MOVER
1070	Colac - Colac	Chassis\HOUSEKEEP	FIT REAR WALK PLATE		DONE AT 748394 KMS	24/09/2026	751781	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	JF MECHANICALS - 3	P/MOVER
					RECO HORTON FAN											
1070	Wodonga - Workshop	Cooling\ENG FAN	Horton needs replacing		DONE AT 748394 KMS	23/09/2026	749570	Repair	Completed	Greenfreight Loening Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	JF MECHANICALS - 3	P/MOVER
1070	Albury - Workshop	Engine\TURBO	replace turbo		Completed	26/08/2026	738262	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Albury Workshop	P/MOVER
1070	Albury - Workshop	DriveLine\DIFF OIL	DriveLine\DIFF OIL Replace Diff oils	DriveLine\DIFF OIL	FILLED WITH DYNADRIVE 80W-90	21/08/2026	748427	PreventativeMaintenance	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER
					DIAGNOSED FRONT DIFF FAILURE - TOWED TO WODONGA DEPOT.											
					REPLACED DRIVE AXLE ASSEMBLIES COMPLETE WITH PARTS FROM 1071. REPLACED THROUGH-SHAFT SEALS. CHECKED AND ADJUSTED.											
1070	Albury - Workshop	DriveLine\DIFF REPAIN	BREAKDOWN-DIFF FAILURE-BULLIOH			21/08/2026	748427	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	DriveLine\DIFF REPAIN	REPLACED DRIVE AXLE ASSEMBLIES COMPLETE WITH PARTS FROM 1071. REPLACED THROUGH-SHAFT SEALS. CHECKED AND ADJUSTED.			21/08/2026	748427	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Susp\WHEEL ALIGN	PERFORM LASER WHEEL ALIGNMENT			21/08/2026	748427	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER
			B Service													
1070	Albury - Workshop	VehService\B5	Serviced @ 740.381 Kims	VehService\B5		05/08/2026	740377	Service	Completed	Greenfreight Loening Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonwa Workshop	P/MOVER
1070	Albury - Workshop	DrCabElec\RADIO	Replace UHF Micra Phones There R.S			05/08/2026	740377	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Engine\BELTS/TENS	CHECK TURBO - REPLACE IDLER AND TENSIONER BEARINGS			31/07/2026	737832	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	VehService\AS	VehService\AS A Service	VehService\AS		23/07/2026	734491	Service	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Albury Workshop	P/MOVER
1070	Albury - Workshop	Tyres\FITMENT	REPLACED TYRES POS 5 6 7 8 9 10 11 12			21/07/2026	748427	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	BORDER BANDAG PTY LTD. - 4	P/MOVER
1070	Albury - Workshop	VehService\AS	VehService\AS A Service	VehService\AS		20/07/2026	731203	Service	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Albury Workshop	P/MOVER
1070	Albury - Workshop	DrCabElec\ELECT P&W	Tablet STILL NOT Charging.		completed by MB	13/07/2026	724073	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Albury Workshop	P/MOVER
1070	Albury - Workshop	Brakes\BRAKE ADJ	adjust brakes		completed by MB	13/07/2026	724073	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Albury Workshop	P/MOVER
1070	Albury - Workshop	Brakes\ABS	Truck Traction Control Light On All The Time Plus ESC & ABS Lights		completed by MB	13/07/2026	724073	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Albury Workshop	P/MOVER
1070	Albury - Workshop	VehService\AS	VehService\AS A Service	VehService\AS	completed by SS JS	13/07/2026	724073	Service	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Albury Workshop	P/MOVER
1070	Albury - Workshop	DrCabElec\ELECT P&W	Tablet Not Charging.		completed by MB	13/07/2026	724073	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Albury Workshop	P/MOVER
			VehService\B1 Svc B 1 Service,													
			Jack up steer axle check bearings and king pins.													
1070	Albury - Workshop	VehService\B1 Svc	Replace cabin filter.	VehService\B1 Svc	completed by JS SS	30/06/2026	718846	PreventativeMaintenance	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonwa Workshop	P/MOVER
1070	Albury - Workshop	DriveLine\OIL LEAK	diff pinion seal leaking		ok	30/06/2026	718846	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Hydraulics\OIL LEAK	leak spotted under hydraulic tank		ok	30/06/2026	718846	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	DrCabElec\PHONE	MICROPHONE FOR PHONE NOT CONNECTED.		ok	30/06/2026	718846	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Susp\WEIGHT GAUGE	finished of scales		completed by KR	26/06/2026	716403	Service	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Albury Workshop	P/MOVER
1070	Albury - Workshop	VehService\AS	VehService\AS A Service	VehService\AS	completed by AR SS	23/06/2026	715939	Service	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Albury Workshop	P/MOVER
1070	Albury - Workshop	VehService\AS	VehService\AS A Service	VehService\AS	completed by TP	13/06/2026	709522	Service	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Air Con\AIR CON	REPLACE HEATER BLOWER MOTOR		REPLACED. TESTED. OK. K.RYAN	04/06/2026	703800	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER
					BREAKDOWN REPAIR											
					-											
					The following breakdown repair for Greenfreight Logging Pty Ltd, to a TG59 Kenworth Truck, vin#6F5000000PA476814,											
					registration#WX28NH & number fleet number#0279 included:											
					* Customer contacted breakdown support to report that truck had broken down											
					* Customer advised that truck had an air leak & would not build up air											
					* Technician sourced replacement parts											
					* Technician travelled to breakdown site, Mannus, NSW											
					* Inspect to diagnose											
					* Located blown air dryer gasket											
					* Removed air dryer											
					* Cleaned down components & surfaces											
					* Installed replacement gasket, aligned & secured air dryer											
					* Pressurised, confirmed & quality checked repair											
					* Returned truck to service											
1070	Albury - Workshop	Frid Serv\AIR DRYER	Frid Serv\AIR DRYER		* Technician returned home	02/06/2026	703337	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	TWIN CITY TRUCK CENTRE - 4	P/MOVER
1070	Albury - Workshop	VehService\CS	VehService\CS C Service	VehService\CS	completed by SMc JS	29/05/2026	701551	Service	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Albury Workshop	P/MOVER
1070	Albury - Workshop	DriveLine\DIFF OIL	DriveLine\DIFF OIL Replace Diff oils	DriveLine\DIFF OIL	completed by SMc JS	29/05/2026	701551	PreventativeMaintenance	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Albury Workshop	P/MOVER
1070	Albury - Workshop	VehService\TRANS OIL	VehService\TRANS OIL Replace Synthetic Transmision oil	VehService\TRANS OIL	completed SMc JS	29/05/2026	701551	PreventativeMaintenance	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Albury Workshop	P/MOVER
1070	Albury - Workshop	VehService\AS	VehService\AS A Service	VehService\AS	KUM AT TIME OF SERVICE 700915	29/05/2026	700915	Service	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Myrtleford Workshop	P/MOVER
1070	Albury - Workshop	Elect\ALT	REPLACE ALTENATOR		DONE AT 677885 KMS	26/05/2026	700915	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Myrtleford Workshop	P/MOVER
1070	Albury - Workshop	Tyres\TP01	Tyres\TP01		TYRE WAS CHANGED LESS THAN 2 WEEKS AGO, DRIVER HIT WEIGHBRIDGE	18/05/2026	694681	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	BORDER BANDAG PTY LTD. - 4	P/MOVER
1070	Albury - Workshop	Body\MUDGUARDS	REPLACE LHF DRIVE M/GUARD			18/05/2026	694376	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Myrtleford Workshop	P/MOVER
1070	Albury - Workshop	Brakes\BACK PLATE	REPLACE MISSING BRAKE BACKING PLATES ON ALL 4 DRIVE WHEELS			18/05/2026	694681	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Myrtleford Workshop	P/MOVER
			REPLACE TOP & BOTTOM BELL CRANK BEARINGS													
1070	Albury - Workshop	DriveLine\CLUTCH	CHECK CLUTCH ADJUSTMENT			18/05/2026	694376	Repair	Completed	Greenfreight Loening Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Myrtleford Workshop	P/MOVER
1070	Albury - Workshop	DriveLine\DRV LN SER	ADJUST POWER DIVIDER			16/05/2026	697881	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Myrtleford Workshop	P/MOVER
1070	Albury - Workshop	DriveLine\WHEEL SEAL	REPLACE RHF DRIVE HUB SEAL		REPLACED JUST THE HUB SEAL BRAKES STILL IN OK CONDITION AND NO OIL ON THIM BEARINGS ALL GOOD	16/05/2026	697881	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Myrtleford Workshop	P/MOVER
1070	Albury - Workshop	DrCabRep\WIPERS	REPLACE BOTH LH & RH TOP BONNET PADS		COMPLETED ON JOB ABOVE	16/05/2026	697881	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Myrtleford Workshop	P/MOVER
1070	Albury - Workshop	DrCabRep\MOUNTS	REPLACE BONNET PIVOT BUSHES & BOTH TOP BONNET SURPORTS			16/05/2026	697881	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Myrtleford Workshop	P/MOVER
1070	Albury - Workshop	Engine\AIR LEAK	REMOVE BYPASSED AIR DRIER & FIT REBUILD KIT			16/05/2026	697881	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Myrtleford Workshop	P/MOVER
1070	Myrtleford - Workshop	VehService\AS	VehService\AS A Service	VehService\AS	KUM AT TIME OF SERVICE 693800	14/05/2026	694227	Service	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Myrtleford Workshop	P/MOVER
			VehService\B1 Svc B 1 Service,													
			Jack up steer axle check bearings and king pins.													
1070	Albury - Workshop	VehService\B1 Svc	Replace cabin filter.	VehService\B1 Svc	completed by TP JS	06/05/2026	689976	PreventativeMaintenance	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonwa Workshop	P/MOVER
1070	Albury - Workshop	Tyres\TP1+2	Tyres\TP1+2		LOW	02/05/2026	689762	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	BORDER BANDAG PTY LTD. - 4	P/MOVER
1070	Albury - Workshop	Engine\COMPRESSOR	Truck will not build up air , maybe compressor or Gov, valve ??		new compressor has been fitted	29/04/2026	697881	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Albury Workshop	P/MOVER
1070	Albury - Workshop	VehService\AS	VehService\AS A Service	VehService\AS	SMc,JS,SC	28/04/2026	683530	Service	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	DriveLine\CLUTCH	Adjust clutch brake.		completed by SMc,IS,JEC	28/04/2026	683530	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER
			A Service													
			Serviced @ 678,344 Kims		completed by TP AM											
1070	Albury - Workshop	VehService\AS	VehService\AS A Service	VehService\AS		18/04/2026	681970	Service	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER
			B Service													
1070	Albury - Workshop	VehService\B5	T133297	VehService\B5		07/04/2026	670004	Service	Completed	Greenfreight Loening Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonwa Workshop	P/MOVER
1070	Albury - Workshop	DriveLine\CLUTCH	Check & Adjust Clutch		SMc	07/04/2026	670004	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER
			Replace Batteries													
1070	Albury - Workshop	Elect\BATTERY				07/04/2026	670004	Repair	Completed	Greenfreight Loening Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonwa Workshop	P/MOVER
1070	Albury - Workshop	Tyres\TP7+8	Tyres\TP7+8			29/03/2026	667350	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	BORDER BANDAG PTY LTD. - 4	P/MOVER
1070	Albury - Workshop	Tyres\TP11+12	Tyres\TP11+12			29/03/2026	667350	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	BORDER BANDAG PTY LTD. - 4	P/MOVER
1070	Albury - Workshop	Tyres\TP9+10	Tyres\TP9+10			29/03/2026	667350	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	BORDER BANDAG PTY LTD. - 4	P/MOVER
1070	Albury - Workshop	Tyres\TP5+6	Tyres\TP5+6			29/03/2026	667350	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	BORDER BANDAG PTY LTD. - 4	P/MOVER
1070	Albury - Workshop	DriveLine\DAMAGE	left front hub seal leaking		completed SMc	18/03/2026	658231	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Albury Workshop	P/MOVER
1070	Albury - Workshop	Susp\HCV	Height adjuster valve rod on LHS		Previously completed	13/03/2026	655484	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Albury Workshop	P/MOVER
1070	Albury - Workshop	VehService\AS	VehService\AS A Service	VehService\AS		13/03/2026	655484	Service	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Albury Workshop	P/MOVER
1070	Albury - Workshop	Chassis\AIR TANKS	Tanks full water		Drain daily	13/03/2026	655484	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Albury Workshop	P/MOVER
1070	Albury - Workshop	DriveLine\DRIVES	FRONT DIFF INPUT SHAFT MOVEMENT NEEDS ADJUSTING		Let develop	13/03/2026	655484	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Albury Workshop	P/MOVER
			King Pins worn													
			Rear engine mounts cracked		Let King pins and engine mounts develop											
			Bell race has play		Loaded, can't look at ballrace											
1070	Albury - Workshop	Chassis	Bottom radiator hose o clamo snapped		Red hose has temo rwear done	13/03/2026	655484	Fault	Completed	Greenfreight Loening Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Albury Workshop	P/MOVER
			Replace Clutch (651770 Kims)													
1070	Albury - Workshop	DriveLine\CLUTCH	ITCTC P/O:			07/03/2026	700915	Repair	Completed	Greenfreight Loening Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	TWIN CITY TRUCK CENTRE	P/MOVER
					LOW											
1070	Albury - Workshop	Tyres\TP1+2	Tyres\TP1+2		CHANGED IN DECEMBER - OVER 50,000KM	28/02/2026	651770	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	BORDER BANDAG PTY LTD. - 4	P/MOVER
1070	Albury - Workshop	VehService\AS	VehService\AS A Service	VehService\AS		21/02/2026	646452	Service	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Susp\HCV	HCV need's adjustment, L/h/S sitting way to high.			17/02/2026	643729	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Albury Workshop	P/MOVER
			RADIATOR LEAKING													
1070	Albury - Workshop	Cooling\RADIATOR	BOTH RADIATOR CROSS BRACES BROKEN		CHARGE AIR COOLER TCTC	16/02/2026	641731	Fault	Completed	Greenfreight Loening Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Albury Workshop	P/MOVER
1070	Albury - Workshop	Susp\HCV	Height adjuster valve rod on L/H/S, [Repair/Replace HCV]		Rose joints replaced	16/02/2026	641553	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Albury Workshop	P/MOVER
1070	Albury - Workshop	DriveLine\SUSPENSION	ALL 4 REAR RIDE HEIGHT ROSE JOINTS NEED REPLACING			16/02/2026	641553	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Albury Workshop	P/MOVER
					Travel to greenfreight wodonga, check the operation of the gaurdian unit.											
					Removed the unit from it mounting bracket, plug the computer into the unit											
					to do a health check.											
					Could not connect to the unit, plugged the reset usb into the gaurdian unit,											
					tried to set up the unit with the computer. Could not connect back to the unit											
					to set it up correctly.											
					They will bring the truck to our yard when they are finished doing repairs.											
					Put everything back together, returned to the workshop. Tried to set up gaurdian											
					unit, could not get the unit to work correctly. Remove the unit and tried with a											
					new unit.											
					The set up worked with the new unit, found the forward facing camera was not											
					working. Remove all required panels to remove the camera.											
			DrCabElec\GPS GUARDIAN		Replaced the camera and test. The unit and camera is working correctly.											
1070	Albury - Workshop	DrCabElec\GPS	T098097		Put the truck back toaether correctly.	09/02/2026	644886	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	ARKON AUTO ELECTRICAL - 4	P/MOVER
1070	Albury - Workshop	Brakes\BRK RELINE	STEER & ALL DRIVE BRAKES ARE GETTING LOW 10 & 15 & 20 PERCENTS		all drive brakes replaced	09/02/2026	640999	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Albury Workshop	P/MOVER
			VehService\B1 Svc B 1 Service,													
			Jack up steer axle check bearings and king pins.													
1070	Albury - Workshop	VehService\B1 Svc	Replace cabin filter.	VehService\B1 Svc		09/02/2026	641067	PreventativeMaintenance	Completed	Greenfreight Loening Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Albury Workshop	P/MOVER
1070	Albury - Workshop	VehService\AS	VehService\AS A Service	VehService\AS	SERVICED AT 638105KMS	04/02/2026	638101	Service	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Myrtleford Workshop	P/MOVER
1070	Albury - Workshop	Body\WIPERS	Body\WIPERS		replace wiper blades	31/01/2026	636920	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Albury Workshop	P/MOVER
1070	Albury - Workshop	VehService\AS	VehService\AS A Service	VehService\AS		27/01/2026	631562	Service	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Albury Workshop	P/MOVER
1070	Albury - Workshop	Steering	Steer WheelBearing need adjusting			14/01/2026	628263	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Cooling	Radiator leaking from bottom tank and sight glass			14/01/2026	628263	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	DrCabRep\HOUSEKEEP	2.NO CAB AIR HOSE			14/01/2026	628263	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Steering\STEER UNI	REPLACE WORN STEERING SHAFT UNIS			14/01/2026	628263	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	DriveLine\CLUTCH	REPLACE CLUTCH BELL CRANK BEARINGS			14/01/2026	628263	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Body\AIR LEAK	1.BAD AIR LEAK UNDER CAB.			14/01/2026	628263	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Engine	Power steering pump leaking			14/01/2026	628263	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	VehService\AS	VehService\AS A Service	VehService\AS		14/01/2026	628263	Service	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Insp\ANN INSP	Insp\ANN INSP	VehService\AS		14/01/2026	628263	PreventativeMaintenance	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Albury Workshop	P/MOVER
1070	Albury - Workshop	VehService\B5	VehService\B5 B Service	VehService\B5		22/12/2025	623196	Service	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Albury Workshop	P/MOVER
1070	Albury - Workshop	VehService\AS	VehService\AS A Service	VehService\AS		22/12/2025	623196	Service	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Albury Workshop	P/MOVER
1070	Albury - Workshop	DriveLine\DIFF OIL	REPLACE DIFF OILS-SEMI-SYNTHETIC	DriveLine\DIFF OIL		22/12/2025	623196	PreventativeMaintenance	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Albury Workshop	P/MOVER
1070	Albury - Workshop	VehService\AS	VehService\AS A Service	VehService\AS	M.NEWELY 1 HR	04/12/2025	605300	Service	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Tyres\TP1+2	Tyres\TP1+2		TYRES WERE CHANGED IN SEPTEMBER BUT TRUCK HAS DONE 46,000KM SINCE THEN AND ONE TYRE HAD BLOWN	02/12/2025	605939	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	BORDER BANDAG PTY LTD. - 4	P/MOVER
1070	Albury - Workshop	Tyres\TP5+6	Tyres\TP5+6			26/11/2025	601574	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	BORDER BANDAG PTY LTD. - 4	P/MOVER
1070	Albury - Workshop	Tyres\TP7+8	Tyres\TP7+8			26/11/2025	601574	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	BORDER BANDAG PTY LTD. - 4	P/MOVER
1070	Albury - Workshop	Tyres\TP9+10	Tyres\TP9+10			26/11/2025	601574	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	BORDER BANDAG PTY LTD. - 4	P/MOVER
1070	Albury - Workshop	Tyres\TP11+12	Tyres\TP11+12			26/11/2025	601574	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	BORDER BANDAG PTY LTD. - 4	P/MOVER
1070	Albury - Workshop	Body\WIPERS	Replace wiper blades L/H/S.			25/11/2025	599368	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Albury Workshop	P/MOVER
			A Service													
1070	Albury - Workshop	VehService\AS	Serviced @ 589.137 Kims	VehService\AS		12/11/2025	589137	Service	Completed	Greenfreight Loening Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonwa Workshop	P/MOVER
1070	Albury - Workshop	VehService\B5	VehService\B5 B Service	VehService\B5		28/10/2025	578784	Service	Completed	Greenfreight Loening Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	DriveLine\OIL LEAK	Leaking RHF Wheel/Axle seal.			16/10/2025	572416	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Albury Workshop	P/MOVER
1070	Albury - Workshop	VehService\AS	VehService\AS A Service	VehService\AS		16/10/2025	572416	Service	Completed	Greenfreight Logging Vic	K

				Customer called breakdown technician * Customer advised of truck had suspected alternator failure * Technician sourced additional parts from GF depot in Wodonga * Technician travelled to breakdown location, Tumbarumba NSW * Inspect & confirmed failed alternator * Removed components for access * Removed/replaced alternator * Re-route cables to suit alternative alternator * Aligned & tensioned all components to specification * Check alternator output & confirmed output * Test, confirmed & quality checked repair * Returned truck to service * Technician returned home												
1070	Albury - Workshop	Engine\ALT	Engine\ALT BREAKDOWN - FAILURE T097215			01/10/2025	559494	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	TWIN CITY TRUCK CENTRE - 4 - OLD	P/MOVER
1070	Albury - Workshop	Brakes\AIR LEAK	Go to Mullengandra to fit quarter inch blank plug to leaking air line, after Wombat strike.			29/09/2025	558338	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Albury Workshop	P/MOVER
1070	Albury - Workshop	VehService\AS	VehService\AS A Service	VehService\AS		24/09/2025	559494	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Tyres\TP1+2	Tyres\TP1+2			24/09/2025	559494	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	BORDER BANDAG PTY LTD - 4	P/MOVER
1070	Albury - Workshop	Drv\Cabflap\WIPERS	PASSENGER SIDE WIPER BLADE FLOW AWAY...			16/09/2025	555707	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Susp\AIR BAG	R/H/F Air Bag Has Rubbed Through, Check Booster Supply That Rubbed Through Air Bag - Possibly Needs Replacement Too B Service			04/09/2025	543652	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	VehService\BS	Service @ 541,000 Kims	VehService\BS		02/09/2025	541306	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonwa Workshop	P/MOVER
1070	Myrtleford - Workshop	Chassis\SCALES	Scales not working-reading (no limits)		Inspected fuses all good problem deeper and needed more time	02/09/2025	541272	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Myrtleford Workshop	P/MOVER
1070	Albury - Workshop	Workshop\MOVE ASSET	DROPPED OFF DRIVER AT YACKANDANDAH.			28/08/2025	538429	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Tyres\Puncture	Tyres\Puncture POS 11 Cruise Control Not Working			24/08/2025	536167	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	BORDER BANDAG PTY LTD - 4	P/MOVER
1070	Albury - Workshop	DrCabElect\CRUISE CON	Kims: 535,045 Brake Lights On Constantly		Removed Panel Behind oedals. Check & Tested Hobbs Switch Found Faulty. Removed Hobbs Switch & Fitted New Hobbs Switch. Texted All Good.	23/08/2025	535045	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonwa Workshop	P/MOVER
1070	Albury - Workshop	Elect\BRK LIGHT	Kims: 535,045		Removed Panel Behind oedals. Check & Tested Hobbs Switch Found Faulty. Removed Hobbs Switch & Fitted New Hobbs Switch. Texted All Good.	23/08/2025	535045	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonwa Workshop	P/MOVER
1070	Myrtleford - Workshop	DrCabElect\SCALES	RE-CALIBRATE CH3 SCALES			22/08/2025	534442	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Myrtleford Workshop	P/MOVER
1070	Albury - Workshop	Engine\RADIATOR	Radiator support / cross braces broken A Service			20/08/2025	541272	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	VehService\AS	Serviced @ 531.122 Kims	VehService\AS		20/08/2025	541272	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonwa Workshop	P/MOVER
1070	Albury - Workshop	Chassis\HOUSEKEEP	Cruise Sensor		-sonar sensor swapped out with rolled over truck + scanned for codes and further faults, cruise fault still present due to ebs module issue	20/08/2025	541272	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Chassis\MUDGUARDS	Mud Flaps On Bull Bar			20/08/2025	541272	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Elect\BRK LIGHT	No Brake Light When Applying Trailer Hand Piece			20/08/2025	541272	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	DrCabElect\CRUISE CON	No Cruise Control		-cruise control will not work due to break light issue	20/08/2025	541272	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Susp	Unn bushing worn on shock			20/08/2025	541272	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Susp	Lhf shock lose on drive			20/08/2025	541272	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	DrCabElect\H/OUSEKEEP	12v plug not working		-key must be in accessories position for 12v socket to work	20/08/2025	541272	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	DrvLine\OIL LEAK	Through seal on drive shaft			20/08/2025	541272	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	DrCabRep\H/OUSEKEEP	-TRUCK STINKS LIKE BODY ODOUR. NEEDS AIRCON BOMB & NEW SEAT COVERS.			20/08/2025	541272	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	DrCabElect\WST/GAUGE	CHECK ALTERNATOR GAUGE NOT WORKING Brake Lights On Constantly.			20/08/2025	541272	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Elect\BRK LIGHT	(Arkon Auto Electrical P/O: T0962361)		-brakes lights staying on truck due to possible internal computer fault	12/08/2025	541272	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	ARKON AUTO ELECTRICAL - 4	P/MOVER
1070	Albury - Workshop	Elect\BRK LIGHT	Brake lights staying on - no cruise as a result REPAIR LEAKING FRONT DIFF.		-removing main esc fuse turns brake lights back to normal, brake switch working as intended, check engine and alternator light coming on intermittently, truck sent to arkon for further assesment and fault finding	12/08/2025	528307	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	DrvLine\OIL LEAK	(TCTC Reserine Under Warranty) pinion seal starting to weep.		Twin City Reseated Front Diff.	09/08/2025	527968	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	TWIN CITY TRUCK CENTRE - 4 - OLD	P/MOVER
1070	Albury - Workshop	DrvLine\DIFF REPAIN	(TCTC Repairing Under Warranty)		Twin City Replaced Pinion Seal. DIFF OILS REPLACED WHILST CARRYING OUT WARRANTY REPAIRS * Drain differential oil * Removed/replaced differential oil filter * Removed/cleaned & replaced differential screens * Installed differential lubricant levels to specification	09/08/2025	527968	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	TWIN CITY TRUCK CENTRE - 4 - OLD	P/MOVER
1070	Albury - Workshop	DrvLine\DIFF OIL	DrvLine\DIFF OIL - DIFF OILS REPLACED		* Re-torque all fittings & fixtures	09/08/2025	527968	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	TWIN CITY TRUCK CENTRE - 4 - OLD	P/MOVER
1070	Albury - Workshop	Steering\KING PIN	RH kingpin has 8 thou movement. May be due for Kingpins at C-service. (TCTC Reserine Under Warranty) Front diff banjo seal leaking.		Twin City Checked Kine Pin Movement. Movement is Within Spec.	09/08/2025	527968	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	TWIN CITY TRUCK CENTRE - 4 - OLD	P/MOVER
1070	Albury - Workshop	DrvLine\OIL LEAK	(TCTC Reserine Under Warranty) Front diff rear thru shaft seal leaking.		Twin City Reseated Diff	09/08/2025	527968	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	TWIN CITY TRUCK CENTRE - 4 - OLD	P/MOVER
1070	Albury - Workshop	DrvLine\OIL LEAK	(TCTC Repairing Under Warranty) JAKE BRAKES DON'T ENGAGE ON CRUISE UNTIL 10KPH.		Twin City Replaced Thru Shaft Seal.	09/08/2025	527968	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	TWIN CITY TRUCK CENTRE - 4 - OLD	P/MOVER
1070	Albury - Workshop	Engine\REBATE	(TCTC Reserine Under Warranty) POWER DIVIDER CLUNKS WHEN ENGAGED.			09/08/2025	527968	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	TWIN CITY TRUCK CENTRE - 4 - OLD	P/MOVER
1070	Albury - Workshop	DrvLine\DRV LN SER	(TCTC Reserine Under Warranty) OIL LEAK FRONT DIFF.		Twin City Inspected Diff & Power Divider Thev Found Not Issue Inside Diff To Cause Clunkine Noise.	09/08/2025	527968	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	TWIN CITY TRUCK CENTRE - 4 - OLD	P/MOVER
1070	Albury - Workshop	DrvLine\OIL LEAK	(TCTC Repairing Under Warranty) RANDOM CRUNCH FROM POWER DIVIDER WHEN UNDER LOAD.		Twin City Reseated Diff	09/08/2025	527968	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	TWIN CITY TRUCK CENTRE - 4 - OLD	P/MOVER
1070	Albury - Workshop	DrvLine\DRV LN SER	(TCTC Reserine Under Warranty) Rh King pin pay in and out.		Twin City Inspected Diff & Power Divider Thev Found Not Issue Inside Diff To Cause Clunkine Noise.	09/08/2025	527968	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	TWIN CITY TRUCK CENTRE - 4 - OLD	P/MOVER
1070	Albury - Workshop	Steering	(TCTC Reserine Under Warranty) clunk in diff when power divider is on (occasionally)		Twin City Checked Kine Pin Movement. Movement is Within Spec.	09/08/2025	527968	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	TWIN CITY TRUCK CENTRE - 4 - OLD	P/MOVER
1070	Albury - Workshop	DrvLine\DIFF REPAIN	(TCTC Reserine Under Warranty) diff has a major amount of freeplay (lash) when going on + off the power.		Twin City Inspected Diff & Power Divider Thev Found Not Issue Inside Diff To Cause Clunkine Noise.	09/08/2025	527968	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	TWIN CITY TRUCK CENTRE - 4 - OLD	P/MOVER
1070	Albury - Workshop	DrvLine\DIFF REPAIN	(TCTC Reserine Under Warranty)		Twin City Adjusted Pinion Free Play.	09/08/2025	527968	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	TWIN CITY TRUCK CENTRE - 4 - OLD	P/MOVER
1070	Albury - Workshop	DrvLine\OIL LEAK	RHF AXLE GASKET LEAKING NEEDS REPLACING.			05/08/2025	527940	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	DrvLine\OIL LEAK	front - R/H side differential oil visible			05/08/2025	527940	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	VehService\AS	VehService\AS A Service	VehService\AS		03/08/2025	525094	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Body\H/OUSEKEEP	CHECK OVER RADIATOR STAYS AND FRONT DIFF OIL LEAK			02/08/2025	525800	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Albury Workshop	P/MOVER
1070	Albury - Workshop	VehService\AS	VehService\AS A Service VehService\B1 Svc B 1 Service,	VehService\AS	#460905	26/07/2025	520520	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	VehService\B1 Svc	Jack up steer axle check bearings and king pins. Replace cabin filter. -CHECK GEARBOX OIL LOW PRESSURE LIGHT (PO:T095709) GEARBOX PRESSURE LIGHT ON * Connected laptop & scanned for faults * Found gearbox pressure switch to be faulty * Removed & replaced hobb switch	VehService\B1 Svc		26/07/2025	520520	PreventativeMaintenance	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonwa Workshoo	P/MOVER
1070	Albury - Workshop	DrCabElect\WST/GAUGE	* Test operations - All ok. fault no lonaer present			25/07/2025	520295	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	PACCAR PARTS FLEET SERVICES - 4	P/MOVER
1070	Albury - Workshop	DrvLine\GEARBOX	gear box pressure light on			25/07/2025	520295	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	PACCAR PARTS FLEET SERVICES - 4	P/MOVER
1070	Albury - Workshop	Tyres\TP1+12	Tyres\TP1+12			24/07/2025	519291	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	BORDER BANDAG PTY LTD - 4	P/MOVER
1070	Albury - Workshop	Tyres\TP9+10	Tyres\TP9+10			24/07/2025	519291	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	BORDER BANDAG PTY LTD - 4	P/MOVER
1070	Albury - Workshop	Brakes\EBS FAULTS	ENSURE TRAILER ABS FUSES ARE FITTED AND WORKING		Opened Fuse Box, Checked EBS Fuse's Were In Correct Positions & Not Blown, Closed Fuse Box, Checked EBS Leads Were Connected To Trailer's.	24/07/2025	518172	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Workshop\MOVE ASSET	Pick up from TCTC after dropping off 1026 DrvLine\CLUTCH REPLACEMENT (PO:T095715) Machine flywheel CLUTCH CUSTOMER REPORTED UNABLE TO ADJUST CLUTCH & FOUND PIECE OF SPRING WHEN ATTEMPTING TO ADJUST ** PARTS RETAIL CHARGE TO CUSTOMER AS CLUTCH OUT OF WARRANTY & EATON REFUSING TO OFFER ANY SUPPORT		Arrived at TCTC to pickup truck. Was advised still had 20 minutes of work left on it. Waited. Was then advised there was a leaking brake booster on the combination and would require more time. Given loan car to go off site until finished. Breakdown - Called back in to sticlus combination once completed	21/07/2025	516210	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	DrvLine\CLUTCH	TCTC COVERED LABOUR GF COVERED PARTS DUE TO ABOVE			18/07/2025	514900	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	PACCAR PARTS FLEET SERVICES - 4	P/MOVER
1070	Albury - Workshop	VehService\AS	VehService\AS A Service (PO:T095708)	VehService\AS		18/07/2025	515303	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	PACCAR PARTS FLEET SERVICES - 4	P/MOVER
1070	Albury - Workshop	DrvLine\DRV LN SER	ADJUSTED DIFF. CHECKED OIL LEVEL.			17/07/2025	522081	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Elect\H/OUSEKEEP	Elect\H/OUSEKEEP replace electrical plug Engine\ALT			15/07/2025	504077	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Engine\ALT	Check alternator for charge rate. All good.			15/07/2025	511077	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Elect\H/OUSEKEEP	Check awar box oil level no clearance lights		Completed by Blair an keith B/7	09/07/2025	505495	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	VehService\AS	VehService\AS A Service	VehService\AS		07/07/2025	503957	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Workshop\MOVE ASSET	Hook up to T3M/B12			07/07/2025	503957	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	DrvLine\CLUTCH	ADJUST CLUTCH FREE TRAVEL.			07/07/2025	503957	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Body\MUDGUARDS	RHF DRIVE GUARD REPLACEMENT-KANGAROO DAMAGE		Previously completed	07/07/2025	503957	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Body	Rh Bonnet indicator out			07/07/2025	503957	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	DrCabElect\FLECT P&W	UHF bottom one dial broken			07/07/2025	503957	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Brakes\BRK RELINE	Rear drive brakes bow - Replace			07/07/2025	503957	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	DrvLine\WHEEL SEAL	LHR hubseal			07/07/2025	503957	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	DrCabElect\WST/GAUGE	REPAIR/ REPLACE VOLT GAUGE.		-volt gauge inspected, couldnt fault -USB points under UHF units replaced due to being smashed off -A UHF control knob replaced	07/07/2025	503957	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Workshop\MOVE ASSET	Unhook trailers		-	03/07/2025	503956	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	DrvLine\CLUTCH	Clutch brake needs adjusting		Inspected clutch. Found excessive grease inside housing. Adjusted clutch and freeplay. Tested operation - Clutch brake not holding. Adjusted clutch again. Tested operation again - Clutch brake still not holding	03/07/2025	503956	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	DrCabElect\WST/GAUGE	ALT GAUGE READING THEN NOT READING		CHECK VOLTAGE ALL GOOD REPLACED FUSE REPLACED GAUGE LIGHT STARTED AND RECHECK UNABLE TO FAULT	03/07/2025	503922	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Albury Workshop	P/MOVER
1070	Albury - Workshop	Hydraulics\HYD LEAKS	HYD SLOW AND OIL LEAK AT TANK		INSPECTED LEVEL FOUND TO BE LOW TOP UP ALSO REPLACED RETURN FILTER HOUSING DO TO OLD LEAKING TESTED AND ALL GOOD	03/07/2025	503922	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Albury Workshop	P/MOVER
1070	Albury - Workshop	DrCabRep\H/OUSEKEEP	Truck Stinks like Body Odor Needs Aircon Bomb & New seat Covers.		Started up truck turned A/C on to recirculate set bomb off in cabin closed doors, let bomb do it's job, removed bomb from cabin, turned A/C Off, sent truck back into service.	02/07/2025	503230	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	VehService\CS	VehService\CS	VehService\CS		28/06/2025	502109	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	VehService\TRANS OIL	Transmission Oil Change	VehService\TRANS OIL	REPLACED OIL AND FILTER	28/06/2025	502109	PreventativeMaintenance	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	DrvLine\OIL LEAK	RHF drive axle gasket leaking		REPLACED GASKET. KR.	28/06/2025	502109	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	DrvLine\DIFF OIL	DrvLine\DIFF OIL	DrvLine\DIFF OIL		28/06/2025	502109	PreventativeMaintenance	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Workshop\MOVE ASSET	Unhook trailers and park truck behind workshop			27/06/2025	501390	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Tyres\TP5+6	Tyres\TP5+6			23/06/2025	497176	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	BORDER BANDAG PTY LTD - 4	P/MOVER
1070	Albury - Workshop	Tyres\TP7+8	Tyres\TP7+8		UNREPAIRABLE PUNCTURE	23/06/2025	497176	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	BORDER BANDAG PTY LTD - 4	P/MOVER
1070	Albury - Workshop	Tyres\TP1+2	Tyres\TP1+2			23/06/2025	497176	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	BORDER BANDAG PTY LTD - 4	P/MOVER
1070	Albury - Workshop	VehService\AS	VehService\AS A Service	VehService\AS		21/06/2025	496362	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Albury Workshop	P/MOVER
1070	Albury - Workshop	DrvLine	Front diff pinion seal leaking			21/06/2025	502207	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	PACCAR PARTS FLEET SERVICES - 4	P/MOVER
1070	Albury - Workshop	VehService\AS	VehService\AS A Service	VehService\AS		21/06/2025	502207	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	PACCAR PARTS FLEET SERVICES - 4	P/MOVER
1070	Albury - Workshop	Body\MUDGUARDS	RHF drive guard - Roo damage VehService\B1 Svc B 1 Service,			13/06/2025	490035	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	VehService\B1 Svc	Jack up steer axle check bearings and king pins. Replace cabin filter.	VehService\B1 Svc		30/05/2025	481812	PreventativeMaintenance	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonwa Workshoo	P/MOVER
1070	Albury - Workshop	DrvLine\PTO	PTO not engaging Repair Air Leak At Gear-Box.		Refit missing PTO fuse due to previous trailers left as flat tow pending repairs Received call from costumer in regards to truck having air leak. Drove down to workshop and packed work Ute. Drove out to costumer. Located air leaking coming from main feed air line to gear box. Found fitting to be Broken. Removed old fitting and installed new fitting. Hooked air line into new fitting. Started truck and checked for air leaks and found all good. Packed up work area and drove back home. Filled out paper work.	29/05/2025	541272	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	DrvLine\AIR LEAK	(Bidgee Mechanical P/O: T094701)			28/05/2025	484637	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	BIDGEE MECHANICAL	P/MOVER
1070	Albury - Workshop	Susp\DAMAGE	Height control leaver fell off			26/05/2025	475698	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Chassis\BULLBAR	BOLT MISSING ON BULLBAR. A Service. Serviced @ 477,471 Kims			24/05/2025	477471	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	VehService\AS	VehService\AS	VehService\AS		24/05/2025	477471	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonwa Workshoo	P/MOVER
1070	Albury - Workshop	VehService\AS	VehService\AS A Service	VehService\AS	Booked into TCTC 16/5 #TD94159	21/05/2025	472259	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	PACCAR PARTS FLEET SERVICES	P/MOVER
1070	Albury - Workshop	Susp\AIR BAG	Air bag on drive RHS rear		REPLACED RR AIRBAG.	14/05/2025	469026	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Body\PANELS	Straighten & Repair R/H/S Front Quarter Guard			14/05/2025	469618	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Susp\AIR BAG	ROBINSON'S TRUCK & COACH - HARD'S TRUCK AND TRAILER REPAIRS- BREAKDOWN. TRAVEL TO AND FROM BENALLA-TATONG RD. REPLACE RRR BLOWN AIRBAG.			14/05/2025	541272	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	ROBINSON'S TRUCK & COACH - 4	P/MOVER

			Susp\AIR BAG BREAKDOWN REPAIR The following breakdown repair for GreenFreight Logging Pty Ltd, to a T659 Kenworth Truck, vin#6F5000000PA476814, registration#KW75GX & number fleet number#1070 included: * Customer contacted dealership breakdown technician with information regarding breakdown * Customer advised technician that truck had failed tyres & blown air bag * Technician sourced replacement parts * Technician travelled to breakdown site, Shelley-Wallara Rd, Vic * Removed walkway for air bag access * Blocked off failed air bag line & pressurised system to raise air bags * Balled & removed RHR drive wheel equipment * Removed failed RH front air bag,airlines & mounting components * Removed/replaced air bag * Installed wheel equipment * Align & tension all components * Pressurised, test, confirm & quality check repair * Removed ballasting * Returned truck to service																			
1070	Albury - Workshop	Susp\AIR BAG	* Technician returned home							06/05/2025	464217	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	PACCAR PARTS FLEET SERVICES - 4	P/MOVER
1070	Albury - Workshop	Tyres\TPX-10	Tyres\TPX-10							06/05/2025	464107	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	BEAUREPAIRES - 4	P/MOVER
1070	Albury - Workshop	Tyres\TP7-8	Tyres\TP7-8							06/05/2025	464107	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	BEAUREPAIRES - 4	P/MOVER
			DAMAGE CAUSED BY TYRE FAILURE-																		
1070	Albury - Workshop	Body\DAMAGE	REPAIR/ REPLACE DAMAGED GUARDS, CTI LINES AND OTHER REQUIRED COMPONENTS.							01/05/2025	461893	Repair	Completed	Greenfreight Loxenne Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Albury Workshop	P/MOVER
1070	Albury - Workshop	Body\PANELS	BATTERY BOX							28/04/2025	459932	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	DriveLine\OIL LEAK	Front diff leak			Monitor				28/04/2025	459932	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	DriveLine\SUSPENSION	Right engine mount split							28/04/2025	459932	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	DrCabElec\SCALES	Scales not working properly not at all on back trailer.							28/04/2025	459932	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Susp\Torque Rod	Torque rod Bush's worn replace at b service			Monitor				28/04/2025	459932	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	VehService\85	VehService\85 B Service		VehService\85					28/04/2025	459932	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Air Con\AIR CON	AC NEEDS CLEAN OUT - FAN BARELY BLOWS							28/04/2025	459932	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	DrCabElec\HOUSEKEEP	fuse cover on dash missing LH screw retainer							28/04/2025	459932	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Brakes\AIR LEAK	Hot hose leaking							28/04/2025	459932	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Engine\COMPRESSOR	CHECK COMPRESSORT OR GOVERNOR VALVE. LOSING AIR.							28/04/2025	459932	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Body\PANELS	L/H BATTERY BOX LID MISSINGL...?							28/04/2025	459932	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Chassis\AIR LEAK	Air tank infront of middle axle drivers side leaking fittings							28/04/2025	459932	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Air Con\AIR CON	A/C ISN'T COOLING & FAN STILL NOT BLOWING HARD.							28/04/2025	459932	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Body\HOUSEKEEP	no battery case p/side							28/04/2025	459932	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Brakes\BRAKE ADJ	PARKING BRAKE HAS HIGH PITCHED SQUEAL							28/04/2025	459932	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	DriveLine\SUSPENSION	Right engine mount split							28/04/2025	459932	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Air Con\AIR CON	no a/c - hot air only							28/04/2025	459932	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Brakes\AIR LEAK	Truck air drains to 0kpa when off. Check and repair air leaks							28/04/2025	459932	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Air Con\AIR CON	NO A/C- HOT AIR ONLY.							17/04/2025	456739	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	ARKON AUTO ELECTRICAL	P/MOVER
1070	Albury - Workshop	Workshop\ABOVE ASSET	DROP OFF ARKON AUTO ELECTRICAL.							15/04/2025	456201	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Albury Workshop	P/MOVER
			VehService\81 Svc																		
1070	Albury - Workshop	VehService\81 Svc	TCTC PO #TD82975		VehService\81 Svc					15/04/2025	440000	PreventativeMaintenance	Completed	Greenfreight Loxenne Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	PACCAR PARTS FLEET SERVICES - 4	P/MOVER
						Truck odometer 455911															
1070	Albury - Workshop	VehService\AS	VehService\AS A Service		VehService\AS	Hot hose leaking fix asap				15/04/2025	455912	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Chassis\HYDRAULICS	Male hydraulic coupling worn							15/04/2025	455912	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
			TWIN CITY TRUCK CENTRE-																		
1070	Albury - Workshop	Engine\OIL LEAK	REPLACED POWER STEER GASKET. (WARRANTY)							11/04/2025	453864	Repair	Completed	Greenfreight Loxenne Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Albury Workshop	P/MOVER
1070	Albury - Workshop	Engine\BOOST HOSE	REPLACED BOOST HOSE.							11/04/2025	453864	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Albury Workshop	P/MOVER
1070	Albury - Workshop	Tyres\TP10	Repair Punctured Tyre Position 10. (Wodonga Tyre & Auto P/O: T093304)							03/04/2025	446724	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	BEAUREPAIRES - 4	P/MOVER
1070	Albury - Workshop	VehService\AS	VehService\AS A Service		VehService\AS					01/04/2025	445626	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Comp\Truck Safe	FIT TRUCKSAFE STICKER.							01/04/2025	445626	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Engine\BOOST HOSE	TURBO/ INTERCOOLER/ BOOST PIPE LEAK- CAN HEAR IT WHISTLE.			Couldn't fault during service				01/04/2025	445626	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
			VehService\AS A Service																		
1070	Albury - Workshop	VehService\AS	PO #TD93110		VehService\AS					27/03/2025	440000	Service	Completed	Greenfreight Loxenne Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Albury Workshop	P/MOVER
1070	Albury - Workshop	Susp\SUSPENSION	CHECK FRONT OF TRUCK FOR DAMAGE OR WEAR.			K.RYAN 1 HOUR LABOUR.				26/03/2025	443971	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Albury Workshop	P/MOVER
1070	Albury - Workshop	Tyres\TP1+2	Tyres\TP1+2							25/03/2025	444370	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	BEAUREPAIRES - 4	P/MOVER
						*A/C not working System low on gas. Pressure test system. Tx valve is blocked. Remove dash panels to gain access to the evaporator. Unbolt heater box and remove evaporator. Fit new evaporator. Reassemble dash. Replace cabin filter and dryer. Pressure test system. Evacuate system. Charge system with 1200g of R134a. Check operation of system. Failed to cycle, vent temps to cold. Will need to replace thermistor. Degas the A/C system, pull the dash panels off to expose the heater box. Pull the evaporator cover. Remove the thermistor and fit the new one. Refit all the covers and dash panels. Refill the A/C system with 1200g of R134a ass. Test the A/C system. Ok. Dross off at Greenfreight.										
1070	Albury - Workshop	Air Con\AIR CON	A/C NOT FLOWING WELL. (Arkon Auto Electrical P/D: T093214)							17/03/2025	436794	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	ARKON AUTO ELECTRICAL - 4	P/MOVER
						lower bell crank bearing was way pass its use bye date removed and replaced readjusted free travel inspected clutch tested all good															
1070	Myrtleford - Workshop	DriveLine\CLUTCH	clutch needs adjusting			INLM at time of reaar 435811				14/03/2025	436508	Fault	Completed	Greenfreight Loxenne Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Myrtleford Workshop	P/MOVER
1070	Albury - Workshop	VehService\AS	No truck safe sticker			On order as per another fault				13/03/2025	434782	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Cooling\ENG FAN	Horton needs rebuild							13/03/2025	434782	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	VehService\AS	VehService\AS A Service		VehService\AS					13/03/2025	434782	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	DriveLine\OIL LEAK	Oil still throwing out of input shaft,front left. (Warranty)			Previously completed				13/03/2025	434782	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	DriveLine\OIL LEAK	Oil throwing out of front Diff Input Shaft.			Previously completed				13/03/2025	434782	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	VehService\AS	VehService\AS A Service		VehService\AS					06/03/2025	431833	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Engine\BOOST HOSE	BOOST/TURBO LEAK							04/03/2025	430245	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Engine\HOUSEKEEP	intake boost leak							04/03/2025	430245	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
			INTAKE CHANGE PIPE LEAK @ A JOINER.																		
1070	Albury - Workshop	Engine\BOOST HOSE	(AUDIBLE SQUEAL UNDER LOAD)			Completed by Keith				04/03/2025	430245	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Air Con\AIR CON	air conditioner minimal airflow in cab - probably heater core under dash blocked			Completed by Russell				04/03/2025	430245	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Tyres\TP12	Tyres\TP12							04/03/2025	429375	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	BEAUREPAIRES - 4	P/MOVER
1070	Wodonga - Workshop	VehService\85	VehService\85		VehService\85					02/03/2025	428513	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	VehService\AS	VehService\AS A Service		VehService\AS					02/03/2025	428513	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	DrCabElec\ELECT P&W	Volt gauge moving around between 10 to 14 volts (stereo switched on & off a few times while doing so.			Jimmy replaced wiring				28/02/2025	428206	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Body\MUDGUARDS	REPLACED DAMAGED DRIVE GUARD. ADJUSTED AND TIGHTENED OUTRIGGERS.							18/02/2025	420456	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Albury Workshop	P/MOVER
1070	Wodonga - Workshop	VehService\AS	VehService\AS		VehService\AS					17/02/2025	420455	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
			- ATTEND CALLOUT TO ALPINE MSF TO VEHICLE REPORTED																		
			NOT STARTING, FOUND FAILED STARTER MOTOR, REPORT TO																		
1070	Albury - Workshop	Elect\START MOTR	GREENFREIGHT MANAGEMENT. RETURN TO WORKSHOP							11/02/2025	541272	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	ROBINSON'S TRUCK & CDACH - 4	P/MOVER
1070	Wodonga - Workshop	Brakes\BRK RELINE	Brakes\BRK RELINE FRONT DRIVE AXLE							03/02/2025	411231	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	VehService\AS	VehService\AS		VehService\AS					01/02/2025	410631	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
			TWIN CITY TRUCK CENTRE-CALL OUT																		
			* Customer contacted dealership breakdown technician with information regarding breakdown																		
			* Customer advised technician that alternator had caught fire																		
			* Technician sourced replacement parts																		
			* Technician travelled to breakdown site, Tumbarumba, NSW																		
			* Lowered bull bar & lifted bonnet for access																		
			* Confirmed failed alternator																		
			* Removed components for access & alternator																		
			* Installed replacement alternator, pulley & belt																		
			* Check alternator output - 14.2v output confirmed																		
			* Test, confirm & quality check repair																		
			* Returned truck to service																		
1070	Myrtleford - Workshop	Elect\ALT	* Technician returned home							31/01/2025	541272	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	PACCAR PARTS FLEET SERVICES - 3	P/MOVER
1070	Wodonga - Workshop	VehService\81 Svc	VehService\81 Svc		VehService\81 Svc					23/01/2025	405749	PreventativeMaintenance	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Body\AIR FITTIN	REPAIR LEAKING HOSE							21/01/2025	420538	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	RALMATCH ENGINEERING - 4	P/MOVER
1070	Wodonga - Workshop	Elect\ELECT P&W	After Light is ON.			Keith completed this job				15/01/2025	402095	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
						Keith did the top															
						Doug the bottom															
1070	Wodonga - Workshop	VehService\81 Svc	VehService\81 Svc		VehService\81 Svc	Front diff needs reline				15/01/2025	402095	PreventativeMaintenance	Completed	Greenfreight Loxenne Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Elect\ELECT P&W	Trailer ABS Light On all the Time.			This is a trailer issue not a truck issue				15/01/2025	402095	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	BEAUREPAIRES - 4	P/MOVER
1070	Wodonga - Workshop	VehService\AS	VehService\AS		VehService\AS	A b1 service was done not an A				15/01/2025	402095	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Brakes\BRAKE ADJ	Brakes won't hold while loading			Part of the service				15/01/2025	402095	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
						REPLACED CAB FILTER.															
1070	Wodonga - Workshop	Air Con\AIR CON	*CHECK A/C. POOR AIR FLOW. REALLY STRUGGLED WITH OVER 35° TEMP DAY.			KEITH.				15/01/2025	402715	Fault	Completed	Greenfreight Loxenne Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Tyres\TP3+4	Tyres\TP3+4							07/01/2025	396335	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	BEAUREPAIRES - 4	P/MOVER
1070	Albury - Workshop	Tyres\TP7-8	Tyres\TP7-8							07/01/2025	396335	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	BEAUREPAIRES - 4	P/MOVER
1070	Albury - Workshop	Tyres\TP5-6	Tyres\TP5-6							07/01/2025	396335	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	BEAUREPAIRES - 4	P/MOVER
1070	Albury - Workshop	Tyres\TP9+10	Tyres\TP9+10							07/01/2025	396335	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	BEAUREPAIRES - 4	P/MOVER
1070	Wodonga - Workshop	Brakes\BRAKE ADJ	Check & Adjust Brakes			Doug ashved truck requires a padslpa				07/01/2025	396335	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Cooling\RADIATOR	Possible Intercooler Leak.			No leak found				06/12/2024	387167	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Engine\EXHAUST	Weld new flange on exhaust pipe							28/11/2024	380173	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	VehService\85	VehService\85		VehService\85					28/11/2024	379613	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	DriveLine\WHEEL SEAL	Axle Seals Leaking Badly on Front Drive.			Cherish repaired				28/11/2024	379613	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	DriveLine\OIL LEAK	Axle seal leaking worse - there won't be any oil left soon....			Duplicate job				28/11/2024	379613	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Brakes\BRAKE ADJ	Brakes don't hold on hills when black button is in			Brakes were under adjusted now corrected				28/11/2024	379613	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	DriveLine\OIL LEAK	Front drive axle seals still leaking badly			Cherish repaired				28/11/2024	379613	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Tyres\FITMENT	Replace Drive Tyres Positions 3,4,5,6. (Wodonga Tyre & Auto P/O: T090140)							06/11/2024	365760	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	BEAUREPAIRES - 4	P/MOVER
1070	Albury - Workshop	Tyres\STEER TYRE	Replace Steer Tyres. (Wodonga Tyre & Auto P/O: T090140)							06/11/2024	365760	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	BEAUREPAIRES - 4	P/MOVER
1070	Wodonga - Workshop	VehService\AS	VehService\AS		VehService\AS					06/11/2024	366661	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	DriveLine\GEARBOX	Gearbox Rattling Under Shifter Random							06/11/2024	366661	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Steering\WHEEL ALGN	Steers Pulling To Right Constant							06/11/2024	366661	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Chassis\SCALES	scales not working			Scales Repaired				06/11/2024	366661	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	DrCabElec\CRUISE CON	when on cruise and you put foot on brakes the cruise control stay on			Repaired By TCTC				06/11/2024	366661	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	DrCabReg\ST Wwel	When Cruise Control On & You Brake The Cruise Doesn't Click Out			Repaired By TCTC				06/11/2024	366661	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	DrCabElec\SCALES	SCALES DON'T WORK.			Scales Repaired				06/11/2024	366661	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Air Con\AIR CON	AIR CONDITIONER NOT WORKING.			works				06/11/2024	366661	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	DrCabElec\CRUISE CON	Cruise/Cntr Cut Not Working On Brake Pedal			repaired By TCTC				06/11/2024	366661	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Chassis\SCALES	Scales Not Working Still			Scales Repaired				06/11/2024	366661	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	DrCabElec\CRUISE CON	CRUISE NOT DISENGAGING WITH BRAKE PEDAL.			Repaired By TCTC				06/11/2024	366661	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Elect\ELECT P&W	SCALES NOT WORKING ON TRAILERS.			Scales Repaired				06/11/2024	366661	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	DrCabElec\CRUISE CON	CRUISE CONTROL STAYING ON WHEN USING BRAKE.			Checked works as should				06/11/2024	366661	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Myrtleford - Workshop	Elect\WORK LIGHT	replace broken work light bracket on log guard RH lower							05/11/2024	365759	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Myrtleford Workshop	P/MOVER
1070	Myrtleford - Workshop	DriveLine\CTI Drive	tighten loose CTI line LHR drive							05/11/2024	365759	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Myrtleford Workshop	P/MOVER
1070	Albury - Workshop	Tyres\TP08	Tyres\TP08							30/10/2024	358301	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	BEAUREPAIRES - 4	P/MOVER
1070	Wodonga - Workshop	DrCabElec\ELECT P&W	TC light on all the time			Checked an light was not on. Driver to monitor.				18/10/2024	352324	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Brakes\ABS	ABS TRK, TRL ABS "ON" DASH			Duplicate job				18/10/2024	352324	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	DrCabElec\INST/GAUGE	After treat light flash on/off							18/10/2024	352324	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Brakes\ABS	ABS trailer light on			The trailer needs to be assessed not the truck				18/10/2024	352324	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	VehService\AS	VehService\AS		VehService\AS					18/10/2024	352324	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Chassis\AIR LEAK	Losing Air To 600 PSI							18/10/2024	352324

			Air Con\AIR CON REPORTS AIRCON NOT COLD & LEAKING GAS																
			* Test operations & confirmed fault * Found gas to be leakings from condenser * Inspected further & found leak caused from impact damage - non warrantable * Disconnected all lines * Unbolted & removed condenser * Installed replacement condenser * Removed & replaced receiver dryer * Installed replacement bug screen as found to alos be damaged * Vacced down A/C system * Regased with dye as required														
1070	Albury - Workshop	Air Con\AIR CON	* Test operations - All ok. fault no lonaer present					16/10/2024	350317	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	PACCAR PARTS FLEET SERVICES - 4	P/MOVER
1070	Albury - Workshop	Tyres\TP7+10	Tyres\TP7+10					11/10/2024	346897	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	BEAUREPAIRES - 4	P/MOVER
1070	Albury - Workshop	Tyres\TP7+8	Tyres\TP7+8					11/10/2024	346897	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	BEAUREPAIRES - 4	P/MOVER
1070	Myrtleford - Workshop	Steering\WHEEL STUD	replaced broken wheel nut washer RHF steer				removed and replaced nut retention ed recheck all good	09/10/2024	344893	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Myrtleford Workshop	P/MOVER
1070	Wodonga - Workshop	DrCabRep\WIPERS	fill water washer bottle				completed by Doug	07/10/2024	343159	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	VehService\AS	A Service. Serviced 341.849 Kms	VehService/AS				03/10/2024	366661	Service	Comoleted	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonwa Workshop	P/MOVER
1070	Wodonga - Workshop	Body\DAMAGE	Repair Bullbar					25/09/2024	338298	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	VehService\BS	B Service	VehService/BS		Done by Ruby		24/09/2024	338303	Service	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	VehService\AS	VehService\AS	VehService/AS				24/09/2024	338303	Service	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	VehService\AS	VehService\AS	VehService/AS				04/09/2024	325168	Service	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	DrivLine\WHEEL SEAL	Outer drive Wheel Seal Leaking.					04/09/2024	325168	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	DrCabElec\INST/GAUGE	1 dash light out			Job completed by cherysh		30/08/2024	322341	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	DrCabElec\BATTERY	Flat batterys start of shift doug jump started					29/08/2024	320856	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	VehService\AS	VehService\AS	VehService/AS				29/08/2024	320856	Service	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Myrtleford - Workshop	Elect\ELECT P&W	slide locks not unlocking			inspected and found problem to be in the ele plugs (both male -female plugs need replacing)		26/08/2024	323107	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Myrtleford Workshop	P/MOVER
			UNCOMPLETED C SERVICE ITEMS: AIR DRYER																
1070	Wodonga - Workshop	VehService	LH STEER BEARINGS					20/08/2024	315653	Fault	Comoleted	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonwa Workshop	P/MOVER
1070	Wodonga - Workshop	VehService\AS	VehService\AS	VehService/AS				20/08/2024	315653	Service	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Tyres\TP7+2	Tyres\TP7+2					14/08/2024	311386	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	BEAUREPAIRES - 4	P/MOVER
1070	Wodonga - Workshop	VehService\AS	VehService\AS	VehService/AS				10/08/2024	308642	Service	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	VehService\CS	C Service	VehService/CS				01/08/2024	301387	Service	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
			DrCabElec\GPS Travel to Greenfreight Wodonga yard. Diagnose issue with cellular dropping out on mt data. Couldn't fault hardware issue. Contact mt data for health check. They found unit was using an old firmware and pushed update. Also fixed update issue on tablet. They could not find a fault in the logs and believes the update will fix issue. Fixed charging issue with tablet as well. Look at trailer loader switch only unloading not loading. Check switch is working. Found hydraulic solenoid had a bad connection. Replaced both hirschmen connctors and confirmed wiring to them are ok. If still faulting it will be a mechanical issue.																
1070	Albury - Workshop	DrCabElec\GPS	Return to workshop					26/07/2024	298011	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	AIRCON AUTO ELECTRICAL - 4	P/MOVER
1070	Wodonga - Workshop	VehService\B1 Svc	VehService\B1 Svc	VehService/B1 Svc				23/07/2024	295467	PreventativeMaintenance	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Myrtleford - Workshop	DrCabElec\SCALES	calibrate scales			cerebrated all 3 ch (tare and span)		23/07/2024	295467	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Myrtleford Workshop	P/MOVER
1070	Wodonga - Workshop	Air Con\AIR CON	AC FREEZES UP.					11/07/2024	286220	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	VehService\AS	VehService\AS	VehService/AS		286224ks		11/07/2024	286220	Service	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Unknown	L/H hub cap missing					11/07/2024	286220	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Air Con\HEATER	CABIN HEATER NOT WORKING. RADIATOR LEAKING TOP L/H SIDE.			WORKING WHEN TESTED.		02/07/2024	338303	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Cooling\COOL LEAKS	LOW COOLANT SENSOR DIDN'T COME ON.			Yes radiator is leakine too left corner and coolant level sensor didn't come on warranty job		02/07/2024	338303	Fault	Comoleted	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonwa Workshop	P/MOVER
1070	Albury - Workshop	Tyres\TP3+6	Tyres\TP3+6					29/06/2024	277952	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	BEAUREPAIRES - 4	P/MOVER
1070	Albury - Workshop	Tyres\TP7+8	Tyres\TP7+8					29/06/2024	277952	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	BEAUREPAIRES - 4	P/MOVER
1070	Albury - Workshop	Tyres\TP5+6	Tyres\TP5+6					29/06/2024	277952	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	BEAUREPAIRES - 4	P/MOVER
1070	Albury - Workshop	Tyres\TP9+10	Tyres\TP9+10					29/06/2024	277952	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	BEAUREPAIRES - 4	P/MOVER
1070	Wodonga - Workshop	VehService\AS	VehService\AS	VehService/AS		261740		17/06/2024	261735	Service	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Tyres\TP1+2	Tyres\TP1+2					06/06/2024	251154	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	BEAUREPAIRES - 4	P/MOVER
						251153 km													
1070	Wodonga - Workshop	VehService\AS	VehService\AS	VehService/AS				05/06/2024	251149	Service	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonwa Workshop	P/MOVER
1070	Wodonga - Workshop	VehService\B1 Svc	B 1 Service	VehService/B1 Svc				05/06/2024	251149	PreventativeMaintenance	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Engine\GOV VALVE	REPLACE GOVERNOR VALVE.			REPLACED GOVERNOR VALVE. TESTED. OK.		31/05/2024	240845	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	VehService\AS	A Service	VehService/AS				22/05/2024	238193	Service	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection	Insp/ANN INSP				22/05/2024	238193	PreventativeMaintenance	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	DrCabRep\ST Weel	STEERING WHEEL CABLE BROKEN.					22/05/2024	238193	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Elect\WORK LIGHT	L/H BOTTOM LOAD LIGHT CAB RACK NEED PUTTING ON TOP OF BRACKET TO GET RAKE HOE OUT.					09/05/2024	227884	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Brakes	Record Check Results As Attached To This.Job					09/05/2024	227884	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Air Con\AIR CON	check air con - Blowing hot air on day shift					09/05/2024	227884	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Tyres	STEERING SHAKE - DRIVE TYRES WEARING UNEVEN.					09/05/2024	227884	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Brakes\EBS FAULTS	TRAILER ABS LIGHT ON.					09/05/2024	227884	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	DrivLine\CLUTCH	CLUTCH ADJUST.					09/05/2024	227884	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Engine\ADBLUE	AFTER TREART LIGHT FLASHES ON & OFF.					09/05/2024	227884	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	VehService\BS	Service As Per Attached Checklist	VehService/BS				09/05/2024	227884	Service	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Unknown	SERVICE.					09/05/2024	227884	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Brakes	Record Check Results As Attached To This.Job					28/04/2024	217139	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Steering	TRUCK PULLS LEFT.					28/04/2024	217139	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Air Con\AIR CON	A/C freezing up					28/04/2024	217139	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Air Con\AIR CON	check air con - Blowing hot air on day shift					28/04/2024	217139	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Steering\WHEEL ALGN	needs wheel alignment					28/04/2024	217139	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Air Con\AIR CON	AIR CON NOT WORKING AS SHOULD.					28/04/2024	217139	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Tyres	STEERING SHAKE - DRIVE TYRES WEARING UNEVEN.					28/04/2024	217139	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Air Con\AIR CON	AC FREEZING UP.					28/04/2024	217139	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Comp\Truck Safe	FIT TRUCKSAFE STICKER.					28/04/2024	217139	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	VehService\AS	Carry out A Service as per job card for T909 X15	VehService/AS				28/04/2024	217139	Service	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	VehService\AS	Carry out A Service as per job card for T909 X15	VehService/AS				24/04/2024	276519	Service	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Brakes	Record Check Results As Attached To This.Job					24/04/2024	276519	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Susp\AIR BAG	L/H AIRBAG GOING FLAT.			REPLACED AND ADJUSTED LH HCV TO EQUAL PRESSURES.		18/04/2024	227101	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Myrtleford - Workshop	Susp\HCV	CHECK RIDE HEIGHT VALVE.			REPLACED RH HCV. LHS REPLACED AT WODONGA WORKSHOP.		18/04/2024	209676	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Myrtleford Workshop	P/MOVER
1070	Albury - Workshop	VehService\AS	Carry out A Service as per job card for T909 X15	VehService/AS				16/04/2024	208020	Service	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Brakes	Record Check Results As Attached To This.Job					16/04/2024	208020	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	DrCabElec\INST/GAUGE	ENGINE BRAKE LIGHT OUT ON DASH.					16/04/2024	208020	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
						RH TOP WORK LIGHT MOUNT BROKEN													
						* Inspected work light and confirmed fault * Removed and replaced as required * Connected all wiring * Aligned & tensioned as required														
1070	Albury - Workshop	Elect\WORK LIGHT	- R/H TOP WORK MOUNTS BROKEN.			* Test operations - All ok		16/04/2024	208020	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	DrCabElec\INST/GAUGE	- ENGINE BRAKE LIGHT ON DASH OUT.					16/04/2024	208020	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Elect\WORK LIGHT	TOP R/H/S LOAD LIGHT BROKEN BRACKET.					16/04/2024	208020	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Body\PANELS	BOLT REAR DECK PLATE KEEPS COMING LOOSE.					16/04/2024	208020	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
						NO FAULT.													
						ADJUST RIDE HEIGHT AS REQUIRED													
						* Adjusted as required													
1070	Albury - Workshop	Susp\HCV	check ride height adjustment			* Test operations - All ok. fault no lonaer present		16/04/2024	208020	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Brakes	Record Check Results As Attached To This.Job					09/04/2024	201086	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	DrCabElec\INST/GAUGE	ENGINE BRAKE LIGHT OUT ON DASH.					09/04/2024	201086	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Tyres	STEERING SHAKE - DRIVE TYRES WEARING UNEVEN.					09/04/2024	201086	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Elect\WORK LIGHT	- R/H TOP WORK MOUNTS BROKEN.					09/04/2024	201086	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	DrCabElec\INST/GAUGE	- ENGINE BRAKE LIGHT ON DASH OUT.					09/04/2024	201086	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Elect\WORK LIGHT	TOP R/H/S LOAD LIGHT BROKEN BRACKET.					09/04/2024	201086	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Body\PANELS	BOLT REAR DECK PLATE KEEPS COMING LOOSE.					09/04/2024	201086	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	DrivLine\DIFF OIL	replace Diff oils					09/04/2024	201086	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Unknown	SERVICE.					09/04/2024	201086	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	VehService\AS	Carry out A Service as per job card for T909 X15	VehService/AS				09/04/2024	201086	Service	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Comp\Truck Safe	FIT TRUCKSAFE STICKER.					03/04/2024	196869	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Brakes	Record Check Results As Attached To This.Job					03/04/2024	196869	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	DrCabRep\WIPERS	washer bottle leaking					03/04/2024	196869	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Air Con\AIR CON	AC NOT COLD ON HOT DAYS.					03/04/2024	196869	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Brakes\ABS	TRK ABS & TRL ABS LIGHT ON.					03/04/2024	196869	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Tyres	STEERING WHEEL SHAKE.					03/04/2024	196869	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Steering	TRUCK PULLS LEFT.					03/04/2024	196869	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Air Con\AIR CON	A/C freezing up					03/04/2024	196869	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Air Con\AIR CON	check air con - Blowing hot air on day shift					03/04/2024	196869	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Steering\WHEEL ALGN	needs wheel alignment					03/04/2024	196869	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	DrCabElec\INST/GAUGE	ENGINE BRAKE LIGHT OUT ON DASH.					03/04/2024	196869	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Air Con\AIR CON	AIR CON NOT WORKING AS SHOULD.					03/04/2024	196869	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Tyres	STEERING SHAKE - DRIVE TYRES WEARING UNEVEN.					03/04/2024	196869	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Elect\WORK LIGHT	- R/H TOP WORK MOUNTS BROKEN.					03/04/2024	196869	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	DrCabElec\INST/GAUGE	- ENGINE BRAKE LIGHT ON DASH OUT.					03/04/2024	196869	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	VehService\AS	Carry out A Service as per job card for T909 X15	VehService/AS		Needs reline rear drives		03/04/2024	196869	Service	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Tyres\TP1+2	Tyre Position 1 = 2					26/03/2024		Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Albury Workshop	P/MOVER
1070	Wodonga - Workshop	Elect\ELECT P&W	ADBLUE GAUGE. AFTER TREAT LIGHT. RH TOP WORK LIGHT MOUNT. ENGINE BRAKE LIGHT.					20/03/2024	189142	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Steering\WHEEL ALGN	needs wheel alignment					20/03/2024		Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	DrCabElec\INST/GAUGE	ENGINE BRAKE LIGHT OUT ON DASH.					20/03/2024		Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Air Con\AIR CON	AIR CON NOT WORKING AS SHOULD.					20/03/2024		Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Tyres	STEERING SHAKE - DRIVE TYRES WEARING UNEVEN.					20/03/2024		Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Comp\Truck Safe	FIT TRUCKSAFE STICKER.					20/03/2024		Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	DrCabRep\WIPERS	washer bottle leaking					20/03/2024		Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Air Con\AIR CON	AC NOT COLD ON HOT DAYS.					20/03/2024		Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Brakes\ABS	TRK ABS & TRL ABS LIGHT ON.					20/03/2024		Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Tyres	STEERING WHEEL SHAKE.					20/03/2024		Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Steering	TRUCK PULLS LEFT.					20/03/2024		Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Air Con\AIR CON	A/C freezing up					20/03/2024		Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Air Con\AIR CON	check air con - Blowing hot air on day shift					20/03/2024		Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	DrCabElec\INDICATORS	-ADBLUE GAUGE READING EMPTY.			REMOVED AND CHECKED GAUGE.

1070	Albury - Workshop	Tyres\Punct	3-10				02/03/2024		Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Albury Workshop	P/MOVER	
1070	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				02/03/2024	176217	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	CTI\CTI Elect	CTI NOT BUILDING UP PRESSURE. 78PSI - ALARM GOING OFF.				02/03/2024	176217	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	Elect\WORK LIGHT	R/H TOP WORK LIGHT BRACKET MOUNT U/S.				02/03/2024	176217	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	DrCabElect\INST/GAUGE	ENGINE BRAKE LIGHT OUT ON DASH.				02/03/2024	176217	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	VehService\AS	Carry out A Service as per job card for T909 X15	VehService\AS			02/03/2024	176217	Service	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	Unknown	TRUCK NEEDS SERVICE.				02/03/2024	176217	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	DrivLine\OIL LEAK	Oil Leak @ Front Diff				27/02/2024	171320	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	DrivLine\OIL LEAK	Oil leak front diff				27/02/2024	171320	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Albury - Workshop	Tyres\Punct	3-10				26/02/2024		Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Albury Workshop	P/MOVER	
			The following breakdown repair for Greenfreight Logging Pty Ltd, to a T659 Kenworth Truck, vin#6F550000DPA476814, registration#XW75GX & number fleet number#1070 included:															
			-															
			* Customer contacted dealership to report breakdown															
			* Customer advised that truck CTI is displaying system has no air															
			* Technician travel to breakdown location, Wodonga Depot															
			* Inspected truck to diagnose repair															
			* Checked all wiring & connections for possible cause - no failure evident															
			* Removed CTI box cover for access															
			* Test & confirmed a single solenoid not clicking															
			* Removed/replaced & retested - still not working															
			* Unable to complete repair - Part will need to be sourced from OEM															
1070	Albury - Workshop	CTI\CTI Drive	* Technician returned home				25/02/2024	171331	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Albury Workshop	P/MOVER	
1070	Wodonga - Workshop	DrivLine\DRV LN SER	movement in front diff hoke				21/02/2024	1	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	Brakes\EBS FAULTS	TRAILER ABS FAULT.				21/02/2024	1	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	Brakes\ABS	TRK ABS & TRL ABS LIGHT ON.				21/02/2024	1	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
					TRAVEL TO DEPOT													
					CALLOUT AFTER HOURS													
1070	Wodonga - Workshop	Brakes\EBS FAULTS	TRAILER ABS LIGHT ON.		REPAIR WIRING ON A TRAILER FOR EBS		21/02/2024	1	Repair	Completed	Greenfreight Loxenne Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	Tyres	STEERING WHEEL SHAKE.				21/02/2024	1	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	Steering	TRUCK PULLS LEFT.				21/02/2024	1	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	Engine\ADBLUE	AFTER TREAT LIGHT ON.		CHECKED CODES. CLEANED INJECTOR. REPLACED CONNECTOR.		21/02/2024	1	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	Engine\FAULT CODE	after treat light on				21/02/2024	1	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
			R/H side light out wire broken															
1070	Wodonga - Workshop	Elect\ELECT P&W	check work lights				21/02/2024	1	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	Brakes\ABS	ABS light on				21/02/2024	1	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	DrCabElect\INST/GAUGE	dash light out				21/02/2024	1	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	Air Con\AIR CON	cabin aircon filter , clean				21/02/2024	1	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	Steering\WHEEL ALGN	needs wheel alignment				21/02/2024	1	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	DrCabRep\DOOR LOCK	L/H side box under door need latch repairs				21/02/2024	1	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	Brakes\ABS	TRK ABS & TRL lights on				21/02/2024	1	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	VehService\B1 Svc	Service As Per Attached Checklist				15/02/2024	163001	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				15/02/2024	163001	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	Comp\Truck Safe	FIT TRUCKSAFE STICKER.				15/02/2024	163001	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	Comp\Truck Safe	FIT TRUCKSAFE.				15/02/2024	163001	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	Brakes\EBS FAULTS	TRAILER ABS FAULT.				15/02/2024	163001	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	Air Con\AIR CON	AC NOT COLD ON HOT DAYS.				15/02/2024	163001	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	Brakes\ABS	TRK ABS & TRL ABS LIGHT ON.				15/02/2024	163001	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	Brakes\EBS FAULTS	TRAILER ABS LIGHT ON.				15/02/2024	163001	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	Tyres	STEERING WHEEL SHAKE.				15/02/2024	163001	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	Steering	TRUCK PULLS LEFT.				15/02/2024	163001	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
			A/C NOT WORKING PROPERLY.															
1070	Wodonga - Workshop	Air Con\AIR CON	SEE PREVIOUS R/R				15/02/2024	163001	Fault	Completed	Greenfreight Loxenne Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
			CHECK FRONT END- PULLS TO THE LEFT.															
1070	Wodonga - Workshop	Steering	- VIBRATION/ SHAKE IN STEERING.				15/02/2024	163001	Fault	Completed	Greenfreight Loxenne Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	Air Con\AIR CON	A/C NOT GETTING COLD.				15/02/2024	163001	Fault	Completed	Greenfreight Loxenne Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	Engine\ADBLUE	AFTER TREAT LIGHT ON.				15/02/2024	163001	Repair	Completed	Greenfreight Loxenne Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	Brakes\ABS	TRAILER ABS LIGHT ON.				15/02/2024	163001	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	Elect\ELECT P&W	MARKER LIGHT OUT, O/S ABOVE TAIL LIGHT.		repaired wiring		15/02/2024	163001	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	DrivLine\DRV LN SER	movement in front diff hoke				15/02/2024	163001	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				02/02/2024	152662	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	VehService\AS	Carry out A Service as per job card for T909 X15	VehService\AS			02/02/2024	152662	Service	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Albury - Workshop	Tyres\TP1+2	STEERING SHAKE - DRIVE TYRES WEARING UNEVEN.				31/01/2024		Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Albury Workshop	P/MOVER	
1070	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				18/01/2024	142340	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	Brakes\EBS FAULTS	TRAILER ABS FAULT.				18/01/2024	142340	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	Engine\FAULT CODE	CHECK ENGINE LIGHT COMES ON.				18/01/2024	142340	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	Engine\FAULT CODE	ENGINE LIGHT ON.				18/01/2024	142340	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	DrCabRep\WIPERS	Drivers side wiper rubber need re-fitting / replace				18/01/2024	142340	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	Steering\CONSUMABLE	L/H FRONT HUB CAP MISSING.				18/01/2024	142340	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	Engine\ADBLUE	AFTER TREAT LIGHT ON.				18/01/2024	142340	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	Brakes\ABS	TRK ABS & TRL ABS LIGHT ON.				18/01/2024	142340	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	Comp\Truck Safe	FIT TRUCKSAFE.				18/01/2024	142340	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS			18/01/2024	142340	Service	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				04/01/2024	133319	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	VehService\AS	Carry out A Service as per job card for T909 X15	VehService\AS			04/01/2024	133319	Service	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	Comp\Truck Safe	FIT TRUCKSAFE STICKER.				04/01/2024	133319	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	DrCabElect\INST/GAUGE	3 X Dash lights out				30/12/2023	131854	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				28/12/2023	130319	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	VehService\AS	Carry out A Service as per job card for T909 X15	VehService\AS			28/12/2023	130319	Service	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Albury - Workshop	Tyres\TP05	Tyre Position 5				21/12/2023		Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Albury Workshop	P/MOVER	
1070	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				16/12/2023	126793	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	VehService\AS	Carry out A Service as per job card for T909 X15	VehService\AS			16/12/2023	126793	Service	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				12/12/2023	123248	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	Brakes\EBS FAULTS	TRAILER ABS FAULT.				12/12/2023	123248	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	Engine\FAULT CODE	CHECK ENGINE LIGHT COMES ON.				12/12/2023	123248	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	Air Con\AIR CON	AC NOT COLD ON HOT DAYS.				12/12/2023	123248	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	Engine\FAULT CODE	ENGINE LIGHT ON.				12/12/2023	123248	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	DrCabRep\WIPERS	Drivers side wiper rubber need re-fitting / replace				12/12/2023	123248	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	Elect\WORK LIGHT	L/H Top Work light loose		previously completed		12/12/2023	123248	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	VehService\AS	Carry out A Service as per job card for T909 X15	VehService\AS			12/12/2023	123248	Service	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
			B 1 Service,															
			Jack up steer axle check bearings and king pins.															
1070	Wodonga - Workshop	VehService\B1 Svc	Replace cabin filter.	VehService\B1 Svc			12/12/2023	123248	PreventativeMaintenance	Completed	Greenfreight Loxenne Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	Unknown	NEEDS GREASING.				12/12/2023	123248	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	Elect\WORK LIGHT	Tightened Lit Top Work Light				08/12/2023	123314	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	Engine\FAULT CODE	CHECK ENGINE LIGHT COMING ON.				06/12/2023		Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
					On site job - Bacchus March over pass heading towards Melbourne													
					Site contact Jessie 0458 904 033													
					Mechanic went to site for break downs.													
					Site was not safe													
					Moved truck to safe location to truck parking													
					Inspected for brake issue													
					Found air line pulled out of break valve													
					When front brake applied air rushes out - suppling no air for trailer brakes													
					Uncut cable ties from the dolly straddle													
					Pull lines tighter													
					Re-cable tie													
					Re-connect hose													
					Test operation of brakes - OK													
1070	Wodonga - Workshop	Brakes\AIR LEAK	Break Down - No brakes		Adjusted brakes on A & B trailer.		05/12/2023		Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				01/12/2023	115180	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	Comp\Truck Safe	FIT TRUCKSAFE STICKER.				01/12/2023	115180	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	Comp\Truck Safe	FIT TRUCKSAFE STICKER.				01/12/2023	115180	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	Comp\Truck Safe	FIT NHVAS STICKER.				01/12/2023	115180	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	VehService\AS	Carry out A Service as per job card for T909 X15	VehService\AS			01/12/2023	115180	Service	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				28/11/2023	113344	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
					BROKEN TEST PORT ON A.													
1070	Wodonga - Workshop	Brakes\EBS FAULTS	TRAILER ABS FAULT.		COLAS ALIXS ON B		28/11/2023	113344	Fault	Completed	Greenfreight Loxenne Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	Engine\FAULT CODE	CHECK ENGINE LIGHT WAS OFF & ON ALL NIGHT. HASN'T BEEN ON SINCE LEAVING ROSEWOOD.				28/11/2023	113344	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	CTI\CTI Elect	TYRE PRESSURE TAKING AGES TO BUILD UP AND WON'T DUMP AIR.				28/11/2023	113344	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	Chassis\FUEL TANK	L/H Fuel Cap Needs A Rubber Ring Under It				28/11/2023	113344	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS			28/11/2023	113344	Service	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	Unknown	SERVICE				28/11/2023	113344	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Albury - Workshop	Tyres\TP03	fit run out				28/11/2023	110563	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	BEAUREPAIRES - 4	P/MOVER	
1070	Albury - Workshop	Tyres\TP7+8	Tyre Position 7 + 8				15/11/2023		Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Albury Workshop	P/MOVER	
1070	Albury - Workshop	Tyres\TP9+10	Tyre Position 9 + 10				15/11/2023		Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Albury Workshop	P/MOVER	
1070	Albury - Workshop	Tyres\TP1+2	Tyre Position 1 + 2				15/11/2023		Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Albury Workshop	P/MOVER	
1070	Albury - Workshop	Tyres\TP3+4	Tyre Position 3 + 4				15/11/2023		Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Albury Workshop	P/MOVER	
1070	Albury - Workshop	Tyres\TP5+6	Tyre Position 5 + 6				15/11/2023		Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Albury Workshop	P/MOVER	
1070	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				08/11/2023	101574	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	VehService\CS	Service As Per Attached Checklist	VehService\CS			08/11/2023	101574	Service	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	Unknown					08/11/2023	101574	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				03/11/2023	97116	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	Comp\Truck Safe	FIT TRUCKSAFE STICKER.				03/11/2023	97116	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	Comp\Truck Safe	FIT TRUCKSAFE STICKER.				03/11/2023	97116	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	Comp\Truck Safe	FIT NHVAS STICKER.				03/11/2023	97116	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	DrCabRep\HOUSEKEEP	FIT FIRST AID KIT.				03/11/2023	97116	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS			03/11/2023	97116	Service	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				27/10/2023	90878	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS			27/10/2023	90878	Service	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	Chassis\STRAPS	REPLACE CAB RACK BUSHES.				21/10/2023	86189	Fault	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	VehService\B1 Svc	Service As Per Attached Checklist				21/10/2023	86189	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				21/10/2023	86189	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	Comp\Truck Safe	FIT TRUCKSAFE STICKER.				21/10/2023	86189	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt Gambier	XW75GX	Wodonga Workshop	P/MOVER	
1070	Wodonga - Workshop	Comp\Truck Safe	FIT TRUCKSAFE STICKER.				21/10/2023	86189	Repair	Completed	Greenfreight Logging Vic	KWX1SLOG	Mt Gambier	Mt G

1070	Wodonga - Workshop	Elect\WORK LIGHT	REPLACE LOAD LIGHT BRACKET R/H/S BOTTOM (RACK)		previously done	21/09/2023	589929	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Unknown	SERVICE.			21/09/2023	589929	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	DrCab\Rep\HOUSEKEEP	no first aid kit			21/09/2023	589929	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Engine\FAULT CODE	after treat light on			21/09/2023	589929	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS		21/09/2023	589929	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Elect\WORK LIGHT	Replaced Broken Worklight Bracket- RH Bottom Cab Rack			19/09/2023	59193	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Brakes	Record Check Results As Attached To This.Job			13/09/2023	52196	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
			Service As Per Attached Checklist (TCTC)													
1070	Albury - Workshop	VehService\BS	Purchase Order Number: TO80969	VehService\BS		13/09/2023	52196	Service	Completed	Greenfreight Leeming Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonas Workshop	P/MOVER
1070	Albury - Workshop	Brakes	Record Check Results As Attached To This.Job			08/09/2023	48380	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Comp\Truck Safe	FIT TRUCKSAFE STICKER.			08/09/2023	48380	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Comp\Truck Safe	FIT TRUCKSAFE STICKER.			08/09/2023	48380	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	CTI\CTI Elect	CTI WON'T PUMP UP/ DOWN WHEN MOVING. GOES TO 0 ON DISPLAY. (VALVE COMMS LOST) APPEARING ON SCREEN FROM TIME TO TIME.			08/09/2023	48380	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Comp\Truck Safe	FIT NH VAS STICKER.			08/09/2023	48380	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	VehService\AS	Carry out A Service as per job card for T909 X15	VehService\AS		08/09/2023	48380	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Brakes	Record Check Results As Attached To This.Job			01/09/2023	42237	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Comp\Truck Safe	FIT TRUCKSAFE STICKER.			01/09/2023	42237	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	CTI\CTI Elect	CTI WON'T PUMP UP/ DOWN WHEN MOVING. GOES TO 0 ON DISPLAY. (VALVE COMMS LOST) APPEARING ON SCREEN FROM TIME TO TIME.			01/09/2023	42237	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	VehService\AS	Carry out A Service as per job card for T909 X15	VehService\AS		01/09/2023	42237	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Brakes	Record Check Results As Attached To This.Job			26/08/2023	37667	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	VehService\AS	Carry out A Service as per job card for T909 X15	VehService\AS		26/08/2023	37667	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Comp\Truck Safe	FIT TRUCKSAFE STICKER.			26/08/2023	37667	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Brakes\AIR LEAK	REPAIRED BOOSTER HOSE MIDDLE AXLE. TESTED. FOLDED. PARKED.			25/08/2023	36218	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Brakes	Record Check Results As Attached To This.Job			18/08/2023	33610	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	VehService\AS	Carry out A Service as per job card for T909 X15	VehService\AS		18/08/2023	33610	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Comp\Truck Safe	FIT TRUCKSAFE STICKER.			18/08/2023	33610	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Brakes	Record Check Results As Attached To This.Job			18/08/2023	30550	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	VehService\AS	Carry out A Service as per job card for T909 X15	VehService\AS		18/08/2023	30550	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Brakes	Record Check Results As Attached To This.Job			04/08/2023	17084	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	VehService\AS	Carry out A Service as per job card for T909 X15	VehService\AS		04/08/2023	17084	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
			CTI WON'T PUMP UP/ DOWN WHEN MOVING. GOES TO 0 ON DISPLAY. (VALVE COMMS LOST) APPEARING ON SCREEN FROM TIME TO TIME.													
1070	Albury - Workshop	CTI\CTI Elect	NEEDS AUTO ELECT			28/07/2023	11359	Repair	Completed	Greenfreight Leeming Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonas Workshop	P/MOVER
1070	Albury - Workshop	Steering\OIL LEAK	POWER STEERING OIL LEAK AROUND BOX.			28/07/2023	11359	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Albury - Workshop	Brakes\ABS FAULTS	TRAILER ABS LIGHT ON.		Fault in Trailer.	28/07/2023	11359	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
			Carry Out A Service (TCTC)													
1070	Albury - Workshop	VehService\AS	Purchase Order Number: TO79902	VehService\AS		28/07/2023	11359	Service	Completed	Greenfreight Leeming Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonas Workshop	P/MOVER
1070	Albury - Workshop	Tyres\TP07	Tyre Position 7			26/07/2023		Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Albury Workshop	P/MOVER
1070	Wodonga - Workshop	Brakes	ABS LEAD WON'T CONNECT TO TRAILER.		CONNECTED TO "A" TRAILER(T390) NO POWER GETTING TO TRAILER- CHECKED FUSES IN CAB-OK. ISSUE IN TRAILER.	25/07/2023	8881	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Wodonga - Workshop	Brakes\ABS	ABS LEAD WON'T CONNECT TO TRAILER.			25/07/2023	8881	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
					CUSTOMER REPORTS THAT FRONT DIFF IS GETTING HOT ENOUGH TO BLISTER PAINT AND UNABLE TO TOUCH.											
					VIBRATION IN DRIVELINE, GAUGE IS READING MAX BOOST. REPAIR AS REQUIRED											
					-											
					* Inspect to diagnose											
					* Check & confirmed end float											
					* Located chunk of retread missing on LHR outer drive tyre - causing inbalance vibration											
					* Customer to monitor & advise											
1070	Albury - Workshop	DrivLine\DRV LN SER	FRONT DIFF HOT VIBRATION, CLUNKING NOISE.		LABOUR COVERED UNDER TCTC SERVICE GOODWILL POLICY	20/07/2023	7205	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Albury Workshop	P/MOVER
					The following 1st service inspection for Greenfreight Logging Pty Ltd, to a T659 Kenworth Truck, Chassis#6F5000000PA476814											
					and registration #KW75GX included:											
					-											
					* Removed/replaced engine filter & oil, specification used in parts section below.											
					* Check all engine operation & components											
					* Removed/replaced transmission oil filter											
					* Check all hydraulic lines fitting & level lubricant levels to specification											
					* Removed/replaced power steering filter & gasket											
					* Removed/replaced differential oil, specification used in parts section below.											
					* Removed/replaced fuel filter											
					* Check cooling system & pressure test											
					* Check all belts, idler pulleys, fan, shrouds & adjust to specification											
					* Check all electrical routing, wiring looms, switches, sensors & components											
					* Check all wheel equipment & steering components											
					* Check all braking & adjust to specification											
					* Check clutching & adjust to specification											
					* Check all suspension components											
					* Check all internal cabin operation, components & adjust to specification											
					* Check all external cabin components & adjust to specification											
					* Check windscreen washers, wipers, refill & test operation											
					* Lubricate, adjust relevant components as required											
					* Re torque all fitting & fixtures											
			***COMPLIMENTARY NO CUSTOMER LABOUR CHARGE KENWORTH TRUCK 1st SERVICE POLICY ***		* Wash vehicle complete											
1070	Albury - Workshop	VehService	***CUSTOMER RESPONSIBLE FOR ALL PARTS REQUIRED FOR 1st SERVICE***		* Road test. confirm & quality check	20/07/2023	7205	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Albury Workshop	P/MOVER
			REPLACE STEER MUDFLAPS WITH NON-ANTISPRAY VERSION													
			* Removed existing guards, mudflaps & components													
			* Source replacement parts													
			* Drilled positional mounting points for mudflaps													
			* Installed replacement mudflaps													
			* Align all components & tension to specification													
			* Test, confirm & quality check repair													
1070	Albury - Workshop	Body\MUDGUARDS	COMPLIMENTARY NO LABOUR CHARGE			20/07/2023	7205	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Albury Workshop	P/MOVER
1070	Albury - Workshop	DrCab\Elect	SUPPLIED & INSTALLED AIR BLOWER BEHIND DRIVERS SEAT			20/07/2023	7205	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Albury Workshop	P/MOVER
1070	Myrtleford - Workshop	DrCab\Elect\SCALES	WT SCALE NOT READING ON ALL 3 CHANNELS.			14/07/2023		Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Myrtleford Workshop	P/MOVER
					CHECK TYRE PRESSURE DROPPING WHILE DRIVING											
					CALLOUT AFTER HOURS											
					TRAVEL TO DEPOT											
					CHECK OVER WHOLE CDI - CHECK POWER AND EARTH AT CDI UNIT OK											
					CHECK CONTINUITY FROM CDI UNIT TO CDI BOX- LOCATE OPEN CIRCUIT											
					TRACE WIRING CIRCUIT AND LOCATE FAULTY WIRING											
					REPAIR AS REQUIRED											
1070	Albury - Workshop	CTI\CTI Elect	CTI WON'T PUMP UP/ DOWN WHEN MOVING. GOES TO 0 ON DISPLAY. (VALVE COMMS LOST) APPEARING ON SCREEN FROM TIME TO TIME.		CHECK OPERATION OK	14/07/2023		Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Albury Workshop	P/MOVER
1070	Albury - Workshop	Tyres\TP3+4	Tyre Position 3 + 4			08/07/2023		Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Albury Workshop	P/MOVER
1070	Albury - Workshop	Tyres\TP5+6	Tyre Position 5 + 6			08/07/2023		Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Albury Workshop	P/MOVER
1070	Albury - Workshop	Tyres\TP7+8	Tyre Position 7 + 8			08/07/2023		Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Albury Workshop	P/MOVER
1070	Albury - Workshop	Tyres\TP9+10	Tyre Position 9 + 10			08/07/2023		Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Albury Workshop	P/MOVER
1070	Wodonga - Workshop	Workshop\MOVE ASSET	UNHOOKED T547/548.			07/07/2023		Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER
1070	Myrtleford - Workshop	DrCab\Rep\SCALES	recalibrate scales			04/07/2023	1550	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Myrtleford Workshop	P/MOVER
1070	Wodonga - Workshop	Insp\Truck Pre	Truck Pre-delivery as per check list			28/06/2023	276235	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Mt Gambier	Mt Gambier	KW75GX	Wodonga Workshop	P/MOVER