EquipmentName	Workshop	CodeAndSubCode	Description	Schedule	CompletionComments	DateDone	DistanceDone	Worktype	Workstate	EquipmentOwner	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
1067	Colac - Colac	DrCabElect\ELECT P&W	DIAGNOSE & REPAIR CIGARETTE LIGHTER FAULT.			06/10/2026	836170	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	JF MECHANICALS - 3	P/MOVER
1067	Colac - Colac	Engine\FAULT CODE	CHECK ENGINE FAULT			16/09/2026	825146	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	JF MECHANICALS - 3	P/MOVER
1067	Colac - Colac	Cooling\COOL LEAKS	REPLACED DRAW DOWN PIPE P/CLAMPS, REPLACED HOT PIPE P/CLAMPS, TIGHTEN LOWER BRADIATOR HOSE & HEATER HOSES. TOP UP COOLANT			06/09/2026	821767	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	JF MECHANICALS - 3	P/MOVER
1067	Colac - Colac	Tyres\TPS+2	Tyres\TPS+2			04/09/2026	821403	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Colac Workshop	P/MOVER
1067	Colac - Colac	Engine\ADBLUE	AD BLUE FAULT, CLEAN DOSER & PUMP			04/09/2026	820830	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	JF MECHANICALS - 3	P/MOVER
1067	Colac - Colac	VehService\AS	VehService\AS A Service	VehService\AS		04/09/2026	821767	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	JF MECHANICALS - 3	P/MOVER
1067	Colac - Colac	Engine\ADBLUE	AD BLUE FAULT			02/09/2026	820470	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	JF MECHANICALS - 3	P/MOVER
1067	Colac - Colac	Susp\WHEEL ALIGN	COMPLETE WHEEL ALIGNMENT			25/08/2026	816660	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	GEELONG TRUCK AND STEERING	P/MOVER
1067	Colac - Colac	VehService\AS	VehService\AS A Service	VehService\AS	KLM AT TIME OF SERVICE 814748	13/08/2026	816660	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Colac Workshop	P/MOVER
1067	Albury - Workshop	Tyres\TPS+10	Tyres\TPS+10			25/07/2026	808543	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	BORDER BANDAG PTY LTD - 4	P/MOVER
1067	Albury - Workshop	Tyres\TPS1+12	Tyres\TPS1+12			25/07/2026	808543	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	BORDER BANDAG PTY LTD - 4	P/MOVER
1067	Albury - Workshop	VehService\CS	VehService\CS C Service Chassis\FIFTH WHEE	VehService\CS		24/07/2026	806412	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER
1067	Albury - Workshop	Chassis\FIFTH WHEE			BALIRACE DRILLED - TCTC	24/07/2026	806412	Repair	Completed	Greenfreight Loxeine Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER
1067	Albury - Workshop	Brakes\ABS	trailer abs light on			24/07/2026	806412	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER
1067	Albury - Workshop	Brakes\ABS	trailer abs fault			24/07/2026	806412	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER
1067	Albury - Workshop	VehService\AS	VehService\AS A Service	VehService\AS		17/07/2026	806233	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Albury - Workshop	Steering\KING PIN	KING PINS NOTED AS HAVING MOVEMENT. MEASURE TO CONFIRM OUT OF SPEC >.015" LATERAL MOVEMENT.			17/07/2026	806233	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
					MTDATA TRACKING REPAIR Travel to greenfreight wodonga. Unit on truck not tracking. Opened IAP box to access unit under seat. Unit had no power led lit up on it. Checked power and ignition to unit. Has power but not powering up. Opened unit to perform hard reset. Did not fix issue. Removed and replaced sd card, put unit back together and tested. Connected profile on tablet. Icons appeared on tablet after waiting for a few moments. Checked installer companion, can see unit tracking. Called mt data and confirmed unit tracking. Also confirmed DVR and engine data working.									
1067	Albury - Workshop	DrCabElect\GPS	DrCabElect\GPS		Closed so IAP box. Returned to workshop.	01/07/2026	792103	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER
1067	Albury - Workshop	DriviJne\CTI Drive	CDI stop's pumping up on H/Way.		completed by SS	30/06/2026	792103	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Albury - Workshop	Engine\ADBLUE	after treat light on not using adblue		completed SS	30/06/2026	792103	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Albury - Workshop	Brakes\RED VALVE	not working park door alarm		completed SS AR JS	30/06/2026	792103	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Albury - Workshop	DrCabElect\DOOR ALARM	park door alarm not working		completed by SS AR JS	30/06/2026	792103	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Albury - Workshop	DrCabElect\ELECT P&W	cab gaurd lights have a short		completed by MB JS	30/06/2026	792103	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Albury - Workshop	VehService\AS	VehService\AS A Service VehService\B1 Svc B 1 Service, Jack up steer axle check bearings and king pins.	VehService\AS	completed by SMc JS	27/06/2026	790680	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Albury - Workshop	VehService\B1 Svc	Reolace cabin filter.	VehService\B1 Svc	comoleted by JS SS AR	20/06/2026	786030	PreventativeMaintenance	Completed	Greenfreight Loxeine Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonwa Workshoo	P/MOVER
1067	Albury - Workshop	Elect\BATTERY	replaced 4 batteries		completed by KR	02/06/2026	776396	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER
1067	Albury - Workshop	Elect\BATTERY	Jump start truck. Body\BREAKDOWN		completed by JS	01/06/2026	774176	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER
1067	Albury - Workshop	Body\BREAKDOWN	T134232		AAA TOWING SHELLEY - TCTC	27/05/2026	777447	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	TWIN CITY TRUCK CENTRE - 4	P/MOVER
1067	Albury - Workshop	DriviJne\DIFF REPMN	FRONT DIFF FAILURE- TCTC REPAIRING			27/05/2026	777447	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	TWIN CITY TRUCK CENTRE - 4	P/MOVER
1067	Albury - Workshop	VehService\AS	VehService\AS A Service	VehService\AS	completed by JS TP AR	25/05/2026	771030	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER
1067	Albury - Workshop	Tyres\TPS+2	Tyres\TPS+2			11/05/2026	769935	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	BORDER BANDAG PTY LTD - 4	P/MOVER
1067	Albury - Workshop	VehService\BS	VehService\BS B Service	VehService\BS		08/05/2026	766478	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER
1067	Albury - Workshop	DriviJne\WHEEL SEAL	3 drive hub seals leaking		completed by SMc JS	08/05/2026	766478	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER
1067	Albury - Workshop	DriviJne\SUSPENSION	LHF slight cracking		completed by SMc JS	08/05/2026	766478	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER
1067	Albury - Workshop	VehService\AS	VehService\AS A Service	VehService\AS	completed by SMc JS	08/05/2026	766478	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER
1067	Albury - Workshop	Brakes\BRK RELINE	rear drive brakes need replacing		completed by SMc JS REPLACED BOOSTER	08/05/2026	766478	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER
1067	Albury - Workshop	Brakes\BOOSTER	left rear booster needs repalcing leaking		T.PEACHEY J.STRONG	03/05/2026	762058	Fault	Completed	Greenfreight Loxeine Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER
1067	Albury - Workshop	Brakes\BRAKE ADJ	Brake adjustment needed,[truck & trailer's are rolling when on incline]		completed by TP	30/04/2026	760365	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER
1067	Albury - Workshop	DriviJne\GEARBOX	Squeal under Cab, Thrust or Gearbox.		completed SMc	30/04/2026	759867	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Albury - Workshop	DriviJne\OIL LEAK	Front Diff is still leaking oil.		completed SMc	30/04/2026	759867	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Albury - Workshop	Engine\ELECT P&W	After treat fault/light is ON.		completed SMc	30/04/2026	759867	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Albury - Workshop	Elect\WORK LIGHT	CAB GUARD LIGHTS SHORTING		checked ok SMc	30/04/2026	759867	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Albury - Workshop	Body\DAMAGE	Replace damaged guard's.		completed SMc	30/04/2026	759867	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Albury - Workshop	Body\ELECT P&W	Cab rack light's have a short and blow's fuse.		checked ok	30/04/2026	759867	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Albury - Workshop	DriviJne	Front drive hub seals blown		completed SMc	30/04/2026	759867	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Albury - Workshop	Body\MUDGUARDS	Tighten both front guard's.		completed SMc	30/04/2026	759867	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Albury - Workshop	VehService\AS	VehService\AS A Service	VehService\AS	completed SMC,TP,JS	30/04/2026	759867	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Albury - Workshop	Elect\ELECT P&W	No cab guard work light's.		completed SMc	30/04/2026	759867	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Albury - Workshop	Body\MUDGUARDS	R/H front guard to be replaced.		roadworthy SMc	30/04/2026	759867	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Albury - Workshop	DriviJne\DIFF OIL	Front Diff leaking Oil, after repair was done at TCTC.		checked ok SMc	30/04/2026	759867	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Albury - Workshop	Body\MUDGUARDS	Guard's are Damaged.		clean diff breathers	30/04/2026	759867	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Albury - Workshop	Elect\ELECT P&W	Cab guard light's Not working.		completed SMc	30/04/2026	759867	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Albury - Workshop	Body\MUDGUARDS	Repair/Replace Bent Broken Guard's.		completed by SMc	30/04/2026	759867	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Albury - Workshop	DrCabElect\INST/GAUGE	After treat light on dash		Completed SMc	30/04/2026	759867	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Albury - Workshop	Body\ELECT P&W	No cab guard light's.		no fuse KR	30/04/2026	759867	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Albury - Workshop	DrCabRep\SEAT	REPLACE DRIVER'S SEAT		completed EC	30/04/2026	743998	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Albury - Workshop	Steering\PWR STEER	Steering box need's adjusting		within spec SMc	30/04/2026	759867	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Albury - Workshop	Engine\FAULT CODE	Check Engine Light Flickers On Start Up		completed SMc	30/04/2026	759867	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Albury - Workshop	Cooling\ENG FAN	Replace/Repair Horton Fan.		checked ok SMc	30/04/2026	759867	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Albury - Workshop	DrCabRep\SEAT	Driver's Seat may need to be replaced.		replaced arm rest EC	30/04/2026	743998	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Albury - Workshop	DrCabElect\INST/GAUGE	After treat light is ON.		completed SMc REPLACED ARM REST.	30/04/2026	759867	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Albury - Workshop	DrCabRep\SEAT	Seat base is loose and need's a left hand arm rest as well.		ETHAN C	30/04/2026	759867	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Albury - Workshop	Steering\DAMAGE	steering wheel cable need fixing		checked ok SMc CALL OUT TO BENALLA	30/04/2026	759867	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Albury - Workshop	Tyres\TPS+6	Tyres\TPS+6		RUN FLAT	28/04/2026	759605	Repair	Completed	Greenfreight Loxeine Vic	KWX15LOG	Colac	GTK	XW79CD	BORDER BANDAG PTY LTD - 4	P/MOVER
1067	Albury - Workshop	Tyres\TPS+8	Tyres\TPS+8		CALL OUT TO BENALLA	28/04/2026	759605	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	BORDER BANDAG PTY LTD - 4	P/MOVER
1067	Albury - Workshop	Steering\DAMAGE	steering column not locking in temp fix completed		SMc	16/04/2026	751128	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER
1067	Albury - Workshop	DrCabRep\Steerbox	DrCabRep\Steerbox VehService\B1 Svc B 1 Service, Jack up steer axle check bearings and king pins.		completed by MN	15/04/2026	750187	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER
1067	Albury - Workshop	VehService\B1 Svc	Reolace cabin filter.	VehService\B1 Svc	no oaaer work provided	13/04/2026	749531	PreventativeMaintenance	Completed	Greenfreight Loxeine Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonwa Workshoo	P/MOVER
1067	Albury - Workshop	DrCabRep\SEAT	replace drivers seat Oil leak front diff. (TCTC Warranty Repair)		repaired and fitted armrest EC	02/04/2026	743998	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Albury - Workshop	DriviJne\OIL LEAK	743.414 Kms			31/03/2026	743435	Fault	Completed	Greenfreight Loxeine Vic	KWX15LOG	Colac	GTK	XW79CD	TWIN CITY TRUCK CENTRE - 4	P/MOVER
1067	Albury - Workshop	VServLab	SERVICE			16/03/2026	732831	Fault	Completed	Greenfreight Loxeine Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER
1067	Albury - Workshop	Body\MUDGUARDS	R/H Front Guard Replace			16/03/2026	732831	Fault	Completed	Greenfreight Loxeine Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER
1067	Albury - Workshop	Body\MUDGUARDS	left front drive gaurd replace bracket and tighten hanger			16/03/2026	732831	Fault	Completed	Greenfreight Loxeine Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER
1067	Albury - Workshop	VehService\AS	VehService\AS A Service	VehService\AS		16/03/2026	732831	Service	Completed	Greenfreight Loxeine Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER
1067	Albury - Workshop	Brakes\BRAKE ADJ	Check/Adjust Brake's. WARRANTY/ REWORK TWIN CITY TRUCK CENTRE- VehService\B1 Svc B 1 Service, Jack up steer axle check bearings and king pins.			16/03/2026	733256	Fault	Completed	Greenfreight Loxeine Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER
1067	Albury - Workshop	DriviJne\OIL LEAK	FRONT DIFF LEARING FROM BOTTOM PLATE			12/03/2026	732831	Repair	Completed	Greenfreight Loxeine Vic	KWX15LOG	Colac	GTK	XW79CD	TWIN CITY TRUCK CENTRE - 4	P/MOVER
1067	Albury - Workshop	Tyres\TPS+10	Tyres\TPS+10			05/03/2026	732607	Repair	Completed	Greenfreight Loxeine Vic	KWX15LOG	Colac	GTK	XW79CD	BORDER BANDAG PTY LTD - 4	P/MOVER
1067	Albury - Workshop	Tyres\TPS1+12	Tyres\TPS1+12			05/03/2026	732607	Repair	Completed	Greenfreight Loxeine Vic	KWX15LOG	Colac	GTK	XW79CD	BORDER BANDAG PTY LTD - 4	P/MOVER
1067	Albury - Workshop	DriviJne\OIL LEAK	oil leak at bottom of front diff		TCTC	28/02/2026	724128	Fault	Completed	Greenfreight Loxeine Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Albury - Workshop	VehService\BS	VehService\BS B Service	VehService\BS	serviced at 724,128	28/02/2026	724128	Service	Completed	Greenfreight Loxeine Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Albury - Workshop	VehService\AS	service			28/02/2026	724128	Fault	Completed	Greenfreight Loxeine Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Albury - Workshop	VehService\AS	VehService\AS A Service	VehService\AS	serviced 724,128	28/02/2026	724128	Service	Completed	Greenfreight Loxeine Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Albury - Workshop	DriviJne\OIL LEAK	check front diff lock oil leak			28/02/2026	724128	Fault	Completed	Greenfreight Loxeine Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Albury - Workshop	Tyres\TPS+2	Tyres\TPS+2 A Service		CALL OUT AFTER HOURS	24/02/2026	721402	Repair	Completed	Greenfreight Loxeine Vic	KWX15LOG	Colac	GTK	XW79CD	BORDER BANDAG PTY LTD - 4	P/MOVER
1067	Albury - Workshop	VehService\AS	Serviced @ 718.240 Kms	VehService\AS		21/02/2026	718320	Service	Completed	Greenfreight Loxeine Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonwa Workshop	P/MOVER
1067	Albury - Workshop	Engine\FAULT CODE	After Treat light has been on since start up on sunday. and no Ad Blu has been used.			10/02/2026	708431	Fault	Completed	Greenfreight Loxeine Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER
1067	Albury - Workshop	Cooling\ENG FAN	REPLACE HORTON FAN ASSEMBLY VehService\B1 Svc B 1 Service, Jack up steer axle check bearings and king pins.			07/02/2026	708893	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Albury - Workshop	VehService\B1 Svc	Reolace cabin filter.	VehService\B1 Svc		07/02/2026	706893	PreventativeMaintenance	Completed	Greenfreight Loxeine Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonwa Workshoo	P/MOVER
1067	Albury - Workshop	Insp\ANN INSP	Insp\ANN INSP Annual Inspection As Per Checklist	Insp\ANN INSP		02/02/2026	703215	PreventativeMaintenance	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER
1067	Albury - Workshop	DriviJne\OIL LEAK	Front Diff Pinion Seal	ok		02/02/2026	703215	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER
1067	Albury - Workshop	DriviJne	Front input shaft seal need replacing	ok		02/02/2026	703215	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER
1067	Albury - Workshop	DriviJne\DIFF REPMN	replace pinion seal front diff and adjust bearing.	ok		02/02/2026	703215	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER
1067	Albury - Workshop	VehService\AS	VehService\AS A Service	VehService\AS		02/02/2026	703215	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER
1067	Albury - Workshop	Engine\COMPRESSOR	Compressor is rattling.	ok		02/02/2026	703215	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER
1067	Albury - Workshop	Susp\Torque Rod	LHR trackrod bushs need replacing next service	ok		02/02/2026	703215	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER
1067	Albury - Workshop	Steering\STEER UNI	Middle steering uni worn	ok		02/02/2026	703215	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER
1067	Albury - Workshop	Insp\ANN INSP	Insp\ANN INSP	Insp\ANN INSP		02/02/2026	703215	PreventativeMaintenance	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER
1067	Albury - Workshop	Tyres\RUN OUT	Tyres\RUN OUT POS 9		BIG BOLT IN TYRE UNABLE TO REPAIR	28/01/2026	704432	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	BORDER BANDAG PTY LTD - 4	P/MOVER
1067	Albury - Workshop	Engine\ADBLUE	fit sensor in adblue			21/01/2026	694737	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER
1067	Albury - Workshop	VehService\AS	VehService\AS A Service	VehService\AS		23/01/2026	693682	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Albury - Workshop	Engine\ADBLUE	Nox sensor replace		replaced	22/01/2026	693388	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER
1067	Albury - Workshop	Elect\DRV LIGHT	L/H Driving light Not working.			17/01/2026	687712	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER
1067	Albury - Workshop	DrCabElect\INST/GAUGE	Cruise light in dash...Maybe blown globe?			17/01/2026	687712	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER
1067	Albury - Workshop	Engine\FUEL TANK	FUEL/WATER SENSOR			17/01/2026	687712	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER
1067	Albury - Workshop	VehService\BS	VehService\BS B Service	VehService\BS		17/01/2026	687712	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER
1067	Albury - Workshop	DrCabElect\INST/GAUGE	Engine Brake light Not working on dash.			17/01/2026	687712	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER
1067	Albury - Workshop	Engine\TURBO	Turbo Boost dropped to 180, won't Pull.			17/01/2026	687712	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER
1067	Albury - Workshop	Engine\FAULT CODE	After Treat Fault.			17/01/2026	687712	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER
1067	Albury - Workshop	DrCabElect\INST/GAUGE	After treat light is coming on when brake is applied.			17/01/2026	687712	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER
1067	Albury - Workshop	Cooling\RADIATOR	Repair/Replace Radiator [Leaking Core]		REMOVED, REPAIRED AND REFITTED RADIATOR. S.McCABE	09/01/2026	679517	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Albury - Workshop	Tyres\TPS+8	Tyres\TPS+8		DIAGNOSED AND REPAIRED LOOSE PIPE	20/12/2025	677824	Repair	Completed	Greenfreight Loxeine Vic	KWX15LOG	Colac	GTK	XW79CD	BORDER BANDAG PTY LTD - 4	P/MOVER
1067	Albury - Workshop	Tyres\TPS+6	Tyres\TPS+6		REPLACING WITH PARTS FROM 1071	20/12/2025	677824	Repair	Completed	Greenfreight Loxeine Vic	KWX15LOG	Colac	GTK	XW79CD	BORDER BANDAG PTY LTD - 4	P/MOVER
1067	Albury - Workshop	Engine\COMPRESSOR	LOUD NOISE FROM COMPRESSOR		SENT TO TCTC (SUSPECTED COMPRESSOR FAILURE-WARRANTY) INTERCOOLER HAVING SMALL LEAK REPAIRED AT NATRAD.	20/12/2025	674314	Repair	Completed	Greenfreight Loxeine Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonwa Workshoo	P/MOVER
1067	Albury - Workshop	Cooling\RADIATOR	RADIATOR AND INTERCOOLER HAVE MAJOR LEAKS.		S.McCABE	20/12/2025	674314	Repair	Completed	Greenfreight Loxeine Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonwa Workshoo	P/MOVER
1067	Albury - Workshop	Engine\TURBO	Check for Boost leak's.			18/12/2025	686381	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER
1067	Albury - Workshop	DrCabRep\ELECT P&W	After Treat Lights comes on & off			18/12/2025	674314	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER
1067	Albury - Workshop	Engine\FAULT CODE	After treat light comes On when going down hill's with Jake Brake on.			18/12/2025	674314	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER

						WHILST CARRYING OUT REPAIRS, FOUND DIFF OIL REQUIRED REPLACING - REPLACE BOTH FRONT & REAR DIFF OIL WITH DYNADRIVE SEMI-SYNTHETIC OIL * Drain differential oil * Removed/replaced differential oil filter * Removed/cleaned & replaced differential screens * Installed differential lubricant levels to specification											
1067	Albury - Workshop	DriveLine\DIFF OIL	DriveLine\DIFF OIL CHANGE	DriveLine\DIFF OIL	* Re torque all fittings & fetures	18/12/2025	673898	PreventativeMaintenance	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	TWIN CITY TRUCK CENTRE - 4 - OLD	P/MOVER		
1067	Albury - Workshop	Tyres\TP1+2	Tyres\TP1+2 CALL OUT		TYRES HAD ROCKS IN THEM	17/12/2025	674314	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	BORDER BANDAG PTY LTD - 4	P/MOVER		
1067	Albury - Workshop	VServLab	SERVICE			11/12/2025	672279	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	Engine\ADBLUE	After Treat Light On		Connected computer to truck carried out doser pump test/s, flushed air side of doser pump, flushed wet side of doser pump, carried out flow rate test on doser pump, removed	11/12/2025	672279	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	Engine\ADBLUE	ADJUST AIR COMPRESSOR. GAUGES ONLY REACH 750. SITS ON 700.		Adjusted governor valve to correct operating pressures.	11/12/2025	672279	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	Engine\ADBLUE	ADJUST AIR COMPRESSOR. GAUGES ONLY REACH 750. SITS ON 700.		Adjusted governor valve to correct operating pressures.	11/12/2025	672279	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	Engine\ADBLUE	AFTERTREAT LIGHT BEEN ON ALL WEEK. DUE TO DEBATE. A Service		Connected computer to truck carried out doser ouma test/s. flushed air side of doser ouma. flushed wet side of doser ouma. carried out flow rate test on doser ouma. removes	11/12/2025	672279	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	VehService\AS	Serviced @ 672.279 Kims	VehService\AS		11/12/2025	672279	Service	Completed	Greenfreight Loxeine Vic	KWX15LOG	Colac	GTK	XW79CD	Woodonwa Workshop	P/MOVER		
1067	Albury - Workshop	Engine\FAULT CODE	CLEAR ENGINE & AFTERTREAT CODES.		Connected computer to truck carried out doser ouma test/s. flushed air side of doser ouma. flushed wet side of doser ouma. carried out flow rate test on doser ouma. removes	11/12/2025	672279	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	Engine\AIR LEAK	air pressure only reaching 750 , so Comp running continually. VehService\B1 Svc B 1 Service, Jack up steer axle check bearings and king pins.		Adjusted governor valve to correct operating pressures.	11/12/2025	672279	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	VehService\B1 Svc	Reelace cabin filter.	VehService\B1 Svc		07/12/2025	668500	PreventativeMaintenance	Completed	Greenfreight Loxeine Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER		
1067	Albury - Workshop	VehService\AS	VehService\AS A Service	VehService\AS		07/12/2025	668500	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER		
1067	Albury - Workshop	Engine\ADBLUE	Has Not used Ad-Blu since Monday. ADBLUE LIGHT ON. A Service			07/12/2025	668500	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER		
1067	Albury - Workshop	VehService\AS	Serviced @ 663,000 Kims	VehService\AS		29/11/2025	663019	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Woodonga Workshop	P/MOVER		
					Mitchell Newley 1.5hrs													
1067	Albury - Workshop	Engine\ADBLUE	After Treat Light On Dash A Service			29/11/2025	663019	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Woodonga Workshop	P/MOVER		
1067	Albury - Workshop	VehService\AS	Serviced @ 655.705 Kims	VehService\AS		22/11/2025	655706	Service	Completed	Greenfreight Loxeine Vic	KWX15LOG	Colac	GTK	XW79CD	Woodonwa Workshop	P/MOVER		
					The following breakdown repair for Greenfreight Logging Pty Ltd, to a T659 Kenworth Truck, vin#6F5000000DPA476811, registration#XW79CD & number fleet number#1067 included: - * Customer called breakdown technician * Customer advised of truck not building air * Technician sourced additional parts * Technician travelled to breakdown location, Nth of Holbrook, NSW * Removed chassis walkway for access * Inspect & Located air exhausting from air dryer & governor * Removed line from air dryer & signal coming from governor valve * removed/replaced governor valve * Pressurise, test, confirmed & quality checked repair * Installed chassis walkway * Return truck to service * Technician returned home													
			Brakes\BREAKDOWN															
1067	Albury - Workshop	Brakes\BREAKDOWN	T097467			19/11/2025	651761	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	TWIN CITY TRUCK CENTRE - 4 - OLD	P/MOVER		
1067	Albury - Workshop	DriveLine\CTI Drive	CDI Line leaking air to inside tyre.			17/11/2025	650711	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER		
1067	Albury - Workshop	Tyres\Punct	Tyres\Punct POS 7			17/11/2025	651815	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	BORDER BANDAG PTY LTD - 4	P/MOVER		
1067	Albury - Workshop	Tyres\Punct	Tyres\Punct POS 6			16/11/2025	651761	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	BORDER BANDAG PTY LTD - 4	P/MOVER		
1067	Albury - Workshop	Chassis\AIR LEAK	Replace Hot Pipe. A Service Serviced @ 650,367		Replaced Hot Line, Adjusted Governor Valve To Correct Setting.	15/11/2025	650377	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Woodonga Workshop	P/MOVER		
1067	Albury - Workshop	VehService\AS		VehService\AS		15/11/2025	650970	Service	Completed	Greenfreight Loxeine Vic	KWX15LOG	Colac	GTK	XW79CD	Woodonwa Workshop	P/MOVER		
1067	Albury - Workshop	VServLab	B SERVICE			10/11/2025	646344	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Woodonga Workshop	P/MOVER		
1067	Albury - Workshop	VehService\B5	VehService\B5 B Service	VehService\B5		10/11/2025	646344	Service	Completed	Greenfreight Loxeine Vic	KWX15LOG	Colac	GTK	XW79CD	Woodonwa Workshop	P/MOVER		
1067	Albury - Workshop	Elect\TRL LIGHTS	NO LIGHTS OR INDICATORS ON TRAILERS. VehService\B1 Svc B 1 Service, Jack up steer axle check bearings and king pins.			10/11/2025	646344	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Woodonga Workshop	P/MOVER		
1067	Albury - Workshop	VehService\B1 Svc	Reelace cabin filter.	VehService\B1 Svc		10/11/2025	646344	PreventativeMaintenance	Completed	Greenfreight Loxeine Vic	KWX15LOG	Colac	GTK	XW79CD	Woodonwa Workshop	P/MOVER		
1067	Albury - Workshop	VehService\AS	VehService\AS A Service	VehService\AS		04/11/2025	642315	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Woodonga Workshop	P/MOVER		
1067	Albury - Workshop	CTI\CTI Drive	CTI Slow To Inflate			27/10/2025	652746	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Woodonga Workshop	P/MOVER		
1067	Albury - Workshop	Elect\DRV LIGHT	Driving lights Loose Wire			27/10/2025	652746	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Woodonga Workshop	P/MOVER		
1067	Albury - Workshop	Elect\WORK LIGHT	Rear Work Lights Not Working A Service			27/10/2025	652746	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Woodonga Workshop	P/MOVER		
1067	Albury - Workshop	VehService\AS	Serviced @ 637.036 Kims	VehService\AS		27/10/2025	652746	Service	Completed	Greenfreight Loxeine Vic	KWX15LOG	Colac	GTK	XW79CD	Woodonwa Workshop	P/MOVER		
1067	Albury - Workshop	Tyres\TP9+10	Tyres\TP9+10			25/10/2025	639415	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	BORDER BANDAG PTY LTD - 4	P/MOVER		
1067	Albury - Workshop	Tyres\TP11+12	Tyres\TP11+12			25/10/2025	639415	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	BORDER BANDAG PTY LTD - 4	P/MOVER		
1067	Albury - Workshop	Tyres\TP1+2	Tyres\TP1+2 VehService\B1 Svc B 1 Service, Jack up steer axle check bearings and king pins.		Steer tyres were reolaced due to tyres beine out of balance. Mav have got a bad batch of steer tyres as 1068 had the same issue on Thursday 23/10/25 and tyres were only a mo	21/10/2025	637034	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	BORDER BANDAG PTY LTD - 4	P/MOVER		
1067	Albury - Workshop	VehService\B1 Svc	Reelace cabin filter.	VehService\B1 Svc		19/10/2025	629792	PreventativeMaintenance	Unlocked	Greenfreight Loxeine Vic	KWX15LOG	Colac	GTK	XW79CD	Woodonwa Workshop	P/MOVER		
1067	Albury - Workshop	Chassis\AIR LEAK	Hot Line Fitting Leaking Air Tank End		Fault not found during service	11/10/2025	623649	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Woodonga Workshop	P/MOVER		
1067	Albury - Workshop	VehService\AS	Overdue Service		Completed on 11/10/25	11/10/2025	623649	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Woodonga Workshop	P/MOVER		
1067	Albury - Workshop	Engine\ADBLUE	After Treat Light On Dash (Stays On)		Issues did not present on day of service	11/10/2025	623649	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Woodonga Workshop	P/MOVER		
1067	Albury - Workshop	VehService\AS	Over Due Service A Service		Completed 11/10/25	11/10/2025	623649	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Woodonga Workshop	P/MOVER		
1067	Albury - Workshop	VehService\AS	Serviced @ 623650 Kims	VehService\AS		11/10/2025	623649	Service	Completed	Greenfreight Loxeine Vic	KWX15LOG	Colac	GTK	XW79CD	Woodonwa Workshop	P/MOVER		
1067	Albury - Workshop	DrCabRep\ELECT P&W	Right hand indicator on dash not working.			11/10/2025	623649	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Woodonga Workshop	P/MOVER		
1067	Albury - Workshop	Body\ELECT P&W	Replace right hand side Park light.		Replaced during a service	11/10/2025	623649	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Woodonga Workshop	P/MOVER		
1067	Albury - Workshop	Body\ELECT P&W	Right hand indicator on front guard is shorting. After treat light staying ON , On dash.		Completed during service	11/10/2025	623649	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Woodonga Workshop	P/MOVER		
1067	Albury - Workshop	DrCabRep\ELECT P&W	FOUND LEAKING ADBLUE FLUID DURING SERVICE			30/09/2025	612134	Fault	Completed	Greenfreight Loxeine Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER		
1067	Albury - Workshop	VehService\CS	VehService\CS	VehService\CS		30/09/2025	612134	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER		
					* Customer called breakdown technician * Customer advised of truck not building air * Technician sourced additional parts * Technician travelled to breakdown location, Tumbarumba * Removed chassis walkway for access * Inspect & confirmed air dryer leaking from blown out cork gasket * Unbolt air dryer & removed failed gasket * Cleaned all surface areas & installed replacement gasket * Installed, aligned & tensioned air dryer * Pressurise, test, confirmed & quality checked repair * Installed chassis walkway * Return truck to service * Technician returned home													
1067	Albury - Workshop	Engine\COMPRESSOR	Engine\COMPRESSOR		Technician ID 1108185. Drive to workshop at 5.40 am to meet driver. Inspect truck and found truck will not build up air. Disconnect trailer, check for air leaks around truck, hot line, unloader valve & governor valves, all ok. Connect insite tool. Troubleshoot air compressor dignosis on quicksereve on line. Visually inspect air intake system for blockages or damage, all ok. Inspect air filter, all ok. Inspect air compressor inlet tube for blockage or damage, all ok. Visually inspect air system for leaks as per procedure 010 024, visually inspect air compressor plumbing for leaks as per 010 024. Inspect exhaust pipe for leaks, cracks & loose connections as per 010 024, all are ok. Inspect charge air cooler hoses for leaks and pressure test charge air cooler for leaks as per 010 027. Found charge air cooler pressure drops 2.5 psi in 15 seconds, all ok. Inspect air intake system for leaks as per 010 024, no leaks. Ise soapy water, check air leaks on air compressor gaskets, air system hoses, fittings, tanks & valves, no leaks. This confirmed air compressor air pressure relief vlave is not operating correctly. Disconnect air compressor inlet tube 012 019. Hold a piece of paper in front of air compressor intake port, & operate the engine to activate air compressor. Found paper blows away from air compressor intake, then found air compressor relief valve malfunctioning detected. Wabco compressor air pressure relief valve is an integral part of air compress cylinder head, and will require head replacement. Remove air compressor cylinder head 013007 section 12, check inside circumference for scratches and damage. Remove power steering pump, drain coolant and air intake pipe to assist in repairs. Remove and replace air compressor as per 012 014. Replace air compressor mount gasket & tension bolts. Steam clean all parts. Re-install power steering pump with new gasket, tension bolts, refit air intake pipe. Refil coolant, start truck,													
1067	Albury - Workshop	Engine\COMPRESSOR	Engine\COMPRESSOR - BREAKDOWN		check for leaks. all wood. Repairs completed	25/09/2025	602889	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	TWIN CITY TRUCK CENTRE - 4 - OLD	P/MOVER		
1067	Albury - Workshop	Body\WIPERS	Windscreen Wipers Arms Need Oil		Lowered bull bar, lifted bonnet over, lubricated wiper arms, lowered bonnet, lifted bull bar, parked truck out in logging compound.	20/09/2025	605693	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Woodonga Workshop	P/MOVER		
1067	Albury - Workshop	Engine\ADBLUE	After Treatment Light On Dash For 2 Days		Emotied tool box to eain access to doser ouma. removed all lines off doser ouma. flushed lines. flushed doser ouma /wet & drv sidel. orimed doser ouma. insected & cleaned	20/09/2025	605693	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Woodonga Workshop	P/MOVER		
1067	Albury - Workshop	Workshop\MOVE ASSET	UNHOOKED B TRAILER. HOOKED UP T54B			17/09/2025	602890	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Woodonga Workshop	P/MOVER		
1067	Albury - Workshop	Brakes\VALVES	REPLACED BROKEN TRAILER BRAKE HANDPIECE WITH PART FROM #1003			17/09/2025	602890	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Woodonga Workshop	P/MOVER		
1067	Albury - Workshop	Body\MUDGUARDS	mudflaps between drive RHS.			17/09/2025	602890	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Woodonga Workshop	P/MOVER		
1067	Albury - Workshop	Susp\SHOCK ABS	Both left hand side. Top shock rubbers need to be replaced			17/09/2025	602890	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Woodonga Workshop	P/MOVER		
1067	Albury - Workshop	Chassis\MUDGUARDS	Replace L/H Drive Guards			17/09/2025	602890	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Woodonga Workshop	P/MOVER		
1067	Albury - Workshop	Chassis\MUDGUARDS	Tighten Left Front Guard Outrigger, Replace Guard & Brackets			17/09/2025	602890	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Woodonga Workshop	P/MOVER		
1067	Albury - Workshop	VehService\AS	Service			13/09/2025	599745	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Woodonga Workshop	P/MOVER		
1067	Albury - Workshop	VehService\AS	VehService\AS A Service BREAKDOWN CALLOUT $770.00	VehService\AS		13/09/2025	599745	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Woodonga Workshop	P/MOVER		
			- The following breakdown repair for Greenfreight Logging Pty Ltd, to a T659 Kenworth Truck, vin#6F5000000PA476811, registration#XW79CD & number fleet number#1067 included: - * Customer called breakdown technician * Customer advised of truck not building air * Technician sourced additional parts * Technician travelled to breakdown location, GF Depot, Vic * Removed chassis walkway for access * Inspect & confirmed air dryer constantly exhausting * Removed air dryer air lines, mounting bolts & removed air dryer * Installed, aligned & tensioned replacement air dryer * Pressurise, test, confirmed & quality checked repair * Installed chassis walkway * Return truck to service * Technician returned home													
1067	Albury - Workshop	Engine\AIR DRYER				29/08/2025	580277	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	TWIN CITY TRUCK CENTRE - 4 - OLD	P/MOVER		
1067	Albury - Workshop	Engine\ADBLUE	After Treat Fault		Removed all adblue lines & flushed out. removed and flushed out iniector. flushed drv side of doser ouma & flushed wet side of doser ouma. reconnected all adblue lines. carri	29/08/2025	580049	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Woodonga Workshop	P/MOVER		
1067	Albury - Workshop	Engine\FAULT CODE	Engine Light - Codes - 3569, 3575, 1852, 418		Found rubbed wire on water in fuel sensor, repaired wire, tested, all good	29/08/2025	580049	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Woodonga Workshop	P/MOVER		
1067	Albury - Workshop	Body\HOUSEKEEP	Replace brackets for top cabguard lights		-cabguard lights in good condition, working	25/08/2025	602888	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Woodonga Workshop	P/MOVER		
1067	Albury - Workshop	DriveLine\OIL LEAK	FRONT DIFF LEAKING			25/08/2025	602888	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Woodonga Workshop	P/MOVER		
1067	Albury - Workshop	Elect\INDICATORS	Right bonnet indicator only working sometimes		-RHS bonnet indicator wiring broken from light, part replaced	25/08/2025	602888	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Woodonga Workshop	P/MOVER		
1067	Albury - Workshop	Air Con\HEATER	CHECK HEATER CORE UNDER DASH.			25/08/2025	602888	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Woodonga Workshop	P/MOVER		
1067	Albury - Workshop	VehService\AS	VehService\AS A Service	VehService\AS		25/08/2025	602888	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Woodonga Workshop	P/MOVER		
1067	Albury - Workshop	DriveLine\OIL LEAK	Front Diff Leaking			25/08/2025	602888	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Woodonga Workshop	P/MOVER		
					Replace brake shoes and drums on rear axle, check and adjust bearings, refill hubs with oil.													
1067	Albury - Workshop	Brakes\BRK RELINE	Brake Reline Rear Drive Axle.		Scam tube bushes worn	25/08/2025	602888	Repair	Completed	Greenfreight Loxeine Vic	KWX15LOG	Colac	GTK	XW79CD	Woodonwa Workshop	P/MOVER		
1067	Albury - Workshop	Susp\SHOCK ABS	Both left hand side. Top shock rubbers need to be replaced			25/08/2025	602888	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Woodonga Workshop	P/MOVER		
					-cab guard lights checked, all mounts and lights ok -lights check done													
1067	Albury - Workshop	DrCabElect\ELECT P&W	REPLACE ALT!! LIGHT BEEN FLASHING ON DASH FOR 2 MONTHS (FIX IT)		-bonnet right hand side indicator replaced -hieh beam indicator faulty. 2nd hand oart installed. lieht workine but dull	25/08/2025	602888	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Woodonga Workshop	P/MOVER		
1067	Albury - Workshop	DrCabElect\INST/GAUGE	High Beam Tell Tail Light In Dash Not Working.		-high beam indicator replaced with 2nd hand part	25/08/2025	602888	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Woodonga Workshop	P/MOVER		
1067	Albury - Workshop	DrCabElect\INDICATORS	indicator on RH guard not working		-bonnet indicator replaced	25/08/2025	602888	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Woodonga Workshop	P/MOVER		
1067	Albury - Workshop	DriveLine	Input shaft seals leaking			25/08/2025	602888	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Woodonga Workshop	P/MOVER		
1067	Albury - Workshop	DrCabElect\INST/GAUGE	ALT ON MOST OF SHIFT.		-couldnt fault alternator issue	25/08/2025	602888	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Woodonga Workshop	P/MOVER		
1067	Albury - Workshop	Elect\ALT	ALT LIGHT- REWIRE ALTERNATOR.		-alternator checked over on truck, working	25/08/2025	602888	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Woodonga Workshop	P/MOVER		
1067	Albury - Workshop	DriveLine\OIL LEAK	Rear diff input seal weeping 31/5/25			25/08/2025	602888	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Woodonga Workshop	P/MOVER		
1067	Albury - Workshop	DriveLine\OIL LEAK	Front diff input seal weeping 31/5/25			25/08/2025	602888	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Woodonga Workshop	P/MOVER		
1067	Albury - Workshop	DriveLine\OIL LEAK	front diff pinion seal			25/08/2025	602888	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Woodonga Workshop	P/MOVER		

			VehService\B1 Svc B 1 Service, Jack up steer axle check bearings and king pins.															
1067	Albury - Workshop	VehService\B1 Svc	Reelace cabin filter.	VehService\B1 Svc		25/08/2025	602888	PreventativeMaintenance	Completed	Greenfreight Loxeine Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	Engine\ADBLUE	After Treat Fault		Removed Adblue Lines & Flushed With Hot Water. Flushed Air Side Of Doser Pump. Flushed Wet Side Of Doser Pump & Adblue Iniector. Carried Out Flow Test. All Good Refitted	23/08/2025	585943	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	DrCabElect\INST/GAUGE	High Beam Globe In Dash		Replaced Globe Found That Didn't Fix The Issue, Found Circuit Board For Dash Lights Has A Dry Solder, Will Be Fixed Next Service.	23/08/2025	585943	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	Chassis\AIR LEAK	AIR LEAK			17/08/2025	583708	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	Elect\INDICATORS	RH INDICATOR ON SIDE OF BONNET			17/08/2025	583708	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	VehService\AS	VehService\AS A Service	VehService\AS		17/08/2025	583708	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	Chassis\AIR LEAK	Check For Air Leak/s Truck Won't Build Up Air Over 600 kpa			14/08/2025	580235	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	Engine\ADBLUE	After Treat Fault		Blocked injector and lines, flushed all lines and pump, Shaun test drove vehicle fault self cleared	14/08/2025	580235	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	Tyres\TPS+2	Tyres\TPS+2			08/08/2025	575507	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	BORDER BANDAG PTY LTD - 4	P/MOVER		
1067	Albury - Workshop	VehService\AS	VehService\AS A Service	VehService\AS		05/08/2025	574333	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	Brakes\BRK RELINE	Rear drive brakes getting low 31/5/25		INCORRECTLY REPORTED	05/08/2025	574333	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	DrCabRep\ST Weel	Adjust Steering Wheel To Straight		Realigned Steering Wheel.	02/08/2025	570907	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	Steering\WHEEL ALGN	Wheel Alignment		Realigned Steering Wheel.	02/08/2025	570907	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	Steering\WHEEL ALGN	wheel alignment		Realigned Steering Wheel.	02/08/2025	570907	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	Steering\WHEEL ALGN	wheel alignment		Realigned Steering Wheel.	02/08/2025	570907	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	Tyres\TPT+8	Tyres\TPT+8			24/07/2025	563322	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	BORDER BANDAG PTY LTD - 4	P/MOVER		
1067	Albury - Workshop	Tyres\TPS+6	Tyres\TPS+6			24/07/2025	563322	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	BORDER BANDAG PTY LTD - 4	P/MOVER		
1067	Albury - Workshop	Brakes\EBS FAULTS	ENSURE TRAILER ABS FUSES ARE FITTED AND WORKING		Opened Fuse Box, Checked EBS Fuse's Were In Correct Positions & Not Blown, Closed Fuse Box, Checked EBS Leads Were Connected To Trailer's.	24/07/2025	562539	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	VehService\AS	VehService\AS A Service	VehService\AS		23/07/2025	562476	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	Workshop\MOVE ASSET	Move truck from tyre bay		Went to park truck for tyre fitters, Noticed after treat light was on once I parked down at the log yard. Parked behind workshop so after treat fault could be repaired	21/07/2025	560707	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	Engine\BREAKDOWN	Aftertreat fault		Inspected aftertreat fault. Found dose iniector had blocked up and was cracked. Reolaced dose iniector and tested. Took for test drive down Bandianna Link road and back. Alfa	21/07/2025	560707	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	Chassis\SCALES	no scales - replace load cells			15/07/2025	554861	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	VehService\BS	VehService\BS B Service	VehService\BS		15/07/2025	554198	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER		
1067	Albury - Workshop	VehService\AS	VehService\AS A Service	VehService\AS		14/07/2025	554197	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER		
1067	Albury - Workshop	Susp	Rf shock bush			14/07/2025	554197	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER		
			VehService\B1 Svc B 1 Service, Jack up steer axle check bearings and king pins.															
1067	Albury - Workshop	VehService\B1 Svc	Reelace cabin filter.	VehService\B1 Svc		02/07/2025	544529	PreventativeMaintenance	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	Engine\ADBLUE	AD blue tank cover loose			02/07/2025	544529	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	VehService\AS	VehService\AS A Service	VehService\AS		02/07/2025	544529	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	Steering\PWR STEER	RAPID HYDRAULICS- REPLACE POWER STEERING HOSE.			02/07/2025	544529	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
					-cage lights replaced													
1067	Albury - Workshop	DrCabRep\HOUSEKEEP	replace brackets both top cab guard lights		-trailer lights cleaned with wiring fixed up as required	02/07/2025	544530	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	Elect\WORK LIGHT	brackets top two work lights		-scales checked over for faults, couldnt fault	02/07/2025	544530	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	Chassis\SCALES	scales faulty			02/07/2025	544530	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	Chassis\AIR LEAK	REPLACE AIR DRYER GASKET & O RING ALSO CHECK MATING SURFACES ALL OK			25/06/2025	537624	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Myrtleford Workshop	P/MOVER		
1067	Albury - Workshop	Tyres\RUN OUT	Tyres\RUN OUT POS 1			24/06/2025	536854	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	BORDER BANDAG PTY LTD - 4	P/MOVER		
1067	Albury - Workshop	Tyres\TPS+10	Tyres\TPS+10			24/06/2025	536854	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	BORDER BANDAG PTY LTD - 4	P/MOVER		
1067	Albury - Workshop	Tyres\TPS1+12	Tyres\TPS1+12			24/06/2025	536854	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	BORDER BANDAG PTY LTD - 4	P/MOVER		
1067	Albury - Workshop	VehService\AS	VehService\AS A Service	VehService\AS		24/06/2025	536787	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	Body\MUDGUARDS	REPLACE LH REAR GUARD & OUTRIGGER.			13/06/2025	529648	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER		
1067	Albury - Workshop	VehService\BS	VehService\BS B Service	VehService\BS		11/06/2025	525985	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	Tyres\TPS+2	Tyres\TPS+2			04/06/2025	520852	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	BEAUREPAIRES - 4	P/MOVER		
1067	Albury - Workshop	Body\PANELS	REPAIR CRACKED BONNET.		multiple entry	31/05/2025	517080	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	Body\PANELS	REPLACE RH S GUARD.		multiple entry	31/05/2025	517080	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	VehService\AS	VehService\AS A Service	VehService\AS		31/05/2025	517080	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	Tyres	Tyres NO TYRE POS PROVIDED			29/05/2025	514286	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	BEAUREPAIRES - 4	P/MOVER		
1067	Albury - Workshop	Tyres\Punct	Tyres\Puncture POS 10			19/05/2025	505630	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	BEAUREPAIRES - 4	P/MOVER		
1067	Albury - Workshop	VehService\BS	B Service			19/05/2025	505630	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	Elect\DRV LIGHT	Driving lights Have Short		-couldn't fault driving lights or alternator	19/05/2025	505630	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	VehService\B1 Svc	Service			19/05/2025	505630	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
			VehService\B1 Svc B 1 Service, Jack up steer axle check bearings and king pins.															
1067	Albury - Workshop	VehService\B1 Svc	Reelace cabin filter.	VehService\B1 Svc		19/05/2025	505630	PreventativeMaintenance	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	Brakes\EBS FAULTS	TRAILER ABS LIGHT ALWAYS ON.			19/05/2025	505630	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	Chassis\BULLBAR	REPLACE MISSING BULLBAR BOLT.		Previously completed	19/05/2025	505630	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	Elect\DRV LIGHT	DRIVING LIGHTS FLICKERING.			19/05/2025	505630	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	DrCabRep\WINDSCREEN	Windscreen Leak's L/H/S.			19/05/2025	505630	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	Brakes\ABS	TRAILER ABS LIGHT ON.			19/05/2025	505630	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	VehService\AS	VehService\AS A Service	VehService\AS		19/05/2025	505630	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	Brakes\ABS	Trailer ABS Light On Dash		Light not on at service	19/05/2025	505630	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	Brakes\ABS	TRAILER ABS LIGHT ON DASH 1 MONTH (FIX IT)		Previously completed	19/05/2025	505630	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	DrivLine\WHEEL SEAL	AN APOLOGY FOR PUTTING ME IN DANGER LAST WEEK WOULD BE APPROPRIATE ALSO.			14/05/2025	505630	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER		
					* Customer contacted dealership breakdown technician with information regarding breakdown * Customer advised of truck dropped air & will not build up air * Technician sourced additional parts * Technician travelled to breakdown location, Jingellic Rd, Mannus, NSW * Inspected pulleys, belts, compressor & components * Located failed air dryer gasket & constantly exhausting * Removed air dryer air lines & air dryer complete * Removed/replaced failed gasket * Installed air dryer, air lines & tensioned to specification * Removed/replaced filer * Pressurised, test, confirmed & quality checked repair												
			Repair Air Leak/s In Front Of Front L/H Drive Tyres.		* Returned truck to service													
1067	Albury - Workshop	Chassis\AIR LEAK	(TCTC P/O- T0942821) MM DIESELS-		* Technician returned home	09/05/2025	498113	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	TWIN CITY TRUCK CENTRE - OLD	P/MOVER		
			REPORTED BLOWN RH STEER HUB SEAL.															
1067	Albury - Workshop	Steering\WHEEL SEAL	REPLACE COMPONENTS AS REQUIRED.		REPLACED WHEEL SEAL BRAKES AND HUB.	08/05/2025	503505	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	MM DIESEL - 4	P/MOVER		
1067	Albury - Workshop	VehService\AS	VehService\AS A Service	VehService\AS	Blown hub seal RHF steer	07/05/2025	497055	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	Elect\BATTERY	JUMP START.		Replace batteries	17/04/2025	484860	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	VehService\BS	VehService\BS B Service	VehService\BS	Prepared batterys	17/04/2025	484860	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	Elect\WORK LIGHT	Worklight On Cab Rack R/H Bottom Loose			17/04/2025	484860	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	Chassis\AIR LEAK	CHECK AIR DRYER FOR LEAKS.			17/04/2025	484860	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
			ROBINSON'S TRUCK & COACH-HARO'S MECHANICAL BENALLA-															
1067	Albury - Workshop	Chassis\AIR LEAK	BREAKDOWN- TRAVEL TO SAMARIA ST. BENALLA. REPAIR BLOWN AIR DRYER GASKET. REPLACE AIR DRYER GASKET.			14/04/2025	537624	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	ROBINSON'S TRUCK & COACH - 4	P/MOVER		
1067	Albury - Workshop	Chassis\AIR LEAK	HORO'S TRUCK & TRAILER BENALLA.		#454876	14/04/2025	537624	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	ROBINSON'S TRUCK & COACH - 4	P/MOVER		
1067	Albury - Workshop	Brakes\ABS	Trailer ABS Light On Dash		Multiple job card	08/04/2025	478610	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	Body\MUDGUARDS	LHF Guard drive (Replace)			08/04/2025	478610	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	Chassis\MUDGUARDS	Replace L/F Guard On Drive			08/04/2025	478610	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	Body\MUDGUARDS	REPLACE LEFT FRONT GUARD BRACKET-DRIVE.			08/04/2025	478610	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	Engine\ALT	Alternator light keep's coming on.			08/04/2025	478610	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	Brakes\AIR LEAK	Air dryer gasket blown			08/04/2025	478610	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	VehService\AS	VehService\AS A Service	VehService\AS	478612 KMS	08/04/2025	478610	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	Body\MUDGUARDS	LH quarter guard need's adjusting.			08/04/2025	478610	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	Body\WINDSCREEN	L/H Windscreen Still Leaks			08/04/2025	478610	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	Brakes\EBS FAULTS	TRAILER ABS FAULT.			08/04/2025	478610	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	Brakes\ABS	trailer abs fault - light on		Multiple faults	08/04/2025	478610	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	Body\LIGHTS	Driving light cover's			08/04/2025	478610	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	Body\PANELS	REPAIR CRACKED BONNET.			08/04/2025	478610	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	Body\PANELS	Repair cracked bonnet			08/04/2025	478610	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	DrCabElect\INST/GAUGE	ALTERNATOR LIGHT FLASHING ON.			08/04/2025	478610	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
			VehService\AS A Service															
1067	Albury - Workshop	VehService\AS	TCTC PO #T093158	VehService\AS		04/04/2025	472220	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	PACCAR PARTS FLEET SERVICES - 4	P/MOVER		
1067	Albury - Workshop	DrCabElect\INST/GAUGE	ALT LIGHT STILL COMING ON.		Unable to fault	04/04/2025	472220	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	PACCAR PARTS FLEET SERVICES - 4	P/MOVER		
1067	Albury - Workshop	Elect\ALT2 DR	Alt Light Comes On When Using Lights & Working		Unable to fault	04/04/2025	472220	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	PACCAR PARTS FLEET SERVICES - 4	P/MOVER		
1067	Albury - Workshop	DrivLine\OIL LEAK	front pinion seal leaking		Completed	04/04/2025	472220	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	PACCAR PARTS FLEET SERVICES - 4	P/MOVER		
1067	Albury - Workshop	Engine\FAULT CODE	alt fault - light flashing		unable to fault	04/04/2025	472220	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	PACCAR PARTS FLEET SERVICES - 4	P/MOVER		
1067	Albury - Workshop	Engine\COMPRESSOR	replace compressor hotline		Completed	04/04/2025	472220	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	PACCAR PARTS FLEET SERVICES - 4	P/MOVER		
1067	Albury - Workshop	Elect\ELECT P&W	Trailer lights not working		Reset circuit breakers	29/03/2025	470976	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER		
1067	Albury - Workshop	VehService\B1 Svc	VehService\B1 Svc	VehService\B1 Svc		26/03/2025	467892	PreventativeMaintenance	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	VehService\AS	VehService\AS A Service	VehService\AS		26/03/2025	467892	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	Brakes\BRK RELINE	Brakes\BRK RELINE FRONT DRIVE RELINE			18/03/2025	460993	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	Engine\FAULT CODE	Aftertreat light on		Fault code 3575. Flushed out pump. Fault cleared	18/03/2025	460993	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	VehService\AS	VehService\AS	VehService\AS		17/03/2025	460963	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	VSim\ab	SERVICE.		Completed as above	17/03/2025	460963	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	DrCabRep\ST Weel	STEERING COLUMN LOCK.		Previously completed	17/03/2025	460963	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	Brakes\ABS	TRUCK ABS LIGHT ON DASH.		Previously completed	17/03/2025	460963	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	VehService\AS	VehService\AS A Service	VehService\AS		17/03/2025	460963	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	Steering\WHEEL ALGN	Wheel Alignment.			14/03/2025	457033	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	DrCabRep\WINDSCREEN	LH WINDSCREEN CRACKED.		Previously completed	14/03/2025	457033	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	VehService\AS	VehService\AS A Service	VehService\AS		14/03/2025	457033	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Wodonga - Workshop	Tyres\TPS+2	Tyres\TPS+2 STEER			12/03/2025	460993	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	BEAUREPAIRES - 4	P/MOVER		
1067	Wodonga - Workshop	Tyres\TPS+6	Tyres\TPS+6			05/03/2025	457740	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	BEAUREPAIRES - 4	P/MOVER		
1067	Wodonga - Workshop	Tyres\TPS+4	Tyres\TPS+4			05/03/2025	457740	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	BEAUREPAIRES - 4	P/MOVER		
1067	Albury - Workshop	Engine\MOUNTS	Replace front Engine Mount's.		K. RYAN 4 HOURS LABOUR.	01/03/2025	452043	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	DrCabRep\ST Weel	Steering column lock need's to be fixed.		Duplicate job	28/02/2025	451093	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	VehService\AS	VehService\AS A Service	VehService\AS		28/02/2025	451093	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	DrCabRep\ST Weel	Steering column lock is not working.		Duplicate job	28/02/2025	451093	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
					Checked alternator output with all lights on high beam chatging at 13 volts no alternator light came on. Could hear a squeal pulled belt off oncheck bearing. Not coming from alternator													
1067	Albury - Workshop	DrCabElect\ELECT P&W	Alternator light intermittenly flashing.		Drive to monitor	28/02/2025	451093	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	Susp\SHOCK ABS	Front shocker's are bouncing truck off the road on corrigated road surfaces.(maybe shocker's are Stuffed)		DUplicate job	28/02/2025	451093	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	Elect\ALT	Alternator light comes on when loaded & high beam.		Duplicate job	28/02/2025	451093	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	Susp\SHOCK ABS	Replace front shocker's		Parts ordered 28/2/25	28/02/2025	451093	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	Engine\ALT	Alternator Fault - Dash light (ALT) flashes.		Duplicate job	20/02/2025	445613	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	DrCabElect\INST/GAUGE	Stop Engine light comes on when Engine temp hit's 100, once fan is on it goes out.		Russel said this was an old fault that has beenresolved	20/02/2025	445613	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	VehService\BS	VehService\BS	VehService\BS		20/02/2025	445613	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	DrivLine\OIL LEAK	R/H/F HCB Seal Leaking.		Russel completed	20/02/2025	445613	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER		
1067	Albury - Workshop	Brakes\ABS	Trailer ABS Fault.		Russel completed	20/02/2025	445613	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop

1067	Wodonga - Workshop	Steering\PWR STEER	Wheel alignment		Duplicate job		28/01/2025	431030	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Susp\WHEEL ALIGN	WHEEL ALIGNMENT - STEERS.		Duplicate job		28/01/2025	431030	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Steering\WHEEL ALIGN	wheel alignment - pulling left		Duplicate job		28/01/2025	431030	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Steering\WHEEL ALIGN	wheel alignment - pulling to left				28/01/2025	431030	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Tyres\ALIGNMENT	Wheel alignment - Pulling to the left		Duplicate job		28/01/2025	431030	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Steering\WHEEL ALIGN	Pulls to Left when Empty		Inspect front end both king pins have minor play arther grease recamend replace		28/01/2025	431030	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Engine\FAULT CODE	stop engine light on comes on when going up hill, goes off on flat - Coolant full!		Shaun checked coad and is oil thermistat to be booked to twin city		28/01/2025	431030	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
					Coolant leak on top lhs coolant hose tighten clamps												
1067	Wodonga - Workshop	VehService\AS	VehService\AS	VehService\AS	Rhs hub cap leakine tighten hub cas bolts		28/01/2025	431030	Service	Completed	Greenfreight Loxeine Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Myrtleford - Workshop	DrivLine\CLUTCH	clutch very heavy and needs adjusting		clutch is very heavy adjusted free travel retested all good		22/01/2025	428863	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Myrtleford Workshop	P/MOVER
1067	Wodonga - Workshop	DrivLine\CTCH PACK	adjust clutch - too much free travel		Previously done.....blair		20/01/2025	427067	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Brakes\ABS	Trailer ABS light on		Trailer issue not truck		20/01/2025	427067	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
			REPLACE RH 'L GUARD.														
1067	Wodonga - Workshop	Body\PANELS	ADJUST LH 'L GUARD.		Adjusted lh euard		20/01/2025	427067	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	VehService\AS	VehService\AS	VehService\AS			18/01/2025	426582	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Engine\FAULT CODE	engine brake light in dash		Driver repaired himself		17/01/2025	425152	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
					Recommend reclace												
1067	Wodonga - Workshop	DrCabRep\WINDSCREEN	REPLACE LH WINDSCREEN.				09/01/2025	420712	Fault	Completed	Greenfreight Loxeine Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Body\LIGHTS	Left - Top Cab Guard Work light Falling OFF.		Cable tied up and surcured		09/01/2025	420712	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	VehService\AS	VehService\AS	VehService\AS	Coolant leak Tighten hose claps		09/01/2025	420712	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Body\WINDSCREEN	Replace LH windscreen		Recommend replacing		09/01/2025	420712	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	DrivLine\CLUTCH	adjust clutch		Adjust clutch		09/01/2025	420712	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Engine\FAULT CODE	STOP ENGINE LIGHT KEEPS COMING ON WHEN WORKING LOADED UP HILL.		Informed to leave it by shuan and Keith		09/01/2025	420712	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Steering\WHEEL HUB	Refill both steer hubs check for leaks		Hubs all good no leakshub oil good		09/01/2025	420712	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Susp\SWAYBAR	REPLACE SWAYBAR BUSHES.		Perused not major damage		09/01/2025	420712	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Engine\HOUSEKEEP	Truck Idling To Fast		All good		09/01/2025	420712	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Albury - Workshop	Tyres\TPS-2	Tyres\TPS-2				09/01/2025	420342	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	BEAUREPAIRES - 4	P/MOVER
1067	Wodonga - Workshop	VehService\CS	C Service	VehService\CS	TCTC are Doing Service.		18/12/2024	413418	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	PACCAR PARTS FLEET SERVICES	P/MOVER
1067	Wodonga - Workshop	VehService\AS	VehService\AS	VehService\AS			14/12/2024	411486	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Engine\FAULT CODE	Check Engine Codes- Would'nt Flash Any Codes On Dash.		Low voltage code inactive		10/12/2024	408306	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Elect\ALT2 DR	Check Alternator, Guage Showing Under 12v and Check Engine Lightcomes on when High Beam is ON.		Alt charging at 9 volts replaced checked charge		10/12/2024	408306	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Elect\DRV LIGHT	REPLACE MISSING DRIVING LIGHT COVER.		previously completed.		02/12/2024	402532	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	VehService\AS	VehService\AS	VehService\AS			02/12/2024	402532	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	VServLab	A-SERVICE.				02/12/2024	402532	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Brakes\AIR FITTIN	REPLACE AIR LINE PLUG.				02/12/2024	402532	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Engine\EJECT P&W	PTO IDLE INCREASE NOT WORKING.		COULDN'T FAULT.		02/12/2024	402532	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Chassis\SCALES	No Scale Back Bay (8 Trailer)		COULDN'T FAULT.		02/12/2024	402532	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	VehService\AS	VehService\AS	VehService\AS			21/11/2024	393004	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
					I spent 10 minutes on this job												
					Dan did the top												
					Shane McCabe did underneath												
1067	Wodonga - Workshop	VehService\AS	VehService\AS	VehService\AS	383758ks		11/11/2024	384425	Service	Completed	Greenfreight Loxeine Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Chassis\MUDGUARDS	Replace R/H 1/4 Guard		Duplicate job		11/11/2024	384425	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	VServLab	A SERVICE.		COMPLETED 7/11/24		08/11/2024	382907	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Albury - Workshop	Tyres\STEER TYRE	Replace Steer Tyres & Balance. (Wodonga Tyre & Auto P/O: T090095				01/11/2024	381171	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	BEAUREPAIRES - 4	P/MOVER
1067	Wodonga - Workshop	Chassis\FIFTH WHEE	Grease Turn Table				01/11/2024	378030	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	VServLab	SERVICE.				30/10/2024	375024	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	VehService\AS	VehService\AS	VehService\AS			30/10/2024	375024	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Cooling\COOL LEAKS	Heater Core Leaking- Coolant On Floor.		TIGHTENED CLAMPS		30/10/2024	375024	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	VehService\AS	VehService\AS	VehService\AS			24/10/2024	369830	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Body\LIGHTS	L/H Front Guard Indicator Still Not Working				15/10/2024	364057	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	VehService\AS	VehService\AS	VehService\AS			15/10/2024	364057	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Elect\INDICATORS	LH INDICATOR OUT. FRONT GUARD.				15/10/2024	364057	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Body\CONSUMABLE	Replace Windscreen Wiper Blades.				14/10/2024	363225	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Albury - Workshop	Tyres\TPT+8	Tyres\TPT+8				11/10/2024	363215	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	BEAUREPAIRES - 4	P/MOVER
1067	Albury - Workshop	Tyres\TPS+6	Tyres\TPS+6				11/10/2024	363215	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	BEAUREPAIRES - 4	P/MOVER
1067	Albury - Workshop	Tyres\TPS+10	Tyres\TPS+10				11/10/2024	363215	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	BEAUREPAIRES - 4	P/MOVER
1067	Albury - Workshop	Tyres\TPS+4	Tyres\TPS+4				11/10/2024	363215	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	BEAUREPAIRES - 4	P/MOVER
1067	Albury - Workshop	Brakes\EBS FAULTS	TRAILER ABS LIGHT ON DASH.				11/10/2024	364057	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	TWIN CITY TRUCK CENTRE - OLD	P/MOVER
1067	Albury - Workshop	VehService\CS	B1 service - C service ???				11/10/2024	364057	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	TWIN CITY TRUCK CENTRE - OLD	P/MOVER
1067	Albury - Workshop	VehService\AS	VehService\AS	VehService\AS			11/10/2024	364057	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	TWIN CITY TRUCK CENTRE - OLD	P/MOVER
1067	Albury - Workshop	Brakes\ABS	TRUCK ABS LIGHT ON DASH. ATC LIGHT WILL NOT GO OFF.				11/10/2024	364057	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	TWIN CITY TRUCK CENTRE - OLD	P/MOVER
1067	Albury - Workshop	Engine\FAULT CODE	STOP ENGINE LIGHT KEEPS COMING ON.				11/10/2024	364057	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	TWIN CITY TRUCK CENTRE - OLD	P/MOVER
1067	Albury - Workshop	Brakes\ABS	ATC Still Playing Up Lights Up Won't Turn Off				11/10/2024	364057	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	TWIN CITY TRUCK CENTRE - OLD	P/MOVER
1067	Albury - Workshop	VehService\BS	B Service. (TCTC P/O: T089316)	VehService\BS			11/10/2024	364057	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	TWIN CITY TRUCK CENTRE - OLD	P/MOVER
1067	Albury - Workshop	Engine\FAULT CODE	Stop Engine Still Comes On				11/10/2024	364057	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	TWIN CITY TRUCK CENTRE - OLD	P/MOVER
1067	Albury - Workshop	VehService\AS	Due For Service				11/10/2024	364057	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	TWIN CITY TRUCK CENTRE - OLD	P/MOVER
1067	Wodonga - Workshop	VehService\AS	SERVICE.				10/10/2024	363207	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	TWIN CITY TRUCK CENTRE - OLD	P/MOVER
1067	Wodonga - Workshop	VehService\AS	SERVICE.				10/10/2024	363207	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	TWIN CITY TRUCK CENTRE - OLD	P/MOVER
1067	Wodonga - Workshop	VehService\BS	B Service	VehService\BS			10/10/2024	363207	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	TWIN CITY TRUCK CENTRE - OLD	P/MOVER
1067	Wodonga - Workshop	VehService\AS	SERVICE.				10/10/2024	363207	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	TWIN CITY TRUCK CENTRE - OLD	P/MOVER
1067	Wodonga - Workshop	VServLab	SERVICE - 7,000KM OVERDUE.				10/10/2024	363207	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	TWIN CITY TRUCK CENTRE - OLD	P/MOVER
1067	Wodonga - Workshop	Engine\ADBLUE	CHECK ADBLUE (LIGHT ON DASH)				10/10/2024	363207	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	TWIN CITY TRUCK CENTRE - OLD	P/MOVER
1067	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection	Insp\ANN INSP			10/10/2024	363207	PreventativeMaintenance	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	TWIN CITY TRUCK CENTRE - OLD	P/MOVER
1067	Wodonga - Workshop	Susp\SHOCK ABS	Loose & Worn Shockey Rubber				01/10/2024	356327	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	DrCabRep\WIPERS	REPLACE WIPER BLADES.				01/10/2024	356327	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Steering\PWR STEER	Check weld on steering column in cab				01/10/2024	356327	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	DrCabElect\ELECT P&W	LH indicator on bonnet				01/10/2024	356327	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Susp\SHOCK ABS	Replace shocker mount as per R&R 131910				01/10/2024	356327	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Engine\FAULT CODE	REPAIR BROKEN WIRE FOR CHECK ENGINE LIGHT.				01/10/2024	356327	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
			VehService\AS														
1067	Wodonga - Workshop	VehService\AS	Serviced @ 385,327 Kims	VehService\AS			01/10/2024	356327	Service	Completed	Greenfreight Loxeine Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Elect\ELECT P&W	ATC wont turn off				01/10/2024	356327	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Body\MUDGUARDS	REPLACE RH GUARD BRACKET-DRIVE.				01/10/2024	356327	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Elect\INDICATORS	LH indicator bonnet				01/10/2024	356327	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Elect\INDICATORS	LH indicator on side of bonnet				01/10/2024	356327	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	DrCabElect\INST/GAUGE	Stop engine light wire				01/10/2024	356327	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	DrCabRep\HOUSEKEEP	window wiper LH side				01/10/2024	356327	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	DrivLine\PTO	P.T.O. FAST IDLE NOT WORKING.				01/10/2024	356327	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Engine\ENG FAN	Check temp sensor/scotch horton coming on late				01/10/2024	356327	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	VehService\AS	A servise				26/09/2024	356327	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	VehService\AS	VehService\AS	VehService\AS			26/09/2024	356327	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Brakes\BRAKE ADJ	Check brake linnings				26/09/2024	356327	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Body\MUDGUARDS	Adjust RH 1/4 Guard		Ruby completed required work		27/08/2024	326154	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
			VehService\AS														
			Serviced @ 323680 Kims														
1067	Wodonga - Workshop	VehService\AS	VehService\AS	VehService\AS			23/08/2024	323678	Service	Completed	Greenfreight Loxeine Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	VehService\AS	A Service				23/08/2024	323678	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	VehService\AS	VehService\AS	VehService\AS			15/08/2024	316813	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	VServLab	A SERVICE				15/08/2024	316813	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Albury - Workshop	Tyres\TPS+2	Tyres\TPS+2				13/08/2024	315208	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	BEAUREPAIRES - 4	P/MOVER
1067	Wodonga - Workshop	VehService\AS	VehService\AS	VehService\AS			08/08/2024	310546	Service	Completed	Greenfreight Loxeine Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	VehService\AS	A SERVICE.				08/08/2024	310546	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	VehService\AS	SERVICE.				08/08/2024	310546	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	VServLab\AS	A SERVICE (CHECK COOLANT- REPAIR RADIATOR)				08/08/2024	310546	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	VehService\AS	Service				08/08/2024	310546	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Myrtleford - Workshop	Susp\SHOCK ABS	RHFD shocker loose in top bracket		inspected shocker all good found rubbers u/s and top mount worn out replaced rubbers but top mount needs to be replaced		06/08/2024	309060	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Myrtleford Workshop	P/MOVER
1067	Albury - Workshop	Elect\DRV LIGHT	RH DRIVING LIGHT.		Repaired by TCTC under warranty		05/08/2024	307836	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	TWIN CITY TRUCK CENTRE - OLD	P/MOVER
1067	Albury - Workshop	Cooling\RADIATOR	CHECK COOLANT LEVEL.		Repaired by TCTC under warranty		05/08/2024	307836	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	TWIN CITY TRUCK CENTRE - OLD	P/MOVER
					Repaired by TCTC under warranty												
1067	Albury - Workshop	Cooling\COOL LEAKS	replace / repair leaking radiator				05/08/2024	307836	Fault	Completed	Greenfreight Loxeine Vic	KWX15LOG	Colac	GTK	XW79CD	TWIN CITY TRUCK CENTRE - OLD	P/MOVER
1067	Albury - Workshop	Engine\OIL LEAK	Oil Leak		Repaired by TCTC under warranty		05/08/2024	307836	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	TWIN CITY TRUCK CENTRE - OLD	P/MOVER
1067	Albury - Workshop	Elect\DRV LIGHT	R/H Driving Light		Repaired by TCTC under warranty		05/08/2024	307836	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	TWIN CITY TRUCK CENTRE - OLD	P/MOVER
1067	Albury - Workshop	Tyres\TPS+4	Tyres\TPS+4				02/08/2024	306403	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	BEAUREPAIRES - 4	P/MOVER
1067	Wodonga - Workshop	Elect\DRV LIGHT	Tyres\TPS+4+5+6+7+8+9+10				30/07/2024	301434	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
			RH DRIVING LIGHT HAS A SHORT.														
			Elect\TRL LIGHTS														
			CHECK RH BLINKER R/W A/H														
			TRAVEL TO G/F														
			CHECK AND REPAIR BROKEN WIRING														
			ALSO LOCATE FAULTY SIDE CLEARANCE LIGHT														
			GET PART FROM TCTC. RETURN TO SITE														
			FIT AS REQUIRED														
1067	Albury - Workshop	Elect\TRL LIGHTS	CHECK OPERATION OK				24/07/2024	296640	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	HAGANS AUTO ELECTRICAL - 4	P/MOVER
1067	Wodonga - Workshop	VehService\AS	VehService\AS	VehService\AS			11/07/2024	324372	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Engine\ADBLUE	REPLACE ADBLUE INJECTOR & HOSE.				11/07/2024	324372	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
			Broken Adblue Injector Fitting, Flush Doser Pump, Replace Injector Hose If Needed (TCTC P/O: T087229)														
1067	Albury - Workshop	Engine\ADBLUE					08/07/2024	281974	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	TWIN CITY TRUCK CENTRE - OLD	P/MOVER
1067	Wodonga - Workshop	Chassis\MUDGUARDS	Fit Flat Steel Strap To Front Left Drive Guard				03/07/2024	278756	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Body\MUDGUARDS	Replace left front gaurd [hit by kangaroo]				02/07/2024	277485	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
					277488ks												
					Front right guard torn and split badly damaged												
1067	Wodonga - Workshop	VehService\AS	VehService\AS	VehService\AS	Front left auard has a tear		02/07/2024	277484	Service	Completed	Greenfreight Loxeine Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	VehService\AS	SERVICE.				02/07/2024	277484	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Elect\INDICATORS	RH INDICATOR ON BONNET SIDE NOT WORKING.				02/07/2024	277484	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	DrCabElect\SCALES	SCALES FAULTY.				02/07/2024	324372	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	VehService\AS	SERVICE.				02/07/2024	324372	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Susp\WHEEL ALIGN	REPAIR/ AUGN - RADAR.				02/07/2024	324372	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Body\FUEL TANK	ADBLUE LEAK.				02/07/2024	324372	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Brakes\ABS	TRACTION CONTROL/ESC LIGHT COMING ON & STAYING ON OCCASIONALLY.				02/07/2024	324372	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	DrCabElect\SCALES	CHECK TRUCK SCALES FOR LOOSE WIRING. (NOT READING CORRECT)				02/07

1067	Wodonga - Workshop	DrivCabRep\WIPERS	LH WIPER NEEDS ADJUSTMENT.				03/05/2024	226487	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Unknown	A SERVICE.				03/05/2024	226487	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				03/05/2024	226487	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	DrivCabRep\ST Weel	Check Steering Column Cab Loose Joint When Tilted				03/05/2024	226487	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Body	Straighten/Turn L/H Exaust Stack				03/05/2024	226487	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Elect\DRV LIGHT	RH DRIVING LIGHT NOT WORKING.				03/05/2024	226487	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	VehService\AS	Carry out A Service as per job card for T909 X15	VehService\AS			03/05/2024	226487	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Engine\ADBLUE	AFTER TREAT LIGHT ON (2 DAYS) BLOCK.		CHECKED CODES. DOSER PUMP BLOCKAGE. DIAGNOSED AND CLEANED BLOCKED INJECTOR. FLUSHED LINES. FLOW TESTED. OK. CLEARED CODES. CLEANED UP.		01/05/2024	222494	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Albury - Workshop	Tyres\TP7-R	Tyre Position 7 + 8				26/04/2024	233050	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER
1067	Albury - Workshop	Tyres\TP9+10	Tyre Position 9 + 10				26/04/2024	233050	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER
1067	Wodonga - Workshop	DrivCabRep\ST Weel	Check Steering Column Cab Loose Joint When Tilted				20/04/2024	214414	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				20/04/2024	214414	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Brakes\BRK RELINE	RELINE REAR AXLE.				20/04/2024	214414	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	DrivCabElect\ELECT P&W	REPLACE TURBO TIMER. ORDERED.				20/04/2024	214414	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Engine\ELECT P&W	REMOVE EXTENDED IDLE SHUTDOWN.				20/04/2024	214414	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	DrivCabElect\INST/GAUGE	Trailer ABS light on dash				20/04/2024	214414	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Body	Straighten/Turn L/H Exaust Stack				20/04/2024	214414	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Elect\DRV LIGHT	RH DRIVING LIGHT NOT WORKING.				20/04/2024	214414	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Elect\DAY LIGHTS	RH DAY LIGHT BROKEN.				20/04/2024	214414	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	DrivLine					20/04/2024	214414	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	DrivLine\DRV LN SER	POWER DIVIDER CLUNKING BADLY AND AFTER DISENGAGING GIVES LOUD CLUNK GOING DOWN ROAD.				20/04/2024	214414	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Engine\BOOST HOSE	TURBO POWER HAS DROPPED FROM 300KPA TO 180KPA.				20/04/2024	214414	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Unknown	A SERVICE.				20/04/2024	214414	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	VehService\AS	Carry out A Service as per job card for T909 X15	VehService\AS			20/04/2024	214414	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	DrivCabElect\ELECT P&W	REPLACE TURBO TIMER.		DIAGNOSED FAULTY TIMER. ORDERED.		18/04/2024	213331	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Engine\ADBLUE	AFTER TREAT LIGHT STAYS ON.		FLUSHED ADBLUE LINES, INJECTOR AND DOSER PUMP. FLOW TESTED. OK.		17/04/2024	211304	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Myrtleford - Workshop	DrivLine\CLUTCH	ADJUST CLUTCH.				09/04/2024	204409	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Myrtleford Workshop	P/MOVER
1067	Albury - Workshop	Engine\ADBLUE	After Treatment Light On				09/04/2024	164502	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER
1067	Wodonga - Workshop	DrivCabRep\ST Weel	Check Steering Column Cab Loose Joint When Tilted				06/04/2024		Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Body	Straighten/Turn L/H Exaust Stack				06/04/2024		Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Unknown	Service				06/04/2024		Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				06/04/2024	203810	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Comp\Truck Safe	FIT TRUCKSAFE STICKER.				06/04/2024	203810	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Engine\ELECT P&W	REMOVE EXTENDED IDLE SHUTDOWN.				06/04/2024	203810	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	DrivLine\CLUTCH	Clutch brake needs adjusting				06/04/2024	203810	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Elect\DRV LIGHT	Right hand driving light needs replacing				06/04/2024	203810	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Body\AIR LEAK	Air leak bad dumping all air				06/04/2024	203810	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	DrivCabElect\INST/GAUGE	Trailer ABS light on dash				06/04/2024	203810	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Chassis\AIR LEAK	CHECK FOR AIR LEAK. CANNOT BUILD UP AIR.				06/04/2024	203810	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Elect\DRV LIGHT	REPLACE RH DRIVING LIGHT. (BROKEN MOUNT)				06/04/2024	203810	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Unknown	A SERVICE.				06/04/2024	203810	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Brakes\BRK RELINE	RELINE REAR AXLE.				06/04/2024	203810	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
			STILL TO COMPLETE FROM C SERVICE:														
			STEER WHEEL BEARINGS														
1067	Wodonga - Workshop	Unknown	SUSPENSION CHECK- U-BOLT TORQUE.				06/04/2024	203810	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	DrivLine\DIFF OIL	Replace Diff oils	DrivLine\DIFF OIL			06/04/2024	203810	PreventativeMaintenance	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	VehService\C5	Service As Per Attached Checklist	VehService\C5			06/04/2024	203810	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	DrivCabElect\INST/GAUGE	Air pressure gauges reading 1000 KPI				03/04/2024		Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Body\EXHAUST	L/H exhaust loose				03/04/2024		Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Body\EXHAUST	STRAIGHTENED EXHAUST STACK.				29/03/2024		Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Engine\GOV VALVE	REPLACED GOVERNOR VALVE.				29/03/2024		Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				26/03/2024	196840	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Engine\ELECT P&W	REMOVE EXTENDED IDLE SHUTDOWN.				26/03/2024	196840	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	DrivLine\CLUTCH	Clutch brake needs adjusting				26/03/2024	196840	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Brakes\ABS	trailer ABS fault				26/03/2024	196840	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Comp\Truck Safe	FIT TRUCKSAFE STICKER.				26/03/2024	196840	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	VehService\AS	Carry out A Service as per job card for T909 X15	VehService\AS			26/03/2024	196840	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Comp\Truck Safe	NHVR and Truck safe stickers missing				23/03/2024		Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Comp\Truck Safe	FIT TRUCKSAFE.				23/03/2024		Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Comp\Truck Safe	FIT TRUCKSAFE STICKER.				23/03/2024		Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Body\PANELS	REPAIR DAMAGE TO BONNET.				23/03/2024		Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Brakes\ABS	TRAILER ABS FAULT.				23/03/2024		Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Brakes\ABS	TRAILER ABS FAULT.				23/03/2024		Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Engine\ELECT P&W	REMOVE EXTENDED IDLE SHUTDOWN.				23/03/2024		Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
			Trailer ABS light still on dash														
1067	Wodonga - Workshop	Brakes\ABS	please cancel cozies				23/03/2024		Fault	Completed	Greenfreight Loxeine Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Hydraulics\OIL/FILTER	REFILL HYDRAULIC OIL.				23/03/2024		Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				15/03/2024	187730	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	DrivLine\CLUTCH	Clutch brake needs adjusting				15/03/2024	187730	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Brakes\ABS	TRAILER ABS FAULT.				15/03/2024	187730	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Brakes\ABS	trailer ABS fault				15/03/2024	187730	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Engine\EXHAUST	replace L/H exhaust stack				15/03/2024	187730	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Brakes\ABS	TRAILER ABS FAULT.				15/03/2024	187730	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
			Trailer ABS light still on dash														
1067	Wodonga - Workshop	Brakes\ABS	please cancel copies				15/03/2024	187730	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	VehService\AS	Carry out A Service as per job card for T909 X15	VehService\AS			15/03/2024	187730	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Albury - Workshop	Tyres\TP7-R	Tyre Position 7 + 8				14/03/2024		Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER
1067	Albury - Workshop	Tyres\TP9+10	Tyre Position 9 + 10				14/03/2024		Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER
1067	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				08/03/2024	181765	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Brakes\ABS	TRAILER ABS FAULT.				08/03/2024	181765	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Engine\ADBLUE	AFTER TREAT FAULT.				08/03/2024	181765	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Engine\ELECT P&W	REMOVE EXTENDED IDLE SHUTDOWN.				08/03/2024	181765	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Body\PANELS	LIFT QUARTER GUARD BACK INTO PLACE L.H. SIDE ROO DAMAGED.				08/03/2024	181765	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Body\FUEL TANK	RUBBER SEAL IN FUEL CAPS NEED REPLACING.				08/03/2024	181765	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
			Trailer ABS light still on dash														
1067	Wodonga - Workshop	Brakes\ABS	please cancel cozies				08/03/2024	181765	Repair	Completed	Greenfreight Loxeine Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	DrivCabRep\WIPERS	replace wiper blades				08/03/2024	181765	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Body\DAMAGE	replaced L/H stack				08/03/2024	181765	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	VehService	service				08/03/2024	181765	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Unknown	SERVICE.				08/03/2024	181765	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Comp\Truck Safe	FIT TRUCKSAFE STICKER.				08/03/2024	181765	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS			08/03/2024	181765	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Unknown	A SERVICE.				08/03/2024	181765	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Albury - Workshop	Tyres\TP1+2	Tyre Position 1 + 2				02/03/2024		Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER
1067	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				28/02/2024	178212	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	VehService\AS	Carry out A Service as per job card for T909 X15	VehService\AS			28/02/2024	178212	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Brakes\ABS	trailer ABS fault				24/02/2024		Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
					checked valve on air tank												
					cleaned filter into valves												
1067	Wodonga - Workshop	CTI\CTI Drive	CTI fault wont inflate / deflate		replaced leakne fittins		24/02/2024		Fault	Completed	Greenfreight Loxeine Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Engine\EXHAUST	replace L/H exhaust stack				24/02/2024		Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				23/02/2024	168982	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Brakes\ABS	TRAILER ABS FAULT.				23/02/2024	168982	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	VehService\AS	Carry out A Service as per job card for T909 X15	VehService\AS			23/02/2024	168982	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				16/02/2024	163115	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Comp\Truck Safe	FIT TRUCKSAFE.				16/02/2024	163115	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Air Con\AIR CON	air conditioner freezing up - Water under left mat when defrosted		REPLACED CAB FILTER.		16/02/2024	163115	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Air Con\AIR CON	air con not working				16/02/2024	163115	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	DrivLine\CLUTCH	Clutch brake needs adjusting				16/02/2024	163115	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Engine\ADBLUE	AFTER TREAT FAULT.				16/02/2024	163115	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Body\FUEL TANK	SEALS FOR FUEL CAPS.				16/02/2024	163115	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	VehService\AS	Carry out A Service as per job card for T909 X15	VehService\AS			16/02/2024	163115	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Engine\ADBLUE	After Treat Fault		removed doser pump hoses & cleared out blocked hoses & re-asemble		10/02/2024	159403	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				08/02/2024	156340	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Comp\Truck Safe	FIT TRUCKSAFE STICKER.				08/02/2024	156340	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Comp\Truck Safe	NHVR and Truck safe stickers missing				08/02/2024	156340	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Comp\Truck Safe	FIT NHVAS AND TRUCKSAFE STICKERS.				08/02/2024	156340	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Comp\Truck Safe	FIT TRUCKSAFE STICKER.				08/02/2024	156340	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Engine\ELECT P&W	REMOVE EXTENDED IDLE SHUTDOWN.				08/02/2024	156340	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Air Con\AIR CON	AIR CONDITIONER FREEZING UP.				08/02/2024	156340	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Body\PANELS	REPAIR DAMAGE TO BONNET.				08/02/2024	156340	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	DrivLine\CLUTCH	CLUTCH FREE PLAY NEEDS ADJUSTING (TOO MUCH)				08/02/2024	156340	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS			08/02/2024	156340	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				31/01/2024	148563	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Body\PANELS	REPAIR DAMAGE TO RH SL GUARD.		ADJUSTED SL GUARD.		31/01/2024	148563	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	VehService\AS	Carry out A Service as per job card for T909 X15	VehService\AS	TIGHTENED PITMAN ARM.		31/01/2024	148563	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	DrivLine\CLUTCH	CLUTCH FREE PLAY (ADJUST) TOO MUCH.		ADJUSTED CLUTCH.		30/01/2024		Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	CTI\CTI Elect	CTI PLAYING UP. CANNOT OPERATE DEFLATE OR INFLATE, KEEP (SAYING AIR LEAK/ NO AIR)		REPLACED CTI SUPPLY VALVE.		30/01/2024	146059	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				20/01/2024	141308	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	VehService	Due for A svc				20/01/2024	141308	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	DrivLine\CLUTCH	Clutch brake needs adjusting				20/01/2024	141308	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Air Con\AIR CON	air conditioner freezing up - Water under left mat when defrosted				20/01/2024	141308	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Air Con\AIR CON	air con not working				20/01/2024	141308	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER
1067	Wodonga - Workshop	Comp\Truck Safe	FIT TRUCKSAFE.				20/01/2024	141308	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga

1067	Wodonga - Workshop	Tyres\TP3+4	replace tyres				01/12/2023	106997	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	Tyres\TP5+6	Replace tyres				01/12/2023	106997	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	Tyres\TP7+8	replace tyres				01/12/2023	106997	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	Tyres\TP9+10	replace tyres				01/12/2023	106997	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				24/11/2023	101740	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Albury - Workshop	Comp\Truck Safe	FIT TRUCKSAFE STICKER.				24/11/2023	101740	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Albury - Workshop	Comp\Truck Safe	NHVR and Truck safe stickers missing				24/11/2023	101740	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Albury - Workshop	Comp\Truck Safe	FIT NHVAS AND TRUCKSAFE STICKERS.				24/11/2023	101740	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Albury - Workshop	DrivLine\OIL LEAK	TRANS OIL LEAK.				24/11/2023	101740	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Albury - Workshop	DrCabElect\RADIO	2 Way Speakers Are Very Cheap Rubbish Need Replacement Can't Even Hear ! Find Better At A 2 Dollar Shop				24/11/2023	101740	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Albury - Workshop	Unknown	B SERVICE				24/11/2023	101740	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Albury - Workshop	Unknown	A SERVICE. Service As Per Attached Checklist (TCTC)				24/11/2023	101740	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Albury - Workshop	VehService\CS	Purchase Order Number: T082488-1	VehService\CS			24/11/2023	101740	Service	Completed	Greenfreight Loxeine Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				11/11/2023	92576	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Albury - Workshop	DrivLine\GEARBOX	OIL LEAK AT REAR COVER ON GEARBOX.				11/11/2023	92576	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Albury - Workshop	VehService\B5	Service As Per Attached Checklist	VehService\B5			11/11/2023	92576	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Albury - Workshop	Unknown	A SERVICE.				11/11/2023	92576	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				31/10/2023	85183	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	Engine\FAULT CODE	CHECK/RESET CHECK ENGINE CODES.				31/10/2023	85183	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	DrivLine\GEARBOX	OIL LEAK AT REAR COVER ON GEARBOX.				31/10/2023	85183	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS			31/10/2023	85183	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	Elect\ALT	REPLACE ALTERNATOR.				18/10/2023		Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	Engine\FAULT CODE	CHECK/RESET CHECK ENGINE CODES.				18/10/2023		Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	Unknown	SERVICE.				18/10/2023		Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				18/10/2023	75141	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	Comp\Truck Safe	FIT TRUCKSAFE STICKER.				18/10/2023	75141	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	VehService\B1 Svc	Service As Per Attached Checklist		REPLACED ALTERNATOR. UNHOOKED. GREASED TURNTABLE.		18/10/2023	75141	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	Comp\Truck Safe	NHVR and Truck safe stickers missing				18/10/2023	75141	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	DrCabElect\INST/GAUGE	ALTERNATER LIGHT INTERMITTENT FAULT.		REPLACED ALTERNATOR.		18/10/2023	75141	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	Elect\ALT	ALTERNATOR FAULT- LIGHT FLASHING ON.		REPLACED ALTERNATOR.		18/10/2023	75141	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	Elect\ALT	ALT LIGHT COMES ON & STAYS ON CRUISING DOWN H/WAY AND WORKING HARD.		REPLACED ALTERNATOR.		18/10/2023	75141	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	Comp\Truck Safe	FIT NHVAS AND TRUCKSAFE STICKERS.				18/10/2023	75141	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Albury - Workshop	Tyres\Punct	7				11/10/2023		Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER	
1067	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				11/10/2023	71055	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	Comp\Truck Safe	FIT TRUCKSAFE STICKER.				11/10/2023	71055	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	Comp\Truck Safe	NHVR and Truck safe stickers missing				11/10/2023	71055	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	DrCabElect\EJECT P&W	LIFT AXLE OVER-RIDE SWITCH NOT WORKING.				11/10/2023	71055	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	DrCabElect\INST/GAUGE	ALTERNATER LIGHT INTERMITTENT FAULT.				11/10/2023	71055	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	DrCabElect\EJECT P&W	LIFT AXLE OVER-RIDE NOT WORKING.				11/10/2023	71055	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	CTI\CTI Elect	CTI FAULTY. NOT FILLING OR DUMPING.		TCTC		11/10/2023	71055	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	Elect\ALT	ALTERNATOR FAULT- LIGHT FLASHING ON.				11/10/2023	71055	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	Elect\ALT	ALT LIGHT COMES ON & STAYS ON CRUISING DOWN H/WAY AND WORKING HARD.				11/10/2023	71055	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	DrCabRep\WINDSCREEN	WINDSCREEN LEAKS WATER LH SIDE UNDER CAMERAS. TOP.		ALBURY AUTO SCREEN		11/10/2023	71055	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	DrCabRep\HOUSEKEEP	NEED NEW R&R BOOK.				11/10/2023	71055	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	Unknown	A SERVICE.				11/10/2023	71055	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS			11/10/2023	71055	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				03/10/2023	65136	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	Comp\Truck Safe	NHVR and Truck safe stickers missing				03/10/2023	65136	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	DrCabRep\WINDSCREEN	LH WINDSCREEN LEAKS. TOP RIGHT.		TCTC.		03/10/2023	65136	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	Brakes\EBS FAULTS	TRAILER ABS FAULT				03/10/2023	65136	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS			03/10/2023	65136	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	Brakes\EBS FAULTS	TRAILER ABS FAULT.				03/10/2023	65136	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	Brakes\EBS FAULTS	TRAILER ABS FAULT.				03/10/2023	65136	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				26/09/2023	59030	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	Comp\Truck Safe	FIT TRUCKSAFE STICKER.				26/09/2023	59030	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	Brakes\EBS FAULTS	TRAILER ABS FAULT.				26/09/2023	59030	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	DrCabElect\EJECT P&W	LIFT AXLE OVER-RIDE SWITCH NOT WORKING.				26/09/2023	59030	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	DrCabElect\INST/GAUGE	ALTERNATER LIGHT INTERMITTENT FAULT.				26/09/2023	59030	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	Brakes\EBS FAULTS	TRAILER ABS FAULT.				26/09/2023	59030	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	DrCabElect\EJECT P&W	LIFT AXLE OVER-RIDE NOT WORKING.				26/09/2023	59030	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS			26/09/2023	59030	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				19/09/2023	55091	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	Brakes\EBS FAULTS	TRAILER ABS FAULT.				19/09/2023	55091	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	DrCabElect\EJECT P&W	LIFT AXLE OVER-RIDE SWITCH NOT WORKING.				19/09/2023	55091	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS			19/09/2023	55091	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	Brakes\AIR FITTIN	REPAIR RED BRAKE SUPPLY TO TRAILER- TEMPORARY JOINER.				19/09/2023	55091	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	DrCabElect\INST/GAUGE	ALTERNATER LIGHT INTERMITTENT FAULT.				19/09/2023	55091	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	Brakes\EBS FAULTS	TRAILER ABS FAULT.				19/09/2023	55091	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	DrCabElect\EJECT P&W	LIFT AXLE OVER-RIDE NOT WORKING.				19/09/2023	55091	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	Comp\Truck Safe	FIT TRUCKSAFE STICKER.				19/09/2023	55091	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	Unknown	SERVICE				19/09/2023	55091	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Albury - Workshop	Tyres\TP1+2	Tyre Position 1 + 2				16/09/2023		Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER	
1067	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				12/09/2023	50347	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Albury - Workshop	Brakes\EBS FAULTS	TRAILER ABS FAULT		Not completed		12/09/2023	50347	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Albury - Workshop	DrCabElect\EJECT P&W	LIFT AXLE SWITCH NOT WORKING. Service As Per Attached Checklist (TCTC)		worked as required at time of inspectiopn		12/09/2023	50347	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Albury - Workshop	VehService\B5	Purchase Order Number: T080950	VehService\B5			12/09/2023	50347	Service	Completed	Greenfreight Loxeine Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Albury - Workshop	Unknown	SERVICE.		completed		12/09/2023	50347	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	VehService\B1 Svc	Service As Per Attached Checklist				06/09/2023	46039	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				06/09/2023	46039	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Albury - Workshop	Brakes\EBS FAULTS	TRAILER ABS FAULT.				05/09/2023	27748S	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Albury - Workshop	Unknown	SERVICE.				05/09/2023	27748S	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Albury - Workshop	Brakes\EBS FAULTS	TRAILER ABS FAULT.				05/09/2023	27748S	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Albury - Workshop	DrCabElect\EJECT P&W	LIFT AXLE OVER-RIDE SWITCH NOT WORKING AS PER R&R 129140.				05/09/2023	27748S	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Albury - Workshop	Brakes	TRAILER ABS LIGHT ON.				05/09/2023	27748S	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Albury - Workshop	Engine\ADBLUE	Aflter treat fault				05/09/2023	27748S	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Albury - Workshop	Brakes\EBS FAULTS	Trailer ABS Faults.				05/09/2023	27748S	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	DrCabElect\INST/GAUGE	Alternator light comes on dash.				01/09/2023	41771	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				30/08/2023	39735	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	VehService\AS	Carry out A Service as per job card for T909 X15	VehService\AS			30/08/2023	39735	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				19/08/2023	33395	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	VehService\AS	Carry out A Service as per job card for T909 X15	VehService\AS			19/08/2023	33395	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	DrCabRep\DOOR LOCK	ADJUST DRIVER DOOR. TOP FRONT.				11/08/2023	27748S	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	DrCabRep\DOOR LOCK	ADJUST DRIVER DOOR.- EXCESSIVE AIR THROUGH TOP FRONT CORNER & WORSE THAN PREVIOUS R & R.				11/08/2023	27748S	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				08/08/2023	24543	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	DrCabRep\DOOR LOCK	ADJUST DRIVER DOOR.		adjusted Driver to monitor		08/08/2023	24543	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	DrCabRep\WINDSCREEN	LH WINDSCREEN LEAKS. TOP RIGHT.				08/08/2023	24543	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	VehService\AS	Carry out A Service as per job card for T909 X15	VehService\AS			08/08/2023	24543	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	Comp\Truck Safe	NHVR and Truck safe stickers missing				08/08/2023	24543	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	Unknown	SERVICE.				08/08/2023	24543	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				02/08/2023	21257	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	Body\OH&S	REPLACE FIRE EXTINGUISHER WITH CORRECT SERVICED ONE IN WORKSHOP OFFICE.				02/08/2023	21257	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	DrCabRep\DOOR LOCK	ADJUST DRIVER DOOR.				02/08/2023	21257	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	DrCabRep\WINDSCREEN	LH WINDSCREEN LEAKS. TOP RIGHT.				02/08/2023	21257	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	Chassis\WINCH/STRP	REPLACE QUICK RELEASE CABLE.				02/08/2023	21257	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	Chassis\STRAPS	REPLACE HOLD DOWN DOG & STRAIGHTEN- BRACKET.				02/08/2023	21257	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	Unknown	SERVICE.				02/08/2023	21257	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	VehService\AS	Carry out A Service as per job card for T909 X15	VehService\AS			02/08/2023	21257	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	Unknown	SERVICE.				02/08/2023	21257	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	Body\OH&S	REPLACE FIRE EXTINGUISHER WITH CORRECT SERVICED ONE IN WORKSHOP OFFICE.				26/07/2023		Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER	
1067	Albury - Workshop	Tyres\TP3+4	Tyre Position 3 + 4				26/07/2023		Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER	
1067	Albury - Workshop	Tyres\TP5+6	Tyre Position 5 + 6				26/07/2023		Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER	
1067	Albury - Workshop	Tyres\TP7+8	Tyre Position 7 + 8				26/07/2023		Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER	
1067	Albury - Workshop	Tyres\TP9+10	Tyre Position 9 + 10				26/07/2023		Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Albury Workshop	P/MOVER	
1067	Wodonga - Workshop	VehService\AS	A Service	VehService\AS			25/07/2023	16721	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	Chassis\FIRE EXTIN	REPLACE FIRE EXTINGUISHER IN TOOLBOX.		NO FAULT		18/07/2023	11146	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	DrCabElect\DOOR LOCK	ADJUST DRIVER DOOR- TOP FRONT CORNER- LEAKING AIR/ WATER.		NO FAULT		18/07/2023	11146	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	Brakes\ABS	TRAILER ABS LIGHT ON DASH.		NO FAULT		18/07/2023	11146	Fault	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	Brakes\BRAKE ADJ	Check, Adjust & Record Brake %				18/07/2023	11146	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	VehService\CS	Carry Out First Service (TCTC) Purchase Order Number: WWO79582 (Parts Only) HOOKED UP T547/548.	VehService\CS			18/07/2023	11146	Service	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	Workshop\MOVE ASSET	REARRANGED HOSING TO SUIT TRAILERS.				07/07/2023		Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	
1067	Wodonga - Workshop	Insp\Truck Pre	truck pre delivery as per check list				29/06/2023	667	Repair	Completed	Greenfreight Logging Vic	KWX15LOG	Colac	GTK	XW79CD	Wodonga Workshop	P/MOVER	