EquipmentName	Workshop	CodeAndSubCode	Description	Schedule	CompletionComments	DateDone	DistanceDone	Worktype	Workstate	EquipmentOwner	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
1075	Wodonga - Workshop	VehService\AS	VehService\AS A Service	VehService\AS		21/07/2026	488090	Service	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER
1075	Wodonga - Workshop	Engine\WATER PUMP	COOLANT LEAK FRONT OF ENGINE			21/07/2026	488090	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER
1075	Wodonga - Workshop	Steering\WHEEL ALGN	Vibration in steering wheel.			21/07/2026	488090	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER
1075	Wodonga - Workshop	Steering\WHEEL ALGN	Steering is wondering, very hard to keep straight.			21/07/2026	488090	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER
1075	Wodonga - Workshop	Engine\OIL LEAK	rhf hub seal and engine oil leaks			21/07/2026	488090	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER
					Checkout found abs leed shredded replace with one driver had in truck, checlon lights found not in											
					correct pins trace found leed damaged and wiring ripped out of plugs, replace check and found wired												
1075	Wodonga - Workshop	Elect\SUZI COIL	Elect\SUZI LEAD		to different code connect us check all ok.	06/07/2026	475786	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	MARULAN TRUCK & BUS PTY LTD	P/MOVER
1075	Wodonga - Workshop	DrCabElect\DOOR ALARM	inspect hob switch		completed by AR	18/06/2026	466206	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER
1075	Wodonga - Workshop	Tyres\ROTATION	Tyres\ROTATION 1-2		REBALANCE	17/06/2026	466231	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	BORDER BANDAG PTY LTD	P/MOVER
1075	Wodonga - Workshop	Tyres\TP7+8	Tyres\TP7+8			12/06/2026	466714	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	BORDER BANDAG PTY LTD	P/MOVER
					REMOVE TYRES DAMAGED AND PUT ONTO SOLD TRAILER											
1075	Wodonga - Workshop	Tyres\TP5+6	Tyres\TP5+6		POSSIBEL CLAIM?	12/06/2026	466714	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	BORDER BANDAG PTY LTD	P/MOVER
					Labour- Mobile											
					Traveled to Redbank											
					Mounted and wired reverse squawker											
1075	Wodonga - Workshop	Elect\ELECT P&W	Elect\ELECT P&W		Checked operation- All ok	09/06/2026	459636	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	WARREGO TRANSPORT REPAIRS	P/MOVER
1075	Wodonga - Workshop	Prevent\TRANS OIL	Prevent\TRANS OIL Synthetic gearbox oil change	Prevent\TRANS OIL		07/05/2026	442999	PreventativeMaintenance	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER
1075	Wodonga - Workshop	DrivLine\DIFF OIL	DrivLine\DIFF OIL Replace Diff oils	DrivLine\DIFF OIL		07/05/2026	442999	PreventativeMaintenance	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER
1075	Wodonga - Workshop	DrCabElect\INST/GAUGE	check engine light and stop light on			07/05/2026	442999	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER
1075	Wodonga - Workshop	DrivLine	Middle left hub seal weeping			07/05/2026	442999	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER
1075	Wodonga - Workshop	Insp\ANN INSP	Insp\ANN INSP To Complete R/W within 12 months	Insp\ANN INSP	completed by JS SMs TP	07/05/2026	442999	PreventativeMaintenance	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER
1075	Wodonga - Workshop	VehService\CS	VehService\CS C Service	VehService\CS	completed by JS SMs TP	07/05/2026	442999	Service	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER
1075	Wodonga - Workshop	Engine	Exhaust leak cylinders 1 4 and 6		Checked by tim peachy and diagnozed to be okay.	06/05/2026	442999	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER
1075	Wodonga - Workshop	Tyres\TP1+2	Tyres\TP1+2		LOW	29/04/2026	441901	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	BORDER BANDAG PTY LTD	P/MOVER
1075	Wodonga - Workshop	Tyres\TP9+10	Tyres\TP9+10		LOW	29/04/2026	441901	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	BORDER BANDAG PTY LTD	P/MOVER
1075	Wodonga - Workshop	Tyres\TP11+12	Tyres\TP11+12		LOW	29/04/2026	441901	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	BORDER BANDAG PTY LTD	P/MOVER
1075	Wodonga - Workshop	Elect\ALT	BROWN & HURLEY YATALA-BREAKDOWN. DIAGNOSE AND REPAIR ALTERNATOR LIGHT ON. CHECK FOR WARRANTY AVAILABILITY.			29/04/2026	441482	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	PACCAR PARTS FLEET SERVICES	P/MOVER
					Travel to vehicle at Hume and diagnose faulty alternator.											
					Collect new alternator from Canberra Trucks.											
1075	Wodonga - Workshop	Engine\ALT	Engine\ALT		Fit alternator. check charge rate and found 14.21 volts.	28/04/2026	441482	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	AMEYS MECHANICAL REPAIRS	P/MOVER
			Body\WINDSCREEN RHS													
1075	Wodonga - Workshop	Body\WINDSCREEN	WW098881		completed by JS SMs TP	14/03/2026	412966	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	AUTOTEX AUSTRALIA	P/MOVER
			Engine\BREAKDOWN - TANK AIR FITTING BROKEN.													
			TRAVEL TO WORKSHOP & OPEN.													
			LOAD PARTS & TOOLS IN UTE & TRAVEL TO UNIT.													
			REMOVE BROKEN THREAD FROM TANK.													
			FIT NEW FITTING AS REQUIRED.													
			START & RUN - OK.													
1075	Wodonga - Workshop	Engine\BREAKDOWN	COMPLETE PAPERWORK & TRAVEL HOME.			11/03/2026	441482	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	TATIARA TRUCK & TRAILER REPAIRS	P/MOVER
			Replace Clutch (408325 Kims)													
			(TCTC P/O:													
1075	Wodonga - Workshop	DrivLine\CLUTCH				07/03/2026	441482	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	TWIN CITY TRUCK CENTRE	P/MOVER
1075	Wodonga - Workshop	Tyres\TP02	Tyres\TP02 (22)		CALL OUT	03/03/2026	408363	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	BORDER BANDAG PTY LTD	P/MOVER
			A Service													
			Serviced @ 408,316 Klms													
1075	Wodonga - Workshop	VehService\AS	VehService\AS	VehService\AS	Reolace hvatertas	02/03/2026	408316	Service	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER
1075	Wodonga - Workshop	Tyres\TP5+6	Tyres\TP5+6		LOW	27/02/2026	408363	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	BORDER BANDAG PTY LTD	P/MOVER
1075	Wodonga - Workshop	Tyres\PRES CHECK	check tyres			10/02/2026	395986	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER
1075	Wodonga - Workshop	Body\WINDSCREEN	replace window cracked right side		new one fitted auto screen	10/02/2026	395986	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER
1075	Wodonga - Workshop	Body\WIPERS	new window wipers			10/02/2026	395986	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER
1075	Wodonga - Workshop	DrivLine\DIFF OIL	DrivLine\DIFF OIL Replace Diff oils	DrivLine\DIFF OIL		10/02/2026	395986	PreventativeMaintenance	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER
1075	Wodonga - Workshop	VehService\BS	VehService\BS B Service	VehService\BS		10/02/2026	395986	Service	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER
1075	Wodonga - Workshop	VehService\AS	service due			10/02/2026	395986	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER
					Travel to breakdown at Coke a Cola Moorabbin as requested,											
					Inspected truck not starting,											
					Found to have starter failed, pick up new starter on way to job,											
					Disconnect batteries, removed all wiring and removed starter from truck as required, fitted and secured new starter motor,											
					connect and secured all wiring, connect batteries and start all o/k,											
1075	Wodonga - Workshop	Engine\START MOTR	Engine\START MOTR		Clean worksite and travel back to workshop	06/02/2026	407552	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	ELITE DIESEL REPAIRS	P/MOVER
					Travelled to site											
					Located and inspected unit											
					Charged up vehicle's batteries- unable to charge past											
					12.1v.											
					Disconnect batteries and inspected											
					Found dropped cells											
					Organised and collected replacement batteries											
					Fitted to vehicle and cleaned											
					terminals											
1075	Wodonga - Workshop	Engine\BATTERY	Engine\BATTERY		Checked charge rate (13.1v)	06/02/2026	395986	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	WARREGO TRANSPORT REPAIRS	P/MOVER
					grounded for pinion seal leak											
1075	Wodonga - Workshop	DrivLine\OIL LEAK	DrivLine\OIL LEAK		nesairs carried out at tctc under warrantv	24/12/2025	371555	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER
1075	Wodonga - Workshop	DrCabRep\ST Weel	Steering Wheel Won't Adjust		After Hours Call Out Blokes Repair & Maintenance	23/12/2025	372201	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER
			Compressor Failed Broken Reid Valve (Reef Hills Parking Bay South Bay)													
1075	Wodonga - Workshop	Engine\COMPRESSOR	(TCTC Repaired Under Warrantv			27/11/2025	441482	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	HARO TRUCK & TRAILER	P/MOVER
			Truck Won't Build Up Air Past 4 Bar (Reef Hills Parking Bay South Bay)													
1075	Wodonga - Workshop	Chassis\AIR LEAK	(Hare's Truck &Trailer P/O: WW0990283			27/11/2025	441482	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	HARO TRUCK & TRAILER	P/MOVER
1075	Wodonga - Workshop	Elect\BATTERY	JUMP START. PUT ON CHARGER.			19/11/2025	352843	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER
			A Service													
			Serviced @ 352,652 Klms													
1075	Wodonga - Workshop	VehService\AS		VehService\AS		15/11/2025	382511	Service	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER
1075	Wodonga - Workshop	VehService\AS	VehService\AS A Service	VehService\AS		23/10/2025	344750	Service	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER
			REMOVED AND REALIGNED STEERING WHEEL.													
1075	Wodonga - Workshop	DrCabRep\ST Weel	CLEANED UP.			19/10/2025	335399	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER
1075	Wodonga - Workshop	DrCabRep\ST Weel	STEERING WHEEL ON THE PISS. WHEEL ALIGNMENT.			02/10/2025	335384	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER
1075	Wodonga - Workshop	Elect\BATTERY	JUMP STARTED. MOVED TO WORKSHOP. PUT ON CHARGER.			02/10/2025	335384	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER
					CALLED OUT TO ATTEND TRUCK AFTER HOURS AT 6.00 PM CUSTOMER INFORMS AIR BAG LINE ON L/H SIDE HAS											
					RUBBED THROUGH AND LEAKING EXCESSIVELY											
					$600.00											
					-											
					MET TRUCK AT TCTC WORKSHOP. REMOVED CHASSIS WALKWAY TO ASSIST REPAIRS, INSPECT FOR LEAKS, FOUND											
					AIR BAG LINE ON L/H/S BETWEEN L/H SIDE FRONT AIR BAG & 2ND FROM L/H SIDE REAR, HAS RUBBED THROUGH AND											
					LEAKING. REMOVE AIR BAG LINE, P CLAMPS, CABLE TIES, REMOVE AIR BAG LINE FROM AIR BAG END. SUS GUAGE											
					LINE & HEIGHT CONTROL VALVE LINE. REMOVE AIR BAG LINE & INSTALL NEW AIR LINE. TENSION AIR LINE ON AIRBAG											
					END. SWAP AIR SUPPLY LINE AND SUSPENSION AIR GUAGE REQUIRED, REFIT P CLAMPS, SECURE USING CABLE TIES.											
1075	Wodonga - Workshop	Susp\AIR BAG	Susp\AIR BAG		START TRUCK, BUILD UP AIR, CHECK OVER, ALL GOOD. PACK UP AND GO HOME	29/09/2025	360102	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	TWIN CITY TRUCK CENTRE - OLD	P/MOVER
					-went flat at twin city											
					-batteries tested and loaded, in ok condition											
					-vehicle charging as intended											
1075	Wodonga - Workshop	Elect\BATTERY	Inspect and repair flat battery fault		-left over night for monitorine. will need to be checked in mornine of 09.07.25	29/09/2025	290980	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER
1075	Wodonga - Workshop	Tyres\TP7+8	Tyres\TP7+8			25/09/2025	335382	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	BORDER BANDAG PTY LTD	P/MOVER
1075	Wodonga - Workshop	VehService\AS	VehService\AS A Service	VehService\AS		23/09/2025	335382	Service	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER
			Repair Adblue Leak.													
1075	Wodonga - Workshop	Engine\ADBLUE	/Callaway Diesel P/O: WW096930			12/09/2025	360102	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	CALLAWAY DIESEL	P/MOVER
			Front Uni Has Slight Movement, Grease Starting To Push Out Of Caps.													
1075	Wodonga - Workshop	DrivLine\UNI JOINTS	(TCTC To Repair Under Warrantv) 320.288 Klms.			27/08/2025	386132	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	TWIN CITY TRUCK CENTRE - OLD	P/MOVER
1075	Wodonga - Workshop	VServlab	SERVICE A			26/08/2025	320287	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER
1075	Wodonga - Workshop	Tyres\FITMENT	2x R/H DRIVE TYRES			26/08/2025	320287	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER
1075	Wodonga - Workshop	Cooling\COOL LEAKS	COOLANT LEAKING			26/08/2025	320287	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER
1075	Wodonga - Workshop	Air Con\HEATER	HEATER STILL HASN'T BEEN FIXED. NOT WORKING ON FLOOR. KEEPS STOPPING.			26/08/2025	320287	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER
1075	Wodonga - Workshop	VehService\AS	VehService\AS A Service	VehService\AS		26/08/2025	320287	Service	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER
1075	Wodonga - Workshop	DrCabRep\HOUSEKEEP	NEED NEW BOOK. R&R.			26/08/2025	320287	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER
1075	Wodonga - Workshop	Chassis\SUZI COIL	Replace Suzi Coil Pole Spring Broken (Done)		Suzi Coil pole Spring Repained By Driver	19/08/2025	312483	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER
			B Service													
1075	Wodonga - Workshop	VehService\BS	Serviced @ 304035 Klms	VehService\BS		30/07/2025	304157	Service	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER
1075	Wodonga - Workshop	DrivLine\CTCH PACK	Clutch has no more adjustment			30/07/2025	304157	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER
1075	Wodonga - Workshop	Engine\CUMTUNEUP	Fuel has been turnt down. Now gets hotter. Not good for the motor. Every hill fan on even in cold			30/07/2025	304157	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER
1075	Wodonga - Workshop	Workshop\MOVE ASSET	Drop off to TCTC			10/07/2025	291079	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER
1075	Wodonga - Workshop	Workshop\MOVE ASSET	Pick up from TCTC			10/07/2025	291079	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER
1075	Wodonga - Workshop	Tyres\TP1+2	Tyres\TP1+2			09/07/2025	291016	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	BORDER BANDAG PTY LTD	P/MOVER
1075	Wodonga - Workshop	Chassis\FIFTH WHEE	Fit dog bones to turntable			27/06/2025	285069	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER
					Also inspected clutch adjustment - adjuster seized.											
1075	Wodonga - Workshop	VehService\AS	VehService\AS A Service	VehService\AS	Also fitted doe bones to turntable	27/06/2025	285069	Service	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER
1075	Wodonga - Workshop	Tyres\TP11+12	Tyres\TP11+12			11/06/2025	274010	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	BORDER BANDAG PTY LTD	P/MOVER
1075	Wodonga - Workshop	Tyres\TP10	Tyres\TP10			11/06/2025	274010	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	BORDER BANDAG PTY LTD	P/MOVER
			TRUCK TOO SLOW 98KM AT MOST.													
1075	Wodonga - Workshop	Engine\DERATE	/Cummins Wodonea P/O: WW094796)			07/06/2025	352652	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	CUMMINS SOUTH PACIFIC P/L	P/MOVER
			OIL PRESSURE GLOBE.													
			CRUISE LIGHT.													
1075	Wodonga - Workshop	DrCabElect\INST/GAUGE	ENGINE BRAKE LIGHT.		Comoleted durine service	06/06/2025	272528	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER
1075	Wodonga - Workshop	VehService\AS	VehService\AS A Service	VehService\AS		06/06/2025	272528	Service	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER
1075	Wodonga - Workshop	Tyres\FITMENT	ALL DRIVE TYRES NEED REPLACING, UNEVEN TREAD PATTERN & WORN ON INSIDE & OUTSIDE & SHAKING VIBRATING.		Drive tyres done by border bandag	06/06/2025	272528	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER
1075	Wodonga - Workshop	Susp\WGHT GAUGE	Scales out of calibration		Insepected scales. Calibrated. Insected truck ride heiaht and found out of spec. Adiusted ride heiaht at back of truck and recalibrated scales. Truck was ridine 10mm hieher in back of truck then front. Adiusted s	30/05/2025	267291	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER
1075	Wodonga - Workshop	Susp\WGHT GAUGE	WEIGHT GAUGE NOT CORRECT.		ADJUSTED WEIGHT ON TRUCK	29/05/2025	270930	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER
1075	Wodonga - Workshop	VehService\AS	VehService\AS A Service	VehService\AS		16/05/2025	258840	Service	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER
1075	Wodonga - Workshop	Chassis\FIFTH WHEE	Change turntable to high profile - Swap with 1026			14/05/2025	258693	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER
1075	Wodonga - Workshop	Susp\SHOCK ABS	LHM shock bushes - under warranty		Previously completed	01/05/2025	251746	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER
1075	Wodonga - Workshop	VehService\AS	VehService\AS A Service	VehService\AS		01/05/2025	251746	Service	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER
1075	Wodonga - Workshop	Body\PANELS	CHECKER PLATES BROKEN.		Repair spare deck plate and fuel tank plates, and instal	01/05/2025	251746	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER
			Susp\SHOCK ABS													
			DURING SERVICE, FOUND DRIVE SHOCK BUSHES UNSERVICABLE $359.40													
			* Ballast vehicle													
			* Inspect shock absorbers, bushes & components													
			* Located unserviceable shock absorber													
			* Loosened components to acess repair													
			* Removed/replaced failed shock absorber													
			* Installed remaining components back to specification													
			* Tension, test & quality check repair													
			* Remove vehicle ballasting													
1075	Wodonga - Workshop	Susp\SHOCK ABS				08/04/2025	236804	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	PACCAR PARTS FLEET SERVICES	P/MOVER
			Elect\DERATE													
			TRUCK TRAVELLING TOO FAST													
			* Test operations & confirmed fault													
			* Connected laptop & found parameters set incorrectly													
			* Adjusted parameters as required													
			* Test drove vehicle again with GPS													
1075	Wodonga - Workshop	Elect\DERATE	* Confirmed truck now travelline at correct speed			08/04/2025	236804	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	PACCAR PARTS FLEET SERVICES	P/MOVER
1075	Wodonga - Workshop	Prevent\STEER W/B	Prevent\STEER W/B	Prevent\STEER W/B		08/04/2025	236804	PreventativeMaintenance	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	PACCAR PARTS FLEET SERVICES	P/MOVER

			C Service																
1075	Wodonga - Workshop	VehService\CS	TCTC PO WW0931266	VehService\CS		08/04/2025	236804	Service	Completed	FL Green Distribution	KWX15HWY	Wodonwa	LHB	XW09GY	PACCAR PARTS FLEET SERVICES	P/MOVER			
1075	Wodonga - Workshop	Prevent\TRANS OIL	Prevent\TRANS OIL	Prevent\TRANS OIL		08/04/2025	236804	PreventativeMaintenance	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	PACCAR PARTS FLEET SERVICES	P/MOVER			
1075	Wodonga - Workshop	DrivLine\DIFF OIL	DrivLine\DIFF OIL Engine\ENG TUNE The following engine tune up as per manufacturer specification included: * Removed & check air intake for restrictions * Check radiator for oil indicating compression or oil leaks * Removed rocker cover to access internal components * Check top end components * Adjust valve clearance to specification * Set all parameters to specification * Install rocker cover & components complete * Check & adjust all belts * Pressure test CAC * Test, confirm & quality check engine operation	DrivLine\DIFF OIL		08/04/2025	236804	PreventativeMaintenance	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	PACCAR PARTS FLEET SERVICES	P/MOVER			
1075	Wodonga - Workshop	Engine\ENG TUNE	* Comolete ECM download Engine\BELTS/TENS WHILST CARRYING OUT SERVICE, FOUND FAN BELT CRACKED			08/04/2025	236804	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	PACCAR PARTS FLEET SERVICES	P/MOVER			
1075	Wodonga - Workshop	Engine\BELTS/TENS	* Removed & reolaced belt as required			08/04/2025	236804	Rwair	Completed	FL Green Distribution	KWX15HWY	Wodonwa	LHB	XW09GY	PACCAR PARTS FLEET SERVICES	P/MOVER			
1075	Wodonga - Workshop	Elect\INDICATORS	LEFT INDICATOR NOT MAKING IT TO TRAILERS MISSING WITH FUSE BOX WOULD FIX TEMPORARILY.			01/04/2025	236484	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	AIRKON AUTO ELECTRICAL	P/MOVER			
1075	Wodonga - Workshop	Prevent\WHEEL ALGN	Prevent\WHEEL ALGN	Prevent\WHEEL ALGN	Previously completed	26/03/2025	230264	PreventativeMaintenance	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER			
1075	Wodonga - Workshop	Insp\ANN INSP	Insp\ANN INSP	Insp\ANN INSP		26/03/2025	230264	PreventativeMaintenance	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER			
1075	Wodonga - Workshop	Body\MIRRORS	READJUST L/H MIRROR CASING.		previously completed	26/03/2025	230264	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER			
1075	Wodonga - Workshop	VehService\AS	VehService\AS A Service	VehService\AS		26/03/2025	230264	Service	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER			
1075	Wodonga - Workshop	Elect\TRL LIGHTS	LIGHT PLUG NOT WORKING.		Previously completed	26/03/2025	230264	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER			
1075	Wodonga - Workshop	DrivLine\OIL LEAK	RESEAL FRONT DIFF.		WARRANTY WORK	26/03/2025	230264	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER			
1075	Wodonga - Workshop	Elect\TRL LIGHTS	No brake lights and no LH indicators on trailers		Inspected light plug. Found excessive exposed wires inside of plug. Fitted new light plug and reset circuit breaker for brake lights. Tested all lights and confirmed repair	17/03/2025	225955	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER			
1075	Wodonga - Workshop	Tyres\FITMENT	Tyres\FITMENT			07/03/2025	221958	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	BEAUREPAIRES	P/MOVER			
1075	Wodonga - Workshop	Tyres\ROTATION	Tyres\ROTATION steer 1-2			27/02/2025	216213	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	BEAUREPAIRES	P/MOVER			
1075	Wodonga - Workshop	VehService\BS	VehService\BS	VehService\BS		22/02/2025	215703	Service	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER			
1075	Wodonga - Workshop	VehService\AS	VehService\AS	VehService\AS	REPLACED PRIMARY FUEL FILTER AS FILTER VERY DIRTY.	15/02/2025	209674	Service	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER			
1075	Wodonga - Workshop	Air Con\AIR CON	ONLY BODY AIRCON VENTS WORKING.			03/02/2025	199001	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER			
1075	Wodonga - Workshop	Body\MIRRORS	Passenger Mirror Small Casing Missing Both Due To Fallen Tree Hanging Into Road.			03/02/2025	199001	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER			
1075	Wodonga - Workshop	Body\MIRRORS	Passenger Mirror Large Cracked			03/02/2025	199001	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER			
1075	Wodonga - Workshop	VehService\AS	VehService\AS	VehService\AS	194600ks Back/bottom of gear box leaking	28/01/2025	194600	Service	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER			
1075	Wodonga - Workshop	Elect\TRL LIGHTS	POWER CONNECTOR FOR TRAILER DAMAGED.			14/01/2025	186854	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER			
1075	Wodonga - Workshop	Chassis\SUZI COIL	Air /power lines keep snapping on T615 trailer driver side ratchet			14/01/2025	186854	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER			
1075	Wodonga - Workshop	VehService\AS	VehService\AS	VehService\AS	Replaced secondary fuel filter	14/01/2025	186854	Service	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER			
1075	Wodonga - Workshop	Elect\HEAD LIGHT	HEADLIGHTS AIMING TO LOW.			14/01/2025	186854	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER			
1075	Wodonga - Workshop	DrCabRep\WIPERS	passenger wiper replace			14/01/2025	186854	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER			
1075	Wodonga - Workshop	Brakes\AIR FITTIN	REPLACE SUZI COILS. IF POSSIBLE RECTIFY CATCHING ON TRAILER RATCHET.			07/01/2025	441482	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonwa	LHB	XW09GY	PACCAR PARTS FLEET SERVICES	P/MOVER			
1075	Wodonga - Workshop	Chassis\BREAKDOWN	Repair/Replace Damaged Suzie Leads. (Brown & Hurley Darra P/O: WW091123) Elect\TRL LIGHTS			01/01/2025	179069	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	PACCAR PARTS FLEET SERVICES	P/MOVER			
1075	Wodonga - Workshop	Elect\TRL LIGHTS	As oer defect notice		work comoleted defect siened off	14/12/2024	165976	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonwa	LHB	XW09GY	Wodonwa Workshop	P/MOVER			
1075	Wodonga - Workshop	Tyres\TP10	Repair Tyre Puncture On Position 10. (West Melbourne Goodyear Autocare P/O: WW090909)			11/12/2024	164482	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	BEAUREPAIRES	P/MOVER			
1075	Wodonga - Workshop	Tyres\STEER TYRE	Tyres\STEER TYRE 1-2			11/12/2024	163362	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER			
1075	Wodonga - Workshop	Chassis\SUZI COIL	Replace Damaged Suzie Leads. (Brown & Hurley Kyogle P/O: WW091073)		Traveled To Chinderah from TPX to pick up parts for breakdown. Picked up parts and traveled to Chinderah BP. When arrived found suzi leads and narva trailer plug to have been pulled out and broken as they	10/12/2024	330881	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	PACCAR PARTS FLEET SERVICES	P/MOVER			
1075	Wodonga - Workshop	VehService\BS	VehService\BS	VehService\BS		03/12/2024	156587	Service	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER			
1075	Wodonga - Workshop	VehService\AS	VehService\AS	VehService\AS	7 am - 8.30	03/12/2024	156587	Service	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER			
1075	Wodonga - Workshop	VehService\AS	VehService\AS	VehService\AS		26/10/2024	130409	Service	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER			
1075	Wodonga - Workshop	Body\WIPERS	Replace Wipers Tyres\RUN FLAT		Not complete pass to pending	26/10/2024	130409	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER			
1075	Wodonga - Workshop	Tyres\RUN FLAT				18/10/2024	126375	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonwa	LHB	XW09GY	BEAUREPAIRES	P/MOVER			
1075	Wodonga - Workshop	DrivLine\DIFF OIL	DrivLine\DIFF OIL	DrivLine\DIFF OIL		28/08/2024	99456	PreventativeMaintenance	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER			
1075	Wodonga - Workshop	VehService\AS	A Service	VehService\AS		28/08/2024	99456	Service	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER			
1075	Wodonga - Workshop	VehService\BS	B Service	VehService\BS		28/08/2024	99456	Service	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER			
1075	Wodonga - Workshop	VehService\CS	C Service As Per Attached Checklist	VehService\CS		19/04/2024	75541	Service	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER			
1075	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			19/04/2024	75541	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER			
1075	Wodonga - Workshop	Brakes\BREAKDOWN	Replace Damaged Suzzie Lines (Brown & Hurley Townsville P/O: WWQB5121)			02/04/2024	75541	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER			
1075	Wodonga - Workshop	Chassis\SUZI COIL	repair damaged suzi coils			07/02/2024	23043	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER			
1075	Wodonga - Workshop	Elect\BATTERY	Truck not starting			06/02/2024	1274	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER			
1075	Wodonga - Workshop	Insp\Truck Pre	truck pre-delivery as per check list			02/02/2024	670	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER			
1075	Wodonga - Workshop	Comp\Truck Safe	FIT TRUCKSAFE STICKER.			02/02/2024	670	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW09GY	Wodonga Workshop	P/MOVER			