EquipmentName	Workshop	Description	CompletionComments	DateDone	DistanceDone	Workstate	Location	Division	Rego	Supplier	EquipmentType
1074	Wodonga - Workshop	Cab Vibrations Getting Worse	Repaired OK, Replaced rear cab mount with new	29/08/2026	498565	Completed	Wodonga	LHB	XW08GY	Wodonga	P/MOVER
1074	Wodonga - Workshop	Jumping Out Of Gear & Gear Linkage Feels Off	Inspected may be causing by cab mounts cracked and had play, driver to report and monitor Completed By Sammy at same time as Job: 476354	29/08/2026	498565	Completed	Wodonga	LHB	XW08GY	Wodonga	P/MOVER
1074	Wodonga - Workshop	Wandering All Over The Road	Inspected steer king pins, pitman arm totai bar, tie rod OK, checked both steer tyres OK, pressure OK. Completed By Sammy at same time as Job: 476354	29/08/2026	498565	Completed	Wodonga	LHB	XW08GY	Wodonga	P/MOVER
1074	Wodonga - Workshop	Steering Wheel On An Angle To The Right Pulling, Steers Need Replacing Scrubbing.	Inspected OK. Both steers have around 12mm tread, Pressure OK, 100 PSI. Inspected both side rear cab mountings, replaced with new.	29/08/2026	498565	Completed	Wodonga	LHB	XW08GY	Wodonga	P/MOVER
1074	Wodonga - Workshop	cab mounts/suspension (very rough ride/lots of vibrations through cab + steering cab also doesn't look straight from rear view)	R/H/S front cab mount has play 5mm, need to replace ASAP	29/08/2026	498565	Completed	Wodonga	LHB	XW08GY	Wodonga	P/MOVER
1074	Wodonga - Workshop	R/H Side Of Cab Is Lower, On L/H Cornering R/H Is Bogging Down And Nearly Throwing You Into The Corner	Inspected OK	29/08/2026	498565	Completed	Wodonga	LHB	XW08GY	Wodonga	P/MOVER
1074	Wodonga - Workshop	Voltage Is Still Low 10-11 Volts Surging On Start Up, Lights Flickering	Jacked over cabin, checked voltage at batteries, started and ran with all lights and accessories on checked voltage at batteries & alternator, alternator putting out 14.5 volts, batteries were at 14.2 volts, lowered cabin.	22/08/2026	497365	Completed	Wodonga	LHB	XW08GY	Wodonga	P/MOVER
1074	Wodonga - Workshop	Air Restriction Light Inop	Refitted dash globe back into gauge	22/08/2026	497365	Completed	Wodonga	LHB	XW08GY	Wodonga	P/MOVER
1074	Wodonga - Workshop	Axle Gauge Light Inop	Refitted dash globe back into gauge	22/08/2026	497365	Completed	Wodonga	LHB	XW08GY	Wodonga	P/MOVER
1074	Wodonga - Workshop	load scale ref previous R+R	Replumbed weight scales in cabin so weight gauge was reading off both spring pressure gauges.	22/08/2026	497365	Completed	Wodonga	LHB	XW08GY	Wodonga	P/MOVER
1074	Wodonga - Workshop	clutch adjustment	Checked & adjusted clutch.	22/08/2026	497365	Completed	Wodonga	LHB	XW08GY	Wodonga	P/MOVER
1074	Wodonga - Workshop	low voltage - surging on start up/lights flickering	Jacked over cabin, checked voltage at batteries, started and ran with all lights and accessories on checked voltage at batteries & alternator, alternator putting out 14.5 volts, batteries were at 14.2 volts, lowered cabin.	22/08/2026	497365	Completed	Wodonga	LHB	XW08GY	Wodonga	P/MOVER
1074	Wodonga - Workshop	Load Scale Plumbing To Be Rectified	Replumbed weight scales in cabin so weight gauge was reading off both spring pressure gauges.	22/08/2026	497365	Completed	Wodonga	LHB	XW08GY	Wodonga	P/MOVER
1074	Wodonga - Workshop	Adjust Guardian Camera, Due To Pointing Down To Dash. B Service	Adjusted guarding driver facing camera & tightened up so driver is unable to adjust.	22/08/2026	497365	Completed	Wodonga	LHB	XW08GY	Wodonga	P/MOVER
1074	Wodonga - Workshop	Serviced @ 490,495 Klm	Replaced L/H Steer Hub Seal	12/08/2026	490550	Completed	Wodonga	LHB	XW08GY	Wodonga	P/MOVER
1074	Wodonga - Workshop	diffs have a small weep		12/08/2026	490550	Completed	Wodonga	LHB	XW08GY	Wodonga	P/MOVER
1074	Wodonga - Workshop	boost leak when coming off throttle		12/08/2026	490550	Completed	Wodonga	LHB	XW08GY	Wodonga	P/MOVER
1074	Wodonga - Workshop	Severe vibration when jakes are on		12/08/2026	490550	Completed	Wodonga	LHB	XW08GY	Wodonga	P/MOVER
1074	Wodonga - Workshop	Access steps are bent/Damaged.		23/07/2026	474919	Completed	Wodonga	LHB	XW08GY	Wodonga	P/MOVER
1074	Wodonga - Workshop	Gearbox whine in top gear.		23/07/2026	474919	Completed	Wodonga	LHB	XW08GY	Wodonga	P/MOVER
1074	Wodonga - Workshop	vibration rear drives change		23/07/2026	474919	Completed	Wodonga	LHB	XW08GY	Wodonga	P/MOVER
1074	Wodonga - Workshop	VehService\AS A Service		21/07/2026	471346	Completed	Wodonga	LHB	XW08GY	Wodonga	P/MOVER
1074	Wodonga - Workshop	Suzi coils seem squashed around connection		21/07/2026	471346	Completed	Wodonga	LHB	XW08GY	Wodonga	P/MOVER
1074	Wodonga - Workshop	Grill loose		21/07/2026	471346	Completed	Wodonga	LHB	XW08GY	Wodonga	P/MOVER
1074	Wodonga - Workshop	Drive lights not working		21/07/2026	471346	Completed	Wodonga	LHB	XW08GY	Wodonga	P/MOVER
1074	Wodonga - Workshop	Tyres\RUN OUT POS 5-6 + 7-8		14/07/2026	470141	Completed	Wodonga	LHB	XW08GY	BORDER	P/MOVER
1074	Wodonga - Workshop	Tyres\STEER TYRE 1-2		14/07/2026	470141	Completed	Wodonga	LHB	XW08GY	BORDER	P/MOVER
1074	Wodonga - Workshop	Repair After Treatment Fault	completed by TP JS	25/06/2026	463209	Completed	Wodonga	LHB	XW08GY	Wodonga	P/MOVER
1074	Wodonga - Workshop	VehService\AS A Service	completed by JS MB KR SMc TP inspected ,neither diff was leaking	25/06/2026	463209	Completed	Wodonga	LHB	XW08GY	Wodonga	P/MOVER
1074	Wodonga - Workshop	Front diff leaking	comoleted bv MB Traveled to Oberon BP Diagnosed complaint of no clearance lights Checked plug, all other lights operate Found no voltage at pin 7 Checked fuses and found breaker blown again Found dead short in A trailer coming from clearance light Cut and repaired wiring	25/06/2026	463209	Completed	Wodonga	LHB	XW08GY	Wodonga	P/MOVER
1074	Wodonga - Workshop	Elect\ELECT P&W	Tested lights and breaker, did not blow	28/05/2026	451976	Completed	Wodonga	LHB	XW08GY	WARREG	P/MOVER
1074	Wodonga - Workshop	Tyres\TP01	NEW RIM + TYRE + CALLOUT DONE IN GOULBURN completed by JS TP	04/05/2026	440656	Completed	Wodonga	LHB	XW08GY	BORDER	P/MOVER
1074	Wodonga - Workshop	VehService\AS A Service	no brakes recorded	25/04/2026	434869	Completed	Wodonga	LHB	XW08GY	Wodonga	P/MOVER
1074	Wodonga - Workshop	DrivLine\DIFF OIL	completed by SMc	31/03/2026	428664	Completed	Wodonga	LHB	XW08GY	Wodonga	P/MOVER
1074	Wodonga - Workshop	Insp\ANN INSP		31/03/2026	428664	Completed	Wodonga	LHB	XW08GY	Wodonga	P/MOVER
1074	Wodonga - Workshop	VehService\CS 430,000	completed by SMc	31/03/2026	428664	Completed	Wodonga	LHB	XW08GY	Wodonga	P/MOVER
1074	Wodonga - Workshop	Prevent\STEER W/B	completed SMc	31/03/2026	428664	Completed	Wodonga	LHB	XW08GY	Wodonga	P/MOVER
1074	Wodonga - Workshop	Prevent\TRANS OIL	S.McCABE	31/03/2026	428664	Completed	Wodonga	LHB	XW08GY	Wodonga	P/MOVER
1074	Wodonga - Workshop	trans oil due	completed by SMc	31/03/2026	428664	Completed	Wodonga	LHB	XW08GY	Wodonga	P/MOVER
1074	Wodonga - Workshop	diff oil due	completed by SMc	31/03/2026	428664	Completed	Wodonga	LHB	XW08GY	Wodonga	P/MOVER
1074	Wodonga - Workshop	B-service due	completed by SMc	31/03/2026	428664	Completed	Wodonga	LHB	XW08GY	Wodonga	P/MOVER
1074	Wodonga - Workshop	VehService\BS B Service		02/02/2026	394181	Completed	Wodonga	LHB	XW08GY	Wodonga	P/MOVER
1074	Wodonga - Workshop	Driving light not working	Fuse	02/02/2026	394160	Completed	Wodonga	LHB	XW08GY	Wodonga	P/MOVER
1074	Wodonga - Workshop	VehService\AS A Service		02/02/2026	394160	Completed	Wodonga	LHB	XW08GY	Wodonga	P/MOVER
1074	Wodonga - Workshop	Tyres\TP9+10		21/01/2026	386944	Completed	Wodonga	LHB	XW08GY	BORDER	P/MOVER
1074	Wodonga - Workshop	Tyres\TP11+12	UNEVEN WORN OUT	21/01/2026	386944	Completed	Wodonga	LHB	XW08GY	BORDER	P/MOVER
1074	Wodonga - Workshop	Tyres\TP1+2	EDGES WORN OUT BOTH TYRES	19/11/2025	351377	Completed	Wodonga	LHB	XW08GY	BORDER	P/MOVER
1074	Wodonga - Workshop	Front diff leaking	WASHED AND TOPPED UP.	27/10/2025	338304	Completed	Wodonga	LHB	XW08GY	Wodonga	P/MOVER
1074	Wodonga - Workshop	Check Front Diff Oil Level		27/10/2025	339764	Completed	Wodonga	LHB	XW08GY	Wodonga	P/MOVER
1074	Wodonga - Workshop	VehService\AS A Service		27/10/2025	339764	Completed	Wodonga	LHB	XW08GY	Wodonga	P/MOVER
1074	Wodonga - Workshop	After Treat Light On & Truck Getting Hot & Derating		17/09/2025	316309	Completed	Wodonga	LHB	XW08GY	Wodonga	P/MOVER
1074	Wodonga - Workshop	Truck A/C Stopped Working After work Done On Friday Find & Repair Broken Wire In Horton Solenoid Circuit.		17/09/2025	316309	Completed	Wodonga	LHB	XW08GY	Wodonga	P/MOVER
1074	Wodonga - Workshop	(Arkon Auto Electrical P/O: WW096940		13/09/2025	389072	Completed	Wodonga	LHB	XW08GY	ARKON A	P/MOVER
1074	Wodonga - Workshop	Horton Fan Not Working Correctly After New Horton Being Fitted B Service	Checked over fan circuit found to be a broken wire between fan solenoid & ECM, called in auto electrician.	13/09/2025	389072	Completed	Wodonga	LHB	XW08GY	ARKON A	P/MOVER
1074	Wodonga - Workshop	Serviced @ 314,465 Klms.		12/09/2025	314465	Completed	Wodonga	LHB	XW08GY	Wodonga	P/MOVER
1074	Wodonga - Workshop	Check & Adjust Clutch		12/09/2025	314465	Completed	Wodonga	LHB	XW08GY	Wodonga	P/MOVER
1074	Wodonga - Workshop	Replace Horton, Due To Leaking Air & Noisy.		12/09/2025	314465	Completed	Wodonga	LHB	XW08GY	Wodonga	P/MOVER
1074	Wodonga - Workshop	Tyres\Puncture POS 9 & 12		09/09/2025	313956	Completed	Wodonga	LHB	XW08GY	BORDER	P/MOVER
1074	Wodonga - Workshop	BELT PULLEY BEARING SOUNDS LIKE IT'S ON WAY OUT.	REPLACED BOTH BELTS. REPLACED A/C IDLER AND TENSIONER BEARINGS.	01/09/2025	306494	Completed	Wodonga	LHB	XW08GY	Wodonga	P/MOVER
1074	Wodonga - Workshop	VehService\AS A Service		09/08/2025	307247	Completed	Wodonga	LHB	XW08GY	Wodonga	P/MOVER
1074	Wodonga - Workshop	Turn on battery isolater	Turned on isolator so trailer shed could service trailers hooked up to truck	21/07/2025	279471	Completed	Wodonga	LHB	XW08GY	Wodonga	P/MOVER
1074	Wodonga - Workshop	Tyres\TP7+8		17/07/2025	277566	Completed	Wodonga	LHB	XW08GY	BORDER	P/MOVER
1074	Wodonga - Workshop	Tyres\TP5+6 VehService\BS		17/07/2025	277566	Completed	Wodonga	LHB	XW08GY	BORDER	P/MOVER
1074	Wodonga - Workshop	* Carried out A & B Truck service on 17/05/2025 as per Greenfreight service sheet schedule Trailer Brakes Won't Release, At Coke In Mentone.	Booked into TCTC 17/5 PO #WW094186 WAY IN MENTONE TO CHECK AND REPORT ON THE TRAILER BRAKES NOT RELEASING. DRIVER - 0459 089 065. DATE 27-6-25 TRAVELLED TO SITE. FOUND AIR BUILDING UP IN VEHICLE BUT NOT RELEASING TRAILER BRAKES. CONNECTED AIR TO TRAILER FROM BREAKDOWN VAN AND RELEASED BRAKES. INSPECTED BRAKES AND FOUND OUT OF ADJUSTMENT. ADJUSTED AS REQUIRED. STILL NOT RELEASING BRAKES. INSPECTED AND FOUND AIRLINES FOR RED AND YELLOW BUTTON AND FOIUND RED KINKED. REROUTED AND SHORTED . TESTED AND TRAILER RELEASING.	01/07/2025	239513	Completed	Wodonga	LHB	XW08GY	PACCAR I	P/MOVER
1074	Wodonga - Workshop	(Hallam truck Centre P/O: WW095301)	RETURNED HOME	28/06/2025	265398	Completed	Wodonga	LHB	XW08GY	PACCAR I	P/MOVER
1074	Wodonga - Workshop	Radiator cap stuck	Pried radiator cap off. Damaged neck in the process. Parked truck outside workshop and tilted cab all the way over to gain more access to top of radiator. Repaired damaged filler neck and refilled radiator until full.	27/06/2025	264886	Completed	Wodonga	LHB	XW08GY	Wodonga	P/MOVER
1074	Wodonga - Workshop	Front diff temp guage globe blown		27/06/2025	264886	Completed	Wodonga	LHB	XW08GY	Wodonga	P/MOVER
1074	Wodonga - Workshop	front number plate about to fall off		27/06/2025	264886	Completed	Wodonga	LHB	XW08GY	Wodonga	P/MOVER
1074	Wodonga - Workshop	In cab bunk cooler about to fall off the wall	Reattached bunk cupboard to wall	27/06/2025	264886	Completed	Wodonga	LHB	XW08GY	Wodonga	P/MOVER
1074	Wodonga - Workshop	VehService\AS A Service		27/06/2025	264886	Completed	Wodonga	LHB	XW08GY	Wodonga	P/MOVER
1074	Wodonga - Workshop	Sounds like a bearing or something at the front of the engine is on the way out		17/06/2025	257619	Completed	Wodonga	LHB	XW08GY	Wodonga	P/MOVER
1074	Wodonga - Workshop	Boost leak	Pressure tested charge air circuit. Found damaged hose and multiple loose clamps. Repaired. Test drove around yard to confirm repair complete	24/04/2025	224900	Completed	Wodonga	LHB	XW08GY	Wodonga	P/MOVER
1074	Wodonga - Workshop	Batteries dead. (Batteries Supplied By Marshall Batteries P/O: WW094074)		22/04/2025	224519	Completed	Wodonga	LHB	XW08GY	Wodonga	P/MOVER
1074	Wodonga - Workshop	Tyres\TP9+10		17/04/2025	224519	Completed	Wodonga	LHB	XW08GY	BEAUREP	P/MOVER
1074	Wodonga - Workshop	Tyres\TP7+8		17/04/2025	224519	Completed	Wodonga	LHB	XW08GY	BEAUREP	P/MOVER
1074	Wodonga - Workshop	VehService\AS A Service		15/04/2025	224519	Completed	Wodonga	LHB	XW08GY	Wodonga	P/MOVER
1074	Wodonga - Workshop	Horton fan warn out Body\PANELS REPLACE GRILLE MESH . * Unbolted & removed grille * Disassembled grille * Removed & replaced mesh * Refit grille * Aligned, adjusted & tensioned all to specifications	REBUILT HORTON.	15/04/2025	224519	Completed	Wodonga	LHB	XW08GY	Wodonga	P/MOVER
1074	Wodonga - Workshop	DrivLine\WHEEL SEAL REPLACE FAILED LHR DRIVE HUB SEAL . * Ballast axle & removed wheel end equipment * Removed drum & hub assembly * Inspected brakes & bearings - All ok * Cleaned down all components * Refit hub with replacement seal as required * Refit drum & wheel end equipment * Aligned, adjusted & tensioned all components		14/04/2025	224519	Completed	Wodonga	LHB	XW08GY	PACCAR I	P/MOVER
1074	Wodonga - Workshop	* Test operations - All ok		14/04/2025	224519	Completed	Wodonga	LHB	XW08GY	PACCAR I	P/MOVER
1074	Wodonga - Workshop	DRIVING LIGHTS STOPPED WORKING, BARE WIRES FROM RUBBING ON THE GRILL	Truck at TCTC arkon going there to completed work	09/04/2025	221514	Completed	Wodonga	LHB	XW08GY	ARKON A	P/MOVER
1074	Wodonga - Workshop	REPLACED SUZI COILS, EBS LEAD AND LIGHT PLUG.		07/04/2025	220836	Completed	Wodonga	LHB	XW08GY	Wodonga	P/MOVER
1074	Wodonga - Workshop	VehService\AS A Service	R.S. 1 HOUR LABOUR.	28/03/2025	213317	Completed	Wodonga	LHB	XW08GY	Wodonga	P/MOVER
1074	Wodonga - Workshop	CHECKED DIFFS. TOPPED UP FRONT DIFF. FRONT DIFF INPUT LEAKING.		20/03/2025	209213	Completed	Wodonga	LHB	XW08GY	Wodonga	P/MOVER
1074	Wodonga - Workshop	Check Front Diff Oil Level & Top Up If Required. (Brown & Hurley Coffs Harbour P/O: WW092873)		19/03/2025	349516	Completed	Wodonga	LHB	XW08GY	PACCAR I	P/MOVER

			Torque rod bushsstarting to wear							
1074	Wodonga - Workshop	VehService\AS A Service DIFF SEAL HAS HEAVY LEAK. TCTC - carried out a diff housing reseal, input seal replacement & diff oil pump reseal.		06/03/2025	197230	Completed	Wodonga LHB	XW08GY	Wodonga P/MOVER	
1074	Wodonga - Workshop	No paperwork completed due to it been a warranty job. 21/1/2025		12/02/2025	171989	Completed	Wodonga LHB	XW08GY	PACCAR I P/MOVER	
1074	Wodonga - Workshop	VehService\AS		11/02/2025	182413	Completed	Wodonga LHB	XW08GY	Wodonga P/MOVER	
1074	Wodonga - Workshop	Check Tyre Pressures On Positions 3,4,5,6,7,8,9&10. (Wodonga Tyre & Auto P/O: WW091637)		30/01/2025	172816	Completed	Wodonga LHB	XW08GY	BEAUREP P/MOVER	
1074	Wodonga - Workshop	Replace Tyres On Positions 1&2. (Wodonga Tyre & Auto P/O: WW091637)		30/01/2025	172816	Completed	Wodonga LHB	XW08GY	BEAUREP P/MOVER	
1074	Wodonga - Workshop	Wheel Alignment. (Hume Truck Technics P/O: WW091578)		25/01/2025	189742	Completed	Wodonga LHB	XW08GY	HUME TR P/MOVER	
1074	Wodonga - Workshop	Fabricate and fit number plate backing plate.		23/01/2025	172789	Completed	Wodonga LHB	XW08GY	Wodonga P/MOVER	
1074	Wodonga - Workshop	A & B SERVICE DUE.		23/01/2025	172789	Completed	Wodonga LHB	XW08GY	Wodonga P/MOVER	
1074	Wodonga - Workshop	Bunk cooler/ AC Not working.	Coolabah Cooler Repaired By MVM. (Warranty)	23/01/2025	172789	Completed	Wodonga LHB	XW08GY	Wodonga P/MOVER	
1074	Wodonga - Workshop	TRAILER BRAKES DON'T RELEASE STRAIGHT AWAY. CAN TAKE 10 OR MORE SECONDS AFTER PUSHING BUTTON FOR BRAKES TO RELEASE. BRAKES TAKE AGES TO RELEASE WHEN HOOKED UP TO TRAILER. CAN TAKE 30 SEC TO 1 MIN SOMETIMES.		23/01/2025	172789	Completed	Wodonga LHB	XW08GY	Wodonga P/MOVER	
1074	Wodonga - Workshop	TRUCK WILL BE UNUSED FRIDAY 29-11 TO MONDAY 2-12.	Releasing brakes can take longer than 30 seconds to a minute Checked trailer plug.	23/01/2025	172789	Completed	Wodonga LHB	XW08GY	Wodonga P/MOVER	
1074	Wodonga - Workshop	LEFT INDICATOR NOT WORKING ON TRAILERS. POSSIBLE PLUG ISSUE.	Everything works on the truck end this is a trailer issue	23/01/2025	172789	Completed	Wodonga LHB	XW08GY	Wodonga P/MOVER	
1074	Wodonga - Workshop	ABS Lead Damaged & Needs Replacing.	Previously done	23/01/2025	172789	Completed	Wodonga LHB	XW08GY	Wodonga P/MOVER	
1074	Wodonga - Workshop	Bunk A/C Stopped Working and wont turn On.	JOB#449979	23/01/2025	172789	Completed	Wodonga LHB	XW08GY	Wodonga P/MOVER	
1074	Wodonga - Workshop	Grill Not Secure.	Afternoon shift was tasked with doing this job 23 1 25 Russell	23/01/2025	172789	Completed	Wodonga LHB	XW08GY	Wodonga P/MOVER	
1074	Wodonga - Workshop	Clutch Came Out of Adjustment by Euroua.		23/01/2025	172789	Completed	Wodonga LHB	XW08GY	Wodonga P/MOVER	
1074	Wodonga - Workshop	C Service		23/01/2025	172789	Completed	Wodonga LHB	XW08GY	Wodonga P/MOVER	
1074	Wodonga - Workshop	Insp\ANN INSP		23/01/2025	172789	Completed	Wodonga LHB	XW08GY	Wodonga P/MOVER	
1074	Wodonga - Workshop	takes a long time for trailer brakes to release had same issue with 3 sets of trailers		23/01/2025	172789	Completed	Wodonga LHB	XW08GY	Wodonga P/MOVER	
1074	Wodonga - Workshop	Replace Leaking Hub Seal. (Parts Supplied By TCTC P/O: WW091719)		12/01/2025	167563	Completed	Wodonga LHB	XW08GY	Wodonga P/MOVER	
1074	Wodonga - Workshop	Clutch Brake Not Working.		11/01/2025	167535	Completed	Wodonga LHB	XW08GY	Wodonga P/MOVER	
1074	Wodonga - Workshop	Adjust Clutch...		11/01/2025	167535	Completed	Wodonga LHB	XW08GY	Wodonga P/MOVER	
1074	Wodonga - Workshop	VehService\BS	Front diff needs reseal	07/01/2025	164744	Completed	Wodonga LHB	XW08GY	Wodonga P/MOVER	
1074	Wodonga - Workshop	Clutch Adjustment. A Service.	Replaced clutch breake and adjust	07/01/2025	164744	Completed	Wodonga LHB	XW08GY	Wodonga P/MOVER	
1074	Wodonga - Workshop	Serviced @ 132.329 Klms		19/10/2024	132329	Completed	Wodonga LHB	XW08GY	Wodonga P/MOVER	
1074	Wodonga - Workshop	VehService\AS	Replaced felpro filter as fuel was up at change level	26/09/2024	123814	Completed	Wodonga LHB	XW08GY	Wodonga P/MOVER	
1074	Myrtleford - Workshop	Tyres\TP01		21/09/2024	120595	Completed	Wodonga LHB	XW08GY	BEAUREP P/MOVER	
1074	Wodonga - Workshop	Lost All Gauges In Dash.		29/08/2024	105454	Completed	Wodonga LHB	XW08GY	Wodonga P/MOVER	
1074	Wodonga - Workshop	Check & Adjust Clutch		29/08/2024	105454	Completed	Wodonga LHB	XW08GY	Wodonga P/MOVER	
1074	Wodonga - Workshop	DRIVER SEAT BELT WON'T PULL OUT OR RETRACT.		23/08/2024	102514	Completed	Wodonga LHB	XW08GY	Wodonga P/MOVER	
1074	Wodonga - Workshop	VehService\AS	102514kms clutch was also adjusted i	23/08/2024	102514	Completed	Wodonga LHB	XW08GY	Wodonga P/MOVER	
1074	Wodonga - Workshop	Steering Wheel Won't Lock Into Position Connect 1074 Up To Trailer T660	Previously completed	23/08/2024	102514	Completed	Wodonga LHB	XW08GY	Wodonga P/MOVER	
1074	Wodonga - Workshop	Fit Driving Lights Behind Grill (Hagan's Auto Electrical P/O: WW087225)	Also fitted new trailer fleet numbers to T660.[Andrew]	07/07/2024	73474	Completed	Wodonga LHB	XW08GY	Wodonga P/MOVER	
1074	Wodonga - Workshop			06/07/2024	72102	Completed	Wodonga LHB	XW08GY	HAGANS P/MOVER	
1074	Wodonga - Workshop	B Service	14 litres of oil needed	05/07/2024	93250	Completed	Wodonga LHB	XW08GY	Wodonga P/MOVER	
1074	Wodonga - Workshop	A Service	54728 ks	31/05/2024	54729	Completed	Wodonga LHB	XW08GY	Wodonga P/MOVER	
1074	Wodonga - Workshop	Record Check Results As Attached To This Job		03/05/2024	70254	Completed	Wodonga LHB	XW08GY	Wodonga P/MOVER	
1074	Wodonga - Workshop	A Service As Per Attached Checklist		03/05/2024	70254	Completed	Wodonga LHB	XW08GY	Wodonga P/MOVER	
1074	Wodonga - Workshop	A Service As Per Attached Checklist		03/04/2024	27608	Completed	Wodonga LHB	XW08GY	Wodonga P/MOVER	
1074	Wodonga - Workshop	Record Check Results As Attached To This Job		03/04/2024	27608	Completed	Wodonga LHB	XW08GY	Wodonga P/MOVER	
1074	Wodonga - Workshop	truck rolled into gutter	Royans Shepparton repaired Organise requires parts for repairs Travel to Vehicle located 10-30 Fitzpatrick Street Revesby Removed and replaced damaged Suzi leads and checked for leaks- all ok	27/02/2024	27419	Completed	Wodonga LHB	XW08GY	Wodonga P/MOVER	
1074	Wodonga - Workshop	BRAKES STARTING TO SQUEAL. AIR LINES PULLED OFF POST.	Returned to workshoo	06/02/2024		Completed	Wodonga LHB	XW08GY	Albury W P/MOVER	
1074	Wodonga - Workshop	REPAIRED SUZI LEADS.		25/01/2024		Completed	Wodonga LHB	XW08GY	Wodonga P/MOVER	
1074	Wodonga - Workshop	PICK UP TCTC.	* Removed/replaced engine filter & oil, specification used in parts section below. * Check all engine operation & components * Removed/replaced transmission oil filter * Check all hydraulic lines fitting & level lubricant levels to specification * Removed/replaced power steering filter & gasket * Removed/replaced differential oil, specification used in parts section below. * Removed/replaced fuel filter * Check cooling system & pressure test * Check all belts, idler pulleys, fan, shrouds & adjust to specification * Check all electrical routing, wiring looms, switches, sensors & components * Check all wheel equipment & steering components * Check all braking & adjust to specification * Check clutching & adjust to specification * Check all suspension components * Check all internal cabin operation, components & adjust to specification * Check all external cabin components & adjust to specification * Check windscreen washers, wipers, refill & test operation * Lubricate, adjust relevant components as required * Re torque all fitting & fixtures * Wash vehicle complete	23/01/2024	11097	Completed	Wodonga LHB	XW08GY	Wodonga P/MOVER	
1074	Wodonga - Workshop	C Service As Per Attached Checklist	* Road test, confirm & quality check	17/01/2024	11082	Completed	Wodonga LHB	XW08GY	Wodonga P/MOVER	
1074	Wodonga - Workshop	Record Check Results As Attached To This Job		17/01/2024	11082	Completed	Wodonga LHB	XW08GY	Wodonga P/MOVER	
1074	Wodonga - Workshop	Tyre Position 3 + 4 POSITIONED THE TRUCK INTO THE WORKSHOP. REPALCED DAMAGED SUZI COILS & ABS LEAD CAUSE BY LEADS BEING CONNECTED WHEN TRUCK DROVE AWAY FROM TRAILER. RESECURED TRAILER LEAD TO NEW SUZI COILS.		11/01/2024		Completed	Wodonga LHB	XW08GY	Albury W P/MOVER	
1074	Wodonga - Workshop	RETURNED THE TRUCK TO SERVICE.		11/01/2024	5707	Completed	Wodonga LHB	XW08GY	Albury W P/MOVER	
1074	Wodonga - Workshop	Truck Pre-delivery		16/12/2023	614	Completed	Wodonga LHB	XW08GY	Wodonga P/MOVER	