EquipmentName	Workshop	Description	CompletionComments	DateDone	DistanceDone	Workstate	Division	Rego	Supplier	EquipmentType
		Replace Leaking L/H Steer Hub Seal								
1064	Wodonga - Workshop	(Parts Supplied By Maxi Parts P/O:	COMPLETED. S.McCABE	26/08/2026	700919	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	POWER PLUG NEEDED TO BE REPLACE	S.McCABE	07/08/2026	685867	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
		Frid Serv\AIR DRYER								
1064	Wodonga - Workshop	WW099151		20/07/2026	676763	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	Tyres\TP1+2	LOW	20/06/2026	663023	Completed	HCU	XW58CD	BORDER BANDAG PTY LTD	P/MOVER
1064	Wodonga - Workshop	Tyres\TP7+8		19/06/2026	663023	Completed	HCU	XW58CD	BORDER BANDAG PTY LTD	P/MOVER
1064	Wodonga - Workshop	Tyres\TP5+6		19/06/2026	663023	Completed	HCU	XW58CD	BORDER BANDAG PTY LTD	P/MOVER
1064	Wodonga - Workshop	Coolabah Cooler/Heater Cuts Out U/S	COMPLETED BY TP	10/06/2026	656223	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	Coolabah Bunk A/C is cutting out.	REPAIRED BY TP	10/06/2026	656223	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	COOLABAH BUNK COOLER HAS LEAKING REFRIGERANT HOSE	REPAIRED OK TP	10/06/2026	656223	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	BUNK COOLER NOT WORKING.	REPAIRED BY TP	10/06/2026	656223	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	Coolabah bunk battery/charger needs replacement.	INSPECT CHARGER TEST OK	10/06/2026	656223	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	AIRCON TO BE REGASSED	REPAIRED OK TP	10/06/2026	656223	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	VehService\AS A Service	COMPLETED BY TP JS SMc	10/06/2026	656223	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	VehService\AS A Service	completed by SMc	16/05/2026	644357	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	Timing case starting to leak engin oil	Monitor	17/04/2026	630597	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	VehService\AS A Service		17/04/2026	630597	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	CHECKER PLATE MISSING OVER CHASSIS RAIL		17/04/2026	630597	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	TURN/ WARNING BUZZER NOT WORKING		17/04/2026	630597	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	Fit New Deck Plate To Chassis (Checker Plate)		17/04/2026	630597	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	Insp\ANN INSP To Complete R/W within 12 months		17/04/2026	630597	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	NEEDS NEW ABS TRAILER PLUG FOR TRUCK.		19/03/2026	618604	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
			completed at 614,635kms							
1064	Wodonga - Workshop	A Service	SMc	19/03/2026	618604	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	HEATER & AIRCON NOT WORKING.		19/03/2026	618604	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	CHECK A/C GAS - STRUGGLES IN HOT WEATHER		19/03/2026	618604	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	LIGHTER NEEDS FIXING. NOT WORKING.		19/03/2026	618604	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	Diesel Tank Damaged		19/03/2026	618604	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	STEERS NEED TO BE CHECKED. SHAKING SOMETIMES.		19/03/2026	618604	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	OIL LEAK FRONT SUMP GASKET OR TIGHTEN.		19/03/2026	618604	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	HEATER TAP STUCK OR CONTROL UNIT NOT WORKING.		19/03/2026	618604	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	WEIGH GAUGES NOT WORKING.		19/03/2026	618604	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	Bunk cooler short's out on A/C mode.		19/03/2026	618604	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	Check A/C Gas, is struggling in hot weather.		19/03/2026	618604	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	Air Leak		19/03/2026	618604	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	COOLABAH BUNK BATTERY/ CHARGER NEEDS REPLACEMENT.		19/03/2026	618604	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	Vibration In Steering Wheel		19/03/2026	618604	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	CRUISE CONTROL NOT WORKING		19/03/2026	618604	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	steer tyres bad shakes		19/03/2026	618604	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	Exhaust Leak At Muffler Bracket		19/03/2026	618604	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	Front sway bar bushes oil soaked		19/03/2026	618604	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	All torque rod bushes worn		19/03/2026	618604	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	Sump gasket leaking		19/03/2026	618604	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	Tyres\Punct POS 5		13/03/2026	618603	Completed	HCU	XW58CD	BORDER BANDAG PTY LTD	P/MOVER
		DIFF SEALS.								
		TCTC- WARRANTY OR RE-WORK								
1064	Wodonga - Workshop	BLOWN FRONT DIFF PINION SEAL		25/02/2026	605541	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
		REAR OIL LEAK- POSSIBLE DIFF?								
		TCTC- WARRANTY OR RE-WORK								
1064	Wodonga - Workshop	BLOWN FRONT DIFF PINION SEAL		25/02/2026	605541	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
		Rear Oil Leak. Possible Diff.								
		TCTC- WARRANTY OR RE-WORK								
1064	Wodonga - Workshop	BLOWN FRONT DIFF PINION SEAL		25/02/2026	605541	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
		Front diff oil leak.								
		TCTC- WARRANTY OR RE-WORK								
1064	Wodonga - Workshop	BLOWN FRONT DIFF PINION SEAL		25/02/2026	605541	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
		DrivLine\DIFF OIL Replace Diff oils								
		TCTC- WARRANTY OR RE-WORK								
1064	Wodonga - Workshop	BLOWN FRONT DIFF PINION SEAL		25/02/2026	605541	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	VehService\CS C Service		11/02/2026	610083	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
		TCTC- WARRANTY OR RE-WORK								
1064	Wodonga - Workshop	BLOWN FRONT DIFF PINION SEAL		05/02/2026	605541	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	Tyres\TP11+12	CHANGED IN AUGUST BUT TYRES HAVE DONE	16/01/2026	599678	Completed	HCU	XW58CD	BORDER BANDAG PTY LTD	P/MOVER
1064	Wodonga - Workshop	Tyres\TP9+10	CHANGED IN AUGUST BUT TYRES HAVE DONE	16/01/2026	599678	Completed	HCU	XW58CD	BORDER BANDAG PTY LTD	P/MOVER
		DIAGNOSED AND REPLACED NOx SENSOR WITH PARTS FROM 1078.								
1064	Wodonga - Workshop	ARKON WW099055		16/01/2026	676763	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	Tyres\TP09		14/10/2025	555543	Completed	HCU	XW58CD	BORDER BANDAG PTY LTD	P/MOVER
1064	Wodonga - Workshop	Tyres\TP1+2		14/10/2025	555543	Completed	HCU	XW58CD	BORDER BANDAG PTY LTD	P/MOVER

		Repair Damaged Fuel Tank Strap.								
1064	Wodonga - Workshop	(G&S Diesel's P/O: WW097375		13/10/2025	600632	Completed	HCU	XW58CD	G & S DIESEL SERVICE	P/MOVER
1064	Wodonga - Workshop	AIR LEAK.		18/09/2025	562693	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	EXHAUST BRAKE LIGHT NOT WORKING		18/09/2025	562693	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	VehService\AS A Service		18/09/2025	562693	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	Tyres\TP5+6		28/08/2025	532623	Completed	HCU	XW58CD	BORDER BANDAG PTY LTD	P/MOVER
1064	Wodonga - Workshop	Tyres\TP7+8		28/08/2025	532623	Completed	HCU	XW58CD	BORDER BANDAG PTY LTD	P/MOVER
1064	Wodonga - Workshop	Tyres\TP9+10		28/08/2025	532623	Completed	HCU	XW58CD	BORDER BANDAG PTY LTD	P/MOVER
1064	Wodonga - Workshop	Tyres\TP11+12		28/08/2025	532623	Completed	HCU	XW58CD	BORDER BANDAG PTY LTD	P/MOVER
1064	Wodonga - Workshop	Drop Truck Off To TCTC And Pick Up From TCTC.		23/08/2025	529404	Completed	HCU	XW58CD	TWIN CITY TRUCK CENTRE - OLI	P/MOVER
		Rear diff needs reseal								
1064	Wodonga - Workshop	(TCTC Repaired Diff Leak Under Warranty @525,359 Klms)		23/08/2025	529404	Completed	HCU	XW58CD	TWIN CITY TRUCK CENTRE - OLI	P/MOVER
		Front diff Ned's reseal								
1064	Wodonga - Workshop	(TCTC Repaired Diff Leak Under Warranty @525,359 Klms)		23/08/2025	529404	Completed	HCU	XW58CD	TWIN CITY TRUCK CENTRE - OLI	P/MOVER
		Check For Diff Oil leak & Repair, Check Diff Oil Level.								
1064	Wodonga - Workshop	VAWDREY P/O: WW096420		20/08/2025	526431	Completed	HCU	XW58CD	VAWDREY AUSTRALIA PTY LTD	P/MOVER
1064	Wodonga - Workshop	Accidentally Broke Camera Tried To Adjust		09/08/2025	530615	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	VehService\BS B Service		20/07/2025	550660	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	SERVICE		20/07/2025	550660	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	Fuel Gauge Working Sometimes - Not Accurate		18/07/2025	550660	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	FUEL GAUGE WORKS WHEN FULL BUT FLUCTUATES AFTER HALF TANK.		18/07/2025	550660	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
		Elect\ALT (PO:WW095549)								
		AFTER HOURS CALL OUT TO TRAVEL TO THE BP SERVICE								
		STATION (INBOUND) TO CHECK AND REPORT ON								
		THE ALTERNATOR LIGHT STAYING ON.								
		LOW VOLTAGE ALSO.								
		DRIVER - 0417 000 671.								
		DATE 9-7-25								
		TRAVELLED TO SITE.								
		TESTED ALTERNATOR AND FOUND CHARGING AT 12.2V.								
		REMOVED REQUIRED HARDWARE.								
		SWAPPED OVER PULLEY TO NEW ALTERNATOR.								
		REFITTED REMOBED HARDWARE.								
		TESTED AND ALL OK.								
		12L LABOUR ENGINE ELECTRICAL								
		12L AFTER HOURS CALL OUT 200.00								
1064	Wodonga - Workshop	TRAVEL TRAVEL COSTS PER KM		14/07/2025	509324	Completed	HCU	XW58CD	HALLAM TRUCK CENTRE - HALL	P/MOVER
		Replace Damaged Suzie Leads.								
1064	Wodonga - Workshop	(Gilbert & Roach Huntingwood P/O: WW095622)		13/07/2025	554113	Completed	HCU	XW58CD	PACCAR PARTS FLEET SERVICES	P/MOVER
1064	Wodonga - Workshop	VehService\AS A Service		04/07/2025	504212	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
			-blown fuse for ACC socket							
			-faulty fuel sender							
1064	Wodonga - Workshop	Cigarette Lighter Not Work	-battery dying for coolaba system	04/07/2025	503093	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
		PROGRESS HEAVY VEHICLE REPAIRS.								
1064	Wodonga - Workshop	REPLACE REVERSE ALARM AS DIRECTED BY CUSTOMER.		24/06/2025	554113	Completed	HCU	XW58CD	PROGRESS HEAVY VEHICLE REP	P/MOVER
1064	Wodonga - Workshop	VehService\AS A Service		14/06/2025	488897	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	CLUTCH NEEDS ADJUSTMENT.		14/06/2025	488897	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	Front Left Hub Seal Leaking	Axle gasket leaking not hub. Cleaned and adju	21/05/2025	474171	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
		A Service.								
		Serviced @ 461,780 Klms								
1064	Wodonga - Workshop			02/05/2025	465825	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	Steering Wheel Tilt Adjuster NOT Working.	Adjusted tilt shock and changed cable	02/05/2025	465825	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	PICKED UP FROM TCTC.		01/05/2025	465825	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
		VehService\BS								
1064	Wodonga - Workshop	PO TCTC #WW093227		15/04/2025	456587	Completed	HCU	XW58CD	PACCAR PARTS FLEET SERVICES	P/MOVER
1064	Wodonga - Workshop	Insp\ANN INSP		15/04/2025	456587	Completed	HCU	XW58CD	PACCAR PARTS FLEET SERVICES	P/MOVER
1064	Wodonga - Workshop	Front Diff Leaking		15/04/2025	456587	Completed	HCU	XW58CD	PACCAR PARTS FLEET SERVICES	P/MOVER
		Coolabah Not Working								
1064	Wodonga - Workshop	TCTC inspected		15/04/2025	456587	Completed	HCU	XW58CD	PACCAR PARTS FLEET SERVICES	P/MOVER

		DrivLine\WHEEL SEAL WHILST CARRYING OUT SERVICE, FOUND LH STEER HUB SEAL BLOWN . * Ballast axle & removed wheel end equipment * Removed hub & drum assembly * Found brakes to be contaminated * Removed brakes & cleaned down all components * Installed replacement brake shoes * Checked bearings - All ok * Refit hub with replacement seal * Refit drum & wheel end equipment * Aligned, adjusted & tensioned all components							
1064	Wodonga - Workshop	* Test operations - All ok, fault no longer present		15/04/2025	456587	Completed	HCU	XW58CD	PACCAR PARTS FLEET SERVICES	P/MOVER
		Engine\ENG TUNE Engine rattle at front WHILST ENGINE STRIPPED & RADIATOR REMOVED, FOUND HORTON TO BE LOW . * Stripped down horton assembly * Rebuilt horton assembly * Installed horton, fan & all other components as required							
1064	Wodonga - Workshop	* Test operations - All ok		15/04/2025	456587	Completed	HCU	XW58CD	PACCAR PARTS FLEET SERVICES	P/MOVER
		Engine\RADIATOR WHILST RADIATOR REMOVED, FOUND REQUIRES DE-BUG . * Wash/clean radiator assembly complete * Wash/clean AC, CAC hoses & pipes * Wash/clean engine & components complete * Installed radiator complete * Installed AC, CAC hoses & pipes * Install CAC assembly * Replaced coolant * Secured all hoses, pipes & components * Pressure test cooling system							
1064	Wodonga - Workshop	* Road test, confirm & quality check repair		15/04/2025	456587	Completed	HCU	XW58CD	PACCAR PARTS FLEET SERVICES	P/MOVER
		DriCabRep\HOUSEKEEP RH CAB RAM LEAKING . * Ballast cab weight * Removed components for access * Disconnected lines * Unbolted & removed cab ram * Swapped all fittings Installed replacement cab ram & connected all lines * Aligned, adjusted & tensioned all components to specifications * Topped up fluids & bled system as required							
1064	Wodonga - Workshop	* Test operations - All ok, fault no longer presen		15/04/2025	456587	Completed	HCU	XW58CD	PACCAR PARTS FLEET SERVICES	P/MOVER
1064	Wodonga - Workshop	Drop Truck Off To TCTC		12/04/2025	464495	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	Tyres\TP1+2		12/04/2025	464071	Completed	HCU	XW58CD	BEAUREPAIRES	P/MOVER
1064	Wodonga - Workshop	Aftertreat on		10/04/2025	462553	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	Truck had a miss then lost power on hills rectified itself after being shut down c	Sent to TCTC. TCTC couldn't fault	10/04/2025	462553	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	DrCabElect\IAP TRACKER NOT WORKING		04/04/2025	462564	Completed	HCU	XW58CD	ARKON AUTO ELECTRICAL	P/MOVER
		A Service. Serviced @ 455,456 Klms.								
1064	Wodonga - Workshop			29/03/2025	454201	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	CHECK TURNTABLE JAWS FOR ADJUSTMENT.	Checked Turn Table Adjustment & Greased.	29/03/2025	454201	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
		VehService\AS Carried out A service and Suspension check on 22/02/2025 as per service								
1064	Wodonga - Workshop	sheets required		13/03/2025	443873	Unlocked	HCU	XW58CD	PACCAR PARTS FLEET SERVICES	P/MOVER
		Steering\WHEEL HUB WHILST CARRYING OUT SERVICE, FOUND RHF DRIVE HUB SEAL FAILED . * Ballast axle * Removed wheel end equipment * Removed drum & hub assembly * Found brake shoes contaminated with oil * Removed brake shoes & cleaned down all components * Installed replacement brake shoes * Inspected bearings & found also to be worn * Removed & replaced bearings							
1064	Wodonga - Workshop	* Refit hub assembly with replacement seal as required		13/03/2025	443873	Completed	HCU	XW58CD	PACCAR PARTS FLEET SERVICES	P/MOVER

1064	Wodonga - Workshop	Turn table Needs adjusting.		01/03/2025	435464	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	Steering wheel won't adjust back and forth.		01/03/2025	435464	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	Fit New Mattress. Windscreen Cracked.		22/02/2025	427442	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	Autoscreen to do		25/01/2025	418162	Completed	HCU	XW58CD	AUTOTEK AUSTRALIA	P/MOVER
1064	Wodonga - Workshop	VehService\AS		24/01/2025	418162	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	Check & Test All Batteries, Check Charge Rate, Replace If Needed. (G&S Diesel F Engine\FUEL TANK BREAKDOWN REPAIR . The following breakdown repair for Greenfreight Distribution Pty Ltd, to a Kenworth K220, vin#6F5000000NA483088, registration#XW58CD & fleet number#1064 included: . * Customer contacted dealership breakdown technician with information regarding breakdown * Customer advised that fuel was leaking * Technician travelled to customer depot, Wodonga * Inspected to diagnose * Located leaking fuel rail relief valve * Inspect & located missing washer (evidence that someone has changed this before) * Installed replacement fuel relief valve & washer * Cleaned down fuel contamination * Start, monitor & confirmed repair * Returned truck to service		31/12/2024	554113	Completed	HCU	XW58CD	G & S DIESEL SERVICE	P/MOVER
1064	Wodonga - Workshop	* Technician returned home		10/12/2024	400561	Completed	HCU	XW58CD	PACCAR PARTS FLEET SERVICES	P/MOVER
1064	Wodonga - Workshop	Tyres\TP5+6		10/12/2024	399669	Completed	HCU	XW58CD	BEAUREPAIRES	P/MOVER
1064	Wodonga - Workshop	Tyres\TP9+10		10/12/2024	399669	Completed	HCU	XW58CD	BEAUREPAIRES	P/MOVER
1064	Wodonga - Workshop	Tyres\TP3+4		10/12/2024	399669	Completed	HCU	XW58CD	BEAUREPAIRES	P/MOVER
1064	Wodonga - Workshop	Tyres\TP7+8		10/12/2024	399669	Completed	HCU	XW58CD	BEAUREPAIRES	P/MOVER
		SAT. CHECK A/C N/W TRAVEL TO GREEN FRIEGHT CHECK A/C HOOK UP GAUGES FOUND GAS IN SYSTEM FOUND HI PRESSURES FOUND HORTON FAN NOT ENGAGING DIAGNOSE FAULTY HORTON PRESSURE SWITCH DEGAS AC SYSTEM								
1064	Wodonga - Workshop	REMOVE AND REPLACE RECEIVER DRIER AND HORTON PRESSURE SWITCH	Right hand	08/12/2024	395283	Completed	HCU	XW58CD	HAGANS AUTO ELECTRICAL SEF	P/MOVER
1064	Wodonga - Workshop	service	1395283 Right hand cab ram leak8ng Front diff is not leak8ng through shaft input shaft and banjo are dry Breather was leak8ng Underneath needs a wash as does engine Tctc coming out to repair leak8ng fuel rail under warranty	07/12/2024	399326	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	C Service	Sump leak8ng	07/12/2024	399326	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	Truck Won't Start. Air Con\AIR CON	Traveled to yard, jacked over cabin, checked b Diagnose coolibah charging system, Coolibah battery faulty. Shaun to organise repair Job started at 10 finished 12:30	02/12/2024	394622	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	COOLABAH NOT WORKING		29/11/2024	394621	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	Tyres\TP1+2		29/10/2024	376099	Completed	HCU	XW58CD	BEAUREPAIRES	P/MOVER
1064	Wodonga - Workshop	Job Created from Purchase Order #: 105094		18/10/2024	368719	Completed	HCU	XW58CD	CUMMINS SOUTH PACIFIC P/L	P/MOVER
1064	Wodonga - Workshop	Check oil leaks around diffs	Warranty tctc	09/09/2024	346334	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	VehService\AS	342289ks	09/09/2024	346334	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	A Service		09/09/2024	346334	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	Front diff leak	Warranty tctc	09/09/2024	346334	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	B-Service Due @ 302500	Cherysh completed B Service on the 13/8/202	06/09/2024	345571	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	B Service		13/08/2024	329339	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	Front Diff has Oil Leak Somewhere ,Possible Breather.		13/08/2024	329339	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	Alternator Charging Output ?	Has been replaced by twin city	13/08/2024	329339	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER

1064	Wodonga - Workshop	ABS Light Comes On When Plugged into A Trailer.		13/08/2024	329339	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	A-Service Due @ 312500		13/08/2024	329339	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	Batteries Flat/ Jump Start.	Completed	12/08/2024	329275	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	A Service Serviced @ 296354 on 21/06/24		10/08/2024	328726	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	Check & Test Batteries Replace If Needed	Truck needs to go to tctc for warranty replace	03/07/2024	303012	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	B Service Service Done @ 292994 Klms		28/05/2024	292994	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	DIFF OIL IS DIRTY	REPLACED	25/04/2024	260003	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	DrivLine\DIFF OIL Replace Diff oils	REPLACED DUE TO BEING REPORTED DIRTY	25/04/2024	260003	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	Record Check Results As Attached To This Job		25/04/2024	260003	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	PERNAMENT POWER SOCKET NEEDED UNDER PASSENGER SEAT.		25/04/2024	260003	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	A Service As Per Attached Checklist	DIAGNOSED AND REPAIRED DASH AIR LEAK. TI	25/04/2024	260003	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	locate and repair air leak in suspension	REPAIRED LEAK IN DASH.	25/04/2024	260003	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	REPLACED EBS CABLE.		22/03/2024		Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	Record Check Results As Attached To This Job		20/03/2024	237751	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	RH CAB RAM LEAKING.		20/03/2024	237751	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	REPLACE MISSING JACK.		20/03/2024	237751	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	PERNAMENT POWER SOCKET NEEDED UNDER PASSENGER SEAT.		20/03/2024	237751	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	STEERING STARTING TO SHAKE/ TYRES.		20/03/2024	237751	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	STEERING HAS GOT THE SHAKES / TYRES.		20/03/2024	237751	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	BRAKE ADJUSTMENT.		20/03/2024	237751	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	B Service As Per Attached Checklist		20/03/2024	237751	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	A-SERVICE DUE.		20/03/2024	237751	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	REAR DIFF BANJO SEAL LEAKING.		20/03/2024	237751	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	Tyre Position 1 + 2		25/02/2024		Completed	HCU	XW58CD	Albury Workshop	P/MOVER
1064	Wodonga - Workshop	Tyre Position 7 + 8		25/02/2024		Completed	HCU	XW58CD	Albury Workshop	P/MOVER
1064	Wodonga - Workshop	Tyre Position 9 + 10		25/02/2024		Completed	HCU	XW58CD	Albury Workshop	P/MOVER
1064	Wodonga - Workshop	Tyre Position 5 + 6		13/02/2024		Completed	HCU	XW58CD	Albury Workshop	P/MOVER
1064	Wodonga - Workshop	Tyre Position 3 + 4		13/02/2024		Completed	HCU	XW58CD	Albury Workshop	P/MOVER
1064	Wodonga - Workshop	Record Check Results As Attached To This Job		26/01/2024	210657	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	REPLACE MISSING JACK.		26/01/2024	210657	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	PERNAMENT POWER SOCKET NEEDED UNDER PASSENGER SEAT.		26/01/2024	210657	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	STEERING STARTING TO SHAKE/ TYRES.		26/01/2024	210657	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	A Service As Per Attached Checklist		26/01/2024	210657	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	Record Check Results As Attached To This Job		23/12/2023	190360	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	FRONT DIFF LEAKING	CLEANED BREATHER.	23/12/2023	190360	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	REPLACE MISSING JACK.		23/12/2023	190360	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	A Service As Per Attached Checklist		23/12/2023	190360	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	RH CAB RAM LEAKING.		23/12/2023	190360	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	PICKED UP TCTC.		08/12/2023		Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	C Service As Per Attached Checklist		07/12/2023	180455	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	Record Check Results As Attached To This Job		07/12/2023	180455	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	Reattach Broken Fire Extinguisher Bracket		07/12/2023	180455	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	FIT TRUCKSAFE STICKER.		07/12/2023	180455	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	C Service 160000?		07/12/2023	180455	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	FRONT DIFF LEAKING		07/12/2023	180455	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	REPLACE MISSING JACK.		07/12/2023	180455	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	A Service 153450?		07/12/2023	180455	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	SERVICE???		07/12/2023	180455	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	FAULTY DOOR SWITCH, SETS OFF BRAKE ALARM.	REPAIRED BY TCTC UNDER WARRANTY.	26/11/2023	173758	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	PERNAMENT POWER SOCKET NEEDED UNDER PASSENGER SEAT.		26/11/2023	173758	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	NEEDS CLUTCH ADJUST AND CABLE SHIFT ADJUSTMENT.		26/11/2023	173758	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	CLUTCH REQ ADJUSTMENT.		26/11/2023	173758	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	Oil Leak Somewhere Near The Front Diff	WASHED OFF FRONT & CHASSIS. ROAD TESTEI	26/11/2023	173758	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	Record Check Results As Attached To This Job		08/10/2023	143550	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	Reattach Broken Fire Extinguisher Bracket		08/10/2023	143550	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	FAULTY DOOR SWITCH, SETS OFF BRAKE ALARM.		08/10/2023	143550	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	PERNAMENT POWER SOCKET NEEDED UNDER PASSENGER SEAT.		08/10/2023	143550	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	NEEDS CLUTCH ADJUST AND CABLE SHIFT ADJUSTMENT.		08/10/2023	143550	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	CLUTCH REQ ADJUSTMENT.		08/10/2023	143550	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	B Service As Per Attached Checklist		08/10/2023	143550	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	SERVICE???		08/10/2023	143550	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	FIT TRUCKSAFE STICKER.		08/10/2023	143550	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	1-10		20/08/2023		Completed	HCU	XW58CD	Albury Workshop	P/MOVER
1064	Wodonga - Workshop	DrivLine\DIFF OIL Replace Diff oils	D.LOUGHMAN	11/08/2023	93294	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	VehService\AS A Service B Service	D.LOUGHMAN	11/08/2023	93294	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	Serviced @ 75254 Klms		15/07/2023	516663	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	Adjust Clutch		12/07/2023	88452	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER

		Engine Failure Cummins to Repair								
1064	Wodonga - Workshop	Under Warranty		12/05/2023	302421	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	1-10		10/05/2023		Completed	HCU	XW58CD	Albury Workshop	P/MOVER
1064	Wodonga - Workshop	Tyre Position 7 + 8		27/04/2023		Completed	HCU	XW58CD	Albury Workshop	P/MOVER
1064	Wodonga - Workshop	Record Check Results As Attached To This Job		25/04/2023	52606	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	Reattach Broken Fire Extinguisher Bracket		25/04/2023	52606	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	FAULTY DOOR SWITCH, SETS OFF BRAKE ALARM.		25/04/2023	52606	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	PERNAMENT POWER SOCKET NEEDED UNDER PASSENGER SEAT.		25/04/2023	52606	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	A Service As Per Attached Checklist		25/04/2023	52606	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	MADE TRAILER LIGHTS ADAPTOR.		13/03/2023		Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
			ATTEND AFTERHOURS BREAKDOWN SARGENTS RD MINCHINBURRY CHECK AND REPORT TRUCK NOT STARTING NOT CRANKING SUBLET - AFTER HOURS CALL OUT MINCHINBURY.							
		Will Not Start Flat Batteries Not Warranty as driver left something on to drain batteries.	CHECKED FOR CAUSE OF NO START. FOUND FLAT BATTERIES. JUMP STARTED VEHICLE.							
1064	Wodonga - Workshop	PO# WW077453	CHECKED CHARGING.ALL OK	03/03/2023		Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	Record Check Results As Attached To This Job		19/02/2023	19568	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	Reattach Broken Fire Extinguisher Bracket		19/02/2023	19568	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	A Service As Per Attached Checklist		19/02/2023	19568	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	PICKED UP TCTC.		05/02/2023	12183	Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
		***COMPLIMENTARY NO CUSTOMER LABOUR CHARGE KENWORTH TRUCK 1st SERVICE POLICY ***	specification used in parts section below. * Check all engine operation & components * Removed/replaced transmission oil filter * Check all hydraulic lines fitting & level lubricant levels to specification * Removed/replaced power steering filter & gasket * Removed/replaced differential oil, specification used in parts section below. * Removed/replaced fuel filter * Check cooling system & pressure test * Check all belts, idler pulleys, fan, shrouds & adjust to specification * Check all electrical routing, wiring looms, switches, sensors & components * Check all wheel equipment & steering components * Check all braking & adjust to specification * Check clutching & adjust to specification * Check all suspension components * Check all internal cabin operation, components & adjust to specification * Check all external cabin components & adjust to specification * Check windscreen washers, wipers, refill & test operation							
1064	Wodonga - Workshop	***CUSTOMER RESPONSIBLE FOR ALL PARTS REQUIRED FOR 1st SERVICE***	* Lubricate, adjust relevant components as	22/01/2023	10998	Completed	HCU	XW58CD	Albury Workshop	P/MOVER
1064	Wodonga - Workshop	New Truck Pre Delivery		06/01/2023		Completed	HCU	XW58CD	Wodonga Workshop	P/MOVER
1064	Wodonga - Workshop	Tyre Position 3 + 4		16/12/2022		Completed	HCU	XW58CD	Albury Workshop	P/MOVER
1064	Wodonga - Workshop	Tyre Position 5 + 6		16/12/2022		Completed	HCU	XW58CD	Albury Workshop	P/MOVER
1064	Wodonga - Workshop	Tyre Position 7 + 8		16/12/2022		Completed	HCU	XW58CD	Albury Workshop	P/MOVER
1064	Wodonga - Workshop	Tyre Position 9 + 10		16/12/2022		Completed	HCU	XW58CD	Albury Workshop	P/MOVER