EquipmentName	Workshop	CodeAndSubCode	Description	Schedule	CompletionComments	DateDone	DistanceDone	Worktype	Workstate	EquipmentOwner	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
1072	Wodonga - Workshop	VehService\AS	VehService\AS A Service	VehService\AS		07/09/2026	472010	Service	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	BOAG'S DIESEL MECHANICS	P/MOVER
					Removed necesisary components to access the front differential input/pinion shaft seal. Removed and replaced leaking input shaft seal with new seal. Reassembled all components, checked differential oil level and topped up as required.											
1072	Wodonga - Workshop	DrivLine\DAMAGE	front diff pinion leaking oil		Cleaned affected area and checked for leaks following repairs – all OK at time of insoection.	07/09/2026	472010	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	BOAG'S DIESEL MECHANICS	P/MOVER
1072	Wodonga - Workshop	VServLab	SERVICE			07/08/2026	454067	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	Susp\SUSPENSION	FRONT END HAS MOVEMENT CHECK PINS BUSHES			07/08/2026	454067	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	Engine\FAULT CODE	ENGINE CHECK LIGHT COMING ON.			07/08/2026	454067	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	DrivLine\TAIL SHAFT	gearbox yoke loose			07/08/2026	454067	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	VehService\BS	B Service Serviced @ 454,171 Klms	VehService\BS		07/08/2026	454067	Service	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
					Labour - Mobile - Breakdown Travelled to Tamworth Located and inspected unit Jacked over cab Found an air leak Carried out repairs Started and tested - all good Lowered cab											
1072	Wodonga - Workshop	DrivLine\AIR LEAK	BREAKDOWN-AIR LEAK AT GEARBOX		Packed away and returned home	02/08/2026	451355	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	WARREGO TRANSPORT REPAIRS	P/MOVER
1072	Wodonga - Workshop	VehService\AS	A Service	VehService\AS	completed by SMc KR	19/06/2026	426288	Service	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	DrCabElect\INDICATORS	Indicator's keep tripping fuse out when trailer is plugged in.		Trailer Plug Been Repaired ok	19/06/2026	426288	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	DrivLine\DIFF OIL	Both Diff's are leaking		SMc KR ok	19/06/2026	426288	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	Cooling\RADIATOR	leaking heater tap on side of block		SMc KR ok	19/06/2026	426288	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	DrCabElect\CONSUMABLE	Engine brake light still not working.		SMc KR ok	19/06/2026	426288	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	DrCabElect\INST/GAUGE	cruise light globe		SMc KR ok	19/06/2026	426288	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	Cooling\ENG FAN	horton fan stuck on		Horton Fan Repaired By TCTC ok	19/06/2026	426288	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	DrCabElect\INST/GAUGE	engine brake light globe		SMc KR ok	19/06/2026	426288	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	DrCabElect\CONSUMABLE	Cruise control light still not working.		SMc KR ok	19/06/2026	426288	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	DrCabRep\MOUNTS	Front end squeaking, driver think's that it is NOT getting greased enough.		SMc KR ok	19/06/2026	426288	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	Susp\AIR FITTIN	Air tank drain cable need's to be fixed/replaced.		SMc KR	19/06/2026	426288	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	Brakes\BRK RELINE	Brake Reline Rear Axle.		completed by JS 55	18/06/2026	426288	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	Susp\SUSPENSION	Grease front spring's.		completed by EC	16/06/2026	424427	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	Brakes\BRAKE ADJ	Adjust Brake's		completed by EC	16/06/2026	424427	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	Engine\BATTERY	Engine\BATTERY WW133883		4 NEW BATTERIES	18/05/2026	409639	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	REGIONAL BATTERY SUPPLIES	P/MOVER
1072	Wodonga - Workshop	Body\FIFTH WHEE	Turn table need's adjusting.		no grease in ball race greased JS CP	18/05/2026	416096	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	Engine\COOL LEAKS	Leaking heater Tap @ side of engine block.			18/05/2026	416096	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	DrCabElect\INST/GAUGE	Engine brake light globe and cruise light globe are Not working and need to be replaced.		completed	18/05/2026	416096	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	DrCabElect\INST/GAUGE	ENGINE BRAKE LIGHT NOT WORKING		completed by JS	18/05/2026	416096	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	DrCabElect\INST/GAUGE	CRUISE LIGHT NOT WORKING		completed by JS CUSTOMER REPORTS HORTON IS OPERATING ERRATIC.. DIAGNOSE/QUOTE AND REPAIR. . * Ran engine and monitored horton operation, Confirmed erratic operation on/off. * Visually inspected wiring for faults, no visual faults found. * Shook wiring in sections to pin point wiring fault. * Found section of wiring near engine oil filler area to be the fault. * Stripped back wiring section to expose. * Found broken wire. * Cut out wire section at fault. * Soldered in new section of wire and heat shrink/wrapped. * Wrapped wiring section back up with tape. * Cable tied wiring section back in place. * Ran engine and tested horton operation, All ok. * Test drive and monitored horton operation, All ok.	18/05/2026	416096	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	Cooling\ENG FAN	Horton fan is stuck on WW133815		* Repair completed	18/05/2026	409666	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	Cooling\ENG FAN	Fan keep's coming on, turn fan off then fan comes back on again.		completed by JS TP	07/05/2026	403718	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	DrCabElect\BATTERY	Jump start [battery's flat]			27/04/2026	401515	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	VehService\BS	VehService\BS B Service	VehService\BS		15/04/2026	397746	Service	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	DrivLine\CLUTCH	ADJUST CLUTCH			15/04/2026	397746	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	Elect\ELECT P&W	Light's keep tripping out in fuse box when plugging in.			15/04/2026	397746	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	Prevent\TRANS OIL	Prevent\TRANS OIL	Prevent\TRANS OIL		15/04/2026	397746	PreventativeMaintenance	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	Tyres\TP1+2	Tyres\TP1+2			08/04/2026	397698	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	BORDER BANDAG PTY LTD	P/MOVER
					Checked ign system on tracking unit. Found no ign to tracking unit. Removed overhead console and found ign wire was pulled out of terminal. Crimped and soldered new terminal on and tested. Put console back.											
1072	Wodonga - Workshop	DrCabElect\ELECT P&W	DrCabElect\ELECT P&W RH SCREEN CRACKED		Trackine unit now workine	28/03/2026	389595	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	ARKON AUTO ELECTRICAL	P/MOVER
1072	Wodonga - Workshop	DrCabRep\WINDSCREEN	PO created WW092548			14/03/2026	344068	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	AUTOTEK AUSTRALIA	P/MOVER
1072	Wodonga - Workshop	DrivLine\CLUTCH	Adjust Clutch.			11/03/2026	344068	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	DrivLine\DIFF OIL	DrivLine\DIFF OIL	DrivLine\DIFF OIL		07/03/2026	344068	PreventativeMaintenance	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	Prevent\STEER W/B	Prevent\STEER W/B	Prevent\STEER W/B		07/03/2026	344068	PreventativeMaintenance	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	VehService\CS	VehService\CS	VehService\CS	completed at 382,638 km SMc EC	07/03/2026	344068	Service	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
					Jump Started Checked Batteries & Charge Rate All Good Batteries Went Flat Due To Fridge & Accessories being Left On.											
1072	Wodonga - Workshop	Elect\BATTERY	Flat Batteries		(After Hours Call Out Done By Blokes Repairs & Maintenance.)	27/12/2025	344068	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	VehService\AS	VehService\AS A Service	VehService\AS		13/12/2025	344068	Service	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	DrCabRep\WINDSCREEN	both screens chipped			22/11/2025	334287	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	Susp\SUSPENSION	BANGING IN FRONT END			22/11/2025	334287	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	VehService\AS	VehService\AS A Service	VehService\AS		22/11/2025	334287	Service	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	DrCabRep\WINDSCREEN	BOTH SCREENS CHIPPED			22/11/2025	334287	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	VServLab	SERVICE			22/11/2025	334287	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	Cooling\RADIATOR	RADIATOR/ INTERCOOLERS NEED CLEAN			22/11/2025	334287	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	DrCabElect\INST/GAUGE	CRUISE LIGHT GLOBE BLOWN			22/11/2025	334287	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	Chassis\FIFTH WHEE	Excessive play in turn table bushes			22/11/2025	334287	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	Air Con\AIR CON	AC not working			22/11/2025	334287	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	VServLab	A SERVICE			22/11/2025	334287	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	Elect\HEAD LIGHT	Broken front left quater Guard headlights not working.			22/11/2025	334287	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
					Labour - Mobile - Breakdown Travelled to Acco Australia Reconnected the 7 pin plug											
1072	Wodonga - Workshop	Elect\ELECT P&W	Elect\ELECT P&W WW097377		Checked laht operation - All ok Labour - Mobile - After Hours Breakdown Travelled to Yass Service Centre Located & inspected vehicle Reported to have ripped trailer plug apart Found that A trailer curtain ratchet had become caught up on cable and pulled the wires out while navigating tight turns	14/10/2025	317496	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	WARREGO TRANSPORT REPAIRS	P/MOVER
1072	Wodonga - Workshop	Elect\SUZI COIL	Elect\SUZI LEADS WW097376 Driver Side Windscreen Cracked.		Re wired plug as required and reset suz leads with cable ties so not to catch on ratchet aeain	14/10/2025	317496	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	WARREGO TRANSPORT REPAIRS	P/MOVER
1072	Wodonga - Workshop	Body\WINDSCREEN	(Autotek P/O: WW097361			11/10/2025	316074	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	AUTOTEK AUSTRALIA	P/MOVER
1072	Wodonga - Workshop	DrCabElect\INST/GAUGE	Warning Buzzer Not work		Checked buzzer found it had been disconnected, removed lower dash panel, reconnected warning buzzer, tested all good, refitted lower dash panels.	07/10/2025	313660	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	Elect\HEAD LIGHT	FIT HEADLIGHT PROTECTORS.			30/09/2025	311105	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	Body\PANELS	REPLACE MISSING CHECKER PLATE.			30/09/2025	311105	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	DrCabRep\DOOR LOCK	FIT RH DOOR RUBBER. AC NOT WORKING -ARKON AUTO ELEC TO COMPLETE			30/09/2025	311105	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	Air Con\AIR CON	WW097180 Repair Accident Damage (Roo Strike)			30/09/2025	311105	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	Body\DAMAGE	(Complete Body Craft P/O: WW096172)			06/09/2025	344068	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	COMPLETE BODY CRAFT	P/MOVER
1072	Wodonga - Workshop	Tyres\TP5+6	Tyres\TP5+6			23/08/2025	309653	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	BORDER BANDAG PTY LTD	P/MOVER
1072	Wodonga - Workshop	Tyres\TP11+12	Tyres\TP11+12			23/08/2025	309653	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	BORDER BANDAG PTY LTD	P/MOVER
1072	Wodonga - Workshop	Tyres\TP7+8	Tyres\TP7+8			23/08/2025	309653	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	BORDER BANDAG PTY LTD	P/MOVER
1072	Wodonga - Workshop	Tyres\TP9+10	Tyres\TP9+10			23/08/2025	309653	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	BORDER BANDAG PTY LTD	P/MOVER
1072	Wodonga - Workshop	DrCabRep\ELECT P&W	Fit Anderson plug in cab.		-live anderson plug mounted on passenger seat with ACC socket remounted	04/08/2025	308528	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	Brakes\BRK RELINE	Brakes\BRK RELINE Middle & Rear axle both sides			28/07/2025	309653	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	Chassis\FIFTH WHEE	Turntable pins have excecdive movement			28/07/2025	309653	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	Insp\ANN INSP	Insp\ANN INSP	Insp\ANN INSP		28/07/2025	309653	PreventativeMaintenance	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	DrCabElect\ELECT P&W	NEW IGNITION KEY.		Could not fault key or ignition during service	28/07/2025	309653	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	Susp\WHEEL ALGN	DESTROYING ANOTHER SET OF STEER TYRES.			28/07/2025	309653	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	VehService\BS	VehService\BS B Service	VehService\BS		28/07/2025	309653	Service	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	Susp\HOUSEKEEP	Truck air bags need to be reset			28/07/2025	309653	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	DrCabElect\INST/GAUGE	weight gauges needs replacing			28/07/2025	309653	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	DrCabRep\WIPERS	change windscreen wipers			28/07/2025	309653	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	Brakes\BRK RELINE	Drive brakes all due for reline - Under warranty			28/07/2025	309653	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	VehService\AS	VehService\AS A Service	VehService\AS	Find all info of serviceable and faults on b service paperwork	28/07/2025	309653	Service	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	Body\HOUSEKEEP	Banging in front end		Front cabmounts worn	28/07/2025	309653	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	DrivLine\CTCH PACK	clutch adjustment Tyres\Puncture REPAIR & CALL OUT POS 12		Adjusted clutch	10/07/2025	299099	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	Tyres\Punct				30/06/2025	291283	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	BORDER BANDAG PTY LTD	P/MOVER
1072	Wodonga - Workshop	VehService\AS	VehService\AS A Service alternator light flashing on-off check.	VehService\AS		14/06/2025	282671	Service	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	Engine\ALT	(Brown & Hurley Coffs Harbour P/O: WW094453)			27/05/2025	344068	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	PACCAR PARTS FLEET SERVICES	P/MOVER
1072	Wodonga - Workshop	Tyres\ROTATION	Tyres\ROTATION 1-2 steer & 3-10 drive Drivers side cupboard in bunk fallen off wall.			22/05/2025	266711	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	BEAUREPAIRES	P/MOVER
1072	Wodonga - Workshop	DrCabRep\DAMAGE	(Ultimate Fasteners P/O: WW094248)		REPAIRED DRIVER AND PASSENGER SIDE CUPBOARDS.	20/05/2025	265586	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	VehService\AS	VehService\AS A Service	VehService\AS		10/05/2025	260585	Service	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	Brakes\BRK RELINE	Check brakes next service possible reline FRONT DIFF PUMPING OIL OUT THE BREATHER.		NOT CRITICAL	10/05/2025	260585	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	DrivLine\OIL LEAK	Dana supplied updated breather- installed GF to monitor.			02/04/2025	257181	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	PACCAR PARTS FLEET SERVICES	P/MOVER
1072	Wodonga - Workshop	VehService\BS	VehService\BS	VehService\BS		02/04/2025	257181	Service	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	PACCAR PARTS FLEET SERVICES	P/MOVER

			Engine\BELTS/TENS WHILST CARRYING OUT SERVICE, FOUND BELTS TO BE WORN * Removed & replaced belts as required * Aligned, adjusted & tensioned all components														
1072	Wodonga - Workshop	Engine\BELTS/TENS				02/04/2025	237181	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	PACCAR PARTS FLEET SERVICES	P/MOVER
			VehService\AS A Service														
1072	Wodonga - Workshop	VehService\AS	TCTC PO WWW093236 ALTERNATOR LIGHT ON (INTERMITTENT) REPORTS BUNK COOLER NOT CHARGING CORRECTLY * Inspected alternator & battery wiring - All ok * Started truck & checked alternator * Found charge rate at alternator to be at 12.8V - 13V * Removed coolabah power supply from alternator & found charge rate to increase to 14V * Suspect alternator charge not enough when coolabah battery flat or using coolabah overnight * Possibly require upgraded alternator	VehService\AS		02/04/2025	236365	Service	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	PACCAR PARTS FLEET SERVICES	P/MOVER
1072	Wodonga - Workshop	Elect\ALT	* Customer to monitor			02/04/2025	236365	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	PACCAR PARTS FLEET SERVICES	P/MOVER
1072	Wodonga - Workshop	DrCabElect\ELECT P&W	BUNK COOLER BATTERY DOESN'T CHARGE PROPERLY.			02/04/2025	236365	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	PACCAR PARTS FLEET SERVICES	P/MOVER
1072	Wodonga - Workshop	Tyres\TP3+2	Tyres\TP3+2			14/03/2025	227948	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	BEAUREPAIRES	P/MOVER
1072	Albury - Workshop	Brakes\BRAKE ADJ	adjust drive brakes please		Brakes were in need of adjustment.....Out by more than galf a turn	21/02/2025	210596	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Albury - Workshop	VehService\AS	VehService\AS	VehService\AS	210596ks	21/02/2025	210596	Service	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	Susp\AIR FITTIN	Suzi to be Replaced			07/02/2025	202218	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	Body\HOUSEKEEP	Drivers Weather Shield Please			07/02/2025	202218	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	Steering\WHEEL ALGN	Still Pulling Left and Wandering in the Drive.		Not pulling any more still wondering in back end	07/02/2025	202218	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	DrCabRep\DOOR LOCK	DRIVER'S WEATHER SHIELD PLEASE. suzi coil need replacing		Been done	07/02/2025	202218	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	Chassi\SUZI COIL	(sleave out my ioiners back in truck)		Keith reolaced	07/02/2025	202218	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonana	LHB	XW06GY	Wodonwa Workshoo	P/MOVER
1072	Wodonga - Workshop	VehService\AS	VehService\AS	VehService\AS	Replace dip stick as broken	07/02/2025	202218	Service	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	Tyres\ROTATION	ROTATE DRIVE TYRES.		COMPLETED UNDER WORK ORDER #193851	07/02/2025	202218	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	Tyres\TP7+8	Tyres\TP7+8			05/02/2025	200396	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	BEAUREPAIRES	P/MOVER
1072	Wodonga - Workshop	Tyres\TP9+10	Tyres\TP9+10			05/02/2025	200396	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	BEAUREPAIRES	P/MOVER
1072	Wodonga - Workshop	Tyres\TP7+8	Tyres\TP7+8			23/01/2025	191410	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	BEAUREPAIRES	P/MOVER
1072	Wodonga - Workshop	Tyres\TP9+10	Tyres\TP9+10 VehService\CS			23/01/2025	191410	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	BEAUREPAIRES	P/MOVER
1072	Wodonga - Workshop	VehService\CS	TCTC comoletine work	VehService\CS		07/01/2025	178656	Service	Completed	FL Green Distribution	KWX15HWY	Wodonana	LHB	XW06GY	Wodonwa Workshoo	P/MOVER
					* Customer contacted dealership with information regarding breakdown * Customer advised that truck wont * Technician travelled to breakdown site, GF depot, Wodonga * Inspected wiring, connections & components for possible cause - no failure evident * Jump started truck & took to TCTC * Battery tested & confirmed within specification though * Returned truck back to GF depot & turned off isolator											
1072	Wodonga - Workshop	Elect\BATTERY	Flat Batteries. (TCTC P/O: WW091269)		* Technician returned home Service advisor actioned technician to attend GF depot * Technician travelled to deport * Check electrical routing * Check & load test batteries * Batteries below specification now * Removed/replaced batteries * Located a suspect terminal though[1] * Returned truck to TCTC for further repair * Re-checked electrical routing * Found current draw drom devices in cabin * Turned off isolator & found fine * Returned truck to GF depot * Advised staff to tun off isolator when not in use	04/01/2025	178736	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	TWIN CITY TRUCK CENTRE - OLD	P/MOVER
1072	Wodonga - Workshop	Elect\BATTERY	Replace Batteries. (TCTC P/O: WW091270)		* Technician returned to dealershio	04/01/2025	178719	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	TWIN CITY TRUCK CENTRE - OLD	P/MOVER
1072	Wodonga - Workshop	Tyres\TP3+4	Tyres\TP3+4			29/11/2024	160564	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	BEAUREPAIRES	P/MOVER
1072	Wodonga - Workshop	Tyres\TP09	Tyres\TP09			29/11/2024	160564	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	BEAUREPAIRES	P/MOVER
1072	Wodonga - Workshop	Tyres\TP7+8	Tyres\TP7+8			29/11/2024	160564	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	BEAUREPAIRES	P/MOVER
1072	Wodonga - Workshop	Tyres\TP5+6	Tyres\TP5+6			29/11/2024	160564	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	BEAUREPAIRES	P/MOVER
1072	Wodonga - Workshop	Steering\WHEEL ALGN	WHEEL ALIGN. (Hume Truck Technics P/O: WW090383)			26/11/2024	144731	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	HUME TRUCK TECHNICS	P/MOVER
1072	Wodonga - Workshop	Tyres\WHEEL ALGN	WHEEL ALIGNMENT (PULLING LEFT SCRUBBING TYRES). (Hume Truck Technics P/O: WW090383)			26/11/2024	144731	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	HUME TRUCK TECHNICS	P/MOVER
1072	Wodonga - Workshop	Steering\WHEEL ALGN	Wheel Alignment. (Hume Truck Technics P/O: WW090383)			26/11/2024	144731	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	HUME TRUCK TECHNICS	P/MOVER
1072	Wodonga - Workshop	VehService\JBS	VehService\JBS	VehService\JBS		24/11/2024	157048	Service	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	VehService\AS	VehService\AS	VehService\AS	Duplicate job	24/11/2024	157048	Service	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	Elect\TRL LIGHTS	No R/H Indicator On Trailers.		Tested trailer electrical lead found no power at trailer end, found join in trailer lead, tested from truck to join found no power, cut out join fitted new plug to electrical lead, fitted new base socket to truck due	29/10/2024	138428	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	DrivLine\CLUTCH	Check & Adjust Clutch			26/10/2024	137938	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	VehService\AS	VehService\AS	VehService\AS		26/10/2024	137938	Service	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	VServLab	SERVICE.		Duplicate job	26/10/2024	137938	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	DrCabRep\WIPERS	WASHERS BLOCKED.			26/10/2024	137938	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	Body\CH&S	Tint Windows. (All About Window Tinting P/O: WW089364)			02/10/2024	126256	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	DrCabRep\HOUSEKEEP	TINT WINDOWS.			02/10/2024	126256	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	DrCabRep\DOOR LOCK	New Ignition Key			27/09/2024	126255	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	VehService\AS	Service			27/09/2024	126255	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	VehService\AS	VehService\AS	VehService\AS		27/09/2024	126255	Service	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	Body\WIPERS	Washers Blocked			27/09/2024	126255	Fault	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	VehService\AS	VehService\AS	VehService\AS		07/09/2024	113738	Service	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	VehService\AS	VehService\AS	VehService\AS	98493 ks	17/08/2024	98493	Service	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	VehService\JBS	VehService\JBS	VehService\JBS	Completed full b service error with tablet check list	07/08/2024	90308	Service	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	VehService\AS	VehService\AS	VehService\AS	RUBY H % HOUR LABOUR	23/07/2024	79729	Service	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	VehService\AS	A Service	VehService\AS	55098	14/06/2024	55098	Service	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	Insp\ANN INSP	Insp\ANN INSP Check alternator.	Insp\ANN INSP		14/06/2024	55098	PreventativeMaintenance	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	Elect\ALT2 DR	liahts and aauaes oulsine at idle		Tested alternator charaine at a constant 14.5 volts no fluctuations driver to monitor	14/06/2024	55098	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			29/03/2024	29825	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	VehService\AS	A Service As Per Attached Checklist	VehService\AS		29/03/2024	29825	Service	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	Susp\HCV	CHECKED OVER TRUCK FOR AIR LEAKS, LUBRICATED HCV,S. CHECKED AND ADJUSTED RIDE HEIGHT.			20/03/2024		Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job A Service As Per Attached Checklist			10/02/2024	21979	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	BARRY MANEY - 3	P/MOVER
1072	Wodonga - Workshop	VehService\AS	POH WW084016	VehService\AS		10/02/2024	21979	Service	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	BARRY MANEY - 3	P/MOVER
1072	Wodonga - Workshop	Chassi\SUZI COIL	damaged suzi coils REPLACE RH ARM REST ON DRIVERS SEAT - Mark out holes in leather & make up holes to suit new			30/01/2024	3700	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	DrCabRep\SEAT	new arm rest. Installed arm rest & tightened bolts. Resecured seat cover & tighten. Test operation, ok.			23/01/2024	65729	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	BARRY MANEY - 3	P/MOVER
1072	Wodonga - Workshop	Body\HOUSEKEEP	Housekeeping REPAIR LIGHTS - Inspect fault for dome light, move switch to door operation & test, okay.			23/01/2024	65729	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	BARRY MANEY - 3	P/MOVER
1072	Wodonga - Workshop	Elect\HEAD LIGHT	Inspect fault for dump switch, removed dash and inspect, found plug not plugged in all the way. Refit olue. test. all okav. Refit dash.			23/01/2024	65729	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	BARRY MANEY - 3	P/MOVER
1072	Wodonga - Workshop	Elect\ELECT P&W	BLOWN FUSE FOR CIGARETTE PLUG - Inspect fuse, found to be blown. Driver advised plug is used for coffee machine. Locate amp rating from coffee machine & replaced fuse to 15 amp to suit application.			23/01/2024	65729	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	BARRY MANEY - 3	P/MOVER
1072	Wodonga - Workshop	Body\MOUNTS	MOVE SUZI BRACKET AS FAR FORWARD AS POSSIBLE - Loosened suzi lead mounting bolts & moved forward as far as oossible as requested. Tiehtened mountine bolts.			06/01/2024	7301	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	BARRY MANEY - 3	P/MOVER
1072	Wodonga - Workshop	Elect\HEAD LIGHT	FIT LIGHTS BEHIND GRILLE - Removed grille, measure up length of steel tubing for spot lights support, cut to suit. Painted bracket. Manufacture wiring looms for spot lights. Run wiring from switch in cab to lights. Mounted spot lights to bracket & mounted bracket to truck. Connected wiring, Adjust light bars. Lowered cab & checked clearance. Secured new wiring & reinstalled grille. Check operation, all ok.			06/01/2024	7301	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	BARRY MANEY - 3	P/MOVER
1072	Wodonga - Workshop	Elect\ELECT P&W	FIT EXTRA POWER SOCKET - Remove fuse panel & passenger side kick panel. Locate mounting spot for power socket Drilled hole in seat base and fitted plug. Removed floor rail trim, run wires from fuse box to seat. Reinstalled trim. Wired in power and earth for olue. Tested wires. all okav.			06/01/2024	7301	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	BARRY MANEY - 3	P/MOVER
1072	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			06/01/2024	7301	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	VehService\CS	C Service As Per Attached Checklist (Kenworth first service)	VehService\CS		06/01/2024	7301	Service	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	Elect\TRL LIGHTS	electrical plug pulled out			23/12/2023	3154	Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER
1072	Wodonga - Workshop	Insp\Truck Pre	Truck pre-delivery			16/12/2023		Repair	Completed	FL Green Distribution	KWX15HWY	Wodonga	LHB	XW06GY	Wodonga Workshop	P/MOVER