EquipmentName	Workshop	Description	CompletionComments	DateDone	DistanceDone	Workstate	Location	Division	Rego	Supplier	EquipmentType
1056	Wodonga - Workshop	VehService\AS A Service		05/07/2026	1057487	Completed	Wodonga	HCU	XV19VU	B&M MECHANICAL REPAIRS	P/MOVER
1056	Wodonga - Workshop	Tyres\ROTATION left hand window cracked	ROTATION AND BALANCE 1-2	23/06/2026	1023313	Completed	Wodonga	HCU	XV19VU	BORDER BANDAG PTY LTD	P/MOVER
1056	Wodonga - Workshop	CLEAR DEFECT REPAIR FRONT DIFF PINION SEAL LEAK.		17/06/2026	1023313	Completed	Wodonga	HCU	XV19VU	G & S DIESEL SERVICE	P/MOVER
1056	Wodonga - Workshop	CLEAR DEFECT	Labour-Workshop FoundAdBluefault	17/06/2026	1023313	Completed	Wodonga	HCU	XV19VU	G & S DIESEL SERVICE	P/MOVER
1056	Wodonga - Workshop	Engine\ADBLUE VehService\CS C Service @1,040,038km	ReplacedAdBlueinjectorandfilte	12/06/2026	1023313	Completed	Wodonga	HCU	XV19VU	WARREGO TRANSPORT REPAIRS	P/MOVER
1056	Wodonga - Workshop	WW134150		06/06/2026	1040038	Completed	Wodonga	HCU	XV19VU	B&M MECHANICAL REPAIRS	P/MOVER
1056	Wodonga - Workshop	DrivLine\DIFF OIL Replace Diff oils		06/06/2026	1040038	Completed	Wodonga	HCU	XV19VU	B&M MECHANICAL REPAIRS	P/MOVER
1056	Wodonga - Workshop	VehService\AS A Service DIAGNOSE AND REPAIR/REPORT TAPPING SOUND IN ENGINE WHEN COLD.	diagnose report for tapping sound in engine when cold start engine noise in front of engine remove fan belt & a/c belt check all pulleys & tensioners start engine no noise check horton fan refit belts & noise starts up again take	03/05/2026	1023313	Unlocked	Wodonga	HCU	XV19VU	B&M MECHANICAL REPAIRS	P/MOVER
1056	Wodonga - Workshop	(DISCUSS WITH PETER DRAYTON IF EXPLANATION REQUIRED)	for test drive noise went within 1 minute possible horton fan issue has the usual horton knock	03/05/2026	1023313	Unlocked	Wodonga	HCU	XV19VU	B&M MECHANICAL REPAIRS	P/MOVER
1056	Wodonga - Workshop	Refit deck plate	NO ISSUE CURRENT	03/05/2026	1023313	Completed	Wodonga	HCU	XV19VU	B&M MECHANICAL REPAIRS	P/MOVER
1056	Wodonga - Workshop	REPAIR/ REPLACE TURTABLE GREASE LINES	REPAIRED PREVIOUSLY	03/05/2026	1023313	Completed	Wodonga	HCU	XV19VU	B&M MECHANICAL REPAIRS	P/MOVER
1056	Wodonga - Workshop	Tyres\Punct POS S		31/03/2026	1004170	Completed	Wodonga	HCU	XV19VU	BORDER BANDAG PTY LTD	P/MOVER
1056	Wodonga - Workshop	gear stick boot	completed by B&M mechanical repairs	15/03/2026	993519	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	VehService\BS B Service VehService\AS A Serv WW099061	at 993,517 km's	15/03/2026	993519	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	974,238km		15/02/2026	974239	Completed	Wodonga	HCU	XV19VU	B&M MECHANICAL REPAIRS	P/MOVER
1056	Wodonga - Workshop	Tyres\TP1+2		10/02/2026	977591	Completed	Wodonga	HCU	XV19VU	BORDER BANDAG PTY LTD	P/MOVER
1056	Wodonga - Workshop	Cooling\HOUSEKEEP BROWN & HURLEY SUBLET TO PRO TRUCK ELECTRICAL-	DIAGNOSE & REPLACE FAULTY COOLABAH SLEEPER COOLER CHARGER	03/02/2026	1023313	Completed	Wodonga	HCU	XV19VU	COFFS MOBILE AUTO ELECTRICS	P/MOVER
1056	Wodonga - Workshop	BREAKDOWN. REPAIR DAMAGED SUZI COILS, LIGHTS LEAD AND EBS LEAD.	Labour- Mobile Inspected horton fan Found requires overhaul	02/02/2026	965450	Completed	Wodonga	HCU	XV19VU	PACCAR PARTS FLEET SERVICES	P/MOVER
1056	Wodonga - Workshop	Engine\ENG FAN G & S DIESEL-	Manually locked fan up with boltS	28/01/2026	965450	Completed	Wodonga	HCU	XV19VU	WARREGO TRANSPORT REPAIRS	P/MOVER
1056	Wodonga - Workshop	BREAKDOWN- REPLACE BROKEN SUZI-COILS AND ELECTRICAL LEADS IF REQUIRED AT SOLAGREY SOLARIS PAPER, PROSPECT RESERVOIR.		27/01/2026	962148	Completed	Wodonga	HCU	XV19VU	G & S DIESEL SERVICE	P/MOVER
1056	Wodonga - Workshop	DriCabRep\WINDSCREEN Adjust Drive Wheel Bearings,		24/01/2026	962118	Completed	Wodonga	HCU	XV19VU	AUTOTEK AUSTRALIA	P/MOVER
1056	Wodonga - Workshop	(G&S Diesel P/O: WW098654 Rebuild Horton Fan Due To Leaking Air.		17/01/2026	962148	Completed	Wodonga	HCU	XV19VU	G & S DIESEL SERVICE	P/MOVER
1056	Wodonga - Workshop	(G&S Diesel P/O: WW098654		17/01/2026	962148	Completed	Wodonga	HCU	XV19VU	G & S DIESEL SERVICE	P/MOVER
1056	Wodonga - Workshop	Tyres\TP05	CALL OUT - CORNUBIA QLD	09/12/2025	931189	Completed	Wodonga	HCU	XV19VU	BORDER BANDAG PTY LTD	P/MOVER
1056	Wodonga - Workshop	VehService\BS B Service	Completed by B&M mechanical repairs	01/12/2025	961739	Completed	Wodonga	HCU	XV19VU	B&M MECHANICAL REPAIRS	P/MOVER
1056	Wodonga - Workshop	REPAIR SPEEDO FAULT VehService\AS A Service		01/12/2025	961739	Completed	Wodonga	HCU	XV19VU	B&M MECHANICAL REPAIRS	P/MOVER
1056	Wodonga - Workshop	WW098095	Completed by B&M mechanical repairs	01/12/2025	961739	Completed	Wodonga	HCU	XV19VU	B&M MECHANICAL REPAIRS	P/MOVER
1056	Wodonga - Workshop	Tyres\ROTATION FLIP STEERS POS 1-2 New Batteries Needed	Jacked over cabin, removed batteries, fitted new batteries, started truck checked charge rate, lowered cabin. 4x Batteries XN70ZZMF	18/11/2025	930596	Completed	Wodonga	HCU	XV19VU	BORDER BANDAG PTY LTD	P/MOVER
1056	Wodonga - Workshop	WW097827	Batteries Replaced @ 925,339 Klms.	14/11/2025	925340	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	AC fan not working VehService\AS A Service		09/11/2025	919329	Completed	Wodonga	HCU	XV19VU	B&M MECHANICAL REPAIRS	P/MOVER
1056	Wodonga - Workshop	WW097718 VehService\AS A Service		09/11/2025	919329	Completed	Wodonga	HCU	XV19VU	B&M MECHANICAL REPAIRS	P/MOVER
1056	Wodonga - Workshop	WW097432 REPAIR OIL LEAK AT FRONT DIFF As Per Defect		19/10/2025	910077	Completed	Wodonga	HCU	XV19VU	B&M MECHANICAL REPAIRS	P/MOVER
1056	Wodonga - Workshop	(Brown & Hurley Darra P/O: WW096878) Check Slack Adjuster Replace If Required As Per Defect	DIFF IS BEING RESEALED.	11/09/2025	889948	Completed	Wodonga	HCU	XV19VU	BROWN & HURLEY	P/MOVER
1056	Wodonga - Workshop	(Brown & Hurley Darra P/O: WW096878 Check & Adjust Brakes As Per Defect.		11/09/2025	889948	Completed	Wodonga	HCU	XV19VU	BROWN & HURLEY	P/MOVER
1056	Wodonga - Workshop	(Brown & Hurley Darra P/O:WW096878 B Service		11/09/2025	889948	Completed	Wodonga	HCU	XV19VU	BROWN & HURLEY	P/MOVER
1056	Wodonga - Workshop	(B&M Mechanical)	SUPENSION CHECKLIST NOT COMPLETE. CONFIRMED OK ON PHONE.	31/08/2025	883247	Completed	Wodonga	HCU	XV19VU	B&M MECHANICAL REPAIRS	P/MOVER
1056	Wodonga - Workshop	Wiper blades need replacing		31/08/2025	883247	Completed	Wodonga	HCU	XV19VU	B&M MECHANICAL REPAIRS	P/MOVER
1056	Wodonga - Workshop	Tyres\ROTATION POS 1-2		26/08/2025	880357	Completed	Wodonga	HCU	XV19VU	BORDER BANDAG PTY LTD	P/MOVER
1056	Wodonga - Workshop	Tyres\TP5+6		26/08/2025	880357	Completed	Wodonga	HCU	XV19VU	BORDER BANDAG PTY LTD	P/MOVER
1056	Wodonga - Workshop	Tyres\TP9+10		26/08/2025	880357	Completed	Wodonga	HCU	XV19VU	BORDER BANDAG PTY LTD	P/MOVER
1056	Wodonga - Workshop	Tyres\TP7+8		26/08/2025	880357	Completed	Wodonga	HCU	XV19VU	BORDER BANDAG PTY LTD	P/MOVER
1056	Wodonga - Workshop	Tyres\TP3+4		26/08/2025	880357	Completed	Wodonga	HCU	XV19VU	BORDER BANDAG PTY LTD	P/MOVER
1056	Wodonga - Workshop	Elect\SUZI COIL BREAKDOWN	Labour - Mobile - Breakdown Travelled to the site Located and inspected the unit Replaced the suzi lead and the trailer electrical plug	22/08/2025	883668	Completed	Wodonga	HCU	XV19VU	WARREGO TRANSPORT REPAIRS	P/MOVER
1056	Wodonga - Workshop	Tyres\Puncture POS 1 Repair Damaged Electrical Suzie Lead & Plug.		20/08/2025	878174	Completed	Wodonga	HCU	XV19VU	BORDER BANDAG PTY LTD	P/MOVER
1056	Wodonga - Workshop	(G&S Diesel P/O: Engine\START MOTR	Labour - Mobile Travelled to supplier Sourced parts Travelled to Virginia Tested and found faulty starter motor Removed and replaced starter motor Re-secured cabling Checked operation	19/08/2025	876320	Completed	Wodonga	HCU	XV19VU	G & S DIESEL SERVICE	P/MOVER
1056	Wodonga - Workshop	REMOVED AND REPLACED STARTER MOTOR		14/08/2025	878312	Completed	Wodonga	HCU	XV19VU	WARREGO TRANSPORT REPAIRS	P/MOVER
1056	Wodonga - Workshop	BREAKDOWN. AFTER TREAT LIGHT ON. BEING DIAGNOSED		14/08/2025	945557	Completed	Wodonga	HCU	XV19VU	G & S DIESEL SERVICE	P/MOVER
1056	Wodonga - Workshop	Insp\ANN INSP		14/08/2025	874074	Completed	Wodonga	HCU	XV19VU	B&M MECHANICAL REPAIRS	P/MOVER
1056	Wodonga - Workshop	VehService\AS A Service		14/08/2025	874074	Completed	Wodonga	HCU	XV19VU	B&M MECHANICAL REPAIRS	P/MOVER
1056	Wodonga - Workshop	Tyres\PRES CHECKS POS 1-12 Thermostate		12/08/2025	871117	Completed	Wodonga	HCU	XV19VU	BORDER BANDAG PTY LTD	P/MOVER
1056	Wodonga - Workshop	(Parts Supplied By TCTC P/O: WW095980)	REPLACED THERMOSTAT. CHECKED. OK.	31/07/2025	864293	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	starter motor	S.McCABE.	31/07/2025	864293	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	VehService\AS A Service BROWN & HURLEY COFFS HARBOUR- REPLACE CLUTCH. DRIVER CONCERNED CLUTCH IS FAILING.		31/07/2025	881240	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	DIAGNOSED AS CLUTCH FAILURE. APPROVED TO REPLACE.		08/07/2025	965450	Completed	Wodonga	HCU	XV19VU	PACCAR PARTS FLEET SERVICES	P/MOVER
1056	Wodonga - Workshop	Tyres\TP1+2		19/06/2025	843328	Completed	Wodonga	HCU	XV19VU	BORDER BANDAG PTY LTD	P/MOVER
1056	Wodonga - Workshop	AIR LEAK L/H/S	REPLACED GOVERNOR VALVE	19/06/2025	842939	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	CLUTCH	ADJUSTED CLUTCH	19/06/2025	842939	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Prevent\TRANS OIL Synthetic gearbox oil change		05/06/2025	837873	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	VehService\CS		05/06/2025	837873	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	DrivLine\DIFF OIL Replace Diff oils		05/06/2025	837873	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Air leak RHS of engine	Heat shield had rubbed through shift air lines cut fit joiners had to wait for parts from tctc	20/05/2025	829968	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	AIR LEAK UNDER CAB. YASS TOWING- SUBLET TO CMF WILLIAMS-		20/05/2025	829968	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	DIAGNOSE AND REPAIR TRAILER LIGHTS AT YASS SERVICE CENTRE.		10/05/2025	926826	Completed	Wodonga	HCU	XV19VU	YASS TOWING	P/MOVER
1056	Wodonga - Workshop	Prevent\TRANS OIL		09/05/2025	822999	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Power steering pump gasket leaking - Change next B service	Completed during B service	09/05/2025	822999	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	VehService\BS		09/05/2025	822999	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	DrivLine\DIFF OIL No Trailer Lights.		09/05/2025	822999	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	(Mavin Truck Centre)		02/05/2025	818899	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	VehService\AS A Service BROWN & HURLEY COFFS HARBOUR-	Also replaced drivers wind deflector Bring truck into workshop. Connected computer in get a download. Troubleshoot code 1887. Check power and earth and load with a bulb. Remove and fit new nox sensor. Clear inactive codes.	08/04/2025	807690	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	DIAGNOSE AND REPAIR AFTER TREAT ISSUE.	Driver will have to drive truck and reach 200 degree exhaust temp before light will go out	03/04/2025	965450	Completed	Wodonga	HCU	XV19VU	PACCAR PARTS FLEET SERVICES	P/MOVER
1056	Wodonga - Workshop	VehService\AS A Service		19/03/2025	796693	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER

		RAPID HYDRAULICS- Hyd lines on truck Travel to site: Yard Inspect hoses Remake (reused couplers)										
1056	Wodonga - Workshop	Fitted the hoses to the truck		18/03/2025	962148	Completed	Wodonga	HCU	XV19VU	RAPID HYDRAULICS	P/MOVER
1056	Wodonga - Workshop	Rotate Steer's		24/02/2025	788102	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	VehService\AS A Service		24/02/2025	788102	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Driver's door lock not working on remote or lock button.		24/02/2025	788102	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Ignition some time's take's a few second's to start.	Started perfect when don't rush start it	24/02/2025	788102	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Cruise and engine light's on dash not working.	Replace globe	24/02/2025	788102	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	VehService\AS		07/02/2025	776070	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	DriCabRep\ DRIVERS SIDE DOOR LOCKING MECHANISM NOT WORKING	Keith fixed battery up side down in key	07/02/2025	776070	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Front End knocking and thuding, bit loose.	Cab mounts have slighy play	22/01/2025	767451	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Repair Air Leak On Suzie Leads		22/01/2025	767451	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	New cab filter for A/C	Has been replaced	22/01/2025	767451	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Door lock faulty on driver's side door.	Door lock actuator has been replaced	22/01/2025	767451	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	De Bug radiator/AC	Have given the radiator a blow out	22/01/2025	767451	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	REPLACE DRIVE BACKING PLATES.		22/01/2025	767451	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Door Lock Grinding, when Locking / Unlocking Door.		22/01/2025	767451	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Radiator / AC Condenser De Bug.		22/01/2025	767451	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Front End Has A Thud Noise. B Service.	Cab mounts have slight play	22/01/2025	767451	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Serviced @ 767,450 Klms. A Service.		22/01/2025	767450	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Serviced @ 767,450 Klms.		22/01/2025	767450	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Repair Coolant Leak @ Water pump Housing (Rework). (Parts Supplied By TCTC P/O: WW091416)	Drained cooling system, removed alternator, A/C compressor, water pump water pump housing, cleaned up all surfaces, replaced all O-rings on water pump housing & wat	18/01/2025	765203	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Oil Cooler Thermostat.		18/01/2025	765203	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	RADIATOR DE-BUG		19/12/2024	747868	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	POGO STICK LOOSE		19/12/2024	747868	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	engine fan coming on a bit on hot days	Engine fan com8ng on more often due to air con being on all the time	19/12/2024	747868	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	something loose or worn in front end		19/12/2024	747868	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Tyres\TP7+8		17/12/2024	746382	Completed	Wodonga	HCU	XV19VU	BEAUREPAIRES	P/MOVER
1056	Wodonga - Workshop	Tyres\TP3+4		17/12/2024	746382	Completed	Wodonga	HCU	XV19VU	BEAUREPAIRES	P/MOVER
1056	Wodonga - Workshop	Tyres\TP9+10		17/12/2024	746382	Completed	Wodonga	HCU	XV19VU	BEAUREPAIRES	P/MOVER
1056	Wodonga - Workshop	Tyres\TP5+6		17/12/2024	746382	Completed	Wodonga	HCU	XV19VU	BEAUREPAIRES	P/MOVER
1056	Wodonga - Workshop	Battery Box Cover Starting To Break At The Bottom	Repair broken battery box cover	12/12/2024	742241	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	a service		12/12/2024	742241	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	VehService\AS		12/12/2024	742241	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	drivers side steer hub seeping oil	Checked all ok, driver to monitor	12/12/2024	742241	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	HUB LEAK FRONT STEER	Checked all ok, driver to monitor	12/12/2024	742241	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Rotate Steers. (Wodonga Tyre & Auto P/O: WW090105)		15/11/2024	720731	Completed	Wodonga	HCU	XV19VU	BEAUREPAIRES	P/MOVER
1056	Wodonga - Workshop	Adjust Clutch	Dan and Keith did this job	07/11/2024	714634	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Wire Up Indicator/Warning Buzzer	Dan completed 10mins	07/11/2024	714634	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	A Service	This job was done after I left for the day	07/11/2024	714634	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Adjust Headlights Down A Little	Dan adjusted Sheses i8gh5s	06/11/2024	714634	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Pulling To The Right Under Brakes Temp gauge not working	Brakes adjusted	06/11/2024	714634	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	ARKON REPAIRING.	Arkon doing this job	06/11/2024	714634	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	H/H/S Headlight Missing Screws		06/11/2024	714634	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	VehService\AS		06/11/2024	714634	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Check & Repair Oil Leak @ Front Diff. (TCTC P/O: WW089910)		31/10/2024	708734	Completed	Wodonga	HCU	XV19VU	TWIN CITY TRUCK CENTRE - OLD	P/MOVER
1056	Wodonga - Workshop	FRONT DIFF GAUGE NOT WORKING. (TCTC P/O: WW089910)		31/10/2024	708734	Completed	Wodonga	HCU	XV19VU	TWIN CITY TRUCK CENTRE - OLD	P/MOVER
1056	Wodonga - Workshop	Front diff leaking	INSPECTED. FOUND COMING FROM BREATHER. REMOVED AND CLEANED. FIT.	24/10/2024	696610	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	BUZZER NOT WORKING.	DIAGNOSED AND REPAIRED BROKEN WIRE. TESTED. OK.	24/10/2024	696610	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Job Created from Purchase Order #: 105258		18/10/2024	697260	Completed	Wodonga	HCU	XV19VU	PACCAR PARTS FLEET SERVICES	P/MOVER
1056	Wodonga - Workshop	CHECK CAB MOUNTS.	CHECKED. OK.	17/10/2024	696610	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	A SERVICE		17/10/2024	696610	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	PULLING TO THE RIGHT WHEN BRAKING.	FOUND BRAKES NOT ADJUSTED EVENLY. ADJUSTED BRAKES.	17/10/2024	696610	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	New Batteries	PREVIOUSLY COMPLETED.	17/10/2024	696610	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	VehService\AS	REPLACE FRONT DRIVE MUDFLAPS.	17/10/2024	696610	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Tyres\TP3+4		17/10/2024	696611	Completed	Wodonga	HCU	XV19VU	BEAUREPAIRES	P/MOVER
1056	Wodonga - Workshop	Check Front End		02/10/2024	694075	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Alarm Not Working	Horns were disconnected park brake alarm was not working	02/10/2024	694075	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Pulling To Right When Braking		02/10/2024	694075	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Batteries Losing Charge Over The Weekend		02/10/2024	694075	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Front Diff Temp Gauge Not Working		02/10/2024	694075	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Truck Needs New Checker Plate		02/10/2024	694075	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Needs New Steer Tyres & Possibly An Alignment		02/10/2024	694075	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	New wiper Blades On Both Wipers	Previously completed	02/10/2024	694075	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	A Service		02/10/2024	694075	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	FRONT DIFF TEMP GAUGE NOT WORKING.		02/10/2024	694075	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	ALARM NOT WORKING.	Horn was unplugged	02/10/2024	694075	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	A SERVICE		02/10/2024	694075	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	ABS Plug On Truck Needs To Be Moved (Keeps Ripping Off)		02/10/2024	694075	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Cab Shocks Need Replacing	Previously completed	02/10/2024	694075	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Diff Leak On Front Diff	Blocked breather.now cleared *Park brake lights flash when indicators are on* Inspect light on dash flashing with indicators. remove telltale and globes, check diodes, found faulty diode, replace and test.	02/10/2024	694075	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	LOW AIR DASH LIGHT COMING ON WITH INDICATORS. (Arkon Auto Electrical P/O:	Lights working as normal.	02/10/2024	694075	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	FRONT DIFF TEMP GAUGE NOT WORKING.		02/10/2024	694075	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	NEW CHECKER PLATE. VehService\AS		02/10/2024	694075	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Serviced @ 684592 Klms.		02/10/2024	694075	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Low Air Light Coming On With Indicators		02/10/2024	694075	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Diff Leaks (Input & Breather)		02/10/2024	694075	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	DIFF OIL PUSHING OUT FRONT BREATHER ONTO LHS CHASSIS.		02/10/2024	694075	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	ALARM BUZZER NOT WORKING/ RIPPED OUT OF SOCKET.		02/10/2024	694075	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Passenger Side Mirror Cover Missing		02/10/2024	694075	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Alarm For Indicators & Faults Broken Out Of Socket		02/10/2024	694075	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Tyres\TP1+2		27/09/2024	681243	Completed	Wodonga	HCU	XV19VU	BEAUREPAIRES	P/MOVER
1056	Wodonga - Workshop	SMALL PUDDLE OF COOLANT ON GUARD AFTER BEING PARKED UP FOR THE NIGHT.	TIGHTENED BOTTOM RADIATOR HOSE.	24/09/2024	678897	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Check Cab Mounts & Shockers, Replace If Required. (TCTC P/O: WW089132)	* Supported cab * Ballast steer axle & removed wheel end equipment for access * Secured, unbolted & removed shocks * Installed replacement shocks * Secured in place * Aligned & tensioned all components * Test operations - All ok. * Inspected & confirmed leaking hub seal * Ballast axle & removed wheel end equipment * Removed drum, hub, bearings & components * Inspected bearings - All ok * Cleaned down all components * Removed & replaced brake shoes * Refit hub with replacement seal * Refit all components * Adjusted, aligned & tensioned all components to specifications * Test operations - All ok, fault no longer present.	20/09/2024	671796	Completed	Wodonga	HCU	XV19VU	TWIN CITY TRUCK CENTRE - OLD	P/MOVER
1056	Wodonga - Workshop	Replace Leaking Hub Seal L/H Front Drive. (TCTC P/O: WW089132)		20/09/2024	671796	Completed	Wodonga	HCU	XV19VU	TWIN CITY TRUCK CENTRE - OLD	P/MOVER
1056	Wodonga - Workshop	Replace Wiper Blades. (TCTC P/O: WW089132)	SUPPLY WIPER BLADES.	20/09/2024	671796	Completed	Wodonga	HCU	XV19VU	TWIN CITY TRUCK CENTRE - OLD	P/MOVER

			Major external clean and pressure test radiator assembly Dismantle and remove top and bottom radiator tanks Flow test, clean and flush core Clean and service tanks and header plates Unscrew and reseal leaking sight glass Supply gasket and bolt set, cap and overflow hose Reassembled all parts, pressure test, dry and paint. WHILST RADIATOR REMOVED FOR ENGINE REPAIRS . * Disassembled radiator & sent to Natrad for servicing * Upon return, reassembled radiator & refit * Replaced thermostat									
		Remove Radiator & Repair.										
1056	Wodonga - Workshop	(TCTC P/O: WW089132)	* Replaced belts & tensioned all components.	20/09/2024	671796	Completed	Wodonga	HCU	XV19VU	TWIN CITY TRUCK CENTRE - OLD	P/MOVER	
1056	Wodonga - Workshop	Prevent\WHEEL ALGN. (Hume Truck Technics P/O: WW088697)		14/09/2024	678797	Completed	Wodonga	HCU	XV19VU	HUME TRUCK TECHNICS	P/MOVER	
1056	Wodonga - Workshop	Steering bad between 80-95kms shakes whole front end and steering wheel. (rides pretty rough)		12/09/2024	671773	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	Brakes need fixing - Whole truck moves to right when braking steering wheel doesn't pull just whole truck goes right - have to steer left to keep in lane		12/09/2024	671773	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	B Service		29/08/2024	667514	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	VehService\AS		29/08/2024	667514	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
			Cody and Dan started this job I came in after 667514ks									
1056	Wodonga - Workshop	C Service	Cody and Keith completed the job	28/08/2024	668731	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	IAP tablet Not In Truck, Left side bottom mirror cover Missing.		28/08/2024	668731	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
		Check For Coolant Leaks & Repair										
1056	Wodonga - Workshop	(Parts Supplied By Burson's Auto Parts P/O: WW088333)	Cleaned up area around hole on header tank, repaired hole, filled with coolant & pressure tested, all good no leaks.	27/08/2024	667514	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	checker plate to be removed or replaced	Removed checker plate	09/08/2024	659574	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	Replace ABS lead	Replaced ABS lead	09/08/2024	659574	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
		Damaged Trailer Plug & Lead (Hagan's Auto Electrical P/O: WW087264)										
1056	Wodonga - Workshop			10/07/2024	649642	Completed	Wodonga	HCU	XV19VU	HAGANS AUTO ELECTRICAL SERVICE	P/MOVER	
1056	Wodonga - Workshop	TRUCK ABS LIGHT ON.	REMOVED WHEELS AND DRUMS. CLEANED SENSOR RINGS, SENSORS AND RESET SENSORS. ASSEMBLED. TESTED. OK.	04/06/2024	635849	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	A Service		01/06/2024	668731	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	re-line drive brakes		01/06/2024	668731	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	Insp\ANN INSP	I	01/06/2024	668731	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	Replace/Repair Damaged Trailer Electrical Lead (MM Diesel P/O: WW		31/05/2024	635850	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	REPAIR ELECTRICAL LEAD & EBS LEAD- (GOT CAUGHT ON FRONT OF TRAILER WHILE TURNING AND SNAPPED OFF)	DRIVE IN DANDENONG SOUTH TO ATTEND TO THE SUZI LEADS BETWEEN THE PRIME MOVER AND THE 'A' TRAILER THAT HAD BEEN RIPPED OUT. DRIVER - BARRY 0409 65.	29/05/2024	634692	Completed	Wodonga	HCU	XV19VU	HALLAM TRUCK CENTRE - HALLAM	P/MOVER	
		repair and clear defect HVN068655?										
1056	Wodonga - Workshop	on axle 1 - right - brake linings contaminated		24/05/2024	634286	Unlocked	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	replace damaged Suzi coils		21/05/2024	631627	Completed	Wodonga	HCU	XV19VU	G & S DIESEL SERVICE	P/MOVER	
1056	Wodonga - Workshop	callout a/h from doug trailer lights not working on truck. travel out GF yard found truck inside warehouse. check tralier plug found tralier wireing being		20/05/2024	630800	Completed	Wodonga	HCU	XV19VU	HAGANS AUTO ELECTRICAL SERVICE	P/MOVER	
1056	Wodonga - Workshop	Starting to spray / leak oil where tail shaft goes into front Diff		02/05/2024	620644	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	B Service As Per Attached Checklist		25/04/2024	616571	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	MOVEMENT IN AIR GAUGES. MAYBE A SMALL AIR LEAK IN TRAILERS.	NO FAULT FOUND.	25/04/2024	616571	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	B SERVICE.		25/04/2024	616571	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	Diff oil due to be changed according to sticker		25/04/2024	616571	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	SMELL OCCASIONALLY COMING FROM COOLIBAH MODULE IN PASSENGER DOG BOX.		25/04/2024	616571	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	ADJUST CLUTCH.	ADJUSTED.	25/04/2024	616571	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	Cab shocks may be at end of life		25/04/2024	616571	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	STEERING WHEEL CENTRE CLIPS BROKEN. KEEPS POPPING UP.		25/04/2024	616571	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	sterring wheel cover keeps popping up	REPLACED.	25/04/2024	616571	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	Record Check Results As Attached To This Job		25/04/2024	616571	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	A Service As Per Attached Checklist		11/04/2024	604647	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	A SERVICE.		11/04/2024	604647	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	Diff oil due to be changed according to sticker		11/04/2024	604647	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	CHECK BRAKES WEAR.		11/04/2024	604647	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	LEAKING HEATER TAP. (BEHIND TURBO)		11/04/2024	604647	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	Cab shocks may be at end of life		11/04/2024	604647	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	Exhaust leak back of turbo near flexi		11/04/2024	604647	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	Coolant leak out of filter or heater tap near back of turbo		11/04/2024	604647	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	STEERING WHEEL CENTRE CLIPS BROKEN. KEEPS POPPING UP.		11/04/2024	604647	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	sterring wheel cover keeps popping up		11/04/2024	604647	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	Record Check Results As Attached To This Job		11/04/2024	604647	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	after treat light came on breifly		23/03/2024		Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	A svc		23/03/2024		Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	A Service As Per Attached Checklist	REPLACED EXHAUST FLEX. WELDED BRACKET.	21/03/2024	592652	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	AIR CONDITIONING BLOWING HOT AIR.		21/03/2024	592652	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	OIL AROUND TURBO.		21/03/2024	592652	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	STEERING WHEEL CENTRE CLIPS BROKEN. KEEPS POPPING UP.		21/03/2024	592652	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	sterring wheel cover keeps popping up		21/03/2024	592652	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	Record Check Results As Attached To This Job		21/03/2024	592652	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
		TRAVEL TO GREENFREIGHTS YARD' CONNECT GAUGES CHECK & FOUND LOW PRESSURE DEGAS A/C, TRAVEL BACK TO HAGANS PICK NITRO GEAR TRAVEL BACK TO GREENFREIGHT YARD PRESSURE TEST CHECK FOR LEAKS NONE FOUND VACC DOWN A/C SYSTEM CHECK HOLDING VACC ALL OK ADD OIL & UV DYE REGAS WITH REQUIRED AMOUNT TEST ALL OK 06/03/2024 TRUCK AT HAGANS hook gauges check a/c found horton fan not cutting in when it high pressure hits 300psi and countinue to climb pass 400psi. manunly set horton fan on pressure high pressure operate around 300psi but not going down. degas system found drier freezing up while degasing. rr drier and horton fan pressure swtich. vac system down ok regas system test a/c vent temp going down to 10,c and										
1056	Wodonga - Workshop	horten fan cuts in at around 290psi and operate around 200psi with fan on in 30,c enviroment		07/03/2024		Completed	Wodonga	HCU	XV19VU	Albury Workshop	P/MOVER	
1056	Wodonga - Workshop	A Service As Per Attached Checklist		29/02/2024	577077	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	A SERVICE		29/02/2024	577077	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	NEW STEERS (FLAT SPOTS ON BOTH TYRES BUT WORSE ON PASSENGER SIDE)		29/02/2024	577077	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	Record Check Results As Attached To This Job		29/02/2024	577077	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	Tyre Position 1 + 2		28/02/2024		Completed	Wodonga	HCU	XV19VU	Albury Workshop	P/MOVER	
		ROAD SIDE SERVICE MARULAN, TO GREENFREIGHTS K200, XV19UV, WITH NO FRONT BRAKE ACTUATION. REMOVED AIR LINE FROM FRONT BRAKE BOOSTER, FOUND NO SUPPLY WHEN BRAKES APPLIED. CHECK FOR AIR AT RELAY VALVE, FOUND AIR FROM FOOT PEDAL TO VALVE OK. FOUND FRONT AIR TANK HAD BEEN MOVED TO STACK GANTRY AND SUPPLY PLUMBED INTO ONE WAY VALVE.(NOT FACTORY SET UP) REPLUMED LINES INTO CORRECT VALVES, NOW HAS SUPPLY TO FRONT BRAKES, ALL GOOD.										
1056	Wodonga - Workshop	RETURN TO WORKSHOP.		16/02/2024		Completed	Wodonga	HCU	XV19VU	Albury Workshop	P/MOVER	
1056	Wodonga - Workshop	B Service As Per Attached Checklist		08/02/2024	559332	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	B SERVICE ON 7/1/24.		08/02/2024	559332	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	NEW DRIVERS SIDE WIPER BLADE. BROKEN CLIP KEEPS SLIDING OFF.		08/02/2024	559332	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	NEEDS STEER ROTATION.		08/02/2024	559332	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	Record Check Results As Attached To This Job		08/02/2024	559332	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	A Service As Per Attached Checklist		26/01/2024	550406	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	A SERVICE.		26/01/2024	550406	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	STEERING WHEEL CENTRE CLIPS BROKEN. KEEPS POPPING UP.		26/01/2024	550406	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	DIFF LEAKS STARTING TO APPEAR.		26/01/2024	550406	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	FRONT DRIVERS SIDE SHOCK HAS COME OUT OF CHASSIS MOUNT AT TOP.		26/01/2024	550406	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	ROTATE STEERS.		26/01/2024	550406	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	sterring wheel cover keeps popping up		26/01/2024	550406	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	Record Check Results As Attached To This Job		26/01/2024	550406	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	A SERVICE.		03/01/2024	534243	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	NEW FRONT SHOCKS.		03/01/2024	534243	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	A Service As Per Attached Checklist		03/01/2024	534243	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	NEW FRONT SHOCKS REQUIRED.		03/01/2024	534243	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	sterring wheel cover keeps popping up		03/01/2024	534243	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	Record Check Results As Attached To This Job		03/01/2024	534243	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	A Service As Per Attached Checklist		14/12/2023	522373	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	sterring wheel cover keeps popping up		14/12/2023	522373	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	check fuel filter (Pretty dirty)	OK.	14/12/2023	522373	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	Record Check Results As Attached To This Job		14/12/2023	522373	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	A svc		14/12/2023	522373	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	
1056	Wodonga - Workshop	Tyre Position 9 + 10		07/12/2023		Completed	Wodonga	HCU	XV19VU	Albury Workshop	P/MOVER	
1056	Wodonga - Workshop	Tyre Position 7 + 8		07/12/2023		Completed	Wodonga	HCU	XV19VU	Albury Workshop	P/MOVER	
1056	Wodonga - Workshop	Tyre Position 5 + 6		07/12/2023		Completed	Wodonga	HCU	XV19VU	Albury Workshop	P/MOVER	
1056	Wodonga - Workshop	Tyre Position 3 + 4		07/12/2023		Completed	Wodonga	HCU	XV19VU	Albury Workshop	P/MOVER	
1056	Wodonga - Workshop	A Service As Per Attached Checklist		30/11/2023	510410	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER	

1056	Wodonga - Workshop	MISJUDGED BRAKE %. (NOT MY WORK) REFITTED LR BRAKE/ WHEEL ASSEMBLY. TENSIONED WHEEL NUTS. FITTED NUT COVERS. REFIT ALL GUARDS. A		30/11/2023	510410	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Record Check Results As Attached To This Job		30/11/2023	510410	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	New Wiper Blades	REMOVED AND STRAIGHTENED WIPER ARMS.	23/11/2023		Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	C Service As Per Attached Checklist		09/11/2023	498241	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	End of Warrenty inspection		09/11/2023	498241	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	diff oil leak		09/11/2023	498241	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	NEW STRUTT BUSH ON DRIVER'S SIDE FRONT.		09/11/2023	498241	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Record Check Results As Attached To This Job		09/11/2023	498241	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
		Repair Drive Tyre Puncture (Beaurepaires Macsville)									
1056	Wodonga - Workshop	Purchase Order Number: WW081750		17/10/2023	647775	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Replaced H/Duty Trailer Plug		07/10/2023	470969	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	A Service As Per Attached Checklist		05/10/2023	470535	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	A SERVICE.		05/10/2023	470535	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	NEW STRUTT BUSH ON DRIVER'S SIDE FRONT.		05/10/2023	470535	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	BLOW OUT RADIATOR.	BLEW OUT RADIATOR AND INTERCOOLER.	05/10/2023	470535	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	STEER ROTATION.		05/10/2023	470535	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	BIT OF SPRAY FROM BACK DIFF WHICH WAS ONLY FIXED LAST WEEK.	TCTC.	05/10/2023	470535	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	CHECK DIFF BREATHERS.	TCTC.	05/10/2023	470535	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
			TCTC.								
			* Raise cab and lower bullbar								
			* Connect laptop and scanned for faults								
			* Check the pipework going to and returning from the aftertreatment DEF dosing unit for any signs of a leak - All ok								
			* Check the plumbing going to and coming from the SCR diesel exhaust fluid pump for any signs of a leak								
			* Diconnect batteries and the SRC diesel exhaust fluid supply pipe from aftertreatment nozzle								
			* Drain excess SRC diesel exhaust fluid								
			* Remove aftertreatment nozzle retaining nut								
			* Perform adblue over ride test to confirm pump is not blocked								
			* Found injector was cracked								
			* Removed and replaced injector								
			* Found plastic fitting on top of the injector to be brittle and cracked								
			* Replaced fitting								
			* Cleared all codes								
1056	Wodonga - Workshop	NOT USING MUCH ADBLUE.	* Test all operations - All ok, fault no longer present	05/10/2023	470535	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	TOP STRUT RUBBER ON PASSENGER SIDE DRIVE. FRONT ONE.		05/10/2023	470535	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
			FIT CIG SOCKET								
			REMOVE FRIDGE FOR WARRANTY PURPOSES.								
			pull interior apart.remove draw fridge. fit and wire up cig socket to constant power test ok put								
1056	Wodonga - Workshop	LIGHT PLUG.	interior back together	05/10/2023	470535	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	ABS PLUG.		05/10/2023	470535	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	PASSENGER STRUT RUBBER.		05/10/2023	470535	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	AFTER TREAT LIGHT COMES ON AND OFF.	TCTC.	05/10/2023	470535	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	PARKER LIGHTS KEEP TRIPPING CIRCUIT BREAKER IN TRUCK WHEN TURNING CORNERS.	HAGANS.	05/10/2023	470535	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Record Check Results As Attached To This Job		05/10/2023	470535	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Perform laser wheel alignment		22/09/2023		Completed	Wodonga	HCU	XV19VU	Albury Workshop	P/MOVER
1056	Wodonga - Workshop	Tyre Position 1 + 2		21/09/2023		Completed	Wodonga	HCU	XV19VU	Albury Workshop	P/MOVER
		A Service As Per Attached Checklist									
1056	Wodonga - Workshop	PO# WW081106		18/09/2023	110096	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Record Check Results As Attached To This Job		18/09/2023	110096	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	1-2		16/09/2023		Completed	Wodonga	HCU	XV19VU	Albury Workshop	P/MOVER
1056	Wodonga - Workshop	B SERVICE.	Refer Job # 417209	19/08/2023	441884	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	A SERVICE.	Refer Job # 417209	19/08/2023	441884	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
			* Carried out A & B Truck service as per Greenfreight service sheet schedule								
			* Replaced A/C belt whilst replacing tensioner								
			* Test all operations - All ok								
			FURTHER REPAIRS REQUIRED								
			*								
1056	Wodonga - Workshop	B Service As Per Attached Checklist	* Filler neck leak at block (monitor)	19/08/2023	441884	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	B SERVICE. 14000 OVERDUE.		19/08/2023	441884	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	NOT USING MUCH ADBLUE.		19/08/2023	441884	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	BOTH DIFFS LEAKING.		19/08/2023	441884	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	TOP STRUT RUBBER ON PASSENGER SIDE DRIVE. FRONT ONE.		19/08/2023	441884	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	LIGHT PLUG.		19/08/2023	441884	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	ABS PLUG.		19/08/2023	441884	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	DIFF LEAKING.		19/08/2023	441884	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	PASSENGER STRUT RUBBER.		19/08/2023	441884	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
		A SERVICE.									
		TRAILER SERVICE.									
1056	Wodonga - Workshop	NEW SERVICE STICKERS FOR UPCOMING SERVICES.	Refer Job # 417209	19/08/2023	441884	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	DIFF LEAKS ON BOTH DIFFS.		19/08/2023	441884	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	AFTER TREAT LIGHT COMES ON AND OFF.		19/08/2023	441884	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	PARKER LIGHTS KEEP TRIPPING CIRCUIT BREAKER IN TRUCK WHEN TURNING CORNERS.		19/08/2023	441884	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Record Check Results As Attached To This Job		19/08/2023	441884	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	A SERVICE.		20/07/2023	412046	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
		A SERVICE.									
		TRAILER SERVICE.									
1056	Wodonga - Workshop	NEW SERVICE STICKERS FOR UPCOMING SERVICES.		20/07/2023	412046	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	A Service As Per Attached Checklist	REPLACED SHOCK RUBBERS.	20/07/2023	412046	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	AFTER TREAT LIGHT COMES ON AND OFF.		20/07/2023	412046	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	PARKER LIGHTS KEEP TRIPPING CIRCUIT BREAKER IN TRUCK WHEN TURNING CORNERS.		20/07/2023	412046	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Record Check Results As Attached To This Job		20/07/2023	412046	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Repair Front Diff Oil Leak		31/05/2023	647775	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
		Repair After Treatment Issues (Brown & Hurley Coffs)									
1056	Wodonga - Workshop	Purchase Order Number: WW078661		30/05/2023	647775	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	C Service	Refer Job # 411070	25/05/2023	369698	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	C Service As Per Attached Checklist	CARRY OUT GREENFREIGHT A,B & C SERVICE WITH SERVICE SHEETS PROVIDED	25/05/2023	369698	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	C SERVICE.	Refer Job # 411070	25/05/2023	369698	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	C SERVICE.	Refer Job # 411070	25/05/2023	369698	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Rear Diff Leak	Refer Job # 411079	25/05/2023	369698	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
			CARRIED OUT ENGINE TUNE AND CHECK INTERNAL COMPONENTS IN TOP OF ENGINE AS REQUIRED								
			- Removed rocker cover to access internal components								
			- Check top end components								
			- Adjust valve clearance to specification								
			- Set all parameters to specification								
			- Install rocker cover & components complete								
1056	Wodonga - Workshop	Tune Up.	- Test, confirm & quality check engine operation	25/05/2023	369698	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Voltmetre not working.		25/05/2023	369698	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Diff Oil Change		25/05/2023	369698	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	DIFF LEAK ON REAR DIFF. BREATHER?		25/05/2023	369698	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	DRIVER'S SIDE MUDFLAP HANGING ON 2 BOLTS.		25/05/2023	369698	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	FEEDER HOSE FOR ADBLUE KEEPS COMING OFF WHERE IT GOES INTO THE EXHAUST.		25/05/2023	369698	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	AFTER TREAT LIGHT ON A LOT.		25/05/2023	369698	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	NEW BATTERIES.		25/05/2023	369698	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	AIR LEAKING INTO FRONT DIFF		25/05/2023	369698	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Record Check Results As Attached To This Job		25/05/2023	369698	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Tyre Position 1 + 2		07/05/2023		Completed	Wodonga	HCU	XV19VU	Albury Workshop	P/MOVER
1056	Wodonga - Workshop	A Service As Per Attached Checklist		07/04/2023	335059	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	A SERVICE.		07/04/2023	335059	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	A SERVICE.		07/04/2023	335059	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	VOLT METER NOT WORKING.		07/04/2023	335059	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	MUDFLAP HANGING ON BY 2 BOLTS, NEEDS NEW MUDFLAP.. NUDFLAP HANGING ON BY 2 BOLTS, NEEDS NEW MUDFLAP.		07/04/2023	335059	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	AFTER TREAT LIGHT BEEN ON FOR MOST OF TRIP SINCE BRISBANE.		07/04/2023	335059	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	VOLTMETRE NOT WORKING SINCE NEW ALTERNATOR.. VOLTMETRE NOT WORKING SINCE NEWE ALTERNATOR.		07/04/2023	335059	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Record Check Results As Attached To This Job		07/04/2023	335059	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	aftertreat light on	cummins wodonga POww077410	22/03/2023	647775	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	A Service As Per Attached Checklist		16/03/2023	317694	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	A SERVICE.		16/03/2023	317694	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Record Check Results As Attached To This Job		16/03/2023	317694	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	VOLTMETRE NOT WORKING SINCE NEWE ALTERNATOR.		16/03/2023	317694	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	AIR LEAKING INTO FRONT DIFF		16/03/2023	317694	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	CHECKED CHARGING SYSTEM.		13/03/2023		Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	A Service Due		02/03/2023	306502	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	A Service As Per Attached Checklist	REPLACED TRAILER PLUG WITH HEAVY DUTY.	02/03/2023	306502	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Heavy Duty Plug		02/03/2023	306502	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER

		New Drivers Side Windscreen Autotek Albury											
1056	Wodonga - Workshop	PO# WW077020. New Drivers Side Windscreen		02/03/2023	306502	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	Record Check Results As Attached To This Job		02/03/2023	306502	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	JUMP STARTED.		27/02/2023		Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	Tyre Position 9 + 10		19/02/2023		Completed	Wodonga	HCU	XV19VU	Albury Workshop	P/MOVER		
1056	Wodonga - Workshop	Tyre Position 7 + 8		19/02/2023		Completed	Wodonga	HCU	XV19VU	Albury Workshop	P/MOVER		
1056	Wodonga - Workshop	Tyre Position 5 + 6		19/02/2023		Completed	Wodonga	HCU	XV19VU	Albury Workshop	P/MOVER		
1056	Wodonga - Workshop	Tyre Position 3 + 4		19/02/2023		Completed	Wodonga	HCU	XV19VU	Albury Workshop	P/MOVER		
1056	Wodonga - Workshop	A SERVICE.		11/02/2023	294663	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	B Service As Per Attached Checklist		11/02/2023	294663	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	A SERVICE.		11/02/2023	294663	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	ALTERNATOR LIGHT OCCASIONALLY COMES ON GAUGE FLOATS AROUND A BIT.	CHECKED FITTINGS & BELT TENSION. COULDN'T FAULT.	11/02/2023	294663	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	GRILL PIECE IS LOOSE.		11/02/2023	294663	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	EXHAUST STACK BRACKET BROKEN/ LOOSE.		11/02/2023	294663	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	TUNE UP?		11/02/2023	294663	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	AIR LEAKING INTO FRONT DIFF	??	11/02/2023	294663	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	Record Check Results As Attached To This Job		11/02/2023	294663	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	A Service As Per Attached Checklist	REPLACED TOWN HORN. ADJUSTED CLUTCH.	26/01/2023	283196	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	Record Check Results As Attached To This Job		26/01/2023	283196	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	AIR LEAKING INTO FRONT DIFF		12/01/2023	271815	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	A SERVICE.	Please refer Job # 400413	12/01/2023	271815	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	A Service As Per Attached Checklist		12/01/2023	271815	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	THROUGH-SHAFT SEAL LEAKING.		12/01/2023	271815	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	Record Check Results As Attached To This Job		12/01/2023	271815	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
		WINDSCREEN DRIVER'S SIDE. AUTOTEK ALBURY TO REPLACE											
1056	Wodonga - Workshop	PO# WW076098. WINDSCREEN DRIVER'S SIDE.		11/01/2023	647775	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	A Service As Per Attached Checklist		29/12/2022	260698	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	THROUGH-SHAFT SEAL LEAKING.		29/12/2022	260698	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	TUNE UP?		29/12/2022	260698	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	Record Check Results As Attached To This Job		29/12/2022	260698	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	A SERVICE.		15/12/2022	251822	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	B SERVICE.		15/12/2022	251822	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	A Service As Per Attached Checklist		15/12/2022	251822	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	STEERING WHEEL LOCK NOT HOLDING.		15/12/2022	251822	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	TUNE UP?		15/12/2022	251822	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	STEERING WHEEL LOCK NOT HOLDING.		15/12/2022	251822	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	DIFF OIL CHANGE.		15/12/2022	251822	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	Blow out Radiator		15/12/2022	251822	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	Record Check Results As Attached To This Job		15/12/2022	251822	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
		B Service As Per Attached Checklist											
1056	Wodonga - Workshop	Oil Sample Number: SIF 42627888		01/12/2022	239876	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	STEERING WHEEL LOCK NEEDS TIGHTENING.		01/12/2022	239876	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	Steering wheel lock faulty, wheel goes while locked.		01/12/2022	239876	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	Blow out Radiator		01/12/2022	239876	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	Record Check Results As Attached To This Job		01/12/2022	239876	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	Tyre Position 1 + 2		24/11/2022		Completed	Wodonga	HCU	XV19VU	Albury Workshop	P/MOVER		
1056	Wodonga - Workshop	A Service As Per Attached Checklist		15/11/2022	228059	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	Record Check Results As Attached To This Job		15/11/2022	228059	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	A Service As Per Attached Checklist		02/11/2022	218950	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	A Service		02/11/2022	218950	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
		Oil pressure sensor leaking. Sent to Cummins for repair.											
1056	Wodonga - Workshop	Truck under Warranty.		02/11/2022	218950	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	Blow out Radiator		02/11/2022	218950	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	A SERVICE.		02/11/2022	218950	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	Record Check Results As Attached To This Job		02/11/2022	218950	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	DIFF LEAK.		02/11/2022	218950	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	A Service As Per Attached Checklist		20/10/2022	206982	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	Check Diff Leaks	UNBLOCKED FRONT DIFF BREATHER.	20/10/2022	206982	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	Record Check Results As Attached To This Job		20/10/2022	206982	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	Alternator light coming on intermitantly	Brown and Hurley Coffs Harbour to inspect	19/10/2022		Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	POS 1 & 2		30/09/2022		Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	C SERVICE.		29/09/2022	189246	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	ASSISTED BEAUREPAIRS. UNHOOKED. PARKED.		29/09/2022	189246	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	A SERVICE.		29/09/2022	189246	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	C Service As Per Attached Checklist		29/09/2022	189246	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	Record Check Results As Attached To This Job		29/09/2022	189246	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	A Service As Per Attached Checklist		15/09/2022	180526	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	Record Check Results As Attached To This Job		15/09/2022	180526	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	REPLACED FRONT MUDFLAPS. USED RF TO REPLACE LR.		08/09/2022	174848	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	A Service As Per Attached Checklist	ADDED 4L ENGINE OIL.	01/09/2022	168983	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	A SERVICE.		01/09/2022	168983	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	NEW GUARD ON DRIVE.	REPLACED OUTRIGGERS, LOOP KIT, MUDFLAP AND SUPPORT BRACKETS. HOOKED UP.	01/09/2022	168983	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	Record Check Results As Attached To This Job		01/09/2022	168983	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop			01/09/2022	168983	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	Tyre Position 9 + 10		01/09/2022		Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	Tyre Position 7 + 8		01/09/2022		Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	Tyre Position 5 + 6		01/09/2022		Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	supply and fit 8 tyres		01/09/2022		Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
		Left Hand Windscreen replacement											
1056	Wodonga - Workshop	Albury Autoscreens PO#WW073659		25/08/2022		Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	DROP OFF TCTC.		25/08/2022	63328	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
		Steering Wheel not staying in position.											
1056	Wodonga - Workshop	TCTC to repair under Warranty.		24/08/2022	647775	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
			Replaced diff oils. Front Diff Oil Sample SIF # 43273166										
1056	Wodonga - Workshop	Replace Diff Oils	Rear Diff Oil Sample SIF # 43276420	18/08/2022	160055	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	A Service As Per Attached Checklist	REPLACED DIFF OILS.	18/08/2022	160055	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	TRUCKSAFE STICKER OUT OF DATE.		18/08/2022	160055	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	Record Check Results As Attached To This Job		18/08/2022	160055	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	A SERVICE.		04/08/2022	149756	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	A Service As Per Attached Checklist		04/08/2022	149756	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	Record Check Results As Attached To This Job		04/08/2022	149756	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	supply and fit 2tyres		28/07/2022		Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	B Service As Per Attached Checklist	Engine Oil Sample SIF # 42623396	21/07/2022	138388	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	B Service		21/07/2022	138388	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	Record Check Results As Attached To This Job		21/07/2022	138388	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
		Brake Lights Staying on. Brown & Hurley organised to do works.											
1056	Wodonga - Workshop	PO# WW072834		19/07/2022		Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	ADJUSTED CLUTCH.		14/07/2022	132699	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	A Service As Per Attached Checklist		07/07/2022	127017	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	Record Check Results As Attached To This Job		07/07/2022	127017	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	A Service As Per Attached Checklist		24/06/2022	118429	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	fit new walk plate due to damage	Repaired trailer plug wiring damaged	24/06/2022	118429	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	repair damage to Air dryer purge tank		24/06/2022	118429	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	DRIVERS STEP.	Not damaged	24/06/2022	118429	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	REPLACE WORN TURNTABLE TOP.	Not required	24/06/2022	118429	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	Record Check Results As Attached To This Job		24/06/2022	118429	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	REPLACE WIPERS.	Not required	24/06/2022	118429	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	A Service As Per Attached Checklist		27/05/2022	98626	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	REPLACE WIPERS.		27/05/2022	98626	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	REPLACE WORN TURNTABLE TOP.		27/05/2022	98626	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	Record Check Results As Attached To This Job		27/05/2022	98626	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	A Service		05/05/2022	85990	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	A Service As Per Attached Checklist		05/05/2022	85990	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
1056	Wodonga - Workshop	Record Check Results As Attached To This Job		05/05/2022	85990	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		
		Drivers side windscreen replacement. Albury Autoscreen Replaced											
1056	Wodonga - Workshop	PO# WW071618. Drivers side windscreen replacement.		04/05/2022	647775	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER		

			SAMPLED AND REPLACED DIFF OILS. Engine Oil Sample SIF # 41797666 Front Diff Oil Sample SIF # 41797569									
1056	Wodonga - Workshop	B Service As Per Attached Checklist	Rear Diff Oil Sample SIF # 41797574	15/04/2022	77782	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Changed during service		15/04/2022	77782	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Record Check Results As Attached To This Job		15/04/2022	77782	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	FITTED CURTAINS.		04/04/2022		Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	SUPPLY AND FIT 2 TYRES		02/04/2022		Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	FIT RUNOUT		01/04/2022		Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	A Service As Per Attached Checklist		30/03/2022	66849	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	TRUCKSAFE STICKER OUT OF DATE.		30/03/2022	66849	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	SPEED PUT FROM 97 TO 100KM/H	PREVIOUSLY COMPLETED.	30/03/2022	66849	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Record Check Results As Attached To This Job		30/03/2022	66849	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	REPLACED SUZI COILS WITH TRAIL LINK ONES. REFIT QUICK RELEASE COUPLINGS IN LOW MOUNT PLATE.		24/03/2022	63933	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	REMOVED AND TRIMMED DAMAGED WALK PLATE.		21/03/2022	60966	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	REPLACE BOTH CRACKED/ CHIPPED WINDSCREENS.		17/03/2022	58115	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	REPLACE WORN TURNTABLE TOP.		17/03/2022	58115	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	CAN THE BUNK COOLER VENTS BE FLIPPED?	NO.	17/03/2022	58115	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	A Service As Per Attached Checklist		17/03/2022	58115	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	BUTTON ON CLUTCH FOR ENGINE/ CRUISE IS RIGHT AT THE END OF THE PEDAL.		17/03/2022	58115	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Record Check Results As Attached To This Job		17/03/2022	58115	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	REPLACE BOTH CRACKED/ CHIPPED WINDSCREENS. Replace left & Right hand windscreens Albury Autoglass	Refer Job # 375091	16/03/2022	647775	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	PO#WW070695 - 1		16/03/2022	647775	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	BUTTON ON CLUTCH FOR ENGINE/ CRUISE IS RIGHT AT THE END OF THE PEDAL.		03/03/2022	46651	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	A Service As Per Attached Checklist		03/03/2022	46651	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Record Check Results As Attached To This Job		03/03/2022	46651	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	A SERVICE. NEEDS 4 OR SO LITRES OF OIL.		03/03/2022	46651	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	repiar suzi coils due to being damaged	Brown and hurley coffs habour to carry out repair P/O WW070263	18/02/2022	647775	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	A Service As Per Attached Checklist		17/02/2022	34833	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Record Check Results As Attached To This Job		17/02/2022	34833	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
			Brown & Hurley Darra								
1056	Wodonga - Workshop	Replace damaged suzi leads and electrical lead	PO # WW070118	11/02/2022	647775	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	A Service As Per Attached Checklist		28/01/2022	19921	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Record Check Results As Attached To This Job		28/01/2022	19921	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Instruments & Gauges		20/01/2022		Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	ABS/ATC & ESC truck lights displayed came on after driving through a storm and now wont turn off.	Sent to TCTC for diagnosis	19/01/2022	647775	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Instruments & Gauges		19/01/2022	647775	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
			* Removed/replaced engine filter & oil, specification used in parts section below. * Check all engine operation & components * Removed/replaced transmission oil filter * Check all hydraulic lines fitting & level lubricant levels to specification * Removed/replaced power steering filter & gasket * Removed/replaced differential oil, specification used in parts section below. * Removed/replaced fuel filter * Check cooling system & pressure test * Check all belts, idler pulleys, fan, shrouds & adjust to specification * Check all electrical routing, wiring looms, switches, sensors & components * Check all wheel equipment & steering components * Check all braking & adjust to specification * Check clutching & adjust to specification * Check all suspension components * Check all internal cabin operation, components & adjust to specification * Check all external cabin components & adjust to specification * Check windscreen washers, wipers, refill & test operation * Lubricate, adjust relevant components as required * Re torque all fitting & fixtures * Wash vehicle complete								
		The following 1st service inspection for Greenfreight Distribution Pty Ltd, to a K200 Kenworth Truck,									
1056	Wodonga - Workshop	Chassis#6F5000000MA471426, and registration #XV19VU included:	* Road test, confirm & quality check	15/01/2022	10826	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	JUMP START.		14/12/2021		Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	reset air bag height to comply with PBS 2 x Stickers 3 Points of Contact Safepak Albury	TCTC to carry out adjustment	25/11/2021	647775	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	PO#WW068705		23/11/2021	593	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Truck Pre Delivery	TARE= 10850KG	23/11/2021	593	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Tyre Position 9 + 10		20/11/2021	600	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Tyre Position 7 + 8		20/11/2021	600	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Tyre Position 5 + 6		20/11/2021	600	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
1056	Wodonga - Workshop	Tyre Position 3 + 4		20/11/2021	600	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER
		*MT Data Install-MDVR *IAP Install Tablet serial # 000041726 Tracking unit serial # 479001826 Tracking unit sim card # 8200098249541 Tag #'s 024950 & 024949 MDVR serial # C704CBAFC1891 Phone # 0409880277	Mount and wire up supplied IAP tracking unit under passenger seat. Mount GPS and high gain antennas on rope rail above LH door just behind door. Mount tablet and mic above radio & gauges, mount speaker above rear of RH door. Mount MDVR under passenger seat, wire up, mount forward facing camera, run wiring and connect camera to MDVR. Connect and wire in engine data control box to CAN wiring & power and earth as necessary. Connect scales to tracking unit. Connect power, earth & ignition, mic and speaker, re-assemble truck and test. Contact MtData support to setup and test unit. Complete IAP								
1056	Wodonga - Workshop	Support persons name -Sudha	paperwork & send off.	27/10/2021	447	Completed	Wodonga	HCU	XV19VU	Wodonga Workshop	P/MOVER