EquipmentName	Workshop	CodeAndSubCode	Description	CompletionComments	DateDone	Workstate	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
T564	Wodonga - Workshop	Body\TRL FLOOR	Move Mezz Decks	Finished mezzanine deck and welded skidplate	25/06/2026	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection		25/06/2026	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\AIR LEAK	Air leak somewhere under rear axle's.		25/06/2026	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	VehService\DS D Service		25/06/2026	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\TP11	Tyres\TP11 (31)		06/03/2026	Completed	Tliner	Wodonga	HCU	YV97EU	BORDER BANDAG PTY LTD	TRAILER
T564	Wodonga - Workshop	Body\TRL FLOOR	Check Mezz Deck Height & Adjust If Required		28/02/2026	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	VehService\DS D Service		27/02/2026	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\TP05	Tyres\TP05 (25)		19/11/2025	Completed	Tliner	Wodonga	HCU	YV97EU	BORDER BANDAG PTY LTD	TRAILER
				-air locker signal wire was installed incorrectly, repaired as required								
				-floor battery missing								
T564	Wodonga - Workshop	Body\TRL FLOOR	SET MEZZININE FLOOR TO FLAT FLOOR LEVEL	-floor moved into position with wiring disconnected	17/10/2025	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\HCV	Trailer Ride Height Seems To Be Very Low Has Been Rubbing On Tyres		10/10/2025	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	VehService\DS D Service		10/10/2025	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	VehService\DS D Service	Lfl air bag will need replacing soon	09/08/2025	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	VehService\DS D Service		23/06/2025	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	Remove curtains.		14/05/2025	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	LEFT SIDE REAR ROLLER TORN AWY FROM CURTAIN.	I have completed this job, as the curtains have been swapped out for another set.	13/05/2025	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	Curtains need major repairs	I have completed this job, as the curtains have been swapped out for another set.	13/05/2025	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	NEW CURTAINS OR MAJOR REPAIR.	I have completed this job,as the curtains have been swapped out with a better set.	13/05/2025	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	curtain rollers catching in tracks	This job has been completed because second hand curtains have been fitted to trailer.	13/05/2025	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\TP12	Tyres\TP12		20/12/2024	Completed	Tliner	Wodonga	HCU	YV97EU	BEAUREPAIRES	TRAILER
T564	Wodonga - Workshop	VehService\DS	VehService\DS		09/11/2024	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\TP5+6	Tyres\TP5+6+1+9+10		18/10/2024	Completed	Tliner	Wodonga	HCU	YV97EU	Myrtleford Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	VehService\DS		08/10/2024	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\TP1+2	Tyres\TP1+2		30/08/2024	Completed	Tliner	Wodonga	HCU	YV97EU	BEAUREPAIRES - 3	TRAILER
T564	Wodonga - Workshop	Tyres\TP3+4	Tyres\TP3+4		30/08/2024	Completed	Tliner	Wodonga	HCU	YV97EU	BEAUREPAIRES - 3	TRAILER
T564	Wodonga - Workshop	Tyres\TP7+8	Tyres\TP7+8		30/08/2024	Completed	Tliner	Wodonga	HCU	YV97EU	BEAUREPAIRES - 3	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service		27/08/2024	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\TP01	Tyres\TP01		26/08/2024	Completed	Tliner	Wodonga	HCU	YV97EU	BEAUREPAIRES	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	Temporally Repair L/H Curtain (G&S Diesel P/O: WW088275)		19/08/2024	Completed	Tliner	Wodonga	HCU	YV97EU	G & S DIESEL SERVICE	TRAILER
T564	Wodonga - Workshop	Tyres\TP02	Tyres\TP02		13/06/2024	Completed	Tliner	Wodonga	HCU	YV97EU	BEAUREPAIRES	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		20/04/2024	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		20/04/2024	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	CURTAINS IN VERY POOR CONDITION.		07/04/2024	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		07/04/2024	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	REPAIR CRACKED UPRIGHTS.		07/04/2024	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		07/04/2024	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	REPAIR CRACKED UPRIGHTS.		09/02/2024	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	CURTAINS ARE IN VERY POOR CONDITION.		09/02/2024	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL FLOOR	MOVED INTO PLACE AND DISABLED MEZZ DECK.		09/02/2024	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		09/02/2024	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		09/02/2024	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist		25/01/2024	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL FLOOR	Mezz Floors does not move.		25/01/2024	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	DrivLine\AXLE REPLC	Replace 3 x Axles at TCTC approved by Wayne De Larue.		25/01/2024	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		25/01/2024	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		25/01/2024	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	Over due for Service last service 07/23	Refer job # 421550	08/10/2023	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		08/10/2023	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		08/10/2023	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\PRES CHECK	1-12		03/10/2023	Completed	Tliner	Wodonga	HCU	YV97EU	Albury Workshop	TRAILER
				* Removed components for access								
				* Removed blown shocks								
				* Removed worn airbags								
				* Repaired damaged airline								
				* Fit new shocks and airbags as required								
				* Aligned & tensioned all as required								
T564	Wodonga - Workshop	Susp\SHOCK ABS	BLOWN SHOCKS	* Test operations - All ok, faults no longer present	25/07/2023	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	DrivLine\AXLE REPLC	Replace 3 x Axles at TCTC approved by Wayne De Larue.		25/07/2023	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes\BRK RELINE	REAR BRAKE SHOES LOW AS POINTED OUT BY NHVR ON THE 16/3/23.		25/07/2023	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
				REPLACE FRONT AXLE BUSHES								
				* Inspected axles								
				* Found lip in axles								
				* Removed all components								
				* Removed axles								
				* Found axle unserviceable and require replacement								
				* Removed height control valve from old axle								
				* Fit to new axle								
				* Positioned axles under trailer								
				* Lifted axles into place								
				* Aligned & tensioned as required								
				* Fit all ABS sensors and replaced damaged LHR sensor								
				* Adjusted brakes and ride height								
				* Fit wheels and tensioned as required								
				* Lowered trailer								
				* Re-tensioned all components								
T564	Wodonga - Workshop	Susp\SUSPENSION	FRONT AXLE BUSHES.	* Test all operations - All ok	25/07/2023	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
				* Removed springs								
				* Pressed out damaged bushes and pressed in new bushes as required								
				* Refit springs with new spring wraps								
				* Replaced worn springs								
			2 x broken spring wraps LHS.	* Replaced all U-Bolts								
			Sent to TCTC for repairs.	* Aligned & Tensioned as required								
T564	Wodonga - Workshop	Susp\SPRNG PACK	LH SPRING WRAPS BROKEN, SPRING EYE BOLTS, BUSHES AND NUTS & LEAF SPRINGS FOUND UNSERVICEABLE	* Test all operations - All ok	25/07/2023	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
			CURTAINS TO BE REPAIRED AT TWIN CITY GRAPHICS.									
T564	Wodonga - Workshop	Body\TRL REPS	TC Graphics Repaired.		07/07/2023	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes\BRK RELINE	REAR BRAKE SHOES LOW AS POINTED OUT BY NHVR ON THE 16/3/23.		05/07/2023	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\SUSPENSION	FRONT AXLE BUSHES.		05/07/2023	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Elect\INDICATORS	WORN THROUGH INDICATOR WIRE EARTHING OUT ON DRIVER'S SIDE WHERE IT GOES INTO TAIL LIGHT ASSEMBLY.		05/07/2023	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Elect\ELECT P&W	WIRE FOR INDICATOR HAS RUBBED THROUGH AND EARTHING OUT WHERE IT GOES THROUGH TO TAIL LIGHT ASSEMBLY. DRI	NOFAULT FOUND	05/07/2023	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Elect\ELECT P&W	MISSING CLEARANCE LIGHT NEAR BACK TRI PASSENGER SIDE.		05/07/2023	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	NEEDS ABOUT 5 OR 6 NEW BUCKLES OVER THE 2 TRAILERS.. NEEDS ABOUT 5 OR 6 NEW BUCKLES OVER THE Z TRAILERS.		05/07/2023	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\SPRNG PACK	2 x broken spring wraps LHS.		05/07/2023	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Elect\ELECT P&W	LR CLEARANCE LIGHT OUT.		05/07/2023	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	CURTAINS TO BE REPAIRED AT TWIN CITY GRAPHICS.		05/07/2023	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	ADJUSTED LM LF WHEEL BEARINGS.	04/07/2023	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		04/07/2023	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	Carry out crack repairs to damaged components		02/07/2023	Completed	Tliner	Wodonga	HCU	YV97EU	Albury Workshop	TRAILER
T564	Wodonga - Workshop	Susp\SPRNG PACK	2 x broken spring wraps LHS.		20/05/2023	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		20/05/2023	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes\BRK RELINE	REAR BRAKE SHOES LOW AS POINTED OUT BY NHVR ON THE 16/3/23.		20/05/2023	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\SUSPENSION	FRONT AXLE BUSHES.		20/05/2023	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Elect\INDICATORS	WORN THROUGH INDICATOR WIRE EARTHING OUT ON DRIVER'S SIDE WHERE IT GOES INTO TAIL LIGHT ASSEMBLY.		20/05/2023	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Elect\ELECT P&W	WIRE FOR INDICATOR HAS RUBBED THROUGH AND EARTHING OUT WHERE IT GOES THROUGH TO TAIL LIGHT ASSEMBLY. DRI		20/05/2023	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Elect\ELECT P&W	MISSING CLEARANCE LIGHT NEAR BACK TRI PASSENGER SIDE.		20/05/2023	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	NEEDS ABOUT 5 OR 6 NEW BUCKLES OVER THE Z TRAILERS.		20/05/2023	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Elect\ELECT P&W	LR CLEARANCE LIGHT OUT.		20/05/2023	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		20/05/2023	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		16/03/2023	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Elect\ELECT P&W	MISSING CLEARANCE LIGHT NEAR BACK TRI PASSENGER SIDE.		16/03/2023	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER

T564	Wodonga - Workshop	Body\TRL REPS	NEEDS ABOUT 5 OR 6 NEW BUCKLES OVER THE Z TRAILERS.		16/03/2023	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	CURTAINS TO BE REPAIRED AT TWIN CITY GRAPHICS.		16/03/2023	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		16/03/2023	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Elect\ELECT P&W	LR CLEARANCE LIGHT OUT.		16/03/2023	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\BREAKDOWN	Breakdown		10/03/2023	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		02/03/2023	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service due		02/03/2023	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Elect\ELECT P&W	MISSING CLEARANCE LIGHT NEAR BACK TRI PASSENGER SIDE.		02/03/2023	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	NEEDS ABOUT 5 OR 6 NEW BUCKLES OVER THE Z TRAILERS.		02/03/2023	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Elect\ELECT P&W	3 CLEARANCE LIGHTS NOT WORKING.		02/03/2023	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Elect\ELECT P&W	SAME ISSUE AS A TRAILER WITH BRAKE LIGHTS.		02/03/2023	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Elect\ELECT P&W	WIRES DRAGGING UNDER TRUCK.		02/03/2023	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		02/03/2023	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\AIR BAG	REPAIRED AIR LINE TO RR AIRBAG.		19/02/2023	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\TP11+12	Tyre Position 11 + 12		28/01/2023	Completed	Tliner	Wodonga	HCU	YV97EU	Albury Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\TP9+10	Tyre Position 9 + 10		28/01/2023	Completed	Tliner	Wodonga	HCU	YV97EU	Albury Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		26/01/2023	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	NEEDS ABOUT 5 OR 6 NEW BUCKLES OVER THE Z TRAILERS.		26/01/2023	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Elect\ELECT P&W	SAME ISSUE AS A TRAILER WITH BRAKE LIGHTS.		26/01/2023	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Elect\ELECT P&W	WIRES DRAGGING UNDER TRUCK.		26/01/2023	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		26/01/2023	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	CURTAINS TO BE REPAIRED AT TWIN CITY GRAPHICS.		12/01/2023	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	Curtains Damaged	REPLACED 20 BUCKLES AND STRAPS. REPAIRED CRACKS AT FRONT WALL, MEZZ DECK, UPRIGHTS AND GOOSENECK. CABLE TIED CURT	12/01/2023	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		29/12/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		29/12/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL FLOOR	MEZZ FLOOR NEEDSTO COME DOWN 1 HOLE. LOST POWER WHEN I HAD TO MOVE IT SO COLES COULD GET A PALLET OUT.		29/12/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		29/12/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		29/12/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		15/12/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL FLOOR	MEZZ FLOOR NEEDSTO COME DOWN 1 HOLE. LOST POWER WHEN I HAD TO MOVE IT SO COLES COULD GET A PALLET OUT.		15/12/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		15/12/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL FLOOR	CHAIN FOR MEZZ FLOOR CAN'T PLEASE BE REMOVED OR REPAIRED.		08/12/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist		01/12/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Myrtleford Workshop	TRAILER
T564	Myrtleford - Workshop	Body\TRL FLOOR	MEZZ FLOOR NEEDSTO COME DOWN 1 HOLE. LOST POWER WHEN I HAD TO MOVE IT SO COLES COULD GET A PALLET OUT.		01/12/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Myrtleford Workshop	TRAILER
T564	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		01/12/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Myrtleford Workshop	TRAILER
T564	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist		03/11/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	Curtains Damaged		03/11/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		03/11/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		03/11/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	DROP BUCKLE HAS BIG TEAR AND NEEDS TO BE REPAIRED.		02/11/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Elect\ELECT P&W	MISSING CLEARANCE LIGHT ON PASSENGER SIDE ABOVE FRONT AXLE.		02/11/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	HOLES IN CURTAINS NEED REPAIR.		02/11/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	CURTAIN REPAIRS/ HOLES NEED PATCHING. TEARS ON DROP SECTIONS.		02/11/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	Belly buckles need fixing, starting to tear		02/11/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	Holes in curtains		02/11/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	CURTAINS DAMAGED.		02/11/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	RR CURTAIN POLE CHANNEL BENT IN.		02/11/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	LR DROP DECK FLAP MISSING. HOLES AND RIPS.		02/11/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\CHAS CRACK	CRACKS AT GOOSE NECK.		02/11/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\CHAS CRACK	Cracks in Mezz Deck uprights.		02/11/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	CURTAINS DAMAGED.		20/10/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		20/10/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		20/10/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		15/09/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		15/09/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		18/08/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	Belly buckles need fixing, starting to tear		18/08/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	RR CURTAIN POLE CHANNEL BENT IN.		18/08/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	LR DROP DECK FLAP MISSING. HOLES AND RIPS.		18/08/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		18/08/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	REPLACED LF CURTAIN RATCHET.		31/07/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\SUSPENSION	REPLACED RF SEB.		14/07/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	STRAPPED DOWN MEZ DECK. REPLACED 5 STRAPS AND BUCKLES.	07/07/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	RR CURTAIN POLE CHANNEL BENT IN.		07/07/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job Air leak in hose Inland Truck centre Dubbo		07/07/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes\AIR LEAK	PO# WW072572		04/07/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\AIR BAG	air bag issues	taree kenworth atending PO	06/06/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Unknown	SERVICE		27/05/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	REPLACED 2 STRAPS.	27/05/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	Drop buckle ripped off passenger side.		27/05/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\AIR FITTIN	New Suzi couplings required.		27/05/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		27/05/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		15/04/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		15/04/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	REPAIRED DAMAGED RR CURTAIN POLE C CHANNEL.		28/03/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	REPLACED BROKEN LR U-BOLTS.	24/03/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		24/03/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\AIR LEAK	REPAIRED AIR LEAK AT RM AIR BAG LINE.		24/02/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\CHAS CRACK	CRACKS AT GOOSE NECK.		17/02/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	LR DROP DECK FLAP MISSING. HOLES AND RIPS.		17/02/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		17/02/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL FLOOR	mez deck motor not working		17/02/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		17/02/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\TP11+12	Tyre Position 11 + 12		04/02/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\TP9+10	Tyre Position 9 + 10		04/02/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\TP7+8	Tyre Position 7 + 8		04/02/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\TP3+4	Tyre Position 3 + 4		04/02/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\TP1+2	Tyre Position 1 + 2		04/02/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	REPLACED STAP AND BUCKLES.		14/01/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	ADJUSTED LF LR WHEEL BEARINGS	14/01/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL FLOOR	mez deck motor not working		14/01/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\SHOCK ABS	LM LR SHOCKS NEED REPLACING.		14/01/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\CHAS CRACK	Cracks in Mezz Deck uprights.		14/01/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		14/01/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\STRAPS	BELLY RATCHET MISSING POP RIVET	REPLACED BUCKLE AND STRAP.	06/01/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\PANELS	COVER UNDER MEZZ FLOOR LOOSE	REPLACED NUTS AND BOLTS ON COVER. PARK.	06/01/2022	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	REPLACED RM LR SEB AND LM LR SHOCKS. REPAIRED AIR AT ABS MODULE.	23/12/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		23/12/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\SHOCK ABS	LM LR SHOCKS NEED REPLACING.		28/10/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	PICK UP TRAILERS. ADJUSTED ALL WHEEL BEARINGS.	28/10/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	PARK OUTSIDE.	28/10/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Elect\TRL LIGHTS	Clearance light not working in the middle of the drivers side.		28/10/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL FLOOR	mez deck motor not working		28/10/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body			28/10/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		28/10/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\TP5+6	supply and fit 2 tyres		29/09/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\PRES CHECK	Pressure Check		18/09/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER

T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		11/09/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		11/09/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body			09/09/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL FLOOR	mez deck motor not working		09/09/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\CHAS CRACK	Cracks in Mezz Deck uprights.		09/09/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Workshop\MOVE ASSET	Moving Assets.		07/08/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Elect\SUZI COIL	Replaced trailer light plug + right rear taillight blinker.		07/08/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL FLOOR	Replaced left side damaged rail on side of trailer. Check all over for air leaks.		07/08/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\AIR LEAK	Found two clamps loose and drain cock valve. Replaced. Right top rear blinker missing. Right side wall blinker not working. Two side wall clearance lights bent.		07/08/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Elect\TRL LIGHTS	Left side front clearance light not working.		07/08/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\SPRNG HANG	Left middle spring arm support plate broken.(Spring Wrapper)		07/08/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL WALL	Multiple cracks inside front wall.		07/08/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	Seven straps missing. Record Check Results As Attached To This Job		07/08/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Full reline required.		07/08/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\SPRNG HANG	LM Spring wrapper is worn.	Replaced.	07/08/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Elect\INDICATORS	Right Rear top Blinker out.		07/08/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	DrivLine\WHEEL BRGS	Rear axles will need doing next service. 2 x clearance lights U/S		07/08/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Elect\TRL LIGHTS	Right hand Top indicater U/S		07/08/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Elect\TRL LIGHTS	R.H. clearance light broken (sidewall)		07/08/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\LIGHTS	L front clearance light		07/08/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\MUDGUARDS	LHF guard bracket cracked		07/08/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\MUDGUARDS	RHF guard bracket cracked		07/08/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes\L.H.M	Reline Due on left Hand Middle		07/08/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\SKID PLATE	Skid Plate still cracked, U/S		07/08/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Elect\BRK RELINE	LH low		07/08/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\SUSPENSION	LHM trailer arm strap broken multiple cracks on this trailer		07/08/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\CHAS CRACK	Both front uprights and both rear goosenecks.		07/08/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\FIFTH WHEE	skid plate worn needs replacing Pick up trailers from yard + build air of the trailer.	As per Job# 349332	07/08/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Workshop\MOVE ASSET	Sweep floor befor service. Right top rear blinker missing. Right side wall blinker not working. Two side wall clearance lights bent.		07/08/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Elect\TRL LIGHTS	Left side front clearance light not working.		07/08/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\SPRNG HANG	Left middle spring arm support plate broken.(Spring Wrapper)		07/08/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	DrivLine\WHEEL BRGS	LM, LF and RM needed adjusting.		07/08/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL WALL	Multiple cracks inside front wall.		07/08/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	Seven straps missing.		07/08/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		07/08/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\FAILURE	Tyre check.		07/08/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL FLOOR	mez deck motor not working Record Check Results As Attached To This Job		07/08/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Full reline required.		07/08/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	L/H/R curtain grabbing, Im jamming my back everytime I move it.		05/08/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	Buckles on L/H/R need replacing someone has hit the trailer on something. L/H/R curtain getting stuck it will break if not fixed ASAP. All rollers need replacing.		05/08/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	Uprights for back not attached at top unsafe.		05/08/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	Rips, Holes and rollers needed.	completed at TCTC Graphics	05/08/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	holes		05/08/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Steering\WHEEL ALGN	Pulling to the left - Refer Dean.		14/07/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\SPRNG PACK	Rear Left Spring Eye bush needs replacing.	previously completed	14/07/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\SUSPENSION	DROP AT HTT SPLIT TRAILERS AND UNLOAD TRAILER. PICK UP FROM CUMMINS.		10/07/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Steering\WHEEL ALGN	Pulling to the left - Refer Dean.	Wheel Alignment needed.	03/07/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\SHOCK ABS	bushes worn	Replaced right hand rear spring eye bush and spring wrap.	03/07/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\TRL LEGS	Legs are getting noisy and grinding intermittenly.	Inspected all OK changed Bolt.	03/07/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	Replace damaged buckles. L/H/R curtain getting stuck it will break if not fixed ASAP. All rollers need replacing.	Completed.	03/07/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	Uprights for back not attached at top unsafe.		03/07/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL FLOOR	mez deck motor not working	Loaded could not get to deck.	03/07/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Workshop\MOVE ASSET	Take trailer from Trailer shed to put over pit.		26/06/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Workshop\CLEAN	Finish paperwork for handover.		26/06/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\SPRNG HANG	LM Spring wrapper is worn.	Albury Truck & Trailer	26/06/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\SPRNG PACK	Rear Left Spring Eye bush needs replacing.	KIT REPAIR SPRING EYE BPW "AL" SUSP'N TAPER HANGER 70MM SPRIN	26/06/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	DrivLine\WHEEL BRGS	All 6 Wheel bearing need adjustment.	Adjusted all 6 wheel bearings.	26/06/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Elect\INDICATORS	Right Rear top Blinker out.		26/06/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		26/06/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	Replace damaged buckles.		26/06/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	L/H/R curtain getting stuck it will break if not fixed ASAP. Record Check Results As Attached To This Job		26/06/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Need Reline ASAP.		26/06/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		29/05/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Workshop\CLEAN	Clean trailer shed service bay and move trailers.		29/05/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	DrivLine\WHEEL BRGS	Rear axles will need doing next service.		29/05/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist 2 x clearance lights U/S		29/05/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Elect\TRL LIGHTS	Right hand Top indicater U/S		29/05/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Elect\TRL LIGHTS	R.H. clearance light broken (sidewall)		29/05/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres	LR inner tyre has flat		29/05/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\LIGHTS	L front clearance light		29/05/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\MUDGUARDS	LHF guard bracket cracked		29/05/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\MUDGUARDS	RHF guard bracket cracked		29/05/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		29/05/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		29/05/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Albury - Workshop	Brakes\L.H.M	Reline Due on left Hand Middle		10/04/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Albury Workshop	TRAILER
T564	Albury - Workshop	Chassis\SKID PLATE	Skid Plate still cracked, U/S		10/04/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Albury Workshop	TRAILER
T564	Albury - Workshop	DrivLine\WHEEL BRGS	Adjusted all bearings		10/04/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Albury Workshop	TRAILER
T564	Albury - Workshop	Chassis\CHAS CRACK	Cracks in Mezz Deck uprights.		10/04/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Albury Workshop	TRAILER
T564	Albury - Workshop	Body\TRL REPS	Rips, Holes and rollers needed. 2 x clearance lights U/S		10/04/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Albury Workshop	TRAILER
T564	Albury - Workshop	Elect\TRL LIGHTS	Right hand Top indicater U/S		10/04/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Albury Workshop	TRAILER
T564	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist		10/04/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Albury Workshop	TRAILER
T564	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		10/04/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Albury Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\TP9+10	Supply and fit 2 tyres		17/03/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes\BRK RELINE	need reline soon		10/03/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Elect\TRL LIGHTS	R.H. clearance light broken (sidewall)		10/03/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres	LR inner tyre has flat		10/03/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		10/03/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		10/03/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Workshop\CLEAN	clean up from work/paperwork		03/03/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Workshop\MOVE ASSET	move trailers onto tyre pad		03/03/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Albury - Workshop	Tyres\TP11+12	Supply and Fit 2 tryes		03/03/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Albury Workshop	TRAILER

T564	Wodonga - Workshop	Body\TRL REPS	repairs to uprights and curtains		10/02/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Workshop\MOVE ASSET	unload for repairs		10/02/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Workshop\MOVE ASSET	reload trailer		10/02/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Elect\INDICATORS	RH indicator n/w		26/01/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	Carry Out D Service	26/01/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job	carry out D Service	26/01/2021	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\TP5+6	replace 2 tyres		23/12/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\TP3+4	replace 2 tyres		23/12/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\TP1+2	replace 2 tyres		23/12/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\HOUSEKEEP	check over	completed	23/12/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\AIR BAG	Job Added From Invoice		04/12/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Workshop\MOVE ASSET	move trailer		02/12/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Elect\BRK RELINE	LH low		02/12/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\AIR BAG	RHM 30K	replace RHM 30K airbag - includes smoko	02/12/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		02/12/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		02/12/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Workshop\W/S MAINT	weld posts for Ricey for parking spots and swap gas bottle		05/11/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\AIR BAG	R.R airbag start pealing from bottom		05/11/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\WHEEL BRGS	R.F,M and L.R axle bearing adjusted		05/11/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\LIGHTS	L front clearance light		05/11/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
				move trailers								
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	adjusted bearing	05/11/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		05/11/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\SUSPENSION	LHM trailer arm strap broken		04/10/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\MUDGUARDS	LHF guard bracket cracked		04/10/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\MUDGUARDS	RHF guard bracket cracked		04/10/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\WHEEL BRGS	adjusted all 6x wheel sets		04/10/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		04/10/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		04/10/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp	Check for air leaks around air bags	located and repaired leak	30/09/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Workshop\MOVE ASSET	move trailers		23/09/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\SKID PLATE	skid plate cracked	wodonga engneering welding crack Poww058224	23/09/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		23/09/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		23/09/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\MUDGUARDS	Job Added From Invoice		15/09/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	one small holes LHS curtain		05/09/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	numerous damaged buckles	to be done when it comes back for skid plate repairs	05/09/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	re-list given to Greg at workshop		05/09/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	DrivLine\WHEEL BRGS	Adjusted RHF RHM LHR	ok	05/09/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\WHEEL BRGS	grese burnt monitor		05/09/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres	RHM inner needs replacing	previously done	05/09/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\SUSPENSION	PO FOR U BOLTS-AWAITING JOB CARD		05/09/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\MUDGUARDS	RHF mudflap needs replacement	previously done	05/09/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	done	05/09/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
			mez deck doesn't move									
			air leak at rear of trailer	previously done								
T564	Wodonga - Workshop	Body\TRL FLOOR	buckles L/H/R need replacing	deck loaded	05/09/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job	ok	05/09/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\DAMAGE	body cracks	done	05/09/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\SUSPENSION	needs bush's replaced	done	05/09/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
			box corners, cracking									
T564	Wodonga - Workshop	Chassis\CHAS CRACK	major crack RH side next to doubler of bottom deck	as per job#304183	05/09/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	small holes old rips and tears	temp repairs, done to rips at lower decks	05/09/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	holes	needs to be sent for proper repairs as old patching looks horrible!	05/09/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\CHAS CRACK	multiple cracks on this trailer	still pending to be done when skid plate is replaced	05/09/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\FIFTH WHEE	skid plate worn needs replacing	still pending	05/09/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\SHOCK ABS	bushes worn	still pending	05/09/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice		05/09/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice		05/09/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	DrivLine\WHL HUB	Job Added From Invoice		28/08/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp	Job Added From Invoice		28/08/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	DrivLine\WHEEL BRGS	Adjusted RHF RHM LHR		28/08/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\WHEEL BRGS	grese burnt monitor		28/08/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres	RHM inner needs replacing		28/08/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\SUSPENSION	PO FOR U BOLTS-AWAITING JOB CARD		28/08/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		28/08/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Elect\TRL LIGHTS	no lights		28/08/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\AIR LEAK	drops all air in trailers	LHR brake hoses worn	28/08/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\FIFTH WHEE	turn table getting hard to operate when splitting. Gets very hard to pull handle like its jammed		28/08/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\ELECT P&W	no lights	completed	28/08/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\ELECT P&W	connections on trailer cor light is broken	completed	28/08/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	numerous damaged buckles		28/08/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		28/08/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice		27/08/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice		27/08/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Workshop\CLEAN	CLEAN MESS LEFT IN PIT FROM REPAIRS DONE ON PIT		27/08/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\HOUSEKEEP	check over trailers	ATT for u bolts Poww057434- FOUND LHM TRAILING ARM U BOLTS HAD SNAPPED. ALSO FOUND LHR BRAKE HOSES WORN AND LEA	27/08/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	brake test results attached		26/08/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist		26/08/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Workshop\MOVE ASSET	opperate fork and move trailers		04/07/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\MUDGUARDS	replace rear r/h mud flap and reallign guard mount		04/07/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\DAMAGE	body cracks		04/07/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		04/07/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		04/07/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		13/06/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\AIR LEAK	drops all air in trailers		13/06/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\FIFTH WHEE	turn table getting hard to operate when splitting. Gets very hard to pull handle like its jammed		13/06/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\ELECT P&W	no lights		13/06/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\ELECT P&W	connections on trailer cor light is broken		13/06/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	numerous damaged buckles		13/06/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	re-list given to Greg at workshop		13/06/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\MUDGUARDS	RHF mudflap needs replacement		13/06/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
			mez deck doesn't move									
			air leak at rear of trailer									
T564	Wodonga - Workshop	Body\TRL FLOOR	buckles L/H/R need replacing		13/06/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		13/06/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Workshop\MOVE ASSET	moved trailers for next service		09/06/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Workshop\CLEAN	clean top shed floor		02/06/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Workshop\MOVE ASSET	move trailers		02/06/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	PO FOR PARTS AWAITING WORK CARD		02/06/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
				Arkon to supply electrical parts P/O WW054958								
				Rapid to supply air fittings P/O WW054959								
				Finished replacing motor & controls, cleaned up tools and swept out trailer								
T564	Wodonga - Workshop	Body\TRL FLOOR	replace Mezz deck motor	Repaired mex deck lock holes	30/05/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL FLOOR	PO FOR PARTS FOR MEZZ DECK		28/05/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Elect\HOUSEKEEP	started fabricating mount for control box for mez deck		22/05/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\CHAS CRACK	weld cracks at right hand goose neck		22/05/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Workshop\MOVE ASSET	take 564 out and park up		22/05/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL FLOOR	pock up floor (mezz) tools and testing gear, strap down close curtains		22/05/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\WHEEL BRGS	adjust all hub bearings including 2x thrust		22/05/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL FLOOR	mezzanine floor repairs (floor not active)		22/05/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER

T564	Wodonga - Workshop	Elect\BATTERY	change battery no success		22/05/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\SUSPENSION	needs bush's replaced box corners, cracking		22/05/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\CHAS CRACK	major crack RH side next to doubler of bottom deck		22/05/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	small holes old rips and tears		22/05/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		22/05/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\MUDGUARDS	RHF mudflap needs replacement mez deck doesn't move air leak at rear of trailer	need to order correct size	22/05/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL FLOOR	buckles L/H/R need replacing		22/05/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	holes	curtains need send for proper repairs	22/05/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\REFLECTORS	LH	replaced	22/05/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\SHOCK ABS	LHM shock loose	done	22/05/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\MUDGUARDS	front guard	good	22/05/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\WHEEL SEAL	6x hub seals leaking	none leaking	22/05/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\KING PIN	plate worn out	ok	22/05/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\CHAS CRACK	cracks in gussets	ok	22/05/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\CHAS CRACK	multiple cracks on this trailer		22/05/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\FIFTH WHEE	skid plate worn needs replacing		22/05/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\SHOCK ABS	bushes worn		22/05/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		22/05/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\SHOCK ABS	shocky straps fraying	still ok	22/05/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice		02/05/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice		02/05/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\CASE STOCK	Job Added From Invoice		02/05/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		25/04/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		25/04/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\WHEEL BRGS	replace thrust washers	adjust all all 6 & repack outer bearings	24/04/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\HOUSEKEEP	grease		24/04/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\SUSPENSION	tighten U bolts		24/04/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Workshop\MOVE ASSET	reload & pack up	shut shed	04/04/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	repairs to uprights		04/04/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Workshop\MOVE ASSET	unload & move trailers for repairs to uprights		04/04/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Workshop\CLEAN	clean up work shop		04/04/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\MUDGUARDS	RHF mudflap needs replacement		04/04/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL FLOOR	Mez floor not working mez deck doesn't move air leak at rear of trailer		04/04/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL FLOOR	buckles L/H/R need replacing		04/04/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\AIR BAG	LHM leaking - others perished		04/04/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	holes		04/04/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Elect\TRL LIGHTS	all light is working except two indicators and wires problem		04/04/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	DrivLine\WHEEL BRGS	check and adjusted rear axle, middle axle and RHF		04/04/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\MUDGUARDS	R/F mudguard cracked needs welding		04/04/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\MUDGUARDS	front guard		04/04/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\AIR BAG	LHR airbag starting perish LHM leaking	checked bags -ok for now	04/04/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\SHOCK ABS	LHM shock loose		04/04/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\REFLECTORS	LH		04/04/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\AIR FITTIN	replaced air fitting on RHS		04/04/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL FLOOR	after hours breakdown: attempted to lift floor (mezdeck) checked batter, wiring and fuses, found locks had no air supply. Dele		04/04/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	As per #278031	22/03/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		22/03/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\MUDGUARDS	RHF mudflap needs replacement		22/03/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\WHEEL SEAL	6x hub seals leaking		22/03/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		22/03/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL FLOOR	mez deck motor not working		11/03/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL FLOOR	Trailer Floor Repairs		11/03/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Elect\BATTERY	Replaced Battery		11/03/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D service		26/02/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	DrivLine\WHEEL BRGS	bearings (pull apart & repack change seals clean & inspect)		26/02/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\FIFTH WHEE	skid plate inspections by andrew & paul		26/02/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	brake test results attached		26/02/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Workshop\W/S MAINT	clean up grease guns ,parts & needles & bends		22/02/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	DrivLine\WHEEL SEAL	WHEEL SEAL WEEPING		21/02/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Workshop\CLEAN	clean up from job		20/02/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Workshop\MOVE ASSET	hook up set & move remove wash/inspect & repack RHM & bolts		20/02/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	DrivLine\WHL HUB	front inner & outer bearings	reassemble the hubs & bearings & adjust	20/02/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Elect\BATTERY	Job Added From Invoice		06/02/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice		24/01/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice		24/01/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\HOUSEKEEP	climb under and zip tie all loose hanging wires and hoses		19/01/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\AIR BAG	replace 3x airbags		19/01/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\ELECT P&W	rewire light		19/01/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\CHAS CRACK	make new light and reflector brackets		19/01/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\CHAS CRACK	straighten under side of side rail and weld new light & reflector brackets		19/01/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\MUDGUARDS	replace guard		18/01/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Workshop\CLEAN	clean up		18/01/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\AIR BAG	replace airbag x3		18/01/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\ELECT P&W	make new light brackets and repairs to lights		18/01/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		18/01/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job mez deck doesn't move air leak at rear of trailer	LHM/LHR/RHF Airbags 30k inspect for air leaks Moved assets Cleaned up Hard to build air	18/01/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL FLOOR	buckles L/H/R need replacing	Deck was loaded - could not inspect	18/01/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\AIR BAG	LHM leaking - others perished		12/01/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL FLOOR	loaded, underside ok		12/01/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\KING PIN	plate worn out		12/01/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\KING PIN	replaced kingpin		12/01/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Steering\WHEEL BRGS	tighten all wheel bearings		12/01/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\AIR LEAK	boost lines loose		12/01/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	holes		12/01/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		12/01/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		12/01/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\REFLECTORS	LH		12/01/2020	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
				Moved trailers into shed. Only temp fix done - no red curtain - too hard to stick to painted side.								
T564	Wodonga - Workshop	Body\TRL REPS	replace buckle and curtain repairs to be done	Curtains need to be sent for repairs	08/12/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Elect\INDICATORS	Replaced 2x indicator & fixed the wiring issue		18/11/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	Check curtain straps - All ok		18/11/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Elect\TRL LIGHTS	all light is working except two indicators and wires problem		09/11/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\AIR FITTIN	replaced air fitting on RHS		09/11/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\AIR BAG	LHR airbag starting perish LHM leaking		09/11/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\SHOCK ABS	LHM shock loose		09/11/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\CHAS CRACK	cracks in gussets		09/11/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	DrivLine\WHEEL BRGS	check and adjusted rear axle, middle axle and RHF		09/11/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\CHAS CRACK	multiple cracks on this trailer		09/11/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\MUDGUARDS	R/F mudguard cracked needs welding		09/11/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	Carried out D Service	09/11/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER

T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		09/11/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		28/09/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\CHAS CRACK	weldcracks @ goose neck and uprights		28/09/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		28/09/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Elect	Job Added From Invoice		25/09/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Elect\TRL LIGHTS	clearance light		10/09/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\CHAS CRACK	weld various cracks(frontwall, goose necks , uprights of mez deck)		10/09/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\AIR BAG	air leak from L/H/R airbag		10/09/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\AIR BAG	left hand middle and right hand rear perished and leek , 30 k		10/09/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\MUDGUARDS	front guard cracked		10/09/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\AIR BAG	2 or 3 airbags leaking 30K		10/09/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\MUDGUARDS	front guard		10/09/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\SHOCK ABS	shock straps worn		10/09/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\SUSPENSION	spring eye bushes worn		10/09/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\FIFTH WHEE	skid plate worn needs replacing		10/09/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes\AIR LEAK	middle and rear		10/09/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	rips and holes in curtain		10/09/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\SHOCK ABS	shocky straps fraying		10/09/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	holes in curtain only small ones		10/09/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\SUSPENSION	bushes worn		10/09/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	small corners rips and buckles and straps		10/09/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\WHEEL ALGN	wheel alignment		10/09/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\AIR LEAK	tank connector leaking back		10/09/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes\AIR LEAK	leaking airlines		10/09/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\FIFTH WHEE	needs replacing		10/09/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\SHOCK ABS	bushes worn		10/09/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\AIR BAG	left hand middle and right hand rear perished and leek , 30 k		03/09/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\MUDGUARDS	front guard cracked		03/09/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	as per checklist		31/08/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Brake test results attached		31/08/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\AIR BAG	air leak from L/H/R airbag		31/08/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\MUDGUARDS	front guard		31/08/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\MUDGUARDS	front guard		31/08/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\MUDGUARDS	front guard cracked		31/08/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\AIR BAG	2 or 3 airbags leaking 30K		31/08/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	replaced 4 curtain buckles and straps		21/08/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\AIR LEAK	tank connector leaking back		03/08/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes\AIR LEAK	leaking airlines		03/08/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\FIFTH WHEE	needs replacing		03/08/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\SHOCK ABS	bushes worn		03/08/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\MUDGUARDS	front guard		03/08/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	completed	03/08/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	DrivLine\WHEEL BRGS	adjust wheel bearings		03/08/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\AIR BAG	2 or 3 airbags leaking 30K		03/08/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\SHOCK ABS	shock straps worn		03/08/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\SUSPENSION	spring eye bushes worn		03/08/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\FIFTH WHEE	skid plate worn needs replacing		03/08/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\MUDGUARDS	front guard		03/08/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes\AIR LEAK	middle and rear		03/08/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	rips and holes in curtain		03/08/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\MUDGUARDS	front guard cracked		03/08/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	completed	03/08/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\SHOCK ABS	shocky straps fraying	job still pending	03/08/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\SHOCK ABS	loose shockys	job previously completed	03/08/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	DrivLine\WHEEL BRGS	bearing adjustments	completed	03/08/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	holes in curtain only small ones	job still pending	03/08/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\DAMAGE	RHF duels u/s	job previously completed	03/08/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\SUSPENSION	bushes worn	job still pending	03/08/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	small corners rips and buckles and straps	job still pending	03/08/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\WHEEL ALGN	wheel alignment	job still pending	03/08/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		03/08/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
				Repaired runner & lead, tested.								
				Strapped deck								
T564	Wodonga - Workshop	Elect\ELECT P&W	electrical guide come apart from deck	Took Graham to TCTC to pick up truck for this set	20/07/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes\AIR LEAK	air coupling leak	Previously done	20/07/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\TP15	R/H/F inner tyre bald	Previously done	20/07/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice		14/07/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice		14/07/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\AIR LEAK	Air leak repairs		13/07/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes\AIR LEAK	air coupling leak		29/06/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\TP15	R/H/F inner tyre bald		29/06/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		29/06/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		29/06/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice		26/06/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice		26/06/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	Replaced R/H lead roller		16/06/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\SHOCK ABS	shocky straps fraying		22/05/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\SHOCK ABS	loose shockys		22/05/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	DrivLine\WHEEL BRGS	bearing adjustments		22/05/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	holes in curtain only small ones		22/05/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\DAMAGE	RHF duels u/s		22/05/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		22/05/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		22/05/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Albury - Workshop	DrCabElect\INDICATORS	L/H indicator not working wiring and bracket hanging in floor channel	replaced L/rear indicator	18/05/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Albury Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\RETREAD	Job Added From Invoice		14/04/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice		14/04/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\CASE STOCK	Job Added From Invoice		14/04/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\MUDGUARDS	replace both front mudflaps and anti sway/move out of shed and get service		31/03/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	repair curtain pole		31/03/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Workshop\CLEAN	operate deck all way up and down clean up		31/03/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\SHOCK ABS	tighten loose shocks		31/03/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Elect\ELECT P&W	repair wiring above r/rear airbag		31/03/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\DAMAGE	repair right front upright		31/03/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\SHOCK ABS	LHM & LHF shocks loose		31/03/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\SUSPENSION	bushes worn		31/03/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\CROSS MBR	cracks in box corners, doublers and upright post's		31/03/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	small corners rips and buckles and straps		31/03/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		31/03/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		31/03/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body	Job Added From Invoice		15/03/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	replace R/H curtain ratchet	fit new curtain ratchet r/front	13/03/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body	Job Added From Invoice		30/01/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		25/01/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		25/01/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\DAMAGE	Job Added From Invoice		20/01/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice		18/01/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice		18/01/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\WHEEL ALGN	wheel alignment		16/01/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Workshop\CLEAN	cleaning		16/01/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\SUSPENSION	jack and check bushes make parts list 05.34.830.360 spring rapper part number		16/01/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	fit R.H.S between front uprights and secure upright's also various cracks		16/01/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER

T564	Wodonga - Workshop	Body\REFLECTORS	replace rear marker signs		16/01/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL WALL	R/H/S cracked at back wall		16/01/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	R/H curtain roller 1/2 way along trailer		16/01/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL FLOOR	cracks in floor	rewired control box for mez deck	16/01/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	mez deck upright cracked	also fit doubler's	16/01/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
				replaced 11 buckles, 8 curtain straps and 3 hook straps								
T564	Wodonga - Workshop	Body\TRL REPS	buckles and straps rips and holes	replaced more buckles and straps cleaned out deck straped deck down	16/01/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Elect\TRL LIGHTS	clearance light out		16/01/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\DRV TYRES	RHM duels u/s	previously done on the 12/1/19	16/01/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\FIFTH WHEE	plate a/s 6 to 7mm gap with straight edge	inspected ok	16/01/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\SCRAP TYRE	Job Added From Invoice		10/01/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\AH Callout	Job Added From Invoice		10/01/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice		10/01/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice		10/01/2019	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	Service		29/12/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		29/12/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL FLOOR	cracks in floor		29/12/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	mez deck upright cracked		29/12/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	buckles and straps rips and holes		29/12/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Elect\TRL LIGHTS	clearance light out		29/12/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\DRV TYRES	RHM duels u/s		29/12/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Workshop\MOVE ASSET	move trailers		29/12/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\BREAKDOWN	Airbag		08/12/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	service and inspect mez deck		22/11/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		22/11/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	Trailer (Tautliner) Repairs	replace straps and buckles as per RNR	14/11/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	LH side curtain buckk in front of tri needs replacing		10/11/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	DrivLine\WHL HUB	Job Added From Invoice		06/10/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL LEGS	prep and paint new landing leg for tailer and clean spray gun		05/10/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\MUDGUARDS	replace u/s guards		03/10/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		03/10/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\HOUSEKEEP	no bolts bottom of uprights / roof support	completed previously	03/10/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		03/10/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\RETREAD	Job Added From Invoice		20/09/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice		20/09/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	DrivLine\WHEEL BRGS	Remove check and repack wheel bearings		12/08/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		12/08/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job	completed during service	12/08/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\AXLES	found broken U bolt during service		12/07/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\AIR LEAK	air leak - airbag	as per job#178336	12/07/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Elect\ELECT P&W	plug for control box		12/07/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\HOUSEKEEP	no bolts bottom of uprights / roof support		12/07/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\FIFTH WHEE	plate a/s 6 to 7mm gap with straight edge		12/07/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
				replaced L/front and r/rear airbags								
T564	Wodonga - Workshop	Susp\AIR LEAK	LHF airbag u/s	replaced broken u-bolt l/centre	12/07/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	DrivLine\TANK MANI	hubs and bearings need full inspection u/s	previously done	12/07/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	holes in curtains u/s		12/07/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\DRV TYRES	RHM inner tyre u/s	previously done	12/07/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\AIR LEAK	inspect + repair air leak		12/07/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	holes and tears u/s		12/07/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		12/07/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		12/07/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	Service		27/05/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		27/05/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\DAMAGE	inspected started repairs on skid plate		27/05/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	DrivLine\WHEEL BRGS	bearing adjustments		27/05/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Workshop\MOVE ASSET	pick up from HTT		25/04/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Workshop\MOVE ASSET	deliver to HTT		25/04/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice		25/04/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice		25/04/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Workshop\CLEAN	Manpower & chase parts for trailer		14/04/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	to be completed with repairs in repair bay	13/04/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Workshop\CLEAN	cleaning		13/04/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Elect\ELECT P&W	lights		13/04/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\DAMAGE	mezz deck repairs		13/04/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Workshop\CLEAN	clean area around rear of trailer and pre to strip hubs and bearings		13/04/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	weld doublers to uprights and weld deck lock plated in position		13/04/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	weld and grind mezz uprights		13/04/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	mez repairs		13/04/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
			R/H rear lock									
T564	Wodonga - Workshop	Body\AIR FITTIN	all locks don't spring out how they should - blocked air line		13/04/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\HOUSEKEEP	no bolts bottom of uprights / roof support		13/04/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\HOUSEKEEP	LH lock stopper plate missing - rear	all lock holes need repairs	13/04/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\FIFTH WHEE	plate a/s 6 to 7mm gap with straight edge		13/04/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\AIR LEAK	LHF airbag u/s		13/04/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\SHOCK ABS	LHM shocky u/s	as per job no. 163692	13/04/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
				#163698 hubs and bearings full inspection								
				-all bearing replace, and inspection of all major components								
T564	Wodonga - Workshop	DrivLine\TANK MANI	hubs and bearings need full inspection u/s	bearing replacement #163698	13/04/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\CROSS MBR	gusset cracks u/s		13/04/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	holes in curtains u/s		13/04/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Elect\BATTERY	mez deck battery u/s		13/04/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\DRV TYRES	RHM inner tyre u/s		13/04/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\AIR LEAK	inspect + repair air leak		13/04/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\SHOCK ABS	loose shocky LHM	checks ok not leaking	13/04/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\CHAS CRACK	cracks in drop deck		13/04/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	holes and tears u/s		13/04/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		13/04/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL FLOOR	repair lock missing pin	not complete	10/03/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\AIR LEAK	LHF airbag u/s		07/03/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\SHOCK ABS	LHM shocky u/s		07/03/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\FIFTH WHEE	plate a/s 6 to 7mm gap with straight edge		07/03/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	DrivLine\TANK MANI	hubs and bearings need full inspection u/s		07/03/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\CROSS MBR	gusset cracks u/s		07/03/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	holes in curtains u/s		07/03/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Elect\BATTERY	mez deck battery u/s		07/03/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\DRV TYRES	RHM inner tyre u/s		07/03/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		07/03/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\AIR LEAK	inspect + repair air leak		07/03/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
			R/H rear lock									
T564	Wodonga - Workshop	Body\AIR FITTIN	all locks don't spring out how they should - blocked air line		07/03/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\HOUSEKEEP	no bolts bottom of uprights / roof support		07/03/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\HOUSEKEEP	LH lock stopper plate missing - rear		07/03/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\SHOCK ABS	loose shocky LHM		07/03/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		07/03/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\PRES CHECK	Job Added From Invoice		05/03/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\BREAKDOWN	Breakdown		30/01/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Workshop\CLEAN	cleaning		26/01/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Elect\ELECT P&W	electric repairs		26/01/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\SHOCK ABS	loose shocky LHM		26/01/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\CHAS CRACK	cracks in drop deck		26/01/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER

T564	Wodonga - Workshop	Body\TRL REPS	holes and tears u/s		26/01/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\REFLECTORS	side markers and lights u/s		26/01/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		26/01/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
				loaded unsafe to work on refer to supervisor								
T564	Wodonga - Workshop	Body\AIR FITTIN	air locks not working on rear of floor	unloaded trailer for repairs. Replaced L./R lock cylinder tested ok	26/01/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\HOUSEKEEP	no bolts bottom of uprights / roof support	needs further inspection when unloaded and safe to work on	26/01/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
				all over extention plates broken and or missing refer to supervisor loaded unsafe to work on								
T564	Wodonga - Workshop	Body\HOUSEKEEP	LH lock stopper plate missing - rear	to be repaired on 30/1/18	26/01/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\AIR FITTIN	Rear lock busted	LHR lock not operating informed supervisor for further repairs loaded unsafe to work on	26/01/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		26/01/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\RETREAD	Job Added From Invoice		16/01/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice		16/01/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres	Job Added From Invoice		16/01/2018	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	DrivLine\WHEEL BRGS	RH- M&F , LH - F adjusted	Check all other R & R's to be done.	31/12/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\LIGHTS	Return clearnce light u/s	Replace & rewire RH-M clearnce light	31/12/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		31/12/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\AIR LEAK	air leaking near tri	loose booster hose line	31/12/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\HOUSEKEEP	no bolts bottom of uprights / roof support	Trailer was loaded & tagged 30th/12/17	31/12/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\SHOCK ABS	LHM shock loose u/s	Previously done	31/12/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		31/12/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
				locks repairs completed								
T564	Wodonga - Workshop	Body\TRL FLOOR	repair mez locks	deck post's to be welded properly at 3rd top hole at later date	23/12/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Elect\BREAKDOWN	repair wiring on mez floor		08/12/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\PRES CHECK	Job Added From Invoice		27/10/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\SHOCK ABS	LHM shock loose u/s		25/10/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist		25/10/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		25/10/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		25/10/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\MOUNTS	replace and fabricate new lock stops for deck		07/09/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Elect\ELECT P&W	rewire lights to new mounts and add new reflectors		07/09/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\MOUNTS	move side clearance light brackets and weld cracked coming rail and weld new binder bars in. fit new angle to coming rail		07/09/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	fixed curtains ratchets		07/09/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Insp\RWC COMP	rego label	9/11/17 is expiry date	07/09/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\AIR LEAK	air leaks		07/09/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	locks and locating holes need repair	changed air - ram left rear, lock stops need attention	07/09/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
				lock stopers need attention								
				fitted lock doublers								
T564	Wodonga - Workshop	Body\DAMAGE	deck locks will need attention soon & adjust chains. deck locks will need attention soon	adjust running chains	07/09/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\AIR LEAK	bad air leak		07/09/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\WINCH/STRP	L/H curtain winch pin coming out		07/09/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes\BOOSTER	booster line leaking		27/08/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Elect\ELECT P&W	Fix LH side clearance light		27/08/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		27/08/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\WINCH/STRP	L/H curtain winch pin coming out		27/08/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		27/08/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice		24/08/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice		24/08/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice		03/08/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice		03/08/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\PRES CHECK	Job Added From Invoice		29/07/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice		21/07/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\ROTATION	Job Added From Invoice		21/07/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice		21/07/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\WINCH/STRP	L/H curtain winch pin coming out		15/07/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\AIR BAG	LH-rear & both middle bags	inspect - replaced x airbags	15/07/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL FLOOR	replaced RHR deck lock closed up		12/07/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Elect\ELECT P&W	rewire deck controller please		12/07/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\DAMAGE	L/H front upright cracked at 3rd hole	also numerous cracks all over locks	12/07/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\AIR LEAK	Air Leak/s		04/07/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\AIR BAG	LH-rear & both middle bags		01/07/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		01/07/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\SHOCK ABS	loose shocky		01/07/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		01/07/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\SHOCK ABS	loose shocky		17/05/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		17/05/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Elect\ELECT P&W	wires hanging from L/H rear axle	previously done	17/05/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
			R/H rear lock needs fixing									
T564	Wodonga - Workshop	Body\AIR LEAK	air leaks	previously done	17/05/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		17/05/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres	Job Added From Invoice		11/05/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	replaced leaking airbag r/front	19/04/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		19/04/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\BREAKDOWN	air bags not raising		30/03/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\AIR BAG	RHF air bag u/s 30k	inspected	29/03/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL FLOOR	mez deck locks u/s	trailer is loaded	29/03/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\TP21	Job Added From Invoice		23/03/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\TP11	Job Added From Invoice		17/03/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		15/03/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		15/03/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\TP15	Job Added From Invoice		07/02/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\TP13	Job Added From Invoice		07/02/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\TP11	Job Added From Invoice		07/02/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Workshop\MOVE ASSET	moved trailers clean up looked for service		28/01/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\MUDGUARDS	replace both rear mudflaps		28/01/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		14/01/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job	Replaced broken/worn ubolts lcentre	14/01/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	1 X load strap		14/01/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL GATES	RH rear lock needs attention	Fix mez floor lock	05/01/2017	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Elect\TRL LIGHTS	Job Added From Invoice		23/12/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\LIGHTS	Job Added From Invoice		23/12/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\AIR BAG	Job Added From Invoice		16/12/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\AIR BAG	R/H/F airbags		15/12/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\SUSPENSION	rebush hangers	HTT repaired	14/12/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		13/12/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		13/12/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL FLOOR	mez deck locks u/s		13/12/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
				move trailers								
				replaced clearance light								
				replaced indicator								
				repaired RHF curtain								
T564	Wodonga - Workshop	Body\TRL REPS	repair rips in curtain	repaired LH curtain	13/12/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		13/12/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		13/12/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\AIR BAG	RHF air bag u/s 30k		13/12/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	curtain repairs		07/12/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\AIR LEAK	plus RHF airbag leaking BPW 30		07/12/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp	inspected bushes found to be worn		07/12/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\TP11	Job Added From Invoice		28/11/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body	Job Added From Invoice		08/11/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body	Repair left hand curtain please	Repaired curtain as best I could. Trailer had been loaded in was unable to get inside to patch properly	05/11/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		30/10/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER

T564	Wodonga - Workshop	Insp\ANN INSP	perform annual inspection	completed during service	30/10/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body	R/H rear lock needs fixing	could not fault	30/10/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body	fix tears in curtain on drop join on curtain please		30/10/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		30/10/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		21/09/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL FLOOR	R/H rear lock needs fixing		21/09/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body	fix tears in curtain on drop join on curtain please		21/09/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		21/09/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Elect\HEAD LIGHT	Job Added From Invoice		24/08/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL FLOOR	Left hand upright busted 3rd hole		07/08/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\TP11	Job Added From Invoice		06/08/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body	back passenger pole on B		30/07/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\DAMAGE	repair damage to L/R of trailer		30/07/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		30/07/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		30/07/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body	repair looking holes on mezz decks and unload/reload		16/07/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\TP11	Job Added From Invoice		14/07/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body	front L/H side lock needs replacing, check other locks		07/07/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body	L/H front lock pin to be replaced		07/07/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL FLOOR	weld plates on 3rd from the top lock holes	complete	07/07/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL FLOOR	needs new mez lock	front left lock and front right lock replaced	07/07/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\FIFTH WHEE	cracks under plate		07/07/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	Job Added From Invoice		05/07/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService	service		26/06/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	please replace broken buckles drivers side		26/06/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		26/06/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService	service		26/06/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		26/06/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL FLOOR	weld plates on 3rd from the top lock holes		07/06/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\TP11	Job Added From Invoice		20/05/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist		18/05/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		18/05/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		18/05/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\TP11	Job Added From Invoice		19/04/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\TP11	Job Added From Invoice		19/04/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\HCV	repaired ride height		16/04/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL FLOOR	needs new mez lock		15/04/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\FIFTH WHEE	cracks under plate		15/04/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\CHAS CRACK	skid plate cracks		15/04/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes\ABS	ABS not working	inspected everything looks ok issue possibly in truck	15/04/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes\BRAKE ADJ	tri locking up	checked - no problem found	15/04/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Steering\WHEEL HUB	RHF sounds dry needs to be looked at u/s	checked - all ok	15/04/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		15/04/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		15/04/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\TP15	Job Added From Invoice		22/03/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\SUSPENSION	LHM ubolt broken u/s		22/03/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Steering\WHEEL HUB	RHF sounds dry needs to be looked at u/s		22/03/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\CHAS CRACK	cracks on floor u/s front RH corner u/s	weld cracks	22/03/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes\AIR LEAK	front tank release valve leaking	replaced release valve	22/03/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes\ABS	ABS not working		22/03/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes\BRAKE ADJ	tri locking up		22/03/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\AIR LEAK	air leak at tri axle	replaced drain plug	22/03/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes\AIR LEAK	Find and repair air leak behind rear tri	replaced drain plug	22/03/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\MUDGUARDS	Replace front P/S mudguard	both quarter guards are fine	22/03/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL FLOOR	inspect and repair mez deck	inspected mez deck, couldn't find any faults	22/03/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\SUSPENSION	LHM ubolt broken u/s		17/03/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Steering\WHEEL HUB	RHF sounds dry needs to be looked at u/s		17/03/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\CHAS CRACK	cracks on floor u/s front RH corner u/s		17/03/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes\AIR LEAK	front tank release valve leaking		17/03/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		17/03/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes\ABS	ABS not working		17/03/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes\BRAKE ADJ	tri locking up		17/03/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\AIR LEAK	air leak at tri axle		17/03/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes\AIR LEAK	Find and repair air leak behind rear tri		17/03/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\MUDGUARDS	Replace front P/S mudguard		17/03/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		17/03/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes\ABS	ABS not working		05/03/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes\BRAKE ADJ	tri locking up		05/03/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis\AIR LEAK	air leak at tri axle removed RHR & LHR mezdeck locks welded mezdeck locks		05/03/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body	refitted RhR & LHR mezdeck locks		25/02/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Susp\AIR BAG	DS/Rear air bag		24/02/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body	remove broken doubler'sand replace on goose neck (rear)		24/02/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		19/02/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		19/02/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\TP11	Job Added From Invoice		06/02/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\TP19	Job Added From Invoice		06/02/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\TP19	Job Added From Invoice		06/02/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\TP13	Job Added From Invoice		06/02/2016	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	check chains - found chain link on the floor	job complete	31/12/2015	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\TRL REPS	LH rear upright needs repair	job complete	31/12/2015	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\TP22	Job Added From Invoice		12/12/2015	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Body\AIR LEAK	air leak around rear tri	job complete	09/12/2015	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Tyres\TP15	Job Added From Invoice		02/12/2015	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis	Repair cross beam near legs.	under warranty	17/11/2015	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis	Repair cracks forming on RHS chassis infront of front axel.	job complete	17/11/2015	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Chassis	Remove skid plate and repair cracks above	under warranty	17/11/2015	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Brakes	check and record brakes	all ok Replaced elec base, reflectors and load binder straps.	06/11/2015	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER
T564	Wodonga - Workshop	Insp\ANN INSP	Carry out internal roadworthy	Other jobs found have been put onto new job	06/11/2015	Completed	Tliner	Wodonga	HCU	YV97EU	Wodonga Workshop	TRAILER