EquipmentName	Workshop	CodeAndSubCode	Description	Schedule	CompletionComments	DateDone	DistanceDone	Worktype	Workstate	EquipmentOwner	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
T570	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		25/06/2026	876993	Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL FLOOR	Move Mezz Decks		Moved mezzanine floor	25/06/2026	876993	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		12/05/2026	876993	Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL FLOOR	Move mezzanine floor		Completed wired in external plug as to move deck	02/05/2026	876993	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		30/04/2026	876993	Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL FLOOR	Move Mezz Deck down 2 hole's, as per Operation's Instruction's.			19/03/2026	876993	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		04/03/2026	876993	Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Steering\WHEEL ALGN	Wheel alignment needed trailer tracking left.		Pending	04/03/2026	876993	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Susp\HCV	Susp\HCV		Pending	04/03/2026	876993	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		04/02/2026	876993	Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\TP11+12	Tyres\TP11+12 (31-32)			03/02/2026	876993	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	BORDER BANDAG PTY LTD	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	1.TORN CURTAIN (PO #WW095331)		DPB booked for 2/7 @4.30pm	27/01/2026	876993	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	DPG REPAIRS- BREAKDOWN. REPAIR RIP IN CURTAIN.			27/01/2026	876993	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	DPB REPAIRS	TRAILER
T570	Wodonga - Workshop	Tyres\RUN OUT	Tyres\RUN OUT pos 27		TYRE HAD SIDE WALL PUNCTURE - BIG NAIL	03/12/2025	876993	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	BORDER BANDAG PTY LTD	TRAILER
					FLEET #7570											
					DIAGNOSE AIR LEAK AT FRONT OF TRAILER											
					MEZ DECK LOCK PIN AIR SUPPLY LINE WORN											
					CUT OUT DAMAGED LINE & FIT JOINER											
					REFIT & CHECK FOR LEAKS											
					SUPPLY CURTAIN RATCHET STRAPS											
					PARTS:											
					1X 8MM JOINER											
					10X CURTAIN RATCHET STRAPS											
T570	Wodonga - Workshop	Body\AIR LEAK	Body\AIR LEAK		WORKSHOP MATERIALS/ EPA	03/11/2025	876993	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	G & S DIESEL SERVICE	TRAILER
					T569 mez deck floor raised as required, missing control box, battery is dead flat											
T570	Wodonga - Workshop	Elect\INDICATORS	->RIGHT SIDE TAIL BLINKER NOT WORKING.		-lights checked and resaired as resuired	17/10/2025	876993	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshoo	TRAILER
					-T569 trailer mez deck floor control box and battery missing,											
					-several cracks in uprights, not safe to raise floor											
					-will need to be inspected											
					-T570 control box wiring faulty, will need to be rewired											
					-battery flat on trailer, will need to be replaced											
T570	Wodonga - Workshop	Body\TRL FLOOR	Move Mezz Deck to floor height.		-andenson olue added under mez deck floor to move floor as control box wasnt workene	17/10/2025	876993	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		17/10/2025	876993	Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes\BRAKE ADJ	BRAKES NEED TO BE ADJUSTED.			17/10/2025	876993	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\DAMAGE	Crank handle broken			17/10/2025	876993	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\Punct	Tyres\Puncture POS 26			18/09/2025	876993	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	BORDER BANDAG PTY LTD	TRAILER
T570	Wodonga - Workshop	Tyres\RUN OUT	Tyres\RUN OUT POS 32			23/08/2025	876993	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	BORDER BANDAG PTY LTD	TRAILER
			Brakes\BREAKDOWN													
			ROAD SIDE SERVICE													
			ROAD SIDE SERVICE TO YASS SERVICE CENTRE FOR TRAILER BRAKE LOCKING UP.													
			CHECKED OVER ALL TRAILER BRAKES.													
			FOUND RH/S OUT OF ADJUSTMENT.													
			JACKED UP WHEEL AND ADJUSTED BRAKES.													
T570	Wodonga - Workshop	Brakes\BREAKDOWN	CHECKED OVER WHEEL BEARINGS. FOUND OK			18/07/2025	876993	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	CANBERRA TRUCK REPAIRS	TRAILER
T570	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		07/07/2025	876993	Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL LEGS	legs not working			07/07/2025	876993	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes\BRAKE ADJ	service brakes			07/07/2025	876993	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes\BRK O/HAUL	NO TRAILER BRAKES.			07/07/2025	876993	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\ELECT P&W	Right Hand Indicator			07/07/2025	876993	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Insp\ANN INSP	Insp\ANN INSP	Insp\ANN INSP		02/07/2025	876993	PreventativeMaintenance	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
			ELITE DIESEL- BREAKDOWN.													
			TRAVEL TO DANDENONG WOOLWORTHS DC.													
T570	Wodonga - Workshop	Body\TRL REPS	REPAIR CURTAIN FALLEN OUT OF RUNNER.			01/07/2025	876993	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	VAWDREY AUSTRALIA PTY LTD	TRAILER
T570	Wodonga - Workshop	Tyres\TP7+8	Tyres\TP7+8 (27-28)			26/06/2025	876993	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	BORDER BANDAG PTY LTD	TRAILER
T570	Wodonga - Workshop	Tyres\TP9+10	Tyres\TP9+10 (29-30)			26/06/2025	876993	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	BORDER BANDAG PTY LTD	TRAILER
T570	Wodonga - Workshop	Body\BREAKDOWN	G & S DIESEL- BREAKDOWN. TRAVEL TO AND FROM MICHINBURY DC. REPAIR CURTAIN ROLLER OUT OF ROLLER TRACK.			18/06/2025	876993	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	G & S DIESEL SERVICE	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	Repair Damaged Curtains. (Sign Effects P/O: WW092721)			18/03/2025	876993	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	TWIN CITY GRAPHICS	TRAILER
					REPLACED 2 BUCKLES AND 8 STRAPS. REPAIRED TORN CURTAIN.											
T570	Wodonga - Workshop	Body\TRL REPS	Need buckles & straps, curtains are sticking.		KR 2 HOURS LABOUR.	13/02/2025	876993	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshoo	TRAILER
T570	Wodonga - Workshop	Chassis\WINCH/STRP	BUCKLES AND STRAPS.			13/02/2025	876993	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\DAMAGE	Quick Fix Curtain Rips with Cable Ties, Need to keep trailers on road.			07/01/2025	876993	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		06/01/2025	876993	Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
					After hours Callout - Truganina											
					Attend site, locate vehicle											
					Diagnose r/h indicator not working											
					Check wiring at taillight (OK)											
					Check wiring along chassis - found broken wires											
					Repair wiring and check all lights (OK)											
					Reassemble vehicle and exit site											
T570	Wodonga - Workshop	Body\ELECT P&W	R/H Indicator NOT Flashing. (Hot Spark Auto Electrical P/O: WW091237)			31/12/2024	876993	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	HOT SPARK AUTO ELECTRICAL	TRAILER
T570	Wodonga - Workshop	Tyres\TP1+2	Replace Tyres On Positions 1&2. (Wodonga Tyre & Auto P/O: WW093161)			28/12/2024	876993	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	BEAUREPAIRES	TRAILER
T570	Wodonga - Workshop	Elect\ELECT P&W	Light connection broken			06/12/2024	876993	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\AIR FITTIN	Replace Bungy for Suzi Lines.			06/12/2024	876993	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	Temp repair UHF CWR curtain flap.		curtains need to be replaced	14/11/2024	876993	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		14/11/2024	876993	Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\ELECT P&W	Check operation of Mezz Deck.			21/10/2024	876993	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	LHR CURTAIN POLE BENT.			16/10/2024	876993	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		16/10/2024	876993	Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		18/09/2024	876993	Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\TAIL LIGHT	R/H Tail Light Not Working			18/09/2024	876993	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	DrCabElect\INDICATORS	Left side indicator broken			18/09/2024	876993	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	FAULTY ROLLER RHS 5TH ROLLER ON BELLY			31/08/2024	876993	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	LH CURTAIN KEEPS GETTING STUCK.			23/08/2024	876993	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection	Insp\ANN INSP		20/08/2024	876993	PreventativeMaintenance	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService\DS	D Service	VehService\DS		20/08/2024	876993	Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\TP7+8	Tyres\TP7+8			29/06/2024	876993	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	BEAUREPAIRES	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	Right side 5th curtain roller repair, as per R&R.		Curtain rail has been Damaged with forklift, whilst trailer was being loaded or unloaded.	22/06/2024	876993	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\INDICATORS	RH INDICATOR NOT WORKING.			14/06/2024	876993	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\AIR LEAK	repair air leaks			30/05/2024	876743	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL FLOOR	repair wiring loom bracket			30/05/2024	876743	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL FLOOR	Replace Mezz deck locks (PO: WWDB4117) (Vawdrey)			14/02/2024	876993	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			01/02/2024	123351	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Comp\Truck Safe	REPLACE NHVAS STICKER.			01/02/2024	123351	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		01/02/2024	123351	Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\ELECT P&W	REPLACED RH CLEARANCE AND INDICATOR LIGHTS.			01/02/2024	123351	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	WELDED CRACKS IN FRONT MEZZ DECK UPRIGHTS.			01/02/2024	123351	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes\ABS FAULTS	CHANGED ABS SOCKET.			01/02/2024	123351	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	REPLACED ALL BROKEN CURTAIN BUCKLES AND STRAPS.			01/02/2024	123351	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL FLOOR	REPAIRED MEZZ DECK. REPLACED LOCKS.			01/02/2024	123351	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Insp\DEFECT	CLEAR RMS DEFECT NOTICE NUMBER HVND872966			25/01/2024	123351	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Albury Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	REPLACE CURTAINS.			12/01/2024	876993	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	RIPPED CURTAINS.			12/01/2024	876993	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\TAIL LIGHT	Repaired LH Tail Light Wiring			06/12/2023	119135	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			18/11/2023	118144	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		18/11/2023	118144	Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Comp\Truck Safe	ORDER AND FIT NHVAS STICKER.			18/11/2023	118144	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	REPLACE CURTAINS.			18/11/2023	118144	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Comp\Truck Safe	REPLACE NHVAS STICKER.			18/11/2023		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	REPAIR CURTAINS.		TEMPORARILY PATCHED	03/11/2023		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	RIPPED CURTAINS.			03/11/2023	123351	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\TP1+2	Tyre Position 1 + 2			24/09/2023		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Albury Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			06/09/2023	112677	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Comp\Truck Safe	REPLACE NHVAS STICKER.			06/09/2023	112677	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		06/09/2023	112677	Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	REPAIR CURTAINS.			06/09/2023	112677	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		05/09/2023	876993	Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			05/09/2023	876993	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Chassis\MUDGUARDS	Replaced Rear Mudflaps			30/08/2023	115345	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Susp\SPRING HANG	Left front U bolt loose.			18/07/2023	111948	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			18/07/2023	111948	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	Curtains need replacing.			18/07/2023	111948	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\STRAPS	LH CURTAIN WILL REQUIRE REMOVAL FOR REPAIRS.			18/07/2023	111948	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL WALL	REAR WALL TWISTED			18/07/2023	111948	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL WALL	FRONT REAR WALL CRACKED.			18/07/2023	111948	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	CURTAINS NEED REPLACING.			18/07/2023	111948	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	small holes in curtains			18/07/2023	111948	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	MULTIPLE SPOT IN CURTAINS NEED PATCHING			18/07/2023	111948	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		18/07/2023	111948	Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Susp\AIR BAG	Left centre air bag U/S		REPLACED AIRBAG. CHECKED FOR LEAKS.	18/07/2023	111948	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\SLUD COIL	Trailer plug socket loose and causing lights to flicker.			18/07/2023	111948	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	Tear in curtain various spots.			18/07/2023	111948	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	BUCKS NEEDS TO BE FIXED.			18/07/2023	111948	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	CURTAINS HAS 2 RIPS.			18/07/2023	111948	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP		18/07/2023	111948	PreventativeMaintenance	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Comp\Truck Safe	REPLACE NHVAS STICKER.			18/07/2023	111948	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
			Replace Axle & Check All Wheel Bearings (Brown & Hurley Yatala)													
T570	Wodonga - Workshop	DrivLine\AXLE REPLC	Purchase Order Number: WW079540			15/06/2023	876993	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshoo	TRAILER
			Tow Off Motor Way To Brown & Hurley Yatala (Barnes Auto Co)													
T570	Wodonga - Workshop	DrivLine\WHEEL BRGS	Purchase Order Number: WW078994			15/06/2023	876993	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshoo	TRAILER
T570	Wodonga - Workshop	Tyres\TP3+4	Tyre Position 3 + 4			04/06/2023		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Albury Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\TP5+6	Tyre Position 5 + 6			04/06/2023		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Albury Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\TP9+10	Tyre Position 9 + 10			04/06/2023		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Albury Workshop	TRAILER
			Uprights and goose necks cracked.													
T570	Wodonga - Workshop	Body\TRL REPS	Weld Cracks on inside of platform and deck.			13/05/2023		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshoo	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			12/05/2023		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		12/05/2023		Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	Curtains need replacing.			12/05/2023		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	Uprights and goose necks cracked.			12/05/2023		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	DrivLine\WHEEL BRGS	Adjusted wheel bearings.			12/05/2023		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			12/04/2023	88161	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\STRAPS	LH CURTAIN WILL REQUIRE REMOVAL FOR REPAIRS.			12/04/2023	88161	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL WALL	REAR WALL TWISTED			12/04/2023	88161	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL WALL	FRONT REAR WALL CRACKED.			12/04/2023	88161	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	CURTAINS NEED REPLACING.			12/04/2023	88161	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	small holes in curtains			12/04/2023	88161	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	MULTIPLE SPOT IN CURTAINS NEED PATCHING			12/04/2023	88161	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\SLUD COIL	Trailer plug socket loose and causing lights to flicker.			12/04/2023	88161	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	Tear in curtain various spots.			12/04/2023	88161	Repair	Completed	FL Green Distribution	Tilmer	Wodon

T570	Wodonga - Workshop	DriveLine|WHEEL BRGS	Adjusted all bearings							12/04/2023	88161	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Susp|SPRING HANG	Left front U bolt loose.							12/04/2023	88161	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Susp|AIR BAG	Left centre air bag U/S							12/04/2023	88161	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres|TP3+2	Tyre Position 1 + 2							02/04/2023		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Albury Workshop	TRAILER
T570	Wodonga - Workshop	Tyres|TP11+12	Tyre Position 11 + 12							02/04/2023		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Albury Workshop	TRAILER
T570	Wodonga - Workshop	Body|TRL DOORS	REPAIRED RIGHT SIDE REAR WALL CHANNEL.							20/01/2023	43343	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job							18/01/2023		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body|TRL REPS	CURTAINS NEED REPLACING.							18/01/2023		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body|TRL REPS	small holes in curtains							18/01/2023		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body|TRL REPS	MULTIPLE SPOT IN CURTAINS NEED PATCHING							18/01/2023		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService|DS	D Service As Per Attached Checklist		VehService|DS					18/01/2023		Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job							04/01/2023		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body|STRAPS	LH CURTAIN WILL REQUIRE REMOVAL FOR REPAIRS.							04/01/2023		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body|TRL WALL	REAR WALL TWISTED							04/01/2023		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body|TRL WALL	FRONT REAR WALL CRACKED.							04/01/2023		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body|TRL REPS	CURTAINS NEED REPLACING.							04/01/2023		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body|TRL REPS	small holes in curtains							04/01/2023		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body|TRL REPS	MULTIPLE SPOT IN CURTAINS NEED PATCHING							04/01/2023		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService|DS	D Service As Per Attached Checklist		VehService|DS					04/01/2023		Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres|TP02	Puncture repair							15/12/2022		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Albury Workshop	TRAILER
T570	Wodonga - Workshop	Tyres|TP10	Puncture repair							15/12/2022		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Albury Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job							10/12/2022		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService|DS	D Service As Per Attached Checklist		VehService|DS					30/12/2022		Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService|DS	D Service As Per Attached Checklist		VehService|DS					21/11/2022	876993	Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job							21/11/2022	876993	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Comp|Truck Safe	NHVAS STICKER DAMAGED							21/11/2022	876993	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job							08/10/2022	744	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body|TRL WALL	MULTIPLE CRACKS BOTH SIDES OF REAR WALL					REPAIRED REAR WALL, FRONT WALL AND DECK GUIDE.		08/10/2022	744	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService|DS	D Service As Per Attached Checklist		VehService|DS			TIGHTENED RR U-BOLTS.		08/10/2022	744	Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes|BRK RELINE	RELINE.							08/10/2022	744	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body|TRL REPS	REPLACED FRONT RIGHT CURTAIN RATCHET.							08/10/2022	744	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres|TP5+6	supply and fit 4 tyres							14/09/2022		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres|TP7+8	Tyre Position 7 + 8							14/09/2022		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job							11/09/2022		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService|DS	D Service As Per Attached Checklist		VehService|DS			ADJUSTED LM WHEEL BEARING. REPLACED TRUCKSAFE STICKER.		11/09/2022		Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job							29/07/2022	368230	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService|DS	D Service As Per Attached Checklist		VehService|DS			ADJUSTED LM RM WHEEL BEARINGS.		29/07/2022	368230	Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job							29/06/2022	267129	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect|INDICATORS	REPLACE RH INDICATOR.							29/06/2022	267129	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService|DS	D Service As Per Attached Checklist		VehService|DS			REPLACED LF AIRBAG, BROKEN BOTTOM SADDLE AND SHOCK. REPAIRED BRAKE LIGHTS. REPLACED 3 STRAPS AND 2 BUCKLES.		29/06/2022	267129	Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Insp|ANN INSP	Annual Inspection As Per Checklist		Insp|ANN INSP					02/06/2022	366220	PreventativeMaintenance	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body|TRL WALL	FRONT REAR WALL CRACKED.							02/06/2022	366220	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body|TRL REPS	CURTAINS NEED REPLACING.							02/06/2022	366220	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job							02/06/2022	366220	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body|TRL REPS	small holes in curtains							02/06/2022	366220	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body|TRL REPS	MULTIPLE SPOT IN CURTAINS NEED PATCHING							02/06/2022	366220	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body|TRL WALL	MULTIPLE CRACKS BOTH SIDES OF REAR WALL							02/06/2022	366220	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService|DS	D Service As Per Attached Checklist		VehService|DS					02/06/2022	366220	Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect|INDICATORS	REPLACE RH INDICATOR.							02/06/2022	366220	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect|INDICATORS	REPAIR RHS INDICATORS.					TESTED ALL PLUGS. DIAGNOSED AND REPAIRED RUBBED/ BROKEN WIRING FROM SIDE MARKER TO REAR ASSEMBLY.		21/05/2022		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
			Find and replace leaking floor lock																	
			Wodonga Pneumatics to Supply parts																	
T570	Wodonga - Workshop	Body|TRL FLOOR	PO# WWO71939							17/05/2022		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
			Air leak in Mez floor.																	
T570	Wodonga - Workshop	Body|AIR LEAK	Need air leak fixed ASAP.					Refer Job # 381388		17/05/2022		Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
			Tyre Blowout																	
			2 x Front Left Axle																	
T570	Wodonga - Workshop	Tyres|TP1+2	Beaurepairs contacted to attend							14/05/2022		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body|TRL FLOOR	AIR LEAK IN MEZ STILL, CAUSES DELAY IN TAKING OFF AND IS A PAIN AT COLES.					NOT LEAKING IN WORKSHOP. UNBUCKLED AND SPRAYED FITTINGS. NO AIR LOST WHEN SITTING FOR 1.5 HOURS.		11/05/2022		Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job							27/04/2022		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body|REFLECTORS	REPLACE REFLECTORS							27/04/2022		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body|TRL FLOOR	SEVERE AIR LEAK IN MEZ FLOOR							27/04/2022		Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService|DS	D Service As Per Attached Checklist		VehService|DS					27/04/2022		Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes|AIR LEAK	DIAGNOSED AND REPAIRED AIR LEAK AT RISABLE DECK INSIDE TRAILER. DIAGNOSED AND REPLACED BROKEN BOLTS IN DECK ROLLER BRACKETS. TESTED. ADJUSTED BRAKE!							29/04/2022	768229	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job							30/03/2022	258229	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService|DS	D Service As Per Attached Checklist		VehService|DS					30/03/2022	258229	Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body|AIR LEAK	BAD AIR LEAK IN DECK, LOOSES AIR FAST.					NO AIR LEAK AT SERVICE.		30/03/2022	258229	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job							02/03/2022	258229	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body|REFLECTORS	REPLACE REFLECTORS							02/03/2022	258229	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body|TRL FLOOR	SEVERE AIR LEAK IN MEZ FLOOR							02/03/2022	258229	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body|AIR LEAK	BAD AIR LEAK IN DECK, LOOSES AIR FAST.							02/03/2022	258229	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService|DS	D Service As Per Attached Checklist		VehService|DS					02/03/2022	258229	Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres|TP5+6	supply and fit 2tyres							23/01/2022	260250	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job							23/01/2022	368228	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes|AIR LEAK	AIR LEAK.							23/01/2022	368228	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes|AIR LEAK	AIR LEAK					CHECKED WITH SOAP WATER		23/01/2022	368228	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService|DS	D Service As Per Attached Checklist		VehService|DS			ADJUSTED ALL WHEEL BEARINGS		23/01/2022	368228	Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body|REFLECTORS	REPLACE REFLECTORS							23/01/2022	368228	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body|TRL REPS	MULTIPLE SPOT IN CURTAINS NEED PATCHING							23/01/2022	368228	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body|TRL WALL	MULTIPLE CRACKS BOTH SIDES OF REAR WALL							23/01/2022	368228	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Chassis|MUDGUARDS	Replace Mudflaps					Replaced both side mudflaps.		30/12/2021	360229	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Susp|AIR BAG	REPAIRED RUBBED AIRLINES TO MIDDLE AXLE AIRBAGS.							15/12/2021		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job							12/12/2021	389350	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body|TRL FLOOR	repair wiring for mez floor							12/12/2021	389350	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService|DS	D Service As Per Attached Checklist		VehService|DS					12/12/2021	389350	Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect|ELECT P&W	ELECTRICAL CABLE AND BRACKET HANGING OFF MEZ DECK UNDERSIDE R/H SIDE.							12/12/2021	389350	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres|RIMS CHECK	Pressure Check							24/11/2021	288229	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job							04/11/2021	368228	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body|STRAPS	RIPS CURTAINS AT DROP DECK							04/11/2021	368228	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService|DS	D Service As Per Attached Checklist		VehService|DS			REPLACED LF RF LM RM RR WHEEL BEARINGS		04/11/2021	368228	Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Comp|Truck Safe	NHVAS STICKER DAMAGED							04/11/2021	368228	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body|STRAPS	LH CURTAIN WILL REQUIRE REMOVAL FOR REPAIRS.							04/11/2021	368228	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body|TRL WALL	REAR WALL TWISTED							04/11/2021	368228	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes|AIR LEAK	REPLACED AIRLINE FROM BOOSTER TO VALVE							04/11/2021	368228	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Susp|SUSPENSION	REPLACED LM RR U-BOLTS							04/11/2021	368228	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
			REPLACED LR TOP LIGHTS AND STRAIGHTENED BAR.																	
T570	Wodonga - Workshop	Elect|ELECT P&W	PAINTED.							04/11/2021	368228	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Workshop|MOVE ASSET	PICKUP T570/569 SET. TAKE TO SERVICE BAY. CHECKED LIGHTS. CHANGED STICKER FOR SERVICE AFTER FOUND AIRLEAK A AND B TRAILER. AFTERWARDS PARK INTO TRUCI							03/11/2021		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job							22/09/2021	268729	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService|DS	D Service As Per Attached Checklist		VehService|DS					22/09/2021	268729	Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes|AIR LEAK	REPLACED TWO LEAKING AIR LINES							22/09/2021	268729	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect|ELECT P&W	REPLACED LH WALL CLEARANCE LIGHT.							22/09/2021	268729	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body|REFLECTORS	REPLACED REFLECTORS							22/09/2021	268729	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body|PANELS	MAKE STRAIGHT SOME LIGHT HAS BENT							22/09/2021	268729	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	DriveLine|WHEEL BRGS	ADJUSTED ALL WHEEL BEARINGS							22/09/2021	268729	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres|Re-Tor	POS 1,2,3,4,9,10							18/09/2021	258829	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Workshop|MOVE ASSET	Moving trailers and pick up for servicing.							15/09/2021		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres|TP1+2	Supply and fit 6 tyres							11/09/2021	369429	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres|TP3+4	Tyre Position 3 + 4							11/09/2021	369429	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres|TP9+10	Tyre Position 9 + 10							11/09/2021	369429	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres|TP5+6	Supply and fit 4 tyres							28/08/2021	360129	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres|TP7+8	Tyre Position 7 + 8							28/08/2021	360129	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job							14/08/2021	260429	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService|DS	D Service As Per Attached Checklist		VehService|DS					14/08/2021	260429	Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
			Tore Curtain leaving customer site.																	
			Sent to Vawdrey Laraginta																	
T570	Wodonga - Workshop	Body|DAMAGE	PO# WWO66146							10/08/2021		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body|TRL REPS	small holes in curtains							16/07/2021		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body|STRAPS	RIPS CURTAINS AT DROP DECK							16/07/2021		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job							13/07/2021	371929	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Chassis|CHAS CRACK	Cracks in box corners							13/07/2021	371929	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Chassis|FIFTH WHEE	foundation cracks & plates							13/07/2021	371929	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body|TRL WALL	front wall has crack							13/07/2021	371929	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Chassis|TRL LEGS	legs needs welding							13/07/2021	371929	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Chassis|TRL LEGS	legs needs welding							13/07/2021	371929	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService|DS	D Service As Per Attached Checklist		VehService|DS					13/07/2021	371929	Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body|STRAPS	RIPS CURTAINS AT DROP DECK							13/07/2021	371929	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Workshop|CLEAN	Clean top shed and Welding area.							13/07/2021	371929	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
			upgrade mez floor controls and motor																	
			Steel Order from Don Sparks.																	
T570	Wodonga - Workshop	Body|TRL FLOOR	PO# WW 065220					REMOVED UPRIGHTS. FABRICATED NEW UPRIGHTS. REMOVED CROSS BRACING AND WELDED GOOSENECK CRACKS.		17/06/2021		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body|TRL FLOOR	Left hand front lock U/S					Completed.		29/05/2021		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job							14/05/2021		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
								Inspect to find 2 x lights loose due to mount broken. Found LH top rear indicator not working. Remove light to find wire had													
T570	Wodonga - Workshop	Body|LIGHTS	multiple light is loose					broken off flush with body of light. Replace loose light mounts and indicator.		14/05/2021		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body|TRL REPS	buckles damaged and need replacing					Inspect all buckles to find all in good working order.		14/05/2021		Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService|DS	D Service As Per Attached Checklist		VehService|DS			Carry out Trailer D service as per customer's provided service sheet.		14/05/2021	

G&S
CARRY OUT SERVICE ON VEHICLE COMPLETE CHECK OVER
REPAIR & REPORT ON DEFECTS AS REQUIRED
CARRY OUT BRAKE ROLLER & SHAKER CHECK
FIT REFLECTORS
REFITTED CLEARANCE LIGHT R/H SIDE
R & R KING PIN
WORK REQUIRED
TYRES ON 2ND AXLE LOW TREAD

T570	Wodonga - Workshop	VehService\AS	UNEVEN WEAR ON TYRES 1ST & 3RD AXLES				02/04/2021	26149	Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				06/03/2021		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	Gilbert and Roach carried out D-Service		06/03/2021		Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				27/02/2021		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService\DS	Carry Out D Service	VehService\DS	service done by kenworth huntingwood trailers 569/570 PO WW062347		27/02/2021		Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\BREAKDOWN	mez floor wont go down		G&S desiel POWW061349		22/01/2021		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	close up curtains				21/01/2021		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL FLOOR	check mez decks				19/01/2021		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL FLOOR	weld various cracks and lock holes				19/01/2021		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL FLOOR	inspect chains and job				19/01/2021		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL FLOOR	check mez decks operating, clean floor from inside and replaced strap				19/01/2021		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Workshop\CLEAN	pick up from HTT				13/01/2021		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Workshop\MOVE ASSET	drop off to Hume Truck Teknics				13/01/2021	253029	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\BATTERY	replace battery's at Hume Truck				13/01/2021		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Susp\SUSPENSION	needs to have - remaining bushs		HTT to repair		12/01/2021		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body	Mez deck repairs		remove battery's for replace - Pending		12/01/2021	253029	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL FLOOR	repairs floor repairs and adjust chains				12/01/2021	253029	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\LIGHTS	multiple light is loose				10/01/2021	233029	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	multiple strap is missing				10/01/2021	233029	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	curtain buckles				10/01/2021	233029	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body	Mez deck lock				10/01/2021	233029	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Susp\AXLES	inspect middle axle's excessive movement				06/01/2021		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Workshop\CLEAN	clean up from repairs				06/01/2021		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Workshop\CLEAN	repairs to workshop tools				06/01/2021		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				06/01/2021	173828	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Chassis\AIR LEAK	air leak in B Trailer				06/01/2021	173828	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\INDICATORS	RHR indicator has short				06/01/2021	173828	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes\AIR LEAK	check for air leak in brake system major air leak in trailer				06/01/2021	173828	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Susp\AIR LEAK	(needs fixine asap)				06/01/2021	173828	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			06/01/2021	173828	Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Susp\SUSPENSION	inspect and replace middle bushs				06/01/2021	173828	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Workshop\CLEAN	clean up				06/01/2021	173828	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\LIGHTS	multiple light is loose				06/01/2021	173828	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	multiple strap is missing				06/01/2021	173828	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Chassis\WHEEL BRGS	L.R,M.L, M.R, R.R, R.L has adjusted				06/01/2021	173828	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Susp\SUSPENSION	needs to have - remaining bushs				06/01/2021	173828	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Susp\AXLES	replaced front and rear				06/01/2021	173828	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Susp\AIR LEAK	air leaks				05/01/2021		Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	buckles damaged and need replacing				05/01/2021		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\TRL LIGHTS	Locate and repair elec issue with rear indicators				26/11/2020	174020	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				26/11/2020	174020	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\INDICATORS	rear indicators				26/11/2020	174020	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	3 strap missing				26/11/2020	174020	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Susp\AIR LEAK	air leaks rectified				26/11/2020	174020	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL WALL	front wall has crack				26/11/2020	174020	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Chassis\TRL LEGS	legs needs welding				26/11/2020	174020	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Chassis\WHEEL BRGS	five of them adjusted except R. middle				26/11/2020	174020	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Chassis\TRL LEGS	legs needs welding				26/11/2020	174020	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	got problem with light plug prime mover that's why we spent time on it		26/11/2020	174020	Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes\AIR LEAK	Locate and repair air leaks				26/11/2020	174020	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\ELECT P&W	CALLOUT AFTER HOURS. TRAVEL TO DEPOT. CHECK RHS FLASHER NW. CHECK POWER TO TRAILER BASE OK TRACE WIRING FOUND RUBBED THRU ON AIR LINE. REPAIR WIR				26/11/2020		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\AIR LEAK	losing air in mez deck air lines on RHS causing brakes to lock on				19/11/2020		Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\AIR LEAK	fix multiple air leaks				19/11/2020		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\AIR LEAK	major air leak in 570				15/11/2020		Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\INDICATORS	R/H indicator is working on very odd occasions				15/11/2020		Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	Job Added From Invoice				16/10/2020	0	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
					set up for repairs												
					replaced airbags sprayed for leaks												
					tightenened booster lines height control												
					clean up hand over												
T570	Wodonga - Workshop	Susp\AIR LEAK	find air leak in b trailer				10/10/2020	173030	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	replaced damaged curtain buckle l/hand side				03/10/2020	173030	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				03/10/2020	173039	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			03/10/2020	173039	Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Chassis\WHEEL BRGS	adjusted 4k front, rear bearing				03/10/2020	173039	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice				23/09/2020	173029	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice				23/09/2020	173029	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice				17/09/2020	173029	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice				17/09/2020	173029	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\Punct	Job Added From Invoice				17/09/2020	173029	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\TRL LIGHTS	Job Added From Invoice				15/09/2020	0	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				10/09/2020		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			10/09/2020		Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\HOUSEKEEP	pump up LH outer tyre				23/08/2020		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\DAMAGE	weld new gooseneck doublers				15/08/2020		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	repairs to curtains		hook up A o B park up and clan top shed		14/08/2020		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP	cancelled		13/08/2020		PreventativeMaintenance	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL FLOOR	weld mez floor uprights				12/08/2020	63021	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP			12/08/2020		PreventativeMaintenance	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				12/08/2020	63021	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	small holes in curtains				12/08/2020	63021	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Chassis\CHAS CRACK	Cracks in box corners				12/08/2020	63021	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Chassis\FIFTH WHEE	Foundation cracks & plates				12/08/2020	63021	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Susp\AIR BAG	Perished RHM airbag		30K changed		12/08/2020	63021	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			12/08/2020	63021	Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\TRL LIGHTS	Replace LHS Indicator & clearance lights		Straightened & welded brackets. Rewired under trailer & titdied wiring		11/08/2020	63021	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
					MIDDLE AIR TANK EMPTY												
T570	Wodonga - Workshop	Susp\AIR BAG	Call Out Air Bags not raising		- UNSCREWED PRESSURE PROTECTION SPRING OUT		07/08/2020		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL WALL	fix uprights		straighten up rights weld cracks and paint welds		09/07/2020		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				10/06/2020	133829	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	small holes in curtains				10/06/2020	133829	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	rips and holes in curtains		As per #289728		10/06/2020	133829	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	need to be sent for repairs		As per #289729		10/06/2020	133829	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	LHR curtain roller		As per #289730		10/06/2020	133829	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\BRK LIGHT	Brake Light		Previously completed		10/06/2020	133829	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	Trailer (Tautliner) Repairs		As per #289729		10/06/2020	133829	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Susp\SHOCK ABS	Shock Absorber		Previously completed		10/06/2020	133829	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Chassis\CHAS CRACK	Cracks in box corners				10/06/2020	133829	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Chassis\FIFTH WHEE	Foundation cracks & plates				10/06/2020	133829	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Susp\AIR BAG	Perished RHM airbag				10/06/2020	133829	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			10/06/2020	133829	Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice				27/05/2020	173028	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice				27/05/2020	173028	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				09/05/2020	173024	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			09/05/2020	173024	Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	DriveLine\WHL HUB	adjusted R/front				09/05/2020	173024	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Susp\SHOCK ABS	R/rear shocky U/s				09/05/2020	173024	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL FLOOR	mez deck lock cylinders		wodonga pmatics Poww054121		06/05/2020		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\DRV TYRES	Flat tyre LRM outter				04/05/2020		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Workshop\TRAINING	problem solve mezzanine		floor malfunction		30/04/2020		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL FLOOR	VAWDREY QLD: move trailer in and out of workshoo (nil channel. repair and refit RH front Mezzanine deck chain. test operation of mezzanine deck and report. Set mezz		transpower for chain links Poww054120		25/04/2020	173029	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\WRES CHECK	Job Added From Invoice				17/04/2020	172857	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				10/04/2020	172857	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			10/04/2020	172857	Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\BRK LIGHT	no brake lights				10/04/2020	172857	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	small rips at deck folds				10/04/2020	172857	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Susp\SHOCK ABS	RHR shock dust cover broken				10/04/2020	172857	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Chassis\WINCH/STRP	replaced 5 curtain straps and buckles				30/03/2020		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	repair curtain				30/03/2020		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body	Job Added From Invoice				26/03/2020	0	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\REFLECTORS	Job Added From Invoice				26/03/2020	0	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	DriveLine\WHEEL BRGS	Job Added From Invoice				13/03/2020	0	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	repairs to curtain& rollers				12/03/2020		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Chassis\CHAS CRACK	weld Cracks @ gooseneck				11/03/2020		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		Previously completed		11/03/2020		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Chassis\CROSS MBR	cross bracing cracked LH side				11/03/2020		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	Previously completed		11/03/2020		Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			11/03/2020	171123	Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				11/03/2020	171123	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\TP03	LHR outer sidewall damage		Previously completed		11/03/2020	171123	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Chassis\CHAS CRACK	body corners and deck uprights				11/03/2020	171123	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	LHR curtain roller				11/03/2020	171123	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Workshop\MOVE ASSET	Move trailers to top shed		Clean service bay		11/03/2020	171123	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Chassis\MUDGUARDS	Replaced 4x mudflaps				11/03/2020	171123	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Workshop\CLEAN	Clean up work area				11/03/2020	171123	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Workshop\MOVE ASSET	Move & split from T569 for repairs				31/01/2020		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\REFLECTORS	Replace reflectors				31/01/2020	165753	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\CASE STOCK	Job Added From Invoice				24/01/2020	785784	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice				24/01/2020	785784	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\RETREAD	Job Added From Invoice				24/01/2020	785784	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Susp\AIR LEAK	air problem for air bags		centre west diesel POww050955		16/01/2020		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Susp\AIR LEAK	air bags are not going up		Camels truck repairs fixing problem Poww050953		16/01/2020		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL FLOOR	check mez decks and air leak				09/01/2020		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				28/12/2019	160752	Repair	Completed

T570	Wodonga - Workshop	Chassis\CHAS CRACK	body corners and deck uprights					28/12/2019	160752	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Chassis\CROSS MBR	cross bracing cracked LH side					28/12/2019	160752	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Veh\Service\DS	D Service As Per Attached Checklist	Veh\Service\DS				28/12/2019	160752	Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Susp\AIR BAG	Replaced RHF airbag					28/1/2019		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice					23/11/2019	160753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice					23/11/2019	160753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
					airbags are taking 5-10 minutes to build up air																
					drivers are just impatient and not letting the trailer build up																
T570	Wodonga - Workshop	Susp\AIR BAG	check for airbag leak		there are air and iust driving when the brakes release			19/11/2019		Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
					check brake adjustment on trailer																
T570	Wodonga - Workshop	Brakes\BRAKE ADJ	check brake adjustment		-driver must be using handsiece when they are braking			19/11/2019		Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job					14/11/2019		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\TRL LIGHTS	LH clearance light					14/11/2019		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Veh\Service\DS	D Service As Per Attached Checklist	Veh\Service\DS				14/11/2019		Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	Small rips & holes					14/11/2019		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	curtains damaged					14/11/2019	160753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL FLOOR	plate under deck has a broken hinge - hangs down					14/11/2019	160753	Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	needs curtain buckle straps					14/11/2019	160753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Chassis\AIR FITTN	REPLACE BULK HEAD COUPLING					13/11/2019		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Workshop\MOVE ASSET	HOOK UP SET & MOVE TRAILERS					13/11/2019		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL WALL	REPAIRES - BODY CRACKES & DOOR MOUNTS					08/11/2019	160753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL FLOOR	WELD GOOSE NECK CRACKS					08/11/2019	160753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Workshop\MOVE ASSET	MOVE TRAILERS OUT OF SHED TO YARD					08/11/2019	160753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Workshop\CLEAN	CLEAN UP FROM JOBS					08/11/2019	160753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL FLOOR	Mez deck repairs					08/11/2019		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL FLOOR	Mez deck repairs		Remove part of upright. Remove lock assembly, replace cog bearings, fix part of chain, put all back together.			07/11/2019		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Susp\AIR BAG	Inspected trailer for air leak & found that the RHF & RHR air bag are leaking					31/10/2019	160753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TOOLBOX	Tool box would be nice		Paul Johnstone's decision			21/10/2019		Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL FLOOR	broken mezz floor support found on floor of B trailer (needs urgent attention)		has been secured. Requires further attention			21/10/2019		Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL FLOOR	plate under deck has a broken hinge - hangs down					21/10/2019		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	DrCabElect\AIR BAG	R/M & R/F badly leaking cracked					21/10/2019	160753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job					21/10/2019	160753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	small holes in curtains					21/10/2019	160753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\TRL LIGHTS	1x side light EBS base					21/10/2019	160753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Veh\Service\DS	D Service As Per Attached Checklist	Veh\Service\DS				21/10/2019	160753	Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Chassis\FIFTH WHEE	Skid plate has excess wear at front of kingpin		monitor			21/10/2019	160753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\TAIL LIGHT	tail lights not working					21/10/2019	160753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	rips and holes in curtains					21/10/2019	160753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Susp\AIR LEAK	RHF leaking					21/10/2019	160753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	needs curtain buckle straps					21/10/2019	160753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\TRL LIGHTS	LH clearance light					21/10/2019	160753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	curtains damaged					21/10/2019	160753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	DrvLine\WHEEL BRGS	adjusted all bearings					21/10/2019	160753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Chassis\FIFTH WHEE	kingpin undersized u/s					21/10/2019	160753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\TRL LIGHTS	replace LHS clearance light in amongst tri axle					21/10/2019	160753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Chassis\FIFTH WHEE	replace kingpin					21/10/2019	160753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres	Job Added From Invoice					17/10/2019	160753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\PRES CHECK	Job Added From Invoice					17/10/2019	160753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice					17/10/2019	160753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice					17/10/2019	160753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice					17/10/2019	160753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice					17/10/2019	10	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
			smoke coming from LHR side of trailers																		
			airbag took forever to build up air which caused the tyres to rob																		
			Rhm inner tyre flat																		
T570	Wodonga - Workshop	Body\AIR BAG	called Beaucreatrs to fix issue					07/10/2019		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job					30/09/2019	160753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Veh\Service\DS	D Service As Per Attached Checklist	Veh\Service\DS				30/09/2019	160753	Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\TAIL LIGHT	tail lights not working					30/09/2019	160753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	rips and holes in curtains					30/09/2019	160753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Susp\AIR LEAK	RHF leaking					30/09/2019	160753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\ELECT P&W	wiring behind trailer plug rubbed through and shorting out light's, remove bad wiring					26/09/2019		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\BATTERY	changed batteries and fuse and test deck					26/09/2019		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice					17/09/2019	0	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice					17/09/2019	0	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\Alt Callout	Job Added From Invoice					17/09/2019	0	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	replace broken straps					12/09/2019	160753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice					27/08/2019	160753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice					27/08/2019	160753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Brake test results attached					12/08/2019	169753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\TP21	Tyre Position 21					12/08/2019	160753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	DrvLine\WHEEL BRGS	Adjusted RHR wheel bearing					12/08/2019	169753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Chassis\FIFTH WHEE	Skid plate has excess wear at front of king pin					12/08/2019	169753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Veh\Service\DS	D Service	Veh\Service\DS				12/08/2019	169753	Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		completed			14/07/2019	169753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\TRL LIGHTS	1x side light EBS base					14/07/2019	169753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Veh\Service\DS	D Service As Per Attached Checklist	Veh\Service\DS	completed			14/07/2019	169753	Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	DrCabElect\AIR BAG	R/M & R/F badly leaking cracked					14/07/2019	169753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice					14/07/2019	160753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice					14/07/2019	160753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\TRL LIGHTS	Job Added From Invoice					19/06/2019	0	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Chassis\TRL LEGS	Job Added From Invoice					15/06/2019	0	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP				12/06/2019	160753	PreventativeMaintenance	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\ELECT P&W	EBS base changed					12/06/2019	160753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\ELECT P&W	1x c/lamp replaced					12/06/2019	160753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\TRL LIGHTS	1x side light EBS base					12/06/2019	160753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job					12/06/2019	160753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	hole's and reflective stiping u/s					12/06/2019	160753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	small holes in curtains					12/06/2019	160753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TOOLBOX	Tool box would be nice		waiting on parts			12/06/2019	160753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL FLOOR	broken mezz floor support found on floor of B trailer (needs urgent attention)					12/06/2019	160753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes\BRAKE ADJ	adjust brakes					12/06/2019	160753	Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Veh\Service\DS	D Service As Per Attached Checklist	Veh\Service\DS				12/06/2019	160753	Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
			curtain roller drivers side unable to move due to roller coming out of track																		
			the roller right or the curtain handle																		
T570	Wodonga - Workshop	Body\TRL REPS	B buckle in		iob previously completed			12/06/2019	160753	Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL LEGS	trailer legs very hard to wind up					12/06/2019	160753	Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
			high speed jammed																		
			low speed barely usable																		
T570	Wodonga - Workshop	Body\TRL LEGS	as per previous repair request		previously done			12/06/2019	160753	Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	check curtain and repairs					12/06/2019	160753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Susp\AIR BAG	airbags need urgent attention					01/06/2019		Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Chassis\TRL LEGS	trailer legs only work in slow					01/06/2019		Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes\EBS FAULTS	inpact brake isue. EBS plugs on front of T570 and rear of T569 require replacing					23/05/2019	60752	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL LEGS	legs on T570 lock up when in high gear					23/05/2019	60752	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	various curtain buckles need replacing		replaced buckle straps			09/05/2019	660753	Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	2 rollers u/s on curtain					02/05/2019		Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	both curtains hard to pull due to worn rollers					02/05/2019		Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\ELECT P&W	fix wiring under trailer					25/04/2019	169753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL FLOOR	mez floor locking pin missing		repair mez deck lock full rebuild			11/04/2019	160753	Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	2 rollers u/s on curtain					11/04/2019	160753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body	Job Added From Invoice					29/03/2019	0	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\MUDGUARDS	Job Added From Invoice					29/03/2019	0	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\DRV TYRES	RHM I					16/03/2019	160753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\MUDGUARDS	front mudflaps, missing or u/s					16/03/2019	160753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
			goose neck above legs																		
T570	Wodonga - Workshop	Chassis\CHAS CRACK	deck uorisht u/s. fix ASAP					16/03/2019	160753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	DrvLine\CTCH PACK	RHF requires inspection next service					16/03/2019	160753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL LEGS	legs pushed back/bent		legs straightened and reinforced with bracing			16/03/2019	160753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\DRV TYRES	some tyres on "B" need replacing		as per job#216604			16/03/2019	160753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\TRL LIGHTS	no clearance lights on "B"		LHF & LH-F side markers out			16/03/2019	160753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\ELECT P&W	inspect wiring for mez floor and charge rate		wiring replaced and correctly wired so battery not charging with truck lights			16/03/2019	160753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Workshop\MOVE ASSET	move trailers/yard check					16/03/2019	160753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	weld front uprights cracks and fit RHS to stop movement of front deck uprights and chain mounts					16/03/2019	160753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Chassis\CHAS CRACK	repair/weld rear goosenack's					16/03/2019	160753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\DAMAGE	deck lock repairs and chain attention					16/03/2019	160753	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\ELECT P&W	wiring behind trailer plug rubbed through and shorting out lights, remove bad wiring					26/02/2019		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\BATTERY	changed batteries and fuse and test deck					26/02/2019		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\BATTERY	replaced both batteries, unloaded middle of trailer and tested floor and reloaded and parked					25/02/2019	165958	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	mez floor jamming					25/02/2019		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	mezz floor want go back up (needs urgent attention)					23/02/2019		Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\DRV TYRES	some tyres on "B" need replacing					23/02/2019		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\TRL LIGHTS	no clearance lights on "B"					23/02/2019		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\DRV TYRES	RHM I					16/02/2019	150095	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job					16/02/2019	150095	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	curtains roller broken					16/02/2019	150095	Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL FLOOR	repair broken lock					16/02/2019	150095	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Veh\Service\DS	D Service As Per Attached Checklist	Veh\Service\DS				16/02/2019	150095	Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\MUDGUARDS	front mudflaps, missing or u/s					16/02/2019	150095	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	small holes in curtains					16/02/2019	150095	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
			goose neck above legs																		
T570	Wodonga - Workshop	Chassis\CHAS CRACK	deck uorisht u/s. fix ASAP					16/02/2019	150095	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	DrvLine\CTCH PACK	RHF requires inspection next service					16/02/2019	150095	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL LEGS	legs pushed back/bent					16/02/2019	150095	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL LEGS	foot on back floor is broken will not flickout passing side rear					11/02/2019		Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\BREAKDOWN	mez floor issues					11/02/2019		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\Alt Callout	Job Added From Invoice					27/01/2019	0	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		cleaning			04/01/2019	125401	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Veh\Service\DS	D Service As Per Attached Checklist	Veh\Service\DS				04/01/2019	125401	Service

T570	Wodonga - Workshop	Body\TRL LEGS	make and fit new foot to leg clean out strap deck move out of shed					04/12/2018	112044	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	some curtain tie down straps need replacing					18/11/2018	0	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice					16/11/2018	94889	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice					16/11/2018	94889	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\AH Callout	Job Added From Invoice					16/11/2018	94889	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\TAIL LIGHT	breakdown Camels Truck Repairs heading out					14/11/2018		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\DRV TYRES	rear passenger tri tyre - puncture					13/11/2018	201207	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job					07/11/2018	92205	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\MOUNTS	Fill in rope rail on looseneck					07/11/2018	92205	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Chassis\TRL LEGS	landing legs bent and hard to use					07/11/2018	92205	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS				07/11/2018	92205	Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\REFLECTORS	Job Added From Invoice					06/10/2018	0	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\FIFTH WHEE	Check skid plate					06/10/2018		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService\DS	D Service	VehService\DS				04/10/2018		Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\DAMAGE	Repairs					04/10/2018		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job					04/10/2018		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\CHN/RUR/MN	call out to high cube for chain broke found chain broke/lock worn and broken away from ram/and chain cog missing found parts of bearing but no cog case					20/09/2018		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS				13/09/2018	958553	Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job					13/09/2018	958553	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Workshop\MOVE ASSET	Move Assets					13/09/2018		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Workshop\MOVE ASSET	drop trailer at Aldonga					18/08/2018		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\ELECT P&W	no reverse					08/08/2018		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\DOOR LOCK	1 floor lock not operating					08/08/2018		Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\AIR LEAK	Air leaks					08/08/2018		Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		bearing inspection			03/08/2018	930118	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Chassis\FIFTH WHEE	skid plate bowed		replaced by Aldonga			03/08/2018	930118	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	small holes in LH curtains		repaired earlier			03/08/2018	930118	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	hole's and reflective stiping u/s		#182191			03/08/2018	930118	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	DrvLine\WHEEL BRGS	Replace wheel bearings		all bearings replaced and repacked			03/08/2018	930118	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL LEGS	legs are u/s bent		couple, park and split trailers			03/08/2018	930118	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\ELECT P&W	no reverse					03/08/2018	930118	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\MOUNTS	Fill in rope rail on looseneck					03/08/2018	930118	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\DOOR LOCK	1 floor lock not operating		repaired earlier			03/08/2018	930118	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\AIR LEAK	Air leaks		booster hoses tightened RHR & LHM airbags replaced mez deck not strapped down LHF mez deck lock not engaged			03/08/2018	930118	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	RHF mez deck lock box comine asart			03/08/2018	930118	Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\TRL LIGHTS	Job Added From Invoice					13/07/2018	0	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice					07/07/2018	906909	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice					07/07/2018	906909	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job					05/07/2018	906909	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS				05/07/2018	906909	Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\DRV TYRES	check tyre wear					05/07/2018	906909	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\DRV TYRES	check tyre wear					05/07/2018	906909	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\DRV TYRES	possibly replace 2 tyres		l/front replaced replaced l/hand indicator and repiared			05/07/2018	906909	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\ELECT P&W	electrical wiring for side lights broken and hanging down		all darnaged wirine			05/07/2018	906909	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\AIR LEAK	air leaks					05/07/2018	906909	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\DRV TYRES	check tyre wear		as per #171631			31/05/2018	878136	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job					31/05/2018	878136	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\ELECT P&W	no reverse No lights working on trailers 569 - 570					31/05/2018	878136	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\TRL LIGHTS	(indicator & brake lights working)					31/05/2018	878136	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\DRV TYRES	check tyre wear		as per #171631			31/05/2018	878136	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\ELECT P&W	reattach base light plug					31/05/2018	878136	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\AIR LEAK	locate and fix airleaks		checked ok			31/05/2018	878136	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\AIR LEAK	fix air leaks (bad)		previously done			31/05/2018	878136	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\DRV TYRES	possibly replace 2 tyres		l/front tyres next service			31/05/2018	878136	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\ELECT P&W	reattach base light plug					31/05/2018	878136	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\AIR LEAK	locate and fix air leaks		previously done			31/05/2018	878136	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\AIR LEAK	fix air leaks (bad)		previously done			31/05/2018	878136	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\AIR LEAK	fix air leaks		previously done			31/05/2018	878136	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\ELECT P&W	mez floor power box only showing 1 of 4 charge lights		previously done			31/05/2018	878136	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS				31/05/2018	878136	Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService\DS	service sticker says 12/3	VehService\DS	not any more - 30-5			31/05/2018	878136	Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice					26/05/2018	872391	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice					26/05/2018	872391	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\AIR LEAK	fix air leaks					23/05/2018		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\DRV TYRES	replace 2 tyres					23/05/2018		Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\ELECT P&W	mez floor power box only showing 1 of 4 charge lights					23/05/2018	878136	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService\DS	service sticker says 13/3	VehService\DS				23/05/2018		Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Susp\AIR BAG	replace LHR and LHF airbags					17/05/2018	888568	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\AIR LEAK	air leak inspection - LH-R & LHF 30K bags leaking - loaded with blue slip pallets					17/05/2018		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\AIR LEAK	fix air leaks (bad)					17/05/2018		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\DRV TYRES	possibly replace 2 tyres					17/05/2018		Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres	Job Added From Invoice					15/05/2018	860853	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice					15/05/2018	860853	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\DRV TYRES	check tyre wear					09/05/2018		Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\ELECT P&W	reattach base light plug					09/05/2018		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\AIR LEAK	locate and fix air leaks					09/05/2018		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\DRV TYRES	check tyre wear					27/03/2018		Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\BATTERY	Job Added From Invoice					21/03/2018	0	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Chassis\CHAS CRACK	repair cracks in goose neck		also front right wall to deck crack			15/03/2018	817922	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\TRL LIGHTS	replaced u/s lights and brackets					14/03/2018		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Workshop\CLEAN	clean w/shop					14/03/2018		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job					10/03/2018	817922	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Chassis\DIFF OIL	needs 1 straps on back passenger side of B Trailer		previously done			10/03/2018	817922	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\BATTERY	battery indicator lights showing low		previously done			10/03/2018	817922	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\RWC COMP	rego runs out next week		previously done			10/03/2018	817922	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes\AIR LEAK	possible air leak rego due					10/03/2018	817922	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\RWC COMP	service sticker showine 12/2017		oreviously done			10/03/2018	817922	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\DRV TYRES	check tyre wear		previously done			10/03/2018	817922	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS				10/03/2018	817922	Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\TRL LIGHTS	only 2 indicator lights out of 4 working on battery display		inspected deck found lock valve to be faulty changed then ran deck ok now changed batteries and replaced clearance lights			10/03/2018	817922	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP				10/03/2018	817922	PreventativeMaintenance	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	hole's and reflective stiping u/s					10/03/2018	817922	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	DrvLine\WHEEL BRGS	needs full inspection u/s					10/03/2018	817922	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL LEGS	legs are u/s bent					10/03/2018	817922	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL FLOOR	mexx deck repairs					10/03/2018	817922	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	curtain repairs					08/03/2018		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\RUN OUT	Job Added From Invoice					05/02/2018	809296	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice					23/02/2018	797819	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice					23/02/2018	797819	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL FLOOR	repair flogged out lock holes					17/01/2018		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\HOUSEKEEP	access repair on deck locks					14/01/2018	771982	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL LEGS	replaced foot					21/12/2017		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Susp\HCV	A trailer needs height control checked					21/12/2017		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		completed during service			18/12/2017	754738	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS				18/12/2017	754738	Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\ELECT P&W	no reverse					18/12/2017	754738	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	DrvLine\WHEEL BRGS	adjust right front wheel bearings					18/12/2017	754738	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Engine\BATTERY	replace batteries for mez deck motor		replaced batteries under high cube			16/11/2017	728912	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Workshop\MOVE ASSET	moving trailers					16/11/2017	728912	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\DAMAGE	rivet curtain to pole		RHR pole			02/11/2017	717475	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job					28/10/2017	714609	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS				28/10/2017	714609	Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	small holes in LH curtains fix little holse in curtains		more to be done			27/10/2017	714609	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	(product aot water damaee)					27/10/2017	714609	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\PRES CHECK	Job Added From Invoice					05/10/2017	697191	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\RUN OUT	Job Added From Invoice					05/10/2017	697191	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Workshop\CLEAN	clean up after job					29/09/2017		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS				28/09/2017		Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\ELECT P&W	UHF top light u/s		replace 2x side markers and top left light found and repaired 2x breaks and faulty clutch plug sign off paperwork			28/09/2017		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\ELECT P&W	LM clearance light is out/L top light is out		oreanize oaerwork for man07/08			28/09/2017		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\MUDGUARDS	L and R mudflaps need to be changed					28/09/2017		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	small holes in LH curtains		spoke to George on what parts required to complete job. Spoke to paul where we get the patch rolls from Barry said he will organize inspected			28/09/2017		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\ELECT P&W	LH-F top clearance & LH-side clearance u/s		completed areviously			28/09/2017		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	holes		refer to job nbumber 12BB44 inspected			28/09/2017		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\DAMAGE	RM tyre is bald		completed areviously			28/09/2017		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\ELECT P&W	LR blinker out/FL top light is out		inspected, completed previously			28/09/2017		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\MUDGUARDS	LF RF mudflaps u/s					28/09/2017		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\MOUNTS	angle storage compartment to be fitted		had to remove first fitted one and fit smaller one			28/09/2017		Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	new curtain buckles needed		fitted new buckles where required			28/09/2017		Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL FLOOR	check mezdec locks, repair as required		need to rewire deck			28/09/2017		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Chassis\FIFTH WHEE	skid plate bowed					28/09/2017		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job					28/09/2017		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\BREAKDOWN	Breakdown					20/09/2017		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice					03/08/2017	0	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice					03/08/2017	0	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Chassis\TRL LEGS	replace damaged landing legs remove legs and straighten bent leg mounts					23/07/2017		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL LEGS	cut both lees off due to bent mount brackets attemot to bent brackets straight					22/07/2017	655564	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres	Job Added From Invoice					20/07/2017	651164	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\RUN OUT	Job Added From Invoice					20/07/2017	651164	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL LEGS	pot feet

T570	Wodonga - Workshop	Body\MUDGUARDS	LF RF mudflaps u/s						16/07/2017	651154	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL LEGS	trailer leg doesn't have a plate at the bottom						13/07/2017	651154	Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres	Job Added From Invoice						23/06/2017	0	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\PRES CHECK	Job Added From Invoice						23/06/2017	0	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice						23/06/2017	0	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job						01/06/2017	638662	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService\JDS	D Service As Per Attached Checklist	VehService\JDS					01/06/2017	638662	Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\ELECT P&W	LH-F top clearance & LH-side clearance u/s						01/06/2017	638662	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	holes						01/06/2017	638662	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	DrivLine\WHEEL SEAL	bearing adjustments						01/06/2017	638662	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Chassis\CHAS CRACK	inspect above skid plate cracks u/s						01/06/2017	638662	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL LEGS	legs need replacing u/s						01/06/2017	638662	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL LEGS	R hand foot is missing and bar is bent						01/06/2017		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres	Job Added From Invoice						29/04/2017	609523	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job						25/04/2017	609522	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\ELECT P&W	LHF top light u/s			to be done with leg repairs also LH-M rear side marker			25/04/2017	609522	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	DrivLine\WHEEL BRGS	bearing adjustments						25/04/2017	609522	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService\JDS	D Service As Per Attached Checklist	VehService\JDS	moving trailers				25/04/2017	609522	Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\ELECT P&W	LM clearance light is out/L top light is out						25/04/2017	609522	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\MUDGUARDS	L and R mudflaps need to be changed						25/04/2017	609522	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	small holes in LH curtains						25/04/2017	609522	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL LEGS	R hand foot is missing and bar is bent						25/04/2017	609522	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\CHN/RLR/MN	weld brackets to angle compartments and paint						06/04/2017		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Chassis\HOUSEKEEP	measure chassis for angle storage compartment						30/03/2017		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\TP11	Job Added From Invoice						24/02/2017	567443	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Susp\AIR BAG	repairs as required for Uncle Toby's						22/02/2017		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job						21/02/2017		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body	curtains at drop u/s		previously done				21/02/2017		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body	fix curtain tears on gooseneck		previously done				21/02/2017		Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService\JDS	D Service As Per Attached Checklist	VehService\JDS	cleaned workshop				21/02/2017		Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\ELECT P&W	LHF top light u/s						21/02/2017		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	DrivLine\WHEEL BRGS	bearing adjustments						21/02/2017		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	DrivLine\KING PIN	cracks under skid plate						21/02/2017		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL FLOOR	move repairs						21/02/2017		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL FLOOR	repaired mezz floor						21/02/2017		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\BREAKDOWN	mez floor lock faulty		Vawdrey Brisbain repaired				11/02/2017		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Insp\RWC COMP	rego stickers on trailer						08/02/2017		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\TP11	Job Added From Invoice						07/02/2017	554566	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService\JDS	service	VehService\JDS					18/01/2017	545718	Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Insp\ANN INSP	perform annual inspection						18/01/2017	545718	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL FLOOR	mezine floor not working go to up and cuts out		Hi cube trailer (install g/box and chain link)				17/01/2017		Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL FLOOR	Job Added From Invoice						17/01/2017	0	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL FLOOR	Job Added From Invoice						13/01/2017	0	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
			organise b/down																
T570	Wodonga - Workshop	Body\TRL FLOOR	mez deck floor chain unaosed						12/01/2017		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Workshop\MOVE ASSET	to come back + swap trailers						12/01/2017		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Susp\SUSPENSION	bushes u/s		HTT repaired				23/12/2016		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\ELECT P&W	top RHR light not working						23/12/2016		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	ripped on RHL next to legs						23/12/2016		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Susp\SHOCK ABS	RHM shocky mount cracked u/s						23/12/2016		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body	curtains at drop u/s						23/12/2016		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Chassis\CHAS CRACK	cracks around LHR upright u/s						21/12/2016		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\HEAD LIGHT	RH foot bent u/s						21/12/2016		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect	LHB clean lights/nose cone top left light						21/12/2016		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body	repair tears in curtains						21/12/2016		Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body	fix tears in curtain where they hook in middle						21/12/2016		Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body	fix curtain tears on gooseneck						21/12/2016		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\TP14	Job Added From Invoice						17/12/2016	533871	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService\JDS	D Service As Per Attached Checklist	VehService\JDS					15/12/2016		Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job						15/12/2016		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\ELECT P&W	top RHR light not working						15/12/2016		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	ripped on RHL next to legs						15/12/2016		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Susp\AXLES	bushes u/s						15/12/2016		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Susp\SHOCK ABS	RHM shocky mount cracked u/s						15/12/2016		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\TP13	Job Added From Invoice						09/12/2016	525172	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\TP15	Job Added From Invoice						09/12/2016	525172	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\TP19	Job Added From Invoice						09/12/2016	525172	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\TP12	Job Added From Invoice						29/11/2016	519316	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL FLOOR	Change gear box on mez floor						29/11/2016		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL FLOOR	Remove 2x gearboxes out of old mez floors and make up 1x ok one						29/11/2016		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\TRL LIGHTS	Job Added From Invoice						16/11/2016	0	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Chassis\WINCH/STRP	Job Added From Invoice						12/11/2016	0	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect	LHB clean lights/nose cone top left light						10/11/2016		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService\JDS	D Service As Per Attached Checklist	VehService\JDS					10/11/2016		Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job						10/11/2016		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\MUDGUARDS	mudflaps u/s		replace 2x rear mudflaps				10/11/2016		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService	Service due						10/11/2016		Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Brakes hanging on / dragging after application - foot or handpiece						10/11/2016		Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\TP15	Job Added From Invoice						01/10/2016	474552	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	Job Added From Invoice						28/09/2016	0	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\TP11	Job Added From Invoice						26/09/2016	433484	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\TP15	Job Added From Invoice						26/09/2016	433484	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body	mez deck wont go up further than 1 foot						19/09/2016		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\TP11	Job Added From Invoice						17/09/2016	0	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job						15/09/2016		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService\JDS	D Service As Per Attached Checklist	VehService\JDS					15/09/2016		Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\MUDGUARDS	mudflaps u/s						15/09/2016		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body	curtains at drop u/s						15/09/2016		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Chassis\CHAS CRACK	cracks around LHR upright u/s						15/09/2016		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\HEAD LIGHT	RH foot bent u/s						15/09/2016		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\BATTERY	Job Added From Invoice						23/08/2016	0	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL REPS	Job Added From Invoice						09/08/2016	0	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\TP11	Job Added From Invoice						30/07/2016	421901	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL FLOOR	inspect floor battery voltage and charge		replaced battery's x2				28/07/2016		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body	loaded						28/07/2016		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job						07/07/2016		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService	service due						07/07/2016		Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService\JDS	D Service As Per Attached Checklist	VehService\JDS	major electrical issue, rewired front of trailer				07/07/2016		Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body	loaded						07/07/2016		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\TP21	Job Added From Invoice						17/06/2016	384154	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\TP21	Job Added From Invoice						17/06/2016	0	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\TP14	Job Added From Invoice						17/06/2016	384154	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\TRL LIGHTS	no trailer lights						14/06/2016		Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job						22/05/2016		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\BATTERY	battery indicator showing low voltage when in use						22/05/2016		Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService\JDS	D Service As Per Attached Checklist	VehService\JDS					22/05/2016		Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL FLOOR	locks not releasing on mez floor		inspected fuse and air supply found nothing wrong. Bushed locks				15/04/2016		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job						09/04/2016		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService\JDS	D Service As Per Attached Checklist	VehService\JDS					09/04/2016		Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\BATTERY	battery indicator showing low voltage when in use						09/04/2016		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
			rear deck motor would not go down only under own weight																
			replaced female base plug for rear deck found the problem to be the motor																
T570	Wodonga - Workshop	Elect\ELECT P&W	replaced motor but controls are back to front the motor that's in there now needs to be sent off to be checked old motor needs to be sent for rebuild						10/03/2016		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job						09/03/2016		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService\JDS	D Service As Per Attached Checklist	VehService\JDS					09/03/2016		Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Susp\WGHT GAUGE	calibrate weight gauge						01/03/2016		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\TP19	Job Added From Invoice						18/02/2016	337855	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\TP19	Job Added From Invoice						18/02/2016	0	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\TP14	Job Added From Invoice						18/02/2016	337855	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\TP14	Job Added From Invoice						18/02/2016	337855	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Tyres\TP11	Job Added From Invoice						18/02/2016	337855	Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Insp\ANN INSP	roadworthy						18/02/2016		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect\ELECT P&W	greased all mez decks and replaced 3x micro switchers and adjusted sensor lights for locking pins						17/02/2016		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Comp	needs NHVAS sticker		sticker put on				09/02/2016		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Susp\WGHT GAUGE	calibrate weight gauge						09/02/2016		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Susp\WGHT GAUGE	calibrate weight gauge						09/02/2016		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Comp	needs NHVAS sticker						09/02/2016		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job						09/02/2016		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService\JDS	D Service As Per Attached Checklist	VehService\JDS					09/02/2016		Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\ELECT P&W	bell deck wiring problem						02/02/2016		Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Elect	middle mez deck wiring needs fixing						11/01/2016		Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body	replace bolts and nuts holding wire in place RH front pole		replaced bolts and nuts				08/01/2016		Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body\TRL LEGS	needs foot base		previously done				01/01/2016		Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Body	Ripped curtain goose neck		repaired curtain				13/10/2015		Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	VehService\JDS	D Service As Per Attached Checklist	VehService\JDS					07/10/2015		Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job						07/10/2015		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	Wodonga Workshop	TRAILER
T570	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job						26/03/2009		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	O'BRIEN GLASS INDUSTRIES LTD	TRAILER
T570	Wodonga - Workshop	Tyres\DRV TYRES	RHM i						26/03/2009		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	O'BRIEN GLASS INDUSTRIES LTD	TRAILER
T570	Wodonga - Workshop	Chassis\MUDGUARDS	front mudflaps, missing or u/s						26/03/2009		Repair	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	O'BRIEN GLASS INDUSTRIES LTD	TRAILER
T570	Wodonga - Workshop	Tyres\DRV TYRES	some tyres on "B" need replacing						26/03/2009		Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	O'BRIEN GLASS INDUSTRIES LTD	TRAILER
T570	Wodonga - Workshop	Elect\TRL LIGHTS	no clearance lights on "B"						26/03/2009		Fault	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	O'BRIEN GLASS INDUSTRIES LTD	TRAILER
T570	Wodonga - Workshop	VehService\JDS	D Service As Per Attached Checklist	VehService\JDS					26/03/2009		Service	Completed	FL Green Distribution	Tilmer	Wodonga	HCU	949185	O'BRIEN GLASS INDUSTRIES LTD	TRAILER