EquipmentName	Workshop	CodeAndSubCode	Description	Schedule	CompletionComments	DateDone	DistanceDone	Worktype	Workstate	EquipmentOwner	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
TSS4	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		05/08/2026	877716	Service	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Insp\ANN INSP	Insp\ANN INSP	Insp\ANN INSP		05/08/2026	877716	PreventativeMaintenance	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL FLOOR	Move deck to hight			05/08/2026	877716	Repair	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Tyres\Punct	Tyres\Punct POS 27			28/02/2026	877716	Repair	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	BORDER BANDAG PTY LTD	TRAILER
TSS4	Wodonga - Workshop	Elect\HOUSEKEEP	Elect\HOUSEKEEP REPLACE TRAILER PLUG			30/07/2025	877716	Repair	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL FLOOR	Body\TRL FLOOR CHECK MEZ FLOOR WORKS			30/07/2025	877716	Repair	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		30/07/2025	877716	Service	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		24/06/2025	877716	Service	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		21/05/2025	877716	Service	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
					10 Repairs to drivers side 250 inches re-weld section of curtain on drivers side Black tip buckle & INSTALL bottom strap supply & INSTALL 2 Repairs to passenger side 60 inches											
TSS4	Wodonga - Workshop	Body\TRL REPS	Body\TRL REPS			28/04/2025	877716	Repair	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	IFIX TRUCK CURTAINS	TRAILER
TSS4	Wodonga - Workshop	Body\TRL REPS	drivers side curtain damaged at last buckle on drop first roller on drop catching		Pending	07/04/2025	877716	Fault	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		07/04/2025	877716	Service	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL REPS	Body\TRL REPS Passenger side curtain jamming up		Pending,,,, Inspected - Driver organized for trailers to be cross loaded to another set.	07/04/2025	877716	Repair	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL REPS	LHS curtain roller 2/3 towards back has X1 roller trying to fall through track and keeps getting jammed		To be repaired still	05/04/2025	877716	Fault	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL REPS	Repair left rear roller strap on curtain.			26/02/2025	877716	Fault	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Tyres\TP1+2	Tyres\TP1+2			17/02/2025	877716	Repair	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	BEAUREPAIRES	TRAILER
TSS4	Wodonga - Workshop	Tyres\TP11+12	Tyres\TP11+12			17/02/2025	877716	Repair	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	BEAUREPAIRES	TRAILER
TSS4	Wodonga - Workshop	Tyres\Punct	Tyres\Punct 5			17/02/2025	877716	Repair	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	BEAUREPAIRES	TRAILER
TSS4	Wodonga - Workshop	Tyres\TP9+10	Tyres\TP9+10			17/02/2025	877716	Repair	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	BEAUREPAIRES	TRAILER
TSS4	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		07/02/2025	877716	Service	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL REPS	Both curtains need repairs and are catching on the tracks			07/02/2025	877716	Fault	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		09/12/2024	877716	Service	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL FLOOR	Check & Repair Mez-Deck Floor.		Checked & Tested Mez-Deck Floor, Adjusted Chain & Fine Tuned For Correct Operation.	25/10/2024	877716	Repair	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection	Insp\ANN INSP		01/10/2024	877716	PreventativeMaintenance	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	VehService\DS	D Service	VehService\DS		01/10/2024	877716	Service	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL REPS	Repair Damage From Accident			01/10/2024	877716	Repair	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\MUDGUARDS	Replace both rear mudflaps.			25/07/2024	877716	Fault	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			25/04/2024	690891	Repair	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL REPS	ROOF RUBBER WAS HIT BY FORKLIFT DRIVER AND HAS BEEN STRETCHED/ PULLED OUT A BIT.			25/04/2024	690891	Fault	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\AIR LEAK	POSSIBLE AIR LEAK.			25/04/2024	690891	Fault	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		25/04/2024	690891	Service	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Unknown	SERVICE.			25/04/2024	690891	Fault	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Comp\Truck Safe	FIT TRUCKSAFE AND NHVAS STICKERS.			25/04/2024	690891	Repair	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Unknown	SERVICE.			25/04/2024	690891	Fault	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		10/04/2024	877716	Service	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			10/04/2024	877716	Repair	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Elect\TAIL LIGHT	no reverse lights			10/04/2024	877716	Repair	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Elect\INDICATORS	RIGHT FLASHER NOT WORKING.			10/04/2024	877716	Fault	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Comp\Truck Safe	NHVR sticker needs to be replaced			23/03/2024		Repair	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL FLOOR	FLOORS NOT WORKING.			23/03/2024		Fault	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			21/03/2024		Repair	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Elect\TAIL LIGHT	no reverse lights			21/03/2024		Repair	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Elect\INDICATORS	RIGHT FLASHER NOT WORKING.			21/03/2024		Repair	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		21/03/2024		Service	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			29/02/2024	690891	Repair	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		29/02/2024	690891	Service	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			08/02/2024	690891	Repair	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Comp\Truck Safe	NHVR sticker needs to be replaced			08/02/2024	690891	Repair	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Elect\INDICATORS	RIGHT FLASHER NOT WORKING.			08/02/2024	690891	Repair	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL FLOOR	FLOORS NOT WORKING.			08/02/2024	690891	Repair	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL REPS	ROOF RUBBER WAS HIT BY FORKLIFT DRIVER AND HAS BEEN STRETCHED/ PULLED OUT A BIT.			08/02/2024	690891	Repair	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		08/02/2024	690891	Service	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Elect\TAIL LIGHT	no reverse lights			08/02/2024	690891	Repair	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Comp\Truck Safe	NHVR sticker needs to be replaced			08/02/2024		Repair	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Elect\INDICATORS	RIGHT FLASHER NOT WORKING.			08/02/2024		Repair	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL FLOOR	FLOORS NOT WORKING.			08/02/2024		Repair	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL REPS	ROOF RUBBER WAS HIT BY FORKLIFT DRIVER AND HAS BEEN STRETCHED/ PULLED OUT A BIT.			08/02/2024		Repair	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			03/01/2024	690891	Repair	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Elect\INDICATORS	RIGHT FLASHER NOT WORKING.			03/01/2024	690891	Repair	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	VehService	service			03/01/2024	690891	Fault	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		03/01/2024	690891	Service	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Unknown	SERVICE.			03/01/2024	690891	Fault	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Unknown	SERVICE.			03/01/2024	690891	Fault	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL FLOOR	No Power To Solenoid To Make The Hooks Release To Move Floor Down			30/11/2023		Fault	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL FLOOR	Inspect operation of Mezzanine Deck			12/10/2023		Repair	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Albury Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			24/08/2023	99891	Repair	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Elect\TRL LIGHTS	NEEDS NEW FEMALE PLUG OR JUST CAP. SPRING IS BROKEN AND WON'T LATCH ONTO MALE PLUG.		replaced female plug	24/08/2023	99891	Fault	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Elect\TRL LIGHTS	NEED NEW FEMALE PLUG ON FRONT OF B.			24/08/2023	99891	Fault	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		24/08/2023	99891	Service	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP		24/08/2023	99891	PreventativeMaintenance	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Unknown	SERVICE.			24/08/2023	99891	Fault	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Comp\Truck Safe	NHVR sticker needs to be replaced			24/08/2023	99891	Repair	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Unknown	SERVICE.			24/08/2023	99891	Fault	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Tyres\TP3+4	Tyre Position 3 + 4			07/06/2023		Repair	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Albury Workshop	TRAILER
TSS4	Wodonga - Workshop	Tyres\TP7+8	Tyre Position 7 + 8			07/06/2023		Repair	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Albury Workshop	TRAILER
TSS4	Wodonga - Workshop	Tyres\TP5+6	Tyre Position 5 + 6			11/05/2023		Repair	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Albury Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			03/03/2023	699891	Repair	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		03/03/2023	699891	Service	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes\EBS FAULTS	ABS FAULT IN TRAILER.			05/01/2023		Fault	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Comp\Truck Safe	No Sticker, one needs to be ordered.			05/01/2023		Repair	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL FLOOR	RF CRACKED			05/01/2023		Repair	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\DAMAGE	REAR BAR DAMAGED.			05/01/2023		Repair	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TOOLBOX	TOOLBOXES REQUIRED			05/01/2023		Fault	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TOOLBOX	TOOL BOXES FOR STRAPS AND RATCHETS.			05/01/2023		Fault	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\ELECT P&W	MEZZ FLOOR BATTERY CHARGE SYSTEM NOT WORKING.			05/01/2023		Fault	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Elect\INDICATORS	LHS MIDDLE INDICATOR HANGING LOOSE.		REPAIRED INDICATOR,CLEARANCE LIGHT AND STOP/TAIL LIGHT.	05/01/2023		Fault	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes\EBS FAULTS	ABS NOT WORKING.			05/01/2023		Fault	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes\EBS FAULTS	ABS NOT WORKING.			05/01/2023		Fault	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL REPS	RHS CURTAIN HAS A TEAR.			05/01/2023		Fault	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes\ABS	ABS NOT WORKING.			05/01/2023		Fault	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\STRAPS	OVER TENSIONED BUCKLES.(7)			05/01/2023		Fault	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\MUDGUARDS	RHS REAR MUDGUARD LOOSE.			05/01/2023		Fault	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
			MEZZ FLOOR LOCKS NOT RETRACTING. Purchase Order Number: WW076049 Total Tools Purchase Order Number: WW076116 Ultimate Fasteners Purchase Order Number: WW076236 Steel Supplies Albury Wodonga Purchase Order Number: WW076236 Ultimate Fasteners Purchase Order Number: WW076276 Ultimate Fasteners Air Cylinders Rapid Hydraulics Supplied P/O: WW076333											
TSS4	Wodonga - Workshop	Body\TRL FLOOR	Mezdeck Floor Locks Vawdrey P/O: WW076525. MEZZ FLOOR LOCKS NOT RETRACTING.			05/01/2023		Fault	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes\EBS FAULTS	ABS NOT WORKING. TOOLBOXES NEEDED, BIGGER ANGLE RACK. 40x40x2mm SHS, 50x5mm Flat Bar, 30x3mm Flat Bar, 100mm C Channel Don Sparks Steel Supplies			05/01/2023		Fault	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TOOLBOX	Purchase Order Number: WW076400. TOOLBOXES NEEDED. BIGGER ANGLE RACK.		MADE AND FITTED ANGLE RACKS.	05/01/2023		Fault	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\DAMAGE	PLASTIC CHAIN GUIDING MEZZ FLOOR AIR NEEDS REPAIR.			05/01/2023		Fault	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL WALL	CRACKS ON COMBING NEAR HEADBOARD.			05/01/2023		Fault	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	DrivLine\WHL HUB	HUB ODOMETRE NOT WORKING.			05/01/2023		Fault	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	DrivLine\WHL HUB	HUB ODOMETRE NOT WORKING.			05/01/2023		Fault	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\DAMAGE	PLASTIC CHAIN PROTECTING MEZZ FLOOR AIR LINES DAMAGED.			05/01/2023		Fault	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TOOLBOX	TOOLBOXES & BIGGER ANGLE RACK NEEDED.			05/01/2023		Fault	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL WALL	COMBING CRACKED NEAR HEADBOARD.			05/01/2023		Fault	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL FLOOR	RHS REAR ACTUATOR BROKEN.			05/01/2023		Fault	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\MUDGUARDS	RHS REAR MUDGUARD BRACE MISSING BOLT.			05/01/2023		Fault	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes\EBS FAULTS	TRAILER ABS?			05/01/2023		Fault	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL FLOOR	RHS REAR MEZZ FLOOR ACTUATOR BROKEN.			05/01/2023		Fault	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL FLOOR	MEZZ FLOOR PLASTIC CHAIN NEEDS REPAIR.			05/01/2023		Fault	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Elect\ELECT P&W	Charge circuit for Mezz floor not working.			05/01/2023		Fault	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Chassis\MUDGUARDS	RHS Rear mudguard missing a bolt.			05/01/2023		Fault	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL FLOOR	RHS Rear mezz floor actuators broken.			05/01/2023		Fault	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes\AIR LEAK	AIR LEAK UNDER TRAILER.			05/01/2023		Fault	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Unknown	SERVICE OVERDUE. MEZZ FLOOR NOT WORKING. Razor motor and controls replaced			05/01/2023		Fault	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL FLOOR	Parts Supplied by Vawdrey PO# WW076075. MEZZ FLOOR NOT WORKING.			05/01/2023		Fault	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			17/12/2022		Repair	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		17/12/2022		Service	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Insp\DEFECT	Upper end outline marker light inoperative as per Defect # HVN063940 3			17/12/2022		Repair	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Elect\ELECT P&W	TOP RHS CLEARANCE LIGHT NOT WORKING.		Refer Job # 398887	17/12/2022		Fault	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Elect\ELECT P&W	RHS TOP CLEARANCE LIGHT NOT WORKING.		Refer Job # 398887	17/12/2022		Fault	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Elect\ELECT P&W	TOP RHS REAR CLEARANCE LIGHT NOT WORKING.		Refer Job # 398887	17/12/2022		Fault	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\LIGHTS	R.H. rear top clearance not working		Refer Job # 398887	17/12/2022		Repair	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Elect\TRL LIGHTS	RHS Top rear clearance light not working.		Refer Job # 398887	17/12/2022		Repair	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Tyres\TP1+2	Tyre Position 1 + 2			03/12/2022		Repair	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Albury Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			13/11/2022	699890	Repair	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		13/11/2022	699890	Service	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			16/10/2022	699890	Repair	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		16/10/2022	699890	Service	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			02/10/2022	699890	Repair	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		02/10/2022	699890	Service	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes\BRAKE ADJ	ajust brakes		ADJUSTED BAKES AND CHECK OVER.	13/09/2022	899890	Repair	Completed	FL Green Distribution	TlnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Tyres

TSS4	Wodonga - Workshop	Tyres\TP11+12	Tyre Position 11 + 12			Travel to Greenfrieight Wodonga to check fault with trailer abs, plug scan tool into the trailer and got the codes out of the abs module. Found a lot of stored codes in the module, no new codes or recent codes. Disconnect	01/09/2022		Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes\ABS	*ABS fault on High Cube Trailer			the scan tool from the trailer. Advise to monitor.	29/08/2022		Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Chassis\CROSS MBR	CRACK IN LHS UNDERRUN BAR.			WELDED REAR BAR. REPAIRED RH CURTAIN POLE CHANNEL.	21/08/2022	699890	Fault	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Chassis\CROSS MBR	UNDERRUN BAR CRACKED AND BENT.				21/08/2022	699890	Fault	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\DAMAGE	REAR UNDER RUN BAR BROKEN.				21/08/2022	699890	Fault	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\DAMAGE	UNDER RUN PROTECTION BAR CRACKED.				21/08/2022	699890	Fault	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				21/08/2022	699890	Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\STRAPS	OVER TENSIONED BUCKLES.(7)				21/08/2022	699890	Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	DriveLine\WHL HUB	HUB ODOMETRE NOT WORKING.				21/08/2022	699890	Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	REPAIRED RH TAIL LIGHT.		21/08/2022	699890	Service	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TANK COMP	Tanker Wash Out for repair inspection. ATE PO# WW072941 -Cracking/ leaking above skid plate (welded on, restricted access) -Cracking/ leaking at rear bulkhead x 2 -Cracking/ leaking underside of chassis x 2 --Internal corroded from last product Repairs to be done by ATE				15/07/2022	877716	Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TANK PANEL	PO# WW074305				15/07/2022	877716	Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				03/07/2022	699890	Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			03/07/2022	699890	Service	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\DAMAGE	REAR BAR DAMAGED.				03/07/2022	699890	Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				29/05/2022	699890	Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			29/05/2022	699890	Service	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Tyres\TP01	Puncture repair				17/05/2022		Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Tyres\PRES CHECK	PUMPED UP TYRE.				16/05/2022		Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP			01/05/2022		PreventativeMaintenance	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				01/05/2022	699890	Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			01/05/2022	699890	Service	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	VehService\DS	Trailer Service overdue.	VehService\DS			01/05/2022	699890	Service	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Tyres\TP01	fit runout				27/04/2022		Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL WALL	CRACKS ON SIDE AT HEADBOARD			RELOADED STOCK ON TRAILER.	27/03/2022	699890	Fault	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Chassis\CHAS CRACK	CRACKS ON BOTH FRONT CORNERS OF GOOSENECK.				27/03/2022	699890	Fault	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL WALL	CRACKS ON BOTH SIDES NEAR HEADBOARD				27/03/2022	699890	Fault	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				13/03/2022	699890	Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	REPLACED RM AIRBAG.		13/03/2022	699890	Service	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				06/02/2022	699889	Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Susp\AIR BAG	RM AIR BAG PERISHED				06/02/2022	699889	Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	REPAIRED CLEARANCE LIGHTS TOP OF TRAILER AND LH INDICATOR		06/02/2022	699889	Service	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL FLOOR	RF CRACKED				06/02/2022	699889	Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Tyres\TP9+10	SUPPLY AND FIT 2TYRES				09/01/2022	699889	Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				09/01/2022	699889	Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Tyres	LF RR TYRES WORN.				09/01/2022	699889	Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Elect\TRL LIGHTS	RR TOP CLEARANCE LIGHT OUT				09/01/2022	699889	Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			09/01/2022	699889	Service	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL REPS	REPLACED CURTAIN BUCKLE				23/12/2021	699887	Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes\AIR LEAK	REPAIRED AIRLEAKS.				23/11/2021		Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				21/11/2021	699689	Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	PARK.		21/11/2021	699689	Service	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Tyres	LF RR TYRES WORN.				21/11/2021	699689	Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Elect\TRL LIGHTS	RR TOP CLEARANCE LIGHT OUT				21/11/2021	699689	Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Susp\AIR BAG	RM AIR BAG PERISHED				21/11/2021	699689	Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Tyres\TP7+8	supply and fit 2 tyres				28/10/2021	699889	Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Tyres\TP3+4	supply and fit 3 tyres				17/10/2021	699889	Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Tyres\TP08	Tyre Position 8				17/10/2021	699889	Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job RHS Top rear clearance light not working.(P) RHS Middle clearance light not working.(C) LHS Rear on Goosenek light not working.(C). RHS Top rear clearance light not working. RHS Middle clearance light not working.				17/10/2021	699889	Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Elect\TRL LIGHTS	LHS Rear on Goosenek light not workine.				17/10/2021	699889	Fault	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL FLOOR	Mezz floor chains need adjusting			Adjusted chains.	17/10/2021	699889	Fault	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			17/10/2021	699889	Service	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	VehService\DS	Service Due	VehService\DS	Refer Job# 357436		17/10/2021	699889	Service	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Tyres\FITMENT	RF, RR has worn.				17/10/2021	699889	Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	DriveLine\WHEEL BRGS	LR, RR, RF has been adjusted.				17/10/2021	699889	Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Elect\TRL LIGHTS	Fabricate and fit/weld right side clearance light bracket.				17/10/2021	699889	Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Workshop\CLEAN	Clean up floor before service start and pick up trailers from the yard.				17/10/2021	699889	Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				04/09/2021	699889	Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\LIGHTS	R.H. rear top clearance not working				04/09/2021	699889	Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes\ABS	ABS Not Working				04/09/2021	699889	Fault	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes\ABS	ABS not working.				04/09/2021	699889	Fault	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes\ABS	ABS Not working.				04/09/2021	699889	Fault	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Elect\TRL LIGHTS	Top right hand side clearance light not working.				04/09/2021	699889	Fault	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Elect\TRL LIGHTS	Right top clearance light not working.				04/09/2021	699889	Fault	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Elect\TRL LIGHTS	RHS top clearance light not working.				04/09/2021	699889	Fault	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist No Brakes Directed to Yawdrey Dandenong. Invoice # R42147	VehService\DS		Conduct air test.	04/09/2021	699889	Service	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes\BREAKDOWN	PO# WW066476			Adjusted Brakes Inspect trailer for air leak.None found. Adjusted ride height on trailer, took combination to freight shed to confirm height of trailers 4540 mm on both A + B Drive height to top of A trailer 4590 mm.	21/08/2021		Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Susp\AIR LEAK	Air leaks.			Includes smoko.	05/08/2021	699889	Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job Under run protection bar cracked and bent. Both Sides.				01/08/2021	699889	Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Chassis\DAMAGE	Also right side curtain pole turrent/channel. Under run protection bar cracked and bent. Both Sides.				01/08/2021	699889	Fault	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Chassis\HOUSEKEEP	Under run bar has crack in it.			Refer Job# 348433	01/08/2021	699889	Fault	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			01/08/2021	699889	Service	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Unknown	Service due			Refer Job# 348431	01/08/2021	699889	Fault	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Chassis\DAMAGE	Under run bar damaged.			Refer Job# 348433	01/08/2021	699889	Fault	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Comp\Truck Safe	No Sticker, one needs to be ordered.				01/08/2021	699889	Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	DriveLine\WHEEL BRGS	Adjusted front left bearing.				01/08/2021	699889	Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	VehService\DS	D Service overdue.	VehService\DS	Refer Job# 348431 G&S Diesel to carry out repair		01/08/2021	699889	Service	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL WALL	repair damage to rear upright for curtain pole after being damged while going into loading dock			BENT REAR R/H SIDE CHANNEL OF BODY TO ACCESS CURTAIN POLE CHECKED OPERATION OF CURTAIN POLE - OK	29/07/2021		Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Susp\AIR LEAK	Repairs to damaged airhose				28/07/2021		Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				27/06/2021	699889	Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\LIGHTS	R.H. rear top clearance not working				27/06/2021	699889	Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			27/06/2021	699889	Service	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Tyres\TP7+8	Supply and fit 2 tyres				11/06/2021	699889	Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				08/05/2021	699889	Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			08/05/2021	699889	Service	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes\ABS	ABS Not Working			335846 Job no. related with this	08/05/2021	699889	Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes\ABS	ABS not working.				08/05/2021	699889	Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes\ABS	ABS Not working.				08/05/2021	699889	Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\LIGHTS	R.H. rear top clearance not working				08/05/2021	699889	Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Chassis\AIR LEAK	Air Leaks - takes 20 minutes to build up air.			Replaced air bag inspected for leaks. Move trailers and cleaned uo.	10/04/2021		Fault	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				28/03/2021		Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL WALL	Body Cracks			Inspected OK	28/03/2021		Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\AIR LEAK	check airleak from Lock Ram air leak from shaft base			Inspected OK	28/03/2021		Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body	Assess mez deck issue			Locks Worn motor needs updating to new motor when Mezz Floor Stops working	28/03/2021		Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL REPS	oth curtains need attention and buckles			Ongoing issue	28/03/2021		Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL FLOOR	multiple cracks through out trailer and mezz deck needs attention			Inspected OK	28/03/2021		Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL FLOOR	REAR LEFT LOCK ON MEZZ FLOOR LEAKING AIR			Inspected OK	28/03/2021		Fault	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes\ABS	ABS Not Working				28/03/2021		Fault	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\HOUSEKEEP	Service Tag out of date				28/03/2021		Fault	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			28/03/2021		Service	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP			28/03/2021		PreventativeMaintenance	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Workshop\MOVE ASSET	moving trailers				28/03/2021		Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				27/02/2021	699889	Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			27/02/2021	699889	Service	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\PAINT/REST	trailer refurbishment				11/02/2021	699889	Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL REPS	Rips & holes in curtains			completed during refurb	11/02/2021	699889	Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL FLOOR	inspect mez deck for operation				05/01/2021	699889	Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL FLOOR	temp mez deck repairs				05/01/2021	699889	Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Workshop\CLEAN	clean up from job move fork				05/01/2021	699889	Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Workshop\CLEAN	sort out paperwork and clean up from day				05/01/2021	699889	Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP			20/12/2020	699899	PreventativeMaintenance	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job Bulk head air leaks				20/12/2020	699899	Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\AIR LEAK	Suzi coil tass			oreviouslv done	20/12/2020	699899	Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				20/12/2020	699899	Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL WALL	Body Cracks				20/12/2020	699899	Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\AIR LEAK	check airleak from Lock Ram air leak from shaft base				20/12/2020	699899	Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL REPS	rear bar uprights cracked				20/12/2020	699899	Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body	Assess mez deck issue				20/12/2020	699899	Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Elect\INDICATORS	Right indicator faulty			replaced right and left	20/12/2020	699899	Fault	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Elect\TRL LIGHTS	front clearance light mount broken			previously done	20/12/2020	699899	Fault	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL FLOOR	REAR LEFT LOCK ON MEZZ FLOOR LEAKING AIR				20/12/2020	699899	Repair	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Elect\TRL LIGHTS	LHS FRONT CLEARANCE LIGHT BROKEN			previously done	20/12/2020	699899	Fault	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL REPS	2 rear drivers side buckles need replacing			previously done	20/12/2020	699899	Fault	Completed	FL Green Distribution	TlinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER

			buckles need replacing middle flap															
TSS4	Wodonga - Workshop	Body\TRL REPS	riaht hand side front needs repair			previously done	20/12/2020	699899	Fault	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Body\TRL REPS	2 rear drivers side buckles need replacing			previously done	20/12/2020	699899	Fault	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			20/12/2020	699899	Service	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			20/12/2020	699899	Service	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Body\TRL REPS	both curtains need attention and buckles				20/12/2020	699899	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Body\TRL FLOOR	multiple cracks through out trailer and mezz deck needs attention				20/12/2020	699899	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
			trailer are due for service															
TSS4	Wodonga - Workshop	VehService\DS	last services 2/10/20	VehService\DS			20/12/2020	699899	Service	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Body	Assess mez deck issue			trailer needs to come back ASAP for mezz deck repairs	25/11/2020	699889	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attaced To This Job				22/11/2020	699889	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Body\TRL REPS	rear bar uprights cracked				22/11/2020	699889	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Chassis\WHEEL BRGS	adjusted FL				22/11/2020	699889	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	VehService\DS	Service	VehService\DS			22/11/2020	699889	Service	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Body	Reported to have excessive movement while travelling. Opened curtains and checked for any major issues. Found couple of small cracks, unable to v				10/10/2020	699888	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice				08/10/2020	599888	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice				08/10/2020	599888	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				03/10/2020	699888	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			03/10/2020	699888	Service	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
			buckles need replacing middle flap															
TSS4	Wodonga - Workshop	Body\TRL REPS	riaht hand side front needs repair				03/10/2020		Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	VehService\DS	overdue for service last done 23/7/20	VehService\DS			03/10/2020		Service	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Body\TRL REPS	replace curtain buckles				03/10/2020	699888	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Body\LIGHTS	fabricate clearance light bracket and fit and light				03/10/2020	699888	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Elect\INDICATORS	replaced L/H/ and fixed wiring				29/09/2020	699888	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				26/09/2020		Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Body\TRL WALL	Body Cracks				26/09/2020		Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Body\AIR LEAK	check airleak from Lock Ram air leak from shaft base				26/09/2020		Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Elect\INDICATORS	Right indicator faulty				26/09/2020		Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Elect\TRL LIGHTS	front clearance light mount broken				26/09/2020		Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Body\TRL FLOOR	REAR LEFT LOCK ON MEZZ FLOOR LEAKING AIR				26/09/2020		Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Elect\TRL LIGHTS	LHS FRONT CLEARANCE LIGHT BROKEN				26/09/2020		Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			26/09/2020		Service	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Tyres\Punct	Job Added From Invoice				24/09/2020	699888	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Workshop\CLEAN	sweep service bay				29/08/2020	699888	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Body\AIR LEAK	check airleak from Lock Ram air leak from shaft base				29/08/2020	699888	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				24/07/2020	699888	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			24/07/2020	699888	Service	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				19/04/2020	699888	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Elect\TRL LIGHTS	R/h light and bracket broken, repaired			replaced R/H light	19/04/2020	699888	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Body\TRL REPS	replaced buckles				19/04/2020	699888	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			19/04/2020	699888	Service	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice				29/03/2020	699888	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice				29/03/2020	699888	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Tyres\AH Callout	Job Added From Invoice				29/03/2020	699888	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Insp\RWC COMP	inspect 553/554 left outside trailer shed door				29/02/2020	699888	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	DrCabElect\SUZI COIL	cut suzi lines for new hose clamps				29/02/2020	699888	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
						inspection ,left trailers outside service bay door with no R & R												
TSS4	Wodonga - Workshop	Workshop\MOVE ASSET	move trailers			found small air leak reqaired	29/02/2020	699888	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Workshop\MOVE ASSET	park along back fence				29/02/2020	699888	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Body\TRL WALL	repairs to bulk head				23/02/2020	699888	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Body\AIR FITTIN	repair airlines				23/02/2020	699888	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Workshop\MOVE ASSET	split & move trailers				23/02/2020	699888	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				22/02/2020	699888	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Body\REFLECTORS	Reflector broken off RHS of gooseneck			Previously completed	22/02/2020	699888	Fault	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Body\REFLECTORS	reflector broken off RHS of gooseneck			As per #273400	22/02/2020	699888	Fault	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			22/02/2020	699888	Service	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Body\TRL REPS	Rips & holes in curtains				22/02/2020	699888	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Body\TRL REPS	rips and holes in curtains			As per #273645	22/02/2020	699888	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Body\TRL REPS	rips and holes			As per #273645	22/02/2020	699888	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Body\TRL REPS	rips and holes in curtains			As per #273645	22/02/2020	699888	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Body\TRL REPS	curtains need repairs			As per #273645	22/02/2020	699888	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Body\TRL REPS	rips and tears			As per #273645	22/02/2020	699888	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Body\TRL REPS	curtains damaged			As per #273645	22/02/2020	699888	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Body\TRL REPS	curtains damaged			As per #273645	22/02/2020	699888	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Body\TRL REPS	Trailer (Tautliner) Repairs			As per #273645	22/02/2020	699888	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
			Bulk head air leaks															
TSS4	Wodonga - Workshop	Body\AIR LEAK	Suzi coil taps				22/02/2020	699888	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
			A & B air line split leaking air															
TSS4	Wodonga - Workshop	Body\AIR LEAK	cut off solit hose & refitted air fittine				20/02/2020	885372	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				19/01/2020	699887	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			19/01/2020	699887	Service	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Brakes	TEST RESULTS				23/12/2019	699887	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	VehService\DS	D SERVICE	VehService\DS			23/12/2019	699887	Service	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Frid Serv\BATTERY	wasn't starting-terminal had to be replaced				30/11/2019		Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				15/11/2019		Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Body\TRL REPS	Trailer (Tautliner) Repairs				15/11/2019		Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Body\TRL WALL	Body Cracks				15/11/2019		Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	Inspected for damaged		15/11/2019		Service	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				15/11/2019		Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			15/11/2019		Service	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				15/11/2019		Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Chassis\CHAS CRACK	front comb rails crack				15/11/2019		Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			15/11/2019		Service	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Tyres\CASE STOCK	Job Added From Invoice				26/10/2019	699886	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice				26/10/2019	699886	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice				26/10/2019	699886	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
						test height control valve (found to be faulty)												
TSS4	Wodonga - Workshop	Susp\HCV	TEST HEIGHT CONTROL VALVE (FOUND TO BE FAULTY) REPLACE HEIGHT CONTROL VALVE ISOURCED PARTS FROM ALBURY TRUCK AND TRAILER-PICK			reolace heiaht con valve	17/10/2019	699886	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Workshop\MOVE ASSET	Sourced parts from Albury Truck 'n' Trailer - pick up parts)				17/10/2019	699886	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				14/10/2019	699886	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Body\TRL REPS	rips and holes in curtains				14/10/2019	699886	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Body\TRL REPS	curtains need repairs				14/10/2019	699886	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Body\TRL REPS	rips and tears				14/10/2019	699886	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Body\TRL REPS	curtains damaged				14/10/2019	699886	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Chassis\CHAS CRACK	front comb rails crack				14/10/2019	699886	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			14/10/2019	699886	Service	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Tyres	monitor middle axle tyres				14/10/2019	699886	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Body\TRL REPS	curtains damaged				14/10/2019	699886	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	DrivLine\WHEEL BRGS	adjusted LHF & LHR				14/10/2019	699886	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				21/09/2019	699886	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Body\TRL REPS	rips and holes in curtains				21/09/2019	699886	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Body\TRL REPS	rips and holes				21/09/2019	699886	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Body\TRL REPS	rips and holes in curtains				21/09/2019	699886	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Body\TRL REPS	curtains need repairs				21/09/2019	699886	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Body\TRL REPS	curtains need replacing				21/09/2019	699886	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Body\TRL REPS	rips and tears				21/09/2019	699886	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	inspected mezz deck. Adjusted chains and strapped deck down		21/09/2019	699886	Service	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Body\TRL REPS	curtains damaged				21/09/2019	699886	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Chassis\CHAS CRACK	front comb rails crack				21/09/2019	699886	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Body\PANELS	repairs to all four uprights				13/09/2019	699886	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Workshop\CLEAN	clean workshop and move trailers				13/09/2019	699886	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Body\TRL REPS	holes in curtains u/s				12/09/2019	699886	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	DrivLine\WHEEL BRGS	needs full inspection u/s				12/09/2019	699886	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Body\TRL REPS	rips and holes in curtains				12/09/2019	699886	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Body\TRL REPS	rips and holes				12/09/2019	699886	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Body\TRL REPS	rips and holes in curtains				12/09/2019	699886	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Body\TRL REPS	curtains need repairs				12/09/2019	699886	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Chassis\MUDGUARDS	LH rear guard bolt missing				12/09/2019	699886	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Body\TRL REPS	curtains need replacing				12/09/2019	699886	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Chassis\CHAS CRACK	al corners of deck, both channels of front curtain wrapers. Rear wall and floor not connected				12/09/2019	699886	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Body\TRL FLOOR	not connected at rear wall				12/09/2019	699886	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Susp\AIR LEAK	boost lines loose				12/09/2019	699886	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Body\TRL REPS	rips and tears				12/09/2019	699886	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Chassis\CHAS CRACK	cracks in uprights				12/09/2019	699886	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Susp\SUSPENSION	axle straps worn				12/09/2019	699886	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Body\TRL FLOOR	repairs to deck snd cracks , make doublers and weld ito possition				11/09/2019		Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				18/08/2019	699886	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			18/08/2019	699886	Service	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Body\TRL REPS	rips and tears				18/08/2019	699886	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Body\TRL REPS	replaced ratchets				18/08/2019	699886	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Chassis\CHAS CRACK	cracks in uprights				18/08/2019	699886	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Susp\SUSPENSION	axle straps worn				18/08/2019	699886	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Chassis\WINCH/STRP	put straps mex deck as there was none				18/08/2019	699886	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Chassis\WINCH/STRP	replaced ratchets and straps				18/08/2019	699886	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				25/06/2019	699886	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Body\TRL REPS	holes in curtains u/s				25/06/2019	699886	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	DrivLine\WHEEL BRGS	needs full inspection u/s				25/06/2019	699886	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Body\TRL REPS	rips and holes in curtains				25/06/2019	699886	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Body\TRL REPS	rips and holes				25/06/2019	699886	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Body\TRL REPS	rips and holes in curtains				25/06/2019	699886	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Elect\TRL LIGHTS	reverse light broken			as per job #233447	25/06/2019	699886	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
TSS4	Wodonga - Workshop	Insp\RWC COMP	rear markers need replacing				25/06/2019	699886	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER	
			reverse light broken															
TSS4	Wodonga - Workshop	Elect\TRL LIGHTS	clearance liaht broken			as oer iob#233447	25/06/2019	699886	Repair	Completed	FL Green Distribution	TinerMess	Wodonga	HCU

TSS4	Wodonga - Workshop	Elect\TRL LIGHTS	reverse lights clearance			done as per job #233447	25/06/2019	699886	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL REPS	curtains need repairs				25/06/2019	699886	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			25/06/2019	699886	Service	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL FLOOR	floor cracked front wall				25/06/2019	699886	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL FLOOR	floor cracked			as per job#233451	25/06/2019	699886	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
						check airbags											
TSS4	Wodonga - Workshop	Susp\AIR LEAK	S leaking airbags			chanaed r/front l/rear r/rear airbaes	25/06/2019	699886	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Chassis\MUDGUARDS	LH rear guard bolt missing				25/06/2019	699886	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL REPS	curtains need replacing				25/06/2019	699886	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Chassis\CHAS CRACK	al corners of deck, both channels of front curtain wrapers. Rear wall and floor not connected				25/06/2019	699886	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL FLOOR	not connected at rear wall				25/06/2019	699886	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Susp\AIR BAG	airbags leaking 30K				25/06/2019	699886	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Susp\AIR LEAK	boost lines loose				25/06/2019	699886	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL FLOOR	modify mezz deck upright for electric's				25/06/2019	699886	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL FLOOR	rewiring mez deck				25/06/2019	699886	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Elect\TRL LIGHTS	Job Added From Invoice				23/05/2019	0	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL FLOOR	mez deck cracks			also lengthen deck chain and retension, replace clearance light and bend right hand font guard	21/05/2019	699885	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL FLOOR	floor cracked			also rear bar and front wall to deck, both corners	21/05/2019	699885	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
						cleaned upguards											
TSS4	Wodonga - Workshop	Body\MUDGUARDS	inspect and repair guards rubbing			repairs and movinz trailersa sorine windows in truck to see	21/05/2019	699885	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL REPS	curtain repairs				21/05/2019	699885	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				17/05/2019	699885	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Elect\TRL LIGHTS	reverse light broken			job pending	17/05/2019	699885	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Insp\RWC COMP	rear markers need replacing			job pending	17/05/2019	699885	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Tyres\TP11	LHF outer			previously done	17/05/2019	699885	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
			reverse light broken														
TSS4	Wodonga - Workshop	Elect\TRL LIGHTS	clearance light broken			job pending	17/05/2019	699885	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Tyres\TP11	LHF outer tyre u/s			job pending	17/05/2019	699885	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Elect\TRL LIGHTS	reverse and clearance light needs replacing			job pending	17/05/2019	699885	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Insp\RWC COMP	rear marker signs faded			job pending	17/05/2019	699885	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes\AIR LEAK	leaking maxi line			previously done	17/05/2019	699885	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			17/05/2019	699885	Service	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Elect\TRL LIGHTS	reverse lights clearance				17/05/2019	699885	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL REPS	curtains need repairs				17/05/2019	699885	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL FLOOR	floor cracked front wall				17/05/2019	699885	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	DrivLine\WHEEL BRGS	bearing adjustments				17/05/2019	699885	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL FLOOR	floor cracked			job pending	17/05/2019	699885	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Susp\AIR LEAK	S leaking airbags				17/05/2019	699885	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice				15/05/2019	10	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice				15/05/2019	10	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Susp\AIR BAG	airbag's slow to come up				30/04/2019		Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL WALL	weld cracks front wall to deck (corner's)				09/04/2019	699885	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\ELECT P&W	deck wiring and replace motor				09/04/2019	699885	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Elect\TRL LIGHTS	reverse light broken				09/04/2019	699885	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Insp\RWC COMP	rear markers need replacing				09/04/2019	699885	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL REPS	rips and holes				09/04/2019	699885	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Tyres\TP11	LHF outer				09/04/2019	699885	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP			09/04/2019	699885	PreventativeMaintenance	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				09/04/2019	699885	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
			reverse light broken														
TSS4	Wodonga - Workshop	Elect\TRL LIGHTS	clearance light broken				09/04/2019	699885	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Susp\SUSPENSION	monitor play			monitor	09/04/2019	699885	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			09/04/2019	699885	Service	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Tyres\TP11	LHF outer tyre u/s				09/04/2019	699885	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Elect\TRL LIGHTS	reverse and clearance light needs replacing				09/04/2019	699885	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Insp\RWC COMP	rear marker signs faded				09/04/2019	699885	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL REPS	rips and holes in curtains				09/04/2019	699885	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes\AIR LEAK	leaking maxi line				09/04/2019	699885	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL FLOOR	mez deck cracks				09/04/2019	699885	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL FLOOR	floor cracked				09/04/2019	699885	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Susp\SUSPENSION	monitor				09/04/2019	699885	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				07/03/2019	699881	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			07/03/2019	699881	Service	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
			reverse light broken														
TSS4	Wodonga - Workshop	Elect\TRL LIGHTS	clearance light broken				07/03/2019	699881	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL REPS	rips and holes in curtains				07/03/2019	699881	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Susp\SUSPENSION	monitor play				07/03/2019	699881	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Workshop\MOVE ASSET	move trailers out of shed/drop in yard and bring back service				07/03/2019		Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice				16/02/2019	699880	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice				16/02/2019	699880	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				30/01/2019		Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		all ushes checked at Paul Johnstons request- all could not fault	30/01/2019		Service	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Tyres\DAMAGE	RHPr has hole				30/01/2019		Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL REPS	small rips				30/01/2019		Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Chassis\CHAS CRACK	small body cracks in carving				30/01/2019		Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				28/12/2018	699871	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL REPS	bottom straps above wheel arches				28/12/2018	699871	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			28/12/2018	699871	Service	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Elect\BRK LIGHT	brake / tail light N/W			moving trailers replace stop tailight and mud flap	12/12/2018	699864	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body	Job Added From Invoice				22/11/2018	0	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\REFLECTORS	Job Added From Invoice				22/11/2018	0	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Elect	Job Added From Invoice				22/11/2018	0	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Elect\TAIL LIGHT	Job Added From Invoice				22/11/2018	0	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS	svc and inspect mezdeck		21/11/2018	699860	Service	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				01/11/2018		Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			01/11/2018		Service	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Tyres	Job Added From Invoice				20/10/2018	699589	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice				16/10/2018	699858	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice				16/10/2018	699858	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL LEGS	remove old leg feet and fit new short ones				09/10/2018	699851	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Workshop\MOVE ASSET	move trailers				04/10/2018	699859	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL LEGS	inspect LH leg suitable to repair T570. started removing. Cancelled				04/10/2018	699859	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL WALL	repair cracks front wall and deck locks				27/09/2018	699859	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Workshop\MOVE ASSET	hook back up to T553				27/09/2018	699859	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Workshop\MOVE ASSET	hook up trailers and park up				19/09/2018		Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Workshop\MOVE ASSET	take trailer set to wash bay and use curtain cleaner to try are restore curtains back to original colour				19/09/2018		Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Wash\WASH	wash trailers				19/09/2018	699859	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Workshop\CLEAN	clean work shed for 553 to be put into top shed				19/09/2018	699859	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL REPS	inspect deck for repairs. Deck needs to be removed from trailer for repairs				19/09/2018	699859	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL REPS	mez deck repairs				19/09/2018	699859	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				07/09/2018	649858	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL REPS	holes in curtains u/s			to be done when it comes in for bearing replacement	07/09/2018	649858	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	DrivLine\WHEEL BRGS	needs full inspection u/s				07/09/2018	649858	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL REPS	bottom straps above wheel arches			as per job#186870	07/09/2018	649858	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Elect\ELECT P&W	check deck lights			sensors broken replace when deck is repaired	07/09/2018	649858	Fault	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	clean workshop		07/09/2018	649858	Service	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	DrivLine\WHEEL BRGS	wheel bearings - replace wheel bearings				07/09/2018	649858	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Susp\HCV	remove stands, attach height control valve and remove l/hand caps to check all lock clips are fitted - 1 found on floor nearby				07/09/2018	649858	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Workshop\MOVE ASSET	move S56 out of top shed, park on fence and collect 327 for service				07/09/2018	649858	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Susp\AIR BAG	Job Added From Invoice				01/08/2018	0	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\MUDGUARDS	re-attach rear guard mounts				29/07/2018	682617	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\DOOR LOCK	inspected mez deck locks				29/07/2018	682617	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	VehService\DS	Service as per list	VehService\DS			29/07/2018	682617	Service	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				29/07/2018	682617	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Tyres	Job Added From Invoice				05/07/2018	0	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice				05/07/2018	0	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Tyres\RETREAD	Job Added From Invoice				05/07/2018	0	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				28/06/2018	665555	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL REPS	bottom straps above wheel arches				28/06/2018	665555	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Elect\ELECT P&W	check deck lights				28/06/2018	665555	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			28/06/2018	665555	Service	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Tyres	Job Added From Invoice				19/05/2018	0	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice				19/05/2018	0	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Tyres\RETREAD	Job Added From Invoice				19/05/2018	0	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\DAMAGE	grind back and weld cracks on T553 & S54 and paint				16/05/2018	648884	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Workshop\MOVE ASSET	swap 630 (dirty fule) with duff to move set out of shed and drop in yard				16/05/2018	648884	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				15/05/2018	64883	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\CHN/RLR/MN	broken buckle R/H/S rear			check ok	15/05/2018	64883	Fault	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\CHN/RLR/MN	replace worn and missing buckle straps			replaced at earlier date	15/05/2018	64883	Fault	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Elect\ELECT P&W	check deck lights			RHF clearance light	15/05/2018	64883	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			15/05/2018	64883	Service	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\MUDGUARDS	replace mudguard spray skirt			could not fault	15/05/2018	64883	Fault	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\BREAKDOWN	Broken curtain ratchet				12/04/2018		Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Tyres\PRES CHECK	Job Added From Invoice				24/03/2018	628417	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				16/03/2018	628416	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Workshop\MOVE ASSET	moving trailers looking for services			previously done	16/03/2018	628416	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Workshop\CLEAN	cleaning			previously done	16/03/2018	628416	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL REPS	holes in curtains u/s				16/03/2018	628416	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	DrivLine\WHEEL BRGS	needs full inspection u/s				16/03/2018	628416	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			16/03/2018	628416	Service	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				27/02/2018	624223	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL REPS	curtain has holes and tears u/s			previously done	27/02/2018	624223	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL REP

TSS4	Wodonga - Workshop	Workshop\MOVE ASSET	moving trailers looking for services				25/01/2018	616480	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Workshop\CLEAN	cleaning				25/01/2018	616480	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL REPS	curtain has holes and tears u/s				25/01/2018	616480	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice				04/01/2018	0	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice				04/01/2018	0	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				22/12/2017		Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	trailer hasn't moved since last service		22/12/2017		Service	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				22/11/2017	614570	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	VehService\DS	Service "B" trailer hi-cube	VehService\DS			22/11/2017	614570	Service	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL REPS	Curtain rollers lock up				22/11/2017	618616	Fault	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL LEGS	LHS trailer leg bent (damaged)		replace left leg		22/11/2017	618616	Fault	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL LEGS	difficult to wind legs all the way up				22/11/2017	618616	Fault	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\CHN/RLR/MN	lines not in place and chain moving out of recess on front LHS of floor support		previously done		22/11/2017	618616	Fault	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\DAMAGE	left and right side cracked where headboard and deck meet				22/11/2017	618616	Fault	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Elect\ELECT P&W	mez deck blowing fuses when lowering deck will not go all the way down				22/11/2017	618616	Fault	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
					rewired mez deck, fitted new motor													
TSS4	Wodonga - Workshop	Elect\ELECT P&W	rewire burnt out mez		reset all micro switches		22/11/2017	618616	Fault	Completed	FL Green Distribution	TinnerMess	Wodonwa	HCU	91787S	Wodonwa Workshoo	TRAILER
TSS4	Wodonga - Workshop	Body\TRL FLOOR	fix mez asap curtomer refusing to load until mez fully operational refer to R&R 104507, 104505, 104504				22/11/2017	618616	Fault	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL REPS	curtain ripped at drop again				22/11/2017	618616	Fault	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\ELECT P&W	rewire mez burnt out		as per job #138543		22/11/2017	618616	Fault	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\LIGHTS	move & replace both side clearance lights at goose neck and extend load binder bar				22/11/2017	618616	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP	completed previously		22/11/2017	618616	PreventativeMaintenance	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\LIGHTS	no left blinker				10/11/2017		Fault	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Elect\ELECT P&W	plug broken		see job#130099		03/10/2017	595787	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Elect\ELECT P&W	plug broken		replaced heavy denty plug female and male plugs		03/10/2017	595787	Fault	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				27/09/2017		Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Elect\ELECT P&W	LHR top blinker				27/09/2017		Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			27/09/2017		Service	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				03/09/2017	583116	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			03/09/2017	583116	Service	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Elect\ELECT P&W	LHR top blinker				03/09/2017	583116	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				28/08/2017		Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL LEGS	LHS trailer leg (bent) does not retract fully				28/08/2017		Fault	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Elect\ELECT P&W	broken clearance lights				28/08/2017		Fault	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Elect\ELECT P&W	clearance lights need attention				28/08/2017		Fault	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\AIR LEAK	air leak somewhere				28/08/2017		Fault	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			28/08/2017		Service	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL FLOOR	repair locks for trailer floor		Also refitted deck motor hatch		25/08/2017	580449	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Elect\ELECT P&W	fix elec prob on mez floor				16/08/2017	576465	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				16/08/2017	576465	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	VehService\DS	Service	VehService\DS			16/08/2017	576465	Service	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Workshop\W/S MAINT	forklift operation				15/08/2017		Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL FLOOR	Inspect mez deck has electrical fault in controller box and wiring				15/08/2017	576464	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Elect\ELECT P&W	mez not coming down after drop				03/08/2017		Fault	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL FLOOR	mez deck still not able to move				03/08/2017		Fault	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL REPS	LM RM side missing straps and buckles bent				27/07/2017		Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\CHN/RLR/MN	RHR curtain track getting stuck				27/07/2017		Fault	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL REPS	curtains getting stuck at rear fix asap				27/07/2017		Fault	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL REPS	curtains at drop need attention				27/07/2017		Fault	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL REPS	curtains need patching asap product getting wet				27/07/2017		Fault	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL REPS	curtains need fixing now product getting wet				27/07/2017		Fault	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL REPS	curtains hard to move				27/07/2017		Fault	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL REPS	curtains need repair				27/07/2017		Fault	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\BREAKDOWN	Mezz Deck not working				14/07/2017		Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
			mezz deck stuck down															
			troubleshoot problem															
			deck locked in at 3rd top lock. Battery disconnect															
TSS4	Wodonga - Workshop	Body\TRL REPS	curtain repair on LH side				13/07/2017	569852	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Elect\ELECT P&W	repair wiring fault in deck.		removed motor and repaired wires from circuit board inside motor refitted to deck tested with minor repairs made		22/06/2017		Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				22/06/2017	560089	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL REPS	LM RM side missing straps and buckles bent				22/06/2017	560089	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			22/06/2017	560089	Service	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\AIR LEAK	locate air leaks and replace 3/4" and 1/2" rubber hoses where require				17/06/2017		Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Elect\ELECT P&W	inspect wiring on mez deck				17/06/2017		Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Chassis\CHAS CRACK	repair cracks in body				17/06/2017		Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes\AIR LEAK	repair air leaks				17/06/2017		Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\AIR LEAK	locate air leaks and replace 3/4" and 1/2" rubber hoses where required				17/06/2017		Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				26/05/2017	548692	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL REPS	Bent buckles				26/05/2017	548692	Fault	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL FLOOR	Sometimes mez decks wont respond				26/05/2017	548692	Fault	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Elect\ELECT P&W	electrical cords exposed (blue out)				26/05/2017	548692	Fault	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes\LAKE BRAKE	noisy brakes		driver to monitor		26/05/2017	548692	Fault	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\CHN/RLR/MN	lines not in place and chain moving out of recess on front LHS of floor support				26/05/2017	548692	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			26/05/2017	548692	Service	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL REPS	LM RM side missing straps and buckles bent				26/05/2017	548692	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	VehService\DS	overdue for service	VehService\DS			26/05/2017	548692	Service	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL FLOOR	repair elec cable guide				28/04/2017		Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\PANELS	fit angle storage compartment				07/04/2017		Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Susp\AIR LEAK	air leak in larg line under trailer				07/04/2017		Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\DAMAGE	repair damged curtain				30/03/2017		Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Tyres\TP11	Job Added From Invoice				25/03/2017	519713	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Workshop\MOVE ASSET	take trailer to Hume truck technics				25/03/2017		Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				11/03/2017	516410	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\REFLECTORS	missing reflectors u/s				11/03/2017	516410	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Tyres\DAMAGE	RHR inner tyre unroadworthy		fitter has see tyre and they're ok		11/03/2017	516410	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Elect\ELECT P&W	lights need securing				11/03/2017	516410	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL REPS	curtain rollers catching				11/03/2017	516410	Fault	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Elect\ELECT P&W	electrical cords exposed (blue out)				11/03/2017	516410	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			11/03/2017	516410	Service	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Tyres\TP14	Job Added From Invoice				08/03/2017	511621	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Tyres\TRC	Job Added From Invoice				08/03/2017	511621	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
			right hand front outter tyre flat															
			bridgestone 24h to organise															
TSS4	Wodonga - Workshop	Tyres\BREAKDOWN	no PO was given				01/03/2017		Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Tyres\DAMAGE	trailer has flat tyre right hand front - Bridgestone to organise				01/03/2017		Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Tyres\DAMAGE	tyres low tread		Completed		23/02/2017		Fault	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Tyres\TP11	Job Added From Invoice				14/02/2017	0	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Tyres\TP21	Job Added From Invoice				14/02/2017	0	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				22/01/2017	495352	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\REFLECTORS	missing reflectors u/s				22/01/2017	495352	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Tyres\DAMAGE	tyres low tread		RHR inner tyre still unroadworthy		22/01/2017	495352	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			22/01/2017	495352	Service	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Tyres\DAMAGE	RHR inner tyre unroadworthy				22/01/2017	495352	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Elect\ELECT P&W	lights need securing				22/01/2017	495352	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body	Job Added From Invoice				22/12/2016	0	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
					cleaning													
TSS4	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	movine trailers		17/12/2016		Service	Completed	FL Green Distribution	TinnerMess	Wodonwa	HCU	91787S	Wodonwa Workshoo	TRAILER
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				17/12/2016		Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\REFLECTORS	missing reflectors u/s				17/12/2016		Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Tyres\TP11	Job Added From Invoice				29/11/2016	466611	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Elect\ELECT P&W	Job Added From Invoice				16/11/2016	0	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Elect\TRL LIGHTS	Job Added From Invoice				16/11/2016	0	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Elect\CONSUMABLE	Job Added From Invoice				16/11/2016	0	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Elect\ELECT P&W	Job Added From Invoice				15/11/2016	0	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Workshop\MOVE ASSET	move trailers				15/11/2016		Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
					cut out lock mounts clean up to be ready to put back together. Cut old locks out made new surrounds welded together welded nuts on ready to put back in													
					fitted lock ran chains rewired deck tested ready to go													
TSS4	Wodonga - Workshop	Body\TRL FLOOR	inspect and repair mez floor locks		welded motor lid back on		09/11/2016		Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			09/11/2016		Service	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP			09/11/2016		PreventativeMaintenance	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				09/11/2016		Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Elect	left hand blinker not working				09/11/2016		Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body	left hand middle curtain is ripped				09/11/2016		Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\CHN/RLR/MN	RH track u/s				09/11/2016		Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\MUDGUARDS	install pipe D/S & P/S infront of rear try mudguard				09/11/2016		Fault	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Chassis\WINCH/STRP	install bar/pipe on driverside gooseneck for hand straps				09/11/2016		Fault	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\CHAS CRACK	tie rail to be fitted in front of front axle				09/11/2016		Fault	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\CHN/RLR/MN	RH track u/s				09/11/2016		Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Tyres\TP11	Job Added From Invoice				28/10/2016	0	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL REPS	LHS rear drop curtain ripped				05/10/2016		Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Tyres	L/H/F outer has crack in wall				05/10/2016		Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Chassis\CROSS MBR	various cracks				05/10/2016		Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body	curtains need repair				05/10/2016		Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body	rips in curtain at gooseneck				05/10/2016		Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body	rips & holes				05/10/2016		Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL REPS	there is a horizontal tear on the LHS of the curtain in front of the first axle				05/10/2016		Fault	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\CHAS CRACK	tie rail to be fitted in front of front axle				05/10/2016		Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Chassis\MUDGUARDS	install tie down bar infront of D/S + P/S for strap instead of using mudguard support				05/10/2016		Fault	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body	fix tear in curtain P/S + D/S goosneck				05/10/2016		Fault	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body	fix tea P/S rear drop				05/10/2016		Fault	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Chassis\WINCH/STRP	install bar/pipe on driverside gooseneck for hand straps				05/10/2016		Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\MUDGUARDS	install pipe D/S & P/S infront of rear try mudguard				05/10/2016		Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body\TRL REPS	fix holes in curtains				05/10/2016		Fault	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body	rego label unreadable on S54				05/10/2016		Fault	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body	mezzanine floor needs gear/motot cover welding		mex repairs		05/10/2016		Fault	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Elect	left hand blinker not working				05/10/2016		Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	91787S	Wodonga Workshop	TRAILER
TSS4	Wodonga - Workshop	Body	left hand middle curtain is ripped

TS54	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		05/10/2016	Service	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	Tyres\TP11	Job Added From Invoice			10/09/2016 455731	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			02/09/2016	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	DrCabElect\INDICATORS	LH side indicator u/s		previously done	02/09/2016	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	Elect	indicator u/s		previously done	02/09/2016	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	VehService	overdue for service 2 months			02/09/2016	Fault	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	VehService	overdue for service 2 months			02/09/2016	Fault	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	Body	loaded trailer could not check			02/09/2016	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	mez deck needs major repair on A Trailer	02/09/2016	Service	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	Body	rips & holes			02/09/2016	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	Elect\BATTERY	Job Added From Invoice			23/08/2016 0	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	Elect				10/08/2016	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	Body	replaced battery for mez floor			10/08/2016	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			03/08/2016	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	Brakes	brake hoses rubbed			03/08/2016	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	DrCabElect\INDICATORS	LH side indicator u/s			03/08/2016	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		03/08/2016	Service	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	Elect	indicator u/s			03/08/2016	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	Body	rips in curtain at gooseneck			03/08/2016	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	Tyres\TP15	Job Added From Invoice			28/07/2016 0	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	Tyres\TP11	Job Added From Invoice			14/07/2016 447468	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			06/07/2016	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	Tyres	2 bald tyres			06/07/2016	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	Brakes	brake hoses rubbed			06/07/2016	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	Tyres	new tyre			06/07/2016	Fault	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		06/07/2016	Service	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	DrCabElect\INDICATORS	LH side indicator u/s			06/07/2016	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	Body	curtains need repair			06/07/2016	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	Tyres\TP22	Job Added From Invoice			17/06/2016 439559	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	Tyres\TP11	Job Added From Invoice			17/06/2016 439559	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			09/06/2016	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		09/06/2016	Service	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	Tyres	L/H/F outer has crack in wall			09/06/2016	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	Brakes	brake hoses rubbed			09/06/2016	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	Chassis\CROSS MBR	various cracks			09/06/2016	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	Body	loaded trailer could not check			09/06/2016	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	Body\TRL FLOOR	pulled IHR lock apart and rebuilt while still in the deck			17/04/2016	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	Body\TRL FLOOR	mounting brackets for air ram straightened because it was broken			17/04/2016	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	Body\TRL FLOOR	L/H rear deck lock broken			16/04/2016	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	Tyres\TP11	Job Added From Invoice			01/04/2016 386289	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	Tyres\TP18	Job Added From Invoice			01/04/2016 386289	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	Tyres\TP19	Job Added From Invoice			01/04/2016 386289	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	Tyres\TP19	Job Added From Invoice			01/04/2016 0	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			30/03/2016	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	Body\TRL REPS	LHS rear drop cuttain ripped			30/03/2016	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	Body\TRL REPS	there is a horizontal tear on the LHS of the curtain in front of the first axle			30/03/2016	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	Body\CHAS CRACK	tie rail to be fitted in front of front axle			30/03/2016	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	Brakes\BRAKE ADJ	brakes need adjusting		done as part of service	30/03/2016	Fault	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	Tyres	2 bald tyres			30/03/2016	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		30/03/2016	Service	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	Body\CHAS CRACK	tie rail to be fitted in front of front axle			19/03/2016	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	Brakes\BRAKE ADJ	brakes need adjusting			19/03/2016	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	Body\TRL REPS	there is a horizontal tear on the LHS of the curtain in front of the first axle			05/03/2016	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	Tyres\TP13	Job Added From Invoice			01/03/2016 562269	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	Tyres\TP13	Job Added From Invoice			01/03/2016 0	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	Tyres\TP13	Job Added From Invoice			01/03/2016 0	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			28/02/2016	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	Body\TRL REPS	LHS rear drop cuttain ripped			28/02/2016	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		28/02/2016	Service	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	Body\TRL REPS	curtain repaires			05/01/2016	Fault	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	Tyres\TP11	Job Added From Invoice			02/12/2015 326281	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	Tyres\TP11	Job Added From Invoice			02/12/2015 0	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	Body	clips on b/trailor need replacing			02/12/2015	Fault	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	Body	left side and right side over wheels buckles need fixing			02/12/2015	Fault	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	Body	left side and right side over wheels buckles need replacing			02/12/2015	Fault	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	Body	left and right hand sides needs buckles fixing			02/12/2015	Fault	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	Body	clips on trailor need replacing			02/12/2015	Fault	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			25/11/2015	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	Elect	no headlights or diving lights			25/11/2015	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist no headlights or diving lights	VehService\DS		25/11/2015	Service	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER
TS54	Wodonga - Workshop	Elect	CANCELLED			24/11/2015 877716	Repair	Completed	FL Green Distribution	TinnerMess	Wodonga	HCU	917875	Wodonga Workshop	TRAILER