EquipmentName	Workshop	CodeAndSubCode	Description	CompletionComments	DateDone	Workstate	Location	Division	Rego	Supplier	EquipmentType
T383	Colac - Colac	Susp\WHEEL ALGN	WHEEL ALIGNMENT		25/08/2026	Completed	Colac	GTK	37690S	GEELONG TRUCK AND STEERING	TRAILER
T383	Albury - Workshop	Chassis\BOLSTER	3 Bolster LHS Ram Need Replacing		05/08/2026	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Albury - Workshop	Chassis\WINCH/STRP	Last 2 winches need to be oiled, binding + hard to wind		05/08/2026	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
			D Service								
T383	Albury - Workshop	VehService\DS			05/08/2026	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Albury - Workshop	DrivLine\AXLE REPLC	FRONT AXLE BENT - FOUND BY HTT		05/08/2026	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Albury - Workshop	VehService\DS	service		05/08/2026	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Albury - Workshop	Chassis\WINCH/STRP	last 2 winches are tight to turn		05/08/2026	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Albury - Workshop	Tyres\FAILURE	lh front tyre needs replacing starting to crack		05/08/2026	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Albury - Workshop	Hydraulics\RAM	replaced bolster cylinder		31/07/2026	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	VehService\DS	VehService\DS D Service		25/07/2026	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Brakes\EBS FAULTS	EBS Fault lh rear	completed by JS MB	13/07/2026	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Tyres\TP5+6	Tyres\TP5+6 (25-26)	LOW	11/07/2026	Completed	Colac	GTK	37690S	BORDER BANDAG PTY LTD - 4	TRAILER
T383	Albury - Workshop	Tyres\TP1+2	Tyres\TP1+2 (21-22)	LOW	11/07/2026	Completed	Colac	GTK	37690S	BORDER BANDAG PTY LTD - 4	TRAILER
T383	Albury - Workshop	VehService\DS	VehService\DS D Service	completed by SMc	09/07/2026	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Albury - Workshop	Tyres\Punct	Tyres\Punct POS 23		01/07/2026	Completed	Colac	GTK	37690S	BORDER BANDAG PTY LTD - 4	TRAILER
T383	Albury - Workshop	Brakes\BRK RELINE	right rear brakes low	completed by JS AR	15/06/2026	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Tyres\TP11+12	Tyres\TP11+12 (31-32)	LOW	04/06/2026	Completed	Colac	GTK	37690S	BORDER BANDAG PTY LTD - 4	TRAILER
T383	Albury - Workshop	Tyres\TP9+10	Tyres\TP9+10 (29-30)	LOW	04/06/2026	Completed	Colac	GTK	37690S	BORDER BANDAG PTY LTD - 4	TRAILER
T383	Albury - Workshop	Tyres\TP7+8	Tyres\TP7+8 (27-28)	LOW	04/06/2026	Completed	Colac	GTK	37690S	BORDER BANDAG PTY LTD - 4	TRAILER
T383	Albury - Workshop	Susp\AIR BAG	1. LEAKING AIRBAG RL	Airbag previously done checked brakes for air leaks good to go	30/05/2026	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Elect\TAIL LIGHT	Tail light's shorting out, electrical issue, diagnose and repair.	completed by JS	27/05/2026	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
				Perform laser wheel alignment on triaxle B							
				trailer.							
				Fleet No : T383							
				Note : Centre and rear axles ok. Front axle							
			needs wheel alignment tracking out to LHS	severally bent back on left side. Requires							
T383	Albury - Workshop	Tyres\ALIGNMENT	T134028	replacement. Advise Shaun	26/05/2026	Completed	Colac	GTK	37690S	HUME TRUCK TECHNICSP/L-4	TRAILER
T383	Albury - Workshop	Tyres\ALIGNMENT	needs wheel alignment		26/05/2026	Completed	Colac	GTK	37690S	HUME TRUCK TECHNICSP/L-4	TRAILER
				Perform laser wheel alignment on triaxle B							
				trailer.							
				Fleet No : T383							
				Note : Centre and rear axles ok. Front axle							
				severally bent back on left side. Requires							
T383	Albury - Workshop	DrivLine\WHEEL ALGN	Trailer Need's wheel alignment, tracking to the Left.	replacement. Advise Shaun	26/05/2026	Completed	Colac	GTK	37690S	HUME TRUCK TECHNICSP/L-4	TRAILER
T383	Albury - Workshop	VehService\DS	VehService\DS D Service		25/05/2026	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
				completed by JS TP							
T383	Albury - Workshop	VehService\DS	VehService\DS D Service	no brakes were recorded	15/05/2026	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Brakes\BRAKE ADJ	Brake adjustment	completed by TP	30/04/2026	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	VehService\DS	VehService\DS D Service	completed by SMc,TP,JS	30/04/2026	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Albury - Workshop	Brakes\BRK RELINE	Replace right rear brake pad's.	john replaced brakes and checked bearings and checked suspension	27/04/2026	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	VehService\DS	VehService\DS D Service	completed by SMc	15/04/2026	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Insp\ANN INSP	Insp\ANN INSP Annual Inspection As Per Checklist	completed by SMc	15/04/2026	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Tyres\RUN OUT	Tyres\RUN OUT POS 31		29/03/2026	Completed	Colac	GTK	37690S	BORDER BANDAG PTY LTD - 4	TRAILER
T383	Albury - Workshop	Body\CHN/RLR/MN	snapped safety tie down chain	CP MN	24/03/2026	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Tyres\RUN OUT	Tyres\RUN OUT POS 23-24	RF BRAKE BOOSTER FAILING	14/03/2026	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Brakes\L.H.F	BRAKES LOCKING ON FRONT AXLE	Add 2 hrs time for mitch	12/03/2026	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Albury - Workshop	Brakes\BRK RELINE	RELINE LF MR RR		24/02/2026	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Elect\ELECT P&W	CLEARANCE LIGHT ON RIGHT HAND BACK GUARD BROKEN		24/02/2026	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	VehService\DS	VehService\DS D Service		24/02/2026	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Tyres\FITMENT	Tyres\FITMENT STRIP & FIT 21		21/01/2026	Completed	Colac	GTK	37690S	BORDER BANDAG PTY LTD - 4	TRAILER
T383	Albury - Workshop	Susp\SUSPENSION	WHEEL ALIGNMENT NEED.	checked spring eye bush's and tracking	25/12/2025	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Albury - Workshop	VehService\DS	VehService\DS D Service		23/12/2025	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Albury - Workshop	Elect\ELECT P&W	CLEARANCE LIGHT ON RIGHT HAND BACK GUARD BROKEN		04/12/2025	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Albury - Workshop	VehService\DS	VehService\DS D Service	M.NEWELY 1 HR	28/11/2025	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Albury - Workshop	Tyres\TP9+10	Tyres\TP9+10 (29-30)		27/11/2025	Completed	Colac	GTK	37690S	BORDER BANDAG PTY LTD - 4	TRAILER
T383	Albury - Workshop	VehService\DS	VehService\DS D Service		25/10/2025	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Albury - Workshop	Tyres\TP10	L/H/R Inner Tyre		25/10/2025	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Albury - Workshop	Elect\INDICATORS	INDICATORS SHORTING OUT		23/10/2025	Unlocked	Colac	GTK	37690S	Albury Workshop	TRAILER
				-scale issue checked over							
				-fault with tester repaired							
				-wiring checked over to find short in wire when wire is bumped at control box, wiring and plugs replaced							
				-control box not picking up trailer, part faulty, replaced with second hand unit							
T383	Albury - Workshop	Chassis\SCALES	Repair scales.	-didnt have correct style truck or sister trailer to fully test scale unit	10/10/2025	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Chassis\SCALES	No Scales On Back Bay		10/10/2025	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Elect\ELECT P&W	REPAIRED CHANNEL 3 ON SCALES.		07/10/2025	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Albury - Workshop	Body\STRAPS	CHECK STRAPS.		02/10/2025	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	DrivLine\ELECT P&W	CLEARANCE LIGHT KEEP TRIPPING FUSE AND BLINKERS.		02/10/2025	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Chassis\WINCH/STRP	CHECK STRAPS		02/10/2025	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
				-finished repair and fitment of front bolster plate wiring and trailer plugs							
				-rewired and repaired front and rear bolster lights							
				-ABS sensors, wiring and function tested, in working order, front ABS plug replaced							
				-rear combination light wiring repaired at chasis connector							
				-light check done, indicator fault from previous RNR could not be replecated							
				-tail light circuit was shorting due to rubbed through wiring							
T383	Albury - Workshop	Elect\ELECT P&W	CLEARANCE LIGHT KEEP TRIPPING FUSE AND BLINKERS	-previous work for time cards, help remove skid plate, front bolster, wiring, hydraulic lines and fittings for replacement or repair	02/10/2025	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Chassis\STRAPS	CHAIN NEED TO BE LONGER ON DOG		02/10/2025	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Chassis\STRAPS	CHAIN NEED TO BE LONGER ON DOG.		02/10/2025	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Susp	Rear left shock missing needs replacement		02/10/2025	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Chassis\DAMAGE	Front axle, saddles are both cracked, at the top		02/10/2025	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Susp\SHOCK ABS	L/H/R Shock Mounts Snapped		02/10/2025	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Susp\SUSPENSION	Right Front Saddle Cracked In 2 Spots		02/10/2025	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Chassis\CHAS CRACK	Repair left hand Web of chassis rail.		02/10/2025	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Chassis\CHAS CRACK	Crack in chassis webbing behind first bolster cylinder, cracked right through webbing	Completed	02/10/2025	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Chassis\SKID PLATE	Skid Plate Cracked	Replaced skid plate as part of the chassis repair as the plate was removed in the process of repair	02/10/2025	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Brakes\BRK RELINE	RELINED RF LF RM.		04/09/2025	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Susp\AXLES	TRACKING TO THE LEFT AND GETTING WARM 3RD AXLE DRIVER SIDE.	CHECKED. OK.	04/09/2025	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Susp\WHEEL ALGN	Front & Middle Axles Need Wheel Alignment	CHECKED. OK.	04/09/2025	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	VehService\DS	VehService\DS D Service		02/09/2025	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Albury - Workshop	Chassis\BOLSTER	2nd bolster doublers plate cracked		02/09/2025	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Albury - Workshop	Chassis\BOLSTER	2nd bolster doublers plate cracked		02/09/2025	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Albury - Workshop	Chassis\BOLSTER	2nd bolster doublers plate cracked		02/09/2025	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Albury - Workshop	Chassis\BOLSTER	CRACKS IN BOLSTERS	WELDED CRACKS IN FRONT BOLSTER.	02/09/2025	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Albury - Workshop	Tyres\RUN OUT	Tyres\RUN OUT POS 24		04/08/2025	Completed	Colac	GTK	37690S	BORDER BANDAG PTY LTD - 4	TRAILER
T383	Albury - Workshop	Tyres\TP9+10	Tyres\TP9+10		04/08/2025	Completed	Colac	GTK	37690S	BORDER BANDAG PTY LTD - 4	TRAILER
T383	Albury - Workshop	Brakes\BRK RELINE	RELINE LR		01/08/2025	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Albury - Workshop	VehService\DS	VehService\DS D Service		01/08/2025	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
				Connect ABS diagnostic tool and checked codes, found open circuit code for sensor 2A, inspect wiring and found							
				sensor lead had an open circuit, removed and replaced lead, resecured harness, rechecked and cleared codes -							
T383	Albury - Workshop	Brakes\EBS FAULTS	TUMUT AUTO ELECRICS- DIAGNOSE AND REPAIR TRAILER ABS FAULT.	all OK	26/07/2025	Completed	Colac	GTK	37690S	TUMUT AUTO ELECTRICS PTY LTD -4	TRAILER
T383	Albury - Workshop	Elect\ELECT P&W	TUMUT AUTO ELECTRICS- CLEARANCE LIGHT NOT WORKING ON BUMPER.		19/07/2025	Completed	Colac	GTK	37690S	TUMUT AUTO ELECTRICS PTY LTD -4	TRAILER
T383	Albury - Workshop	VehService\DS	VehService\DS D Service		01/07/2025	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER

T383	Albury - Workshop	Chassis\HOUSEKEEP	Replace Broken Quick Release Cord		04/06/2025	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Albury - Workshop	VehService\DS	VehService\DS D Service		02/06/2025	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Albury - Workshop	VehService\DS	VehService\DS D Service	11	03/05/2025	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Albury - Workshop	Insp\ANN INSP	Annual Inspection		11/04/2025	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Albury - Workshop	VehService\DS	VehService\DS D Service		11/04/2025	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Chassis\EXTE TU	REPLACE FRONT WINCH BARREL.	Couldn't fault. Previously completed	04/03/2025	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	VehService\DS D Service	Crack in chassis behind first bolster cylinder, cracked right through chassis to be fixed when empty asap	04/03/2025	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Elect\TRL LIGHTS	light still going off or on	Previously completed	04/03/2025	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Albury - Workshop	Elect\TAIL LIGHT	No Tail light's.	Russell completed this job	19/02/2025	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Albury - Workshop	VehService\DS	VehService\DS		19/02/2025	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Tyres\PRES CHECK	CHECK TYRES		25/01/2025	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	VehService\DS		25/01/2025	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes\BOOSTER	Replace left rear brake booster.		21/01/2025	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Albury - Workshop	Tyres\TP9+10	Tyres\TP9+10		17/01/2025	Completed	Colac	GTK	37690S	BEAUREPAIRES - 4	TRAILER
T383	Wodonga - Workshop	Susp\AXLES	Tighten all U Bolts and Repair Left Rear Top Shocky Mount.	Replaced shock straps and shock stud cut out and Adon to weld Intube	17/01/2025	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Myrtleford - Workshop	Susp\SPRNG PACK	REPLACE LHM SPRING PACK & WRAPER		13/01/2025	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
				Fit new marker light rhr							
				Rhm spring snapped too be replaced							
T383	Wodonga - Workshop	VehService\DS	VehService\DS	RHR shock mount to be replaced	21/12/2024	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Body\MUDGUARDS	NEW STRETCH GUARDS.	/	05/12/2024	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	VehService\DS		05/12/2024	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Albury - Workshop	Tyres\TP9+10	Repair Tyre Punctures On Position 9&10. (Tuckerbox Tyres P/O: T090568)		28/11/2024	Completed	Colac	GTK	37690S	BEAUREPAIRES - 4	TRAILER
T383	Albury - Workshop	Tyres\TP09	Replace Tyres On Position 9. (Tuckerbox Tyres Gundagai P/O: T090045)		11/11/2024	Completed	Colac	GTK	37690S	BEAUREPAIRES - 4	TRAILER
T383	Albury - Workshop	Tyres\TP10	Replace Tyres On Position 10. (Tuckerbox Tyres Gundagai P/O: T090045)		11/11/2024	Completed	Colac	GTK	37690S	BEAUREPAIRES - 4	TRAILER
T383	Wodonga - Workshop	VehService\DS	VehService\DS		11/11/2024	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Albury - Workshop	Tyres\RUN OUT	Tyres\RUN OUT 4 & 8		24/10/2024	Completed	Colac	GTK	37690S	BEAUREPAIRES - 4	TRAILER
T383	Wodonga - Workshop	VehService\DS	VehService\DS		21/10/2024	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Albury - Workshop	Tyres\TP5+6	Tyres\TP5+6		10/10/2024	Completed	Colac	GTK	37690S	BEAUREPAIRES - 4	TRAILER
T383	Albury - Workshop	Tyres\TP7+8	Tyres\TP7+8		10/10/2024	Completed	Colac	GTK	37690S	BEAUREPAIRES - 4	TRAILER
T383	Albury - Workshop	Tyres\TP3+4	Tyres\TP3+4		10/10/2024	Completed	Colac	GTK	37690S	BEAUREPAIRES - 4	TRAILER
T383	Albury - Workshop	Tyres\TP1+2	Tyres\TP1+2		10/10/2024	Completed	Colac	GTK	37690S	BEAUREPAIRES - 4	TRAILER
T383	Albury - Workshop	Tyres\Punct	Repair 2 Punctured Tyres Position Unknown. (Tucker Box Tyres P/O: T090390)		25/09/2024	Completed	Colac	GTK	37690S	BEAUREPAIRES - 4	TRAILER
T383	Albury - Workshop	Tyres\FITMENT	Replace 2 Tyres Position Unknown. (Tucker Box Tyres P/O: T090390)		25/09/2024	Completed	Colac	GTK	37690S	BEAUREPAIRES - 4	TRAILER
T383	Wodonga - Workshop	VehService\DS	VehService\DS		13/09/2024	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
			Carry Out Wheel Alignment (Hume Truck Technics P/O: T088161)								
T383	Albury - Workshop	Tyres\ALIGNMENT			09/08/2024	Completed	Colac	GTK	37690S	HUME TRUCK TECHNICSP/L-4	TRAILER
T383	Wodonga - Workshop	Elect\ELECT P&W	NO SCALES.		06/08/2024	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Tyres\FITMENT	CHECK TYRES.		06/08/2024	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Tyres\FITMENT	CHECK TYRES.	Tyres were all ok	06/08/2024	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	VehService\DS		06/08/2024	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	VehService\DS		18/07/2024	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Chassis\CHAS CRACK	Repair left front chassis rail cracks.	I	18/06/2024	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Body\MUDGUARDS	READJUSTED LF OUTRIGGER. REPLACED LH STRETCH GUARD.		14/06/2024	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Albury - Workshop	Tyres\TP09	Tyres\TP09		14/06/2024	Completed	Colac	GTK	37690S	BEAUREPAIRES - 4	TRAILER
T383	Myrtleford - Workshop	VehService\DS	D Service		07/06/2024	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Wodonga - Workshop	Chassis\SKID PLATE	CRACK ABOVE SKID PLATE ON LHS.		20/04/2024	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Chassis\BOLSTER	REPLACE BOLSTER PIVOT BUSHES.		20/04/2024	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Body\MUDGUARDS	REPLACE LH STRETCH GUARD.		20/04/2024	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
			REVERSE LIGHTS NOT WORKING.								
T383	Wodonga - Workshop	Elect\ELECT P&W	WORK LIGHTS NOT WORKING.		20/04/2024	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Elect	Indicators Short Out When Turning Left Or Right Keeps Tripping Fuse		20/04/2024	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Elect\WORK LIGHT	Rear Work Light Not Working		20/04/2024	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		20/04/2024	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		20/04/2024	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Albury - Workshop	Tyres\TP10	Tyre Position 10		11/04/2024	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Tyres\TP07	Tyre Position 7		11/04/2024	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Myrtleford - Workshop	Elect\INDICATORS	REPLACE R/H BLINKER.		09/04/2024	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Wodonga - Workshop	Susp\SPRNG HANG	RF SPRING HANGER CRACKED.		04/04/2024	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection		04/04/2024	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		04/04/2024	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		04/04/2024	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Chassis\CROSS MBR	CROSSMEMBERS CRACKED.		20/03/2024	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection		20/03/2024	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Elect\WORK LIGHT	Work lights nbot working		20/03/2024	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Elect\TRL LIGHTS	Short in R/H indicator		20/03/2024	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		20/03/2024	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		20/03/2024	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		05/03/2024	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		05/03/2024	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		20/02/2024	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		20/02/2024	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Albury - Workshop	Tyres\CLEANSKIN	no pos		06/02/2024	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Wodonga - Workshop	Elect\WORK LIGHT	Work lights nbot working		06/02/2024	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Elect\TRL LIGHTS	Short in R/H indicator		06/02/2024	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		06/02/2024	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		06/02/2024	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Albury - Workshop	Tyres\TP09	Tyre Position 9		09/01/2024	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Tyres\TP2A	Tyre Position 2A		09/01/2024	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Tyres\TP01	Tyre Position 1		09/01/2024	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		29/12/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		29/12/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Albury - Workshop	Tyres\FITMENT	11-12		15/12/2023	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection		08/12/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes\BRK RELINE	reline L/M & R/R hubs		08/12/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Tyres\RETREAD	Check Tyres		08/12/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Comp\Truck Safe	NHVR sticker unreadable		08/12/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
			loghaul sign unreadable								
T383	Wodonga - Workshop	Body\REFLECTORS	REMOVE. NO LONGER REQUIRED		08/12/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		08/12/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		08/12/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		08/12/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Albury - Workshop	Tyres\TP7+8	replace tyres		29/11/2023	Completed	Colac	GTK	37690S	BEAUREPAIRES - 4	TRAILER
T383	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	REPLACED CRACKED PIVOT MOUNT AND LR SHOCK.	28/11/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		28/11/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Albury - Workshop	Tyres\TP9+10	replace tyres		23/11/2023	Completed	Colac	GTK	37690S	BEAUREPAIRES - 4	TRAILER
T383	Albury - Workshop	Tyres\RETREAD	Check Tyres		16/11/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Albury - Workshop	Elect\INDICATORS	LEFT INDICATOR NOT WORKING.		16/11/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Albury - Workshop	Comp\Truck Safe	NHVR sticker unreadable		16/11/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
			loghaul sign unreadable								
T383	Albury - Workshop	Body\REFLECTORS	REMOVE. NO LONGER REQUIRED		16/11/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		16/11/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
			Service As Per Attached Checklist (TCTC)								
T383	Albury - Workshop	VehService\DS	Purchase Order Number: T082288		16/11/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Chassis\BOLSTER	WELDED BOLSTERS.		16/10/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection		10/10/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER

T383	Wodonga - Workshop	Elect\INDICATORS	LEFT INDICATOR NOT WORKING.		10/10/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes\BRAKE ADJ	ADJUST BRAKES.		10/10/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Susp\WHEEL ALGN	Trailer tracking to the RHS	Perform laser wheel alignment	10/10/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Susp\SUSPENSION	Left Middle spring wrapper broken	REPLACED.	10/10/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Comp\Truck Safe	NHVR sticker unreadable		10/10/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Body\REFLECTORS	loghaul sign unreadable		10/10/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Susp\SUSPENSION	Left Middle spring wrapper broken		23/09/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Body\REFLECTORS	loghaul sign unreadable		23/09/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Tyres	CHECK TYRES.		23/09/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Susp			23/09/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Chassis\WINCH/STRP	No 6 QUICK RELEASE CORD BROKEN OFF.		23/09/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		23/09/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		23/09/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Comp\Truck Safe	NHVR sticker unreadable		23/09/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Albury - Workshop	Tyres\RUN OUT	7	ORGANISED PARTS, PACKED VAN & TRAVELLED TO BREAKDOWN AT TUMUT DEPOT.	21/09/2023	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
				INSPECTED TRAILER & IDENTIFIED FAULTY AXLE 3 LHS BRAKE BOOSTER.							
				REPLACED BRAKE BOOSTER & TENSIONED BOLTS AS REQUIRED. CONNECTED AIR							
			ATTEND CALLOUT OFFSITE AT TUMUT DEPOT @ 222 SNOWY MTS HWY	TO TRAIELR & ADJUSTED BRAKES. ALL TEST OK.							
			CHECK AND REPAIR CAUSE OF BROKEN BOOSTER MOUNTING BOLTS AXLE 3 LHS	RETURNED THE TRAILER TO SERVICE. PACKED VAN & TRAVELLED BACK TO THE							
T383	Albury - Workshop	Brakes\BOOSTER	DRIVERS NUMBER: DEAN - 0400497098	WORKSHOP.	07/09/2023	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Wodonga - Workshop	Chassis\WINCH/STRP	No 6 QUICK RELEASE CORD BROKEN OFF.		03/09/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		03/09/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		03/09/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		13/08/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		13/08/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Albury - Workshop	Tyres\TP9+10	Tyre Position 9 + 10		12/08/2023	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Tyres\TP5+6	Tyre Position 5 + 6		12/08/2023	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Tyres\TP11+12	Tyre Position 11 + 12		12/08/2023	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Wodonga - Workshop	Chassis\STRAPS	TIE DOWN CHAIN TOO SHORT (REPLACE)	COMPLETED BY COCHISE LOVE.	29/07/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job	PERFORMED BY COCHISE LOVE.	29/07/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	COCHISE LOVE LABOUR 12:00-13:30	29/07/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Albury - Workshop	Tyres\TP09	Tyre Position 9		27/07/2023	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Tyres\TP01	Tyre Position 1		27/07/2023	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Wodonga - Workshop	Chassis\WINCH/STRP	No 6 QUICK RELEASE CORD BROKEN OFF.		15/07/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		15/07/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		15/07/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Chassis\STRAPS	TIE DOWN CHAIN TOO SHORT (REPLACE)		21/06/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		21/06/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		21/06/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Albury - Workshop	Tyres\TP5+6	runouts		17/06/2023	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Wodonga - Workshop	Chassis\WINCH/STRP	No 6 QUICK RELEASE CORD BROKEN OFF.		15/06/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		15/06/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		15/06/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
				- Raise and support axles							
T383	Wodonga - Workshop	Steering\WHEEL BRGS	DURING SERVICE FOUND ALL WHEEL BEARINGS REQUIRE ADJUSTMENT	- Adjust all bearings as required	16/05/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Susp\SHOCK ABS	FIT SHOCK AFTER WELD REPAIR	FABRICATE MOUNTS FOR SHOCKIE BRACKET	16/05/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
				- Remove u-bolts and spring eye.							
				- Lower spring and replace wrap.							
				- Replace air bag and refit spring.							
				- Refit u-bolts and lower axle.							
T383	Wodonga - Workshop	Susp\SPRNG HANG	DURING SERVICE FOUND LHM SPRING WRAP BROKEN AND AIRBAG PERISHED	- Tenion all components.	16/05/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Unknown	SERVICE.		16/05/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection		16/05/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Chassis\WINCH/STRP	No 6 QUICK RELEASE CORD BROKEN OFF.		16/05/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Chassis\STRAPS	TIE DOWN CHAIN TOO SHORT (REPLACE)		16/05/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		16/05/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		16/05/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Albury - Workshop	Tyres\TP3+4	Tyre Position 3 + 4		14/05/2023	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Tyres\FITMENT	Fitment		03/05/2023	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		29/04/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		29/04/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		20/04/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		20/04/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		06/04/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		06/04/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Unknown	SERVICE.		06/04/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		31/03/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		31/03/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Elect\ELECT P&W	NO SCALES ON BAY 1.		24/03/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		24/03/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		24/03/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		17/03/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		17/03/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Unknown	DUE FOR B SERVICE.		08/03/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Elect\ELECT P&W	LIGHT ON SECOND BOLSTER R/H/S NOT WORKING.		08/03/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		08/03/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		08/03/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Albury - Workshop	Tyres\TP11+12	Tyre Position 11 + 12		08/03/2023	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		24/02/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		24/02/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Chassis\BOLSTER	TURNED FRONT PEGS. REPLACED RR PISTOL AND REALIGNED BOLSTER.		10/02/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes\BRK RELINE	RELINED LR LF RF RM. REPLACED WHEEL SENSORS AND LR BEARINGS AND DRUM.		10/02/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Chassis\BOLSTER	FRONT L/H BOLSTER IS BENT.		10/02/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Chassis\WINCH/STRP	SECOND STRAP NEED'S REPLACING.		10/02/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Chassis\EXTE TU	SECOND STRAP HARD TO UNHOOK OFF WINCH.	COULDN'T FAULT.	10/02/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Elect\ELECT P&W	R/H/S SECOND BOLSTER LIGHT BROKEN.		10/02/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Chassis\WINCH/STRP	SECOND STRAP NEEDS REPLACING.		10/02/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Body\MUDGUARDS	LEFT HAND MUDGUARD HAD LOG DROPPED ON IT. NEEDS SOME NEW BOLTS.	STRAIGHTENED AND WELDED OUTRIGGER MOUNTS. FITTTED OUTRIGGER AND STRETCH GUARD.	10/02/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		10/02/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	INSPECTED AND ADJUSTED LF WHEEL BEARING. TURNED LF RF PEGS.	10/02/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Chassis\WINCH/STRP	SECOND STRAP NEEDS REPLACING.		19/01/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Comp\Truck Safe	REPLACE NHVAS STICKER.		19/01/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		19/01/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		19/01/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Chassis\WINCH/STRP	Replaced 2nd Winch Strap		19/01/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Body\MUDGUARDS	Replaced Missing Bolts For LH Stretchguard		19/01/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Chassis\WINCH/STRP	SECOND STRAP NEEDS REPLACING.		10/01/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Susp\SHOCK ABS	MISSING 2 SHOCKS.		10/01/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Comp\Truck Safe	REPLACE NHVAS STICKER.		10/01/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		10/01/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		10/01/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Comp\Truck Safe	REPLACE NHVAS STICKER.		04/01/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Elect\ELECT P&W	CHECK LIGHTS. PARKERS. INDICATORS.		04/01/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Elect\WORK LIGHT	NO WORK LIGHT. BLOWING FUSE.		04/01/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER

T383	Wodonga - Workshop	Hydraulics\RAM	REPLACE LEAKING BOLSTER RAM.		04/01/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Chassis\CROSS MBR	CRACKS IN CROSSMEMBERS AND GUSSETS.		04/01/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		04/01/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		04/01/2023	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Albury - Workshop	Tyres\TP9+10	Tyre Position 9 + 10		21/12/2022	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Tyres\TP11+12	Tyre Position 11 + 12		21/12/2022	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Tyres\TP1+2	Tyre Position 1 + 2		21/12/2022	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		17/12/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist Broken shock mounts bottom. Left Centre axle.		17/12/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Susp\SHOCK ABS	Right rear axle.	REPLACED RR LF BOTTOM SHOCK MOUNTS.	07/12/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		07/12/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist Broken shock mounts bottom. Left Centre axle.	FITTED 2 SHOCKS.	07/12/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Susp\SHOCK ABS	Right rear axle.		30/11/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		30/11/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		30/11/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		23/11/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		23/11/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Susp	TRAILERS TRACK OUT OF LINE TOO L/H/S.	REPLACED LF SEB.	16/11/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Susp	L/H MIDDLE SHOCK MISSING.		16/11/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Elect\ELECT P&W	CRAIG BROKE L/H/R CLEARANCE LIGHT. Broken shock mounts bottom. Left Centre axle.		16/11/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Susp\SHOCK ABS	Right rear axle.		16/11/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Chassis\BOLSTER	FIT LONGER PEGS TO REAR BAY.		16/11/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		16/11/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		16/11/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Susp\SHOCK ABS	Missing shocks, base mounts broke off. Broken shock mounts bottom. Left Centre axle.	Refer Job# 395376.	09/11/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Susp\SHOCK ABS	Right rear axle.		09/11/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes\AIR LEAK	REPAIR AIR LEAK.		09/11/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Chassis\BOLSTER	FIT LONGER PEGS TO REAR BAY.		09/11/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes\BRK RELINE	RELINE LR.		09/11/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Susp\SHOCK ABS	REPLACE LM BOTTOM SHOCK MOUNT.	Refer Job# 395376.	09/11/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Susp\SHOCK ABS	LM LOWER SHOCK MOUNT SNAPPED.	Refer Job# 395376.	09/11/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes\BRK RELINE	RELINE LR.	Pad Slap	09/11/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		09/11/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		09/11/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes\BRK RELINE	RELINE LR.		29/10/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		29/10/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		29/10/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Susp\SHOCK ABS	REPLACE LM BOTTOM SHOCK MOUNT.		21/10/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		21/10/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	REPAIRED AIR LEAK RF AXLE.	21/10/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes\VALVES	REPLACE MAXI VALVE.	DIAGNOSED AND REPLACED MAXI VALVE.	17/10/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		14/10/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Unknown	SERVICE.		14/10/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Susp\SHOCK ABS	LM LOWER SHOCK MOUNT SNAPPED.		14/10/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes\BRK RELINE	RELINE LR.		14/10/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Elect\ELECT P&W	R/H NUMBER PLATE LIGHT HANGING.		14/10/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		14/10/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Body\AIR LEAK	Air Leak Around Tri		11/10/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes\AIR LEAK	AIR LEAK AROUND TRI.		11/10/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		05/10/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		05/10/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Myrtleford - Workshop	Susp\SHOCK ABS	REPLACE BROKEN BOTTOM SHOCK MOUNT.		01/10/2022	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Wodonga - Workshop	Brakes\BRK RELINE	RELINE LR.		01/10/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		01/10/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		01/10/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes\BRK RELINE	RELINE LR.		21/09/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job	CARRY OUT GREENFREIGHT LOG TRAILER D-SERVICE AS PER ATTACHED SERVICE SHEET. - Tightened LHF, RHR & LHR shocks	21/09/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	- Adjust axle 2 & 3 wheel bearings	21/09/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Susp\HCV	HEIGHT CONTROL VALVE NOT CORRECT. HAD TO REPAIR IN BUSH.		21/09/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Susp\HCV	HEIGHT CONTROL VALVE NOT CORRECT. HAD TO REPAIR IN BUSH.		20/09/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Body\SUSPENSION	Adjust Suspension		20/09/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Body\MUDGUARDS	STRAIGHTENED LF OUTRIGGER.		17/09/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Elect\ELECT P&W	R/H NUMBER PLATE LIGHT HANGING.		17/09/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Unknown	SERVICE.		17/09/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		17/09/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		17/09/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Unknown	SERVICE.		17/09/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Albury - Workshop	Tyres\TP05	fit runout		15/09/2022	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Tyres\TP9+10	Tyre Position 9 + 10		15/09/2022	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Tyres\TP3+4	supply and fit 4 tyres		15/09/2022	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Tyres\TP03	fit runout		08/09/2022	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Tyres\TP1+2	supplya nd fit 2tyres		08/09/2022	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Wodonga - Workshop	Body\BOLSTER	Check alignment of third bolster		02/09/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		02/09/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		02/09/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Susp\SHOCK ABS	REPLACE BROKEN BOTTOM SHOCK MOUNT.		02/09/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes\AIR LEAK	AIR LEAK UNDER TRI.	DIAGNOSED AND REPLACED RUBBED MAXI HOSE. FITTED PROTECTION.	01/09/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Chassis\STRAPS	SAFETY CHAIN BROKEN.	REPLACED.	30/08/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes\BRK RELINE	RELINE LR.		27/08/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Susp\WHEEL ALGN	TRAILER NOT TRACKING STRAIGHT. (CRAB WALKING)		27/08/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Body\MUDGUARDS	STRETCH GUARD SUPPORT L/H/S BENT. (GUARD LOOSE)		27/08/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Susp\SHOCK ABS	LHM shock missing		27/08/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		27/08/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		27/08/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Body\MUDGUARDS	REMOVED STRETCH GUARD.		20/08/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Albury - Workshop	Tyres\TP11+12	supply and fit 2 tyres		19/08/2022	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Wodonga - Workshop	Elect\TRL LIGHTS	NO LIGHTS.		17/08/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Unknown	SERVICE.		17/08/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Susp\SHOCK ABS	REPLACE BROKEN BOTTOM SHOCK MOUNT.		17/08/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Susp\SHOCK ABS	LHM shock missing		17/08/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		17/08/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		17/08/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Unknown	SERVICE.		17/08/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Albury - Workshop	Tyres\TP9+10	supply and fit 2tyres		03/08/2022	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		29/07/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER

T383	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	HEATED AND STRAIGHTENED RH SKID RAIL.	29/07/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		23/07/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		23/07/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService	Service		23/07/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Susp\SHOCK ABS	LM SHOCK MISSING.	#387186	23/07/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Susp\AXLES	LM U-BOLT SADDLE BROKEN PEG.	#387185	23/07/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Susp\SHOCK ABS	LHM shock missing		23/07/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Susp\SHOCK ABS	REPLACE BROKEN BOTTOM SHOCK MOUNT.		23/07/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Albury - Workshop	Tyres\TP5+6	supply and fit 2tyres		20/07/2022	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Wodonga - Workshop	Susp\SHOCK ABS	LM SHOCK MISSING.		16/07/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Susp\AXLES	LM U-BOLT SADDLE BROKEN PEG.		16/07/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Unknown	SERVICE.		16/07/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	DrCabElect\SCALES	Scales erratic back bay	INSPECTED. CLEANED PLUG.	16/07/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService	Service		16/07/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Susp\SHOCK ABS	LHM shock missing		16/07/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Susp\SHOCK ABS	REPLACE BROKEN BOTTOM SHOCK MOUNT.		16/07/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		16/07/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		16/07/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		07/07/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	REMOVED ALL WINCHES AND LUBRICATED. REFITTED.	07/07/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Susp\SHOCK ABS	Broken lower shocker mount (LHR)		01/07/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Susp\AIR BAG	LHM Airbag		01/07/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		01/07/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		01/07/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Susp\SHOCK ABS	LHM shock missing		24/06/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Susp\SHOCK ABS	REPLACE BROKEN BOTTOM SHOCK MOUNT.		24/06/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		24/06/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	Cleared EBS faults & adjusted all RHS bearings	24/06/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Susp\AIR BAG	Replaced LH middle air bag		21/06/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		21/06/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		21/06/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Susp\SHOCK ABS	Broken lower shocker mount (LHR)		16/06/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Susp\AIR BAG	LHM Airbag		16/06/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		16/06/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		16/06/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Unknown	SERVICE.		07/06/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Susp\AIR LEAK	AIR LEAK UNDER TRI, SUSPENSION ALWAYS GOING DOWN.		07/06/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		07/06/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		07/06/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Unknown	SERVICE.		07/06/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Chassis\BOLSTER	RAISED FIRST BAY BOLSTERS.		02/06/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		01/06/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	TIGHTENED 3RD BOLSTER PIVOT BOLTS.	01/06/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Susp\SUSPENSION	STARTING TO CRAB WALK TO THE LEFT.		20/05/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Chassis\WINCH/STRP	FRONT WINCH NEEDS NEW STRAP.		20/05/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Unknown	SERVICE		20/05/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes\ABS	ABS		20/05/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Susp\SHOCK ABS	REPLACE BROKEN BOTTOM SHOCK MOUNT.		20/05/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		20/05/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		20/05/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Albury - Workshop	Tyres\TP3+4	Tyre Position 3 + 4		15/05/2022	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Tyres\TP1+2	supply and fit 4 tyres		15/05/2022	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Wodonga - Workshop	Chassis\CHAS CRACK	Right hand Chassis Rail crack repair		13/05/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Susp\SHOCK ABS	REPLACE BROKEN BOTTOM SHOCK MOUNT.		07/05/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Unknown	SERVICE.		07/05/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Susp\SCALES	SCALES PLAYING UP ON CH 3. REPLACE HEIGHT CONTROL VALVE?		07/05/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		07/05/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	TIGHTENED LR BOOSTER MOUNT NUTS. REMOVED LM SHOCK.	07/05/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Albury - Workshop	Tyres\TP11+12	supply and fit 2tyres		03/05/2022	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		28/04/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		28/04/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Susp\SUSPENSION	TRAILER CRAB WALKING.	INSPECTED ALL SUSPENSION COMPONENTS. COULDN'T FAULT.	28/04/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		21/04/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	REPLACED LM BOOSTER AND RF SHOCK.	21/04/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Unknown	SERVICE.		13/04/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		13/04/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		13/04/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Elect\ELECT P&W	SCALES FAULTY.	CLEANED OUT PLUG/ SOCKET. MOVED REAR BAY BOLSTER PEGS UP ONE HOLE.	08/04/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		06/04/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		06/04/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Albury - Workshop	Tyres\TP11	Tyre Position 11		06/04/2022	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Tyres\TP7+8	supply and fit 2tyres and 1 runout		06/04/2022	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Wodonga - Workshop	Chassis\HYDRAULICS	2ND LAST BOLSTER NOT COMING UP.		01/04/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Body\BOLSTER	SECOND LAST BOLSTER NOT STANDING UP.	ADDED 2ND HYDRAULIC RAM.	01/04/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Chassis\HYDRAULICS	2ND LAST BOLSTER NOT COMING UP.		29/03/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Body\BOLSTER	SECOND LAST BOLSTER NOT STANDING UP.		29/03/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		29/03/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	CLEARED EBS CODES.	29/03/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Albury - Workshop	Tyres\TP9+10	supply and fit 2tyres		22/03/2022	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Wodonga - Workshop	Unknown	SERVICE		16/03/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Chassis\HYDRAULICS	2ND LAST BOLSTER NOT COMING UP.		16/03/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Body\BOLSTER	SECOND LAST BOLSTER NOT STANDING UP.		16/03/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		16/03/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		16/03/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		09/03/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		09/03/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		01/03/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		01/03/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection		15/02/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Body\WHL HUB	collapse wheel bearing, third axle right side		15/02/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		15/02/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
				FITTED 2ND HYDRAULIC RAM TO 3RD BOLSTER TO HELP LIFT.							
T383	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	ADJUSTED RIDE HEIGHT.	15/02/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Albury - Workshop	Tyres\TP06	supply and fit 1 tyre		01/02/2022	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Wodonga - Workshop	VehService\DS	SERVICE AS PER CHECK SHEET		01/02/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Chassis\STRAPS	REPAIRED BROKEN TRAILER HOLD DOWN CHAIN.		01/02/2022	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
			Hartrites - Supply Ryco field attachable fittings as requested								
T383	Rosewood - Workshop	Hydraulics\HOSES	Delivered to Rosewood w/shop by Rohan		21/12/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
				* Found rear parker light not working							
				* Tested wiring for light/all ok							
				* Removed/replaced light as required							
				* Tested light operation/all ok							
T383	Albury - Workshop	Elect\ELECT P&W	REPAIR FAULTY PARK LIGHT - 29/11/21	* Repair complete	15/12/2021	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER

T383	Albury - Workshop	Susp\SPRNG HANG	REPLACE BROKEN L/H MIDDLE SPRING WRAP - 29/11/21	* Removed shocker & air bag * Removed U-bolts & spring eye bolt * Lowered spring & removed spring wrap * Installed new spring wrap & mounted spring * Installed U-bolts & spring eye bolt * Installed shocker & air bag * Tensioned U-bolts * Repair complete * Raised & supported front axle * Removed wheel required wheel equipment * Removed hub & brakes * Inspected s-cam bushes/all ok * Removed hub seal from hub * Found rear of hub had excessive wear & grooves * Ordered in new hub & bearings * Installed bearings into new hub * Reinstalled hub, found hub hard to spin * Backed off brakes & found it still hard to spin * Removed hub back off axle & inspected * Found no faults with hub * Removed opposite side hub & swapped over * Found both hubs spinning freely * Adjusted wheel bearings & brakes * Lowered down axle & tensioned wheels * Greased required components * Road tested then rechecked wheel bearing adjustment/all ok	15/12/2021	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Brakes\BRK RELINE	CARRY OUT BRAKE RELINE ON L/H FRONT AXLE - 29/11/21 - 2/12/21	* Repair complete	15/12/2021	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	VehService\DS	CARRIED OUT GREENFREIGHT TRAILER D-SERVICE WITH SERVICE SHEET PROVIDED - 29/11/21		15/12/2021	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Tyres\TP7+8	Tyre Position 7 + 8		26/11/2021	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Tyres\TP5+6	supply and fit 4 tyres		26/11/2021	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
			-test drove vehice after long running mis-informed complaint from 1 particular driver. Other driver has none of the issues -did a load ex Rosewood empty to Shelley folded up, Shelley to Tumbarumba at 64 B double -not once did trailer brakes "slam on" by themselves -vehicle does not pull to the left, it actually drives very well								
T383	Rosewood - Workshop	Workshop\MOVE ASSET	-one gear shift was a bit clunky, but I feel that was my fault tested a/c vent temp was 6-9°c		19/11/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	Air Con\AIR CON	engine brakes work perfectly with no unusual noises		18/11/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	Chassis\HYDRAULICS	replace hydraulic fitting		18/11/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	Body\AIR FITTIN	replace fitting on B Trailer		18/11/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	Body\AIR FITTIN	replace fitting on B Trailer		18/11/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		17/11/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	Susp\HCV	adjust ride height, was 40mm too low		17/11/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	VehService\DS	D Service		17/11/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	VehService\DS	D Service		11/11/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		11/11/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Albury - Workshop	Brakes\ABS	REPLACE BROKEN WHEEL SPEED SENSORS - 8/11/21	* Inspected & diagnosed failed L/H rear wheel speed sensor * Removed wheel equipment for access * Removed/replaced sensor * Reinstalled wheel equipment * Repair complete * Raised L/H middle & R/H rear axles * Removed required wheel equipment * Removed brakes & s-cams * Replaced s-cam bushes & s-cams * Installed new brake shoes * Cleaned & repacked wheel bearings * Reinstalled wheel equipment * Adjusted bearings & brakes * Lowered down axles	09/11/2021	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Brakes\BRK RELINE	CARRY OUT BRAKE RELINE - 8/11/21	* Repair complete	09/11/2021	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Rosewood - Workshop	Brakes\AIR LEAK	repair blown air hose at coupling		06/11/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		04/11/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	Brakes\EBS Kit	check ABS/EBS codes. Only current code EPRV slow wheel recovery. Possibly due to lock up?		04/11/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	VehService\DS	D Service		04/11/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Albury - Workshop	Tyres\RETREAD	Tyres bolted on by driver no wheel POS given		27/10/2021	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		21/10/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	Chassis\BOLSTER	turn 1st and 4th left pegs and 2nd, 3rd and 4th right pegs		21/10/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	VehService\DS	D Service		21/10/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		21/10/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	Chassis\BOLSTER	turn 1st and 4th left pegs and 2nd, 3rd and 4th right pegs		21/10/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	VehService\DS	D Service		21/10/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	DriCabRep\WIPERS	nearly all the bolsters need turning around		20/10/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	DriCabRep\WIPERS	all the bolsters need turning around		20/10/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Albury - Workshop	Brakes\BRK RELINE	CARRY OUT BRAKE RELINE ON RHM & LHR AXLES AS REQUIRED - 16/10/21	* Raised & supported both axles * Removed required wheel equipment * Removed brakes & s-cams * Replaced s-cams bushes as required * Installed new brakes & secured * Cleaned & inspected wheel bearings/all ok * Reinstalled required wheel equipment * Adjusted brakes & wheel bearings * Lowered down axles * Repair complete	17/10/2021	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Rosewood - Workshop	DrivLine\AIR LEAK	air leaks		14/10/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	VehService\DS	Service		14/10/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	DrivLine\AIR LEAK	air leaks		14/10/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	VehService\DS	Service		14/10/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		14/10/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	VehService\DS	D Service		14/10/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	Tyres\DAMAGE	replace damaged rim from dmaage from rod		09/10/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		07/10/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	VehService\AS	A Service		07/10/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Tumut - Workshop	Tyres\TP05	fit runout		29/09/2021	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		17/09/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	VehService\DS	D Service		17/09/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		11/09/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	VehService\DS	D Service		11/09/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	VehService\DS	Service		08/09/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	Chassis\DAMAGE	replace 2nd ned kelly pistol on outside left. Cracked		01/09/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		27/08/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	VehService\DS	D Service		27/08/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Tumut - Workshop	Tyres\TP11+12	Supply and fit 2 tyres		21/08/2021	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		20/08/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER

T383	Rosewood - Workshop	Susp\SHOCK ABS	replace missing RHM upper shock mount nut		20/08/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	VehService\DS	D Service		20/08/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		30/07/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	Body\WHL HUB	adjust all wheel bearings		30/07/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	VehService\DS	D Service		30/07/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Tumut - Workshop	VehService\DS	CARRY OUT GREENFREIGHT LOG TRAILER D-SERVICE AS PER ATTACHED SERVICE SHEET - 24/7/21		25/07/2021	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		21/07/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	VehService\DS	D Service		21/07/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	Susp\AXLES	swap rear axle with one sent from Wodonga out of T324		10/07/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	Body\WHL HUB	collapse wheel bearing, third axle right side diagnose RHR wheel bearing very hot strip down wheel/axle/bearing #bearing/hub stuck on axle, heat/cut off axle and inspect axle bent from heat, bearing inner race melted to axle		01/07/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	Susp\AXLES	take details to check into axle availability		01/07/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		26/06/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	DrCabElect\DS	D Service		26/06/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	Elect\WORK LIGHT	no work light	outsource work lights to TAE on shift change	16/06/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	Chassis\WINCH/STRP	lubricate winches		06/06/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	Chassis\WINCH/STRP	fit new winch strap		06/06/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	Elect\TRL LIGHTS	fit new number plate light		06/06/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	Elect\WORK LIGHT	fit new reverse light		06/06/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		03/06/2021	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	VehService\DS	D Service		03/06/2021	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Tumut - Workshop	Susp\HCV	adjust ride height valves	adjust ride height valve	29/05/2021	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		27/05/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	VehService\DS	D Service		27/05/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Tumut - Workshop	Tyres\TP7+8	Supply and fit 2 tyres - Bald on the inside edge of tyres		26/05/2021	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Rosewood - Workshop	Elect\TRL LIGHTS	number plate light not working remove and replace stretch guard		25/05/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	Body\STCH GUARD	broken bolts while removing		20/05/2021	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		13/05/2021	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	VehService\DS	D Service		13/05/2021	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		04/05/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	VehService\DS	D Service		04/05/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		21/04/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	VehService\DS	D Service		21/04/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		07/04/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	VehService\DS	D Service		07/04/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Tumut - Workshop	VehService\DS	D Service		02/04/2021	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	Chassis\WINCH/STRP	winches tight		26/03/2021	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	Chassis\WINCH/STRP	lubricate winches		26/03/2021	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Albury - Workshop	Tyres\TP3+4	Tyre Position 3 + 4		26/03/2021	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Tyres\TP1+2	Supply and fit 4 tyres		26/03/2021	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Tumut - Workshop	VehService\DS	CARRY OUT GREENFREIGHT LOG TRAILER D-SERVICE AS PER ATTACHED SERVICE SHEET. 24/03/2021 DURING SERVICE FOUND: * RHM airbag leaking	CARRY OUT BRAKE RELINE 17/03/2021 Unfold trailer and inspected brakes Found LH rear requires reline. Removed hub and wheel bearings Washed bearings Removed s-cam and replaced s-cam bushes Re-utilised s-cam Repacked bearings and hub as required Refit hub and adjusted bearings and bearings & brakes.	25/03/2021	Completed	Colac	GTK	37690S	Tumut Plant Hire - 4	TRAILER
T383	Tumut - Workshop	Brakes\BRK RELINE	Supply Crake shoe kit, Camshaft repair kit and consumables for Reline LHR	All ok.	18/03/2021	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	Susp\HCV	adjust/check ride height after installation check ok		12/03/2021	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	Susp\AIR FITTIN	ride height valve hit by log broke fitting and housing change		12/03/2021	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job		10/03/2021	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	VehService\DS	D Service		10/03/2021	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job		10/03/2021	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	VehService\DS	D Service		10/03/2021	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Myrtleford - Workshop	Brakes	Record Check Results As Atttached To This Job		10/03/2021	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	VehService\DS	D Service		10/03/2021	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Tumut - Workshop	Tyres\TP9+10	Supply and fit 2 tyres		09/03/2021	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Tumut - Workshop	Tyres\TP5+6	Supply and fit 2 tyres		05/03/2021	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Rosewood - Workshop	Brakes	Record Check Results Attached To This Job		04/03/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	VehService\DS	Carried out D Service		04/03/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		16/02/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	VehService\DS	D Service		16/02/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	VehService\DS	as per T382 serviced properly following TCTC serviced on 29/01/21		02/02/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		02/02/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	VehService\DS	D Service		02/02/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Tumut - Workshop	Tyres\TP11+12	replace 2 tyres		20/01/2021	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Rosewood - Workshop	Chassis\BOLSTER	spin LH bolster peg		14/01/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		12/01/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	VehService\DS	D Service		12/01/2021	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	Chassis\WINCH/STRP	lubricate winches and free up shafts		18/12/2020	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job		15/12/2020	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	VehService\DS	D Service Carry out greenfreight log trailer D-Service as per attached service sheet.		15/12/2020	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	VehService\DS	Adjusted front Axle		02/12/2020	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Rosewood - Workshop	VehService\DS	D Service Due 500km		20/11/2020	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		21/10/2020	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	VehService\DS	D Service		21/10/2020	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		02/10/2020	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	VehService\DS	D Service		02/10/2020	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Tumut - Workshop	Body\MUDGUARDS	crivers side guard torn off		29/09/2020	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	Body\STCH GUARD	plastic guard R/hand side over tri torn (stretch guard)		26/09/2020	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	VehService\DS	D Service		17/09/2020	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job Service As Per Attached Checklist		16/09/2020	Completed	Colac	GTK	37690S	TWIN CITY TRUCK CENTRE - OLD	TRAILER
T383	Myrtleford - Workshop	VehService\DS	Order Number TU9688	Carried out D Service	16/09/2020	Completed	Colac	GTK	37690S	TWIN CITY TRUCK CENTRE - OLD	TRAILER
T383	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		01/09/2020	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	VehService\DS	D Service		01/09/2020	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	Body\AIR LEAK	air tank valve leaking badly after you pull wire too empty valve stays open	Phil Nolte replaced air drain valve	23/08/2020	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job D Service		12/08/2020	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	VehService\DS	adjusted RLH & MRH wheel bearings		12/08/2020	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Wodonga - Workshop	Susp\SUSPENSION	crack on spring eye boss LHS frint	RR's pre Jan 20 (system clean out) 05/08/20	06/08/2020	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		31/07/2020	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER

T383	Rosewood - Workshop	VehService\DS	D Service		31/07/2020	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job	greased and adjusted brakes	16/07/2020	Completed	Colac	GTK	37690S	TWIN CITY TRUCK CENTRE - 4 - OLD	TRAILER
			Service As Per Attached Checklist								
T383	Tumut - Workshop	VehService\DS	Order Number # TU 9121	carried out service as required	16/07/2020	Completed	Colac	GTK	37690S	TWIN CITY TRUCK CENTRE - 4 - OLD	TRAILER
T383	Tumut - Workshop	Elect\TRL LIGHTS	remove and fit new clearance light		12/07/2020	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Rosewood - Workshop	Body\HOUSEKEEP	attend Tumut depot to check over for Service and repairs needed		08/07/2020	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job		24/06/2020	Completed	Colac	GTK	37690S	TWIN CITY TRUCK CENTRE - 4 - OLD	TRAILER
			Service As Per Attached Checklist								
T383	Tumut - Workshop	VehService\DS	Order Number # TU8916		24/06/2020	Completed	Colac	GTK	37690S	TWIN CITY TRUCK CENTRE - 4 - OLD	TRAILER
T383	Tumut - Workshop	Chassis\BOLSTER	1 bolster LHS needs turning		05/06/2020	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	Elect\TRL LIGHTS	RHS bolster clearance light broken		05/06/2020	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	VehService\DS	D Service		05/06/2020	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job		05/06/2020	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
			adjust M/R axle bearing								
T383	Tumut - Workshop	DrivLine\WHEEL BRGS	R&R 120651		05/06/2020	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	VehService\DS	D Service		05/06/2020	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job		23/05/2020	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	VehService\DS	D Service		23/05/2020	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	Elect\TRL LIGHTS	fit clearance lights		13/05/2020	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
			LHS tail light not working								
T383	Tumut - Workshop	Elect\TRL LIGHTS	RHS brake light not working	lights change led cells	13/05/2020	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		09/05/2020	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	VehService\DS	D Service		09/05/2020	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Tumut - Workshop	Tyres\DAMAGE	change flat tyre		03/05/2020	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	Chassis\STRAPS	order new winch system		28/04/2020	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Myrtleford - Workshop	DrCabElect\SCALES	Scales Not Reading Correctly- Driver To Monitor	check all scale plugs and check scales all 3 channels working	21/04/2020	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Elect\WORK LIGHT	load lights not working		21/04/2020	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		18/04/2020	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	VehService\DS	D Service		18/04/2020	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
			check EBS system for codes. IA speed sensor continuilly from 6,000 km previous only thing reset								
			and will monitor								
T383	Rosewood - Workshop	Brakes\EBS Kit	clean EBS plug and sort firmly (may not have been so)		02/04/2020	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		28/03/2020	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	VehService\DS	D Service As Per Attached Checklist		28/03/2020	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Tumut - Workshop	Brakes\AIR LEAK	PO FOR BRAKES		20/03/2020	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	Elect\WORK LIGHT	No Work Light		15/03/2020	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job		15/03/2020	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	VehService\DS	D Service		15/03/2020	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	Susp\AIR BAG	airbags leaking LHS 1st & 3rd axle	change airbags LHS 1st & 3rd axle	06/03/2020	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	Elect\WORK LIGHT	work lights not working off switch		06/03/2020	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	Brakes\BRK O/HAUL	rear two axles running hot	check bearing temps on trailer running at 50°-60°	06/03/2020	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Albury - Workshop	Chassis\WHL HUB	Hubcap replaced		01/03/2020	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Albury - Workshop	Susp\AIR LEAK	air leak around suspension	repaired suspension leaks	28/02/2020	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Elect\WORK LIGHT	load lights not working		28/02/2020	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Susp\WGHT GAUGE	scales not working		28/02/2020	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	DrivLine\WHL HUB	R/H front axle end cap missing	replaced RF hub cap	28/02/2020	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Workshop\MOVE ASSET	hooked up		26/02/2020	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
			checked ABS. unconfigured. Wrong fitment,								
			repaired sensors incorrectly adjusted, service brake lines wrong, sensor looms wrong, wheel								
			bearings loose and contaminated from nut rubbing on hubs								
			configured								
T383	Albury - Workshop	Brakes\EBS FAULTS	tested		26/02/2020	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Chassis\WINCH/STRP	fit up air winches from T400-T401		21/02/2020	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Albury - Workshop	Workshop\MOVE ASSET	unhooked. Hooked up T398/399		20/02/2020	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	DrCabElect\IAP	installed in ecm. Several other faults		20/02/2020	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Brakes\ABS	abs light on checked codes. No configuration		20/02/2020	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Tumut - Workshop	Chassis\EXTE TU	fit up air winches to trailer replace straps x 4 and fit remote release		19/02/2020	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		14/02/2020	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Brakes\BOOSTER	reposition RHR booster		14/02/2020	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Chassis\MUDGUARDS	tension both guard		14/02/2020	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
			trailer service inspection after EBS								
T383	Albury - Workshop	VehService\DS	fit up		14/02/2020	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Myrtleford - Workshop	Chassis\TRL ROLLBK	slider locks not working		05/02/2020	Completed	Colac	GTK	37690S	SHEPPARTON MOTOR PANEL- 4	TRAILER
T383	Myrtleford - Workshop	VehService\DS	D Service Due		05/02/2020	Completed	Colac	GTK	37690S	SHEPPARTON MOTOR PANEL- 4	TRAILER
T383	Myrtleford - Workshop	Elect\TRL LIGHTS	LHS clearance light bolster x2		05/02/2020	Completed	Colac	GTK	37690S	SHEPPARTON MOTOR PANEL- 4	TRAILER
T383	Myrtleford - Workshop	Elect\WORK LIGHT	no work lights		05/02/2020	Completed	Colac	GTK	37690S	SHEPPARTON MOTOR PANEL- 4	TRAILER
T383	Myrtleford - Workshop	Body\MUDGUARDS	B Trailer RH side mudguard shorting to break weld		05/02/2020	Completed	Colac	GTK	37690S	SHEPPARTON MOTOR PANEL- 4	TRAILER
T383	Myrtleford - Workshop	Body\MUDGUARDS	right hand side mudguard broken		05/02/2020	Completed	Colac	GTK	37690S	SHEPPARTON MOTOR PANEL- 4	TRAILER
T383	Myrtleford - Workshop	Brakes\AIR LEAK	RHR BOOSTER HOSE LEAKING		05/02/2020	Completed	Colac	GTK	37690S	SHEPPARTON MOTOR PANEL- 4	TRAILER
T383	Myrtleford - Workshop	Body\MUDGUARDS	LH GUARD FLAP NEEDS TO BE TIGHTENED		05/02/2020	Completed	Colac	GTK	37690S	SHEPPARTON MOTOR PANEL- 4	TRAILER
T383	Myrtleford - Workshop	Steering\SHOCK ABS	needs new straps		05/02/2020	Completed	Colac	GTK	37690S	SHEPPARTON MOTOR PANEL- 4	TRAILER
T383	Myrtleford - Workshop	Brakes\EBS Kit	test and certify ebs system		31/01/2020	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Chassis\BOLSTER	replace 1 bolster and mounts		27/11/2019	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Susp\HOUSEKEEP	repairs to suspension		27/11/2019	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Body\MOUNTS	replace 2x shocker mounts		27/11/2019	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Susp\SHOCK ABS	fit 3x shockers		27/11/2019	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Brakes\BRK O/HAUL	fit 6x s/cams and bushes		27/11/2019	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Brakes\BACK PLATE	fit dust covers		27/11/2019	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Brakes\BRK RELINE	fit 6x brake drums		27/11/2019	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Brakes\BRK RELINE	reline all brakes		27/11/2019	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Brakes\EBS Kit	fit EBS kit		16/10/2019	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Albury - Workshop	Body\RWC COMP	full check over, write out list for repairs		03/10/2019	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		10/08/2019	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	Chassis\HOUSEKEEP	booster hose clamps		10/08/2019	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	VehService\DS	Service		10/08/2019	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Albury - Workshop	VehService\DS	D Service Due in 1,200km		10/08/2019	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Rosewood - Workshop	VehService\DS	D Service		02/08/2019	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	DrCabElect\SCALES	scales not working	scales not working undo connector spray male and female ends with contact cleaner refit and tighten	20/07/2019	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Wodonga - Workshop	Elect\WORK LIGHT	Load lights not working	Change blown fuse, lights are working on truck	20/07/2019	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Body\CHN/RLR/MN	Fit new tie down chain		20/07/2019	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Wodonga - Workshop	Brakes\BRAKE ADJ	Adjusted brakes		19/07/2019	Completed	Colac	GTK	37690S	Wodonga Workshop	TRAILER
T383	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job		03/07/2019	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	Steering\SHOCK ABS	needs new straps		03/07/2019	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	Susp\SHOCK ABS	needs L/F L/R shock absorbers		03/07/2019	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	VehService\DS	D Service		03/07/2019	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	Elect\TRL LIGHTS	LHS clearance light bolster x2		28/06/2019	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	VehService\DS	Service		28/06/2019	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		15/06/2019	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Albury - Workshop	VehService\DS	D SERVICE		15/06/2019	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	VehService\DS	D Service		14/06/2019	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Rosewood - Workshop	Engine\TURBO	cut and joined in a new length of hose and tested ok (travel from Holbrook)		11/06/2019	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	Engine\TURBO	booster hose split and leaking on "supply" side		11/06/2019	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job		10/06/2019	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	Susp\SUSPENSION	LHM broken 1st axle straps missing		10/06/2019	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	VehService\DS	D service carried out by express truck services		10/06/2019	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER

T383	Albury - Workshop	VehService\DS	D SERVICE		21/05/2019	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Tumut - Workshop	VehService\DS	D Service Due		10/05/2019	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Albury - Workshop	VehService\DS	D SERVICE		10/05/2019	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Tumut - Workshop	Elect\TRL LIGHTS	short in trailer lights		02/05/2019	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Rosewood - Workshop	Elect\TRL LIGHTS	short in trailer lights		02/05/2019	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Albury - Workshop	Susp\SUSPENSION	LHF, RHF missing LHM, RHM broken		18/04/2019	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Albury - Workshop	Susp\SHOCK ABS	LHF missing		18/04/2019	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Albury - Workshop	Chassis\BOLSTER	weld cracked RHF bolster weld LH 2nd bolster		18/04/2019	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Albury - Workshop	Steering\WHEEL BRGS	LHM		18/04/2019	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		18/04/2019	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Albury - Workshop	VehService\DS	D SERVICE		18/04/2019	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	Elect\HEAD LIGHT	no RH turn signal		09/04/2019	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	VehService\DS	D Service		06/04/2019	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Albury - Workshop	Susp\SPRNG HANG	1st axle and LHM axle straps missing		06/04/2019	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Albury - Workshop	Susp\SHOCK ABS	LHF shock missing		06/04/2019	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Albury - Workshop	Steering\WHEEL BRGS	RHF, LHF		06/04/2019	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Albury - Workshop	Elect\INDICATORS	repair LHR indicator tail, 3rd bolster lights		06/04/2019	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		06/04/2019	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Albury - Workshop	Insp\ANN INSP	D SERVICE		06/04/2019	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Albury - Workshop	Susp\AIR BAG	REPLACE AIR BAG		05/04/2019	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Rosewood - Workshop	Susp\HCV	remove replace height control valve		04/04/2019	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Tumut - Workshop	Elect\INDICATORS	RH blinker not working		02/04/2019	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job		09/03/2019	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	VehService\DS	D SERVICE		09/03/2019	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Rosewood - Workshop	Chassis\BOLSTER	replaced 4 bolts on bolsters	refit bolster pads and tighten up	05/03/2019	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job		28/02/2019	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	VehService\DS	D SERVICE		28/02/2019	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Albury - Workshop	Susp\AXLES	1st axle on tri doesn't appear straight		31/01/2019	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	VehService\DS	D Service		31/01/2019	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Rosewood - Workshop	VehService\DS	D Service		31/01/2019	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	DrivLine\AXLE REPLC	1st axle on tri doesn't appear straight		31/01/2019	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job		31/01/2019	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	VehService\DS	SERVICE		31/01/2019	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Rosewood - Workshop	Steering\WHEEL ALGN	B Trailer tracking to the right		30/01/2019	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Tumut - Workshop	Tyres\DRV TYRES	B Trailer tracking to the right		30/01/2019	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		17/01/2019	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Albury - Workshop	VehService\DS	D SERVICE		17/01/2019	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	VehService\DS	D Service Due		15/01/2019	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	Elect\TRL LIGHTS	trailer lights not working		20/12/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	Body\MUDGUARDS	B Trailer RH side mudguard shorting to break weld		20/12/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		19/12/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Albury - Workshop	VehService\DS	D SERVICE		19/12/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	Body\AIR LEAK	air leak in trailer		06/12/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Albury - Workshop	Brakes\BRK RELINE	RELINE AND SUSPENSION WORK		22/11/2018	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		03/11/2018	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	VehService\DS	D Service		03/11/2018	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Tumut - Workshop	Tyres\RETREAD	Job Added From Invoice		01/11/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	Tyres\FITMENT	Job Added From Invoice		01/11/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Rosewood - Workshop	Chassis\WINCH/STRP	strap falling off load and ripping off winch	straighten up winch and fix up where winch bolts up to refit, tested ok	31/10/2018	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Tumut - Workshop	Tyres\FITMENT	Job Added From Invoice		24/10/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	Tyres\RETREAD	Job Added From Invoice		24/10/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		24/10/2018	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	VehService\DS	Service		24/10/2018	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Albury - Workshop	Brakes\BRK RELINE	RELINE 2X BRAKES		24/10/2018	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Rosewood - Workshop	Brakes\BRK RELINE	reline		24/10/2018	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		09/10/2018	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	VehService\DS	Service		09/10/2018	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Tumut - Workshop	Tyres\RETREAD	Job Added From Invoice		29/09/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	Tyres\FITMENT	Job Added From Invoice		29/09/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	Tyres	Job Added From Invoice		29/09/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Rosewood - Workshop	Susp\HCV	height control rubber broken on arm find on left hand side	replace broken HCV rubber link	25/09/2018	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job LF shocker saddle u/s RF wrap u/s		22/09/2018	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	Susp\SUSPENSION	LM seb u/s		22/09/2018	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	VehService\DS	D Service		22/09/2018	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Albury - Workshop	DrivLine	Job Added From Invoice remove broken winch handle		22/09/2018	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Rosewood - Workshop	Chassis\WINCH/STRP	replace with 2nd hand		20/09/2018	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	Brakes\BRK RELINE	Reline		07/09/2018	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Albury - Workshop	Brakes\BRK RELINE	RELINE LM.		07/09/2018	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		06/09/2018	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	Susp\SUSPENSION	tighten loose spring eye bolt		06/09/2018	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	VehService\DS	D Service		06/09/2018	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Tumut - Workshop	Tyres\FITMENT	Job Added From Invoice		01/09/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	Tyres	Job Added From Invoice		01/09/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Rosewood - Workshop	VehService\DS	Service		23/08/2018	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		23/08/2018	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	Elect\ELECT P&W	rewire 2nd and 3rd bolster side lights		23/08/2018	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	VehService\DS	D Service		23/08/2018	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Albury - Workshop	Chassis\WINCH/STRP	REPLACE 4X STRAPS		22/08/2018	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Rosewood - Workshop	Elect\ELECT P&W	tidy up loom in chassis rail		15/08/2018	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	Body\STCH GUARD	replaced L/H stretch guards		15/08/2018	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
			strap came off third winch from the front and damaged the guard on right hand rear drive. Needs readjusting. Also put a hole in air line to spin026	replaced 1st winch strap replaced pawl on first winch							
T383	Rosewood - Workshop	Chassis\WINCH/STRP	bent ratchet arm on winch	replaced missing bolts in webbing	15/08/2018	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Albury - Workshop	Chassis\WINCH/STRP	REPLACE WORN STRAPS		15/08/2018	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job brake holding on no air getting to the B Trailer found air leak near electric brake valve for B Trailer bypass valve.		14/08/2018	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	Brakes\AIR LEAK	Brakes released and trailer had air supply tested ok		14/08/2018	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	Body\MUDGUARDS	right hand side mudguard broken		14/08/2018	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	VehService\DS	Service		14/08/2018	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
				CLEANED OUT PLUG. TEST OK.							
T383	Albury - Workshop	Elect\INDICATORS	NO LH INDICATOR	No left hand indicator cleaned out plug test ok CHANGED WIRING IN PLUG ON TRUCK	07/08/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Albury - Workshop	Elect\WORK LIGHT	WORK LIGHTS NOT WORKING whilst at pound creek	no work lights found the problem in the wiring in the plug	07/08/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Rosewood - Workshop	Elect\ELECT P&W	checked lights on trailer		02/08/2018	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Tumut - Workshop	Tyres\RETREAD	Job Added From Invoice		31/07/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	Tyres\FITMENT	Job Added From Invoice		31/07/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	Tyres	Job Added From Invoice		31/07/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	VehService\DS	Service		25/07/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	Elect\INDICATORS	L/H blinker		25/07/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job		25/07/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER

T383	Tumut - Workshop	VehService\DS	D SERVICE		25/07/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Albury - Workshop	VehService	Job Added From Invoice		11/07/2018	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Tumut - Workshop	Body\MUDGUARDS	bolts both side on steel guard missing		07/07/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	Elect\WORK LIGHT	work light L/H side out		07/07/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	Elect\TAIL LIGHT	L/H tail light out		07/07/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	VehService\DS	Service		07/07/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	Body\MUDGUARDS	bolts both side on steel guard missing		07/07/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	Elect\WORK LIGHT	work light L/H side out		07/07/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	Elect\TAIL LIGHT	L/H tail light out		07/07/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	VehService\DS	Service		07/07/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job		07/07/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	VehService\DS	Service		07/07/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Albury - Workshop	Susp\SUSPENSION	BROKEN SPRING SADDLE		29/06/2018	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job		23/06/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	VehService\DS	Service		23/06/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	VehService\DS	D Service		22/06/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	VehService\DS	D Service		22/06/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	Body\AIR LEAK	coupling into B Trailer leaking air		05/06/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	VehService\DS	D Service		05/06/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		05/06/2018	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	Susp\SUSPENSION	replace axle strap		05/06/2018	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	VehService\DS	Service		05/06/2018	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job		26/05/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	VehService\DS	Service		26/05/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	Tyres\RETREAD	Job Added From Invoice		26/05/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	Tyres\FITMENT	Job Added From Invoice		26/05/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	Tyres	Job Added From Invoice		26/05/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Rosewood - Workshop	Body\AIR LEAK	fix air leak	replace two 3/8 hoses re-run hoses so it wouldn't rub again test ok	23/05/2018	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	Susp\SHOCK ABS	Welded 2x new shcoker studs R/F & R/R		15/05/2018	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
			Drop trailer in shed. Start pulling off skid plate had to use 2nd hand skid plate off T324.								
T383	Rosewood - Workshop	Workshop\MOVE ASSET	Pull off T324 skid plate to put on T383 fit skid plate tested okay.		15/05/2018	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	Chassis\CHAS CRACK	Cracked out skid plate		15/05/2018	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Albury - Workshop	VehService\DS	D Service		12/05/2018	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Tumut - Workshop	VehService\DS	Service		12/05/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job		12/05/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	VehService\DS	D Service		12/05/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	Tyres\RETREAD	Job Added From Invoice		04/05/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	Tyres\FITMENT	Job Added From Invoice		04/05/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	Tyres	Job Added From Invoice		04/05/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	Elect\INDICATORS	RHS indicator not working		03/05/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	Susp\AIR FITTIN	air line into trailer plug severed twice		03/05/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job		24/04/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	VehService\DS	D Service		24/04/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	VehService\DS	D Service Due		24/04/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	Elect\ELECT P&W	3rd bolster clearance lights		24/04/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	VehService\DS	D Service		10/04/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job		10/04/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	VehService\DS	Service	refer job#165568	10/04/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Rosewood - Workshop	VehService\DS	D Service		25/03/2018	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Tumut - Workshop	VehService\DS	Service		24/03/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job		24/03/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	VehService\DS	Service		24/03/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	Tyres\RETREAD	Job Added From Invoice		20/03/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	Tyres\FITMENT	Job Added From Invoice		20/03/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	Tyres	Job Added From Invoice		20/03/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Albury - Workshop	Frid Serv	Job Added From Invoice		16/03/2018	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Rosewood - Workshop	Elect\ELECT P&W	caught truck between loads at Towers. Rewired plug to suit loom		15/03/2018	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	Elect\ELECT P&W	repair wiring in cable arm, would not reset		15/03/2018	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Rosewood - Workshop	Body\ELECT P&W	no channel 3 scales	no scales channel 3	15/03/2018	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job		13/03/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	VehService\DS	D Service		13/03/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Albury - Workshop	VehService\DS	D Service		13/03/2018	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Body\BOLSTER	REPLACE NKP.		10/03/2018	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
			REPLACE QR HOOK.								
T383	Albury - Workshop	Chassis\WINCH/STRP	REPLACE WINCH PAWL		10/03/2018	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job		27/02/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	VehService\DS	D Service		27/02/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	Tyres\RETREAD	Job Added From Invoice		27/02/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	Tyres\FITMENT	Job Added From Invoice		27/02/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	Tyres	Job Added From Invoice		27/02/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Albury - Workshop	VehService\DS	D Service		24/02/2018	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		14/02/2018	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	VehService\DS	D Service		14/02/2018	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job		26/01/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	VehService\DS	D Service		26/01/2018	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Albury - Workshop	Chassis\SUSPENSION	RHF missing		13/01/2018	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	DrCabElect\RWC COMP	no truck safe sticker		13/01/2018	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Chassis\AIR LEAK	replace rad valve, loosing air		13/01/2018	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Body\CONSUMABLE	3x grease nipples		13/01/2018	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		13/01/2018	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	VehService\DS	D SERVICE	DONE @ ETS	13/01/2018	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		23/12/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Brakes\AIR LEAK	RHR BOOSTER HOSE LEAKING		23/12/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Body\MUDGUARDS	LH GUARD FLAP NEEDS TO BE TIGHTENED		23/12/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	VehService\DS	D SERVICE		23/12/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
				R&R 107060.							
				REPAIRED AS PER COVER SHEET							
				repair tail lights							
				found broken wired in suzi loom							
				replaced plug on 383							
T383	Albury - Workshop	Elect\TAIL LIGHT	NO LIGHTS ON 'B' TRAILER	cleaned out and resecure plugs	13/12/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	VehService\DS	D SERVICE	DONE @ ETS.	09/12/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Rosewood - Workshop	VehService\DS	D Service		08/12/2017	Completed	Colac	GTK	37690S	Rosewood Workshop	TRAILER
T383	Albury - Workshop	Body\LIGHTS	RHS blinker dull intermittent		02/12/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Tumut - Workshop	Tyres\RETREAD	Job Added From Invoice		29/11/2017	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	Tyres\FITMENT	Job Added From Invoice		29/11/2017	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Tumut - Workshop	Tyres	Job Added From Invoice		29/11/2017	Completed	Colac	GTK	37690S	Tumut Workshop	TRAILER
T383	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		24/11/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	VehService\DS	D SERVICE	SERVICED BY ETS.	24/11/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Chassis\CROSS MBR	broken crossmember on A trailer cracked right through		18/11/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		09/11/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	VehService\DS	D SERVICE	COMPLETED BY EXPRESS TRUCK SERVICE	09/11/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice		26/10/2017	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice		26/10/2017	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER

T383	Myrtleford - Workshop	Tyres	Job Added From Invoice		26/10/2017	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice		02/10/2017	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice		02/10/2017	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Tyres	Job Added From Invoice		02/10/2017	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Albury - Workshop	Brakes\BOOSTER	Booster brake type 30/30	Twin City - 488135	26/09/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Brakes\BOOSTER	LHS front brake booster broken		23/09/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Chassis\FIFTH WHEE	locking pin not working		21/09/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
				Work performed on 20/9/17							
				Free up slides							
T383	Albury - Workshop	Body\PANELS	Locking pin not working	snowy trucks - 00038492	21/09/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
				work performed on 12/9/17							
T383	Albury - Workshop	VehService\DS	D service	Snowy trucks - 00038404	13/09/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		02/09/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
				Work performed on 1/9/17							
T383	Albury - Workshop	VehService\DS	Carried out D service	Carry out d service - Snowy trucks - 00038299	02/09/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
				Work performed on 22/8/17							
				Carried out D service as per GF sheet - remove and replace red valve							
				RHF shock mount broken bottom							
T383	Albury - Workshop	VehService\DS	D service	Snowy trucks - 0003817	23/08/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
			work performed on 8/8/17								
T383	Albury - Workshop	VehService\DS	Carry out D service as per GF service sheet	Snowy trucks - 00038014	10/08/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Myrtleford - Workshop	Tyres	Job Added From Invoice		09/08/2017	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		14/07/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	VehService\DS	D SERVICE	replaced LHF shocker and strap	14/07/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice		12/07/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice		12/07/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Tyres	Job Added From Invoice		12/07/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Tyres\RUN OUT	Job Added From Invoice		07/07/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	VehService\DS	D SERVICE		30/06/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Susp\SPRNG PACK	REPLACE LHF SPRING.(BROKEN)		22/06/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice		21/06/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice		21/06/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Tyres	Job Added From Invoice		21/06/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice		21/06/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice		21/06/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	VehService\DS	D SERVICE		21/06/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Tyres\RUN OUT	Job Added From Invoice		16/06/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Brakes\EBS Kit	EBS KIT		14/06/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	VehService\DS	D SERVICE		11/06/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	VehService\DS	D SERVICE		04/06/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Susp\SPRNG HANG	RHF SEB CRACKED. REQUIRES WELDING		01/06/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Susp\SPRNG HANG	RHF SEB CRACKED. REQUIRES WELDING		28/05/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	VehService\DS	D SERVICE		28/05/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Brakes\AIR LEAK	REPAIR AIR LINE TO FRONT AIR TANK.	replaced section of air line and connector	25/05/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	VehService\DS	D SERVICE		19/05/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	VehService\DS	D SERVICE		12/05/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice		06/05/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice		06/05/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Tyres	Job Added From Invoice		06/05/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Brakes	Record Check Results		02/05/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	VehService\DS	D SERVICE		02/05/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Insp\ANN INSP	Annual Inspection		30/04/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice		28/04/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice		28/04/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Tyres	Job Added From Invoice		28/04/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Body\HOUSEKEEP	REPLACE REGO LABEL		28/04/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
			replaced LF brake booster								
T383	Albury - Workshop	Brakes\BOOSTER	LM brake booster required next opportunity		23/04/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		23/04/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	VehService\DS	Service		23/04/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Body\STCH GUARD	not nut on stretch guard tension bolt l/s	replaced stretch guard bolts	20/04/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Body\AIR LEAK	minor air leak	repaired air leak	20/04/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
			tested scales. Replaced transducer with parts from T393								
T383	Albury - Workshop	DrCabElect\SCALES	tested. Checked wiring and plumbing		13/04/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	DrCabElect\SCALES	FIX SCALES-CH3	replaced scale	13/04/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Brakes\AIR LEAK	AIR LEAK AROUND MIDDLE AXLE		13/04/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Chassis\BOLSTER	REAR PEGS CATCHING UP ON 3RD BOLSTER		13/04/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Brakes	Record Check Results		09/04/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	VehService\DS	D SERVICE		09/04/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Susp\AIR BAG	KINKED AIR LINE ON FRONT AIR BAG.	replaced air line	05/04/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
				check scale operation							
T383	Albury - Workshop	DrCabElect\SCALES	SCALES NOT WORKING	replaced link cable from slave to tranducer	05/04/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	VehService\DS	D SERVICE		02/04/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Tyres\TP17	Job Added From Invoice		30/03/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Chassis\WINCH/STRP	REPLACE BOLTS IN 1ST WINCH BRACKET	REPLACED 1ST WINCH MOUNT BOLTS	29/03/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Body\MUDGUARDS	FIX RH MUD FLAP		23/03/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	VehService\DS	D SERVICE		23/03/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
			RH MIDDLE SHOCKER-BROKEN OFF.	remove wheel to access shocker mount							
T383	Albury - Workshop	Susp\SHOCK ABS	REMOUNT SHOCKER AT NEXT SERVICE	refit wheels	23/03/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
				REPLACED STRAP.							
T383	Albury - Workshop	Chassis\WINCH/STRP	REPLACE STRAP ON 4TH WINCH	STRIAGHTENED HOLDER HOOK.	21/03/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Susp\SHOCK ABS	RH MIDDLE SHOCKER-BROKEN OFF	REMOVED SHOCKER	21/03/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Tyres\TP17	Job Added From Invoice		17/03/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
				FAULT WAS IN T382 UMBILICAL ARM.							
T383	Albury - Workshop	Elect\INDICATORS	LH INDICATOR NOT WORKING	REPLACED INDICATOR LIGHT.	17/03/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Brakes\AIR LEAK	REMOVE OLD CTI HOSES AND FITTINGS		14/03/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Susp\SHOCK ABS	RR SHOCKER IS U/S	REPLACE SHOCKER AND BOLT/NUT	14/03/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Tyres\BREAKDOWN	LEAKING VALVE ON RM TYRE.	REPLACED VALVE AND INFLATE	14/03/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	VehService\DS	D SERVICE	REPAIR AIR LEAKS.	14/03/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	DrivLine\WHEEL BRGS	CHECK AND ADJUST WHEEL BEARINGS	adjusted all wheel bearings	11/03/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Chassis\WINCH/STRP	FRONT WINCH STRAP NEEDS REPLACING		11/03/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Chassis\WINCH/STRP	NO MIDDLE STRAP	replaced winch, winch mount and strap	11/03/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Myrtleford - Workshop	Tyres\TP13	Job Added From Invoice		07/03/2017	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
				REPOSITION BOOSTERS TO PREVENT AIR LINES RUBBING ON BOOSTER CLAMPS							
T383	Albury - Workshop	Brakes\AIR LEAK	AIR LEAKS / PREVENTATIVE MAINTENANCE.	replaced rubbed hoses	04/03/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	VehService\DS	D SERVICE		03/03/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Chassis\WINCH/STRP	WINCHES HARD TO WIND UP	removed hooks from straps	02/03/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Susp\AIR LEAK	AIR LEAK MIDDLE AXLE RH SIDE	REPLACED RM AIR BAG	26/02/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Tyres\TP19	Job Added From Invoice		17/02/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Tyres\TP12	Job Added From Invoice		15/02/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER

				2nd bolster clamping bolts loose 1st bolster nkp bolts loose							
T383	Albury - Workshop	VehService\DS	D service	4th bolster loose bolts	01/02/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Chassis\CHAS CRACK	weld cracks in suspension hangers, bolster and x-member gussets		26/01/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Brakes\AIR LEAK	air leak uder tri.		25/01/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Brakes\AIR LEAK	Brakes slow to release		25/01/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Susp\AIR BAG	Replace LR air bag	all so replaced LM	24/01/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Albury - Workshop	Chassis\BOLSTER	Repair rear bolster stopper	repaired broken bolster stopper	24/01/2017	Completed	Colac	GTK	37690S	Albury Workshop	TRAILER
T383	Myrtleford - Workshop	Brakes\BRAKE ADJ	adjust brakes		17/01/2017	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Elect\TRL LIGHTS	check and repair lights Crack test & reline all wheels		13/01/2017	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Brakes\BRK RELINE	Replace all 6 brake drums		12/01/2017	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		12/01/2017	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist Repair skid plate cracks & chassis & bolster cracks		12/01/2017	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Chassis\FIFTH WHEE	Wheel alignment	Sepparton Motor Panels	01/12/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Tyres\TP21	Job Added From Invoice		17/11/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Tyres\TP11	Job Added From Invoice		17/11/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Body\HOUSEKEEP	wash trailer		17/11/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		15/11/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		15/11/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Brakes\AIR LEAK	fit C700 valve		08/11/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Elect\TRL LIGHTS	repair no side lights		04/11/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		01/11/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		01/11/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Body\MOUNTS	bolster ram pistol broken		28/10/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	DrCabElect\SCALES	no scales		21/10/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		13/10/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		13/10/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		04/10/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		04/10/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Chassis\HOUSEKEEP	Wash Trailer		27/09/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Brakes\BRK RELINE	fit 40% run out brake shoes to LHR & check bearings		27/09/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		17/09/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		17/09/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Tyres\TP21	Job Added From Invoice		15/09/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		07/09/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		07/09/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Brakes\BRAKE ADJ	fit return springs to slack adjusters		02/09/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Brakes\BRAKE ADJ	adjust brakes		02/09/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Body\STCH GUARD	fit RH stretch guard bolts		02/09/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Body	fit new stretch guard to RHS		02/09/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Chassis\BOLSTER	replace worn bolster pivot bushes		31/08/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Brakes\AIR LEAK	inspect low brake percentages		30/08/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		20/08/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		20/08/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Tyres\TP21	Job Added From Invoice		17/08/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Tyres\TP21	Job Added From Invoice		17/08/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Tyres\TP21	Job Added From Invoice		17/08/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Tyres\TP15	Job Added From Invoice		17/08/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Tyres\TP15	Job Added From Invoice		17/08/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Tyres\TP15	Job Added From Invoice		17/08/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Elect\TRL LIGHTS	no brake lights		14/08/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Elect\TRL LIGHTS	no brake lights		13/08/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Tyres\TP11	Job Added From Invoice		11/08/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Tyres\TP11	Job Added From Invoice		11/08/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Tyres\TP11	Job Added From Invoice		11/08/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		10/08/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		10/08/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		29/07/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		29/07/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		19/07/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		19/07/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Tyres\TP16	Job Added From Invoice		08/07/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Chassis\BOLSTER	Adjust 4th Bolster hydraulics		08/07/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	DrCabElect\SCALES	Calibrate scales - span weights	Complete	06/07/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	DrCabElect\SCALES	check & recalibrate scales		06/07/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Tyres\TPS1	Job Added From Invoice		01/07/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Tyres\TP19	Job Added From Invoice		01/07/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Tyres\TP19	Job Added From Invoice		01/07/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Tyres\TP19	Job Added From Invoice		01/07/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		01/07/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		01/07/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
				Fitted reconditioned ram, checked hydraulics - still not lifting. Adjust relief valve pressure - still no good replaced 3rd bolster ram fitted rear ram's shaft stop re adjusted trailer hydraulic relief valve							
T383	Myrtleford - Workshop	Hydraulics\VALVES	Repair rear bolster - not standing up	tested by loading and unloading	28/06/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Elect\ELECT P&W	check scales & settings		24/06/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		22/06/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		22/06/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Brakes\BRAKE ADJ	adjust brakes		10/06/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Tyres\TP17	Job Added From Invoice		30/04/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Tyres\TP17	Job Added From Invoice		30/04/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Tyres\TP17	Job Added From Invoice		30/04/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Susp\HOUSEKEEP	Replace RHR spring eye bush		21/04/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection		20/04/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		20/04/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		20/04/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Tyres\TP17	Job Added From Invoice		27/02/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Tyres\TP17	Job Added From Invoice		27/02/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Tyres\TP17	Job Added From Invoice		27/02/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		23/02/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		23/02/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Tyres\TP12	Job Added From Invoice		23/02/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		10/02/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		10/02/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Chassis\BOLSTER	repair cracks in 2nd & 3rd bolsters		10/02/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Chassis\CROSS MBR	replace missing bolts	completed	08/02/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Tyres\TP13	Job Added From Invoice		06/02/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Tyres\TP13	Job Added From Invoice		06/02/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Tyres\TP13	Job Added From Invoice replace buckle on winch stap		06/02/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Chassis\WINCH/STRP	replace winch spring	completed	27/01/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		27/01/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER

T383	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist		27/01/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Chassis\HOUSEKEEP	check over	completed	22/01/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Brakes\BRAKE ADJ	adjust brakes	completed	22/01/2016	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Chassis\MUDGUARDS	repairs to mudguard	completed	05/12/2015	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
			6 dust covers								
T383	Myrtleford - Workshop	Brakes\BRK RELINE	tctc	completed	27/11/2015	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
				completed							
T383	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job	weld cracks in trailer ramp	26/11/2015	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist	completed	26/11/2015	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
			3 axles+brake parts								
T383	Myrtleford - Workshop	Brakes\BRK RELINE	tctc	completed	25/11/2015	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Brakes\BRK RELINE	reline all wheels	completed	19/11/2015	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Tyres\TP13	Job Added From Invoice		11/11/2015	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Tyres\TP13	Job Added From Invoice		11/11/2015	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
			repair bolster rams								
T383	Myrtleford - Workshop	Hydraulics\RAM	rinl	completed	06/11/2015	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job	completed	05/11/2015	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist	completed	05/11/2015	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Body\MUDGUARDS	replace mudguard	completed	28/10/2015	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Elect\ELECT P&W	cleaned trailer plug out+check taillight bar	completed	28/10/2015	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Tyres\TP22	Job Added From Invoice		27/10/2015	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Tyres\TP21	Job Added From Invoice		27/10/2015	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Tyres\TP21	Job Added From Invoice		27/10/2015	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job	completed	21/10/2015	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist	completed	21/10/2015	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Elect\ELECT P&W	check lights	completed	16/10/2015	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job	completed	08/10/2015	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist	completed	08/10/2015	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job	completed	25/09/2015	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist	completed	25/09/2015	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Tyres\DAMAGE	Job Added From Invoice		24/09/2015	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Tyres\DAMAGE	Job Added From Invoice		24/09/2015	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Tyres\TP22	Job Added From Invoice		24/09/2015	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Tyres\TP17	Job Added From Invoice		24/09/2015	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Body	turn bent pegs	completed	15/09/2015	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job	completed	15/09/2015	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist	completed	15/09/2015	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER
T383	Myrtleford - Workshop	Body\HOUSEKEEP	Service Job Added From Invoice		05/09/2015	Completed	Colac	GTK	37690S	Myrtleford Workshop	TRAILER