EquipmentName	Workshop	CodeAndSubCode	Description	Schedule	CompletionComments	DateDone	DistanceDone	Worktype	Workstate	EquipmentOwner	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
T614	Wodonga - Workshop	VehService\DS	VehService\DS Service	VehService\DS	Jamie on service	05/10/2026	285154	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	Wodonga Workshop	TRAILER
T614	Wodonga - Workshop	Body\TOOLBOX	angle holder need replacing			05/10/2026	285154	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	Wodonga Workshop	TRAILER
T614	Wodonga - Workshop	Body\TRL REPS	pelmet on RHS front rubber			05/10/2026	285154	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	Wodonga Workshop	TRAILER
T614	Wodonga - Workshop	Body\PANELS	pedestrian guard not secure			05/10/2026	285154	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	Wodonga Workshop	TRAILER
T614	Wodonga - Workshop	Elect\TRL LIGHTS	Faulty Trailer Plug		Checked & tested trailer light socket on front of B-trailer, all lights worked as they should, tested trailer light plug, found to be faulty, replaced trailer light plug, tested, brake lights stopped flickering, sent trailer to work.	20/08/2026	285154	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	Wodonga Workshop	TRAILER
T614	Wodonga - Workshop	VehService\DS	VehService\DS Service	VehService\DS		17/07/2026	628560	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T614	Wodonga - Workshop	Body\DAMAGE	rh pallet angle holder fix/replace			14/07/2026	285154	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	Wodonga Workshop	TRAILER
T614	Wodonga - Workshop	VehService\DS	VehService\DS Service	VehService\DS	Jamie and cheyne on service	14/07/2026	285154	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	Wodonga Workshop	TRAILER
T614	Wodonga - Workshop	Body\TRL REPS	Cover plate at front of Pelment rubber to be replaced on both side's.			14/07/2026	285154	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	Tyres\TPT+8	Tyres\TPT+8 (27-28)		LOW	15/06/2026	628560	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	BORDER BANDAG PTY LTD	TRAILER
T615	Wodonga - Workshop	Braken\BRK RELINE	Tagged out for reline		completed b y AM-IW	15/06/2026	628560	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	Braken\AIR FITTIN	Control Air Line between A & B trailer's is Leaking.			11/06/2026	628560	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T614	Wodonga - Workshop	VehService\DS	VehService\DS Service	VehService\DS		11/06/2026	628560	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T614	Wodonga - Workshop	Body\DAMAGE	Repair under run protection		Repained under run protection	21/05/2026	285154	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	Wodonga Workshop	TRAILER
T614	Wodonga - Workshop	VehService\DS	VehService\DS Service	VehService\DS		08/04/2026	285154	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	Wodonga Workshop	TRAILER
T614	Wodonga - Workshop	Insp\ANN INSP	Insp\ANN INSP Annual Inspection As Per Checklist	Insp\ANN INSP		08/04/2026	285154	PreventativeMaintenance	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	Wodonga Workshop	TRAILER
T614	Wodonga - Workshop	VehService\DS	VehService\DS Service	VehService\DS	Reline needed asap	03/04/2026	628560	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	Body\TRL REPS	R/F U/right is missing bottom half [in toolbox] FIX REAR GUARDS TO RAIR NEW BOLTS BOTH SIDE LOOSE.			13/03/2026	628560	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	Body\MUDGUARDS	MUDFLAP GUARD			13/03/2026	628560	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	Braken\AIR LEAK	Control Air Line Between A&B Trailer Leaking		Connected shop air to front of trailers, checked for air leak/s, found split brake hose at trailer coupling (Emergency Brake Side), removed hose clamp and hose, shortened brake hose, refitted brake hose & hose clamp, rechecked for air leaks, all good, packed up all tooling.	28/02/2026	628560	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	VehService\DS	VehService\DS Service	VehService\DS	Will need reline asap	27/02/2026	628560	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	Tyres\TPT+10	Tyres\TPT+10 (29-30)		LOW	26/02/2026	628560	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	BORDER BANDAG PTY LTD	TRAILER
T614	Wodonga - Workshop	VehService\DS	VehService\DS Service	VehService\DS		17/02/2026	285154	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	Wodonga Workshop	TRAILER
T614	Wodonga - Workshop	VehService\DS	VehService\DS Service	VehService\DS		06/01/2026	285154	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	VehService\DS	VehService\DS Service	VehService\DS		05/01/2026	628560	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T614	Wodonga - Workshop	Braken\BRAKE ADJ	ADJUST BRAKES			03/12/2025	285154	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	Wodonga Workshop	TRAILER
T614	Wodonga - Workshop	VehService\DS	VehService\DS Service	VehService\DS		03/12/2025	285154	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	VehService\DS	VehService\DS Service	VehService\DS		21/11/2025	628560	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T614	Wodonga - Workshop	VehService\DS	VehService\DS Service	VehService\DS		14/11/2025	285154	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	Body\TRL REPS	Replace curtain rollers.			11/11/2025	628560	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T614	Wodonga - Workshop	Tyres\TPT+8	Tyres\TPT+8 (27-28)		these 12 were all flat spotted. They are all still at Green freight for anyone that needs to inspect	04/11/2025	285154	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	BORDER BANDAG PTY LTD	TRAILER
T614	Wodonga - Workshop	Tyres\TPT+2	Tyres\TPT+2 (21-22)		these 12 were all flat spotted. They are all still at Green freight for anyone that needs to inspect	04/11/2025	285154	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	BORDER BANDAG PTY LTD	TRAILER
T614	Wodonga - Workshop	Tyres\TPT+4	Tyres\TPT+4 (13-14)		these 12 were all flat spotted. They are all still at Green freight for anyone that needs to inspect	04/11/2025	285154	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	BORDER BANDAG PTY LTD	TRAILER
T614	Wodonga - Workshop	Tyres\TPT+10	Tyres\TPT+10 (29-30)		these 12 were all flat spotted. They are all still at Green freight for anyone that needs to inspect	04/11/2025	285154	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	BORDER BANDAG PTY LTD	TRAILER
T614	Wodonga - Workshop	Tyres\TPT+12	Tyres\TPT+12 (31-32)		these 12 were all flat spotted. They are all still at Green freight for anyone that needs to inspect	04/11/2025	285154	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	BORDER BANDAG PTY LTD	TRAILER
T614	Wodonga - Workshop	Body\TRL REPS	LUBE OR CLEAN CURTAIN ROLLER TRACKS			30/10/2025	285154	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	Wodonga Workshop	TRAILER
T614	Wodonga - Workshop	Body\TRL REPS	Curtain Buckles			30/10/2025	285154	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	Wodonga Workshop	TRAILER
T614	Wodonga - Workshop	Body\TRL REPS	L/H Rear Curtain Support Gets Jammed in Slide			30/10/2025	285154	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	VehService\DS	VehService\DS Service	VehService\DS		29/10/2025	628560	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	Tyres\RUN OUT	Tyres\RUN OUT POS 29			28/10/2025	628560	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	BORDER BANDAG PTY LTD	TRAILER
T614	Wodonga - Workshop	VehService\DS	VehService\DS Service	VehService\DS		14/10/2025	285154	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	Wodonga Workshop	TRAILER
T614	Wodonga - Workshop	Body\TOOLBOX	TOOLBOX LID FAILING OFF.			14/10/2025	285154	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	Wodonga Workshop	TRAILER
T614	Wodonga - Workshop	Body\TRL REPS	RHR UPRIGHT POLE LOCATING TAB BROKEN.			14/10/2025	285154	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	BORDER BANDAG PTY LTD	TRAILER
T614	Wodonga - Workshop	Tyres\Punct	Tyres\Puncture POS 26			20/09/2025	285154	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	BORDER BANDAG PTY LTD	TRAILER
T614	Wodonga - Workshop	Chassis\AIR LEAK	MINOR AIR LEAK		Replace lhm airbag	18/09/2025	628560	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T614	Wodonga - Workshop	Tyres\TP11+12	Tyres\TP11+12 (31-32)			30/08/2025	285154	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	BORDER BANDAG PTY LTD	TRAILER
T614	Wodonga - Workshop	Body\TRL REPS	RHR upright pole locating tab broken			27/08/2025	285154	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	Wodonga Workshop	TRAILER
T614	Wodonga - Workshop	VehService\DS	VehService\DS Service	VehService\DS		27/08/2025	285154	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	Susp\AIR LEAK	TRI AIR NOT STAYING IN AND MAKING TRIP HORRIBLE. PIG BOOTING ALL THE WAY SMASHING ME IN THE BACK WHOLE TRIP- DID PUMP U/P. BU			16/08/2025	628560	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T614	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection	Insp\ANN INSP		16/08/2025	285154	PreventativeMaintenance	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	Chassis\SCALES	Scales Not Working Correctly			16/08/2025	628560	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T614	Wodonga - Workshop	VehService\DS	VehService\DS Service	VehService\DS		16/08/2025	285154	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	Tyres\TP11+12	Tyres\TP11+12 (31-32)			06/08/2025	628560	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	BORDER BANDAG PTY LTD	TRAILER
T614	Wodonga - Workshop	Tyres\Punct	Tyres\Puncture POS 22			29/07/2025	285154	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	BORDER BANDAG PTY LTD	TRAILER
T614	Wodonga - Workshop	Braken\BRAKE ADJ	adjust brakes		Self adjusters.....checked seem to be fine tested rr fl and was at correct adjustment	24/07/2025	285154	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	Wodonga Workshop	TRAILER
T614	Wodonga - Workshop	VehService\DS	VehService\DS Service	VehService\DS		24/07/2025	285154	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	Wodonga Workshop	TRAILER
T614	Wodonga - Workshop	Body\TRL REPS	tube or clean curtain roller tracks			24/07/2025	285154	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	Wodonga Workshop	TRAILER
T614	Wodonga - Workshop	Body\TOOLBOX	Toolbox lid falling off			24/07/2025	285154	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	Wodonga Workshop	TRAILER
T614	Wodonga - Workshop	Tyres\RUN OUT	Tyres\RUN OUT POS 22			21/07/2025	285154	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	BORDER BANDAG PTY LTD	TRAILER
T614	Wodonga - Workshop	Tyres\TPT+10	Tyres\TPT+10 (29-30)			21/07/2025	285154	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	BORDER BANDAG PTY LTD	TRAILER
T615	Wodonga - Workshop	Body\ELECT P&W	Sort out electrical fault in trailer lights.		-wiring repaired in A trailer right hand side combination light + lights check done -sins osarend in trailer oluas	15/07/2025	628560	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	VehService\DS	VehService\DS Service	VehService\DS		15/07/2025	628560	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	Body\TOOLBOX	Toolbox Door to be repaired/replace hinge's.			15/07/2025	628560	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	Susp\AIR LEAK	Tri has No air, even after building up Air, they lose air very quickly.			15/07/2025	628560	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
					Travel from Calloway Workshops To Site At Doughty s Rd Truggirna Customer Reports Brakes Locked On Travel To Site Found female Rear Sail Air line Hose Clamp Loose Tighten Loss Hose Clamp test operation All Ok											
T615	Wodonga - Workshop	Braken\BREAKDOWN	Calloway Road RTC Workshop			14/07/2025	628560	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	CALLAWAY TRUCK	TRAILER
T614	Wodonga - Workshop	VehService\DS	VehService\DS Service	VehService\DS		28/06/2025	285154	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	Wodonga Workshop	TRAILER
T614	Wodonga - Workshop	Body\TRL REPS	Curtain Holes Both Sides			28/06/2025	285154	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	VehService\DS	VehService\DS Service	VehService\DS		31/05/2025	628560	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	Susp\AIR BAG	TRI AIRBAGS VERY LOW & SCALES WON'T ACTUALLY TELL TRUTH.			21/05/2025	628560	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	Susp\VCV	AIRBAGS NOT INFLATING.		Found pressure protection valve blocked. Replaced blocked 70psi valve with new 45psi valve. Tested operation and confirmed fault repaired.	21/05/2025	628560	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T614	Wodonga - Workshop	Body\TRL REPS	LHF Palmar rubber guard damaged			12/05/2025	285154	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	Wodonga Workshop	TRAILER
T614	Wodonga - Workshop	VehService\DS	VehService\DS Service	VehService\DS	1 Repair to passenger side 50 inches	10/05/2025	285154	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	Wodonga Workshop	TRAILER
T614	Wodonga - Workshop	Body\TRL REPS	Curtain Torn L/H Top Second Buckle In		re-weld section of curtain on passenger side	28/04/2025	285154	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	VFX TRUCK CURTAINS	TRAILER
T615	Wodonga - Workshop	VehService\DS	VehService\DS Service	VehService\DS		24/04/2025	628560	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	Body\TRL REPS	Repair holes in curtains.			15/04/2025	628560	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T614	Wodonga - Body		Cracked x brace above rear axle.			04/04/2025	285154	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	Wodonga Workshop	TRAILER
T614	Wodonga - Workshop	Brakes	EBS Valve leaking			04/04/2025	285154	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	Tyres\RUN OUT	Tyres\RUN OUT 11			02/04/2025	628560	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	BEAUREPAIRES	TRAILER
T615	Wodonga - Workshop	Tyres\TPT+10	Tyres\TPT+10			02/04/2025	628560	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	BEAUREPAIRES	TRAILER
T615	Wodonga - Workshop	Tyres\TPT+6	Tyres\TPT+6			02/04/2025	628560	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	BEAUREPAIRES	TRAILER
T615	Wodonga - Workshop	Tyres\TPT+8	Tyres\TPT+8			02/04/2025	628560	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	BEAUREPAIRES	TRAILER
T615	Wodonga - Workshop	Tyres\TPT+4	Tyres\TPT+4			02/04/2025	628560	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	BEAUREPAIRES	TRAILER
T615	Wodonga - Workshop	Tyres\TPT+2	Tyres\TPT+2			02/04/2025	628560	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	BEAUREPAIRES	TRAILER
			The following breakdown repair for Greenfreight Distribution Pty Ltd, to a Maxitrans Trailer, chassis#6FB0000003094632, fleet#TE64 & registration#074857 included: * Customers contacted breakdown technician to report breakdown * Customer advised of blown air bag on RHR * Technician sourced additional parts * Technician travelled to breakdown location, Holbrook, NSW * Removed wheel equipment * Removed air bag airlines & mounting components * Removed/replaced air bag * Installed components & wheel equipment * Align & tension all components * Pressurised, test, confirm & quality check repair * Returned trailer to service * Technician returned home														
T614	Wodonga - Workshop	Susp\AIR BAG				31/03/2025	285154	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	PACCAR PARTS FLEET SERVICES	TRAILER
T614	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection	Insp\ANN INSP		29/03/2025	285154	PreventativeMaintenance	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	Wodonga Workshop	TRAILER
T614	Wodonga - Workshop	Body\TRL REPS	floor cracked + lifting previous repair failing		Need to get back unloaded	29/03/2025	285154	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	Wodonga Workshop	TRAILER
T614	Wodonga - Workshop	Tyres\TPT+8	Tyres\TPT+8			29/03/2025	285154	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	BEAUREPAIRES	TRAILER
T614	Wodonga - Workshop	Tyres\RUN OUT	Tyres\RUN OUT POS 3			29/03/2025	285154	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	BEAUREPAIRES	TRAILER
T615	Wodonga - Workshop	Elect\TRL LIGHTS	TRAILER PLUG NOT FITTED PROPERLY.		BREAKDOWN - Inspected and found exposed wires inside of plug and LH indicator wire had rubbed inside of plugged and shorted out. Plug was new. Trailer serviced within the week. Rewired plug and tested to confirm repairs complete	18/03/2025	628560	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T614	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		15/03/2025	285154	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	VehService\DS	VehService\DS Service	VehService\DS		13/03/2025	628560	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		22/02/2025	628560	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	Body\ELECT P&W	Replace ABS Plug			22/02/2025	628560	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	Elect\INDICATORS	REAR RIGHT FLASHER LIGHT BROKEN.			22/02/2025	628560	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T614	Wodonga - Workshop	Tyres\TPT+6	Tyres\TPT+6			17/02/2025	285154	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	BEAUREPAIRES	TRAILER
T614	Wodonga - Workshop	Braken\BRK RELINE	Reline/padstag front axle.			11/02/2025	285154	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	Wodonga Workshop	TRAILER
T614	Wodonga - Workshop	Drive\Inet\WHEEL SEAL	LHR Hub Leaking		Pad slap	11/02/2025	285154	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	Wodonga Workshop	TRAILER
T614	Wodonga - Workshop	Drive\Inet\WHL HUB	LHR hub leaking grease			11/02/2025	285154	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	Tyres\Punct	Tyres\Punct spare			07/02/2025	285154	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	Wodonga Workshop	TRAILER
T614	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		01/02/2025	285154	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		22/01/2025	628560	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	Elect\LIGD COIL	No ABS PLUG/ Right Hand indicator not working.			21/01/2025	628560	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T614	Wodonga - Workshop	Chassis\LIGD COIL	driver curtain ratchet keeps catching airlines			21/01/2025	628560	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T614	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		10/01/2025	285154	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	Wodonga Workshop	TRAILER
T614	Wodonga - Workshop	Susp\AIR BAG	Airbag leak			10/01/2025	285154	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	Wodonga Workshop	TRAILER
T614	Wodonga - Workshop	Body\DAMAGE	Repair Damaged Trailer Due To Dropped Paper Reel. (Vawdrey Dandenong P/O: WWI090413)			21/12/2024	285154	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	Body\MUDGUARDS	MUDGUARD DAMAGED.			05/12/2024	628560	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		03/12/2024	628560	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	Tyres\RUN OUT	12			19/11/2024	628560	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	BEAUREPAIRES	TRAILER
T615	Wodonga - Workshop	Body\TRL REPS	L/H Curtain Ratchet Faulty			19/11/2024	628560	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	Body\TRL REPS	RATCHET PASSENGER SIDE CURTAIN TIGHTENER BROKEN.			19/11/2024	628560	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T614	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		06/11/2024	285154	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	Wodonga Workshop	TRAILER
T614	Wodonga - Workshop	Body\DAMAGE	Repair/remove side impact protection bars			30/10/2024	285154	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	Susp\VCV	Adjust Ride Height			30/10/2024	285154	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		18/10/2024	628560	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T614	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		21/09/2024	285154	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	Wodonga Workshop	TRAILER
T614	Wodonga - Workshop	Body\Pogo	Retaining Lug on Rear LHS bent			21/09/2024	285154	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	Wodonga Workshop	TRAILER
T614	Wodonga - Workshop	Body\DAMAGE	major damage repairs			21/09/2024	285154	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	VAWDREY AUSTRALIA PTY LTD	TRAILER
T614	Wodonga - Workshop	Braken\BRK RELINE	Reline 2 axles			21/09/2024	285154	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	VAWDREY AUSTRALIA PTY LTD	TRAILER
T615	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		17/09/2024	628560	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T614	Wodonga - Workshop	Tyres\TPO4	Tyres\TPO4			26/08/2024	285154	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	BEAUREPAIRES	TRAILER
T614	Wodonga - Workshop	VehService\DS	D Service	VehService\DS		17/08/2024	285154	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		08/08/2024	628560	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		16/07/2024	628560	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	Elect\ELECT P&W	REPLACE LIGHTS PLUG.			16/07/2024	628560	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	Susp\VCV	Adjust Ride Height Control Valve No Side Lights, All Lights Flash When Indicators Are On (Hagan's Auto Electrical P/O: WWOB7259)			10/07/2024	285154	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	Wodonga Workshop	TRAILER
T614	Wodonga - Workshop	Elect\TRL LIGHTS				10/07/2024	285154	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074857	HAGANS AUTO ELECTRICAL SERVICE	TRAILER
T614	Wodonga - Workshop	VehService\DS	D Service	VehService\DS		27/05/2024	628560	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			27/04/2024	87439	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	Braken\BOOSTER	TIGHTEN LF BOOSTER AND AIR LINES.			27/04/2024	87439	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	Braken\AIR LEAK	REPAIR/ REPLACE LEA

T615	Woodinga - Workshop	Brakes	Record Check Results As Attached To This Job					20/03/2024		Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	VehService/JDS	D Service As Per Attached Checklist	VehService/JDS				20/03/2024		Service	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Brakes	Record Check Results As Attached To This Job					07/12/2023	6033	Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Body\TRL REPS	CURTAIN ROLLERS STICKING.		CHECKED. OK.			07/12/2023		Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Chassis\CROSS MBR	ALL CENSH BARS DAMAGED.					07/12/2023		Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Body\TRL REPS	CURTAIN ROLLERS STUFFED!					07/12/2023		Fault	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	VehService/JDS	D Service As Per Attached Checklist	VehService/JDS				07/12/2023		Service	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Body\TRL REPS	REPLACED RF CURTAIN RATCHET. REPAIRED RR UPRIGHT.					07/12/2023		Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Brakes	Record Check Results As Attached To This Job					08/09/2023		Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	DriveLine\WHEEL BRGS	MOVEMENT IN RF RM LM LR WHEEL BEARINGS. UNDER WARRANTY.					08/09/2023		Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Body\TRL REPS	CURTAIN ROLLERS STICKING.					08/09/2023		Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Body\TRL REPS	CURTAIN ROLLERS STUFFED!					08/09/2023		Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	VehService/JDS	D Service As Per Attached Checklist	VehService/JDS				08/09/2023		Service	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Chassis\CROSS MBR	ALL CENSH BARS DAMAGED.					08/09/2023		Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Tyres\TP1+2	Tyre Position 1 + 2					08/09/2023		Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Albury Workshop	TRAILER
T615	Woodinga - Workshop	Tyres\TP11+12	Tyre Position 11 + 12					08/09/2023		Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Albury Workshop	TRAILER
T615	Woodinga - Workshop	Body\TRL LEGS	BROKEN HANDLE FOR LANDING LEGS - Unbolt damaged handle from trailer. Grind back surfaces & welded on new handle. Painted surfaces and reinstalled to trailer. Operate landing leas. okay.					17/08/2023	803071	Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Albury Workshop	TRAILER
T615			LH INDICATOR N/W - Inspect LH indicator, found light not working and housing was damaged. Removed light from housing, tested power & earth, all okay. Removed indicator & replaced with new.															
T615	Woodinga - Workshop	Elect\INDICATORS	Ordered new housine. needs to return for fittine to protect wirine from weather.					17/08/2023	803071	Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Albury Workshop	TRAILER
T615	Woodinga - Workshop	Tyres\Punct	Puncture Repair (Good Year Adelaide) Purchase Order Number: WWB80117					07/08/2023	628560	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LH8	074952	Wodonga Workshop	TRAILER
T615	Woodinga - Workshop	Brakes	Record Check Results As Attached To This Job					26/05/2023	772664	Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Tyres\TP05	REPLACE INSIDE RM TYRE.					26/05/2023	772664	Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	VehService/JDS	D Service As Per Attached Checklist	VehService/JDS				26/05/2023	772664	Service	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP				26/05/2023	772664	PreventativeMaintenance	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Unknown	SERVICE REQUIRED.					26/05/2023	772664	Fault	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Tyres\TP5+6	Tyre Position 5 + 6					23/02/2023		Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Albury Workshop	TRAILER
T615	Woodinga - Workshop	Tyres\TP3+4	Tyre Position 3 + 4					15/01/2023		Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Albury Workshop	TRAILER
T615	Woodinga - Workshop	Brakes	Record Check Results As Attached To This Job					15/01/2023		Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	DriveLine\WHEEL BRGS	MOVEMENT IN RF RM LM LR WHEEL BEARINGS. UNDER WARRANTY.					15/01/2023		Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Body\TRL REPS	CURTAIN ROLLERS STICKING.					15/01/2023		Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	VehService/JDS	D Service As Per Attached Checklist	VehService/JDS	REPLACED TRAILER LIGHTS SOCKET.			15/01/2023		Service	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Tyres\TP05	REPLACE INSIDE RM TYRE.					15/01/2023		Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Brakes	Record Check Results As Attached To This Job					10/12/2022		Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Body\TRL REPS	REPLACE RIGHT CURTAIN RATCHET HANDLE.					10/12/2022		Fault	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	VehService/JDS	D Service As Per Attached Checklist	VehService/JDS				10/12/2022		Service	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Body\TRL REPS	CURTAIN ROLLERS STICKING.					10/12/2022		Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Tyres\TP9+10	Tyre Position 9 + 10					10/12/2022		Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Albury Workshop	TRAILER
T615	Woodinga - Workshop	Body\TRL REPS	REPAIR 2 ROOF SUPPORT POLES LEFT SIDE.		REPAIRED UPRIGHTS.			17/11/2022		Fault	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Brakes	Record Check Results As Attached To This Job					21/10/2022	701247	Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Tyres\TP3+4	LM INSIDE TYRE.					21/10/2022	701247	Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	DriveLine\WHEEL BRGS	MOVEMENT IN RF RM LM LR WHEEL BEARINGS. UNDER WARRANTY.					21/10/2022	701247	Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Elect\TRL LIGHTS	REPLACE TRAILER LIGHTS.		OK.			21/10/2022	701247	Fault	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	VehService/JDS	D Service As Per Attached Checklist	VehService/JDS				21/10/2022	701247	Service	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Elect\TRL LIGHTS	REPAIRED TRAILER PLUG.					04/10/2022		Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Tyres\TP1+2	supply and fit 2tyres					30/09/2022		Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Elect\TRL LIGHTS	REPLACED LIGHT SOCKET.					23/09/2022	692493	Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Brakes	Record Check Results As Attached To This Job					13/08/2022	682238	Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	VehService/JDS	D Service As Per Attached Checklist Left Middle Outter tyre flat.	VehService/JDS				13/08/2022	682238	Service	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Tyres\Punct	Beausreairs called to attend.					03/08/2022	628560	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LH8	074952	Wodonga Workshop	TRAILER
T615	Woodinga - Workshop	Brakes	Record Check Results As Attached To This Job					21/06/2022	658926	Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	VehService/JDS	D Service As Per Attached Checklist	VehService/JDS				21/06/2022	658926	Service	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Insp\WHC COMP	HOOKED UP TO TG13 ACA TRIPLE COMBINATION. MEASURED FOR PERMIT. PARKED. supply and fit 4 tyres					26/05/2022		Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Tyres\TP11+12	moving inside					26/05/2022		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LH8	074952	Wodonga Workshop	TRAILER
T615	Woodinga - Workshop	Tyres\TP3+4	Tyre Position 3 + 4					26/05/2022		Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Brakes	Record Check Results As Attached To This Job					26/05/2022	653176	Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	VehService/JDS	D Service As Per Attached Checklist	VehService/JDS	HOOKED U/P. REPLACED LEG HANDLE.			26/05/2022	653176	Service	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Tyres\TP3+4	LM INSIDE TYRE.					26/05/2022	653176	Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	DriveLine\WHEEL BRGS	MOVEMENT IN RF RM LM LR WHEEL BEARINGS. UNDER WARRANTY.					26/05/2022	653176	Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Brakes	Record Check Results As Attached To This Job					15/06/2022	639379	Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	VehService/JDS	D Service As Per Attached Checklist	VehService/JDS				15/06/2022	639379	Service	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Unknown	SERVICE					15/06/2022	639379	Fault	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Brakes	Record Check Results As Attached To This Job					11/03/2022	635064	Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	VehService/JDS	D Service As Per Attached Checklist	VehService/JDS				11/03/2022	635064	Service	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Brakes	Record Check Results As Attached To This Job					21/01/2022	615831	Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	VehService/JDS	D Service As Per Attached Checklist	VehService/JDS	SPLIT TRAILERS AND CHECKED TURNTABLE. REPLACED LH NO. PLATE LIGHT ASSEMBLY.			21/01/2022	615831	Service	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Brakes	Record Check Results As Attached To This Job					18/12/2021	611157	Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	VehService/JDS	D Service As Per Attached Checklist	VehService/JDS				18/12/2021	611157	Service	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Tyres\WHEELCHECK	Pressure Check					02/12/2021	607257	Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Tyres\WHEELCHECK	Pressure Check					16/11/2021	604586	Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Brakes	Record Check Results As Attached To This Job					12/11/2021	604585	Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	VehService/JDS	D Service As Per Attached Checklist	VehService/JDS				12/11/2021	604585	Service	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP				12/11/2021	604585	PreventativeMaintenance	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Body\CONSUMABLE	replace LH curtain ratchet ABS System on these set of trailers not working.					22/10/2021		Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Brakes\ABS	ABS Light on truck dash.		Unhook 638 from trailers and hook up 1028 to test drive for ABS faults. No Fault durine drive. Parked Trailers.			09/10/2021	590620	Fault	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Brakes	Record Check Results As Attached To This Job					08/10/2021	19065	Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Chassis\MUDGUARDS	2 x Gaurds need replacing.					08/10/2021	19065	Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Chassis\MUDGUARDS	Worn Mudguards.					08/10/2021	19065	Fault	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Body\TRL REPS	Rear left hand side curtain pole bent.					08/10/2021	19065	Fault	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Body\TRL REPS	Rear left hand curtain ripped at top.					08/10/2021	19065	Fault	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Brakes\ABS	ABS System on these set of trailers not working. ABS Light on truck dash.					08/10/2021	19065	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LH8	074952	Wodonga Workshop	TRAILER
T615	Woodinga - Workshop	Chassis\MUDGUARDS	Worn mudguards as per R&R 17/09/2021		CHECKED GUARD. NOT UN ROADWORTHY			08/10/2021	19065	Fault	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	VehService/JDS	D Service As Per Attached Checklist	VehService/JDS				08/10/2021	19065	Service	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Tyres\Air-Ter	POS 5,6					24/09/2021	585776	Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Tyres\TP06	fit runout					21/09/2021	584586	Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Tyres\WHEELCHECK	Pressure Check					21/09/2021	584586	Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Brakes	Record Check Results As Attached To This Job					02/09/2021	576026	Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Chassis\MUDGUARDS	2 x Gaurds need replacing. Clean up and check services.					02/09/2021	576026	Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Workshop\MOVE ASSET	Pick up trailers for service.					02/09/2021	576026	Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	VehService/JDS	D Service As Per Attached Checklist	VehService/JDS				02/09/2021	576026	Service	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T614	Woodinga - Workshop	Brakes	Record Check Results As Attached To This Job					29/08/2021	61157	Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074857	Woodinga Workshop	TRAILER
T614	Woodinga - Workshop	VehService/JDS	D Service As Per Attached Checklist	VehService/JDS				29/08/2021	61157	Service	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074857	Woodinga Workshop	TRAILER
T614	Woodinga - Workshop	Chassis\MUDGUARDS	LH Guard needs replacing.					29/08/2021	61157	Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074857	Woodinga Workshop	TRAILER
T614	Woodinga - Workshop	Workshop\MOVE ASSET	Moving Assets in Yard.					29/08/2021	61157	Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074857	Woodinga Workshop	TRAILER
T614	Woodinga - Workshop	Brakes	Record Check Results As Attached To This Job					23/07/2021	47182	Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074857	Woodinga Workshop	TRAILER
T614	Woodinga - Workshop	Tyres	LF outer tyre crack					23/07/2021	47182	Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074857	Woodinga Workshop	TRAILER
T614	Woodinga - Workshop	Chassis\MUDGUARDS	R.R guard is missing					23/07/2021	47182	Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074857	Woodinga Workshop	TRAILER
T614	Woodinga - Workshop	VehService/JDS	D Service As Per Attached Checklist	VehService/JDS				23/07/2021	47182	Service	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074857	Woodinga Workshop	TRAILER
T614	Woodinga - Workshop	Tyres\TP3+4	replace 2 tyres					16/07/2021	42108	Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074857	Woodinga Workshop	TRAILER
T614	Woodinga - Workshop	Body\TRL REPS	Repair left hand rear upright.					13/07/2021	41393	Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074857	Woodinga Workshop	TRAILER
T614	Woodinga - Workshop	Tyres\TP09	Puncture repair					11/07/2021		Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074857	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Brakes	Record Check Results As Attached To This Job					29/06/2021	538246	Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Chassis\CHAS CRACK	Cracks in cross bracing under T/table area					29/06/2021	538246	Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Chassis\CROSS MBR	small crack bottom of cross brace					29/06/2021	538246	Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Body\DAMAGE	all safety rails bent and damaged					29/06/2021	538246	Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Chassis\DAMAGE	crash bar right side minimal damage					29/06/2021	538246	Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Body\DAMAGE	side rails bent and broken					29/06/2021	538246	Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Body\TRL WALL	right rear corner bolts broken roof					29/06/2021	538246	Fault	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T614	Woodinga - Workshop	Susp\VEY	Please check ride height.					29/06/2021	538246	Fault	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	VehService/JDS	D Service As Per Attached Checklist	VehService/JDS				29/06/2021	538246	Service	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Chassis\MUDGUARDS	Left rear guard need relocating.		Relocation of LR guard and support bar.			29/06/2021	538246	Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Workshop\MOVE ASSET	Park trailer in yard.					29/06/2021	538246	Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T614	Woodinga - Workshop	Brakes	Record Check Results As Attached To This Job					19/05/2021	17893	Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074857	Woodinga Workshop	TRAILER
T614	Woodinga - Workshop	Chassis\MUDGUARDS	Right Hand Gaurds and Mudflaps					19/05/2021	17893	Fault	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074857	Woodinga Workshop	TRAILER
T614	Woodinga - Workshop	VehService/JDS	D Service As Per Attached Checklist	VehService/JDS				19/05/2021	17893	Service	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074857	Woodinga Workshop	TRAILER
T614	Woodinga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP				19/05/2021	17893	PreventativeMaintenance	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074857	Woodinga Workshop	TRAILER
T614	Woodinga - Workshop	Unknown	Trailer due for service					19/05/2021	17893	Fault	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074857	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Brakes	Record Check Results As Attached To This Job					11/05/2021		Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	VehService/JDS	D Service As Per Attached Checklist	VehService/JDS				11/05/2021		Service	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Brakes	Record Check Results As Attached To This Job					15/04/2021		Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Elect\TRL LIGHTS	RH clearance light missing					15/04/2021		Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	VehService/JDS	D Service As Per Attached Checklist	VehService/JDS				15/04/2021		Service	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T614	Woodinga - Workshop	Tyres\TP02	Tyre Position 2					12/04/2021		Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074857	Woodinga Workshop	TRAILER
T614	Woodinga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP				10/04/2021		PreventativeMaintenance	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074857	Woodinga Workshop	TRAILER
T614	Woodinga - Workshop	Brakes	Record Check Results As Attached To This Job					10/04/2021		Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074857	Woodinga Workshop	TRAILER
T614	Woodinga - Workshop	VehService/JDS	D Service As Per Attached Checklist	VehService/JDS				10/04/2021		Service	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074857	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Workshop\MOVE ASSET	move set					24/03/2021		Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Brakes\BRK RELINE	reline					24/03/2021		Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Tyres\TP9+10	Supply and fit 4 tyres					24/03/2021	498890	Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Tyres\TP11+12	Tyre Position 11 + 12					24/03/2021	498890	Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	DriveLine\WHEEL BRGS	need adjustment done					23/03/2021		Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Susp\SUSPENSION	bush's have movement					23/03/2021		Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T614	Woodinga - Workshop	Brakes\BRK RELINE	Full Reline		TCTC supply Brake Drums & Shoe Kits			23/03/2021		Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T614	Woodinga - Workshop	Body\MUDGUARDS	Missing Guard Rear RHS - supplied by TCTC. Missing Guard Rear RHS					14/03/2021		Fault	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074857	Woodinga Workshop	TRAILER
T614	Woodinga - Workshop	Tyres\TP1+2	Supply and Fit 2 tyres					14/03/2021		Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074857	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Brakes	Record Check Results As Attached To This Job					12/03/2021	492247	Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	Elect\TRL LIGHTS	RH clearance light missing					12/03/2021	492247	Repair	Completed	FL Green Distribution	Tilner	Woodinga	LH8	074952	Woodinga Workshop	TRAILER
T615	Woodinga - Workshop	VehService/JDS	D Service As Per Attached Checklist	VehService/JDS				12/03/2021	492247	Service	Completed	FL

T615	Woodongs - Workshop	Chassis(L)CHAS CRACK	Cracks in cross bracing under T/table area						11/11/2020	427496	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074952	Woodongs Workshop	TRAILER
T615	Woodongs - Workshop	Body(D)AMAGE	side rails bent and broken						11/11/2020	427496	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074952	Woodongs Workshop	TRAILER
T615	Woodongs - Workshop	Chassis(L)CROSS MBR	small crack bottom of cross brace						11/11/2020	427496	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074952	Woodongs Workshop	TRAILER
T615	Woodongs - Workshop	Body(D)AMAGE	all safety rails bent and damaged						11/11/2020	427496	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074952	Woodongs Workshop	TRAILER
T615	Woodongs - Workshop	Susp(S)USPENSION	bush's have movement						11/11/2020	427496	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074952	Woodongs Workshop	TRAILER
T615	Woodongs - Workshop	VehService(JDS	D Service As Per Attached Checklist	VehService\JDS					11/11/2020	427496	Service	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074952	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	Brakes	Record Check Results As Attached To This Job						05/11/2020	405741	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	Elect(T)AIL LIGHT	R.H rego light cover broken, still worn						05/11/2020	405741	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	Chassis(L)WHEEL BRGS	front axle bearing movement						05/11/2020	405741	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	VehService(JDS	D Service As Per Attached Checklist	VehService\JDS					05/11/2020	405741	Service	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T615	Woodongs - Workshop	Body(T)RL REPS	replaced RH front curtain ratch						02/11/2020	423799	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074952	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	Tyres(F)ITMENT	Job Added From Invoice						30/10/2020	396030	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	Tyres(R)ETREAD	Job Added From Invoice						30/10/2020	396030	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	Tyres(F)ITMENT	Job Added From Invoice						29/10/2020	417149	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074952	Woodongs Workshop	TRAILER
T615	Woodongs - Workshop	Tyres(R)ETREAD	Job Added From Invoice						29/10/2020	417149	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074952	Woodongs Workshop	TRAILER
T615	Woodongs - Workshop	Tyres(S)CRAP TYRE	Job Added From Invoice						29/10/2020	417149	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074952	Woodongs Workshop	TRAILER
T615	Woodongs - Workshop	Brakes	Record Check Results As Attached To This Job						08/10/2020		Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074952	Woodongs Workshop	TRAILER
T615	Woodongs - Workshop	DriveLine(W)HEEL BRGS	need adjustment done						08/10/2020		Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074952	Woodongs Workshop	TRAILER
T615	Woodongs - Workshop	Susp(S)HOCK ABS	RHM shock starting to weep		previously done				08/10/2020		Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074952	Woodongs Workshop	TRAILER
T615	Woodongs - Workshop	Body(T)ANK MANI	RHF curtain ratchet		replaced				08/10/2020		Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074952	Woodongs Workshop	TRAILER
					RH rear wall mounts bolts missing LHS cracked																
T615	Woodongs - Workshop	Body(T)RL REPS	bolts are missing from the roof driver-side rear		move trailers resains to wall done and resains to cross brace while exsine				08/10/2020		Fault	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074952	Woodongs Workshop	TRAILER
T615	Woodongs - Workshop	Body(T)RL REPS	please fix or replace driver side curtain ratchet		previously done				08/10/2020		Fault	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074952	Woodongs Workshop	TRAILER
T615	Woodongs - Workshop	VehService(JDS	D Service As Per Attached Checklist	VehService\JDS					08/10/2020		Service	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074952	Woodongs Workshop	TRAILER
T615	Woodongs - Workshop	Insp(A)NN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP					08/10/2020		PreventativeMaintenance	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074952	Woodongs Workshop	TRAILER
T615	Woodongs - Workshop	Workshop(M)OVE ASSET	organise service clean up shed floor						08/10/2020		Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074952	Woodongs Workshop	TRAILER
T615	Woodongs - Workshop	Body(L)IGHTS	LHR on markers						08/10/2020		Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074952	Woodongs Workshop	TRAILER
T615	Woodongs - Workshop	Body(D)AMAGE	all safety rails bent and damaged						08/10/2020		Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074952	Woodongs Workshop	TRAILER
T615	Woodongs - Workshop	Chassis(W)HEEL BRGS	multiple bearings need adjusting						08/10/2020		Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074952	Woodongs Workshop	TRAILER
T615	Woodongs - Workshop	Susp(S)USPENSION	bush's have movement						08/10/2020		Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074952	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	Brakes	Record Check Results As Attached To This Job						24/09/2020	384845	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	VehService(JDS	D Service As Per Attached Checklist	VehService\JDS					24/09/2020	384845	Service	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	Body(T)RL REPS	new rollers, track still knocky						24/09/2020	384845	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	Body(W)HEEL BRGS	multiple bearings needs adjusting						24/09/2020	384845	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	Chassis(L)SKID PLATE	cracks starting to appear						24/09/2020	384845	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
					organise jobs and parts																
					replace both sides of curtain rollers																
T614	Woodongs - Workshop	Body(T)RL REPS	rollers need replacing (sticking)		osserate fork lift				24/09/2020	394854	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T615	Woodongs - Workshop	Body	Job Added From Invoice						19/09/2020	0	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074952	Woodongs Workshop	TRAILER
T615	Woodongs - Workshop	Body(P)ings	upwright repars		removed upright straightened remounted				16/09/2020		Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074952	Woodongs Workshop	TRAILER
T615	Woodongs - Workshop	Brakes	Record Check Results As Attached To This Job						13/09/2020	401755	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074952	Woodongs Workshop	TRAILER
T615	Woodongs - Workshop	Body(T)RL REPS	bolts are missing from the roof driver-side rear						13/09/2020	401755	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074952	Woodongs Workshop	TRAILER
T615	Woodongs - Workshop	Body(T)RL REPS	please fix or replace driver side curtain ratchet		parts on order				13/09/2020	401755	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074952	Woodongs Workshop	TRAILER
T615	Woodongs - Workshop	VehService(JDS	D Service As Per Attached Checklist	VehService\JDS					13/09/2020	401755	Service	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074952	Woodongs Workshop	TRAILER
T615	Woodongs - Workshop	Body(T)ANK MANI	RHF curtain ratchet						13/09/2020	401755	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074952	Woodongs Workshop	TRAILER
T615	Woodongs - Workshop	Chassis(U)LD COIL	sust lines leaking						13/09/2020	401755	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074952	Woodongs Workshop	TRAILER
T615	Woodongs - Workshop	Chassis(L)CROSS MBR	small crack bottom of cross brace						13/09/2020	401755	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074952	Woodongs Workshop	TRAILER
T615	Woodongs - Workshop	Body(T)RL REPS	front right roof pole bent badly						13/09/2020	401755	Fault	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074952	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	VehService(JDS	service	VehService\JDS					13/09/2020	401755	Service	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074952	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	Brakes	Record Check Results As Attached To This Job		carry out D service				01/09/2020	374417	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	Brakes	Record Check Results As Attached To This Job						01/09/2020	374417	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	VehService(JDS	D Service As Per Attached Checklist	VehService\JDS	carry out D service				01/09/2020	374417	Service	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	Body(T)RL REPS	rollers need replacing (sticking)						01/09/2020	374417	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	VehService(JDS	D Service As Per Attached Checklist	VehService\JDS					01/09/2020	374417	Service	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T615	Woodongs - Workshop	Body(T)RL REPS	Job Added From Invoice						29/08/2020	0	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074952	Woodongs Workshop	TRAILER
T615	Woodongs - Workshop	Brakes	Record Check Results As Attached To This Job						08/08/2020	381433	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074952	Woodongs Workshop	TRAILER
T615	Woodongs - Workshop	Elect(S)ELECT PB/W	replace light plugs						08/08/2020	381433	Fault	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074952	Woodongs Workshop	TRAILER
T615	Woodongs - Workshop	VehService(JDS	D Service As Per Attached Checklist	VehService\JDS					08/08/2020	381433	Service	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074952	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	Body(R)EFLECTORS	Job Added From Invoice						08/08/2020	0	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	Body(T)OOLBOX	Job Added From Invoice						08/08/2020	0	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	Body(T)OOLBOX	replace tool box door latches						01/08/2020	395761	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	Brakes	Record Check Results As Attached To This Job						01/08/2020	395761	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	Chassis(U)FITH WHEE	Skid plate foundation broken						01/08/2020	395761	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	Body(T)RL REPS	Curtain trck starting to get notchy						01/08/2020	395761	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	DriveLine(W)HEEL BRGS	LHF bearing movement		Checked - ok				01/08/2020	395761	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	DriveLine(W)HEEL BRGS	check wheel bearings		As per #297719				01/08/2020	395761	Fault	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	VehService(JDS	D Service As Per Attached Checklist	VehService\JDS					01/08/2020	395761	Service	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	Brakes	Record Check Results As Attached To This Job						22/07/2020		Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	VehService(JDS	D Service As Per Attached Checklist	VehService\JDS					22/07/2020		Service	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	Brakes	Record Check Results As Attached To This Job						08/07/2020	362274	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074952	Woodongs Workshop	TRAILER
T615	Woodongs - Workshop	Chassis(L)CHAS CRACK	Cracks in cross bracing under T/table area						08/07/2020	362274	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074952	Woodongs Workshop	TRAILER
T615	Woodongs - Workshop	DriveLine(W)HEEL BRGS	need adjustment done						08/07/2020	362274	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074952	Woodongs Workshop	TRAILER
T615	Woodongs - Workshop	Susp(S)HOCK ABS	RHM shock starting to weep						08/07/2020	362274	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074952	Woodongs Workshop	TRAILER
T615	Woodongs - Workshop	Elect(S)ELECT PB/W	replace light plugs						08/07/2020	362274	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074952	Woodongs Workshop	TRAILER
T615	Woodongs - Workshop	Body(D)AMAGE	side rails bent and broken						08/07/2020	362274	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074952	Woodongs Workshop	TRAILER
T615	Woodongs - Workshop	VehService(JDS	D Service As Per Attached Checklist	VehService\JDS					08/07/2020	362274	Service	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074952	Woodongs Workshop	TRAILER
T615	Woodongs - Workshop	Elect(S)ELECT PB/W	repair electrical socket						26/06/2020		Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074952	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	Brakes	Record Check Results As Attached To This Job						23/06/2020	343801	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	VehService(JDS	D Service As Per Attached Checklist	VehService\JDS					23/06/2020	343801	Service	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	Tyres(F)ITMENT	Job Added From Invoice						13/06/2020	341814	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074952	Woodongs Workshop	TRAILER
T615	Woodongs - Workshop	Tyres(C)LEANSKIN	Job Added From Invoice						13/06/2020	341814	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074952	Woodongs Workshop	TRAILER
T615	Woodongs - Workshop	Tyres(D)RY TYRES	R front Duels						30/05/2020	341814	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074952	Woodongs Workshop	TRAILER
T615	Woodongs - Workshop	Brakes	Record Check Results As Attached To This Job						30/05/2020	341814	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074952	Woodongs Workshop	TRAILER
T615	Woodongs - Workshop	Chassis(L)CHAS CRACK	Cracks in cross bracing under T/table area						30/05/2020	341814	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074952	Woodongs Workshop	TRAILER
T615	Woodongs - Workshop	DriveLine(W)HEEL BRGS	need adjustment done						30/05/2020	341814	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074952	Woodongs Workshop	TRAILER
T615	Woodongs - Workshop	Chassis(U)FITH WHEE	x bracing under T/table		As per #2888346				30/05/2020	341814	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074952	Woodongs Workshop	TRAILER
T615	Woodongs - Workshop	DriveLine(W)HEEL BRGS	continue to monitor wear						30/05/2020	341814	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074952	Woodongs Workshop	TRAILER
T615	Woodongs - Workshop	Susp(S)USPENSION	Cross suports cracking through centre		As per #2888346				30/05/2020	341814	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074952	Woodongs Workshop	TRAILER
T615	Woodongs - Workshop	VehService(JDS	D Service As Per Attached Checklist	VehService\JDS					30/05/2020	341814	Service	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074952	Woodongs Workshop	TRAILER
T615	Woodongs - Workshop	Susp(S)HOCK ABS	RHM shock starting to weep						30/05/2020	341814	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074952	Woodongs Workshop	TRAILER
T615	Woodongs - Workshop	Workshop(L)EAN	Redid service sheets for T615/616 as it wasn't printed till after service was completed						30/05/2020	341814	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074952	Woodongs Workshop	TRAILER
T615	Woodongs - Workshop	Workshop(M)OVE ASSET	Picked up next service						30/05/2020	341814	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074952	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	Brakes	Record Check Results As Attached To This Job						14/05/2020		Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	VehService(JDS	D Service As Per Attached Checklist	VehService\JDS					14/05/2020		Service	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T615	Woodongs - Workshop	Brakes	Record Check Results As Attached To This Job						10/05/2020	331518	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074952	Woodongs Workshop	TRAILER
T615	Woodongs - Workshop	Tyres(D)RY TYRES	R front Duels						10/05/2020	331518	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074952	Woodongs Workshop	TRAILER
T615	Woodongs - Workshop	Susp(S)USPENSION	Cross suports cracking through centre						10/05/2020	331518	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074952	Woodongs Workshop	TRAILER
T615	Woodongs - Workshop	VehService(JDS	D Service As Per Attached Checklist	VehService\JDS					10/05/2020	331518	Service	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074952	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	Tyres(F)ITMENT	Job Added From Invoice						08/05/2020	316203	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	Tyres(R)ETREAD	Job Added From Invoice						08/05/2020	316203	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	Tyres(C)ASE STOCK	Job Added From Invoice						06/05/2020	314990	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	Tyres(F)ITMENT	Job Added From Invoice						06/05/2020	314990	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	Tyres(R)ETREAD	Job Added From Invoice						06/05/2020	314990	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	Tyres(A)H Callout	two tyres needed replacing- sitting at Alpine MDF beauerepaires completed job. (T614/615)						27/04/2020		Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	Tyres(W)RES CHECK	Job Added From Invoice						17/04/2020	304204	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	Body(T)RL REPS	modify bolts and brackets & take out & put in top						14/04/2020	306023	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	Workshop(T)RAINING	operate forklift						14/04/2020	306023	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	Tyres(F)ITMENT	Job Added From Invoice						09/04/2020	299567	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	Tyres(C)LEANSKIN	Job Added From Invoice						09/04/2020	299567	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	Brakes	Record Check Results As Attached To This Job						07/04/2020	304205	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	VehService(JDS	D Service As Per Attached Checklist	VehService\JDS					07/04/2020	304205	Service	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	Body(T)RL REPS	Curtain trck starting to get notchy						07/04/2020	304205	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	DriveLine(W)HEEL BRGS	LHF bearing movement						07/04/2020	304205	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	Workshop(M)OVE ASSET	move trailers & get next service						06/04/2020	304205	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	Body(L)IGHTS	replace light						03/03/2020	293396	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	Brakes	Record Check Results As Attached To This Job		Completed on 06/03/2020				13/03/2020	293396	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	Chassis(L)MUDGUARDS	L rear guard needs replacing		Replaced & removed dead animal particles				13/03/2020	293396	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	VehService(JDS	D Service As Per Attached Checklist	VehService\JDS	Previously completed on 06/03/2020				13/03/2020	293396	Service	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T615	Woodongs - Workshop	Tyres(W)RES CHECK	Job Added From Invoice						13/03/2020	294023	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074952	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	Brakes	Record Check Results As Attached To This Job						07/03/2020	289641	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	Chassis(U)MUDGUARDS	LH rear guard u/s						07/03/2020	289641	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	Chassis(L)MUDGUARDS	L rear guard needs replacing						07/03/2020	289641	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	Susp(S)HOCK ABS	front R shock leaking		Slight weep				07/03/2020	289641	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	VehService(JDS	D Service As Per Attached Checklist	VehService\JDS					07/03/2020	289641	Service	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	Chassis(U)FITH WHEE	Skid plate foundation broken						07/03/2020	289641	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T615	Woodongs - Workshop	Brakes	Record Check Results As Attached To This Job						06/03/2020	294045	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074952	Woodongs Workshop	TRAILER
T615	Woodongs - Workshop	VehService(JDS	D Service As Per Attached Checklist	VehService\JDS					06/03/2020	294045	Service	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074952	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	Tyres(W)RES CHECK	Job Added From Invoice						03/03/2020	285693	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	Tyres(F)ITMENT	Job Added From Invoice						03/03/2020	285693	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	Tyres(R)ETREAD	Job Added From Invoice						03/03/2020	285693	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	Tyres(S)CRAP TYRE	Job Added From Invoice						03/03/2020	285693	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	Brakes	Record Check Results As Attached To This Job						27/02/2020		Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	VehService(JDS	D Service As Per Attached Checklist	VehService\JDS					27/02/2020		Service	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	Tyres(C)ASE STOCK	Job Added From Invoice						14/02/2020	27559	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	Tyres(F)ITMENT	Job Added From Invoice						14/02/2020	27559	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	Tyres(R)ETREAD	Job Added From Invoice						14/02/2020	27559	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	Tyres(A)H Callout	Job Added From Invoice						14/02/2020	27559	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	Workshop(M)OVE ASSET	move trailers & inspect for damage						13/02/2020		Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	Workshop(M)OVE ASSET	move trailers & inspect for damage						13/02/2020		Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	Body(T)RL REPS	replace RH curtain ratchet						13/02/2020		Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER
T614	Woodongs - Workshop	Brakes	Record Check Results As Attached To This Job						02/02/2020	272259	Repair	Completed	FL Green Distribution	Tilner	Woodongs	LH8	074857	Woodongs Workshop	TRAILER

T614	Woodings - Workshop	Elect\TRL LIGHTS	clearance lights front left and next one back not working front right						02/12/2019	246189	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074857	Woodings Workshop	TRAILER
T614	Woodings - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS					02/12/2019	246189	Service	Completed	FL Green Distribution	Tilner	Woodings	LH8	074857	Woodings Workshop	TRAILER
T614	Woodings - Workshop	Elect\TRL LIGHTS	clearance at front not working						02/12/2019	246189	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074857	Woodings Workshop	TRAILER
T614	Woodings - Workshop	Chassis\MUDGUARDS	LH rear guard o/s						02/12/2019	246189	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074857	Woodings Workshop	TRAILER
T615	Woodings - Workshop	Tyres\CASE STOCK	Job Added From Invoice						23/11/2019	10	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T615	Woodings - Workshop	Tyres\ATTMENT	Job Added From Invoice						23/11/2019	10	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T615	Woodings - Workshop	Tyres\RETREAD	Job Added From Invoice						23/11/2019	10	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T615	Woodings - Workshop	Brakes	Record Check Results As Attached To This Job						07/11/2019	237572	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T615	Woodings - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS					07/11/2019	237572	Service	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T615	Woodings - Workshop	Tyres\TP19	RHM inner tyre						07/11/2019	237572	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T615	Woodings - Workshop	Chassis\CHAS CRACK	cracks in cross bracing under Trable area						07/11/2019	237572	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T615	Woodings - Workshop	Body\FIFTH WHEE	adjusted Trable						07/11/2019	237572	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T614	Woodings - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP					26/10/2019		PreventativeMaintenance	Completed	FL Green Distribution	Tilner	Woodings	LH8	074857	Woodings Workshop	TRAILER
T614	Woodings - Workshop	Brakes	Record Check Results As Attached To This Job						29/10/2019		Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074857	Woodings Workshop	TRAILER
T614	Woodings - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS					29/10/2019		Service	Completed	FL Green Distribution	Tilner	Woodings	LH8	074857	Woodings Workshop	TRAILER
T615	Woodings - Workshop	Tyres\CASE STOCK	Job Added From Invoice						18/10/2019	223411	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T615	Woodings - Workshop	Tyres\ATTMENT	Job Added From Invoice						18/10/2019	223411	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T615	Woodings - Workshop	Tyres\RETREAD	Job Added From Invoice						18/10/2019	223411	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T615	Woodings - Workshop	Tyres\ATTMENT	Job Added From Invoice						16/10/2019	217605	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T615	Woodings - Workshop	Tyres\CLEANSKIN	Job Added From Invoice						16/10/2019	217605	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T615	Woodings - Workshop	Tyres\Air Callout	Job Added From Invoice						16/10/2019	217605	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T615	Woodings - Workshop	Tyres\SCRAP TYRE	Job Added From Invoice						16/10/2019	217605	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T615	Woodings - Workshop	Insp\ANN INSP	carry out annual inspection						12/10/2019	223411	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T615	Woodings - Workshop	Brakes	Record Check Results As Attached To This Job						12/10/2019	223411	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T615	Woodings - Workshop	Tyres\FAILURE	rear axle x4 replace		previously done				12/10/2019	223411	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T615	Woodings - Workshop	DriveLine\WHEEL BRGS	Rear axle needs adjusting		checked - no they don't				12/10/2019	223411	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T615	Woodings - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS					12/10/2019	223411	Service	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T615	Woodings - Workshop	Tyres\ATTMENT	Job Added From Invoice						29/09/2019	204878	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T615	Woodings - Workshop	Tyres\CLEANSKIN	Job Added From Invoice						29/09/2019	204878	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T614	Woodings - Workshop	Brakes	Record Check Results As Attached To This Job clearance lights not working						10/09/2019	206296	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074857	Woodings Workshop	TRAILER
T614	Woodings - Workshop	Elect\TRL LIGHTS	*job sendme. waitine on parts*						10/09/2019	206296	Repair	Completed	FL Green Distribution	Tilner	Woodnes	LH8	074857	Woodnes Workshop	TRAILER
T614	Woodings - Workshop	Chassis\MUDGUARDS	LHR guard needs replacing		previously completed				10/09/2019	206296	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074857	Woodings Workshop	TRAILER
T614	Woodings - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS					10/09/2019	206296	Service	Completed	FL Green Distribution	Tilner	Woodings	LH8	074857	Woodings Workshop	TRAILER
T614	Woodings - Workshop	Elect\TRL LIGHTS	top right clearance light out						10/09/2019	206296	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074857	Woodings Workshop	TRAILER
T615	Woodings - Workshop	Brakes	Record Check Results As Attached To This Job						03/09/2019		Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T615	Woodings - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS					03/09/2019		Service	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T615	Woodings - Workshop	Brakes	Record Check Results As Attached To This Job						03/09/2019		Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T615	Woodings - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS					03/09/2019		Service	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T615	Woodings - Workshop	VehService\DS	VehService\DS	VehService\DS					03/09/2019		Service	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T615	Woodings - Workshop	Brakes	Record Check Results As Attached To This Job						03/09/2019		Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T615	Woodings - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS					03/09/2019		Service	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T615	Woodings - Workshop	Brakes	Record Check Results As Attached To This Job						03/09/2019	200711	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T615	Woodings - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS					03/09/2019	200711	Service	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T615	Woodings - Workshop	Tyres\FAILURE	rear axle x4 replace						03/09/2019	200711	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T615	Woodings - Workshop	DriveLine\WHEEL BRGS	Rear axle needs adjusting						03/09/2019	200711	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T615	Woodings - Workshop	Body\TRL GATES	gate rack bent and broken						03/09/2019		Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T615	Woodings - Workshop	Susp\AIR FITTIN	I notice nothine has been done to reroute/support air and electrical lines between the A&B Trailers when turnine thev hane down over the wheels						03/09/2019		Fault	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T615	Woodings - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP					03/09/2019		PreventativeMaintenance	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T614	Woodings - Workshop	Brakes	Record Check Results As Attached To This Job clearance lights not working						31/07/2019		Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074857	Woodings Workshop	TRAILER
T614	Woodings - Workshop	Elect\TRL LIGHTS	*job sendme. waitine on parts*						31/07/2019		Repair	Completed	FL Green Distribution	Tilner	Woodnes	LH8	074857	Woodnes Workshop	TRAILER
T614	Woodings - Workshop	Body\DAMAGE	damage to rear RHS						31/07/2019		Fault	Completed	FL Green Distribution	Tilner	Woodings	LH8	074857	Woodings Workshop	TRAILER
T614	Woodings - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS					31/07/2019		Service	Completed	FL Green Distribution	Tilner	Woodings	LH8	074857	Woodings Workshop	TRAILER
T614	Woodings - Workshop	Chassis\MUDGUARDS	LHR guard needs replacing						31/07/2019		Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074857	Woodings Workshop	TRAILER
T615	Woodings - Workshop	Brakes	Record Check Results As Attached To This Job						31/07/2019	183006	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T615	Woodings - Workshop	Body\TRL GATES	gate rack bent and broken						31/07/2019	183006	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T615	Woodings - Workshop	Susp\AIR FITTIN	I notice nothine has been done to reroute/support air and electrical lines between the A&B Trailers when turnine thev hane down over the wheels		We are looking into alternative routes				31/07/2019	183006	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T615	Woodings - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS					31/07/2019	183006	Service	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T614	Woodings - Workshop	Elect\ELECT PB/W	Replaced female electric base plug		Moved trailers				30/07/2019	182779	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T614	Woodings - Workshop	Tyres\CASE STOCK	Job Added From Invoice						14/07/2019	164342	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074857	Woodings Workshop	TRAILER
T614	Woodings - Workshop	Tyres\WEIS.CHECK	Job Added From Invoice						14/07/2019	164342	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074857	Woodings Workshop	TRAILER
T614	Woodings - Workshop	Tyres\ATTMENT	Job Added From Invoice						14/07/2019	164342	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074857	Woodings Workshop	TRAILER
T614	Woodings - Workshop	Tyres\RETREAD	Job Added From Invoice						14/07/2019	164342	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074857	Woodings Workshop	TRAILER
T615	Woodings - Workshop	Brakes	Record Check Results As Attached To This Job						06/07/2019	170498	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T615	Woodings - Workshop	Body\CHN/RLR/MN	needs angle box		Completed				06/07/2019	170498	Fault	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T615	Woodings - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS					06/07/2019	170498	Service	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T615	Woodings - Workshop	Body\FIFTH WHEE	EAR movement						06/07/2019	170498	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T614	Woodings - Workshop	Brakes	Record Check Results As Attached To This Job						26/06/2019	163630	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074857	Woodings Workshop	TRAILER
T614	Woodings - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS					26/06/2019	163630	Service	Completed	FL Green Distribution	Tilner	Woodings	LH8	074857	Woodings Workshop	TRAILER
T614	Woodings - Workshop	Elect\TRL LIGHTS	4 clearance lamps at front						26/06/2019	163630	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074857	Woodings Workshop	TRAILER
T614	Woodings - Workshop	DriveLine\WHEEL BRGS	L/F 10thou out						26/06/2019	163630	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074857	Woodings Workshop	TRAILER
T614	Woodings - Workshop	VehService\DS	D service	VehService\DS					26/06/2019	163630	Service	Completed	FL Green Distribution	Tilner	Woodings	LH8	074857	Woodings Workshop	TRAILER
T614	Woodings - Workshop	Brakes\BRAKE ADJ	Record check results as attached to this job						26/06/2019	163630	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074857	Woodings Workshop	TRAILER
T614	Woodings - Workshop	Brakes	Record Check Results As Attached To This Job						28/05/2019	146845	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074857	Woodings Workshop	TRAILER
T614	Woodings - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS					28/05/2019	146845	Service	Completed	FL Green Distribution	Tilner	Woodings	LH8	074857	Woodings Workshop	TRAILER
T614	Woodings - Workshop	Elect\TRL LIGHTS	clearance lights not working N4						28/05/2019	146845	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074857	Woodings Workshop	TRAILER
T614	Woodings - Workshop	Body\TRL GATES	Job Added From Invoice						24/05/2019	0	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074857	Woodings Workshop	TRAILER
T615	Woodings - Workshop	Body\TRL GATES	Job Added From Invoice						24/05/2019	0	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T615	Woodings - Workshop	Brakes	Record Check Results As Attached To This Job						19/05/2019	148927	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T615	Woodings - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS					19/05/2019	148927	Service	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T615	Woodings - Workshop	Body\FIFTH WHEE	monitor feet bushes						19/05/2019	148927	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T614	Woodings - Workshop	Tyres\Puncr	Job Added From Invoice						11/05/2019	136514	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074857	Woodings Workshop	TRAILER
T615	Woodings - Workshop	Brakes	Record Check Results As Attached To This Job						04/04/2019		Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T615	Woodings - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS					04/04/2019		Service	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T614	Woodings - Workshop	Brakes	Record Check Results As Attached To This Job						04/04/2019	116880	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074857	Woodings Workshop	TRAILER
T614	Woodings - Workshop	Elect\ELECT PB/W	rewire to 5 pin		previously done				04/04/2019	116880	Fault	Completed	FL Green Distribution	Tilner	Woodings	LH8	074857	Woodings Workshop	TRAILER
T614	Woodings - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS					04/04/2019	116880	Service	Completed	FL Green Distribution	Tilner	Woodings	LH8	074857	Woodings Workshop	TRAILER
T614	Woodings - Workshop	VehService\DS	Service	VehService\DS	job complete				04/04/2019	116880	Service	Completed	FL Green Distribution	Tilner	Woodings	LH8	074857	Woodings Workshop	TRAILER
T615	Woodings - Workshop	Brakes	Record Check Results As Attached To This Job						27/03/2019		Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T615	Woodings - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS					27/03/2019		Service	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T615	Woodings - Workshop	Body\TRL REPS	weld load binder bar's						23/03/2019	121229	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T614	Woodings - Workshop	Brakes	Record Check Results As Attached To This Job						26/02/2019		Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074857	Woodings Workshop	TRAILER
T614	Woodings - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS					26/02/2019		Service	Completed	FL Green Distribution	Tilner	Woodings	LH8	074857	Woodings Workshop	TRAILER
T614	Woodings - Workshop	Brakes	Record Check Results As Attached To This Job						26/02/2019	101203	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074857	Woodings Workshop	TRAILER
T614	Woodings - Workshop	VehService\DS	Service	VehService\DS					26/02/2019	101203	Service	Completed	FL Green Distribution	Tilner	Woodings	LH8	074857	Woodings Workshop	TRAILER
T615	Woodings - Workshop	Body\TRL GATES	gate rack bent and broken						19/02/2019	101668	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T615	Woodings - Workshop	Brakes	Record Check Results As Attached To This Job						19/02/2019	101668	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T615	Woodings - Workshop	VehService\DS	Service	VehService\DS					19/02/2019	101668	Service	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T615	Woodings - Workshop	Body\TRL REPS	Job Added From Invoice						06/02/2019	0	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T615	Woodings - Workshop	Body\TRL REPS	front L/H hand for curtain is broken		replace LHF curtain ratchet				03/02/2019	91927	Fault	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T615	Woodings - Workshop	Body\TOOLBOX	Job Added From Invoice						30/01/2019	0	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T615	Woodings - Workshop	Brakes	Record Check Results As Attached To This Job						22/01/2019		Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T615	Woodings - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS					22/01/2019		Service	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T615	Woodings - Workshop	Brakes	Record Check Results As Attached To This Job						25/12/2018	72260	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T615	Woodings - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	fit NHAAS and service sticker holder				25/12/2018	72260	Service	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T614	Woodings - Workshop	Workshop\MOVE ASSET	move trailers						25/12/2018	72260	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T614	Woodings - Workshop	Brakes	Record Check Results As Attached To This Job						31/12/2018	63302	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074857	Woodings Workshop	TRAILER
T614	Woodings - Workshop	Elect\ELECT PB/W	wiring needs to be fixed up where it runs near rope rails		H duty base is not connected to any wires. Job pending talk to workshop supervisor				31/12/2018	63302	Fault	Completed	FL Green Distribution	Tilner	Woodings	LH8	074857	Woodings Workshop	TRAILER
T614	Woodings - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS					31/12/2018	63302	Service	Completed	FL Green Distribution	Tilner	Woodings	LH8	074857	Woodings Workshop	TRAILER
T614	Woodings - Workshop	Elect\BREAKDOWN	trailer lights cut out when B trailer hooked up		Camels truck repairs sublet auto elec.				07/12/2018		Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074857	Woodings Workshop	TRAILER
T614	Woodings - Workshop	Tyres\Puncr	Job Added From Invoice						05/12/2018	56349	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074857	Woodings Workshop	TRAILER
T614	Woodings - Workshop	Body\MOUNTS	wire wheel all rust off and pop for paint, drill mount holes and fit spacer block's						21/11/2018		Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074857	Woodings Workshop	TRAILER
T615	Woodings - Workshop	Tyres\ATTMENT	Job Added From Invoice						20/11/2018	50418	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T615	Woodings - Workshop	Tyres\CLEANSKIN	Job Added From Invoice						20/11/2018	50418	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T614	Woodings - Workshop	Brakes	Record Check Results As Attached To This Job						13/11/2018	49834	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074857	Woodings Workshop	TRAILER
T614	Woodings - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS					13/11/2018	49834	Service	Completed	FL Green Distribution	Tilner	Woodings	LH8	074857	Woodings Workshop	TRAILER
T614	Woodings - Workshop	Body\TRL REPS	curtain roller end bolts. curtain roller enf bolts						27/10/2018	42563	Fault	Completed	FL Green Distribution	Tilner	Woodings	LH8	074857	Woodings Workshop	TRAILER
T614	Woodings - Workshop	Elect\ELECT PB/W	wiring needs to be fixed up where it runs near rope rails						27/10/2018	42563	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074857	Woodings Workshop	TRAILER
T614	Woodings - Workshop	Workshop\MOVE ASSET	modify roof post stoppers and park up						27/10/2018	42563	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074857	Woodings Workshop	TRAILER
T615	Woodings - Workshop	Tyres	Job Added From Invoice						25/10/2018	39364	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T614	Woodings - Workshop	Body	Job Added From Invoice						24/10/2018	0	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074857	Woodings Workshop	TRAILER
T614	Woodings - Workshop	Brakes	Record Check Results As Attached To This Job		complete during service				17/10/2018	39063	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074857	Woodings Workshop	TRAILER
T614	Woodings - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS					17/10/2018	39063	Service	Completed	FL Green Distribution	Tilner	Woodings	LH8	074857	Woodings Workshop	TRAILER
T614	Woodings - Workshop	Susp\AIR FITTIN	I notice nothine has been done to reroute/support air and electrical lines between the A&B Trailers when turnine thev hane down over the wheels						16/10/2018	3524	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T615	Woodings - Workshop	Body\TOOLBOX	remove doorless toolbox and fit new toolbox						16/10/2018	3524	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T615	Woodings - Workshop	Body\TRL REPS	o/s curtain ratchet broken						16/10/2018	3524	Fault	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T615	Woodings - Workshop	Tyres	Job Added From Invoice						16/10/2018	0	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T615	Woodings - Workshop	Tyres\ATTMENT	Job Added From Invoice						16/10/2018	0	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T615	Woodings - Workshop	Tyres\RETREAD	Job Added From Invoice						16/10/2018	0	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T615	Woodings - Workshop	Brakes	Record Check Results As Attached To This Job						16/10/2018		Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T615	Woodings - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS					16/10/2018		Service	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T614	Woodings - Workshop	Body\DAMAGE	fit angle carrier						14/10/2018		Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074857	Woodings Workshop	TRAILER
T614	Woodings - Workshop	Body\TOOLBOX	weld in tie down rails and fit angle carrier remove hinges from old toolbox and prep new toolbox for paint		Aldonga repaired				14/10/2018		Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074857	Woodings Workshop	TRAILER
T615	Woodings - Workshop	Body\TOOLBOX	*toolbox sent to "CS" for paint. as could not source correct colour						11/10/2018		Repair	Completed	FL Green Distribution	Tilner	Woodnes	LH8	074857	Woodnes Workshop	TRAILER
T615	Woodings - Workshop	Workshop\MOVE ASSET	pick up from TCTC						04/10/2018		Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T615	Woodings - Workshop	Workshop\MOVE ASSET	drop at TCTC						04/10/2018		Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER
T614	Woodings - Workshop	Insp\RWC COMP	Job Added From Invoice						25/09/2018	0	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074857	Woodings Workshop	TRAILER
T614	Woodings - Workshop	VehService	Fit service sticker with todays date						13/09/2018	19384	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074857	Woodings Workshop	TRAILER
T614	Woodings - Workshop	Body\DAMAGE	pelmet rubber repairs						28/08/2018	10155	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074857	Woodings Workshop	TRAILER
T615	Woodings - Workshop	Susp\AIR FITTIN	replaced 7piece air line						22/08/2018	7997	Repair	Completed	FL Green Distribution	Tilner	Woodings	LH8	074952	Woodings Workshop	TRAILER